# Title List of Documents Made Publicly Available

October 1-31, 1982

Office of Administration U.S. Nuclear Regulatory Commission



#### Available from

NRC/GPO Sales Program

Superintendent of Documents Government Printing Office Washington, D. C. 20402

A year's subscription consists of 12 issues for this publication.

Single copies of this publication are available from National Technical Information Service, Springfield, VA 22161

Microfiche of single copies are available from NRC/GPO Sales Program Washington, D. C. 20555

# Title List of Documents Made Publicly Available

October 1-31, 1982

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



# CONTENTS

Preface	V
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket Items by Facility Name	xvii
Docketed Items	
Low Level Radwaste Disposal Sites — Docket 27	1
Domestic Licensing of Source Material — Docket 40	1
Domestic Licensing of Production and Utilization Facilities — Docket 50	7
Domestic Licensing of Special Nuclear Material — Docket 70	328
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions — Docket 71	335
Nondocketed Items	
10 CFR — Commission Meeting Records	339
ACRS — Advisory Committee on Reactor Safeguards	339
COMMISSION — NRC Commissioners	340
CONTRACT — NRC Contracts and Modifications	340
FOIA - Freedom of Information Act Requests and Releases	347
GEN TECH IS — Generic Technical Issues	364
I&E — Inspection and Enforcement	365
MISC — Public Document Room Miscellaneous	366
NUREG — NUREG Reports and Related Correspondence	366
ORG — Correspondence with Other Organizations	370
PR — Proposed Rule	371
PRM — Petition for Rulemaking	374
PROJ — Projects - Predocket Licensing	374
PT 21 — Noncompliance Reports and Related Correspondence	374
QA999 — Quality Assurance Inspections	374
REGGD — Regulatory Guides	376
RES — Research and Technical Assistance Reports	377
REVIEW GROUP NRC Research Review Groups	378
SECY — Position Papers Before the Commission	379
STATE PROG — State Programs	379
TOPREP — Vendor Reports and Related Correspondence	380
WASTE MGT — Nuclear Waste Management	383
XPORTLIC — Export and Import Licenses	384
Personal Author Index	389
Corporate Source Index	419
Report Number Index	449
Cross Reference of Enclosures to Principal Documents	451
Appendix A — Definitions of Docket 50 Categories	A-1
Appendix B — Definitions of Nandocketed Categories	B-1

#### PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

#### DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:


- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences. LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence

- W. Decommissioning stage documents and correspondence
- X Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

(I) P Operating license stage documents & correspondence



- 1. NRC/PDR Document category (see Appendix A)
- 2. NRC Accession Number (year, month, day, and sequence number of nem).
- 3. Description of information contained in the document.
- 4. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source.
- 6. Date of document described.
- 7. Recipient of document and NRC or corporate affiliation.
- 8. Pages in this document.
- 9. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files
- 10. This three-digit portion of this entry is the number of the frame on which this document starts.
- 11. The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
- 12. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

#### NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISCLOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases
GEN TECH IS — Generic Technical Issues

1&E - Inspection and Enforcement

MISC - Public Document Room Miscellaneous

NUREG - NUREG Reports and Related Correspondence

ORG - Correspondence with Other Organizations

PR — Proposed Rule

PRM — Petition for Rulemaking

PROJ — Projects—Predocket Licensing

PT21 - Noncomphance Reports and Related Correspondence

QA999 — Quality Assurance Inspections

REGGD - Regulatory Guides

RES — Research and Technical Assistance Reports

REVIEW GRP — NRC Research Review Groups

RM - Rulemakings

SECY — Position Papers Before the Commission

STATE PROG - State Programs

TOPREP — Vendor Reports and Related Correspondence


WASH — Regulatory Publications—Pre-NUREG Series

WASTE MGT - Nuclear Waste Management

XPORTLIC - Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



- 1. Nondocketed category
- 2. NRC Accession Number (year, month, day, and sequence number of item)
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 6. Corporate, agency or other nonindividual source.
- 7. Contract or financial (FIN) number (if any). If the document has a secondary report number, it will appear following this entry.
- 8. Secondary report number assigned by originator.
- 9 Date of document described.
- 10. NRC organizational recipient.
- Pages in document.
- 12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
- 13. Price for which NRC sells the document.

- 14. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files
- 15 This three-digit portion of this entry is the number of the frame on which this document starts.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

#### NOTES.

1 The address for NRC is.

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C 20555

To place orders, send check or money order, payable to the Superintendent of Documents GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2 The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order

3. The address for the PDR is:

1717 H Street, N W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings, which vary from \$0.50 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018

# ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Level Rad	waste Disposal Sites — Docket 27		40-8452	Bear Creek Uranium Co., Casper, WY	4
27-010	Beatty, NV, U.S. Ecology, Inc.	1	40-8502	Wyoming Mineral Corp., Lakewood, CO	5
27-039	Sheffield, IL, U.S. Ecology, Inc.	1	40-8577	Air Force, Dept. of, Vandenberg AFB, CA	5
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.	1	40-8602	Silver King Mines, Inc., Casper, WY	5
27-048	Richland, WA, U.S. Ecology, Inc.	1	40-8610	Stepan Chemical Co., Maywood, NJ	5
Domestic Licer	ising of Source Material — Docket 40		40-8632	Army, Dept. of, Chambersburg, PA	5
40-0017	Dow Chemical Co., Midland, MI	1	40-8681	Energy Fuels Nuclear, Inc., Denver, CO	5
40-0299	Union Carbide Corp., Grand Junction, CO	1	40-8697	Rocky Mountain Energy Co., Denver, CO	6
40-1162	Western Nuclear Corp., Jeffrey City, WY	2	40-8698	Plateau Resources, Ltd.,	
40-1202	NL Industries, Inc., Niagara Falls, NY	2	40 0714	Grand Junction, CO	6
40-1341	Tennessee Valley Authority,	2	40-8714	Cleveland-Cliffs Iron Co., Cleveland, OH	6
40.0061	Chattanooga, TN	2	40-8728	Teton Exploration Drilling Co., Inc., Casper, WY	6
40-2061	Kerr-McGee Chemical Corp., Oklahoma City, OK	2	40-8743	Conoco, Inc., Denver, CO	6
40-2259	Pathfinder Mines Corp., Riverton, WY	2	40-8745	Ogle Petroleum, Inc., Casper, WY	6
40-3392	Allied Chemical Corp., Morristown, NJ	2	40-8768	Kerr-McGee Nuclear Corp., Oklahoma City, OK	6
40-3453	Atlas Mineral, Inc., Denver, CO	2	40-8771	•	
40-6622	Pathfinder Mines Corp.,	3		Melapai Resources Co., Phoenix, AZ	6
10.7780	Shirley Basin, WY	3	40-8781	Teton Exploration Drilling Co., Inc., Casper, WY	6
40-6659	Getty Oil Co. — Petrotomics Co., Shirley Basin, WY	3	40-8786	Uranium Resources, Inc., Richardson, TX	7
40-7580	Fansteel, Inc., North Chicago, IL	3	40-8793	Conoco, Inc., Denver, CO	7
40-8027	Kerr-McGee Nuclear Corp., Oklahoma City, OK	3	40-8820	Amax Environmental Services, Inc., Golden, CO	7
40-8084	Rio Algom Corp., Moab, UT	4	40-8824	Target Research, Inc., Wharton, NJ	7
40-8102	Exxon Co. USA, Houston, TX	4	Domestic Lices Docket 50	nsing of Production and Utilization Facilities	
40-8111	Kennecott Copper Corp., Salt Lake City, UT	4	50-3	Indian Point Station, Unit 1	7
40-8153	Lebanon Steel Foundry, Lebanon, PA	4	50-10	Dresden Nuclear Power Station, Unit 1	
40-8355	Amax Speciality Metals Corp.,	4	50-13	Babcock & Wilcox Co. Critical Facility	8
40.0000	Parkersburg, WV	7		•	9
40-8380	Rocky Mountain Energy Co., Broomfield, CO	4	50-20	Massachusetts Institute of Technology Research Reacter	9

Docket	Name	Page	Docket	Name	Page
50-22	Westinghouse Test Reactor	9	50-247	Indian Point Station, Unit 2	36
50-27	Washington State Univ. Research Reactor	9	50-249	Dresden Nuclear Power Station, Unit 3	41
50-29	Yankee-Rowe Nuclear Power Station	9	50-250	Turkey Point Plant, Unit 3	43
50-54	Union Carbide Research Reactor	12	50-251	Turkey Point Plant, Unit 4	45
50-57	State Univ. of New York Research Reactor	12	50-254	Quad-Cities Station, Unit 1	47
50-62	Univ. of Virginia Research Reactor	12	50-255	Palisades Nuclear Plant	49
50-70	General Electric Test Reactor	12	50-259	Browns Ferry Nuclear Power Station, Unit 1	51
50-72	Univ. of Utah Research Reactor	13	50-260	Browns Ferry Nuclear Power Station, Unit 2	54
50-83	Univ. of Florida Training Reactor	13	50-261	H. B. Robinson Plant, Unit 2	56
50-133	Humboldt Bay Power Plant, Unit 3	13	50-263	Monticello Nuclear Generating Plant	58
50-142	UCLA Training Rector	13	50-264	Dow Chemical Co.	60
50-148	Univ. of Kansas Research Reactor	14	50-265	Quad-Cities Station, Unit 2	60
50-151	Univ. of Illinois Research Reactor	14	50-266	Point Beach Nuclear Plant, Unit 1	62
50-155	Big Rock Point Nuclear Plant	14	50-267	Fort St. Vrain Nuclear Generating Station	66
50-160	Georgia Institute of Technology Research Reactor	17	50-269	Oconee Nuclear Station, Unit 1	67
50-170	National Naval Medical Center	17	50-270	Oconee Nuclear Station, Unit 2	69
50-182	Purdue Univ. Research Reactor	18	50-271	Vermont Yankee Nuclear Power Station	71
50-184	National Bureau of Standards Reactor	18	50-272	Salem Nuclear Generating Station, Unit 1	73
50-186	Univ. of Missouri Research Reactor	18	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	76
50-188	Kansas State Univ. Research Reactor	18	50-277	Peach Bottom Atomic Power Station, Unit 2	79
50-192	Univ. of Texas Research Reactor	18	50-278	Peach Bottom Atomic Power Station, Unit 3	81
50-199	Manhattan College Research Reactor	18	50-280	Surry Power Station, Unit 1	82
50-201	West Valley Reprocessing Plant	18	50-281	Surry Power Station, Unit 2	85
50-206	San Onofre Nuclear Station, Unit 1	19	50-282	Prairie Island Nuclear Station, Unit !	87
50-208	Columbia Univ. Research Reactor	22	50-285	Fort Calhoun Station, Unit 1	89
50-213	Haddam Neck Plant	22	50-286	Indian Point Station, Unit 3	90
50-219	Oyster Creek Nuclear Power Plant	23	50-287	Oconee Nuclear Station, Unit 3	93
50-220	Nine Mile Point Nuclear Station, Unit I	26	50-289	Three Mile Island Nuclear Station, Unit 1	96
50-223	Univ. of Lowell Research Reactor	28	50-293	Pilgrim Nuclear Power Station, Unit 1	101
50-228	Aerotest Radiography & Research Reactor	28	50-295	Zion Nuclear Power Station, Unit 1	102
50-237	Dresden Nuclear Power Station, Unit 2	28	50-296	Browns Ferry Nuclear Power Station, Unit 3	106
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	30	50-298	Cooper Nuclear Station	107
50-245	Millstone Nuclear Power Station, Unit 1	34	50-301	Point Beach Nuclear Plant, Unit 2	108
				•	- 50

Docket	Name	Page	Docket	Name	Page
50-302	Crystal River Nuclear Plant, Unit 3	111	50-352	Limerick Generating Station, Unit 1	199
50-304	Zion Nuclear Power Station, Unit 2	113	50-353	Limerick Generating Station, Unit 2	201
50-305	Kewaunee Nuclear Power Plant	116	50-354	Hope Creek Nuclear Station, Unit 1	203
50-306	Prairie Island Nuclear Station, Unit 2	118	50-355	Hope Creek Nuclear Station, Unit 2	204
50-309	Maine Yankee Atomic Power Plant	119	50-358	William H. Zimmer Nuclear Station, Unit 1	204
50-311	Salem Nuclear Generating Station, Unit 2	122	50-361	San Onofre Nuclear Station, Unit 2	206
50-312	Rancho Seco Nuclear Generating Station	126	50-362	San Onofre Nuclear Station, Unit 3	209
50-313	Arkansas Nuclear One, Unit 1	129	50-363	Forked River Nuclear Station, Unit 1	210
50-315	Donald C Cook Nuclear Power Plant, Unit 1	131	50-364	Joseph M. Farley Nuclear Plant, Unit 2	210
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	134	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	213
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	137	50-367	Bailly Generating Station	215
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	141	50-368	Arkansas Nuclear One, Unit 2	216
50-320	Three Mile Island Nuclear Station, Unit 2	144	50-369	William B. McGuire Nuclear Station, Unit 1	218
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	146	50-370	William B. McGuire Nuclear Station, Unit 2	221
50-322	Shoreham Nuclear Power Station	148	50-373	LaSalle County Station, Unit 1	222
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	152	50-374	LaSalle County Station, Unit 2	226
50-324	Brunswick Steam Electric Plant, Unit 2	154	50-382	Waterford Generating Station, Unit 3	228
50-325	Brunswick Steam Electric Plant, Unit 1	159	50-387	Susquehanna Steam Electric Station, Unit 1	230
50-327	Sequoyah Nuclear Plant, Unit 1	164	50-388	Susquehanna Steam Electric Station, Unit 2	234
50-328	Sequoyah Nuclear Plant, Unit 2	166	50-389	St. Lucie Plant, Unit 2	235
50-329	Midland Plant, Unit 1	168	50-390	Watts Bar Nuclear Plant, Unit 1	238
50-330	Midland Plant, Unit 2	172	50-391	Watts Bar Nuclear Plant, Unit 2	241
50-331	Duane Arnold Energy Center	176	50-395	Virgil C. Summer Nuclear Station, Unit 1	244
50-333	James A. Fitzpatrick Nuclear Power Plant	178	50-397	WPPSS Nuclear Project, Unit 2	246
50-334	Beaver Valley Power Station, Unit 1	180	50-400	Shearon Harris Nuclear Power Plant, Unit 1	248
50-335	St. Lucie Plant, Unit 1	182	50-401	Shearon Harris Nuclear Power Plant, Unit 2	251
50-336	Millstone Nuclear Power Station, Unit 2	184	50-402	Shearon Harris Nuclear Power Plant, Unit 3	254
50-338	North Anna Power Station, Unit 1	186	50-403	Shearon Harris Nuclear Power Plant, Unit 4	254
50-339	North Anna Power Station, Unit 2	189	50-404	North Anna Power Station, Unit 3	254
50-341	Enrico Fermi Atomic Power Plant, Unit 2	192	50-405	North Anna Power Station, Unit 4	254
50-344	Trojan Nuclear Plant	194	50-409	La Crosse Boiling Water Reactor	255
50-346	Davis-Besse Nuclear Power Station, Unit 1	195	50-410	Nine Mile Point Nuclear Station, Unit 2	257
50-348	Joseph M. Farley Nuclear Plant, Unit 1	197	50-412	Beaver Valley Power Station, Unit 2	258

Docket	Name	Page	Docket	Name	Page
50-413	Catawba Nuclear Station, Unit 2	258	STN-50-485	Sterling Power Nuclear Project, Unit 1	303
50-414	Catawba Nuclear Station, Unit 2	261	STN-50-488	Perkins Nuclear Station, Unit 1	303
50-416	Grand Gulf Nuclear Station, Unit 1	263	STN-50-489	Perkins Nuclear Station, Unit 2	303
50-417	Grand Gulf Nuclear Station, Unit 2	267	STN-50-490	Perkins Nuclear Station, Unit 3	304
50-423	Millstone Nuclear Power Station, Unit 3	269	STN-50-491	Cherokee Nuclear Station, Unit 1	304
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	269	STN-50-492	Cherokee Nuclear Station, Unit 2	304
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	270	STN-50-493	Cherokee Nuclear Station, Unit 3	304
50-434	Surry Power Station, Unit 3	271	STN-50-498	South Texas Project, Unit 1	304
50-435	Surry Power Station, Unit 4	271	STN-50-499	South Texas Project, Unit 2	305
STN-50-437	Floating Nuclear Plant	271	STN-50-508	WPPSS Nuclear Project, Unit 3	306
50-438	Bellefonte Nuclear Plant, Unit 1	271	STN-50-509	WPPSS Nuclear Project, Unit 5	307
50-439	Bellefonte Nuclear Plant, Unit 2	274	50-513	WPPSS Nuclear Project, Unit 4	307
50-440	Perry Nuclear Power Plant, Unit 1	276	50-514	Pebble Springs Nuclear Plant, Unit 1	307
50-441	Perry Nuclear Power Plant, Unit 2	280	50-515	Pebble Springs Nuclear Plant, Unit 2	307
50-443	Seabrook Nuclear Station, Unit 1	284	STN-50-518	Hartsville Nuclear Plant, Unit 1	307
50-444	Seabrook Nuclear Station, Unit 2	286	STN-50-519	Hartsville Nuclear Plant, Unit 2	308
50-445	Comanche Peak Steam Electric Station, Unit 1	287	STN-50-520	Hartsville Nuclear Plant, Unit 3	308
50-446	Comanche Peak Steam Electric Station,	289	STN-50-521	Hartsville Nuclear Plant, Unit 4	309
30-140	Unit 2	209	50-522	Skagit Nuclear Power Project, Unit 1	309
STN-50-447	GESSAR-238	290	50-523	Skagit Nuclear Power Project, Unit 2	310
STN-50-454	Byron Station, Unit 1	291	STN-50-528	Palo Verde Nuclear Station, Unit 1	311
STN-50-455	Byron Station, Unit 2	293	STN-50-529	Palo Verde Nuclear Station, Unit 2	314
STN-50-456	Braidwood Station, Unit 1	295	STN-50-530	Palo Verde Nuclear Station, Unit 3	316
STN-50-457	Braidwood Station, Unit 2	296	50-537	Clinch River Breeder Reactor	318
50-458	River Bend Station, Unit !	297	STN-50-546	Marble Hill Nuclear Station, Unit 1	325
50-459	River Bend Station, Unit 2	298	STN-50-547	Marble Hill Nuclear Station, Unit 2	326
<b>50-46</b> 0	WPPSS Nuclear Project, Unit 1	298	STN-50-553	Phipps Bend Nuclear Station, Unit 1	326
50-461	Clinton Power Station, Unit 1	299	STN-50-554	Phipps Bend Nuclear Station, Unit 2	326
50-462	Clinton Power Station, Unit 2	301	STN-50-556	Black Fox Station, Unit 1	327
50-466	Allens Creek Nuclear Station, Unit 1	301	STN-50-557	Black Fox Station, Unit 2	327
STN-50-470	CESSAR System 80	301	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	327
		301	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	327
		302	STN-50-584	Gibbsar, Gibbs & Hill	328

Docket	Name	Page	Docket	Name	Page
Domestic Lice	nsing of Special Nuclear Material — Docket 70		70-2748	Scioto Memorial Hospital, Portsmouth, OH	334
70-0007	ICN Pharmaceuticals, Inc.,	•••	70-2789	Missouri, Univ. of, Columbia, MO	334
	Irvine, CA	328	70-2792	Lower Bucks Hospital, Bristol, PA	334
70-0025	Rockwell International Corp., Canoga Park, CA	328	70-2873	Puerto Rico, Univ. of, Mayaguez, PR	334
70-0027	Babcock & Wilcox Co., Lynchburg, VA	328	70-2942	Harper-Grace Hospitals, Detroit, MI	334
70-0033	Texas Instruments, Inc., Attleboro, MA	328	70-2944	Duke Power Co., Charlotte, NC	334
70-0036	Combustion Engineering, Inc., Windsor, CT	329	70-2946	Louisiana Power & Light Co., New Orleans, LA	334
70-0135	Babcock & Wilcox Co., Apollo, PA	329	70-2949	Arizona Public Service Co., Phoenix, AZ	334
70-0143	Nuclear Fuel Services, Inc., Erwin, TN	329	70-2949	Edlow International Co., Washington, DC	334
70-0223	California, Univ. of, Los Angeles, CA	330	70-2957	Florida Power & Light Co., Miami, FL	334
70-0278	Dow Chemical Co., Midland, MI	330	70-2968	Cleveland Electric Illuminating Co.,	354
70-0364	Babcock & Wilcox Co., Apollo, PA	330	70-2500	Cleveland, OH	335
70-0371	UNC Naval Products, Inc., Uncasville, CT	330	Packaging of D	adloactive Material for Transport and Transport	stio n
70-0398	Commerce, Dept. of, Washington, DC	331		ve Material Under Certain Conditions — Docket	
70-0416	Colorado State Univ., Ft. Collins, CO	331	71-0030	General Atomic Co.	335
70-0633	Pan American World Airways, Inc., Patrick AFB, FL	331	71-0481	Monroe X-Ray Co., Inc.	335
70-0687	Union Carbide Corp., Tuxedo, NY	331	71-5908	Model: DOT-6M Type B, Babcock & Wilcox Co.	335
70-0753	Wheaton College, Wheaton, IL	331	71-5926	Model: GE-100, General Electric Co.	335
70-0754	General Electric Co., Pleasanton, CA	331	71-5939	Model: GE-1500, General Electric Co.	335
70-0820	United Nuclear Corp.,		71-6115	Model: R1010-0032, Energy, Dept. of	335
	Wood River Junction, RI	331	71-6346	Model: FSV-1, General Atomic Co.	335
70-0824	Babcock & Wilcox Co., Lynchburg, VA	332	71-6347	Model: FSV-3, General Atomic Co.	335
70-1100	Combustion Engineering, Inc., Windsor, CT	332	71-6574	Model: HN-200, Hittman Nuclear &	
70-1113	General Electric Co., Wilmington, NC	332		Development Corp.	
70-1143	Westinghouse Electric Corp., Pittsburgh, PA	332	71-6601	Model: CNS 8-120, Chem-Nuclear Systems, Inc.	333
70-1151	Westinghouse Electric Corp., Pittsburgh, PA	333	71-6639	Model: MH-1A, Army, Dept. of	335
70-1201	Babcock & Wilcox Co., Lynchburg, VA	333	71-6677	Model: LP-12, Energy, Dept. of	335
70-1257	Exxon Nuclear Co., Inc., Richland, WA	333	71-6678	Model: LP-50, Energy, Dept. of	336
70-1510	Nuclear Assurance Corp., Atlanta, GA	333	71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	336
70-1621	Duquesne Light Co., Pittsburgh, PA	333	71-6703	Model: RG-1, General Atomic Co.	336
70-1739	Tri-State Motor Transit Co., Joplin, MO	334	71-6745	Model: FSV-2, General Atomic Co.	336
70-2116	Lawrence General Hospital, Lawrence, MA	334	71-9001	Model: IF-300, General Electric Co.	336
70-2650	St. John's Mercy Medical Center, St. Louis, MO	334	71-9010	Model: NLI-1/2, NL Industries, Inc.	336

Dockel	Name	Page	Docket	Name	Page
71-9034	Model. TRIGA-1, General Atomic Co	336	71-9091	Model: 30A & 30B, Guif Nuclear Co.	337
71-9037	Model TRIGA-2, General Atomic Co.	336	71-9094	Model: CNS 14-195-H, Chem-Nuclear Systems, Inc.	137
71-9044	Model. GE-1600, General Electric Co	336	71-9096	Model: CNS 21-300, Chem-Nuclear	
71-9057	Model: FPD-100, General Atomic Co	336	/1-9090	Systems, Inc.	337
71-9079	Model. HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp.	336	71-9098	Model: UCC-20WC-2 & 2A, Union Carbide Corp.	337
71-9080	Model: 9080, Hittman Nuclear & Development Corp.	336	71-9111	Model: CNS6-80-2, Chem-Nuclear Systems, Inc.	117
71-9081	Model. CNS-1600, Chem-Nuclear Systems, Inc.	336	71-9150	Model: PAT-2, Energy, Dept, of	117
71-9086	Model: HN-100, Series I, Hittman Nuclear & Development Corp.	336	71-9151	Model: HN-100, Series 3, Hittman Nuclear & Development Corp.	317
71-9089	Model HN-100S, Hittman Nuclear	250	71-9167	Model: Type B, Amersham Corp,	117
1,17007	& Development Corp.	337	71-9964	Model: LP-12-1, Energy, Dept. of	137

# ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Low Level Radwaste Disposal Sites - Docket 2	27				
Barnwell, SC, Chem-Nuclear Systems, Inc.	27-047	1	Melapai Resources Co., Phoenix, AZ	40-8771	6
Beatty, NV, U.S. Ecology, Inc.	27-010	1	NL Industries, Inc., Niagara Falls, NY	40-1202	2
Richland, WA, U.S. Ecology, Inc.	27-048	1	Ogle Petroleum, Inc., Casper, WY	40-8745	6
Sheffield, IL, U.S. Ecology, Inc.	27-039	1	Pathfinder Mines Corp., Riverton, WY	40-2259	2
Domestic Licensing of Source Material Dock	cet 40		Pathfinder Mines Corp., Shirley Basin, WY	40-6622	3
Air Force, Dept. of, Vandenberg AFB, CA	40-8577	5	Plateau Resources, Ltd., Grand Junction, CO	40-8698	6
Allied Chemical Corp., Morristown, NJ	40-3392	2	Rio Algom Corp., Moab, UT	40-8084	4
Amax Environmental Services, Inc., Golden, C	O 40-8820	7	Rocky Mountain Energy Co., Broomfield, CO	40-8380	4
Amax Speciality Metals Corp.,	10 00 00		Rocky Mountain Energy Co., Denver, CO	40-8697	6
Parkersburg, WV	40-8355	4	Silver King Mines, Inc., Casper, WY	40-8602	5
Army, Dept. of, Chambersburg, PA	40-8632	5	Stepan Chemical Co., Maywood, NJ	40-8610	5
Atlas Mineral, Inc., Denver, CO	40-3453	2	Target Research, Inc., Wharton, NJ	40-8824	7
Bear Creek Uranium Co., Casper, WY	40-8452	4	Tennessee Valley Authority, Chattanooga, TN	40-1341	2
Cleveland-Cliffs Iron Co., Cleveland, OH	40-8714	6	Teton Exploration Drilling Co., Inc.,		
Conoco, Inc., Denver, CO	40-8743	6	Casper, WY	40-8728	6
Conoco, Inc., Denver, CO	40-8793	7	Teton Exploration Drilling Co., Inc., Casper, WY	40-8781	6
Dow Chemical Co., Midland, MI	40-0017	1	Union Carbide Corp., Grand Junction, CO	40-0299	1
Energy Fuels Nuclear, Inc., Denver, CO	40-8681	5	Uranium Resources, Inc., Richardson, TX	40-8786	7
Exxon Co. USA, Houston, TX	40-8102	4	Western Nuclear Corp., Jeffrey City, WY	40-1162	2
Fansteel, Inc., North Chicago, IL	40-7580	3	• • • • • •		-
Getty Oil Co. — Petrotomics Co., Shirley Basin, WY	40-6659	3	Wyoming Mineral Corp., Lakewood, CO	40-8502	5
Kennecott Copper Corp., Salt Lake City, UT			Domestic Licensing of Production and Utilizati Docket 50	om Lucinities	
	40-8111	4	Acrotest Radiography & Research Reactor	50-228	28
Kerr-McGee Chemical Corp., Oklahoma City, OK	40-2061	2	Allens Creek Nuclear Station, Unit 1	50-466	301
Kerr-McGee Nuclear Corp., Oklahoma City, O	K 40-8027	3	Alvin W. Vogtle Nuclear Plant, Unit I	50-424	269
Kerr-McGee Nuclear Corp., Oklahoma City, O	K 40-8768	6	Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	270
Lebanon Steel Foundry, Lebanon, PA	40-8153	4	Arkansas Nuclear One, Unit 1	50-313	129

Name	Docket	Page	Name	Docket	Page
Arkansas Nuclear One, Unit 2	50-368	216	Comanche Peak Steam Electric Station, Unit 1	50-445	287
Babcock & Wilcox Co. Critical Facility	50-13	9	Comanche Peak Steam Electric Station, Unit 2	50-446	289
Bailly Generating Station	50-367	215	Cooper Nuclear Station	50-298	107
Beaver Valley Power Station, Unit 1	50-334	180	Crystal River Nuclear Plant, Unit 3	50-302	111
Beaver Valley Power Station, Unit 2	50-412	258	Davis-Besse Nuclear Power Station, Unit 1	50-346	195
Bellefonte Nuclear Plant, Unit 1	50-438	271	Diablo Canyon Nuclear Power Plant, Unit I	50-275	76
Bellefonte Nuclear Plant, Unit 2	50-439	274	Diablo Canyon Nuclear Power Plant, Unit 2	50-323	152
Big Rock Point Nuclear Plant	50-155	14	Donald C. Cook Nuclear Power Plant, Unit 1	50-315	131
Black Fox Station, Unit 1	STN-50-556	327	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	134
Black Fox Station, Unit 2	STN-50-557	327	Dow Chemical Co.	50-264	60
Braidwood Station, Unit I	STN-50-456	295	Dresden Nuclear Power Station, Unit 1	50-10	8
Braidwood Station, Unit 2	STN-50-457	296	Dresden Nuclear Power Station, Unit 2	50-237	28
Browns Ferry Nuclear Power Station, Unit 1	50-25 <del>9</del>	51	Dresden Nuclear Power Station, Unit 3	50-249	41
Browns Ferry Nuclear Power Station, Unit 2	50-260	54	Duane Arnold Energy Center	50-331	176
Browns Ferry Nuclear Power Station, Unit 3	50-296	106	Edwin I. Hatch Nuclear Plant, Unit I	50-321	146
Brunswick Steam Electric Plant, Unit 1	50-325	159	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	213
Brunswick Steam Electric Plant, Unit 2	50-324	154	Enrico Fermi Atomic Power Plant, Unit 2	50-341	192
Byron Station, Unit I	STN-50-454	291	Floating Nuclear Plant	STN-50-437	271
Byron Station, Unit 2	STN-50-455	293	Forked River Nuclear Station, Unit I	50-363	210
Callaway Plant, Unit 1	STN-50-483	302	Fort Calhoun Station, Unit !	50-285	89
Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	137	Fort St. Vrain Nuclear Generating Station	50-267	66
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	141	General Electric Test Reactor	50-70	12
Catawba Nuclear Station, Unit 1	50-413	258	Georgia Institute of Technology Research		
Catawba Nuclear Station, Unit 2	50-414	261	Reactor	50-160	17
'stem 80	STN-50-470	301	GESSAR-238	STN-50-447	290
			Gibbsar, Gibbs & Hill	STN-50-584	328
			Grand Gulf Nuclear Station, Unit 1	50-416	263
			Grand Gulf Nuclear Station, Unit 2	50-417	267
			H. B. Robinson Plant, Unit 2	50-261	56
			Haddam Neck Plant	50-213	22
			Hartsville Nuclear Plant, Unit 1	STN-50-518	307
			Hartsville Nuclear Plant, Unit 2	STN-50-519	308

Name	Docket	Page	Name	Docket	Page
Hartsville Nuclear Plant, Unit 3	STN-50-520	308	Nine Mile Point Nuclear Station, Unit 1	50-220	26
Hartsville Nuclear Plant, Unit 4	STN-50-521	309	Nine Mile Point Nuclear Station, Unit 2	50-410	257
Hope Creek Nuclear Station, Unit 1	50-354	203	North Anna Power Station, Unit 1	50-338	186
Hope Creek Nuclear Station, Unit 2	50-355	204	North Anna Power Station, Unit 2	50-339	189
Humboldt Bay Power Plant, Unit 3	50-133	13	North Anna Power Station, Unit 3	50-404	254
Indian Point Station, Unit 1	50-37	7	North Anna Power Station, Unit 4	50-405	254
Indian Point Station, Unit 2	50-247	36	Oconee Nuclear Station, Unit 1	50-269	67
Indian Point Station, Unit 3	50-286	90	Oconee Nuclear Station, Unit 2	50-270	69
James A. Fitzpatrick Nuclear Power Plant	50-333	178	Oconee Nuclear Station, Unit 3	50-287	93
Joseph M. Farley Nuclear Plant, Unit 1	50-348	197	Oyster Creek Nuclear Power Plant	50-219	23
Joseph M. Farley Nuclear Plant, Unit 2	50-364	210	Palisades Nuclear Plant	50-255	49
Kansas State Univ. Research Reactor	50-188	18	Palo Verde Nuclear Station, Unit 1	STN-50-528	311
Kewaunee Nuclear Power Plant	50-305	116	Palo Verde Nuclear Station, Unit 2	STN-50-529	314
La Crosse Boiling Water Reactor	50-409	255	Palo Verde Nuclear Station, Unit 3	STN-50-530	316
LaSalle County Station, Unit 1	50-373	222	Peach Bottom Atomic Power Station, Unit 2	50-277	79
LaSalle County Station, Unit 2	50-374	226	Peach Bottom Atomic Power Station, Unit 3	50-278	81
Limerick Generating Station, Unit 1	50-352	199	Pebble Springs Nuclear Plant, Unit 1	50-514	307
Limerick Generating Station, Unit 2	50-353	201	Pebble Springs Nuclear Plant, Unit 2	50-515	307
Maine Yankee Atomic Power Plant	50-309	119	Perkins Nuclear Station, Unit 1	STN-50-488	303
Manhattan College Research Reactor	50-199	18	Perkins Nuclear Station, Unit 2	STN-50-489	303
Marble Hill Nuclear Station, Unit 1	STN-50-546	325	Perkins Nuclear Station, Unit 3	STN-50-490	304
Marble Hill Nuclear Station, Unit 2	STN-50-547	326	Perry Nuclear Power Plant, Unit 1	<b>50-44</b> 0	276
Massachusetts Institute of Technology	£0.20	٥	Perry Nuclear Power Plant, Unit 2	50-441	280
Research Reactor	50-20	9	Phipps Bend Nuclear Station, Unit 1	STN-50-553	326
Midland Plant, Unit 1  Midland Plant, Unit 2	50-329 50-330	168 172	Phipps Bend Nuclear Station, Unit 2	STN-50-554	326
Millstone Nuclear Power Station, Unit 1	50-245	34	Pilgrim Nuclear Power Station, Unit 1	50-293	101
Millstone Nuclear Power Station, Unit 2	50-336	184	Point Beach Nuclear Plant, Unit 1	50-266	62
Millstone Nuclear Power Station, Unit 3	50-423	269	Point Beach Nuclear Plant, Unit 2	50-301	108
Monticello Nuclear Generating Plant	50-263	58	Prairie Island Nuclear Station, Unit 1	50-282	87
National Bureau of Standards Reactor		38 18	Prairie Island Nuclear Station, Unit 2	50-306	118
National Naval Medical Center	50-184		Purdue Univ. Research Reactor	50-182	18
Manonai Masai Micdical Centel	50-170	17	rutuue Omy, Research Reactor	30-102	

Name	Docket	Page	Name	Docket	Page
Quad-Cities Station, Unit 1	50-254	47	Susquehanna Steam Electric Station, Unit 1	50-387	230
Quad-Cities Station, Unit 2	50-265	60	Susquehanna Steam Electric Station, Unit 2	50-388	234
Rancho Seco Nuclear Generating Station	50-312	126	Three Mile Island Nuclear Station, Unit 1	50-289	96
River Bend Station, Unit 1	50-458	297	Three Mile Island Nuclear Station, Unit 2	50-320	144
River Bend Station, Unit 2	50-459	298	Trojan Nuclear Plant	50-344	194
Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	30	Turkey Point Plant, Unit 3	50-250	43
Salem Nuclear Generating Station, Unit 1	50-272	73	Turkey Point Plant, Unit 4	50-251	45
Salem Nuclear Generating Station, Unit 2	50-311	122	UCLA Training Reactor	50-142	13
San Onofre Nuclear Station, Unit 1	50-206	19	Union Carbide Research Reactor	50-54	12
San Onofre Nuclear Station, Unit 2	50-361	206	Univ. of Florida Training Reactor	50-83	13
San Onofre Nuclear Station, Unit 3	50-362	209	Univ. of Illinois Research Reactor	50-151	14
Seabrook Nuclear Station, Unit I	50-443	284	Univ. of Kansas Research Reactor	50-148	14
Seabrook Nuclear Station, Unit 2	50-444	286	Univ. of Lowell Research Reactor	50-223	28
Sequoyah Nuclear Plant, Unit i	50-327	164	Univ. of Missouri Research Reactor	50-186	18
Sequoyah Nuclear Plant, Unit 2	50-328	166	Univ. of Texas Research Reactor	50-192	18
Shearon Harris Nuclear Power Plant, Unit I	50-400	248	Univ. of Utah Research Reactor	50-72	13
Shearon Harris Nuclear Power Plant, Unit 2	50-401	251	Univ. of Virginia Research Reactor	50-62	12
Shearon Harris Nuclear Power Plant, Unit 3	50-402	254	Vermont Yankee Nuclear Power Station	50-271	71
Shearon Harris Nuclear Power Plant, Unit 4	50-403	254	Virgil C. Summer Nuclear Station, Unit 1	50-395	244
Shoreham Nuclear Power Station	50-322	148	Washington State Univ. Research Reactor	50-27	9
Skagit Nuclear Power Project, Unit 1	50-522	309	Waterford Generating Station, Unit 3	50-382	228
Skagit Nuclear Power Project, Unit 2	50-523	310	Watts Bar Nuclear Plant, Unit 1	50-390	238
South Texas Project, Unit 1	STN-50-498	304	Watts Bar Nuclear Plant, Unit 2	50-391	241
South Texas Project, Unit 2	STN-50-499	305	West Valley Reprocessing Plant	50-201	18
Plant, Unit 1	50-335	182	Westinghouse Test Reactor	50-22	9
Init 2	50-389	235	William B. McGuire Nuclear Station, Unit 1	50-369	218
	<b>የ</b> በ <b>የ</b> ግ	12	William B. McGuire Nuclear Station, Unit 2	50-370	221
		303	William H. Zimmer Nuclear Station, Unit 1	50-358	204
		82	Wolf Creek Generating Station	STN-50-482	301

Name	Docket	Page	Name	Docket	Page
WPPSS Nuclear Project, Unit 4	50-513	307	Louisiana Power & Light Co., New Orleans, LA	70-2946	334
WPPSS Nuclear Project, Unit 5	STN-50-509	307	Lower Bucks Hospital, Bristol, PA	70-2792	334
Yankee-Rowe Nuclear Power Station	50-29	9	Missouri, Univ. of, Columbia, MO	70-2789	334
Yellow Creek Nuclear Plant, Unit 1	STN-50-566	327	Nuclear Assurance Corp., Atlanta, GA	70-1510	333
Yellow Creek Nuclear Plant, Unit 2	STN-50-567	327	Nuclear Fuel Services, Inc., Erwin, TN	70-0143	329
Zion Nuclear Power Station, Unit 1	50-295	102	Pan American World Airways, Inc., Patrick AFB, FL	70-0633	331
Zion Nuclear Power Station, Unit 2	50-304	113	Puerto Rico, Univ. of, Mayaguez, PR	70-2873	334
Domestic Licensing of Special Nuclear Materia	al — Docket 70		Rockwell International Corp., Canoga Park, CA		328
Arizona Public Service Co., Phoenix, AZ	70-2949	334	Scioto Memorial Hospital, Portsmouth, OH	70-2748	334
Babcock & Wilcox Co., Apollo, PA	70-0135	329	St. John's Mercy Medical Center, St. Louis, MC		334
Babcock & Wilcox Co., Apollo, PA	70-0364	330	Texas Instruments, Inc., Attleboro, MA	70-0033	328
Babcock & Wilcox Co., Lynchburg, VA	70-0027	328	Tri-State Motor Transit Co., Joplin, MO	70-1739	334
Babcock & Wilcox Co., Lynchburg, VA	70-0824	332	UNC Naval Products, Inc., Uncasville, CT	70-0371	330
Babcock & Wilcox Co., Lynchburg, VA	70-1201	333	Union Carbide Corp., Tuxedo, NY	70-0687	331
California, Univ. of, Los Angeles, CA	70-0223	330	United Nuclear Corp., Wood River Junction, RI	70-0820	331
Cleveland Electric Illuminating Co., Cleveland, OH	70-2968	335	Westinghouse Electric Corp., Pittsburgh, PA	70-1143	332
Colorado State Univ., Ft. Collins, CO	70-0416	331	Westinghouse Electric Corp., Pittsburgh, PA	70-1151	333
Combustion Engineering, Inc., Windsor, CT	70-0036	329	Wheaton College, Wheaton, IL	70-0753	331
Combustion Engineering, Inc., Windsor, CT	70-1100	332	Packaging of Radioactive Material for Transpor of Radioactive Material Under Certain Condi		
Commerce, Dept. of, Washington, DC	70-0398	331	General Atomic Co.	71-0030	335
Dow Chemical Co., Midland, MI	70-0278	330	Model: 30A & 30B, Gulf Nuclear Co.	71-9091	337
Duke Power Co., Charlotte, NC	70-2944	334	Model: 9080, Hittman Nuclear & Development		
Duquesne Light Co., Pittsburgh, PA	70-1621	333	Corp.	71-9080	336
Edlow International Co., Washington, DC	70-2955	334	Model: CNS 14-195-H, Chem-Nuclear Systems, Inc.	71-9094	337
Exxon Nuclear Co., Inc., Richland, WA	70-1257	333	Model: CNS 21-300, Chem-Nuclear Systems,		
Florida Power & Light Co., Miami, FL	70-2957	334	inc.	71-9096	337
General Electric Co., Pleasanton, CA	70-0754	331	Model: CNS 8-120, Chem-Nuclear Systems, Inc		335
General Electric Co., Wilmington, NC	70-1113	332	Model: CNS-1600, Chem-Nuclear Systems, Inc.	71-9081	336
Harper-Grace Hospitals, Detroit, MI	70-2942	334	Model: CNS6-80-2, Chem-Nuclear Systems, Inc.	71-9111	337
ICN Pharmaceuticals, Inc., Irvine, CA	70-0007	328	Model: DOT-6M Type B, Babcock & Wilcon		
Lawrence General Hospital, Lawrence, MA	70-2116	334	Co.	71-5908	335

Name	Docket	Page	Name	Docket	Page
Model: FPD-100, General Atomic Co.	71-9057	336	Model: LP-12, Energy, Dept. of	71-6677	335
Model: FSV-1, General Atomic Co.	71-6346	335	Model: LP-12-1, Energy, Dept. of	71-9964	337
Model: FSV-2, General Atomic Co.	71-6745	336	Model: LP-50, Energy, Dept. of	71-6678	336
Model: FSV-3, General Atomic Co.	71-6347	335	Model: MH-1A, Army, Dept. of	71-6639	335
Model: GE-100, General Electric Co.	71-5926	335	Model: NFS-4, Nuclear Fuel Services, Inc.	71-6698	336
Model: GE-1500, General Electric Co.	71-5939	335	Model: NLI-1/2, NL Industries, Inc.	71-9010	336
Model GE-1600, General Electric Co.	71-9044	336	Model: PAT-2, Energy, Dept. of	71-9150	337
Model: HN-100, Series 1, Hittman Nuclear Development Corp.	& 71-9086	336	Model: R1010-0032, Energy, Dept. of	71-6115	335
Model: HN-100, Series 2, 2A, Hittman Nuclea & Development Corp.	ar 71-9079	336	Model: RG-1, General Atomic Co.	71-6703	336
Model. HN-100, Series 3, Hittman Nuclear &			Model: TRIGA-1, General Atomic Co.	71-9034	336
Development Corp.	71-9151	337	Model: TRIGA-2, General Atomic Co.	71-9037	336
Model: HN-100S, Hittman Nuclear & Development Corp.	71-9089	337	Model: Type B, Amersham Corp.	71-9167	337
Model: HN-200, Hittman Nuclear & Development Corp.	71-6574	335	Model: UCC-20WC-2 & 2A, Union Carbide Corp.	; 71-9098	337
Model: 1F-300, General Electric Co.	71-9001	336	Monroe: X-Ray Co., Inc.	71-0481	333

## **DOCKETED ITEMS**

#### LOW LEVEL RADWASTE DISPOSAL SITES.

DOCKET 27-010 BEATTY, NV. U S ECOLOGY, INC.

210260304 PNO-V-B2 044 on B2[012, shipment of low level radwaste received from GE Vallecttos Nuclear Ctr containing box w/hole in side Administrative penalty of \$1500 levied Permit suspended indefinitely IMDMAS.R D Region 5. Orfice of Director B2/10/19 ip 15901 361

# DOCKET 27-039 SHEFFIELD, IL. U.S. ECOLOGY, INC

- 8210120320 Summary of 820908 steering committee meeting w/IDNS, State of IL USOS & US Ecology to discuss results of Phase II portion or tritium migration study & to determine need for Phase II investigations Exhibits encl
  SIEFKEN, D.L. Low Level Waste Licensing Branch 82/09/20
  HAWKINS, E.F. Low Level Waste Licensing Branch 6pp 15689 236
- 62:0120411 Notification of contract execution.Mod 5 to "Sheffield Trench Cap Study " Contractor Univ of IL FLEENDR.C M Technical Assistance Contracts Branch FIN 8-6965-2 82/09/28 DAVIS.J , SIEFKEN.D Office of Nuclear Material Safety & Safeguards.Director ip 15691 167
- --8210120419 Mod 5 revising task repts delivery schedule, increasing estimated cost revising voucher submittal & substituting updated Manual Chapter 3202, to "Sheffield Trench Cap Study "PORTER.F W Illinois, Univ of Urbana-Champaign HAGAN,T F. Division of Contracts FIN 8-6965-2 82/09/28 4pp 15691168
- 62(0050095 Joint motion to continue proceedings until 830201 to provide add1 time for settlement negotiations Certificate of S.c. enct LESSY,R P. Hearing Branch 3. WETTERHAHN,M J. US Ecology, Inc (Formerly Nuclear Engineering) 82/10/01 Atomic Gafety and Licensing Board Panel 3pp. 15604 236
- 6210080075 Order granting NRC & applicant joint motion to continue proceedings until 830201 COOBHOPE, A C Atomic Safety and Licensing Board Panel 62/10/06 Office of the Executive Legal Director ip 15643 267

### DOCKET 27-047 BARNWELL, SC. CHEM-NUCLEAR SYSTEMS, INC

- R210120135 Consents to transfer of Licenses 46-13536-01 & 46-19524-01 room Chem-Nuclear Sys. Inc to WMI Holdings. Inc All existing obligations & responsibilities under current license will be applicable to & binding upon subsidiary DAVIS. J Q Office of Nuclear Material Safety & Safeguards Director 82/09/07 HUIZENGA.P Waste Management. Inc 2pp 15692 167
- E210120144 Confirms 820910 arrangements for J Davis 820921 site visit prior to attending 820923-24 meetings in Atlanta. GA PANOBURN, G C Low Level Maste Licensing Branch 82/09/13 FURVIS.J Chem-Nuclear Systems. Inc. ip 194
- 8210120465 Trip rept of 820701-02 visit to Columbia, 8C to attend State of SC hearings on qualifications of Waste Mgt. Inc to conduct radioactive matls operations under licenses currently held by Chem-Nuclear, Inc PANOBURN, 0 C Low Level Waste Licensing Branch 82/07/17 HAWKINS.E F Low Level Waste Licensing Branch 4pp 15671 306

#### DOCKET 27-048 RICHLAND, WA, U.S. ECOLOGY, INC

5210130130 PND-V-82-040 on 821004 notified that shipment of low level radwaste received on 820927 from Smith Kline & French Labs was in violation of BOT regulations 490FR173 393(d) & 172 403(b) Vendor license suspended effective 820928 THEMASIR D Region 5. Office of Director 82/10/05 [p 15673 039]

#### DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0017 DOW CHEMICAL CO , MIDLAND, MI

- 8210180028 Responds to FOIA request for seven categories of documents re Dow Chemical Co & incingration of low level radwastr Request for fee waiver granted Forwards listed documents FELTON. J M Division of Rules and Records 82/08/20 WILGON, A K Affiliation Unknown 2pp 15748 002 24X Fiche 50-264.82/08/20, 8210180028
- --8210180239 Application for renewal of Mat1/Byproduct Licenses 21-0265-06.21-00265-02.21-00265-04.21-00265-07.BMM-1253. 310-527 % R-10B authorizing any byproduct mat1 between Atomic Numbers 3 1 83. tijtiom.Pa-210 & Am-241 HDYLE.H R Dow Chemical Co 73/06/25 2pp 15748 115 24% Fiche 50-264.82/08/20.8210180028
- DOCKET 40-0299 UNION CARBIDE CORP , GRAND JUNCTION, CO
- 8210250017 Forwards "Investigation of Elevated Radioactivity Measurements Around Union Carbide Corp Inactive Tailings Area in Gas Hills.HY." per License Amend 10 WGNG.T Union Carbide Corp 82/0//30 PETTENGILL.H Uranium Recovery Licensing Branch 1p 19808 260
- ~-8210250021 "Investigation of Elevated Radioactivity Measurements Around Union Carbide Corp Inactive Tailings Area in Qas Hills.WY " \* Union Carbide Corp 82/07/30 10pp 15808 261
- 8210190246 Forwards "Semiannual ALARA Rept, Jan-June 1982," per License Condition 17 WONG. T Union Carbide Corp 82/09/03 LYON3.P J Uranium Recovery Licensing Branch to 15759 001
- --8210190256 "Semiannual ALARA Rept. Jan-June 1982" One oversize map encl Aperture card is available in PDR 4 Union Carbide Corp 82/09/03 53ipp 15759 003
- 8210130607 Requests written declaration of intent or interest in two listed tallings situations resulting in pollution & contamination of groundwaters of State of WY FRANCIS.E Wyoming, State of 62/09/07 LINEHAN.J Uranium Recovery Licensing Branch 3pp 15692 335
- 8210220491 Forwards revised lower limits of detection for Ra-226 & Th-230 in water LYONS, P J Union Carbide Corp 82/09/22 PETTENGILL, H Division of Fuel Cycle & Material Safety 2pp 15786 321
- 8210210530 Requests detailed breakdown of revised reclamation cost estimate in order to complete evaluation of 820804 submitted Info should be provided by 821030 PETTENGILL:H J Uranium Recovery Licensing Branch 82/09/30 LYONS:P Union Carbide Corp 2pp 15782 323

- DOCKET 40-1162 WESTERN NUCLEAR CORP , JEFFREY CITY, MY
- 8210220123 Forwards IE Insp Rept 40-1162/82-02 on 820901 No noncompliance noted EROWN 0 D Classion of Vandor & Technical Programs 82/09/28 WELLER, T Western Nuclear. Inc (subs of Phelps Dadge Corp ) 2pp 15778 141
- --B21022012B IE Insp Rept 40-1162/82-02 on B20901 No noncompliance noted Major areas inspected V mill waste mgt activities SHQPENNIN H . CAIN.C L . EVERETT.R J Division of Vendor & Technical Programs B2/09/21 4pp 1577B 143
- 8210220475 Submits review of Split Rock Mill 920630 annual technical evaluation of performance of tailings embantment Embantment performed as sipected No further action necessary GARCIA.P.J. Uranium Recovery Licensing Branch 82/10/05 Uranium Recovery Licensing Branch 2pp 15796-323
- DUCKET 40-1202 NL INDUSTRIES, INC , MIAGARA FALLS, NY
- 8210010418 Forwards IE Insp Rept 40-1202/82-01 Inquiry conducted to determine whether formerly licensed site meets current criteria for release for whrestricted use kINNEMAN. J D Division of Engineering & Technical Programs 82/09/23 JACOSS, J L RL Industries. Inc. 2pp. 15570-217
- --8210010428 IE Insp Rept 40-1202/82-01 on 820595-0702 Inquiry conducted to determine whether formerly licensed site meets current criteria for release for unrestricted use Site meets criteria JOHANSEN. J H , KINNEMAN. J H Region 1, Office of Director 62/08/02 Jpp 15570 219
- --8210010434 Forwards "Summary of Radiological Survey of NL Industries Riagara Falls Plant," final rept JACOBS.J L NL Industries Inc 82/06/24 JOHANSEN.J Region f. Office of Director 2pp 18570 222
- --8210010440 "Summary of Radiological Survey of NL Industries Niagara Falls Plant:" final rept LEIGH,D W NL Industries, Inc. 79/05/31 129pp 15570 224
- DOCKET 40-1341 TENNESSEE VALLEY AUTHORITY, CHATTANDUGA, TN
- 8210050422 FINAL ENVIRONMENTAL STATEMENT RELATED TO THE DECOMMISSIONING OF EDGEMONT URANIUM MILL Doctst No. 40-1941 (Tennessee Valley Authority)
- \* Office of Nuclear Haterial Safety & Safequards, Director NUREO-0846 82/06/30 320pp Available at NRC \$7.00 15623 074
- DOCKET 40-2061 KERR-MCGEE CHEMICAL CORP , OKLAHOMA CITY, DK
- 8210270077 Forwards fee for 820806 application to amend License STA-583 to allow dismantling of Bldgs 2.10.11 & 21 SHELLEY.N J Kerr-McGee Corp 82/09/14 WEISB.D License Fee Management Branch Ip 15836 214
- --921027008B Application for amend to License STA-503 to allow dismantling of Bldgs 2.10.11 & 21
  SHELLEY, IF J. Merr-Higee Corp. 82/08/06 NIXON, IF A. Uranium Fuel Licensing Branch. 2pp. 15836-216
- --8210270091 Requests payment of amend fee, needed to process 820806 application for amend to License STA-583 to allow dismantling of 81695 2, 10, 11 & 21 HEISS.D License Fee Management Branch 82/09/01 SHELLEY, W J Kerr-KcOee Corp 1p 15836 215
- BRIO120187 Order designating NMS Deputy Director to act as presiding officer to conduct hearing on Amend 5 Certificate of Svc and DAVIS.J O Office of Nuclear Material Safety & Safeguards, Director 2pp 13651 235
- 8210150463 Requests info on hearing to be held per Commission 820806 Order CLI-82-21 Response should define rules for procedure, discovery & subposines & should establish schedule SPELMAN.H.J. Harold J. Spelman & Associates 82/10/12 HOYLE.J.C. Office of the Secretary of the Commission 10 15703 104

- 82(0280434 Responds to 920706 ltr commenting on DES se decommissioning of Kerr-McGee Rare Earths facility Final statement will recognize site as alternative storage/disposal site for other residues in West Chicago. It CunningHahr E Division of Fuel Cycle & Material Gafety 832/10/15 CAMILL, P.C. Environmental Protection Agency 2pp 15860 045
- B210250315 Response to Kerr-Hogee B20723 request for consolidation of License Amend & w/License Amend 5 for hearing purposes City does not object Svc list encl SPELMAN, H J West Chicago, IL SPELMAN, H J Harald J Spelman & Associates B2/10/22 Commissioners 3pp 15770 221
- DOCKET 40-2259 PATHFINDER MINES CORP . RIVERTON, WY
- 8210270054 Trip rept of 820826 site visit to tomplete annual insp FRANCIS.E , KEARNEY.D Pathfinder Mines Corp 82/08/26 Pathfinder Mines Corp 2pp 15836 [f]
- 8210150607 Forwards "Quarterly Effluent Monitoring Rept.Apr June 1982." per License Conditions 51 & 54 NUGERIFE L Pathfinder Mines Corp 82/08/31 SCARAND, R A Uranium Recovery Licensing Branch 1p 15715 320
- --8210150613 "Quarterly Efficent Monitoring Rept. Aprilune 190,2" This oversite map encl Aperture card is available in PDR
  \* Pathfinder Mines Corp 82/08/31 13pp 15715 321
- 8210130607 Requests written declaration of intent or interest in two listed tailings situations resulting in pollution to contamination of groundwaters of State of My FRANCIS.E. Myoming State of 82/09/07 LINCHAN. J. Uranium Recovery Licensing Branch. 3pp. 15692 335
- 8210120514 Advises that equipment cost analysis, tailings pond reclamation bond analysis & reclamation bond summary consistent w/approved reclamation plan for Pathfinder Lucky Mc Hill tailings pand SOLLENBERGER, D. PETTENDILL.H J. Oranium Recovery Cicensing Nionch 82/09/20 Uranium Recovery Licensing Branch 3pp 19672 092
- 6210320161 Forwards IE Insp Rept 40-2259/82-01 on 820727-29 & notice of violation of BRDWN, of Division of Vendor & Technical Programs 82/09/27 NUSENT, EL Pathfinder Mines Corp 2pp 15778 058
- ~-8210220165 Natice of violation from insp on 820727-29 \* Division of Vendor & Technical Programs 82/09/27 Ep 15778 060
- --8210220171 IE Insp Rept 40-2259/82-01 on 820727-29 Noncompliance muled failure of personnel to shower or monitor for contamination prior to leaving mill restricted area MHITTEN.JE. DROWN.R.C., EVERETT.R.J. Division of Vendor & Technical Programs 82/09/17 lipp 15778 064
- DOCKET 40-3392 ALLIED CHEMICAL CORP , MORRISTONN, NJ
- 8210150600 informs that drawings in 920701 application for renewal of License 5UB-326 are not proprietary CIPOLLAA J Allied Chemical Corp 82/09/17 PAGE,R O Uranium Fuel Licensing Branch ip 15716 336
- DOCKET 40-9459 ATLAS MINERAL, INC . DENVER, CO
- 8210260079 Forwards second quarter 1982 quarterly rept re sampling & analysis results of environ monitoring program per License Conditions 42.43 & 47 EDMARDS, D.L. Atlas Minerals 82/08/18 SCARAND, R.A. Uranium Recovery Licensing Branch 2pp 19810 257
- --8210240090 Second quarter 1982 sampling analysis results of environ monitoring program a Atlas Minerals 82/08/18 70pp 15810 259
- 8210150596 Responds to NRC 820708 ltr requesting proposed site for relocation of background station used to monitor environ air quality Tables re wind direction, chemical concentration & resident exposure encl.

  BLUBAUOH, R.E. Atlas Minerals 02/02/02 ---

- G21021021 Reviews first quarter 1982 environ munitoring data & dose calculations for nearest receptor required by License Condition 47 Compliance w/40CFR190 stds will be determined when new site becomes operational LARCIA.P J. PETTENGILL.H J. Uranium Recovery Licensing Branch 82/09/20 Uranium Recovery Licensing Branch 4pp 15782 216
- 62(02(052) Issues Amend 10 to License SUA-917 in response to 811204 request & revised by 820428 ftr Amend adds Condition 54 delineating line of authority between radiation safety coordinator & ensite individual SM17H,R D Uranium Recovery Licensing Branch 82/09/30 Atlas Minerals 2pp 15782 311
- 8210210525 Recommends issuance of Amend 10 to License SUA-917 in response to 811204 request 2 revised by 820428 ltr Amend adds Condition 54 delineating line of authority between radiation safety officer 2 onsite individual GARCIA:P J PETTEMOFLE, Uranium Recovery Licensing Branch 82/09/30 Uranium Recovery Licensing Branch 52/09/30 Uranium Recovery Licensing Branch
- DOCKET 40-6622 PATHFINDER MINES CORP . SHIRLEY BASIN. WY
- OC1025002B Forwards State of WY 020721 request for info re tailings seepage & 020729 response RUSSELL J E Pathfinder Mines Corp 02/07/29 PETTENGILL/H NRC No Detailed Affiliation Given 5pp 15790 343
- 82(0150601 Forwards one oversise revised topographic map per Liconse Condition 41 Aperture card is available in PDR SMITH, J.C. Pathfinder Mines Corp. 82/08/06. Uranium Recovery Licensing Branch Ip. 15715-335
- EDIO180415 Forwards "Subsurface Migration Update & Answers to NRC Questions" MURDOCP'E S Pathfinder Mines Corp 82/08/06 SDLLENBERGER.D Utanium Recovery Licensing Branch (p. 15747-220
- --8210183420 "Subsurface Migration Update & Answers to NRC Questions "
  Eight oversize drawings enc! Aperture cards are available in
  PRR
  UNRDOCK. E S , SMITH. J C Pathfinder Mines Corp 82/03/31 /App
  15747 221
- B<sub>E</sub> 10070383 Forwards IE Insp Rept 40-6622/82-02 on 820713-16 & notice or violation SRCMLA D Division of Vendor & Technical Programs 82/08/13 RUSSELL J E Pathfinder Mines Corp 2pp 15633 318
- -8210070385 Notice of violation from insp on 820713-16
   Division of Vendor & Technical Programs 82/08/13 2pp
  15637 320
- --8210070374 IE Insp Rept 40-6622/82-02 on 820713-16 Noncompliance noted on 820715, audible alarm setpoint on survey instrument adjusted to level exceeding acceptable limit CAIN, C.L., MURRAY, B., EVERETT, R.J. Division of Vendor & Technical Programs 82/08/10 9pp 15633 322
- 82:0260013 Forwards revised environ QA program,per Amend 7 to License SUA-442 SMITH,J C Pathfinder Mines Corp 82/08/30 Uranium Recovery Licensing Branch 1p 15814 160
- ---8210260014 Revised environ QA program

  + Pathfinder Mines Corp 82/08/31 92pp 15814 161
- 82:0290177 Forwards stability review for Number 5 embankment per Condition 42 of Amend 8 to License SUA-442 Rept gives strong evidence that Number 5 embankment functioning according to design features RUSSELL.J E Pathfinder Mines Corp 82/09/14 SOLLENBERG Uranium Recovery Licensing Branch 11pp 15874 233
- 5210120644 Advises that preliminary review of application for renewal of License SUA-442 complete General content acceptable but addl info will be needed Current license valid during period of review of renewal application PETTEKOILL, H. J. Uranium Recovery Licensing Branch 62/09/20 RITCHIE, M. I. Pathfinder Mines Corp. ip 15684 233
- 8210220464 Ack receipt of 820903 ltr informing NRC of steps taken to correct violations noted in IE insp rept BROWN.0 D Region 4. Office of Director 82/09/27 RUBSELL, J E Pathfinder Mines Corp ip 15779 130

- --8210220476 Responds to NRC 820813 ltr re violations noted in IE insprept Corrective actions high audible alarm setpoint reset Honthly surface contamination survey procedures improved RUSSELL, J E Pathfinder Mines Corp 82/09/03 BROWN, 0 D Regium 4, Orfice of Birector 2pp 15779 131
- DOCKET 40-6659 GETTY DIL CO PETROTOMICS CD , SHIRLEY BABIN, WY
- 8210220510 Forwards correspondence to & from State of MY re unauthorized disposal of radwaste in U mill tailings disposal facilities PFAFF:S J Cetty Gil Co (Petrotomics) 82/08/26 PETTENGILL:H J Uranium Recovery Licensing Branch 4pp 15786 119
- 8210210254 Forwards marked-up ltr from Getty Oil Co to State of HY indicating that requested info re wells & piezometers is on file at NRC Expresses desire for interagency cooperation ACKERMAN, W C Wyoming, State of 82/09/14 SMITH, D Division of Waste Management 4pp 15774 320
- 8210120628 Advises that remedial actions proposed by licenses in response to 811113 IE Mill Appraisal Rept 40-6657/81-01 sufficient to correct weaknesses No licensing action will be required JONES, S Z , GARCIA, P J Uranium Recovery Licensing Branch 82/09/20 Uranium Recovery Licensing Branch 2pp 15672 269
- 6210210527 Reviews environ monitoring data & 40CFR190 dose calculations for Petrotomics Mill. in response to 820604 ltr NRC concurs w/results submitted by licensee JONES, S. Z. PETTENOILL, H. J. Uranium Recovery Licensing Branch 82/09/30 Uranium Recovery Licensing Branch 5pp 15782 318
- DOCKET 49-7580 FANSTEEL, INC., NORTH CHICAGO, IL
- 8210280180 Ack receipt of 820908 ltr informing NRC of steps taken to correct violations noted in NRC 820813 ltr & notice of violation Add1 info requested within 10 days BROWN, 0 D Division of Vendor & Technical Programs 82/10/25 PIERRET, J A Fansteel Metals (subs of Fansteel, Inc.) (p. 15892-019
- ---8210280184 Responds to NRC 820813 ]tr & notice of violation Corrective actions portable radiation detection instruments calibr against two refs & logged in lab log book PIERRET, J A Fansteel Metals (subs of Fansteel Inc.) 82/09/00 BROWN. 0 D Division of Vendor & Technical Programs 1p 19837 020
- DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP , CMLAHOMA CITY, OK
- 8210240543 Forwards application for amend to License SUB-1010 to construct & operate sludge calcining plant for purpose of converting raffinate sludge to readily disposable form SHELLEY, N. J. Kerr-McGee Corp. 82/09/01 PAGE, R. G. Uranium Fuel Licensing Branch 3pp. 15831 091
- --8210260548 Application for amend to License SUB-1010 to construct & operate sludge calcining plant for purpose of converting raffinate sludge to readily disposable form Oversize drawings encl Aperture cards available in PDR \* Kerr-McGee Corp 82/09/01 133pp 1583; 094
- 8210260565 Forwards OK State Dept of Health, Industrial Waste Mgt Div 820824 1tr transmitting draft permit for use of deep disposal well for permanent disposal of treated raffinate, in ref to application for amend to License SUR-1010 SHELLEY, W J Kerr-McOes Corp 82/08/26 PAOE, R G Uranium Fuel Licensing Branch 6pp 15814 349
- 8210260576 Forwards initial comments on DK State Dept of Health draft permit for use of deep disposal well & replacement Page 1 to permit correcting nitrogen limit Page should be inserted into 820826 version SHELLEY, W. J. Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.) 82/08/31 PAGE, R. & Uranium Fuel Licensing Branch. 3pp. 13814 361
- 82102204B7 Responds to 820824 itr outlining addit requirements for injection well permit Requests option to operate well at pressures agual to pump capacity of 400 psi Const methods & map of proposed monitoring location encl SHELLEY.W J. Kerr-McGee Nuclear Corp 82/09/17 HENSCH.D A Offician State of 7pp 15786-325

- 8210270242 Forwards application for renewal of License SUB-1010 Renewal fee encl SHELLEY, H J Kerr-McGee Corp 82/09/24 PAGE, R G Uranium Fuel Licensing Branch Jpp 15849 175
- --B210270247 Application for renewal of License SUB-1010 to refine U from yellowcake to convert U to pure U herafilmoride Trity-five eversits drawings end! Aperture cards available in PDR SHELLEY, U J Kerr-HcGee Corp 82/09/24 328pp 15849 178

#### DOCKET 40-8084 RID ALGOM CORP , MOAB, UT

8210210515 Reviews two const repts for 15-ft embankment raise in Rio Algom Corp lower tailings dam performed by Dames & Moore & Region 4 No further action required by licenses MODLSEY, IT , PETTEMOLLA, J Uranium Recovery Licensing Branch 82/09/30 Uranium Recovery Licensing Branch 4pp 15782 307

#### DOCKET 40-8102 EXXON CO USA, HOUSTON, TX

- 8210270195 Forwards "Environ Monitoring Data for Second Guarter, 1982."
  pursuant to License Condition 36, including close evaluation
  at nearest residence & results of environ monitoring
  program
  YARNICK.T P Erron Nuclear Co . Inc (subs of Exxon Corp.)
  82/09/02 PETTENGILL.H J Uranium Recovery Licensing Branch ip
  19835-349
- --8210270197 "Environ Monatoring Data for Second Guarter: 1782 "
  \* Erron Nuclear Co : Inc. (subs. of Erron Corp.) 82/09/08
  14pp 15835 350
- 8210260557 Forwards summary of airborne emissions of principal radiomoclides & "Semiamoual ALARA Repti Jan-Jone 1982," pursuant to License Conditions 14 & 35 No liquid effluents discharged to unrestricted areas YARNICK, T.P. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 82/09/03 Uranium Recovery Licensing Branch Spp. 15830-260
- --8210260560 "Semiannual ALARA Rept. Jan-June 1982" # Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 82/09/03 75pg 18830 265
- 82(0120529 Advises that Exton general emergency action plans, submitted w/820526 ltr, are acceptable Condition if to License SUA-1139 should be amended as listed JONES 8 2 , PETIENDILL-H J Uranium Recovery Licensing Branch 82/09/23 Uranium Recovery Licensing Branch 2pp 15672 204
- B210120598 Natifies of issuance of Amend 3 to License SUA-1139, revising License Condition 25 re emergency preparedness SKITH.R D Uranium Recovery Licensing Branch B2/09/23 Exxon Carp 1p 15672 350
- 8210150432 Advises that no addiffees for review of application for Amend 2 to License SVA-1139 required HILLER, N.O. License Fee Management Branch 82/10/07 OILCHRIST, J.E. Exton Corp. ip. 15715-359
- DOCKET 40-8111 KENNECOTT COPPER CORP . SALT LAKE CITY. UT
- 821022066 Advises that NRC closed out license files when license expired in 1976 w/a closeout survey Facility meets NRC criteria for unrestricted use CARRICO, J B Licensing Management Branch 82/10/01 FDLSOM, B Kennscht Co

- --8210220080 Source Matl License SUA-1104 for Kennecott Copper Corp authorizing possession of 2,000 kg U HALARD, J C Atomic Energy Commission 71/12/15 ip 15786 258
- --8210220086 Application for amend to License SVA-1106 licensing plant for storage only of refined product SPEDDEN,H R. Kennecott Copper Corp. 73/11/12 MALARO, J.C. Atomic Energy Commission. 2pp. 15786-259
- --82(0220087 Certificate of disposition of matis mati disposed in compliance w/10CF20 \* Office of Nuclear Material Safety & Safeguards, Director 76/12/17 ip 15786 260
- --8210220072 Confirms recent telcons re unrestricted use of facility Radiation surveys to be performed & results sent to NRC CARRICO.J D. Licensing Management Branch 82/04/01 FOLSOM, D Kennecott Copper Corp. 15pp. 15788

#### DOCKET 40-8153 LEBANON STEEL FOUNDRY, LEBANON, PA

- 8210270370 Application for renewal of Source Matl License SUB-1146authorizing possession of 56 kg U-235.enriched to less than O 4%, for use in area radiation sys ARNOLD.M L Lebanon Stepl Foundry 82/07/23 5pp 15835 001
- DOCKET 40-8355 AMAX SPECIALITY METALS CORP. PARKERSBURG. WV
- 8205240093 Forwards EIA of proposed site stabilization at AMAX, Inc NIKON,W A Uranium Fuel Licensing Branch 82/05/05 KERRIGAN, J AMAX, Inc 1p 15612 022
- --8205240010 Negative declaration re-storage of contaminated soil unlicense PAGE R G Uranium Fuel Licensing Branch 82/05/03 App 15412 023
- --8205240006 EIA supporting proposed site stabilization \* Office of Nuclear Material Safety & Safeguards.Director 82/04/30 90pp 15612 025
- DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO , BROOMFIELD, CO
- B210(B0398 Forwards "Groundwater Restoration Rept for Rocky Mountain Energy-Halliburton-Mono Power Nine Mile Lake R&D in Situ U Project " MEUHANN, M R Rocky Mountain Energy Co 82/08/30 NEUMANN, M R Uranium Recovery Licensing Branch ACKERMAN, W , GARLAHD, B Wijomii State of 2pp 15747 001
- --B2101B0405 "Oroundwater Restoration Rept for Rocky Mountain Energy Halliburton-Mono Power Nine Mile Late R&D In Situ U Project "One oversize map encl Aperture card is available in PDR • Rocky Mountain Energy Co B2/06/21 216pp 15747 004

#### DOCKET 40-8452 BEAR CREEK URANIUM CD , CASPER, WY

- 8210150644 Forwards gradation results for Zone III sandstone in tailings disposal area.in response to 820806 ltr Gradation tests for Zone IV claystone also submitted MEDLOCK, R.L. Bear Creek Uranium Co. 82/08/20 SCARANO, R.A. FEITENGILL, H.J. Uranium Recovery Licensing Branch 10pp 15715-272
- 8210260084 Forwards Self-Bond BCU399-01 to Permit 399 for Bear Creek U Co BRYAN,V J Myoming, State of 82/08/20 FLORY,C Uranium Recovi Licensing Branch 4pp 15814 149
- 8210280446 Forwards self-bond indemnity agreement to Permit 299 for Bear Creek U Mill between State of MY Dept of Environ Quality & Union Pacific Corp Vendor agreed to indemnify any Iiability incurred by Bear Creek BRYAN, V. J. Wyoming. State of 82/08/30 FLORY, C. Uranium Rocove Licensing Branch 5pp 18988 350
- 8210120634 Reviews first quarter 1982 environ monitoring data & dose calculations for Bear Creek U Hill License Conditions 19,49 & 54 estisfied.
  FLORY.C.A., PETTENGILL,H.J. Uranium Recovery Licensing Branch 82/09/20. Uranium Recovery Licensing Branch 5pp 15672 273

ı

#### DACKET 40-8502 MYOMING MINERAL CORP . LAKEWOOD, CO

- E.,10270180 Forwards "Trigaray Mine Site, Bemiannual Activity & Monitoring Rept.Jan-June. 1982" COMON.O W Wyoming Mineral Corp 82/08/25 Region 4, D Director 2pp 15835-332 Donley 4 Office of
- --8210270183 "Irigaray Mine Site, Semiannual Activity & Monitoring Rept, Jan-June, 1982 ### Upoming Mineral Corp #2/08/25 | 14ps | 15835 334
- 8210040338 Discusses ammonia-mitrate relationships applied to groundwater restoration at WY Mineral Corp Irigaray U Solution Mining Project in FES 3 responses to comments on DES LOGSDON,M J., LINEHAN, J. Uranium Recovery Licensing Branch B2709707 Uranium Recovery Licensing Branch 3pp 15597-182
- DOCKET 40-8577 AIR FORCE, DEPT OF, VANDENBERG AFB, CA
- 8210270179 Forwards application for amend to License SUB-1289. 210270174 Forwards application for amend to License Sub-1204, reflecting changes in Western Space A Missile Ctr radiation protection committee A use of TLD instead of film badges BOLLINGER.L J. Air Force, Dept of, Radioisotope Committee LINGER.L J. Air Force, Dept of, Recioise ... Division of Fuel Cycle & Material Safety 4pp 15835 023
- --B210270182 Application for amend to License SUB+1289, reflecting changes in Western Space > Missile Ctr radiation protection committee Personnel resumes encl HEINY, E.L. Air Force, Dept of, Radioisotope Committee 82/09/14 32pp 15835 027
- DOCKET 40-8602 SILVER KING MINES, INC., CASPER, WY
- 62:0250054 Forwards "Preoperational Radiological Environ Monitoring Rept. Jan-June 1982" WDLFF.C E Silver King Mining, Inc. 82/08/27 SCARAND, R A Utanium Recovery Licensing Branch 3pp. 15808 016
- ~-8210250056 "Preoperational Radiological Environ Monitoring Rept. Jan-June, 1982 " \* Silver King Mining, Inc. 82/08/27 109pp 15808 019
- 8210270048 Forwards three warranty doeds per 820810 telcon All deeds to be assigned to Silver King Mine. Inc. as trustee for TVA Deeds fulfill land ownership requirements MDLFF.CE Silver King Mining. Inc. 82/08/20 PANTELL, S. Division of Fuel Cycle & Material Safety 16pp 15836-086
- DOCKET 40-8610 STEPAN CHEMICAL CO , MAYWOOD, NJ
- 8210260341 Forwards QA Program Inso Rept 99990001/82-13 pp 820923 Ng noncompliance noted

  KJNNEMAN, JD Region 1. Office of Director, 82/10/22 FIORE,R A
  Maywood, JJ FIORE,R A Fiore & Jaskot 2pp 15803 033
- --8210260345 GA Program Insp Rept 99970001/82-13 on 820923 No noncompliance moted Major areas inspected measurement of nonconpliance moved hajor areas inspected measurement of radiation levels & gathering of sediment samples in & along Coles Brook, Maywood, NJ JOHANSEN, J. XINNEMAN, J. D. Region 1. Office of Director 82/10/21 6pp 15803-035
- --0210260352 Requests info on whether proposed stream clearance project grocousok requests into on whether proposed stream clearance would create hazard re ladioactive contamination in vicinity of brook Sketches encl FIGRE.R A Fibre & Jaskot 82/07 KINNEMAN, J D Region 1, Office of Director COSOLITO, F N Jersey, State of App 19803-041
- DOCKET 40-8492 ARMY, DEPT OF, CHAMBERSBURG, PA
- 8210270222 Forwards application to amend License SUC-1980 to allow std2/d222 roruges septication to amend License BUC-13BU to all staballuy to be used interchangeably w/depleted U when referring to U alloys TARAS,D N Army, Dept of, Headquarters Material Development & Readiness Command 82/08/27 Division of Fuel Cycle & Mates Readiness Command 82/0 Safety 1p 15836 043 Division of Fuel Cycle & Material

- --8210270227 Application for amend to License SUC-1380 to allow staballoy to be used interchangeably w/depleted U when referring to U alloys SMITHLE E Army. Dept of Headquarters Materiel Development & Readiness Command 82/08/20 Division of Fuel Cycle & Mater Division of Fuel Cucle & Material Safety 2pp 15834 044
- DOCKET 40-8481 ENERGY FUELS NUCLEAR, INC., DENVER, CO.
- 8210220516 Submits questions re Amend B.Condition 18 to License SUA-1358 Rewording of composition of internal audit committee suggested to allow for reorganization DAKER, C E Energy Fuels Nuclear, Inc 82/08/20 GILLEN, D Recovery Licensing Branch 2pp 15786 086 82/08/20 GILLEN.D Uranium
- 8210250034 Application for amend to License SUA-1358 revising representation on internal audit committee & recipient of representation on internal audit committee & recipient of semiannual ALARA audits
  BAKER.C E Energy Fuels Nuclear, Inc. 82/08/20 GILLEN,D Uranium Recovery Licensing Branch 2pp 15808 347
- 8210250006 Forwards "Effluent & Monitoring Rept.Apr-June 1782"
  BAKER: C E Energy Fuels Nuclear, Inc. 82/08/27 GILLEN, D Uranium
  Recovery Licensing Branch 1p 15808 135
- --8210250008 "Effluent & Monitoring Rept. Apr-June 1982 "
  \* Energy Fuels Nuclear, inc 82/08/27 45pp 158 15909 136
- 8210240017 Forwards "Semiannual ALARA Audit Rept for Energy Fuels riogabol/ rorwards "Semiannual Alaka Audit K Nuclear, Inc White Mesa V Mill Blanding, UT " BAKER.C E Energy Fuels Nuclear, Inc 82/ Energy Fuels Nuclear, Inc 1p 15814 305 82/08/31 VINCELETTE, M D
- --8210260018 "Semiannual ALARA Audit Rept for Energy Fuels Nuclear Inc White Mesa U Mill.Blanding.UT " \* Energy Fuels Nuclear, Inc 82/08/31 11pp 15814 306
- B21026022 Application for amend to License SUA-1358, authorizing discharge of tailings into Cell 3 prior to completion of const of Cell 4 safety dike Progressive const of safety dike will contain vol of potential spill BAKER CE Energy Fuels Nuclear, Inc. 82/09/02 GILLEN, D. Uranium Recovery Licensing Branch. 3pp. 15814-318
- 8210270209 Advises that schedule for initiation of const on Cell 3 safety dike at White Mesa will be delayed 1 wk beyond date set forth in 820408 ltr Completion of safety dike may be dalayed until Spring 1983
  BAKER C E Energy Fuels Nuclear, Inc 82/09/03 GILLEN, D Uranium
  Recovery Licensing Branch 1p 15836 034
- 8210270435 Forwards "Tailings Cover Design Revision" in response to NRC 820812 request for info re application for amend to License 8UA-1358 Proposed reduction in thickness of tailings License Bun-1338 Proposed reduction in this reclamation cover adequate BAKER.C E Energy Fuels Nuclear, Inc. 82, Recovery Licensing Branch (p. 15833-001 82/09/03 GILLEN D. Uranium
- --8210270439 "Tailings Cover Design Revision "
  \* D'Appolonia Consulting Engineers, Inc 82/08/28 55pp
- 8210040363 Notification of 820913 meeting w/Energy Fuels Nuclear in Silver Spring. MD to discuss White Mesa Facility reclamation plan, associated costs & proposed surety arrangements GILLEN.DM Uranium Recovery Licensing Branch 82/09/09 LINEHAN.JJ, PETTENGILL, HJ, FLENING, T.E NRC No Detailed Affiliation Given 2pp 15597 191
- 8210120641 Recommends no action be taken on licensee request for 210120641 Recommends no action be taken on licensee request for hearing on license amend to require surety for decommissioning & reclamation Issue may be mooted by licensee submittal of revised reclamation plan LINEHAN, J. Uranium Recovery Licensing Branch 82/09/17 KLUCSIK, J.F. Office of the Ceneral Counsel ip 15672 278
- 8210210532 Issues Amend 15 to License SUA-1358, in response to 820902 request Amend adds Item 9 to License Condition 26 allowing licensee to forego const of Cell 3 safety dike SMITH.R D. Urenium Recovery Licensing Branch 82/09/30 Energy Fuels Nuclear, Inc. Ip 15782 325 Energy
- --8210210534 Recommends issuance of Amend i5 to License 8UA-1358, in response to 820902 request Amend adds Item g to License Condition 26 allowing licensee to forego const of Cell 3 safety dike GILLEN,D M Uranium Recovery Licensing Branch 02/ Uranium Recovery Licensing Dranch 2pp 15782 326.

#### DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO , DENVER, CD

- 821028045; Advises that differences identified in two lab finding for potassium values due to different lab procedures or lab capabilities Differences in pH values due to NML reporting field values
  SCHHITTDIEL.P Myoming, State of 82/04/27 Myoming, State of 4pp 15858 346
- 8210250043 Forwards corrected rept for radionuclide concentrations in Pattern 2 injection & production wells from 820401 stabilization samples for, "Reno Creek Pattern 2 Restoration Rept Addendum " Recky Mountain Energy Co 82/09/09 KALMAN, K Uranium Recovery Licensing Branch 2pp 15788 348
- 8210040344 Discusses review of Rocky Mountain Energy 1982 second quarterly rept for Reno Creek Bite No followup actions necessary KALHANIX L. LINEHANIJ J. Uranium Recovery Licensing Branch 82/09/10 Uranium Recovery Licensing Branch 2pp 15597 185
- DOCKET 40-9498 PLATEAU RESOURCES, LTD , GRAND JUNCTION, CO
- 3210260019 Confirms 820820 conversation re temporary suspension of production at Shootaring Canyon U processing facility Velloucake in sys presently being recovered Plant will resume milling & mining by late 1988 CERDEMAN.F H Plateau Resources. Ltd 82/08/24 FLEMINO.T NRC No Detailed Affiliation Given lp 15614 317
- MCKET 40-8714 CLEVELAND-CLIFFS IRON CD . CLEVELAND, DH
- 3210220515 Notifies that Cleveland Cliffs surface discharge operation monitoring program complies w/requirements of NPDES Permit WY-0030783 No further action required PBHLE.J A . LINEMAN.J J Uranium Recovery Licensing Branch 82/06/03 Uranium Recovery Licensing Branch ip 15786 088
- 3210220036 Advises that License SUA-1352 amended to revise License Condition 10 re authorized use of expanded ion exchange resin SCARANO,R A Uranium Recovery Licensing Branch 82/03/30 LGUDERBACK,T E Cleveland-Cliffs Iron Co 2pp 15786 281.
- MOCKET 40-8728 TETON EXPLORATION DRILLING CO . INC . CASPER. WY
- 2210280412 Forwards State of MY Dept of Environ Quality, Land Quality Div 820519 itr accepting groundwater stabilization in N zone aquifer & advising of plugging of zone wells APPEL-R R Teton Exploration Drilling Co , Inc 82/08/23 ROSS, F W NRC - No Detailed Affiliation Given 3pp 15859 336
- 1210120494 Advises that proposed in-plant radiation safety program acceptable w/listed exceptions, Conditions 25 & 30 of License SUA-1373 should be revised as stated SULLENBERGER, D., PETTENOILL, H.J. Uranium Recovery Licensing Branch 82/09/16 RDB9, F.W. Uranium Recovery Licensing Branch 6pp 18473 644

- B210260577 Objects to conditions on commencement of mining in Unit 2 Collection of baseline water quality data in Unit 3 prior to mining unnecessary to insure environ protection of groundwater CATCHPOLE.0 J Ogle Petroleum, Inc B2/09/02 FRANCIS.E Wyoming, State of 2pp 15830 139
- 821012059; Requests that second aquirer pump test be performed prior to licensing injection of lixiviant into Mining Unit 2 are zone to evaluate confining nature of lower claystone layer Previous test inadequate
  LINEHAN, J J Uranium Recovery Licensing Dranch 82/09/10 Ogle
  Petroleum, Inc. ip 156/2-35;
- --8210120604 Responds to request to analyze Mine Unit 2 pump test & associated data Use of ratio method to determine vertical hydraulic conductivity of lower aquitard invalid WILLIAMS.R E Williams-Robinette & Associates, Inc. 82/09/10 Williams-Robinette & Associates, Inc. 8pp. 15672-352
- 8210280046 Forwards in-plant radon concentrations table for first half of 1982, per NRC request SAUNDERS.O A Ogio Petroleum, Inc 82/09/10 SMITH.D Uranium Recovery Licensing Dranch ip 15863 004
- --8210280049 "Radon Oas Concentration in uCi/ml." Jan-June 1982 4 Ogle Petroleum, Inc. 82/09/10 ip 15863-005
- DDCMET 40-8768 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, DK
- 8210040365 Discusses review of Kerr-McGee G-Band Project quarterly rept for Jan-Mar 1982 To date no serious events identified which necessitate change of operations or shutdown WESTBROOK K B , LINEMAN J J Uranium Recovery Licensing Branch 82/09/07 Uranium Recovery Licensing Branch 4pp 18597 193
- DOCKET 40-8771 MELAPAI RESOURCES CO . PHOENIX. AZ
- 8210120536 Advises that no violation found during NRC 820406-07 preoperational safety insp FLEMIKO, T.E., MARTIN, D.E. Uranium Recovery Licensing Branch 82/09/22 Uranium Recovery Licensing Branch ip 15672 216
- DBCKET 40-878: TETON EXPLORATION DRILLING CD . INC . CASPER, WY
- 8210270066 Expresses appreciation for opportunity to review & comment on DES for Teton Exploration Drilling Project Document adequate re compatibility w/local & regional comprehensive planning MATUSCHECK, R. J. Housing & Urban Development, Dept of 82/08/02 SCARANO, R. A. Uranium Recovery Licensing Branch 1p 15836-127
- 8210250032 Comments on application process to date Use of environ rept for NRC purposes similar to State of MY format will save considerable preparation time APPEL,R R United Nuclear Corp 82/08/23 SCARAND,R A Uranium Recovery Licensing Branch 2pp 15808 345
- 8210260096 Forwards state agency comments on project DES Encl analyses support issuance of combined source & hyproduct matl licenses subj to specific licensing conditions of other local state & faderal stds & regulations HERSCHLERIE Woming State of 82708/26 SCARANOR A Uranium Recovery Licensing Branch 9pp 15810 330
- --8210260099 Comments on DES Sentence that mobile fire units are maintained by Converse County Rural Fire Control Assoc should be added to Page 3-20 LUNDELL B.E Hyoning, State of 82/07/19 Uranium Recovery Licensing Branch 1p 15810 339
- 8210180619 Forwards safety evaluation supporting issuance of License SUA-1403 for commercial in situ leach U mine & recovery plant WDOLSEY,R.T. PETTENGILL: H.J. Uranium Recovery Licensing Branch 82/09/20 Uranium Recovery Licensing Branch ip, 15672 238
- --8210120624 Safety evaluation supporting issuance of License SUA-1403 for commercial in situ leach U mine & recovery plant. MODLSEY,R T, PETTENDILL,H J Uranium Recovery Licensing Branch 82/09/20 22pp. 15672-239

#### DUCKEY 40-8786 URANIUM RESOURCES, INC , RICHARDSON, TX

- G2101B0356 Forwards response to NRC 820723 ltr re malfunctioning flow meters, radiological environ monitoring & as-built pond specs One oversise map encl Aperture Card is available in PDR PELIZZA, M.S. Uranium Resources, Inc. 82/08/12 LINEHAN, J. J. Uranium Recovery Licunsing Branch 3pp 15747-352
- --P210180359 'Pond Soil Analysis "
  \* Affiliation Unknown 82/02/22 2pp 15747 357
- 8210250013 "North Platte Project Guarterly Rept. 820415-0715 "

  \* Uranium Resources, Inc. 82/08/23 68pp 15808 183
- 8210120479 Approves licensee restoration of R&D wellfield using combination groundwater sweep & reinjection of reverse osmosis treated water Helis will be restored to proper levels at end of restoration HESTROUGH B. LINEHAN.J. Uranium Recovery Licensing Branch 62/09/17 Uranium Recovery Licensing Branch 2pp 15672-05.

#### DOCKET 40-8793 CONDCO. INC , DENVER, CO

- 82:10040348 Discusses COMOCO. Inc request for withdrawal of Ruby Ranch In Situ U Project application Option of withdrawing application granted YOUNG, Y A . LINEHAN, J Uranium Recovery Licensing Branch 82/09/10 Uranium Recovery Licensing Branch 4pp 15597 187
- DUCKET 40-8920 AMAX ENVIRONMENTAL SERVICES, INC., GOLDEN, CD
- 6210250035 Advises that radioactive contaminated soil removed from adjacent property owned by Chiyoda Steel Corp Authorization by Chiyoda to enter property & remove soil encl KEPPLER:P AMAX. Inc. 82/08/31 NIXON,W NRC No Detailed Arfiliation Given 3pp 15808 349
- DUCKET 40-8924 TARGET RESEARCH, [NC., WHARTON, NJ
- 8210270373 Forwards application for source matl license, authorizing pussession of 6,000 kg U alloy, enriched to 99 8% U-238, for use in assembling armor-piercing projectiles DAKUM, K E Target Research, Inc. 82/09/15 Division of Fuel Cycle & Material Safety ip 15835 220
- --8210270376 Application for license to possess 6,000 kg depleted U allow, enriched to 99 8% U-238, for use in assembling ammor-piercing projectiles GUADAGNO, V Targot Research, Inc. 82/09/14 17pp 15835 221

#### DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

- DOCKET 50-3 INDIAN POINT STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8210280148 Releases public version of revised emergency plan implementing procedures FELTOR: J H Division of Rules and Records 82/10/12 Document Management Branch 1p 15862 271 24X Fiche 50-003.82/10/12. 8210280148
- --8210280154 Forwards public version of revisions to Emergency Plan Implementing Procedures IP-1020 re airborne radioiodine determination & IP-1046 re util personnel responsibilities during Unit 3 emergencies
  O'TOOLE.J D Consolidated Edison Co of New York 82/10/01
  HAYNES.R C Region 1, Office of Director 3pp 15862 272 24X
  Fische 50-003,82/10/12,8210280148
- --8210280159 Public version of revisions to Emergancy Plan Implementing Procedures IP-1020 re airborns radioiddins determination & IP-1046 re util personnel responsibilities during Unit 3 emergencies

  \* Consolidated Edison Co of New York 82/09/01 16pp 15862 275 24X Fiche 50-003, 82/10/(2:8210280148

- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8207180077 Forwards comments on PRA study dealing w/seismic hazard Validity of conclusions rest on quality of primary data bases & assumptions in both studies Repts are not valid risk assessments due to data base limitations POMEROY.P W Rondout Associates POMEROY.P W ACRS Advisory Committee on Reactor Safeguards 82/08/24 OKRENT, D ACRS Advisory Committee on Reactor Safeguards 7pp 15876 001 24X Fiche 50~003.82/08/24, BOY180077
- P Operating license stage documents & correspondence
- B009080466 Forwards response to B00820 request for status rept re
  Zion/Indian Point task action plan Responsibilities are in
  area of severe accident mitigation features & not in interim
  operational actions portion
  MEYER.J F Reactor Systems Branch B0/08/25 NDVAK,T M Assistant
  Director for Operating Reactors 2pp 03484 009 24X
  Fiche 50-003.80/08/25,8009080466
- B010210036 Discusses SEP Branch review of sys environ qualification of safety-related electrical equipment for 11 SEP plants MCKENNALE M Systematic Evaluation Program Branch B0/07/30 LAINAB.0 C Division of Licensing 2pp 03647 287 24X Fiche 50-003.80/07/30.8010210036
- 8210120103 Add1 response to FOIA request for nine categories of records generated by present NRC Commissioners.primarily Chairman Palladino & Commissioner Roberts & White House Forwards App B documents FELTON.J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 3pp 15670 117 24X Fiche 50-000,82/07/12,6210120103
- --8210120188 Notifies that facility will be decommmissioned by util rather than make ECCS mods to meet NRC criteria Util proposed research funding cannot be provided Recommends approval of proposed itr to util ZECH.0 NRC No Detailed Affiliation Civen 81/11/05 ROBERTS.T M Commissioners 1p 15690 160 24X Fiche 50-000,82/07/12.8210120103
- 8210010401 Forwards application to amend Licenses DPR-26 & DPR-5, changing Tech Specs re facility organization & Unit 2 Tech Specs 3 6 & 4 for a containment isolation valves 3 12 & 4 12 in pipe lines Class I.II & III fees enc! O'TOOLE.ID Consolidated Edison Co of New York 82/08/31 VARGA.B A Operating Reactors Branch 1 3pp 15572 211 24X Fiche 50-003,82/08/31,8210010401
- --B210010409 Application to amend Licenses DPR-26 & DPR-5, revising Tech Spec Figures 3 2 & 6 2-2 re facility organization for Units i & 2, respectively O'TOOLE.J D Consolidated Edison Co of New York 82/08/31 2pp 15572 214 24X Fiche 50-003.82/08/31.8210010401
- --8210010414 Proposed revisions to Tech Spec Figures 3 2 & 6 2-2, reflecting change in Organizational structure to include position of operations superintendent Safety assessment encl \* Consolidated Edison Co of New York 82/08/31 6pp 15572 216 24% Fiche 50-003.82/08/31.8210010401
- --8210010425 Application to amend License DPR-26, revising Tech Specs 3 & & 4 to establish requirements for action required when containment isolation valves are inoperable & reflect changes to isolation valve provisions
  0/TDOLE, J D Consolidated Edison Co of New York 82/08/31 2pp 15572 222 24X Fiche 50-003.82/08/31.8210010401
- ---8210010438 Proposed revisions to Tech Specs 3 6 & 4 4 establishing specific requirements for action during inoperability of containment isolation valves & reflecting changes & additions to isolation valve provisions Safety assessment encl \* Consolidated Edison Co of New York 82/08/31 20pp 15572 224 24X Fiche 50-003 82/08/31,8210010401
- --B210010443 Application to amend License DPR-26, revising Tech Spac Sections 3 12 & 4 12 to defflect editorial change safety-related pipe lines & to efflect editorial change 0/100(E.J D Consolidated Edison Co of New York 82/08/31. 2pp 15572 244 24X Fiche 50-003.82/08/31.8210010401
- --8210010449 Proposed revisions to Tech Spec Sections 3 12 & 4 12, reflecting redesigned support sys for safety-related pips lines & to effect editorial change Safety assessment encl.

  \* Consolidated Edison Co of New York 82/08/31 18pp 13572 246 24X Fiche 50-003, 82/08/31, 8210010401

- à Inspection reports, IE Bulletins & correspondence
- BZCB19023J IE Info Notice 80~35, Suppl 1, "Leaking & Distodged I~125 Inplant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards E2/10/06 Consolidated Edison Co of New York & App 15761 250 24( Fiche 50~000.82/10/06.8208190233
- 82LB(90238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall.Large-Diameter. Stainless Steel. Recirculation Sys Piping at OMF Plants " Svo list end DEYGUND.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 123pp (5810-125 24X Fiche 50-000.82/10/14.8208190238
- DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 0209290125 Releases public version of revised generating station anergency plan corporate command ctr emergency plan replementing procedure FELTON.J M Division of Rules and Records 82/09/16 Document Management Branch ip 15564 122 24X Fiche 50-000.82/09/16. 8209290125
- --B209290225 Public version of Revision 4 to generating station energency plan componate command ctr emergency plan implementing Procedure EUF-3. "Environ/Rergency Coordinator"
  PAJCHSKI.J E., LITERSKI.L A., FLEBSNEK.S A. Commonwealth Edison Co. B2/08/31 tipp 15564 124 24X Fiche 50-000,82/09/16.
- 8210130376 Advises that installation of offsite dose calculation sysprogram fully operational tracking model to operational A-model will be delayed until 821231 to complete prima computer installation
  SMARTZ.E D Commonwealth Edison Co 82/10/06 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15682 098 24X
  Fiche 50-000, 82/10/06-8210130376
- S210290047 Releases public version of revisions to Quad Cities, Zion & Dresdan emergency plan anneres & revised generating statum emergency plan to lephone directory FELTON, J M Division of Rules and Records 82/10/08 Document Management Branch 1p 15877 313 24X Fiche 50-000,82/10/08, 82/0270047
- --8210290060 Forwards public version of Revision 3 to Quad Cities & Zion emergency plan annexes. Revision 2 to Dresden emergency plan annex. Revision 0 to Buron semergency plan annex & revised generating station emergency plan telephone directory MODRE.R D Commonwealth Edison Co 82/07/30 DENTON, H R NRC No Detailed Affiliation Civen Spp 15877 314 24X
  Fich# 50-000,82/10/08.8210290047
- --8210290077 Public version of Revision 3 to Guad Cities & Zion emergency plan annexes. Revision 2 to Dresden emergency plan annex & Revision 0 to Syron emergency plan annex > Commonwealth Edison Co 82/06/30 102pp 19877 319 24X Fiche 50-000, 82/10/08. 8210290047
- --821029008B Public version of revised generating station emergency plan telephone directory GALLED P Commonwealth Edison Co 82/08/12 43pp 15878 218 24X Fiche 50-000,82/10/08/8210290047
- 8210220358 Provides info re organisation & performance of depts responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs TRAMM. TR Commonwealth Edison Co. 82/10/14 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 9pp 15776-287 24X Fiche 50-000, 82/10/14.8210220358
- 8210250170 Advises that plans & preparedness for offsite protection near facility adequate & will be applied in event of radiological emergency IL State & local plans approved subjeto verification of adequacy of alerting & notification system (HOMABL.) Hederal Emergency Management Agency 82/10/14 b187088.9 J dries of the Executive Director for Operations ip 18788:285 24% Fiche 50-010-82/10/14-8210250170

- P Operating license stage documents & correspondence
- 9210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" GULDEN, J.C. Commonwealth Edison Co. 82/10/04 CASE, E.G. Office of Nuclear Reactor Regulation. Director 2pp 15805 137 24X Fiche 50-000, 82/10/04, 8210260526
- --B210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual"
  - namusi 4 Commonwealth Edison Co 82/09/30 83pp 15805 139 24x Fishe 50-000, 82/10/06, 8210260526
- 8210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820707 ltr Staff encouraged to develop & implement means to incorporate pasitive attributes of Phase III in licensee/NRC interface RACICH, RM SEP Dumers Group KACICH, RM Northeast Nuclear Energy Ca (subs of Northeast Utilities) 82/10/07 EISENHUT, D G Division of Licensing 7pp 15682 177 24X Fiche 50-000, 82/10/07, 8210130326
- 8210180195 Forwards "Final Status Rept in Preparation for Chemical Cleaning of Dresden 1." Sept 1982
  RAUSCH.T J Commonwealth Edison Co 82/10/12 EISENHUT.D Q
  Division of Licensing 1p (5749 135 24X Fiche 50-010.82/10/12.8210180196
- --8210180197 "Final Status Rept in Preparation for Chemical Cleaning Deesden 1." Sept 1981 Aperture cards available in PDR \* Dow Chemical Co DNS-D1-034 81/09/30 582pp 15749 [ 14 24X Fiche 50-010.82/10/12.8210180196
- O Inspection reports. IE Bulletins & correspondence
- 8210060329 Forwards IE Insp Repts 50-010/82-02.50-237/82-03 & 50-249/82-03 on 820119-0218 No noncompliance noted LITLE, W 5 Division of Engineering & Technical Programs REED, C Commonwealth Edison Co 2pp 15615-331 24X Fishe 50-010.82/09/22.8210060329
- --8210060335 IE Insp Repts 50-010/82-02,50-237/82-03 & 50-249/82-03 o 82019-0218 No noncompliance noted Major areas inspected open & unresolved items & items of noncompliance reintegrated leak rate test REIMANN,F W Region 3. Office of Director JACKIH, I N Division of Engineering & Technical Programs 82/09/21 7pp 15415 37th 24X Fiche 50-010.82/09/22.8210060329
- 8210150523 Forwards IE Insp Repts 50-010/82-13.50-237/82-17 & 50-249/82-18 on 820708-0809 & natice of violation STREETER. J F Division of Project & Resident Programs 82/09/28 REED. C Commonwealth Edison Co. 2pp 15713 099 24X Fiche 50-010.82/09/28.8210150523
- --B210150530 Notice of violation from insp on 82070B-0809 STREETER, J. F. Division of Project & Resident Programs 82/09/20 1p 15713 101 24% Fiche 50-010.82/09/28.8210150523
- -B210150533 IE Insp Repts 50-010/B2-13,50-237/82-17 & 50-249/82-18 or 820708-0809 Noncompliance noted failure to issue & perform air pressure test procedure TONGUE.T H. JORDAN H J. WALKER,R D. Division of Project & Resident Programs 82/09/28 Bpp 19713 102 24X Fiche 50-010,82/09/28,8210150523
- 8210150539 Forwards IE Insp Repts 50-010/82-15,50-297/82-19 & 50-249/82-20 on 820830-0903 No noncompliance noted PAPERIELLO.C J Division of Emergency Preparedness & Operational Support 82/10/01 REED.C Commonwealth Edison Co 2pp 15714 175 24X Fiche 50-010,82/10/01,8210150539
- --8210150543 IE Insp Repts 50-010/82-15, 50-237/82-19 & 50-249/82-20 or BZ0830-0903 & 09 No noncompliance noted Major areas inspected confirmatory measurements program, GC program for analytical measurements & environ monitoring program SCHUMACHER, M.C., NICHOLSON, N.A., JANUSKA, A.G. DIVISION of Emergency Preparedness & Operational Support 82/09/30 7pp 15714 177 24X Fiche 50-010, 82/10/01, 8210150539
- 8208170233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 157.61 250 24X Fiche 50-000, 82/10/06, 8208170233

- 82/08190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall-Large-Diameter: Stainless Steel-Recirculation Sys Piping at BMR Plants " Svs list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 123pp 15810 125 24% Fichs 50-000.82/10/14.8208190238
- R Periodic operating reports & related correspondence
- 82:10180097 Forwards monthly operating repts for Sept 1982 SCOTT-D J Commonwealth Edison Co 82/10/01 Director's Office, Office of Inspection and Enforcement 1p 15718 001 24X Fiche 50-010: 82/10/01:8210180097
- --8210180100 Monthly operating repts for Sept 1982 SCHROEDER.8 A Commonwealth Edison Co 82/10/01 22pp 15718 002 24X Fiche 50-010, 82101610097
- DOCKET 50-13 BABCOCK & HILCOX CO CRITICAL FACILITY

  F Security, medical, energency & fire protection plans
- 8210210194 Forwards IE Safeguards Insp Repts 50-013/82-03 & 70-0824/82-10 on 820930-1001 No noncompliance noted GlBSON.A F Division of Engineering & Technical Programs 82/10/15 ENGELDER.T C Babcack & Wilcox Co 2pp 15765 304 24X Fichs 50-013.82/10/15.8210210194
- --0210210206 IE Safeguards Insp Repts 50-013/82-03 & 70-0824/82-10 on 820930-1001 No noncompliance noted Major areas inspected physical protection of low enriched SNM Details withheld (ref 100FR2 790) GODE.R · MCGUIRE.D R Division of Engineering & Technical Programs 82/10/15 ip 19765 306 24X Fichs 50-013,82/10/15,8210210194
- P Operating license stage documents & correspondence
- 8210040214 Details evaluation of discrepancy between electronically simulated reactor & channel periods revealed in calibr test performed on Log-N-2 channel No unsafe condition existed & no Tech Spec violation occurred OLSEN.AF Consolidation Coal Co 82/09/27 Standardization & Special Projects Branch 3pp 19583 120 24X Fiche 50-013, 82/09/27.8210040214
- Q Inspection reports, IE Bulletins & correspondence
- 82:02:0194 Forwards IE Safeguards Insp Repts 50-013/82-03 & 70-0824/82-10 on 820930-1001 No noncompliance noted, GIBSON, A F Division of Engineering & Technical Programs 82/10/15 ENGELDER, T C Babcock & Wilcox Co 2pp 15765 304 24X Fiche 50-013,82/10/15,8210210194
- --0210210206 IE Safeguards Insp Repts 50-013/82-03 & 70-0824/82-10 on 820930-1001 No noncompliance noted Major areas inspected physical protection of low enriched SNM Details withheld (ref 10CFR2 790) GODDE,R MCGUIRE,D R Division of Engineering & Technical Programs 82/10/15 1p 15765 306 24X Fichs 50-013,82/10/15, 8210210194
- DOCKET 50-20 MASSACHUSETTS INST OF TECH RES REACTOR

  F Security, medical, emergency & fire protection plans
- 9210170334 Forwards Revision 27 to SAR for MIT research reactor, arfecting physical security plan SAR withheld (ref 10CFR2 790)
  CLARK-L Massachusetts Institute of Technology 82/10/13
  TEDESCO.R L Assistant Director for Licensing 1p 15742 125 24X
  Fiche 50-020, 82/10/13, 8210170334
- DOCKET 50-22 WESTINGHOUSE TEST REACTOR
- O Inspection reports, IE Bulletins & correspondence
- 8210130420 Forwards "Annual Insp of Retired Westinghouse Testing Reactor per License TR-2 for 1982 " MARDIA J Westinghouse Electric Corp 82/09/30 Stendardization & Special Projects Branch ip 15680 264 24X Fiche 50-022,82/09/30,8210130420
- ---8210130426 "Annual Insp of Retired Westinghouse Testing Reactor per License TR-2 for 1982" \* Westinghouse Electric Corp 82/09/16 3pp 15680.265. 24X Fiche 50-022,82/09/30.8210130420

- R Periodic operating reports & related correspondence
- 8210130420 Forwards "Annual Insp of Retired Westinghouse Testing Reactor per License TR-2 for 1982 " NARDIA J Westinghouse Electric Corp 82/09/30 Standardization & Special Projects Branch ip 15680 264 24X Fiche 50-022,82/09/30.8210130420
- --8210130426 "Annual Insp of Retired Wastinghouse Testing Reactor per License TR-2 for 1982 " # Westinghouse Electric Corp 82/09/16 3pp 15680 265 24X Fiche 50-022,82/09/30,8210130420
- DOCKET 50-27 HASHINGTON STATE UNIV RESEARCH REACTOR

  Q Inspection reports, IE Bulletins & correspondence
- 8210190632 Forwards IE Insp Rept 50-027/82-02 on B20714-16 & 0810 No noncompliance noted B00K.H E Division of Radiological Bafety & Safeguards Program 82/10/01 WILBON.W E Washington, Univ of 2pp 15740 025 24X Fiche 50-027, 82/10/01, 8210190632
- DOCKET 50-29 YANKEE-ROME NUCLEAR POWER STATION

  F Security, medical, emergency & fire protection plans
- 8210060034 Forwards IE Safeguards Insp Rept 50-027/82-09 on 820802-05 No noncompliance noted MARTIN.T Division of Engineering & Technical Programs 82/09/27 HEIDER.L H Yankse Atomic Electric Co 2pp 15615-051 24X Fiche 50-029, 82/09/27/8210060034
- --B210060049 IE Safaguards Insp Rept 50-029/82-09 on B20802-05 No noncompliance noted Major areas inspected testing & maint records, physical barriers in protected & vital areas & security sys power supply Details withheld (ref 100CR/79 21) DUNLAP, J. M., SMITH, O.C., ODDY, A.T. Division of Engineering & Technical Programs B2/09/29 ip 15615-053 24X Fichs 50-029, 82/09/27, 8210060034
- 8210060306 Ack receipt of 820827 ltr informing NRC of steps taken to implement recommendations nated in IE Emergency Preparedness Appraisal Rept 50-029/81-20 SMITH, 0 H Division of Emergency Preparedness & Operational Support 62/09/27 HEIDER, L H Yanke Atomic Electric Co ip 15619 230 24, Fiche 50-029, 82/09/29, 8210060306
- --B210060310 Responds to NRC 820630 ltr re findings noted in IE Emergency Preparedness Appraisal Rept 50-027/81-20 Corrective actions chemistry personnel placed on radio pager sys to afford earlier notification & response HEIDER, L H Yankee Atomic Electric Co 82/08/27 HAYNEB, R C Region 1, Office of Director. 62pp 15619-231 24% Fiche 50-029,82/09/27.8210060306
- 8210210345 Forwards Amend 73 to License DPR-3 & notice of issuance Amend incorporates guard training & qualification plan, in response to licenses 810410 & 1208 applications CRUTCHFIELD D Operating Reactors Branch 5 82/09/30 KAY, J A Yankee Atomic Electric Co 3pp 15782 352, 24X Fichs 50-029, 82/09/30, 8210210345
- --B210210552 Amend 73 to License DPR-3, requiring implementation of guard training & qualification plan within 60 days & qualification of all security personnel within 2 yes CRUTCHFIELD, D Operating Reactors Branch 5 82/09/30. 5pp 15782-355 24X Fiche 50-029,82/09/30.8210210545
- ---8210210555 Notice of issuance of Amend 73 to License DPR-3 CRUTCHFIELD,D Operating Reactors Branch 5 82/09/30 2pp. 15782 358 24X Fichs 50-029,82/09/30,8210210545
- 8210220153 Ack receipt of 820927 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-029/82-08.
  STAROSTECKI.R. Division of Project & Resident Programs HEIDERL H Vankee Atomic Electric Co ip 15778,090. 24X Fiche 50-027,82710715,8210220153

- --9210220157 Responds to MRC 820901 ltr re violations noted in IE Safeguards (map Rept 50-029/82-08 Corrective actions withheld (ref 10CFR2 790) HEIDER, L H Yankes Atomic Electric Co 82/09/27 HAYNES, R C Region t, Office of Director 2pp 15778 091 24X Fichs 50-029, 82/10/15, 8210220153
  - Operating license stage documents & correspondence
  - 10040397 Requests processing of listed documents re SEP Topic 11-04 E. "Dam Integrity" SHITH:H Operating Reactors Branch 5 82/09/17 Division of Technical Information & Document Control 2pp 15597 226 247 Fiche 50-029, 82/09/17, 8210040399
  - 10040132 Forwards safety evaluation & technical evaluation repts of licensee response to proposed design mods to degraded grid voltage Schedule for response requested within 30 days CRUTCHFIELD. D. Operating Reactors Branch 5 62/09/27 KAY. J A Yankee Atomic Electric Co 2pp 15583 095 24% Fichs 50-029, 82/09/27, 8210040632
  - B210040139 Safety evaluation re degraded grid voltage protection for Class IE sus Design acceptable subj to resolution of listed items

    # Operating Reactors Branch 5 82/09/27 7gp 15583 097 24%
    Fiche 50-029,82/09/27.8210040132
- -8209200475 "Proposed Design Mads & Tech Spec Changes on Grid Voltage Degradation for Yankes Rome Nuclear Power Station," technical swaluation rept SELAN.J C Lawrence Livermore Laboratory FIN A-0250 UCID-19147 82/07/30 NRC - No Detailed Affiliation Given 13pp 15583 104 24% Fiche 58-029,82/09/27,8210040132
- 210120207 Forwards safety evaluation of SEP Topic III-4 C reinternally generated missiles Generation of internal missiles within facility will not prevent safe shutdown GARUSOR Operating Reactors Branch 5 82/09/29 KAY, J A Yankee Atomic Electric Co 28pp. 15652 155 24X Fiche 50-027,82/09/29, 8210120207
- 1210080098 Proposed Change 178 to License DPR-3,adding & deleting containment isolation valves specifying equipment parameters, adding new equipment & recategorizing valves to accommodate mod implementation during refueling outage HEIDER-L H Vankes Atomic Electric Co 82/09/30 Office of Nuclear Reactor Regulation, Director 9pp 15640 244 24% Fichs 50-029,82/09/30,8210080098
- --8210080102 Proposed Tech Spec pages, adding & deteting containment isolation valves, specifying equipment parameters, adding new equipment b recategorizing valves to accommodate mod implementation during refueling outage

  \* Yantee Atomic Electric Co 82/09/30 22pp. 15640 253 24X
  Fiche 50-029, 82/09/30, 8210080098
- B210120245 Forwards safety evaluation & technical evaluation repts of SEP Topics II-3, A, II-3 B, II-3 B i & II-3 C re hydrologic considerations Facility does not meet NRC criteria Deviations will be resolved in integrated safety assessment, CARUSO, R Operating Reactors Branch S B2/09/30 RAY, J. A. Yanke, Atomic Electric Co. Sipp 15651 CO1 24X Fiche 50-029, 82/09/30, B210120245
- --8208100269 "Hydrological Considerations (SEP, II-3 A,B, B 1,C, III-3 B)," technical evaluation rept SHERRER, J Franklin Institute/Franklin Research Center. NRC-03-79-118 TER-05257-426 82/08/06 STALEY, Q NRC No Detailed Affiliation Given Bipp. 15651:032 24X 17.739,82/09/30,8210120245

- ~-8210210552 Amené 73 to License DPR-3, requiring implementation of guard training & qualification plan within 60 days & qualification of all security personnel within 2 yrs CRUTCHFIELD, D Operating Reactors Branch 5 82/09/30 5pp 13782 355 24X Fiche 50-029,82/09/30,8210210545
- --8210210555 Notice of issuance of Amend 73 to License DPR-3 CRUTCHFIELD.D Operating Reactors Branch 5 82/09/30 2pp 15782 358 24% Fiche 50-029,82/09/30.8210210545
- B210070169 Forwards topic difference summary for SEP Topic III-6,
  "Seismic Design Considerations" & updated difference
  summaries for Topics V-10 B.V-11 B.VII-3 & IX-3 re RHR sys
  \$ sys required for safe shutdown
  CARUSO.R Operating Reactors Branch 5 B2/10/01 KAY.J A Yankee
  Atomic Electric Co 7pp 15627 001 24X Fiche 50-029,82/10/01,
  B210070169
- 8210070085 Forwards drart safety evaluations of SEP Topics III-6 re seismic design considerations & SEP III-11 re component integrity Licensee proposal re dedicated hot shutdown sysuall be evaluated during integrated assessment of facility CARUSO.R Operating Reactors Branch 5 82/10/04 KAY.J A Yankee Atomic Electric Co 20pp 15628 331 24X Fiche 50-029.82/10/04, 8210070085
- ---821007009[ "Seigmic Design Bases & Criteria for Yankee Rowe Queerating Station SEP " \* Engineering Decision Analysis Company, Inc. EDAC 175-130 02 DRF 79/01/31 29pp 15628 351 24% Fiche 50-029,82/10/04, 8210070085
- ---8210070094 "SEP.Review of Saismic Re-evaluation Program of Yankee Nuclear Power Station" \* NRC - No Detailed Affiliation Given 82/09/30 85pp 15629 018 24X Fichs 50-029.82/10/04.8210070085
- --9210070099 "Technical Evaluation of Yankee Rows Power Station Seismic Design," Aug 1982 BRIDGES, T L , BUSCH, S L , THOMPSON, T R EG&G, Inc FIN A-6426 EGG-EA-6017 82/09/31 CHENG, T Division of Licensing 253pp 15629 100 24X Fiche 50-029, 82/10/04, 8210070085
- 8210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820707 ltr Staff encouraged to develop & implement means to incorporate positive attributes of Phase III in licensee/NRC interface KACICH.R M SEP Duners Oroup KACICH.R M Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/07 CISENHUT.D O Division of Licensing 7pp 15682 177 24X Fiche 50-000,82/10/07,8210130326
- 8210130401 Concurs W/content of systematic assessment of licensee performance board recommendations, per NRC 820903 ltr. Licensee action on primery vent stack monitor failures should be clarified to show thorough evaluation of LERS KAY. J. Yankee Atomic Electric Co. 82/10/08 STAROSTECKI.R Division of Project & Resident Programs 2pp 15682 070 24X Fiche 50-029, 82/10/08, 8210130401
- 82:0150363 Responds to Generic Ltr 82-12 re plant working hours flant policy re working hours should not be incorporated into Tach Specs due to loss of flexibility KAY. JA Yankee Atomic Electric Co 82/10/08 EISENHUT, D Q Division of Licensing 2pp 15704 305 24X Fiche 50-027, 82/10/00, 82:0150363
- 8210180187 Clarifies 820804 request for add1 info re NUREO-0737.

  Item II B 3, "Post-Accident Sampling Sys" Guidance on meeting NUREO-0737 criteria discussed CRUTCHFIELD D Operating Reactors Branch 5 82/10/08 KAY. J A Yantee Atomic Electric Co 3pp 15719, 130 24X
  Fiche 50-029, 82/10/08, 82/10/080187
- B210210123 Forwards evaluation of SEP Topic III-3 A. "Effects of High Mater Level on Structures," based on 820318 SAR Turbine & svc bidgs: screenwall & pumphouse unprotected from postulated flood condition.

  CARUSO: R Operating Reactors Branch S B2/10/13 KAY. J A Yankee Atomic Electric Co. 7pp 15766 027 24X Fiche 50-027,82/10/13. 8210210123
- B2101906B6 Application to amend License DPR-3, replacing 40 fuel assemblies to refuel for Core XVI operation & inserting cycle dependent parameters in Tech Spece HEIDER, L. H. Yankes Atomic Electric Co. 82/10/15. Office of Nuclear Reactor Regulation, Director 2pp 1973B 165 24X Fiche 50-029,82/10/15,8210190686
- --B210190490 Proposed Yech Spec mod inserting cycls dependent parameter \* Yankes Atomic Electric Co B2/10/15 25pp, 15738 167 24X Fichs 50-029,82/10/15,8210190686,

- 8210C80094 Application to amend App A of License DPR-3.compisting of Proposed Change 179, allowing increase in plant operating elexibility while maintaining sufficient RHR flow to ensure reactor vessel water temp does not exceed 140 F in Mode 6 HEIDER.L H Yankee Atomic Electric Co 92/10/15 Office of Nuclear Reactor Regulation, Director 2pp 15837 185 24X Fiche 50-029, 82/10/15, 8210280074
- --8210280103 Proposed Tech Spec Change 179, allowing increase in plant operating flexibility while maintaining sufficient RHR flow to ensure reactor vessel water temp does not exceed 140 F in Mode 6

  \* Yanke Atomic Electric Co 82/10/15 4pp 15837 187 24X Fiche 50-029, 82/10/15, 8210280094
- O Inspection reports: IE Bulletins & correspondence
- 8210070097 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J H Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50~000, 82/08/10, 8210070007
- --B210070139 Forwards tabulated data on steam generator insp & maint at racilities Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch B2/04/01 VARGA.S Operating Reactors Branch 1 CLARK.R Operating Reactors Branch 1 CLARK.R Operating Reactors Branch 3 STOLZ.J Operating Reactors Branch 4 Spp 15445 131 24% Fiche 50~000, 82/08/10.8210070007
- --8210070172 Forwards info re steam generator integrity & insps at all operating PMRs, per 750320 & 21 requests Details of insps, including defect indications, tube plugging criteria & tubes plugged uill not be provided except for Point Beach 1 GOLLERIX R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY, R Division of Technical Review (NRR-1975 only) 5pp 15645 194 24X Fishe 50-000, 82/08/10, 8210070007
- 8210060034 Forwards IE Safeguards Insp Rept 50-029/82-09 on 820802-05 No noncompliance noted MARTIN T T Division of Engineering & Technical Programs 82/09/2 HEIDER, L H Yankee Atomic Electric Ca 2pp 15615 051 24X Fiche 50-029, 82/09/27, 8210060034
- --8210060049 IE Safeguards Insp Rept 50-029/82-09 on 820802-05 No noncompliance noted Major areas inspected testing & maint records physical barriers in protected & vistal areas & security sys power supply Details withheld (ref 100FR73 21) DUNLAP. J M . SMITH. G C . GDDY. A T Division of Engineering & Technical Programs 82/09/23 lp 15615 053 24X Fiche 50-029, 82/09/27.8210060034
- 8210060306 Ack receipt of 820827 ltr informing NRC of steps taken to implement recommendations noted in IE Emergency Preparedness Appraisal Rept 50-029/81-20 SMITH.0 H Division of Emergency Preparedness & Operational Support 82/09/29 HEIDER,L H Yankee Atomic Electric Co Ip 15619 230 24/ Fiche 50-029.82/09/29.8210060306
- --B210060310 Responds to NRC B20630 ltr re findings noted in IE Emergency Preparedness Appraisal Rept 50-029/81-20 Corrective actions chemistry gersonnal placed on radio pager sys to afford earlier notification & response HEIDER.L H Yankee Atomic Electric Co B2/08/27 HAYNEB.R C Region 1, Uffice of Director 62pp 19617 231 24X Fiche 50-029.82/09/29.8210060306
- 8210120272 Forwards avaluation of util response to SEP Topic III-3 C, "Inservice Insp of Water Control Structures " Present insp program does not conform w/Reg Guide 1 127 & should be modified to incorporate NRC recommendations CARUSO, R Operating Reactors Branch 5 82/10/04 KAY, J A Yanke, Atomic Electric Co 10pp 15651 190 24X Fiche 50-027,82/10/04, 8210120272
- --8207190431 "Hydrological Considerations.Inservice Insp of Water Control Structures (SEP III-3 C). Yankee Rowe Nuclear Power Station, "technical evaluation rept SCHERRER, J Franklin Institute/Franklin Research Center NRC-03-79-118 TER-05257-544 82/07/15 STALEY, G NRC No Detailed Affiliation Given 29pp 15651 200 24X Fiche 50-029,82/10/04/8210120272
- 8208190233 IE Info Notice 80-35, Suppl i, "Leaking & Dislodged I-125 Implant Sweds " Svc list end County of State of County of Swedship of

- 8210130401 Concurs w/content of systematic assessment of licensee performance board recommendations.per NRC 820703 ltr Licensee action on primary vent stack monitor failures should be clarified to show thorough evaluation of LERs KAY. J Yankee Atomic Electric Co 82/10/08 STAROSTECKI.R Division of Project & Resident Programs 2pp 15682 070 24X Fiche 50-029.82/10/08.8210130401
- 8210290147 Forwards IE Insp Rept 50-029/82-10 on 820802-0930 No noncompliance noted STARDSTECKI, R Division of Project & Resident Programs 82/10/08 HEIDERLL H Yanke Atomic Electric Co 2pp 15854 214 24X Fiche 50-029, 82/10/08.8210290147
- --8210290157 IE Insp Rept 50-029/82-10 on 820802-0903 No noncompliance noted Major areas inspected review of plant operation, plant maint observation, plant events, LERs, licensee plant info rept, periodic & special repts & preparation for refueling COLLINGS J., GALLO, R M Division of Project & Resident Programs 82/10/07 16pp 15854 216 24X Fiche 50-029,82/10/08.8210290147
- \$208190238 IE Bulletin \$2-03, "Stress Corrosion Cracking in Thick-Wall. Large-Diameter. Stainless Steel. Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York I15pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- 8210220153 Ack receipt of 820727 itr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-027/82-08

  STAROSTECKI.R Division of Project & Resident Programs 82/10/15

  HEIDERIL H Yankee Atomic Electric Co ip 15778 090 24X
  Fiche 50-027, 82/10/15. 8210220153
- --8210220157 Responds to NRC 820701 ltr re violations noted in IE Safeguards Insp Rept 50-029/82-08 Corrective actions withheld (ref 10CFR2 770) HEIDER,L H Yankee Atomic Electric Co 82/09/27 HAYNES,R C Region 1, Office of Director 2pp 15778 091 24X Fiche 50-029,82/10/15,8210220153
- S Reportable occurrences. LERs & related correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL, R A Critical Mass
- --8109280175 Requests add1 info re loss of offsite power event on 810914, SANDS,8 F Director's Office 81/09/18 CARUSO,R Operating Reactors Branch 5 ip 15730 250 24X Fiche 50-000,82/06/28, 8210010008
- --B210010161 Discusses potential problem re sequoyah reactor pressure nozzle, supplementing B00222 memo Underclad cracks found by use of ultrasonic equipment Addlitems of recent origin discussed Related info encl
  DENTON, HR Office of Nuclear Reactor Regulation, Director B0/02/28 AHEARNEJ Commissioners 9pp 15727 178 24X
  Fiche 50-000, 82/04/28, 8210010008
- 8210130230 Forwards LER 82-025/03L-0 AUTIO,H, A Yankse Atomic Electric Co B2/09/30 HAYNES,R C Region 1, Office of Director 1p 15675 269 24X Fiche 50-029.82/09/30.82/0130230
- --8210130235 LER 82-025/03L-0 on 820831.gas leak developed in weld joining safety valve drain line to valve body on waste gas decay 2 drum safety valve Cause not stated Leaking weld isolated, ground out & rewelded RICE.D A Yanker Atomic Electric Co 82/09/30 Region 1, Office of Director 1p 15675 270 24X Fiche 50-029,82/09/30,8210130230
- 8210130218 Forwards LER 82-027/03L-0 AUTIO.H A Yankee Atomic Electric Co 82/10/01 HAYNEB,R C Region 1, Office of Director 1p 15675 235 24X Fiche 50-029,82/10/01.8210130218
- --8210130225 LER 82-027/03L-O on 820902; while in Mode 1, auxiliary builer room sprinkler sys isolated to stop & repair gasket leak Caused by insufficient gasket contact w/valve\*F8-V-739 Gasket replaced.

  MAY.E L Yankse Atomic Electric Co 82/10/01 Region 1, Office of Director ip 15675 234, 24x Fiche 50-029,82/10/01; 8210130218

- 9210130519 Forwards LER 92-026/03L-0 AUTIO.H A Yantse Atomic Electric Co 92/10/01 RAYNEB,R C Region I. Office of Oirector 1p 15482 361 24X Fiche 50-029, 82/10/01, 92/0130519
- -8210130531 LER 82-026/03L-0 on 820702 while performing surveillance of low main coolant flow sys train A. boop 3, phase C relay failed to drop out when de-energized Caused by abnormal amount of friction between plunger & upper bushing FRENCH.L D Yantee Atomic Electric Co 82/10/01 Region 1. Office of Director 1p 15692 362 24% Fiche 50-029,82/10/01,8210130519
- 12:02:60:109 LER p2-032/017 on 82:1006.positive indication observed during shipping of second cycle fuel assembly 8-578 Analysis shows assembly caused slight increase in reactor coolant activity during Core 15 operation AUTIO.H A Yantee Atomic Electric Co 82/10/07 HAYNES.R C Region 1. Office of Director ip 15799 116 24X Fiche 50-029, 82/10/07, 82:0260109
- 210290267 Part 21 deficiency rept re-potential galling problem between stem & bonnet of 1 25-inch & larger A105 carbon steel & A182-F22 valves supplied Feb 1981-Aug 1982 Valves should be serviced & stem & Ara bonnet replaced 19ABELLE.L D. Conval. Inc. 82/10/11 HAYNES.R C. Region 1, Office of Director 17pp 15854 232 24X Fiche 50-000,82/10/11.
- 210260106 RO 50-29/82-33 on 821009 main coolant pump i vent isolation valve wald discovered slightly moist Weld will be repaired during current refueling outage AUTIO, HAYNES ATOMIC Electric Co 62/10/12 HAYNES R C Region 1. Office of Director ip 15799 119 24X Fache 50-029, 82/10/12,8210260104
- '10260165 Forwards LER 82-029/03L-0 AUTIO.H A Vantee Atomic Electric Co 82/10/13 HAYNES.R C Region 1, Office of Director 1p 15799 001 24X Fiche 50-029.82/10/13.8210260165
- B210260169 LER B2-029/03L-0 on B20913, during refusing outage in Mode 5 while performing calibr of steem generator marrow-range level trip sup, trip setpoint 3 found less than Tech Bpec limit Caused by setpoint drift FRENCH.L D Yankee Atomic Electric Co B2/10/13 Region 1, Office of Director ip 15799 002 24X Fiche 50-029, B2/10/13, 8210260165
- 10260428 LER B2-035/01T on 821013, reactor protection sys permissive listables 8/5 420 & B/S 423 found calibr out of tolerance laused by surveillance procedure inadequacy Bistables acalibr NUTIO.H A Yankee Atomic Electric Co 82/10/13 HAYNES,R C legion 1. Office of Director. 1p 15806 293 24X iche 50-029, 82/10/13,8210260428
- O280085 LER 82-032 has been canceled JUTIO,H A Yantee Atomic Electric Co 82/10/20 HAYNES,R C legion 1, Office of Director 1p 15837 183 24X 1che 50-029, 82/10/20,8210280085

#### KET 50-54 UNION CARBIDE RESEARCH REACTOR

Operating license stage documents & correspondence

- 0:30302 Forwards figures inadvertently omatted from 800523 pplication for renewal of License R-81 & addl minor hanges to Tech 8pecs
  OTH/M H Union Carbide Corp 82/09/29 BERNARD.H tandardization & Special Projects Branch 15pp 15678 318 24x iche 50-054,82/09/29,8210130302
- 210130306 Proposed Tech Spec changes re-fueled experiments & staffing.supplementing 800523 application to rense License R-Bi = Union Carbide Corp B2/09/29 5pp 15678 333 24X Fiche: 50-084, 82/09/29, 8210130302
- KEY 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR Security, medical, emergency & fire protection plans
- 0010277 Forwards Revision 4 to security plan Revision withheld ref 10CFR2.790) ENRY.L. 0 New York, State Univ of, Buffalm 82/09/17 THOMAS,C tandardization & Special Projects Branch. 1p 15573 121 24X 1che: 50-057, 82/09/17

- DOCKET 50-42 UNIV OF VIRGINIA RESEARCH REACTOR
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8210050377 SAFETY EVALUATION REPORT RELATED TO THE RENEWAL OF THE OPERATING LICENSE FOR THE UNIVERSITY OF VIRGINIA OPEN-POOL RESEARCH REACTOR Docket No 50-062 4 Division of Licensing NUREG-0928 92/09/30 77pp Available at NRC \$5 00 15626 030 24% Fich \$50-062,82/09/30,8210050377
- P Operating license stage documents & correspondence
- 8210060086 Informs of minor mods made to ECCS piping Flexible piping installed on tank side of remote coupling to provide necessary movement for coupling alignment Repair will have no adverse effect on ability of ECCS to perform BRENIZER.JS Virginia Univ of 82/09/27 Standardization & Special Projects Branch Opp 15615 038 24X Fiche 50-062, 82/09/27,8210060086
- B2100B0237 Forwards licensee B20929 ltr to ORNL requesting shipment of DDE-owned MTR type reactor fuel using HFIR spent fuel shipping cask BENNECHE, P E Virginia, Univ of B2/09/30 CARTER, R E Standardization & Special Projects Branch | 3pp | 15638 078 | 24X Ficha 50-062, 82,09/30,82108080237
- 8210120475 Forwards Amend 15 to License R-66.CIA & notice of issuance/ negative declaration Amend CLL for 20 yrs THOMAS.C O Standardization & Special Projects Branch 82/09/30 BRENIZER.J S Virginia. Univ of 2pp 15672-005 24X Fiche 50-062.82/09/30.8210120475
- --8210120480 Amend 15 to License R-66 renowing OL for 20 yrs
  THOMAS.C D Standardization & Special Projects Branch 82/09/30
  34pp 15672 007 24% Fiche 50-062.82/09/30.8210120475
- --8210120487 ElA supporting Amend 15 to License R-66 \* Standardization & Special Projects Branch 82/09/30 3pp 15672 042 24% Fiche 50-068.82/09/30,8210120475
- --8210120492 Notice of renewal of facility OL & negative declaration re Amend 15 to License R-66 THOMAS: C O Standardization & Special Projects Branch 62/09/30 2pp 15672 049 24% Fiche 50-062.82/09/30.0210120475
- 8210180014 Submits daily highlight for 820930 NRR issued 20-yr renewal of License R-66 CARTER: R E Standardization & Special Projects Branch 82/10/DI CASE.E . CARTER: J Office of Nuclear Reactor Regulation, Director EISENHUT. D Division of Licensing 1p 15717 352 24X Fiche 30-082.82/10/01.8210180014
- OCCKET 50-70 GENERAL ELECTRIC TEST REACTOR

  G Adjudicatory correspondence
- 82102000B7 Notice of ASLB reconstitution OH Frye, chairman & H Foreman & GA Linenberger, members COTTER: 8 P About Safety and Licensing Board Panel 82/10/14 2pp 15753 196 24X Fiche 50-070,82/10/14,8210200087
- 8210220343 Memorandum & order directing OE to file rept on intention to submit applications to renew QL & SNM license, within 15 days of svc of order FRYE. J H Atomic Bafety and Licensing Board Panel 82/10/21 General Electric Co 3pp 15776 265 24X Fiche 50-070.82/10/21.8210220343
- P Operating license stage documents & correspondence
- 8210280110 Application to amend License TR-1, requesting addited Epec changes reflecting removal of irradiated SNM by eliminating tests re reactor bidg integrity CUNNINAMA, 6 E General Electric Co. 82/10/12 TEDESCO, R L Assistant Director for Licensing 2pp 15787 028 24X Ficha 50-070, 82/10/12, 8210250110
- --8210250113 Proposed Tech Spec changes reflecting removal of irradiate SNM by eliminating tests re reactor bldg integrity \* General Electric Co. 82/10/12 2pp. 15707 030 24% Fiche 50-070,82/10/12,8210250110

- DOCKET 50-72 UNIV OF UTAH RESEARCH REACTOR
- A Periodic operating reports & related correspondence
- 8210260224 Ack receipt of 820924 ltm forwarding revised annual operating rept for 1981 SEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs 82/10/22 JACO88, H.R. Utah, Univ. of 1p. 15799 156
- 24% Fiche 50-072, 82/10/22, 8210260224
- ~~8210260230 Forwards revised "Annual Operating Rept.1981 " JACOBS.H R Utah. Uni. of 82/09/24 MADSEN.G L Region 4. Office of Director ip 15799 157 24X Fiche 50~072,82/10/22.
- --8210260234 Revised "Annual Operating Rept.1981" SANDOUIST G M Utah Univ of 82/07/24 2pp 15799 158 24% Fiche 50-072,02/10/22,0210260224

#### DOCKET 50-93 UNIV DE FLORIDA TRAINING REACTOR

- G Inspection reports, IE Bulletins & correspondence
- 8210010120 Forwards IE Insp Rept 50-083/82-02 on 820811-13 No noncompliance noted
  VERRELLI,D M Division of Project & Resident Programs 82/08/31
  JACOBS,A M Florida, Univ of Gainesville 2pp 15566 032 24X Fiche 50-083, 82/08/31, 8210010120
- ELUCTURE IE Insp. Rept 50-083/82-02 on 820811-13 No noncompliance noted Major areas inspected radiation protection.

  PERRY: W. BARR: K.P. Division of Engineering & Technical Programs 82/08/30 3pp 15564 034 24% Ficha 50-083,82/08/31,8210010120 ~-8210010122 IE Insp Rept 50-083/82-02 on 820811-13 No noncompliance

#### DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

- F Security, medical, emergency & fire protection plans
- 6210010198 Forwards safeguards info re changes implemented in security plan info withheld (ref lockers 21)
  CRANE.P A Pacific Gas & Electric Co 82/09/23
  Office of Nuclear Reactor Regulation, Director
  Fiche 50-133.82/09/23.8210010198 DENTON, H R 1 p 15568 077 24X
- G Adjudicatory correspondence
- 8210060189 Order extending time until 821012 for Commission to act to review Director's Decision DD-82-7 CHILKS J Office of the Secretary of the Commission 82/10/04 Commissioner Ip 15613 228 24X Fiche 50-133,82/10/04.
- 82:0)50193 Advises that Commission declined review of Director's Decision DD-82-7 Time for Commission to act expired Decision became final agency action on 82:012 CHILK.S J Office of the Secretary of the Commission 82/10/3 QUENTHER R Affiliation Unknown ip 13707 299 24X Fiche 90-133, 82/10/13, 82:10150193 82/10/13
- P. Operating license stage documents & correspondence
- 8210260359 Responds to Generic Ltr 82-12, "Policy on Factors Causing Fatigue of Operating Personnel at Nuclear Reactors "Existing procedures comply w/policy statement CRANE.P A Pacific Gas & Elactric Co 82/10/21 MIRAQLIA,F J Licensing Branch 3 1p 15804 258 24X Fiche 50~133,82/10/21,821020359
- Q Inspection reports: IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Syc list encl COBB.L. I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 1976 24X Fiche 50-000,82/10/06,8208190233 15761 250
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list and DEVOUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New i15pp 15810 125 24X Fiche 50-000,82/10/14,8208170238

- R Periodic operating reports & related correspondence
- 8210250192 Forwards third quarterly status rept re plant operational status & util activities, per 820216 order Study re future disposition of plant uill be completed within & months of issuance of NRC final reactor safety policy statement OHLBACH.R., CRANE.P A. LOCKE.R F Pacific Oas & Electric Co 82/10/01 LAZO.R M. SCHINK, D R. LINKENBERGER. G Atomic Safety and Licensing Board Panel 2pp 15787 336 24X Fiche 50-133,82/10/01,
- --8210250196 Third quarterly status rept for facility Certificate of Svc EUCKE, R. F. Pacific Gas & Electric Co. 82/10/01 4pp 15/97 338 24x Fiche 50~133,82/10/01,8210250192

#### DOCKET 50-142 UCLA TRAINING REACTOR

- F Security, medical, emergency & fire protection plans
- 8210290029 Partial response to FOIA request for documents re UCLA Lab & research reactors Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/09/09 HIRSCH.D Government Accountability Project 2pp 15864 195 24X FELTON J H Division of Rules and Records 82/07/03 Government Accountability Project 2pp 13864 195 Fichs 50-142,82/09/03,8210290023
- ~-8210290036 Requests that licensee submit new physical security plan to comply w'new regulations to 10CFR80.70 & 73 by 740107 SKOWHOLID D Atomic Energy Commission. Directorate of Licensing 73/11/30 HICKS.TE California. State of 1p 15864 259 24) Fich 50-142,82/09/03,8210290023
- --8210290043 Forwards add1 info re physical security plan Info withheld (ref 10CFR2 790) ASHBAUGH, C.E. California, Univ. of, Los Angeles 74/11/27 GOLLER, K.R. Atomic Energy Commission, Directorate of Licensing Ip. 15844 260 24X Fiche 50-142.82/09/03.8210270023
- --8210270051 Forwards SNM inventory info for nonpower reactor facilities Info withheld (ref 10CFR2 770) Authorization to retain inventory requested ABHGAUGH, C. E. California, Univ. of, Los Angeles. 76/01/30 GOLLER, K. R. Division of Operating Reactors. 2pp. 15864 2 Fiche 50-142, 82/09/03, 8210290023 15864 263 24X
- --8101200322 Notifies that since reactor operating & SNM storage sites are contiguous, facility must implement interim Category I physical security requirements Compliance plan required by MILLER, J. R. Standardization & Special Projects Branch 81/01 WEOST, W. F. California, Univ. of, Los Angeles 1p 15865 093 24X Fiche 50-142,82/09/03,8219290023

#### O Adjudicatory correspondence

- B210080077 Response supporting Committee to Bridge the Oap B20720 motion for summary dismissal of NRC & util 820701 & 03 motions for summary disposition. ABLB statements on use of summary disposition flagrantly disregarded by NRC & util SHIRLEY. B J Santa Monice.CA 82/10/06 Atomic Safety and Licensing Board Panel 6pp 15640 193 24X Fiche 50-142,82/10/06.
- 8210120261 Response opposing Committee to Bridge the Gap 820920 motion to dismiss NRC & applicant 820901 summary disposition motions Extension until 821113 should be granted to allow Committee response W/Certificate of Svc WOODHEAD.C P Hearing Branch I 82/10/08 Atomic Bafety and Licensing Board Panel 26pp 15652 184 24X Fiche 50-142,82/10/08, 8210120261
- 8210190454 Response opposing Committee to Bridge the Gap 820920 motion to dismiss NRC & util motions for summary disposition Commission rules preclude dismissal of summary disposition motions filed per schedule W/Certificate of Svc CORMIER.W H California, Univ of, Los Angeles. 82/10/08 Atomic Safety and Licensing Baard Panel 19pp 18703 132 24X Fiche 50-142,82/10/08,8210150456 Atomie
- B210280076 Forwards UCLA 821008 ltr to NRC amending Feb 1980 license renewal application Changes include reducing licensed limit on permissible inventory of fuel to less than 500 g enriched U-235 CORMIER.W H California, Univ. of, Los Angeles. 82/10/15 FRYE.J H. PARIB.O H. LUEBKE.E A Atomic Sefety and Licensing Board Panel 11pp 15789 352 24% Fiche 50-142.82/10/15.8210250076

8210250223 Hemorandum & order denying Committee to Bridge the Gap (CBG)
820920 motion to summarily dismiss NRC & util autions for
summary disposition or alternative relief UCLA.NRC & CBO
must furnish lists of citations of matl fact
LUEBKE.E A. PARIS.O H. FRYE.J H. Atomic Safety and Licensing Board
Panel 82/10/22 Committee to Bridge the Gap 12pp 15789 314
24X Fiche 50-142.82/10/22,8210250223

## P Operating license stage documents & correspondence

- 8210130115 Requests amend to application for 10CFR70 license to reflect reduced inventory of unirradiated U-235 reactor fuel THOMAS.C O Standardization & Special Projects Branch 82/09/27 4E0ST.M F California. Univ of, Los Angeles ip 15696 082 24X Fiche 50-142.82/09/27.8210130115
- 8210200081 Application for amend to Feb 1980 renewal application for License R-71, replacing pages re reduction of permissible inventory of reactor fuel & altering purpose & function of safety high level radiation monitor WEOST.H F California, Univ of, Los Angeles 82/10/08 THOMAS.C O Standardization & Special Projects Branch 10pp 15753 198 24X Fiche 50-142,82/10/08,8210200081
- B210250076 Forwards UCLA B21008 ltr to NRC amending Feb 1980 license renewal application Changes include reducing licensed limit on permissible inventory of fuel to less than 500 g enriched U-235 CORMIER. H H California, Univ of, Los Angeles 82/10/15 FRYE. J H. PARIS.O H. LUEGKE.E A Atomic Safety and Licensing Board Panel 11pp 15789 352 24X Fiche S0-142.82/10/15.8210250076

## O frapection reports, IE Bulletins & correspondence

- B210270023 Partial response to FOIA request for documents re UCLA Lab & research reactors Forwards documents listed in App A FELTON.J M Division of Rules and Records B2/09/03 HIRSCH.D Government Accountability Project 2pp 15864 195 24X Fiche 50-142.82/09/03.8210270023
- --8210290048 Discusses insp of activities authorized under License R-71 & SNM-974 on 750520 No noncompliance noted Hajor areas inspected control of SNM & selective exams of procedures & personnel interviews

  ENGELKEN, R H Region 5, Sam Francisco, Office of the Director 75/06/10 BROHN, H V California, Univ of, Los Angeles ip 15864 282 24X Fiche 50-142,82/09/03.8210290023

## DOCKET 50-148 UNIV OF KANSAS RESEARCH REACTOR

#### H General correspondence

- 8208270090 FOIA request for six documents to Univ of KB research reactor ROBINSON B Affiliation Unknown 82/09/07 FELTON, J M Division of Rules and Records 2pp 15636 210 24x Ficher 30-148,82/09/07, 8208290090
- 8208270097 FOIA request for documents re Univ of KS research reactor BARNES.C Affiliation Unknown 82/09/07 Docketing & Services Branch ip. 15859 119 24X Fiche 50-148,82/09/07,8208290097
- 8210060437 Responds to FOIA request for six documents re Univ of KS research reactor Request referred to PDR for processing FELTON, J M Division of Rules and Records 82/09/13 ROBINSON, 8 Affillation Unknown 1p 15636 212 24X Fiche 50-148,82/09/13,8210060437
- 8210280387 Responds to FOIA request for listed documents to Univ of KS research reactor Request referred to PDR for processing FELTON, J M. Division of Rules and Records 82/09/14 BARNES, C. Affiliation Unknown 1p 15859 120 24X Fiche 50-148,82/09/14,8210280389

## DOCKET 50-151 UNIV OF ILLINOIS RESEARCH REACTOR

#### 8 Reportable occurrences. LERs & related correspondence

9210130476 RD from 820103-0505 reactor operated under reactor operator w/expired licenses. Caused by oversight Unicensed operator in charge of operation for approx 50-h.Individual filling application for license BECK. 0.P Illinois. Univ of Urbana-Chempaign 82/09/29 Division of Licensing 2pp 15682-161 24X Fiche 50-151-82/09/29, 82/03/00476.

## DOCKET 50-155 BIG ROCK POINT MUCLEAR PLANT

- F Security, medical, emergency & fire protection plans
- 8210060222 Forwards addl fire protection info re associated circuits, alternate safe shutdown design & emergency condenser caustic attack in response to NRC 820400 lit & NRC questions raised during 820908-09 site meeting concerning 10CFR50 App R VANDEMALLE.D J Consumers Power Co 82/09/28 CRUTCHFIELD.D Operating Reactors Branch 5 57pp 15620 062 24X Fiche 50-155,82/09/28.8210060222
- 8210080279 Confirms commitment to incorporate responses to IE Insp Rept 50-155/81-17 into emergency plan implementing procedures & requests approval to use general ofc control ctr as temporary emergency operations facility VANDEHALLE. D J Consumers Power Co 82/10/01 KEPPLER. J G Region J. Office of Director 5pp 15638 203 24X Fiche 50-155,62/10/01.
- 8210200029 Forwards emergency preparedness pamphlet for use in 5-mile emergency planning ione in Charlevoix County & part of Emnet County Pamphlet incorporates revisions & mods set forth in ASLB 820806 partial initial decision OALLO, J. Isham, Lincoln & Beale GALLO, J. Consumers Power Co. 82/10/14 GLOCH, P. B., PARIS, D. H., SHON, F. J. Atomic Bafety and Licensing Board Panel 30pp 15756 149 24X Fiche 50-155,82/10/14. 8210200029
- 821025037; Provides addl info on proposed shift technical advisor position based on review of plant administrative procedures & site emergency plan & implementing procedures Min shift provides necessary protection in event of emergency BORDING.TC Consumers Power Go 82/10/19 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 15790 186 24X Fiche 50-155,82/10/19.82102503/1

#### G Adjudicatory correspondence

- 8210010408 Motion for extension of time until 621011 to file petition for reconsideration 2/or motion for clarification resemengency planning portions of ASLB 820914 decision Certificate of Svc encl GALLO.J Consumers Power Co GALLO.J Isham. Lincoln & Deale 82/09/28 Atomic Safety and Licensing Board Panel Spp 13572 176 24X Fichs 50-155.82/09/28.8210010408
- 8210010446 Forwards util 820916 itr to NRC re future scheduling matters in spent fuel pool mod proceeding Related correspondence GALLO.J Isham, Lincoln & Beale GALLO.J Consumers Power Cp 62/09/29 BLOCK, P B . PARIS D H . SHDN.F J Atomic Safety and Licensing Board Panel 4pp 15572 292 24% Fiche 50-155.82/09/29, 8210010446
- 8210040081 Forwards proposed findings of fact & conclusions of law on O'Neill Contention II E 3 recriticality
  GODDARD, R J Hearing Branch 3 82/10/01 BLOCH, P B , SHON, F J ,
  PARIS, D H Atomic Safety and Licensing Board Panel lp 15504 212
  24X Fitchs 50-155,82/10/01,8210040081
- --8210040083 Proposed findings of fact & conclusions of law on O'Neill Contention II E-3 re-criticality OODDARD, R J Hearing Branch 3 82/10/01 10pp 15584 213 24X Fiche 50-155,82/10/01,8210040081
- 8210080232 Proposed snittal decision on criticality contention Certificate of Bvc encl GALLO.J. THORNTON.P Consumers Power Co. GALLO.J. Isham. Lincoln & Beale 82/10/01 28pp 15610 353 24X Fiche 50~155,82/10/01. 8210030232
- 8210050396 Proposed findings of fact & conclusions of law on criticality contention Certificate of Svc encl
  OALLO, J. THORNION, P. Consumers Power Co. GALLO, J. Isham, Lincoln & Beale 82/10/01 17pp 19609 025 24X Fiche 50-155,82/10/01,8910050394.
- 8210060204 Motion to establish hearing dates during wk of 821115-19 to litigate Christa-Maria Contentions 2.9(1).9(6).9(8) & 9(9) & 0.70eill Contentions II A. II B & II E-4 Early resolution of issues serves interests of parties W/Certificate of 8vc OALLO, J Consumers Power Co OALLO, J Callo, J 82/10/01 Atomic Safety and ticensing Board Panel 8pp 15614 162 24X Fichs 50-155,82/10/01,8210060204
- 8210040192 Order deferring briefing of Christa-Maria exceptions to ASLB 820915 third partial initial decision & tolling time for filing exceptions to future partial initial decisions until syc of last decision Piecameal review unproductive TOMPKINB:B A Atomic Bafety and Licensing Appeal Panel 82/10/04 3pp 15613.290 24X Fiche 50-155.82/10/04.8210060192

- 8210130448 Forwards roply to intervenor proposed findings of fact & conclusions of law on O'Neill Contention II-C re cask drop
  - 1880E COPELAND, V O Isham, Lincoln & Beale COPELAND, V O Consumers Power Co 82/10/06 BLOCKLP B , PARTS, D H , SHON, F J Atomic Syfety and Licensing Board Panel 1p 15682 118 24X Fiche 50-155, 82/10/06, 8210130448
- --8210130457 Reply to intervenor proposed findings of fact & conclusions of law on O'Neill Contention II-C re cask drop issue GALLO.J. COPELAND.V G Consumers Power Co GALLO.J Isham, Lincoln & Beale 82/10/07 9pp 15682 119 24X Fiche 50-155.82/10/06.8210130448
- -8210130471 Affidavit of TC Bordine re util commitments to upgrade visual acusty requirement for crane operators to comply wisted of ANSI 830 2-1976, "Goverhead & Qantrys Cranes" to cross-ref maint procedures Certificate of Svc enci BQRDINE,T C Consumers Power Co 82/10/05 4pp 15682 128 24X Fichs 50-155, 82/10/06.
- 9210150300 Motion for extension of time until 821203 for util to demonstrate that deficiencies are remedied are not serious or are being remedied Util has diligantly pursued steps to address deficiencies GALLO, J. Consumers Power Co. GALLO, J. Isham, Lincoln & Beale 82/10/12 Atomic Safety and Licensing Board Panel. 5pp. 15707-273 24x Fiche 50-155.82/10/12.8210150300
- --0210150307 Affidavit of RW Sinderman re util actions in response to ASLB 020914 initial decision Add1 time required to assemble & document info in manner consistent W/ASLB request Certificate of Svc encl SINDERMAN R W Consumers Power Co 02/10/11 14pp 15707 278 24X Fiche 50-155 02/10/12.0210150300
- E210150341 Responses opposing licensee motion to fragment hearing
  Intervenors would be denied right to be represented by
  counsel, noney would be wasted & fragmentation would violate
  intent of ASLAB order Certificate of Svc encl
  SEMMEL, R Christa-Maila SEMMEL, H Antioch College of Law
  82/10/12 Atomic Safety and Licensing Board Fanel App
  15706 00P 24x Fiche 50-155.82/10/12.8210150341
- 8210150470 Reply to Christa-Maria B20927 proposed findings of fact & conclusions of law on O'Neill Contention IIE-3 recribicality Contention w/o merit & should be dismissed Certificate of Sev cent!
  GALLO.J. THORNTON.P Consumers Power Co. GALLO.J. Isham. Lincoln & Beale 02/10/12 tOpp 15703-063 24X Fiche 50-155,02/10/12. 8210150470
- 8210180206 Mption for clarification &/or petition for reconsideration of portion of ASLB 820914 partial initial decision re legal requirement of NUREO-0654 Term "relocation requirement" unclear Certificate of Svc encl CALLO. J Consumers Power Co OALLO. J Isham, Lincoln & Bealt 82/10/12 Atomic Safety and Licensing Board Panel App 15718 128 24X Fiche 50-155.82/10/12.8210180206
- 8210)80242 Motion for extension of time until 821012 to file motion for clarification b/or petition for reconsideration of ASLB 820914 partial initial decision Holiday to honor Columbus Day not considered in schedule GALLO, J Consumers Power Co GALLO, J Isham, Lincoln & Beale 82/10/12 Atomic Safety and Liconsing Board Panel 2pp 15718 059 24X Fichs 50-155,82/10/12,6210180242
- 6210150167 Memorializes 621008 telcon w/ASLB re NRC position on util 621001 motion to establish hearing dates NRC agrees to splitting hearing into two phases but dates pose unalterable conflict w/another hearing for ASLB chairman & NRC counsel CODDARD.R J Hearing Branch 3 62/10/13 BLOCH.P B, SHON,F J, PARIB.O H Atomic Safety and Licensing Board Panel 2pp 15707 180 24% Fiche SO-155,82/10/13,8210150167
- 8210150469 Forwards 0 Zech 821012 trip rept of 820928 site visit, sugmartring events & conversations ROBERTS.T M Commissioners 82/10/13 SEMMEL.H Antioch College of Law SEMMEL.H Christa-Maria 3pp 15703 060 24X Fiche 50-155,82/10/13,8210150469
- 8210200029 Forwards emergency preparedness pamphlet for use in 5-mile amergency planning zone in Charlevoix County & part of Emmet County Pamphlet incorporates revisions & mods set forth in ASLD 820806 partial initial decision OALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co 82/10/14 BLOCH, P.B., PARIS, O.H., SHON, F.J. Atomic Safety and Licensing Board Panel 30pp 15756 149 24X Fiche 50-155,82/10/14,8210200029

- 8210210349 Memorandum & order denying util 821001 motion to establish hearing dates & 821012 motion for clarification Hearing on issues delayed by applicant deferred Clarification motion not ripe for adjudication BLOCH, P B . PARIS.O H . SHON, F J Atomic Bafety and Licensing Hoard Panel 82/10/19 Consumers Power Co 3pp 15764 201 24% Fiche 50-155.82/10/19.8210210349
- 8210210381 Opposition to licensee motion to continue plant operations w/o compliance w/ASLB order on emergency planning Continued operation u/o adequate planning poses threat to lives & health of citizens W/Certificate of Svc SEMMEL.H . WIKTOR:D Christa-Maria SEMMEL.H Antioch College of Law 82/10/21 Atomic Safety and Licensing Board Panel App 13745 153 24X Fiche SO-155,82/10/21,8210210381
- 8210220338 Memorandum & order granting util 821012 motion for extension of time until 821201 to comply w/ASLB 821014 order to demonstrate compliance w/Commission emergency planning requirements
  BLOCH.P B . PARIS,O H . SHON,F J Atomic Safety and Licensing Board Panel 82/10/21 Carolina Power & Light Co 3pp 19776 008
  24X Fishe 50-155,82/10/21.8210220338
- 8210250301 Advises that Region 3 will notify util to delete erroneous language in emergency preparedness pamphlet re respiratory protection measures Mods would not contrevene ASLB order CODDARD.R J. Hearing Branch 3 82/10/22 BLOCH.P B. PARIB.O II. SHON.F J. Atomic Safety and Licensing Board Panel 2pp 15790 215 24X Fiche 50-155.82/10/22.8210250301
- 821027027: Confirms 821026 telcon Intervenor has not decided whether to file 10CFR2 206 petition to suspend or revoke license because of emergency planning concerns BACHMANN.R 9 Hearing Branch 1 82/10/28 SEMMEL.H Antioch Callege of Law 1p 15854 072 24X Fiche 50-195.82/10/28, 221020029
- J Insurance & indemnity information
- 82(0050100 Bubmits responses to 820712 questions concerning addlinsurance coverage re 820622 request for exemption BACON.J L. Consumers Power Co. 82/08/10 SALTZMAN.J. Office of State Programs, Director 3pp. 15603 298 24X Fiche 50-155.82/08/10.8210050100
- P Operating license stage documents & correspondence
- 8210280013 Responds to FOIA request for all internal non-public documents nemos, evaluation repts & other math dealing w/ nuclear plant to perations Forwards documents listed in App A FELTON J M D(vision of Rules and Records 82/09/17 MCINNIS, D News & Observer 5pp 15860 065 24X Ficke 50-000, 82/09/17, 8210280013
- ~~8208310034 Forwards draft info notice re deficiencies in air filtration by ventilation sys Notice based on radioactive resin release at Filgrim 1 & on four related events at other plants involving deficiencies in maint & testing of filter sys MATTBON.R J Division of Bystems Integration (post 81/005) 82/08/05 JORDAN.E L Division of Engineering & Quality Assurance 5pp 15861 024 24X Fiche 50-000.82/09/17.8210280013

- 8210050425 Forwards "Evaluation of High Energy Pipe Broak Inside Containment for Sig Rock Point Nuclear Plant:" in response to SEP Topic III-53 VANDEWALLE: D. J. Consumers Power Co. 82/09/30 CRUTCHFIELD, D. Operating Reactors Branch 5 2pp. 15607-042 24X Fiche 50-195, 82/09/30, 8210050425
- --8210050427 "Evaluation of High Energy Pipe Break Inside Containment for Big Rock Point Nuclear Plant " GEBERLY V. MAGER, T.R. RICCARDELLA, P. NUTECH (Nuclear Technology, Inc.) CPC-01-110 ROD 81/10/23 79pp 15607 044 24X Fichs 50-155,82/09/30,8210050425
- 6210060152 Comments on NRC draft safety evaluation of SEP Topic V-5, "RCPB Leakage Detection." per 820319 request Info missing from Tables I & 2 of 820319 submittal encl Detection sysmest intent of current licensing criteria VANDEWALLE, D J Consumers fower Co 82/09/30 CRUTCHFIELD, D Operating Reactors Branch 5 9pp 15614 047 24X Fiche 50-153, 82/09/30, 8210060152
- 8210040237 Forwards response to NRC request for add1 info on SEP Topic 111-2. "Wind & Tornado Loadings " App C supersades 820803 submittal Drawing showing cross-section of south end of control room wall can be retrieved from NMSS VANDEWALLE.D J Consumers Power Co 82/09/30 CRUTCHFIELD.D Operating Reactors Branch 5 12pp 15619 327 24X Fiche 50-155.82/09/30.8210060239
- ---8210060241 "Specs for Designing, Furnishing & Erecting Reinforced Concrete Chimney" # Bechtel Corp 3159 C-21 61/03/17 (2pp 15617 339 24X Fiche 50-155, 82/09/30. 8210060239
- 821025009; Forwards draft safety evaluation & technical evaluation rept. "Design Codes, Design Criteria & Load Combinations (SEP 111-7 B), Big Rock Point " Util requested to respond to factual correctness of SER in 30 days CRUTCHFIELD, D. Operating Reactors Branch 5 82/09/30 VANDEMALLE, D. J. Consumers Power Co. 11pp 15788 001 24X Fiche 50-155, 82/09/30, 8210250091
- --8209160459 "Design Codes, Design Critéria & Loading Combinations (SEP III-7 B), Big Rock Point, "technical evaluation rept STILMELL, T Frantlin Institute/Frantlin Research Center NRC-03-79-118 TER-C5257-317 82/09/13 PERSINKO, D NRC No Detailed Affiliation Given 2160p 15788 012 24% Fiche 50-155,82/09/30,8210250091
- 8210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820909 ltm Staff encouraged to develop & implement means to incorporate positive attributes of Phase III in licensee/NRC interface KACICH.R H BEP Owners Group KACICH.R H Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/07 EIBENNUT.D 0 Division of Licensing 7pp 19682 179 24% Fichs 50-000.82/10/07, 8210130326
- 8210150505 Advises of Franklin Research Ctr B20430 technical evaluation rept, "Containment Leakage Rate Testing-(A 04)." Exemptions for instrument pressure lines should be granted to significant degradation of penetration seals observed BURDINE, T C Carolina Power & Light Co 82/10/12 CRUTCHFIELD.D Operating Resetors Branch 5, 2pp 15714 210 24x Fiche 50-153,82/10/12.8210150505
- 8210190459 Forwards current status of program to evaluate adequacy of averload & short-circuit protection for electrical circuits that pass through reactor containment per SEP Topic VIII-4 "Electrical Penetrations of Reactor Containment." TONER.K A Consumers Power Go 82/10/12. CRUTCHFIELD, D Operating Reactors Branch 5 21pp 13740 268 24X Fiche 50-000,82/10/12. 82(0)90459
- 8210200041 Forwards safety evaluation of SEP Topic IX-5, "Ventilation Sys " Evaluation will be basic input to integrated safety assessment Also forwards "Review of Pesign & Operation of Ventilation Sys for SEP Plants," technical availation rept GRUTCHFIELD.D Operating Reactors Branch 5 NRC-03-79-118 B2/10/12 VANDEMALE, D J Consumers Power Co 9pp 15755;358 24X Fichs 50-155,82/10/12,8210200041.
- --8208180082 "Review of Design & Operation of Ventilation Sys for SEP Plants," final technical evaluation rept HERRIOK.R.C. Franklin Institute/Franklin Research Center NRC-03-79-118, TER-05257-414 82/08/13 BROWN.S NRC No Detailed Affiliation Given, 21pp 15756 005 24K Fiche: 50-153, 82/10/12, 8210200041

 $\frac{(1+\frac{1}{2})^2}{(1+\frac{1}{2})^2} \frac{(1+\frac{1}{2})^2}{(1+\frac{1}{2})^2} \frac{(1+\frac{1}{2})^2}{(1+\frac{1}{2})$ 

- 82:0150469 Forwards O Zech 82:012 trip rept of 82:0928 site visit, summarizing events 2 conversations ROBERTS, Th Commissioners 82:10/13 SEMMEL.H Antioch College of Law SEMMEL, H Christa-Maria 3pp 15703 060 24X Fiche 50-155, 82:10/13, 82:10/150469
- 8210150533 Comments on 820812 final safety evaluation of SEP Topics V-11 A. "Requirements for Isolation of High & Low Pressure Sys" & V-11 B. "RHR Interlock Requirements" Core spray sys designed to perform function safely TOWER, K. A. Consumers Power Co. 82/10/13 CRUTCHFIELD, D. Operating Reactors Branch 5. App. 15713 145 24X Fiche 50-155,82/10/13, 82/10/50533
- 8210250213 Forwards evaluation of SEP Topic III-4 C, "Internally Oenerated Missiles," % related SER Facility meets acceptance criteria for topic Info will be basic input to integrated sarety assessment CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/14 VANDEMALLE, D. J. Consumers Power Co. 25pp. 15/88 247 24X Fishe 50-155.82/10/14.8210250213
- B210220368 Forwards safety evaluation of NURCG-0737. Item 11 E 4 .2. "Containment Isolation Dependability "Facility meets guidance Item resolved CRUTCHFIELD.D Operating Reactors Branch 5 B2/10/18 VANDEWALLE.D Consumers Power Co 5pp 15/79 189 24X Fishs 50-155. B2/10/18 B210220368
- 8210250323 Forwards Amend 54 to License DPR-6, safety evaluation is notice of issuance & availability Amend approves Tech Opec changes re NUREG-0737. Item II F 1(3) on leak testing intervals
  CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/18
  VANDEHALLE, D. J. Consumers Power Co. 1p. 15790-010 24X
  Fiche S0-155, 82/10/18. 8210250323
- --8210250327 Amend 54 to License DPR-6, changing fech Specs re containment high radiation monitor requirement by TMI Action Item II F t(3) on leak testing intervals CRUTCHFIELD,D Operating Reactors Branch 5 82/10/18 10pp 15790 011 24X Fiche 50-155,82/10/18,8210250323
- --8210250333 Safety evaluation supporting Amend 94 to License DPR-6 • Office of Nuclear Reactor Regulation, Director B2/10/10 Upp 15790 021 24X Fiche 50-155.82/10/18.8210250323
- --8210250337 Notice of issuance & availability of Amend 54 to License PPR-6 CRUTCHFIELD.D Operating Reactors Branch 5 82/10/18 2pp 15790 024 24X Fichs 50-155, 82/10/18,8210250323
- 8210220117 Forwards GE turbine hydraulic control lever Diagram 2127316-A (ALTO), requested by Power Sys Branch during 821013 conference call per SEP Topic III-4 B, "Turbine Missiles" TONER, K. A. Consumers Power Co. 82/10/19 CRUTCHFIELD, D. Operating Reactors Branch 5 2pp 15778 147 24% Fiche 50-155, β2/10/19, 8210220117
- 8210270270 Forwards draft safety evaluation of SEP Topics III-6.
  "Seismic Design Considerations" & III-11. "Component
  Integrity " Licensee analyses of structures.bursed piping &
  reactor coolant loop piping insdequate
  CRUTCHFIELD.D Operating Reactors Branch 5 82/10/19
  VANDEMALLE.D Consumers Power Co 3App 15852 048 24X
  Fische 50-155.82/10/19,8210270270
- --8208110271 Forwards geotechnical review of srismic safety margin study in response to verbal request during 820524 meeting Range of soil shear module values used in parametric study by licensee adequately envelope expected values
  LEAR.9 Hydrologic & Geotechnical Engineering Branch 82/07/30 RUSSCL.W T Systematic Evaluation Program Branch 10pp 15852 IO8 24X Fiche 50-155, 82/10/19,8210270270
- ---BR05250010 Forwards "Seismic Review of Big Rock Point Nuclear Power Plant Containment Shell Structure.as Part of SEP "
  LD.T Laurence Livermore Laboratory FIN A--0436 82/05/20 RUSSELL, W T Systematic Evaluation Program Branch 19 15852 118 24X Fiche 50-155, 82/10/19,8210270270
- --8205250020 "Beismic Review of Big Rock Point Nuclear Power Plants Containment Shell Structure, as Part of SEP " LIAM.C Y E940, Inc FIN A-0495 SRC-307 B2/04/30 NRC - No Detailed Affiliation Given 28pp 15852 I19 24X Fiche 50-155,82/10/19,8210270270
- --8210270288 "Seismic Design," informal technical evaluation rept CALL.V B.: THOMPSON,Y R EQ&O, Inc FIN A-6426 EQQ-EA-6051 82/09/30 HERRINO,K Division of Licensing S2pp 15852 146 24X Fiche 50-155,82/10/19.8210270270

- ©210250310 Forwards safety evaluation of SEP Topic XV-19, "LOCA micidents Resulting From Spectrum of Postulated Piping Broaks Within RCPB (Radiological) "Facility meets acceptance criteria CRUICHFIELD.0 Operating Reactors Branch 5 82/10/20 VA.(DEMALLE,D J Consumers Power Co 10pp 15790 093 24X Fiche 50-155, 82/10/20 82/0250310
- p210270269 Advises that NUREG-0737, Items II K 3 18 % II K 3 45 ro automatic depressorization sys. inapplicable to facility Therefore, items resolved CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/20 VANDEHALLE, D. Consumers Power Co. 4pp. 15829-045 24X Fiche 50-155, 82/10/20, 8210270265
- 🕝 Inspection reports, 1E Bulletins & correspondence
- \$210050336 Ack receipt of B20917 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Rept 50-155/82-12 SPESSARD.R L Division of Project & Resident Programs 82/09/24 DENITY.R B Consumers Pawer Co ip 15610 098 24X Fiche 50-155.82/09/24.8210050336
- --8210050342 Responds to NRC 820817 ltrie noncompliance noted in IF Insp Rept 50-155/82-12 Corrective actions unauthorized activity terminated on 820617 following review by operations superintendent VARIOECIALLE. D.J. Consumers Power Co. 82/09/17 KEPPLER, J. G. Region 3. Office of Director 2pp 15610 099 24X Fiche 50-155, 82/09/24, 8210050336
- E3 210080279 Confirms commitment to incorporate responses to IE Insp Rept 50-157/81-17 into emergency plan implementing procedures & requests approval to use general oft control ctr as temporary emergency operations facility VANDEMALE.D J. Consumers Power Co. 82/10/01 KEPPLER.J O. Region J. Office of Director. 5pp. 15638-203 24X Fiche 50-155.82/10/01, 8210080279
- F3≥0819023.1 IE Info Notice 80-35. Suppl 1, "Looking & Disjodged I-125 Implant Seeds " Svc list encl C088.L I Division of Fuel Facilities. Materials & Safeguards 62/10/06 Consolidated Edison Co of New York 66pp 15761 250 24x Fiche 50-000.82/10/06.82081902.33
- 3210220233 Forwards evaluation of SEP Topic III-3 C. "Inservice Insp of Water Contiol Structures" Insp program needs mod to conform W/Reg Ovide 1 127
  CRUTCH\*IELD.D. Operating Reactors Branch 5 02/10/12
  VANDEMALLED.D.J. Consumers Power Co. 8pp 15775 104 24X
  Fiche 50-155, 82/10/12, 8210220233
- -6206300188 "Hydrological Considerations Inservice Insp of Water Control Structures, (SEP.II-3A.B.B.), C.III-3B.), "technical evaluation rept SCHERRER, J Franklin Institute/Franklin Research Center NNC-03 79-118 TER-C5257-542 62/06/23 STALEY, O NRC No Detailed Affiliation Given 15pp 15775 112 24X Fiche 50-155,82/10/12.8210220233
- 208190238 IE Dulletin 82-03, "Stress Corrosion Cracking in Thick-Gall, Large-Diameter: Stainless Steel, Recirculation Sys Paping at BMR Plants" Svc list encl
  DEYOUND.R C Director's Office, Office of Inspection and
  Emprocement 82/10/14 Consolidated Edison Co of New York
  115pp 15810 125 24x Fiche 50-000, 82/10/14, 8208190238
- 210260220 Advises that spiked air particulate filter being forwarded to util for analysis per 820427 discussion Util results will to compared w/NRC analysis, in effort to close out open item in IE insp Rept 50-155/82-07

  PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 82/10/20 HOFFMAN, D P Consumers Power Co ip 15804 247 24% Fichs 50-155/82/10/20,8210240220
- 11 O260315 Ack receipt of 821015 Itr informing NRC of steps taken to Correct violations noted in IE Insp Rept 50-155/82-09
  PADRELIUS.C E Division of Project & Resident Programs 82/10/22
  DEWITTR B Consumers Power Co 1p 15799 328 24X
  Fische 50-155, 62/10/22, 8210260315
- B210260316 Responds to NRC 820917 ltr re violations noted in IE Insp Rept 50-155/82-09 Corrective actions training procedures & requirements revised & will be clarified by 830101 VANDEWALLE, D. J. Consumers Power Co. 82/10/15 KEPPLER, J. G. Region 3, Office of Director 6pp 15799 329 24X Fiche 50-135,82/10/22,8210260315

- 5 Reportable occurrences, LERs & related correspondence
- 8210080251 PNO-111-82-097 on 820914.ASLB issued order delineating deficiencies in state offsite emergency preparedness Util given 1 month to demonstrate deficiencies remedied PAGLIARO.J. AXELSON.W. PAPERIELLG.C. Region 3, Office of Director 82/09/20 ip 15638 11B 24X Fiche 50-155.82/09/20.8210080251
- T Hearing transcripts on hon-antitrust matters
- 8210290360 Forwards signed original transcript of L Reiter deposition taken on 820917 W/o encl BACHMANN R G Hearing Branch I 82/10/28 GALLO, J Isham Lincoln & Beale O GALLO, J Consumers Power Co Ip 19853 089 24X Fiche 50-155
- DOCKET 50-160 GEORGIA INST OF TECH RESEARCH REACTOR

  O Inspection reports, IE Bulletins & correspondence
- 8210220312 Ack receipt of 82:1004 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-160/82-02 VERRELLI, D M Division of Project & Resident Programs 82/10/14 CARLSON, M O Georgia Institute of Technology 1p 15776 117 24x Fichs 50-160, 82/10/14, 82:10:220312
- ~-8210220319 Responds to NRC 82090B ltr re-violations noted in IC Insp Rept 90~160/82~02 Corrective actions personnel counseled RUSSELLJ L Georgia Institute of Technology 82/10/04 VERRELLI.D M Division of Project & Residont Programs 3pp 15776 118 24% Fiche 50~160.92/10/14.8210220312
- --8210220330 Notice of violation from insp on 820825-26 \* Division of Project & Resident Programs 82/09/08 ip 19774 123 24x Fiche 90-160/82/10/14/8210220312
- --8210220341 IE Insp Rept 50-160/82-0P on 820825-26 Noncompliance noted on 820513 irradiated mat1 removed from biological shield penetration H-12 w/o health physics supervised PERY.H W. BARR.K. Bivision of Project & Resident Programs 82/09/07 Ap 19776 124 24X Ficks 50-160.82/10/14.8210220312

DUCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

- G Adjudicatory correspondence
- 8210050273 Order scheduling B21015 prehearing conference in Bethesda. MD re remaining outstanding issues Proposed schedules should be presented HOYI.H F Atomic Safety and Licensing Board Panel 82/10/01 2pp 15607 191 24X Fiche 50-170.82/10/01.8210050273
- 8210150317 Becond supplemental response to first set of interrogatories Certificate of SVc encl Related correspondence
  MACKLIN-L Citizens for Nuclear Reactor Safety, Inc MACKLIN-L Institute for Public Representation 82/10/08 47pp 13701 270 24X Fiche 50-170, 82/10/08, 8210150317
- 8210150375 Provides info re counsel for Citizens for Nuclear Reactor Safety E Entoisle to continue as counsel L Macklin & Inst for Public Representation will withdraw as counsel effective 821215.

  MAGKLINL Institute for Public Representation MACKLINL Citizens for Nuclear Reactor Safety, inc 82/10/08 HQYT, H Atomic Safety and Licensing Board Panel 2pp 15704 032 24X Fiche 50-170, 82/10/08, 82/1050375
- 82:0220439 Forwards motion for encl protective order to protect against public disclosure or misuse of I Stillman address & telephone number or misuse of I Stillman address & telephone number MACKLIN.L. Institute for Public Representation MACKLIN.L. Citiens for Nuclear Reactor Safety, Inc 82/10/19 HOYT.H Atomic Safety and Licensing Board Panel 1p 15778 239 24X Fishe 50-170,82/10/19,8210220439.
- --8210220448 Motion for protective order to protect against public disclosure or misuse of I Stillman address & telephone number Proposed protective order & Certificate of Svc encl MACKLIN.L.W S. Citizens for Nuclear Reactor Safety, Inc MACKLIN.L.W,S. Institute for Public Representation 82/10/19. Atomic Safety and Licensing Board Panel 5pp 15778 240 24X Fiche 50-170,82/10/19.8210220439

9210250235 Order granting Citizens for Nuclear Reactor Safety 821019 motion for protective order to protect against public disclosure or misuse of I Stillman address & telephone 82/10/21

HOYT.H F Atomic Safety and Licensing Board Panel 92/10 Citizens for Nuclear Reactor Safety, Inc. 1p 15788 357 Fiche 90-170, 82/10/21,8210250235

8210280220 Provides dates when Citizens for Nuclear Reactor Safety would be available for plant tour MACKLIN, L Institute for Public Representation Citizens for Nuclear Reactor Safety.Inc 82/10/21 HOYT.H Safety and Licensing Board Panel 2pp 15837 087 24X Fiche 50-170.82/10/21.8210280220

8210260425 First supplementary answers to interrogatories Certificate of Svc encl RICKARD,D C Armed Forces Radiobiological Research Institute 82/10/22 Citizens for Nuclear Reactor Safety, Inc 12pp 15806 03B 24X Fiche 50-170.82/10/22.8210260425

### H General correspondence

S210150200 Notice of change of address
ENTHISLE,E B Citizens for Nuclear Reactor Safety, Inc
ENTHISLE,E B Entwisle,E B 82/10/08 1p 15701 362 24x
Fiche 50-170,82/10/08,9210150200

## T Hearing transcripts on non-antitrust matters

6210170238 Transcript of 821015 prehearing conference re license renewals in Dethesda.MD Pp 652-738

\* Atomic Safety and Licensing Board Panel 82/10/15 97pp
15742 230 24% Fiche 50-170.82/10/15.8210170238

DOCKET 50-182 PURDUE UNIV RESEARCH REACTOR

## P Operating license stage documents & correspondence

8210050540 Forwards Amend 6 to License R-87 & safety evaluation Amend changes Tech Specs re drop times of shim safety rods & time intervals between meetings or surveillance action THOMAS. O Standardization & Special Projects Branch
STANSBERRY. E R Purdus Univ 2pp 19637 204 24x
Fiche 50-192, 82/09/13, 8210050540

--B210030543 Amend A to License R-B7, changing Tech Spec limits on drup times of shim safety rods & changing certain surveillance Therwals

THOMAS, C O Standardization & Special Projects Branch

11ap 15637 206 24X Fiche \$0-182,82/09/13,8210050540

--8210050548 Safety evaluation supporting Amend 6 to License R-8/

\* Office of Nuclear Reactor Regulation, Director 82/09/13
15537 217 24X Ficha 50-182-82/09/13,8210050540 82/09/13 3pp

DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR G Inspection reports: IE Bulletins & correspondence

8210270300 Forwards IE Insp Rept 50-184/82-02 on 820708-10 & notice of violation
STAROSTECKI.R Division of Project & Resident Programs 82/10/08

--8210270301 Notice of violation from insp on 820708-10 \* Division of Project & Resident Programs 82/10/08. 1p 15855 038. 24% Fiche, 50-184, 82/10/08, 8210290300

--8210290304 IE Insp Rept 50-184/82-02 on 820908-10 Noncompliance noted PLOGGOUGH IE INSPIRED SUPERSON OF MEMORIAN NORGEMEITAICS NOTE failure to instruct worker in precautions, procedures, purposes & functions of protective devices used to minimize personal exposure to radioactive mail & radiation KINNEY, W W . KEIMIG.R R Division of Project & Resident Programs BR/09/28 9pp 18855-039 24X Fichs 50-184.82/10/08,8210290300

# R Periodic operating reports & related correspondence

8210130160 Forwards "Operations Rept 33, Jan-June 1982,"
CARTERR S Commerce Dept of National Bureau of Standards
82/09/30 THOMAS, C O Standardization & Special Projects Branch
1p 15673 066 24X Fiche 50-184,82/09/30,8210130160.

--8210130163 "Operations Rept 33, Jan-June 1982 "
CARTER,R 8 Commerce, Dept of, National Bureau of Standards 82/09/30 5pp. 15673 067 24X Fiche 50-184,82/09/30,8210130160

DOCKET 50-186 UNIV OF MISSOURI RESEARCH REACTOR

- O Inspection reports, IE Bulletins & correspondence
- 8210050359 Forwards IE Insp Rept 50-186/82-01 on 820816-17 & notice of Division of Engineering & Technical Programs ALDER, D.M. Hissouri, Univ. of. Columbia 2pp. (5609-00) Fiche 50-(86, 82/09/15, 2210050359
- --810050365 Notice of violation from insp on 8208[6-17 HILLER, JR Division of Engineering & Technical Programs 82/09/15 2pp 15609 003 24% Fiche 50~186,82/09/15,82100억0 1학년

--8210050380 JE Insp Rept 50-186/82-01 on 820816-17 Noncompliance noted failure to perform surveys, to post radiation & radioactive matis area & storage of radwaste at unauthorized radioactive mass area of the confisher facility
LOVENDALE,P C , GRANT,W B , GREGER,L R Division of Engineering &
Technical Programs 82/09/14 8pp 15409 005 24X
Fiche 50-184,82/09/15,8210050359

DOCKET 50-189 KANSAS STATE UNIV RESCARCH REACTOR R Periodic operating reports & related correspondence

8210190365 Submits list of facility procedure changes tests & experiments for Oct 1981-Sept 1982.per 10CFR50 59(b) FAU.R E Kansas State Univ 82/10/11 MILLER, J. R. Standa & Special Projects Branch 2pp 15/40 316 24X F(che 50-188, 82/10/11, 8210190365 Standardreatton

DOCKET 50-192 UNIV OF TEXAS RESEARCH REACTOR

- P Operating license stage documents & correspondence
- 8210050174 Forwards description of mods to be made to reactor instrumentation & control sys Changes will modernize function or reliability of current console functions Phase i.Parts A & B of changes completed BAVER.T L. Texas. Univ of 82/07/30 HUNNICUIT Region 4, Uffile of Director 14pp 15604 124 24X Fiche 50-192,82/07/30. 8210050174

DOCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR

- P Operating license stage documents & correspondence
- 8210050341 Requests guidance on procedure for renewal of 10-yr tilenam R-94.which expires on B30930 KANE,R S Manhattan College 82/09/28 BERNARD,H Standardiration & Special Projects Branch ip 15610 120 24x Fiche 50-199, 82/09/28,8210050341
- 8210260506 Responds to 820928 request for guidance in proparing application to renew license NRC evaluations of recent applications encl W/o encl
  THOMAS, C O Standardization & Special Projects Branch 82/10/14
  KANE.R S Manhattan College 2pp 15830 156 24X
  Fiche 90-179,82/10/14.8210260506

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

- @ Adjuditatory correspondence
- 6210260581 Forwards NFS & NY State Energy R&D Authority 820716 joint ltr notifying of 820716 settlement date Settlement satisfies all three conditions of Paragraph 8 A of License CSF-1 for termination of NFS authority & responsibility under license EDOAR.9 L Morgan, Lewis & Bockius EDOAR.9 L Nuclear Fuel Services, Inc (subs of Getty Oil Co ) 82/07/16 CUNNINGHAM.8 L Division of Fuel Cycle & Material Safety ip 19830 143 24% Fiche. 30-201, 82/07/16, 8210260581
- --8210260582 Notifies of 820916 settlement date Settlement satisfies all three conditions of Paragraph B A of License CSF-1 for termination of NFS authority & responsibility under license. JACK: A New York: State of: Energy Research & Development Administration DEUSTER; R W Huclear Fuel Services. Inc. (subsof Getty Dil Co.) 82/09/16 CUNNINDHAM: R Division of Fuel Cycle & Material Safety. Ip 15830 144 24X Fiche 50-201:82/09/16.8210260581

- 8210070183 Informs that time for Commission to review ALAB-679 expired Commission declined review Decision became final agency action on 821001 CHILK S.J. Office of the Secretary of the Commission 82/10/05 Office of the Executive Legal Director 1p 15634 261 24X Fichs 50-201.82/10/05.8210070183
- Operating license stage documents & correspondence
- 3210210041 GEDMORPHIC PROCESSES AND EVOLUTION OF BUTTERMILK VALLEY AND SELECTED TRIBUTARIES.MEST VALLEY.NEW YORK BOOTHROYD, J C, TIMBON.B S, DUNNE, L A New York, State of FIN B-6350 NURREC/CR-2862 82/07/31 Division of Health, Siting & Environment 117pp 15785 255 24X Fiche 50-201.82/07/31.
- \$210260981 Forwards NFS & NY State Energy R&D Authority 820916 joint litr notifying of 820916 settlement date Settlement satisfies all three conditions of Paragraph 8 A of License CSF-1 for termination of NFS authority & responsibility under license EDGAR.G L. Morgan, Leuis & Bockius EDGAR.G L. Nuclear Fuel Services. Inc (subs of Cetty Dil Co ) 82/09/16 CUNNINGHAM.R E Division of Fuel Cycle & Material Safety ip 15830 143 24X Fichs 50-201.82/09/16.8210260581
- -8210260582 Notifies of 820916 settlement date Settlement satisfies all three conditions of Paragraph 8 A of License CSF-1 for termination of NFS authority & responsibility under license JACK, R A New York, State of, Energy Research & Development Administration DEUSTER, R W Nuclear Fuel Services, Inc (subs of Cetty Dil Co) 82/09/16 CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 1p 15830 144 24X Fiche 50-201,82/09/16,8210260581
- PIOIBO414 Notification of contract execution. Mod 4 to "West Valley Haste Burial" Contractor State Univ of NY. Albany JACOBS. A Research Contracts Branch FIN B-6350 82/09/26 BATSON W. NICHOLSON.J Office of Nuclear Regulatory Research. Director 1p 15745 275 24X Fishe 50-201.82/09/26.8210180414
- -8210180419 Mod 4, extending period of performance to 831231 to "West Valley Waste Durial" MAURER, R. J. New York, State of GUSTAVE, R.P. Division of Contracts FIN 8-6350 82/09/24 12pp 15745 276 24X Fiche 50~201,82/09/24,8210180414
- OCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

  Security, medical, emergency & fire protection plans
- 210080210 Ack receipt of 820710 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-206/82-21 BIEHOP, I W Division of Resident, Reactor Project & Engineering Programs 82/10/04 FD9/AFTY, D J Bouthern California Edison Co ip 15640 080 24X Fiche 50-206,82/10/04,8210080210
- -8210080211 Responds to NRC 820812 ltr re violations noted in IE Insp Rept 50-206/82-21 Corrective actions nonfire retardant wood, orly rags & combustible debris romoved from areas & amend to include smergency light impairment prepared FOOARTY, D & Southern California Edison Co 82/09/10 ENGELKEN, R H. Region 5, Office of Director 5pp 15640 081 24X Fiche 50-206,82/10/04,8210080210
- 210190525 Forwards Revision 7 to physical security plan Revision withheld (ref 10CFR73 21)
  BASKIN:K P Southern California Edison Ca 82/10/15 EIBENHUT, D 0
  Office of Muclear Reactor Regulation, Director 1p 15740 035
  24x Fich 50-206, 82/10/15, 8210190825
- Operating license stage documents & correspondence
- PIGEBOOID Responds to FOIA request for all internal non-public documents, memos, evaluation repts & other math dealing w/ nuclear plant operations forwards documents listed in App A FELTON. J M Division of Rules and Records 82/09/17 MCINNIS. D News & Observer 5pp 15860 045 24X Fiche 50-000, 82/09/17. 8210280013
- 8210280082 "Dasimetry Placement for Steam Generator Workers "
  WARNOCK,R Institute of Nuclear Power Operations 82/01/31
  13pp 15860 310 24% Fiche 50-000,82/09/17,8210280013
- 10050300 Forwards draft evaluation of SEP Topic III-7 B. "Design Codes. Design Criteria & Load Combinations " Response to factual correctness of SER & proposed schedule for resolution of open items requested within 30 days PAULSUN. U Operating Reactors Branch 5 82/09/21 DIETCH.R Southern California Edison Co 11pp 15602 OOI 24X Fiche 50-206.82/09/21.8210050300

- ---B208170083 "Design Codes, Design Criteria & Loading Combinations (SEP. III-7D), "technical evaluation rept STILKELL.T C Franklin Instalute/Franklin Research Center NRC-03-79-118 TER-C5257-318 82/08/13 PERSINKO, D NRC No Detailed Affiliation Given 222pp 15602 012 24X Fiche 50-206, 82/09/21, 8210050300
- --0207300222 Draft "SEP Structural Review of San Dnofre Unit 1 Containment Structure Under Combined Loads" LOIT Lawrence Livermore Laboratory FIN A-0436 UCID-17141 DRFT 82/05/31 45pp 15602 234 24X Fiche 50-206.82/09/21, 82
- 8210060003 Requests submittal of fees for 820625 application for Amend 62 to License DPR-62.permitting delay in safety injection sys hydraulic valve testing MILLER.W O License Fee Management Branch 62/09/23 DIETCH.R Southern California Edison Co ip 15636 266 24X Fichs 50-206.82/09/23,8210060003
- 8210040062 Forwards safety evaluation rept & technical evaluation re main steam line break w/continued resolvator addition Analysis acceptable CRUTCHFIELD.D Deparating Reactors Branch 5 82/09/27 DIETCH.R Southern California Edison Co. 2pp 15584 178 24x Fiche 30-206.82/09/27,8210040062
- ~-8210040064 Safety evaluation re main steam line break w/continued feedwater addition Licensee commitment acceptable w/installation of auxiliary feedwater motor driven pump w/pump runout protection ◄ Office of Nuclear Reactor Regulation, Director 82/09/27 7pp 15884 IBO 24X Fiche 50-206.82/09/27,8210040062
- --8206030064 "PNR Main Steam Line Break W/Continued Feedwater Addition," technical evaluation rept VOSBURY.F W Franklin Institute/Franklin Research Center NRC-03-81-130 TER-05506-151 82/05/28 HEARN,P NRC No Detailed Affiliation Given 25pp 15584 187 24X Fiche 50-206,82/09/27:8210040062
- 8210040153 Advises that util proposed masonry wall test program acceptable, subj to satisfactory resolution of concerns delineated in encl evaluation Addl info requested no later than 30 days prior to proposed restart data PAULSON. W Operating Reactors Branch 5 82/09/29 DIETCH, R Bouthern California Edison Co. App. 15582 341 24% Fiche 50-206.82/09/29.8210040153
- 8210040177 Forwards "Seismic Evaluation of Reinforced Concrete Masonry Walls: San Onofre Unit 1," Vol 5 Fuel Storage Bidg Soil Backfill Condition Evaluation, per SEP Topic III-6 No addl mods required to fuel storage bldg BASKIN.K P Bouthern Callfornia Edison Co B2/09/3D CRUTCHFIELD, D Operating Reactors Branch 5 1p 15582 045 24X Fiche 50-206: 82/09/30: B210040177
- --8210040178 "Seismic Evaluation of Reinforced Concrete Masonry Walls, San Onofre Unit 1," Vol 5 Fuel Storage Bldg Soil Backfill Condition Evaluation \* Computech Engineering Services, Inc. R543-02 VOS 82/09/30 159pp 15582 046 24X Fiche 50-206,82/09/30,8210040177
- 8210130276 Forwards abstract of paper on experience gained in evaluating effects of high energy line breaks at facility Paper will be presented at ASME Pressure Vassel & Piping Div 2 Analysis Committee 4th Natl Congress

  BASKIN.K P Snuthern California Edison Co 82/10/04 CHEN, P NRC No Detailed Affiltation Given 2pp 19678 165 24X

  Fichs 90-206, 82/10/04,8210130274
- 8210260249 Provides add1 info supporting 820923 position that no fees are required for Amend 62 issued 820825 Surveillance program previously submitted w/Amend 57 for which appropriate fees applied BASKIN.K P Southern Celifornia Edison Co 82/10/04 MILLER.W C License Fee Management Branch in 18799: 352 24X Fiche 30-206.82/10/04.82102260249
- 8210070082 Discusses use of radwaste solidification sys Unit 2 license condition does not prevent util from using Chem-Nuclear Sys. Inc process to solidify wet solid radwaste produced at Unit 1 Safety evaluation will be performed BASKIN.K P Southern California Edison Co 82/10/05 CRUICHFIELD, D Operating Reactors Branch 3 2pp 15628 162, 24% Fithe 50-206,82/10/05,8210070082
- B2100B0093 Informs that crane operating, maint & insp procedures implemented on B21001 per B2070A ltr. insuring compliance w/NUREO-0612 Cost & implementation schedule of Item 1/3 to be completed by B21215 due to vendor delays KRIEOER,R W Southern California Edison Co B2/10/05 CRUTCHFIELD, D Operating Reactors Branch 5 lp 15640 234 24X Fiche 30-206.82/10/05.82100B0093

- 821013008B Responds to 820825 ltr requesting info re SEP Topics [II-2 & III-4 A. "Mind & Formado" be withheld Request cannot be approved until appropriate affidavit submitted CRUTCHFIELD. O Operating Reactors Branch 5 82/10/05 DIETCH.R Bouthern Callfornia Edison Ca 2pp 15473 124 24X Fiche 50-206. 82/10/05, 8210130088
- 8210180070 Forwards Amend 64 to License BPR-13, safety evaluation to notice of issuance & availability Amend revises App A Tech Specs & bases to reflect revised time intervals for entering various subcritical modes CRUTCHFIELD D. Operating Reactors Branch 5 82/10/06 DIETCH.R Southern California Edison Co. 3pp. 15719 351 24X Fichs 50-206, 82/10/06, 82/0180070
- --8210180073 Amend 44 to License DPR-13, revising App A Tech Specs & bases to reflect revised time intervals for entering various subcritical operational modes when limiting condition cannot be satisfied CRUTCHFIECD, D. Operating Reactors Branch \$ 82/10/06 7pp 157/9 354 24X Fiche 50-206, 82/10/06.8210180070
- --8210180076 Safety evaluation supporting Amend 64 to License DPR-13 4 Office of Nuclear Reactor Regulation, Director 82/10/06 Jpp 15719 361 24X Fiche 50-206.62/10/06.8210180070
- --8210180077 Notice of issuance & availability of Amend 64 to License PR-13 CRUTCHFIELD, D Operating Reactors Branch 5 82/10/06 2pp 15720 OOL 24% Fiche 50-206.82/10/06.8210180070
- 8210130324 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820909 ltm Staff encouraged to develop & implement means to incorporate positive attributes of Phase III in iscensee/NRC interface MACICH.R M SEP Owners Group 82/10/07 ETSENHUY.D G Division of Licensing 7pp 15482 177 24X Fiche 50-000.82/10/07,8210130326
- 8210190065 Clarifies NRC 920630 request for add1 info re TMI Item II B 3, "Post-Accident Sampling Sys" CRUTCHFIELD D Operating Reactors Branch 5 82/10/07 DIETCH,R Southern California Edison Co 3pp 15720 007 24X Fiche 50-206, 82/10/07,8210180065
- 6210240214 Advises that final evaluation to determine applicability of EPRI program test results for power operated relief valves, safety valves & block valves.per TMI I tem [I D I, will be sent by 821130 Delay due to need for add I analyses KRIEOER.R W Southern California Edison Co 82/10/08 CRUTCHFIELD.D Operating Reactors Branch 5 ip 15804 265 24X Fiche 50-204.82/10/08,6210240214
- 8210150144 Submits updated schedules re NUREC-0737. Items II E 1 2, "Auxiliary Feedwater Initiation & Flow Indication."

  I A 1 3 1, "Limit Overtime," II D 1, "Performance Testing of PMR Relief & Safety Valves" & III D 3 4

  BASKIN.X F Southern California Edison Co 82/10/12
  CAUTCHIELD.D Operating Reactors Branch 5 2pp 15697 292 24X

  Fiche 50-206, 82/10/12,8210150144
- 8210200023 Forwards draft evaluation of SEP Topic 181-4 C. "Internally Canenated Missles " Facility adequately protected from internally generated missles PAULSON. H Operating Reactors Branch 5 82/10/12 DIETCH. R Southern California Edison Co. 33pp 19757 230 24X Fichs 50-206.82/10/12,8210200029
- B21015029B Notification of B21021 meeting w/util at plant site to discuss soil parameters re-seismic re-evaluation per BEP Topics III—6 & II-4 1
  PAULSON.W A Operating Reactors Branch 5 B2/10/13 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 15706 132 24X Fiche 50-206. 82/10/13.821015027B
- 8210190671 Summary of 821001 meeting w/util in Bethesda, MD re scope of seismic remevaluation program Addl info re vent stack, electrical equipment & instrument supports required PAULSON. WA A Operating Reactors Branch 5 82/10/13 Operating Reactors Branch 5 59 15737 248 24X Fiche 50-206, 82/10/13. 8210190671
- 8210240448 Advises that safety-grade replacements for commercial grade anneter & transducer have been received & will be installed prior to return to power from current outage Upgrades complete necessary compliance w/MUREO-0737, Item II E 1 2 BASKIN,K P Southern California Edison Co 82/10/14 CRUTCHFIELD, D Depreting Reactors Branch 5 1p. 15806 154, 24X Fiche-50-206, 92/10/14, 8250260448

- 5210260272 Requests additime to complete proposed Tech Specs recontainment leakage testing, reflecting App J of 10CFR50, as requested in MRC 820803 ltr Proposed Tech Specs expected to be submitted by 821100 KRIEOER, RW Bouthern California Edison Co 82/10/15 CRUTCHFIELD, D. Operating Reactors Branch 5 ip 15801 351 24% Fiche 50-206, 82/10/15, 8210260272
- 8210260229 Forwards request for additinfo to assist in NRC review of SEP Topic II-4 F, "Settlement of Foundations & Burled Equipment "Revised SAR incorporating appropriate revisions re soil conditions should be submitted CRUTCHFIELD.D Operating Reactors Branch 5 82/10/18 DIETCH.R Southern California Edison Co 9pp 15799 139 24X Fiche 50-206.82/10/18.8210260229
- 8210260450 Forwards "Status of Category A Unresolved Safety lissues at San Onofre Nuclear Generating Station Unit 1" Rept provides description of each issue & discussion of NRC generic bases for continued operation & sate specific considerations MEDFORD, MO Southern California Edison Co 82/10/20 CRUTCHFIELD, D Operating Reactors Branch 5 40pp £5806 155 ,14% Fiche 50-206.82/10/20.8210260450
- 8210260472 Forwards supplemental info rept re NUREG-0612. "Control of Heavy Loads at Nuclear Power Plants" Rept contains commitments requiring changes to crane operating procedures to be implemented by 830115

  BASKIN.K P. Squthern California Edison Co. 82/10/21

  CRUICHFIELD. D. Operating Reactors Brench 5 1p 15807 230 P4x

  Fiche 50-206.82/10/21.8210260472
- ---8210260477 "Control of Heavy Loads, San Onofre Nuclear Generating Station Unit 1." supplemental info rept 4 Southern California Edison Co 82/10/31 22pp 15807 211 244 Fiche 50-206, 82/10/21, 8210260472
- B210290169 Forwards Amend 65 to License DPR-13 safety evaluation & notice of Issuance & availability Amend incorporates NUREG-0737. Item If E i 1. "Auxiliary Feedwater Pumps & Valves" into Tech Specs CRUTCHFIELD. D. Operating Reactors Branch 5 82/10/22 DIETCH. (I Southern California Edison Co. 3pp. 15854 189 24X Fiche 50-206. ()2/10/22, 8210290169
- --8210290175 Amend 65 to License DPR-13.incorporating NUREG-0737.ltrm IT E 1 1. "Auxiliary Feedwater Pumps & Valves" into Tech Specs CRUTCHFIELD.D Operating Reactors Branch 5 82/10/22 5pp 15884 192 24X Fiche 50-206.82/10/22.8210290169
- --8210290180 Safety evaluation supporting Amend 65 to License DPN 13 4 Office of Nuclear Reactor Regulation. Director 82/10/22 15pp 15854 197 244 Fiche 50-206.82/10/22,8210290189
- --8210290183 Notice of issuance & availability of Amend 65 to License DRR-13 GRUTCHFIELD, D. Operating Reactors Branch 5 82/10/22 2pp 18854 212 24X Fiche 50-204, 82/10/22,8210290169
- O Inspection reports: IE Bulletins & correspondence
- 821001000B Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UBELL.R A Critical Mass Energy Project 15pp 15727 005 24% Fiche 50-000.82/06/28.821001000B
- --8111191042 Comments on draft IE circular re MSIV failures to close Problem W/Control air for MSIV may be part of larger spectrum of problems for many valves MICHELSON, C Director's Office Gi/10/01 JDRDAN, E L Division of Resident & Regional Reactor Inspection ip I5730 335 24X Fiche 50-000, 82/06/28, 8210010008
- 8210070007 Responds to FOIA request for eight categories of records restam generators & steam turbines App A documents provided in R Udell FDIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 82/08/10 LONG, D J Winthrog, Stimson, Putnam & Roberts 9pp 13645 063 24X Fiche 50-000, 82/08/10, 8210070007
- --8210070139 Forwards tabulated data on steam generator insp & maint at factilities Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VAROA.S Operating Reactors Branch 1 CLARK.R Operating Reactors Branch 3 STOLZ.J Operating Reactors Branch 4 Spp 15445 131 24X Fiche 50-000, 82/08/10,8210070007

- -8210070172 Forwards info re steam generator integrity & insps at all operating PMRs.per 750320 & 21 requests Details of insps.
  including defect indications, tube plugging criteria & tubes plugged will not be provided escept for Point Deach (
  GDLLER R R Division of Reactor Licensing (NRR-1975 only)
  75/03/24 MACCARY.R B Division of Technical Review (NRR-1975 only)
  5pp 15645 196 24% Fiche 50-000/82/08/10,8210070007
- 210060264 Forwards IE Insp Rept 50-206/82-24 on 820802-31 No noncompliance moted

  BISHOP.T & Division or Resident. Reactor Project & Engineering

  Programs 82/09/17 PAPAY.L T Southern California Edison Copp 15519 309 24 (Fiche 50-206.82/09/17, 8210060264
- -8210060269 [E Insp Rept 50-206/82-24 on 820802-3] No noncompliance 10060264 IE Insp Hept 50-206/82-24 on 820602-31 No noncompilance noted Major areas inspected plant operations during long-term shutdown annual review of plant operations, monthly maint 8 surveyllance activities & LER followup MILLER L. KIRSCH.D F. Division of Resident, Roactor Project & Engineering Programs 82/09/16 App 15619 3[1 247 Fiche 50-204.82/09/17:8210060264
- 110040294 Forwards IE Insp Rept 50-204/82-25 on 820830-0903 No noncompliance noted

  BIGHGP, T W Division of Resident, Reactor Project & Engineering

  Programs 82/09/21 PAPAY, L T Southern California Edison Co

  2pp 15619 223 24x Fishe 30-206,82/09/21,8210060294
- 8210050299 IE Insp Rept 50-206/82-25 on 820830-0903 No noncompliance elgobory it inspirely su-206/82-25 on H20830-0903 No noncompliance noted Major areas inspected const activities associated w/seismic upgrading of safety-related structures & supports MACN-R.W. J. ZMETZIG.G B. Division of Resident. Reactor Project & Engineering Programs. 82/09/17 Spp. 15619 225 24X Fiche 50-206.82/09/21.8210060294
- '10170232 Ark receipt of payment of civil penalties imposed on 620811 Proposed corrective action will be examined in future insp. AKEIRAD. J. A. Enforcement Staff 82/09/22 PAPAY.L T. Southern falltornia Edison (c. 2pp. 15758 175 24X Fiche 50-206.82/09/22,
- 1001004P Canfirms 82102) mgt meeting in Rosemead.CA to discuss tystemafic assessment of licensee performance Anticipated meeting attendees & agenda encl CREWS.J L Division of Resident. Reactor Project & Engineering Programs 82/09/27 PAPAY.L T Southern California Edison Co Rpp 15565 317 24x Fiche 50-206.82/09/27,8210010042
- (0250302 Forwards info per Item 3 of IE Bulletin 62-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants " Rapts required Item 4 will be submitted within 70 days of outage completion
- HATNEB.J G Bouthern California Edison Co 82/10/01 Region 5, Orfice of Director 5pp 15790 200 24x Fichs 50-206, 82/10/01.8210250302 82/10/01 ENGELKEN, R H
- TORBUZIO Ack receipt of 820710 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-206/82-21 BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 82/10/04 FOGARTY,D J Southern California Edison Co ip 15440 080 24X Fiche 50-204/82/10/04/8210080210
- 6210060211 Responds to NRC 620812 ltr re violations noted in It Insp Rept 50-202/82-21 Corrective actions nonfire retardant wood, only rags & combustible debris removed from areas & amend to Include emergency light impairment prepared
  FDGARTY D J Southern Colifornia Edison Co 82/09/10
  FNGELKCN, R H Region 5. Office of Director 5pp 15640 081 24X
  Fiche 50-206, 82/10/04-8210080210
- 10080212 Ack receipt of 820907 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-206/82-23
  BISHGP.T U Division of Resident. Reactor Project & Engineering Programs 82/10/04 PAPA/L T Southern California Edison Co ip 15438 086 24% Fiche 50-206.82/10/04.8210080212
- 82:0080214 Responds to NRC 820812 ltr re violations noted in 1E Insp Rept 50-206/82-23 Corrective actions station procedure Rept 50-206/82-23 Corrective actions station procedure amended to include instructions on drawing reactor coplant samples from all locations & double valve verification PAPAYL T Southern California Edison Co 82/09/07 ENGELKEN, R H Region 5, Office of Director 3pp 15638 (Fiche 50-206.82/10/04.8210080212 , 15938 08/ 54X
- OB190233 IE Info Notice 80-35, Suppl i, "Leaking & Dislodged I-125 Implant Beeds" Svc list encl
  COBB.L I Division of Fuel Facilities, Materials & Safeguards
  82/10/06 Consolidated Edison Co of New York 66pp 19741 250
  24X Fiche 50-000.82/10/06.8208190233

- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- S Reportable occurrences, LERs & related correspondence
- 8210080124 Recommends that 810717 event reagnition of gaseous waste decay tank should be considered for inclusion in NRC third quarterly AD rept to Congress for 1981 Details of event ORNSTEIN.H L Director's Office 81/08/06 MICHELSON.C Director's Office Jpp 15663 285 24X Fiche 50-206.81/08/06.8210080124
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J H. Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24x Fichs 50~000.82/06/28.8210010008
- --8108130268 Forwards details re 810717 ignition of gaseous waste decay tank at facility Event should be included in Commission thank at facility Event should be included in Commission third quarterly AO rept to Congress for 1981 ORNSTEIN.H L. Director's Office BI/08/06 MICHELSON, C Director's Office Jpp 15730 103 24X Fiche 50-000, 82/06/28, 8210010008
- --8111300367 Operating Reactor Event Memorandum 81-32 on 810903, control INSUUSA/ Operating reactor Event Hemorandum di-32 on Bio703 Contro room operator manually tripped reactor after transient from 88% power initiation by steam generator flow & level oscillator Caused by regulated power supply failure EISENHUT, D @ Division of Licensing 81/10/31 VGLLMER,R H Division of Engineering HANAVER,S H Division of Human Factors Safety MATTSON,R U Division of Safety Technology 7pp Safety MATTSON, R J Division of Safety Techno 15731 059 24X Fiche 50-000, 82/04/28, 8210010008
- --8201150180 Forwards draft FR notice re 810903 AD on failure of high Polibutto Forwards grant in notice re allows he on failure or nigity pressure safety injection sys
  DIRCKS.W J Office of the Executive Director for Operations
  B1/12/08 CHILK.S J Office of the Secretary of the Commission
  Ppp 19732 007 24X Fiche 50-000.82/06/28.8210010009
- 8210010260 PNO-V-82-038A on 820922, one truckload of trace contaminated (10010260 PNU-V-82-0384 on 82092) one truckload of trace con sewage dwmped at Los Angeles County sewage treatment facility Contamination found in rinse truck Truck returned to licensee for decontamination Addl samples will be taken VUMAS. C. NENSLAWSKI.F. Region 5. Office of Director 82/ 1p 15574 055 24% Fiche 50-204.82/09/24.8210010240
- 6210190490 Forwards revised LES 81-025/01%-2 Detailed event analysis RAY.H B Southern California Edison Co 82/10/06 Region 5. Office of Director 2pp 15735 335 24x Fiche 50-206,82/10/06,8210190490 ENGELKEN: R. H
- --B210190506 Revised LER B1-025/01X-2 on B11025, while conducting co' shutdown valve testing, ball valve CV-534 did not close automatically on isolation signal Caused by failed relay closing circuit of each valve Relays replaced RAY, H B Southern California Edison Co B2/10/06 Re Office of Director 1p 15735 337 24X Fiche 50-206, 82 8210190490
- 8210250280 RD 82-025 on 821012 & 13 fire watch patrol posted lubrication oil reservoir area but not at post Time period exceeded 1-h interval by 30 minutes Caused by personnel misunderstanding Mayonderstanding RAY,H D Southern California Edison Co 82/10 Region 5, Office of Director 2pp 15791 096 Fiche 50-206, 82/10/14, 8210250280 82/10/14
- 8210280066 Forwards LER 82-023/03L-0 Detailed event analysi RAY, H B Southern California Edison Co 82/10/19 ENGE Region 5, Office of Director 2pp 15837 249 24X Fiche 50-206.82/10/19,8210280066 19 ENGELK 24X
- ~-8210280068 LER B2~023/03L-0 on 820919, fire water crosstie d ZIOZEDUCEN LEN B2-OXI/VSI-O on B20719; fire water crosstie d during new const activities Caused by incorrect const digging process West fire water pump returned to svc flack fire suppression hoses rigged RAY, H B. Southern California Edison Co 82/10/19 Re Office of Director ip 15837 251 24X Fichs 50-206.82 8210280066

## V Operator Examinations

- 8210290314 Forwards "Improvements in Training & Requalification Programs as Required by TMI Action Items I A 2 1 & 11 B 4 for San Onofre Nuclear Generating Station.Unit I." technical evaluation rept Training programs acceptable CRUTCHFIELD. D. Operating Reactors Branch 5 82/10/26 DIEYCH.R Southern California Edison Co. 3pp 15894 101 24X Fiche 50-206.82/10/26.8210290316
- --B210290320 "Improvements in Training & Requalification Programs as Required by THI Action Items I A 2 1 & If B 4 for San Gnofre Nuclear Generating Station, Unit i," technical evaluation rept

  = Stience Applications, Inc. NRC-03-B2-096 SAI-186-029-17 B2/08/17 NRC No Detailed Affiliation Given 15pp 15854 104 24X Fiche 50-206, 82/10/26,8210290316

#### DOCKET 50-208 COLUMBIA UNIV RESEARCH REACTOR

- P Operating license stage documents & correspondence
- 8210270307 Advises that reactor has never been fueled or operated Fuel not on campus No plans to activate reactor in near future Requests variance to 10CFR50.App E requirements until anticipated reactor startup MELKONIAN.E Columbia Univ 82/10/12 DENTON.H R Office of Nuclear Reactor Regulation, Director [p 15853 166 24X Fiche 50-208, 82/10/12, 8210270307

#### DOCKET 50-213 HADDAM NECK PLANT

- P Operating license stage documents & correspondence
- 8209300326 Forwards "Geological & Szismological Studies.Haddam Neck Nuclear Station:Part I Responses to 1977 NRC Info Request" & "Part II Responses to 1981 NRC Info Request," in response to BEP Topics 11-4 & II-4 B COUNSIL.W G Connecticut Yankee Atomic Power Co 82/09/22, CRUTCHFIELD, D Operating Reactors Branch 5 2pp 15557-179 24X Fiche 50-213,82/09/22,8209300324
- --8209300332 "Geologica) & Seismological Studies Haddam Neck Nuclear Station Part I Responses to 1979 NRC Info Request " Tuelve oversize figures encl Aperture cards are available in PDR \* Nestern Geophysical, 82/09/30 194pp 15557 181 24X Fiche 50-213,82/09/22,8209300326
- 8210010207 Forwards "Haddam Neck Plant Procedure AOP 3 2-22-C RCS Venting of Moncondensible Gasss" & "Hillstone Nuclear Power Station RCS Venting Procedure OP 2398," in response to THI Action Plan I tam II B I. "RCS High Point Vents"
  COUNSIL.H 0. Connecticut Yantse Atomic Power Co. COUNBIL.H 0 Northeast Nuclear Energy Co. (subs of Northeast Utilities)
  COUNSIL.H 0. Northeast Utilities 82/09/22 CRUTCHFIELD.D Operating Reactors Branch 3 CLARK.R A. Uperating Reactors Branch 3 3 3pp 15568 048 24X Fiche 50-000.82/09/22.8210010207
- --8210910210 Revision 2 to "Haddam Neck Plant Procedure AOP 3 2-22-C RCB Venting of Noncondensible Gases"

  \* Connecticut Yankee Atomic Power Co. 82/08/26. 11pp 15548 051 24X Fiche 50-000.82/09/22.8210010207
- --8210010214 Revision 2 to "Millstone Nuclear Power Station Unit 2 Plant Procedure DP 2398 RCS Venting Procedure " SCACE.6 E Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/08/20 lipp 15566-062 24X Fiche 50-000.82/09/22.8210010207
- 8210010312 Requests that processing of B20812 license amend application be postponed Revised application changing radiological affluent Tech Specs will be docketed on or about 821115 for both facilities
  COUNSILW O Connecticut Yankee Atomic Pawer Co COUNBILW O. Northeast Nuclear Energy Co (subs of Northeast Utilities)
  COUNBILW O Northeast Utilities 82/09/22 CLARKER A Operating Reactors Branch S CRUTCHFIELD.D. Operating Reactors Branch 5
  3pp 15574 047. 24X Fiche 50-000.82/09/22,8210010312

- 8210190863 Responds to open items re SEP Topic III-6 "Seismic Design Considerations," per 820622-23 meetings to discuss status of seismic rerevaluation program GOUNBIL, NO Connecticut Yankee Atomic Power Co 82/09/27 CRUTCHFIELD. Operating Reactors Branch 5 5pp 15738 213 249 Fiche 50-213, 82/09/27,8210190663
- --8210190668 "Mechanical & Electrical Equipment Seismic Re-Evaluation Program.Haddam Neck Nuclear Generating Station." Interim rept 4 Stevenson & Associates 810132 | 82/06/30 224pp 15738 218 24X Fiche 50-213,82/09/27,8210190663
- 8210070010 Forwards summary of SEP topics for which facility does not meet current licensing acceptance rriteria CRUTCHFIGLD. D Operating Reactors Branch 5 82/09/30 COUNSIL, H. G. Connecticut Yankee Atomic Power Co. 45pp 15628 082 24X Fiche 50-213.82/09/30.8910070010
- 82)0130331 Discusses revision of administrative procedures to incorporate revised working hour guidelines & provisions for authorizing deviations per 820208 & 0615 requests.TMI Item I A 1 3. "Shift Manning" & Generic Ltr 82-12 COUNSIL, W 0. CAONETTAL JP Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W 0. Connecticut Yankee Atomic Power Co. 82/10/01 EISENNUT, D 0. Division of Licensing. 3pp. 15679-127. 24X Fiche 50-000.82/10/01.8210130331
- 8210070404 Advises that review indicates requirements of NUREQ-0737 Items II E 4 2 & & II E 4 2 7 re-containment isolation dependability have been met CRUTCHFIELD. D. Operating Reactors Branch 5 82/10/04 COUNSIL.N.C. Connecticut Yankee Atomic Power Co. 3pp. 15633-314 24X Fiche 50-213,82/10/04,8210070404
- 8210120296 Forwards "Haddam Neck Plant Seismic Design," technical evaluation rept
  CRUTCHFIELD, D. Operating Reactors Branch 5 FIN A-6426 ff2/10/04
  CDUNBILLU G. Connecticut Yankee Atomic Power Co. 44pp. 15654 201
  24X Fiche 50~213.82/10/04.8210120296
- --B210120300 "Haddam Nock Plant Selamic Design," technical evaluation rept BRID0EB,T L , DUSCH, S L , MORTON, D K E080, Inc FIN A-6426 EGC-EA-6016 B2/08/31 CHENO, T Division of Licensing 283pp 15654 293 24X Fiche 50-213, 82/10/04, 8210120296
- 8210130205 Forwards safety evaluation of NUREG-0737. TMI Action life II E 1 2, "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication (F-16, F-17). Haddam Neck Plant." technical evaluation rept CRUTCHFIELD. D Operating Reactors Branch 5 82/10/05 COUNSII. W Q Connecticut Yankee Atomic Power Co 6pp 15675 271 24X Fiche 30-213, 82/10/05, 8210130205
- --B20B19017B "Auxiliary Feedwater Automatic Initiation & Flow Indicatic Haddam Neck Plant," technical evaluation rept KANCHER.JE, FERTMERK Franklin Institute/Franklin Research Center NRC-03-79-11B TER-05297-294 B2/0B/17 KCNDALL,R, WIGDOR,M NRC No Detailed Affiliation Given 16pp 19675 2// 24X Fiche 50-213,B2/10/05/B210130205
- B21013032& Comments on proposed scape of Phase III of SEP as reflect+4 in individual topic definitions appended to 820707 ltr Staff accouraged to develop & implement means to incorporate positive attributes of Phase III in licensee/NRC interface KACICHR M BEP Owners Group B2/10/07 EISENHUTT. 0 0 Division of Licensing 7pp 15692 179 24% Fiche 50-000,82/10/07,821013032&
- 8210210226 Forwards safety evaluation of licenses safety assessment of SEP Topic III-5 A. "Effects of Pipe Break on Structures. Bys & Components Inside Containment "Methodology & acceptance criteria appropriate to resolve issues in safety evaluation CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/12 CQUNGIL, W.C. Connecticut Yankee Atomic Power Co. 10pp 15766 321 24X Fiche 50-213, 82/10/128210210226
- 8210270200 Forwards summary of NRC positions on 26 unresolved safety issues; consisting of excerpts from NRC publications 5 repts to Congress & assessment of generic applicability Adequate basis exists to warrant continued plant operation COUNSIL.44 0. DPEKALJF Connecticut Yankee Atumic Power Co COUNSIL.44 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/13 CRUTCHFIELD.D Dparating Reactors Brants 3 48pp 15824 254, 24X Fiche 50-000,82/10/13,8210270200
- 8210250363 Forwards \*SEP Topic VII-I A. Isolation of Reactor Protection Sys From Nonsafety Bys for Haddam Nack Plant, " final technical evaluation. CRUTCHFIELD. D Operating Reactors Branch 5 FIN A-6425 82/10/20 COUNSIL.N Q Connecticut Yankee Atomic Power Co 2pp 15790 151 24X Fiche 50-213,82/10/20.8210250363

- 8210250372 "SEP Topic VII-t A. Isolation of Reactor Protection Sys From Nonsafety Sys for Haddam Neck Plant," final technical evaluation
  - evaluation MORKEILD J., UDY.A ( EG\$0, Inc. FIN A-6425 EGG-EA-6033 52/07/30 23pp 15770 153 24x Fiche 50-213,82/10/20,8210250363

# G. Inspection reports. IE Bulletins & correspondence

- EC10070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in
  - App B FELTEN.J M Division of Rules and Records 82/08/10 LONG.D J Winthrop. Stimson. Putnam & Ruberts 9pp 15645 063 24X Fishe 50~000.82/08/10,82100/0007
  - P210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees [PPOLLITO, T Operating Reactors Assessment Branch B2/04/01 VARCA.S Operating Reactors Branch i 5pp 15645 131 24X Fiche 50-000, 82/08/10, 8210070007
  - 82100701'2 Forwards info re steam generator integrity & insps at all operating PURs, per 750320 & 21 requests Details of insps. including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach 1 GDLLER, K. R. Division or Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY, R. Division of Technical Review (NRR-1975 only) 5pp 15645 176 24X Fichs 50-000, 82/08/10, 8210070007
- 5210010332 Ack receipt of 820513 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50~213/82~03 Violation uill be rescined due to misunderstanding retermination dates of contractor employees MARTIN. I T Division of Engineering & Technical Programs 82/09/23 CCUNSTL. N G Connecticut Yankee Atomic Power Co 2pp 15549 164 24x Fiche 50~213,82/09/23,8210010332
- SCIOOSO376 Ack receipt of 820628 evaluation of SEP lopic III-3 C. Inservice Insp of Water Control Structures "No comments forwarded CDUNSIL N C Connecticut Yankee Atomic Power Co 82/09/24 (RUTCHFIELD, D Operating Reactors Branch 5 ip 15608 276 24X Fiche 50-213, 82/09/24, 82(0050376
- S2:0150699 Forwards request for add1 info to complete review of B01104 response to IE Bulletin 60-11. "Masonry Wall Design" "Rosponse expected within 60 days of ltr receipt LARK.R A Operating Reactors Branch 3 82/09/28 COUNSIL.W G (onnecticut Yankes Atomic Power Co COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 13pp 15716 100 24X Fiche 50-000.82/09/28.8210150699
- 62.08190233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged 1-12b Implant Seeds " Svc list encl (DBB.L I Division of Fuel Facilities, Materials & Safeguards B2/10/06 Consolidated Edison Co of New York 46pp 15761 250 24x Fiche 50-000,82/10/06.8208190233
- 5-309170238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants "Svc list enci DEYCUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- 5210290189 Forwards IC Insp Rept 50-213/82-17 on 820823-0926 No noncompliance noted STAROSTECKI, R Division of Project & Resident Programs 82/10/18, COUNSIL.N O Connecticut Yankee Atomic Power Co 2pp 15853 313 24% Fiche 50-213,82/10/15,8210290189
- --8210270194 IE Insp Rept 50-213/82-17 on 820823-0926 No noncompliance noted Major areas inspected facility tours, log & record review, surveillance & containment ent; REDELOMEKI, T., ELSASSER, T.C. Division of Project & Resident Programs 82/10/14 7pp 15853 315 24X Fiche 50-213.82/10/15, 8210270189
- S Reportable occurrences. LERs & related correspondence
- 9210270245 Forwards LER 81-005/03L-0 GRAVES,R H Connecticut Yankee Atomic Power Co 81/05/18 ORIER, B Region 1. Philadelphia Office of the Director (81/03/01) lp 15822 341 24X Fiche 50-213,81/05/18,8210270245

- --B210270249 LER B1-005/03L-0 on B10424, unattended welding cables found running through access in fire barrier, possibly preventing closure Caused by contractor failing to inspect fire barriers & failing to provide connectors in cables
  TEST.R Z Connecticut Yankee Atomic Power Co B1/05/18 Region
  1, Philadelphia, Office of the Director (B1/03/01) 2pp
  15822 342 24X Fiche 50-213,81/05/18.8210270245
- 8210010008 Responds to FDIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28.8210010008
- --BliiBOOOl Recommends comprehensive assessment of plant operating conditions to determine specific predetermined time related sequences of occurrence to emergency buses SRP should be revised re design features

  ABHE.F Director's Office Bl/10/16 MICHELSON.C Director's Office 4pp 15731 047 24% Fiche 50-000.B2/06/28, B21001000B
- 8210190122 Forwards LER 82-006/03L-0 CRAVES.R H Connecticut Vankee Atomic Power Co 82/10/05 HAYNES.R C Region 1, Office of Director 1p 15721 277 24X Fiche 30-213.82/10/03.2210150122
- --821015012B LER 82-006/03L-0 on 820919, emergency do battery bank II, cell 42, found leaking electrolyte through seam crack Insprevealed 11 more batteries w/cracks in same location Caused by cell plate expansion against jar & battery age QVINH. II D Connecticut Yankee Atomic Power Co 82/10/05 Region I. Office of Director 2pp 15721 278 24X Fiche 50-213, 92/10/05, 8210150122
- 9210280071 Forwards LER 82-007/03L-0 GRAVES.R H Connecticut Yankee Atomic Power Co 82/10/20 HAYNES.R C Region 1. Office of Director 1p 15837 247 24X Fiche 50-213.82/10/20.8210280071
- --8210280074 LER 82-007/03L-0 on 820927, operator received rod drive slave cycler failure/rod stop alarm-rendering all bank 8 subgroups inoperable Caused by master cycler relay hanging up due to poor relay contact Mercury wetted contacts rewet QUINN:H D Connecticut Yankee Atomic Power Co 82/10/20 Region 1, Office of Director 1p. 15837 248 24% Fiche 50-213,82/10/20.8210280071

# DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT F Security, medical, emergency & fire protection plans

- 8210220182 Ack receipt of 820812 ltr informing NRC of actions taken to improve smergency preparedness program per IE Emergency Preparedness Appraisal Rept 50-219/82-01 ALLANIJ M Region I. Office of Director. 82/10/12 FIEDLER.P D General Public Utilities GPU Service Corp 2pp 15774 328 24X Fiche 50-219.82710/12.8210220182
- --8210220187 Responds to IE Emergency Preparedness Appraisal Rept 50-219/82-01 Corrective actions training program developed, amergency control ctr moved away from control room & ventilation sys upgraded FIEDLER, P. B. General Public Utilities - QPU Bervice Corp 82/08/12 SMITH, G. H. Division of Emergency Preparedness 9p 13776, 330, 24X Fiche 50-219, 82/10/12, 8210220182
- 8210250383 Forwards Revision 13 to physical security plan Revision withheld LAGOARIH W General Public Utilities GPU Service Corp 82/10/19 Diffice of Nuclear Reactor Regulation Director 1P. 15790-134 24X Fiche 50-219.82/10/17,8210250383

## H General correspondence

- 8207180051 FOIA request for seven categories of info re nuclear math transported by M Roh in Apr 1980 to Beatty, NV & General Public Utils submissions from 800101 per Price Anderson Act VAN BYCC, C Tomer, Parks, Beliger, Simonoff & Adourian, 82/08/24 FELTON-J M. Division of Rules and Records. 2pp 15760 196 24X Fiche 50-219,82/08/24,8207180051
- 8210190163 Partial response to FOIA request for seven categories of info re nuclear math transported by M Roh in Apr 1980 to Beatty, NV & General Public Utils submissions since 800101 per Price-Anderson Act re facility Forwards App A documents FELTON, J M Division of Rules and Records. 82/09/15, VAN BYUC, C Tomar, Parks, 82/1981, Signonoff & Adourian 2pp 15760, 198 24X Fiche 50-219, 82/09/15, 8210190163

## P Operating license stage documents & correspondence

- 8210010063 Informs that Erron Test Rept XN-NF-78-12, "Spray Cooling Heat Transfer Test Results, Phase-II Facility & Test Data ENC 8:8 BMR Fuel," will be withheld per 10CFR2 790, in response to 820806 request CRUICH-IELD. O Operating Reactors Branch 5 82/09/23 FIEDLER, P. 2 General Public Utilities GPU Service Corp 3pp 15567 167 24) Fische 50-219, 82/09/22, 8210010063
- 8210010077 Forwards Mark I containment long-term program plant-unique analysis repts for suppression chamber & vent sys & torus attached piping Safety relief valve piping analyses will be completed & forwarded by 821215

  FIEDLER.P B General Public Utilities GPU Service Corp 82/09/24
  CRUTCHFIELD.D Operating Reactors Branch 5 2pp 15566 053 24X
  Fiche 50-219.82/09/24.8210010077
- --8210010091 "Gyster Creek Nuclear Generating Station Mark I Containment Long-Term Frogram.Plant-Unique Analysis Rept.Suppression Chamber & Vent Sys " \* MPR Associates, Inc. MPR-733 82/08/31 300pp 15566-055 24X Fiche 50-219.92/09/24.8210010077
- --8210010085 "Oyster Creek Nuclear Generating Station Mark I Containment Long-Term Program, Plant-Unique Analysis Rept. Torus Attached Piping " MPR Associates, Inc. MPR-734 82/08/31 157pp 15566 359 24% Fiche 50-219,82/09/24,8210010077
- 6210040261 Forwards notice of consideration of issuance of amend to provisional OL, DPR-16.re increase in spent fuel storage capacity to 2,600 assemblies CRUTCHFIELD. D. Operating Reactors Branch 5 62/09/28 FIEDLER.P. General Public Utilities OPU Service Corp 2pp 15595 003 24X Fiche 50-219.02/09/28.0210040261
- --B210040265 Notice of consideration of issuance of amend to provisional QL.DPR-16.re (norease in spent fuel storage capacity to 2.600 assamblies GRUFCHFIELD.D Operating Reactors Branch 5 82/09/28 4pp 15595 005 24X Fiche 50-219, 82/09/28, 8210040261
- 8210080053 Forwards INPO "Evaluation of Oyster Creek Nuclear Generating Station." per Moseley 810806 request & Stello 810626 memo BMITH, G H. Division of Emergency Preparedness & Operational Support 82/09/29 FALCR, G H. Division of Reactor Programs ip 15643 037 24% Fiche 50-219, 82/09/29, 8210080063
- --B2100B0079 "Evaluation of Oyster Creek Nuclear Generating Station" # Institute of Nuclear Power Operations B1/12/31 33pp 15643 038 24% Fiche 50-219.82/09/29.8210080063
- 9210270345 INTEGRATED PLANT SAFETY ASSESSMENT, SYSTEMATIC EVALUATION PROGRAM Dister Creek Nuclear Generating Station Docket 50-219 (GPU Nuclear Corporation And Jersey Central Power And Light Company)

  \*\*Bivision of Licensing NUREG-0822 DRFT 82/09/30 537pp 15850 146 24X Fiche 50-219,82/09/30,8210270345
- 8210130326 Comments on proposed scope of Phase III of SEP as reflected in indivadual topic definitions appended to 820909 itr Staff encouraged to develop & implement means to incorporate positive attributes of Phase III in licensee/NRC interface MACICH, R M SEP Owners Group 82/10/07 EISENHUT.D © Division of Licensing 7pp 15682 179 24% Fiche 50-000,82/10/07.8210130326

- 82(0190502 Advises that company no longer performing analyses for LearNuclear supplied fuel under irradiation in plant Util made
  separate arrangements Util vitilizing or planning to utilize
  fuel for operating conditions outside analyzed conditions
  OMSLEY.G F Erron Nuclear Co. Inc. (subs. of Erron Corp.)
  82/10/13 RUBENSTEINL S Assistant Director for Core & Plant
  Systems Ip [5740 198 24X Fiche 50-219.82/10/13.8210190562
- 8210200060 Forwards corrected FR notice of consideration of amoud to License DPR-66 respent fuel storage capacity published 821008 reflecting 821108 as deadline for requesting hearing CRUTCHFIELD D Operating Reactors Branch 5 82/10/13 FIFLDIM.P & General Public Utilities GPU Service Corp 4pp 15737 JB6 J41 Fiche 50-219, 82/10/13.8210200060
- 8210260182 Forwards Amend 63 to License DPR-16, safety evaluation R notice of issuance & availability Amend authorizes addition of control rod drive scram discharge vol high level & rod block to Tech Specs
  CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/15 Fieldin, P. B. General Public Utilities GPU Service Corp. 2pp. 15803, 130, 141
  Fiche 50-219, 82/10/15, 8210260182
- --8210260185 Amend 63 to Liceuse DPR-16, authorizing addition of control rod drive scram discharge vol high level & scram trip byposes rod block to Tech Spacs
  CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/15 (App. 1880) 292 244 Fiche 50-219,82/10/15,8210260182
- --8210260187 Safety evaluation supporting Amend 63 to License 10th 16 of Orfice of Nuclear Reactor Regulation, Director 62/10/15 15803 241 24X Fishe 50-219.82/10/15, 8210260182
- --B202010167 "Technical Evaluation Rept for BWR Scram Discharge Vol Long-Term Mods Dyster Cieek Nuclear Generating Station "HUCHA,E Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-58 B2/01/27 ECCLESTON,K NMC Mu Detailed Affiliation Given 55pp 15803 244 24X Fiche 50-219, 82/10/15, 8210206182
- --8210260191 Notice of insuance & availability of Amend 63 to (icen) e DPR-16 CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/15 Pμρ 15803 298 24X Fiche 50-219.02/10/15.8210240182
- 8210210280 Submits add1 comments on SEP Phase II During final stages of SEP.NRC properly & effectively assessed safety intent of SRPs & evaluated merits of alternative proposals CLARK.PR General Public Utilities GPU Service Corp. 82/10/18 CRUTCHFIELD.D Operating Reactors Branch 5 2pp. 15/63 148 244 Fiche 50-219.82/10/18.8210210280
- 8210250136 Forwards info re reactor protection sys power supply.in response to 820702 request for addl info Periodic functional testing will be performed on assemblies by removing motor generator set from distribution bus FIEDLER.P B General Public Utilities GPU Service Corp 02/10/16 CRUTCHFIELD.D Operating Reactors Branch 3 2pp 15707 005 24x Fiche 50-219, 82/10/18,6210250136
- 8210250187 Requests approval of Tech Spec Change Request 80 re adequaty of station electric distribution sys voltages & degraded grid protection for Class IE power sys.in response to 811016 itrs Voltage regulators provide no safety function FIEDLER.P B Ceneral Public Utilities QPU Service Corp. 82/50/18 CRUCTRIFIELD. D. Operating Reactors Branch 5 2pp. 15708-286 244 Fiche 50-217, 82/10/18,8210250189
- G210270254 Submits corrections to discrepancies identified in util 821008 ltr re control room habitability One oversize drawing encl Aperture card is available in PDR FIEDLER.P B General Public Utilities GPU Service Corp 62/10/19 EISENHUTD Q Division of Licensing 2pp 15853 112 24X Fiche 50-219, B2/10/19, 8210299284
- 8210270202 Advises of review of deviations to stated positions contained in NUREO-0737. Item II F 1 3. "Containment High Range Radiation Honitor" Monitors expected to be installed during Cycle II refueling outage CRUTCHFIELD. D Operating Reactors Branch 5 82/10/20 FIEDLER.P 9 General Public Utilities GPU Service Corp 2pp 15823 004 24E Fiche 50-217. 82/10/20,8210270202
- 8210250284 Notification of 821103 meeting w/util in Bethesda, HD to discuss core spray sparger effectiveness in steam environ at facility LOMBARDO, J. Operating Reactors Branch 5, 82/10/21 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 15791 175 24K Fiche 30-217, 82/10/21, 8210250284

- BE10270004 Advises that response to NUREG-0737. Item II K 3 25, "Effect of Loss of AC Power on Pump Beals," acceptable, based on endorsement of BHR owners group position Mods to seal cooling for recirculation pumps not required CRUTCHH-IEED, D. Operating Reactors Branch 5 B2/10/22 FIEDLER, P. B. General Public Utilities GPU Service Corp. 7pp. 15815-353 24X Fiche 50-219, B2/10/22, 8210270004
- Q Inspection reports, IE Bulletins & correspondence
- H2(0080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events 5 safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON, J H Division of Rules and Records 82/07/12 UDELL,R A United Hass Energy Project 9pp 15665 027 24X Fiche 50-000, 82/07/12,8210080015
- --8210080140 Systematic assessment of licensee performance notes re facility evaluation for Aug 1979-Jul 1980 4 NRC - No Detailed Affiliation Given 80/07/3t 7pp 15668 ODB 24X Fiche 50-000, 82/07/12:8210080015
- 8210070268 Forwards IE Insp Rept 50-219/82-20 on 820803-0907 & notice of violation STARCSTECKLR Division of Project & Resident Programs 82/09/22 FJEDLER, P B General Public Utilities GPU Service Corp 2pp 15634 14B 24X Fiche 50-219,82/09/22,8210070268
- -9210070270 Notice of violation from insp on 820803-0907 • Division of Project & Resident Programs 82/09/22 tp 19634 t50 24% Fiche 50-219,82/09/22,8210070268
- --8210070275 IE Insp. Rept 50-219/82-20 on 820803-0907 Noncompliance noted failure to follow equipment control procedures & prepare procedures consistent w/1000720 for work involving personnel radiation exposure COMBILL.C. THOMAS. J. TRIPP.L. E. Division of Project & Resident Programs 82/09/17 10pp 15634 151 24X Fiche 50-219,82/09/22,82/09/070268
- 6210070341 Forwards IE Insp Rept 50-219/02-19 on 020002-06 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/09/24 FIEBLER.P B General Public Utilities GPU Service Corp 2pp 15634 092 24% Fiche 50-219.02/09/24.02810070341
- -8210070345 IE Insp Rept 50-219/82-19 on 820802-06 No noncompliance noted Major areas inspected licensee action on previous insp findings, radiation protection instrument calibr & training, pasting, labeling, ALARA program & radwaste program WRAY.J R. RONE.C A. GREENMAN.E 0 Division of Engineering & Technical Programs 82/09/23 Hpp 15634-094 24X Fiche 50-219.82/09/24.8210070341
- 9208190233 IE info Notice 80-35, Suppl 1, "Leaking & Distodged I-125 Implant Seeds" Svc list encl CD88.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15741 250 24/
- G210250285 Requests relief from insp of listed welds using volumetric & surface exam methods Results of review of inservice insp program requirements & justification for relief in inspecting 10 dissimilar metal welds encl
  FIEDLER: P B General Public Utilities GPU Service Corp 82/10/08
  CRUTCHFIELD. D Operating Reactors Branch 5 3pp 15791 172 24X
  Fiche 50-219. 82/10/08.8210250285
- 62:0190375 Ack receipt of 620831 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/80-17
  MARTIN T T Division of Engineering & Technical Programs 82/10/12
  FIEDLER.P B General Public Utilities OPU Service Corp 2pp
  15741 017 24X Fiche 50-219.82/10/12.8210170375
- --8210190398 Responds to NRC 820416 ltr reviolations noted in IE Insp.
  Rept 50-219/80-17 Corrective actions GA audit insp.program
  of health physics activities implemented & training &
  definitions of radiation protection staff improved
  FIEDLER.P B General Public Utilities GPU Service Corp.
  82/08/31 SMITH, G H Division of Emergency Preparedness &
  Operational Support 15pp 15741 019 24X Fiche 50-219,82/10/12,8210190375
- 8210220182 Ack receipt of 820812 ltr informing NRC of actions taken to improve emergency preparedness program per IE Emergency Preparedness Appraisal Rept 50-219/82-01
  ALLAN, J M Region I, Office of Director 82/10/12 FIEDLER, P B Oeneral Public Utilities OFU Service Corp 2pp 15776 328 24X Fiche 50-219, 82/10/12,8210220182

- --8210220187 Responds to IE Emergency Preparedness Appraisal Rept 50-219/82-01 Corrective actions training program developed, emergency control ctr moved away from control room & ventilation sys upgreded FIEDLER,P B General Public Utilities - GPU Service Corp 82/08/12 SMITH.G H Division of Emergency Preparedness 9pp 15776-330 24X Fiche 50-219.82/10/12.8210220182
- 8208190298 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Syc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- S Reportable occurrences, LERs & related correspondence
- 8210070438 Forwards engineering evaluation rept on 810827 shutdown cooling sys HX failure Failures diagnosd as fattgue Failures due to flow induced vibration Event not considered AC Repairs to be complete by 811012 LANIK.© Director's Office 7pp 15637 337 24X Fichs 50-219,81/10/15.8210070438
- 821001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28.8210010008
- ---8110230085 Forwards engineering evaluation rept on shutdown couling sys
  HX failures which occurred in late Aug 1981 Failures
  diagnosed as fatigue failures due to flow induced vibration
  Recommends event not be considered AD
  LANIK, 0 F NRC No Detailed Affiliation Given 81/10/15 NRC
   No Detailed Affiliation Given 7pp 15731 0/42 24X
  Fiche 50-000,82/06/20.8210010008
- 8210130167 Ro on 820814, normal shutdown initiated to investigate higher than normal differential pressure readings in emergency svc water sys Caused by debris blockage consisting of live & dead animal matter Organisms removed & tubes cleaned FIEDLER.P B General Public Utilities OPU Service Corp 82/07/22 HAYNES.R C Region i. Office of Director 4pp 15673 047 24X Fiche 50-219, 82/09/22, 8210130167
- 8210070178 Forwards LER 82-049/03L-O Detailed event analysis encl FIEDLER.P B General Public Utilities - GPU Service Corp 82/09/24 HAYNES.R C Region 1. Office of Director 3pp 15634 298 24X Fiche 50-219.82/09/24.8210070178
- --8210070181 LER 82-049/03L-0 on 920825, seven hydraulic snubbers failed functional testing after being replaced by certified functional spares Two snubbers had improper matl seals Caused by seal degradation &/or worn poppet valves CHARTERINAL J General Public Utilities GPU Bervice Corp 82/09/24 Region 1. Office of Director 1p 15634-301 24X Fiche 50-219,82/09/24.8210070178
- 8210070238 Forwards LER 82-048/03L-0 Detailed event analysis encl FIEDLER.P B General Public Utilities - GPU Service Corp 82/09/27 HAYNES.R C Region 1. Office of Director 3pp 15637 151 24X Fiche 50-219:82/09/27:8210070238
- --8210070241 LER 82-048/03L-0 on 820826, reactor water level instrumentation for one channel in each of several safety sys rendered inoperable as result of loss of ref column head RIGGLE, E I General Public Utilities OPU Service Corp 82/09/27 Region i, Office of Director ip 15637-154 24X Fiche 50-219, 82/09/27, 8210070238
- 8210130357 RO on 820829, reactor startup conducted w/inoperable rod worth minimizer Minimizer failed due to defective clock drive module in slot 4J of CPM unit, damaging several components Ali damaged components replaced FIEDLER.P B General Public Utilities QPU Service Corp 82/09/28 MAYNES R C Region 1, 0ffice of Director 2pp 15679 010 24% Fiche 50-219, 82/09/28,8210130357
- 8210060374 PND-1-82-043 on 821001, anonymous phone caller notified licensee that bomb was set to go off in plant No bomb discovered in protected area COMPILL.C . TRIPP. MCCABE Region 1. Office of Director. 82/10/01 ip 15619 055 24X Fiche 50-219.82/10/01.8210060376
- 8210150098 Forwards LER 82-050/03L-0 Detailed event analysis encl FIEDLER.P B General Public Utilities - GPU Service Corp 82/10/01 HANNES,R C Region i Office of Director 3pp 15701 178 24X Fiche 50-219, 82/10/01,82101500

- --8210150112 LER 82-050/03L-0 on 820828, reactor vessel pressurised in sixess of 110 paig u/reactor water temp greater than 212 F Caused by inadequate Procedure &02 4 001 Test procedure will be reviewed to redefine temp/pressure requirements SANTELLA, A General Public Utilities OPU Service Corp 82/10/01 Region 1. Office of Director 1p 15701 181 24X Fishe 50-219,82/10/01.8210150098
- DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8210010275 Forwards "Systematic Assessment of Licensee Performance (SALP). Nine Hilz Foint Nuclear Station Unit 1." for Hay 1991 Apr 1982.util 820728 ltr re performance improvements & NRC 820630 request List of SALP 820708 meeting attenders encl HAYNES. R. C. Region 1. Office of Birector 82/09/28 RHODE. G. K. Niagara Mahauk Power Corp. 4pp 15568 327 24% Fiche 50-220. 82/09/28, 8210010275
- --8210010280 "Systematic Assessment of Licensee Performance, Nine Mile Point Nuclear Station Unit 1." for May 1981-Apr 1982 \* Region 1, Office of Director 82/06/22 27pp 18569 331 24x Fiche 50-220,82/09/28.8210010275
- 8210050202 Ack receipt of 820324 ltr informing NRC of steps taken to improve items identified in Apps A:B & C of IE Emergency Preparedness Appraisal Rept 50-220/81-18 SHITH.G H Division of Emergency Preparedness & Operational Support 82/09/29 RI(DE:O K Niagara Mohawi Power Corp 2pp 15614-018 24X Fiche 50-220.82/09/29.8210060202
- --8210060208 Responds to NRC 820222 ltr transmitting IE Emergency Preparedness Appraisal Rept 50-220/61-18 Descriptions of assessment/actions to be taken for improving items identified in Apps A.B.& C of rept encl
  LEMPGES.T E Niagara Mohawk Power Cosp 82/03/24 HAYNES.R C Region f. Office of Director 22pp 15614 020 24% Fiche 50-220,82/09/29,8210060202
- 8210040276 Forwards review of safe shutdown analysis in response to 820426 request for add! info re 100FR50.App R. Sections 131 G & III L BC say 125-volt analysis for breaker fuse coordination to be completed by 821235 MANGAN.C V Niagara Hohauk Power Corp 82/10/01 VASSALLO D B Operating Reactors Branch 2 1p 15976 001 24X Fiche 50-220.82/10/01.8210040276
- --B210040303 App R review of eafe shutdown analysis a Miagara Hobauk Power Corp 82/10/01 441pp 15596 002 24X Fiche 50-220, 82/10/01-8210040274
- 8210050083 Forwards "Dispersion Model Description for Nine Hile Point/ James A Fitspatrick Nuclear Stations," upgraded meteorological sys description per Thi Action Item III A 2 BAYME, J.P. Power Authority of the State of New York 82/10/01 VASSALLO, D.B. Operating Reactors Branch 2 2pp 15604 255 24X Fiche 50-333,82/10/01,8210050083

- P Operating license stage documents & correspondence
- 82(0050014 Approves recirculation sys piping removal info required prior to safe-end replacement VASSALLO,D 8 Operating Reactors Branch 2 82/09/02 DISE,D PRINTED MARKET MARKET MARKET STREET PRINTED TO SEE THE SUPERIOR STREET S
- 8210120632 Advises that 800421 request for title change of vice-president closed out since util advised change no longer required VASSALLO, D.B. Operating Reactors Branch 2 82/09/17 DISE, D.P. Miagara Mohaul Power Corp. 2pp. 15672 271 24X Fiche 50-220, 82/09/17, 8210120632
- 8210010033 Submits info re removal & replacement of reactor recirculation sys piping.per 820922 request Combined man rem exposure estimates bounded by original estimate of 2.906 man rem MANOAN.C V Niagara Mohawk Power Corp 82/09/27 EISENBUT, D C Division of Licensing 2pp 15565 170 24X Fiche 50 220.0.7/09/77.
- 8210040117 Forwards fee for Icch Spet changes re containment is dialized dependability (n compliance w/requirements of NURCO-0737 & reactor recirculation safe-end replacements program Fee submittal in response to NRC 820825 itr NANOANIC V Niggra Hohawk Power Corp 82/07/27 DIGGS.R licenst Fee Management Branch 2pp 15581 189 24% Fiche 50-220.02/07/27, 8210040117
- 8210040182 Forwards "Nine Mile Point Unit 1 Station Power Distribution Sgs (Class IE) Load Study & Field Test." In response to NRC 810202 request Required motor rewinding & cable replacement will be performed during nett scheduled refueling outage LEMPOES, T.E. Niagara Mohawk Power Corp. 82/09/27 VASSALIT, B. Operating Reactors Branch 2 3pp. 15892 206 24X Fichs 50-220.82/09/27.8210040182
- --B210040183 "Nine Mile Point Unit I Station Power Distribution Tys (Class IE) Load Study & Field Test " BLASIAK.L J. RIBEIRO, J. LAIRD.R C. Niagara Hohauk Power (orp B1/12/10 96pp 15582 210 24X Fiche 50 220.82/09/2/.8/2100404082
- 82(00)0275 Forwards "Systematic Assessment of Licensee Performance (SALP). None Hile Point Nuclear Station Unit 1." for May 17(1) Apr 1982. util 820728 ltr performance improvements & NRC 820630 request List of SALP 820708 meeting attendees encl HAYNES.R C Region 1, Office of Director 82/09/28 RHOBL.U K Niagera Mohawk Power Corp 4pp 15568 327 24X Fiche 50-220,82/09/28,8210010275
- ~~8210010280 "Systematic Assessment of Licenses Performance, Nine Hile Point Nuclear Station Unit 1." for May 1981-Apr 1982 \* Region 1. Office of Director 82/06/22 27pp 15568 J/N 44 Fiche 50-220,82/09/28.8210010275
- --8210010287 Responds to radialogical controls section of 920A22 systematic assessment of licensee performance rept Commitments for performance improvements provided LEMPOES.T E Niagara Mohauk Power Corp 82/07/26 STAROSTECKI.R Division of Project & Resident Programs 4pp 15568 350 24% Fiche 50-220.82/09/28.8210010275
- --8210010274 Informs of 820708 meeting at site to discuss NRC 870641 systematic assessment of licensee performance Discussion of efforts re-radiological control activities should be prepared STAROSTECKI,R Division of Project & Resident Programs 82/06/30 LEMPOES,T E Niagara Mohauk Power Corp 2pp 19968-362 24X Fiche 50-220, 82/09/28 8210010275
- 8210050240 Forwards 42 oversize drawings showing connection of alternate shutdown sys to normal shutdown sys in response to NRC 820426 Ity Aperture cands are available in PDR MANOAN.C V Niegera Hohauk Power Corp 82/09/30 VASSALLO, D 8 Operating Reactors Branch 2 ip 15603 001 24X Fiche 50-220.82/09/30.8210050240
- 8210050334 Notifies that proposed mods to automatic depressuritation sys logic will not be submitted until 821203 Delay needed to consider affects of listed analyses HANGAN C V Miagara Mohawk Power Corp 82/07/30 EISENHUT. D 0 Division of Licensing in 15401 348 24x Fiche 50-220, 82/09/30 8210050364
- 8210050111 Forwards one oversize revised schedule for recirculation sys repairs at facility. Aperture card is available in PDR MANGANIC V Niagara Mohauk Power Corp 82/10/01 VASSALLO D 8 Operating Reactors Branch 2 ip 15603 002 24X Fiche 50-220.82/10/01.821005011

- 82[0130107 Submits addl info to 820927 ltr re analysis criteria for recirculation sys piping replacement Reanalysis criteria provides same mangin as original criteria High energy line break would not affect engineered safeguard sys MANOANIC V Niagara Mohawk Power Corp 82/10/05 EISENHUT, D C Division of Licensing 3pp 15673 101 24% Fiche 90-220,82/10/05. 6210130107
- 8210280144 Informs that review of technical evaluation rept.
  "Comparison of Plant & Model Radiological Effluent Tech
  Specs & Plant Offsite Dose Calculation Manuali Nine Mile
  Foint Nuclear Station Unit i." will be completed by \$21130
  LEMPOES.T E Niagara Mohauk Power Corp 82/10/25 VASSAL
  Operating Reactors Branch 2 1p 15837 135 24X
  Fiche 50-220.82/10/25.9210280144 VASSALLO D B
- Q Inspection reports, IE Bulletins & correspondence
- 8210080015 Addl response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON, J H. Division of Rules and Records 82/07/1; Critical Mass Energy Project 9pp 15645 027 24X Fiche 50-000, 82/07/12, 8210080015 82/07/12 UDELL, R A

- --B210080139 Systematic assessment of licensee performance notes re facility evaluation for Feb 1980-Oct 1981 \* NRC No Detailed Affiliation Given 81/01/31 Spp 15668 003 24% Fiche 50-000.82/07/12.8210080015
- 1210070337 Forwards IE Insp Rept 50-220/82-14 on 820801-31 & notice of vialation STAROSTECKI.R Division of Project & Resident Programs 82/09/22 RHODE, G.K. Niagara Mohawk Power Corp. 2pp. 15634 073 Fiche 50-220, 82/09/22, 8210070337
- -8210070342 Notice of violation from insp on 820801-31 \* Region I, Office of Director 82/09/22 ip 19634 075 24X Fithe 50-220,82/09/22,8210070337
- -8210070350 IE Insp Rept 50-220/82-14 on 820801-31 Noncompliance noted failure to follow radiation work permit requirements for full face respirators
  HUDBON.8 D , KIBTER.H 8 Division of Project & Resident Programs
  82/09/17 8pp 15634 076 24X Fishe 50-220,82/09/22,8210070337
- 210010197 Ack receipt of 820818 ltr informing NRC of steps taken to currect violations noted in IE Insp Rept 50-220/82-10
  MARTIN: T T Division of Engineering & Technical Programs B2/09/2
  RHODE. O K. Niagara Mohawk Power Corp ip 19967 254 24X
  Fichs 50-220,82/09/24.8210010187 89/09/94
- -8210010165 Responds to NRC 820719 ltr re violations noted in IE Insp Rept 50-220/82-10 Corrective actions safety evaluation & procedures for reactor vessel recirculation nozzle safe-end replacement reviewed by site operations review committee LEMPGES: T & Niagara Mohawk Power Corp 82/08/18 MARTIN.T T Division of Engineering & Technical Programs 3pp 19567 255, 24X Fiche: 90-220, 82/09/24, 8210010157
- 'EOO10275 Forwards "Bystematic Assessment of Licensee Performance (SALP), Nine Mile Point Nuclear Station Unit 1," for May 1981 -Apr 1982, util 820728 itr re performance improvements & NRC 820630 raquest List of SALP 820708 meeting attendess encl HAYMES.R.C Region 1, Office of Director 82/09/28 RHODE, 0 K Niagara Mohauk Power Corp 4pp 15568 327 24X Fiche 50-220, 82/09/28 8210010275
- 8210Di0280 "Systematic Assessment of Licensee Performance, Nine Mile Point Nuclear Station Unit 1." for May 1981-Apr 1982 \* Region i. Office of Director 82/06/22 27pp 15568 331 2/ Fiche 50-220,82/09/28,8210010275 15568 331 24X
- 9210010287 Responds to radiological controls section of 820622 systematic assessment of licensee performance rept Commitments for performance improvements provided LEMPOES.TE Niegare Mohauk Power Corp 82/07/28 STAROBTE Division of Project & Resident Programs 4pp 15568 358 Fiche 50-220,82/07/28,8210010275 BTAROSTECKI, R
- 3210010294 Informs of 820708 meeting at site to discuse NRC 820623 systematic assessment of licenses performance Discussion of efforts re-radiological control activities should be prepared
  BTAROSTECKI,R Division of Project & Resident Programs 82/06/3
  LEMPGES.T E Niagara Mohawk Power Corp. 2pp 15568 362 24X
  Fichs 50-220,82/09/28,8210010275 82/06/30

- 8210060202 Ack receipt of 820324 ltr informing NRC of steps taken to improve items identified in Apps A.B & C of IE Emergency Preparedness Appraisal Rept 50-220/81-18 SMITH.0 H Division of Emergency Preparedness & Operational Support 62/09/29 RHODE.0 K Niagara Mohawk Power Corp 2pp 15614 018 24X Fiche 50-220.62/09/29.8210060202
- --821006020B Responds to NRC 820222 1tr transmitting IE Emergency 21006020B Responds to NRC 820222 Itr transmitting IE Emer Preparedness Appraisal Rept 50-220/81-18 Descriptions of assessment/actions to be taken for improving itoms identified in Apps A.B & C of rept enci LEMPGES.T E Niagara Mohawk Power Corp 82/03/24 HAV Region 1. Office of Director 22pp 15614 020 24X Fiche 50-220.82/09/29.8210060202 HAYNES R C
- 8208190233 IE Info Notice 80-35. Suppl 1, "Leaking & Dislodged I-12b Implant Seeds " Svc list encl COBBL I Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolsdated Edison Co of New York 66pp 13761 206 82/10/06 Consoledated Edison Co. of New York 66pp 24x Fiche 50-000:02/10/06:8208190233
- 8210210255 Forwads IE Insp Rept 50-220/82-16 on 820824-27 No Andelogo Formans IE ansp Rept Surezo/d2-10 on Bybb29-27 No moncompliance noted MARTIN-TT Division of Engineering & Technical Programs B2/10/06 RHODE, 0 K Niagara Mohawk Power Corp 2pp 15766 237 24X Fiche 50-220, 82/10/06,8210210255
- --8210210264 IE Insp Rept 50-220/82-16 on 820824-27 No noncompliance
- 8210290103 Forwards IE Bafeguards Insp Rept 50-220/82-18 on 820915-16 No noncompliance noted

  MARTIN T Division of Engineering & Technical Programs 82/:
  SUNSER, J Niagara Mohawk Power Corp 2pp 15853 257 24X
  Fiche 50-220, 82/10/08, 8210270103 82/10/08
- --8210290107 IE Safeguards Insp Rept 50-220/82-18 on 820915-16 No noncompliance noted Major areas inspected organization & operation whipping & receiving storage & internal control physical inventory & records & repts COHEN.I. WOLTNER.E. GODY, A.T. Division of Engineering & Technical Programs 82/10/07 App 19853-257 24% Fichs 50-220, 82/10/08, 82/10/00
- 820819023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-20819023B 1E Bulletin B2-03, "Stress Carrosion Cracking in Thick Wall).Large-Diameter, Staanless Steel, Recirculation Sys Piping at BHR Plants " Syc list encl DEYGUNO, R C Director's Office, Office of Inspection and Enfarcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- 8210260177 Ack receipt of 820915 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-220/82-06 MARTIN.T T Division of Engineering & Technical Programs 82/10/6 RHODE, 0 K Niagara Mohawk Power Corp ip 15799 042 24X Fiche 50-220,82/10/21,8210260177 82/10/21
- --8210260184 Responds to NRC 820819 ltr re violations noted in IE Insp Rept 50-220/82-06 Corrective actions personnel surveyed, nasal smears taken, meeting held w/personnel & disciplinary action taken
  LEMPGES: T E Niagara Mohawk Power Corp 82/09/15 MARTIN.T T
  Division of Engineering & Technical Programs 2pp 15799 043
  24x Fiche 50-220.82/10/21.8210280177
- A Periodic operating reports & related correspondence
- 82(0130347 Forwards monthly operating rept for Sept 1982 LEMPGES, T E Niagara Mohawk Power Corp 82/10/06 Director's Office, Office of Inspection and Enforcement 1p 15679 134 24X Fiche 50-220.82/10/06.8210130347
- 8 Reportable occurrences, LERs & related correspondence
- 8210150135 Forwards LER 81-019/03L-0 8ARTLETT, J Niagara Mohawk Power Corp 81/07/07 GRIER, B H Region 1, Philadelphia, Office of the Director (81/03/01) Ip 15697 OBS 24X Fiche 30~220, B1/07/07, B210150135

- --8210150142 LER BL-019/03L-O on 810607.while performing local leak rate tasking. I-inch Fisher isolation valve 39-11 of emergency condenser steam line drain sys failed to seat Caused by worn seating & packing mails Valve repacked NELD.J Kiapara Hohawk Power Corp 81/07/06 Region 1. Philadelphia, Office of the Director (81/03/01) ip 15697 086 24X Fiche 50-220,81/07/07.82(0150135)
- 8210050284 Forwards LER 82-012/04L-0 LEMPCES.T E Niagara Hohawk Pouer Corp 82/09/24 HAYNES.R C Region 1. Office of Director 1p 15621 071 24X Fiche 50-220.82/09/24.8210060284
- -8210060291 LER 82-012/04L-0 on 820831.lower limit of detection sensitivity not met for several radionuclides in analysis of fish samples Tech Spec parameter too narrow for weelding weight units conversion Tech Spec revision underway FARROW N Niagara Mohaux Power Corp 82/09/24 Region L. Ottice of Director ip 15621 072 24X Fishe 50-220,82/09/24,8210060284
- 8210010007 PNO-1-82-031C on 820924.eight ultrasonic indications found in emergency condenser sys piping & four in shutdown cooling sys piping Evaluation revealed indications due to piping geometry & not reportable XISTER.H. BRUNER.E. Region I. Office of Director 82/09/27 ip 15565 162 24X Fiche 50-220.82/09/27.8210010007
- 8210280121 LER 82-001 has been canceled COLLINS.H Niagara Mohawk Power Corp. 82/10/19 Region 1. Office of Director up. 15837-022 24X Fiche 50-220.82/10/19, 8210280121
- DOCKET 50-223 UNIV OF LOHELL RESEARCH REACTOR

  R Feriodic operating reports & related correspondence
- 6210280183 Forwards monthly operating for June 1982 HALLACE,T Lowell. Univ of 82/10/21 Director's Office of Inspection and Enforcement ip 15837 Olj 24X Fache 50-223.82/10/21,8210280183
- --8210280186 Monthly operating rept for June 1982 \* Lowell, Univ of 82/10/21 7pp 15837 012 24X Fiche 50-223,82/10/21,8210280183
- DOCKET 50-228 AEROTEST RADIOGRAPHY & RESEARCH REACTOR
  F Security, medical, emergency & fire protection plans
- 8210050126 Forwards (E Insp Rept 50-228/82-02 on 820830 & 0902 No noncompliance noted 300K. H E Division of Radiologica) Safety & Safeguards Program 82/09/15 NEGACHECK. R Aerotest Operations 4pp 15614-320 24X Fiche 50-228
- --8210060131 IE lasp Rept 50-228/82-02 on 820830-0902 No noncompliance noted Hayor areas inspected radiation protection programs emergency planning program & environ monitoring program CILLISIM, MENSLAMSKI,F.A. BOOK,H.E. Division of Radiological Safety & Bafeguards Program 82/09/14 8pp 15614 324 24X Fiche 50-228,82/09/15.8210060126

- --B209290189 Forwards public version of Revision 4 to generating statics emergency plan corporate command ctr Emergency Plan Implementing Procedure EOF-3, "Environ/Emergency Coordinator " Receipt form encl PAUDMERF, J E Commonwealth Edison Co 82/09/01 DENTON, H R NPC -- No Detailed Affiliation Given ip 15544 123 24X Fichs 50-000, 82/09/16, 9209290125
- --B209290225 Public version of Revision 4 to generating station emergency plan corporate command ctr emergency plan implementing Procedure EOF-3, "Environ/Emergency Coordinator"

  PAJOHEKI, J E , LITERSKI, L A , FLESSNER, S A Communwealth Edison Co B2/0B/31 lipp 15564 124 24X Fiche 50-000, B2/09/16, B209290125
- 8210010009 Forwards info to suppl 820701 request for exemption from Agg R per 820917 telcon Request applies to Sections III 0 2 a till 0 3 b re installation of fire suppression sys RAUSCH, T J. Commonwealth Edison Co. 82/09/23 EISENHUT, D 0 Division of Licensing 8pp. 15365-152 24X Fiche 50-000.82/69/23, 82/09/00009
- B210130376 Advises that installation of offsite dose calculation sysprogram fully operational tracking model & operational A-model will be delayed until 821231 to complete prime computer installation SHARTZ.E D Commonwealth Edison Co 82/10/06 DENTON, H R Uffice of Nuclear Reactor Regulation, Director 2pp 15682 078 24X Fiche 50-000, 82/10/06, 8210130376
- B210290047 Releases public version of revisions to Quad Cities, Zion b Desiden emergency plan annexes & revised generating station emergency plan telephone directory FELTON.J H Division of Rules and Records 82/10/08 Document Hanagement Branch 1p 15877 313 24X Fiche 50-000, 82/10/08. B210270047
- --B210270060 Forwards public version of Revision 3 to Quad Cities & Iio1
  emergency plan annexes.Revision 2 to Dreaden emergency plan
  annex.Revision 0 to Byron emergency plan annex & revised
  generating station emergency plan telephone directory
  MODRE.R D Commonwealth Edison Co 82/07/30 DENTON.H R NRC No Detailed Affiliation Given Spp 15877 314 24X
  Fiche 50-000,82/10/08,8210290047
- --8210270077 Public version of Revision 3 to Guad Cities & Zion emergency plan annexes, Revision 2 to Dresden emergency plan annex & Revision O to Byron emergency plan annex \* Commonwealth Edison Co 82/06/30 102pp 15877 319 24X Fichs 80-000, 82/10/08, 8210290047
- --8210290088 Public version of revised generating station emergency plantelephone directory
  GALLE.D P Commonwealth Edison Co 82/08/12 43pp 18878 218
  24X Fiche 50-000.82/10/08.8210290047
- 8210220398 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 commitment, Training coordinator assigned in Apr 1982 to improve health physics training programs
  TRAMM. T.R. Commonwealth Edison Co. 82/10/14 DENTUN. H.R. Office of Nuclear Reactor Regulation, Director 9pp 19774 287 24X
  Ficha 50-000, 82/10/14, 8210220358
- 8210290170 Advises that plans & preparedness for offsite protection near facility adequate & will be applied in event of radiological amergency IL State & local plans approved subj to verification of adequacy of alerting & notification sys THOMAS.L M Federal Emergency Management Agency 82/10/14 DIRCKS W J GFfice of the Executive Director for Operations 19 15788 285 24X Fiche 50-010,82/10/14.8210250170
- G Adjudicatory correspondence
- 8210010257 Decision ALAB-695 affirming LBP-81-37 & LBP-82-65, sanctioning mod to OL for Unit 3 to permit installation of five high density spent fuel storage racks & authorizing issuence of amends to OLs, respectively TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 82/09/29 pp 15574 036 24% Fiche 50-207.82/09/29:8210010257
- P Operating license stage documents & correspondence
- 8210080001 Advises that board notification issued on 820903 rs use of auxiliary overhead crans rather than main overhead crans to move spent fuel pool racks should have been assued w/Number BN-82-92
  MIRACLIA-F. Assistant Director for Safety Assessment 62/09/14
  Atomic Safety and Licensing Board Panel 4pp 15668 341 24%
  Fiche 30-237.62/09/14.8210080001

## DOCKETED ITEMS

- --8210080002 Board Notification 82-92 informs of util failure to carry out fuel pool rack removal & installation in manner described in testimony at hearings Auxiliary overhead crane used instead of redundant main overhead crane IPPOLITO. TA Assistant Director for Safety Assessment 82/09/03 Atomic Safety and Licensing Board Panel Rpp 15668 345 24X Fiche 50-237,82/09/14,8210080001
- --8209210383 Recommends board notification re util use of auxiliary crane instead of main redundant crane to install fuel racks, as described in testimony before ASLB Licensee has committed to rollow testimony in completing remaining work

  IPPOLITO, T A Assistant Director for Safety Assessment 82/09/03

  EISEMHUT, D & Division of Licensing 2pp 15668 349 24X

  Fiche 50-237, 82/09/14.8210080000t
- 6210050309 Forwards final safety evaluation of SEP Topic VI-4, 'Containment Isolation Sys' Evaluation will be basic input to integated safety assessment Differences from current criteria listed O CONNOR.P Operating Reactors Branch 5 82/09/24 DELGEORGE, L Commonwealth Edison Co 28pp 15608 184 24X Fiche 50-237, 82/09/24, 8210050309
- 8210120105 Requests delay of implementation due dates re NUREO-0737, Items II B 2. "Plant Shielding," II B 3. "Post-Accident Sampling' & II F 1 1. "Noble Gas Effluent Monitor" SWARTZ-E D Commonwealth Edison Co 82/10/04 EISENHUT, D 0 Division of Licensing Spp 15651 237 24% Fiche 50-000,82/10/04, e21012010.05
- 8210190464 Informs that mods to SRP Section B 3 2 re SEP Topic VIII-3 B on dc power sys bus voltage monitaring & annunciation initiated Mods will provide battery voltage indication in control room & will replace process computer RAUSCH.T J Commonwealth Edyson Co 82/10/05 O'CONNOR.P Operating Reactors Branch S Ip 15740 298 24Y Fiche 30-237.82/10/05.8210190464
- 6210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" ODLDEN, J. C. Commonwealth Edison Co. 62/10/06 CASE, E. G. Office of Nuclear Reactor Regulation, Director 2pp 15805-137 24X Fiche 50-000-82/10/06.8210260526
- --8210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculatio Manual" \* Commonwealth Edison Co 82/09/30 83pp 15805 139 24X Fiche 50-000, 82/10/06, 8210260526
- 8210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820707 ltr Staff encouraged to develop b implement means to incorporate positive attributes of Phase III in licenses/NRC interface KACICH, R M SEP Duners Group 82/10/07 EISENHUT, D G Division of Licensing 7pp 15692 177 24X Fiche 50-000, 82/10/07, 8210130326
- 3210180057 Provides add1 guidance & clarification re 820806 request for add1 info per NUREG-0737. Item II B 3. "Post-Accident Sampling Sys " Detailed reliability analysis not required to satisfy NRC concerns CRUTCHFIELD, D Operating Reactors Branch 5 82/10/08 DELOEORGE, L Commonwealth Edison Co 3pp 15720 004 24X Fiche 50-000. 82/10/08.8210180059
- NZIO190565 Responds to SEP Topic III-4 B, "Turbine Missiles " Visual & fiber optic exams revealed water cutting in line w/keyways on hub wheels RAUSCH.T J Commonwealth Edison Co 82/10/08 O'CONNOR.P Departing Reactors Branch 5 2pp 15736 135 24X Fiche 50-237.82/10/08.8210190565
- •210190680 Forwards safety evaluation of licensee 820414 & 0611 responses to NUREG-0737. Item II E 4 2. "Purge/Vent Valve Isolation Dependability " Responses acceptable Topic review completed CRUTCHFIELD. D. Operating Reactors Branch 5 82/10/13 DELGEORGE.L. Commonwealth Edison Co. Spp. 15738 192 24X Fiche 50-237, 82/10/13.8210190680
- 210190445 Forwards supplemental response to Generic Ltr B2-05 re implementation status of NURCG-0737: Items II B 3:II F 1 2:
  II F 1 3:II F 1 5 & II F 1 4:iin response to B2:006 request SWARTZ.E D Commonwealth Edison Co 82/10/14 EISENHUT.D 9
  Division of Licensing 5pp (574) 202 24% Fiche 50-000.82/10/14, B2:10190445
- 210220335 Forwards info re NUREO-0737. Item II D 1, "Performance Testing of BWR Safety/Relief Valves," per 820727 request Info adequately demonstrates applicability of results of BWR owners group generic test rept NEDE-24988-P to facility SWARTZ.E D Commonwealth Edison Co 82/10/15 EISENHUT.D C Division of Licensing 17pp 15774 011 24X Fiche 50-237.82/10/15, 8210220335

- 8210250203 Forwards preliminary draft of integrated plant safety assessment rept.Chapter 4, "Integrated Assessment Summary "
  Encl draft includes commitments submitted in response to NRC 820715 Itr & assessment meetings CRUTCHFIELD.D Operating Reactors Branch 5 82/10/15 DECOERGE.L Commonwealth Edison Co 60pp 15789 204 24X Fiche 50-237, 82/10/15, 8210250203
- 8210250155 Forwards corrections to proposed Tech Spec Pages 1 2/2 2-1: 3,3/4 3-5, supporting review of future reloads & revised Figure 3 5 1, Sheet 1 providing extended MAPLHOR vs exposure curves for barrier lead test assembly fuel RAUSCH, T. J. Commonwealth Edison Co. 82/10/18 DENTON, H. R. Diffice of Muclear Reactor Regulation, Director 2pp 15768 233 24X Fische 50~000, 82/10/18, 8210250155
- --8210250177 Errata & Addenda Sheet 8, reglacing Page 4-10 to "LDCA Analysis Rept for Dresden Units 2 & 3 & Guad Cities ! & 2 Nuclear Power Stations " • General Electric Co NEDD-24146A ERR 08 82/09/30 3pp 15768 239 24X Fiche 50-000.82/10/18.8210250155
- 8210250069 Provides add1 info re reactor water cleanup room area temp monitors Temp elements cause no automatic plant response beyond control room alarms RAUSCH: T J Commonwealth Edison Co 82/10/19 £15ENHUT, D Q Division of Licensing 2pp 15787 081 24X Fiche 50-000; 82/10/19, 8210250069
- 8210260485 Provides add1 into re actuation of relief valve PRV 2-1201-80 on reactor water cleanup sys Existing configuration adequate to handle transient w/o mither reactor scram or reactor water cleanup overpræsumization RAUSCH, T. J. Commonwealth Edison Co. 82/10/19 0'CONNOR, P. Operating Reactors Branch 5 2pp 15807 257 24X Fiche 50-237, 82/10/19, 8210260485
- 8210260296 Forwards safety evaluation of BMR owners group generic response to NUREO-0737. Item II K 3 25. "Effect of Loss of AC Power on Pump Seals " No mods to seal cooling for recirculation pumps required Item resolved CRUTCHFIELD: D Operating Reactors Branch 5 82/10/21 DELGEORGE, L COMmonwealth Edison Co 7pp 15803 018 24X Fithe 50-237. 82/10/21.8210260296
- O Inspection reports, IE Bulletins & correspondence
- 0210040329 Forwards IE Insp Repts 50-010/82-02.50-237/82-03 & 50-249/82-03 on 820119-0218 No noncompliance noted LITTLE,W 9 Division of Engineering & Yochnical Programs REED.C Commonwealth Edison Co 2pp 15415 331 24X Fiche 50-010.82/09/22.8210040329
- --8210060335 IE Insp Repts 50-010/82-02.50-237/82-03 & 50-249/82-03 un 820119-0218 No noncompliance noted Major areas inspected open & unresolved items & items of noncompliance reintegrated leak rate test REIMANN, F W Region 3, Office of Director JACKIW, I N Division of Engineering & Technical Programs 82/09/21 7pp 15615 333 24X Fichs 50-010.82/09/22.8210060329
- 8210150523 Forwards IE Insp Repts 50-010/82-13, 50-237/82-17 50-249/82-18 on 820708-0807 & notice of violation STREETERJ F Division of Project & Resident Programs REED.C Commonwealth Edison Co 2pp 15713 099 PAY Fiche 50-010, 82/09/28, 8210150523
- --B210150538 IE Insp Repts 50-010/82-13,50-237/82-17 t 820708-0809 Noncompliance noted failure to issue the air pressure test procedure TONOUE,T M. JORDAN,M J. WALKER,R D. Division of Resident Programs 82/09/28 8pp 15713 102 24 Fiche 50-010,82/09/28,8210150523
- 8210060359 Ack receipt of 820910 ltr informing NRC of a correct violations noted in IE Insp Repts 50-237/81-5 50-247/81-32, 50-254/81-23, 50-265/81-23, 50-275/81-31 & 90-304/81-29 SPESSARD, R L Division of Project & Resident Program REED, C Commonwealth Edison Co Ip 15618 354 24 Fiche. 50-000 82/10/01, 8210060359.
- --8210040347 Responds to NRC 820712 itr re violations n Repts 50-237/81-39,50-247/81-32,50-254/81-23,50-265 50-295/81-31 & 50-304/81-29. Corrective actions trai mgt priorities re plant availability will be conduc REED, C Commonwealth Edison Co 82/09/10 KEPPLE 3, Office of Director 13pp. 15618,355 24% Fiche,50-000,82/10/01.8210060359.

- 8210080178 Forwards listing of piping sys which fail to meet FSAR requirements, per NRC 800818 confinatory action ltr IE Bulletin 79-14 operability evaluation updates uill not be provided for Dresden & Guad Cities Final update by Dec 1982 RAUSCH T J Commonwealth Edison Co 82/10/01 MEPPLER. J G Region 3, Dffice of Director App 15440 LS9 24% Fiche 50-000.82/10/01,
- 8210180539 Forwards IE Insp Repts 50-010/82-15,50-237/82-19 & 210150337 Forwards IE Insp Repets 50-010/28-15.03-23//02-17 0 50-249/20-20 on 820830-0903 No noncompliance noted PAPERIELLO.C J Division of Emergency Preparedness & Operational Support B2/10/01 REED.C Commonwealth Edison Co 2pp 15714 175 24X Fiche 50-010.B2/10/01.8210150539
- --8210150543 IE lnsp Repts 50-010/82-15.50-237/82-19 & 50-249/82-20 on 820830-0903 & 09 No noncompliance noted Major areas expositionary a dy No noncompliante noted Major areas inspected confirmatory measurements program 60 program for analytical measurements & environ monitoring program SCHUMACHER. M C . NICHOLEUN N A . JANUSKA A G Division of Energency Preparedness & Operational Support 82/09/30 15714 177 24X Fiche 50~010.82/10/06.8210150539
- 8210060266 Confirms 821103 enforcement conference at Region 3 oft re GA aspects associated w/procurement, installation & use of non-qualified valve guides in electromagnetic relief valves at facilities
  SPESSARD.R L Division of Project & Resident Programs REED, C Commonwealth Edison Co ip 15640 181 Fishe 50-000, 82/10/04, 82(0080190
- 8210080190 Confirms B21103 enforcement conference at Region 3 ofc re GA aspects associated w/procurement, installation & use of non-qualified valve guides in electromagnetic relief valves at facilities

  SPESGARD.R L. Division of Project & Resident Programs

  REEO.C Commonwealth Edison Co ip 15640 (81 24X

  Fiche 50-000.82/10/04.8210080190
- 8208170233 IE Info Notice 80-35, Suppl 1, "Leating & Disindged 1-125 Implant Seeds " Svc list and! COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000.82/10/06.8208170233 15761 250
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-COSTOCATE IN UTIES IN 32-03, "Stress Corrosion Cracking in Thick Mail: Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list enci DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.62/10/14.8208190238
- R Periodic operating reports & related correspondence
- 8210180097 Forwards monthly operating repts for Sept 1982 SCOTT.D J. Commonwealth Edison Co. 82/10/01 Director's Office of Inspection and Enforcement ip 15718 001 24X Fiche 50-010.62/10/01.8210180097 Director's Office,
- --8210180100 Monthly operating repts for Sept 1982 8CHROEDER.B A Commonwealth Edison Co 82/10/01 15718 002 24% Fiche 50-010.82/10/01.8210180097
- S Reportable occurrences. LERs & related correspondence
- 8210150044 Forwards LER 81-059/03L-0 SCOTT. DJ Commonwealth Edison Co 81/10/08 KEPPLER, J G Region 3. Chicago, Office of the Director (81/03/01) 1p 15701 126 24X Fiche. 50-237, 81/10/08, 8210150044
- --B210150049 LER 81-059/03L-0 an 810910, while conducting insp on pump 2A.CCSW outboard bearing found borned out Caused by lack of lubricetion in sealed bearing Bearing replaced ZIRMAS.X R Communealth Edison Co 81/10/08 Region 3. Chicago, Office of the Director (81/03/01) 2pp 15701 127 24) Fiche 50-237.81/10/08.8210150044. 15701 127 24X
- 62:00800:5 Addl response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOLA Exemption 5)
  FELTON. J. M Division of Rules and Records. 82/07/12 UDELL.R A
  Critical Mass Energy Project 9pp 15645 027 24X
  Ficha 50-000.82/07/12.8210080015
- --8210080197 NRC operations ctr usage chart re events at facilities \* NRC No Datailed Affiliation Given 82/07/12, 1p 15668-221 24X Fiche 50-000.82/07/12.8210080015

- 8210040188 Forwards LER 92-040/03L-0 SCOTT, D. J. Commonwealth Edison Co. 82/09/15 KEPPLER, J.O. Region 3. Office of Director Lp. 15583 164 24% Fiche 50-237,82/09/15. Region R210040188
- --8210040189 LER 82-040/03L-0 on 820830. valve Z-1601-33A exhibited binding during movement while performing torus-drywell vacuum breaker operability test (DOS 1600-9) Cause not Wetermined Repairs to be made during next outage
  WEE, D T Commonwealth Edison Co 82/09/15 Region 7, Office of
  Director 2pp 15583 145 24X Fiche 50-237,82/09/15,82(0040188
- SCOTTED J Commonwealth Edison Co 82/09/22 KEPPLER, J G Region 30 GF71ce of Director Ip 15611 026 24% Fiche 50-237,82/09/22,8210050227 8210050227 Forwards LER 82-038/03L-0
- --8210050233 LER 82-038/03L-0 on 820829, during MSIV timing surveillants valves 2-203-6C & 2-203-1D had closed times of 2 25-3 & 2 67-s, respectively Caused by timing mechanism drift Valves adjusted
  RHEE, S Commonwealth Edison Co 82/09/22 Region 3, Office p
  Director 2pp 15611 027 24% Fiche 50-237, 82/09/22, 8210050227 Region 3. Office of
- 8210040198 PNO-III-82-101 on 820824.plant tripped due to broken cooling water line to generator hydrogen cooling sys spraying water onto current transformer Line repaired & transformer replaced
- TONOUS, T., WALKER, R., STREETER, J. Region 3, Office of Director 82/09/27 1g 15883 147 24X Ficho 50-237,82/09/27,8210040190
- 8210250268 Forwards LER 62-042/03L-0 SCOTT,D J Commonwealth Editon Co 82/10/12 KEPPLER,J Q Region 3, Office of Director 1p 15791 (45 24% Fiche 50-237,82/10/12, 8210250268
- --8210250278 LER 82-042/03L-0 on 820930, control rod drive N-10 overtrad 210230278 LEN 82-042/03L-O on 82073D control rod drive N-10 overty.

  # alarm annunciated & rod position indication lost Caused by
  uncoupled inner filter Drive recoupled at greater than 207
  power Drive uill be overhauled during next refueling outage
  ## HOLLAND, P. Commonwealth Edison Co. 82/10/12 Region 3. Office
  ## Of Director 2pp 15791 146 24% Fiche 50-237, 82/10/12. 8210250268
- 8210250283 Forwards LER 82-042/01T-0 SCOTT.D J Commonwealth Edison Co 82/10/14 KEPPLER, J G Regio 3, Office of Director 1p 15791 102 24X Fiche 50-237,82/10/14 8210250283
- --8210250296 LER 82-042/01T-0 on 021002, sightglass isolation & vent valves reported open w/no indication of excess makeup Calculations indicate leakage was in excess of Tech Spec Caused by operator error Valves closed HOLLAND, P. Commonwealth Edison Co. 82/10/14 Region 3 of Director app. (5791-103 24X Fiche 50-237,82/10/14, entropping Region 3. Office 8210290283
- DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1 F Security, medical, emergency & fire protection plans
- 82:01:5062: Releases public version of revision to emergency plan implementing procedures
  FELTON, J H Division of Rules and Records 62/09/30 Docum
  Hanagement Branch ip 157:17 064 24X Fiche 50-244.82/09/30. 8210150621
- --8210150643 Forwards public version of revision to emergency plan implementing procedures, including Procedure SC-411 re NY State warning point test & Procedure SC-410 re insport emergency equipment MAIER, JE Rochester Cas & Electric Corp B2/09/23 CRUTCHFIELD, D Operating Reactors Branch 5 lp 157: Fiche 50-244,82/09/30.8210150621 15717 065 241
- --8210150648 Public version of revision to emergency plan implementally procedures, including Procedure 80-411 re NY State warning point phone test & Procedure 80-410 re insp of emergency equipment BODINE, J C , SPECTER, S M Rochester Gas & Electric Corp 48pp. 15717 O66 24X Fiche 50-244, 82/09/30, 821015067 82/09/20
- 8210190580 Ack receipt of 820224 ltr informing NRC of steps taken to correct violations noted in JE Insp Rept 50-244/81-22 ALLANJ H Region i. Office of Director 82/10/07 MAIER. J E Rochester Oas & Electric Corp ip 15739 307 24X Fiche 50-244, 82/10/07, 8210190580

- --B210190591 Responds to NRC Bil215 ltr re violations noted in 1E Insp Rept 50-244/Bi-22 Corrective actions emergency plan training program will be realigned by 820115 to be consistent w/ functional area requirements MAIER. J & Rochester Gas & Electric Corp B2/02/24 HAYNES. R C Region 1. Office of Director 4pp 15739 308 24X Fiche 50-244,82/10/07.8210190580
- --82:0190618 Responds to NRC 811215 ltr re violations noted in IE Insp Rept 50-244/81-22 Corrective actions clarified required action.eliminated existing ambiguities, inconsistencies & errors for emergency functions MAIER.J E Rochester Gas & Electric Corp 82/04/19 HAYNES.R C Region I. Office of Director 2pp 15739 312 24X Fiche 50-244,82/10/07,8210190580
- --821019063/ Responds to NRC 820520 ltr re violations noted in IE Insp Rept 50-244/81-22 Corrective actions committee established to evaluate & inventory supplies Rept will be submitted by 821231 MAIER, J E Rochester Cas & Electric Corp 82/06/30 SMITH, G H Division of Emergency Preparedness & Operational Support 22pp 15739-314 244 Fiche 50-244,82/10/07,8210190880
- ~-8210190647 Responds to NRC 811215 ltr re violations noted in IE Insp Rept 50-244/81-22 Corrective actions revision of Emergency Plan 8C-1 completed prior to startup after 1982 refueling shutdown MAIER, J E Rochester Gas & Electric Corp 82/10/07 HAYNES, R C, Region I, Office of Director 1p 15739 336 24X Fiche 50-244,82/10/07,8210190580
- 6210290212 Ack receipt of 821015 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/82-15 STAROSTECKIR Division of Project & Resident Programs 82/10/25 MAIER, J E. Rochester Gas & Electric Corp. 10 15853 279 24% Fiche 50-244-82/10/25,8210290212
- --8210290217 Responds to NRC B20914 ltr re violations noted in IE Insp Ropt 50-244/82-15 Corrective actions situation reviewed & determined to be isalated case Further action unnecessary MAIER. J C Rochester Gas & Electric Corp 82/10/15 BRUNNER, E J Region I. Office of Director 2pp 15853 280 24X Fiche 50-244,82/10/25,8210290212

## Adjudicatory correspondence

- 6210280060 Updates 820730 status rept on NRC issuances Final integrated plant safety assessment rept to be issued on 821029 Conversion safety evaluation rept & update to FES to be issued in Nov YOUNG.M A Hearing Branch 4 82/10/26 OROSSMAN.H , LUEBKE.E A . COLE.R F Atomic 8afety and Licensing Board Panel 1p 15837 262 24X Fiche 50-244,82/10/26,8210280060
- D Advisory Committee on Reactor Safeguards reports & correspondence
- 9208290018 Summarizes 268th ACRS meeting on 820812-14 in Washington, DC re full power OLs for Grand Oulf I & Watts Bar I & II.
  systematic evaluation & integrated reliability assessment or Ginna & control room habitability
  GREWHON, P ACRS Advisory Committee on Reactor Safeguards 82/08/06 PALLADING, N J Commissioners 3pp 15647 233 24X
  Fiche 50-000,82/08/26,8208290018
- B210180074 Forwards B20917 response to ACR9 comments & recommendations per facility SEP review CRUTCHFIELD, D Operating Reactors Branch 5 82/10/07 MAIER, J E Rochester Gas & Electric Corp 2pp 15719 347 24X Fiche 50-244,82/10/07.8210180074
- --8210180083 Responds to ACRS 62081B comments & recommendations refactlity SEP review Draft NUREQ-0821 will be revised to reflect agreements

  DENTON, H R Office of Nuclear Reactor Regulation, Director 82/09/17 SHEWNON, P S ACRS Advisory Committee on Reactor Safeguards 2pp 15719 349 24% Fiche 50-244,82/10/07, 8210180074
- P Operating license stage documents & correspondence
- B210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records B2/06/28 UDELL, R A Critical Mass Energy Project 15pp 15727 005 24X Fishe 50-000, B2/06/28, B210010008

- --8003310179 Forwards NRC evaluation of use of four mixed oxide fuel assemblies for Cycle 10 Use of assemblies is acceptable w/no changes For future cycles NRC will require increase in nuclear uncertainty re total peaking factor CHECK, P & Reactor Safety Branch 80/03/11 ZIEMANN, D L Operating Reactors Barety Branch 2 (Pre 800428) 8pp 15727 036 24X Fiche 50-000, 82/06/28, 8210010008
- 8210120103 Add1 response to FOIA request for nine categories of record, generated by present NRC Commissioners, primarily Chairman Palladino & Commissioner Roberts & White House Forwards App B documents
  FELTON, J M Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project 3pp 15690 117 24X
  Fiche 50-000, 82/07/12, 82:0120103
- --B210120131 Agrees w/point raised in 820201 mamo re NRC incident response program Points raised by staff will be addressed in rept on lessons learned at incident response ctr from facility event
  PALLADINO, N J Commissioners 82/02/16 ROBERTS, T M Commissioners 19 19690 138 24X Fiche 50-000,82/07/12, 8210120103
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson, Putnem & Roberts 9pp 15645 063 24X Fiche 50-000, 82/08/10, 8210070007
- ---8202170310 Forwards background summary of operating experience w/
  steam generators prior to 820125 tube rupture
  JOHNSTON.H V Assistant Director for Materials & Qualifications
  Engineering 82/01/28 LAINAS.G C Assistant Director for Bafety
  Assessment 5pp 15645 104 24X Fiche, 50-000, 82/08/10.
  8210070007
- --8202240397 Bubmits daily highlight re 820203 insp of steam generator Ø to determine location of 820125 ruptured tube event Eddy current tests performed on tube near periphery on hot leg side & four adjacent tubes
  LYONS, J E Operating Reactors Branch 5 82/02/03 DENFON, H ,
  CARTER, J , EISENHUT. D NRC No Detailed Affiliation Given 1p
  15645 089 24X Fiche 50-000, 82/08/10.8210070007
- --8203020267 Submits daily highlights for 820210 meeting w/util re requirements for restart Prior to restart util should finish fiber optic insp of secondary side of B steam generator & obtain designer opinion on effects of plugging LYONS, J E Operating Reactors Branch 5 82/02/11 DENTON, H R . CARTER, J . EISCHHUT, D NRC - No Detailed Affiliation Given ip 15645 092 24X Fiche. 50-000, 82/08/10,8210070007
- ---B203040502 Submits daily highlight re television insp of B steam generator revealing missing, partially missing & damaged tubes & presence of foreign objects Meeting w/NRC planned LYONS, J.E. Operating Reactors Branch 5 BZ/0Z/19 DENTON, H, CARTER, J, EISENHUT, D NRC No Detailed Affiliation Given, ip 15445 096 24X Fichs 30-000.82/0B/10,8210070007
- --8203100373 Submits daily highlights re insp of ruptured tube using fiber optics Five-inch kite shaped rupture caused by stress corrosion linked to differential expansion between tube & tube wrapper using Foundation plugged
  LYONS, J. E. Operating Reactors Branch 5 82/02/08 DENTON, H, CARTER, J, EISENHUT, D NRC No Detailed Affiliation Given 1p 19645 091 24X Fichs 50-000,82/08/10,8210070007
- --8203110304 Submits highlights re fiber optic investigation of secondary side of B steam generator revealing damage to previously plugged tubes Preliminary indications show one tube severed investigation of peripheral area continuing.

  LYONS, J E Operating Reactors Branch 5 BE2/02/12 DENTON.H., CARTER, J. EISENRUT.D. NRC No Detailed Affiliation Given Ip. 19545-094 24% Fiche 50-000, B2/08/10, B210070007
- --8203110339 Submits daily highlights re insp of periphery of B steam generator hot leg Insp results indicate approx 7-10 previously plugged tubes in peripheral area severly damaged TV insp planned for A & B generators.

  LYDNS, J E Operating Reactors Branch 5, 82/02/16 DENTON, H . CARTER, J . EIBENHUT, D NRC No Detailed Affiliation Given 2pp 15645 095 24% Fiche 50-000, 82/08/10,8210070007
- --8203110403 Forwards response to JD Dumele, chairman of Pollution Control Board, State of IL, questions in 820127 ltr
  JOHNSTON, M. V. Assistant Director for Materials & Qualifications
  Engineering 82/02/22. LAINAS.G. Assistant Director for Safety
  Assessment. 2pp. 15645 126 24X Fiche, 50-000, 82/08/10.
  8210070007.

- --8206070250 Forwards Operating Reactors Assessment Branch input for Oinna restart safety evaluation rept. Section 5, re stam generator insp program. Failure analysis & repairs IPPOLITO.Y.A. Operating Reactors Assessment Branch 82/05/18 CRUTCHFIELD.D Operating Reactors Branch 5 45pp 15645 138 24X Fiche 50-000,82/08/10.8210070007
- ---8206290655 Forwards Mechanical Engineering Branch input to restart SER Sections 4 5 through 4 8.5 1.5 2.5 4.6 1 & 6 2, per 820423 request MIDHT.J.P. Assistant Director for Components & Structures Engineering 82/06/15 LAINAS.9 C Assistant Director for Safety Assessment 13pp 15645 183 24X Fiche 50-000.82/08/10.
- --8210070030 Util handout from 820210 meeting w/NRC re 820125 steam generator tube rupture at facility # Rochester Gas & Electric Corp 82/02/10 17pp 15645 072 24% Fiche 50-000, 82/08/10.8210070007
- --8210070068 Submits daily highlightire 820210 meeting w/util concerning requirements to be met prior to restart of facility No sufficient basis presented at this time to permit plant to return to operation
  LYONS.JE Operating Reactors Branch 5 82/02/11 DENTON.H.
  CARTER.J. EISENNUT.D NRC No Detailed Affiliation Given ip
  15445-093 24X Fiche 50-000.82/08/10.8210070007
- --8210070073 Submits daily highlight re util 820219 press conference presenting update on recovery activities at facility Kasting w/NRC scheduled for 820302 CAMPAGE STATES OF S
- ---8210070076 Submits daily highlight re 820301 meeting w/util & 820302 meeting w/Westinghouse in Bethesda MD to discuss recovery activities at facility & generic steam generator tube degradation, respectively tyONB.J E Operating Reactors Branch 5 82/02/26 DENTON.H, CARTER.J, EISCHHUT.D NRC No Detailed Affiliation Given ip 15645 078 24X Fiche 50-000, 82/08/10,8210070007
- --8210070080 Submits daily highlight re 820301 meeting u/util re proposed recovery program for facility NRC concurred w/proposal to remove small number of steam generator tube sections for metallurgical exam

  LYONS.J E Operating Reactors Branch 5 82/03/04 DENTON.H ,
  CARTER.J , EISENHUT.D NRC No Detailed Affiliation Given ip
  13645 099 24X Fiche 50-000.82/08/10.8210070007
- --8210070083 Submits daily highlight re util completion of cutting 3-inch hole in steam generator B on 82030B Burst tube & tubes 844054,R43054 & R43056 removed for metallurgical eram Heeting tentatively scheduled for 820322 LYONS-J.E Operating Reactors Branch 5 82/03/10 DENTON.H. CARTER.J. EISENHUT.D NRC NO Detailed Affiliation Given 1p 15645 100 24X Fichs 50-000,82/08/10.8210070007
- --8210070087 Bubmits daily highlight re 820323 meeting w/util to Westinghouse concerning status of proposed repair activities Twenty-four tubes removed from stamm generator Beforeign object found in Hedge Area 4
  LYONS-JE Operating Reactors Branch 5 82/04/05 DENTON.H.
  CARTER-J. EISENNUT.D NRC No Detailed Affiliation Given 2pp 13645 101 24X Fiche 50-000, 82/08/10.8210070007
- ---8210070090 Submits daily highlight re restart of facility Plant expected to be ready for operations above 5% power upon completion of startup physics testing on 820325 LYONS.JE Operating Reactors Branch 5 82/08/25 DENTON.H , CARTER.J , EISENHUT, D NRC No Detailed Affiliation Given ip 15645 103 24% Fitche 50-000, 82/08/10,8210070007
- --8210070121 Forwards preliminary estimate of leak rate vs time during Ginna 820125 steam generator tube rupture event & plot showing important parameters & status of sys IPPOLITO.T A Operating Reactors Assessment Branch 82/02/05 RDE.J. NRC No Detailed Affiliation Given 3pp 15645 121 24X Fiche 50-000,82/08/10.8210070007
- --B210070135 Bevil rept input re Ginna 820125 steam generator tube rupture event NRC 16th monthly status rept to Congress ra TMI-1 restart encl \* NRC No Detailed Affiliation Given 82/03/11 3pp 15645 12B. 24X Fiche 50-000,82/08/10.8210070007
- --8210070165 Beyil rept input re removal of selected tube samples through two access ports drilled in side of steam generator to obtain metallurgical data for evaluation of steam generator B tube failure mechanism

  \* NRC No Detailed Affiliation Given 82/04/08 2pp 15645 136 24K Fiche 50-000, 82/08/10, 8210070007

- 8210010444 Responds to NRC 620902 request for review of NUREO-0737. Item II B 3. "Post-Accident Sampling " Criterion will be adequately addressed by 830213 MAIER. J E Rochester Oas & Electric Corp 82/09/23 CRUTCHFIELD. D Operating Reactors Branch S 1p 15570 174 24X Fiche 50-244.82/09/23.8210010444
- 8210010357 Forwards application to amend App A of License DPR-18 & proposed Tech Specs to permit reorganization of plant staff MAIER J E Rochester Gas & Electric Corp 82/09/28 DENION, H B Office of Nuclear Reactor Regulation, Director 1p 15574 144 24% Fiche 50-244,82/09/28,8210010357
- --8210010365 Application to amend App A of License DPR-18, changing lech Specs to permit reorganisation of plant staff MAIER. J E Rochester Gas & Electric Corp 82/09/28 2pp 13374 145 24% Fiche 50-244.82/09/28.8210010357
- --8210010369 Proposed Tech Spec changes to permit reorganization of plant staff

  \* Rochester Qas & Electric Corp 82/09/28 11pp 15574 147 24% Fiche 50-244,82/09/28,8210010357
- 82:0040281 Forwards application to amend License DPR-18, revising containment isolation boundary requirements
  MAIER, J E Rochester Gas & Electric Corp 82/09/28 DENTON, H H
  Office of Nuclear Reactor Regulation, Director 1p 15587 169 24K
  Fiche 50-244, 82/09/28, 82:0040281
- --8210040284 Application to amend License DPR-i8, revising containment isolation boundary table MAIER, JE Rochester Gas & Electric Corp 82/09/28 4pp 15587 170 24% Fiche 50-244, 82/09/28, 821004028;
- --8210040288 Proposed change to Tech Spec Page 3 6-6 re containment isolation boundary table Safety evaluation encl \* Rochester Qas & Electric Corp 82/09/28 3pp 15587 L74 24x Fiche 50-244,82/09/28.8210040286
- B210050214 Notifies that except for occasional transient species, no federally listed or proposed threatened or endangered species exist in project impact area, in response to 820902 request Federal list of endangered species encl HAMILYON, P.P. Interior. Dept of, Fish & Wildlife Service 82/07/20 CRUTCHFIELD, D. Operating Reactors Branch 5. 3pp. 15611 257 24X Fiche 50-244,82/09/28,8210050214
- 8210050059 Approves 800220 request for withholding info re use of mixed or ide fuel assemblies for Cycle 10 from public disclosure (ref 10CFR2 790)
  CRUTCHFIELD,D Operating Reactors Branch 5 82/09/29
  WIESEMANN,R A Westinghouse Electric Corp 3pp 15605 171 24x
  Fiche 50-244,82/09/29,8210050059
- 8210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820709 ltr Staff encouraged to develop & implement means to incorporate positive attributes of Phase III in licensee/NRC interface MACION R H SEP Duners Group 82/10/07 EISENHUT, D G Division of Licensing 7pp 15682 179 24X Fiche 50-000.82/10/07.8210130326
- B210180074 Forwards 820717 response to ACRB comments & recommendations per facility SEP review CRUTCHFIELD,D Operating Reactors Branch 5 82/10/07 MAIER. J E. Rochester Oas & Electric Corp 2pp 15719 347 24X Fiche 50-244,82/10/07,8210180074
- --8210180083 Responds to ACRS 820818 comments & recommendations re facility SEP review Draft NUREO-0821 will be revised to reflect egreements DENTON, H R Office of Nuclear Reactor Regulation, Director 82/09/17 SHEWMON, PS ACRS - Advisory Committee on Reactor 8afeguards 2pp 15719 349 24X Fiche 50-244,82/10/07, 8210180074
- 8210180082 Forwards Amend 54 to License DPR-18, safety evaluation & notice of issuance & availability Amend approves provisions updating containment isolation valve in Table 3 6-1, to reflect plant sys mod CRUTCHFIELD.D. Operating Reactors Branch 5 82/10/07 MAIER.J E Rochester Oas & Electric Corp. 2pp. 15719 294 24X Fiche 50-244, 82/10/07, 8210180082
- ---8210180087 Amend 54 to License DPR-18.approving provisions updating containment isolation valve in Table 3 6-1, to reflect plant sys mod CRUTCHFIELD, D Derating Reactors Branch 5 82/10/07 1p 19719 296 24X Fiche 50-244
- --8210180090 Sefety evaluation supporting Amend 54 to License DPR-1B + Office of Nuclear Reactor Regulation, Director 82/10/07 Opp 15719-300 24X Fiche 50-244.82/10/07,8210180082

- --8210180094 Notice of issuance & availability of Amend 54 to License PRR-18
  GRUTCHF[ELD,D Operating Reactors Branch 5 82/10/07 2pp 15717 303 24X Fiche 50-244, 82/10/07, 8210180082
- 8210180112 Forwards 821004 FR notice announcing ACRS Subcummittee on Eitreme External Phenomena 821021 & 22 meetings in Santa Monica.CA to discuss flooding & selsmic hazards CRUTCHFIELD. D. Operating Reactors Branch 5 82/10/07 MAIER. J E Rochester Oas & Electric Corp. Jpp. 15719 322 24X Fiche 50-244.82/10/07.8210180112
- 8210180149 Forwards Amend 55 to License DPR-18 safety evaluation & notice of issuance & availability Amend incorporates new License Condition 2 C(10) to confirm that next steam generator insp will be performed during refueling outage CRUTCHFIELD. D. Operating Reactors Branch 5 82/10/08 MAIER, J E Rochester Cas & Electric Corp. 2pp 15719 105 24X Fiche 50-244, 82/10/08,8210180149
- --8210180153 Amend 55 to License DPR-18.incorporating new License Condition 2 C(10) to confirm that next steam generator inspinyolving eddy current & visual insps & water lancing will be performed during refueling outage CRUTCHFIELD.D Operating Reactors Branch 5 82/10/08 2pp 15719 107 24% Fiche 50-244, 82/10/08.8210180149
- --8210180158 Bafety evaluation supporting Amend 35 to License DPR-18 4 Office of Nuclear Reactor Regulation, Director 82/10/08 3p, 15717 109 24X Fiche 50-244,82/10/08,8210180149
- --8210180161 Notice of issuance & availability of Amend 55 to License DRR-18 GRUTCHFIELD,D Operating Reactors Branch 5 82/10/08 2pp 15719 112 24X Fiche 50-244,82/10/08,8210180149
- 8210180181 Clarifies 820702 request for add1 info re NUREQ-0737, Item II B 3, "Post-Accident Sampling Sys " Clarification section of 820702 ltr provides staff guidelines, not requirements on meeting NUREC-0737 criteria CRUTCHFIELD, D Derating Reactors Branch 5 82/10/08 MAIER, J E Rochester Gas & Electric Corp 3pp 19719 145 24X Fiche 50-244, 82/10/08, 8210180181
- B210220105 Advises that review of util 810904 response to NUREO-0737, Item III D 3 4, "Control Room Habitability," completed Issue satisfactorily resolved except for single failure criterion of intake & exhaust ductwork CRUTCHFIELD D Operating Reactors Branch 5 82/10/18 MAIER, J E Rochester Gas & Electric Corp 2pp 15775 100 24% Fiche 50-244, 82/10/18, 8210220105
- --8209140027 Informs that info submitted by licensee in response to NUREO-0737. Item III D 3 4. "Control Room Habitability" acceptable MURPHY, D W Battelle Hemorial Institute, Pacific Northwest Laboratory FIN 8-2323 82/03/23 HULMAN, L Q Accident Evaluation Branch 2pp 15775 102 24X Fiche 50-244,82/10/18,8210220105
- E210250275 Forwards status rept re unresolved safety issues, per NRC B20617 request Info includes description of problem based on NRC documentation MAIER, J E Rochester Gas & Electric Corp 82/10/19 CRUTCHFIELD, D Operating Reactors Branch 5 47pp 15791 049 24% Fiche 50-244, B2/10/19, B210250275
- Q Inspection reports, IE Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON J M Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 15445 063 24X Fiche 50-000, 82/08/10,8210070007
- --B210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VARQA,B Operating Reactors Branch 1 5pp 15645 131 24X Fichs 50-000,82/08/10,8210070007

- --8210070172 Forwards info re steam generator integrity & insps at all operating PiRs.per 750320 & 21 requests Details of insps. including defect indications tube plugging criteria & tubes plugged will not be provided except for Point Beach 1 GOLLER.K R Division of Reactor Licensing (RRR-1975 only) 75/03/24 MACCARY.R R Division of lechnical Review (NRR-1975 only) 5pp 15645 196 24X Fiche 50-000.82/08/10.8210070007
- 8208190233 IE Info Notice 80-35. Suppl 1: 'Leaking & Dislodged I-125 Implant Seeds '' Svc list ond Indiana Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15/61 250 24X Fiche 50-000.82/10/06 #208190233
- 6210130439 Discusses results of eddy current fiber optics,video & visual insps Burst in inactive tube in B-steam generator inlet probably caused by reduction in uall due to wear & pressurization from primary side through leaking plug MAIER. J E Rochester Gas & Electric Corp 82/10/06 CRUTCHFIELD. D Operating Reactors Dranch 5 3pp 15682 010 24x Fiche 50-244,82/10/06,8210130439
- 8210210201 Forwards IE Insp Rept 50~244/82-16 on 820830 0903 No noncompliance noted MARTIN T T Division of Engineering & Technical Programs 82/10/06 MATER. J E Rochester Gas & Clectric Corp 2pp 15/66 345 24X Fiche 50~244
- --8210210213 IE Insp Rept 50-244/82-16 on 820830 0703 No noncompliance noted Major areas inspected followup on previously identified insp findings, administrative controls for design changes & mods & mod & design program BLUMBERG.N. BISSETT.P. CAPHTON. & L. Division of Project & Resident Programs 82/10/05 9pp 15766 347 24X Fiche 50-244,82/10/06,8210210201
- 0210190500 Ack receipt of 020224 ltr informing NRC of steps taken to correct violations noted in IC Insp Rept 90-244/81-22 ALLANJ M Region 1. Office of Director 02/10/07 MA(FR.J E Rochester 0as & Electric Coip ip 15739 307 24x Fiche 50-244,02/10/07.0210190500
- --8210190591 Responds to NRC 811215 ltr re violations noted in Il Irisp Rept 50-244/81-22 Corrective actions emergency plan training program will be realigned by 820115 to be consistent w/ functional area requirements MATER. J E Rochester Oas & Electric Corp 82/02/24 HAYNE's, R C Region 1. Office of Director 4pp 15739 300 249 Fiche 50-244.82/10/07.8210190580
- --82(0190618 Responds to NRC 811215 ltr re violations noted in IL lisp Rept 50-244/81-22 Corrective actions clarified required action, eliminated existing ambiguities, inconsistencies & errors for emergency functions

  MAIER, J E Rochester Gas & Electric Corp 82/04/19 HAYRES, R (
  Region 1, Office of Directo; 2pp 19739 312 24X
  Fiche 50-244,82/10/07,8210170580
- --8210190637 Responds to NRC 820520 itr re violations noted in 11 Insp Rept 50-244/81-22 Corrective actions committee established to evaluate & inventory supplies Rept will be submitted by 921231 MATER, J.E. Rochester Gas & Electric Corp. 82/06/30 SMITH, G.H. Division of Emergency Preparedness & Operational Support. 22pp 15739-314 24X Fichs 50-244, 82/10/07, 8210190580
- --8210190647 Responds to NRC 811215 ltr re violations noted in IE Insp Rept 50-244/81-22 Corrective actions revision of Emergency Plan 8C-1 completed prior to startup after 1982 refueling shutdown MAIER, J.E. Rochester Oas & Electric Corp. 82/10/07 HAYNES, R.C. Region 1, Office of Director 1p. 15739 336 24X Fiche 50-244,82/10/07.8210190580
- 8210180149 Forwards Amend 55 to License DPR-18 safety evaluation & notice of issuance & availability Amend incorporates new License Condition 2 C(10) to confirm that next steam generator insp will be performed during refueling outage CRUTCHFIELD.) Operating Reactors Branch 5 82/10/08 MAIER, J & Rochester Oas & Electric Corp 2pp 15719 105 24% Fichs 50-244, 82/10/08, 8210180149
- --8210180153 Amend 55 to License DPR-18, incorporating new License Condition 2 C(10) to confirm that next steam generator insprinvolving eddy current & visual insprax water lancing will be performed during refueling outage CRUTCHFIELD, D Derating Reactors Branch 5 82/10/08 2p.p. 13719 107 24X Fiche 50-244, 82/10/08, 8210180149
- --B2101B0198 Safety evaluation supporting Amend 55 to License DPR-18 \* Office of Nuclear Reactor Regulation. Director B2/10/08 3pp 15719 109 24X Fiche 50-244.82/10/08.8210180149

- -8210180161 Notice of issuance & availability of Amend 55 to License DPR-18
  CRUICHFIELD.D Operating Reactors Branch 5 82/10/08 2pp 15/19 112 24X Fiche 50-244,82/10/08,8210180149
- 8210220344 Ack receipt of 820915 & 1005 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/82-14
  STAROSIECKI.R Division of Project & Resident Programs 82/10/13 MAIER.J E Rochester Gas & Electric Corp lp 15777 355 24X Fiche 50-244.82/10/13.8210220344
- --8210220352 Responds to NRC B20B16 ltr reviolations noted in IE Insp Rept 50-244/B2-14 Corrective actions all four 480-volt safeguard buses tested & draft test procedure issued to off-site engineering dept for review MAIER. J E Rochester Gas X Electric Corp 82/09/15 BRUNNER. E J Region 1, Off-ice of Director 2pp 15777 356 24X Fiche 50-244.82/10/13.8210220344
- --8210220360 Responds to NRC 820816 ltr re violations noted in IE Insp Rept 50-244/82-14 Corrective actions all four 480-volt safeguards buses tested & draft test procedure issued to off-site engineering dept for review MATER-J E Rochester Gas & Electric Corp 82/10/05 BRUNNER, E J Region I. Off-ice of Director 2pp 15777 358 24X Fiche 50-244,82/10/13.8210220344
- 8208190238 IE Gulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sysfiping at BMR Plants "Svc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24x Fiche 50-000. 82/10/14.82881902238
- 8210290171 Forwards IE Insp Rept 50-244/82-18 on 820901-0930 No noncompliance noted STAROSTECKI.R Division of Project & Resident Programs 82/10/1 MATER.J E Rochester Ges & Electric Corp 2pp 15853 276 24X Fiche 50-244.02/10/14,8210290171
- --8210290173 IE Insp Rept 50-244/82-18 on 820901-0930 No noncompliance noted Hajor areas inspected plant operations, surveillance testing, LERs, licensed 'nonlicensed employee training programs & followup or THE lessons learned implementation ZIMMERMAN, R.P., BAUNACK, W.H., KISTER, H.B. Division of Project & Resident Programs 82/10/13 11pp 15853 298 24X Fiche 50-244,82/10/14.8210290171
- 8210290212 Act receipt of 821015 ltr informing BRC of steps taken to correct violations noted in IE Insp Rept 50-244/82-15 STAROSTECKI.R Division of Project & Resident Programs 82/10/25 MAIER, J E Rochester Oas & Electric Corp 1p 15853 279 24X Fiche 50-244,82/10/25,8210290212
- --8210270217 Responds to NRC 820714 ltr re violations noted in IE Insp Rept 50-244/82-15 Corrective actions situation reviewed 5 determined to be isolated case Forther action unnecessary MAIER, J.E. Rochester Gas & Electric Corp. 82/10/15 BRUNNER, E.J. Region 1. Office of Director 2pp. 15853 280 24X Fiche 50-244/82/10/25, 8210270212

- 8210190703 LER 82-022/017 on 821001 one tube of A steam generator inlet found w/crevice intergranular attack indication above plugging limit 8 steam generator inlet had 28 tubes above plugging limit 8 2 w/stress corrosion Rept follows
  SNOW, 8 A Rochester Cas & Electric Corp 82/10/04 HAYNES, R C
  Region 1, Office of Director ip 10736 154 24X
  Fiche 50-244, 82/10/04,82/107903
- 8210250334 Forwards LER 82-022/01T-0
  MAIER, J E Rochester Oas & Electric Corp 82/10/15 HAYNES, R C
  Region 1. Office of Director 1p 15790 001 24X
  Fiche 50-244, 82/10/15, 8210250334
- --8210250343 LER 82-022/01T-0 on 821001, eddy current exam of steam generator A inlet indicated one tube w/crevice intergranular attack indication above plugging criteria & 32 tubes on steam generator 8 w/indications All 33 tubes plugged BDDINE.J C Rochester Gas & Electric Corp 82/10/15 Region I Office of Director 2pp 15790 002 24X Fiche 30-244, 82/10/15.8210250334
- DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8210040120 Discusses util compliance w/SEP Topic VIII-3 B. "DC Power Sys Dus Voltage Monitoring & Annunciation "Sufficient monitoring equipment provided in control room or locally to alert operators of dc sys trouble No mode needed CDUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) CDUNSIL.W G Northeast Utilities 82/09/23 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 15381 204 24% Fiche 50-245, 82/09/23, 8210040120
- 8210210192 Forwards IE Insp Repts 50-245/82-17 & 50-334/82-19 on 820808-0925 No nuncompliance noted STAROSTICKI, R Division of Project & Resident Programs 82/10/0/ COUNSIL.N Q Northeast Nuclear Energy Ca (subs of Northeast Utilities) 2pp 15766 041 24% Fiche 50-245,82/10/07,8210810102
- --6210210196 IE Insp Repts 50-245/82-17 & 50-336/82-19 on 620808-09.5 k noncompliance noted Major areas inspected plant & refueling operations, equipment alignments & readiness, radiation protection & physical security SHEDLOSKY.J T , LIPINSKI.D R , ELABSER.T C Division of Project L Resident Programs 82/10/05 15pp 15766 043 24X Fiche 50-245,82/10/07,8210210182
- P Operating license stage documents & correspondence
- 8210010312 Requests that processing of 820812 license amend application be postponed Revised application changing radiological effluent Tech Specs will be docketed on or about 82115 for both facilities
  COUNSIL.W O Connecticut Yankee Atomic Power Co COUNSIL.W Q
  Northeast Nuclear Energy Co (subs of Northeast Utilities)
  COUNSIL.W O Northeast Utilities 82/09/22 CLARK,R A Operating Reactors Branch 3 CRUTCHFIELD.D Operating Reactors Branch 3 Spp. 15574 047 24X Fiche 30-000.82/09/22.8210010312
- 621005011B Forwards summary of differences for SEP topics & description of intended actions Schedule provided for topics requiring add1 into Topics will be addressed in detail in topics specific correspondence COUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W 0 Northeast Utilities 82/09/22. CRUTCHFIELD.D Operating Reactors Branch 5 48pp 15604 182 J4x Fiche 50-245,82/09/22.8210050118
- B210010320 Summary of B20915 meeting w/util in Bethesda,MD re post-LOLA combustible gas control evaluation fuel/clad gap iodine release vs water radiolysis rates Calculational methodology presented in util 820806 submittal acceptable SHEA.J J Operating Reactors Branch 5 82/09/23 Operating Reactors Branch 5 6pp 15874 040 24X Fiche 50-245,82/09/23.8210010320
- 8210050177 Comments on NRC evaluation of SEP Topic VIII-2, "Emergency Unsite Power Sys" Protective trips of gas tupbine interlacks should be bypassed under accident conditions unless bypassing trip would result in machine destruction COUNBIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.W O Northeast Utilities 82/09/27 CRUTCHFIELD.D Operating Reactors Branch 5 4pp 13603 350 241 Fichs 30-245,82/09/27,8210050177
- 8210040233 Informs that SEP Topic V-6, "Reactor Vessel Integrity:"
  meets current criteria Evaluation will be basic input to
  integrated safety assessment for facility.
  SHEA: J Operating Reactors Branch 5 82/09/29 COUNSIL. W 0
  Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp
  15581 360 24X Firbs, 50-245, 82/09/29, 8210040233.

# DOCKETED ITEMS

- 8210040293 Informs that licensee response to Item (a) of NRC 820428 ltr re SEF Topic III-5 B. 'Pipe Break Outside Containment," acceptable NRC draft evaluation factually correct & considered final NRC evaluation of topic SHEA. J. Operating Reactors Branch 5 82/09/29 COUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 15587 135 24X Fiche 50-245.82/09/29.8210040293
- 821006004B Comments on NRC evaluation of SEP Topic 111-4 B, "Turbine fitseles" Current insp & testing schedules adequate to provide assurance that turbine missiles not safety concern COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities 82/09/29 CRUTCHFIELD.D Deprating Reactiols Branch 5 2pp [5614 332 24% Fiche 50-245, 82/09/29, 8210060048
- 8210040074 Responds to open items identified in 820430 safety evaluations for 6EP Topics III-6. "Seismic Design Considerations" & III-11. "Component Integrity " Corrections & status of IE Bulletin 79-14 program mods encl COUNSIL. II O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL. II O Northeast Utilities 82/09/29 CRUICHFIELD. D Operating Reactors Branch 5 9pp 15615 013 24X Fiche 50-245.82/09/29.8210060074
- 82;0290405 Responds to request for estimate of amount of lodine released to coolant following LOCA Total care inventory of iodine both stable & radioactive isotopes, approx 10 kg, w/variation depending on fuel burnup HULMAN.L G Accident Evaluation Branch 82/09/29 CRUTCHFIELD,D Operating Reactors Branch 3 Jpp 15863 307 24X Fiche 50-245, 82/09/29, 8210290405
- G210150362 Advises that gas turbine generator bldg can adequately resist design basis tornado loadings.per SEP Topic III-2 re wind & tornado loadings Fechnical evaluation rept & final SER encl SHEALJ Operating Reactors Branch 5 82/09/30 COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 9pp 15710 244 24X Fiche 50-245.82/09/30.8210150382
- --8206230020 'Wind & Tornado Loadings." technical evaluation rept BARRETT.D J., AGARNAL.R Franklin Institute/Franklin Research Center NRC-03-79-118 TER-C5257-403 82/06/21 PERSINKO.D NRC - No Detailed Affiliation Given 120pp 15710 254 24X Fiche 50-245,82/09/30.8210150382
- 6210130331 Discusses revision of administrative procedures to incorporate revised working hour guidelines & provisions for authorizing deviations per 820208 & 0615 requests. TMI I fem I A 1.3. "Shift Manning" & Generic Ltr 82-12 COUNSIL W G. CAONETTA J.P. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL W G. Connecticut Yankes Atomic Power Co. 82/10/01 EISENHUT, D.G. Division of Licensing. 3pp. 15679-127 24X Fichs 50-000, 82/10/01. 8210130331
- 5210130073 Forwards request for addl info to containment purge & vent operability (B-24) necessary to complete review CRUTCHFIECLD.D Operating Reactors Branch 5 B2/10/05 COUNBIL.W O Northeast Nuclear Cnergy Co (subs of Northeast Utilities) 4pp 15673 115 24X Fiche 50-245.82/10/05.8210130093
- 8210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820909 ltm Staff encouraged to develop & implement means to incorporate positive attributes of Phase III in licensee/NRC interface KACICH,R H SEP Owners Group 82/10/07 EISENHUT,D G Division of Licensing 7pp 15682 179 24% Ficha 50-000,82/10/07.8210130326
- 8210220486 Forwards final evaluation of SEP Topic VI-4, "Containment Isolation Sys" Deviations from review guidelines listed Implementation of administrative controls on valves recommended SHEALU J Operating Reactors Branch 5 B2/10/08 COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 34pp 15779 036 24X Fiche 50-245,82/10/08.8210220486
- 8210270200 Forwards summary of NRC positions on 26 unresolved safety issues, consisting of excerpts from NRC publications & repts to Congress & assessment of generic applicability Adequate basis exists to warrant continued plant operation COUNSIL, H O . OPEKA, J F Connecticut Yankee Atomic Power Co COUNSIL, W O . Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/13 CRUICHFIELD, D Operating Reactors Branch 5 48pp 15824 354 24x Fiche 50-000, 82/10/13, 8210270200
- 8210240194 Discusses util review of rod control carcuitry No credible single failure could cause inadventent movement of more than one control rod at time info should resolve concerns re SEP Topic IV-2, "Reactivity Control Bys "
  COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities 92/10/14
  CRUICHFIELD.D Operating Reactors Branch 5 2pp 15799 019 24X Fiche 50-245, 82/10/14 8210260194

- 8210260414 Provides addl info re 2-phase degraded grid undervoltage protection scheme for Class IE power sys.in response to 820623 request Mods will be deferred until 1984 refueling outage Next rept will be submitted during Jul 1983 CDUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O . OPEXALJ F Northeast Utilities 82/10/14 CRUTCHFIELD.D Operating Reactors Branch 5 App 19806 144 24X Fichs 50-245.82/10/14.8210260414
- 8210250124 Forwards draft integrated plant safety assessment rept Draft provided for SEP Subcommittee 821026-27 maeting CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/15 COUNSIL,W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 79pp 15787 164 24X Fiche 50-245,82/10/15.8210250124
- 8210260519 Forwards proprietary "STR Bundle Submittal Millstone-1 Segmented Test Rod Bundle Suppl 6." as app to 821015 Reload B Iscense amend submittal Rept withheld (ref 100FR2 790) COUNSIL W O. OPEMA.J F Northeast Nuclear Energy Co. (subs of Northeast Utilities) COUNSIL, W O. Northeast Utilities 82/10/15 CRUTCHFIELD, D. Operating Reactors Branch 5 3pp 15805 228 24x Fiche 50-245, 82/10/15, 8210260519
- 6210260459 Forwards corrections to draft evaluation of SEP Topic III-1, "Classification of Structures, Components & Sys." in response to 820505 request COUNSIL.W 9. BISHOP.R W. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL.W 9. Northeast Utilities. 62/10/19 CRUTCHFIELD.D. Operating Reactors Branch 5. 13pp. 15806-210-24X Fiche 50-245.82/10/19.8210260459
- 8210250217 Advises that SEP Topic VI-6 "Containment Leak Testing," considered complete to conduct integrated assessment Multi-plant Item A-4 review will be conducted independent of SEP SHEA. J Operating Reactors Branch 5 82/10/22 COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p 15788 344 24% Fiche 30-245, 82/10/22, 8210830219
- Q Inspection reports, IE Bulletins & correspondence
- 8210060233 Advises that masonry wall mods will be complete by Nov 1982 & const will be completed by June 1983, per IE Bulletin 80-11 COUNSIL.W C Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities #2/09/24 HAYNES.R C Region 1. Office of Director 2pp 15620 008 24X Fiche 50-245, 82/09/24, 8210060233
- 8210150697 Forwards request for addl info to complete review of 801104 response to IE Bulletin 80-11, "Masonry Hall Design "
  Response expected within 60 days of ltr receipt
  CLARK A Operating Reactors Branch 3 82/09/20 COUNSIL, H 0
  Connecticut Yankee Atomic Power Co COUNSIL, H G Northeast Nuclear Energy Co (subs of Northeast Utilities) 13pp 15716 100 24X Fiche 50-000.82/09/28,8210150699
- 821006004B Comments on NRC evaluation of SEP Topic III-4 B, "Turbing Missiles" Current insp & testing schedules adequate to provide assurance that turbine missiles not safety concern COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O Northeast Utilities 82/07/27 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 19614 332 24X Fiche 50-245.82/07/27.8210060048
- 8210070352 Ack receipt of 820714 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/82-10 & 50-336/82-14
  MARTIN.T T Division of Engineering & Technical Programs 82/10/05
  COUNSIL.N G Northeast Nuclear Energy Co (subs of Northwast Utilities) ip 15634 051 24% Fiche 50-245,82/10/05,8210070352
- --8210070356 Responds to NRC 820813 itr reviolations noted in II. Insp. Repts 50-245/82-10 & 50-336/82-14 Corrective actions controlled documents updated & Unit 1 control room drawing deficiencies corrected COUNSIL.W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W Q Northeast Utilities 82/09/14 MARTIN.TT Division of Engineering & Technical Programs 3pp 13584 032 24% Fiche, 50-245, 82/10/05, 8210070352
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Beeds " Svc list encl COBB.L 1 Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidate Edison Co. of New York 66pp 13761 250 24% Fiche 50-000,82/10/06.8208190233
- 8210210182 Forwards IE Insp Repts 50-245/82-17 & 50-336/82-17 on 820808-0925 No noncompliance noted STAROSTECKI, R Division of Project & Resident Programs 82/10/07 COUNSIL-W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 15766 041. 24X Fiche 50-245,82/10/07,8210210182

- --8210210198 IE Insp Repts 50-245/82-17 & 50-336/82-19 on 820808-0925 No noncompliance noted Hajor areas inspected plant & refueling operations, equipment alignments & readiness, radiation protection & physical security SHEDLOSKY, J T., LIPINSKE, D R., ELASSFRIT C. Division of Project & Resident Programs 82/10/05 15pp 15766-043 24X Fichs 50-245,82/10/07.8210210182
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl DEYQUNO.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 11Spp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- 82:0220479 Notification of 82:029 meeting w/util in Bethesda, HO to discuss spray sparger crack indications detected during visual insplusing underwater television equipment SHEA.J.J. Operating Reactors Branch 5 82/10/21 CRUTCHFIELD. D Operating Reactors Branch 5 3pp 15779 075 24X Fiche 50-245, 82/10/21, 82/10220479
- S Reportable occurrences, LERs & related correspondence
- 82:00:0008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety groblems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 19727 005 24X Fiche 30-000.82/06/28.8210010008
- --8103190719 Operating Reactor Event Memo 81-29 re cracking in several ASME Code Class ( & Class 2 piping syx Affected sys are isolation condenser.shutdown cooling.cleanup & LPCI subsystem Defective sections are under repair EISENHUT, D O Division of Licensing 81/03/05 VOLLMER, R Division of Engineering 4pp 15728 259 24X Fiche 50-000,82/06/28,8210010008
- 8210080015 Addi response to FDIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FDIA Exemption 5)
  FELTON.J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X
  Fiche 50-000.82/07/12.8210080015
- --8206070106 Operating Reactor Event Memo 82-01 re 8:0810 reactor scram w/water hammer event Study of Unresolved Safety Issue A-1 shows no other water hammer events in BWR isolation condensers
  EISENHUT, D @ Division of Licensing 82/05/25 VOLLHER, R H Division of Engineering MATTSON, R J Division of Systems Integration (post 81:005) HANAUER, S H Division of Safety Technology 7pp 15665 150 24X Fiche 50-000, 82/07/12, 8210080015.
- 8210070360 LER 82-018/03P on 820925, while performing remate visual image of core agray spargers, crack indication identified on one core agray sparger to junction box welds, Addl info will be provided in 14-day followup rept
  MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities. 82/09/27
  HAYKES, C. Region 1, Office of Director. ip. 15624-059-249
  Fiche 50-245, 82/09/27, 8210070360
- 9210070304 LER 82-019/01P on 820928, three safety relief valves failed to open at required setpoint pressure during bench test Cause under investigation Three remaining safety relief valves will be removed & bench tested.

  NROCZNA:E J Mortheast Nuclear Energy Co (subs of Northeast Utilities)

  HAYNES-R C Region 1. Office of Director 1p 15634 245 24X Fiche 50-245, 82/07/29, 8210070304
- 8210070250 Telecopy message of LER 82-020/01P on 820930.1TT Orinnell snubbers failed foctup & bised rate requirements Snubbers will be made operable or replaced prior to reactor startup MRGCZKA.E J Northeast Noclear Energy Co (subs of Northeast Utilities) MRGCZKA.E J Northeast Utilities 82/10/01 MRGCZKA.E J NORTHEAM MRGCZKA.E J
- 8210210425 Forwards LER 82-018/01T-0 Detailed event analysis encl MRDCZKA: E J Kortheast Nuclear Energy Co (subs of Northeast Utilities). MRDCZKA: E J Northeast Utilities 82/10/12 HAYNES: R C. Region in Office of Director. 2pp 15763 087, 24X Fiche 50-245, 82/10/12, 8210210425

- --B210210430 LER B2-018/017-0 on B20925, crack indication identified on one core spray sparger to junction but weld Caused by high weld residual stresses Stress corresion cracking may have initiated indication Sparger hold clamp will be installed THULLIS Northeast Utilities B2/10/12 Region I. (Iffice of Director ip 15763 069 24% Fiche 50-245, B2/10/12, B310210425
- 9210220103 Forwards LER 92-021/03L-0 Defailed event analysis encl MRDCZKA.E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MRDCZKA.E J Northeast Utilities 82/10/13 HAYNES: R C Region 1. Office of Director 2pp 15778 169 ,14x Fighe 50-245, 82/10/13.8210220103
- --8210220108 LER 82-021/03L-0 on 820913, diesel generator tripped durioperational readiness demonstration test Caused by broken ring type wire lug at current transformer secondary connection due to flexing during installation THULL.T 5 Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/13 Region 1. Office of Director ip 15778 171 24X Fiche 50-245.82/10/13.8210220103
- 8210220112 Forwards LER 82-020/017-0 Detailed event analysis and of MRGCZKALE J MRGCZKALE J Mortheast Nuclear Energy Collision of Northeast Utilities & 82/10/15 HAYNES/R C Region 1, liftice of Director Opp 15778 164 24% Fiche 50-245.82/10/15.82/10/15
- --B210220116 LER 82-020/01T-0 on 820930, four ITT Orinnell shubbers fails to fall within recommended range Fulther analysis showed that only one shubber failed design acceptance range Caused by oil leakage through cracked reservoir THULL, T B Northeast Nuclear Energy Co (subs of Northeast Utilities) B2/10/15 Region 1, Office of Directo; 1p 15778 167 24% Fiche 50-245,82/10/15,8210220112
- 6210220195 Forwards LER 92-019/01T-0 Detailed event analysis envi MRGCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MRGCZKA,E J Northeast Utilities 82/10/15 HAYNESR C Region 1, Office of Director 2pp 15/// 2/0 .4s
- --B210220201 LER 82-019/01T-0 on 820928, five safety relief valves failing to open at required setpoint Cause being investigated by UP Two valves will be replaced or rebuilt Other three will be reworked & retested THULL, TS Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/15 Region i. Office of Director ip 15777 272 24x Fiche 50-245,82/10/15,8210220195
- DOCKET 50-247 INDIAN POINT STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- 8210060145 Forwards "Testing & Repair of Siren Portion of Alert I. Notification Sys for Indian Point Nuclear Power Generating Flant: per discussion at 820708 status meeting MELLY.J J Power Authority of the State of New York (12/6)///: DAVIDOFF, D New York, State of 1p 19614 275 24X Fiche 50-247, 82/707/15, 8210060145
- -8210060148 "Testing & Repair of Siron Portion of Alert & Mutificati Bys for Indian Point Nuclear Power Generating Plant " \* Power Authority of the State of New York 82707/14 lipp 15614 296 24% Fithe 50-247,82707/15,8210060145
- 8210280148 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 82/10/12 Decument Management Branch ip 15862 271 24X Fiche 50-00J, 62/10/14.
- --8210280154 Forwards public version of revisions to Emergency Plan
  Implementing Procedures IP-1020 re airborne radioiodine
  determination & IP-1046 re util personnel responsibilities
  during Unit 3 emergencies
  O'TOOLE.J D Consolidated Edison Co of New York 92/10/01
  HAYMEGR C Region 1: Office of Director 3pp 158/2 2/J 24:
  Fiche 80-003.82/10/12.8210280148
- --8210280159 Public version of revisions to Emergency Plan leplacetoprocedures IP-1020 re airborne radioiodine determination & IP-1046 re util personnel responsibilities during Unit 3 emergencies < Consolidated Edison Co of New York 82/09/01 | Gop 15862 275 24X Fiche 50-003,82/10/12,8210280148

- B210200019 Advises that serious deficiencies in emergency preparedness will not be corrected since State of MY & FEMA not addressing concerns of local officials by involvement in current changes HOLT.J Public Interest Research Group, New York POSNER, P Parents Concerned About Indian Point FLEISHER.Z S West Branch Conservation Association 82/10/15 PALLADINO, N J , AHEARNE, J F , GIL INSKY V Commissioners 5pp 15755 083 24X Fische 50-247, 82/10/15, 82/0200019
- Adjudicatory correspondence
- SLO6230788 Ack receipt of 800416 memo w/insp repts verifying into imactions required of facilities in 800211 confirmatory orders Requests verification that Item F 2 in orders is met Item E 5 in W Gammill 800317 memo should be F 5 NOVAK.T M Assistant Director for Operating Reactors 80/06/13 BRYAN, S E Division of Reactor Operating Inspections 1p 02765 285 24X Fiche 50-247,80/06/03.8006230788
- E210050235 Declines invitation to appear before Subcommittee on Energy Conservation & Power Subcommittee investigation is intrusion into ongoing negulatory proceeding & threatens independence of Commission MORGAN, C Morgan Associates MORGAN, C Power Authority of the State of New York 82/09/30 OTTINGER, R L House of Rep , Energy & Commerce 10pp 15619-360 24X Fiche 50-247,82/09/30,8210060235
- GD10040108 Order CLI-82-28, requesting ASL8 reconstituted by CLI-82-24 to estimate when recommendations called for by CLI-81-23 can be provided CHILK.S J Office of the Socretary of the Commission 82/10/01 Aromic Safety and Licensing Board Panel ip 15580 350 24X Fiche 50-247, 82/10/01, 8210040108
- 9210050254 Memorandum & order restating contentions & establishing procedures based on Commission guidance GLEASON.JP. PARIS.OH. SHON.FJ. Atomic Safety and Licensing Board Panel 82/10/01 42pp 15609 211 24X Fiche 50~247. 62/10/01.82105050254
- 8210130335 Motion for ASLB to direct NRC to reschedule 821013 meeting w/wtile : Sandia in Albuquerque, MM to either New York, NY or Washington, DC Intervener unable to attend meeting in NM WEISS, E.R. Union of Concerned Scientist WEISS, E.R. Public Interest Research Group, New York 82/10/07 Atomic Safety and Licensing Board Panel 3pp 15682 050 24X Fiche 50-247, 82/10/07, 82(0130335)
- --0210130337 Motion for Commission to direct that all future meetings on issues be held in NY or Washington, DC & that intervenors be given notice concurrently w/other parties
  WEISS,E R Union of Concerned Scientists WEISS,E R Public Interest Research Group, Neu York 02/10/07 Commissioners
  2pp 15682 053 24X Fiche 50-247.60/10/07.8210130335
- G210180203 Reply to ASLB 821001 memorandum & order Plant should be totally reinspected w/appropriate tests of piping, electrical tentral systemators and parties should be shortened to active participants Certificate of Svc encl FLEISHER: Z S West Branch Conservation Association 82/10/11 4pp 15718 124 24X Fiche 50-247,82/10/11,8210180203
- 8210150072 Order denying UCS/NY PIRC 821007 motion to direct NRC to reschedule 821013 meeting in Albuquerque, NM to NY or Washington, DC Only Commission has jurisdiction over NRC partormance of administrative responsibilities PARIS, D H. SHON, F J. GLEASON, J P. Atomic Safety and Licensing Board Pamet 82/10/12 Union of Concerned Scientists 3pp 15701 194 24X Fiche 50-247, 82/10/12, 8210150072
- B2(0)50141 Order scheduling B21103-04 prehearing conference in White Plains,NY re oral argument on responses to ASLB B2(00) memorandum 2 order restating contentions GLEASON, J P Atomic Safety and Licensing Board Panel B2/10/12 2pp 15678 306 24% Fiche 50-247,82/10/12,8210150141
- 8210180138 Motion in response to ASLB 821001 order requesting clarification & importance of term "discussion" & extension of time to determine pasition relissue of consolidation Certificate of Svc encl KAPLAN, C New York, NY 82/10/13 Atomic Bafety and Licensing Board Panel 7pp 15719 123 24X Fiche 50-247, 82/10/13, 8210180138
- 8210200069 Telegraphic order granting licensee request for extension of time to file responses to 821001 order All party responses due 821019 GLEASON, J.P. Atomic Safety and Licensing Board Panel 82/10/14 Poper Authority of the State of New York 1p 15757 280 24X Fiche 50-247, 82/10/14, 8210200069

- 8210200019 Advises that serious deficiencies in emergency preparedness will not be corrected since State of NY & FEMA not addressing concerns of local officials by involvement in current changes
  HOLT, J Public Interest Research Group, New York PUSNER, P
  Parents Concerned About Indian Point FLEISHER, Z S West Branch
  Conservation Association 82/10/15 PALLADINO, N J , AHEARNE, J F ,
  OILINSKY, V Commissioners 5pp 15755 083 24X
  Fiche 50-247, 82/10/15, 8210200019
- 6210220369 Submittal of comments on ASLB 821001 memorandum & order & motion for ASLB to issue reformulated contentions on Commission Questions 3 & 4 by 821115 & to restore Contention 6 2 Certificate of Svc enci TOSCANI,K Parents Concerned About Indian Point 82/10/15 Atomic Safety and Licensing Board Panel 2pp 15777 307 24X Fiche 50-247,82/10/15,8210220389
- 8210210390 Requests destruction of West Branch Conservation Assor 821011 reply to 821001 memorandum & order & substitution of encl version FLEISHER, Z B West Branch Conservation Association 82/10/18 NRC - No Detailed Affiliation Given 1p 15744 099 24X Fiche 50-247.82/10/18.8210210390
- --8210210397 Response to 821001 memorandum & order Certificate of Svc encl FLEISHER. Z S West Branch Conservation Association 82/10/13 4pp 15744 100 24X Fiche 50-247, 82/10/18,8210210390
- 8210200059 Response to ASLB 821001 order ASLB should narrow language of ASLB Question 1 1 % adopt proposed schedule for continuation of proceeding Certificate of Svc enci MODRE, J., MCOURRENIH J. Hearing Branch 1 82/10/19 9pp 15757 290 24X Fiche 50-247,82/10/19,8210200059
- 8210220375 Request for mod of ASLB 821001 order, to permit Rockland County to continue presentation of witnesses re Commission Questions 3 & 4 prior to taking evidence on Questions 1, 2, 5, 6 & 7
  THORSEN,E D Rockland County, NY 82/10/19 Atomic Safety and Licensing Board Panel 2pp 15779 187 24X Fiche 50-247, 82/10/19, 8210220375
- 8210220410 Joint response of intervenors to ASLB 821001 order Meaning of "discussion" of probability should be clarified & ASLB should immediately reformulate contentions on Guestions 3 & 4 Certificate of Svc encl WEI8S.E R. Union of Concerned Scientists WEISS.E R. Harmon & Weiss 82/10/19 Atomic Safety and Licensing Board Panel 12pp 15778 313 24X Fiche 50-247,82/10/19,8210220410
- B2102500B1 Proposed hearing schedule Certificate of Svc encl BRANDENBURG. B Consolidated Edison Co of New York MDRGAN, C Power Authority of the State of New York MDRGAN, C Morgan Associates B2/10/19 9pp 15787 049 24X Fiche 50-247, 82/10/19, 82/102500B1
- 8210250216 Response to ASLB 821001 order reformulating contentions Opposes admission of new Contention 1 1.Contentions 2-1(a)-(d).2 2(a) & 2 2(b) & ASLB Question 2 2 1 Notice of appearance & Certificate of Svc encl MCRGAN, C Power Authority of the State of New York MCRGAN, C Morgan Associates 82/10/19 Atomic Safety and Licensing Board Panel 35pp 15789 166 24X Fiche 50-247.82/10/19.8210250216
- 8210250265 Notice of appearance in proceeding BAUM, S.L. Fower Authority of the State of New York DAUM, B.L. Morgan Associates 82/10/19 1p [579] 132 24X Fiche 50-247,82/10/19,8210250265
- 8210250287 Motion for order reversing ASLB 821001 memorandum & order re taking of testimony on Questians 3 & 4 & establishing schedule for presentation of testimony upon expiration of 120-day clock Certificate of Svc encl VETERE.L A Westchester County.NY 82/10/19 Atomic Safety and Licensing Board Panel 7pp 15791 165 24X Fiche 50-247,82/10/19,8210250287
- 8210250324 Memorandum re ASLB 821001 order reformulating contentions Objects to new Contention 1 1.Bases 1a & 1b.Contentions 2 1(a), 2 1(b), 2 1(c), 2 1(d), 2 2(a) & 2 2(b) Certificate of Svc encl BRANDENBURO, B Commonwealth Edison Co 82/10/19 Atomic Safety and Licensing Board Panel 49pp 15790 243 24X Fiche 50-247, 82/10/19, 8210250324
- 8210250099 Motion for leave to file memorandum in response to ASLB 821001 order i day late Mechanical difficulties encountered w/word processing equipment Certificate of Svc encl BRANDENBURG.B Consolidated Edison Co of New York 82/10/20 Commissioners 6pp 15787 062 24X Fiche 50-247,82/10/20, 8210250099.

- 8210280242 Requests Commission issue order directing all meetings between NRC & licensee be held in Washington.DC or NY, that between NRC & licensee be held in Washington DC or NY, that intervenors receive notice of meetings concurrently u/utils & that intervenors be provided u/minutes of 82:013 meeting WEISS.E R Union of Concerned Scientists 82:10/25 PALLADINO, N J . AHEARNE, J . OILINSKY, V Commissioners 2pp 15937 058 24X Fiche 50-247-82/10/25, 23:0098042
- 8210260230 Advises that NRC does not intend to respond to intervenor motions filed in response to ASLO 821001 order until after 210280230 Advises that the does not intered to capable to motions filed in response to ASLB 821001 order until after 821103-04 prehearing conference
  MDGREJE Hearing Branch | 82/10/27 GLEASON.JP, SHON,FJ,
  PARIS,O H Atomic Safety and Licenting Goard Panel | 1p | 15837-082 24X Fighe 50-247,82/10/27,8210280230
- 8210280353 Response opposing UCB/NY PIRG B21012 motion to direct NRC to reschedule all future meetings on hearing issues in NY or Washington; DC NRC should be permitted flexibility to determine most appropriate location W/Certificate of Svc MCGURREN, H J Hearing Branch 1 92/10/27 Commissioners 9pp 18839 048 24% Fiche 50~247,82/10/27,8210280353
- 8210290271 Advises that licensees plan to address all matters raised in responses/motions re ASLB 821001 memorandum & order at 821103-04 prehearing conference BRANDENBURG, B. Consolidated Edison Co. of New York MORGAN, C. Power Authority of the State of New York MORGAN, C. Morgan Associates 82/10/27 GLEASON, P. SHON, F. J., PARIS, D. H. Atomic Safety and Licensing Board Panet 2pp 15853 012 P4X Fiche 50-247, 82/10/27, 8210290271

## H General correspondence

- 8210250272 Requests substitution of SL Baum w/TR Frey on official evo List for proceeding Related correspondence
  COLARULLI.P F Morgan Associates COLARULLI.P F Power Authority
  of the State of New York 82/10/19 STUCKY.S H Docketing &
  Services Branch 1p 15/79/ 190 24X Fiche 50-247,82/10/19 8210250272
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8207180077 Forwards comments on PRA study dealing w/seismic hazard Validity of conclusions rest on quality of primary data bases & assumptions in both studies Repts are not valid risk bases & assumptions in both studies Repts are not valid risk assessments due to data base limitations POMERGY.P W ACRE - Advisory Committee on Reactor Safeguards 82/08/24 OKRENT,D ACRE - Advisory Committee on Reactor Safeguards 7pp 15876 001 24X Fiche 50-003.82/08/24.8207180077

- 8007310117 Forwards request for addl info required to complete transit, Research Ctr evaluation of adequacy of steam generator & reactor coolant pump supports Request should be sent to NICHMAN, K.R. Operating Reactors Assessment Branch B0/07/14 VARGA: S.A. Operating Reactors Branch I. 7pp. 03056-268-24% Fiche 50-247, 80/07/14,8007310117
- BCOBOSO220 Requests LD Marsh be permitted to continue reviewing overpressure protection sys & associated Tech Specs NGVAK.T Assistant Director for Operating Reactors BO/07/10 ERRST.M L Assistant Director for Technology Review 1P 03078 175 24X Fiche 50-247.80/07/30.8008050220
- 8008130744 Summary of 800617 meeting w/utils in Bethesda.MD recontainment structural response to core molt accident JF Power Systems Branch 80/07/31 Power S 93265 243 24X Fiche 50-247,80/07/31,8008130744 Power Systems Brance
- B009100104 Approves Tech Specs revision proposal re insp of hydraulit sluid of snubbers supplied by common reservoir & ercessive fluid loss due to external tubing leakage BARRETTI.L H Operating Reactors Assessment Branch 60/06//05 VARGA.S A Operating Reactors Branch 1 (Pre 800420) ip 03516 0/4 24x Fiche 50-247.80/08/805.8009100104
- 6008210627 Forwards request for addl info re-spent fuel pool retarting info needed to complete review of util application for license amend RUDENSTEIN, L S STEIN.L 8 Assistant Director for Core & Containment (witers) 708 NOVAK.T M Assistant Director for Operating Reactors 93382 306 24% Fiche 50 247.80/08/08.8008210627 80/08/08
- 8007100100 Forwards recommendations on staff task action plan to be sent to licensees for review & response
  DARRETT, L. H. Operating Reactors Associated BARRETT, L. H. Operating Reactors Assessment Branch (80/08) VAROA, S. A. Operating Reactors Branch ( (Pre 8000428) | Bpp 03516 066 24X Fiche 30-247, 80/08/08, 8009100100
- 8007030304 Forwards Reactor Fuel Section questions re LOPAR fuel an core previously containing HIPAR fuel Questions should be torwarded to licensee Forwarded to licensee
  RUBENBEIN.L S. Assistant Director for Core & Containment Systems
  B0/08/18 NOVAK.T M. Assistant Director for Operating Reactors
  3pp 03462 022 24X Fiche 50-247.80/08/18.8009030734
- 80090B0446 Forwards response to 800B20 request for status rept in Zion/Indian Point task action plan Responsibilities are in area of severe accident mitigation features & not in interim operational actions portion MEYER. Operational actions portion
  MEYER.JF Reactor Systems Dranch Bi
  Director for Operating Reactors 2pp
  Fiche 50-003,80/08/25,8009080486 BO/OB/25 NOVAK, T.M. Assistant 03404 009

- 2010240644 Forwards safety evaluation re electrical override of manual /10240644 Forwards safety evaluation re electrical override of ma actuation features for containment ventilation isolation to other ESF sys OLSHIMSKI.J A Operating Reactors Assessment Branch 80/10/06 VARQA.S A Operating Reactors Branch 1 3pp 03661 092 24X Fiche 50-247.80/10/06.8010240644
- 8-)10270312 Advises that Franklin Research Ctr was notified to proceed of final realization of fracture toughness of steam generator. Franklin Research Ctr was notified to proceed to reactor coolant pump supports Due to util B00828 request for delay, appropriate conservative assumptions will be made OLSHRISH J A Operating Reactors Assessment Branch NRC-03-79-J18 B0/L0/06 VARGALS A Operating Reactors Branch J 2pp 03661 208 24X Fiche 50-247.80/10/06.8010270312 NRC-03-79-118
- entifices A Requests Instrumentation & Control Sys Branch evaluation of util responses to questions is incore instrumentation tubes at facilities Info will aid branch evaluation mitigation reatures re backfitting of severe mitigation mitigation reatures re backfitting of severe mitigation features SPEIS.T P Reactor Systems Branch 80/10/09 SATTERFIELD, R Instrumentalium & Control Systems Branch ip 02227 001 2-Fiche 50-247 80/10/09 8011110084
- E010280098 Forwards NRC questions % of it answers re backfitting of severe accident mitigation features Evaluation needed in two Structural Engineering Branch 1p 65767 184 24X Fiche 50-247.80/10/17.8010280078
- 8011200025 Forwards Power Sys Branch evaluation of differences between Indian Point 2 & 3, in response to technical assistance request Requests meeting w/licensee prior to formal response te evaluation
  CHECP P S Assistant Director for Plant Systems 80/10/21
  NOVAN 7 Assistant Director for Operating Reactors 21pp
  03743 111 24X Fiche 50-247, 80/10/21, 8011200025 80/10/21
- HOL1210284 Forwards draft safety evaluation of licensee response to last Action Plan Iten II E 1 2 Automatic initiation logic, instrumentation be associated circuitry & automatic feedwater flow indication channels meet safety-grade requirements SATTERFIELD.R Instrumentation & Control Systems Branch 80/10/6 VARGA.S Operating Reactors Branch 1 8pp 03744 123 24X Fishe 50-247.80/10/22.8011210284 80/10/22
- R011070227 Requests all operating reactor project managers to conduct telephone survey w/licensees to determine if plants are susceptible to svc water leaks Results of survey requested By 801031 OLSIAN: H Decrating Reactors Branch 1 80/10/29 Operation Reactors Branch 1 1p 03715 124 24X Fiche 50-247,80/10/29,
- 8011120679 Forwards response to request for determination of licensing basis for reactor pressure vessel & containment fan cooler sys re FSAR requirements & current NRC criteria Licensee nust perform thermal & stress analysis of vessel LEERING LAINAS.G C Assistant Director for Safety Assessment 80/10/29 EIGENHUT.D Q Division of Licensing 6pp 03719 357 24X Fiche 50-247.B0/10/29.B011120679
- 8011100165 Submits revision of relative concentration for short-term release following an accident Facilities exclusion radius found to be 520 maters resulting in relative concentration equal to 0 00051 sec/cu meter in southwest direction HOUSTEN.R W Accident Evaluation Branch 80/10/30 VARGA.S A Operating Reactors Branch | 1p 65768 021 24% Fiche 50-247,80/10/30,8011100165
- 8207050085 FOIA request for eight categories of records re steam generators & steam turbines LGNO.D J Winthrop, Etimson, Putnam & Roberts 82/07/13 Of of Administration 3pp 15645 O60 24% Fiche 50-247.82/07/13.
- 6210070097 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R\_Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000, 82/08/10, 8210070007

- 8210010401 Forwards application to amend Licenses DPR-26 & DPR-5, troubled Forwards application to amend Licenses DPR-26 & DPR-5, changing Tech Specs refacility organization & Unit 2
  Tech Specs 3 & & 4 & recontainment isolation valves 3 12 & 4 & 12 in pipe lines Class I, II & III fees encl
  0'TGOLE.J D Consolidated Edison Co of New York 82/08/31
  VAROA.S A Operating Reactors Branch I 3pp 15572 211 24X
  Fiche 50-003, 82/08/31,8210010401
- --B210010409 Application to amend Licenses DPR-26 & DPR-5, revising Tech Spec Figures 3 2 & 6 2-2 re facility organization for Units 1 & 2, respectively O'TOOLE, J D Consolidated Edison Co of New York B2/08/31 2pp 15572 214 24x Fiche 50-003,82/08/31,8210010401
- --8210010414 Proposed revisions to Tech Spec Figures 3 2 & 6 2-2, reflecting change in organizational structure to include position of operations superintendent Safety assessment enc 1 enci \* Consolidated Edison Co of New York 82/08/3 15572 216 24% Fiche 50-003,82/08/31,8210010401
- --8210010425 Application to amend License DPR-26, revising Tech Specs 3 6 & 4 4 to establish requirements for action required when containment isolation valves are inoperable & reflect changes to isolation valve provisions
  O'TODLE, J D Consolidated Edison Co of New York
  15572 222 24X Fithe 50-003.82/08/31.8210010401 82/08/31 2on
- --8210010438 Proposed revisions to Tech Specs 3 6 & 4 4, establishing specific requirements for action during inoperability of containment isolation valves & reflecting changes & additions to isolation valve provisions Safety assessment encl \* Consolidated Edison Co of New York 82/08/31 20pp 15572 224 24X Fiche 50-003,82/08/31,8210010401
- --B210010443 Application to amend License DPR-26, revising Tech Spec Sections 3 12 & 4 12 to defflect editorial change safety-related gipe lines & to efflect editorial change O'TOOLE, J D Consolidated Edison Co of New York 82/08/31 & 15572 244 24X Fiche 50-003,82/08/31,8210010401 82/08/31 200
- --8210010449 Proposed revisions to Tech Spec Sections 3 12 & 4 12, reflecting redesigned support sys for safety-related pipe lines & to effect edutorial change Safety assessment encl \* Consolidated Edison Co of New York 82/08/31 18pp 24X Fiche 50-003,82/08/31,8210010401
- 8210080049 Notification of 820929-30 meeting w/util & Franklin Research Ctr in Buchanan NY to discuss contractor review of util THE December 19 of 18 cost of the latest of review at the radiological effluent Tech Specs
  THOMAL J D Operating Reactors Branch 1 82/09/23 VAROA, B A
  Operating Reactors Branch 1 2pp 66367 356 24X
  Fiche 50-247, 82/09/23, 8210080049
- 8210130602 Informs that review of 810731 response to Generic Ltr 81-01, "Qualifications for Insp.Exam & Testing & Audit Personnel," complete Commitments & exceptions to Revision 1 to Reg Guide 1 188 Reg Guide 1 146 acceptable VARQA.S A Operating Reactors Branch 1 82/09/27 0'700LE, J D Consolidated Edison Co of New York 2pp 15672 347 24X Fiche 50-247.82/09/27,8210130602
- 8210130495 Forwards responses to Items 1,3,4 & 8 of NRC 820315 request for add1 info re control of heavy loads (NUREO-0612) Info addressing Items 2:5,6 & 7 will be submitted by 830131 O'TOOLE, J D Consolidated Edison Co of New York 83/09/30 UARGA: 8 A Operating Reactors Branch 1 7pp 15682 019 24X Fiche 50-247, 82/09/30, 8210130485
- 8210120253 Forwards initial comments on Sandia Natl Labs 820825 preliminary draft ltr rept on review & evaluation of probabilistic safety study, addressing wind, seismic, fire, pressurized thermal shock & fan coller issues D'TOOLE, J D Consolidated Edison Co of New York BAYNE, J P PL Authority of the State of New York B2/10/06 VARGA, B A Operat Reactors Branch 1 62pp 15652 215 24X Fiche 30-247,82/10/06,8210120253 Operating
- 6210190693 Advises that results of 820920 svc water sys test prove that Indian Point probabilistic safety study reflect actual plant configuration Remaining plant improvements in 820305 ltr.sxcept ATMS mod.to be complete by return to svc O'TOOLE.J D Consolidated Edison Co of New York 82/10/08 VARGA,6 A Operating Reactors Branch 1 2pp 15738 141 24X Fiche 50-247,82/10/08.8210190493
- 8210210032 Forwards request for addl info to complete review of TMI Item II K 3 25, "Power to Pump Seals" Areas of conformance or deviation from stated position should be identified & info re design & operation of cooling sys provided VAROA.5 A Operating Reactors Branch 1 82/10/15 0/TODLE, J D Consolidated Edison Co of New York 3pp 15774 360 24X Fiche 50-247,82/10/15,8210210032

- 8210280242 Requests Commission issue order directing all meetings between NRC & licensee be held in Washington DC or NY, that intervenors receive notice of meetings concurrently w/utils that intervenors be provided w/minutes of 821013 meeting WEISS.E R Harmon & Heiss WEISS.E R Union of Concerned Scientists 82/10/25 PALLADINO, N J AMEARNE, J GILINBAY, V Commissioners 2pg 15837 058 24X Fiche 50-247, 92/10/25, 9310390342
- 8210280230 Advises that NRC does not intend to respond to intervenor motions filed in response to ASLB 821001 under until after 82103-04 prehearing conference MODRE.J E. Hearing Branch I. 82/10/27 OLEASON.J P., SHON.F J., PARIS.O H. Atomic Safety and Licensing Board Panel. ip. 18837-082 24X Fiche 50-247.82/10/27.8210280230
- 8210280353 Response opposing UCB/HY PIRO 821012 motion to direct NRC to reschedule all future meetings on hearing issues in NY or Washington DC NRC should be permitted flexibility to determine most appropriate location W/Certificate of Svc MCGURREN,H J Hearing Branch | 92/10/27 Commissioners 9pp 15837 048 24% Fiche 50-247-82/10/27-82/0280353
- 8210290271 Advises that licensees plan to address all matters raised in responses/motions re ASLB 821001 memorandum & order at 821003-04 prehearing conference RANDENBURG. B Consolidated Edison Co of New York MORGAN, C Pouer Authority of the State of New York MORGAN, C Horgan Associates 82/10/27 GLEASCH. J P. SHON, F J. PARIS. O H Atomic Safeky and Licensing Board Panel 2pp 19853 012 24X Fiche 50-247. B2/10/27. 8210290271

#### H Ceneral correspondence

;

. |

- 9210250272 Requests substitution of SL Baum w/TR Fray on official syclist for proceeding Related correspondence COLARULLI, P. F. Morgan Associates COLARULLI, P. F. Power Authority of the State of New York 82/10/19 STOCKY, S. W. Docketing & Strvices Branch ip 15791 190 24X Fiche 50-247,82/10/19, 921079-0772
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8207180077 Forwards comments on PRA study dealing w/seismic hazard Validity of conclusions rest on quality of primary data bases & assumptions in both studies Repts are not valid risk assessments due to data base limitations POMEROV, P W ACRS Advisory Committee on Reactor Safeguards 82/08/24 GKRENT, D ACRS Advisory Committee on Reactor Safeguards 7pp 15876 001 24X Fiche 50-003.82/08/24.B207180077
- P Operating license stage documents & correspondence
- 8006240951 Discusses postulated fuel handling accident inside containment, based on licenses 770615 accident analysis Analysis includes worst single failure during accident Sarety evaluation & containment purge sys Tech Specs encl BARRETTIL Operating Reactors Assessment Branch 80/06/06/VARGA, Operating Reactors Assessment Branch 80/06/06/Fiche 50-247,80/06/06.8006240851
- 8007010658 Operating Reactor Event Memo 80-7 re nearly simultaneous trips of Units 2 & 3 Event was of negligible safety significance & trips were unrelated & coincidental EISENHUT.D 0 Division of Licensing 60/06/13 VOLLHER,R H Division of Engineering MATTBON,R J Division of Safety Technology HAMAUER,B H Division of Fuman Factors Bafety 2pp 02815 145 24X Fiche 50-247.80/06/13.8007010658
- 8007070448 Operating Reactor Event Memo 80-8 relows of offsite power Effects of thunderstorm resulted in total loss of offsite power Emergency diesel generators functioned properly EISENHUT. D.O. Division of Licensing 80706/13. VOLLMER, R. H. Division of Engineering ROSS, D.F. Division of Systems Integration (pre 81005) ARNAVERS S. Division of Human Fectors Safety Bpp 02881 349. 24X Fiche 30-247,80/06/13,8007070448
- 8007150303 Notifies that review will be conducted of Offshore Power Bys short-term risk studies using various resources, in response to 800405 request Evaluation will be submitted by 800922 MATTSON, R J Bivision of Bafety Technology. 80/07/02. EISENHUT, D Q Bivision of Licensing 2pp 02752 301 24X Fiche 50-247, 80/07/02, 8007150302
- 8007280312 Summary of 800628 meeting w/util re implications of Class 9 accidents on liquid pathways at facility.

  CODELL. R Hydrologic & Geotechnical Engineering Branch 80/07/08 LEAR Q. Hydrologic & Geotechnical Engineering Branch 5pp.

  03016-253. 24X ficks 50-247, 80/07/08, 8007280312

- 8007310117 Forwards request for add1 info required to complete Franklys Research Ctr evaluation of adequacy of steam generator & reactor collant pump supports Request should be sent to licensee WICHMAN, K. R. Operating Reactors Assessment Branch 80/07/14 VARGA, S. A. Operating Reactors Branch 1 7pp 03056 268 24K Fichs 50-247, 80/07/14, 8007310117
- 8008050220 Requests LS Harsh be permitted to continue reviewing overpressure protection sys & associated Tech Specs NOVAK, T Assistant Director for Operating Reactors 80/0//30 ERNSTM L Assistant Director for Technology Review 1P 030/8 175 24X Fiche 50-247.80/0//30.8008050220
- B008130744 Summary of B00617 meeting w/utils in Bethesda,MD re containment structural response to core melt accident sequences MEYER.JF Power Systems Branch B0/07/31 Power Systems Brar s 3pp 03266 243 24X Fiche 50-247.80/07/31,8008130744
- 8009100104 Approves Tech Specs revision proposal re insp of hydraulic fluid of snubbers supplied by common reservoir & excessive fluid loss due to external tubing leakage BARRETT, L. H. Operating Reactors Assessment Branch 80/09/45 VAROA: S. A. Operating Reactors Branch 1 (Pre 800428) ip 03516 074 24% Fitche 50-247.80/08/05.8009100104
- BOOB210627 Forwards request for add1 info to spont fue) poul veraching
  Info meeded to complete review of util application for
  license amend
  RUBENSTEIN-L S Assistant Director for Core & Containment Systems
  BO/08/08 NOVAK, T M Assistant Director for Operating RestLuis
  3pp 03382 306 24X Fichs 50-247.80/08/08.BDOB21062/
- 8009100100 Forwards recommendations on staff task action plan to be sent to licensees for review 3 response
  BARRETTLUM Operating Reactors Assessment Branch (80/08/08/ VARGA, 8 Operating Reactors Branch 1 (Pre 800428) Upp 03916 086 24X Fithe 50-247.80/08/08/8009100100
- 8009030334 Forwards Reactor Fue) Section questions re tillAR first income previously containing HIPAR fuel Questions should be forwarded to licenses
  RUBEHSTEIN, L. S. Assistant Director for Core & Containment Lystem, 80709/18 NOVAK, T.M. Assistant Director for Operating Heartors
  3pp 03462-022 247 Fiche 50-247,80708/18.8009030344
- 8007080466 Parwards response to 800820 request for status rept rezion/Indian Point task action plan Responsibilities are in area of severe accident mitigation features & not in interesponsional actions portion MEYER.JF Reactor Systems Branch 80/08/25 NIVAK.TH Assass Director for Operating Reactors 2pp 03484 009 24x Fiche 50-003.80/08/25.8009080466
- 8010150103 Discusses union representative allegation re harashes; t security guard personnel Add] info necessary prior to MHK investigation of allegations MARD.M J Office of Inspection & Enforcement. Office of the Director 80/08/28 Office of Inspection & Enforcement. Heffer the Director 2pp 03630 268 24% Fichs 50-247, 80/01/28, 8010150103
- 8007250204 Submits description of work being done on analysis of releases from facilities Simple I-D multicompartment thermal hydraulic code being uritten to dualyze variety of FVEO designs Related data enct restance of the state of the st
- B010220234 Responds to B00917 request re control room review FAC Lite detailed five addl items to near-term GL requirements Item III D 3 4 requires analysis of control room habitability by B10101 HOUSTON.R W Accident Evaluation Branch B0/09/23 VASOA S A Operating Reactors Branch i p 03560 001 24X Fiche 50-247,80/09/25,8010220234
- BO102107B3 Forwards recommendations for meeting ausiliary feafwald min flow requirements Licenses must demonstrate decay heat removal for 10 minutes w/o operator action or reset control valve throttled position CHECK.P S Assistant Director for Plant Bystems BO/07/16 NOVAK.T M Assistant Director for Operating Reacture 2pp 03647 104 24X Fiche 50-247.80/09/28.8010210783
- 8010240329 Discusses human factors control room design intege error on 802217-22 & 800310-11 Corrective actions procedures & implementation schedule provided. Can Ed & PASNY control room dasign repts found incomplete MORELV. A Division of Human Factors Bafety. 80/09/29 CLSHINBKI.J Division of Licensing 3pp 03689 357 248 Fiche 50-247.80/09/29,8010240329.

- E010240644 Forwards safety evaluation re electrical override of manual actuation features for containment ventilation (solation to niher ESF systulesHINSKI, J. A. Operating Reactors Assessment Branch 80/10/06
  - VARGA S A Operating Reactors Branch 1 3pp 03661 092
- 3010270312 Advises that Franklin Research Ctr was notified to proceed of final evaluation of fracture toughness of stoam generator. Treactor coolant pump supports Due to util 800828 request for delay, appropriate conservative assumptions will be made OLSKINSHI, J. A. Operating Reactors Assessment Branch NRC-03-79-118 80/100/05 VARGAS A. Operating Reactors Branch 1 2pp 03461-208 24X Fiche 50-247.80/10/06.8010270312
- 3011110094 Requests Instrumentation & Control Sys Branch evaluation of util responses to questions is incore instrumentation tubes at facilities Info will aid branch evaluation mitigation reatures re backfitting of severe mitigation features SPEIS 1 P Ruactor Systems Branch 80/10/09 SATIERFIELD, R Instrumentation & Control Systems Branch ip 02227 001 24X Fiche 50-247, 80/10/09, 8011110084
- MICEBOOR Forwards NRC questions & util answers re backfitting of severe accident mitigation features Evaluation needed in two
- ETELD, I P Reactor Systems Branch 80/10/17 SCHAUER, F P Structural Engineering Branch Ip 65767 184 24X Fiche 50-247, 80/10/17, 8010280098
- 3011200025 Forwards Power Sys Branch evaluation of differences between Indian Point 2 & 3.in response to technical assistance request Requests meeting w/licensee prior to formal response to evaluation
  - CHECK.P 5 Assistant Director for Plant Systems 80/10/20 ACAP.T Assistant Director for Operating Reactors 21pp 03743 111 24X Fiche 50-247.80/10/21.8011200025
- |011210284 Forwards draft safety evaluation of licensee response to lask Action Plan Item II E | 2 Automatic initiation logic, instrumentalian & associated circuitry & automatic feedwater rice indication channels meet safety-grade requirements VARGA, S | Operating Reactors Branch | 1 | 3 | 3744 | 123 | 24x | 126 | 50-247, 80/10/22, 8011210284
- HOLOSO528 Forwards questionnaire to be completed by each near-term UL teach licensed plant by 80:107 Objective is to assess best collective judgment re extent or problems recently experienced at facility JGRDAN,E L. Office of Inspection & Enforcement, Office of the Director 80/10/28 BRUNNER,E J. Region 1, Philadelphia, Reactor Operations Muclear Support Branch LEWIS,R C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch HEISHMAN,R F. Region 3, Chicago Reactor Operations Nuclear Support Branch 2pp 94581 186 24X Fiche 50~247.80/10/28,8101050528
- Olio70227 Requests all operating reactor project managers to conduct telephone survey w/licensess to determine if plants are susceptible to avo water leaks Results of survey requested
- by 801031 OLSHAUL H Operating Reactors Branch 1 80/10/29 Operati Reactors Branch 1 1p 03715 124 24X Fiche 50-247,80/10/29, 8011070227
- Oil120677 Forwards response to request for determination of licensing basis for reactor pressure vessel & containment fan cooler sys re FSAR requirements & current NRC criteria Licensee must perform thermal & stress analysis of vessel LAINAS. G C Assistant Director for Safety Assessment 80/10/27 EISENHUT. D Q Division of Licensing 6pp 03719 357 24X Fiche 50-247.80/10/29.8011(20679
- Oli100165 Bubmits revision of relative concentration for short-term release following an accident Facilities exclusion radius round to be 520 meters resulting in relative concentration equal to 0 00051 sec/cu meter in southwest direction HUUSTON.R W Accident Evaluation Branch 80/10/30 VAROA.S A Operating Reactors Branch 1 ip 65768 021 24X Fiche 50-247,80/10/30.801:100165
- 207050085 FOIA request for eight categories of records re steam generators & steam turbines
  LONG.D J Ninthrop. Stimson, Putnam & Roberts 82/07/13 Of
  of Administration 3pp 15645 060 24X Fiche 50-247.82/07/13. Office 8207050085
- 210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R\_Vdell FOIA Request 81-313 Forwards documents listed in APP B FELTON, J M Division of Rules and Records 82/08/10 Winthrep, Stimson, Putnam & Roberts 9pp 15645 063 Fiche 50-000, 82/08/10, 8210070007 LONG D J

- B210010401 Forwards application to amend Licenses DPR-26 & DPR-5, changing Tech Spacs re-facility organization & Unit 2
  Tech Spacs 3 6 & 4 4 re-containment isolation valves 3 12 & 4 12 in pipe lines Class I.II & III fees
- --8210010409 Application to amend Licenses DPR-26 & DPR-5, revising Ta Spec Figures 3 2 & 6 2-2 re facility organization for Units 1 & 2, respectively UT0016, VD Consolidated Edison Co. of New York 82/08/31 2p Units 1 & direspectatory 0'TOOLE, J D Consolidated Edison Co of New York 15572 214 24X Fiche 50-003.82/08/31.821001040:
- ---B210010414 Proposed ravisions to Tech Spec Figures 3 2 & A 2-2, reflecting change in organizational structure to include position of operations superintendent Safety assessment \*\* Consolidated Edison Co. of New York 82/08/3 15572 216 244 Ficha 50-003,82/08/31,8210010401 82/08/31
- --0210010425 Application to amend License DPR-26, revising Tech Specs 3 6 & 4 4 to establish requirements for action required when containment isolation valves are inoperable & reflect changes to isolation valve provisions (1700LE, J.D. Cansolidated Edison Co. of New York 85, 15572 222 24% Fiche 50-003, 82/08/31, 8210010401 82/08/31 2p
- --821001043B Proposed revisions to Tech Specs 3 & & 4 4.establishing specific requirements for action during inoperability of containment isolation valves & reflecting changes & additions to isolation valve provisions Safety assessment encl # Consolidated Edison Co of New York 82/08/31 20pp 15572 224 24X Fiche 50-003.82/08/31.2230010401
- --8210010443 Application to amend License DPR-2A, revising Tech Spec Sections 3 12 & 4 12 to defflect editorial change safety-related pipe lines & to efflect editorial change O'TOOLE, J D Consolidated Edison Co of New York 82/08/31 15572 244 24% Fiche 50-003,82/08/31.8210010401 82/08/31 2:
- --8210010449 Proposed revisions to Tech Spec Sections 3 12 & 4 12, reflecting redesigned support sys for safety-related pipe lines & to effect editorial change Safety assessment encl \* Consolidated Edison Co of New York 82/08/31 18pp 15572 246 24X Fiche 50-003, 82/08/31,8210010401
- B2100B0049 Notification of B20929-30 meeting w/util & Franklin Resear Ctr in Buchanan, NY tu discuss contractor review of util radiological effluent Tech Specs THOMA, J O Operating Reactors Branch 1 82/09/23 VAROA, S A Operating Reactors Branch 1 2pp 66367 356 24X Fiche 50-247, 82/09/23, 82100B0049
- 8210130602 Informs that review of 810731 response to Generic Ltr 81-4 POLIDODE Informs that review or BID/31 response to Generic Let da "Qualifications for Insp.Exam & Testing & Audit Personnel," complete Commitments & exceptions to Revision 1 to Reg Quide 1 58 & Reg Quide 1 144 acceptable VARQA.B A Operating Reactors Branch 1 82/09/27 0'TOOLE, J D Consolidated Edison Co of New York 2pp 15692 347 24X Fiche 50-247, 82/09/27, 8210130602
- 8210130455 Forwards responses to Items 1.3.4 & 8 of NRC 820315 requestor add1 info re control of heavy loads (NUREG-0612) Info addressing Items 2.5.6 & 7 will be submitted by 830131 O'TOOLE.J D Consolidated Edison Co of New York 83/09/30 VARGA:S A Operating Reactors Branch 1 7pp 18682 019 24X Fiche 30-247, 82/09/30, 8210130455
- 8210120283 Forwards initial comments on Sandia Natl Labs 820825 preliminary draft ltr rept on review & evaluation of probabilistic safety study, addressing wind, seismic, fire, pressurized thermal shock & fan cooler issues
  O'TOOLE, J D Consolidated Edison Co of New York BAYNE, J. P Por Authority of the State of New York B2/10/06 VARGA: 8 A. Operat Reactors Branch 1 62pp. 15652 215 24X Fichs 50-247, 82/10/06, 82101200283
- 62:10190693 Advises that results of 820920 svc water sys test prove t Indian Point probabilistic safety study reflect actual plant configuration Remaining plant improvements in 820303 ltr-except ATMS mod-to be complete by return to svc O'TOOLE, J D Consolidated Edison Co of New York 82/10/08 VAROA, B A Operating Reactors Branch 1 2pp 18738 141. 24X Fiche 50-247.82/10/08.8210190693
- 8210210032 Forwards request for add1 info to complete review of TMI Item II K 3.25, "Power to Pump Seals " Areae of conformance or deviation from stated position should be identified & info re design & operation of cooling sys provided VARGA-S A Operating Reactors Branch I 82/10/15 D/TOOLE, J D Consolidated Edison Co of New York 3pp 15774 360 24% Fiche 50-247, 82/10/15, 8210210032

- 8210280428 Forwards safety evaluation of adequacy of station electric distribution sys voltages based on util 820709 ltm Sys voltages adequate Review closed VARQA, S.A. Operating Reactors Branch 1 82/10/18 0'TOOLE, J.b. Consolidated Edison Co. of New York 2pp 15860-019 24X Fiche 50-247, 82/10/18, 8210280428
- --8210280430 Safety evaluation supporting adequary of station electric distribution sys voltages
  -- Office of Nuclear Reactor Regulation. Director 19860-021 24X Fiche 90-247-82/10/18-8210280428
- --8210280432 "Adequacy of Station Electric Distribution Sys Voltages.
  Indian Point Nuclear Station, Unit 2 "
  UDY.A C. HEBER, D. A. 6030, Inc. FIN A-6429 EQQ-EA-5307 R01
  62/09/30 PREVATTE.R L. Division of Systems Integration (post
  811005) 14pp 15860 028 247 Fiche 50-247,89/10/18.8210280428
- 8210260332 Notifies of changes in estimated schedule of completion for TMT ftems II F 1. "Noble Gas Monitoring." II B 3. "Post-Accident Sampling." & III D 3: 4. "Control Room Habitability " Mads will be completed by end of refueling O'TOOLE. J D Consolidated Edison Co of New York 82/10/19 WARGA. B A Operating Reactors Branch 1 2pp 15802-357 24X Fiche 50-247, 82/10/19.82102000332
- O Inspection reports: IF Hulbetins & correspondence
- 0210080015 Add1 response to FOIA request for 19 categories of informational reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
  FELTON J II Division of Rules and Records 92/07/12 UDELL.R A Critical Mass Energy Project 9p 19/65 027 24X
  Fithe 50-000, 82/07/12, 8210080015
- ---B2100B0137 Bystematic assessment of licensee performance notes re facility evaluation for 1780 \* NRC - No Betailed Affiliation Given 80/12/31 7pp 15667 358 24X Fiche 50-000, 82/07/12,82100B0015
- 6210070097 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in A Udeki FOIA Request 91-363 Forwards documents listed in App B FELTON, J M Division of Rules and Records 62/08/10 LONG, D J Wintbrop, Stimson, Putham & Roberts 9pp 19645 063 24X Fiche 90-000, 82/08/10, 621007000 /
- --8010070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensess IPPGLITO. T. Operating Reactors Assessment Branch 82/04/01 VARGA.S. Operating Reactors Branch 1 5pp 19645 131 24X Fiche 50-000, 82/08/10, 8010070007
- --G210070172 Forwards into resteam generator integrity & insps at all operating PNRs.per /50370 & 21 requests Details of insps. including defect indications tube plugging criteriat tubes plugged will not be provided except for Point Beach 1 GOLLER.R R Division of Reactor Licensing (NRR-1975 only) 75/03/744 MACCARY.R Division of Technical Review (NRR-1975 only) 5pp 15645 196 24X Fiche 50-000,62/08/10,8210070007
- 8210200078 Forwards stoom generator exam program for 1982 refueling/ maint gutage G'TODLE, J D. Commonwealth Edison Co. 82/08/18 VARGA, 8 A Licensing Branch 1, 21pp 15753 178 24X Fiche 50~247,82/08/18, 8210200078
- ### 8210060024 Forwards IE Insp Rept 50-247/82-18 on 820801-31 & notice of violation

  ### STAROSTECKI.R Division of Project & Resident Programs | 82/09/17 O'TODLE-J D | Consolidated Edison Co | of New York | 2pp | 13615 054 24X Fiche | 50-247.82/09/17.8210060024
- --B210060041 Notice of violation from insp on 820801-31 # Division of Project & Resident Programs 82/07/17 is. 15615 056 24% Fiche 50-247,82/09/17,8210060024
- --B210060046 IE Insp. Rept 50-247/82-18 on B20301-31 Noncompliance notes feilure to maintain containment integrity for isolation valves REGELOWSKI, T., KOLTAY, P., KIBTER, H. Division of Project & Resident Programs. B2/09/16 iSpp. 13515-057 24X Fiche 50-247, 82/09/17, 8210060024
- 8208170233 IE Info Notice 80-35. Buppl 1. "Leaking & Dislodged I-125 Implant Beede " Byc list encl COBB.L I Division of Fuel Facilities. Materials & Bafeguards 82710706 Consolidated Edison Co of New York 66pp 15761 250 24X Fishe 50-000.82/10/06.8208170233

- 8210130556 Ack receipt of 820915 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/82-14
  STARGSTECKI.R Division of Project 2 Resident Programs
  O'TODLE.J D Consolidated Edison Co of New York 1p 15483 304
  24X Fiche 50-247.82/10/06.8210130556
- --B210130559 Forwards response to NRC B20816 ltr re violations noted at IE Insp Rept 50-247/82-14 Corrective actions post-maint tests/insp per CBL-51 will be ensured All post-maint activities after B21101 will be verified D/TOBLE, J. Consolidated Edison Co. of New York B2/09/15 STARDSTECKI.R Division of Project & Resident Programs 1p 15483 305 24X Fishe 50-247,82/10/04,8210130556
- 8210210300 Forwards IE Insp Rept 50-247/82-19 on 820901-30 No honcompliance noted STARQSTECKI, R Division of Project & Resident Programs 82/10/07 O'TODLE, J D Consolidated Edison Co of New York 2pp 1576; 248 24% Fiche 50-247,82/10/07,8210210300
- --8210210307 IE Insp Rept 50-247/82-19 on 820901-30 No noncompliance noted Major areas inspected licensee mgt changes.operational safety verification, plant tours, operability of ESF, safety sys challenges & LER followups
  REBELOWSKI, T., FOLEY, T., KISTER, H. Division of Project & Resident Programs 82/10/06 17pp 15764 250 24% Fiche 50-247,82/10/07 8210210300
- 8208190238 IE Autletin 82-03. "Stress Coriosian Cracking in Ibidi-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- S Reportable occurrences, LERs & related correspondence
- 6210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDHILR A Critical Mass Energy Project 55pp 15727 005 24X Fiche 50-000, 82/06/28, 8210010008
- --8011120679 Forwards response to request for determination of licens basis for reactor pressure vessel & containment fan cooler sys re FBAR requirements & current NRC criteria Licenses must perform thermal & stress analysis of vessel LAINAS, G C Assistant Director for Safety Assessment 80/L0/29 EISENBUIT, B G Division of Licensing App 15728-045 24x Fichs 50-000,82/06/28,8210010008
- ---8011240024 Forwards Containment Sys Branch discussion paper compar facility event w/current licensing criteria RUBENSTEIN. L. Assistant Director for Core & Containment Systems 80/11/07 LAINAS. C. Assistant Director for Safety Assessment 6pp 15728 051 24X Fiche 50-000.82/06/28.8210010008
- ~~BIO3070387 Informs that Safety Program Evaluation Branch does not develop requirements for non-RCS leakage detection Branch evaluates proposed requirement adequary in terms of cost-benefit analysis & possible adverse consequences MURLEY, F.E. Division of Safety Technology 81/02/27 EIBENHUT, D.O. Division of Licensing 2pp 15728 033 24% Fichs 50~000,82/06/28,8210010008
- B210080015 Add1 response to FDIA request for 17 categories of info nuclear reactor events & safety problems. Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON.J M. Division of Rules and Records B2/07/12 UDELL.A A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000.82/07/12.8210080018
- --8205030617 Forwards "Engineering Evaluation of Indian Point Unit Flooding Event of 801017" LANNING W D Director's Office 82/04/22 MICHEL80N.C Director's Office ip 15665 239 24X Fiche 50-000,82/07/12,8210080015
- --8205030617 "Engineering Evaluation of Indian Point Unit 2 Flood; Event of 801017 " LANNING, W D. Director's Office 82/04/30 25pp 15665 240 Fichs 50-000,82/07/12:8210080015.

- 6210060396 Forwards LER 82-036/03L-0 0'TQDLE.J D Consolidated Edison Co of New York 82/09/24 MAYNES.R C Region I. Orfice of Director 1p 15615 326 24X Fiche 50-247, 82/09/24, 8210060396
- --8210060400 LER 82-036/03L-0 on 820825, temporary change procedure authorized to permit simultaneous operation under load of two diesel generators during surveillance tests potentially reducing degree of redundancy Test procedure PTM-21 changed SMITH-M C Consolidated Edison Co of New York 82/09/24 Region I, Office of Director 2pp 15615 327 24X Fiche 50-247.82/09/24.8210060396
- 5210070361 Forwards LER 82-034/03L-0 O'TOCLE.J D Consolidated Edison Co of New York 82/09/27 HAYKES.R C Region 1. Office of Director 1p 15634 060 24X Fiche 50-247, 82/09/27, 8210070361
- --8210070366 LER 82-034/03L-0 on 820828, during normal operation, charging pump 22 developed leak & was declared inoperable Caused by defective gasiet on cylinder head 4 Gasket replaced & pump returned to svc 4 Consolidated Edison Co of New York 82/09/27 Region 1. Office of Director 1p 15634 061 24X Fiche 50-247, 82/09/27. 8210070361
- 6210040141 Forwards LER 82-032/01T-0 O'TOOLE-J D Consolidated Edison Co of New York 82/09/28 HAYNES R C Region 1, Office of Director 1p 15583 088 24 Fiche 50-247, 82/09/28, 8210040141
- --8210040145 LER 82-032/01T-0 on 820817.blowdown outer isolation valve FCV 1215A failed closed due to failure of solenoid valve SOV 1315A Caused by open circuit in pilot solenoid valve SOV 1315A cail Goil replaced F1TZPATRICK,8 Consolidated Edison Co of New York 62/08/31 Region 1. Office of Director 3pp 15583 089 24X F1che 50-247.82/09/28.8210040141
- 8210130411 Forwards LER 82-035/03L-0 O'TGOLE.J D Consolidated Edison Co of New York 82/09/28 HAYNES.R C Region 1. Orfice of Director 1p 15680 241 24X Fiche 50-247. 82/09/28.8210130411
- --B210130419 LER 82-035/03L-0 on 820829 nuclear power range instrumentation channel NAI became inoperative due to failure of power supply unit Cause of unit failure not stated Defective high voltage power supply removed NADIPURAN.P Consolidated Edison Co of New York 82/09/28 Region 1. Office of Director ip 15680 242 24X Fiche 50-247.82/09/28.8210130411
- 8210290267 Part 21 deficiency rept re potential galling problem between stem & bonnet of 1 25-inch & larger A105 carbon steel & A182-F22 valves supplied Feb 1981-Aug 1982 Valves should be serviced & stem &/or bonnet replaced ISABELLE.L D Convai. Inc 82/10/11 HAYNES.R C Region 1, Office of Director 17pp 15854 232 24X Fiche 50-000,82/10/11, 62/10270267
- 82:10250145 Forwards LER 82-039/03L-0 O'TOCLE.J D Consolidated Edison Co of New York 82/10/12 HAYNES.R C Region 1, Office of Director 1p 15787 354 24) Fiche 50-247, 82/10/12:8210250145
- ~-8210250149 LER 82-039/03L-0 on 820910, chemical sampling indicated 13 15% cuncentration of boric acid in storage tank 22 Boric acid transfer pump also out of svc for maint Cause not stated Contents diluted HIMPICHES O Consolidated Edison Co of New York 82/10/12 Region 1. Office of Director 1p 15787 355 24X Fiche 50-247.82/10/12.8210250145
- T Hearing transcripts on non-antitrust matters
- 8210060232 Testamony of JD O'Toole before US House of Representatives Subcommittee on Energy & Conservation of Committee on Energy & Conmerce re role of public participation in NRC proceedings M/Certificate of Bvc Related correspondence O'TOOLE.J D Consolidated Edison Co of New York 82/10/01 2ipp 15621 204 24X Fiche 30-247,82/10/01,8210060232

- DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

  F Security, medical, emergency & fire protection plans
- 8209290125 Releases public version of revised generating station emergency plan corporate command ctr emergency plan implementing procedure FELTON. J. M. Division of Rules and Records 82/09/16 Document Management Branch 1p 15564 122 24X Fiche 50-000,82/09/16,82/099/125
- --B209290225 Public version of Revision 4 to generating station emergency plan corporate command the emergency plan implementing Procedure EOF-3, "Environ/Emergency Coordinator"

  PAJONSKI, J E , LITERSKI, L A , FLESSNER, S A Commonwealth Edison Co B2/08/31 lipp 15564 124 24X Fiche 50-000, 82/09/16, 82/08/270125
- 8210010009 Forwards info to suppl 820701 request for exemption from App R per 820917 telcon Request applies to Sections III 0 2 a & III 0 3 b re installation of fire suppression sys RAUSCH,T J Commonwealth Edison Co 82/09/23 EISENHUT,D Q Division of Licensing 8pp 15565 152 24X Fiche 50-000,82/09/23, 8210010009
- 8210130376 Advises that installation of offsite dose calculation syspogram fully operational tracking model & operational A-model will be delayed until 821231 to complete prime computer installation SHARTZLE D Commonwealth Edison Co 82/10/06 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 15682 098 24X Fiche 50-000, 82/10/06, 8210130374
- 8210270047 Releases public version of revisions to Quad Cities, Zion & Dresden emergency glan annexes & revised generating station semergency plan telephone directory FELTON.J M Division of Rules and Records 62/10/08 Document Management Branch 1p 15877 313 24X Fiche 50-000,82/10/08. 8210270047
- --8210270060 Forwards public version of Revision 3 to Quad Cities & Zion emergency plan annexes.Revision 2 to Dresden emergency plan annex.Revision 0 to Byron emergency plan annex & revised generating station emergency plan tolephone directory MCORE.R D Commonwealth Edison Co 82/07/30 DENTON,H R NRC No Detailed Affiliation Given 5pp 15877 314 24X Fiche 50-000,82/10/08.8210270047
- --8210290077 Public version of Revision 3 to Quad Cities & Zion emergency plan annexes Revision 2 to Dresden emergency plan annex Revision 0 to Byron emergency plan annex \* Commonwealth Edison Co 82/06/30 102pp 15877 319 24X Fiche 50-000,82/10/08:8210290047
- --8210270088 Public version of revised generating station emergency plan telephone directory OALLE, D.P. Commonwealth Edison Co. 82/08/12 43pp 15878, 218 24X Fiche 50-000, 82/10/08, 8210270047
- 8210220358 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs.

  TRAMM.T R Commonwealth Edison Co 82/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp 15776 287 24X Fiche 50-000, 82/10/14, 8210220358
- 8210250170 Advises that plans & preparedness for offsite protection near facility adequate & will be applied in event of radiological emergency IL. State & local plans approved subject verification of adequacy of alerting & notification sys THOMABLEM Federal Emergency Hanagament Agency 82/10/14 DIRCKS, W J Office of the Executive Director for Operations ip 15788:285 24X Fiche 50-010,82/10/14,8210250170.
- Q Adjudicatory correspondence
- 8210010257 Decision ALAB-695 affirming LBP-81-37 & LBP-82-65, sanctioning mod to OL for Unit 3 to permit installation of five high density spant feel storage racks & authorizing issuence of amends to OLs, respectively.

  TOMPKINB.B A Atomic Sefety and Licensing Appeal Panel 82/09/29.

  2pp 15574.056 24X Fiche: 50-237, 82/09/29, 82(0010257

- P Operating license stage documents & correspondence
- 6210090001 Advises that board notification issued on 820903 re use of auxiliary overhead crane rather than main overhead crane to move spent fuel pool racks should have been assued w/Number 81/-82-92
  MIRAGLIA: F. Assistant Director for Safety Assessment 82/09/14
  Atomic Safety and Licensing Board Panel 4pp 15668 341 24%
  Fiche 50-237, 82/09/14, 8210080001
- --8210080002 Board Notification 82-92 informs of util failure to tarry out fuel pool rack removal & installation in manner described in testimony at hearings Auxiliary overhead crane used instead of redundant main overhead crane IPPOLITO.T A Assistant Director for Safety Assessment 82/09/03 Atomic Safety and Licensing Board Panel 2pp 15668 345 24X Fiche 50-237.82/09/14.8210080001
- --8209210383 Recommends board notification re util use of auxiliary crane instead of main redundant crane to install fuel racks, as described in testimony before ASLB Licensee has committed to follow testimony in completing remaining work.

  IPPOLITO, T.A. Assistant Director for Safety Assessment 82/09/03 EISENHUT.D O Division of Licensing 2pp 15668 349 24X Fichs 50-237,82/09/14,8210880001
- 6210120105 Requests delay of implementation due dates rm NUREG-0737, fitems II B 2. "Plant Shielding." II B 3, "Post-Accident Sampling" & II F I 1, "Noble 0as Effluent Monitor" SHARTZ.E D Commonwealth Edison Co 82/10/04 EISENHUT, D 0 Division of Licensing Spp 15651 237 24% Fiche 50-000,82/10/04,8210120105
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" OCCOMMONWEALTH Edison Co 82/10/06 CASE.E 9 Office of Nuclear Reactor Regulation, Director 2pp 15805 137 24X Fiche 50-000, 82/10/06, 82/1026
- --8210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Hanual"

  \* Commonwealth Edison Co 82/09/30 83pp 15805 139 24X Fiche 50-000.82/10/06.8210260526
- 8210180059 Provides addl guidance & clarification re 820806 request for addi info per NUREO-0737. Item II B 3, "Post-Accident Sampling Sys " Detailed reliability analysis not required to satisfy NRC concerns CRUTCHFIELD.D Operating Reactors Branch 5 82/10/08 DELQEOROE.L Commonwealth Edison Co Spp 15720 004 24X Fiche 50-000, 82/10/08, 8210 180059.
- 8210190680 Forwards safety evaluation of licensee 820414 & 0611 responses to NUREO-0737. Item II E 4 2. "Purge/Vent Velve Isolation Dependability " Responses acceptable Topic review completed CRUTCHFIELD.D Operating Reactors Branch 5 82/10/13 DELOEORGE, L. Commonwealth Edison Co 5pp 15738:192 24X Fiche: 80-237. 82/10/13. 82/10/2080
- 8210190445 Forwards supplemental response to Generic Ltr 82-05 re implementation status of NUREG-0737, Items II 8 3, II F 1 2, II F 1 5 & II F 1 6, In response to 821005 request SWARTZ, E D Commonwealth Edison Co 82/10/14, EISENHUT, D G Division of Licensing 5pp 15741 202, 24X Fichs 50-000, 82/10/14, G210190445
- 8210220335 Forwards info re NUREQ-0737, Item II D i, "Performance Testing of BWR Bafety/Relief Velves," per 820727 request.
  Info adequately demonstrates applicability of results of BWR owners group generic test rept NEDE-24998-P to facility BWARTZ.E D Commonwealth Edison Co. 82/10/15 EIBENHUT, D G. Division of Licensing 17pp 15776 Gii 24% Fiche 50-237.82/10/15, 8210220335
- B210250155 Forwards corrections to proposed Tech Spec Pages 1, 2/2, 2-1 & 3 0/4 3-5, supporting review of future reloads & revised Figure 3 5 i, Sheet I, providing extended MAPLHOR vs exposure curves for harrier lead test assembly fuel RAUSCH: T J Commonwealth Edison Co 82/10/18 DENTON: H R Defice of Nuclear Reactor Regulation. Director 2pp 15788, 233 24X Ficher 30-000; 82/10/18, 8210250155
- --8210250177 Errate & Addenda Sheet S, replacing Page 4-10 to "LOCA Analysis Rept for Dresden Units 2 & 3 & Guad Cities 1 & 2 Nuclear Power Stations"

  " General Electric Co NEDC-24146A ERR OB. 82/09/30 3pp. 13788-239. 24% Fiche.50-000,82/10/18:8210250155

- 9210250069 Provides addl info re reactor water cleanup room area ter; monitors Temp elements cause no automatic plant response beyond control room alarms. RAUSCH. TJ Commonwealth Edison Co 82/10/19 EISENHUT, N 0 Division of Licensing 2pp 15787 081 24X Fiche 50-000.82/10/19
- B210260276 Forwards safety evaluation of BMR owners group generic response to NUREO-0737. Item II K 3 25. "Effect of Loss of AC Power on Pump Seals " No mods to seal cooling for rectrculation pumps required Item resolved CRUTCHFIELD. D Operating Reactors Branch 5 82/10/21 DELEGHARIE. Commonwealth Edison Co 7pp 15803 018 24X Fiche 50-217. 82/10/21. B210260276
- O Inspection reports. IE Bulletins & correspondence
- B210060329 Forwards IE Insp Repts 50-010/82-02.50-237/82-03 & 50-249/82-03 on 820119-0218 No noncompliance notes LITTLE.W S Division of Engineering & Fechnical Programs B2/07/7 RED. C Commonwealth Edison Co 2pp 15615 331 26% Fiche 50-010.82/09/22.8210060329
- ~-8210060335 IE Insp Repts 50-010/82-02,50-237/82-03 b 50 249/02 C1: 820119-0218 No moncompliance noted Major areas inspected open & unresolved items & items of noncompliance reintegrated leaf rate test REIMANN,F M Region 3, Office of Director JACKIM-1 N Distinct of Engineering & Technical Programs 82/09/21 /pp 15655 33: 24X Fichs 50-010.82/09/22.8210040329
- 8210180523 Forwards IE Insp Repts 50-010/82-13.50-237/82 1/ 1 50-249/82-18 on 820708-0809 % notice of violation STREETER. J F Division of Project % Resident Programs (h2/09/13 REED C Commonwealth Edison Co 2pp 15713 099 24x Fiche 50-010.82/09/28.8210150523
- --B210150530 Notice of violation from insp on B20708-0009 STREETER J F Division of Project & Resident Programs (02/67): ip 15713 101 24X Fiche 50-010.82/09/28.8210100529
- --B21015053B IE Insp Repts 50-010/82-13,50-237/82-17 \$ 50 249/ft\* la 820708-0809 Noncompliance noted failure to issue & performair pressure test procedure TONQUE,T M , JORDAN,M J , WALKER,R D Division of Programs 82/09/28 Bpp 15713 102 24x Ff/the 50-010,82/09/28,8210155529
- 82100A0359 Ack receipt of 820910 itr informing NRC of steps team to correct violations noted in IE Insp Repts 50-237/81:19. 50-249/81-23.50-254/81-23.50-265/81-23.50-295/81-11 t 50-304/81-29 SPESSARD, R L Division of Project & Resident Programs | DJ/ICC| REED, C Commonwealth Edison Co | Ip | 154/8 334 24x F(che 50-004,82/10/01/8210080359
- ~-8210060367 Responds to NRC 820712 ltr re visiations noted in LE:
  Repts 50-237/81-39, 50-249/81-32, 50-294/81-23, 50-264/81 23
  50-295/81-31 & 50-304/81-29 Corrective actions training far
  mpt priorities re plant availability will be conducted
  REED, C. Commonwealth Edison Co. 82/09/10 KERPter, J. Q. 481
  3. Office of Director 13pp 15618 355 24X
  Fichs 50-009, 82/10/01/8210060359
- 8210080178 Forwards listing of piping sys which fell to meas bear requirements; per NRC 800818 confirmatory action ltr II Bulletin 79-14 operability evaluation updates will not be provided for Dresden & Guad Cities Final update by Det 146-2 RAUSCNIT J Commonwealth Edison Co 82/10/01 KEPPIER & C 3, Office of Director 6pp 15640 159 24X Fichs 50 Oc. 5 62-1080178
- 8210150539 Forwards IE Insp Repts 50-010/82-15.50-237/82-14 t 50-249/82-20 on 820830-0903 No noncompliance noted PAPERIELLO,C J Division of Emergency Properedness to Operation Bupport 82/10/01. REED,C. Commonwealth Edison Co Pyp 15714.175 24X Fiche 50-010.82/10/01.8210150539
- --8210150543 IE Insp Repts 50-010/82-15,50-237/82-19 & 50 %49-8; 820830-0903 & 09 No noncompliance noted Hajor area; inspected confirmatory measurements program. GC program far analytical measurements & environ monitoring program SCHUMACHER, M.C., NICHOLSON, N.A., JANUSKA, A.O. Division of Emergency Preparedness & Operational Support 82/09-25, 15714-177. 24X Fichs 50-010, 82/10/01, 8210150539
- 8210080190 Confirms 821103 enforcement conference at Region 3 a aspects associated w/procurement, installation & use of non-qualified valve guides in electromagnetic relief valves at facilities.

  SPEESARD.R.L. Division of Project & Resident Programs, REED.C. Commonwealth Edison Co ip 15640:181, 24g Fiche, 50-000, 82/10/04, 8210080190

- 8208190233 IE info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 implant Seeds " Svc list ent! COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24
- 8208190238 le Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Syc list encl DEYOUMD, R.C. Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- R Periodic operating reports & related correspondence
- SCI0180097 Forwards monthly operating repts for Sept 1982 SCOTT.D J Commonwealth Edison Co 82/10/01 Director's Office. Office of Inspection and Enforcement Ip 19718 001 24X Fiche 50-010.82/10/01.8210180097
- ~-8210180100 Monthly operating repts for Sept 1982 SCHROEDER, B. A. Commonwealth Edison Co. 82/10/01 22pp 19718 002 24X Ficha 50-010,82/10/01,8210180097
- S Reportable occurrences. LERs & related correspondence
- ©2:0150097 Forwards LER 81-026/03L-0 SCOTT, D.J. Commonwealth Edison Co. 81/10/13 KEPPLER, J.Q. Regio 3, Chicago. Office of the Director (81/03/01) 1p 15701 182 24 Fiche 50-249, 81/10/13, 8210150097
- --R210150102 LER 81-026/03L-0 on Bi0915, while shutting down rod P-10 showed wrong position on rod worth minimizer Caused by several diode failures on two digital output printed circuit boards Boards removed, repaired & tested satisfactorily SCHROEDER. B. Commonwealth Edison Co. Bi/09/29 Region 3, Chicago, Office of the Director (81/03/01) 2pp 18701 183 24X Fiche 50-249,81/10/13,8210150097
- B210270251 Forwards LER 81-040/017-0 SCOTT.D J Commonwealth Edison Co 81/12/15 KEPPLER, J Q Region J. Chicago. Office of the Director (81/03/01) 1p 15829 233 24X Fiche 50-249, B1/12/15, 8210270251
- ---9210270254 LER Bi-040/01T-0 on Bil201, when Rx pressure decreased to 32 psig.rud N-9 notched from position 02 to 04 & then to position 06 Cause unknown Mork request issued to check single notch control switch during next refueling outage SCHROEDER, B A Commonwealth Edison Co 81/12/07 Region 3, Chicago, Office of the Director (81/03/01) 3pp 15829 234 24X Fiche 50-249,81/12/15,8210270251
- 8210040126 Forwards LER B2-035/03L-0 SCOTT.B J Commonwealth Edison Co 82/09/16 KEPPLER.J Q Region J. Office of Director ip 15581 207 24X Fiche 50-249,82/09/16, B210040126
- --8210040129 LER 82-035/03L-0 on B20705, during testing of control rod drive H-4 for overtravel overtravel alarm came up & position indication lost, indicating uncoupling of control blade from drive Probably caused by inner filter becoming detached WHALEN, R Commonwealth Edison Co 82/07/16 Region 3, Office of Director 2pp 15581 208 24X Fiche 50-249,82/07/16,8210040126
- B210250306 Forwards updated LER 82-029/01X-1 SCOTT. D J Commonwealth Edison Co 82/09/22 KEPPLER, J G Region 3. Office of Director 1p 13791 038 24X Fiche, 50-249, 82/09/22, 8210340306
- --B210250316 Updated LER B2-027/01X-1 on B20712, magnetrol switches B2C & B2D did not trip when tested for proper tripping upon water loading Cause not known Visual insp,review & waskly testing revealed no abnormalities Vendor review encl.

  WHALEN, R Commonwealth Edison Co 82/09/22, Region 3, Office of Director 3pp 15791 039 24X Fiche 50-249,82/09/22,8210250304
- 8210250328 Forwards updated LER 82-023/01X-1 SCOTT.D J Commonwealth Edison Co 82/09/22 KEPPLER, J Q Regio 3. Office of Director ip 15790 082 24X Fiche 50-249,82/09/22, 8210250328
- --B210250348 Updated LER 82-023/01X-1 on B20510, no low power range monitor input to rod block monitor (RBM) noted during DDP 700-E3 Caused by shorted steering diodes on several RBM cards Defective diodes replaced MOROAN, W Commonwealth Edixon Co 82/09/22 Region 3, Office of Director, 2pp 15790 083 24X Fiche 50-249,82/09/22,8210250328

- 6210130197 Forwards LER 62-034/03L-0 SCOTT.D J Commonwealth Edison Co 62/09/28 KEPPLER.J O Region 3. Office of Director ip 15474 117 24% Fiche 50-249,82/09/28. 8210130197
- --9210130201 LER 82-024/03L-O on 920701, investigation revealed that substandard electromatic relief velve main valve disc guide steeve utilized on ERV 3-203-3C Caused by personnel error in ordering sleeve Sleeve will be replaced HOLLAMO.P Commonwealth Edison Co 92/09/28 Region 3, Office of Director 2pp 15674 118 24X Fiche 50-249.82/09/28, 8210130197
- 8210190458 Forwards LER 82-036/03L-0 SCOTT.D J Commonwealth Edison Co 82/10/05 KEPPLER, J Q Region 3. Office of Director 1p 15735 319 24X Fiche 50-249,82/10/05, 8210190458
- --8210170471 LER 82-036/03L-0 on 820912 during startup at 45% power, annunciator 903-5-N-4 indicated turbine pressure operator load rejection & turbine stop valve scrams bypassed on one subchannel of Channel A half scram circuitry TURNQUESTL Commonwealth Edison Co 82/10/05 Region 3, Office of Director 2pp 15735 320 24% Fiche 50-249,82/10/05,8210190458
- 8210190403 Forwards LER 82-037/03L-0 SCOTT.D J Commonwealth Edison Co 82/10/06 KEPPLER, J G Region 3. Office of Director 1p 15740 356 24% Fiche 50-249,82/10/06, 8210190403
- --8210190412 LER 82-037/03L-O on 820922, transient in-core prote ball valve 3E would not reclose Caused by loss of tension in high tension spring in drive mechanism Valve closed & spring retensioned MOROAN W Commonwealth Edison Co 82/10/06 Region 3, Office of Director 2pp 15740 357 24X Fiche 50-249,82/10/06,8210190403

DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

- F Security, medical, emergency & fire protection plans
- 8207170062 Forwards Revision 6 to physical security plan Revision withheld (ref 10CFR73 21)
  UHRIO,R.E. Florida Power & Light Co 82/07/08 EISENHUT, D G
  Division of Licensing 2pp 14710 067 24% Fiche 50-250, 82/07/08, 8209170062
- G210190178 Releases public version of emergency plan implementing procedure FELTON.J M Division of Rules and Records G2/09/30, Document Management Branch 1p 1575B 062 24X Fiche 50-250,82/09/30, G210190178
- --B210190184 Forwards public version of Emergency Plan Implementing Procedures 20104. "Emergency Roster," 20101, "Duties of Emergency Coordinator," 20107, "Fire/Explosion Emergencies" & 20127 "Duties of Assembly Area Bupervisor" UHRIO, R E Florida Power & Light Co. 82/09/24 0'REILLY, J P. Region 2. Office of Director ip. 15758.063, 24X Fichs 50-250,82/09/30,8210190178
- --B210190194 Public version of Emergency Plan Implementing Procedures 20101, "Duties of Emergency Coordinator," 20104, "Emergency Roster:" 201007, "Fire/Explosion Emergencies" & 20127, "Duties of Assembly Area Supervisor" \* Florida Power & Light Co 82/09/16 Supp 15758:064 24X Fichs 50-250, 82/09/30, 8210190178
- 8210190440 Extends invitation to observe 821019 demonstration of emergency response sys at Technology for Energy Corp. Knoxville, TN UHRIO, R E Florida Power & Light Co. 82/10/12 EISENHUT, D. Q. Division of Licensing is 15741:186. 24X Fiche 50-000.82/10/12, 8210190440
- 8210250244 Forwards revisions to physical security plan. Revisions withhold (ref 10CFR73 21)
  KAMER, D. 8 Tennessee Valley Authority 82/10/19 DENTON, H R
  Office of Nuclear Reactor Regulation, Director, 1p 15788, 345, 24x
  Fiche 50-250, 82/10/19, 8210250244
- B210280291 Forwards Revision 1 to 10CFR30 App R fire protection review Revision corrects typographical errors in 820701 submitted UHRIOR E. Floride Power & Light Co 82/10/22 EISENHUT, D. O Division of Licensing. 1p 15838/080. 24X Ficher 50~250,82/10/22,8210280291.

1 [

1

- --8210280293 Revision 1 to 10CFR50 App R fire protection review \* Florida Power & Light Co 82/10/22 43pp 15838 081 24X \* Florida Power & Light Co 82. Fiche 50-250, 82/10/22, 8210280291
- P Operating license stage documents & correspondence
- 8210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in FELTON, J M Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fishe 50-000, 82/08/10,8210070007
- B210120521 Gummary of exit interview following 820713-15 audit of pressurized thermal shock in-plant training programs & operating procedures GROTENHUIS, B. Operating Reactors Branch 1 82/09/15 Operating Reactors Branch 1 5pp 15672 261 24X Fiche 50-250,82/09/15,
- 8210280013 Responds to FOIA request for all internal non-public documents memos, evaluation repts & other mati dealing w/ nuclear plant operations Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/09/17 MCINNIS, D News & Observer Spp 13860 065 24X Ficbs 50-000,82/09/17.
- --8208310034 Forwards draft info notice re-deficiencies in air filtration & ventilation sys Notice based on radioactive resin release at Pilgrim 1 & on four related events at other plants involving deficiencies in maint & testing of filter sys MATTBON.R J Division of Systems Integration (post 81:005) 82/08/05 JRBON.E L Division of Engineering & Quality Assurance. Spp 15861.024 24X Fiche 50-000.82/09/17,8210280013
- --8210280100 Notifies that on 820224.C Alderson advised that rept sent re possible willful violation of reporting requirements & falsification of GA & guard qualification records at facilities
  REGNER, M E Office of Inspector & Auditor 82/03/01 Office
  Inspector & Auditor 1p 15861 039 24X Piche 50-000,82/09/17. 8210280013
- 8210050589 Requests submittal of fees for 820505 request for Tech Spec clobuloby requests summittal of fees for S2000a request for Sechings are degraded grid voltage & B20810 request for approval of mods to turbine runback sys
  DIOOB:R M License Fee Hanagement Branch 82/09/23 UHRIO. R.E.
  Florida Power & Light Co ip 13624 290 24% Fiche 50-250,
  82/09/23,8210050589
- 82:00:10292 Forwards response to NRC 820219 ltr requesting addl info re anviron qualification of TMI action items contained in NUREQ-07:37 NUREG-0737 UHRIG.R E. Florida Power & Light Co. 82/09/24 VAR Operating Reactors Branch | 56pp 15573 125 24x Fiche: 50-250: 82/09/24:8210010292 VARGA, S. A.
- 8210040281 Forwards revised schedule for providing final response recontrol of heavy loads on Quideline 4 (special lifting devices) & Quideline 7 (crame design) Only manufacturers can obtain requested info
  UHRIO,R E Florida Power & Light Co. 82/09/30, VAROA,8 A. Operating Reactors Branch 1. 2pp. 15621.162, 24X
  Fiche: 50-250: 82/09/30, 8210060281.
- 8210159407 Revised application for Amends 87 & 81 to Licenses DPR-91 & DPR-41, respectively, correcting typographical errors re DHR UHRIG.R.E Florida Power & Light Co B2/10/11 EIBENHUT, D C. Division of Licensing ip. 15704:025, 24X Fiche: 50-250,82/10/11,8210150407.
- ---8210150413 Corrected pages to Tech Opens re DNR systeplanting pages in B01230 submittal. \* Florida Power & Light Co 82/10/11, Rpp. 15704.026 24X Ficha: 50-250, 82/10/11, 8210150407.
- B210150439 Advises that review of current status of nuclear power plant staff working hours per Generic Ltr B2-22 indicates requirements adequately enforced by incorporation in administrative procedures Amend to Tach Specs unnecessary. UMRIO.R.E. Florida Power & Light Co. 82/10/12. EISENHUT, D. Q. Division of Licensing. ip. 18705-004. 24X Fichs. 50-250, 82/10/12, 8210150437.
- BRIO190559 Ferwards payment of proposed license amend fee re-redundancy in RHR sys. UHRIO,R.E. Florida Power & Light Co. 82/10/12, MILLER, W. G. License Fee Hanagement Branch, 2pp. 15735:014, 24X Ficha: 30-250, 32/10/12, 9210190557.

- B210270253 Forwards util B21012 ltr containing payment of license artiffer re redundancy in RHR sys requested in NRC 020816 ltr
  UMRIO.R E Florida Power & Light Co 82/10/21 DIGGS.R M License Fee Management Branch 1p 15828 278 24X Fiche 50-250.82/10/21.
  B210270253
- Q Inspection reports. IE Bulletins & correspondence
- 8210070007 Responds to FDIA request for eight categories of records re steam generators & steam turbines App A documents provided in R\_Udell FDIA Request 81-313 Forwards documents listed in App a FELTON.J M Division of Rules and Records 92/08/10 Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 Fiche 50-000, 92/08/10,8210070007 LONG, D J
- --8210070[37 Forwards tabulated data on steam generator insp % maint of facilities Data should be provided to licensess IPPOLITO.Y Operating Reactors Assessment Branch 82/04/0; VARRA, 6 Operating Reactors Branch 1 Spp 15645 131 24X Fichs 50-000,82/08/10,8210070007
- --BR10070172 Forwards info re steam generator integrity & inapt at all alouv01/2 Forwards into re steam generator integrity & intps, at a operating PHRs.per 730320 & 21 requests Details of intps, including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach 1 QUILLER.K R Division of Reactor Licensing (NRR-1973 only) 75/03/24 MACCARY.R R Division of Technical Review (NRR-1973 only) 5pp 15645 196 24X Fiche 50-000.82/00/10.0210070007
- B210010316 Ack receipt of BR0B25 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/B2-24 & 50-231/B2-24 DANCE. H C Division of Project & Resident Programs 92/09/13 UHRIO, R E Florida Power & Light Co ip 19568 224 24x Fiche S0-250, 82/09/13, 8210010316
- --8210010321 Responds to NRC 820726 itr re violations noted in 1t 1\*4, Repts 50-250/82-24 & 50-251/82-24 Corrective actions plant manager discussed need for increased control of activities affecting fire barrier penetrations w/const personnel UHRIG,R E Florida Power & Light Co 82/08/25 0'RENLY, J P Region 2, Office of Director 3pp 19568 225 24% Fiche 50-250.82/09/13.8210010316
- --8210010329 Forwards IE Insp Repts 50-250/82-24 & 50-251/82 24 en 820526-0625 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/07/26 UHRIO.R E. Florida Power & Light Co 2pp 15568 228 24 K Fiche 50-250.82/09/13.8210010316
- --9210010338 Notice of violation from insp on 820326-0625 LEWIS.R C Division of Project & Resident Programs 6 2pp 15568 230 24X Fiche, 50-250, 82/07/13, 8210010316 02/07/25
- --82:0010346 IE Insp Repts 50-250/82-24 & 50-251/82-24 on 820526 04:1 Noncompliance noted inadequate corrective action allowed recurrence of reportable condition re failure to adhere to radiation work permit
  VOOT-LOWELL,R, JULIAN.C Division of Project & Resident Program
  B2/07/26 App [5568.232 24X Fiche 50-250.82/07/13.8210010];
- 8208190233 IE Info Notice 80~35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl COBB.C.I. Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 64pp 15761 27 82/10/06 Consolidated Edison Co of New York &App 157&1 271 24X Fiche.50-000,82/10/06,8208190233
- 8210220274 Ack receipt of 820927 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/82-80 & 251/02-20 80-201/82-20 LEMIS, R.C. Division of Project & Resident Programs 82/10/09 UHRIO, R.E. Florida Power & Light Co. 1p 15776-093 24x Fiche: 50-250, 82/10/08, 8210220296
- ---8210220304 Responds to NRC 820826 ltr re violations noted in 16 IrH Repts 50-250/82-28 & 50-251/82-28 Corrective actions access log established to control access to high radiation areas Alarm sys installed on Unit 3 RRR pit access gate UHRIGRE. Florida Power & Light Co 82/09/27 O'REILLY, J F Region 2, Office of Director 2pp. 15776-094, 24X Fiche, 50-250, 82/10/08, 8210220296
- --8210220310 Forwards IE Insp Repts 50-250/82-28 & 50-251/82-28 em 820624-0725 & notice of violation.

  LEMIS.R.G. Division of Project & Resident Programs 82/08/24

  UHRIO.R E Floride Power & Light Co., 2pp 15774-096 24x

  Ficha: 50-250,82/10/08,8210220294
- --8210220317 Notice of violation from insp on 820626-0725 \* Division of Project & Resident Programs. 82/08/26 15776:098. 24% Ficher 50-250, 82/10/08, 8210220296 82/08/26 19

- --8210220327 IE Insp Repts 50-250/82-28 & 50-251/82-28 on 820626-0725 Noncompliance noted on 820701, ground level gates to Unit 4 RHR pit stairmays, surveyed at dose rates excreding 1,000, found open & unattended VGGT-LORELL, R. JULIAN. C Division of Project & Resident Programs 82/08/24 Spp 15776 099 24% Fiche 50-250.82/10/08.8210220296
- 8210190351 Advises that util review of current nuclear plant staff working hours indicates that overtime restrictions meet intent of revised NRC policy Requirements incorporated in administrative procedures & need not be added to Tech Spers UHRIO.R E Florida Power & Light Co 82/10/12 EIGENHUT.D 0 Division of Licensing ip 15742 111 24X Fiche 50-250,82/10/12.82(0)90361
- 9208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Mall. Large-Diameter: Stainless Steel, Recirculation Sys Piping at BUR Plants "Svc list encl BEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp. 15810 125 24X Fiche 50-000, 92/10/14,8208190238
- S Reportable occurrences, LERs & related correspondence
- 8210080104 Forwards "Engineering Evaluation of Feedwater Transient & Sys Pipe Break at Turkey Point Unit 3 on 801119;" in response to request re Congressmen DB Fascell 810129 ltr HICHELSON.C Director's Office 81/03/02 REHM.T A Office of the Executive Director for Operations 1p 15670 001 24X Fiche 50-250.81/03/02/28210080104
- 8210090252 Forwards LER 82-012/017-0 WILLIAMS, J W Florida Power & Light Co 82/10/01 O'REILLY, J P Region 2. Office of Director 1p 15638 112 24X Fiche 50-250, 82/10/01, 8210080252
- --8210080257 LER 82-012/017-0 on 820917, insp revealed that electrical penetration did not meet double barrier criteria of 10CFR50 & testability requirements of App J Caused by failure to properly document plant changes Plant change implemented PACE, P L Florida Power & Light Co 82/10/01 Region 2, Office of Director 3pp 15638 113 24% Fiche 50-250,82/10/01,8210080252
- 8210260116 Forwards LER 82-013/03L-0 WILLIAMS, JW Florida Power & Light Co 82/10/18 O'REILLY, J P Region 2. Office of Director 1p 19799 105. 24X Fiche 50-250, 82/10/18, 8210260116
- --8210260117 LER 82-013/03L-0 on 820917. steam turbine pressure control valve CV-3707 did not close completely, resulting in poor pressure & causing safety relief valve to trip auxiliary feedwater pump C Caused by foreign matter under valve seat PAGE, P.L. Florida Power & Light Co. 82/10/18 Region 2. Office of Director 3pp 15799 106 24X Fiche. 50-250, 82/10/18, 8210260116.

## DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

- F Security, medical, emergency & fire protection plans
- 8209170052 Forwards Revision 6 to physical security plan Revision withheld (ref 10CFR73 21)
  URRIG.R E Florids Fower 5 Light Co 82/09/08, EIBENHUT, D 0
  Division of Licensing 2pp 14910,069 24X Fiche 50-250,82/09/08,8209170062
- 8210190178 Releases public version of emergency plan implamenting procedure FELTON, J M Division of Rules and Records, 82/09/30. Document Management Branch ip 15758 062 24X Fiche, 50-230, 82/09/30, 8210190178
- --9210190186 Forwards public version of Emergency Plan Implementing Procedures 20104, "Emergency Roster," 20101. "Duties of Emergency Coordinator," 20107. "Pres/Explosion Emergencies" & 20127 "Duties of Assembly Area Supervisor" UHRIO,R E Florida Power & Light Co 82/09/24 O'REILLY, J P. Region 2. Office of Director ip 15758 063 24X Fiche. 50-250,82/09/30,8210190178.
- --8210190194 Public version of Emergency Plan Implementing Procedures 20101, "Duties of Emergency Coordinator," 20104, "Emergency Roster," 20107, "Fire/Explosion Emergencies" & 20127, "Duties of Assembly Area Supervisor" e Florida Power & Light Co 82/09/16 SOpp 15758-064 24X Fiche 50-250,82/09/30,821019/0178

- 8210190440 Extends invitation to observe 821019 demonstration of emergency response sys at Technology for Energy Corp. Knoxville, TN UHRIO.R E Florida Power & Light Co 82/10/12 EISENHUT, D G Division of Licensing 1p 15741 186 24X Fiche 50-000, 82/10/12, 8210190440
- 8210280291 Forwards Revision 1 to 10CFR50 App R fire protection review Revision corrects typographical errors in 820701 submittel UHR10, R E Florida Power & Light Co 82/10/22 EISENHUT.D 0 Division of Licensing 1p 15838 080 24X Fiche 50-250,82/10/22,8210280291
- --8210280293 Revision 1 to 10CFR50 App R fire protection review

  \* Florida Power & Light Co 82/10/22 63pp (5838 081 24X
  Fiche 50-250, 82/10/22,821028029)
- P Operating license stage documents & correspondence
- 8210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 19645 063 24X Fiche 50-000, 82/08/10, 8210070007
- 82(0280013 Responds to FOIA request for all internal non-public documents, memos, evaluation repts & other math dealing w/nuclear plant operations Forwards documents listed in App A FELTON. J M Division of Rules and Records 82/09/17 MCINNIS. D News & Observer 5pp 15860 065 24X Fiche 50-000,82/09/17. P210290013
- --8210280100 Notifies that on B20224.C Alderson advised that rept sent reposible willful violation of reporting requirements & falsification of GA & guard quelification records at facilities
  RESNER,M E Office of Inspector & Auditor 82/03/01 Office of Inspector & Auditor 82/03/01 Auditor 19 15861 039 24X Fiche 50-000,82/09/17, 8910280013
- 8210050589 Requests submittel of fees for 820606 request for Tech Spec changes re degraded grid voltage & 820810 request for approval of mods to turbine runback sys DIOOS,R M License Fee Management Branch 82/09/23 UHRIO,R E Florida Power & Light Co ip 15626 290 24X Fiche 50-250. 82/09/23,8210050589
- 8210010292 Forwards response to NRC 820219 1tr requesting add1 info re environ qualification of TMI action (tems contained in NUREO-0737 UHRIG:R.E Florida Power & Light Co 82/09/24 VARGA,S A Operating Reactors Branch 1 56pp 15973 125 24X Fiche 30-250.82/09/24.8210010292
- 8210060281 Forwards revised schedule for providing final response recontrol of heavy loads on Guideline 4 (special lifting devices) & Ouideline 7 (crane design) Only manufacturers can obtain requested info
  UHRIG.R E Florida Fower & Light Co 82/09/30 VARGA.8 A
  Operating Reactors Branch 1 2pp 15621 162 24X
  Fiche 80-250,82/09/30.8210060281
- 8210150407 Revised application for Amends 87 & 81 to Licenses DPR-31 & DPR-41 respectively, correcting typographical errors re DHR sys

  UHRIO,R E Florida Power & Light Co 82/10/11 EISENHUT, D G

  Division of Licensing 1p 15704 025 24X Fiche 50-250,82/10/11,
  8210150407
- --8210150413 Corrected pages to Tech Specs re DHR sys.replacing pages in 801230 submittal

  \* Floride Power & Light Co 82/10/11 2pp 15704 026 24X
  Fiche 50-250,82/10/11,8210150407.
- 8210150439 Advises that review of current status of nuclear power plant staff working hours per Generic Ltr 82-22 indicates requirements adequately enforced by incorporation in administrative procedures Amend to Tech B
- 8210190559 Forwards payment of proposed license amend fee re redundancy in RHR sys.
  UHRIG: RE. Florida Power & Light Co 82/10/12 MILLER: H O License Fee Management Branch 2pp 15735 014 24X Fiche: 50-250; 82/10/12:8210190559

- 8210220090 Advises that procedures/plans submitted for Unit 3 for steam generator repair project apply to Unit 4 & need not be resubmitted UHRIGAR E Florida Power & Light Co 82/10/15 EISENHUT.D G Division of Licensing ip 15778 183 24X Fiche 50-251.82/10/15, 8210220090
- 8210270253 Forwards util 821012 ltr containing payment of license amend fee re redundancy in RHR sys requested in NRC 820816 ltr WHRIG.R E Florida Fower & Light Co 82/10/21 DIGGS.R M License Fee Management Branch 1p 15828 278 24X Fiche 50-250,82/10/21, 8210270253
- O Inspection reports, 1E Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J K Division of Rules and Records 82/08/10 LONG, D J Hinthrop, Stimson, Putnam & Roberts 9pp 15445 063 24X Fiche 50-000, 82/08/10, 8210070007
- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees
  [PPOLITO.T Operating Reactors Assessment Branch 82/04/01
  VARGA.S Operating Reactors Branch 1 5pp 19645 131 24X
  Fiche 50-000,82/08/10.8210070007
- --B210070172 Forwards info to steam generator integrity & insps at all operating PWRs, per 750020 & 21 requests Details of insps, including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach i GOLLER, K.R. Division of Reactor Licensing (MRR-1975 only) 75/03/24 MACCARY, R.R. Division of Technical Review (MRR-1975 only) 5pp 15645 196 24X Fiche 50-000,82/08/10,8210070007
- 8210010316 Ack receipt of 820825 ltr informing NRC of steps taken to correct violations noted in EE insp Repts 50-250/82-24 & SO-251/82-24 DANCE.H C Davision of Project & Resident Programs 82/09/13 UHRIG.R E Florida Power & Light Co ip 19568 224 24X Fiche 30-250.82/09/13.8210010316
- --8210010321 Responds to NRC 820726 ltr re violations noted in 1E Insp Repts 50-250/82-24 & 50-251/82-24 Corrective actions plant manager discussed need for increased control of activities affecting fire barrier penetrations w/const personnel UHRIO.R & Florida Power & Light Co 82/08/25 O'REILLY, J P Region 2. Office of Director 3pp 19568 225 24X Fiche 50-250,82/09/13.8210010316
- --0210010329 Forwards IE Insp Repts 50-250/02-24 & 50-251/02-24 on 020526-0625 & notice of violation LEWIS.R C Division of Project & Resident Programs 02/07/26 UHRIG.R E Florada Power & Light Co 2pp 15568 228 24x Fiche 50-250.82/07/13.8210010316
- --B2:001033B Notice of violation from insp on 820526-0625 LEMIS.R C Division of Project & Resident Programs 82/07/26 2pp 15568 230 24X Fiche 50-250.82/09/13.8210010316
- ---B210010346 IE Insp Repts 50-250/B2-24 & 50-251/B2-24 on 920926-0625 Noncompliance moted inadequate corrective action allowed recurrence of reportable condition re failure to adhere to radiation work permit UOT-LONELL R. JULIAN.C Division of Project & Resident Programs B2/07/26 App 15568 232 24X Fiche 50-250, B2/07/13, B210010316
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Syc list encl COSB.L. I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06.6208190233
- 8210220296 Ack receipt of 820927 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-230/82-80 & 50-251/82-28 LEMIG.R C Division of Project & Resident Programs 82/10/08 UHRIO.R E Florada Power & Light Co 1p 15776 093 24X Fiche 50-250.82/10/08.8210220296
- --B210220304 Responds to NRC 820826 ltr re violations noted in IE Insp. Repts 50-250/82-28 & 50-251/82-28 Corrective actions access log established to control access to high radiation areas Alarm sys installed on Unit 3 RMR pit access gate UMRIG.R E Florida Power & Light Co 82/09/27 C/REILLY, J P. Region 2. Office of Director 2pp 15776 094 24X Fiche 50-250.82/10/08.8210220296

- --8210220310 Forwards IE Insp Repts 50-250/82-28 & 50-251/82-28 on 820626-0725 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/08/26 URRIG.R E Floride Power & Light Co 2pp 15776-076 24X Fichs 50-250.82/10/08.8210220296
- --8210220317 Notice of violation from insp on 820626-0725 \* Division of Project & Resident Programs 82/08/26 ip 15776 098 24% Ficha 50-250, 82/10/08, 8210220296
- --8210220327 IE Insp Repts 50-250/82-28 & 50-251/82-28 on 820626-0725 Noncompliance noted on 820701.ground level gates to Unit 4 RHR pit stairways, surveyed at dose rates exceeding 1,000. found open & unattended VMOT-LOMPLL, R. JULIAN, C Division of Project & Resident Programs 82/08/24 5pp 15776 099 24% Fiche 50-250,82/10/08,8210220295
- 82:10190351 Advises that util review of current nuclear plant staff working hours indicates that overtime restrictions meet intent of revised NRC policy Requirements incorporated in administrative procedures & need not be added to Tech Specs UHRIG.R E Florida Power & Light Co 82/10/12 EISENHUT.D O Division of Licensing ip 15742 iii 24X Fiche 50-250,82/10/13.
- 9208190238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick-Wall.Large-Diameter: Stainless Steel.Recirculation Bys Piping at BMR Plants" Svc list encl
  DEYGUNG.R C Director's Office. Office of Inspection and
  Enforcement 82/10/14 Consolidated Edison Co of New York
  115pp 15810 125 24X Fiche 50-000,82/10/14,8208190238
- S Reportable occurrences. LERs & related correspondence
- 8207210425 Responds to FDIA request for eight categories of LERs Forwards documents listed in App A FELTON.J H Division of Rules and Records 82/08/20 ARNULD.J Miami Herald 3pp 14746 262 24X Fiche 50~000,82/08/20,
- --B209210527 Forwards draft FR notice re AD pressure transients during shutdown at nuclear power plant for approval DIRCKS.W J Office of the Executive Director for Operations B2/07/27 CHILK, S J Office of the Secretary of the Commission 18pp 14746 353 24% Fiche 50-000.82/08/20.8209210428
- 8210270083 Add1 response to FOIA request for eight categories of LHs Forwards documents listed in App A App B documents withheld (ref FOIA Exemption 5) FELTON. J M Division of Rules and Records B2/09/20 ARNOLD. J Miami Herald App 15836 221 24X Fiche 50-251.82/09/20, 6210270873
- --8210270096 Concurs w/draft Commission paper proposing facility low temp overpressure event as AO DENTON.H R Office of Nuclear Reactor Regulation, Director BI/06/16 MICHELSON.C Director's Office 2pp 19836 270 24x Fichs 50-281.82/09/20.8210270083
- --8206240117 Requests approval of AO determination re pressure transle while unit shutdown in preparation for startup DIRCKS, W J Office of the Executive Director for Operations SECY-62-255 82/06/17 10pp 15836 272 24X Fiche 50-251,82/09/20,8210270083
- 8210060209 Forwards LER 82-013/03L-0 HILLIAMB.JW Fiorada Power & Light Co 82/10/01 O'REILLY,J P Region 2. Office of Director 1p 15614 043. 24X Fich: 50-251.82/10/01.8210060209
- --8210060212 LER 82-013/03L-0.on 820706.RCS experienced rapid detrease pressure Caused by failed open pressurizer spray valve Reactor manually tripped & automatic safety injection actuated Pressure control regained using charging pumps PACE.P L Florida Power & Light Co 82/10/01 Region 2. Offic of Director. 3pp. 15614-044 24X Fiche 50-251,82/10/01.
- 8210190376 PND-II-82-107 on 921010, unit shut down for scheduled refueling & maint for 6 months, All three steam generators will be replaced Licensee plans news release. LANDIB, K D , JULIAN, C A Region 2, Office of Director 82/10/12 15 15740:315 24X Fiche 50-251,82/10/12,8210190376

- DOCKET 50-254 GUAD-CITIES STATION. UNIT 1
- F Security, medical, emergency & fire protection plans
- 8-109290125 Releases public version of revised generating station energency plan corporate command ctr energency plan inplementing procedure FELTQN. J M Division of Rules and Records 82/09/16 Document Hanagement Branch Ip 15564 122 24X Fiche 50-000.82/09/16, 8209290125
- --8209290189 Forwards public version of Revision 4 to generating station erergency plan corporate command ctr Emergency Plan Implementing Procedure EGF-3, "Environ/Emergency Coordinator " Receipt form enci PA/JOJASKI J E Commonwealth Edison Co 82/09/01 DENTON, H R NRC No Detailed Affiliation Given 1p 15564 123 24% Fiche 50-000, 82/09/16, 8209290125
- --8209290225 Public version of Revision 4 to generating station energency plan corporate command ctr emergency plan Implementing Procedure EDF-3, "Environ/Emergency Coordinator PAJOMSKI, J E Commonwealth Edison Co B2/08/31 11pp 15544 124 24X Fiche 50-000, 82/09/16, 8209290125
- 8210010009 Forwards info to suppl 820701 request for exemption from App R per 820717 telcon Request applies to Sections III 0 2 a £ III 0 3 b re installation of fire suppression sys AAUSCH, T J Commonwealth Edison Co 82/09/23 EISENHUT, D 0 Division of Licensing 8pp 19565 152 24X Fiche 50-000, 82/09/23, 8210010009
- G210120546 Releases public version of rovised cover sheet to facility procedures FELTON.J H Division of Rules and Records 82/09/24 Document Hanagement Branch 1p 15672 219 24X Fiche 50-254,82/09/24,82/0120546
- --0210120551 Forwards public version of revision cover sheet to facility procedures Completion of encl checklist requested MALIVIANAKIS,N Commonwealth Edison Co 82/09/15 DENTON,H R Office of Nuclear Reactor Regulation, Director 6pp 15672 220 24X Fiche 50-254,82/09/24,8210120546
- 8210150487 Forwards IE Insp Repts 50-254/82-14 & 50-265/82-16 on 820823-25 & 0903 & 09 No noncompliance noted MEPPLER.J G Region 3. Office of Director 82/09/30 REED, C Commonwealth Edison Co 3pp 15721 289 24X Fiche 50-294,82/09/30,8210150487
- --8210150495 IE Insp Repts 50-254/82-14 & 50-265/82-16 on 820823-25 & 0903 & 09 No noncompliance noted Major areas inspected emergency preparadness exercise & liconsee actions on previously identified emergency preparadness items PHILLIPS.N P . SMITH.M J . AXELEON.W L Division of Emergency Preparadness & Operational Support 82/09/29 15pp 15721 292 24X Fiche 50-254.82/09/30.8210150487
- 8210130376 Advises that installation of offsite dose calculation sysphogram fully operational tracking model & operational A-model will be delayed until 821231 to complete prime computer installation
  SWARTZ-E D Commonwealth Edison Co 82/10/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15682 098 24X
  Fichs 50-000,82/10/06.8210130376
- 8210290047 Releases public version of revisions to Quad Cities, Zion & Dreaden emergency plan annexes & revised generating station emergency plan telephone directory FELTQN. J H Division of Rules and Records 82/10/08 Document Management Branch ip 15877 313 24X Fiche 50-000, 82/10/08, 8210290047
- --8210270060 Forwards public version of Revision 3 to Quad Cities & Zipn emergency plan annexes. Revision 2 to Dreaden emergency plan annex Revision 0 to Byron emergency plan annex & revised generating station emergency plan telephone directory MODRE. R D Commonwealth Edison Co 82/07/30 DENTON. H R NRC No Detailed Affiliation Given 5pp 15877 314 24X Fiche 50-000.82/10/08.8210270047
- --82i0290077 Public version of Revision 3 to Guad Cities & Zion emergency plan annexes Revision 2 to Dresden emergency plan annex & Revision 0 to Byron emergency plan annex & Commonwealth Edison Co 82/06/30 325pp 15877 319 24X Fiche 50-000,82/10/08,8210290047.
- -- 82i0290088 Public version of revised generating station emergency plan telephone directory GALLE, D.P. Commonwealth Edison Co. 82/08/12 43pp 15878 218 24X Fiche 50-000,82/10/08,8210290047

- 82:0190753 Forwards 92:0722 ltr re late submittals of exercise scenarios & failure to adhere to FEMA Guidance Memo 17 If FEMA does not observe exercise, offsite authorities will not participate HIND. J A Division of Emergency Preparedness & Operational Support 82:10/12 REED.C Communuealth Edison Co 2pp 13736 247 24X Fiche 50-254.82/10/12,8210190753
- --8210190760 Discusses concerns re late submittals of emergency exercise scenarios & failure to adhere to FEMA Guidance Memo 17
  Future exercise not meeting intent of advance notification guidance should be postponed or canceled
  BREHENY.P J Federal Emergency Management Agency 82/09/22
  KEPPLER.J G Region 3. Office of Director 1p 15736 249 24X
  Fiche 50-254,82/10/12,8210190753
- 8210280361 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/10/12 Document Management Branch ip 15859 204 24X Fiche 50-254,82/10/12, 8210280361
- --B210280364 Forwards public version of revised emergency plan implementing procedures, including Procedures GEP 200-0 re emergency conditions, GEP 200-T1 re emergency action levels & GEP 330-3 re SFING control terminal operation KDVACK, T S., GERNER, L F. Commonwealth Edison Co. 82/09/23 DENTON, H R. NRC No Detailed Affiliation Given 2pp 15859 205 24X Fiche 50-254, 82/10/12, 8210280361
- --8210280375 Public version of revised emergency plan implementing procedures, including Procedures GEP 200-0 re emergency conditions. GEP 200-T1 re emergency action levels \$ GEP 330-3 re 8PINO control terminal operation

  \* Commonwealth Edison Co 82/09/23 21pp 15859 207 24X Fiche 50-254.82/10/12.81028036
- 8210220358 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs TRAMM.T R Commonwealth Edison Co 82/10/14 DENTON.H R Office of Nuclear Reactor Regulation, Director 9pp 15776 287 24% Fiche 50-000, 82/10/14, 8210220358
- 8210280307 Responds to 820917 telcon request for info re fire protection safe shutdown rept Items 2 & 3 are preliminary results, subj to revision following engineering review RAUSCH, T J Commonwealth Edison Co 82/10/18 EISENHUT, D O Division of Licensing App 15790 215 24% Fiche 80-254, 82/10/18, 8210250309
- P Operating license stage documents & correspondence
- 8210050142 Requests that charcoal adsorber F64-DY#2 be counted within 2 wks of receipt decay corrected to 790319 lavels & returned Liquid beta analyses results received in NRC 820917 ltr will be incorporated in rept addendum PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 82/09/28 KALIVIANAKIS, N Commonwealth Edison Co ip. 15605 167 24% Fichs 50-254, 82/09/28, 8210050142
- 8210120105 Requests delay of implementation due dates re NUREO-0737, Items II B 2, "Plant Shielding," II B 3, "Post-Accident Sampling" & II F 1 i, "Noble Qas Effluent Monitor "SMARTZ,E D Commonwealth Edison Co 82/10/04 EISENHUT,D O Division of Licensing 5pp 15651 237 24% Fiche 50-000.82/10/04, 8210120105
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual." GDLDEN.J C Commonwealth Edison Co 82/10/06 CASE.E 0 Office of Nuclear Reactor Regulation. Director 2pp 15805 137 24X Fiche's 50-000, 82/10/06
- --8210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Hanual" \* Commonwealth Edison Co 82/09/30 83pp 15805:139 24X Fiche 50-000,82/10/06.8210260526
- 8210160059 Provides addl guidance & clarification re 820806 request for addl info per NUREG-0737, Item II B 3, "Post-Accident Sampling Bys " Detailed reliability analysis not required to satisfy NRC concerns CRUTCHFIELD.D Operating Reactors Branch 5 82/10/08 DELGEORGE, L. Commonwealth Edison Co 3pp 15720 004 24X Fiche: 50-000, 82/10/08, 821018 (80059

- 8210190780 Forwards "OE DWR Extended Load Line Limit Analysis for Quad Cities Nuclear Power Station Unit 1.Cycle 7 & Unit 2.Cycle 6" RAUSCH.T J Commonwealth Edison Co 82/10/12 EISENHUT.D 0 Division of Licensing 1p 15736 206 24X Fiche 50-254.82/10/12, 8210190780
- --8210190785 "GE BWR Extended Load Line Limit Analysis for Quad Cities Nuclear Power Station Unit 1.Cycle 7 & Unit 2.Cycle 6 " General Electric Co NEDD-22192 82/07/31 31pp 15736 207 24% Fiche 50-234,82/10/12.8210190780
- B210190445 Forwards supplemental response to Generic Ltr B2-05 re implementation status of NUREO-0737, Items II B 3, II F 1 2, II F 1 3, II F 1 4, in response to B21004 request SHARTZ.E D Commonwealth Edison Co B2/10/14 EISENNUT.D G Division of Licensing 5pp 15741 202 24X Fiche 50-000, 92/10/14, 8210190445
- 8210250114 Application for amend to License DPR-29, changing safety relief actuating setpoint of Target Rock valve to 1.135 paig & changing setpoint of two electromatic relief valves to 1.115 paig RAUSCH: TJ Commonwealth Edison Co 82/10/18 DENTON, KR Office of Nuclear Reactor Regulation, Director 3pp 15787 032 24X Fiche 50-254, 82/10/18, 8210250114
- --B210250126 Proposed changes to Tech Specs changing safety relief actuating setpoint of Target Rock valve to 1,135 psig & setpoint of two electromatic relief valves to 1,115 psig \* Commonwealth Edison Co B2/10/18 3pp 15787 035 24X Fiche 50-254,82/10/18,8210250114
- 6210250155 Forwards corrections to proposed Tech Spec Pages 1 2/2 2-1 & 3 3/4 3-5, supporting review of future reloads & revised Figure 3 5 1, Sheet 1, providing extended MAPLHGR vs exposure curves for barrier lead test assembly fuel RAUSCH, T J Commonwealth Edison Co 82/10/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15788 233 24% Fiche 50-000, 82/10/18, 8210250155
- --8210250169 Revised proposed Tech Spec Pages 1 2/2 2-1 & 3 3/4 3-5, supporting review of future reloads & revised Figure 3 5 1, Sheet i providing steended MAPLHGR vs exposure curves for barrier lead test assembly fuel Supersedes 820819 version \* Commonwealth Edison Co 82/10/18 4pp 15768 235 24X Fichs 50-000, 82/10/18.8210250155
- ---8210250177 Errata & Addenda Sheet B. replacing Page 4-10 to "LOCA Analysis Rept for Dresden Units 2 & 3 & Quad Cities 1 & 2 Nuclear Power Stations" \* General Electric Co NEDO-24146A ERR 08 82/09/30 3pp 19788 239 24X Fiche 50-000, 82/10/16,8210250155,
- 8210250069 Provides add1 info re reactor water cleanup room area temp monitors Temp elements cause no automatic plant response beyond control room elemms
  RAUSCH.T J Commonwealth Edison Co 82/10/19 EIBENHUT, D Q
  Division of Licensing 2pp 15787 081 24X Fiche 50-000,82/10/19,8210250069
- O Inspection reports: IE Bulletins & correspondence

1.

11 0

- 8210150487 Forwards IE Insp Repts 50-254/82-14 & 50-265/82-16 on 820823-25 & 0903 & 09. No noncompliance noted KEPPLER J Q Region 3. Office of Director 82/09/30 REED, C Commonwealth Edison Co 3pp 15721 289 24X Fiche 50-254.82/09/30.8210150487
- --8210150495 IE Insp Repts 50-294/82-14 k 30-265/82-16 on 820823-25 k 0903 k 09 Ne noncompliance noted Major areas inspected emergency preparedness exercise & licensee actions on previously identified emergency preparedness itsms PHILLIPS M P . SHITH M J . AKELSON K L Division of Emergency Preparedness & Operational Support 82/09/29 15pp 15721 292 24X Fichs 50-254,82/09/30.8210150487
- 8210060359 Ack receipt of 820910 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-237/81-39, 50-249/81-23, 50-254/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29

  SPESSARD, R L Division of Project & Resident Programs, 82/10/01 REED, C. Commonwealth Edison Co 1p, 15618 354 24X Fiche: 50-000, 82/10/01, 8210060359
- --8210060357 Responds to NRC 820712 ltr reviolations noted in IE Insp. Repts 50-237/81-39, 50-249/81-32,50-254/81-33, 50-256/81-23, 50-257/81-31 & 30-304/81-29, Corrective actions training for mgt priorities replant availability will be conducted REED. C. Commonwealth Edison Co. 82/09/10 KEPPLER, J. 9 Region 3, Office of Director 13pp 15618, 355 24X Fishe 50-000, 62/10/01, 6210060359.

- B210080178 Forwards listing of piping sys which fail to meet FBAR requirements, per NRC 800B18 confirmatory action ltr [E Bulistin 79-14 operability sysluation updates will not be provided for Dresden & Guad Cities Final update by Dec 1902 RAUSCH.T J Commonwealth Edison Co 82/10/01 KEPPLER, J 0 Regir 3, Office of Director 6pp 15640 159 24X Fiche 50-000, 62/10/01. 8210080178
- 8210080190 Confirms B21103 enforcement conference at Region 3 of the waspects associated w/procurement installation & use of non-qualified valve guides in electromagnetic relief valves at facilities
  SPESSARD, R. L. Division of Project & Resident Programs 82/10/04
  REED. C. Commonwealth Edison Co. 1p. 15640-181 24x
  Fichs 50-000, 82/10/04, 8210080190
- 820B1902G3 IE Info Notice 80-35. Suppl i, "Leaking & Dislodged I [2] Implant Seeds " Svc list enc! COBB.L I Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 2°3 24X Fiche 50-000.82/10/06.8208190233
- 9208190238 1E Bulletin 82-03. "Stress Corrosion Cracking in Thick Wall-Large-Diameter. Stainless Steel Recirculation Sys Piping at BUR Plants "Svc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 92/10/14 Consolidated Edison Co of New York 115pp 15810 128 24X Fiche 50-000, 82/10/14, 8208190238
- R Periodic operating reports & related correspondence
- 8210130386 Forwards monthly operating repts for Bept 1982 RALIVIANAKIS, N Commonwealth Edison Co 82/10/01 Director s Office, Office of Inspection and Enforcement 1p 15680 199 200 Fiche 50-254, 82/10/01, 8210130386
- --8210130390 Monthly operating repts for Sept 1982 BUSS. R D Commonwealth Edison Co 82/10/04 13pp 136(10 114) 24% Fische 50-254, 82/10/01, 8210130386
- S Reportable occurrences. LERs & related correspondence
- 8011060561 Discusses facility 770103 loss of air event & effect on scram capability Conservative analysis of data indicates short operator response time Immediate scram on loss of control rod driveline air header should be required LANIK. G Darector's Office 80/10/20 MICHELSON, C Director's Office 3pp 15692 268 24X Fiche 50-254-80/10/20-8011060561
  - -8011060565 Forwards senior resident inspector 800829 memo re effect of facility 770103 loss of air event & its effect on scram capability KEPLER. J O Region 3. Chicago, Office of the Director 80/u//2/ MIGHELSON. C Director's Defice ip 15692 271 24X Fiche 50-254,80/10/20.8011060561
- --8011060568 Discusses facility 770103 loss of air event & effect es scram capability Event indicates that scram discharge vol. although filled to approx 59% capacity, was capable of accepting vol of water to shut down reactor safely CHRISSOTIMOS, N. Region 3, Chicago, Office of the Director 80/08/29 SPEBSARD, R. L. Region 3, Chicago, Reactor Operations Nuclear Support Branch 2pp 15692 272 24% Fiche 50-254,80/10/20.8011060561
- 8210060395 Forwards LER 82-026/03L-0 KALIVIANAKIS, N Commonwealth Edison Co 82/09/27 KFFPILR, J Region 3. Office of Director ip 15616 017 24X Fiche 50-254,82/09/27,8210060395
- --8210060405 LER BR-026/03L-0 on 820906, flange seal gasket leak water found exceeding 30 SCFH & possibly exceeding Tech Spec limit of 36 72 SCFH for double-gasket seals Caused by seal gasket deterforation Oasket to be repaired/replaced MENDENHALL, E.E. Commonwealth Edison Co. 82/09/27 Region 3. Office of Director 1p. 15616-018 24X Fiche 50-254,82/09/27. 8210060395.
- 8210130324 Forwards LER 82-027/01T-0
  KALIVIANAKIS.N Commonwealth Edison Co 82/09/28 KEPPLER, J
  Region 3, Office of Director ip 15678 292 24X
  Fiche 50-254, 82/09/28, 8210130324
- --8210130328 LER 82-029/01T-0 on 820916, two small cracks found in heat affected some of welds 128-F9 & F10 of reactor water cleanup mays piping Caused by stress corrosion Piping to be replaced wistainless steel pipe & fittings prior to startup WILQUE,D Commonwealth Edison Co 82/09/28 Region 3. Office of Director, 4pp 13678 293. 24X Fiche 50-254,82/09/20. 8210130324.

- EPL0130413 Forwards LER 82-027/03L-0
  FALTVIANAKIS R Commonwealth Edison Co 82/09/29 KEPPLER, J
  Region 3, Office of Director Ip 15680 243 24X
  Fiche 50-254, 82/09/29, 8210130413
- --8210130423 LER 82-027/03L-0 on 820902, electromagnetic relief valve main valve guides & piston rings inadvertently undered as nonsefety-related Caused by inadequate implementation of procurement requirements frocedures revised TIETZ. G. Commonwealth Edison Co. 92/09/28 Region 3, Office of Director ip 15680-244 24X Fiche 50-254.82/09/29,8210130413
- 8210130501 Forwards LER 82-025/03L-0 KALIVIANAKIS.N Commonwealth Edison Co 82/09/29 KEPPLER, J Region 3. Office of Director 1p 15682 189 24X fiche 50-254, 82/09/29, 8210130501
- --B210130511 LER 82-025/03L-0 on B20907.1/2A standby gas treatment train heater found tripped during Procedure QDP 02D-1 Caused by conservative switch setting due to inadequate setpoint differences Heater trip reset
  LIHOU.H Commonwealth Edison Co 82/09/27 Region 3, Office of Director 3pp 15882 170 24x Fiche 50-254.82/09/27,8210130501
- 8210130251 Forwards LER 82-031/03L-0 KALIVIANAKIS.N Commonwealth Edison Co 82/09/30 KEPPLER.J Region 3. Office of Director 1p 15678 094 24X Fiche 50-254,82/09/30.8210130251
- 3210130466 Forwards LER 82-032/03L-0 PALIVIANAKIS.N Commonwealth Edison Co 82/09/30 KEPPLER, J Region 3. Office of Director 1p 15602 136 24X Fiche 50-254.82/09/30.821013046
- -8210130473 LER 82-032/03L-0 on B20905.HPCI removed from svc w/o actuation of electromatic relief valves Caused by need to perform scheduled turbing overspeed surveillance test HPCI sys will be tested operable upon return to power LHOU.H Commonwealth Edison Co 82/09/30 Region 3, Office of Disector 1p 19682 137 24X Fishe 50-254.82/09/30.8210130466
- 3210130192 Forwards LER 82-030/03L-0 KALIVIANAKIS.N. Commonwealth Edison Co. B2/10/01 KEPPLER, J & Region 3. Office of Director ip 15674 100 24X Fiche 50-254. B2/10/01. 8210130192
  - 8210(30)76 LER 62-030/03L-0 on 620905, while testing RHR svc water pump 1~1001-650, packing found burned Caused by excessive tightening in packing to limit leakage Mods installed to protect bearings from seal leakage
    SCHNITZMEYER.J Commonwealth Edison Co 62/09/05 Region 3. Office of Director 3pp 15674 101 24X Fichs 50-254,82/10/01. 6210130192
- ©10190658 Forwards LER 92-020/03L-0 MALIVIANAKIE:N Communeatth Edison Co 82/10/04 KEPPLER, J Q Rogion 3, Office of Director 1p 15737 267 24X Fiche 30-254, 82/10/04, 8210190658
- -8210190700 LER 82-020/03L-0 on 820920 & 21.RCIC area high temp isolation 015-28.3 switches 1-1360-14A, 1-1360-17B & 1-1360-16C, would not trip Cause not specifically determined Failed switches returned to manufacturer for analysis PREUSS, M Commonwealth Edison Co 82/10/04 Region 3, Office of Director 3pp 15737 268 24% Fiche 50-254,82/10/04, 82/10/9058
- 210250148 Forwards supplemental LER 82-022/03L-1 KALIVIANAKIS, N. Commonwealth Edison Co. 82/30/07 KEPPLER, J. G. Region 3. Office of Director 1p. 15787-360 24X Fiche 50-254, 82/10/07, 8210250148
- -9210250153 Supplemental LER 82-022/03L-1 on 920816, maint outage for L/2B diesel fire pump exceeded 7-day limit Gause not stated Diesel pump wear rings replaced LtHOU,H Commonwealth Edison Co 82/10/07 Region 3, Office of Director 1p 15787 361 24X Fiche 50-254,82/10/07,8210250148
- 210260467 PND-III-82-112 util notified that high density fuel storage racks installed do not meet design criteria for spacing due to bouing condition Handfacturer resnalyzed seismic response of racks & concluded howed distance acceptable GROBE. J. WALKER, R. STREETER, J. Replon 3. Office of Director 82/10/18, 1 19804 237 24X Fiche 50-254, 62/10/18, 8210260467

- DOCKET 50-255 PALISADES NUCLEAR PLANT
- F Security, medical, emorgency & fire protection plans
- 8210050302 Updates status & schedule for responses to NUREG-0737. Items I D 2. "Plant Safety Parameter Display Console" & III A 2. "Improving Licensee Emergency Preparedness Long-Term "JOHNSON, B D Consumers Power Co 82/09/30 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 15602 359 24% Fiche 30-255, 82/09/30, 8210050302
- 8210280058 Releases public version of revised emergency plan FELTON.J M Division of Rules and Records 62/10/08 Document Hanagement Branch 1p 15862 (24 24X Fiche 50-255, 82/10/06, 8210280058
- --8210280061 Forwards public version of Revision 1 to emergency plan \* Consumers Power Cp 82/09/24 NRC - No Detailed Affiliation Qiven 2pp 15862 125 24X Fiche 50-255.82/10/08.8210280058
- --8210280063 Public version or Revision 1 to emergency plan RANY, J. Consumers Power Co. 82/09/14 105pp 15862 127 24X Fiche 50-255, 82/10/08, 8210280058
- 8210280107 Submits response to NRC questions re util 820701 fire protection submittal JOHNSDN,8 D Consumers Power Co 82/10/25 CRUTCHFIELD,D Operating Reactors Branch 5 3pp 15837 191 24X Fiche 50-255,82/10/25,8210280107
- G Adjudicatory correspondence
- 8210190480 Requests assistance in representing Oreat Lakes Energy Alliance in steam generator replacement proceeding Author deeply involved in Midland proceeding SIRCLAIR:M Great Lakes Energy Alliance B2/10/04 GARDE. @ O
- 8210080082 Motion for indefinite continuance of proceeding Need for steam generator replacement alleviated due to better than expected corrosion performance of steam generator tubes. Future rate of corrosion unpredictable N/Certificate of Svc STEPTOE, P. Consumers Power Co. STEPTOE, P. P. Isham, Lincoln & Beale 82/10/05 Atomic Bafesty and Licensing Board Panel App. 15640 205 24% Fiche 50-259,82/10/05.8210080082
- 8210080099 Notice of appearance in proceeding STEPTOE.P P Consumers Power Co STEPTOE.P P Isham, Lincoln & Beale 82/10/05 ip 15640 275 24X Fichs 50-256.82/10/05. 8210080099
- B2102700B7 Response to applicant B21005 motion for indefinite continuance NRC does not object to motion Certificate of Sycencl
  BARTH.C A Hearing Branch 1 82/10/25 Atomic Gafety and Licensing Board Panel 2pp 13822 338 24X Fiche 50-255.82/10/25, 82/027087
- P Operating license stage documents & correspondence
- 8210120033 Ack receipt of 820830 application proposing Tech Spec changes re ESF filtration sys Application provides supplemental info to 750306 pre-fee application No add) fee required Refund of 820830 application fee authorized MILLER.W O License Fee Management Branch 82/09/23 VANDEWALLE.D J Consumers Power Co. 1p 15689:202 24X Fiche 50-205.82/09/23,8210120033
- 8210050072 Discusses 820208 final assessment rept for SEP Topic IX-4, "Boron Addition Bys " Check valves 3408,3409 % 3410 should be added to Tech Spec Table 4 3 i Response requested within 45 days CRUTCHFIELD, D. Operating Reactors Branch 5 82/09/29 VANDEWALLE, D J Consumers Pawer Co 2pp 15403 186 24K Fiche 50-255,82/09/29,8210050072
- 8210070013 Forwards draft "Offsite Dose Calculation Manual" for facilities VANDEWALLE.D J. Consumers Power Co 82/09/27 CRUTCHFIELD.D Operating Reactors Branch 5 ip 15628 222 24X Fiche 50-000, 82/09/29, 8210070013
- --8210070018 Draft "Offsite Dose Calculation Manual," Palisades Plant Consumers Power Co 82/09/24 55pp 15628 276 24X Fiche. 50-000, 82/09/29, 8210070013

- 8210050265 Confirms that auxiliary feedwater sys mod provides for pumps P-8A & P-BC to be loaded on emergency diesel generators upon loss of offsite power 1033 OF 07733.4 Power JOHNSON, B D Consumers Power Co B2/09/30 CRUTCHFIELD, D Operating Reactors Branch 5 1p 19610 283 24X Fiche 50-255, 82/09/30, 8210050265
- 9210050302 Updates status & schedule for responses to NUREQ-0737, Items I D 2. "Plant Safety Parameter Display Console" & III A 2. "Improving Licenses Emergency Preparedness Long-Term "OHNESON.B D Consumers Power Co 62/07/30 CRUTCHFIELD.D Operating Reactors Branch S 2pp 15602-359 24X Operating Reactors Branch 5 2p Fiche 50-255, 82/09/30, 8210050302
- 8210120078 Submits info re failure of control rod to fully insert during testing in hot shutdown condition Locking paw & pin, piston guido tube, rack assembly & bavel gear housing replaced All defective uncoupling tools removed from svc UCHNBOR. B D Consumers Power Co 82/10/06 CRUYCHFIELD.D Operating Reactors Branch 5 App 15651 246 24X Fiche 50-255: 82/10/06.8210120078
- 8210120323 Forwards suppl to safety evaluation of SEP Topics 11-3 A. Forwards supply to safety evaluation of BEP Topics I IJ-3 S & II-3 C reanalyzing design basis surge level for facility Unresolved differences now considered acceptably resolved & topic reviews complete WAMBACH.T V Operating Reactors Branch 5 B2/10/07 VANDEWALLE.D J Consumers Power Co. 5pp 13653 033 24X Fiche 50-255, B2/10/07, 8210120323
- 82:0130326 Comments on proposed scope of Phase III of SEP as raflected in individual topic definitions appended to 820909 ltr Staff encouraged to develop & implement means to incorporate positive attributes of Phase III in licensee/NRC interface KACICH:R H SEP Curners Group 82/10/07 EIBENHUT.D Q Division of Licensing 7pp 15682 177 24% Fiche 50-000,82/10/07,8210130326 Division of
- 8210190110 Provides addl guidance re purpose of NRC B20630 request for addl info concerning NUREQ-0737. Item II. 8 3 re post-accident sampling sys CRUTCHFIELD. D. Operating Reactors Branch 5 GR/10/07 VANDEWALLE.D. J. Consumers Power Co. 3pp 15719 319 24X Fiche: 50~255, 82/10/07, 8210180110
- 8210130334 Forwards evaluations of open items identified in NRC 820212 ltm re SEP Topic III-7 B, "Design Codes.Design Criteria & Load Combinations." per util 820817 commitment Code change will not affect safety margin of plant structures VANDEWALLE.D J Consumers Power Co 82/10/08 CRUTCHFIELD.D Operating Reactors Branch 5 12pp 15679 140 24X Fiche 50-235.82/10/08.8210130334
- 82:0190459 Forwards current status of program to evaluate adequacy of overload & short-circuit protection for electrical circuits that pass through reactor containment per EEP Topic VIII-4 "Electrical Penetrations of Reactor Containment "TONER.K. A Consumers Power Co 82/10/12 CRUTCHFIELD.D Operatin Reactors Earnch 5 21pp 15740 268 24X Fichs 50-000.82/10/12, Operating Reactors Branch 5 8210170459
- 8210190535 Forwards summary of actions taken to address specific 820412 draft NUREO-0820 concerns re-eccentric loads & valve functionability in small bore piping Summary of plans to perform add1 analysis on control valve CV-3003 encl TONER, K. A. Consumers Power Co. 82/10/13 CRUTCHFIELD, D. Operating Reactors Branch 5 Sipp 15751 255 Q4X Fiche 50-255,82/10/13,8210190535
- 8210190546 Summarizes status of util commitment re SEP Topic IX-3, "Station Svc & Cooling Water Sys " Analysis verifying that component cooling water tamp limits are not exceeded under postulated conditions will be submitted by 821115 TONER.K A Consumers Power Co 82/10/15 GRUTCHFIELD.D Oper Reactors Branch 5 2pp. 19751.361. 24X Fiche 50-255,82/10/15, COMMISSIONERS. B210170546
- 82:0220186 Provides addl info re control room toxic chemical analysis & self-contained breathing apparatus in response to NUREO-0737, Item III.D 3 4 on contol room habitability.per 820720 request
  JOHNSON, B D. Consumers Power Co. 82/10/19. CRUTCHFIELD, D.
  Desnating Reactors Branch S. 9pp, 15777.284. 24X
  Fichs 50-255, 82/10/19, 8210220186
- 8210260179 Responds to 820817 request for removel of administrative limit on auxiliary feedwater flow rate to steam generator. Limits discussed in NRC 801001 immediate action ltr no longer appropriate New flow rates should be established. KEPPLER. J. 9 Region G. Office of Director. 82/10/20, JCHNSON, B D Consumers Power Co. 1p. 15799:036 24X Fiche: 50-255.82/10/20, 8210280179.

- 8210280276 Informs of new commitment dates for NUREO-0737. Items II F 1 1.11 F 1 2.11 F 1 3.11 F 1 6 & 11 B 3 JOHNSON. B D Consumers fower to 82/10/25 CRUTCHFIELD. D Operating Reactors Branch 5 3pp 15837 304 24X Operating Reactors Branch 5 3pt Fiche 50-255, 82/10/25, 82(0280276
- O Inspection reports: IE Bulletins & carrespondence
- B210080015 Addi response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App 8 completely withheld (ref FOIA Exemption 5) FELTON, M Division of Rules and Records 82/07/12 Critical Mass Energy Project 7pp 15645 027 24X Fiche 50-000, 82/07/12,8210080015 82/07/12 UDELL/R A
- -- H2100H0144 Systematic assessment of licensee performance notes re # NRC - No Detailed Affiliation Given 80/09/01 19668 015 24X Fiche 50-000, 82/07/12, 8210080015 80/07/01 10pp
- 8210070007 Responds to FOIA request for eight categories of records ra steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B App B E2/08/10 LONG, D J FELTON, J H Division of Rules and Records E2/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche \$0-000, B2/08/10, B210070007
- --B210070172 Forwards info re steam generator integrity & insps at all operating PWRs.per 750320 & 21 requests Details of insps. including defect indications, tube plugging criteria & tubes glugged will not be provided except for Point Beach i OCLLER.K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY, R R Division of Technical Review (NRR-1975 only) 5pp 15645 176 24X Fiche 50-000,82/09/10,8210070007
- 8210190421 Forwards IE Insp Rept 50-255/82-20 during Aug 1982 & notice of violation
  STRETER, J F Division of Project & Resident Programs
  DEWITT, R B Consumers Power Co 2pp 19741 034 24:
  Fiche 50-255, 82.709/29, 8210190421
- --8210190427 Notice of violation from insp during Aug 1982 BTREETER, J F Division of Project & Resident Programs 1p 15741 036 24K Fiche 50-255,82/09/29,8210190421 82769759
- ~-8210190449 IE Insp Rept 50-255/82-20 during Aug 1982 Moncompliants noted on 820831.08A Bequencer Test Procedure T-157 revised during implementation & new steps involving bypass of safety functions performed w/o permission of shift supervisor JORGENBEN.8 L , HELLER, J K , REYES.L A Division of Project & Resident Programs 82/09/29 7pp 15741 037 24X Fiche 50-255.82/09/29,8210190421
- 8210190699 Forwards IE Mgt Meeting Rept 50-255/82-21 on 820908 No Notice of the state of the stat 82/10/04 DEMITT.R # PPA0P101CB
- --8210190707 IE Mgt Meeting Rept 50-255/82-21 on 820908 No honcomply E-OLFOVY IN MR MERCING REPT DU-MOD/BE-21 on 820908 No noncomplinated Major areas discussed current status of util program for meeting requirements of 810309 confirmatory order regulatory improvement program JDRGENSEN, B. L. BPESSARD, R. L. Division of Project & Assident Programs 82/10/01 3pp 18737 278 24X Fiche 50-255.82/10/, 8210190699.
- B208190233 IE Info Notice 80-35, Suppl i: "Leaking & Dislodged E-12: Implant Beeds." Syc list encl.
  COBB.L.1 Division of Fuel Facilities. Materials & Befsguards
  B2/10/06 Consolidated Edison Co of New York 36pp 13761 2
  24X Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-CONTINUES IN BULLETS DEFOUND THE STREET CONTINUES IN BULLETS BY WAIL, LARGE-Diameter Stainless Steel, Recirculation Bys Piping at BWR Plents." Svc list encl DEVOUNO, R C Director's Office. Office of Inspection and Enforcement, 82/10/14. Consolidated Edison Co of New York 115pp 15810:125, 24% Fiche, 50-000; 82/10/14, 8208190238
- B210260176 Ack receipt of supplemental B20929 ltr informing NRC sestes taken to correct violations noted in IE Insp Rept 50-255/82-07
  NORELIUS, C.E. Division of Engineering & Technical Programs, B2/10/18, DEWITT, R.S. Consumers Power Co. ip. 15799 645
  Ficher 50-255, 82/10/18, B210260176.

- --8210260183 Suppls response to NRC B20412 ltr re violations noted in IE Insp Rept 50-235/82-07 Corrective actions NBS-traceable hydrometer received & compared w/hydrometers used for surve(Illance Calibr results encl JCHMSON, B D Consumers Power Co 82/09/29 KEPPLER, J & Region 3. Office of Director 2pp 15799 046 24X Fiche 50-255, 82/10/16.6210260176
- Periodic operating reports & related correspondence
- 3210130138 Forwards monthly operating rept for Sept 1982 KENNEDY.D II Consumers Power Go 82/10/08 NRG - No Detailed Affiliation Given 1p 15673 090 24X Fiche S0-255, 82/10/08. 82:0130136
- -8210130145 Monthly operating rept for Sept 1982
  PETERSON.D A . VANDERBERG.D Consumers Power Co 82/10/04 4pp
  15673 091 24X Fiche 50-255, 82/10/08,8210130138
- , Reportable occurrences, LERs & related correspondence
- 1210150146 Forwards LER 81-011/03L-0 HDFFMAN, D P Consumers Power Co 81/03/27 KEPPLER, J Q Region 3, Chicago. Dffice of the Director (81/03/01) ip 15697 083 24X Fiche 50-255, 81/03/27, 8210150146
- -8210150152 LER 81-011/03L-0 on B10304.diesel generator i-1 gverspeed & low air pressure alarms actuated & would not reset after 16 cylinder leak test Caused by broken mirro-switch due to high impact resulting from improper use of trip lever = Gonsumers Power Co 81/03/27 Region 3. Chicago. Office of the Director (81/03/01) lp 15697 084 24X Fiche 50-255.81/03/27.8210150146
- 210070415 Discusses abnormal wear encountered on ALOYCO swing check valves installed in low pressure safety injection sus IE. should issue info notice to inform licensees of problem MICHELSON.C Director's Office 81/12/23 DEYOUNO, R C Director's Office. Office of Inspection and Enforcement 5pp 15637 327 24X Fiche 50-255.81/12/23.8210070415
- 21001000B Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents
  1sted in App A
  FELTON, J M Division of Rules and Records 82/06/28 UDELL, R. A
  Critical Mass Energy Project 15pp 15727 005 24X
  Fache 50-000, 82/06/28, 8210010008
- -8201200553 Recommends issuance of info notice to inform licenspas of problems w/ALOYCO swing check valves as encountered at facility Abnormal wear reported in LER 81-037 MICHELSON, C Director's Office 81/12/23 DEYOUNG, R C Director's Office of Inspection and Enforcement 5pp. 19732 076 24% Fiche 50-000, 82/06/28, 8210010008
- 210060213 Forwards LER 82-026/03L-0 JOHNSON B D Consumers Power Co 82/09/29 KEPPLER, J 0 Region 3, Office of Director 1p 15615 097 24X Fiche 50-255,82/09/29, 8210060213
- -8210060216 LER 82-026/03L-0 on 820901 determined that four fire doors mfg by Protective Matls Co not documented to confirm testing & approval by nationally recognized lab Caused by vendor failure to obtain certification following mods & Consumers Power Co 82/09/29 Region 3. Office of Director ip 13615 098 24X Fiche 50-255,82/09/29,8210060213
- 210130146 Forwards LER 82-027/03L-0 JOHNEON B D Consumers Power Co 82/09/30 KEPPLER J Q Region 3, Uffice of Director ip 15673 084 24X Fichs, 50-255, 82/09/30, 8210130146
- -8210130156 LER 82-027/03L-0 on 820901.procedural inadequacies discovered which could cause reduction in dagree of redundancy in containment cooling sys Procedures revised to require fans to be declared inoperable if stopped Consumers Power Co. 82/09/30 Region 3. Office of Director ip 15473 085 24X Fichs 50-255,82/09/30,8210130146
- 210180186 Forwards LER 82-031/03L-0 JOHNSON B D Consumers Power Co. 82/10/06 KEPPLER, J O Region 3, Office of Director 1p 15718 177 24X Fiche 50-255,82/10/06, 8210180186
- -8210180191 LER 82-031/03L-0 on 820909, i-1 diesel generator water jackat heater found inoperable Caused by corrosion of heater element. Heater replaced w/similar type element Mod developed to replace heater element
  - to replace haster element

    Consumers Power Co 82/10/06 Region 3, Office of Director 1p 15718 178 24X Fichs 50-255,82/10/06,8210180186

- 8210190404 Forwards LER 82-028/03L-0 JOHNSON, B D Consumers Power Co 82/10/11 KEPPLER, J Q Region 3, Defice of Director 1p 15739 357 24X Fiche 50-255, 82/10/11. 8210190604
- --B210190615 LER 82-028/03L-0 on 820915.boric acid heat trace circuit 401 (gravity feed line to charging pumps) failed Rudundant channel remained operable Caused by failed heater element Heater element replaced # Consumers Power Co 82/10/11 Region 3. Office of Director 1p 18737 388 24% Fiche 50-255.82/10/11.8210190604
- 8210190620 Forwards LER 82-029/03L-0 JOHNSON, B D Consumers Power Co 82/10/11 KEPPLER, J Q Region 3, Office of Director 1p 15737 219 24X Fiche 50-255, 82/10/11, 8210190620
- --8210190628 LER 82-029/03L-0 on 820916,T-828 (safety injection tank B) level reached Tech Spec limit of 198 inches three times in 24th period Caused by misor leakage past loop theck valve & fill & drain valve Fill & drain cycled to stop leakage \* Consumers Power Co 82/10/11 Region 3. Office of Director ip 15737 220 24X Fichs 50-255,82/10/11,8210170620
- 8210190639 Forwards LER 82-030/03L-0 JOHNSON, B D Consumers Power Co. 82/10/11 KEPPLER, J G Region 3, Office of Director 1p 15740 044 24% Fiche 50-255, 82/10/11, 8210190639
- --8210190649 LER 82-030/03L-D on 820927.boric acid heat trace circuit 432 failed Redundant channel remained operable Caused by blown fuse in controller Circuitry tested & fuse replaced \* Consumers Power Co. 82/10/11 Region 3. Office of Director ip 15740-045 24X Fiche 50-255.82/10/11.8210190639
- DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1
  F Security, medical, emergency & fire protection plans
- 8209170101 Forwards minor revisions to proposed physical security plan Revisions withheld (ref 10CFR73 21) MILLS,L H Tennessee Valley Authority 82/08/31 DENTON,H R Office of Nuclear Resortor Regulation, Director, 2pp 14910 081 24X Fiche 50-259,82/08/31,8209170101
- 8210210034 STATION BLACKDUT AT BROWNS FERRY UNIT ONE-IDDINE AND NOBLE OAS DISTRIBUTION AND RELEASE HICKNER, P., WEBER, C.F., LORENZ, R.A. Oak Ridge National Laboratory FIN 8-0452 NUREO/CR-2182 VO2 82/09/30 Division of Accident Evaluation 261pp. 18773,001 24X Fichs 50-259,82/09/30,8210210034
- 8210250236 Forwards accurity plan table of contents Table of contents withheld (ref 100FR73 21)
  KAMMER D 8 Tennessee Valley Authority 82/10/19 DENTON, H. R
  Office of Nuclear Reactor Regulation, Director ip 15788 362 24x
  Fiche. 50-257.821/0/17.8210250238
- O Adjudicatory correspondence
- 8210120291 Response to ASLAB 820920 order to provide any supplemental info re questions posed to util Authorization is for 5-yr storage of low level reduceste, who limit on use of modules for interim use on backup basis.

  RAHSON:R.J. Hearing Branch 4 82/10/08 8pp 15652 071 24X Fiche. 30-289: 82/10/08, 8210120291.
- --8210120299 Affidavit of P Lousen re application for storage of low level radwaste No restriction requested or contemplated limiting use of modules only to interim use on backup basis LOYSEN, P Advanced Fuel & Bpent Fuel Licensing Branch 82/10/08 23pp 15652,079 24X Fiche. 50-259.82/10/08.8210120291.
- --8210120308 Affidavit of JR McOrath Timely request for renewal of facility license filed for Beatly.NV low level radwatte disposal facility NV State Board of Health voted not to renew facility license.

  HCGRATH.J.R Assistant Director for State Agreements Programs 82/10/08 2pp 15652.102 24X Fiche.50~259,82/10/08.8210120291
- --B210120316 Affidavit of SN Balomon Southeast Interstate Low Level Radwaste Mgt Compact agreed to close Barnwell, BC facility on 921231 & open new site on 911231. Certificate of Byc encl. SALOMON B. N Assistant Director for State Agreements Programs, 82/10/08 App. 15652 104 24X Fiche: 50-259, 82/10/08, 8210120291

- 8210250043 Telecopy message of motion for ASLAB to grant 30-day extension to respond to ASLB 820920 order Time necessary to explore settlement possibilities of all matters in controversy PYLE.R B 92/10/20 Docketing & Bervices Branch 15787 061 24X Fische 50-259, 82/10/20, 8210250063
- 8210260429 Motion for extension of time until 821121 to respond to 820920 order Time necessary to explore possibilities of settlement Certificate of Svc encl PYLE.R B Pyle. R B 82/10/20 Atomic Safety and Licensing Appeal Panel 2pp 15806 026 24X Fiche 50-259.82/10/20, 821026429
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8208170297 Chapter 2 to Browns Ferry updated FSAR. "8ite "
  \* Tennessee Valley Authority 82/08/12 346pp 14852 202 24X
  Fiche 50-259,82/08/12.8208170297
- P Operating license stage documents & correspondence
- 82:0050268 Application to amend License DPR-33, revising Cycle 5 may critical power ratio values Error discovered in active fuel length used in original Cycle 5 analysis Approval requested by 821:19
  MELLS,L M Tennessee Valley Authority 82/09/21 DENTON,H R
  Office of Nuclear Reactor Regulation. Director 2pp 156:11 23:1
  24X Fiche 50-259,82/09/21,82:10050268
- --8210050271 Proposed Tech Specs re max critical power ratio
  \* Tennessee Valleg Authority 82/09/21 3pp 15611 233 24X
  Fiche 50-259, 82/09/21, 8210050268
- 8210060301 Application to amend License DPR-33, updating curve of pressure vs temp to extend applicability through 5 0 effective full power urs Approval of change requested by 821126
  MILLS.L.H. Tempessee Valley Authority 82/09/23 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 15619 293 24X Fichs 50-259.82/09/23.8210060301
- --B210060304 Proposed Tech Spec Figure 3 6-1, updating curve of pressure vs temp to extend applicability through 5 0 effective full power yrs # Tennessee Valley Authority B2/09/23 3pp 15619 275 24X Fiche 50-259, B2/09/23, 8210060301
- 8210070255 Forwards response to NRC request for add1 info on NUREO-0612, "Control of Heavy Loads of Nuclear Power Plants "
  MRLB.L M Tennessee Valley Authority 82/09/28 VASSALLO, D B Operating Reactors Branch 2 56pp 15635 243 24X Fiche 50-289, 82/09/28, 8210070285
- 8210080218 Forwards add1 info in response to NRC 820808 request re NUREO-0737: Item II K 3 24, "Adequacy of Space Cooling for HPCI & RCIC." MILLS.L. H. Tennessee Valley Authority 82/10/04 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 15638:091 24X Fiche: 50-259,82/10/04,82(0060218
- 8210130142 Forwards description of final mods & changes to BMR scram sys & short-term interim commitments for Unit 2 Mods will be implemented for Unit 2 before startup from Reload 4 outage & subsequent Units 1 & 3 outages
  HILLS.L M Tennessee Valley Authority 82/10/06 DENTON.H. R
  Office of Nuclear Reactor Regulation. Director 4pp 15673 086. 24X Fiche 50-259.82/10/06.8210130142
- 8210250096 Forwards revision to 821006 implementing procedures MILLS:L M Tennessee Valley Authority. 62/10/15 DENTON:H R Office of Nuclear Reactor Regulation, Director. 1p 15793:058 24X Fiche:50-259,62/10/15.821025096
- --8210250101 Revised implementing procedures.

  \* Tennesses Valley Authority 82/10/15 16pp 15793.059 24X
  Fichs 50-259.82/10/15.8210250096
- G. Inspection reports, IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & sefety problems. Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5).
  FELTON J M Division of Rules and Records 82/07/12, UDELL.R A Critical Mass Energy Project 9pp. 15665 027 24X Fiche 50-000 82/07/12, 8210080015

- --8210080118 Systematic assessment of licensee performance notes refacility evaluation for Apr 1979-Mar 1980

  # NRC No Detailed Affiliation Given 80/03/31 App
  15647 315 24X Fiche 50-000, 82/07/12-8210080015
- 8210150105 Notifies that corrective actions of IE Insp Repts 50-259/BI-13, 50-260/BI-13 & 50-276/BI-13 delayed Procedure BPM NBOES of exam of CSSQ items to be revised by 820915 BOMER. J A Tennessee Valley Authority 82/07/I3 0'REILLY, J PRegion 2, Office of Director ip 15701 159 24X Fiche 50-259, 82/07/I3.8210150105
- 8210220151 Provides supplemental response to NRC ltr re violations noted in IE Insp Repts 50-299/82-10.50-280/82-10.55-290/82-10.50-280/82-10.50-290/82-10.50-200/82-10.50-290/82-10.50-200
- B210010035 Confirms B2070B site meeting to discuss recent violations re-radwaste shipments Agenda encl
  D'REILLY, J.P. Region 2, Office of Director 82/09/03 PARRIB, H. C. Tennessee Valley Authority 2pp 15565 166 24X
  Fiche 50-259, 82/09/03, 8210010035
- 8210010430 Forwards IE Insp Repts 50-259/82-25.50-260/82-25 & 50-296/82-25 on 820810-11 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs G2/09/07 PARRES.H G Tennessee Valley Authority 2pp 15570 211 24% Fiche 50-259,82/09/03.8210010430
- --8210010432 IE Insp Repts 50-259/82-25, 50-260/82-25 & 50-296/82-23 to 820810-11 No noncompliance noted Hayor areas inspected reactor secondary containment integrity problem & MBIV testing BROOXS, E M. JAPE, F. Division of Engineering & Technical Programs 82/08/27 4pp 15570 213 24X Fiche 50-259, 82/09/03, 821001043)
- 8210150399 Forwards IE Insp Repts 50-259/62-28.50-260/62-28 t 50-296/62-28 on 620630-0903 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 62/09/20 PARRIS.H O Tennessee Valley Authority 2pp 15704 029 24x Fiche 50-259.62/09/20.6210150399
- --8210130406 IE Insp Repts 50-259/82-28,50-260/82-28 t 50-296/82-28 the B20830-0903 No noncompliance noted Major areas inspected inservice inspected inservice inspected inservice inspected grand, E. H., BLAKE, J. Division of Engineering & Technical Programs 82/09/16 4pp 15704 031 24% Fiche 50-259,82/09/20 8210150399
- 8210010097 Approves revised commitment dates for Item 25 of App L to IE Insp Repts 50-259/81-19.50-260/81-19 & 50-296/81-19 & 1tem C 2 of App A to IE Insp Repts 50-259/82-12.50-260/82-12 & 50-296/82-12
- --8210010104 Requests extension to respond to App C. Item 25 in [E Inij Repts 80-259/81-19,50-260/81-19 & 50-296/81-19 & Item C 2 in IE Inij Repts 50-2896/82-12 & 50-266/82-12 & 50-296/82-12 Responses will be submitted by 830101 & 82101. respectively MILLSI, L. M. Tennessee Valley Authority 82/09/01 O'REJLLY, J. P. Region 2. Office of Director ip 15565 002 24% Fiche 50-259,82/09/22.8210010097
- 8210010326 Forwards summary of 820708 enforcement meeting w/util to discuss corrective actions re leakage during shipment of low level waste & util plans for improving employee training D'RETLLY, J.P. Region 2. Office of Director 82/09/22 PARRIE, H. Tennessee Valley Authority 4pp 15567 188 24X Fiche: 50-259, 82/09/22, 8210010326
- 8210010290 Ack receipt of supplemental 820901 ltr informing NRC of steps taken to correct Violation 8 noted in IE Insp Repte 50-295/81-26, 50-260/82-26 & 50-296/81-26 LEWIGLR C Division of Project & Resident Programs 82/09/24 PARRISLH G Tennesses Valley Authority ip 15573 183 24X Fichs. 50-259, 82/09/24,8210010290
- --B210010304 Forwards revised response to NRC 811028 itr re Violatie: I noted in IE Insp Repts 50-259/82-26.50-260/82-26 & 50-296/82-26 Corrective actions R factor returned to within limits & revision to Tech Bpec approved MILLS, L.M Tennessee Valley Authority 82/09/01 O'REILLY. J F Repion 2. Office of Director 3pp 15573-184 24X Fiche 50-259,82/09/24,8210010290

- 8210220370 Forwards IE Ihsp Repts 50-259/82-29.50-260/82-29 & 50-296/82-29 on 820906-10 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/09/30 PAPRIES M O Tennessee Valley Authority 2pp 15779 220 24X Fiche 50-259.82/09/30.8210220390
- --8210220401 IE Insp Repts 50-259/82-29, 50-260/82-29 & 50-296/82-29 on 820906-10 No noncompliance noted Major areas inspected Unit 2 refueling & maint outage & procedural compliance of health physics-related practices by workers COLLINS.T R. BARR.K P Division of Engineering & Technical Programs 82/09/27 Spp 15779 222 24X Fiche 50-259.82/09/30, 8210220390
- 6210080219 Forwards revised request for relief from Inservice Insp 7 re inaccessible welds in piping penetrations & under rigid pipe restraints Best effort visual exam will be performed during sys hydrostatic pressure test
  MILLS.L M Tennessee Valley Authority 82/10/04 DENTON.H R
  Office of Nuclear Reactor Regulation. Director 3pp 15638 083
  244 Fiche 50-259.82/10/04.8210080219
- B20B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds" Svc list encl COBB.L 1 Division of Fuel Facilities, Materials & Safeguards B2/10/06 Consolidated Edison Co of New York 66pp 15761 250 24K Fichs 50-000, B2/10/06 B20B190233
- 8210150218 Forwards update of present work & schedule for implementation of insps required under IE Bulletins 79-02 & 79-14 Phase II evaluation will not be completed until 84080:
  MILLS.L.M. Tennessee Valley Authority 82/10/07 0'REILLY, J.P. Region 2. Office of Director 2pp 15705 276 24X Fiche 50-259.82/10/07.821015021B
- 6208190238 IE Bulletin 62-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter; Stainless Steel, Recirculation Sys Piping at BNR Plants" Syc list encl
  DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co. of New York
  115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- 5 Reportable occurrences, LERs & related correspondence
- 9207300170 Forwards LER 92-071/01T-0 GREEN.H J Tennessee Valley Authority 82/09/24 O'REILLY, J P Region 2, Office of Director 1p 15553 281 24X Fiche 50-259.82/09/24.8209300170
- --8209300175 LER 82-071/01T-0 on 820909, HPC1 condensate storage tank low level switches LS-73-56A & LS-73-56D failed to operate Caused by dirty & corroded level switches activating plates Plate points cleaned tRBY. B J Tennessee Valley Authority 82/09/24 Region 2, Office of Director 2pp 15550 282 24X Fiche 50-259, 82/09/24, 8209300170
- 8210060409 Forwards LER 82-067/03L-0 GREEN H J Tennessee Valley Authority 82/09/30 D'REILLY, J P Region 2. Office of Director | p. 13615 317 24X Fiche 50-239, 82/09/30,8210060409
- --8210060412 LER 82-067/03L-0 on 820901.during normal operation, while performing fire protection surveillance insp, heat detection ione & for spreader room & common to Units 1 & 2 found inoperable Caused by loose fire protection panel relay MURPMY.DE Tennessee Valley Authority 82/09/30 Region 2, Office of Director 2pp 15415 J20 24X Fiche 50-259,82/09/30,8210060409
- 8210060414 Forwards LER 82-06B/03L-0 GREEN.H J Tennessee Valley Authority 82/09/30 O'REILLY, J P Region 2. Office of Director 1p 15615 004 24X Fiche 50-259,82/09/30,8210060414
- --6210060422 LER 82-068/03L-0 on 820702, while performing primary containment isolation valve leak rate test. A hydrogen analyzer became inoperable Caused by failed hydrogen sample intet pump power ralay contacts
  CARTER: 8 D Tennessee Valley Authority 82/09/30 Region 2, Office of Director 2pp 15615 005 24X Fiche 50-259,82/09/30,8210060414

- 82:0130565 Forwards LER 82-049/03L-0 GREEN.H J Tennessee Valley Authority 82/10/05 O'REILLY, J P Region 2. Office of Director 1p 15683 110 24X Fiche 50-259:82/10/05.8210130565
- ---8210130569 LER 82-069/03L-0 on 820907, during startup testing, rod sequence control sys found inoperable Caused by failure of GE sequence generator card Model 19389480AA Card replaced & testing sabisfactorily completed IRBY. B J Tennessee Valley Authority 82/10/05 Region 2, Office of Director 2pp 15683 111 24X Fiche 50-239,82/10/05.8210/30565
- 82:0130165 Forwards LER 82-072/03L-0 OREEN H J Tennesses Valley Authority 82/10/07 O'REILLY, J P Region 2. Office of Director ip 15673 054 24X Fiche 50-259, 82/10/07, 8210130165
- --8210130169 LER 82-072/03L-0 on 820908, during startup, rod worth minimizer (RMM) applied rod blocks when rod 30-51 selected Caused by listing two rods twice in RMM sequence due to tuping error RMM sequence corrected & returned to syc NAVE.E Tennessee Valley Authority 82/10/07 Region 2, Office of Director 2pp 15673 055 24X Fiche 50-259,82/10/07,8210130165
- 8210130172 Forwards LER 82-075/01T-0 OREEN H J Tennessee Valley Authority 82/10/07 O'REILLY, J P Region 2, Office of Director 1p 15673 046 24X Fiche 50-259, 82/10/07, 8210130172
- -8210130176 LER 82-075/01T-0 on 820724, four degraded voltage relays, three timers & one loss-of-voltage relay found to be outside allowable Tech 8pec setpoint range Caused by setpoint drift Relays recaliby & returned to syc CHRISTOPHER, W. Tennessee Valley Authority 82/10/07 Region 2 Office of Director 2pp 15673 047 24X Fiche 50-207, 82/10/07, 8210130172
- 8210130429 Forwards LER 82-070/03L-0 GREEN H J Tennesse Valley Authority 82/10/07 O'REILLY, J P Region 2, Office of Director Ip 15681 160 24X Fiche 50-259, 82/10/07, 8210130429
- --B21013043B LER 82-070/03L-0 on 82090B, while calibr reactor protection sys high-water level switches on scram discharge tank, level switch LS-85-45E operated at 27 gallons, contrary to Tech Specs Caused by calibr drift on level switch SL-305-EI-X IRBY, B J Tennessee Valley Authority 82/10/07 Region 2, Office of Director 3pp 15681 161 24X Fiche 50-259, 82/10/07, 8210130429
- 8210220053 Forwards LER 82-073/03L-0 OREEN, H J Tennessee Valley Authority 82/10/08 O'REILLY, J P Region 2. Office of Director ip 15778 204 24X Fiche 50-259, 82/10/08, 8210220053
- --8210220057 LER 82-073/03L-0 on 820910, while performing maint on diesel generator A, fuel oil flowed out discharge filter drein valve when transfer pumps supplied oil to day tank Caused by personnel error Responsible person reinstructed PORTER, M R Tennessee Vallay Authority 82/10/08 Region 2, Office of Director Ip 15778 205 24X Fiche 50-257, 82/10/08, 8310220053
- 8210290054 Forwards followup LER 82-023/03X-2 OREEN H J Tennessee Valley Authority 62/10/13 O'REILLY, J P Region 2. Office of Director 1p 15854 050 24X Fiche 50-259, 82/10/13, 8210290054
- --B210290057 Followup LER B2-023/03X-2 on 820327, recirculation pump 1A tripped due to spurious generator starter relay operation Caused by Hi-temp relay trip Relay reset in 20 minutes & pump returned to avc No recurrence control planned CHRISTOPHER, W. Tennessee Valley Authority 82/10/13 Region 2, Office of Director 3pp 15854 051 24X Fiche 50-259,82/10/13, 8210290054
- 8210290062 Forwards updated LER 82-042/03X-1 OREEN H J Tennessee Valley Authority 82/10/13 O'REILLY, J P Region 2, Office of Director 1p 15853 339 24X Fiche 50-259, 82/10/13, 8210290062
- --8210290066 Updated LER 82-042/03X-1 on 820\[abla]8, quarterly Surveillance Insp 3 2 8 for testing of HPCI & RCIC vacuum relief valves not performed per ASME Section XI Caused by personnel error Foreman misplaced performance reminder CAMPBELL.G. Tennessee Valley Authority 82/10/13 Region 2, Office of Director 2pp 15853 340 24X Fiche 50-259,82/10/13,8210290062

- 8210290317 Forwards updated LER 82-031/03X-2 GREEN H J Tennessee Valley Authority 82/10/13 O'REILLY, J P Region 2, Office of Director 1p 15853 080 24X Fiche 50-259, 82/10/13, 8210270317
- --8210270321 Updated LER 82-031/03X-2 on 820510, hydrogen analyzer B inoperable due to failure of hydrogen sample inlet pump Caused by failure of Allen Bradley relay Model 700-N400A1 contacts Relay investigation results expected 830215 CARTER, S Tennessee Valley Authority 82/10/13 Region 2. Office of Director 2pp 15853 081 24X Fiche 50-259.82/10/13. 8210290317
- 82:0290368 Forwards LER 82-077/03L-0 ORECN-H J Tennesse Valley Authoraty 82/10/15 O'REILLY, J P Region 2. Office of Director 1p 15853 083 24X Fiche 50-257, 82/10/15,8210270368
- --8210290371 LER 92-077/02L-0 on 920918, control rod 38-39 declared inoperable due to fuse failure alarms & high-water level alarms indicating Caused by control rod drive hydraulic control unit accumulator level switch being grounded MARPHY. D E Tennessee Valley Authority 92/10/15 Region 2, Office of Director 2pp 15853 084 24X Fiche 50-259, 82/10/15.
- 8210260381 Forwards LER 82-076/03L-0 GREEN H J Fennesses Valley Authority 82/10/19 O'REILLY, J P Region 2. Office of Director 1p 15803 359 24X Fiche 50-259, 82/10/19, 8210260381
- --8210260407 LER 82-076/03L-0 on 820925, turbine bldg roaf vent monitor CAM 1-90-251 became inoperable Caused by failure of pump drive motor, model 6K552C due to end of natural jife Drive motor replaced, THORPE, A Tennessee Valley Authority 82/10/19 Region 2, Office of Director 20 15803 360 24X Fiche 50-259,82/10/19,
- 8210260212 Forwards updated LER 82-067/03X-1 QREEN,H J Tennessee Valley Authority 82/10/20 O'REILLY, J P Region 2. Office of Director 1p 15/99 153 24X Fiche 50-259, 82/10/20, 8210260212
- --8210260222 Updated LER 82-067/03x-1 on 820901, heat detection zone 6 for spreader from A & preaction sprinkler automatic initiation circuit found inoperable Gaused by loss fire protection panel relay Relay repositioned & clipped in place HURPHY. D E Tennessee Valley Authority 82/10/20 Region 2, Office of Director 2pp 15799 154 24x Fiche 50-259,82/10/20. 8210240212
- T Hearing transcripts on non-antitrust matters
- G210070133 Testimony of JW Hutton answering ASLAB questions on low level radwaste mgt options Availability of adequate space to dispose of low level wastes in next 5 yrs uncertain Certificate of Svc enc! HUTTON, J W Tennessee Valley Authority 82/10/01 12pp. 15627 031 24% Fiche 50-259,82/10/01.821007013
- DOCKET 50-240 BROWNS FERRY NUCLEAR POWER BYATION, UNIT 2 F. Security, medical, emergency & fire protection plans
- 8209170101 Forwards minor revisions to proposed physical security plan Revisions withheld (ref 100FR73 21) MJLLS.L M Tennessee Valley Authority 82/08/31 DENTON, M R Office of Nuclear Reactor Regulation, Director, 2pp 14910 081 24X Fiche: 50-259,82/08/31,8209170101.
- 8210250236 Forwards security plan table of contents Table of contents withheld (ref 10CFR73 21)

  KAMMER.D B Tennessee Valley Authority 82/10/19 DENTON, H R
  Office of Nuclear Reactor Regulation, Director 1p 15788 362 24X

  Fiche 50-259.82/10/19.8210250236
- 8210230244 Forwards revisions to physical security plan Revisions withheld (ref 10CFR73, 21)
  KAMMER, D 8 Tennesse Valley Authority 82/10/19 DENTON, H R
  Office of Nuclear Reactor Regulation, Director 1p, 15788 345 24X
  Fiche 50~250, 82/10/19, 8210250244

### G Adjudicatory correspondence

- 8210120291 Response to ASLAB 820920 order to provide any supplemental info me questions posed to util Authorization is for 5-yr storage of low level raduaste. Vo limit on use of modules for interim use on backup basis RAWSON, R J Hearing Branch 4 82/10/08 8pp 15652 071 24x Fiche 50-259,82/10/08,8210120291
- --8210120299 Affidavit of P Loysen re application for storage of low level raduste No restriction requested or contemplated limiting use of modules only to interim use on backup basis LOYSEN.P Advanced Fuel & Spent Fuel Licensing Branch 82/10/68 23pp 15652 079 24% Fiche 50-259.82/10/08.8210120291
- ~-8210120308 Affidavit of JR McGrath Timely request for renewal of facility license filed for Beatly.NV low level radwaste disposal facility NV State Board of Health voted not to renew facility license McGRATH, JR Assistant Director for State Agreements Programs 82/10/08 2pp 15652 102 24X Fiche 50-259, B2/10/08.821012024
- --8210120316 Affidavit of SN Salomon Southeast Interstate Low Level Radwaste Mgt Compact agreed to close Barnwell. SC facelity on 921231 & open new site on 911231 Centificate of Svc encl SALOMON.8 N Assistant Director for State Agreements Programs 82/10/08 4pp 15552 104 24X Fiche 50-259.82/10/08 48401002/1
- 82(0250063 Telecopy message of motion for ASLAB to grant 30-day extension to respond to ASLB 820920 bider Time necessary to explore settlement possibilities of all matters in controversy PYLE.R B Fyls. R B 82/10/20 Docketing & Services Branch (g. 15787 061 24% Fiche 50-259,82/10/20.8210250063
- 8210260429 Motion for extension of time until 821121 to respond to 820920 order Time necessary to explore possibilities of settlement Certificate of Svc encl PYLE.R B Pyle. R B 82/10/20 Atomic Safety and Licensing Appeal Panel 2pp 15806 036 24% Fiche 50-259,82/10/29. B210260429
- P Operating license stage documents & correspondence
- 8210070255 Forwards response to NRC request for addl info on NUREO-0612, "Control of Heavy Loads of Nuclear Power Plants"
  HILLS,L M Tennessee Valley Authority 82/09/28 VABSALLO,D & Operating Reactors Branch 2 Sopp 15635 243 24X
  Fiche 50-259,82/09/28.8210070255
- 9210080218 Forwards add1 info in response to NRC 820808 request re NUREO-0737. Item II K 3 24. "Adequacy of Space Cooling for HPCI & RCIC" MILLS.L M Tennessee Valley Authority 82/10/04 DENTON.H H Deffice of Nuclear Reactor Regulation. Director 2pp 15638 091 24X Fiche 50-259.82/10/04.8210080218
- 8210130142 Forwards description of final mods & changes to BHR strad sys & short-term interim commitments for Unit 2 Mods will be implemented for Unit 2 before startup from Reload 4 outages & subsequent Units 1 & 3 outages MILLS.L. M. Tennessee Valley Authority 82/10/06 DENTON.H R Office of Noclear Reactor Regulation. Director 4pp 15673 086 24% Fiche 50-259.82/10/06.8210130142
- 8210250067 Application to amend License DPR-52 to accommodate Reload & Cycle 5 operation & outage-related mods Approval by 830112 requested to avoid impacting refueling & startup MILLS,L.M Tennessee Valley Authority 82/10/15 DENTON:H R Office of Nuclear Reactor Regulation, Director 2pg 15792 145 24% Fiche 30-260,82/10/15.8210250067
- --8210250070 Proposed Tech Spec changes, accommodating Reload 4.Cycle 5 operation & outage-related mods
  \*\* Tennesses Valley Authority 82/10/15 82pp 15792 147 24x
  Fiche: 50-260, 82/10/15,8210250067
- --8210250074 "Supplemental Reload Licensing Submittal for Browns Ferra Nuclear Plant, Cycle 5, Unit 2, Reload 4 " HELF. C. L., ZARBIB, M. A., CHARNLEY, J.S. General Electric Co YEO03501440 82/07/31 36pp 15772 230 24X Fiche 50-260, 82/10/15, 8210250067
- --8210250077 Errata & Addenda Sheet 4 to NEDD-24088-1, "LOCA Analysis for Browns Ferry Nuclear Plant Unit 2" \* General Electric Co NEDD-24088-1 NO4 ERR 82/07/31 Bsp j5792.255. 24X Fiche 50-260,82/10/15,8210250067

## DOCKETED ITEMS

- --82(0250078 Errata % Addenda Sheet 5 to NEDD-24088-1, "LOCA Analysis for Browns Ferry Nuclear Plant Unit 2" General Electric Co NEDD-24088-1 NO5 ERR 82/08/31 2pp 15792 263 24% Fiche 50-260, 82/10/15,8210250067
- F210250076 Forwards revision to 821006 implementing procedures MILLS.L M Tennessee Valley Authority 82/10/15 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 15793-058 15793 058 24 X Fiche 50-259, 82/10/15, 8210250096
- -8210250101 Revised implementing procedures Tennessee Valley Authority 82/10/15 Fiche 50-259 82/10/15:8210250094 16en 15793 059 24X
- o Inspection reports. IE Bulletins & correspondence
- Raloo80015 Addi response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) Fil.10N, J M Division of Rules and Records 82/07/1 Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000, 82/07/12, 8210080015 82/07/12 UDELL,R A
- -8210080118 Systematic assessment of licensee performance notes refacility evaluation for Apr 1979-Mar 1980

  NRC No Detailed Affiliation Given 80/03/31 App 1566/ 315 24X Fiche 50-000.82/07/12.8210080015
- 5210150105 Notifies that corrective actions re IE Insp Repts 50-259/81-13 50-260/81-13 50-296/81-13 delayed Procedure DPM M80E3 re exam of C550 items to be revised by 820915 DPMER.J A Tennessee Valley Authority 82/07/13 O'REILL Region 2. Office of Director ip 15701 159 24X Fichs 50-259, 82/07/13, 82/0150105 O'REILLY, J P
- 6210220151 Provides supplemental response to NRC ltr re violations noted in IE lies Repts 50-259/82-10, 50-260/82-10 & color of the lies Repts 50-259/82-10, 50-260/82-10 by of procedures Manual NB2A3 will not be revised wintil 821001 due to scope of effort involved MILLS.L M Tennessee Valley Authority 82/08/18 O'REILLY, J P Region 2 Office of Director ip 15778 106 24X Fiche 50-259, 82/08/18 8210220151
- 5210010035 Confirms 820908 site meeting to discuss recent violations re raduaste shipments Agenda encl g'REILLY J P Regian 2. Office of Director 82/09/03 PARRIS.H & Tennossee Valley Authority 2pp 15565 166 24X Fiche 50-259.82/09/03.8210010035
- #210010430 Forwards IE insp Repts 50-259/82-25, 50-260/82-25 on 820810-11 No noncompliance nated VERRELLI.D M Division of Project & Resident Programs #2/09/6/PARRES.H & Tennessee Valley Authority 2pp 15570 211 24X Fiche 50-259, 62/09/03, 8210010430 82/09/03
- -6210010432 IE Jnsp Repts 50-259/82-25.50-260/82-25 & 50-296/82-25 on 820910-11 No noncompliance noted Major areas inspected reactor secondary containment integrity problem & MSIV testing BRCCAS.E H . JAPE.F Division of Engineering & Technical Programs 82/08/27 4pp 15570 213 24% Fiche 50-259,82/09/03.8210010430
- 8210150399 Forwards IE Insp Repts 50-259/82-28,50-260/82-28 & 50-296/82-28 on 820830-0903 No noncompliance noted VERRELLI, D.M. Division of Project & Resident Programs 82/09/. PARRIS.H G. Tennessee Valley Authority 2pp 15704 029 24X 82/09/20 PARRIS, H Q Fiche 50-259, 82/09/20, 8210150399
- elulau4u8 IE Insp Repts 50-259/82-28, 50-260/82-28 & 50-296/82-28 on 820830-0903 No noncompliance noted Major areas inspected inservice insp program & inservice testing program review OIRARD, E H. BLAKE, J. Division of Engineering & Technical Programs 82/09/16 4pp 15704 031 24X Fiche 50-259,82/09/20,8210150399 --8210150405 IE Insp Repts 50-259/82-28,50-240/82-28 & 50-294/82-28 on
- 02:00:0077 Approves revised commitment dates for Item 25 of App C to IE Ensp Repts 50-259/81-19.50-260/81-19 & 50-296/81-19 & 1tem C 2 of App A to IE Insp Repts 50-259/82-12.50-260/62-12 & 50-296/82-12 LEWIS.R C Division of Project & Resident Programs 82/ PARRIES.H G Tennessee Valley Authority 1p 15565 001 Fiche 50-259:82/09/22:8210010097
- --8210010104 Requests extension to respond to App C. Item 25 in IE Insp Repts 50-259/81-19.50-260/81-19.50-296/81-19. \$1 tem C. 2 in IE Insp Repts 50-259/82-12.50-260/82-12. \$50-296/82-12. Responses will be submitted by 830101 & 821101.respectively HILLS.L. M. Tennessee Valley Authority 82/09/01 0'REILLY.J.P. Region 2. Office of Director 1p 15565 002 24X Fiche 50-259.82/09/22,8210010097

- 8210010326 Forwards summary of 820708 enforcement meeting w/util to 210010326 Forwards Summary of H20700 enforcement meeting W7011 to discuss corrective actions re leakage during shipment of low level waste & util plans for improving employee training O'REILLY.JP Region 2. Office of Director 82/07/22 PARRIS.H G Tennessee Valley Authority 4pp 15567 188 24X Fiche 50-259, 82/09/22, 8210010326
- 8210010270 Ack receipt of supplemental 820901 ltr informing NRC of steps taken to correct Violation B noted in IE Insp Repts SO-259/81-26, 50-260/82-26 & 50-296/81-26 LENIS.R C Division of Project & Resident Programs 82/09/24 PARRIS.H G Tennessee Valley Authority 1p 15573 183 24X Fichs 50-259, 82/09/24, 8210010290
- --8210010304 Farwards revised response to NRC 811028 ltr re Violation B noted in IE Insp Repts 50-259/82-26,50-260/82-26 & 50-296/82-26 Corrective actions R factor returned to within limits & revision to Tech Spec approved MILLS.L M Tennessee Valley Authority B2/09/01 O'REILL' Region 2. Office of Director 3pp 15573 184 24X Fiche 50-259, 82/09/24, 8210010290
- 8210220390 Forwards IE Insp Repts 50-259/82-29, 90-260/82-29 & 50-296/82-29 on 820906-10 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/09/3PARRISH O Tennessee Valley Authority 2pp 15779 220 24X Fiche 50-259, 82/09/30,8210220390 82/09/30
- --8210220401 IE Insp Repts 50-259/82-29,50-260/82-29 & 50-296/82-29 on 820906-10 No noncompliance noted Major areas inspected Unit 2 refueling & maint outage & procedural compliance of health physics-related practices by workers COLLINS.T R . BARR.K P Division of Engineering & Technical Programs 82/09/27 5pp 15779 222 24X Fiche 50-259,82/09/J0,8210220390
- 8210080219 Forwards revised request for relief from Inservice Insp / re naccessible welds in piping penetrations & under rigid pipe restraints Best effort visual exam will be performed during sys hydrostatic pressure test MILLS.L M Tennesses Valley Authority 82/10/0 Office of Nuclear Reactor Regulation, Director 24X Fichs 50-259,82/10/04,8210080219 82/10/04 DENTON H R irector 3pp 15638 0
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB,L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 1576 24X Fiche 50-000,82/10/06,8208190233
- 8210150218 Forwards update of present work & schedule for implementation of imaps required under IE Bulletins 79-02 & 79-14 Phase II evaluation will not be completed until 640801 MILLS, L.M Tennessee Valley Authority 82/10/07 C Region 2, Office of Director 2pp 15705 276 24X Fiche 50-259, 82/10/07, 8210150218 D'RETLLY, J.P.
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Mall. Large-Diameter. Stainless Steel. Rectroulation Sys Piping at BMR Plants "Syc list encl. DEYGUNO.R C Director's Offics. Offics of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fichs 50-000. 82/10/14/8208190238
- S Reportable occurrences. LERs & related correspondence
- 8210120127 Advises of need for in-depth evaluation of potential for unacceptable interaction between control rod drive sys & nonessential control air sys Margin of safety inherent in licensed design basis should be promptly restored MICHELSON.C Director's Defice 80/08/18 DENTON.H R Office Nuclear Reactor Regulation. Director 3pp 15692 150 24X Fichs 50-296,80/08/18.8210120129 Office of
- B210070470 Discusses B10406 deliberate pump trip Control switchen manipulated for two trains of circulating water sys resulting in pump trip FBI & util investigations failed to find culprit Event listed in safeguerds watch list LANNING, W D. Director's Office. 81/06/24 Director's Office. Ip 15644 358 24% Fiche: 50-260, 81/06/24, 8210070490
- 821001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Korwards documents listed in App A. FELTON.J. M Division of Rules and Records. 82/06/28 UDELL.R. A Critical Mess Energy Project 15pp 15727.005 24X Fiche-50-000.82/06/28.8210010008

- --Bi07i60079 Informs that manipulation of control switches for two trains of circulating water sys resulted in tripping of two circulating water pumps located in intake structure FBI investigated & found no evidence of who operated switches LAWNING:W D Director's Office Bi/06/24 Director's Office p 15727 250 24% Fiche 50-000.82/06/28.8210010008
- --8210260353 LER 82-029/03L-0 on 820921, pinhole leak discovered in 3-inch fire protection line supplying water to cable-tray fixed water spray sys Caused by through-wall pitting corresion attack Ultrasonic testing to be done by 830201 MECKEISEN.T Tennessee Valley Authority 82/10/19 Region 2, Office of Director 2pp 15802 348 24X Fiche 50-260,82/10/19, 82/0260349
- 8210260417 Forwards LER 82-028/03L-0 GREEN.H J Tennesses Valley Authority 82/10/19 O'REILLY, J P Region 2. Office of Director 1p 15806 150 24X Fichs 50-260-82/10/19,8210260417
- ~-8210260446 LER 82~028/02L-O on 820921, during refueling, turbine to reactor bldg doors 237 to 238 opened simultaneously, breaking secondary containment Caused by Folger Adams interlock sys faiture due to loose door latch screws TAYLOR.D Tennessee Valley Authority 82/10/17 Region 2, Office of Director 2pp 15806 151 24X Fiche 50~260,82/10/17, R210204417
- T Hearing transcripts on non-antitrust matters
- 8210070133 Testimony of JW Hutton answering ASLAN questions on low level radwaste mgt aptions Availability of adequate space to dispose of low level wastes in next 5 yrs uncertain Certificate of Svc encl HUTTON, J W Tennessee Valley Authority 82/10/01 12pp 15627 031 24% Fiche 50-25%,82/10/01.0910070133
- DOCKET 50-261 H D ROBINSON PLANT, UNIT 2

  F Security, medical, emergency & fire protection plans
- 8210250202 Forwards acenario for 821014 small-scale emergency preparedness exercise
  ZIMMERNANAS R Carolina Power & Light Co 82/09/02 STOHR, J P
  Division of Emergency Preparedness & Operational Support 5pp
  15788 272 24X Fiche 50-261,82/09/02.8210250202
- 8210150396 Forwards IE Insp Rept 50-261/82-29 on 820816-19 No noncompliance noted LEWIS.R C Division of Project & Resident Programs 82/09/17 JONES. J A Carolina Power & Light Co 2pp 15704 035 24x Fiche 50-261, 82/09/17, 8210150394
- --9210150401 IE Insp Rept 90-261/82-29 on 820616-19 No noncompliance noted Major areas inspected reducingical emergency preparedness CLINE.W E . JENKINS. 6 R Division of Emergency Preparedness & Operational Support 82/09/14 15pp 15704 037 24X Fiche 50-261.82/09/17.8210130396

- --8210060354 "Radiation Shielding Analysis for HB Robinson Fechnical Support Ctr/Emergency Operating Facility " BRODE.R W . NATHAN.S J . SCHMIDT.E R NUS Corp RUS-4154 B2/06/30 54pp 15419 134 24% Fichs 50-241.82/10/04.8210080145
- H General correspondence
- 8210010028 Requests NRC direct all official correspondence to Eh Utle, util vice-president due to 820930 retirement of JA Jones JONES, JA Carolina Power & Light Co. 82/09/27 DERTON, H R Office of Nuclear Reactor Regulation, Director 1p 15565-314 24 Fiche 50-000, 82/09/27, 8210010028
- 8210130323 Requests changes to distribution list for NUREC-0020. "Licensed Operating Reactors Status Summary Rept "
  21MMERMAN,S R Carolina Power & Light Co 82/10/11 BETBE.M P
  APP Systems Development Branch 2pp 15683 361 24X
  Fiche 50-000,82/10/11.8210130323
- P Operating license stage documents & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of into re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Elemption 5) FELTON, J H Division of Rules and Records 82/07/12 Up&LL, R A Critical Mass Energy Project 9pp 15655 027 24X Fichs 50-000, 82/07/12,8210080015
- --8106220165 Provides results of discussion w/licensee re apparent problem u/proper sealing of containment purge valves. Licensee estimated that excessive leakage condition occurred at frequency of one time for every five valve cycles. BANCE:H C. Region 2, Atlanta. Office of the Director. 7H/10, 27 JURPAN.E.L. Division of Reactor Operations Inspections. 2pp. 15668-165. 24X Fiche 50-000, 87/07/12, 82(10080015).
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B
  FELTON.J K Division of Rules and Records 82/08/10 (QMS, D J Winthrop, Stimson, Putnam & Roberts 9pp 15643-063 24X Fiche 50-000, 82/08/10-0210070007
- B207180044 FOIA request for all internal non-public documents, means, evaluation repts & other mati dealing w/nuclear plant operations
  MCINNIS.B News & Observer 82/08/17 Office of Administration 15 15860 064 24X Fiche 50-000.82/08/17, 8207180044
- 8210280013 Responds to FOIA request for all internal non-public documents, memos, evaluation repts & other math dealing w/ nuclear plant operations Forwards documents listed in App A FELTON, J R Division of Rules and Records B2/09/17 HCRNNIH D News & Observer Spg 15860 065 24X Fiche 50-000, 82/09/17, B210280013
- --7908130654 Recommends licensee be requested to submit solid waste process control program & offsite dose calculation manual to aid in timely review of radiological effluent Tech Speca Forwards guidelines

  COLLING, J T Effluent Treatment Systems Branch 79/06/21

  SCHMENCER, A Operating Reactors Branch 1 (Pre 79/030) 10pp
  15860 092 24X Fiche 50-000,82/09/17.82(0280013
  - 1107010140 Marked-up memo re 810323 engineering evaluation rept bn 810127 RCS leak Event & recommendations will be taken into consideration for further evaluation Info has been transmitted to utils DENTON. H R Office of Nuclear Reactor Regulation, Director 81/06/15 MICHELSON, C Director's Office 2pp 15860 229 24 Fiche 50-000,82/09/17.8210280013
  - | 108270422 Notifies that util B01201 request for license agent gas spent fuel pool storage expansion is acceptable Safety evaluation to EIA imput encl KREQER, W E Assistant Director for Radiation Protection B1/07/23 NDVAK.T Assistant Director for Operating Reactors 6pp 15860 240 24X Fichs 50-000, 82/09/17. \$210280013
  - 3112020852 Forwards input to safety evaluation & EIA of proposed 5.5 fuel pool storage capacity expansion Evaluation & appraisal based on info provided in 801201 ltr Proposed mod acceptable HOUSTON, R H. Accident Evaluation Branch, 81/11/17, VARGA, S. Operating Reactors Branch in 3pp 15860 246 24K Fiche, 50-000, 827.97/17, 8210280013

- --0201200658 Forwards technical evaluation of deviation in licensee B10303 response to requirements of NURGO-0737 Item II F 1-1 Yechnical evaluation should be forwarded to licensee for justification of deviations MREGER. W E Assistant Director for Radiation Protection 81/12/15 NOVAK.T M Assistant Director for Operating Reactors 2pp 15860 265 24% Fiche 50-000.82/09/17.8210280013
- --8201200662 "Add) Accident Monitoring Instrumentation." technical evaluation of response to Attachment 1 of Item II F 1 of NUREC-0737 Tup major deviations from requirements unacceptable HUCHTON,8 L Exxon Nuclear Co . Inc (subs of Exxon Corp) 81/(1/02 8pp 15860 767 24% Fiche 50-000.82/09/17.8210280013
- 8203220514 Forwards safety evaluation 5 EIA supporting util 820128 request to allow use of circulating water pump discharge flow as backup source for dilution in calculating radioactive liquid effluent release when pump out of syc HOUSTON. R W Assistant Director for Radiation Protection 82/02/26 NOVAK, T M Assistant Director for Operating Reactors 7pp 15861 017 24X Fiche 50-000.82/09/17.8210280013
- ~-6205050480 Forwards audit of procedures & training for pressurized thermal shock Control room emergency procedures remain weighted toward core cooling & do not go far enough in addressing pressurized thermal shock issue MAZETIS, G R NRC No Detailed Affiliation Given 82/04/15 THOMPSON, H & Division of Human Factors Safety 38pp 15861 045 24% Fiche 50-000,82/09/17,8210280013
  - 8209150106 Provides requested add1 info re 820730 power aperated relief valve block valve failure Maint errors made during previous activities listed BRGUNLE J. LANNING W D. Reactor Operations Analysis Branch 82/08/25 SEYFRIT.K V. Reactor Operations Analysis Branch 15861-344 24X Fiche 50-000, 82/09/17,8210280013
- --0210283042 Responds to encl E Urtey 781229 request for extension to submit draft effluent Tech Specs Request unacceptable Util reason for extension not valid Draft Tech Specs must be submitted by 790215

  COLLINS, J T Effluent Treatment Systems Branch 79/01/08
  SCHWENCER, A Operating Reactors Branch I (Pre 791030) 1p 15860 089 24X Fishe 50-000, 82/09/17.0210280013
- --8210280082 "Dosimetry Placement for Steam Generator Workers " MARNOCK.R Institute of Nuclear Power Operations 82/01/31 13pp 15860 310 24% Fiche 50-000.82/09/17.8210280013
- 6210010051 Ack receipt of 820823 ftr requesting temporary relief from consistents re-training of shift technical advisors Program approved & request forwarded to URR for evaluation G'REILLY, J P. Region 2, Office of Director 82/09/20 JONES, J A Carolina Power & Light Co. 1p. 15565-322 24X
  Fiche 50-000, 82/09/20, 8210010051
- 8210290197 Requests add1 info documenting how each criterion of fUREG-0737. From II B 3, "Post-Accident Sampling Bys" has been satisfied, in order to conduct post-implementation review Schedule requested within 20 days VARGA. S A Licensing Branch | 82/09/24 JONES J A Carolina Power & Light Co 10pp (5876 247 24X Fiche 50-261,82/09/24,8210290197
- 82:10050009 Advises that response to 820318 request for add1 info re NUREG-0737. Item II B I. "RCS Vents." will be submitted 6 months before end of first refueling scheduled to begin in Dec 1983
  EURY,L II Carolina Power & Light Co 82/10/01 VARGA, 8 A Operating Reactors Branch 1 ip 15605 192 24X
  Fiche 50-261, 82/10/01.8210050009
- 0210060013 Application to amend License DPR-23 consisting of revision to Tech Specs providing three auxiliary feedwater pumps operable prior to exceeding RCS temp of 350 F EURY.L W Carolina Power & Light Co 82/10/01 VARGA, S A Operating Reactors Branch 1 2pp 15615 074 24X Fiche 50-261, 02/10/01, 0210060013
- ---8210060016 Proposed revision to Tech Apecs providing three auxiliary feedwater pumps operable prior to exceeding RCS temp of 350 F \*\* Carolina Power & Light Co 82/10/01 5pp 15615 076 24X Fiche 50-261,82/10/01,8210060013
- 8210150264 Forwards add1 info re plant-specific homogeneous number densities for maths & fluid in reactor vessel core region, per 820917 request for info re pressurized thermal shock ZIMMERIMAN.S R Carolina Power & Light Co 82/10/07 VARGA.S A Operating Reactors Branch i 7pp 15703 254 24X Fiche 50-261,82/10/07.8210150264

- 8210150198 Responds to 820707 request for rept documenting pressurizer power operated reliaf valve & pressurizer safety valve failures per NUREG-0737. Item II K 3 3 No failures or challenges identified from 810401 to present ZIMMERHAN. 8 R Carolina Power & Light Co 82/10/08 VARGA. 8 A Operating Reactors Branch 1 2pp 15707 271 24X Fiche 50-261.82/10/08.8210150198
- 8210190707 Forwards "Supplemental Info for Degraded Grid Voltage Analysis CP & L.HB Robinson Nuclear Generating Station Unit 2" (n response to 61031 request re adequacy of electrical distribution sys voltage EURY.L W Carolina Power & Light Co 82/10/14 VAROA 8 A Operating Reactors Branch 1 3pp 15737 287 24X Fiche 50-261.82/10/14.8210190709
- --8210190720 "Supplemental Info for Degraded Orid Voltage Analysis, CP&L, HB Robinson Nuclear Generating Station Unit 2 " MARAYANI, I V , FIELDS, W W , CASEY, B J Ebasco Services, Inc (subs of Enserth Carp ) 82/09/30 209pp 15737 290 24X Ficho 50-261, 82/10/14, 8210190709
- 8210260475 Application to amend License DPR-23, revising Tech Specs to clarify in-place testing criteria used on safety-related HEPA filter sys & compliance w/more recent ANSI std EURY, L. W. Carolina Power & Light Co. 82/10/22 VARGA, 8 A Operating Reactors Branch 1 2pp 15806 228 24X Fiche 80-261,82/10/22,8210260475
- --8210260482 Proposed Tech Spec changes clarifying in-place testing criteria used on safety-related HEPA filter sys & compliance w/more recent ANSI std & Carolina Power & Light Co 82/10/22 2pp 15806 230 24% Fiche 50-241,82/10/22.8210260475
- 8210260508 Application for amend to License DPR-23, revising Tech Spec to clarify limiting conditions of operation for pressurizer code safety valves EURY,L W Carolina Power & Light Co 82/10/22 VARGA, S A Operating Reactors Branch 1 2pp 15805 133 24X Fiche 50-261,82/10/22,8210260508
- --8210260511 Proposed Tech Spec 3 1 1 3 re pressurizor code safety valves \* Carolina Power & Light Co 82/10/22 1p 15805 135 24X Fiche 50-241, 82/10/22, 8210260508
- 8210270358 Requests extension until 821215 for submittal of schedule re TMT Item II II 3, "Post-Accident Sampling Sys" NRC 820724 request for add info significantly expanded scope of work ZIMMERMAN.S R Carolina Power & Light Co 82/10/26 VARGA.S A Operating Reactors Branch 1 ip 15853 047 24X Fiche 50-261.82/10/26.8210270358
- O Inspection reports, IE Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 82/08/10 LONG, D. J Winthrop, Stimson, Putnam & Roberts 9pp 19645 063 24X Fiche 30-000, 82/08/10,8210070007
- --B21007013F Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch 92/04/01 VARQA.6 Operating Reactors Branch 1. 5pp 15645 131 24X Fiche 50-000, 82/08/10.8210070007
- --8210070172 Forwards info re steam generator integrity & inaps at all operating PMRs.per 750320 & 21 requests Details of inaps. including defect indications tube plugging criteria & tubes plugged will not be provided except for Point Beach 1 GOLLER,K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MAGCARY.R R Division of Technical Review (NRR-1975 only) 3pp 15645 196 24X Fiche 50-000.82/08/10.8210070007
- 8210010173 Forwards 1E insp Rept 50-261/82-30 on 920810-12 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 62/09/08 JONES,J A Carelina Power & Light Co 2pp 15568 132 24X Fiche 50-261,82/09/08
- --B210010176 IE Insp Rept 50-261/B2-30 on B20B10-12 No noncompliance noted Major areas inspected post-refueling startup tests & closeout of earlier enforcement item BURNETI.P T , JAPE,F Division of Engineering & Technical Programs B2/09/02 6pp 1556B-134 24X Fiche 50-261, B2/09/0B, B210010173

- 8210190396 Forwards IE Insp Rept 50-261/82-29 on 820816-19 No noncompliance noted LEWIS.R C Division of Project & Resident Programs 92/09/11 JONES.J A Carolina Power & Light Co 2pp 15704 035 24X Fiche 50-261, 82/09/17, 8210150396
- --8210150401 IE Insp Rept 50-261/82-29 on 820816-19 No noncompliance noted Major areas inspected radiological emergency preparedness CLINE,W E, JENKINS,G R Division of Emergency Preparedness & Operational Support 82/09/16 15pp 15704 037 24X Fiche 50-261.82/09/17,8210150396
- 8210150493 Requests addl info re util response to IE Bulletin 80-ii. "Masonry Wall Design " Info required by 821122 to complete review VAROA.S A Operating Reactors Branch 1 82/10/04 JONES. J A Carolina Power & Light Co 4pp 15717 271 24X Fichs 50-261.82710/04.8210150493
- 8208190233 IE Info Notice 80-35, Suppl 1. "Leaking & Dislodged I-125 Implant Seeds " Svc list enc! CDBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York & App 15761 250 24X Fiche 50-000,82/10/06.8208190233
- 8208190238 IE Bullotin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diamster, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consultated Edison Co of New York 115ps, 15810 125 24X Fiche 50-000, 62/10/14,8208190238
- 8210220495 Ack receipt of 821008 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/82-27 LEWIS,R C Division of Project & Resident Programs 82/10/18 UTLEY,E E Carolina Power & Light Co ip 13779 009 24X Fiche 50-261,82/10/18,8210220495
- --B210220499 Responds to NRC 820708 ltr re violations noted in IE Insp Rept 50-261/82-27 Corrective actions changes to plant operating menual included in permanent change book & operations revisions status list updated tudce weekly STARKEY.R B Carolina Power & Light Co 82/10/08 O'REILLY, J P Region 2. Office of Director 4pp 15779 010 24X Fithe 50-261,82/10/18.8210220495
- --8210220300 Forwards IE Insp Rept 90-241/82-27 on 820711-0810 & notice of violation LEXIS,R C Division of Project & Resident Programs 82/09/08 JONES, J A Carolina Power & Light Co 2pp 13779 014 24X Fiche 50-241,82/10/18,82102280495

- 8210190240 Forwards updated LER 80-027/01T-1 STARKEY, R B Carolina Power & Light Co 82/10/11 O'REILLY.J P Region 2: Office of Director 1p 15742 176 24X Fiche 50-261: 82/10/11.8210190240
- --8210190244 Updated LER 80-027/01T-1 on 801122.relay RT-9 in reactor protection train A failed to re-energize during periodic test of reactor protection logic Caused by Shorting of lead usire connection to coll wires Relay replaced CDX.ff T Carolina Power & Light Co 82/10/11 Region 2. Offic of Director 4pp 15742 197 24X Fiche 50-261.82/10/11,
- 8210290074 Forwards updated LER 81-031/01T-1 STARKEY,R B Carolina Power & Light Co 82/10/22 O'REILLY,J P Region 2, Office of Director 1p 15854 028 24X Fiche 50-261.82/10/22.8210290074
- --821029007B Updated LER 81-031/01T-1 on 811201 during hot shutdoun.
  pressurfirer PDRV block valve operators did not fully shut
  block valves Caused by improper maint Valves closed
  nanually
  CDX.H T Carolina Power & Light Co 82/10/22 Region 2. Off
  of Director 3pp 15854 029 24X Fiche 50-261,82/10/22.
- 8210290333 Forwards LER 82-013/03L-0 STARKEY.R B Carolina Power & Light Co B2/10/22 O'REILLY.J P Region 2, Office of Director 1p 15853 103 24X Fiche 50-261,82/10/22,8210290333
- --8210270337 LER 82-013/03L-0 on 820923.svc water pump A failed to restart following periodic test Caused by failed control power fuses fuses replaced & pump started & retested COX.H T Carolina Power & Light Co 92/10/22 Region 2, Offic of Director 2pp 15853 104 24X Fiche 50-261.82/10/22, 8210270333

DOCKET 50-269 MONTICELLO NUCLEAR GENERATING PLANT

- F Security, medical, emergency & fire protection plans
- 8210150385 Forwards IE Insp Rept 50-263/82-09 on 820703-0828 No noncompliance noted STREETER, J F Division of Project & Resident Programs 62/09/28 LARSON, C E Northern States Power Co 2pp 15703 272 24X Fiche 50-263, 82/09/28, 8210150385
- --8210150386 IE Insp Rept 50-263/82-09 on 820703-0828 No noncompliance noted Major areas inspected LER followup.operational safety verification.fire protection/prevention security personnel qualifications.operator overtime & onsite review committee BROWN.C H. MADDEBUNA L. WALKER.R D. Division of Project & Resident Programs 82/09/28 5pp 19703 274 24% Fiche 50-263,82/09/28,8210150385

- --8210010046 Proposed Tech Specs re surveillance, reactor protection monitoring sys, jet pump surveillance, organization & steam line area temp switch deviation # Northern States Power Co 82/09/24 40pp 15565 183 24X Fiche 50-264,82/09/24,8210010030
- --0210060380 Application for amend to License DPR-22. App A Amend changes Pages 207 & 209 to remove 3-cycle per minute min source range monitor count rate when two or fewer adjacent assemblies exist in quadrant MUSQLF.D Northern States Power Co 82/09/30 4pp 15615 341 24X Fiche 50-263, 82/09/30.8210060377
- --8210060386 Proposed Tech Specs 3/4 10.removing 3-cycle per minute min source range monitor count rate when two or fewer adjacent assemblies exist in quadrant 4 Northern States Power Co 82/09/30 2pp 15615 345 24X Fishe 50-263,82/09/30,8210060377
- GE10130260 Discusses implementation of NRC quidelines for working hours, provided in Generic Ltr 82-12 Revised guidelines have been implemented, w/exceptions of 72-h per wk limitation & relief from control board duties

  MUSQLEF, D. Northern States Power Co. 82/10/07. Office of Nuclear Regulation, Director. 2pp. 15676-012. 24X

  Fiche 50-000, 82/10/07, 8210130260
- 8210150364 Forwards response to request for info in Sections 2 2 % 2 3 of Generic Ltr 81-07 re overhead handling sys Revised 9 month submittal, "Control of Heavy Loads" & review of special lifting devices also encl MUSDLF.D Northern States Power Co 82/10/11 Office of Nuclear Reactor Regulation. Director 16p 19715 102 24X Fiche 50-263.82/10/11.8210150364
- --BRIO150377 "Evaluation of Conformance w/NUREG-0612 for Drywell/Reactor Vessel Head & Dryer/Separator Sling Lifting Devices " SHITH: St N. VUGEL: N NUTECH (Nuclear Technology, Inc.) K49-77-008 82/09/29 14pp 15715 118 24X Fiche 50-263,82/10/11.8210150364
- --8210150500 "Design Spec for Reactor Vessel Head Lifting Device "
  FISCHER.L., VOGEL, T.N., SMITH, J.K. NUTECH (Nuclear Technology,
  Inc.) NSP-77-001 R00 82/07/24 9pp 15715 132 24X
  Fiche 50-263,82/10/11.8210150364
- --8210150504 "Evaluation of Selected Special Lifting Devices for Compliance w/NUREG-0612 " SMITH.J K., VOSEL.T N. NUTECH (Nuclear Technology, Inc.) NSP-77-007 ROO 82/09/24 12pp 15715 141 24X Fiche 50-263,82/10/11,8210150364
- --8210150509 "Design Spec for Dryer & Steam Separator Sling Lifting Device " FISHER.L. VOCEL.T N. SMITH.J K NUTECH (Nuclear Technology, Inc.) NSP-77-003 ROO 82/09/24 9pp 15715 153 24X Fiche 50-263.82/10/11.8210150364
- 6210190479 Informs that control room & technical support ctr habitability sys mod.per NUREO-0737. Item II D 3 4 will be delayed until 830515 due to need for design work untimely mati delivery & low productivity Revised schedule encl MUSOLF. D Northern States Power Co 82/10/13 Office of Nuclear Reactor Regulation, Director 3pp 15740 263 24X Fiche 50-263.82/10/13.8210190479
- 8210250320 Confirmatory action ltr relections util will undertake as result of 821014 meeting at Region 3 ofc relectack indications found on welds on recirculation syspiping KEPPLER, J O Region 3, Office of Director 82/10/19 LARBON, C E Northern States Power Co. 2pp 15790 224 24X Fiche 50-263, 82/10/19, 8210250320

- 8210260209 Forwards check to complete fee payment for Addendum 1 to 801010 license amend request MUSCLF, D Northern States Power Co 82/10/22 DIGOS,R M License Fee Management Branch 1p 15799 152 24X Fiche 50-263,82/10/22,8210260209
- O Inspection reports, IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15645 027 24X Fiche 50-000,82/07/12.8210080015
- -8105280476 Requests that regions confirm licenses submittal of rept for satisfactory implementation of Itam 4 of IE Bulletin 79-26. Revision 1
  JORDAN, E. Division of Resident & Regional Reactor Imspection 81/05/18 GRIER, B.H. Region 1. Philadelphia, Office of the Director (81/03/01) O'REILLY, J.P. Region 2. Atlanta, Office of the Director (81/03/01) INEPLEX, J.G. Region 3. Chicago, Office of the Director (81/03/01) Ip 15668 ISO 24X Ficha 50-000,82/07/12,8210080015
- 82101503BB Forwards IE Insp Rept 50-263/82-09 on 820703-0828 No noncompliance noted STREETER.J F Division of Project & Resident Programs 82/09/28 LARSDN.C E Northern States Power Co 2pp 15703 272 24X Fiche 50-263.82/09/28.82101503BS
- --8210150386 IE Insp Rept 50-263/82-07 on 820703-0828 No noncompliance noted Major areas inspected LER followup.operational safety verification, fire protection/prevention, security personnel qualifications, operator overtime & onsite review committee BROWN.C H. MADISON, A L. WALKER.R D. Division of Project & Resident Programs 82/09/28 Spp 15703 274 24X Fiche 50-263,82/09/28,8210150385
- 8210130166 Confirms plans for 821014 meeting in Olen Ellyn, IL to discuss proposed corrective action for cracks in welds on endcap of recirculation Loop A SPESSARD, R L Division of Project & Resident Programs 82/10/05 LARSUN.C E Northern States Power Co ip 15673 053 24X Fiche 50~263.82/10/05.8210130166
- 9209190233 IE Info Notice 80-35, Suppl 1. "Leaking & Dislodged I-125 Implant Beeds " Svc list encl CUBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761.280 24% Fiche 50-000, 62/10/06, 8209190233
- 8208190238 IE Bulletin 8R-03, "Stress Corrosion Cracking in Thick-Walls Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list encl DEYOUNG, R C Director's Office, Defice of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fichs 50-000, 82/10/14.8208190238
- 82:0250320 Confirmatory action ltr re actions util will undertake as result of 82:014 meeting at Region 3 ofc re crack indications found on welds on recirculation sys piping KEPPLER. J O. Region 3. Office of Director 82:10/19 LARSON. C E Northern States Power Co. 2pp 15790 224 24X
- 8 Reportable occurrences, LERs & related correspondence
- 8210150174 Forwards LER 81-020/03L-0 MAYER.L O Northern States Power Co 81/08/24 KEPPLER,J O. Region 3, Chicago Office of the Director (81/03/01) ip 18707 193 24X Fiche 30-263.81/08/24.8210150174
- --8210150180 LER 81-020/03L-0 on 810724, main steam leak revealed in drain line to condenser Caused by piping leaking immediately downstream of 45 degree elbow due to prosion & impingement resulting from steam & water flow from restricting orifice.
  TOBIN.F A Northern States Power Co 81/08/24 Region 3, Chicago, Office of the Director (81/03/01) ip 13707 174 24% Fiche 50-263,81/08/24,8210130174.
- 8210050182 PNO-III-82-103 on 820928, radiographs of recirculation loop cap A revealed four cracks extending from weld root into adjacent heat-affected zone No through-wall cracking evident Repair procedures under evaluation WALKER, R. JORDAN, M. Region 3, Office of Director 82/09/28 lp. 13603 344 24% Fiche 50-263,82/09/28,8210050182

- 8210150396 Forwards IE Insp Rept 50-261/82-29 on 820816-19 No noncompliance noted LEMIS:R C. Division of Project & Resident Programs 82/09/17 JONES:JA Carolina Power & Light Co 2pp 15704 035 24X Fichs 50-261:82/09/17:8210150396
- --8210150401 IE Insp Rept 50-261/82-29 on 820816-19 No noncompliance noted Major areas inspected redibliogical energency preparedness CLINE W E . JENNING B R Division of Emergency Preparedness & Operational Support 82/09/16 19pp 15704 037 24% Fiche 50-261,82/09/17,8210150396
- B20Bi90233 IE Info Notice 80-35. Suppl 1. "Leaking & Disiodged I-125 implant Seeds " Bvc list enc! COBUL 1 Division of Fuel Factities. Materials & Bafeguards B2/10/06 Consolidated Coison Co of New York 65pp 15761 250 24X Fiche 50-000.82/10/06.820Bi90233
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Hall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Syc list encl BEYDUNG!R C Birector's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- B210220495 Ack recript of 821008 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/62-27 LEWIB.R C Division of Project & Resident Programs 82/10/18 UTLEV.E E Carolina Power & Light Co ip 15779 009 24X Fiche 50-261.82710/18.8210220495
- --8210220499 Responds to NRC 82090B ltr re violations noted in IE Insp Rept 50-261/82-27 Corrective actions changes to plant operating namual included in permanent change book & operations revisions status list updated twice weekly STARKEY,R B Carolina Power & Light Co 82/10/09 D'REILLY, J P Region 2. Office of Director App 15779 010 24X Fithe 50-261, 82/10/18,8210220495
- --8210220500 Forwards IE Insp Rept 50-261/82-27 on 820711-0810 & notice of violation LEMIS,R C Division of Project & Resident Programs 82/09/08 JONES,J A Caroline Power & Light Co 2pp 15779 014 24X Fiche, 50-261,82/10/18,8210220495
- --B210220501 Notice of violation from insp on 820711-0810 & Division of Project & Resident Programs 62/09/08 2pp 15779-016 24X Fisha 50-261-82/10/18-8210220495
- --8210220504 IE Insp Rept 50-261/82-27 on 820711-0810 Noncompliance nated adequate review procedures not implemented for Maint Procedure MPS-10 for safety-related instrument valve itneups.

  WEISE, 8. BURGER, C. Division of Project & Resident Programs 82/09/02 IEPP. 13779 OIB 244 Fiche 50-261-82/10/18,8210220495
- R Periodic operating reports & related correspondence
- 9210130242 Forwards monthly operating rept for Bept 1982 STARKEY, R B Carolina Power & Light Co 92/10/08 DEYOUNG, R C Ulrector's Uffice, Office of Inspection and Enforcement 19 15678 096 24X Fichs 50-261.82/10/08.8210130242
- --8210130244 Monthly operating rept for Sept 1982 NORRIS.H.R. Carolina Power & Light Co. 82/10/05 3pp 15678 097. 24% Fichs: 50-261.82/10/08.8210130242
- S Reportable occurrences. LERs & related correspondence
- 8210220265 Forward; LER 82-012/03L-O.
  STARKEY,R. B. Carolina Power & Light Co. B2/10/06 D'REILLY.J.P.
  Region 2. Office of Director. 1p. 15775 202 24X
  Fiche 30-261,82/10/06.8210220265
- --8210220267 LER 82-012/03L-0.on 8209D6.at 94% power, letdown relief valve CVC-203 lifted & would not reseat Caused by water hanner que to operator error in realignment of charging pump from recirculation to normal operation. Operator counseled. COX.H. T. Carolina Power & Light Co. 82/10/06 Region 2, Office of Director 3pp 15776 203 24% Fiche 50-261,82/10/06,8210220265.

- 9210190240 Forwards updated LER 80-027/017-1 STARKEY,R B Carolina Power & Light Co 82/10/11 U FEJLL' Region 2, Office of Director ip 15742 196 "44 Fiche 50-261, 82/10/11, 8210190240
- --B210170244 Updated LER B0-027/017-1 on B01102, relay H7 V 30 11 protection train A failed to re-energize during periodic test of reactor protection logic Caused by shorting of [pi] ture connection to coil wires Relay replaced COX.H T Carolina Power & Light Co 82/10/11 Pagics 2 of Director 4pp 15742 197 24X Fiche 30 [Mi] [2/60/1] R210190240
- 821029074 Forwards updated LER 81-031/017-1 5TARKEY, R B Cardina Power & Light Co 62/19/2, 19/41|L' Region 2, Office of Director ip 15854 029 ,41 Fiche 50-261, 82/10/22, 8210290074

- DOCKET 50-263 MONTICELLO NUCLEAR GENERATINO PLANA
- F Security, medical, emergency & fire protection plans
- B210150385 Farwards IE Insp Rept 50-263/82-09 on D20A kir, con noncompliance noted STREETER. J F Division of Project & Resident Programs for LARSON C E Northern States Power Co 2pp 15/0120. 30 Fiche 50-263, 82/09/28, 8210150385
- --8210150386 IE Insp Rept 50-243/82-07 on 820/81 (6.1) to a noted Major areas inspected LER follows, operations is string varification, fire protection/prevention security personal qualifications, operator overtime & onsite levistic-well-security (ROGM), C. H., MADISON, A. L., MALKER, R. B. Division of Free 14 Resident Programs 82/07/28 5pp 15/01 2/4 44 for Fiche 50-243,82/07/28,8210150385
- 8210260178 Requests that R Walker be added to lock 1 (4 ), '1 to provide for unescorted access to vital b proteits area KEPPLER. J O Region 3. Office of Director 02/19. Left Northern States Power Co ip 15799 160 244 likes (5 ) 4. 62/10/20. 8210260198
- P Operating license stage documents & correspondents
- 8210040005 Responds to 820825 htm re-spent fuel roller in the notification requirements of shipments of irradeatie recification requirements of shipments of irradeatie recifical contained in 100FR73 37 MENCERIA B Region 31 Office of Director MacGM/H (4+t) Minnesota, State of 2pp 15577 262 24x higher as to principle 20000005
- 8210010036 Forwards proposed amend to License OPR 23 :Pa:1:13
  Specs in areas of surveillance, reactor protection heritonings sys. Jet pump surveillance, organization & steam lime areas temp switch deviation
  MUSCLE, D. Northern States Power Co. 82/09/24
  Reactor Regulation, Director ip 15565 172 24s
  Fiche: 50-263, 82/09/24, 8210010036.
- m-8210010041 Proposed amend to License DPR-32 changing 18-3 Sp. areas of surveillance-reactor protection menitating bit in pump surveillance-organization & steam line area between suitch deviation HUSDLF, D. Northern States Power Co. 82/09/24 1289 192 24X Fichs 50-263,82/09/24.8210010036

- ~~8210010044 Proposed Tech Specs to surveillance, reactor protection monitoring sys, jet pump surveillance, organization & steam line area temp switch deviation # Northern States Power Co 82/09/24 40pp 15565 183 24X Fiche 50-263, 82/09/24, 8210010036
- 8210060377 Forwards application for amend to License DPR-22.App A Amend changes Pages 207 & 209 to remove 3-cycle per minute min source range monitor count rate when two or fewer adjacent assemblies exist in quadrant MUSOLF. D. Northern States Power Co. 82/09/30 Office of Nuclear Reactor Regulation. Director ip 15615 340 24X Fiche 50-263.82/09/30.8210060377
- --8210060380 Application for amend to License DPR-22. App A Amend changes Pages 207 & 209 to remove 3-cycle per minute min source range monitor count rate when two or fewer adjacent assemblies exist in quadrant MUSCLE. D. Northern States Power Co. 82/09/30 4pp 15615-341 24X Fiche 50-243, 82/09/30, 8210060377
- --8210050386 Proposed Tech Specs 3/4 10 removing 3-cycle per minute min source range monitor count rate when two or fewer adjacent assemblies exist in quadrant + Northern States Power Co 82/09/30 2pp 15615 345 24X Fiche 50-263,82/09/30,8210040377
- 8210]30261 Submits addl info re application for single loop operation license amend in response to NRC 820920 request MAPLHGR reduction factors reviewed by GE & found applicable to Cycle 10 MUSDLF.D. Northern States Power Co 82/10/05 Office of Nuclear Reactor Regulation, Director ip 15676 014 24X Fiche 50-263.82/10/05.8210130261
- 9210130260 Discusses implementation of NRC guidelines for working hours, provided in Generic Ltr 82-12 Revised guidelines have been implemented, w/exceptions of 72-h per wk limitation & relief from control board duties MUSQLF. D. Northern States Power Co. 82/10/07 Office of Nuclear Reactor Regulation, Director 2pp. 15676-012 24% Fiche 50-000.82/10/07.8210130260
- B210150364 Forwards response to request for info in Sections 2 2 % 2 3 of Generic Ltr 81-07 re overhoad handling sys Revised 9 month submittal, "Control of Heavy Loads" & review of special lifting devices also enc!
  MUSULF.D Northern States Power Co 82/10/11 Office of Nuclear Reactor Regulation. Director 16p 15715 102 24X
  Fiche 50-263, 82/10/11.8210150364
- -8210150377 "Evaluation of Conformance w/NUREG-0612 for Drywell/Reactor Vessel Head & Dryer/Separator Bling Lifting Devices " SHITH, St. VOSEL T N NUTECH (Nuclear Technology, Inc.) NSP-77-008 82/09/29 14pp 15715 118 24X Fiche 50-263,82/10/11.8210150364
- --8210150500 "Design Spec for Reactor Vessel Head Lifting Device " FISCHER. L. , VOGEL, T N , SMITH, J K NUTECH (Nuclear Technology, Inc.) NSP-77-001 R00 82/09/24 9pp 15715 132 24X Fiche 50-263,82/10/11.8210150364
- --8210150504 "Evaluation of Selected Special Lifting Devices for Compliance ω/NUREG~0612"

  SMITH.J K. VOSELT N NUTECH (Nuclear Technology, Inc.)
  NSP-77-007 R00 82/09/24 12pp 15715 141 24X
  Fichs 50-263.82/10/11.8210150364
- --8210150509 "Dosign Spec for Dryer & Steam Separator Sling Lifting Device " FISHER, L., VDOEL, T. N., SMITH, J. K. NUTECH (Nuclear Technology, Inc.) NSP-77-003 ROO 82/09/24 9pp 15715 153 24X Fiche 50~263,82/10/11,8210150364
- 8210190479 Informs that control room & technical support ctr
  habitability sys mod.per NVRED-0737. Item II D 3 4 will be
  delayed until 830515 due to need for design works untimely
  mati delivery & low productivity Revised schedule encl
  MUSQLF.D Northern States Power Co 82/10/13 Office of Nuclear
  Reactor Regulation, Director 3pp 15740 263 24X
  Fiche 50-263.82/10/13.8210190479
- 8210250320 Confirmatory action ltr relactions Util will undertake as result of 821014 meeting at Region 3 ofc recrack indications found on welds on recirculation sys piping KEPPLER, J.O. Region 3. Office of Director 82/10/19 LARBON, C.E. Northern States Power Co. 2pp. 15790-224 24X Fichs 50-243, 82/10/19, 8210250320

- 8210260209 Forwards check to complete fee payment for Addendum 1 to 801010 lacense amend request MUSDLF.D Northern States Power Co 82/10/22 DIGOS,R M License Fee Management Branch 1p 15799 152 24% Fiche 50-263,82/10/22, 8210260209
- O Inspection reports. IE Bulletins & correspondence
- B210080015 Addl response to FOIA request for 19 categories of info re nuclear reactor events & safety problems forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records B2/07/12 UDELL,R A Critical Mass Energy Project 9pp 15669 027 24X Fiche 50-000, 82/07/12,8210080015
- ~8105280476 Requests that regions confirm licensee submittal of rept for satisfactory (mplementation of Item 4 of IE Bulletin 79-26. Revision I JORDAN.E.L. Division of Resident & Regional Reactor Inspection 81/05/18 ORIER.B H Region I. Philadelphia. Office of the Director (81/03/01) O'REILLY-J P Region 2. Atlanta, Office of the Director (81/03/01) MEPPLER.J G Region 3. Chicago. Office of the Director (81/03/01) Ip 15668 130 24% Fiche 50-000.82/07/12.8210080015
- 8210150385 Forwards IE Insp Rept 50-263/82-09 on 820703-0828 No noncompliance noted STRECTER, J F Division of Project & Resident Programs 82/09/28 LARSON.C E Northern States Power Co 2pp 15703 272 24X Fiche 50-263, 82/09/28, 8210150385
- --8210150386 IE Insp Rapt 50-269/82-09 on 820703-0828 No noncompliance noted Major areas inspected LER followup, operational safety varification, fire protection/prevention, security personnel qualifications, operator overtime & onsite review committee BROWN.C H , MADISON.A L , WALKER, R D Division of Project & Resident Programs 82/09/28 Spp 15703 274 24X Fiche 50-263,82/09/28,8210150385
- 8210130166 Confirms plans for 821014 meeting in Olen Ellyn, IL to discuss proposed corrective action for cracks in welds on endcap of recirculation Loop A SPESSARD, R L Division of Project & Resident Programs 82/10/05 LARSON, C E Northern States Power Co ip 15673 059 24X Fiche 50-263, 82/10/05.8210130166
- 6209190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Syc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000.62/10/06.8208170233
- 820Bi9023B IE Bulletin 82~03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Bys-Piping at BWR Plants" Svc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 19810, 125 24X Fichs 50~000, 82/10/14, 820Bi9023B
- 8210250320 Confirmatory action ltr relactions util will undertake as result of 821014 meeting at Region 3 ofc relactions found on welds on recirculation sys piping KEPPLER, J O Region 3, Office of Director 82/10/19 LARSON, C E Northern States Power Cd 2pp 15790 224 24X Fiche 50~263, 82/10/19, 8210250320
- 8 Reportable occurrences, LERs & related correspondence
- 8210150174 Forwards LER 81-020/03L-0 MAYERL D Northern States Power Co 81/08/24 KEPPLER, J G, Region J, Chicago, Dffice of the Director (81/03/01) ip 15707 193 24X Fiche 50-263.81/08/24.8210150174
- --8210150180 LER B1-020/O3L-O on 810724.main steam leak revealed in drain line to condenser Caused by piping leaking immediately downstream of 45 degree elbow due to erosion & impingement resulting from steam & water flow from restricting orifice TOBIN.P A Northern States Power Co 81/08/24 Region 3, Chicago, Office of the Director (81/03/01) 1p 15707 194. 24X Fiche 50-263,81/08/24,8210150174
- 8210050182 PNO-III-82-103.on 820928, radiographs of recirculation loop cap A revealed four cracks extending from weld root into adjacent heat-affected lone. No through-wall cracking evident Repair procedures under evaluation WALKER.R., JORDAN.M. Region 3, Office of Director 82/09/28 ip. 15603 044 24% Fiche: 50-263,82/09/28,8210050182.

- 210080117 RD on 820728.crack indication in end cap of A recirculation riser confirmed by radiography Indications initially detected by ultrasonic etam during normal inservice into Remedial measures under investigation SHAMLA.H A Northern States Power Co 82/09/28 KEPPLER.J 9 Region 3, Office of Director ip 15440 204 24X Fiche 50-253, 82/09/28.8210080117
- 210060258 Ferwards LER 82-008/03L-0 MUSDLF.D Northern States Power Ca 82/09/29 Region 3. Office of Director 1p 15621 067 24X Fiche 50-263.82/09/29.8210060258
- -8210060260 LER 82-008/031-0 on 820830.RCIC barameter condenser cooling water supply valve failed Caused by severed stem due to Rotork motor operator torque suitch misadjustment Valve stem replaced WOUCHGUSKI.A V Northern States Power Co. 82/09/29 Region 3, Office of Director ip 15621 968 24X Fiche 50-263,82/09/29, 8210060288
- 210190289 Forwards LER 82-016/017-0 MUSDLF.D Northern States Power Cq 82/10/12 Region 3. Office of Director 1p. 15742 175 24X Fichs 30-263,82/10/12,82(0190289
- -8210190293 LER 82-016/017-0 on 820928, three indications in 22-inch diameter reactor recirculation sys riser manifold end cap confirmed as rejectable Caused by intergranular stress corrosion cracking End cap to be replaced HAMMER, S. Northern States Power Co. 82/10/12. Region 3, Office of Director 1p. 15742-176. 24X Fiche 50-263,82/10/12.

#### OCKET 50-264 DOW CHEMICAL CO

### ' Insurance & indemnity information

2t004023f Forwards Endorsements 47 & 48 to NELIA Policy NF-160 Endorsement 47 amends description of facility to include Lartin Lab COALMELL-T W Dow Chemical Co 82/09/29 SALTZMAN. J D Antitrust & Economic analysis Branch (Utility Finance) 3pp 15586 111 24X Fiche 50-264,82/09/29,8210040231

### Operating license stage documents & correspondence

- 210180028 Responds to FDIA request for seven categories of documents re Dow Chemical Co & incineration of low level radwaste Request for fee waiver granted Forwards listed documents FELTON J M Division of Rules and Records 82/08/20 WILSON A K. Affiliation Unknown 2pp 15748 002 24X Fiche 50-264,82/08/20,8210180028
- -8210180239 Application for renewal of Matl/Byproduct Licenses 21-00265-06,21-00265-02,21-00265-04,21-00265-07,SNM-1253, STB-927 & R-108 authorizing any byproduct matl between Atomic Numbers 3 & B3. tritium.Po-210 & Am-241 HDYLE-H & Dow Chemical Co 73/06/25 2pp 15748 L15 24X Fiche-50-264,82/08/20.821018032

### Reportable occurrences. LERs & related correspondence

210270202 RO on 821006, maifunction of Eberline AMS-3 continuous air monitor pump caused pump to be inoperable for approx 1-h. No loss of significant signals indicated Pump repaired Changes to procedures or equipment under review RAMPY.L W., KNOLL.F J Dow Chemical Co 82/10/20 MILLER, J R Standardization & Bpscial Projects Branch 1p 15853 384 24X Fichs 50-264, 82/10/20.8210290202

### DOKET 50-265 QUAD-CITIES STATION, UNIT 2

Security, medical, emergency & fire protection plans

- 209290125 Releases public version of revised generating station emergency plan corporate command ctr emergency plan implementing procedure F&LTON.J H. Division of Rules and Records 82/09/16. Document Hanagement Branch 1p. 15564: 122 24X Fiche 50-000, 82/09/16, 200290125
- -8209290189 Forwards public varsion of Revision 4 to generating station amongstery plan corporate command ctr Emergency Plan Implementing Procedure EOF-3. "Environ/Emergency Coordinator." Receipt form ent! PAJOHSKI, J E Commonwealth Edison Co 82/09/01 DENTON.H R NRC No Detailed Affiliation Given [p 15564-123, 24X Fiche 50-000, 82/09/16, 8209290125

- ---8207270225 Public version of Revision 4 to generating station emergency plan corporate command ctr emergency plan implementing Procedure EOF-9, "Environ/Emergency Coordinator"

  PAUDHSKI, J E Commonwealth Edison Co 82/08/31 1ipp 15544 124 24X Fitche 50-000, 82/07/16,8207270125
- 8210010009 Forwards info to suppl 820701 request for exemption from \$\frac{x}{1}\$! R per 820917 telton Request applies to Sections III 0.2 a \( \frac{x}{2} \) it! O.3 b re installation of fire suppression sys RAUBCH, T.J. Commonwealth Edison Co. 82/09/23 EISENNUT, P.O. Division of Licensing Spp. 15545 152 24X Fiche 50-000, 82/09/63 REPORTORORS
- 6210120546 Releases public version of revised cover sheet to facility procedures
  FELTON, J H Division of Rules and Records 82/09/24 Nocument
  Management Branch 1p 15672 219 24X Fiche 50-254, 82/09/24
  8260120546
- --8210120551 Forwards public version of revision cover sheet to facility procedures Completion of encl checklist requested KALIVIANAKIB.N Commonwealth Edison Co. 82/09/15 DENIGN.H Office of Nuclear Reactor Regulation, Director App. 156,73 220 24X Fiche 50-254.82/09/24.8210120544
- 8210150487 Forwards IE Insp Repts 50-254/82-14 & 50-265/B2 16 on 820823-25 & 0903 & 09 No noncompliance noted KEPPLER. J G Region 3. Office of Director 82/09/30 R[6] ( Commonwealth Edison Co 3pp 15721 289 24X Fiche 50 254.83/67/3 8210150487
- --8210150495 IE Insp Repts 50-254/82-14 & 50-265/82-16 on 02002 i 25 6 0703 & 09 No noncompliance noted Major areas inspected emergency preparedness exercise & licensee actions on previously identified emergency preparedness items PHILLIPS: M P Division of Emergency Preparedness & Operational Support B2/09/29 15pp 15721 292 24% Fiche 50 294.82/09/50 8210150487
- 8210130376 Advises that installation of offsite dose calculation sqs program fully operational tracking model & operational A model will be delayed until 821231 to complete prime computer installation SMARTZ, E D Commonwealth Edison Co 82/10/06 DENT(N, ft 8 (1841) of Nuclear Reactor Regulation, Director 2pp 15602 0919 241 Fiche 50-000, 82/10/06, 82/10/3376
- 8210290047 Releases public version of revisions to Quad Cities. Join 1
  Dresden emergency plan annexes & revised generating
  station emergency plan telephone directory
  FELTON. J M Division of Rules and Records 82/10/08 Document
  Management Branch 1p 15877 313 24X Fiche 50-000, 82/10/08
  8210290047
- --8210270060 Forwards public version of Revision 3 to Quad (tities it a emergency plan annexes Revision 2 to Dreaden emergency plan annex, Revision 0 to Byron emergency plan annex it revised generating station emergency plan telephone directory MODRE, R D Commonwealth Edison Cp 82/07/30 DENTON, H R Mai No Detailed Affiliation Given Spp 15877 314 24X Fiche 50-000, 82/10/88 8210290047
- --B210290077 Public version of Revision 3 to Guad Cities & Jibh emergency plan annexes Revision 2 to Dresden emergency plan annex & Revision 0 to Byron emergency plan annex \* Commonwealth Edison Co B2/06/30 325pp 15877 319 348 Ficher 50-000, B2/10/08, B210290047
- --8210290088 Public version of revised generating station saetgening protein telephone directory GALE, DP Commonwealth Edison Co. 82/08/12 43pp 150/8 its 24X Fiche 50-000,82/10/08/8210290047
- 82:0190753 Forwards 820922 ltr re late submittals of exercise scenarios & failure to adhere to FEMA Guidance Memo 17 [f FEMA does not observe exercise offsite authorities will not participate
  HND, J, A Division of Emergency Preparedness & Operational Busing 82/10/12 REED, C Commonwealth Edison Co 2pp 13/36 247 24: Fiche 50-254, 82/10/12, 82:0190753
- ---8210190760 Discusses concerns re late submittals of emergency field, scenarios & failure to adhere to FEMA Guidance Memo 17 Future exercise not mesting intent of advance notification guidance should be postponed or canceled BREHCHY.P. J Federal Emergency Management Agency 82/09/22 KEPPLER.J G Region 3, Office of Director ip 15736 249 24; Fiche 50-254,82/10/12,8210190753.

- 8210280361 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/10/12 Document Management Branch 1p 15859 204 24X Fiche 50-254.82/10/12.8210280361
- --B210280364 Forwards public version of revised emergency plan implementing procedures, including Procedures GEP 200-0 re emergency conditions, GEP 200-11 re emergency action levels & GEP 330-3 re SPINO control terminal operation KOVACK, T S., GERNER, L F. Commonwealth Edison Co. 82/09/23 DENFON, H R. NRC No Detailed Affiliation Given 2pp 15859 205 24X Fiche 50-294,82/10/12,8210280361
- --8210280375 Public version of revised emergency plan implementing procedures, including Procedures GEP 200-0 re emergency conditions, GEP 200-17 re emergency action levels & GEP 330-3 re SFING control terminal operation commowalth Edison Co 82/09/23 21pp 15859 207 24X Fiche 50-254, 82/10/12, 8210280364
- 8210220358 Provides info re organization & performance of depth responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs IRAMM.T R Commonwealth Edison Co 82/10/14 DENTON.H R Office of Nuclear Reactor Regulation. Director 9pp 15776-287 24X Fiche 50-000.82/10/14.8210220358
- 8210250309 Responds to 820917 telcon request for info re fire protection safe shutdown rept Items 2 & 3 are preliminary results, subj. to revision following engineering review RAUSCH, T. J. Commonwealth Edison Co. 82/10/18 EISENHUT, D. Q. Division of Licensing 6pp 15790 215 24X Fiche 50-254,82/10/18,8210250309
- P Operating license stage documents & correspondence
- G210050142 Requests that charcoal adsorber F64-DYH2 be counted within 2 Use of receipt decay corrected to 790319 levels & returned Liquid beta analyses results received in NRC B20917 itr will be incorporated in rept addendum PAPERIECLO.C J Division of Emergency Preparedness & Operational Support 82/09/28 KALIVIANAKIS.N Commonwealth Edison Co ip 15605 167 24% Fiche 50-254,82/09/28,8210050142
- 8210120105 Requests delay of implementation due dates re NUREO-0/37. Items 11 B 2, "Plant Shielding," II B 3, "Post-Accident Sampling" & II F I 1, "Noble Gas Effluent Monitor "
  SNARTZ,E D Commonwealth Edison Co 82/10/04 EISENHUT, D G
  DIVISION of Licensing Spp 15651 237 24X Fiche 50-000,82/10/04,8210120105
- 6210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" GOLDEN, J. C. Commonwealth Edison Co. 62/10/06 CASE, E. G. Offsice of Nuclear Reactor Regulation, Director 2pp. 15805-137 24X Fische 50~000, 82/10/06, 8210260526
- 6210180059 Provides add1 guidance & clarification re 820806 request for add1 info per NUREG-0737, Item II 8 3, "Post-Accident Sampling Sys " Detailed reliability analysis not required to satisfy NRC concerns CRUTCHFIELD, D Operating Reactors Branch 5 82/10/08 DELGEORGE, L Commonwealth Edison Co 3pp 24% Fiche 50-000.82/10/08.8210180059
- 8210190780 Forwards "GE BWR Extended Load Line Limit Analysis for Guad Cities Nuclear Power Station Unit 1,Cycle 7 & Unit 2,Cycle 6 ' RAUSCH, T J Commonwealth Edison Co 82/10/12 EISENHUT, D G Division of Licensing ip 15736
- --8210190785 "OE BWR Extended Load Line Limit Analysis for Quad Cities Nuclear Power Station, Unit 1. Cycle 7 & Unit 2. Cycle 6." \* General Electric O NED-22192 82/07/31 3ipp. 15736-207 24X Fiche 50-254, 82/10/12,8210190780
- 8210190445 Forwards supplemental response to Generic Ltr 82-05 re implementation status of NUREO-0737. Items II 8 3. II F 1 2, II F 1 3. II F 1 5 & II F 1 6. in response to 821006 request SHARTZE D Commonwealth Edison Co 82/10/14 EISENHUT, D 0 Division of Licensing 5pp 24X Fiche 50-000, 82/10/14, 8210190445

- 8210250155 Forwards corrections to proposed Tech Spec Pages I 2/2 2-1 & 3 3/4 3-5, supporting review of future reloads & revised Figure 3.5 I. Sheet I. providiting extended MAPLHOR vs exposure curves for barrier lead test assembly fuel RAUSCH.T.J. Commonwealth Edison Co. 82/10/18 DENTON.H.R. Office of Nuclear Reactor Regulation. Director 2pp 15788 233 24X Fiche 50-000, 82/10/18, 8210250155
- --9210250177 Errata & Addenda Sheet B. replacing Page 4-10 to "LOCA Analysis Rept for Dresden Units 2 & 3 & Quad Cities 1 & 2 Nuclear Power Stations " \* General Electric Co NEDD-24146A ERR 08 82/09/30 3pp 13788 239 24X Fiche 50-000, 82/10/16, 8210250155
- 9210250069 Provides add1 info re reactor water cleanup room area temp monitors Temp elements cause no automatic plant response beyond control room alarms
  RAUBCH, T J Commonwealth Edison Co 82/10/19 EISENHUT, D C Division of Licensing 2pp 15787 081 24% Fiche 50-000,82/10/19,821025064
- Q Inspection reports, IE Bulletins & correspondence
- 8210150487 Forwards LE Insp. Repts 50-254/82-14 % 50-265/82-16 on 820823-25 % 0903 % 09 No noncompliance noted KEPPLER, J G Region 3, Office of Director 82/09/30 REED, C Commonwealth Edison Co 3pp 15721 289 24% Fiche 80-254.82/09/30, 8210150487
- --8210150495 IE Insp Repts 50-254/82-14 & 50-265/82-16 on 820823-25 & 0903 & 09 No noncompliance noted Major areas inspected emergency preparedness exercise & licensee actions on previously identified emergency preparedness items PHILLIPS:M P , SMITH:M J , AXELSON,W L Division of Emergency Preparedness & Operational Support 82/09/29 15pp. 15721 292. 24X Fiche 50-254,82/09/30,8210150487
- 8210060359 Ack receipt of 820910 ltr informing NRC of steps taken to correct violations noted in IS lnsp Repts 50-237/81-39, 50-249/81-32, 50-254/81-23, 50-265/81-23, 50-295/81-31 t 50-304/81-29

  SPEESARD, R L Division of Project & Resident Programs 82/10/01, REED, C Commonwealth Edison Co 1p 15618 354 24X Fiche 50-000, 82/10/01, 8210060359
- --8210060367 Responds to NRC 820712 ltr re violations noted in HE Insp Repts 50-237781-39, 50-249/81-32, 50-284/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29 Corrective actions training for mpt priorities re plant availability will be conducted REED.C Commonwealth Edison Co 82/09/10 KEPPLER, J. 0 Region 3. Office of Director 13pp 15618 355 24X Fiche 50-000, 82/10/01, 8210060399
- B21008017B Forwards listing of piping sys which fail to meet FBAR requirements, per NRC 80081B confirmatory action ltr IE Bulletin 79-14 operability evaluation updates will not be provided for Dresden & Guad Citites Final update by Dec 1982 RAUSCH.T.J. Commonwealth Edison Co. 82/10/01 KEPPLER.J.G. Region 3, Office of Director App. 15440:159 24X Fiche: 50-000.82/10/01.821008017B
- 8210060266 Confirms 821103 enforcement conference at Region 3 ofc re QA aspects associated w/procurement, installation & use of non-qualified valve guides in electramagnetic relief valves at facilities SPESBARD.RL Division of Project & Resident Programs, 82/10/04 REED.C Commonueaith Edison Co ip 15640·181 24X Fiche 50-000,82/10/04.8210080190
- 8208190233 lE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Beeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards, 82/10/06 Consolidated Edison Co of New York 66pp 15761.830 24X Fichs 50-000,82/10/06,8208190233
- B208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Well, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list end!
  DEYGUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810-125 24% Fiche 50-000, 82/10/14, 8208190238
- R Periodic operating reports & related correspondence
- 8210130386 Forwards monthly operating repts for Bept 1982, KALIVIANAKIS, N. Commonwealth Edison Co. 82/10/01. Director's Office, Office, of Inspection and Enforcement 19, 15680-339 24X Fiche, 50-254, 82/10/01, 8210130386.
- --B210130390 Monthly aperating repts for Sept 1982 BUSS.R.D. Commonwealth Edison Co. 82/10/04 13pp 15680 341. 24X Fiche.50-284,82/10/01.8210130386

### S Reportable occurrences. LERs & related correspondence

B210260467 PNO-III-82-112 util notified that high density fuel storage racks installed do not meet design criteria for spacing due to bouing condition Manufacturer reanalyzed seismic response of racks & concluded bound distance acceptable GROBE.J. HALKER.R. STREETER.J Region 3. Office of Director B2/10/18 Ip 15806 237 24x Fiche 50-254.82/10/18.8210260467

### DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8210040117 Discusses revision of plant emergency response procedures specifying necessary precautions required before post-accident re-entry into auxiliary bldg or facade in response to 820914 request for info re NUREO-0737. Item II 8 2 FAY. C W Misconein Electric Power Co 82/09/24 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 2pp 15581 201 24X Fiche 50-266.82/09/24.8210040119

8210050272 Forwards add1 info requested in NRC 820916 telcon to support util 820630 App R exemption request Eight oversize drawings encl Aperture cards are available in PDR FAY.C W Wisconsin Electric Power Co 82/09/29 DENTON.H R Office of Nuclear Reactor Regulation. Director CLARK.R A Operating Reactors Branch 3 13pp 15606 047 24X Fiche 50-266.82/09/29.8210050272

8210050054 Forwards addl info re proposed mods for emergency support ctr FAY.C W Wisconsun Electric Power Co. 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 16pp 15603 328 24X Fiche 50-266.82/09/30.8210050054

8210270256 Releases public version of revised emergency plan implementing procedures FELTON.J H Division of Rules and Records B2/10/08 Document Nanagement Branch 1p 15834 001 24X Fiche 50-266, 82/10/08.

--B210270259 Forwards public version of revised emergency plan implementing procedures including Procedures EPIP ( ) reinitfal classification. EPIP 1 3 re estimation of source term & EPIP 1 4 re radiological dose evaluation FAV.C W. Hisconsin Electric Power Co. 82/09/10 DENTON, H.R. Office of Nuclear Reactor Regulation. Director CLARK, R.A. Operating Reactors Branch 3 4pp. 15834-002 24X Fiche 50-266, 82/10/08:8210270256

--8210270261 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1 1 re initial classification. EPIP 13 re estimation of source term & EPIP 14 re radiological dose evaluation

\* Wisconsin Electric Power Co 82/09/10 244pp 15834 006 24X Fichs 50-266,82/10/08,8210270256

8210130471 Forwards add1 info re 820630 requests for exemption from 10CFR50 App R concerning Fire Area 9, control room & vertical cable trays in response to 821001 & 06 telcons w/NRC W/16 oversite drawings Aperture cards in PDR FAY, C W Hisconsin Electric Power Co 82/10/11 DENTON, H, R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 12pp 15734 350 24X Fiche: 50-266, 82/10/11, 8210150471

### G Adjudicatory correspondence

B210040125 Amend to WI Environ Decade 820810 patition to intervene including affidavits requesting WI Environ Decade to intervene on affiant behalf Certificate of Svc encl ANDERSON, P Wisconsin's Environmental Decade 82/09/28 Commissioners Spp 15581 196 24X Fiche, 50-266, 82/09/28, 8210040125

8210050251 Hemorandum & order granting summary disposition of all WI Environ Decade issues arcept issue of demonstration of adequacy of eddy current tasting to detect cracking BLOCH,P B . KLINE,J R . PAXTON,H C. Atomic Safety and Licensing Board Panel. 82/10/01. Misconsin's Environmental Decade. 19pp 15610 306. 24K Fiche 50-266,82/10/01.8210050251

B210050275 Decision ALAB-696 affirming ASLB B11105 order permitting plant to return to svc after refueling outage during which licenses planned to repair degraded steam generator by slesving TOMPKING, B. A. Atomic Befety and Licensing Appeal Panel 82/10/01, 34pp 15611: 197. 24X Fiche: 50-266,82/10/01,8210050275.

8210120267 Forwards documentation re steam generator replacement application filed prior to 820819 establishment of ABLB Documentation consists of steam generator repair repts & correspondence between licensee & Commission W/o encl RIDGWAY, D.A. Shaw, Pittman, Potts & Trombridge RIDGWAY, D.A. Wisconsin Electric Power Co. 82/10/07 KLINE, J.R., PAXTON, R.C. Atomic Safety and Licensing Board Panel 3pp 15652 327 24x Fiche 50-266,82/10/07.8210120267

B210200027 Notice of B21117-20 evidentiary hearing in Two Rivers, HI to adequacy of inservice nondestructive testing of sleeves proposed to be used to repair corroded steam generator tubes Prehearing conference to be held after hearing DLOCH, P.B. Atomic Safety and Licensing Board Panel 62/10/15 is 15756-325 24X Fichs 50-266, 82/10/15, 8210200027

8210200055 Response to WI Environ Decade 820928 amend to petition to intervene Decade established standing but affiant P Anderson must demonstrate authority to act on behalf of Decade Certificate of Svc encl BACHMANN, R O , MCGURREN.H J Hearing Branch 1 82/10/18 Atcass Safety and Licensing Board Panel 4pp 15753 006 24% Fiche 50-266.82/10/18.8210200055

8210250120 Notice of appearance in proceeding Certificate of Byc enri ANDERBON, P. Hisconsin's Environmental Decade 82/10/20 2pp 15787 114 24X Fiche 50-266.82/10/20.8210250120

8210220242 Notice of relocation of 821117-20 hearing from Two Rivers b to Milwaukee, MI Limited appearance statements will be taken at original location on 821117 BLOCH P B Atomic Safety and Licensing Board Panel 82/10/21 ij 15775 351 24X Fiche 50-266,82/10/21,8210220242

8210260406 Ack receipt of 821018 ltr requesting documents Util will cooperate but is not required to respond since nonparties not entitled to discovery CHURCHILL.8 W Shaw Pittman. Potts & Troubridge 82/10/22 ANDERSON.P Wisconsin's Environmental Decade 3pp 15803 319 14: Fiche 50-266.82/10/22.8310260406

8210280253 Advises that util requested to send FSAR Chapter 14 "Safrig Analyses" to MI Environ Decade, in ref to 821018 telcon 8vc list entl Related correspondence CHURCHILL, B W Shaw, Pittman, Potts & Trombridge CHURCHILL, B W Hisconsin Electric Power Co 82/10/25 ANDERSON, P Wisconsin's Environmental Decade 2pp 15839 027 24X Fichs 50-266,88/10/25 8210280253

## K Utility Final Safety Analysis Report (FSAR) & amends

8207290257 Chapter 4 to Point Beach updated FSAR. "RC8 "

• Wisconsin Electric Power Co 82/07/21 102pp 14821 074 24: Fiche 50-266.82/07/21.8207290257

8207290279 Chapter 11 to Point Beach updated FSAR, "Waste Disposal & Radiation Protection Sys"

\* Wisconsin Electric Power Co 82/07/21 126pp 14823 376 241
Fiche 50-266.82/07/21,8207290279

#### P Operating license stage documents & correspondence

8210210009 Recommends raview of design of interconection between redundant safety-related electrical load groups Design should be modified to assure full compliance w/Reg Quide i 6 MICHELBON, C Director's Office 80/08/27, DENTON, R Daracter & Office, 2pp 18782 209 24% Fiche 50-266.80/08/27, B210210009

821001000B Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON. J M Division of Rules and Records 82/06/RG UDELL. R A Critical Mass Energy Project 15pp 15727 005 24% Fiche: 50-000, 82/06/RB, 821001000B

--8002i40204 Forwards avaltation of proposed Tach Specs change to ejert facility at 2250 on 2000 psia Proposed changes are acceptable M/o enci CMCK, P S. Reactor Sefety Branch 79/12/26 BCHMENCER, A Operating Reactors Branch 1 (Pre 800428) 6pp 15727,030 241 Fiche 50-000,82/06/28,8210010008

8210070007 Responds to FOIA request for eight categories of recording steam generators & steam turbines. App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J. M. Division of Rules and Records 82/08/10 LONO.D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 R4X Fiche: 50-000, 82/08/10, 8210070007

- --7812200285 Summarises steam generator tube leak on 780920 & insp Leak rate reached 560 gpd at 5 00 AM, caused by two tubes w/cracks located w/in thickness of tube sheet & one tube w/leaky plug General cause plant conversion to AVT MOGNAM, V S Engineering Branch (Pre 791030) 78/12/12 GRIMES, B X Assistant Director for Engineers & Projects (Pre 790625) 2pp | 15645-244 24X Fiche 50-000,82/08/10,8210070007
- --7909280105 Discusses steam generator tube leak & inservice insp Steam generator caused by deep crevice cracking of three tubes within tube sheet Not leg tube tests indicated 52 tubes wideep crevice cracking in scress of 50% plugging limit MODNAH, V S Engineering Branch (Pre 791030) 79/08/17 EISENHUT, D G Division of Operating Reactors 3pp 15645 254 24% Fiche 50-000,82/08/10.8210070007
- --8004300616 Requests that util provide BNL w/tube samples for examination Forwards list of tubes FOCHAN, V S Engineering Branch 80/04/14 BCHWENCER, A Operating Reactors Branch 1 (Pre 80042B) 2pp 15645 266 24X Fiche 50-000, 82/08/10, 8210070007
- -8009040493 Forwards safety evaluation of Aug 1980 steam generator insp Concludes generators may be operated safely per 791130 & 800103 orders PAMLICKI.S S. Materials Engineering Branch 80/08/08 CLARK.R A Operating Reactors Branch 2 ip 15645 309 24X Fiche 50-000,82/08/10.8210070007
- --81i0290050 Advises that technical reviewers providing input for BER must be available to testify at 81i029-31 hearings Schedule 7 agenda info entl CLARK-R A Deerating Reactors Branch 3 61/10/20 MURPHY, E, PEHEMIAS, J , MD. T NRC -- No Detailed Affiliation Given 3pp 13645 271 24X Fiche 50-000, 82/08/10,8210070007
  - 3110300460 Requests evaluation by 811023 of util 810702 application for license amend to permit steam generator tube sleaving Info to be presented at ASLB 811029-30 hearing CDLBURN. T G Operating Reactors Branch 3 81/10/19 BALLARD, R L Environmental Engineering Branch 1p 15645 270 24X Fichs 50-000.82/08/10.8210070007
- --Dillo90062 Forwards safety evaluation for proposed steam generator sleeving demonstration covering radiation protection & ALARA aspects RREGER.W E Assistant Director for Radiation Protection B1/10/22 NGVAK.TA Assistant Director for Operating Reactors 4pp 15645 276 24X Fiche 50-000, 82/08/10, 8210070007
- --B111240071 Submits review of util request to demonstrate tube sleeving program Activities of proposed demonstration will not result in any significant environ impact
  BALLARD,R L Environmental Engineering Branch B1/10/23
  CLARK,R A Derating Reactors Branch 3 lp 15645-280 24X
  Fiche 50-000, B2/08/10,8210070007
- --8202120129 Discusses environ review of application for steam generator tube sleeving program Environ impact insignificant MALLARD.R L. Division of Engineering 82/01/25 CLARK.R A Operating Reactors Branch 3 ip 15645 282 24X Fiche 50-000.82/08/10.8210070007
- --8210070185 Responds to 750320 question concerning licensing action repactifity steam generator tube rupture incident M/o enciprelimanary results of tube inspiperformed by licensee, Tech Specs & related info GOLLER.K R Division of Reactor Licensing (NRR-1975 only) /5/03/31 QALLO, J Hearings Division ip 15645-201 24X Fichs 50-000.82/08/10,8210070007
- --8210070187 Informs of incorrect info contained in third paragraph of Encl 2 to 750331 memo re facility steam generator tube rupture incident Corrected paragraph submitted GOLLER, K.R. Division of Reactor Licensing (NRR-1975 only) 75/04/09 OALLO, J. Hearings Division 2pp 15645-202 24X Fichs 50-000,82/08/10.8210070007
- --8210070i91 Requests technical assistance re 750226 steam generator tube leakage incident Review of anci info & current regulatory requirements re steam generator tube integrity requested by 750530 W/o encis

  LEAR. @ Division of Reactor Licensing (NRR-1975 only) 75/04/18 SCHROEDER.F Division of Technical Review (NRR-1975 only) 3pp 15645 204 24X Fiche 50-000,82/08/10,8210070007

- --B210070205 Submits summary of findings & comments re facility steam generator tube leak incident & insp results contained in Annual Operating Rept 1976 Recommends that licensee be requested to submit insp program for next scheduled insp SHAO.L C Engineering Branch (Pre 791030) 77/07/25 EISENHUT.D Q Division of Operating Reactors 2pp 18645 235 24X Fiche 50-000,82/08/10.8210070007
- ~-8210070208 Forwards request for add1 info re 780524 steam generator tube leak.per LER 78-010/01T-0 LER does not clearly indicate evaluation of exact location ★ Engineering Branch (Pre 791030) 78/07/13 SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 3pp 15645 241 24X Fiche 50-000, 82/08/10, 8210070007
- --8210070217 Expresses appreciation for 791130 effort to perform essential licensing work on steam generator matter EISENHUT. D 0 Division of Operating Reactors 79/12/03 TRAMMELL.C W Operating Reactors Branch 1 (Fre 800428) 1p 15645 257 24X Fiche 50-000.82/08/10.8210070007
- --8210070218 Forwards A Schwencer & CM Trammell statements re 791116 LER 79-017, per 791228 request SCHMENCER.A Operating Reactors Branch 1 (Pre 800428) 79/12/31 EISENHUT.D 0 Division of Operating Reactors 6pp 15645 258 24% Fiche 50-000.82/08/16.8210070007
- 8210040414 Forwards Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amends revise inservice insp Tech Bpecs CLARK, R A Operating Reactors Branch 3 82/08/31 FAY.C W Misconstin Electric Power Co 5pp 15597 134 24X Fiche 50-266, 82/08/31, 8210040414
- --B210040420 Amends &3 & 69 to Licenses DPR-24 & DPR-27, respectively, revising language of Tech Specs re inservice inspectively, requirements of safety class components to conform u/100FR50 55
  CLARK, R A Operating Reactors Branch 3 82/08/31 16pp 15597 139 24X Fiche 50-266,82/08/31,8210040414
- --8210040425 Safety evaluation supporting Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively \* Office of Nuclear Reactor Regulation, Director 82/08/31 4p. 15597 155 24% Fiche. 50-266, 82/08/31, 8210040414
- --8204210571 "Point Beach Nuclear Plant Units i & 2 Inservice Insp Program Tachnical Evaluation Rept" \* Science Applications, Inc. NRC-03-82-074 SAI-186-028-22 82/06/15 NRC - No Detailed Affiliation Given 20pp 15597 139 24X Fichs 50-266, 82/08/31,8210040414
- --B210040427 Notice of issuance & availability of Amends 63 & 68 to Licenses DPR-24 & DPR-27.respectively CLARK.R A Operating Reactors Branch 3 B2/08/31 3pp 15597 179 24X Fiche 50-266, B2/08/31, B210040414
- 8210050005 Advises that error analysis of reactor vessel water level instrumentation sys requested in NRC 820619 ltr will be available by 830115 FAY.C W. Hisconsin Electric Power Co 82/09/29 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK.R A Operating Reactors Branch 3 ip 15405 208 24X Fiche 50-266, 82/09/29, 8210050005
- 8210050055 Forwards info requested in NRC 820630 ltr re implementation of TMI Item II 8 2. "Post-Accident Sampling Bys " Addl requirements re backup power sources for lab are beyond scope of original NUREO-0737 implementation schedule BURSTEIN.S Wisconsin Electric Power Co 82/09/30 DENTON.H R Office of Nuclear Reactor Regulation, Director CLARK.P A Operating Reactors Branch 3 21pp 15603 307 24% Fiche 50-266,82/09/30.8210050055
- B210050222 Application to smend Licenses DPR-24 & DPR-27, revising spent fusi pool poison surveillance specimen location & clarifying conditions for operating power-operated relief valves FAY.C W Misconsin Electric Power Co B2/09/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director, Opp 15609,056, 24X Fiche, 30-266,82/09/30,8210050222
- --8210050231 Proposed Tech Baccs revising spent fuel pool poison surveillance specimen location & clarifying condition for operating power-operated relief valves \* Wisconsin Electric Power Co. 82/09/30 3pp, 15609-059 24X Fiche 50-266,82/09/30,8210050822

- 8210290426 Forwards Amends 64 & 69 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amends modify operation & surveillance testing requirements of containment purge supply & exhaust valves COLBURN, TO Operating Reactors Branch 3 62/10/04 FAY. C W Misconsin Electric Pour Co 4pp 15963 143 24x Fiche 50-266, 82/10/04, 8210290426
- --8210270431 Amends 64 & 69 to Licenses DPR-24 & DPR-27, respectively, and frying operation & surveillance testing requirements of containment jurge supply & exhaust isolation valves & terminology of Tech Spec 15 4 4 on testing CLARK, R A Operating Reactors Branch 3 82/10/04 12pp 19863 154 24X Fische 50-266, 82/10/04, 8210270426
- --8210290436 Safety evaluation supporting Amends 64 & 69 to Licenses BPR-24 & BPR-27: respectively \* Office of Nuclear Reactor Regulation, Director 15863 146 24% Fiche 50-266.82/10/04.8210290426
- ---B210270441 Notice of issuance & availability of Amends 64 & 69 to Licenses DPR-24 & DPR-27, respectively CLARK.R A Operating Reactors Branch 3 82/10/04 2pp 15863 151 24X Fiche 50-266.82/10/04.8210290426
- 8210120267 Forwards documentation resteam generator replacement application filed prior to 820819 establishment of ASLB Documentation consists of steam generator repair repts & correspondence between licensee & Commission H/o encl RIDCHAY.D A Shaw. Pittman. Potts & Troubridge. RIDCHAY.D A Wisconsin Electric Power Co. 82/10/07 KLING.J R. PAXTON. H C Atomic Safety and Licensing Board Panel 3pp 15652 327 24% Fiche 50-246.82/10/07.8210120267
- 8210150430 Advises that refueling shutdown at end of Cycle 10 planned to begin 821022 Startup of Cycle 11 expected to occur in early Dec 1982 Cycle 11 reload core designed to operate under current nominal design parameters & Tech Specs FAY.C W Wisconsin Electric Power Co 82/10/11 DENION.H R Office of Nuclear Reactor Regulation, Director CLARK.R A Operating Reactors Branch 3 2pp 15704 019 24X Fiche 50-266,82/10/11.8210150430
- 8210190284 Advises of mod to RCB gas vent sys to prevent operation of power operated valves during normal plant operation.per 82[0]2 teleon Physical restraining device fitted on or over valve operator switch FAY.C H Misconsin Electric Power Co 82/10/15 DENTON.H R Office of Nuclear Reactor Regulation. Director CLARK.R A Operating Reactors Branch 3 1p 15742 177 24X Fiche 50-266.82/10/15.8210190284
- 8210190519 Forwards responses to request for add1 info on Tech Spec Change Request 85 re operation when add1 steam generator tube plugging causes primary says flow to drop below thermal design flow value
  FAY.C H disconsin Electric Power Co 82/10/15 DENTON,H R
  Office of Muclear Reactor Regulation, Director CLARK.R A
  Operating Reactors Branch 3 Spp 15751 238 24X
  Fiche 80-266, 82/10/15, 8210190519
- S210270294 Forwards Amends 65 % 70 to Licenses DPR-24 % DPR-27, respectively, safety evaluation & notice of issuance % availability Amend allows relaxation of monthly turbine stop % governor valve tests during end of cycle operation COLBURN-T 0. Operating Reactors Branch 3 82/10/15 FAY.C WHIsconsin Electric Power Co. 3pp. 15836 316 24X ,8210270294

a Licenses DPR-24 & DPR-27, respectively, nthly turbing stop governor valve operation.

Branch 3 82/10/15 7gp /10/15,8210270294

\* \*^ \*> Licenses

10/15, 200

. 0

\_\_\_

Tech

- --B210260479 Proposed Tech Spec changes incorporating revisions readministrative control of high radiation areas # Wisconsin Electric Power Co 82/10/19 tp 15806 235 24: Fiche 50-266:82/10/19-8210260476
- 8210280295 Application to amend Licenses DPR-24 & DPR-27, changing Title Specs re requirements for periodic leakage rate testing of containment airlock doors Class I & II amend fees encl FAY.C W Misconsin Electric Power Co 82/10/21 DENTON.H R Office of Noclear Reactor Regulation, Director 3pp 15837 272 24X Fiche 50-266.82/10/21.8210280295
- --8210280278 Tech Spec Change Request 82, changing requirements for periodic leakage mate testing of containment air lock doors 4 Wisconsin Electric Power Co 82/10/21 4pp 15837 275 24: Fich > 50-266, 82/10/21,8210280275
- 8210290294 Provides results of confirmatory analysis demonstrating that unacceptable radioactive release from containment would not take place as result of small break LOCA in which operator action required Radioactive release negligible FAY. C W Wisconsin Electric Power Co 82/10/22 CLARK.R A Operating Reactors Breach 3 ip 15853 135 24X Fiche 50-266.82/10/22.8210290294
- O Inspection reports. IE Bulletins & correspondence
- 8107270156 Forwards add1 info in response to IE Bulletin BO-11 re masonry walls Thirteen repts & 109 oversize drawings enc]
  Aperture cords are available in PDR
  FAY.C W Wisconsin Electric Power Co B1/07/17 DENTON.H R
  Office of Nuclear Reactor Regulation, Director CLARK,R Degrating
  Reactors Branch 3 19pp Available at NTIS 09151 026 24x
  Fiche 50-266,81/07/17,8107270156
- ---8107270166 "Cyclic Loading Tests of Masonry Single Piers, Vol ( Hizj to Width Ratio of 2 " HIDALOD,P A , MAYES,R L. , MCNIVEN.H D California, Univ of, Berkeley UCE/EERC-78/27 VOl 78/11/30 141pp Available at NTIS 09151 158 24X Fichs 50-266.81/07/17,8107270156
- --8107270169 "Cyclic Loading Tests of Masonry Single Piers, Vol 2 Heige to Width Ratio of 1" CHEN, S. J. HIDALBOLP A. MAYES, R.L. California, Univ. of, Berkeley UGD/EERC-78/28 VOZ 78/12/31 188pp 09151 298 244 Fiche 50-266, 81/07/17, 8107270156
- --B107270174 "Cyclic Loading Tests of Masonry Single Piers, Vol 3 Fely to Width Ratto of 0 5 " HIDALOO,F A , MAYES,R L , MCNIVEN,H D California, Univ of, Berk=ley UCB/EERC-79/12 VO3 79/05/31 154pp Available at NTIS 09152 124 24% Fiche 50-266/B1/07/17,B107270156
- --8107270178 "Shaking Table Study of Single-Story Masonry Houses, Vol 1
  Test Structures 1 & 2 "
  QULKAN,P MAYES, R L , CLOUGH, R W California, Univ of, Berbelay
  UCB/EERC--79/23 VOI 79/09/30 275pp Available at NTIS
  09152.277 24X Ficher 50-266, 81/07/17, 8107270156
- --8107270182 "Shaking Table Study of Bingle-Story Masonry Houses: Vol 2-Test Structures 3 & 4 " OULKAN: F. MAYES: R L. CLOUGH: R W. California, Univ. of. Berleiq UCB/EERC-79/24 VOZ 79/09/30 300pp 09153 184 24X Fiche 50-266:81/07/17:8107270156
- --8107270185 "Shaking Table Study of Single-Story Hasonry Houses, Vol 3-Summary, Conclusions & Recommendations " CLOUGH, R. H., MAYES, R. L., OULKAN, P. California, Univ. of, Berleles UCB/CEERC-79/25 VOJ 79/09/30 110pp Available at NTIS 09154 078 24X fiche 50-266, 81/07/17, 8107270156
- --BiO7270188 "Cyclic Shear Tests of Masonry Piers, Vol 1 Test Results" MAYES.R.L. OMATE.Y., CLOUGH.R.W. California, Univ. of, Barteleg EERC 76-8 76/05/31 105pp 09194 182 24X Fiche. 50-266. 81/07/17. 8107270156
- --Bi07270191 "Cyclic Shear Tests of Masonry Piers, Vol 2 Analysis of Test Results " MAYES, R L , OMATE, Y , CLOUCH, R W California, Univ of, Bartilly EERC 76-16 76/06/30, 78pp 09154 288 24X Fiche: 50-286, 81/07/17, 8107270156
- --8107270194 "Strength of Timber Roof Connections Subjected to Cyclic Loads "OULKAN, P. MAYEB, R. L., CLOUGH, R. W. California, Univ. of, Berielej, UCB/EERC-78/17. 78/09/30 171pp 09155 005 24X Fiche: 50-266, 81/07/17, 8107270156

- --8107270196 'Literature Survey Transverse Strength of Masonry Walls " DKATE,Y, MAZES,R L. CHEN,S J California, Univ of, Berkeley UCB/EERC-77/07 77/03/31 149pp 09155 140 24X Fiche 50-366.81/07/17.8107270156
- --Bi07270198 'Literature Survey Compressive.Tensile.Bond & Shear Strength of Masonry "
  HAYES R L , CLGUGH.R W California. Univ of Berkeley EERC
  JS-15 75/06/30 212pp 09155 286 24X Fiche 50-266.81/07/17,
- --8107270197 "State-of-the-Art in Seismic Shear Strength of Masonry Evaluation to Review ' MAVES.R L . CLDUGH.R W Lalifornia, Univ of, Berkeley ECRC 75-21 75/10/31 147pp 09156 135 24X Fiche 50-266,81/07/17, 8107270156
- ©210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App D FELTON.J M Division of Rules and Records 82/08/10 LONG, D J Winthrop. Stinson. Putnam & Roberts 9pp 15645 063 24X Fiche 50-000.82/08/10.8210070007
- --7812200285 Surmarites steam generator tube leak on 780920 & insp Loak rate reached 560 gpd at 5 00 AM caused by two tubes w/cracks located w/in thickness of tube sheet & one tube w/leaky plug General cause plant conversion to AVT NBONAN, V S Engineering Branch (Pre 791030) 78/12/12 GRIMES.D K Assistant Director for Engineers & Projects (Pre 790625) 2pp 15645 244 24X Fiche 50-000,82/08/10,8210070007
- --7909280105 Discusses steam generator tube leak & inservice insp Steam generator caused by deep crevice chacking of three tubes within tube sheet Hot leg tube tests indicated 52 tubes w/ deep crevice cracking in excess of 50% plugging limit ADDNANLY S Engineering Branch (Pre 791030) 79/08/17 tisERHUT, D O Division of Operating Reactors 3pp 19645 254 24X Fiche 50-000 82/08/10.8210070007
- -8210070137 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees
  IPPOLITO, f Operating Reactors Assessment Branch 82/04/01
  VARGALS Operating Reactors Branch 1 5pp 15645 131 24X
  Fiche 50-000,82/08/10.8210070007
- --8210070172 Forwards info re steam generator integrity & insps at all operating PNRs, per 750320 b 21 requests Details of insps, including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach 1 COLLER K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY, R R Division of Technical Review (NRR-1975 only) 5pp 15615 196 24X Fichs 50-000,82/08/10,8210070007
- --B210070205 Submits summary of findings & comments ie facility steam generator tube leak incident & inspiresults contained in Annual Operating Rapt 1976 Recommends that licensee be requested to submit inspiprogram for next scheduled inspicable. C. Engineering Branch (Pre 791030) 77/07/25 EISEMHUT, D. O. Division of Operating Reactors 2pp 15645 235 24X Fiche 50-000.82/08/10.8210070007
- --82]0070228 Forwards evaluation of 800226 proposed steam generator inap & tube publing program Recommends that program be revised to reflect listed comments NOONAN-V S Engineering Branch 82/08/10 SCHWENCER. A Operating Reactors Branch 1 (Pre 800428) 2pp 13645 268 24X Fichs 50-000.82/08/10.8210070007
- G210040414 Forwards Amends 43 & 68 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amends revise inservice insp Tech Specs CLARK.R A Operating Reactors Branch 3 62/08/31 FAY, C W Nisconsin Electric Power Co Spp 15597 134 24X Fithe 50-266, 82/08/31, 8210040414
- --8210040420 Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively, revising language of Tach Specs re inservice inspectively, requirements of safety class components to conform w/10CFR50 55
  CLARK, R A Operating Reactors Branch 3 82/08/31 16pp 1557 139 24X Fiche 50-266, 82/08/31,8210040414
- --8210040425 Safety evaluation supporting Amends 63 & 68 to Licenses BPR-24 & DPR-27, respectively 4 fiftice of Nuclear Reactor Regulation, Director 82/08/31 4pp 15597.155 24% Fiche 50-266,82/08/31,8210040414

- --8206210571 "Point Beach Nuclear Plant Units 1 & 2 Inservice Insp Program Technical Evaluation Rapt" # Science Applications, Inc NRC-03-82-096 SAI-186-028-22 82/06/15 NRC - No Detailed Affiliation Given 20pp 15597 159 24X Fiche 50-266,82/08/31,8210040414
- --8210040427 Notice of issuance & availability of Amends 43 & 48 to Licenses DPR-24 & DPR-27.isspectively CLARK,R A Operating Reactors Brauch 3 82/08/31 3pp 15597 179 24% Fiche 50~264.82/08/31.8210040414
- 8210050186 Forwards IE Insp Repts 50-266/82-12 & 50-301/82-12 on 820503-04 & 0615 & notice of violation KEPPLER, J O Region 3, Office of Director 82/07/15 BURSTEIN, 8 Wisconsin Electric Power Co 3pp 15611 115 24X Fiche 50-266,82/07/15,8210050186
- ~-8210050174 Notice of violation from insp on 820503-04 & 0615 KEPPLER, J 0 Region 3, Office of Director 82/09/15 3pp 15611 118 24X Fiche 50-266,82/09/15,8210050186
- --B210050205 IE Insp Repts 50-266/82-12 & 50-301-82-12 on 820503-04 & O615 Noncompliance noted failure to control access to high radiation areas & failure to follow approved procedures LOVENDALE,P C . HAGUE,R L . GREGER,L R Region 3. Office of Director 82/07/13 8pp 15611 121 24X Fiche 50-266.82/09/15, 8210050186
- 8210070033 Notifies that fees for 820820 application requesting relief from certain inservice insprequirements not remitted w/application Class III fee category appropriate DIOGS.R H License Fee Management Branch 82/09/23 FAY.C W Wisconsin Electric Power Co ip 1545 346 24X Ficha 50-266.82/07/23.8210070033
- B210050256 Requests relief from ASHE Section XI. Inservice insprequirements refrequency of reactor vessel interior exam FAY.C W Hisconsin Electric Power Ca B2/09/29 DENTON.H R Office of Nuclear Reactor Regulation. Director CLARK.R A Operating Reactors Branch 3 4pp 15610 286 24X Fiche 50-266.B2/09/29.8210050256
- 8210190667 Forwards IE Insp Repts 50-266/82-20 & 50-301/82-20 on 820914-16 No noncompliance noted LITTLE: W 8 Division of Engineering & Technical Programs 82/10/04 BURSTEIN: 8 Wisconsin Electric Power Co 2pp 15738:152 24X Fichs 50-266:82/10/04.8210190669
- --8210190675 IE Insp Repts 50-266/82-20 & 50-301/82-20 on B20914-16 No noncompliance noted Major areas inspected survaillance & calibr procedures & performance history HABSELR A , PEECHELLJ M , HAWKINGLF C Division of Engineering & Technical Programs B2/09/29 4pp 1973B 154 24X Fiche 50-266, B2/10/04, B210190669
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I~125 Inplant Seeds " Svc list encl COBD, L I Division of Fuel Facilities, Motorials & Safaguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06.8208190233
- 8210180067 Forwards Class III fee re 820820 request for exemptions from certain inservice insp requirements Util considers imposition of 10CFRI70 22 fees inappropriate as request does not involve license emend FAY.C. W. Hisconsin Electric Power Co. 82/10/11. DENTON, H.R. Office of Nuclear Reactor Regulation. Director CLARK.R.A. Operating Reactors Branch 3 1p 15720.003 24X Fiche 50-266,82/10/11.8210180067
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Stoel, Recirculation Sys Piping at BMR Plants." Syc list encl DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 128, 24X Fiche 50-000, 82/10/14, 8208190238
- R Periodic operating reports & related correspondence
- 8210150150 Forwards monthly operating repts for Sapt 1982 FAY,C W Misconsin Electric Power Co 82/10/11 Office of Nuclear Reactor Regulation, Director ip 15697 074 24X Fiche,50-266.82/10/11.8210150150
- ---B210150158 Monthly operating repts for Sept 1982.
  FAY.C W Hisconsin Electric Power Co 82/10/04 Spp 15697.075
  24X Fiche 50-266.82/10/11.8210150150.

- S Reportable occurrences, LERs & related correspondence
- 8210290258 Forwards LER 82-015/03L-0 FAY,C.W Misconsin Electric Power Co 82/10/13 KEPPLER.J G Region 3. Office of Director ip 1579! 148 24X Fiche 50-266, 82/10/13.8210250258
- --8210250262 LER 82-015/03L-0 on 820914. fluid level in gas stripper noted decreasing abnormally after stripper returned to svc following maint Caused by high stress low cycle failure of lap joint flange stub piece Lap joint flange replaced FAY.C W Misconsin Electric Power Co 82/10/13 Region 3, Office of Director 3pp 15791 147 24X Ficha 50-266.82/10/13. 8210250258
- 8210250344 Forwards LER 82-016/01T-0 FAY,C H Hisconsin Electric Power Co 82/10/15 KEPPLER.J & Region 3. Office of Director 1p 15790 332 24X Fiche 50-265. 82/10/15.8210250344
- --8210250352 LER 82-016/01T-0 on 821002.containment isolation velve 10V-3200C in suction line of radioactive gas & particulate monitoring sys failed to close Caused by failure of 3-way solenoid valve to cycle Valve closed & repaired FAY.C W Hisconsin Electric Power Co 82/10/15 Region 3, Office of Director 4pp 15790 333 24X Fiche 50-266.82/10/15, 9210250344
- T Hearing transcripts on non-antitrust matters
- 8210080052 Transcript of 821006 telephone conference to discuss rascheduling of hearing in Washington.DC Pp 1:342-1:352 
  \* Atomic Safety and Licensing Board Panel 82/10/06 12pp 15643 224 Fishe S0-266.82/10/06,8210080052
- DOCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION
  F Security, medical, emergency & fire protection plans
- 8209150434 Releases public version of updated radiological emergency response plan. FELTON, JH Division of Rules and Records 82/08/25 Document Management Branch 1p 14890 193 24X Fiche 50-267, 82/08/25, 8209150434
- --B209180440 Forwards public version of updated radiological emergency response plan, per 820315 request Enci revision is almost complete rewrite except for visitors ctr & RERP-FIELD procedures W/o enci WAREMBOURG, D Public Service Co of Colorada, 62/08/10 ROHRER, D Director's Office, Office of Inspection and Enforcement ip 14890 174 24% Fichs 90-247,82/08/25,8209150434
- B2102500B3 Commits to revising security plan & implementing Procedure APM G-4 to provide for background investigation of outside contractor personnel at facility Screening program will be implemented within 60 days
  LEE.OR Public Service Co. of Colorado 82/08/25 GOLLINB, J T Region 4, Office of Director. 3pp (5787-083-24X) Fiche 50-267,82/08/25,8210250083
- 8210210073 Releases public version of radiological emergency response plan implementing procedures. FELTON.J.H Division of Rules and Records 82/09/29 Document Management Brench ip 15774 [26 24X Fiche 80-267,82/09/29, 821091073
- --B210210081 Forwards public version of radiological emergency response plan implementing procedures, including implant/onsite ure & field monitoring

- 8210220404 Ack receipt of 820819 response to App A items of LE Emergency Preparedness Appraisal Root 50-267/82-01 Addl info needed to complete evaluation of response MADSEN,G L Division of Resident, Reactor Project & Engineering Programs 82/10/19 LEE,OR Public Bervice Co of Colorado Sps 15779 160 24X Fiche 50-267,82/10/19,8210220404
- P Operating license stage documents & correspondence
- 9210040114 Forwards info documenting satisfaction of each criterion of MUREO-0737. Item II B 3 re post-accident sampling system (RNL investigation of source terms remains only open item WAREMBOURO Public Gervice Co of Colorado 82/09/27 CLANK.R A Operating Reactors Branch 3 40pp 15581 146 24X Fishe 50-267, 82/09/27, 8210040114
- 8210080256 Forwards "Radiothemical Analysis of First Plateout Prote From Fort St Vrain High-Temp Gas-Cooled Reactor" WAREMBOURD, D. W. Public Service Co. of Colorado 82/09/2/ WUZMYCZ, O. NRC - No Detailed Affiliation Given ip 15649 200 24X Fiche 50-267.82/09/27.8210080256
- --8210080258 "Radiochemical Analysis of First Plateout Probe from Fors St Vrain High-Temp Cas-Cooled Reactor" BURNETTE, R D OA Technologies, Inc./General Atomic Co. GA-A16/84 82/06/30 128pp 15649 281 24X Fiche 50-267,82/09/27, 8210080256
- 8210060273 Forwards suppl to EE-11-0002, Revision 2, "Addl Burveillance Requirements for PCRV Penetrations & Closures," & suppl to EE-22-0002, Revision 1, "Inservice Insp & Testing Program Addl Surveillance Requirements for Steam Generator " gREY, H L Public Service Co of Colorado 82/09/30 CLARK, R A Operating Reactors Branch 3 2pp 15621 180 24% Fiche 50-267, 82/09/30, 8210060273
- --0210060202 Suppl to EE-11-0002 Revision 2, "Fort St Vrain A44! Burveillance Requirements for PCRV Penetrations & Closures " \* Public Service Co of Colorado 62/09/28 12pp 15621 103 24% Fiche 50-267,02/09/30 8210060273
- --8210060286 Suppl to EE-22-0002 Revision 1. "Fort St Vrain Inservise Insp & Testing Program Addi Surveillance Requirements for Steam Generator"

  \* Public Service Co. of Colorado 82/09/28 7pp 15621 194
  24% Fiche 50-267,82/09/30.8210060273
- 8210190701 Forwards "Fort St Vrain Accident Reanalysis Code (RECA 3)
  Verification Following Region Outlet Temp Redistribution."
  per Bi0210 meeting commitment Code accurately predicts
  transient behavior in temp redistribution configuration.
  gREY.H L Public Service Co of Colorado 82/10/06 NOVAK, I H
  Assistant Director for Operating Reactors 1p 15736 155 241
  Fiche 50-267, 82/10/06, 8210190701
- ---8210190706 "Fort St Vrain Accident Reanalysis Code (RECA 3) Verification Following Region Outlet Temp Redistribution " \* Public Service Co of Colorado 82/10/06 42pp 13/36 Ph 24% Fiche 50-267,82/10/06/8210190701
- 8210270104 Forwards 821012 application to amend License DPR-34.fevtality surveillance requirements LEE.D R Public Bervice Co of Colorado 82/10/15 CLARM-R Assistant Director for Operating Reactors 2pp 15827-030 448 Fiche 90-267.82/10/15, 8210270104
- --8210270113 Application to amend License DPR-34, changing Tech Specary inservice imap & testing program surveillance requirements LEE, D R Public Service Co of Colorado 82/10/12 9ep 15827 052 24X Fiche 50-267, 82/10/15,8210270104
- ---B210270118 Proposed Tech Specs changes involving reserve shuldows the surveillance, primary coolant sys surveillance requirements, tendon corrusion & anchor assemblies Implementation schedule & SAR encl

  \* Public Service Co of Colorado. B2/10/15 54pp 1502/ 061
  24X Fiche 50-267, 82/10/15.8210270104
- G. Inspection reports: IE Bulletins & correspondence
- 8210050226 Forwards IE Insp Rept 50-267/82-20 on 820801-31 Ne noncompliance noted MADBEN, G L pivision of Resident, Reactor Project & Engineering Programs 82/09/16 LEE, G R public Service Co of Coloreds 15508-309, 24 Fiche 50-267, 82/09/16, 8210050226

- -8210050237 IE Insp Rept 50-267/82-20 on 820801-31 No noncompliance noted Major areas inspected surveillance, maint, operational safety verification, previous insp findings, plant operations & procedures & repts
  PICKERSON M W. PLUMEE, G L. WESTERMAN, T. F. Division of Resident Reactor Project & Engineering Programs 82/09/10 13pp
  15408 311 24% Fiche 50-267, 82/09/16.8210050226
- 8210060273 Forwards supplied EE-11-0002, Revision 2. "Add1 Surveillance Requirements for PCRV Penetrations & Closures," & supplied EE-22-0002, Revision 1. "Inservice Insp & Testing Program Add1 Surveillance Requirements for Steam Generator"

  BREY, H. L. Public Service Co. of Colorado. 82/09/30 CLARK, R.A. Operating Reactors Branch 3 2pp. 15621 180 24X

  Fiche 50-267, 82/09/30, 8210060273
- --8210060282 Suppl to EE-11-0002, Revision 2. "Fort St Vrain Addl Surveillance Requirements for PCRV Penetrations & Closures " Public Service Co of Colorado 82/09/28 12pp 15621 182 24X Fiche 50-267, 82/09/30,8210060273
- --8210060286 Suppl to EE-22-0002, Revision 1, "Fort St Vrain Inservice Insp & Testing Program Addl Surveillance Requirements for Steam Generator"
  4 Public Service Co of Colorado 82/09/28 7pp 15621 194 24x Fiche 50-267.82/09/30.8210060273
- 620B190233 IE Info Notice B0-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 244 Fache 50-000.82/10/06.8208190233
- #210280142 Forwards IE Insp Rept 50-267/82-19 on #20809-13 & 0830-0903 & notice of violation 
  #ADSEN.C L Division of Resident. Reactor Project & Engineering 
  Programs #2/10/06 LEE.O R Public Service Co of Colorado 2pp 
  15837 227 24X Fiche 50-267, 82/10/06.6210280142
- --9210280145 Notice of violation from insp on 820809-13 & 0830-0909 # Division of Residenk, Reactor Project & Engineering Programs 82/10/06 ip 15837 229 24X Fiche 50-267, 82/10/06, 4210280142
- --B2102B0149 IE Insp Rept 50-267/82-17 on B20B09-13 & 0830-0903 Noncompliance noted failure to maintain test records of safety-related design changes REDANU, R T , MESTERMAN, T F Division of Resident, Reactor Project & Engineering Programs B2/09/29 9pp 15B37 230 24X Fiche 50-267,82/10/06,8210280142
- 8208190238 IE Bulletin B2-03. "Stress Corrosion Cracking in Thick-Wall. Large-Diameter. Stainless Steel. Recirculation Sys Piping at BUR Plants "Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enrorcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000. 82/10/14.8208190238
- 8210270104 Forwards B21012 application to amend License DPR-34, revising surveillance requirements LEE.O R Public Service Co of Colorado 82/10/15 CLARK.R Assistant Director for Operating Reactors 2pp 15827 050 24X Fichs 50-267.82/10/15.8210270104
- --8210270113 Application to amend License DPR-34, changing Tech Specs re inservice insp & testing program surveillance requirements LEE.O R Public Service Co of Colorado 82/10/12 9pp 13827 052 24% Fiche 50-227,82/10/15,8210270104.
- --B210270118 Proposed Tech Specs changes involving reserve shutdown sys surveillance.primary coolant sys surveillance requirements, tendon corrosion & anchor assemblies Implementation schedule & SAR encl 4 Public Service Co of Colorado 82/10/15 54pp 15827 061 24X Fiche 50-267.82/10/15.8210270104
- 8210220404 Ack receipt of 820819 response to App A items of IE Emergency Preparedness Appraisal Rept 50-267/82-01, Addl info needed to complete evaluation of response MADSEN.O L. Division of Resident. Reactor Project & Engineering Programs 82/10/19 LEE, OR Public Service Co of Colorado 2pp 13779 160 24% Fiche 50-267, 82/10/19, 8210220404
- R Periodic operating reports & related correspondence
- B210130344 Forwards monthly operating rept for Sept 1982
  WAREMBOURG, D. Public Service Co. of Colorado. 82/10/06
  Director's Office. Office of Inspection and Enforcement, 1p
  15682-030 24X Fichs 50-267, 82/10/06, 8210130344

- --8210130349 Monthly operating rapt for Sept 1982 MCBRIDE:L M Public Service Co of Colorado 82/10/06 5pp 15682 031 24% Fiche 50-267.82/10/06.8210130344
- 8210190655 Forwards monthly operating rept for Sept 1982
  WAREMBDURG, D. Public Service Co. of Colorado. B2/10/12
  GAMMILL.W P. Assistant Director for Operating Reactors. 2pp
  15739, 0B1 24X Fiche 50-267, 82/10/12.8210190655
- --8210190667 Monthly operating rept for Sept 1982 Narrative summary encl MCBRIDE:L M Public Service Co of Colorado 82/10/06 9pp 15739 083 24X Fiche 50-267,82/10/12,8210190655
- S Reportable occurrences, LERs & related correspondence
- 8210050331 Forwards LER 82-035/03L-0 Detailed event analysis encl WAREMBOURG-D Public Service Co of Colorado 82/07/23 COLLINS.J T Region 4, Office of Director 4pp 19602 354 24X Fiche 50-267, 82/07/23, 8210050331
- --8210050337 LER 82-035/03L-0 on 820827, engine i8 of standby generator set 1A rendered inoperable Caused by indicator lamp &/or lamp socket short circuiting causing i5 amp fuse to blow in engine 18,125-volt dc cranking circuit
  FULLER,C Public Service Co of Colorado 82/09/23 Region 4, Office of Director ip 15602 358 24X Fiche 50-247,82/09/23,8210050331
- 8210190537 Forwards LER 82-036/03L-0 Detailed event analysis encl (MARCHBOURG) D Public Service Co of Colorado 82/10/08 COLLINS: J Y Region 4, Office of Director Spp 15751 323 24X Fiche 50-267, 82/10/08, 8210190537
- --8210190543 LER 82-036/03L-0 on 820908 one of two bearing water makeup pumps removed from svc Caused by need to rebuild mechanical seal due to normal wear Seal rebuilt FULLER,C Public Service Co of Colorado 82/10/08 Region 4. Office of Director ip 15751 326 24X Fiche 50-267,82/10/08, 8210190537
- 8210190547 PND-IV-82-037 on 821013 indication of increasing reactor bidg activity & decreasing regeneration train pressure occurred Caused by gassous radioactivity leaking from flanged line in A purification train WESTERMAN.T F. MADSEN.Q L. Region 4. Office of Director 82/10/13 p. 13751 340 24X Fiche 50-267.82/10/13.8210190547
- DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8210010352 Forwards revision to safeguards contingency plan Revision withheld (ref 10CFR73 21)
  TUCKER, H B Dute Power Co 62/09/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 15574 139 24X
  Fiche 50-269, 82/09/17, 8210010352
- 8210260527 Agrees w/determination to locate fire hose stations outside affected fire areas Change from earlier commitment acceptable
  8TGLZ.J F Operating Reactors Branch 4 82/09/23 TUCKER.H B
  Duke Fower Co 2pp 15830 189 24% Fiche 50-269,82/09/23,
  8210260527
- 8210040232 Application to amend Licenses DPR-98, DPR-47 & DPR-55 Amend requests delation of Tech Spec 6 4 2 re site amengency drill & definition of time within which redundant component test must be performed prior to performing maint per Tech Spec TUCKER.H. B Duke Power Co 82/09/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 15586 104 24X Fiche 50-269, 82/09/27, 8210040232
- ---8210040245 Proposed revision to Tech Spec Pages 3 3-4 & 4,4-1 re site amergency drill & time period within which redundant component test must be performed prior to performing maint 4 Duke Power Co. 82/09/27 4pp. 15586
- P Operating license stage documents & correspondence
- 8205130256 Forwards task force on pressurized thermal shock audit of Robinson plant re adequacy of in-plant training programs & operating procedures NRC will conduct similar audit at Brunswick plant.

  NDVAK:T M Assistant Director for Operating Reactors. 82/04/23, PARKER:W Q Duke Power Co. 2pp 13089 038 24X

  Fiche. 50-249, 82/04/23, 8205130256

- B210080036 Responds to FOIA request for documents re pins designed to hold newbron shielding pads in place under accident conditions forwards documents listed on App A FELTON, J M Division of Rules and Records B2/08/13 EDDLEMAN, W Public Interest Research Group in North Carolina 2pp 15669 240 24X Fichs 50-269,82/08/13,8210080036
- --8210080044 Notification of 811009 meeting w/util in Bethesda.MD to discuss broken thermal shield bolts in Unit 1 HAONER.P C Operating Reactors Branch 4 81/10/05 STOLZ.J F Operating Reactors Branch 4 2pp 15669 268 24X Fi
- --8208250417 Discusses broken core barrel assembly thermal shield bolts at Ocones 1 & applicability to other BMF plants Insp of Gcones 3 & other BMF plants w/thermal shield bolts made of same matts recommended GLSHINSKI, J. A. Division of Engineering & Technical Programs 82/03/29 EIBENHULD 0 Division of Licensing 4pp 15669 285 24% Fiche 50-000, 82/08/10,8210080036
- 8210040107 Advises that util response to NRC 820218 ltr will be provided by 821008 Receipt of info from crane vendor & extraordinary analytical work have delayed response TUCKER: H B Dute Power Co 82/09/24 DENTON: H R Defice of Nuclear Reactor Regulation. Director 870LZ.JF Operating Reactors Branch 4 ip 15581 024 24% Fiche 50-269.82/09/24,8210040107
- 8210040232 Applacation to amend Licenses DPR-38, DPR-47 & DPR-55 Amend requests deletion of Tech Spec 6 4 2 resite emergency drill & definition of time within which redundant component test must be performed prior to performing maint per Tech Spec TUCKER, H D Dute Power Co 82/09/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 870L7, JF Operating Reactors Branch 4 3pp 15586 104 24X Fiche 50-269,82/09/27,9210040232
- --8210040245 Proposed revision to Tech Spac Pages 3 3-6 & 6 4-1 re site emergency drill & time period within which redundant component test must be performed prior to performing maint \* Duke Power Co 82/09/27 4pp 15586.107 24X Fiche 50-269.82/09/27.8210040232
- 9210190145 Forwards Amends 113,113 & 110 to Licenses DPR-3B, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs to allow full power operation of Unit 3 during Fuel Cycle 7

  WAGNER, P. C. Operating Reactors Branch 4 82/09/29 TUCKER, H. B. Buke Power Co. 2pp. 15757 341 24X Fithe 50-269, 82/09/29, 82/0190145
- --8210190154 Amends 143,113 & 110 to Licenses BPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs to allow full power operation of Unit 3 during Evel Cycle 7 STOL7.J F Operating Reactors Branch 4. 82/09/29 31pp 15757 343 24X Fiche 50-269, 82/09/29,8210190145
- --8210190161 Safety evaluation supporting Amends 113,113 & 110 to Licenses DFR-30, DFR-47 & DFR-55, respectively \* Office of Nuclear Reactor Regulation Director 82/09/29 App 15758-012 24% Fiche 50-269,82/09/29,8210190145
- --8210170169 Notice of issuance & availability of Amends 113,113 & 110 to Licenses DPR-38, DPR-47 & DPR-55, respectively BTOL7, JF Operating Reactors Branch 4 B2/09/29 2pp 15758 018 24X Fiche 50-269,82/09/29,8210190145
- 3210180323 Responds to 820913 ltr re reactor bldg purge sys Position given in 810707 & 17 ttrs remains unchanged Schedule for submitting info indicating purge sys meets operability requirements requested LAINAS, G.C. Assistant Director for Operating Reactors 82/09/30 Co. Spp. 15745 334. 24X

ongoing NRC research program 11 sys Facility W MSSS plant Declines

> Office of Division of /07,8210130159

re adequacy of info

Office of trating Reactors 8210180055

- --8210180060 Forwards partial response to Franklin Rosearch Ctr draft technical evaluation rept re control of heavy loads, per NUREO-0612
  - NURED-0612
    TUCKER.H B Duke Power Co 82/10/08 DENTON,H R Diffice of Nuclear Reactor Regulation, Director STOLZ.J F Operating Reactors Branch 4 5pp 15720 011 24X Fiche 50-269.82/30/03 82/10/180055
- B210210131 Responds to NRC 820908 ltr transmitting technical evaluator rept on emergency feedwater sys Sys may not meet all current criteria for seismic qualification, but will remain functionally operable during OBE TUCKER, H B Duke Power Co B2/10/13 DENYUN, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactor Branch 4 App 15766-956 24% Fiche 50-269,82/10/13.8210210131
- 8210210407 Application to amend OLs, revising Tech Spec 3 1 allowing full gower operation of Unit 1 for interim period until appropriate safety valve ring settings can be implemented TUCKER. H B Duke Power Co. 82/10/14 DENTON, H R Office of Nuclear Reactor Regulation. Director STOLZ, J F Operating Reactor Branch 4 Bpg 15764 038 24X Fiche 50-269,82/10/14,6210210407
- --8210210411 Proposed revision to Tech Spec 3 1 allowing full power operation of Unit 1 for interim period until appropriate safety valve ring setting can be implemented 4 Dute Power Co 82/10/14 1p 15764 048 24X Fiche 50-269, 82/10/14, 8210210407
- O Inspection reports. IE Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight categories of records in steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 82/08/10 [ONG.D J Winthrep, Stimson, Putnam & Roberts 7pp 15645 063 24% Fiche 50-900.82/08/10.8210070007
- --9210070172 Forwards info re steam generator integrity & ineps at ill operating PWRs.per 750320 & 21 requests Details of ineps. including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach ( GOLLER:K R Division of Reactor Licensing (KRR-1975 anly) 75/03/24 MACCARV:R R Division of Technical Review (NRR-1975 only) 5pp (15645-196 24X Fiche 50-000.82/08/10.021007000)
- 8210150369 Forwards results of investigation of Item 7a of IC Insp. Repts 50-269/82-21, 50-270/82-21 & 50-287/82-21 Deadtime values for gamma spectroscopy analyses of waste gas silver resolite cartridges will cause only insignificant errors TUCKER. H B Duke Power Co 62/08/17 O'REILLY, J P Region 2 Office of Director 2pp 15704 269 24X Fichs 50-269, 62/08/17 6210150369.
- 8210010117 Forwards IE Insp Repts 50-269/82-33, 50-270/82-33 t 50-287/82-33 on 820817-20 No noncompliance noted DANCE H C Division of Project t Resident Programs 82/09/02 TUCKER, H B Duke Power Co 2pp 15566 019 24X Fiche 50-269, 82/09/02,8210010117
- --B210010124 IE Insp Repts 50-269/82-33,50-270/82-33 & 50-287/82-33 on 820817-20 No noncompliance noted Major areas inspected action on previous enforcement matters, auxiliary fredwater header repair & inservice insp procedures CROMLEY, B R., BLAKE, J J Division of Engineering & Technical Programs 82/09/01 8pp 15566-021 24X Fichs 50-269.82/09/12 82/10010117
- 8210010198 Forwards IE Insp Repts 50-249/62-30, 50-270/82-39 & 90-287/82-30 on 820716-0810 No noncompliance noted DANCE, H C Division of Project & Resident Programs (82/09/02 TUCKER, H D Duke Power Co 2pg 15567 258 24X Fiche 50-269, 82/09/02,8210010158
- --8210010166 IE Insp Repts 50-269/82-30, 50-270/82-30 & 50-207/82-30 p 820716-0810 No noncompliance noted Major areas inspected operations, surveillance testing, maint, NUREO-0737 mods & refueling activities

  ORDERS, W. FALCONER, D. BRYANT, J. C. Division of Project & Reiler Programs 82/09/02 13pp 15567 260 24X Fiche 50-269, 82/09,% 8210010138
- 8210010458 Ack receipt of 820805 ltr informing NRC of steps takes to correct violations noted in IE Insp Repts 50-269/82-23, 50-289/82-23
  LEWIS:R C Division of Project & Resident Programs 82/09/17 TUCKER.H.B Duke Power Co ip. 15570 182 24X
  Fithe. 50-269, 82/09/17, 8210010458

- --8210010463 Responds to NRC 820712 ltr re violations noted in 1E Insp Repts 50-269/82-23.50-270/82-23 & 50-287/82-23 Corrective actions personnel counseled & valve 2Pr-14 cut out & properly reinstalled TUCKER.H.B. Dute Power Co. 82/08/05 D'REILLY, J.P. Region 2, Office of Director 4pp 15570 183 24X Fiche 50-269.82/09/17, 8210010458
- --8210010468 Forwards IE Insp Repts 50-269/82-23,50-270/82-23 & 50-287/82-23 on 820510-0610 % notice of violation LEWIS,R C Division of Project & Resident Programs 82/07/18 PARKER,W D Duke Power Co 2pp 15570 187 24% Fiche 50-269,82/09/17.8210010458
- --8210010471 Notice of violation from insp on 820510-0610 \* Division of Project & Resident Programs 82/07/12 2pp 15570 189 24X Fiche 50-269,82/09/17,8210010458
- --9210010474 IE Insp Repts 50-269/82-23.50-270/82-23 t 50-287/82-23 un 820510-0610 Noncompliance noted failure to follow procedures resulting in plant trip to inadequate procedure resulting in improper reassembly of safety-related valve ORDERS.W. FALCONER.D. BRYANT.J.C. Division of Project & Resident Programs 82/07/09 12pp 15570 191 24X Fiche 50-269.82/09/17, 8210010458
- 5210150253 Forwards IE Insp Repts 50-269/82-32, 50-270/82-32 & 50-287/82-32 on 820817-18 No noncompliance noted DANCE.N C Division of Project 7, Resident Programs 82/09/17 TUCKER.N B Duke Power Ca 2pp 15703 267 24X Fiche 50-269, 82/09/17, 8210150253
- --8210150263 1E [nsp Repts 50-269/82-32, 50-270/82-32 & 50-287/82-32 on 820817-18 No noncompliance noted Major areas inspected lab QC & review of radiochemistry procedures & records EVANS.C D . MONTODHERY.D M Division of Emergency Preparedness & Operational Support 82/09/15 3pp 15703 269 24X Fiche 50-269, 82/09/17, 8210150253
- ⊕≥1015083: Forwards IE Insp Repts 50-269/82-35,50-270/82-35 & 50-287/82-35 on 820908-10 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/23 TUCKER.H B Duke Power Co 2pp 15698 312 24X Fiche 50-267,82/09/23.8210150131
- -- 8210150143 IE Insp Repts 50-269/82-35,50-270/82-35 & 50-287/82-35 on 820708-10 No noncompliance noted Hajor areas inspected RCS leakage calculations BURNETT.P T , JAPE.F Division of Engineering & Technical Programs 82/09/21 4pp 15698 314 24% Fiche 50-269,82/09/23,8210150131
- 문교10130290 Requests relief from inservice inspirequirements
  (hydrostatic) of Section XI of ASME Boiler & Pressure Vessel
  Code
  TUCKER.H IP Duke Power Co 82/10/04 DENTON, H R Office of
  Nuclear Reactor Regulation, Director STOLZ, JF Operating Reactors
  Branch 4 20pp 15578 243 24% Fiche 30-269, 82/10/04, 8210130290
- B210220426 Forwards Revision 5 to response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " TUCKER.H B Dute Power Co 82/10/08 O'REILLY, J P Region 2, Office of Director 24pp 15778 273 24X Fiche 50-269,82/10/08, 52:10220426
- B210150285 EN-82-021A on 821012, order imposing civil monetary penalty issued to licensee Action based on failure to follow procedures affecting safe operation of facility BARBER. 9. AXELRAD. J Director's Office, Office of Inspection and Enforcement 82/10/12 ip 15701 319 24X Fiche 50-269.82/10/12.8210150285
- DEOB190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys
  Paping at BWR Plants " Svo list encl
  DEYOUNG, R C Director's Office, Office of Inspection and
  Enforcement B2/10/14 Consolidated Edison Co of New York,
  115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- R. Periodic operating reports & related correspondence
- ⇒210190544 Forwards monthly operating repts for Bept 1982 TUCKER.H B Duke Power Co 82/10/15 Director's Office, Office of Inspection and Enforcement 1p 15751 343 24X Fiche 90-269, 82/10/15.8210190544

- --8210190552 Monthly operating repts for Sept 1982 REAVIS.J A Duke Power Co 82/10/15 16pp 15751 344 24x Fiche 50~269,82/10/15,8210190504
- S Reportable occurrences. LERs & related correspondence
- 8210150077 Forwards LER 81-001/03L-0 Detailed event analysis encl PARKER, W O Duke Power Co 81/02/04 O'REILLY, J P Region 2, Atlanta, Office of the Director (81/03/01) 3pp 15697 063 24) Fiche 50-267, 81/02/04, 8210150079
- --8210150084 LER Bi-001/03L-0 on 810105, turbine trip from 90% full power occurred Caused by loss of excitation on generator field resulting from mismatch during personnel attempt to raise volt ampores reactive on Units 1 & 2
  JONES, J L Dute Power Co B1/02/04 Region 2, Atlanta, Office of the Director (81/03/01) ip 15697 066 24X
  Fiche 50-269,81/02/04.8210150079
- BRIODIODOB Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 009 24X Fiche 50-000.82/06/28,9210010008
- --8210040374 Forwards LER 80-20/03L & RO 269/80-9 re failure to open auxiliary feedwater valve & failure of fire detection sys, respectively AddI attention may be warranted BENDER.M ACRE Advisory Committee on Reactor Safeguards 80/05/23 FRALEY.R F. ACRE Advisory Committee on Reactor Safeguards 1p 15727 272 24X Fithe 50-000,82/06/28,8210010008
- 8210190653 PNG-II-82-111 on 821014. Unit 2 shut down after determining that pressurizer code safety valve design flow could not be fully maintained if called upon Seven-day outage required to change valves Exemption requested for Unit 1 IGNATONIS.A. DANCE.HC Region 2. Office of Director 82/10/14 2pp 15740 036 24X Fiche 50-269.82/10/14.8210190653
- 8210290395 Forwards LER 82-014/03L-0 Detailed event analysis encl TUCKER.H B Duke Power Co 82/10/14 O'REILLY, J P Region 2. Office of Director. 3pp 15893 043 24X Fiche 50-269,82/10/14, 8210290355
- --8210290365 LER 82-014/03L-O between 820816-0920, reactor bldg conling unit fam iA tripped on low speed thermal overloads seven times Cause unknown Fan under surveillance Fan motor may be replaced if cause of trips cannot be determined PETTY, J C Duke Power Co 82/10/14 Region 2, Office of Director ip 15853 046 24X Fiche 50-269,82/10/14,8210290355
- 8210290190 Forwards LER 82-015/03L-0 Detailed event analysis encl TUCKER, H D Dute Power Co 82/10/15 O'REILLY, J P Region 2. Office of Director 3pp 19853 287 24X Fiche, 50-269, 62/10/15, 8210290190
- --8210290197 LER 82-015/03L-0 on 820917, reactor protection sys trip pushbutton declared technically inoperable Caused by procedure deficiency which did not include required test, Necessary procedures changed PETTY, J C Duke Power Co 82/10/15 Region 2, Office of Director 1p 15853 290 24X Fiche 50-269,82/10/15,8210290190

DOCKET 50-270 GCONEE NUCLEAR STATION: UNIT 2

- A Application/construction stage documents & correspondence
- 821001000B Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON, J. M Division of Rules and Records 82/06/28 UDELL, R. A. Critical Mass Energy Project 15pp 19727 005 24X Fiche 50-000, 82/06/28, 8210010000B
- --B204290048 Recommends prompt attention be given to problem of reactor coolent pump closure stud corrosion detected at facilities.
  Response by 820419 requested
  EISENHUT, D O Division of Licensing 82/03/24 HANAUER, S H
  Division of Systems Integration (post 811005) 3pp. 15745 270
  24% Fiche: 50-000, 82/06/28, 8210010008
- F Security, medical, emergency & fire protection plans
- B210010352 Forwards revision to tafeguards contingency plan Revision withheld (ref 10CFR73 21).

  TUCKER, H, B Dute Power Co 82/09/17. DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 15574 139 24X Fiche 50-269, 82/09/17, 8210010352.

- 9210260929 Agrees w/determination to locate fire hose stations outside affected fire areas Change from seriier commitment acceptable STOLZ, J.F. Operating Reactors Branch 4 92/09/23 TUCKER, H.B. Duke Power Co. 2pp. 19830
- 8210040232 Application to amend Licenses DPR-38. BPR-47 & DPR-55 Amend requests deletion of Tech Spec 6 4 2 Te site emergency drill & definition of time within which redundant component test must be performed prior to performing maint per Tech Spec TUCKER.H B Duke Power Co 82/09/27 DENTON.H A Defice of Muclear Reactor Regulation, Director 3pp 15886 104 24% Fiche 50-249.82/09/27,8210040232
- --8210040245 Proposed revision to Tech Spec Pages 3 3-6 & 6 4-1 re site smargency drill & time period within which redundant component test must be gerformed prior to performing maint + Duse Power Co 82/09/27 4pp 15586 107. R44 Fiche 50-269, 82/09/27, 8210040232

## P Operating license stage documents & correspondence

- B2100B0036 Responds to FOIA request for documents re pins designed to hold neutron shielding pads in place under accident consistions forwards documents listed on App A FELTON. J M Division of Rules and Records 82/08/13 EDDLEMAN, W Public Interest Research Oroup in North Carolins 2pp 15669 240 24X Fichs 50-289,82/08/13.82100B0036
- 8210040107 Advises that util response to NRC 820218 ltr will be provided by 821008 Receipt of info from crane vendor & extraordinary analytical work have delayed response TUCKER.H B Duke Power Co 82/09/24 DENTON.H R Office of Nuclear Reactor Regulation, Director STOLZ.J.F Operating Reactors Branch 4 1p 15581 024 24% Fichs 50-269.82/09/24,8210040107
- 82(0040232 Application to amend ticenses DPR-3B:DPR-47 & DPR-55 Amend requests deletion of Tech Spec 6 4 2 re site emergency drill & definition of time within which redundant component test must be performed prior to performing maint per Tech Spec TUCKER. H B Duke Power Co 62/09/27 DENTON. H Office of Nuclear Resulation, Director STOL. J. F Operating Reactors Branch 4 3pp 15388-104 24% Fishe. 50-269.82/09/27, 82/09/27.82/090833
- ~~8210040245 Proposed revision to Tech Spec Pages 3 3-6 & 6 4-1 re sitp emergency drill & time period within which redundant component test must be performed prior to performing maint a Duke Power Co 82/09/27 4pp 15586 107 24X Fiche 50-269,82/09/27,8210040232
- B210190145 Forwards Amends (13,113 & 110 to Licenses DPR-3B, DPR-47 & DPR-55. respectively, safety avaivation & notice of issuance & avaitability Amends revise Tech Specs to allow full power operation of Unit 3 during Fuel Cycle 7
  WAGNER, P.C. Operating Reactors Branch 4 B2/09/29 TUCKER, H B
  Duke Fower Co. 2pp 18757 341 24X Fichs: 50-269, 82/09/29, 82/01/0145
- --8210190154 Amends 113.113 % 110 to Licenses DPR-38, DPR-47 % DPR-55, respectively, revising Tech Spacs to allow full power operation of Unit 3 during Fuel Cycle 7 BTOLZIJ P. Operating Reactors Branch 4 82/09/29 Sipp 15757:343 24X Fiche 50-249.82/09/29.8210190145
- --8210190161 Bafety evaluation supporting Amends 11G,113 & 110 to Licenses DPR-38,DPR-47 & DPR-55-respectively. Defice of Nuclear Reactor Repulation, Director 82/09/29 App 15758 012 24X Ficha 50-269,82/09/29,8210190145.
- --B210190169 Notice of issuance & availability of Amends 113,113 & 110 to Licenses DPR-3B, DPR-47 & DPR-3B, braspectively SYOLX.JF Gparating Reactors Branch 4 82/09/29 20p 18758 018 24X Fiche: 50-269, 82/09/29,8210190145
- 8210180323 Responds to 820913 itr re reactor bldg purgs sys Position given in 810707 & 17 ltre remains unchanged. Bchedula for submitting info indicating purge sys meets operability requirements requested LAINAS.O.C Assistant Director for Operating Reactors. 82/09/30. TUCKER.H. B. Dute Power Co. 3pp. 15745:334 24% Fiche 80-269.82/09/30.8210180323
- 8210180055 Responds to NRC 82060B request for add1 info re adequacy of station electric distribution sys voltages. Requested info expected by 821022.
  TUCKER, H B. Duke Power Co. 82/10/08. DENTON: H R. Office of Nuclear Reactor Regulation, Director. BTDLZ, J F. Operating Reactors Branch 4. 1p. 15720.010. 24% Fiche 50-269,82/10/08.8210180055.

- \*\*\*B210180060 Forwards partial response to Franklin Research Ctr deals technical evaluation rept re control of heavy loads.per NUREG-0612

  TUCKER,H B Duke Power Co B2/10/08 DENTON,H R Defice of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 Spp 15720 011 24X Fiche 50-269,82/10/02
- 8210210131 Responds to NRC 820708 itr transmitting technical evaluation rept on emergency feedwater sys Sys may not meet all current criteria for seismic qualification, but will remain functionally operable during OBE TUCKER: H B Duke Power Co 82/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Decrating Reactor Branch 4 App 15766-356 24X Fiche 50-269, 82/10/13, 82(021013)
- 8210210407 Application to amend DLs, revising Tech Spec 3 1 allowing full power operation of Unit 1 for interim period until appropriate safety valve ring settings can be implemented TUCKER. H B Dute Power Co 82/10/14 DENTON-H R Office of Nuclear Reactor Regulation, Director STOLZ. J F Operating React: Branch 4 Bpp 13764 038 24% Fiche 50-267,82/10/14,8210210407
- --82102104ti Proposed revision to Tech Spec 3 I allowing full power operation of Unit 1 for interim period until appropriate safety valve ring setting can be implemented a Duke Power Co 82/10/14 ip 15764 048 24X Fiche 50-269,82/10/14,8210210407
- Q Inspection reports, IE Bulletins & correspondence
- 8210070037 Responds to FOIA request for eight categories of records is steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed (n App B FELTON, J M Division of Rules and Records 82/08/10 LONO, D J Hinthrop, Stimson, Putham & Roberts 9pp 15645 063 24X Fiche 80-900, 82/08/10,8210070007
- --8210070172 Forwards info to steam generator integrity & image at all operating PMRs.ger 750320 & 21 requests Details of inage. including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach & QOLLER.K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY.R R Division of Technical Review 1989-1975 only) Spp. 15445 196 24X Fiche 50-000,82/08/10,8210070007
- 8210150369 Forwards results of investigation of Item 7a of IE Inty-Repts 50-269/82-21.50-270/82-21 & 50-267/82-21 Deadtime values for gamma spectroscopy analyses of waste gas silver reolite cartridges will cause only insignificant errors TUCKER, H B Dute Power Go 82/08/17 O'REILLY, J P Region 2, Office of Director 2pp 13704 269 24X Fishe 50-269.02/03/17.6210150369
- 8210010117 Forwards 1E Insp Repts 50-269/82-33,50-270/82-33 & 50-287/82-33 on 820817-20 No noncompliance noted DANGE.H.C Division of Project & Resident Programs 82/09/02 TUCKER.H B Duke Power Ca 2pp 15566 019 24X Fiche: 50-269, 82/09/02, 8210010117
- --8210010124 IE Insp Repts 50-269/82-33, 30-270/82-33 2 50-287/82-33 on 820817-20 No noncompliance noted Major areas inspected action on previous enforcement matters, auxiliary feedwater header repair & inservice insp procedures CROMLEY, B R , BLAKE, J J Division of Engineering & Technical Programs 82/09/01 Spp 15566 021 24% Fiche 50-269,82/09/28 8210010117
- 8210010158 Forwards IE Insp Repts 50-269/82-30, 50-270/82-30 & 50-287/82-30 on 820716-0810 No noncompliance noted DANCE, M. C Division of Project & Resident Programs 62/09/02 TUCKER, M. B Duke Power Co 2pp 15567 258 24% Fiche 50-269, 82/09/02, 8210010158
- ---8210010166 IE Insp Repts 50-267/82-30, 50-270/82-30 & 50-287/82-30 a 820716-0810 No noncompliance noted Major areas inspected operations, surveillance testing, maint, NUREO-0737 mode & refueling activities
  ORDERS, N. FALCUNER, D., BRYANT, J. C. Division of Project & Reside Programs. 82/09/02 13pp 15567 260, 24X Fiche 50-269, 82/041
- 6210010458 Ack receipt of 820805 itr informing NRC of steps talent torrect violations noted in IE Inep Repts 50-269/82-23, 50-270/82-23 t 30-287/82-23 LEMIS, R.C. Division of Project & Resident Programs 82/09/17. TUCKER, H B Dute Power Co ip 15570, 182, 24X Fiche: 50-269, 82/09/17, 8210010458

## DOCKETED ITEMS

- --8210010463 Responds to NRC 820712 ltr re violations noted in IE Insp Repts 50-249/82-23.50-270/82-23 & 50-287/82-23 Corrective actions personnel counseled t valve 2HP-14 cut out & properly reinstabled TUCKER, H B Duke Power Co 82/08/05 O'REILLY, J P Region 2, Office of Director 4pp 15570 183 24X Fiche 50-269, 82/09/17, 82(00)10458
- --B210010468 Forwards IE Insp Repts 50-269/82-23,50-270/82-23 & 50-287/82-23 on B20510-0610 & notice of violation LEWIS.R C Division or Project & Resident Programs 82/07/12 PARKER.W O Dive Power Co 2pp 15570 187 24X Fiche 50-269,82/09/17.8210010458
- --8210010471 Natice of violation from insp on 820910-0610 \* Division of Project & Resident Programs 82/07/12 2p 15970 189 24% Fiche 50-269, 82/09/17/8210010458
- --B210010474 IE Insp Repts 50-269/B2-23.50-270/B2-23 & 50-2B7/B2-23 on B20510-0610 Noncompliance noted failure to follow procedures resulting in plant trip & inadequate procedure resulting in improper reassembly of safety-related valve BRDERS, W. FALCOMER.D. BRYANT.J.C. Division of Project & Resident Programs 82/07/07 12pp 15570 191 24X Fiche 50-269.B2/09/17.B210010458
- 6210150253 Forwards IE Insp Repts 50-269/82-32.50-270/82-32 & 50-287/82-32 on 820817-18 No noncompliance noted DARCE. H C Division of Project & Resident Programs 82/09/17 TUCKER, H B Duke Power Co 2pp 15703 267 24X Fiche 50-269.82/09/17.8210150253
- --8210150263 1E Insp Repts 50-269/B2-32,50-270/B2-32 & 50-287/B2-32 on 820817-18 No nancompliance noted Major areas inspected lab QC & revieu of radoctemistry procedures & records EVAUS.C D , MONTOOMERY.D II Division of Emergency Preparedness & Operational Support 82/09/15 3pp 15703 269 24X Fiche 50-269,82/09/17,8210150283
- 6210150131 Forwards IE Insp Repts 50-269/82-35,50-270/82-35 & 50-287/82-35 on 820908-10 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/09/23 TUCKER, H B Duke Power Co 2pp 15698 312 24X Fiche 50-269, 82/09/23, 8210150131
- -8210150143 IE Insp Repts 50-269/82-35,50-270/82-35 & 50-287/82-35 on 820708-10 No noncompliance noted Major areas inspected RCS leakage calculations
  BURNETT, P T . JAPE.F Division of Engineering & Technical Programs 82/09/21 4pp 15678 314 24X Fiche 50-267,82/09/23, 8210150131
- 9210130290 Requests relief from inservice insp requirements (hydrostatic) of Section XI of ASME Boiler & Pressure Vessel Code TUCKER, H B Duke Power Co 82/10/04 DENTON, H R Office of Muclear Reactor Regulation, Director STOLZ, JF Operating Reactors Branch 4 20pp 15678 243 24X Fiche 50-269, 82/10/04, 8210130290
- B20B190233 | E Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds" Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards B2/10/06 Consolidated Edison Co of New York 64pp 15761 250 244 Fiche 50-000.82/10/06,8208190233
- 8210220424 Forwards Revision 5 to response to IE Bulletin 77-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts"

  TUCKER, H B Duke Power Co 82/10/08 O'REILLY, J P Region 2, Office of Director 24pp 15778 273 24X Fiche 50-269, 82/10/08, 8210220424
- 620Bi9023B IE Bulletin 82-03, "Btress Corrosion Cracking in Thick-Wall Large-Diameter, Stainless Steel, Rectroulation Bys Piping at DNR Plants "Svc list encl peryOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York, 115pp 15810 125 24X Fiche 50-000, 82/10/14,820Bi9023B
- R Periodic operating reports & related correspondence
- 8210190544 Forwards monthly operating repts for Sept 1982 TUCKER, H B Duke Power Co 82/10/15 Director's Office of Inspection and Enforcement ip 15751 343 24X Fiche 50-269, 82/10/15.8210190544
- --8210190552 Monthly operating repts for Sept 1982 REAVIS, J A Duke Power Co 82/10/15 16pp 15751 344 24X Fiche 50-269,82/10/15,8210190544

- S Reportable occurrences, LERs & related correspondence
- 8210190653 PNO-II-82-111 on 821014. Unit 2 shut down after determining that pressurizer code safety valve design flow could not be fully maintained if called upon Seven-day outage required to change valves Exemption requested for Unit 1 IGNATONIS. A. DANCE, H. C. Region 2. Office of Director 82/10/14 2pp 15740 036 24% Fiche 30-269.82/10/14.8210190653
- 8210170695 RO on 821014. Unit 2 core relief valves declared inoperable due to analysis prompted by BRW safety concern Unit 3 valves were offsite undergoing ring adjustment Immediate shutdown of Unit 2 commenced Duke Fower Co 82/10/14 Region 2, Office of Director ip 15736 200 24% Fishe 50-270.82/10/14,8210190645
- 8210290083 Forwards LER 82-012/03L-0 Detailed event analysis encl TUCKER.H B Duke Power Co 82/10/15 O'REILLY, J P Region 2, Office of Director 2pp 15854 047 24X Fiche 50-270,82/10/15, 8210290083
- --B2102900B7 LER 82-012/03L-0 on 820714, turbine driven emergency feedwater pump declared inoperable when trip/throttle valve 2MS-74 discovered tripped in closed position Cause not known Valve resut Video alarm will be repaired PETTY.J C Duke Power Co 82/10/15 Region 2, Office of Director ip 15854 049 24X Fiche 50-270, 82/10/15, 8210270083
- DOCKET 50-271 VERMONT VANKEE NUCLEAR POWER STATION

  F Security, medical, amergency & fire protection plans
- 8210120346 Informs that Revision 6 to physical security plan acceptable Encl to 820720 ltr transmitting revision withheld (ref 10CFR73 21)
  VASSALLO, D B Operating Reactors Branch 2 82/09/22 SINCLAIR, J B
  - VASSALLO, D B Operating Reactors Branch 2 82/09/22 SINCLAIR. J B Vermont Yankee Nuclear Power Corp 2pp 15691 101 24X Fiche 50-271.82/09/22.8210120346
- 8210210221 Forwards IE Safeguards Insp Rept 50-271/82-15 on 820728-30 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/10/04 SINCLAIR.J B. Vermont Yankee Nuclear Power Corp 2pp 15766 331 244 Fische 50-271.82/10/04.8210210221
- --8210210238 IE Safeguards Insp Rept 50-271/82-15 on 820728-30 No noncomptiance neted Major areas inspected facility organization measurement & controls shipping & receiving storage & internal control & physical inventory DELLA RATTA: A. WOLTNER, E.F. 000Y. A.T. Division of Engineering & Technical Programs B 82/09/30 7pp 15766-339 24X Fiche 50-271,82/10/04.8210210221
- B210270426 Releases public version of revised emergency plan FELTON, J M Division of Rules and Records 62/10/08 Document Management Branch 1p 19833 054 24X Fiche 50-271, 82/10/08, B210270426
- --8210270430 Forwards public version of Revision 4 to emerge MARKT.D.I Vermont Vankee Nuclear Power Corp. MARKT.D. Atomic Electric Co 82/09/30. Office of Nuclear Reac Regulation Director 2pp 15833 055 24X Fiche 50-27 8210270426
- --8210270432 Public version of Revision 4 to emergency plan MURPHY, W F Vermont Yankee Nuclear Power Corp 82/09/28 15833 097 24X Fiche 50-271,82/10/08,8210270426
- 8210180190 Forwards additinfo requested in 820812 telcon repratternate shutdown sys Encl info addresses separate routing of cables for valves FCV 2-17 & FCV 2-18 & RHR valves VIO-17 & VIO-18 MARSOLAIS, D Vermont Yankes Nuclear Power Corp 82/10/11 VASSALLO, D B Operating Reactors Branch 2 2pp 15719 118 Fichs 80-271, 82/10/12, 8210180190
- 8210220411 Ack receipt of 820908 itr informing NRC of steps to correct violations noted in 1E Insp Rept 50-271/82-05.
  ALLANJIM Region 1, Office of Director 82/10/12 MURPH) Vermont Yankse Nuclear Power Corp. 1p. 15780 228 24X Fichs 50-271, 82/10/12, 8210220411
- --8210220418 Responds to NRC B20722 itr re violations noted if Rept 50-271/82-05 Corrective actions study performed to determine how intent of augmentation goals of NVREG-0654 could be achieved after declaration of emergency.

  MURPHY.W P Vermont Yankee Nuclear Power Corp. 82/09/08 SMITH, 0 H Division of Emergency Preparedness & Operation Bupport. 29pp 15780 229 24X Fiche 50-271,82/10/12,821

- 8210280136 Releases public version of emergency plan itrs of agreement FELTON, J N Division of Rules and Records 82/10/12 Document Management Branch 1p 15862 248 24X Fiche 50-271,82/10/12.
- --B210280438 Forwards public version of errata to Change 4 to emergency plan App E. consisting of ltrs of agreement between licensee & States of V.T.M. & N.H.NDA.US Air Force & various local hosps & businesses Receipt form and HARKT.D. Vermont Yankee Nuclear Power Corp. MARKT.D. Vermont Yankee Nuclear Power Corp. MARKT.D. 240.000 S2/10/05 Office of Nuclear Reactor Regulation. Director ip 15862 249 24X Fiche 50-271.82/10/12, 8210280136
- -- B210280143 Public version of strats to Change 4 to energency plan App E. consisting of ltrs of agreement between licensee & States of VT.MA & NH.NDAA.US Air Force & various local hosps & businesses a Vermont Yankee Nuclear Power Corp & Yankee Atomic Electric Co B2/10/05 Pipp 15862 250 24X Fiche 50-271.82/10/12.
- P Operating license stage documents & correspondence
- 8210210185 Forwards safety evaluation of methods used for analysis of physics & thermal-hydraulic performance VASSALLO.D B Operating Reactors Branch 2 82/09/15 SINCLAIR, J D Vermont Yankee Nuclear Power Corp. 2pg. 15774 270 24X Fiche 50-271-32/09/15,8210210185
- --B210210200 Safety evaluation supporting reload analysis methods based on review of technical repts submitted by util re analysis of physics & thermal-hydraulic performance BROOKS, H . H931, Y . ROQNEY, V . Office of Nuclear Reactor Regulation. Director B2/09/15 27pp 15774 272 24% Fichs 50-271.82/09/15.8210210185
- 8210210104 Forwards Amend 72 to License DPR-28, safety evaluation & notice of issuance & availability Amend incorporates revised core thermal hydraulic limiting conditions of operation during Fuel Cycle 9 ACONEY.V L Operating Reactors Branch 2. 82/09/16 SINCLAIR, J B Vermont Yankee Nuclear Power Corp 2pp 13774 301 24X Fiche 50-271, 62/09/16, 6210210101
- ~~B210210112 Amend 72 to License DFR-2B, changing Tech Specs to incorporate revised core thermal hydraulic limiting conditions during Funl Cycle 9
  VASSALLO, D B Operating Reactors Branch 2 82/09/16 App 15774 303 24X Fiche 50-271.82/09/16.8210210101
- --8210210121 Safety evaluation supporting Amend 72 to 1.tcente DDR-28 \* Office of Nuclear Reactor Regulation, Director 82/09/16 App 15774 307 24X Fiche 50-271,82/09/16,8210210101
- --6210210127 Notice of issuance & availability of Amend 72 to License BPR-28 VASSALLO,D B Operating Reactors Branch 2 82/07/16 2pp 15774 311 24% Ficher 80-271-82/07/16.8210210101
- 8210040113 Comments on systematic assessment of licenses performance rept.discussed at 820708 meeting Rept fair appraisal of activities for rept period MURPHY.W P Vermont Yankes Nuclear Power Coop 82/09/28 STAROSTECKI.R Division of Project & Resident Programs 2pp 15581 144. 24X Fichs 30-271,82/09/28.8210040113
- 8210120343 Requests listing of submittals re inservice testing program within 30 days
  VASBALLO,D B Operating Reactors Branch 2, 82/09/28 SINCLAIR.J B Vermont Yankee Nuclear Power Corp 2pp 15691 089 24X Fichs 50-271.82/09/28.8210120343
- 82:0150447 Informs that revision to administrative section of Tech Specs re shift manning requirements & working hour guidelines not appropriate Suitable controls already imposed & will be subj to insp & enforcement by Region 1 MURPHY. W P Vermont Yankse Nuclear Power Corp. 82/10/12 EISENHUT, 9 0 Division of Licensing 1p. 15705 028 24X Fiche 50-271, 82/10/12,8210150447
- 8210270356 Advises that util response to NUREO-0578 also satisfies NUREO-0737. Item II E 4 i, "Bedicated Hydrogen Penetrations" I tem resolved. VASBALLO, D B Operating Reactors Branch R 62/10/14 BIMCLAIR. J B Vermont Yankee Nuclear Power Corp is 15834 359 24X Fiche. 30-271. 82/10/14. 8210270356.

- G Inspection reports. IE Bulletins & correspondence
- 8210050448 Forwards request for add1 info based on review of 800707 & 1110 responses to IE Builetin 80-11 re masonry wall design VASSALLO, D B. Operating Reactors Branch 2 82/08/30 SINCLAIR, J & Vermont Yankee Nuclear Power Corp. Spp. 15612 357 24X Fiche 50-271, 82/08/30, 8210050448
- 8210070376 Forwards IE Insp Rept 50-271/82-16 on 820802-30 No noncompliance noted STARDETECKI.R Division of Project & Resident Programs 82/09/24 SINCLAIR.J B Verment Yankee Nuclear Power Corp 2pp 15633 3£0 24.4 Fiche 50-271.82/09/24.8210070376
- --B210070393 IE Insp Rept 50-271/B2-16 on B20802-30 No noncompliance noted Major areas inspected previous insp findings.plant operations.physical security.operational surveillance, maint activities & safeguard sys operability RAYMOND.W J. OALLO.R M. Division of Project & Resident Programs B2/09/22 16pp 19634 001 24x Fiche 50-2/1.82/09/24.82(0070376
- B210010136 Advisos that all future correspondence from Region 1 (211) be addressed to MP Murphy Change will assure direct communication to senior licensee mgt re NRC inspleinings, enforcement actions or requests HAYNES.R C. Region 1. Office of Director 82/09/27 MURPHY.H P Vermont Yankee Nuclear Power Corp. 3pp. 19567 237 24X Fiche 50-271, 82/09/27, 8210010136
- 9210150246 Forwards IE Insp Rept 50-271/8P-14 on 920706-30 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 62/09/22 BINCLAIR, J B Vermont Yankee Nuclear Power Corp 2pp 15704 331 24X Fiche 50-271.82/09/27.8210150246
- --9210150298 Notice of violation from insp on 820706 30
  # Division of Project & Resident Programs 82709727 Lp
  15704 336 24X Firhe 50-271.82709727.8210150246
- --8210150274 IE Insp Rept 50-271/82-14 on 820706-30 Noncompliance noted failure to post hot spot radiation area per plant Administrative Procedure 0503 & Tech Spets RAYMOND. & J. COLLINS. B. J. GALLO. R. M. Division of Project & Resident Programs 02/07/21 20pp 15704 337 24% Fiche 50-271,82/09/27,8210150244
- 82100401i3 Comments on systematic assessment of licenses performance rept.discussed at 820908 meeting Rept fair appraisal of activities for rept period
  MCRPHY BP Vermant Vankee Nuclear Power Corp 82/09/20
  STAROSTECKI, R Division of Project & Resident Programs 2pp
  15591 144 24X Fichs 50-271,82/09/28,8210030113
- 8210210221 Forwards IE Safeguards Insp Rept 50-271/8P-15 on 620 A-8-3. No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 92/10, SINCLAIR, J B Vermont Yankes Nuclear Power Corp 2pp 1576.5 Div
- --8210210238 IE Bafeguards Insp Rept 90-271/B2-15 on 820728-10 No mencompliance noted Major areas inspected facility organization, measurement & controls, shipping & receiving storage & internal control & physical inventory DELLA RATTA.A. WOLTNER: E.F., CODY, A.T. Division of Engineering Technical Programs 82/09/30 7pp 15766-333 24X Fiche, \$0-271,82/10/04,8210210221
- 8208190233 lE Info Notice 80-35, Suppl 1. "Leaking & Dislodged 3-124 fmplent Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York & Sapp 15761 2' 24X Fiche 50-000,82/10/06.8208190233.
- 9210150267 EN-92-033 on or about 921015, notice of violation to motice civil penalty will be taxued Action based on violation refailure of station personnel to promptly recognize changes in status of safety-related equipment CRAIG.J. AXELRAD.J. Region 1. Office of Director 82/10/12 1 15703 244 24X Fiche 30-271,82/10/12,8210190267
- 8210220411 Ack receipt of 820908 ltr informing NRC of steps taken; correct violations noted in IE Insp Rept 50-271/82-05 ALLAN.J N Region I. Office of Director 82/10/12 HURPHY, M p Vermont Yankse Nuclear Power Corp ip 18780 228 24X Fiche 50-271.82/10/12.8210220411

- -8210220418 Responds to NRC 820722 ltr re violations noted in IE Insp Rept 50-271/82-05 Corrective actions study performed to getermine now intent of augmentation goals of NURGE-0654 could be achieved after declaration of emergency MURPHY, WP Vermont Vankee Nuclear Power Corp 82/09/08 SMITH G H Division or Emergency Preparedness & Operational Support 29pp 15780 229 24X Fiche 50-271,82/10/12,8210220411
- 6308190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Mallitarge-Diameter.Stainless Stool.Recirculation Sys Piping at BWR Plants "Syc list encl DEYQUNO.B C Director's Office Office of Inspection and Enforcement 62/10/14 Consolidated Edison Co of New York 115pp (5810-125 24X Fiche 50-000.82/10/14.8208190238
- A Periodic operating reports & related correspondence
- S210130189 Forwards monthly operating rept for Sept 1982 MURPHY, W.P. Vermont Vankee Nuclear Power Corp. 82/10/08 Management Information Branch 1p 15674 107 24X Fiche 50-271, 82/10/08, 8210130189
- --8210133193 Monthly operating rept for Bept 1982 BURGER, F. J. Vermont Yantoe Nuclear Power Corp. 82/10/08 6pp 15674 108 24X Fiche 50-271,82/10/08,8210130189
- S Reportable occurrences, LERs & related correspondence
- 9210190022 Forwards LER 82-020/03L-0
  PELLETIER, J P Vermont Yanker Nuclear Power Corp 82/10/05
  HAYNES, R C Region 1, Office of Director 1p 15742 139 24X
  Fiche 50-271, 82/10/05, 8210190022
- --8210190029 LER 82-020/03L-0 on 820902, indication on RHR 898 blinked on & off at 2,700 gpm flow rate Indication lost when valve shut Caused by loase wiring on valve limit switch resulting in loss of position indication Connection tightened PELLETIER. J P Vermont Yankee Nuclear Power Corp 82/10/05 Region 1. Diffice of Director 3pp 15742 140 24X Fiche 50-271,82/10/05,8210190022
- B210210204 Forwards LER 82-021/03L-0 PELLETIER, J P Vermont Yankes Nuclear Power Corp B2/10/12 HAYNES, R C Region 1, Office of Director ip 15766 343 24X Fiche 50-271,82/10/12,8210210204
- --8210210214 LER 82-021/03L-0 on 820914, while performing pump operability survey llance on RCIC sys.RCIC turbine tripped on overspeed Caused by failure of electric governor module Module replaced Bad transistor found in tach generator PELLETIER.J P Vermont Yankee Nuclear Power Corp 82/10/12 Region 1. Office of Director 1p 15766-344 244 Fiche 50-271.82/10/12.8210210204
- DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8210250245 Forwards 1982 FEMA/NRC observed exercise scenario for B21013 exercise Revisions reflect changes agreed upon during 820420 neeting w/NRC & FEMA 2UPKO. J M Public Service Electric & Oas Co of New Jersey 82/09/16 HAYNES,R C Region 1, Office of Director 148pp 15789 002 24X Fiche 50-272,82/09/16,8210250245
- 8210260518 Forwards exemption from requirements of 10CFR50 48 re fire protection of safe shutdown capability VARGA: 8 A Operating Reactors Branch | 82/09/14 UDERITZ: R A Public Service Electric 8 Gas Co of New Jersey 3pp 15830 168 24X Fiche 50-272,82/09/16,8210260518
- --8210260521 Exemption from requirements of 10CFRSO 48 re fire protection of safe shutdown capability
  EISENHUT D 0 Division of Licensing 82/09/16 Public Service
  Electric & Oas Co of Now Jersey 4pp 15930 171 24X
  Fiche 50-272,82/09/16.8210260518
- --8210240524 Safety evaluation supporting licensee request for exemption from requirements of 10CFR50 48 re fire protection of safe shutdown capability # Office of Nuclear Reactor Regulation, Director 82/09/14 3pp 15830 175 24X Fiche 50-272,82/09/14,8210240518
- 8210060431 Forwards exemption from requirements of Section IV F 1 of App E to 10CFR50, to allow next full-scale emergency preparedness esercise at facility to be conducted on or about 820929, granting 820709 request VARGA. S A Operating Reactors Branch 1 82/09/23 UDERITZ. R A Public Service Electric & Oas Co of New Jersey 3pp 15636 227 24% Fiche. 50-272, 82/09/23. 8210060431

- --8210060433 Exemption from requirements of Section IV F 1 of App E to 100FR50.to allow next full-scale emergency preparedness exercise at facility to be conducted on or about 820929 Evaluation encl EIBENHUT.D Q Division of Licensing 82/09/23 Public Service Electric & Oas Co of New Jersey 5pp 15636 230 24X Fiche 50-272.82/09/23.8210060931
- P Operating license stage documents & correspondence
- 8210050485 Forwards documentation of satisfactory completion of requirements contained in 790921 ltr re TMI Action Item II E i I concerning auxiliary feedwater sys VAROA.5 A Operating Reactors Branch i 82/09/20 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 3pp 15626 277 24X Fiche 50-272.82/09/20.8210050485
- --8210050490 "Suppl to Safety Evaluation Rept for Salem Units 1 & 2 Implementation of Recommendations for Auxiliary Feedwater Sys "
  \* Office of Nuclear Reactor Regulation, Director 82/09/20 3pp 15626 280 24% Fiche 50-272
- 6210130403 Advises that installed monitoring sys required by TMI Action Items II F i 4:II F i 5 & II F i 6 acceptable & items considered closed VARQA.S A Operating Reactors Branch i 82/09/28 UDERIIZ,R A Public Service Electric & Gas Co of New Jersey 2pp 15692 349 24X Fiche 50-272.82/09/28.8210130603
- 8210190047 Informs that util rod exchange methodology not approved because of calculational content of reactivity measurement New submittal or return to boron dilution method requested VARGA.S A Operating Reactors Branch 1 82/09/29 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 3pp 15761 041 24X Fiche 50-272.82/09/29,8210190047
- 8210190507 Application for amend to Licenses DPR-70 & DPR-75 revising core limits, fractional thermal power factor limit, performance of RCS water inventory balance & boron concentration & contained vol limits
  LIDEN, E A Public Service Electric & Gas Co of New Jersey
  82/10/05 VARSA & A Deparating Reactors Branch i 2pp 15863 124
  24X Fichs 50-272.82/10/05.8210190507
- --8210190515 Proposed Tech Specs supporting application to amend Licenses DPR-70 & DPR-75, revising core limits, fractional power factor limit performance of RCS water inventory balance & boron concentration & contained vol limits
  \* Public Service Electric & Oas Co of New Jersey 82/10/08
  17pp 15863 126 24% Fichs 50-272,82/10/05.8210190507
- 8210270136 License Change Requests 82-17-20-21 & 22 to Licenses DPR-70 & DPR-75 Changes involve inservice insp of snubbers steam generator insp ports, containment ventilation valve insp & surveillance functional testing
  LINDEN.E A Public Service Electric & Gas Co of New Jersey
  82/10/07 VARGA: 8 A Operating Reactors Branch 1 3pp 15827 026
  24X Fichs 50-272.82/10/07.8210270136
- --8210270142 Proposed Tech Spec changes re inservice insp of snubbers, installation of steam generator insp ports, pressure drop test & reactor trip instrumentation

  \*\* Public Service Electric & Gas Co of New Jersey 82/10/07
  8pp 15827 029 24X Fiche 50-272,82/10/07,8210270136
- 8210180009 Advises that design changes satisfying concerns expressed in 820917 request for additinfors reactor protection sys/ESF actuation sys initiated Tech Specs will be modified to address setpoint changes
  LIDEN.E A Public Service Electric & Gas Co of New Jersey, 82/10/09, VARQA,S A Operating Reactors Branch 1 ip 15720 024 24X Fiche 50-272,82/10/08,8210180009
- 8210220275 Informs that review & plans re Cycle 5 reload core is expected to achieve burnup of 11500 MMD/MTU Startup physics testing will include control rod drive tests & droptime & critical boyon concentration measurements
  LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey
  82/10/14 VAROA, B. Operating Reactors Branch i 4pp. 15778 191
  24X Fiche 50-272,82/10/14,8210220275
- 8210270392 Forwards Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively, safety evaluation & notice of issuance & availability Amend revises process & effluent monitors to agree w/existing plant conditions ROSS.W J Operating Reactors Branch i 82/10/18 UDERITZ.R A Public Service Electric & Gas CO of New Jersey 2pp 19834 318. 24X Fiche 50-272.82/10/18,6210270352

- --6210270355 Amends 48 & 13 to Licenses DPR-70 & DPR-75 respectively, revising process & effluent monitors to agree w/existing plant conditions VARCA, & A Dereting Reactors Branch 1 82/10/18 14pp 15834 320 24X Fiche 50-272,82/10/18,8210270352
- --B210270360 Safety evaluation supporting Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively. + Office of Nuclear Reactor Regulation, Director 15834 334 24% Fiche 50-272.82/10/18.8210270352
- --8210270366 Notice of issuance & availability of Amends 48 & 13 to Licenses DPR-70 & DPR-75 respectively VARGA, S.A. Operating Reactors Branch 1. 82/10/18 2pp 15934 340 24X Fiche 50-272, 82/10/18,8210270332
- O Inspection reports. #E Bulletins & correspondence
- 8210080015 Addl response to FDIA request for 19 categories of info re nuclear reactor events & safety problems forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
  FELTON, J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X
  Fiche 50-000.82/07/12,8210080015
- --8210080150 Systematic assessment of litensee performance notes refacility evaluation for Sept 1979-Aug 1980
  NRC No Detailed Affiliation Oiven 80/08/31 8pp
  15689 043 24X Fiche 50-000,82/07/12,8210080015
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON. J M Division of Rules and Records 82/08/10 LONG. D J Winthrop. Stimson, Putnam & Roberts 7pp 15445 083 24X Fiche 50-000. 82/08/10.82/0070007
- --8210070137 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees IPPOLITO T Operating Reactors Assessment Branch 82/04/01 VARGALS Operating Reactors Branch 1, 5pp 15645 131 24X Fiche 50-000, 82/08/10, 8210070007
- 8210120328 Responds to violations noted in IE Insp Repts 50-272/82-17 & 50-311/82-17 on 820707-0803 Connective actions administrative procedure will be revised so future temporary design changes are removed on timely basis UDERITI.R A Public Service Electric & Gas Co of New Jersey 82/09/28 HAYNB3R C Region 1. Office of Director STARUBTECKI.R Division of Project & Resident Programs 5pp 15652 123. 24X Fichs 50-272.82/09/28.32/10120328
- 92102(0146 Forwards IC Insp Rept 50-272/82-23 on 920931 & 0901-03 No noncompliance noted MARTIM-T T Division of Engineering & Technical Programs. 92/10/05 UDERITZ:R A Public Service Electric & Gas Co of New Jersey 2pp 15766
- --8210210162 IE Insp Rept 50-272/82-23 on 820831 & 0901-03 No noncompliance noted Major areas inspected inservice testing surveillance program for pumps & valves & containment penetration teakage testing surveillance REKITO.W A , BETTENMAUSEN.L Division of Engineering & Technical Programs 82/09/29 Spp 15766 094 24X Fiche 50-272,82/10/05,8210210146
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 implant Seeds " Svc list encl CDB.t I Division of Fuel Facilities, Materials & Safeguerds 62/10/06 Consolidated Edison Co of New York 66pp. 18761 250 24X Fiche: 50-000, 82/10/06, 8208190233
- 8210210435 Forwards IE Insp Repts 50-272/82-20 & 50-311/82-20 on 820816-20 No noncompliance noted MARTIN-T T Division of Engineering & Technical Programs. 82/10/04 UOERITZ-R A Public Service Electric & Gas Co. of New Jersey. 2pp 15763-036 24% Fichs 50-272-82/10/06-8210210435
- --8210210451 IE Insp Repts 50-272/82-20 & 50-311/82-20 on 820816-20 No noncompliance noted, Major areas inspected; qualification & training, radiological surveys, radiation exposure permits, posting licensee audits & exposure control HOSEY.C.M. ROWE,C.A. PREEMMAN.E.Q. Division of Engineering & Technical Programs 82/09/30. Spp 15763:038, 24% Fiche: 50-272,82/10/06,8210210405.

- 8210210464 Forwards IE Insp. Repts 50-272/82-25 & 50-311/82-24 an 820901-27 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 82/10 & UBERITZ, R. A. Public Service Electric & Gas Co. of New Jersey 2, 13763 018 24X Fiche 50-272,82710/06.8210210464
- --8210210469 Notice of violation from insp on 820901-27 \* Region 1, Office of Director 82/10/06 ip 15763 020 : Fiche 50-272, B2/10/06, B210210464
- --8210210477 IE Insp Repts 50-272/82-25 & 50-311/82-24 on 820701-27 Noncompliance noted trip breakers closed w/o two operable source range instruments in svc & failure to submit 30-day LER MERRHOLM, L. J., SUMMERS, R., TRIPP, I. E. Division of Project & Resident Programs 82/10/04 15pp 15763 021 24% Fiche 50-272,82/10/04,8210210464
- 8210270136 License Change Requests 82-17-20-21 & 22 to Licenses [fi] & DPR-75 Changes involve inservice insp of snubbers, steam generator insp ports, containment ventilation valve insp & surveillance functional testing LINDEN, E A Public Service Electric & Gas Co of New Jersey 82/10/07 VARQA, S A Operating Reactors Branch 1 3pp 15927 1 24X Fiche 50-272, 82/10/07, 8210270136
- --9210270142 Proposed Tech Spec changes re inservice insp of shall installation of steam generator insp ports, pressure drop test & reactor trip instrumentation

  A Public Service Electric & Oas Co of New Jersey 92/10/61

  Bpp 15927 029 24X Fiche 50-272, 82/10/07, 8210270136
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Well, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Svc list encl DEYGUNO.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 129 24% Fiche 50-000, 82/10/14.8208190238
- 8210280221 EN-B2-034 on 821027 notice of violation & proposed imposition of civil penalty in amount of \$40.000 issued re inadequate vital physical area barrier RDSANO, R AXELRAD, J Director's Office, Office of Inspection at Enforcement B2/10/22 ip 15837 089 24X Fiche 50-272,82/[] 2 8210280221

6.

ez.

62

**6**21

- R Periodic operating reports & related correspondence
- 8210200085 Forwards monthly operating rept for Sept 1982 MIDURA: H J Public Service Electric & Gas Co of New Jersey 82/10/10 Director's Office, Office of Inspection and Enformanip 19757 201 24% Fiche 30-272.82/10/10.8810200085
- --8210200090 Monthly operating rept for Sept 1982 MILLER, L K Fublic Service Electric & Oas Co of New Jersey 62/10/10 14pp 15757 202 24X Fiche 50-272,82/10/10.82(000.2
- S. Reportable occurrences: LERs & related correspondence
- B210120369 Discusses consistent failure of solenoid valves in containment fan coil unit syc water flow control valves Licenses investigation determined that overheated valves caused sticking Valves replaced CHIRAMAL.M Director's Office 80/09/12 Director's Office L 15690 170 24X Fiche 50-272,80/09/12,8210120369
- B21001000B Responds to FDIA request for 19 categories of documents nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J. M. Division of Rules and Records 82/06/20 UDELL.R & Critical Mass Energy Project 13pp 15727 005 24X Fiche 50-000, 82/06/28, 8210010008
- --8202120236 Notifies that inadvertent isolation of containment Not coolers sys due to radiation alarms is not likely LER reservants of the system of the sy
- 8210080015 Add1 response to FOIA request for 19 categories of infar nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Examption 5)
  FELTON, J M Division of Rules and Records 82/07/12, UDELL.FA Critical Mass Energy Project 9pp 15665 027 24X
  Fiche: 50-000, 82/07/12, 8210080015
- --8210080197 NRC operations ctr usage chart re events at faciliting # NRC No Detailed Affiliation Given 82/07/12. 1p 1588 E 24X Fiche 50-000.82/07/12,8210080015.

- 8210610181 Forwards LER 82-069/03L-0 Detailed event analysis encl MEDURA.H J Public Service Electric & Gas Co of New Jersey B2/09/L6 HAYNES.R C Region 1. Office of Director 3pp 15567 302 24x Fiche 50-272,82/09/16.8210010181
- --8210010192 LER 92-069/03L-0 on 820831, svc water leak discovered on charging pump 12 lube oil coaler outlet piping & pump declared inoperable Caused by erosion of piping by silt-laden svc water Pipe replaced INSLLER, R Public Service Electric & Cas Co of New Jersøy 82/09/16 Region 1. Office of Director 1p 15567 305 24% Fiche 50-272,82/09/16,8210010181
- 8210010383 Forwards LER 82-068/03L-0 Detailed event analysis encl MIDURA: H J Public Service Electric & Gas Co of New Jersey 82/09/16 HAYNES: R C Region 1. Office of Director 3pp 15569 193 24X Fiche 50-272, 82/09/16, 8210010383
- --E210010390 LER 82-068/03L-0 on 820827,100-ft slevation containment air lock declared inoperable after excessive leakage discovered gast inner door seals Caused by closing door w/excessive force Seal replaced Installation of snubbers proposed HELLER.R Public Service Electric & Gas Co of New Jersey 82/09/16 Region 1, Office of Director 1p 15567 176 24X Fiche 50-272,82/09/16.8210010383
- B210070305 Forwards LER 82-073/03L-0 Detailed event analysis encl MIDURA: H J Public Service Electric & Gas Co of New Jersey B2/09/22 HAYNES, R C Region 1. Office of Director 3pp 15634 107 24X Fiche 50-272, 82/09/22, 8210070305
- --8210070314 LER 82-073/03L-0 on 820906, raiculation showed that quadrant power tilt ratio for bottom detector N42 exceeded max allowable (init Caused by failed milliamp detector switch in current meter assembly Assembly replaced & channel tested FRAHM.R Public Service Electric & Gas Co of New Jersey 82/09/22 Region 1. Office of Birector 1p 15634 110 24X Fiche 50-272,82/09/32,8210070305
- 121007036B Forwards LER 82-074/04L-0 Detailed event analysis encl HIDURALH J Public Service Electric & Gas Co of New Jersey B2/09/22 HAYNES,R C Region 1. Office of Director 3pp 13634 031 24X Fiche 50-272,B2/09/22,821007036B
- -8210070375 LER 82-074/04L-0 on 820903, indication of unplanned release through plant vent received Three individuals contaminated during attempts to locate source Caused by door hitting against drain valve 100312, causing valve to loosen & open HELLER.R. Public Service Electric & Gas Co of New Jersey 82/09/22 Region 1. Office of Director 1p 15634 034 24% Fiche 50-272.82/09/22.8210070368
- 210070380 Forwards LER 82-071/04L-0 Detailed event analysis encl HIBURA, H J Public Service Electric & Oas Co of New Jersey 82/09/22 HAYNES, R C Region I, Office of Director 3pp 15633 356 24X Fiche 50-272,82/09/22,8210070380
- -8210070398 LER 82-071/04L-0 on 820827, control operator discovered increasing level on plant vent radioactivity monitor & asseed significant event notifications for unplanned releases Caused by primary coolant leakage from RCS filter FRAUL, R Fublic Service Electric & Gas Co of New Jersey 62/09/22 Region i. Defice of Director ip 15633 359 24X Fiche 50-272, 82/09/22, 8210070380
- 210150058 Forwards LER 82-066/03X-1 Detailed event analysis encl MIDURA, H J Public Service Electric 8 Gas Co of New Jersey 82/09/29 HAYMES,R C Region 1. Office of Director 3pp 15698 276 24X Fiche 50-272,82/09/29,8210150058
- -8210150066 LER 82-066/03K-1 on 820825,100 ft elevation containment air lock outer door discovered not properly sealed Caused by seal damage due to personnel closing door w/excessive force Seal replaced & door tested satisfactorily HELLER.R Public Service Electric & Gas Co of New Jersey 82/09/27 Region 1, Office of Director 1p 15698 299 24X Fiche 50-272,82/09/27,8210150058
- P10150071 Forwards LER 82-044/03X-1 Detailed event analysis encl MIDURA,H J Public Service Electric & Oas Co of New Jersey 82/09/29 HANYES,R C Region 1. Office of Director Spp 15701 243 24X Fiche 50-272,82/09/29,8210150071
- 8210150075 LER 82-044/03Y-1 on 820623, during routine operation, vital ventilation control ctr 10 tripped, rendering control room emergency air conditioning fan 12 inoperable, Caused by setpoint drift & breaker iCi6Y trip Breaker replaced HELLER, R Public Bervice Electric & Oas Co of New Jersey 82/09/29 Region 1. Office of Director ip 15701 246 24X Fiche 50-272, 82/09/29, 8210150071

- 8210150111 Forwards LER 81-019/03X-1 Detailed event analysis encl MIDURA.H J Public Service Electric & Qas Co of New Jersey 82/09/29 HAYNES.R C Region 1. Office of Director 3pp 15697 070 24X Fiche 50-272.82/09/29,8210150111
- -B210150121 LER S1-019/03X-1 on B10221, fire alarm annunciation on Fanel IRPS for waste gas compressor observed but no audible alarm heard Caused by failure of amplifier to discruminate sys noise from announcement function Amplifier adjusted HELLER.R Public Bervice Electric & Gas Co of New Jersey 82/09/29 Region 1. Office of Director ip 15697 073 24X Fiche 50-272,82/09/29.8210150111
- 8210150127 Forwards LER B2-067/03L-0 Detailed event analysis encl MIDURA.H J Public Service Electric & Oas Co of New Jersey B2/09/29 HAYNES.R C Region 1. Office of Director 3pp. 15698 324 24X Fichs 50-272.82/09/29/.B210150127
- --8210150140 LER 82-047/03L-0 on 820912, no indication of eye water flow to containment fan coal unit ii noted while coal unit ii inoperable Caused by terminal screw on eye water flow transmitter breaking off Screw replaced FRAMM.R Public Bervice Electric & Oas Co of New Jersey 82/09/29 Region 1. Defice of Director ip 15498 327 24% Fichw 50-272,82/09/29,8210150127
- 8210150148 Forwards LER 82-051/03X-1 Detailed event analysis encl MIDURA: H J Public Service Electric & Oas 20 of New Jersey 82/09/29 HAYNEB: R C Region 1, Office of Director 3pp 15497 288 24X Fiche 50-272.82/09/29.8210150148
- --8210190155 LER 82-051/03X-1 on 820728, following reactor trip, level in auxiliary feed storage tank dropped below Tech Spec min Caused by binding of valve 1DR6 Valve manually cycled & tank level restored to normal Valve returned to remote mode HELLER, R Public Service Electric & Oas Co of New Jersey 82/07/27 Region 1, Office of Director ip 15697 291 24X Fishe 50-272,82/09/29,8210150148
- 8210210134 Forwards LER 82-070/034-0 Detailed event analysis encl MIDURA, H J Public Service Electric & Gas Co of New Jersey 82/10/04 HAYNES, R C Region i, Office of Director 3pp 15766 120 24X Fiche 50-272,82/10/06.8210210134
- --8210210144 LER 82-070/03L-0 on 820912 & 14. pressurizer pressure controller shifted to manual mode w/decreasing pressure Caused by intermittent problem in pressure controller or manual-auto station Manual-auto station replaced FRAHM.R. Public Service Electric & Gas Co of New Jersey 82/10/06 Region 1. Office of Director ip. 15766 123 24X Fichs 50-272,82/10/06 8210210134
- 8210290216 Forwards corrected LER 82-016/04L-0 Detailed event analysis encl MIDURA, H J Public Service Electric & Gas Co of New Jersey 82/50/06 HAYNES, R C Region 1, Office of Director. 3pp 13853-250 24X Fiche 50-272,82/10/04,8210290216
- --8210290218 Corrected LER 82-014/04L-0 on 820326, during gaseous release from waste gas sus, containment/plant vent monitors iRila. IRI2A & IRI28 incorrectly aligned Caused by operator failure to properly perform operating instruction. FRAHM.R Public Service Electric & Gas Co of New Jersey 82/04/13 Region 1 Office of Director 1p. 15853 253 24X Fiche 50-272,82/10/04.8210270216
- 8210270310 Forwards corrected LER 82-050/04L-0 Detailed event analysis encl MIDURA, H J Public Service Electric & Oas Co of New Jersey 82/10/06 HAYNES, R C Region 1, Office of Director 3pp, 13853:090 24X Fiche 50-272,82/10/06,8210270310.
- --8210290314 Corrected LER 82-050/04L-0 on 820710, Atlantic loggerhead turtle faund impinged on circulating water sys intake trash bars Caused by inability of turtle to actively avoid approach valocities to intake due to weakened state FRAHM.R Public Service Electric & Gas Co. of New Jersey. 82/08/06 Region 1 Office of Director ip. 15853,093. 24X Fiche 50-272,82/10/06.8210270310
- @210290353 Forwards corrected LER 82-045/04L-0 Detailed event analysis and MIDURA, H J Public Service Electric & Qas Co of New Jersey. 82/10/06. HAYNES, R C Region 1, Office of Director 3pp 15853 014 24X Fiche 50-272,82/10/06,8210290353
- --8210290361 LER 82-045/04L-0 on 820710; waste monitor tank contents sample discarded before composite samples assembled Caused by technician inadvertently pouring out sample.Personnel counseled reprocedures Simulated sample made. FRAHM,R. Public Service Electric & Oas Co. of New Jersey 82/07/28 Region 1: Office of Director, 1p. 15853 017, 24X Fiche 50-272,82/10/06,8210290353

- DOCKET 50-275 DIABLO CANYON NUCLEAR POHER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 821001000B Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems. Forwards documents listed in App A FELTON, J H Division of Rules and Records 82/06/28 UDELL, R A Critical Hass Energy Project 15pp 15727 005. 24X Fiche 50-000.82/06/28,821001000B

- --8008050265 Discusses addl required info to better define potential for cracking in reactor vessel notiles
  NGONAN, V S Assistant Director for Materials & Qualifications
  Engineering 80/05/05 TEDESCO.R L Assistant Director for
  Licensing 2pg 15727 176 24X Fiche 50-000,82/06/28,8210010008
- F Security, medical, emergency & fire protection plans
- 8210010406 Forwards application for amend to Litense DPR-76, revising Recurity plan

  CRANKE.P.A Pacific Gas & Electric Co 82/09/17 DENTON.H R

  Office of Nuclear Reactor Regulation, Director ip. 15572.207. 24X

  Fichs. 50-275. 82/09/17.8210010406.
- --BR10010413 Application to amend License DPR-76, revising security plan Safeguards into deleted. MAKEATIB.O A., CRANE.P. A. Pacific Oas & Electric Co 3pp 1957:208. 24X Fichs 50-275.82/09/17.8210010406.
- 8210210033 Releases public version of revised emergency plan implementing procedures. FELTON.U.M. Division of Rules and Records 82/10/01 Docum Management Branch Ip. 15762:091 24X Fiche: 50-275, 82/10/01, 8210210033. Document
- --6210210044 Forwards public version of revised emergency plan implementing procedures, including Procedure EP M-3 re chloring release, EP M-5 re Taunami warning & EP M-8 re cantainment energency personnel hatch.

  GRANE.P.A. Pacific Oss & Electric Co. 82/09/23, E
  Region 5. Cffice of Director. 3pp. 18782:092, 24X
  Piche. 50-275.82/10/01/8210210033 ENGELKEN A H
- --B210210048 Public version of revised emergency plan implementing procedures, including Procedure EP M-3 re chlorine release, EP M-5 re Teunani warning & EP M-8 re containment emergency personnel hatch.

  Pecific Cas & Electric Co. 82/09/13, 84pp. 15782:095. 24Fiche: 80-276.82/10/01.8210210033. 82/09/13, 84pp. 15782:095, 24X
- G210180389 Suppl to G20719 application for emend to License DPR-76 re security plan.Enci withheld (ref 10CFR73.21), CRANK.P.A. Pacific Cas & Electric Co. 92/10/12, DENTON, H.R., MIRAGLIA Office of Nuclear Reactor Regulation, Director, 2pp, 187031274, 24X Fiche: 80-275.82/10/12,8210180389.

# Q. Adjudicatory correspondence

- 88:0270449 Responds to 820512 patition requesting action under iOCFRG. 206. For reasons stated in enclosed Director's Decision, patition denied.
  DENION:H.R. Office of Nuclear Reactor Regulation, Director.
  82/09/28, REVNOLDS-J. Center for Law in the Public Interest. Spp. 16863:166. SAX Fiche: 80-278,82/09/28,8210290449.
- =-8210870451 Cirestor's Decision DD-82-10 denying Ctr for Law in Public Interest 880518 petition requesting NRC leave order to util to submit amand to DL to cover OA & QC issue, DENTON M.R. Office of Nuclear Rescue Regulation; Director. 82/09/28, 8210890449.
- BRIGO40102 Order extending time until BRIGOS for Commission to act to review ALAS-681, OHILMS, U. Office of the Secretary of the Commission. 82/09/00. Commissioners. Ip. 18881:028. 84X Fishe: 80-978, 82/09/00. 8810040108.

- 8210050218 Reply to applicant & NRC 820924 briefs re status of pr appeals from authorization of low power operation No adequate factual basis exists to support ASLB dismissal of adequate factual basis exists to support ASLB dismissal of Joint Intervenor OA contention as moot W/Certificate of Bvc REVNOLDS, J. R. Joint Intervenors-Diablo Canyon REYNOLDS, J. R. Center for Law in the Public Interest B2/09/30 Atomic Stand Licensing Appeal Panel Bpp 15611 237 24% Fiche 50-275, 82/09/30, 8210050218 Atomic Saf
- 8210060220 Reply brief to other party briefs re monthess of low p contentions Emergency planning issues & certain other issues mont Certificate of Svc encl LOCKE, R F Pacific Oas & Electric Co B2/09/30 Atomic Saf and Licensing Appeal Penel App 15620 190 24x Fiche 30-275, 82/09/30, 8210060220
- 8210040097 Reply to Governor Brown & Joint Intervenors 820924 fill in response to ASLB 820902 order on mootness of low power issues Emergency planning issues & some low power contentions mooted Cartificate of Syc and JONES, B W. Hearing Brench 1 82/10/01 Atomic Gafety and Licensing Appeal Panel 9pp 15981 026 24X Fiche 50-275.82/ Licensing Appeal Panel 8210040097
- 8210050180 Reply brief to util & NRC 820924 briefs re moothess of power issues, per ASLE 820902 order Issues not moot Controversy still exists & issue is of practical constroversy still exists & issue is of practical significance Cartificate of Bkc encl BROWN, H H Kirkpatrick, Lcc BROWN, H H Callfornia, State of BROWN, H H Kirkpatrick, Lcc Hill, Christopher & Phillips 82/10/01 Atomic Sefety and Licensing Appeal Panel Spp 15603 345 24X Fiche 50-275,82,8210050180
- 8210060186 Request for leave to withdraw certain exceptions to AS B20831 initial decision ASLB 820927 clarification of & local jurisdiction acquiescence to preconditions res SOPs render exceptions unnecessary Certificate of Svc encl HAGGELL, D.F. Hearing Branch 1 82/10/04 Atomic Safety and Licensing Appeal Panel 5pp 19613 193 24X Fiche 50-275, 82-8210060186
- 8210070145 Order extending time until 821008 for Commission to at review ALAB-681 CHILK.B.J. Office of the Secretary of the Commission 82/ Commissioners. 1p 15627 076 24X Fiche 50-275,82/10/05.
- 8210130272 Forwards Ban Luis Ohispo County Board of Supervisors faction approving Ban Luis Ohispo County huclear power plant emargency response plan & State of CA Benate Bill 1473 amending govt code, Certificate of Svc encl CRANE, P. A Pacific Oas & Electric Co. B2/10/06 BUCK. J N . JDKNBON. W. R . MODRET B . Atomic Befety and Licensing Appeal Pi
- 8210120332 Order CLI-82-30 directing all natl security classifies be expunged from ALAB-653 & underlying record info not essential to ABLAB opinion & expunction would not prejudice any party or public CHICK-8. J. Office of the Secretary of the Commission 82/10/22p. 15652:108. 24X Fiche 50-275,82/10/08,8210120332
- 8210130327 Order extending time until 821026 for Commission to as 10130327 Green exercises the Secretary of the Commission. 82/10/1 CHILK, S. J. Office of the Secretary of the Commission. 82/10/1 Commissioners. 1p. 15678:282, 24X Fichs 50-275.82/10/08.
- 8210210422 Order extending time until 821105 for Commission to at review NRR Director 820922 denial of Joint Intervenors 100FR2.206 request.
  CHILK, B. J. Office of the Secretary of the Commission 82/10/: Commissioners. 1p. 15763.083 24X Fiche: 50-275,82/10/18,8210310825
- 8210280248 Memorandum in response to util 820924 motion for clarification of ASLB 820831 initial decision Decision supports conclusion of law on adequacy of offsite emergency planning. HDLF: J.F. HOLF, J.F. Atomic Bafety and Licensing Board Panel 82/10/2& 15837: 056, 24% Fichs. 50-275, 82/10/26, 8210280245.

## H. General correspondence

8210220363 Advises that 821010 ltr requesting util recalculate s. safety are at plants will be sent to all parties GILINBKY, V. Commissioners. 82/10/20, BCHULKE, B. Affiliation Unknown. 1p. 18779: 201, 24X Fighe: 80-275, 82/10/20, 821022038:

- --82(0220369 Urges util be forced to recalculate entire sgismic safety sys at plant SCHUME.S Affiliation Unknown 82/10/10 GILINSKY, V Commissioners in 15779 202 24X Fiche 50-275, 82/10/20, 8210220363
- P Operating license stage documents & correspondence
- E210080350 Informs that procedure including proposed "Statement re Fotential of Apparent Conflicts of Interest," meets requirements for independence Requests procedure be included in program mgt plans for Phase I & Phase II DENITON, HR Office of Nuclear Reactor Regulation, Director 82/09/08 COOPER, W E Teledyne Engineering Services ip 15663 316 24x Fiche 50-275,82/09/08,8210080350
- SE10010406 Forwards application for amend to License DPR-76.revising security plan GRANE.P A Pacific Gas & Electric Co 82/09/17 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 15572 207 24% Fische 50-275. B2/09/17.2210010406
- --B210010413 Application to amend License DPR-76, revising security plan Safeguards info deleted MAKEATIS.G A. CRANE.P A Pacific Gas & Electric Co 82/09/17 Jpp 15572 208 24X Fiche 50-275,82/09/17,8210010406
- 8210040429 Informs of decision to partially refund fees remitted w/ BOC821 application to extend latest CP completion dates MILLER,N O License Fee Management Branch 82/09/21 FURBUSH,M H Pacific Oas & Electric Co ip 15597 262 24X Fiche 50-275,82/09/21,8210040429
- 8210130056 Responds to 820727 request for status rept on design verification program & briefing on proposed Phase II of program Info discussing background & current status encl DIRCMS,W J Office of the Executive Director for Operations 82/09/24 PALLADINO,W J GILINBKY,V, AHEARNE,J F Commissioners 28pp 15692 284 24X fishe 50-275,82/09/24,8210130056
- 8210010149 Provides guidance to assure independence of Teledyne Engineering Svcs while recognizing need for communication between Teledyne & util DENION, H R Office of Nuclear Reactor Regulation, Director 82/09/29 COOPER, H E Teledyne Engineering Services Spp 15567 244 24X Fiche 50-275,82/09/29,8210010149
- 6210080191 Forwards Revision 2 to Procedure DCNPP-IDVP-PP-005,
  "Potential or Apparent Conflicts of Interest of
  Individuals " Mords "engineering mgt" inadvertently omitted
  in Section 2 O during retyping of Revision 1
  CODPER. WE Toledyne Engineering Services 82/09/29 DENTON, H R
  Office of Nuclear Reactor Regulation, Director ENGELKEN, R H
  Region 5, Office of Director MANKATIS, O A Pacific Qas & Electric
  Co 1p 15640 182 24X Fiche 50-275,82/09/29,8210080191
- --8210080193 Revision 2 to DCNPP-IDVP-PP-005, "Potential or Apparent Conflicts of Interest of Individuals"

  COCPER.W E Teledyne Engineering Services 82/07/29 Spp
  L5440 183 24% Fiche 50-225,82/07/29.8210080191
- 8210050122 Forwards info addressing Sections 2 1.2 2, 2 3 & 2 4 of Generic Ltr 81-07 re NUREO-0612. "Control of Heavy Loads" Section 2 ( updates B10924 submittal Submittal addressing remaining required analyses expected by end of Feb 1983 CRANE.P A Pacific Gas & Electric Co 82/09/30 MIRAGLIA.F J Licensing Branch 3 176pp 15605 212 24X Fiche 50-275,82/09/30,8210050122
- 8210050144 Responds to Generic Ltr 82-12 re plant staff working hours
  Util administrative procedures address revised working
  hours
  CRANE.P A Pacific Gas & Electric Co 82/10/01 MIRAQLIA.F J
  Licensing Branch 3 lp 15605 161 24% Fiche 50-275,82/10/01.
  8210050144
- B210120278 Forwards "Design Verification-Phase I," final rept & "Blume Internal Review (BIR) independent Internal Reviews of Work Done by LR8/Blume Engineers on Diablo Canyon Nuclear Power Flant "
  CRANE.P A Pacific Oas & Electric Co 82/10/01 EISENNUT, D. 9
  Division of Licensing 2pp 19653 243 24X Fiche 50-275, 82/10/01, 8210120278
- --9210120283 "Design Verification Phase 1.Final Rept "

  \* Pacific Gas & Electric Co T1002745 R03 82/10/01 233pp
  15653 245 24X Fiche 50-275,82/10/01.8210120278

- --8210120285 "Blume Internal Review Independent Internal Review of Work Done by URS/Blume Engineers on Diablo Canyon Nuclear Power Plant: "final rept + URS Corp URS/JAB 8216 82/09/30 80pp 15654 117 24X Fiche 50-275, 82/10/01.8210120278
- B210080272 Notifies that program procedure for communication from & to independent design verification program will be revised to conform w/guidelines provided in 820727 ltr CGOPER.W E Teledyne Energy Systems 82/10/02 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 19638 124 24X Fiche 50-275,82/10/02.8210080272
- 8210080078 Forwards interim technical rept "Independent Design Verification Program Verification Program for PG&E Carrective Action," Revision O DENISON.E Robert L Cloud Associates, Inc 82/10/05 DENTON,H R Office of Nuclear Reactor Regulation, Director ENGELMEN,R H Region 5, Office of Director MANCATIS, 0 E Pacific Gas & Electric Co 1p 15440 277 24% Fiche 50-275,82/10/05,8210080078
- --B2100B00B0 "Independent Design Verification Program Verification Program for PQ&E Corrective Action," Revision 0 DENISON,E Robert L Cloud Associates, Inc. P. 105-4-839-00B ROD B2/10/05 6ipp 1540 278 24% Fiche 50-275.82/10/05.82100B007B
- 8210250167 Forwards "Diablo Canyon Nuclear Power Plant Independent Design Verification Program Program Plan. Revision 1, Adjunct Program for Evaluation of Const QA"

  COOPER.W E Teledyne Engineering Services 82/10/05 DENTON, H R Office of Nuclear Reactor Regulation. Director ENGELKEN, R H Region 5, Office of Director MANEATIS, Q A Pacific Gas & Electric Co 2pp 15787 120 24% Fiche 50-275,82/10/05.8210250167
- --8210250171 "Diablo Canyon Nuclear Power Plant Independent Design Verification Program Program Plan. Revision 1. Adjunct Program for Evaluation of Const GA " \* Teledyne Engineering Services 82/10/01 12pp 15787 122 24X Fichs 50-278.82/10/05.8210250167
- 821025016B Forwards RH Engalken 820915 memo re RF Reedy, Inc exit meeting concerning QA audits for consideration in evaluation of QA program EISENHUT, D G Division of Licensing 82/10/06 COUPER, W E Teledyne Engineering Services. 2pp 15808 009 24X Fiche 50~275, 82/10/06, 8210250168
- ---B210250372 Bunmary of 820910 meeting w/util & RF Ready, Inc re GA audit of in-house design ENGELKEN, R H Region 5, Office of Director 82/09/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 15808-011 24% Fiche 50-275,82/10/06,8210250168
- 8210250240 Forwards independent design verification program comments on Phase I final rept Rept should contain detailed descriptions of scope, criteria, methodology & models for all structures, sys & components COOPER, B Teledyne Engineering Services 82/10/07 DENTON. H R Office of Nuclear Reactor Regulation. Director ENGELKEN, R H Region 5, Office of Director MANEATIB. Q A. Pacific Oas & Electric Co 16pp 15789 150 24X Fiche 50-279.887/10/07.8810250240
- 8210080123 Notifies of 821007 meeting w/util in San Francisco, CA to discuss status of Phases I & II. instrument test rig for verification of corrective action & NRC 820819 ltr re fuel load.

  \* Teledyne Energy Systems 82/10/08 Teledyne Energy Systems ip 13640 129 24X Fiche 50-275,82/10/08,8210080129
- 8210270446 Staff requirements mamo re 821007 affirmation/discussion & vote on extension of const completion dates for WPRBS, purging of classified matel in ALB-653 & amergency preparedness & risks associated w/fuel loading, CHILK,B J Office of the Secretary of the Commission. 82/10/08 Office of the Secretary of the Commission. 82/10/08 Fiche: 50-000, 82/10/08,8210290446
- 8210190470 Provides info re ownership of Bechtel Power Corp FRIENO.H B Bechtel Corp 82/10/11 MIRAGLIA, F J Licensing Branch 3 ip 15740 181 24X Fiche 50-275,82/10/11.8210190470.
- 8210270351 Advises that Bechtel Power Corp is entity responsible for work on project Ownership held by officers of Bechtel Orough Inc FRIEND, H. B. Pacific Cas & Electric Co FRIEND, H. B. Bechtel Corp 82/10/11 MIRAQLIAF, J. Licensing Brench 3 ip 15834-358, 24X Fiche 50-275, 82/10/11, 8210270351
- 8210150389 Supp) to 820719 application for amend to License DPR-76 re security plan Encl withheld (ref 10CFR73 21) CRANE,P.A Pacífic Ose & Electric Co 82/10/12 DENTON,H R , MIRAOLIA Office of Nuclear Reactor Regulation, Director, 2pp. 15703 279 24% Fiche 50-275,82/10/12,8210150389

- 8210250291 Clarifies 821007 statement re required sys.structures & components for plant operating modes for independent design verification program COOPER, M E Teledyna Engineering Services 62/10/12 EISENHUT, D Q Bivision of Licensing 4pp 15790 191 24X Fiche 50-275,82/10/12,8210250291
- 8210290097 Requests explanation of process & chronology of events in which Teledyne discussed const QA review of plant w/util. Bechtel & StW Info required to determine presence of conflict of interest Heeting requested BROWN, H H Kirkpatrack, Lockhart, Hill, Christopher & Phillips BROWN, H K California, State of 82/10/12 COOPER, W E Teledyne Engineering Services 2pp 15853 361 24X Fiche 50-278,82/10/12, 2210270097
- 8210290214 Provides NRC recommendation re Phase II of independent design verfication program Phase II program plan & requirement that Phase II review/evaluations be completed prior to fuel load/low power decision approved DIRCKS.W J. Office of the Executive Director for Operations SECY-82-414 82/10/13 61pp 15876 261 24X Fiche 50-275, 82/10/13, 8210290214
- 8210190583 Advises that two former Bechtel employees will be retained on independent design verification program Individuals do not violate procedure on conflict of interest & will not verify work participated in as Bechtel employee COOPER.H E. Teledyne Engineering Services 82/10/14 DENTON.H R Befice of Nuclear Reactor Regulation. Director ENGELKEN.R H Region 5. Office of Director MANEATIS.O A Pacific Cas & Electric Co. 3pp 15791 184 24X Fichs 50-275.82/10/14.8210190583
- 8210190584 Provides preliminary response to 820701 request for review of seven points re validity of ENL results & generic implications in final rept concerning enalysis of facility COOPER.W E Teledyne Engineering Services 82/10/15 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 15791 187 24X Fiche 50-275.82/10/15.8210190584
- 9210220371 Forwards add1 sections for Phase I final rept re design varification program per commitment made in 820820 ltr. Revision 4 to outline Phase I final rept & revision to sections previously submitted CRANE.P A Parific Oas & Electric Co 82/10/15 EISENRUT.D G Division of Licensing 10ipp 19779 238 24% Fiche, 50-278, 82/10/15, 82/1020371
- 9210250210 Identifies concerns resulting from review of URG/Blumb containment annulus structure model systuation Concerns resulted in issuance of EOI Files 3006 & 3007 MRAY.R Teledune Engineering Services 92/10/15 MANEATIS, G A Pacific Gas & Electric G 4pp 15789 292, 24X Fiche-50-275-82/10/15, 8210250210
- 8210250318 Comments on Region 5 820915 memo re Phase II of independent design verification program.per 821006 request Change in Phase II not indicated COPPER-W E Teledyne Engineering Services 82/10/15 EISCNMUT.D Q Division of Licensing Spp 15790 048 24X Fiche 50~275,82/10/15,8210250318
- 8210280272 Notifies of planned 821101 meeting w/plant personnel to discuss audit logistic planning for activities performed tince 820820 REEDV.R F. R F Reedy, Inc 82/10/15 COOPER,W E Teledyne Engineering Services 3pp (5837 292 24% Fiche 50-275, 82/10/15, 8210280272

- G Inspection reports, IE Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight categories of recording steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 82/08/10 (1840 D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24K Fiche 50-000, 82/08/10, 8210070007
- --B2\$0070139 Forwards tabulated data on steem generator line & raible facilities Date should be provided to licensees.

  IPPOLITOR T Operating Reactors Assessment Branch 92/04/01

  VARCA.S Operating Reactors Branch 1 5pp 19645 131 246

  Fiche 50-000,82/08/10.8210070007
- 8210060133 Forwards IE Insp Repts 50-275/82-26 & 50-323/62-13 am 820728-30,0816-20 & 0830-0901 No noncompliance noted BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/09/17 CRANE, P A Pacific Cas & Electric Co \$## 15614 307. 24X Fiche 50-275/82/09/17/8210060133
- --8210060141 IE Insp Repts 50-275/82-26 & 50-323/82-13 on 0.0/26-2 0816-20 & 0830-0901 No noncompliance noted Major area; inspected site tour & mod to piping & electrical rareway supports resulting from revised annulus selemts spectra BURDOIN JF, IMETZIO, 9 & Division of Resident, fisactor Projri, Engineering Programs BZ/09/17 9pp 15614 311 24% Fichs 50-275,82/09/17,8210060133
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-13)
  Implant Seeds " Svc list encl
  COBp.L I Division of Fuel Facilities, Materials & Gafequards
  82/10/04 Consolidated Edison Co of New York 66pp 10/61 27
  24% Fachs 50-000,82/10/04,8208190233
- 8208190238 IE Builetin 82-03, "Stress Corrosion Cracking in Thick-Wall: Large-Diameter: Stainless Steel, Recirculation flys Piping at BMR Plants "Sve list encl DEYOUNG: R C Director's Diffice, Diffice of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 30-000: 82/10/14, 12081902.10
- 8210280287 Forwards IE Insp Rept 50-275/82-29 on 820827-1002 k3 noncompliance noted BISHOP, T W Division of Resident, Reactor Project & Ingineering Programs 82/10/14 CRANE, P A Pacific Qas & Electric Co 4,1 15839 010 24X Fiche 50-275,82/10/14.8210280287
- --8210280303 IE Insp Rept 50-275/82-29 on 820829-1002 No norceplied noted Major areas inspected plant operations, surveillance testing, physical security, maint & TMI task action plan thans GARLSON, J B. MENDONCA, M M. KIRSCH, D F. Division of Resident Reactor Project & Engineering Programs 82/10/13 5pp 15837 014 24% Fiche 50-275, 82/10/14,8210280287
- 8210280324 Forwards IE Insp Repts 50-275/82-30 & 50 (2.1/12-14 em 820914-16 No moncompliance noted BIROP.T W Division of Resident, Reactor Project & Inginiering Programs 82/10/14 CRNELP A Pacific Oas & Electric Ca 731 15839, 019 24X Fichs 50-275,82/10/14,8210280324
- --B210280330 IE Insp Repts 50-275/82-30 & 50-323/82-14 on fluid late; noncompliance noted Major areas inspected implementation of independent verification program; including independents qualifications of personnel & implementation of OA grogrem MORRILL.P.J., ECKHARDT.J.H., BISHOP.T.H. Division of Resident Reactor Project & Engineering Programs 82/10/08 &pp 15839.021. 24% Fiche 50-278, 82/10/14.8210280324
- R Periodic operating reports & related correspondence
- 32:0270319 Forwards "Diablo Canyon Nuclear Power Plant Indipendent Design Verification Program," semimonthly rept for dept 1982 COOPER, H. E. Teledyne Engineering Services 82/09/24 ČEKTCM.... Uffice of Nuclear Reactor Regulation, Director. ENGELERIA MREGION 5. Office of Director MANCATIB, O. Pacific 981 & Elect. Co. 1p. 15854, 119 24X Fiche 50-275, 82/09/24, 8210270319
- --8210270322 "Diable Canyon Nuclear Power Plant Independent Deright Verification Program" semimonthly rept for Sept 1982 + Teledune Engineering Services. 82/09/24 49pp 15634 123 24X Ficher 50-278.82/09/24.8210270319.
- 3210130151 Forwards "Bemimonthly Rept 23, Diablo Cenyon Verification Program." 820921-1004 CRANE,P A Pacific Gas & Electric Co 82/10/08 DENTON,M & Office of Nuclear Reactor Regulation, Director ENGELKEN, F H Region 5, Defice of Director 1p. 15697 294, 24X Fiche: 50-275, 82/10/08, 8210150151

- --8210150159 "Semimonthly Rept 23. Diable Canyon Verification Program," HOCH. J B Pacific Gas & Electric Co 82/10/08 51pp 15697 295 24X Fiche 50-275,82/10/08,8210150151
- 8210250197 Forwards "Independent Design Verification Program," semimonthly rept for Oct 1982 COGPER, U.C. Teledyne Engineering Services 82/10/08 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ENGELKEN, R.H. Region 5, Office of Director MANEATIS, O.A. Pacific Cas & Flectric Co. 3pp. 15787-264 24X Fiche 50-275.82/10/08,821025019.
- --8210250201 "Independent Design Verification Program," semimonthly rept for Oct 1982 Engineering Services 82/10/08 29pp 15789 267 24X Fiche 50-275.82/10/08.8210250197
- 8216250221 Advises that RL Cloud Associates. Inc hes not issued onen elu290221 Advises that RL Cloud Associates, inc has not issued open then repts during prior reporting period DENISON.E Robert L Cloud Associates, Inc 82/10/08 DENTON.H R Office of Nuclear Reactor Regulation, Director ENGELKEN.R H Region D. Office of Director MANEATIS, O A Pacific Oas & Electric Co Ip 15788 348 24X Fiche 50~275.82/10/08,8210250221
- 8210250247 Submits Semimonthly Progress Rept 20 for 820702-1008 No open item repts is sued but two open item repts identified individuals completed acceptable statements re potential or Individuals completes acceptance statements responses to apparent conflicts of interest REEDY,R F R F Reedy, Inc 82/10/08 DENTON,H R Office of Nuclear Reactor Regulation, Director ENGELMEN,R,H Region 5. Office of Director MANEATIS,O A Pacific Gas & Electric Co 15786 342 24X Fiche 50-275,82/10/08.8210250247
- 0210250308 Forwards Oct 1982 semimonthly rept.consisting of Open Item 21032030B Forwards Dct 1982 semimonthly rept, consisting of Open Item flepts 8007-8020
  FESTAK.F Stone & Webster Engineering Corp. 82/10/08 DENTON, H R Office of Nuclear Reactor Regulation. Director ENGELKEN, R H Region 5. Office of Director MANCATIS, O Pacific Oss & Electric Co 36pp 15790 097 24X Fiche 50-275,82/10/08,8210250308
- E210280157 Forwards program managers 3rd Friday Oct 1982 rept re independent design verification program REEDY.R F R F Reedy, Inc. 82/10/15 COOPER.W E Teledyne Engineering Services 6pp. 15837 215 24% Fiche 50~275.82/10/15, 8210280157
- BB10270236 Forwards "Diablo Canyon Verification Program," Semimonthly Rept 24 for B21005-18 per Commission Order CLT-81-30 CRANE,P A Pacífic Gas & Electric Co B2/10/22 DENTON.H. R Office of Nuclear Reactor Regulation, Director ENGELKEN,R H Region 5. Office of Director ip 15828 222 24X Fiche 50-275-82/10/22-8210270236
- --8210270240 "Diable Canyon Verification Program," Semimonthly Rept 24 for 821005-18 # Pacific Gas & Electric Co 82/10/22 52pp 15828 223 24X Fiche 50-275,82/10/22,82/0270236
- 8210280211 Forwards "Diablo Canyon Nuclear Power Plant Independent Design Verification Program," semimonthly status rept for Oct 1982 Oct 1982 CODPER G E Teledyne Engineering Services 82/10/22 DENTON, H.R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5. Office of Director MANEATIS, G A Pacific Oas & Electric Co 2pp 15838 OOI 24X Fiche 50-275,82/10/22,8210280211
- --- P210280212 "Diable Canyon Nuclear Power Plant Independent Design Varification Program" semimonthly status rept for Oct 1982 Teledyne Engineering Bervices 82/10/22 76pp 15838.003 24X Fiche 50-275.82/10/22.8210280211
- S Reportable occurrences, LERs & related correspondence
- 8210250055 PND-V-82-043 on 821016, unusual event declared when grass fire started in 500 kV switchyard On 821017, three \$00 kV circuits tripped, resulting in lose of all offsite power Second unusual event declared STERNBERG. D M Region 5, Office of Director 92/10/16 ip 15787 100 24X Fichs 50-275, 82/10/16, 8210250055
- B210290219 Forwards LER 82-009/01T-0 EHIFFER, J D Pacific Qas & Electric Co 82/10/18. ENGELKEN, R H Region 5. Gffice of Director ip 15853 224. 24X Fiche 50-275, 82/10/18, 8210290219

- --8210290222 LER 82-009/01T-D on 821007, testing on auxiliary saltwater sys revealed sys susceptible to water hammer effects during anticipated operational transients Caused by water column separation 5 recombination at piping slope change KAEFER. W 8 Pacific Cas & Electric Co 82/10/19 Region 5, Office of Director 2pp 15853 227 24X Fiche 30-275,82/10/18, contractions. Office of Director 8210270217
- T Hearing transcripts on non-antitrust matters
- 8210290370 Unofficial transcript of 821020 public discussion of Phase II reverification program in Washington.DC Pp 1-113 Supporting documentation encl. Commissioners 82/10/20 144pp 15845-095 24X Fiche 50-275, 82/10/20, 8210290370
- 8210220416 Forwards transcript of Commission 821020 meeting to receive NRC briefing on proposed scope of Phase II of independent design verification program & 821017 meeting w/ util 2 participants re program & 8ECY-82-414 W/o encl CHILK, 8 J Office of the Secretary of the Commission 82/10/21 Office of the Executive Legal Director ip 15779 211 24X Fiche 50-275, 82/10/21, 8210220416
- DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2 J Insurance & indamnity information
- 8210060276 Forwards Endorsement 99 to NELIA Policy NF-140 & Endorsement BRADLEY, E J Philadelphia Electric Co 82/09/30. SALTZMAN, J Assistant Director for State & Licensee Relations 3pp. 15619 204 24/ Fiche 50-277,82/09/30,8210060296
- P. Operating license stage documents & correspondence
- 8210280013 Responds to FOIA request for all internal, non-public documents, memos, evaluation repts to other matidualing w/ nuclear plant operations Forwards documents listed in App A FELTON.JM Division of Rules and Records 82/09/17 MCINNIS, D News to Observer 5pp 15860 O65 24X Ficha 90-000,82/09/17. B210280013
- --B208310034 Forwards draft info notice re deficiencies in air filtration & ventifation sys. Notice based on radioactive resin release at Pilgrim 1 & on four related events at other plants involving deficiencies in maint & testing of filter sys. MATTSCN.R J Division of Systems Integration (post 81008). 82/08/05 JORDAN, E.L. Division of Engineering & Quality Assurance 5pp 15961:024 24X Fiche. 90-000, 82/09/17, 8210280013
- 8210050320 Forwards "Thermal Mapping Rept 82-3 for 820818 for Thermal Monitoring Requirements." per App B to ETS WILLSEY, N B Philadelphia Electric Co 82/09/28 IPPOLITG, T. A WILLBEY, W B Philadelphia Electr Operating Reactors Branch 3 ip Fiche 50-277,82/09/28,8210050320 15601-358
- --8210050321 "Thermal Mapping Rept 82-3 for 820818 for Thermal Monitoring Requirements \* Philadelphia Electric Co 82. Fiche 50-277,82/09/28,8210050320 82/09/28 4pp 15601 359 24X
- 82:0150282 Forwards "Rept of Plant Startup Following fifth Refueling Outage," Feb 1982 ALDEN-M M. Philadelphia Electric Co 82/10/06. HAYNES,R C Regi 1. Office of Director ip. 15705:266 24X Fiche 50-277,82/10/06.
- --8210150292 "Rept of Plant Startup Following Fifth Refueling Outage." 820219
  - DESCRIPTION OF THE PROPERTY OF
- 8210260329 Submits info re potential problem w/ventilation systassociated w/battery & emergency switchgear rooms, solution to problem & schedule for completion of necessary mode Mode will be completed by 821231 COONEY, M. J. Philadelphia Electric Co. 82/10/14 HAYNEB, R. C. Region i, Office of Director Spp. 15803, 205 24X Fiche: 50-277, 82/10/14,8210260329 HAYNEB R C.
- 8210200046 Forwards application to amend Licenses DPR-44 & DPR-56 to ciuguoune rormanes application to amend Licenses DPR-44 & DPR-56 to reflect mods required to meet criteria of NUREO-0861,App A; "Mark I Containment Long-Term Program." BRADLEY,E J Philadelphia Electric Co. 82/10/13 DENTON,H. R. Office of Nuclear Reactor Regulation, Director. 1p. 15756:135. 24X Fiche:50-277,82/10/15,8210200046

11.

. .

١,

ų.

,

- --8210200063 Application to amend Licenses DPR-44 & DPR-56 to reflect mode required to meet criteria of NURCO-0661 App A. "Mark I Containment Long-Term Program" Affidavit & Certificate of Svc encl BAUER. E G , BRABLEY, E J Philadelphia Electric Co 82/10/15 70s 15756 136 24X Fiche 50-277.82/10/15.8210200046
- --8210200068 Proposed Tech Spec pages, reflecting mods required to meet criteria of NUREO-0661. App A. "Mark I Containment Long-Term Program"

  4 Philadelphia Electric Co. 82/10/15 App 19756 143 24X Fishe 50-277, 82/10/15
- B210210297 Bubmits add1 info re util B11229 response to NUREG-0803.
  "Bafety Concerns Associated W/Pips Breaks in BWR Scram
  Sys." in response to NRC 820824 request
  DALTROFF.S L. Philadelphia Electric Co. 82/10/15 STOLZ.J F
  Operating Reactors Branch 4 10pp 15764 267 24X
  Fiche 80-277.82/10/15.8210210297
- 8210210330 Proposes 830131 as date for responding to NUREQ-0737, Item II B 3, "Post-Accident Sampling Sys "
  DALTROFF, S L Philadelphia Electric Co 82/10/15 STOLZ, J F Operating Reactors Branch 4 2pp 13765 063 24X Fiche 50-277, 82/10/15, 8210210330
- 8210280196 Forwards response to draft technical evaluation rept recontrol of heavy loads Addl info requested in 820405 teleon one!

  DALTROFF. 8 L Philade[phia Electric Co 82/10/25 STOLZ.J F Operating Reactors Branch 4 45pp 15839.136 24X Fiche 50~277.82/10/25.8210280196
- --B2102B0198 "Structural Analysis of Peach Bottom Units 2 & 3 Reactor Pressure Vessel Head Drop Shroud Head Assembly Drop & Steam Dryer Assembly Drop Conditions " HERRERA,M L. MOK.9 Deneral Electric Co 82-32 82/08/3i 38pp
- --B210280201 "Lifting Devices & Lifting Points Stress Analysis for Reactor Pressure Vessel Head Stronpback Stoam Dryer/ Separator Sling & Svc Platform to Comply W/NUREG-0612 for Peach Bottom Units 2 & 3 " KONG.Y H General Electric Co MSE-50-0582 82/05/31 Sipp 18839 219 24X Fiche 50-277,82/10/25.8210280196
- --8210280204 "Lifting Devices & Lifting Points Stress Analysis for Fuel Paol Oate Lifting Points. Hydraulic Tensioner Lifting Device & Lifting Points & Reactor Pressure Vessel Insulation Removal Lifting Device & Insulation Lifting Points " SZUMBKI,T J Philadelphia Electric Co NSEQ-72-0782 82/07/31 27pp 15839 250 24X Fichs 50-277.88/10/25.8210280192
- O Inspection reports: IE Bulletins & correspondence
- 8210070317 Forwards IE Insp Repts 50-277/82-20 & 50-278/82-19 on 820816-20 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 82/09/22 DALTROFF, 8 L. Philadelphia Electric Co 2pp 19634, 135 24% Fiche 50-277, 82/09/22, 8210070317
- --8210070322 Notice of violation from insp on B20816-20.

  \* Division of Engineering & Technical Programs 82/09/14 ip 15634 137 24% Fiche. 30-277, 82/09/22,8210070317
- --8210070330 IE Insp Repts 50-277/82-20 & 50-278/82-19 on 820816-20 Mancompliance noted no notification given for almormal degradation in primary containment, evidenced by unacceptable local leak rate test results for nine isolation valves PULLANI.8 V , BETIENHAUSEN L Division of Engineering & Technical Programs 82/09/14 7pp 15634 138 24X Fiche.50-277.82/09/22, 8210070317.
- 8210150297 Forwards IE Insp Repts 50-277/82-19 k 50-278/82-18 on 820807-0915 No noncompliance noted STAROSIECKI, R Division of Project & Resident Programs, 82/09/27, DALTROFF, S L. Philadelphia Electric Co 2pp 15707 234 24X Fiche: 50-277, 82/09/27, 8210150299
- --8210150302 IE Insp Repts 50-277/82-19 & 50-278/82-18 on 920807-0915. No noncompliance noted Major areas inspected operational safety-radiation protection-physical security-control room activities & IE bulletin followup.

  BLOUGH.A R. MCCANE.E C Division of Project & Resident Programs.

  B2/09/20 19pp. 15707 236 24K Fiche 50-277.82/09/27.8210150299.
- 8210070177 Forwards inservice insp rept completed during 820220-0702 refueling outage, Insp requirements met satisfactorily, COUNEY. H. J. Philadelphia Electric Co. 82/09/29 HAYNEB, R. C. Region I. Defice of Director. 1p. 15635 298. 24X Fiche. 50-277, 82/09/29, 8210070177.

- --8210070188 Inservice insp rept completed during 820220-0702 refusirg outage # Philadelphia Electric Co 82/09/20 96pp 15635 299 248 Fiche 50-277, 82/09/29, 8210070177
- 8210150069 Submits final response to IE Bulletin 81-01. "Surveille" of Mechanical Shubbers "Pacific Scientific Co manufactures 48 mechanical shubbers utilized at facility List of mode) numbers encl DALTROFF, S. L. Philadelphia E)ectric Co. 82/10/04 HAYNES, R. C. Region 1. DFPice of Director 2pp. 15701 241 24% Fiche 50-277, 82/10/04,8210150069
- 820B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-321 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Baieguarde 82/10/06 Consolidated Edison Co of New York 66pp 13761 25 24x Fiche 50-000,82/10/06,8208190233
- B210130291 Ack receipt of B20929 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/82-14 & 50-278/82-14 BTAROSTECKI.R Division of Project & Resident Programs 82/10/66 DALTROFF, B. Philadelphia Electric Co ip 15678 347 24X Fiche 50-277, 82/10/06,8210130291
- --B210130276 Responds to NRC B20901 ltr re violations noted in IE Ira Repts 50-277/82-14 & 50-278/82-14 Corrective actions defective locking mechanism replaced & personnel instructed to be more forceful when checking locked doors DALTROFF, B. L. Philadelphia Electric Co. B2/09/29 BTAR091641 ( Division of Project & Resident Programs 2pp. (5678-348-24) Fiche 50-277, B2/10/06, B210130291
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Gys
  Piping at BMR Plants "Svc list encl
  DEYCUNG, R C Director's Office, Defice of Inspection and
  Enforcement 82/10/14 Consolidated Edison Co of New York
  115pp 15810 125 24X Fichs 50-000, 82/10/14,8208190238
- R Periodic operating reports & related correspondence
- 8210150356 Forwards Thermal Mapping Rept 82-4 for 820907 for thereal monitoring requirements, per App 8 to ETB WILLSEY, N B Philadelphia Electric Co 82/10/08 JPPOLITO, T A Operating Reactors Branch 3 1p 15704 277 24X Fiche 50-277, 82/10/08, 8210150354
- --B21015036B Thermal Mapping Rept 82-4 for 820909 \* Philadelphia Electric Co 82/10/08 4pp 15704 27|| 241 Fiche 80-277,82/10/08,8210150356
- 8210220170 Forwards monthly operating repts for Bept 1982 GOONEY, M. J. Philadelphia Electric Co. 92/10/15 Director's Office. Office of Inspection and Enforcement 1p 15777 273 24s Fiche 50-277, 82/10/15.0210220170
- ---8210220194 Monthly operating repts for Sept 1982 ALDEN.W M Philadelphia Electric Co 82/10/15 10pp 15/// 2/4 24X Fiche 50-277,82/10/15,8210220190
- S Reportable occurrences, LERs & related correspondence
- 8210060074 Forwards LER 82-027/017-0 Detailed event analysis enti CDONEY, M J Philadelphia Electric Co 82/09/24 HAYNES, R C Region 1, Office of Director 3pp 15615 047 24X Fiche. 50-277, 82/09/24.8210060074
- ---B210060083 LER B2-027/01T-0, on B20910, svc air valve to containaint found open Caused by personnel failure to make entry in locked valve log book when valves opened Valve closed & locked CGONEY, M. J. Philadelphia Electric Co. 82/09/24 Region I. Office of Director 1p. 15615-050-24X Fiche, B0-277, B2/09/24 B250060074
- 8210060353 LER 82-025/03L-0 on 820827, while performing surveiblance test: C RNR pump room C cooling fan would not start in automatic Caused by corroded contacts on C fan switch BPS 0400-16 Switch rewired & calibr COONEY, M J Philadelphia Electric CO 82/09/24 MAYNES, R C Region 1, Office of Director ip 15615 194. 24X Fiche 30-277, 82/09/24,8210060353.

- 8210060047 LER 82-028/03L-0 on 820908.LIS-2-3-73B.reactor Lo-Lo-Lo containment spray interlock discovered out of calibr Caused by satpoint drift of Rosemont Model 1151 trip unit Device recalibr wevice recalls COONEY, M J Philadelphia Electric Co 82/09/27 HAYNES, R C Pegion 1. Office of Director 1p 15615 088 24X Fiche 50-277.82/09/27.8210060047
- 0210060177 LER 82-026/03L-0 on 820831.RHR pump 2A failed to start during test on FR-2-10-143 Caused by uncharged breaker closing spring due to faulty closing latch monitoring switch in charging motor circuitry Switch replaced
  OPPI
  OPPI
  OP Director 1p 15615 099 24X Fiche 50-277.82/09/30, 8210060177 Region 1, Office
- 8210150400 LER 82-031/03L-0 on 820831, smoke detector 814 in emergency SUITCH SETUSION OF BEST TO ASSESS THE SECRET SIN IN AMERICAN SET TO BE SET TO BE SET TO SET THE SET THE SET OF SET Fithe 50~277, 82/09/30, 8210150400
- 6210150154 Forwards LER 82-030/01T-0 Detailed event analysis submitted COONEY.H J Philadelphia Electric Co 82/10/01 HAYNES.R C Region L Office of Director 3pp 18707 311 24X Fiche 50-277, 82/10/01.8210150154
- --9210150179 LER 82-030/01T-0 on 820917. w/both units at power, small quantity of slightly contaminated water released from recombiner bldg into stoim drain sys Caused by spurious action of Orinnell Model B fire suppression valve COONEY. H J Philadelphia Electric Co 82/10/01 Region 1, Office of Director 1p 15707 314 24X Fiche 50-277,82/10/01,
- 6210260112 LER 82-029/03L-0 on 820915, during power, supervisory Alarm occurred indicating fire sys problems Investigation revealed heat detectors in startup switchgear bidg inoperable Caused by disconnected circuit breaker due to stripped screw COUNEY.M J Philadelphia Electric Co 82/10/14 HAYNES,R Region 1, Office of Director ip 15805 247 24X Fiche 50-277.82/10/14.8210260112 HAYNES R C
- 8210270366 PNO-1-82-06B on 821024, primary sys relief valve began cycling during startup after maint shutdown, causing sys swell which resulted in feed pump trip on high reactor water level followed by low level scram HPCI manually initiated MCCABE, EC. KEIMIQ Region 1, Office of Director 82/10/25 15853 034 24X Fiche 30-277,82/10/25,82/0270366
- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3
- J Insurance & indemnity information
- 0210060296 Forwards Endorsement 99 to NELIA Policy NF-140 & Endorsement 210060296 Forwards Engorsement 77 to NELLA FULLEY NOT-53 to MAELU Policy MF-67 BRADLEY.E J Philadelphia Electric Co 82/09/30 Assistant Director for State & Licensee Relations 24X Fiche 50-277,82/09/30.6210060296 SALTZMAN, J 3pp 15619 206
- P Operating license stage documents & correspondence
- 8207090201 Forwards application to amend License DPR-56, changing Tech Specs to reflect changes to ODYN computer code & including Revision 1 to "Supplemental Reload Licensing Submittal for Peach Bottom Unit 3.Reload 4 "
  BRADLEV.E J Philadelphia Electric Co 82/07/06, DENTON.H R
  Dffice of Nuclear Reactor Regulation, Director ip 13788,113, 24x
  Fiche 80-278.82/07/06.8207090201
- --8207090208 Application for amend to License DPR-54, changing Tech Bpscs to reflect changes in analyses resulting from corrections to DIVN computer code PALTROFF, 8 Philadelphia Electric Co 82/07/06 6pp 13788.115, 24X Fiche 50-278,82/07/06,8207090201 DALTROFF, 8
- ---8207090215 Tech Spec Tables 3 5 K 2 & 3 5 K 3 & Figures 3 5 K 1 & 3 5 K 2. supporting application for amend to License DPR-56 \* Philadelphia Electric Co. 82/07/06 4pp 13788 120 Fiche 50-278, 82/07/06, 8207090201
- --8207090224 Revision 1 to "Supplemental Reload Licensing Submittal for Peach Bottom Atomic Power Station Unit 3, Reload 4 "
  LEASER, J D , ENGEL, R E General Electric Co Y1003J01A20 R01.
  82/06/30 41pp 13788-124 24X Fiche 50-278, 82/07/06, 8207070201.
- 8210050320 Forwards "Thermal Mapping Rept 82-3 for 820818 for Thermal Monitoring Requirements," per App 8 to ET8
  WILLSEY,W B Philadelphia Electric Co 82/09/28 IPPOLITO, T. A Operating Reactors Branch 3 ip, 15401,358 24X
  Fiche 50-277.82/09/28.8210050320

- --8210050321 "Thermal Mapping Rept 82-3 for 820818 for Thermal Monitoring Requirements "
  # Philadelphia Electric Co 82, Fiche 50-277, 82/09/28, 8210080320 82/09/28 4pp 15401 359 24x
- 8210240329 Submits info re-potential problem w/ventilation sys-associated w/battery & emergency switchgear rooms, solution to problem & schedule for completion of necessary mode Mode will be completed by 821231 COONEY.M J Philadelphia Electric Co 82/10/14 HAYNES,R ( Region 1, Office of Director 3pp 15803 205 24X Fiche 50-277, 82/10/14,8210260329
- 8210200046 Forwards application to amend Licenses DPR-44 & DPR-56 to reflect mode required to meet criteria of NUREO-0661, App A. "Mark I Containment Long-Term Program"

  BRADLEY, E. J. Philadelphia Electric Co. B2/10/15 DENTON, H R THATE CONCESTIBLE OR TERM PROGRAM PARTIES OF BEAUTION OF THE PROGRAM OF THE PROGR
- --8210200063 Application to amend Licenses DPR-44 & DPR-56 to reflect mods required to meet criteria of NUREG-0661.App A, "Hark I Containment Long-Term Program " Affidavit & Certificate of Svc ancl Svc enci BAUER, E 0 . BRADLEY,E J Philadelphia Electric Co 82/10/15 7pp 19786.136 24X Fiche 50-277,82/10/15,8210200046
- ---8210200068 Proposed Tech Spec pages, reflecting mods required to meet criteria of NUREG-0661. App A. "Mark I Containment Long-Term Program" \* Philadelphia Electric Co 82. Fiche 50-277,82/10/15,8210200046 82/10/15 6pp 15796 143 24X
- 8210210297 Submits addi info re util 811229 rusponse to NUREO-OBO3, "Safety Concerns Associated M/Pipe Breaks in BWR Scram 8ys." in response to NRC 820824 request DALTROFF, B L. Philadelphia Electric Co. 82/10/15 8TOLZ, J, F. Operating Reactors Branch 4 10pp 15764 267 24X Fiche 50-277, 82/10/15, 8210210297
- 8210210330 Proposes 830131 as date for responding to NUREQ-0737. Item IT B 3, "Post-Accident Sampling Sys "
  DALTROFF, B L Philadelphia Electric Co 82/10/15 STOLZ, J F Operating Reactors Branch 4 2pp 15765 063 24X Fiche 50-277, 82/10/15, 8210210330
- 8210220006 Forwards application to amend License DPR-56, requesting Tech Spec change to extend insp interval applicable to two inaccessible hydraulic snubbers BRADLEY, E.J. Philadelphia Electric Co. 82/10/19 DENTON, H.R. BRADLEY.E J Philadelphia Electric Co 82/10/19 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 15778 219 Fiche 50-278, 82/10/19.8210820006
- --8210220007 Application to amend License DPR-56, changing Tech Specs to extend insp interval applicable to two inaccessible hydraulic snubbers Certificate of Bvc encl
  BAUER,E 0, BRADLEY,E J Philadelphia Electric Co
  6pp 15778 220 24X Fiche 30-278,82/10/19,82/0220006
- 9210280196 Forwards response to dreft technical evaluation rept re control of heavy loads Addl info requested in 820405 telcon enci DALTROFF,8 L Philadelphia Electric Co B2/10/28 STOLZ:J F Operating Reactors Branch 4 45pp. 15839 134 24x Fiche 50-277,82/10/25,8210280196
- --B210280198 "Btructural Analysis of Peach Bottom Units 2 & 3 Reactor Pressure Vessel Head Drop. Shroud Head Assembly Drop & Steam Dryer Assembly Drop Conditions " HERRERAM L. MCK.O General Electric Co. 82-32 82/08/31 38pp 15839, 181 24X Fiche: 50-277.82/10/25.8210280196.
- --- 8210280201 "Lifting Devices & Lifting Points Stress Analysis for Reactor Pressure Vessel Head Strongback Steam Dryer/ Separator Sling & Syc Platform to Comply W/NUREQ-0612 for Parch Bottom Units 2.2.4 Peach Bottom Units 2 & 3 "

  KONO.Y.H. Oeneral Electric Co NSE-50-0582 82/05/31, 31pp
  15837 217 24X fiche: 50-277, 882/10/25, 8210280176 24X Fiche 50-277, 82/10/25, 8210280196
- ---8210280204 "Lifting Devices & Lifting Points Stress Analysis for Fuel Pool Cate Lifting Points, Hydraulic Tensioner Lifting Device & Lifting Points & Reactor Pressure Vessel Insulation Removal Lifting Device & Insulation Lifting Points " SZUMBKI.T J. Philadelphia Electric Co. . NBEO-72-0782. 82/07/31 29pp 15839, 250 24X Fiche: 50-277, 82/10/25, 8210280196.

## Q Inspection reports. IE Bulletins & correspondence

- 8210070317 Forwards IE Insp Repts 50-277/82-20 & 50-278/82-19 on 820816-20 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 82/09/22 DALTROFF.8 L Philadelphia Electric Co 2pp 15534 135 24X Fiche 50-277,82/09/22,8210070317
- --B210070330 IE Insp Repts 50-277/B2-20 & 50-278/B2-19 on 620816-20 Noncompliance noted no notification given for abnormal degradation in primary containment, evidenced by unacceptable local leak rate test results for nine isolation valves PULLANI.S V , BETTENHAUSENIL Division of Engineering & Technical Programs. 82/09/14 7pp. 15634.138 24X Ficher50-277,82/09/22,8210070317
- 8210070294 Forwards IE Insp Rept 50-278/81-28 on 811013-15
  MARTIN.T T Division of Engineering & Technical Programs
  DALTROFF,S L Philadelphia Electric Co 2pp 15534:218
  24X
  Fitche 50-278,82/09/24,8210070294
- --8210070308 IE Insp Rept 50-278/81-28 on 811013-15 Noncompliance noted failure to follow radiation protection procedure & promptly notify NRC in accordance w/100FRS0 72
  NIMITZ.R L , OREENMAN.E Ø. Division of Engineering & Technical Programs. 82/07/26 18pp 15634 220 24% Fiche 50-278,82/09/24,8210070296
- 8210150299 Forwards IE Insp Repts 50-277/82-19 & 50-278/82-18 on B20807-0915 No noncompliance noted STAROBTECKI.R. Division of Project & Resident Programs 82/09/27. DALTROFF, B L Philadelphia Electric Co 2pp 19707 234 24X Fiche: 50-277.82/09/27.8210150299
- --8210150302 IE Insp Repts 50-277/82-19 & 50-278/82-18 on 820807-0915 No noncompliance noted Hajor areas inspected operational safety, radiation protection, physical security, control room activities & IE builetin followup BLOUGH. A R., MCGANE. E C. Division of Project & Resident Programs 82/09/20 19pp 15707 236 24X Fiche 50-277, 82/09/27, 8210150299
- 8208190233 IE Info Notice 80-35, Suppl (, "Leaking & Dislodged I-125 Implant Seeds," Svc list encl. CD85L I Division of Evel Facilities, Materials & Safeguards 82/10/04 Consolidated Edison Co of New York 46pp 15761 250 24X Fiche-50-000.82/10/06.8208190233
- 6210130291 Ack receipt of 620929 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/82-14 & 50-276/82-14.

  STAROSTECKI.R Division of Project & Resident Programs 82/10/06, DALTROFF, S L Philadelphia Electric Co. 1p. 15678 347 24X Fiches: 50-277, 82/10/06, 8210130291
- --8210130296 Responds to NRC 820901 ltr re violations noted in TE Insp. Rapts 50-277/82-14 & 50-278/82-14 Corrective actions defective locking mechanism replaced & personnel instructed to be more forcaful when checking locked doors.

  DALTROFF.8 L. Philadelphia Electric Co. 82/09/29. STAROSTECKI.R. Division of Project & Resident Programs. 2pp. 19678 348 24X Fiche 50-277.82/10/06.8210130291.
- 8208190238 IE Sulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter. Stainless Steel. Recirculation 8ys Piping at BMR Plants " Svc list encl.

  DEVOUNG.R.C Director's Office. Office of Inspection and Enforcement. 82/10/14 Consolidated Edison Co. of New York 115pp 13810-125 24X Fiche. 50-000. 82/10/14.8208190238
- 8210220006 Forwards application to amend License DPR-56, requesting Tech Spec change to extend insp interval applicable to two inaccessible hydraulic shubbars. BRADLEY.E.J. Philadelphia Electric Co 82/t0/19 DENTON, H R. Office of Nuclear Reactor Regulation, Director ip. 15778; 219, 24X Fichs. 50-278, 82/10/19, 8210220006.
- --821022007 Application to amend License DPR-56-changing Tech Specs to artend insp interval applicable to two inaccessible hydraulic snubbars. Cartificate of Bvc encl.
  BAUER. E. 0. BRADLEY. E. J Philadelphia Electric Co. 82/10/19. 6pp. 15778: 220. 24K Fiche. 50-278, 82/10/19, 8210220006.
- R Periodic operating reports & related correspondence
- 8210150356 Forwards Thermal Happing Rept 82-4 for 820909 for thermal monitoring requirements, per App 8 to EY8
  HILLSEY.W B. Philadelphia Elactric Co 82/10/08. IPPOLITO, T A Operating Reactors Sranch 3. 1p 13704:277. 24%
  Fichs. 50-277, 82/10/08, 8210150356.

- --B210150368 Thermal Mapping Rept 82-4 for B20909 + Philadelphia Electric Co 82/10/08 4pp 15704 27g 29 Fiche 50-277,82/10/08.8210150354
- 8210220190 Forwards monthly operating repts for Bept 1922 CDONEY:M J Philadelphia Electric Co 82/10/15 Directs\*'s Office. Office of Inspection and Enforcement 1p 13777 273 P Fiche 50-277, 82/10/15,8210220190
- --8210220194 Monthly operating repts for Sept (982 ALDEN,W M Philadelphia Electric Co 82/10/15 10pp 19777 24X Ficha 50-277.82/10/15,8210220190
- 8 Reportable occurrences, LERs & related correspondence
- E210070474 Discusses B10225 menual scram of reactor after irad." RKR relay logic A signal initiated simultaneous cloure of both recirculation pump discharge valves All battery ground tracing should be done w/ohmeter w/o fuee. ABHE.F Director's Office B1/04/17 Director's Office B15644 351 24X Fiche 50-278, 81/04/17, 8210070474
- 821001000B Responds to FOIA request for 19 categories of doller's nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 62/06/20 UDELL'S' Critical Mass Energy Project 15pp 15727 003 24x Fiche 30-000.82/06/28.821001000B
- --B210050023 Discusses 810225 simultaneous closure of rectarvial discharge valves Event occurred while station personnel were attempting to remove ground associated w/A div of [25-vels dc subsystem ABHE:F Director's Office 81/04/17 Director's Office 15729 039 24X Fiche 50-000, 82/06/28, 8210010008
- 8210060017 LER 82-015/03L-0.on 820822.drywell pressure retorder his failed downscale Caused by blown fuse Fuse replaced hisys operation verified CODMEY: M. J. Philadelphia Electric Co. 82/09/21 RAYNES # ( Region 1, Office of Director ip 15615-08/ 24X Fiche. 80-278.82/09/21.8210060017
- 8210130226 LER 82-017/03L-0 on B20902 during heavy reinitors egging between that vent stack flow recorder indicated downcals on both channels Caused by pilot tubes filling w/waitr during severe storm indication returned when store subsided COONEY.M. J Philadelphia Electric Co 82/10/01 MAYNES.B € Region 1. Defice of Director ip 15679 009 24% Fichs: 50-278. 82/10/01. 8210130226
- DOCKET 50-280 BURRY POWER STATION, UNIT I
- F Security, medical, emergency & fire protection plans
- 8210010156 Ack receipt of 820820 responses re wmergency preparely deficiency items per 820406 confirmation of action lit Corrective action & plans will be examined during subsequent inspection of Project & Resident Programs 82/07/18 LEASBURG, R. H. Virginia Electric & Power Co. 1p. 18585 375 & Fiche 50-280, 82/07/10, 82/00/0156
- R210010125 Forwards revised security training & qualification per Plans withheld, LEASBURGOR H Virginia Electric & Power Co 82/09/17 New X-Diffice of Nuclear Reactor Regulation, Director, VARGA-S A Operating Reactors Branch 1 ip 18866-019 24X Fiche 30-000, 82/09/17, 8210010125
- 8210050D76 Submits correction to 820628 Revision 3 to risperse to NUREO-0737. Item I. D. 2. "Bafety Parameter Display By: "Correction should be included in schedular exceptions pertaining to emergency response capabilities LEASBURG, R.M. Virginia Electric & Power Go. 82/09/29 DOTA Defice of Nuclear Reactor Regulation, Director. E186M47.5 B Division of Licensing ip. 15603:185 24X Fiche 50-000 82 > 8210050076.
- 8210210030 Releases public version of changes to swarganty plat implementing procedure FELTON, J M Division of Rules and Records, 82/09/29 Store Management Branch 1p. 15774-109, 24X Fichs.50-280.82/09/29 8210210050.

- --B210210053 Forwards public version of Change 1 to Emergency Plan Implementing Procedure EPJP-4 11, "Followup Offsite Release Assessment: "Change 2 to emergency plan re NVREO-0654 cross-ref & Change 3 modifying Table 5 1
  DEWANDEL, E. P. Virginia Electric & Power Co. B2/09/17 NRC Octailed Affiliation Given 1p. 15774 110 24x
  Fiche 50-280, 82/09/29, 8210210050 NRC - No
- --8210210055 Public version of Change 1 to Emergency Plan Implementing Procedure EPIP-4 11. "Followup Offsite Release Assessment" + Virginia Electric & Power Co 82/09/17 2pp 15774 111 24X Fiche 50-280,82/09/29.8210210050
- --8210210058 Public version of Changes 2 & 3 to emergency plan re NUREC-0654 cross-ref & Table 5 1, "Min Shift Manning Requirements," respectively Virginia Electric & Power Co 82/09/17 10pp 15774 113 24X Fiche 50-280,82/09/29,8210210050
- □ Operating license stage documents & correspondence
- 3210280013 Responds to FOIA request for all internal, non-public documents, memos, evaluation repts & other mat1 dealing w/
  nuclear plant operations Forwards documents listed in App A.
  FELTOR, J M Division of Rules and Records 82/09/17 MCINNIS, D
  News & Observer 5pp 15860 045 24X Fiche 50-000, 82/09/17. 8210280013
- --8208310034 Forwards draft info notice re deficiencies in air filtration & ventilation sys Notice based on radioactive resin release at Pilgrim i & on four related events at other plants involving deficiencies in maint & testing of filter sys HATTSDN, R J Division of Bystems Integration (past 811005) 82/08/05 JORDAN, E L Division of Engineering & Guality Assurance 5pp 15861 024 24X Fiche 50-000,82/09/17,8210280013
- 1210120265 Informs of implementation status of NUREO-0737, Item II B 2, 'Plant Shielding' per NRC 820517 request All required work completed
- LEASBURG, R H Virginia Electric & Power Co 82/10/01 PENTON, H R Office of Nuclear Reactor Regulation, Director EISEMHUT, D Q Division of Licensing 2pp 15451 230 24% Fiche 50-000,82/10/01. 8210120245
- #210120297 Forwards errata to Topical Rept VEP-FRD-33, "VEPCO Reactor Core Thermal-Hydraulic Analysis Using COBRA IIIc/MIT Computer Code "
- LeadBURO.R H Virginia Electric & Power Co 82/10/04 DENTON, H R Office of Nuclear Reactor Regulation, Director EIBENHUT, D 9 Division of Licensing 2pp 15652 350 24X Fiche 50-000, 82/10/04, 823012027
- -8210120305 Errata to "VEPCO Reactor Core Thermal Hydraulic Analysis Using COBRA-IIIc/MIT Computer Code " \* Virginia Electric & Power Co VEP-FRD-33 ERR 82/10/04 ip 15652 332 20% Fiche 50-000.82/10/04.8210120277
- 2:01:201:10 Forwards payment of requisite technical review fees for inservice imap & testing program
  LEASBUROR H Virginia Electric & Power Co 82/10/05 DENTON, H R
  Office of Nuclear Reactor Regulation, Director VARGA, 8, A
  Operating Reactors Branch i p 15651 250 24X
  Fichs 50-280, 82/10/05, 82/10/2010
- 210120258 Forwards payment of requisite technical review fees for relief requests from requirements of ABPE Section XI LEASBURG.R H Virginia Electric & Pawer Co 82/10/05 DENTON, H R Office of Nuclear Reactor Regulation. Director VARGA, S A Operating Reactors Branch 1 p 15652 210 24X Fishe 50-280:82/10/05.8210120258
- 210200043 Application for amend to Licenses DPR-32 & DPR-37 consisting
- elb200044 Application for amend to Licenses DPR-32 & DPR-37 consistig of proposed changes to Tech Specs modifying reporting & notification requirements
  LEASBURGOR H Virginia Electric & Power Co 82/10/06 DENTON.H R
  Office of Nuclear Reactor Regulation, Director VAROA,8 A
  Operating Reactors Branch i. 3pp 15757-225 24X
  Fiche 30-280,88/10/06.8210200043
- -821020004B Proposed changes to Tech Specs modifying reporting & notification requirements \* Virginia Electric & Power Co 82/10/06 2pp 15757 228 24X Fiche 50-280, 82/10/06, 8210200043
- 210270298 Ack receipt of 820918 application requesting relief from cartain post-repair test requirements of ABME code Class III fee requested since review involves consideration of single Safety issue
  Bl008.R H License Fee Management Branch 82/10/18
  Virginia Electric & Power Co ip 15836-329 24X
  Fiche 50-280, 82/10/15, 8210270298 82/10/15 LEASBURG, R H,

- 8210220170 Forwards corrected drawing re 1 1/2-inch drain valve f-MS-74 Valve incorrectly labeled f-MS-208 in 820915 ltr LEASBURG.R H Virginia Electric & Power Co. 82/10/18 DENTON.H R Office of Nuclear Reactor Regulation. Director VARGA.S A Operating Reactors Branch 1. 2pp 15778 043 24X Fiche 50-280, 82/10/18,8210220170
- 8210220178 Comments on evaluation of significant dynamic loads in determining capacity of slings used per NUREG-0612 Rating can be safely expressed in terms of max static load EASBURG.R H Virginia Electric & Fower Co 82/10/18 DENTON, H R Office of Nuclear Reactor Regulation. Director EISENHUT.D Q. Division of Licensing 2pp 15777 293. 24X Fiche 50-000,82/10/18,8210220178
- 8210280266 Informs that containment purge valve qualification program for 36-inch containment purge valves completed To ensure prevention of radioactive release, new automatic isolation valve will be installed LEASBURG.R H Virginia Electric & Power Co. 82/10/25 DENTON, H R LEABBURG, R H Virginia Electric & Power Co 82/10/25 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, 8 A Operating Reactors Branch 1 2pp 15837 316 24% Fiche 30-280, 82/10/25, 8210280266
- 8210280130 Informs that review of new fuel container lifting rig completed Rig does not comply w/Paragraph 3 2 1 I of ANSI NI4 6-1978 Proposed design mod for conformance being reviewed & will be implemented by 840322 LEASBURG, R H Virginia Electric & Power Co 82/10/28 DENTON, H R Office of Nuclear Reactor Regulation. Director EISENHUE, D & Division of Licensing ip 15837 163 24X Fiche 50-280, 82/10/28, 8210280130
- O Inspection reports, IE Bulletins & correspondence
- 8210080015 Add1 response to FDIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FDIA Exemption B) FELTON, J M Division of Rules and Records 82/07/12 Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000, 82/07/12, 8210080015.
- --8210080154 Systematic assessment of licensee performance notes re facility evaluation for May 1979-Apr 1980 \* NRC No Detailed Affiliation Given 80/04/30 6pp. 1868-051 24% Fiche: 50-000, 82/07/12,8210080015
- 8208260424 Ack receipt of util 820609 ltr & payment of civil penalty Based on review of incidents no basis for remission or nitigation of penalty identified LIEBERMAN.J Enforcement Staff 82/07/29 LEASBURG.R H Virgins Electric & Power Co Spp 15574 313 24X Fiche 50-280,82/07/29, 8208260424
- --8206160306 Responds to NRC 820510 ltr re violations noted in IE Inap
  Rept 50-280/82-58 Corrective actions prestartup chacklist
  will be performed by instrument supervisor & all employees
  counseled re procedural compliance
  LEASBURG,R H Virginia Electric & Power Co 82/06/07
  DEYOUNG,R. C Director's Office. Office of Inspection and
  Enforcement App 15574 316 24X Fiche 50-280.82/07/29,
  8208260324 Enforcement 8208260424
- --821001023B Forwards IE Insp Repts 50-280/82-04 & 50-281/82-04 on 820125-0226. Enforcement action sent separately on 820510 O'REILLY, U.P. Region 2. Office of Director. 82/03/13 LEASBURG, R. H. Virginia Electric & Power Co. 2pp 15574, 320. Fiche 50-280, 82/07/29, 8208260424. 15574, 320. 24X
- --8210010245 IE Insp Repts 50-280/82-04 & 50-281/82-04 on 820125-0226 Noncompliance noted failure to maintain operability of steam flow instrumentation & to follow GA manual & procedures for documenting inoperable steam flow instrumentation.

  8URKE D J : DAVIB.M J : DANCE.H C Division of Project & Resident Programs . 82/04/08. 9pp. 15574.322 24X Fiche 50-280.82/07/29, 8208260424.
- 8210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines. App A documents provided in R\_Udell FOIA Request 81-313 Forwards documents lieted in App B FELTON, J H Division of Rules and Records. B2/08/10. Winthrop. Stimson: Putnam & Roberts 9pp. 15645.063 Fichs. 50-000, 82/08/10, 8210070007. 82/08/10. LONG, D J
- --B210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensess IPPOLITO, T. Operating Reactors Assessment Branch. B2/04/01. VAROA, B. Operating Reactors Branch 1 5pp. 15645 131 24X Fiche: 50-000, 82/08/10, 8219070007.

- --8210070172 Forwards info re steam generator integrity & insps at all operating PWRs.per 730320 & 21 requests Details of insps. including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach I GOLLER.K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY.R R Division of Technical Review (NRR-1975 only) 5pp 15648 196 24X Fiche 50-000.62/08/10,8210070007
- 8210010156 Ack receipt of 820820 responses re emergency preparedness deficiency items per 820406 confirmation of action ltr Corrective action & plans will be examined during subsequent inaps LEMIS, R.C. Division of Project & Resident Programs 82/09/10 LEASBURO.R H. Virginia Electric & Power Co. 1p. 15565-325 24X Fiche 50-260, 82/09/10, 8210010156
- B210130427 Forwards "Inservice Insp Program, Interval 2,821222-921222 "
  Relief requested from ASME Code, Section XI testing & Insp
  requirements
  LEASBURO, R H Virginia Electric & Power Co 82/09/21 DENTON-H R
  Office of Nuclear Reactor Regulation, Director EISENHUY, D 0
  Division of Licensing 1p 15679 152 24X Fiche 50-280,82/09/21,
  3210130427
- ~-9210130431 "Inservice Ensp Program Interval 2,821222-921222"

  \* Virginia Electric & Power Co 82/09/21 492pp 15679 153
  24X Fichs: 50-280,82/09/21,8210130427
- 8210220331 Forwards IE Insp Repts 50-280/82-25 & 50-281/82-25 on B20830-0903 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/10/04 LEASBURG.R H Vinginia Electric & Power Co 2pp 15776 275. 24x Fiche 50-280.82/10/04.8210220331
- ~~8210220356 IE Insp Repts 50-280/82-25 t 50-281/82-25 on 820830-0903 No noncompliance noted Major areas inspected followup on previous enforcement matters to unresolved items t followup on unplanned release of gaseous radioactivity HOSEY.C M. BARR, K.P. Division of Engineering t Technical Programs 92/09/30 10pp 15776 277 24X Fiche: 50-280, 82/10/04, 8210220331.
- 8210120110 Forwards payment of requisite technical review fees for inservice inep & testing program
  LEASBURG.R H Virginia Electric & Power Co 82/10/05 DENTON.H R
  Office of Nuclear Reactor Regulation, Director VARGA.S A
  Operating Reactors Branch 1 is 15651 250 24X
  Fiche 50-280,82/10/05.8210120110
- 8208190233 IE Info Notice 80-35. Suppl 1: "Leaking & Dislodged 1-125 Implant Seeds " Syc list encl. CD88.L.I Division of Fuel Facilities: Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 64pp. 15761 250 24X Fiche 50-000.82/10/05.8208190233
- 8208190238 IE Sulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at SNR Plants " Svc list encl DEYOUNG, R C Director's Office, Diffice of Inspection and Enforcement. 82/10/14 Consolidated Edison Co of New York, 1159p. 15810 125. 23X Fichs 30-000, 82/10/14,8288190238
- S. Reportable occurrences. LERs & related correspondence
- \$210150095 LER 81-022/03L-0 on 810703, low flow alarm observed for process vent sys Caused by process blower motors out of syc due to valve 1-CM-21 leaking through to vent piping during attempt to drain mixed bed demineralizer IA for resin fill HILSON, J. Virginie Electric & Power Co. 81/07/31 Region 2, ector 2pp 15701 192 24X Fiche 50-280,81/07/31.

- 8210150139 LER 81-029/03L-0 on B10808, while at 1007 power, individual rod position indicator for rod F 12 indicated erratically & 12 steps less than bank demand position Caused by poorelectrical connection between coil & signal module HILBON, J L Virginia Electric & Power Co 81/08/28 Region | Philadelphia, Office of the Director (81/03/01) 2pp \$55698 303 24X Fiche 50-280-81/08/28,8210150137
- 8210270212 Forwards LERs 81-069/03L.81-073/03L-0 & 81-072/03L-0 MILSON.J L Virginia Electric & Power Co BI/12/07 D'REILLY, J Regian 2, Atlanta, Office of the Director (81/03/01) 1p 15927 042 24% Fichs 50-280.81/12/07.8210270212
- --8210270215 LER 81-069/03L-0 on 911115.discovered loss of flow the BM-0M-101 & 102 process went monitors Caused by radiation monitor sample young circuit breaker tripping Cause not determined Breaker reset & pump started WALSOM, J L Virginia Electric & Power Co 81/12/07 Region Atlanta, Office of the Director (81/03/01) 3pp 15927 043 Fiche 50-280.81/12/07.8210270212
- --8210270220 LER 81-072/03L-0 on 811108, motor operated va)ve 286% to open when operated from control room during testing Cause undetermined Valve opened normally when tested later WILSON, J. Virginia Electric & Power Co. 81/12/07 Regist Atlanta, Office of the Director (81/03/01) 2pp 15827 046; Fiche 50-280, 81/12/07, 8210270212
- --8210270224 LER 81-073/03L-0 on 811108, isolation valve to recircul. spray HX A failed to close Cause undetermined Valve operated normally later Limit switch & torque settings examined & found satisfactory
  WILBON, J L Virginia Electric & Power Co 81/12/07 Regination to the Director (81/03/01) 2pp 19027 048, Fiche 90-280, 81/12/07, 8210270212
- 8210050103 Forwards LER 82-086/03L-0 WILBON, J L Virginia Electric & Power Co 82/07/24 O'REILLY. Région 2, Office of Director 1p 15603 292 24X Fiche 50-280.82/07/24.8210050103
- --8210050109 LER 82-084/03L-0 on 820827, radiation monitor RM-LU-II indicated 9 OE4 CPM w/o annunciation of alarm Caused by defective push button & setpoint drift Push button replaced & monitor recalibr HTLSON.JL Virginia Electric & Power Co 82/09/24 Regil Office of Director 2pp 15403 293 24X Fiche 50-280,82/09,82/09,82/05050303
- B210050073 Forwards LER 82-083/03L-0 & updated LER 82-084/01X-1 HILBON, J L Virginia Electric & Power Co 82/09/27 Cl'AFILLS. Region 2, Office of birector ip. 15603 175 24x Fiche 50-280, 82/09/27, 8210050071
- --8210050074 LER 82-083/03L-0 on 820831, performance of PT-27E This that amplicating for heat tracing panel 9, circuit 20, was below acceptance criteria Caused by excessive heat king tracing replaced & tested WILSON, J. L. Virginia Electric & Power Co. 82/09/27 Region 8210050071 Process of Director 2pp. 15603-176 24X Fiche 50-280.82/09/8210050071
- --8210050078 Updated LER 82-084/01X-1 on 820808, venting of A charge pump resulted in max instantaneous release rate being exceeded Caused by Pailure to change radiation monitor setpoint alarms to reflect new vent sys flow rates MILBON, J. Virginia Electric & Power Co. 82/09/27 Reji: Office of Director 3pp 15403 178 24X Fiche 50-280,82/09-8210050071
- 821005008; Forwards LERs 82-093/03L-0.82-054/03L-0.8 82-092/03L-0 WILBON, J L Virginia Electric & Power Co 82/09/27 O'REILLY. Region 2. Office of Director ip 15604 244, 24X Fichs.50-280.82/09/27.8210050081.
- --8210050086 LER 82-093/03L-0 on 820904, at 100% power, air bant if emergency diesel generator 1 found w/insufficient air pressure to start generator Caused by failure to reset local low air pressure Bottles filled to 200 psi WILSON-J L Virginia Electric & Power Co 82/09/27 Repi Office of Director 2pp 15604 245. 24x Fiche. 30-280, 82/09.8210050081
- --8210050091 LER 82-054/03L-0 on 820905, unattended portable pue; i to clean weterbox C swung around & flooded svc water pit containing svc water Valve MOV-SM-2028 grounded in open position Caused by operator error MOV-SM-2028 dried WILSON, J L. Virginia Electric & Power Co 82/09/27 Rejuit Office of Director 3pp 15604 247 24X Fiche 50-280,82/04/8210050081.

## **DOCKETED ITEMS**

- --8210050092 LER 82-092/03L-0 on 820905.at full power, RPI F-8 observed fluctuating up to 15 steps Caused by exposure of containment side electrical penetration to excessive moisture & faulty signal Steam leak repaired NLESUN.J L Virginia Electric & Power Co 82/09/27 Region 2, Office of Director 2pp 15604 250 24X Fiche 50-280.82/09/27, 8310030081
- 8210060361 Forwards LERs 82-087/03L-0 & 82-057/03L-0
  HILSON,J L. Virginia Electric & Power Co. 82/09/30 O'REILLY,J P
  Region 2. Office of Director 1p 15619 006 24X
  Fichs 50-280,82/09/30.8210060361
- --B210060372 LER 92-087/03L-0 on B20901 & 20, pump i-SW-P-10A experienced loss of suction power & on B20901.14 & 20, pump i-SW-P-10A experienced similar loss of suction Cause due to insufficient NPSH Svc water replaced Svc water pumps vented WILSON, J L Virginia Electric & Power Co 82/09/30 Region 2, Office of Director 3pp 15619 007 24X Fiche 50-280,82/09/30,62(006036)
- --82:0060398 LER 82-057/03L-0 on 820901.13.18 & 20, pump 2-8W-P-10A experienced loss of suction pressure & on 820913 & 14. pump 2-5W-P-10B experienced similar loss of suction Caused by insufficient NPBH Svc water reduced Svc water pump vented WILSON, J L Virginia Electric & Power Co 82/09/30 Region 2. GF10c0-0341 Proceedings of Director 3pp 15619 010 24X Fiche 50-280.82/09/30.
- 8210130204 Forwards LERs 82-055/03L-0.82-096/03L-0 & 82-095/03L-0 WILSON, J L Virginia Electric & Power Co 82/10/04 D'REILLY, J P Region 2. Office of Director ip 15675 258 24X Fiche 50-280.82/10/04,8210130204
- --9210130208 LER 82-055/03L-0 on 820906; charging pump auxiliary oil pump A tripped leading to tripping of replacement pump/motor Auxiliary pump failure caused by open winding in motor Replacement tripping caused by undersized thermal overloads UILSON, J. Virginia Electric & Power Co 82/10/04 Region 2, Office of Director 2pp 15675 259 24X Fiche 50-280,82/10/04,8210130204
- --8210130213 LER 82-096/03L-0 on 820916, w/unit at 99% power, PT-27C revealed that amp readings for beat tracing Panel 9, circuit 19, was below acceptance criteria Caused by excessive heat Defective heat tracing replaced & tested WILSDN, JL Virginia Electric & Power Co 82/10/04 Region 2, Office of Director 2pp 15675 261 24% Fithe 50-280, 82/10/04, 8210130204
- --8210130216 LER 82-095/03L-0 on 820911.w/unit at full power, steam generator C level indication LI-1-495 drifted high Caused by body-bonnet leak on transmitter ref leg root valve Repairs uill be performed during next outage WILSON, J. L. Virginia Electric & Power Co 82/10/04 Region 2, Office of Director 2pp 15675 263 24X Fiche 50-280,82/10/04, 9210130204
- \$210130500 Forwards LER B2-091/03L-0 WILSON, J. L. Virginia Electric & Power Co. 62/10/04 O'REILLY, J.P. Region 2. Office of Director ip. 15482 186 24X Fiche 50-280, 82/10/04, 8210130500
- --8210130507 LER 82-091/03L-0 on 820905, water & sediment found in lube oil of charging pump i-CH-P-1A Gaused by leak in one tube of lube oil cooler Godler replaced, oil changed & pump returned to svc III.50N. J. Virginia Electric & Power Co. 82/10/07 Region 2, Diffice of Director 2pp 15682 187 24X Fiche 50-280,82/10/04, 82/10/30500
- 8210220392 Forwards updated LER 80-019/03X-1 & LERs 82-058/03L-0 & 82-099/03L-0 WILSOM, J. Virginia Electric & Power Co 82/10/08 O'REILLY, J P Region 2. Office of Director ip 15779 212 24X Fiche 50-280. 82/10/08. 8210220392
- --8210220398 Updated LER 80-019/03X-1 on 800304, error discovered in vol of contaminated drain tanks for increasing tankage Caused by erroneous labeling Vols relabeled & other tanks evaluated for use in liquid waste release calculations
  WILSON, J. L. Virginia Electric & Power Co 82/10/08 Region 2,
  Office of Director 3pp 15779 213 24X Fiche 50-280, 82/10/08,
  8210220392
- --8210220408 LER 82-058/03L-0 on 820915, safety injection accumulator C round w/reduced boron concentration of 1.924 ppm Caused by leakage through check valve 2-81-144 during sensitized pipe flush Flush stopped Valve to be reworked during outage WILSON, J L Virginia Electric & Power Co 82/10/08 Region 2, Office of Director 2pp 15779 216 24X Fiche 50-280,82/10/08,8210220392

- --8210220413 LER 82-099/03L-0 on 820920, radiation monitors RJ-9W-101 & 102, VO-103 & 104 & RM-LW-108 lost power for 10 minutes Caused by blown supply fuse due to inadvertent shorting of control relay to ground fuse replaced WILSON, J L Virginia Electric & Power Co 82/10/08 Region 2, Office of Director 2pp 15779 218 24X Fiche 50-280, 82/10/08, 821020309
- 8210290267 Part 21 deficiency rept re potential galling problem between stem & bonnet of 1 25-inch & larger A105 carbon steel & A182-F22 valves supplied Feb 1981-Aug 1982 Valves should be serviced & stem &/or bonnet replaced IGABELLE, L D Conval, Inc 82/10/11 HAYNES, R C Region 1, Dffice of Director 17pp 13854 232 24X Fiche 50-000,82/10/11, 8210270267
- 8210220095 Forwards LERs 82-098/03L-0 & 82-053/03L-0 HILBON, J. L. Virginia Electric & Power Co 82/10/14 G'REILLY, J. P. Region 2. Office of Director ip 15778 177 24X Fiche 50-280, 82/10/14, 8210220095
- --8210220097 LER 82-098/03L-0 on 820919. Liquid waste monitor RM-LW-108 alarm setpoint exceeded Tech Spacs limit during performance of PT-26 1 Caused by defective log rate board. Defective parts replaced & meter calibr WILSON, J L Virginia Electric & Power Co 82/10/14 Region 2, Defice of Director 2pp 15778 178 24X Fiche 50-280, 82/10/14, 8210220095
- --B210220100 LER B2-053/03L-0 on B20714, pump 2-SH-P-10A lost suction pressure Caused by insufficient NPBH due to throatled syc water to air conditioning chillers Pump vented to restore NPSH MILSON, J L Virginia Electric & Power Co. B2/10/14 Region 2 Uffice of Director 3pp 15778 180 24% Fiche 50-280,82/10/14,8210220095
- 8210290264 Forwards LERs 82-100/03L-0,82-102/03L-0 & 82-103/03L-0 WILSON, J. L. Virginia Electric & Power Co. 82/10/22 O'REILLY, J.P. Region 2, Office of Director ip. 15853 128 24X Fiche 50-280,82/10/22,8210270264
- --8210270270 LER 82-100/03L-0 on 820922.pump 1-SWP-108 became airbound during use of air to clear sensing lines to water strainers in delta P gauges Caused by injecting air into syc water lines upstream of pump Personnel reinstructed WILSON. J L Virginia Electric & Power Co 82/10/22 Region 2. Office of Director 2pp 15853 129. 24X Fiche 50-280,82/10/22. 8210270264
- --8210290276 LER 82-102/03L-O on 820923, discovered pin attaching snubber 1-8HP-H58-35B to main steam line partially out & snubber cocked Caused undetermined Snubber straightened & pins properly installed HILSON, J. Virginia Electric & Power Co. 82/10/22 Region 2, Office of Director 2pp 15853 131 24X Fiche 50-280, 82/10/22, 231080244
- --8210270282 LER 82-103/03L-0 on 820927.amp readings for heat tracing panel 2 circuit 24D found below acceptance level Cause unknown Defective heat tracing replaced & design change initiated HTLBON.J L Virginia Electric & Power Co 82/10/22 Region 2, Office of Director 2pp 15853.133 24X Fiche 50-280,82/10/22,8210270264.
- DOCKET 50-201 SURRY POWER STATION, UNIT 2

  F Security, medical, emergency & fire protection plans
- 8210010156 Ack receipt of 820820 responses re emergency preparedness deficiency items per 820406 confirmation of action itr Corrective action & plans will be examined during subsequent insps.

  LEMIS, R. C. Division of Project & Resident Programs 82/07/10 LEASBURG, R. H. Virginia Electric & Power Co. 1p. 15565-325 24X Fichs 50-280, 82/07/10,8210010156
- 8210010125 Forwards revised security training & qualification plans Plans withheld LEASBURG,R.H Virginia Electric & Power Co. 82/09/17. DENTON,H R Office of Nuclear Reactor Regulation. Director VAROA,B A Operating Reactors Branch 1 ip. 15566-013 24X Fiche 50-000,82/09/17,8210010125
- 8210050076 Submits correction to 820528 Revision 3 to response to NUREO-0737. Item I.D 2, "Bafety Parameter Display Sys."

  Correction should be included in schedular exceptions pertaining to emergency response capabilities

  LEASBURG, R H. Virginia Electric & Power Co. 82/09/29 DENTON, H R Office of Nuclear Rescutor Regulation. Director. EISENHUT, D 0 Division of Licensing ip 15603 185 24% Fiche 50-000, 82/09/29, 82/0050076

- 8210210050 Releases public version of changes to emergency plan implementing procedure FRETON.J M Division of Rules and Records 82/09/29 Document Management Branch ip 15774 109 24X Fiche 50-280.82/09/29, 8310210050
- --8210210093 Forwards public version of Change i to Emergency Plan Implementing Procedure EPIP-4 ii. "Followup Offsite Release Assessment." Change 2 to wmergency plan re NUREG-0554 cross-ref & Change 3 modifying Table 5 i DEMANDEL.E P Virginia Electric & Power Co 82/09/17 NRC No Detailed Affiliation Given ip 15774 110 24x Ficha 50-280.82/09/29.8210210050
- --8210210055 Public version of Change 1 to Emergency Plan Implementing Procedure EPIP-4 11. "Fullowup Offsite Release Assessment" 
  + Virginia Electric & Power Co 82/09/17 2pg 15774 111 24X 
  Fiche 50-280, 82/09/29, 8210210050
- --B21021005B Public version of Changes 2 & 3 to emergency plan re NUREO-0654 crost-ref & Table 5 i. "Min Shift Manning Requirements." respectively 4 Virginia Electric & Power Co 82/09/17 10pp 15774.113 24X Fiche.50-280.82/09/29,8210210050
- P Operating license stage documents & correspondence
- 8210120265 Informs of implementation status of NUREG-0737, Item II 10 2, "Plant Shielding" per NRC 620517 request All required work completed LEASBURG, R H Virginia Electric & Power Co 82/10/01 BENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D Q Division of Licensing 2pp 15651 230 24X Fiche 50-000, 92/10/01, 8210120265
- 8210120297 Forwards erreta to Topical Rept VEP-FRD-33, "VEPCO Reactor Core Thermal-Hydraulic Analysis Using COBRA IIIc/HIT Computer Gode "
  LEASBURG: H Virginia Electric & Power Co 82/10/04 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D 0 Division of Licensing 2pp 15552 330 24X Fiche 80-000, 82/10/04, 9210120297
- --8210120305 Errata to "VEPCO Reactor Core Thermal Hydraulic Analysis Using COBRA-IIIc/MIT Computer Code " \* Virginia Electric & Power Co VEP-FRD-33 ERR 82/10/04 Ip 18552 332 24% Fiche 30-000.82/10/04.8210120297
- 8210200043 Application for amend to Licenses DPR-32 & DPR-37 consisting of proposed changes to Tech Bjecs modifying reporting & notification requirements.

  LEASBURG, R. H. Virginia Electric & Power Co. 82/10/06 DENTON, H. R. OPFICE of Nuclear Reactor Repulation, Director VARDA, S. A. Operating Reactors Branch i 3pp. 15757 225 24X Fiche 50-280, 82/10/06, 8210200043
- --8210200048 Proposed changes to Tech Specs modifying reporting & notification requirements 
  4 Virginia Electric & Power Co 82/10/06 2pp 15757 228 24x 
  Fiche 50-280:82/10/06:8210200043
- 8210220178 Comments on avaluation of significant dynamic loads in determining capacity of slings used par NUREO-0512 Rating can be safely expressed in terms of max static load LEASBURGE H Virginia Electric & Power Co. 82/10/18 DENTON, H R Office of Nuclear Reactor Regulation, Director ESENHUT, D. 0 Division of Licensing. 2pp 15777, 293. 24% Fiche 50-000, 82/10/18, 8210820178
- 8210280266 Informs that containment purge valve qualification program for 36-inch containment purge valves completed To ensura prevention of radioactive release new automatic isolation valve will be installed.

  LEABSURG, R. K. Virginia Electric & Power Co. 92/10/25, DENTON, H. R. Office of Nuclear Reactor Regulation Director. VARGA, S. A. Operating Reactors Branch 1 2pp. 15837, 316, 24X Fiche 50-280, 82/10/25, 8210280266
- 8210280130 Informs that review of new fuel container lifting rig completed. Rig does not comply w/Paragraph 3.2 i 1 of AMSI Ni4 6-1978 Proposed design mod for conformance being reviewed & will be implemented by 840032 LEABBURG. R. H. Virginia Elsetric & Power Co. 82/10/28 DENYON, H. R. Office of Nuclear Reactor Regulation. Director. RISENHUT. D. D. Division of Licensing 10. 13837-163. 24% Fichs. 50-280.82/10/28.

- Q Inspection reports, IE Bulletins & correspondence
- 8210080015 Add1 response to fOIA request for 19 categories of 1518 to nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completaly withheld (ref FOIA Exemption 5)
  FELTON, J M Division of Rules and Records 82/07/12 UDGL # a Crifical Mass Energy Project 9pp 15645 027 24%
  Fiche 50~000, 82/07/12, 8210080015
- ~-B2100B0154 Systematic assessment of licensee performance notes 14 facility evaluation for May 1979-Apr 1980

  \* NRC No Detailed Affiliation Given 80/04/30 hpp 15648 051 24X Fiche 50-000, 82/07/12.8210080015
- B20B260424 Ack receipt of util B20609 itr & payment of civil parally Based on review of incidents, no basis for remission or mitigation of penalty identified LIEBERHAN, J Enforcement Btaff 82/07/29 LEASBURG, R N V// TElectric & Power Co Spp 15574 313 24X Fiche 50 280,02/07/24 820B260424
- --B206160306 Responds to NRC B20510 ltr reviolations noted in 15°, Rept 50-280/82-58 Corrective actions prestartup checklysis will be performed by instrument supervisor & all employees counseled reprocedural compliance

  LEABBURG, R H Virginia Electric & Power Co B2/06/09

  DEYOUNG, R C Director's Office, Office of Inspection and Enforcement App 15574 316 24X Fiche 80-280/82/07/23
- --8210010238 Forwards IE Insp Repts 50-280/82-04 & 50 &81/82 C4 : 820125-0226 Enforcement action sent separately on 620510 O'REILLY, J P Region 2, Office of Director 82/05/17 LEASBURG, R M Virginia Electric & Power Co 2pp 15574 J. Fichs 50-280,82/07/29.8208260424
- --B210010245 IE Insp Repts 50-280/82-04 & 50-281/82 04 on gardate.

  Noncompliance noted failure to maintain operability of size flow instrumentation & to follow OA manual & procedures for focumenting inoperable steam flow instrumentation BURKE, D. J. DAVIB.M. J., DANCE, H. C. Division of Project & Rep. Programs 82/04/08 9pp 15574 322 24X Fight 50-aird 47. September 200220424
- 8210070007 Responds to FOIA request for eight categories of rection steam generators & steam turbines App A documents processes in R Udell FOIA Request 81-919 Forwards documents listed an App B FELTON, J. M. Division of Rules and Records 82/00/10 ilred \$ . Hinthrop. Btimson. Putnam & Roberts 9pp 19649 069 241 Fiche: 50-000, 82/08/10, 8210070007
- --8210070137 Forwards tabulated data on steam generator image & pacifities Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch (\$270 to VAROA-8 Operating Reactors Branch 1 5pp 15645 to 341 Fiche 50-000,82/08/10,8210070007
- --B210070172 Forwards info re steam generator integrity & properting PMRs:per 750320 & 21 requests Details of trips including defect indications; tube plugging triteria & Little plugged will not be provided except for Point Bases & QOLLER, K.R. Division of Reactor Licensing (MRR:1475 & http://doi.org/10.1016/
- සි210010156 Ack receipt of 820820 responses in swergenty pressing deficiency items per 820406 confirmation of action the Corrective action by plans will be examined during subsequent insps.

  LEMIS.R C Division of Project & Resident Progress සිදුරුත් ද LEMIS.R C Division of Project & Power Co is දෙනුම් හිදුරුත් ද Fiche. 50-280, 82/09/10.8210010156
- B210220331 Forwards IE Insp Repts 50~280/82-25 k 50 181/82 \$5.27 820830~0903 No noncompliance nated DANCE.M.C. Division of Project & Resident Programs \$27/17 k LEABURG.R H Virginia Electric & Power Co 2pp 13772 2% Fiche 30~280.82/10/04.8210220331
- --8210220356 IE Insp Repts 50-280/82-25 & 50-281/82 25 on the concern factor noted Major areas inspected follows an previous enforcement matters & unresolved Items & Fallows on unplanned release of gaseous radioactivity HOBEY.C M : BARR.K P Division of Engineering & Tacanatal Programs 82/09/30 10pp 15776 277 24x Ficks \$2 2005.

- DB190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl CO85.& I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24x Fiche 30-000.82/10/06.8208190233
- OB190238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys
  Piping at DNR Plants " Svc list encl
  DEYCUNG.R C Director's Office, Office of Inspection and
  Enforcement 82/10/14 Consolidated Edison Co of New York
  115pp 15810 125 24% Fiche 50-000, 82/10/14, 8208190238
- Reportable occurrences, LERs & related correspondence
- 10150359 LER 81-042/03L-0 on 810719 containment spray chemical addition tank (CAT) level found below Tech Specs Caused by Jeaking valve MDV-CS-202B valve scheduled for repair during next outage Tank level restored WFLSON J L Virginia Electric & Power Co 81/08/17 Region 2. Atlanta. Office of the Director (81/03/01) 2pp 15704 315 24: Fiche 50-281.81/08/17.8210150359
- ·10270212 Forwards LERs 81-069/03L,81-073/03L-0 & 81-072/03L-0 WILBON J L Vinginia Electric & Power Co 81/12/07 O'REILLY, J P Region 2, Atlanta, Office of the Director (81/03/01) ip 15827 042 24X Fiche 50-280,81/12/07,8210270212
- @210270220 LER BI-072/03L-0 on Bill0B, motor operated valve 2867B failed to open when operated from control room during testing Cause undetermined Valve opened normally when tested later WILSON, J. L. Virginia Electric & Power Co. 81/12/07 Region 2, Atlanta. Office of the Director (81/03/01) 2pp 15827 046 24X Fiche 50-280,81/12/07,8210270212
- E210270224 LER 81-073/03L-0 on 811108, isolation valve to recirculation spray HX A failed to close Cause Undetermined Valve operated normally later Limit switch & torque settings examined & found satisfactory
  HILSONJU L Virginia Electric & Power Co 81/12/07 Region 2, Atlanta, Office of the Director (81/03/01) 2pp 15827 048 24X Fiche 50-280,81/12/07,8210270212
- :10080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
- FELTON: J H Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 7pp 15665 027 24X Fiche 50-000:82/07/12:8210080015
- -8204120487 Discusses problems w/water in fuel ail tank Case does not have generic implications TREMANN M. Director's Office 82/04/06 MICHELSON, C. Director's Office Spp 15665 036 24X Fiche 50-000, 82/07/12, 8210080018
- -8205180493 Forwards engineering evaluation of 820118 loss of reserve station svc transformer B
  TREMAN.N K Director's Office 82/05/10 MIGHELSON.C
  Director's Office 2pp 15466 089 24X Fiche 50-000,82/07/12,8210030015
- 210050081 Forwards LERs 82-093/03L-0,82-054/03L-0 & 82-092/03L-0 WILSDN.J L Virginia Electric & Power Go 82/09/27 0'REILLY.J.P Region 2. Office of Director 1p 15604 244. 24X Fiche 50-280.82/09/27,8210050081
- ~ P210050091 LER 82-054/03L-0 on 820905, unattended portable pump in use to clean waterbox C swung around & flooded svc water pit containing svc water Valve MOV-5M-202B grounded in open position Caused by operator error MOV-5M-202B dried WILSOM-J.L. Virginia Electric & Power Co 82/09/27 Region 2, Office of Director 3pp 15404 247 24X Fiche 50-280,82/09/27, 8210050081
- Q10060361 Forwards LERs 82-087/03L-0 & 82-057/03L-0
  WELSON, J L. Virginia Electric & Power Co 82/09/30 0'REILLY, J P.
  Region 2. Office of Director 1p 15619:006 24X
  Fiche 50-280,82/09/30,8210060361
- -8210040398 LER 82-057/03L-0 on 820901, 13, 18 % 20, pump 2-8M-F-10A siperienced loss of suction pressure & on 820913 & 14, pump 2-5M-F-10B experienced similar loss of suction Caused by insufficient NPBH Suc water reduced Syc water pump vented. WILSOM J L Virginia Electric & Power Co 82/09/30 Region 2, Office of Director 3pp 15619 010, 24X Fiche 50-280, 82/09/30, 8210960561

- 8210130204 Forwards LER: 82-055/03L-0,82-076/03L-0 & 82-075/03L-0 MILEON,J L Virginia Electric & Power Co 82/10/04 6'REILLY,J P Region 2, Dffice of Director 1p 15675 258 24X Fiche 50-280.82/10/04,8210130204
- --8210130208 LER 82-055/03L-0 on 820906, charging pump auxiliary oil pump A tripped leading to tripping of replacement pump/motor Auxiliary pump failure caused by open winding in motor Replacement tripping caused by undersized thermal overloads WILSON, J L Virginia Electric & Power Co 82/10/04 Region 2, Office of Director 2pp. 15475:259 24X Fiche 50-280, 82/10/04, 8210130204.
- 8210220424 Forwards LER 82-056/03L-0.
  MILSON, J L Virginia Electric & Power Co 82/10/07 O'REILLY, J P
  Region 2, Office of Director 1p. 15778:270 24X
  Fiche 50-281,82/10/07,8210220424
- --8210220435 LER 82-056/03L-0 on 820907.pressure in nitrogen bottle supplying emergency air to PCV-MB-202A & B discovered below limit Caused by leaking nitrogen bottle connection Replacement bottle correctly installed.

  WILSON, J L Virginia Electric & Power Co 82/10/07 Region 2, Office of Director. 2pp 15778 271 24X Fiche: 50-281,82/10/07.821020424
- 821020392 Forwards updated LER 80-019/03X-1 & LERS 82-058/03L-0 & 82-099/03L-0 .

  WILSON, J. L. Virginia Electric & Power Co. 82/10/08 G'REILLY, J. P. Region 2, Office of Director 1p. 15779 212 24X Fiche 50-280, 82/10/08, 8210220392
- --8210220408 LER 82-058/03L-0 on 820915, safety injection accumulator C found w/reduted boron concentration of 1, 924 ppm, Caused by leakage through check valve 2-81-144 during sensitized gipe flush Flush stopped Valve to be reworked during outage MILBON, J L Virginia Electric & Power Co 82/10/08 Region 2, Office of Director 2pp 15779 216 24X Fiche 50-280,82/10/08, 8210220372
- 8210270267 Part 21 deficiency rept re potential galling problem between stem & bonnet of i 28-inch & larger A105 carbon steel & A182-F22 valves supplied Feb 1781-Aug 1782 Valves should be serviced & stem t/or bonnet replaced [BABELLE, L D Convel, Inc 82/10/11 HAYNES,R,C Region 1, Office of Director 17pp 15854 232 24X Fiche, 50-000, 82/10/11.
- 8210220075 Forwards LERs 82-078/03L-0 & 82-059/03L-0 UILBON, J. L. Virginia Electric & Power Co. 82/10/14, D'REILLY, J.P. Region 2. Office of Director. 19 15778:177. 24X Fichs 50-280, 82/10/14, 8210220095
- --8210220100 LER 82-053/031-0:on 820914.pump 2-8W-P-10A lost suction pressure Caused by insufficient NP8H due to throttled svc water to air conditioning chillers. Pump vented to restore NP8H WILSON, J. L. Virginia Electric & Power Co. 82/10/14 Region 2: Office of Director 3pp. 15778:180 24X Fiche 50-280,82/10/14,8210220095
- DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 8210250200 Forwards scenario cutline for 821014 emergency plan evaluation exercise, per NRC 820112 guidance ltr. WARD,E C Northern States Power Co 82/09/01 Region 3, Office of Director 2pp 13788 277. 24X Fichs. 50-282, 82/09/01,8210250200
- 8210040345 Forwards IE Insp Repts 50-282/82-15 & 50-306/82-15 on 820824-25 No noncompliance nated PAPERIELLO,C J Division of Emergency Preparedness & Operational Support 82/09/10 LARSON.C.E. Northern States Power Co 2pp. 1599 356 24x Fiche: 50-282, 82/09/10, 821004035
- --B210040354 IE, Insp Repts 50-282/82-15 & 50-306/82-15 on 820824-25 No moncompliance noted Major areas inspected previous deficiencies in prompt notification/unarning sys. PATTERSON.J.P., AXELSON.W.L. Division of Emergency Preparedness & Operational Bupport 82/09/09. 4pp. 15593.358, 24X Fichs.50-282,82/09/10.8210040345
- 8210080184 Forwards revised Page 4 reflecting NRC guidance on activation of public alert & notification system 821014 emergency plan exercise MARD: C. Northern States Power Co. 82/07/28 AXELSON: W.L. Region G. 0ffice of Director. 2pp. 15640:175 24X Fiche: 50-282,82/09/28,82/0080184

- B210120559 Notification of B21001 meeting u/licensee.BNL & Engineering, Planning & Mgt. Inc in Bethesda.MD to discuss requests for exemption from 10CFR50.App R requirements re fire protection
  DITANNI.D C Operating Reactors Branch 3 B2/09/26
  Operating Reactors Branch 3 2pp 15672 346 24X
  Fishe 50-282, 82/09/28, 8210120589 82/09/29 CLARK, R A
- 3210260374 Ack receipt of FEMA 820526 ltr re evaluation of offsite emergency preparedness for facility exercise & associated final exercise evaluations Offsite emergency preparedness final electies evaluations urraise energency preparations deficiencies should be addressed by util HIND.J A Division of Emergency Preparadness & Operational Support 82/10/21 GILBERTS.D E Northern States Power Co 2pp 15804 001 24X Fichs 50-282.82/10/21.8210260374
- 3210270262 Forwards info clarifying 820630 rept. "Fire Protection Safe Shutdown Analysis in Compliance W/10CPR50, App R. Section III G & Substantive Basis for Exemption Requests." per III G & Substantive Decision 821001 meeting w/NRC
  HUSGLF,D Northern States Power Co B2/10/22
  HUSGLF,D Northern Director 132pp 15829 04 Office of Nuclear 15829 049 24X Reactor Regulation, Director 13 Fiche 50-202, 82/10/22, 8210270262

# Operating license stage documents & correspondence

- 8210040123 Submits supplemental info re util 820614 request for amend to Licenses DRR-42 & DRR-60 "LOCA ECCS Limiting Break & Exposure Sensitivity Analysis for ENC XN-1 & XN-2 Reloads at Prairie Island I " applies to both Units 1 & 2 MUSDLF-D. Northern States Power Co 82/09/24 Office of Nuclear Regulation, Director ip 15581 203 24X Office of Nuclear Fiche 50-282, 82/09/24, 8210040123
- 8210050319 Forwards response to Core Performance Branch 820816 concerns re-methods of monitoring core power distributions for Cycle 7 operation MUSOLF, D Norther Cycle 7 operation MUSOLF.D Northern States Power Co Reactor Regulation. Director 13pp Fiche 50-282.82/09/29.8210050319 82/09/29 Office of Nuclear 15610 268 24X
- 9210130260 Discusses implementation of NRC guidelines for working hours provided in Generic Ltr 82-12 Revised guidelines have been implemented wexceptions of 72-h per we limitation & relief from control board duties MUSOLF, D Northern States Power Co B2/10/07 Of Reactor Regulation, Director 2pp 15676 012 24X Fiche 50-000, 82/10/07, 8210130260
- 8210190422 Forwards "Analysis of Capsule P From Northern States Power Co Prairie Island Unit i Reactor Vessel Radiation Surveillance Program " 8017481114168 Program "MUSOLF.D Northern States Power Co. 82/10/12 / Reactor Regulation, Director. 1p 15741 044 24X Fiche 50-292/82/10/12/8210190422 Office of Nuclear
- --8210190429 "Analysis of Capsule P From Northern States Power Co Prairie Island Unit 1 Reactor Vessel Radiation Surveillance Program "
  YANIGHKU,8 E , TRAN.K C , XAISER,W T Westinghouse Electric Corp
  WGAP-10102 82/05/31 68pp 15741 045 24X
  Fiche 50-282,82/10/12,8210190422
- 8210260154 Advises that mods required by NUREO-0737. Item III D 3 4. "Control Room Mabitability," will not be completed until 830315 due to delays in receipt of mati & sampling equipment MUSDLF, D Northern States Power Co 82/10/22 D Reactor Regulation, Director Spp 15799.012 24X Fiche: 50-282, 82/10/22,8210260154 Office of Nuclear

#### O Inspection reports: IE Bulletins & correspondence

- S210070007 Responds to FUIA request for eight categories of records re-steem generators & steem turbines App A documents provided in R Udell FUIA Request 81-313 Forwards documents listed in FÉLTON, J. M. Division of Rules and Records. 82/08/10 LONG, D. J. Winthrop, Stimeon, Putnam & Roberts, 9pp 15645, 063 24X Fiche 50-000, 82/08/10, 8210070007
- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities. Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VARGA-8 Operating Reactors Branch 5pp. 10645:131 24X Fiche 50-000.82/08/10.8210070007

- --8210070172 Forwards info re steam generator integrity & integral of operating PNRs, per 750320 & 21 requests Details of image. (reluding defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach 1 GULLER, K R Division of Reactor Licensing (NRR-1975 only) 5pp 15645 196 24X Fiche 50-000,82/08/10.0210070007
- 9210040345 Forwards IE Insp Repts 50-282/82-15 & 50-306/82-15 on PADERIELLO, C J Division of Energency Preparedness & Operations Support 82/09/10 LARBON, C E Not them States Power Co 73, 15593 356 24% Fiche 50-282, 82/09/10, 8210040345
- --8210040354 IE Insp Repts 50-282/82-15 & 50-306/82-15 on Na0824-25 o 210040334 It Insp Repts 30-262/06-10 & 00-300/82-35 on 120024-35 g noncompliance noted Major areas inspected previous deficiencies in prompt notification/warning sys PATTERSON, J. P., AXELSON, W. L. Division of Emergency Preparedress L Operational Support 82/09/09 4pp 15593 358 24x Fiche 50-282,82/09/10.8210040345
- 920B190233 IE Info Notice 80-35. Suppl 1. "Leaking & Distodged 1-12" Implant Seeds " Svc list encl 2008.L I Division of Fuel Facilities, Materials & Bafeguards B2/10/06 Consolidated Edison Co of New York 66pp | 1576| [\* 24X Fiche 50-000.82/10/06.8208190233
- 82:0190432 Ack receipt of 820915 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/82-11 & 50-30A/B2-11 50-306/82-11
  SPESSARD,R L Division of Project & Resident Programs
  LARSON.C E Northern States Power Co ip 15741 182
  Fiche 50-282, 82/10/07, 8210190432 02/10/01
- --8210190439 Responds to NRC 820817 ltr re violations noted in 14 Pro-Repts 50-282/82-11 & 50-306/82-11 Corrective actions startup program changed to normalize flux difference startup program changes to normalize tul difference channels LARSUN.C E Northern States Power Co 82/09/15 SIREFIE Division of Project & Resident Programs 2pp 15741 [83 Fiche 50-282,82/10/07-8210190432 STREETER JF ;
- 8210150249 Ack receipt of 820928 itr informing NRC of stept taken to correct violations noted in IE Imap Repts 50-282/82-13 & 50-306/82-13 STREETER, J F Division of Project & Resident Programs (82/10/63 LARSON, C E Northern States Power Co ip 15/04 361 24s Fiche 50-282, 82/10/08,8210150249
- --8210150255 Responds to NRC 820702 ltr re violations noted in IL I ; Repts 50-282/82-13 & 50-306/82-13 Corrective actions dissel generator test procedures will be revised by 821201 4 investigative rept will be discussed w/operators
  LARSON.C E Northern States Power Co 82/09/28 hTRLH2.Jf
  Division of Project & Resident Programs 2pp. 19/04 362 443
  Fiche 50-282,82/10/08.8210150249
- 8210280144 Forwards IE Insp Repts 50-282/82-16 & 50-306/82 16 on B20901-17 & notice of violation
  BTREETER, J F Division of Project & Resident Programs DA/IC/13
  LARSON, C E Northern States Power Co 2pp 1583/ 179 248
  Fiche, 50-282, B2/10/13,0210280164
- --8210280168 Notic of violation from insp on 820901-17 STREETER, J F Division of Project & Resident Programs 02/12.1 ip 15837 201 24% Fiche 50-282,82/10/13,8210280164
- --8210280171 IE Insp Repts 50-282/82-16 & 50-306/82-16 on 82991-1F Noncompliance noted failure to post no smoking sign in safety-related equipment areas & operators found smoking DUBRY.N.E. REYES.L. Division of Project & Resident Programs 82/10/12 6pp 15837 202 24X Fiche 50-282,82/10/13.836282.1
- 8208190238 IE Bulletin 62-03, "Stress Corrosion Cracking in Thirthwall, Large-Diameter, Stainless Steel, Recirculation SysPiping at BNR Plants " Svc list encl
  DEYQUNO, R C. Director's Office, Office of Inspection and
  Enforcement. 82/10/14 Consolidated Edison Co of New York
  115pp 15810,125 24X Fiche 50-000,82/10/14.8208193238
- S Reportable occurrences, LERs & related correspondence
- 8210150381 Forwards LER 81-011/01T-0 MAYER.L G Northern States Power Ca 81/08/24 MEPP Region G. Chicago. Office of the Director (81/03/01) 15704:065 24% Fiche 50-282.81/08/24.8210150391 KEPPLER, J &

- --B210150390 LER B1-011/01T-0 on 810812.D2 diesel generator tripped & locked out during operability test Caused by generator operating in unfamiliar mode & var & watt meters being confused by operator HURSTAD.A A Northern States Power Co 81/08/24 Region 3, Chicago, Office of the Director (81/03/01) 2pp 15704 046 24X Fiche 30-282,81/08/24.8210150381
- E210130510 Forwards LER B2-016/03L-0 MUCCLF.D Northern States Power Ca B2/10/06 Region 3, Office of Director 1p 15682 256 24X Fiche 50-282,82/10/06,8210130510
- --82(0130533 LER 82-016/03L-0 on 820906, spike occurred in RCS activity up to 1 38 uCi/g dose equivalent I-131 Caused by reactor trip 2 subsequent washout of fission product from existing fuel defects Region 9 fuel will be removed HUNSTABLA A Northern States Power Co 82/10/06 Region 3, Office of Director App 15682 257 24X Fiche 50~282,82/10/06, 9210130510
- 8210250177 Forwards LER 82-019/03L-0 MUSOLF, D. Northern States Power Co. 82/10/15 Region 3, Dffice of Director 1p. 15788 276 24X Fiche 50-282/82/10/15,8210250179
- --8210250183 LER 82-019/03L-0 on 820917 diesel cooling water pump 22 did not start on demand during testing Start attempt 7 minutes later successful Cause unknown In 5 days of testing failure could not be reproduced HURISTAD, A A Northern States Power Co 82/10/15 Region 3. Office of Director 1p 15788 297 24X Fiche 50-282,82/10/15,8210250179
- B210250364 Forwards LER 82-018/03L-0 MUSQLF.D Northern States Power Co 82/10/15 Region 3, Office of Director 1p 15790 177 24% Fiche 50-282,82/10/15,8210250364
- --8210250376 LER 82-018/03L-0 on 820915 discovered that two ventilation flow tests not performed as scheduled Caused by personnel error Tests rescheduled HUMSTAD. A A Northern States Power Co 82/10/15 Region 3, Office of Director ip 15790 178 24X Fiche 50-282,82/10/15,8210250346
- DOCKET 50-285 FORT CALHOUN STATION, UNIT 1
- A Application/construction stage documents & correspondence
- E21001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28.8210010008
- --8204270048 Recommends prompt attention be given to problem of reactor coolant pump closure stud corrosion detected at facilities Response by B20415 requested EISENHUT.D G Division of Licensing 82/03/24 HANAUER.S.H Division of Systems Integration (Post B11005) 3pp 15745 270 24% Fische 50-000.82/06/28.8210010008
- F Security, medical, emergency & fire protection plans
- 8209)70051 Forwards site security plan Revision 11 Revision withheld (ref 10CFR73 21)
  JONES.W C Omaha Public Power District 82/08/27 DENTON.H R
  Office of Nuclear Reactor Regulation, Director 1p 14910 097 2:
  Fiche 50-285
- 6210220110 Notifies of emergency preparedness appraisal team 821108 site visit to close out Apps A & B items identified in IE Emergency Preparedness Appraisal Rept 50-285/82-27 on 811207-16
  SEIDLE: W C Division of Resident, Reactor Project & Engineering Programs 82/10/19 JONES: W C Omaha Public Power District 1 13778 168 24X Fiche 50-285.82/10/19:0210220110
- H General correspondence
- 8210060244 Requests that author be deleted from mailing list Further mailings should be sent to Metropolitan Planning Agency KIRSHEN, A H Kirshen, A H 82/09/30 TOURIGNY, E NRC No Detailed Affiliation Given ip 15619 320 24X Fiche 50-289, 82/09/30, 8210060244

- P Operating license stage documents & correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL, R A Critical Mass Energy Project 19pp 15727 005 24X Fiche 50-000, 82/06/28, 8210010008
- --8004i00193 Forwards evaluation of facility for Cycle & operation All Tech Spec changes & safety analyses required for 1500 M/ approved CHECK.F 8 Reactor Safety Branch 80/03/18 REID.R W Operating Reactors Branch 4 (Pre 800428) 34pp 15727 044 24X Fiche 50-000.82/06/28.8210010008
- 8210080015 Addl response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
  FELTON, J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X
  Fiche 50-000,82/07/12,8210080015
- --B105040512 Discusses actions proposed as result of boric acid corrosion damage of stud bolts & piping at PWR plants IE proposal & schedule for actions will be discussed at 810407 maeting in Bethesda.MD SNIEZEK.J H. Division of Resident & Regional Reactor Inspection 81704702 EIBENHUT.D 0 Division of Licensing ARLOTTO.G A Division of Engineering Standards 3pp 1566B 127 24X Fiche 50-000,82707712.B210080015
- 8210050247 Forwards post-accident sampling sys status update & revised completion schedule per NUREQ-0737. Item II B 3 Reasons for delay of TMI action plan mod discussed JONES.W C Omaha Public Power District 82/09/30 CLARK,R A Operating Reactors Branch 3 3pp 15610 330 24X Fiche 50-285,82/09/30.8210050247
- 8210060176 Advises of delay in receipt of motor curves from vendor per 820521 commitment to provide justification re adequacy of electrical distribution sys voltages Curves & evaluation scheduled for submittal by 821201

  JONES, W. C. Omaha Public Power District 82/10/01 CLARK, R. A. Operating Reactors Branch 3 ip 15614 CO9 24X

  Fiche 50-285, 82/10/01, 8210050176
- 8210290038 Forwards PNL final rept on 820608-10 audit of procedures & training addressing pressurized thermal shock issue Max & min subcooling margin curve.NDT & saturation curves should be available on single plot in control room CLARK.R A Operating Reactors Branch 3 82/10/12 JGNES.W C Omaha Public Power District Spp 15877 278 24% Fiche 50-285.82/10/12.8210290038
- --8210290041 "Audit of Fort Calhoun Procedures & Training that Address Pressurized Thermal Shock Issue," final rept CLARK.R O. AMES, K. RANKIN.H O. Battelle Memorial Institute. Pacific Northwest Laboratory 82/06/30 28pp 15877 281 24X Fiche 50-285,82/10/12.8210290038
- 8210 Concern Ad I --- that that amounted achedule for fulfilling NUREO-

- --8210190349 IE Insp Rept 50-285/82-17 on 820830-0903 No nancompliance noted Major areas inspected housekeeping/cleanliness, onsite review committee & calibr MURPHY.M E , FLIPPO.T.A , MUNNIGUTT,D M Division of Resident, Reactor Project & Engineering Programs 82/09/20 App 15742 144 24% Fiche 50-285,82/09/22,8210190347
- 8210190531 Forwards IE Insp Rept 50-285/82-16 on 820801-31 No noncompliance noted SEIDLE.W C Division of Resident, Reactor Project & Engineering Programs 82/09/22 JONES.W C Omaha Public Power District 2pp 15781 306 24X Fiche 50-285,82/09/22,8210190531
- --B210190539 IE Insp Rept 50-285/82-16 on 820801-31 No moncompliance noted Hajor areas inspected operational safety verifications survaillance testing meint, preparation for refueling & LER follows YANDELL.i. A., HUNNICUTT.D.H. Division of Resident, Reactor Project & Engineering Programs 82/09/17 6pp 15751 308 24X Fiche 50-285,82/09/22,8210190531
- 3210070326 Ack receipt of 820629 ltr supplementing 811012 & 0904 ltrs informing NRG of steps taken to correct violations noted in IE Insp Rept 50-285/81-16
  SEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs 82/10/05 JONES.W.C. Omnha Public Power District ip 15-544 085 24% Fishe 50-285,82/10/05.0210070326
- --B210070333 Responds to NRC B10B05 ltr re violations noted in IE Insp Rept 50-285/81-16 Corrective actions all GA records will be entered into record mgt sys by B31231 Info updates B10904 & IO12 responses JONES, W C Omaha Public Power District B2/06/29 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 2pp 15634 086 24X Fiche 50-285, 82/10/05, B210070326
- 120B190233 IE Info Notice BO-35. Suppl 1. "Leaking & Dislodged 1-125 Implant Seeds " Syc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000.82/10/06.8208190233
- 1208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys
  Piping at BMR Plants "Syc list encl
  DEYDUNG.R C Director's Office, Office of Inspection and
  Enforcement 82/10/14 Consultdated Edison Co. of New York
  115pp 15810 125 24X Fiche 50-000,82/10/14,8208190238,
- 1210220110 Notifies of emergency preparedness appraisal team 821108 site visit to close out Apps A & B items identified in IE Emergency Preparedness Appraisal Rept 50-285/82-27 on 811207-16 SEIDLE-H C Division of Resident, Reactor Project & Engineering Programs 82/10/19 JONES-H C Omaha Public Power District 1p 15778 168 24X Fiche 50-285,82/10/19,8210220110

# Periodic operating reports & related correspondence

- 210190736 Forwards monthly operating rept for Sept 1982 JONES W C Omaha Public Power District. 82/10/12 DEYGUNG, R C Director's Office, Office of Inspection and Enforcement Ip 15736 262 24X Fiche, 50-285, 82/10/12/8210190736
- ~8210190746 Monthly operating rept for Sept 1782 SHORT, R. W Omaha Public Power District 82/10/12 7pp 15736.263 24X Fiche 50-285,82/10/12,9210190736

## Reportable occurrences, LERs & related correspondence

- 210040186 Forwards LER 82-018/01T-0
  JONES.N C Omaha Public Power District. 82/09/20 SEIDLE.N C
  Region 4. Office of Director. 1p 15581:352 24X
  Fiche 50-285.82/09/20.8210040186
- -9210040187 LER 82-018/01T-0 on 820917, review of electro-pneumatic (E/P) valve positioners revealed absence of analysis or test qualification data for Honsywell Model 67400-023 positioners Control circuit, solenoid valves to be nodified HEMAFFEY,R F. Omaha Public Power District 82/09/17 Region 4, Office of Director. 4pp. 15581:333 24X Fichs 50-285,82/09/20,8210040186.
- 210130570 Forwards LER 92-017/03L-0 JONES H C Omaha Public Power District 82/09/29 SEIDLE-W C Division of Resident, Reactor Project & Engineering Programs. ip. 15479:109 24% Fiche 50-285,82/09/29,8210130570.

- --8210050303 LER 82-017/03L-0 on B20830, control room operator natical valve position indication for inboard containment isolation valves, HCV-0208 & 8210 Caused by Valcor Engineering Cosolenoid valves containing failed solenoid coils CORE, M R Omaha Public Power District B2/09/29 Region 4 Office of Director 4pp 15410 262 24% Fiche 50-295, D2/10/C1 P210050301

#### V Operator Examinations

8210200077 Advises that util proposed schedule for fulfilling NUSEC-0737. Item I A 1 3, "Shift Hamming Requirements." has been delayed due to NRC not having graded exams for two ionion reactor operator trainees New completion date is 830101 JONES.W C Omaha Public Power District 82/10/15 CLARK.R A Operating Reactors Branch 3 2pp 15755 354 24% Fichs 50-285.82/10/15.9210200077

DOCKET 50-286 INDIAN POINT STATION, UNIT 3
F Security, medical, emergency & fire protection plans

- B210060091 Submits request for mods to emergency notification eye.f. to upcoming relocation of emergency facilities BRONS.J C Power Authority of the State of New York B2/09/13 SMITH. Of H Division of Emergency Proparedness & Operational Sept... 2pp 15614 359 24X Fiche 50~286.82/09/13.8210060071
- 8210060145 Forwards "Testing & Repair of Siren Portion of Alert & Notification Sys for Indian Point Nuclear Power Generating Plant," per discussion at 820708 status meeting KELLY.J J Power Authority of the State of New York 6.2/67/15 DAVIDOFF.D New York State of 1p 15614 295 24x Fiche 50-247, 82/09/15 8210060145
- --8210060148 "Testing & Regair of Siren Portion of Alert & Molificat Sys for Indian Point Nuclear Power Generating Plant" \* Power Authority of the State of New York 02/09/14 Ope 15614 296 24% Fiche 50-247.82/09/15.8210060145
- B210130047 Notification of B20924 meeting w/util in Bethseda.HD to discuss App R review THOMA,J O Operating Reactors Branch 1 B2/09/20 VARGA.S A Operating Reactors Branch 1 2pp 15696 282 24X Fiche 30-286, B2/09/20, B210130047
- 8210130604 Forwards Auxiliary Bys Dranch input to agenda for 9267.4 meeting in Bethesda MD to discuss App R & probabilistic risk assessment
  - Tisk assessment VAROA, B A Operating Reactors Branch 1 82/09/21 LiNCLAIR, L Power Authority of the State of New York 8pp 15692 351 246 Fiche 50-286, 82/09/21, 8210130604
- 8210040206 Ack receipt of 820902 ltr describing status of activities underway to correct significant deficiencies identified by FEMA: In response to NRG 820803 ltr BMITH: 0 H Division of Emergency Preparedness & Operational E.p. 82/09/27 BRONS, J C Power Authority of the State of New Yerk ip 15583 134. 24X Fiche 50-286, 82/09/27, 8210040206
- --B210040213 Forwards description of activities planned or underway correct deficiencies listed in FEMA 820730 interia findings re adequacy of radiological emergency response preparadness of state & local govts.per NRC 820803 request BAYNE, J. P. Fower Authority of the State of New York 82/09/02 HAYNES, R. C. Region j. Office of Director lipp 13503 135 7 Fiche 50-284,82/09/27,8210040204
- 8210050079 Informs that installation of CRT terminal in emergency operations facility & video surveillance sys per IMI Action Item III.A i 2 will be completed by end of current rafueling outage BAYNE.J.P Power Authority of the State of New York 62/09/30 VARGA.S.A Operating Reactors Branch i 2pp 15604 274 241 Fiche S0-286, 82/09/30, 8210050079.
- 8210190738 Forwards schedule for providing into requested in the 62 ltr re App R
  BAYNE, J P Power Authority of the State of New York 62/t0/12
  VARGA, B. A Operating Reactors Branch i 4pp 15736 258 281
  Fiche 50-286, 82/10/12,8210190738.

- 8210200019 Advises that serious deficiencies in omergency preparedness will not be corrected since State of NY & FEMA not addressing concerns of local officials by involvement in current changes MOLT. J Public Interest Research Group, New York KESSLER, J Rockiand Citizens for Safe Energy SCHEINER, C A Westchester Peoples Action Coalition Inc. 82/10/15 PALLADINO, N J . ROBERIS.T M . ASSELSINE. J K Commissioners 5pp 15755 083 24X Fiche 50-247.82/10/15.8210200019
- C Adjudicatory correspondence
- 8CO623078B Ack receipt of 800416 memo w/insp repts verifying interim actions required of facilities in 800211 confirmatory orders Requests verification that Item F 2 in orders is met. Item E 5 in W Oammil 800317 memo should be F 5 MOVAK.T M Assistant Director for Operating Reactors 80/06/13 RRYAN.S E Division of Reactor Operations Inspections 1p 02765 285 24% Fiche 50-247.80/06/03.8006/30788
- 8210060235 Declines invitation to appear before Subcommittee on Energy Conservation & Power Subcommittee investigation is intrusion into ongoing regulatory proceeding & threatens independence of Commission MDRGAN.C Morgan Associates MDRGAN.C Power Authority of the State of New York 82/09/30 OTTINGER.R L House of Rep. Energy & Commerce 10pp 15619 360 24% Fiche 50-247/82/09/30.8210060235
- B21004010B Order CLI-92-28, requesting ASLB reconstituted by CLI-B2-24 to estimate when recommendations called for by CLI-B1-32 can be provided CHILK.S J Office of the Secretary of the Commission 82/10/01 Atomic Safety and Licensing Board Panel 1p 19580 350 24% Fiche 50-247, 82/10/01,8210040108
- 8210050254 Memorandum & order restating contentions & establishing procedures based on Commission guidance GLEASON, J.P., PARIS, O.H., SHON, F.J. Atomic Safety and Licensing Board Panel B2/10/01 42pp 15609 211 24X Fiche 50-247, 82/10/01, 8210050254
- 6210130335 Motion for ASLB to direct NRC to reschedule 821013 meeting woutils & Sandia in Albuquerque.NM to either New York.NY or Washington.BC Intervenor unable to attend meeting in NM WEISS.ER Union of Concerned Scientists WEISS.ER Public Interest Research Group. New York 82/10/07 Atomic Safety and Licensing Board Panel 3pp 15682 050 24X Fiche 50-247.82/10/07.8210130335
- --8210130337 Motion for Commission to direct that all future meetings on issues be held in NY or Washington DC & that intervenors be given notice concurrently w/other parties NEISS.E.R. Union of Concerned Scientists WEISS.E.R. Public Interest Research Group, New York 82/10/07 Commissioners 2pp 15682 053 24x Fiche 50-247,82/10/07,8210130335
- G210180203 Reply to ASLB 821001 memorandum & order Plant should be totally reinspected w/appropriate tosts of piping.electrical & control sys conducted List of parties should be shortened to active participants Certificate of Svc encl FLEISHER. Z S Hest Branch Conservation Association 82/10/11 4pp 15718 124 24X Fiche 50-247,82/10/11.8210180203
- 6210150092 Order denying UCS/NY PIRO 821007 motion to direct NRC to reschedule 821013 meeting in Albuquerque,NM to NY or Mashington, BC Only Commission has jurisdiction over NRC performance of administrative responsibilities PARIS. O H . SHON.F J . GLEASON, J P Atomic Safety and Licensing Board Panel 82/10/12 Union of Concerned Scientists 3pp 13701 194 24X Fiche 50-247, 82/10/12, 8210150092
- 6210150141 Order scheduling 821103-04 prehearing conference in White Flains.NY re oral argument on responses to ASLB 821001 memorandum & order restating contentions GLEASON.J P Atomic Safety and Licensing Board Panel 82/10/12 2pp 15698 306 24X Fiche 50-247.82/10/12.8210150141
- 8210180138 Motion in response to ABLB 821001 order, requesting clarification & importance of term "discussion" & extension of time to determine position re issue of consolidation Certificate of Svc encl MAPLAN.C New York.NY 82/10/13 Atomic Safety and Licensing Board Fanel 7pp 15719 123 24X Fiche 50-247,82/10/13,8210180138
- 8210200069 Telegraphic order granting licenses request for extension of time to file responses to 821001 order All party responses due 821019
  GLEASON, J P. Atomic Safety and Licensing Board Panel 82/10/14
  Power Authority of the State of New York ip 15757 280 24X
  Fiche 50-247, 82/10/14, 8210200069

- 8210200019 Advises that serious deficiencies in emergency preparedness will not be corrected since State of NY & FEMA not addressing concerns of local officials by involvement in current changes
  HOLT, J Public Interest Research Group, New York POENER,P
  Parents Concerned About Indian Point FLEIGHER, Z S Wast Branch
  Conservation Association 82/10/15 PALLADINO,N J , AHEARNE, J F ,
  GILINSKY, V Commissioners 5pp 15755 089 24X
  Fiche 50-247, 82/10/15, 8210800019
- 8210220389 Submittal of comments on ASLB 821001 memorandum & order & motion for ASLB to issue reformulated contentions on Commission Questions 3 & 4 by 821115 & to restore Contention 6 2 Certificate of Svc encl TOSCANI.K Parents Concerned About Indian Point 82/10/15 Atomic Safety and Licensing Board Panel 2pp 15777 307 24% Fiche 50-247.82/10/15,8210220389
- 8210210390 Requests destruction of West Branch Conservation Assoc 821011 reply to 821001 memorandum & order & substitution of encl version FLEISHER, Z S West Branch Conservation Association 82/10/18 NRC - No Detailed Affiliation Given ip 15764 099 24X Fiche 50-247, 82/10/18, 8210210390
- --8210210377 Response to 921001 memorandum & order Certificate of Svc encl FLEISHER/I 8 West Branch Conservation Association 92/10/13 4pp 15744 100 24% Fiche 50-247, 92/10/18, 8210210370
- 8210200059 Response to ASLB 821001 order ASLB should narrow language of ASLB Question 1 1 & adopt proposed schedule for continuation of proceeding Certificate of Svc encl MODRE, J. MCOUREN, H.J. Hearing Branch 1 82/10/19 9pp 15757 290 24% Fiche 50-247.82/10/19.8210200059
- B210220375 Request for mod of ASLB B21001 order to permit Rockland
  County to continue presentation of witnesses re Commission
  Questions 3 & 4 prior to taking evidence on Questions 1,2,5,
  6 & 7
  THORREN,E O Rockland County, NY B2/10/19 Atomic Safety and
  Licensing Board Panel 2pp 15779 187 24X Fiche 50-247,82/10/19,
  B210220375
- 8210220410 Joint response of intervenors to ASLB 821001 order Meaning of "discussion" of probability should be clarified & ABLB should immediately reformulate contentions on Questions 3 & 4 Certificate of Svc encl MEISS, E R Union of Concerned Scientists WEISS, E R Harmon & Weiss 82/10/19 Atomic Safety and Licensing Board Penel, 12pp 15778 313 24x Fichs 50-247,82/10/19,8210220410
- B210250081 Proposed hearing schedule Certificate of Svc encl
  BRANDENBURG. B Consolidated Edison Co of New York MORGAN, C
  Power Authority of the State of New York MORGAN, C
  Associates 82/10/19 9pp 13787 049 24X Fiche 50-247,82/10/19,
- 8210250216 Response to ASLB 821001 order reformulating contentions Opposes admission of new Contention t 1.Contentions 2-1(a)-(d),2 2(a) & 22(b) & ASLB Question 2 2 1 Notice of appearance & Certificate of Bvc encl MCRGAN.C Power Authority of the Btate of New York MCRGAN.C Morgan Associates 82/10/17 Atomic Safety and Licensing Board Panel 35pp 15789 166 24x Fiche 50-247.82/10/17.8210250216
- 8210250265 Notice of appearance in proceeding BAUM 8 L. Power Authority of the State of New York BAUM 8 L Morgan Associates 82/10/19 1p 15791 152 24X Fiche 50-247, 82/10/19, 8210250265
- 8210250287 Motion for order reversing ASLB 821001 memorandum & order re taking of testimony on Guestions 3 & 4 & establishing schedule for presentation of testimony upon expiration of 120-day clock Certificate of Bvc encl VETERE.L A Westchester County.NV 82/10/19 Atomic Sefety and Licensing Board Panel 7pp 15791 165 24X Fiche 50-247.82/10/19, 8210250287
- B210250324 Memorandum re ASLB 821001 order reformulating contentions Objects to new Contention 1 1, Bases Ia & 1b, Contentions 2 1(a), 2 1(b), 2, 1(c), 2 1(d), 2 2(a) & 2 2(b), Certificate of 8vc encl BRANDENBURG, B Commonwealth Edison Co B2/10/19 Atomic Sefety and Licensing Board Panel 47pp. 15790 243 24% Fichs 50-247, 82/10/19, 8210250324.
- 8210250099 Motion for leave to file memorandum in response to ASLB 821001 order 1 day late Mechanical difficulties encountered w/word processing equipment Certificate of Svc encl BRANDENBURG. B Consolidated Edison Co of New York. 82/10/20. Commissioners App 15787-062 24X Fiche 50-247.82/10/20, 8210250099

- 8210280242 Requests Commission issue order directing all meetings between NRC & licensee be held in Mashington, DC or NV. that interveners receive notice of meetings concurrently within the thirty energy by the provided wiminutes of 821013 meeting WEISS.E R Harmon & Heiss WEISS.E R Union of Concerned Scientists 82/10/25 PALLADINO, N J. AMEARNEJ, O GL. NRSKY, V Commissioners 2pp 15837 058 24X Fiche 30-247, 82/10/25,
- 8210280230 Advises that NRC does not intend to respond to intervenor motions filed in response to ASLB 821001 order until after 821103-04 preharing conference MOORE, J E Hearing Branch I 82/10/27, GLEASON, J P , SHON, F J , PARIS, D H Atomic Safety and Licensing Board Panel ip 15837 082 24X Fiche 50-247,82/10/27,8210280230
- 8210280353 Response opposing UC8/NY PIRO 821012 motion to direct NRC to reschedule all future meetings on hearing issues in NY or Hashington DC NRC should be permitted flexibility to determine most appropriate location W/Certificate of Svc HCOURREN, H U Hearing Branch 1 B2/10/27 Commissioners 7pp 15839 048 24x Fishe 50-247.82/10/27.8210280353
- 82:029027: Advises that licensess plan to address all matters raised in responses/motions re ASLB 82:001 memorandum & order at 82:103-04 prehearing conference 8RANDENBURG.B Consolidated Edison Co of New York HORGAN, C Power Authority of the State of New York HORGAN, C Horgan Associates 82/10/27 GLEASON.JP, SHON, FJ, PARIS, O H Atomic Safety and Licensing Board Panel 2pp 15853 012 24X Fiche 50-247, 82/10/27, 821029027t

#### H General correspondence

- 8210190713 Informs that SS Zullo & RA Burne authorized to sign util ltrs to NRC BAYME.J P Power Authority of the State of New York 62/10/13 Office of Nuclear Reactor Regulation, Director 2pp 15738 209 24X Fiche 50-000.82/10/13.82/0190713
- B210250272 Requests substitution of SL Baum w/TR Frey on official svc list for proceeding Related correspondence COLARULLI,P F Morgan Associates COLARULLI,P F Power Authority of the State of New York 82/10/19 STUCKY,S W Docketing & Services Branch 10 15791 190 24X Fiche 50-247.82/10/19, 6210350372
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8207180077 Forwards comments on PRA study dealing w/seismic hazard Validity of conclusions rest on quality of primary data bases & assumptions in both studies Repts are not valid risk assessments due to data base limitations POMEROY, P W Rondout Associates 82/08/24 OKRENT, D ACRS Advisory Committee on Reactor Safeguards 7pp 15876 001 24X Fiche 80-286.82/08/24, 9207180077
- P Operating license stage documents & correspondence
- 8007010658 Operating Reactor Event Hemo 80-7 re nearly simultaneous trips of Units 2 & 3 Event was of negligible safety significance & trips were unrelated & coincidental EISENHUT, D O Division of Licensing 80/06/13 VOLLMER, R H Division of Engineering MATTSDN:R J Division of Bafety Technology. HANAVER:8 H Division of Human Factors Safety 2pp 02815 145 24% Fiche 50-247.80/06/13.8007010658
- 8007280312 Summary of 800625 meeting w/util re implications of Class 9 accidents on liquid pathways at facility CODELL-R Hydrologic & Geotechnical Engineering Branch. 80/07/08 LEAR.0 Hydrologic & Geotechnical Engineering Branch 5pp 03016 253. 24% Fiche 50-247.80/07/08.8007280312
- 8008050220 Requests LB March be permitted to continue reviewing overpressure protection sys & associated Tech Bpecs NOVAK: T Assistant Director for Operating Reactors 80/07/30, ERNBT. M L Assistant Director for Technology Review 19 03078.175. 24X Fiche, 50-247, 80/07/30, 8008050220,
- 9008130744 Summary of BDO617 meeting w/utils in Bethesda, MD re containment structural response to core melt accident sequences MEYER, J. F. Power Bystems Branch B0/07/31 Power Systems Branch 3pp 03266:243 24X Fiche 50-247,80/07/31,8008130744
- 8007100100 Forwards recommendations on staff task action plan to be sent to licensees for review & response.

  BARRETTL M. Operating Reactors Assessment Branch 80/08/08 VARGA.S. A Operating Reactors Branch (Pre 80042B) 8pp 03516 066 24X Fiche-50-247.80/08/08.8009100100.

- 8009080466 Forwards response to 800820 request for status rept re-Zion/Indian Point task action plan Responsibilities are in area of severe accident mitigation features & not in interia operational actions portion MEYER, J.F. Reactor Systems Branch 80/08/25 NOVAK, T.M. Atlist Director for Operating Reactors 2pp 03484 009 24x Fichs 50-003,80/08/25,8009080466
- 8010150103 Discusses union representative allegation re hardsmart if security guard personnel Addl info necessary prior to NRC investigation of allegations HARPLM J Office of Inspection & Enforcement, Office of the Director 80/08/28 Office of Inspection & Enforcement, Office the Director 2pp 03630 268 24X Fiche 50-247, 80/08/20, 80/0150103
- 8009250234 Submits description of work being done on analysis of releases from facilities Simple 1-D multicompartment thereal hydraulic code being unitten to analyse variety of FVCB designs Related data encl
  FENSIERMACHER Reactor Systems Branch 80/09/10 SPE18.1 P
  Reactor Systems Branch 4pp 03589 257 24% Fiche 50 247.80/F 8009250234
- B010220234 Responds to 800917 request re control room review ARC (1).

  It detailed five add1 items to near-term OL requirements

  Item III D 3 4 requires analysis of control room

  habitability by 810101

  HOUSTON: R W Accident Evaluation Branch 80/09/25 VARGA, 8 A

  Operating Reactors Branch 1 1p 03560 001 24X

  Fichs 50-247, 80/09/25, 8010220234
- 8010210783 Forwards recommendations for meeting auxiliary feedwall\*, min flow requirements Licensee must demonstrate decay heat removal for 10 minutes w/o operator action or reset control valve throttled position
  CHECK.P S Assistant Director for Plant Systems 80/09/20
  NDVAK.T H Assistant Director for Operating Reactors 29p
  03647 104 24X Fichs 50-247.80/09/28.8010210783
- EDITIONAR Requests Instrumentation & Control Sys Branch evaluation util responses to questions re incore instrumentation takes at facilities Info will aid branch evaluation mitigation features re backfitting of severe mitigation features SPEIS.T P Reactor Systems Branch 80/10/09 BATTERFIFID.R Instrumentation & Control Systems Branch 1p 02927 001 243 Fiche 50-247,80/10/09.8011110084
- 8060280098 Forwards NRC questions & util answers is backfittiff of severe accident mitigation features Evaluation needed in two uts SPEIS, TP Reactor Systems Branch 80/10/17 8CMAULR, FP Structural Engineering Branch 1p 65747 184 24X Fichs 50-247, 80/10/17, 8010280098
- 8011200025 Forwards Power Sys Branch evaluation of differences labor Indian Point 2 & 3.1n response to technical assistance request Requests meeting w/licenses prior to formal response to evaluation CHECK.P B Assistant Director for Plant Systems 80/10/21 NOVAK.T Assistant Director for Operating Reactors 21;p 03749 111 24% Fiche 30-247.80/10/21/8011200025
- B210070007 Responds to FOIA request for eight categories of receff; steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 82/08/10 10M2 \*\*\* J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 241 Fiche 50-000,82/08/10,8210070007
- 8210050452 Requests comments on draft Sandia "Ltr Rept on Review's Evaluation of Indian Point Probabilistic Safety Study" by 821001 Meeting to discuss comments will be held approx 621013 M/o encl VAROA: 8 A Operating Reactors Branch I 82/09/15 SIKK: AM La Power Authority of the State of New York 2pp 13626 248 24t Fiche 50-286: 82/09/15,8210050452
- B210040400 Notification of 820921 meeting w/util in Setheria. PQ to discuss proposed repair program for steam generator shall THOMA, J D Operating Reactors Branch 1 62/09/16 VAR9A B A Operating Reactors Branch 1 ip 15597 228 24X Fiche: 50-286, 82/09/16, 8210040400
- 9210050534 Requests reply to 800923 request for add1 info \*4 GA program VARGA:S A Operating Reactors Branch 1 B2/09/21 SIMCLATE to Power Authority of the State of New York 2pp 15624 358 241 Fiche 50-284, 82/09/21 8210050534

- 8210290203 Requests results of evaluations, analyses & detailed EIGENOMY: Requests results or evaluations analyses & details of description of any ongoing or planned insp & plans & standule for repair to steam generator Results requested within 30 days of receip? of itr EISENHUT.D O Division of Licensing 82/09/24 SINCLAIR.L W Power Authority of the State of New York 3pp 15876 244 24X Fiche 50-286. 82/09/24.8210270203
- ©2:0130043 Summary of 820921 meeting w/util.Westinghouse.C-E & BMI re problems w/steam generator tubes Util proposed to sleeve degraded tubes & plug remaining tubes Viewgraphs encl THOMA.JO Operating Reactors Branch I 82/07/28 Operating Reactors Branch I 80pp 15694 276 24X Fithe 50-286,82/09/28.
- 8210060181 Forwards responses to 820315 request for addl info. Items 1, 2.3 t 8 re control of heavy loads, per 820421 commitment Responses to Items 5.6 t 7 t supplemental response to Item 2 will be provided by 821130 BATME, J f Power Authority of the State of New York 82/07/30 VARSA.5 A Operating Reactors Branch 1 9pp 15614 111 24X Fiche 50-286.82/07/30.8210060181
- 6210120253 Forwards initial comments on Sandia Natl Labs 820825 preliminary draft ltr rept on review & evaluation of probabilistic safety study, addressing wind, seismic, fire, pressurized thermal shock & fan cooler issues

  0 TOCLE, J D Consolidated Edison Co of New York BAYNE, J P Power Authority of the State of New York 82/10/06 VARQA, S A Operating Reactors Branch i 62pp 15452 215 24% Fiche 50-247,82/10/04, 82/10/253
- SE1015003: Forwards addit payment required for 820604 application to amend Tech Specs re mgt organization structure.per NRC B20719 itr Addit payment made under protest pending final determination of legality of fee schedule BANKE.JP Power Authority of the State of New York B2/10/08 MILLER.W O License Fee Management Branch Spp 15701 265 24X Fische 50-000.82/10/08.B210150031
- 0210190728 Forwards info re NUREO-0737. Item II B 3. "Post-Accident Sampling Sys." per NRC 820630 ltr SANGE.J P Power Authority of the State of New York 82/10/12 VARCA-S A Deprating Reactors Dranch I 2pp 15734 272 24X Fiche 50-286. 82/10/12. 8210190728
- --6210190734 "Response to 820630 NRC Info Request Concerning Post-Accident Sampling "

  \* Power Authority of the State of New York 82/10/31 24pp
  15/36 274 24X Fiche 50-286, 82/10/12, 8210190728
- E210220455 Forwards request for additinfo re TMI Item II K 3 25.
  Power to Purp Seals "Areas of conformance & deviation from stated position should be identified & info re design & operation of affected cooling sys provided VARGA. S A Operating Reactors Branch I 82/10/15 SINCLAIR.L. Power Authority of the State of New York 3pp 15786 211 24X Fiche 50-286, 62/10/15, 6210220455 SINCLAIR.L. W
- E210210459 Forwards application to amend License DPR~64 & proposed Tech Spec changes re steam generator surveillance requirements DAYNE, J.P. Power Authority of the State of New York 82/1 VARGA.S A Dperating Reactors Branch 1 2pp 15762 236 Fiche 50-286.02/10/16,8210210459
- ---B210210470 Application to amend License DPR-64 changing Tech Specs re steam generator surveillance requirements BAYNE.J P Power Authority of the State of New York 62/10/18 2pp 15762 238 24% Fiche 50-286.82/10/18,8210210459
- --8210210473 Proposed Tech Spec changes re steam generator surveillance requirements
  4 Power Authority of the State of New York 82/10/18 16pp 15762 240 24X Fichs 50-286, 82/10/18, 8210210459
- 8210280070 Forwards response to NRC 820924 request for info re girth weld repair program

  BAYNE, J.P. Power Authority of the State of New York 82/10/:
  EISENHUT.D.Q. Division of Licensing 51pp 15845 095 24X
  Fiche 50-286, 82/10/25, 8210280070 82/10/25
- @ Inspection reports. IE Bullatins & correspondance
- 8210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R\_Udelf FOIA Request 81-313 Forwards documents listed in App B FELTON J M FELTON.J M Division of Rules and Records 82/08/10 LONG.D.J Wanthrop, Stimson, Putham & Roberts 9pp 15645 063 24X Fache 50-000,82/08/10,8210070007

- --8210070139 Forwards tabulated data on steam generator insp & maint at Facilities Data should be provided to licensees

  IPPGLITO.T Operating Reactors Assessment Branch

  VAROA.B Operating Reactors Branch 1 5pp 156/
  Fiche 80-000,82/08/10.8210070007 5pp 15645 131
- 8210070214 Forwards IE Insp Rept 50-286/82-16 on 820816-0915 No noncompliance noted

  STAROSTECKI,R Division of Project & Resident Programs

  BRONS,J C Power Authority of the Btate of New York 2

  18534 245 245 Fichs 50-286.82/09/23.8210070214
- X100/U216 IE Insp Rept 50-286/82-16 on 820816-0915 No noncompliance noted Major areas inspected plant operations, plant tour, surveillance, maint, purging & venting of containment, test & measurement equipment program FOLEY, T & KENNY, T J & KISTER, H Division of Project & Resident Program 82/09/22 10pp 15634 248 24% Fiche 50-286,82/09/23,8210070214 ~-8210070216 IE Insp Rept 50-286/82-16 on 820816-0915 No noncompliance
- 8210290203 Requests results of evaluations, analyses & detailed close values and entering or planned (insp & plans & detailed description of any ongoing or planned (insp & plans & schedule for repair to steam generator Results requested within 30 days of receipt of ltr.

  EISENHUT, D 9 Division of Licensing 82/09/24 BINCLAIR, L W Power Authority of the State of New York. 3pp 15876 244 24X Fiche 30-286 62/09/24,8210270203
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds "Svc list encl CDBR,L I Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000, 82/10/06,8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BUR Plants " Svc list encl DEYDUNG: R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 15810 125 24X Fiche 50-000, 82/10/14, 820817023B
- R Periodic operating reports & related correspondence
- 8210180088 Forwards monthly operating rept for Sept 1982 BRONSLJ C Power Authority of the State of New York Management Information Branch ip 15719 340 24X Fiche. 50-286. 82/09/12.8210180088 82/09/12
- --8210180091 Monthly operating rept for Sept 1982 AUTERING.L Power Authority of the State of New York App. 15719 341 24X Fiche 50-286,82/09/12,8210180088
- S Reportable occurrences, LERs & related correspondence
- 8210270267 Part 21 deficiency rept re potential galling problem between stem & bonnet of 1 25-inch & larger A105 carbon steel & A182-F22 valves supplied Feb 1781-Aug 1782 Valves should be serviced & stem &/or bonnet replaced ISABELLE, L D. Conval. Inc 82/10/11 HAYNEB.R C Region 1. Office of Director 179p. 15854 232 24X Fiche 50-000,82/10/11. 8210270267.
- T Hearing transcripts on non-antitrust matters
- 8210040232 Testimony of JD D'Toole before US House of Representatives Subcommittee on Energy & Conservation of Committee on Energy & Conservation of Committee on Energy & Commerce re role of public participation in NRC proceedings H/Certificate of Svc Related correspondence.

  O'TOOLE, J D Consolidated Edison Co of New York 82/10/01 Ripp 15621.204 24X Fiche 80-247.82/10/01.8210040232
- DOCKET BO-287 OCONEE NUCLEAR STATION, UNIT 3 F Security, medical, emergency & fire protection plans
- 8210010352 Forwards revision to safeguards contingency plan Revision withheld (ref 100FR73 21)
  TUCKER.H B Duke Power Co 82/09/17, DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 15574,139 24X
  Fiche 80-269,82/09/17,8210010352
- 8210260527 Agrees w/determination to locate fire hose stations outside affected fire areas Change from earlier commitment acceptable

  STOLE-J F Operating Reactors Branch 4 82/09/23 TUCKER, H. B

  Duke Power Co 2pp 15830.189. 24X Fiche 50-269, 82/09/23, 8210260520 8210260529

- 8210040232 Application to amend Licenses DPR-39.DPR-47 & DPR-55 Amend requests deletion of Tech Spec 6 4 2 re site emergency drill & definition of time within which redundant component test must be performed prior to performing maint per Tech Spec TUCKER.H B Duke Power Co 82/09/27 DENTON.H R Defice of Nuclear Resolutor Regulation. Director 3pp 15586-104 24X Fiche 50-269.82/09/27.8210040232
- --B210040245 Proposed revision to Tech Spec Pages 3 3-6 & 6 4-1 re site emergency drill & time period within which redundant component test must be performed prior to performing maint # Dute Power Co 82/09/27 4pp 15586 107 24X Fiche 50-269,82/09/27,8210040232

#### P Operating license stage documents & correspondence

- B210080036 Responds to FQIA request for documents re pins designed to hold neutron shielding pads in place under accident conditions Forwards documents listed on App A FELTON. JM Division of Rules and Records B2/08/13 EDDLEMAN. W Public Interest Research Group in North Carolina 2pp 15669 240 246 Fichs 50-237.02/08/13.821008036
- ~-8210080047 Discusses work items to be accomplished after 820423 shutdown for extended refueling outage Lower thermal shield bolts will be replaced w/Inconel X-750 studs a nut assembly Unit 3 scheduled to return to operation on 820915 MAGNER,P C Operating Reactors Branch 4 82/06/15 DENTON,H R, CARTER,J, EISENHUT,D Q NRC No Detailed Affiliation Given ip 15669 283 24X Fiche 50-000,82/08/13,8210080036
- B210040107 Advises that util response to NRC G20218 ltr will be provided by B21008. Receipt of info from crane vendor & extraordinary analytical work have delayed response TUCKER, H B. Duke Power Co. G2/09/24 DENTON, H R. Office of Nuclear Reactor Regulation. Director STOLZ, J F. Operating Reactors Branch 4 ip 15581-024 24X Fiche 50-269,82/09/24,8210040107
- 8210040232 Application to amend Licenses DPR-38.DPR-47 & DPR-85 Amend requests deletion of Tech Spec & 4 2 re site emergency drill & definition of time within which redundant component test must be performed prior to performing maint per Tech Spec TUCKER.H B Dute Power Co 82/09/27 DENTON.H R Office of Nuclear Reactor Regulation. Director STOLX.J F Operating Reactors Branch 4 3pp. 15586-104 24X Fiche 50-269.82/09/27,8210040232
- --8210040245 Proposed revision to Yech Spec Pages 3 3-6 & 6 4-1 re site emergency drill & time period within which redundant component test must be performed prior to performing maint.

  4 Duke Power Co 82/09/27 4pp 15586 107 24X Fishe 50-28/9,82/09/27,8210040232
- 8210190145 Forwards Amends 113,113 & 110 to Licenses DPR-38,DPR-47 & DPR-58, respectively, safety avaluation & notice of issuance & availability Amends revise Tech Spacs to allow full power operation of Unit 3 during Fuel Cycle 7 HAGNER, P. C. Operating Reactors Branch 4 82/09/29 TUCKER, H. B. Dute Power Go. 2pp 15757 341. 24X Fiche 50-269,82/09/29. 8210190145
- --8210190154 Amends t13, i13 % 110 to Licenses DFR-38, DFR-47 % DFR-55, respectively, revising Tech Specs to allow full power operation of Unit 3 during Fuel Cycle 7 STOLZ, J F Operating Reactors Branch 4 82/09/29 Sipp 15757 343 24% Fiche: 50-269, 82/09/29, 8210190145
- ---8210190161 Bafety avaluation supporting Amends 113,113 & 110 to Licenses DPR-38.DPR-47 & DPR-55.respectively + Office of Nuclear Reactor Regulation, Director 82/09/29 6pp 15738 012. 24X Ficha 30-269,82/09/29/8210190145
- --8210190169 Notice of issuance & availability of Amends 113,113 & 110 to Licenses DPR-38, DPR-47 & DPR-55, respectively STGLZ, J F. Operating Reactors Branch 4 82/09/29, 2pp 13758 OIB. 24X Fiche.50-289,82/09/29,8210190145.
- 8210210292 Advises that review of info on mods to emergency feedwater sys & repairs made to once-through steam generators complete. Plant may resume operation w/listed conditions LAINAB. O C Assistant Director for Operating Reactors 82/09/29. TUCKER. H. B Duke Power Co 3pp 15774: 347. 24X Fiche. 50-287. 82/09/29. 8210210292
- --8210210299 Safety evaluation supporting steam generator repair & energency feedwater sys mods \*\* Office of Nuclear Reactor Regulation, Director. 62/09/29. 7pp. 15774: 350. 24X Fiche. 50-287. 82/09/29, 8210210292.

8210180323 Responds to 820913 ltr re reactor bldg purge sigs Position given in 810707 & 17 ltrs remains unchanged Schedule for submitting info indicating purge sys meets operability requirements requested LAINAS, G C Assistant Director for Operating Reactors 82/09/X TUCKER, H B Duke Power Co 3pp 15745 334 24X Fiche 50-269, 82/09/30, 8210180323

1

- 8210150519 Discusses NRR actions taken under Task Interface Aprill' 82-20 for steam generator auxiliary feedwater header damage Licensee authorized to resume power operation at Oconee 3
  EISENHUT, D 0 Division of Licensing 82/10/06 DLSHIMON, J Division of Engineering & Technical Programs 1p 15717 261 2. Fichs 50-000, 82/10/06 8210150519
- --821015052B Forwards safety evaluation re once-through steam gaver, repair & emergency feedwater sys mod Licenses authorized to resume power operation LAINAS, G.C. Assistant Director for Operating Reactors 02/452 TUCKERI H B Dive Power Co. 2pp. 15717-262 24% Fiche 50-000, 82/10/06.8210150519
- --8210150535 Safety evaluation supporting resumption of power opinifollowing once-through steam generator repair & emergency feedwater sys mods WAGNER, P.C., HAFIZ, A., RIDGELY, J. Assistant Director for Opini-Reactors 82/09/29 7pp 15717 264 24X Fiche 50-000.82/11.4 8210150519
- 9210130502 Advises that flow demonstration & water hammer tests.jer NRC 820929 ltr.confirm that modified auxiliary feedwater sys satisfactory Bys supplies required amount of feedwater w/no evidence of water hammer phenomenon TUCKER.H B Dute Power Co 82/10/07 DENTON.H R ()ffice of Nuclear Reactor Regulation. Director STCLZ.JF Operating Rest Branch 4 ip 15482 232 24% Fiche 50-287,82/10/07,021013057
- 8210180055 Responds to NRC 820608 request for add1 info re adeq.acristation electric distribution sys voltages Requested info expected by 821022
  TUCKER.H B Dute Power Co 82/10/08 DENTON.H R Office of Nuclear Reactor Regulation, Director STOLZ.JF Operating Perbranch 4 1p 15720 010 24X Fiche 50-269.82/10/08.021010055
- --B2101800AO Forwards partial response to Franklin Research Ctr 4's technical evaluation rept re control of heavy loads, per NUREG-0612
  TUCKER, H B Duke Power Co 82/10/08 DENTON, H R Office of Nuclear Reactor Regulation, Director BTOLZ, J F Operating Reactors Branch 4 Spp 15720 011 24X Fiche 50-269, 63/10 14 8210180053
- 8210210131 Responds to NRC 820908 ltr transmitting technical s.al., rept on emergency feedwater sys Sys may not mest all current criteria for seismic qualification; but will remain functionally operable during OBE TUCKER.H B Duke Power Co B2/10/13 DENYON,H R Office of Nuclear Reactor Regulation, Director STOL7.JF Operating Fee Branch 4 App 15766-356 24X Fiche 50-249.82/10/13.82102(61)
- 8210210407 Application to amend DLs.revising Tech Spec 3 taller.g full power operation of Unit 1 for interim period until appropriate safety valve ring settings can be implemented TUCKER.H B. Duke Power Co. 82/10/14 DENTON-II R. Office of Nuclear Reactor Regulation, Director STOLZ.J F. Operatory Fac. Branch 4. Spp. 15764-038 24X Fiche 50-269.82/10/14.821021081
- --B210210411 Proposed revision to Tech Spec 3 i allowing full state operation of Unit 1 for interim period until appropriate safety valve ring setting can be implemented 4 Dute Power Co. B2/10/14 ip 15764 048 24% Fiche: 50-269, B2/10/14, B210210407
- O Inspection reports, IE Bulletins & correspondence
- B210070007 Responds to FOIA request for eight categories of Facarist steam generators & steam turbines App A documents provided in R Udell FOIA Request Bi-313 Forwards documents listed in App B.
  FELTON, J M Division of Rules and Records. 82/08/50 tCRR. 0 J Winthrop, Stimson, Putnam & Roberts 9pp 15645 G63 24% Fiche: 50-000, 82/08/10, 8210070007
- --8210070172 Forwards info re steam generator integrity & IRAPS SEL operating PWRs.per 750320 & 21 requests Details of IRAPS. including defect indications, tube plugging criteria & tybes plugged will not be provided except for Point Beach & GOLLER.K.R. Division of Reactor Licensing (MRR-1975 enly) 75/03/24, MACCARY.R. Division of Technical Review (MRR-1875 only) 5pp. 13645 196. 24X Fiche 50-000,82/08/10.92/0070307

- O150369 Forwards results of investigation of Item 7a of IE Inspiepts 50-269/82-21, 50-270/82-21 & 50-287/82-21 Dedetime alues for gamma spectroscopy analyses of waste gas silver colite cartridges will cause only insignificant errors UCHER.H B Dute Power Co 82/08/17 O'REILLY, J P Region 2, 18f3ce of Director 2pp 19704 269 24X Fiche 50-269,82/08/17, 12(0150369
- Octo117 Forwards IE Insp Repts 50-269/82-33.50-270/82-33 & 10-287/82-33 on 820817-20 No noncompliance noted ARCE, H C Division of Project & Resident Programs 82/09/02 UCKER. II Duke Power Co 2pp 15546 019 24X sche 50-269, 82/09/02.8210010117
- '210010124 IE Insp Repts 50-269/82-33.50-270/82-33 & 50-287/82-33 on 820817-20 No noncompliance noted Major areas inspected action on previous enforcement matters, auxiliary feedwater header repair & inservice insp procedures CROMLEY B R , BLAKE J J Division of Engineering & Technical Programs 82/09/01 8pp 15566 021 24X Fiche 50-269.82/09/02,8210010117
- OOI0158 Forwards IE Insp Repts 50-249/82-30, 50-270/82-30 & 00-287/82-30 on 820716-0810 No moncompliance noted ArcE. H C Division of Project & Resident Programs 82/09/02 UCKEN. H B Dute Power Co 2pp 15567 258 24X iche 50-249, 82/09/02.8210010158
- '210010166 JE Insp Ropts 50-269/82-30.50-270/82-30 & 50-287/82-30 on 620716-0810 No noncompliance noted Major areas inspected operations, surveillance testing, maint, NUREG-0737 mods & refueiling activities GROBERS.W. FALCONER.D. BRYANT.J C Division of Project & Resident Programs 82/09/02 13pp 15567 260 24X Fiche 50-269.82/09/02, 8210010159
- CO10498 Ack receipt of 820805 ltr informing NRC of steps taken to orrect violations noted in IE Insp Repts 50-269/82-23, 50-267/82-23
  EMIS.R C Division of Project & Resident Programs 82/09/17
  EUCKER.H B Duke Power Co ip 15570 182 24X
  \*\*sche 50-269-82/09/17-8210010458
- 3210010463 Responds to NRC 820712 ltr re violations noted in IE Insp Repts 50-269/82-23.50-270/82-23 & 50-287/82-23 Corrective actions personnel counseled & valve 2HP-14 cut out & properly reinstalled TUCKER.H D Duke Power Co 82/08/05 O'REILLY, J P Region 2, Office of Director 4pp 15570 183 24X Ficha 50-269,82/09/17, 6210010488
- 3210010468 Forwards IE Insp Repts 50-269/82-23,50-270/82-23 k 50-287/82-23 on 820510-0610 k notice of violation LEWIS.R C Division of Project & Resident Programs B2/07/12 FARKER, W D Duke Power Co 2pp 15570 187 24X Fiche 50-269,82/09/17,8210010458
- B210010474 IE Insp Repts 90-269/82-23,50-270/82-23 & 50-287/82-23 on B20510-0610 Noncompliance noted failure to follow procedures resulting in plant trip I inadequate procedure resulting in improper reassembly of safety-related valve ORDERS.H . FALCONER.D . BRYANT.J C Division of Project & Resident Programs B2/07/09 12pp 15570 191 24X Fiche 50-269.82/09/17, B210010458
- 10150253 Ferwards IE Insp Repts 50-269/82-32.80-270/82-32 & 50-267/82-32 on 620817-18 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/17 TUCKER.H B Duke Power Co 2pp 15703 267 24X Fiche 50-269.82/09/17.8210150253
- B210150263 IE Insp Repts 50-269/82-32,50-270/82-32 & 50-287/82-32 on 820817-19 No noncompliance noted Major areas inspected lab QC & review of radiochemistry procedures & records EVANS.C D. MONTOOMERY,D M. Division of Emergency Preparedness & tiperational Support 82/09/15 Spp 15703 269 24X Fiche 50-269,82/09/17,8210150253
- 10150131 Forwards IE Insp Repts 50-269/B2-85,50-270/B2-35 & 50-287/B2-35 on 820908-10 No noncompliance noted DANCE: H C Division of Project & Resident Programs 82/09/23 TUCKER, H B Duke Power Co, 2pp 15698 312, 24X Fiche 50-269, 82/09/23,8210150131

- 8210130290 Requests relief from inservice insp requirements (hydrostatic) of Saction XI of ABME Boiler & Pressure Vessel Code TUCKER. H B Duke Power Co 82/10/04 DENTON, H R Office of Nuclear Reactor Regulation, Director BTGLZ. J F Operating Reactors Branch 4 20pp 15678 243 24X Fiche 50-269.82/10/04.8210130290
- 8208190233 IE Info Notice 80-35. Suppl i, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl. COBB.L I Division of Fuel Facilities, Materials & Safeguards BZ/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000.82/10/06.8208190233.
- 8210220426 Forwards Revision 5 to response to IE Bulletin 79-02, "Pips Support Base Plate Designs Using Concrete Expansion Anchor Bolts "
  TUCKER, H B Duke Power Co 82/10/08 Q'REILLY, J P Region 2, Office of Director 24pp 15778 273 24X Fiche 50-269, 82/10/08, 8210220426
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation SysPiping at BMR Plants " Svc list encl
  DEYGUNO, R C Director's Office, Office of Inspection and
  Enforcement 82/10/14 Consolidated Edison Co of New York
  115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- R Pariadic operating reports & related correspondence
- 8210190544 Forwards monthly operating repts for Sept 1982 TUCKER.H B Duke Power Co 82/10/15 Director's Defice of Inspection and Enforcement 1p 19751 343 24X Fiche 50-269.82/10/15.8210190344
- ~-8210190552 Monthly operating repts for Bept 1982 REAVIS.J.A. Duke Power Co 82/10/15 16pp 15751 344 24X Fiche 50-249, 82/10/15,8210190544.
- 8 Reportable occurrences, LERs & related correspondence
- 8210120114 Advises of immediate need for imposing specific requirements re operational restrictions for Class IE 120-volt ac vital instrument buses in operating plants MICHELSON, C Director's Office 80/07/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 15687-165 24X Fiche 50-000,80/07/15,8210120114
- 82(00)0008 Responds to FDIA request for 17 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J H Division of Rules and Records 82/06/28 UDELL,R.A Critical Mass Emergy Project 15pp 15727 005 24X Fiche 50-000,82/06/28.8210010008
- 6210190447 PNO-11-82-108 on BR1010, increasing steam generator tube leakage indicated in 3A steam generator Reactor placed in hot shutdown. No abnormal radioactive releases identified IGNATONISA. BRYANT, J. C. Region 2, Office of Director 82/10/12 ip 15740:169 24X Fiche 50-287.82/10/12,8210190447
- 8210190653 PNO-II-82-111 on 821014. Unit 2 shut down after determining that pressurizer code safety valve design flow could not be fully maintained if called upon Beven-day outage required to change valves Exemption requested for Unit 1 IONATONIS.A Region 2, Office of Director 82/10/14 2pp 24x Fichs. 50-287, 82/10/14, 8210190653.
- 82:0190695 RO on 82:014, Unit 2 core relief valves declared indperable due to analysis prompted by 8&W safety concern. Unit 3 valves were offsite undergoing ring adjustment Immediate shutdown of Unit 2 commenced.

  \* Duke Fower Co 82/10/14. Region 2, Office of Director, 1p. 15736 200 24X Fiche 50-270,82/10/14,8210190695.
- 8210290308 Forwards LER 82-010/01T-0 Detailed event analysis enci TUCKER. H B Duke Power Co 82/10/18 0'REILLY, J.P Region 2, Office of Director. 3pp 13853 018 24X Fiche. 50-287, 82/10/18, 8210270308
- --8210270313 LER 82-010/01T-0 on 821004, discovered that weekly boron waste storage tank boron sample not taken as scheduled, contrary to Tech Spac 4, 1 3 Caused by personnel not having access to posted schedule board Board replaced.

  PETTY, J C. Duke Power Co. 82/10/18, Region 2, Office of Director, ip. 15853 021 24X Fiche 50-287,82/10/18,8210270308

- DOCKET 50-289 THREE HILE ISLAND NUCLEAR STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- B210050491 Forwards exemption from annual emergency plan exercise requirements of 100FR50.App E re level of govt participation STOLZ, J F Operating Reactors Branch 4 B2/09/14 HUKILL, H D General Public Utilities ~ QPU Service Corp. 7pp 15626 291 24X Fiche 50~289, 82/09/14-8210050491
- --B210050495 Exemption from annual embrgency plan requirements re level of govt participation in exercises EISENHUT, D Q Division of Licensing B2/09/14 General Public Utilities OPU Service Corp 4pp 15626 298 24X Fiche 50-289,82/09/14,8210050491
- 8210060228 Forwards revisions to fire hazards analysis rept & App R Section III 0 re safe shutdown evaluation HUKILL.H D General Public Utilities - GPU Service Corp G2/10/0 EISENHUT.D G Division of Licensing 2pp 15620 013, 24X Fiche 50-289,82/10/01,8210060228
- --8210060230 Revisions to fire hazards analysis rept & App R Section III G re safe shutdown evaluation • General Public Utilities - GPU Service Corp 62/10/01 32pp 13620 015 24X Fiche 50-289, 82/10/01.8210060228
- 8210:3024B Advises of dairy farm located approx 1 i miles east of TMI yielding fose commitment greater than six of seven present milk sampling stations Results of land census to be included in 83050: annual radiological environ operating rept HWKILL-H D General Public Utilities GPU Service Corp 82/10/04 HAYNES, R C Region 1. Office of Director 1p 15676 008 24X Fiche 50-289, 82/10/04, 8210:30248
- 8210150202 Clarifies position re Action 4 of IE Bulletin 79-21. "Temp Effects on Level Heasurements "Inclusion of tables, curves or correction factors in emergency procedures will unnacessarily complicate procedures, HUMILLIH D General Public Utilities - GPU Service Corp 82/10/04 HAYNES: R C Region 1, Office of Director 2pp 15701 334 24X Fiche: 50-289, 82/10/04, 8210150202
- 8210130161 Responds to ASLAB 811204 partial initial decision re alert to notification sys Siren sys for offsite alerting adequate, pending determination of compliance w/NWREG-0564 & FEMA REP-1.

  KRIMM.R W Federal Emergency Management Agency 82/10/06 GRIMES, B Division of Emergency Preparedness 5pp 15673 061. 24% Fiche 50-289. 82/10/06.8210130161
- 8210130320 Bubmits updated status rept on offsite emergency planning issues at facility Emergency preparedness brockures distributed Siren sys testing satisfactorily completed Communications drill held on quarterly basit KRIMM.R W Federal Emergency Management Agency 82/10/06 ORIMES.B K Division of Emergency Preparedness 2pp 15678.158 24X Fiche 50-289,82/10/06,8210130320

#### G Adjudicatory correspondence

- 6210070028 Board Notification 82-93 forwards RJ Mattson 620830 memoto DO Eisenhut notifying of results of Samiscale test on feed & Aleed capability
  LAINAS-0.C Assistant Director for Operating Reactors 82/09/14
  Atomic Safety and Licensing Appeal Panel 4pp 13645:317 24X
  Fiche 30-269-82/09/14,8210070028
- --9210070032 Requests all PWR licensing boards be informed of results of Semiscale feed & bleed test.Unexpected uncovery of core simulator occurred MATTSON-R.J. Division of Systems Integration (post 811005). 82/09/30 EIBENNUT.D.J Division of Licensing 3pp. 15645-321 24% Fiche: 50-289, 82/09/14, 8210070028
- --8210070035 Recommends that board notification on Semiscale feed & blood experiments not be issued ASSETT.0 E Division of Accident Evaluation 82/08/23 SPEIS, T.P. Assistant Director for Reactor Safety 22pp 15645-324 24x Fiche: 50-287, 82/09/14,8210070028.
- 8210010427 Memorandum & order granting licensee request to refer Ammodt 820903 motion to reopen evidentiary record to ASLAB ASLAB Lacks jurisfiction over subj matter SMITM, I.W. Atomic Safety and Licensing Board Panel 82/09/29 Metropolitan Edison Co. 8pp. 15569:355. 24X Fiche 50-289,82/09/29,821003027.

- 8210050176 Brief in support of exceptions to ASLB 810827 & 820727 partial initial decisions re mpt issues & reopened proceedings
  BRADFORD.L., DOROSHOW.J Three Mile Island Alert 82/09/30 Atomic 92fety and Licensing Appeal Panel 93pp 15404-025 Fight 50-289, 82/09/30, 8210050176
- 6210050192 Brief on exceptions to ABLB 810827 & 820727 partial inhibits decisions on mgt issues training & integrity Certificate of 8vc encl AAMDDT: M K Aamodts, The 82/09/30 Atomic Safety and Life 1-1, Appeal Panel 36pp 15609 256 24X Fiche 50-289,82/09/30, 8210050192
- B210050237 Advises that THI Alert unable to present full discussion is some issues in brisf due to severe time constraints.

  BRADFORD, t. Three Hile Island Alert 82/09/30 EDLEG, Q J Atts. C Safety and Licensing Appeal Panel BUCK, J H , KOHL, C Alemis Safety and Licensing Appeal Panel 19 15609 051 24X

  Fichs, 50-289, 82/09/30, 8210050237
- S210060210 Brief supporting UCS brief on exceptions to ASIB 820/27 partial initial decision ASIB cannot continue to rely on operator judgment understanding & integrity to compensate for lack of reliable equipment Certificate of Svc sncl MEISS.E R Metropolitan Edison Co MEISS.E R Harnon & Weiss 82/09/30 Atomic Safety and Licensing Appeal Panel 3659 15614 121 24X Fiche 50-289,82/09/30,8210060210
- 8210060218 Brief in support of exceptions to ASLB 820727 partial initial decision on reopened proceeding on operator cheating Centificate of Svc encl ADLER,R H Pennsylvania, State of 82/09/30 Atomic Gafety \*\*4 Licensing Appeal Panel 45pp 15614 243 24X Fiche 50-289, 82/09/30, 8210060218
- 6210070194 Forwards THI training program assessment, representing recent view of program & covering hearing topics GPU has made significant progress Recommendation for changes made M/o rept Svc list enci
  BLAKE. E. Shaw. Pittman. Potts & Troubridge BLAKE. I. I. Metropolitan Edison Co 82/10/05 EDLES, G J , BUCK, J H , PG.R. C s Atomic Bafety and Licensing Appeal Panel 4pp \$5534 2/4 241 Fiche 50-289, 82/10/05, 8210070194
- 8210070149 Order scheduling 821109 hearings in Harrisburg.PA (coess) will hear parties re ASLB 811214 & 820727 partial initial decisions & will hold public meeting on restart CHICK 8 J Office of the Secretary of the Commission (12/10/25 3pp 15627 077 24% Fiche 50-289, 82/10/06.821007014)
- 8210080094 Forwards licensee first annual progress rept on invisition of exact replica simulator Bid package delayed from Apr to Sept.1982 Installation expected in 1985 Svc list encl BLAKE, E. L. Shaw Pittman, Potts & Troubridge Blake, Potts & Troubridge Bla
- 82(0)20274 Responds to 820914 Doard Notification DN-02-93 re tests on feed & bleed & motion that ASLAB direct NRC to provide pertinent documentation UCB Exceptions 9-11, 16, 10-19 & 107 should be sustained W/Certificate of Evc POLLARD.R.D. WEISSER Wijon of Concerned Eclentists Religious Harmon & Weiss 82/10/07 Atomic Eafsty and ticensing Abject Panel 17pp 15452 297 24X Fiche 80-209, 82/10/07, 02/010/27st
- 9210130275 Advises that ltr-designated Individual O resigned wifell a S21015 Individual O was NRC licensed control room operator whose performance on tests & exams was issue in reopened phase of proceeding Svc list enc!
  BLAKE, E.L. Shaw, Pittman, Potts & Troubridge BLAKE, E.I.
  Metropolitan Edison Co. 82/10/07, EDLES, G.J., BUCK, J.R., MC-4, [4]
  Atomic Safety and Licensing Appeal Panel 3pp 15678 162 248
  Fithe 30-289, 82/10/07, 8210130275
- 8210120256 Forwards Commission 821006 order scheduling 82107 hear.win Harrisburg. PA.in response to 811216 request BICKHIT.L. Defice of the General Counsel 82/10/08 1081 hear Mile 1sland Public Interest Resource Center 1p. 18652 Rig 217 Fiche 50-287, 82/10/08,8210120256
- 8210120314 Forwards Commission 821006 order advising of 821109 patts meeting in Harrisburg.PA
  BICKWIT.L. Diffice of the General Counsel 82/10/00 Middle, JE
  Dauphin County, PA ip 15651 251 24X Fiche.50~289.82/10/06.
- 8210130288 Requests to make limited appearance statement at Computer 821109 meeting in Harrisburg, PA re lifting of immediate effectiveness orders HOFFMAN, J C Friends & Family of TMI. 82/10/08 CHILK. Q C File Becretary of the Commission ip 15678 305 241 Fiche: 50-287, 82/10/08, 8210130288

- 8210210359 Motion to file brief supporting exceptions to ASLB 810807 & 820727 partial initial decisions out of time on 821002 Circumstances beyond intervenor control necessitate extension Certificate of Svc encl AAMODT.M M Asmodts. The 82/10/09 Atomic Safety and Licensing Appeal Panel 4pp 15763 342 24X Fiche 50-289,82/10/09, 8210210359.
- 8210180160 Advises that 1tr-designated Individuals 0 & VV will not respond to UCS.Commonwealth of PA.THI Alert & Aamodés briefs supporting exceptions THI Alert Exceptions 23 & 24 & Aamodé Exception 133 waived VOIOT.H H Lepoeuf, Lamb, Leiby & MacRae 82/10/13 EDLES, 0 J , BUCK.J H , KOHL.C N Atomic Safety and Licensing Appeal Panel 1 15719 169 24X Ficho 50-289, 82/10/13,8210180160
- 8210180180 Memorandum & Order CLI-82-31 directing IE to determine ubsther civil penalty proceeding should be instituted against licensee for acts uncovered in hearing & Ofc of Investigations to investigate alleged metl false statement GHILK.8 J Office of the Secretary of the Commission 82/10/14 10pp 15719 135 24% Fiche 50-209.82/10/14.8210180180
- S210200033 Advises that licensee will file one consolidated brief, on S2104 in response to Commonwealth of PA.TMI Alert UCS & Aamodt briefs supporting appellant exceptions re mgt issues. Svc list encl
  BLAKE.E.L. Shaw. Pittman. Potts & Trowbridge BLAKE.E.L. Metropolitan Edison Co. B2/10/14 EDLES.O.J. BUCK.J.H., KOHL.C.N. Atomic Safety and Licensing Appeal Panel App. 15757 304 24X Fiche 50-289.62/10/14.8210200033
- 8210200006 Order directing NRC to respond to UCS 821007 motion, characterized as response to Board Notification BN-82-93, that NRC provide all documents re semiscale test on feed & bleed capability
  SHOEMAKER.C.J Atomic Safety and Licensing Appeal Panel 82/10/15
  Office of the Executive Legal Director 3pp 15753.208 24X
  Fiche 50-289,82/10/15.8210200006
- S210200011 Order extending time until 821022 for Commission to act to review ALAB-485 CHILK.8 J Office of the Secretary of the Commission 82/10/15 Commissioners 1p 15753 211 24X Fiche 50-289,82/10/15, 8210200011.
- 8210210378 Advises that author will represent Commonwealth of PA at 921109 oral presentations before Commission. Bvc list encl ADLER.R W Pennsylvania. State of 82/10/18 CHILK.B J Office of the Secretary of the Commission. 3pp 15760 147 24X Fiche, 50-289, 82/10/18, 8210210378
- 8210260400 Advises that NO Aamodt will represent Aamodt family at 821109 oral presentations in Harrisburg, PA
  AAMODT, M M Aamodts, The 82/10/19 CHILK, 8 J. Office of the Secretary of the Commission 1p 15803, 103 24X
  Fichs 50-289, 82/10/19, 8210860400
- 8210210374 Notifies that licensee will appear at 821109 public hearing to make presentation & respond to questions re restart Licensee expects to reserve portion of time for rebuttal of other presentations Svc list encl TROMBRIDGE.0 F Shaw, Pittman. Potts & Trowbridge TROMBRIDGE.0 F Shaw, Pittman. Potts & Trowbridge TROMBRIDGE.0 F Hebropolitan Edison Co. 82/10/20. PALLADINO.N J . OILINSKY, V . AHEARNE.J F . Commissioners 4pp. 15762 014 24X Fiche 50-289.82/10/20.8210210374
- 82102(0493 Order establishing arrangements for 821109 meetings in HarrisburgsFA re restart CHILK, B.J. Office of the Secretary of the Commission. 82/10/20, 3pp. 15762, 259. 24X Ficher 50-289, 82/10/20, 8210210493.
- 8210220445 Advises that JM Cutching, JR Coldberg & JR Gray will represent NRC at oral argument on whether to lift immediately effective shutdown orders in view of ASLB B20727 & B11214 partial initial decisions. CRAY, J. R. Hearing Branch 4, B2/10/20 CHILK, S J Office of the Secretary of the Commission 1p. 15778 338 24X Fiche: 50-289, 82/10/20,8210220445.
- 9210220465 Advises that author will represent UCB at 921109 oral argument Certificate of Svc encl HEISS.E R Harmon & Weiss. WEISS.E.R Union of Concerned Scientists. 92/10/20 PALLADINO.N.J. AHEARNE.J., GILINGKY.V. Commissioners 4pp 15779:121 24X Fichs: 80-289,82/10/20,0210200AAM
- 8210250325 Forwards Commissioners TM Roberts & V Gilinsky corrected separate views on Order CLI-82-31
  8TUCKY.S W. Docksting & Bervices Branch. 82/10/21 Office of the Executive Legal Director. 1p, 13790.077. 24X Fiche 50-289, 82/10/21, 8210250325

- --8210250332 Corrected separate views of Commissioners TM Roberts & V 0111nky on Order CLI-82-31 ROBERTS.T M , 01LINSKY.V Commissioners 82/10/21 4pp 15790 078 24X Fiche 50-289, 82/10/21,8210250325
- 8210260433 Decision AtAB-698 affirming ASLB decision not to require predistribution of permanent record dosimeters & modifying decision on emergency support director SHOEMAKER.C J. Atomic Safety and Licensing Appeal Panel 82/10/22 67pp 15805 328 24X Fiche 50-289.82/10/22.8210260433
- 8210260449 Decision ALAB-697 affirming ASLB decisions on emergency planning w/condition that Commonwealth of PA agricultural info brochure be given to farmers in 10-mile plume exposure emergency planning ione SHOEMAKER.C J Atomic Bafety and Licensing Appeal Panel 82/10/22 50pp 15807-054 24% Fiche 50-289-82/10/22 8210260449
- 8210260468 Order CLI-82-32 edvising that ASLAB should not be concerned about current status of compliance w/restart requirements Proceeding should determine necessary actions to protect public & progress of long-term items CHILK, S. J. Office of the Secretary of the Commission 82/10/22 Atomic Safety and Licensing Appeal Panel 4pp 15806-224 24% Fiche 50-289.82/10/22.8210260468
- B210270070 Response to ASLAB B21015 order UCS requests for relief in 821007 response to Board Notification BN-82-93 should be denied All documents NRC considers relevant & matl re Semiscale tests served on UCS RAWSON.R J Hearing Branch 4 B2/10/25 10pp 15815 302 24X Fiche 50-289.82/10/25.8210270090
- --B210270095 Affidavit of BW Sheron & ML Jensen re Semiscale S-SR-2 results Test results do not raise significant safety issue, do not shibit any new phenomena & can be adequately predicted by existing computer codes W/Certificate of Svc SHERON, 3 W , JENSEN, H L Reactor Systems Branch B2/10/25 43pp 15815 311 24X Fiche 50-229,82/10/25,92/10270090
- 8210280250 Confirms 821025 telcon in which Docketing & Svc Granch agreed to add name to svc list, as counsel for ltr-designated Individuals D & VV Related correspondence MCBRIDE, M F. LeBoeuf, Lamb. Leiby & MacRae 82/10/25 Docketing & Services Branch ip 15837 050 24X Fiche 50-289,82/10/25, 22(028038)
- 8210280360 Reply opposing UCS 821007 response to Board Notification 82-93 re Semiscale tests of feed & bleed & motion that AGLB direct NRC to provide documentation Feed & bleed capacity not essential to operation W/Certificate of Svc BAXTER.T A Metropolitan Edison Co BAXTER.T A Shaw, Pittman, Potts & Troubridge. 82/10/25 Atomic Safety and Licensing Board Panel 9pp 15845 146 24X Fiche.50-289,82/10/25,8210280360
- 8210280265 Order allocating time for presentation of oral arguments on immediate effectiveness of ASLB 820727 & 811214 partial initial decisions Issues to be discussed in detail 11sted CHILK: 8 J Office of the Secretary of the Commission 82/10/27 2pp. 15837.312 24X Fiche 50-289.82/10/27.8210280265

1 1

1

- 8210070440 Responds to 820825 itr transmitting constituent JB Hurst 820810 inquiry re restart Changes made as result of reopened proceedings will satisfy conterns DIRCHS.W J Office of the Elecutive Director for Operations 82/09/16 SPECTER.A Senate 4pp 15649 224 24X Fiche \$0-289.82/09/16.8210070440
- --8208010016 Requests response to constituent JR Hurst 820810 inquiries for restart proceedings SPECTER.A Sanate 82/08/25 NRC No Detailed Affiliation Given 5pp 15649 228 24X Fishs 50-289, 82/09/16, 8210070440
- 0210210501 Responds to constituent J Doroshou 020020 ltr re ASLU partial initial decision on cheating TMI Alert Filed exceptions to decision & presented views on restart to Commission DIRCKS, W J Office of the Executive Director for Operations 02709/27 SPECTER, A Senate 9pp 15702 266 24X Fiche 50-209, 82/09/29, 8210210501
- 8210250015 Responds to constituent J Doroshov 820820 ltr re ASLB 820727 partial initial decision Commission is now deciding restart issues DIRCKS.N J Office of the Elecutive Director for Operations 82/09/29 PROXMIRE.N Senate 7pp 15808 128 24X Fiche 50-289.82/09/29.8210250015
- 8210280236 Opines that questions re operator exam cheating must be thoroughly investigated DRADFORD. L. Three Hile Island Alert 82/10/25 PALLADINO.N J. GILINSKY, V. AHCARNE. J.F. Commissioners 2pp 15837-042 24X Fiche 50-289, 82/10/25, 8210280236

### J insurance & indemnity information

- R210150147 Forwards Endorsements 53 & 54 to MAELU Policy MF-73 & Endorsements 61 & 62 to NELIA Policy NF-220 GERETY.H F Oeneral Public Utilities GPU Bervice Corp 82/10/07 SALTZMANJ Antitrust & Economic analysis Branch (Utility Finance) 5pp 1567/359 24X Fiche 50-289.82/10/07.8210150147
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8210090015 Add1 response to FBIA request for 17 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FDIA Exemption 5) FELTON, J M Bivision of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000.82/07/12, 9210080015
- --B2100B0051 Forwards General Public Utils 820407 News Release 45-82 discussing suspected cause of TMT-1 steam generator tube degradation problem & proposed repairs Repairs estimated to be completed by Uct 1982 MAJOR.R ACRE Advisory Committee on Reactor Safeguards 82/04/20 KOELLER.D W ACRE Advisory Committee on Reactor Safeguards 82/04/20 KOELLER.D W ACRE Advisory Committee on Reactor Safeguards 82100B0015
- 8210270410 Summary of ACRS Subcommittee on Metal Components 820407 meeting in Palo Alto.CA re status of Steam Generator owners group program & TMI-; steam generator problems & mods

  \* ACRS Advisory Committee on Reactor Safeguards 82/08/11

  ACRS Advisory Committee on Reactor Safeguards 9pp 15833 268
  244 Fiche 50-289,82/08/11.8210270410

license stage documents & correspondence

& safety evaluation re modered to inadvertent 'Oss of mentation power MICHELSON, C Director's 81/09/04.8210080026

ories of documents re inds documents

12/06/28 UDELL, R. A

ng re reactor water lavel to to util equirements for

ICHELBON.C Director's 1,82/06/28,8210010008

- 8210080015 Addl response to FOIA request for 19 categories of infair nuclear reactor events & safety problems Forwards documents (issed in App A Documents in App B completely withheld traf FOIA Exemption 5)
  FELTON, J M Division of Rules and Records 82/07/12 Utill.R4 Critical Mass Energy Project 9pp 15669-027 24%
  Fiche 50-000,82/07/12:8210080015
- --8204200438 Forwards std order for DDE work "Evaluation of TM1-16'.

  Cenerator Corrosion"

  VOLLMER, R. H. Division of Engineering. FIN D-2505 D2/04/34

  FREMLING, A C Energy. Dept of 2pp 15545, 137 24x

  Ficha 50-000, 82/07/12, 8210080015
- --8204200442 8td order for DDE work: "Evaluation of THI 1 Squar &Fr. Corrosion." issued to DANL VOLLMER.R H Division of Engineering FIN 0-2506 2 82/24: \$ 1p 15665 138 24% Fiche 50-000.82/07/12.8210000015
- --BP04290237 Discusses info available re unit steam generators Tail regists status updates & notehooks of info on tube fabrication, identification & operating history encl H/d encl NGUAK, T H Assistant Director for Licensing 82/04/05 EISENHUT, D O Division of Licensing 2pp 15668 321 241 Fiche 50-000.82/07/12-8210000015
- --8205280533 Recommends formal review of facility steam gamerator corrosion problem. Detailed discussion of rationals for request and JOHNBTON, W V Assistant Director for Materials & Ougastraster Engineering 82/05/19 NOVAK.T Assistant Director for Carr. Reactors 5pp 1565:146 24X Fichs. 50-000, 82/07/12, 822656...
- --B206140329 Discusses facility steam generator tube review Meeting licenses to discuss details of procedures to be followed proposed NRC will develop complimentary independent program intended to verify repair process.

  NOVAK.T M Assistant Director for Operating Meachers D2:03.4
  EISENHUT, D O Division of Licensing 2pp 15665-157 246
  Fichs 50-000,82/07/12,8210080015.
- --8210080091 Forwards std order for DOE work. "Evaluation of tal-jp Generator:" issued to BNNL Period of performance estants to 821015 W/no addition to NRC VOLLHER, R. H. Division of Engineering. FIN 8-2506 M2/22/14 FREMLING, A 0 Energy Dept. of. ip. 15666 150 34% Fiche 50-000, 82/07/12, 8210080015
- --8210080076 8td order for DDE work "Evaluation of TM1 1 % Leas Congrator," issued to BNHL. VOLLMER, R. H. Division of Engineering. FIN 8-2508 7 M7 24.4 ip 19666.181. 24 Fiche: 80-000; 82/07/12, 82100800; 5
- 8210030806 Recommends approval of deferral of implementation Fether NOREO-0737, Items II B G. II F. 1.4 4 II F 1.5 & II F 1.4 4 ALL & 83033 or before restart. Approval of Item II B R 2 should be withheld until review completion.

  DIRCKE, M J. Office of the Executive Director for Specifics 82709/16 Pp 15624 033. 24% Fiche 50-289.88709/16 R1521, A
- --8210050536 Informs that package re facility restart is reat tap Commission for approval of change in NUREO-0737 false [8] become precipitation problem affects conformance w/regulations.deferral amounts to exemption SCINTOL Office of the Executive Legal Director \$2700.74 EISENHUT,D. 9. Division of Licensing App. 15624 043 3a; Fiche: 50-289,82/09/16.8210050506

- --8207050040 Requests NUREC-0737 requirement deferrals be addressed as outlined in Commission 810325 order Paper discusses staff plans for certifying completion of restart requirements on SECY-82-250 & describes approach to be taken on NUREC-0737 PALLADINO.N J Commissioners 82/07/27 DIRCKS,W J Office of the Executive Director for Operations in Available at NRC nrc 15624 048 24X Fiche 50-289.82/09/16.8210050506
- 6210210503 Provides Commission W/status of implementation of NUREO-0737 requirements on TMI-I Recommends deferral of implementation dates for NUREO-0737. Items II B 3.II F 1 4.II F 1 5 & II F 1 6 until 830331 or before restart DIRCKS. U Office of the Executive Director for Operations SECY-82-384 82/09/16 14pp 15782 283 24X Fiche 50-289, 82/09/16, 8210210503
- 82:0050113 Forwards outline of Phase 1 ventilation separation program to meet short-term intent of ASLB G11214 order Program completed & sys turned over to plant operations Further details discussed in restart rept. Suppl 1. Part 2
  HUMILL.H D General Public Utilities ~ GPU Service Corp 92/09/29
  STOLZ.J F Operating Reactors Branch 4 4pp 15603 257 24X
  Fiche 50-209.82/09/29.8210050113
- 6210050196 Forwards table listing 96 emergency feedwater sys/instrument air valves as suppl to 820914 Itr Valves structurally & operationally adequate during SSE stresses & normal loads HUKILL.H D General Public Utilities GPU Service Corp 82/09/29 STGLZ.J F Operating Reactors Branch 4 2pp 15609 292 24X Fiche 50-289.82/09/29.8210050196
- 8210070372 Advises that util has contracted w/Electronic Associates.Inc for basic principles trainer Contracted date of delivery is Dec 1982 HUKILL.H D. General Public Utilities - OPU Bervice Corp. 82/09/29 STOLZ.J F. Operating Reactors Branch 4 Ip. 15693 317 24X Fishe 50~289.82/09/29.8210070372
- 8210120043 Notification of 821013-14 meeting w/PNL.ORNL.Franklin Research Ctr.OH State & util in Bethesda,MD to review status of steam generator recovery program JACOBS.R H Operating Reactors Branch 4 82/09/29 8TDL7.J F Operating Reactors Branch 4 2pp 15689 205 24X Fiche 50-289.82/09/29.8210120043
- 6210/30206 Forwards application to amend License DPR-50 consisting of Tech Spec Change Request 118, deleting App B Tech Specs HUKILL:N D General Public Utilities - GPU Service Corp 82/09/30 STGLZ-J F Operating Reactors Branch 4 1p 15674 127 24X Fichs 50-299, 82/09/30, 82/0130206
- --8210130210 Application to amend License DPR-50 consisting of Toch Spec Change Request 118, deleting App D Tech Specs Justification enci HUKILL, H D General Public Utilities - OPU Service Corp 82/09/30 3pp 15674 128 24X Fiche 50-289, 82/09/30, 8210130206
- 9210060342 Forwards "Assessment of Selected TMI-1 Training Progrems,"
  Vol 1 Rept concludes that util has made significant progress
  in past 3 yrs to expand TMI training capability & to improve
  quality of training programs
  ARNOLD, R C General Public Utilities GPU Bervice Corp 82/10/01,
  DENTON, H R Office of Nuclear Resector Regulation, Director 1p
  15618 020 24X Fiche 50-289,82/10/01,8210060342
- --8210060348 "Assessment of Selected TMI-1 Training Programs," Vol 1 % Data Design Laboratories 82/09/10 301pp 15618 021 24) Fische 50-289,82/10/01.8210060342
- 8210080043 Forwards status rept re procurement & installation of replica simulator.per 820827 mgt piping & instrumentation diagrams Second status rept will be provided in Oct 1983 HUMILL.H D General Public Utilities GPU Service Corp 82/10/04 STOLZ.JF Operating Reactors Branch 4 Jpp 13443 281 24X Fiche 50-289, 82/10/04,8210080043
- 9210080308 Forwards first status rept re procurement & installation of replica simulator for TMI-1.per requirements of Paragraph 583 (3) of 810827 mgt PID Next status rept will be provided in Oct 1983 HUMILL.H D General Public Utilities OPU Service Corp 82/10/04, STOLZ.J F. Operating Reactors Branch 4 3pp 15638-044 24X Fiche 50-269, 82/10/04,8210080308
- 8210130248 Advises of dairy farm located approx i.i miles east of THI yielding dose commitment greater than six of seven present milk sampling stations Results of land census to be included in 830501 annual radiological environ operating rept HUKILLHD General Public Utilities GPU Service Corp 82/10/04, HAYNES, R C Region 1, 0ffice of Director ip 15676 008 24X Fiche 50-289, 82/10/04, 8210130248

- 8210130548 Forwards Revision 1 to "TMI-1 Steam Generator Repair Safety Evaluation," submitted on 820820 as suppl to LER 81-13 Revisions of not affect previous conclusions Revision withheld (ref 100FR2 790) HUKILL, H D General Public Utilities 9PU Service Corp. 82/10/05 EISENHUT.D Q Division of Licensing 1p 15684 195 24X Fiche 50-287, 82/10/05.8210130548
- B210290162 Notification of date change for B21018-19 meetings w/wtil & consultants in Bethesda, MD to discuss results of steam generator repair qualification program, eddy current testing program & RCB cleaning
  JACOBS, R H Operating Reactors Branch 4 82/10/05. BTOLY, J F
  Operating Reactors Branch 4 1p 15876 229 24X
  Fiche 50-289, 82/10/05. B210270162
- 8210270342 Clarifies request for add1 info re TMI Item II B 3, "Post-Accident Sampling Sys"
  STOLZ, J F Operating Reactors Branch 4, 82/10/07 HUKILL, H D
  Oeneral Public Utilities GPU Service Corp Spp 15851 347, 24X
  Fiche 50-289, 82/10/07, 8210270342
- 8210220249 Staff requirements memo re 821006 briefing on status of certification of licensee compliance w/restart requirements CHILK/S J Office of the Secretary of the Commission 82/10/12 Office of the Secretary of the Commission 1p 15786 210 24X Fiche 50-289,82/10/12.8210220249
- 8210250092 Forwards operational GA plan for facilities FIEDLER,P B General Public Utilities - GPU Service Corp 82/10/12 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 15792 265 24X Fiche 50-000, 82/10/12, 8210250092
- --8210250097 Operational GA plan for facilities KAYANAS,N C , LOND,R L , HUKILL,H D Oeneral Public Utilities --GPU Bervice Corp 1000-PLN-7200 01 R00 B2/09/01 150pp 15792 267 24X Fiche 50-000, B2/10/12.8210250092
- 8210270015 Forwards documents to be placed in PDR. Documents respond to NRDC & Sierra Club 820917 third request for production of documents & Sierra Club 27th set of interrogatories, SHEEMEY, M.F. Office of the Executive Legal Director 82/10/22 SCOTT, S. Document Management Branch 4pp, 15818 092 24X Fiche 50-000, 82/10/22, 8210270015
- --8210270020 "Greater Commitment Needed to Solve Continuing Problems At TMI," rept to Congress
  \* General Accounting Office. EMD-81-106 81/08/26 122pp
  13818-076 24X Fichs: 50-000, 82/10/22: 8210270015
- 8210270204 Forwards summary status rept for items needing NRC certification prior to restart, per 770807 order & notice of hearing. Date of equivalent timing for verification will be provided in future status summaries
  ARNOLD, R C General Public Utilities QPU Service Corp 82/10/25
  DENTON, H R Office of Nuclear Reactor Regulation, Director 3pg 15853 273 24X Fichs 30-289, 82/10/25,8210270204
- Q Inspection reports. IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of info re

- ~-8210150232 IE Insp Rept 50-289/82-13 on 820802-05.31 & 0901-03 No noncompliance noted Major areas inspected actions on previous insp findings, reactor bldg flood level limitations, plant shielding design review & restart mode-implementation HAVERKAHP.D., EAPEN,P., FASANO, A. Division of Project & Resident Programs 82/10/01 20pp 15705 214 24% Fiche 50-287,82/10/01, 9210150221
- 6210150202 Clarifies position re Action 4 of IE Bulletin 77-21, "Temp Effects on Level Measurements" Inclusion of tables curves or correction factors in swergency procedures will unnecessarily complicate procedures HUKILL.H D General Public Utilities QPU Service Corp 82/10/04 HANNES.R.C. Region 1, Office of Director 2pp 15701 334, 24% Fiche 50-289, 82/10/04.8210150202
- 82:0150076 Notifies that 820727 IE Insp Rept 50-289/82-14 was submitted w/srroneous insp Rept Number 82-12 STAROSTECKIR Division of Project & Resident Programs 82/10/05 HUKILL,H D General Public Utilities GPV Service Corp 15696 337 24% Fiche, 50-289, 82/10/05, 82:0150076
- --8210150083 Forwards IE Insp Rept 50-289/82-14 on 820807-0907 No noncompliance noted.
  STAROSTECKI. Bivision of Project & Resident Programs 82/09/29 HUKILL.H D. Ceneral Public Utilities GPU Service Corp 2pp 18696 340 24X Fiche: 50-289, 82/10/05.8210150076
- ~~8210150091 IE Insp Rept 50~289/82~14 on 820807~0907 No noncompliance noted Hajor areas inspected plant operation, including steam generator repairs & restart mods CONTE.R. YQUNO.F. FABANO.A Division of Project & Resident Programs 82/09/21 opp 15696 342 24X Fichs 50~289.82/10/05, 8210150076
- B210210052 Forwards IE Insp Rept 50-269/82-16 on B20907-10 No noncompliance noted MARTIN-T T Division of Engineering & Technical Programs 82/10/05 HUKLLL-K D General Public Utilities - QPU Service Corp 15762 018 24% Fiche: 50-289.B2/10/05:8210210052
- --8210210056 IE Insp Rept 50-289/82-16 on 820707-10 No nancompliance noted Major areas inspected licenses action re TMI Item I C 7 on feedback of operating experience k Item I C 6 on verification of teeting k maint activities

  MEYER: 0 W : CAPHYON. D. L Division of Engineering & Technical Programs 82/07/27 App 15762 020 R4X Fiche 50-287, 02/10/05, 8210210052
- 8208190233 IE Info Notice 80-35. Suppl I, "Leaking & Dielodged I-125 Implant Beeds," Svc list encl.
  COBS.L I Division of Fuel Facilities, Materials & Bafequards 82/10/06 Consolidated Edison Co of New York 66pp 15761, 250, 24K Fiche 50-000, 82/10/06, 8208190233
- 9208170238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Stepl, Recirculation SysPiping at BWR Plants "Sve list encl OEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/10/14, Consolidated Edison Co of New York, 115pp 18810-125 24% Fiche 50-000, 82/10/14, 8208170238
- 9210290068 Forwards IE Insp Rept 50-287/82-18 on 820720-24 No noncompliance noted.

  MARTINIT T. Division of Engineering & Technical Programs. 82/10/15

  HOWILL, H D. General Public Utilities QPU Service Corp 15853, 342, 24% Fiche 50-287,82/10/15,8210290068
- --8210290072 IE Insp Rept 50-287/82-18 on 820920-24 No noncompliance noted Major areas inspected licenses action on previous insp items. procedures & representative records & interviews w/personnel BHAU88.5: NAPUDA, Q. CAPHTON, D.L. Bivision of Engineering & Technical Programs 82/10/08 10pp 15853 344 24% Fiche 50-289,82/10/15,8210290068

# R Periodic operating reports & related correspondence

8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines. App A documents provided in R Udell FOIA Request 81-013. Forwards documents listed in App B FELTON, J M. Division of Rules and Records 82/08/10. LONO. D J. Hinthrap. Stimpon, Putham & Roberts. 9pp 15645:060 24X

- --8210070135 Sevil rept input re Ginna 820125 steam generator til; rupture event NRC 16th monthly status rept to Congress re TMC-1 restart encl 4 NRC - No Detailed Affiliation Given 82/03/11 3pp 15645 128 24X Fiche 50-000, 82/08/10,8210070007
- 8210260499 Forwards Revision 1 to "Effluent & Waste Disposal Semiannual Rept. Jan-June 1982" Revision reflects change in Fe-55 batch mode for second quarter HUXILL. H D. General Public Utilities ~ GPU Service Corp. 62/Jr HAYKES: R C. Region I. Office of Director 19 18804 135 24; Fiche 50-289, 82/10/15, 8210260499
- --8210260505 Revision i to "Effluent & Heste Disposal Semiannus) t<sub>r.</sub>
  Jan-June 1982 "

  \* General Public Utilities GPU Service Corp B2/10/15 []
  15806 137 24X Fiche \$0-289,82/10/15,8210260499
- S Reportable occurrences, LERs & related correspondence
- B210010008 Responds to FDIA request for 19 categories of documents nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/20 UNEIL, 8, Chitical Mass Energy Project 15pp 15727 OOS 24X Fichs 50-000, 82/06/28, 8210010008
- --BilliBOOO! Recommends comprehensive assessment of plant operations to determine specific predetermined time related sequences of occurrence to emergency buses SRP should be revised re design features

  ASHE.F. Director's Office. Bi/10/16 MICHELSON.C. Direct.

  Office 4pp 15731 047 24X Fiche 50-000.82/06/28.828086.
- 8210130515 Forwards LER 82-013/03L-0 HUMILL,H D General Public Utilities - QPU Service Corp 82.; HAYNES,R C Region 1, Office of Director ip 13682 276 24 Fiche 50-289, 82/07/29,8210130915
- --8210130526 LER 82-013/03L-0 on 820830, plant effluent radiative (RM-L-7) had no sample flow Caused by open breaker on sample pump BR-P-4 Breaker closed Operator surveillance progres continued to ensure progre flow STEPHENSON, C.J. General Public Utilities OPU Service Corp. 82/09/29 Region 1, Défice of Director 2pp 15602 277 Fiche, 50-289, 82/09/29, 8210130315
- B210070245 PND-TMI-B2-020 on B21005, game positive apprehended at property & turned over to state police & Came Commission No vital areas threatened Security increased Licensee will issue press release HIEBE, J., BELLAMY, R. Region 1. Office of Director B2/10/05, 15634 306 24% Fiche 50-289, 82/10/06, 8210070265
- 82/02/20483 PNO-1-82-047 on 82/022, kinetic expansion conducted at rows of tubes in B ance-through steam generator Espansion involves controlled detonation within tube Some media attention expected CONTE.R., WEINIO.R., BTARDSTECKI.R. Region 1. Diffice of Disa 82/10/22 1p. 15806 232 24X Fichs 50-289,82/10/22,821026
- T Hearing transcripts on non-antitrust matters
- 9210130075 Porwards Commission determination statement withhelf transcript of 820910 restart proceeding CHILK, 8 J Office of the Secretary of the Commission. 82/07 Public Document Branch ip 15696 250. 24X Fiche 50-289.6
- ~-8210130087 Commission determination withholding transcript of Commission 820910 discussion of contested issues in restriction of the Commission BP CHILK, B J Office of the Secretary of the Commission BP 15676: 251 24X Fiche 50-289, 82/09/28, 8210430075
- 8210270188 Transcript of 821006 public meeting re status of Alcertification on licensee compliance w/restart requirement on THI-1 in Washington.0C.Pp.1-34 Commissioners 82/10/06 34pp 15838 276 24x Fiche. 50-289, 82/10/06, 8210270188,
- 8210210428 Forwards transcript of Commission 821014 meeting transcript of Commission 821014 meeting transcript of the Secretary of the Commission 62101 CHILK: 8 J. Office of the Secretary of the Commission 6210fice of the Executive Legal Director, 1p. 15762 272 1 Fiche. 50-287: 82/10/15:8210210428

### DOCKETED ITEMS

- E2[02]0434 Transcript of 82[014 public meeting in Washington, Dc Pp |-9| Viewgraphs re request for NRC approval of recommendations for implementation of NUREG-0737, Item II F 2 encl # Commissioners 82/10/14 91pp 15762 273 24X Fishe 50-269,82/10/15 8210210428
- 5 LVET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT 1
- P Operating license stage documents A correspondence
- E-1008C015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & sarety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON J H Division of Rules and Records 82/07/12 UDELL R A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000 82/07/12.8210080015
- 2203290028 Forwards "Engineering Evaluation of Salt Svc Water Sys Flow Blockage at Pilgrim Nuclear Power Station by Blue Mussels (Mytrius Edilus) "Further recommendations re sys fauling by aquatic organisms not needed IMMRO.E V Director's Office 82/03/18 MICHELSON, C Director's Office 2pp 15666-073 24X Fiche 50-000,82/07/12,8210080015
- --RP03290031 Engineering Evaluation of Salt Svc Water Sys Flow Blockage at Pilgrim Woclear Power Station by Blue Mussels (Mytilus Editus) " IMBRO.E ("Director's Office 82/03/31 14pp 15666-075 24X Fiche 50-000.82/07/12.8210080015
- --B205130114 Advises that engineering evaluation of saltwater sys flow blockage by blue mussels indicates surveillance requirements in Tech Specs are not sufficient to demonstrate sys operability "11CHELSON.C Director's Office 82/05/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 15666 070 24X Fiche 50~000,82/07/12.8210080015
- PALICOGOOBO Application for Proposed Change 82-11 to License DPR-35, changing Tech Specs 3.7 D.1 & 3.7 D.2 to permit operation in 4 between reactor modes when isolation valve is inoperable MARRIMGTON W.D. Boston Edison Co. 82/09/30 VASSALLO, D.B. Operabing Reactors Branch 2. 2pp. 15615-044. 24X Fiche 50-273, 82/09/30,821006080
- --0210060005 Proposed changes to Tech Specs 3 7 D 1 % 3 7 D 2 allowing aperation in % between reactor mode when isolation valve is inoperable % satisfying conditions for primary containment integrity

  # Beston Edison Co 82/09/30 ip 15615 046 24X
  Fiche 50-293.82/09/30.8210060080
- GalO150444 Requests extension to submit Mark I containment program plant-unique analysis Delay due to need for extensive GA verification not proviously identified by Teledyne Corp MCRISI.A V Boston Edison Co. 82/10/03 VASSALLO, D. B. Operating Reactors Branch 2 lp 15705 005 24X Fiche 50-293.82/10/08, BEIO150444
- 6210220015 Concurs w/LLL evaluation of util 820617 submittal redegraded protection for Class IE power sys Mods, procedures, aperating restrictions & voltage schedules will ensure that Class IE equipment will not be exposed to degraded voltage vASSALLO.D B Operating Reactors Branch 2 82/10/08 MORISI.A V Boston Edison Co 2pp 15786 226 24X Fiche 50-273,82/10/08,8210720015
- --8210220017 Safety evaluation supporting licensee conclusion that add1 protection not required for unit auxiliary transformer power source to Class IE buses PREVATTE.R Operating Reactors Branch 2 82/10/08 4pp 15786 228 24X Fiche 50-293, 82/10/08, 8210220015
- --B209130461 "Technical Evaluation Rept (Revision I) on Proposed Design Mods 5 Tech Spec Changes on Orid Voltage Degradation for Pilgrim Nuclear Power Station, Unit I "

  SELANG J C Lawrence Livermore Laboratory FIN A-0250 UCID-18689 R01 B2/08/20 NRC No Detailed Affiliation Qiven 13pp 15786 232 24% Fichs 50-293, 82/10/08.8210220015
- 8210250085 Forwards filing fee for 820930 proposed Tech Spec Change 82-11 MCRISI, A V Boston Edison Co 82/10/15 VASSALLO, D B Operating Reactors Branch 2 1p 15787 075 24X Fiche 50-293,82/10/15, 8210280085

- @ Inspection reports. IE Bulletins & correspondence
- 8204160212 Responds to MRC 820118 notice of violation & proposed imposition of civil penalties Corrective actions containment atmospheric control sys made fully operable on 810605 & procedure re performance of analyses being reviewed STASZESKY.F M Boston Edison Co 82/03/19 DEYBUNG.R C Director's Office. Office of Inspection and Enforcement lipp 15611 275 24X Fiche 50-293,82/03/17,8204160212
- ---B204160222 Forwards performance improvement program in response to NRC 820118 order modifying license, effective immediately Program details 18 to 24-month period that will result in demonstrated effective regulatory performance HARRINGTON H D Boston Edison Co 82/03/18 HAYNES, R C Region 1, Office of Director 3pp 15611 284 24% Fiche 50-273, 82/03/19,8204160212
- --8204160225 "Performance Improvement Plan " # Boston Edison Co 82/03/08 16pp 15611 287 24) Fiche 50-273,82/03/19,8204160212
- 8210080015 Add1 response to FQIA request for 17 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FQIA Exemption 5) FELTON, J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24% Fiche 50~000, 82/07/12,8210080015
- --82100BD145 By stematic assessment of licensee performance notes re facility evaluation for Aug-Dec 1980 4 NRC - No Detailed Affiliation Oiven 80/12/31 10pp 15648 025 24% Fiche 50-000.82/07/12,82100B0015
- 8210070277 Forwards IE Insp Rept 50-293/82-23 on 820817-20 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/09/22 HARRINGTON.Y D Boston Edison Co 2pp 15634 162 24X Fiche 50-293,82/09/22,8210070277
- --8210070283 IE Insp Rept 50-293/82-23 on 820817-20 No moncompliance nobed Major areas inspected licensee action on provious insp finding, followup on IE Bulletin 81-01, surveyllance of mechanical snubbers & Cycle 6 post-refueling startup tests PETRONE, C D . BETTENHAUSEN, L Region 1, Office of Director 82/09/09 7pp 15634 164 24X Fiche 50-293 82/09/22, 8210070277
- 8210010372 Confirms licensee actions taken in response to Revision 1 of performance improvement program discussed during 920824 mgt meeting Summary of areas needing clarification or corrections enc!
  HAYNES.R C Region 1. Office of Director 82/07/27
  HARRINGTON.H D Boston Edison Co 3pp 15573 087 24X
  Fiche 50-293.82/07/27.8210010372
- 8210150001 Forwards IE Insp Rept 50~293/82-22 on 820802-0906 & notice of violation STAROSTECKI,R Division of Project & Resident Programs 82/09/28 HARRINGTON, N P Boston Edison Co 2pp 15696 285 24X Fiche 50-293, 82/09/28, 8210150001
- --8210150003 Notice of violation from insp on 820802-0706
  \* Division of Project & Resident Programs 82/07/28 2pp
  15676 287 24X Fiche 50-273,82/07/28,8210150001
- --8210150017 IE Insp Rept 50-273/82-22 on 820802-0906 Nencompliance noted failure to notify NRC within 1-h of reactor scram & to perform leak rate test required by limiting conditions for operation for inoperable alarm sys JOHNSON J. EICHENHOLZ.H. ELBASSER.T Division of Project & Resident Programs 82/09/22 20pp 19696 287 24X Fiche 50-293,82/09/28,8210150001
- 8210050166 Forwards response to request for further info re IE Bulletin 80-11 "Masonry Wall Design " Issues discussed include shear stress for safety-related shear walls, block pullouts, use of Branson formula, masonry wall cracks to allowable tension MORISI.A V Boston Edison Co 82/09/29 VASSALLO, D B Operating Reactors Branch 2 Gpp 15605 114. 24% Fiche 50-293, 82/09/29, 8210050166
- 8210060150 Ack receipt of 920806 & 27 ltrs informing NRC of steps taken to correct violations noted in IE Imap Rept 50-293/82-12 STAROSTECKI.R Division of Project & Resident Programs, 82/09/30 HARRINGTON W D. Boston Edison Co ip 15615 081 24X Fiche 50-293, 82/09/30, 8210060150

- --8210060164 Responds to NRC 820707 ltr re-violations noted in 1E Insp. Rept 50-293/82-12 Corrective actions draft training plan written, interin administrative controls re-Tech Specs implemented & operator requalification program revised HARRINGTON: ID Boston Edison Co 82/08/27 STARGSTECKI. R Division of Project & Resident Programs 2pp 15615-082 24X Fiche S0-293, 82/09/30. 8210060150
- --8210060180 Responds to NRC 820707 ltm re violations noted in IE lusp Rept 50-293/82-12 Corrective actions add1 operator training implemented & reactor water level divergence issue incorporated into operator requalification program HARRINGTON, H D Boston Edison Co 82/08/06 STARDSTECKI, R Division of Project & Resident Programs 4pp 15615 084 24X Fiche 50-293.82/09/30.8210060150
- 8210220521 Notification of 821005 meeting w/sti) in King of Prussia.PA to discuss licensee response to NRC order ELSASSER,T Division of Project & Resident Programs 82/09/30 DIRCKS.N J Office of the Executive Director for Operations DEYOUND.R C Director's Office, Office of Inspection and Enforcement MURRAY.JP Office of the Executive Legal Director is 15/86 076 24% Fiche 50-293.82/09/30.8210220321
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Distodged 1-125 Implant Seeds " Svc list and COBB.L I Division of Fuel Facilities, Materials & Gafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000, 82/10/06,8208170233
- 8210190721 Completes response to 1E Bulletin 30-06, "ESF Reset Controls " Review of actions taken in compliance w/bulletin revealed deficiencies in Temporary Procedure 81-6A re valve testing New test procedures developed MCRIBI. A V Boston Edison Co 82/10/07 MAYNES.R C Region 1. Defice of Director 2pp 15736 310 24X Fiche 50-293,82/10/07,921019721
- 8210290275 Porwards IE Insp Rept 50-293/82-25 on 820914-17 No moncompliance noted MARTIN: T T Division of Engineering & Technical Programs 82/10/13 HARRINGTON W D Boston Edison Co 2pp 15894 059 24X Fiche 50-293, 82/10/13, 8210290275
- --8210290280 IE Insp Rept 50-293/82-25 on 820914-17 No noncompliance noted Major areas inspected inservice insp program & drawing control.licenses action on previous insp findings & licenses response to IE builetins

  KCBRCARTY,R A , BURR.J P Division of Engineering & Technical Programs 82/10/05 App 15854-061 24X Fiche 50-293.82/10/13.8210290275
- 8208170238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diemeter: Stainless Steel, Rocircutation Sys Piging at BUR Plants" Svc list enc! BEYOUNG.R C Director's Office. Office of Inspection and BEYOUNG.R C Consolidated Edison Co. of New York 115pp 19810 125 24% Fichs 50-000. 82/10/14,8208170238
- 8 Reportable occurrences, LERs & related correspondence
- 8210120155 Informs of adequacy of Graft IE info notice. "Potential failure of BMR Backup Manual Scram Capability" initiated by NRR. IE & GE subsequent to 800829 LER 80-038/017-0 CHIRANAL-M Director's Office 80/12/18 Director's Office lp 15692.179 24% Fiche 50-293,80/12/18,8210120155
- --8210120164 Forwards draft IE info notice: "Potential Failure of DWR Backup Manual Stram Capability." per 801208 meeting agreement LAINAS, C.C. Assistant Director for Safety Assessment 80/12/15 URDAM, E.L. Division of Resident & Regional Reactor Inspection 4pp 15692 180 241 Fichs 50-293.80/12/18.8210120135
- 8210040100 Forwards LER 82-037/03L-0
  MATHIS, C J Boston Edison Co 82/09/22 HAYNES, R C Region 1,
  Defice of Director 1p 15580 354 24% Fiche 50-293, 82/09/22,
  8210040100
- --8210040105 LER 82-037/03L-0 pn 820823, three monthly functional surveillances performed in slight excess of allowable 25% tolerance Caused by personnel oversight Senior lavel compliance review implemented Proposed test aids planned. HHITNEY, 0 0. Boston Edison Co. 82/09/22 Region 1, Diffice of Director 20p 15580:355 24% Ficha.50-293.82/09/22,6210040100
- 8210060023 Forwards LER 82-034/03L-0
  MATHIB.C J. Boston Edison Co. 82/09/24 MAYNES, R C Region & Diffice of Director in 18415 072 24X Fiche 50-293, 82/09/24, 821006023

- --B210060030 LER B2-034/03L-0 on B20826, both HPCI area smale delector systaken out of svc for corrective maint Maint required due to maisture from steam leak condensing inside detectors causing false smoke indication Detectors replaced 2 tostes LHITMEY.O G Boston Edison Co B2/07/24 Region 1, 01/14e c4 Director ip 15615 0/3 24X Fiche 50-293,82/09/24,82/09/24.
- --8210070247 LER 62-036/03L 0 on 820903.during 75% power, main stratti, flow indicator B went to 0 % three other steam flows increased Gause suspected to be valve stem separation flow paper Valve repair plan will be implemented after outage wiff They, 0 g Boston Edison Co 82/09/29 Region 1, Office 4 Director 1p 15637 143 24% Tiche 50-293,822097.29.891003.cu
- 8210070340 Forward's LER 82-035/03L-0

  HATHIS.C J Boston Edison Co 82/09/29 HAYNES.R C Region 1

  Office of Director ip 15634 066 24% Fichs 50-29 1 8/09/27,

  8210070340
- --8210070346 LER 82-035/03L-0 np. 820830, during HPC1 surveillance (ed. gland seal condensor gasket failed Caused by overpressure of gasket during startup Gasket mati changed to rubber bonds) asbestor Unit tested 5 returned to svc (HITMEY, 0.6 Boston Edison Co. 82/09/29 Region 1, 041.0 p. Director ip 15634 067 24X Fiche 50-293, 82/09/29 (H/Cu7uJh)
- 8210130472 Forwards updated LER 82-003/79X-1 MATHIS.C J Boston Edison Co 82/09/30 HAYNES/R C Region 1, Office of Director ip 15682 132 24X Fiche 50 -071/81/09/33 8210130472
- --8210130479 Updated LER 82-003/99X-1 on 820901.util organisation revised Tech Specs being reviewed for submittal to MAL Updated reorganization chart and MALTNEY.0 0 Boston Edison Co. 82/09/30 Region 1. 0ffice .1 Director 3pp 15682 133 24X Fiche 50-293.82/09/30 82801 MARY:
- 8210190235 Forwards updated LER 82-0.44/03X-1 MATHIS,C J Boston Edison Co 82/10/01 HAYNES,R C Region I B#ffce of Director 1p 15737 239 24X fiche 90-494.32/10/01 8210190235
- 8210280129 Forwards LER 82-039/03L-0

  MATHIS.C J Boston Edison Co 82/10/20 HAYNES.R C 89930n J

  Office of Director ip 15837 117 24X Fiche 50-294.(12/10/2-1
- --8210280131 LRR 82-039/03L-0 on 820720, timing tests of three featings received the cleanup isolation valves 1201-2:-5 % -80 not completed within allowed time Caused by operational constraints requiring testing at reduced power WHITNEY, 0 9 Boston Edison Co 82/10/20 Region J. (Heris Parector 2pp 1583/118 24X Fiche 50-293, 61/10/20, 84/618/13
- 8210280146 Forwards LER 82-040/03L-0
  MATHIS.C J Boston Edison Co 82/10/20 HAYNES.R C Region 1
  Office of Director 1p 15837 225 24X Fiche 50-293.82/10/a\*
- --8210280150 LER 82-040/03L-0 on 820920, found reactor protection is initiation function of turbine stop valve completed | Jay | late Caused by decision to defer that due to MBIV D intrinsicial information Tracking sys implemented to prevent recurrents | MMITMEY, 0 Q Boston Edison Co. 82/10/20 Region | Office Director 1 p 15837 226 24X Fiche 30-293, 82/10/20, 821828014
- POSKET 50-295 ZION NUCLEAR POWER STATION. UNIT 1

  F Security, medical, emergency & fire protection plans
- 8209290125 Releases public version of revised generating status energency plan corporate command ctr emergency plan implementing procedure FELTON-J M Division of Rules and Records 92/09/16 Detailed Hanagement Branch, ip 15564 122 24X Fiche 50-000.82/09/18.8209290125

- --B209270187 Forwards public version of Revision 4 to generating station emergency plan corporate command ctr Emergency Plan inplementing Procedure EOF-3. "Environ/Emergency Coordinator" Receipt form encl PAJOMSKI.J E Commonwealth Edison Co B2/07/01 DENTON, H R NRC No Detailed Affiliation Given 1p 15364 123 24% Fichs 50-000, B2/09/16, 8209270125
- --8209290225 Public version of Revision 4 to generating station emergency plan corporate command ctr Emergency Plan Implementing Procedure EUF-3: "Environ/Emergency Coordinator"

  PAJDHEKI.J E Commonwealth Edison Co 82/08/31 11pp 1554 124 24X Fiche 50-000, 82/09/16, 8209290125
- E210080029 Releases public version of revision to emergency plan implementing procedure FELTON.J M Division of Rules and Records 82/09/22 Document Management Branch 1p 15669 307 24X Fiche 50-295,82/09/22,8210080029
- --8210080030 Forwards public version of Revision 3 to Emergency Plan Implementing Procedure EPIP 550-3, "Radiological Supplies for Medical Emergencies" Receipt form encl PLIML.G Commonwealth Edison Co 82/09/07 DENTON, H R NRC No Detailed Affiliation Given ip 15669 308 24X Fiche 50-295,82/09/22,8210080029
- --8210080031 Public version of Revision 3 to Emergency Plan Implementing Procedure EPIP 550-3, "Radiological Supplies for Medical Emergencies" Procedure change request form encl a Commonwealth Edison Co 82/09/03 Opp 15669 309 24X Fiche 50-295.82/09/22.8210080029
- B210050207 Forwards revised exemption requests from provisions of 10CFR50. App R. Section III 0.2 re post-fire shutdown capability.per 820917 telicon LENTINE.F 0 Commonwealth Edison Co 82/10/01 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 30pp 15611.086 24X Fiche 50-295,82/10/01.8210050207
- 8210130376 Advises that installation of offsite dose calculation sysprogram fully operational tracking model & operational Amodel will be delayed until 821231 to complete prime computer installation SMARTZ.E D Commonwealth Edison Co 82/10/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15682 098, 24X Fiche 50-000, 82/10/06, 8210130376
- 9210290047 Releases public version of revisions to Quad Cities, Zion & Bresden emergency plan annexes & revised generating station emergency plan telephone directory FELTON. J M Division of Rules and Records 82/10/08 Document Management Branch 1p 19877 313 24X Fiche 50-000, 82/10/08, 82/10290047
- --BRIO270060 Forwards public version of Revision 3 to Quad Cities & Zinn emergency plan annexes.Revision 2 to Dresden emergency plan annexes.Revision 0 to Byron emergency plan annex & revised generating station emergency plan telephone directory MUDRE.R D Commonwealth Edison Co 82/07/30 DENTUN.H R NRC No Detailed Affiliation Given 5pp 15877 314 24% Fiche 50-000.82/10/08.8210290047
- ---8210290077 Public version of Revision 3 to Guad Cities & Zion emergency plan annexes. Revision 2 to Dresden emergency plan annex & Revision 0 to Byron emergency plan annex & Commonwealth Edison Co. 82/06/30 325pp 15877 319. 24X Fiche 50-000, 82/10/88, 8210270047
- --8210290088 Public version of revised generating station emergency plan telephone directory GALLE-D P Commonwealth Edison Co 82/08/12 43pp 15878 218 24% Fiche 50-000, 82/10/08,8210290047
- 8210280117 Releases public version of revised emergency plan implementing procedure. FELTON-J M Division of Rules and Records 82/10/12 Document Management Branch 1p 15862 241 24X Fiche 50-275,82/10/12, 8210280117
- --B210280120 Forwards public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 150-1, "Btores Director" Receipt form encl. PLIML 0 Commonwealth Edison Co 82/09/17, DENTON, H, NRC - No Detailed Affiliation Given ip 18862 242 24X Fiche 50-275,82/10/12.821028017

- 8210280419 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 82/10/12 Document Management Branch Ip 15860 001 24X Fiche 50-295.82/10/12.8210280419
- --B210280424 Forwards public version of Revision 5 to Emergency Plan Implementing Procedure 110-1, "Station Director "Procedure change request & receipt forms encl PLIML, G Commonwealth Edison Co B2/09/17 DENTON, H R NRC - No Detailed Affiliation Given 2pp 15860 002 24X Fiche 50-295, 82/10/12, 82102800419
- --8210280427 Public version of Revision 5 to Emergency Plan Implementing Procedure 110-1, "Station Director" Revised index encl \* Commonwealth Edison Co 82/09/16 9pp 15860 004. 24X Fiche 50-295,82/10/12,8210280419
- B210280442 Releases public version of revised emergency plan implementing procedure FELTON.JM Division of Rules and Records B2/10/12 Document Management Branch ip 15899 001 24X Fiche 50-275,82/10/12,8210280442
- --B210280445 Forwards public version of Revision 4 to Emergency Plan Implementing Procedure EPIP 530-2, "Environ Emergency Wit & Emergency Operations Facility Radiological Equipment" Receipt form and PLTML-0 Commonwealth Edison Co B2/09/10 DENTON, H R NRC No Detailed Affiliation Qiven in 15859 002 24X Fiche 50-295, 82/10/12, 8210280442
- --8210280447 Public version of Revision 4 to Emergency Plan Implementing Procedure EPIP 550-2, "Environ Emergency Kit & Emergency Operations Facility Radiological Equipment " Procedure change request form encl # Commonwealth Edison Co 82/09/03 App 15859 003 24X Fiche 50-295,82/10/12,8210280442
- 8210220358 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1782 to improve health physics training programs
  TRAMM.T R Commonwealth Edison Co 82/10/14 DENTON.H R Defice of Nuclear Reactor Regulation, Director 7pp 15776 287, 24% Fiche 50-000, 82/10/14, 210220358
- 8210280405 Notification of 821028-29 meetings w/util & BNL in Bethewda, MD to discuss & resolve questions on proposed exemption to App R WIOQINTON D Operating Reactors Branch 1 82/10/22, VARQA, B, A. Operating Reactors Branch 1. 2pp 15859, 327 24X Fiche 50-295, 82/10/22, 8210280405

# H General correspondence

- B210210235 Comments on facility operation NRC should deny util permission to use high burnup nuclear fuel Evidence supporting continued operation of facility should be provided to public GUIGO. C Pollution & Environmental Problems. Inc B2/10/11. Director's Office, Office of Inspection and Enforcement Spp 15746 259. 24x Fichs 50-295. B2/10/11. B210210235
- J Insurance & indemnity information
- B210040283 Forwards Endorsements 60 % 51 to NELIA Policy NF-201 & MAELU Policy MF-64; respectively OSTER, J. Commonwealth Edison Co. 82/10/01 BALTZMAN, J. Assistant Director for State & Licenses Relations. 3pp 15621.07d. 24X Fiche: 50-295, 82/10/01.8210040283
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8210270408 Comments on probabilistic risk assessment per 811221 mat1. General methods & principles employed in analysis of possible earthquake shaking & site appear to apply modern state of art techniques.

  TRIFUNAC.M D Bouthern California. Univ. of. TRIFUNAC.M.D. ACR8 Advisory Committee on Reactor Safeguards 82/02/23 QRIEBMEYER.J M. ACR8 Advisory Committee on Reactor Safeguards 3pp. 15832,353,24X Fiche. 30-295,82/02/23,8210270408
- P Operating license stage documents & correspondence
- 8007150303 Notifies that review will be conducted of Offshore Power Sysshort-term risk studies using various resources in response to 800605 request Evaluation will be submitted by 800922 MATTSON, R. J. Division of Safety Technology 80/07/02 EISENHUT, D O. Division of Licensing 2pp 02952:301, 24X Fiche 50-247, 80/07/02, 80/07130303

- BOOB130744 Summery of 800617 meeting w/utils in Bethesda. HD re containment structural response to core melt accident
  - sequences HEYERJ F Power Systems Branch 80/07/31 Power Systems Branch 3pp 03266 243 24% Fichs 30-247.80/07/31.8008130744
- 8007100100 Forwards recommendations on staff task action plan to be sent to licensess for review & response. BARRETTL H Operating Reactors Assessment Branch 80/08/08 VAROA.S A Operating Reactors Branch 1 (Pre 800428) Bpp 03516 066 24X Fiche 50-247.80/08/08/09/100100
- 8D09250234 Submits description of work being done on analysis of releases from facilities. Bimple I-D multicompartment thermal hydraulic code being written to analyse variety of FVCS designs Related data ent. FENSIERNACHER Reactor Systems Branch 80/09/10 SPEIS, T P Reactor Systems Branch 80/09/10 SPEIS, T P Reactor Systems Branch 4pp 03589 257 24X Fiche 50-247,80/09/10,8009250234
- 8010220234 Responds to 800917 request re control room review NRC 800507 ltr detailed five additions to near-term OL requirements from III D S 4 requires enalysis of control room habitability by 810101 HOUSTON, R W. Accident Evaluation Branch 80/09/25 VARCA, S A Operating Reactors Branch I 1p 03560 001 24X Fichs 50-247, 80/09/25,8010220234
- 8010210036 Discusses SEP Branch review of mys environ qualification of safety-related electrical equipment for II SEP plants MCKENNALE M Systematic Evaluation Program Branch 80/09/30 LAINAS, G C Division of Licensing 2pp 03647 289 24X Fichs, 50-003, 80/09/30, 8010210036
- 8011110084 Requests Instrumentation & Control Sys Branch systuation of util responses to questions re incore instrumentation tubes at facilities Info will sid branch evaluation mitigation features re backfitting of severe mitigation features SPEIS.T P Reactor Systems Branch 80/10/09 SATTERFIELD.R Instrumentation & Control Systems Branch ip 02227 001 24X Fiche 30-247.80/10/09.8011110084
- 80;0280098 Forwards NRC questions & util answers re backfitting of severa accident mitigation features Evaluation needed in two wks SPEIS, T.P. Reactor Systems Branch 80/10/17 SCHAVER, F.P. Structural Engineering Branch ip 65767 184 24X Fiche 30-247, 80/10/17, 80(0200098
- 82;0070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON.J M Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson, Putnem & Roberts 9pp 15645-063 24X Fichs 50-000, 82/08/10, 8210070007
- --B203110403 Forwards response to JD Dumelerchairman of Pollution Control Board, State of IL questions in 820127 ltr JOHNSTON, H.V. Assistant Director for Materials & Qualifications Engineering 82/02/22 LAIMAS, Q. Assistant Director for Safety Assessment 2pp 15645, 126 24X Fiche 50-000, 82/08/10, 8210070007
- 8209160503 Buppls 820831 ltr rs 820908 meeting at Region 3 ofc Recent operation of Unit 2 w/two inoperates auxiliary feedwater pumps added to agenda KEFPLER, J. G. Region 3, Office of Director. 82/09/03 REED, C Commonwealth Edison Co ip 14904:087 24X Fiche 50-295,82/09/03, 8209160503
- 8210040218 Requests reaffirmation of technical basis for operation at 100% power Bignificant financial penalties incurred due to operation in overly conservative manner.

  STIEDE. M.L. Commonwealth Edison Co. 82/09/27 DEYOUNO, R.C. Director's Office, Office of Inspection and Enforcement 3pp 15583 115. 24% Fiche 50-295,82/09/27,8210040218
- 8210050270 Forwards wingle Class III amend fee for proposed change to License DPR-39 LENTING.F. G. Commonwealth Edison Co 82/09/27, DENTON.H R Office of Nuclear Reactor Regulation, Director ip 15409:186, 24X Fiche 50-295, 82/09/27, 8210050270.

- 0210120105 Requests delay of implementation due dates re MURED 17,"

  Items II B 2. "Plant Shielding." II B 3. "Post-Accident
  Sampling" & II F 1 1. "Noble Oas Effluent Monitor "
  SHARTZE D Commonwealth Edison Co 82/10/04 E[GENHUT.D 0
  Davision of Licensing 5pp 15451 237 24X Fiche 50-003.82/11, 8210120105
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Date Calculation Hanual Topic Commonwealth Edison Co 82/10/06 CASE, E 9 Off, Nuclear Reactor Regulation, Director 2pp 15805 137 24x Fishe 50-000 82/10/66 22/10260526
- --8210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Hanual"

  # Commonwealth Edison Co 82/09/30 83pp 15805 139 241
  Fishe 50-000,82/10/06,8210260526
- 82(0220399 Supple 820414 response to Franklin Respanch Ctr 8[]C.1., technical evaluation rept re control of heavy loads (NUREO-0612), per 820824 & 25 telicons (LENTINE, F.G. Commonwealth Edison Co. 82/10/12 DENIGN H.R. of Nuclear Reactor Regulation, Director Spp. 15777-327 Its Fiche 50-295, 82/10/12,8210220399
- 8210190443 Forwards add1 info re NUREO-0737. Item II D 3. \*Post-Accident Sampling Sys." in response to NRC 820722 Iter Util currently pursuing possibility of developing procedura to estimate core damage via Westinghouse owners group SMARTZE D Commonwealth Edison Co 82/10/13 FESTMAN De Bivision of Licensing 15pp 19741 187 24X Fiche 50-293.62...
- 8210270344 Notification of 821115-16 meetings w/util in Glen Ills. to discuss bases for corrent inservice testing proposed exemption, including alternatives to required inaps HIGGINTON, D. Operating Reactors Branch 1 82/10/22 VASULS Departing Reactors Branch 1 2pp 19851 354 24X Fiche 50-295, 82/10/22,8210270344
- G Inspection reports, IE Bulletins & correspondence
- --8210050107 Notice of violation from insp on 820300-31.0107 (14) KEPPLER, J O Region 3. Office of Director 82/07/09 3jj 15605.024 24X Fiche 50-295,82/07/09.8210050103
- 8210070007 Responds to FOIA request for eight categories of FRII PT team generators & steam turbines App A documents provided in R Udeli FOIA Request 81-313 Forwards documents listed in App B FELTON J M Division of Rules and Records. 82/08/10 LOW # Winthrop, 8timson, Putnam & Roberts 9pp 15645 063 241 Fiche 50-000, 82/08/10, 8210070007.

E)

Θ.

R.

- --B210070139 Forwards tabulated data on steam generator inspiles facilities. Data should be provided to licensees IPPOLITO.T. Operating Reactors Assessment Branch. B2/04°C: VAROALS. Operating Reactors Branch 1 Spp. 15645
- --8210070172 Forwards info re steam generator integrity & initial operating PWRs:per 750320 & 21 requests Details of (hist-including defect indications, tube plugging criteria & twee plugged will not be provided except for Point Deach i OULLER: K R. Division of Reactor Licensing (MRR-[975 enls] 75703/24 MACCARY. R. Division of Technical Review (MRR-17 only) 5pp 15645-176. 24% Fichs 50-000,82/08/10-92100%20
- 8210190569 Forwards IE Enforcement Conference & Insp Repts 30-2818 & 50-304/82-17 on 820717-0909 & notice of violation SPESSARD, R L. Division of Project & Resident Programs \$2.7242 REED. C. Commonwealth Edison Co. 2pp. 15736 112 24X Fiche 50-295, 82/09/30, 8210190568.
- --8210190579 Notice of violation from insp on 820717-0831 \* Division of Project & Resident Programs. 82/09/30 15736:113 24% Fiche: 50-295, 82/09/30, 8210190348

- -8210190597 IE Enforcement Conference & Insp Repts 50-295/82-19 & 50-304/82-17 on 820717-0909 Nancompliance noted failure to follow 800229 confirmatory order requiring expeditious shutdoun whenever auxiliary feedwater sys inoperable MATERS. J R , SCHNEIDER. G O , REVES. L Region G, Office of Director 82/09/22 9pp 15736 114 24X Fiche 50-295/82/09/30, 8210190568
- B210060359 Ack receipt of B20910 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-237/61-39, 50-249/61-32, 50-254/61-23, 50-265/61-23, 50-295/81-31 & 50-304/81-29

  SPESSAPD, R L Division of Project & Resident Programs B2/10/01 REED. C Commonwealth Edison Co ip 15618 354 24X
  Fishe 50-000, 82/10/01, 8210060359
- --8210060367 Responds to NRC 820712 ltr re violations noted in IE Insp Repts 50-237/81-39,50-249/81-32,50-254/81-23,50-265/81-23, 50-295/81-31 & 50-304/81-29 Corrective actions training for mot priorities re plant availability will be conducted REED.C Commonwealth Edison Co 82/09/10 KEPPLER, J O Region 3. Office of Director 13pp 15618 355 24X Fiche 50-000,82/10/018210060359
- •210080178 Forwards listing of piping sys which fail to meet FSAR requirements, per NRC 800818 confirmatory action ltr IE Bulletin 79-14 operability evaluation updates will not be provided for Dresden & Quad Citites Final update by Dec 1982 RAUSCHIT J Commonwealth Edison Co 82/10/01 KEPPLER. J O Region 2. Office of Director App 15640 159 24X Fichs 50-000,82/10/01,8210080178
- 210190617 Forwards 1E Insp Rept 50-295/82-21 on 820908-10 No noncompliance noted
  LITTLE-W S Division of Engineering & Technical Programs 82/10/05
  REED.C Commonwealth Edison Co 2pp 15739 094 24X
  Fiche 50-295,82/10/05.8210190617
- -8210190626 IE Insp Rept 50-295/82-21 on 820908-10 No noncompliance noted Major areas inspected Cycle 7 control red drop time tests, control red drive & position indication checks & reactor thermocouple/resistance temp device cross-callbr ROSINSON.D L. JACKIN-I N Region 3. Office of Director 82/10/01 4pp 19739 096 24% Fiche 50-295,82/10/05,8210190617
- 308170233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards E2710706 Consolidated Edison Co of New York 66pp 13761-250 24x Fiche 50-000/82/10/06/8208190233
- \*10190613 Ack receipt of 820910 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/82-14 & 50-304/82-13 Interpretation of Tech Spec 1 0 D unacceptable SPESSARD, R L Division of Project & Resident Programs 82/10/07 REED, C Commonwealth Edison Co ip 15739 361 24X Fiche 50-295, 82/10/07,8210190613
- B210190624 Responds to NRC B20813 ltr re violations noted in IE Insp Repts 50-295/82-14 & 50-304/82-13 Disputes NRC classification of B20625 reactor trip Trip inadvertent Interpretation of Tech Spec 1 O D encl STIEDE.W L Commonwealth Edison Co 82/09/10 KEPPLER.J 9 Region 3, Office of Director 4pp 15740 001 24% Fiche 50-295,82/10/07,8210190613
- O8190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter: Stainless Steel. Recirculation Sys
  Piping at BWR Plants " Svc list encl
  DEYOUNO.R C Director's Defice. Office of Inspection and
  Enforcement 82/10/14 Consolidated Edison Co of New York
  115pp 15810 125 24% Fiche 50-000, 82/10/14-8208190238
- 10270344 Notification of 821115-16 meetings w/util in Olen Ellyn, IL to discuss bases for current inservice testing proposed exemption, including alternatives to required insp. wiGGINTON D. Operating Reactors Branch 1. 82/10/22, VARGA, 8 A Deparating Reactors Branch 1. 2pp. 15851-354 24X Fisher 50-295.82/10/22,8210270344
- Periodic operating reports & related correspondence
- | CO150405 Forwards monthly operating rapts for Sept 1982 | FRAESSER.K.L. Commonwealth Edison Co. 82/10/04 Director's | Diffice. Office of Inspection and Enforcement 1p 15704 003 24: | Tiche 50-295.82/10/06,8210150405.
- 3210150411 Monthly operating repts for Sapt 1982 AUSTIN-0 Commonwealth Edison Co 82/10/06 11pp. 15704'004 24X Fiche 50-295.82/10/06.8210150405.

- S Reportable occurrences, LERs & related correspondence
- 9210120182 Discusses findings re numerous failures of containment isolation valves All failures resulted from inoperable ASCO Series 6320 solenoid valves, usually due to oil in air supply Valves undergoing qualification LANNING, W D Director's Office 80/08/22 Director's Office 2pp 15492 214 24X Fiche 50-295,60/08/22,8210120182
- 8210070429 Discusses 810115 solenoid valve failure failure of valve to shift attributed to impursties in oil settling on valve surface Valves replaced No further action recommended ASHE,F Director's Office 81/11/10 MICRELSON,C Director's Office 4pp 15644 317 24% Fiche 50-295,81/11/10.8210070429
- 82:0070422 Recommends IE issue info notice to inform licenses of possible inadequate surveillance for proper tuning of output capacitance for certain inverters Recommendation based on Bi0505 & 28 sola output transformer shorts HELTEMES.C J Director's Office. 81/12/10 JORDAN.E L Division of Resident & Regional Reactor Inspection. 4pp 15444 285 24X Fiche 50-295.81/12/10,8210070422
- 8210010008 Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A
  FELTON, J M Division of Rules and Records. 82/06/28 UDBLL, R. A
  Critical Mass Energy Project 15pp (5727 005 24X
  Fiche 50-000, 82/06/28,8210010008
- --Bi11270314 Discusses LER 81-002/03X-1.dtd 810480,re inoperable solenoid valves, Cause found to be impurities in internal mechanisms Valves replaced w/Keane valves & solenoids w/higher strength coil Findings to be incorporated in instrument air study AHEF, Director's 0ffice, 81/11/10 MICHELSON,C Director's Office 3pp 15731 109 24X Fiche 50-000,82/05/28,8210010008
- 8210080088 PNO-III-82-106 on 820930.while operating at full power, one of two main feedwater pumps failed Reactor control rod drive sys failed to insert rods automatically Caused by faulty circuit board Circuit board replaced REYEB.L. STREEYER.J. SPE68ARD.R Region 3. Office of Director 82/10/01 1p 15640 222 24% Fiche 50-295.82/10/01.8210080088
- 8210190689 Forwards LER 82-027/03L-0 ORAESSER, K. Commonwealth Edison Co 82/10/05 KEPPLER, J & Region 3, Office of Director ip 15738 143 24x Fiche 50-295, 82/10/05, 8210190689
- --8210190715 LER 82-027/03L-0 on 820905, 1C containment spray diesel driven pump found completely void of engine jacket water. Caused by leak in jacket water heater due to corresion Heater replaced w/pipe plug New heaters ordered SHRM, K. Cemmenwealth Edison Co. 82/10/05 Region 3, Office of Director ip 15739 144 24X Ficher 50-278,82/10/05,8210190689
- 8210190483 Forwards LER 82-028/03L-0 GRAESBER, K. L. Commonwealth Edison Co. 82/10/08 MEPPLER, J @ Region 3, Office of Director ip 15740 266 24X Fiche 50-293, 82/10/08,8210190483.
- --8210190493 LER 82-028/03L-0-on 820910, during surveillance at 100% power, RHR miniflow control valve switch 1FIC-610A failed & would not close miniflow valve at 1000 gpm as designed Caused by suitch out of tolerance Hod initiated BINOGELT.8 L Commonwealth Edison Co 82/10/08 Region 3, Office of Director 1p 15740 247 24X Fiche.50-295, 82/10/08, 8210190483
- 8210260399 Forwards LER 82-030/03L-0 QRAEBEER, L Commonwealth Edison Co 82/10/19. KEPPLER, J Q Region 3, Office of Director. 1p 19803 327 24X Fiche 50-295: 82/10/19, 8210260399.
- --B21026041i LER B2-030/03L-0 on B20919, charging flow found 30 gpm less than letdown flow increased demand on charging flow control valve did not increase flow rate Caused by fatigue Rotating alement replaced investigation ongoing BINO9ELIB.C. Commonwealth Edison Co B2/10/19 Region 3, Office of Director 3pp 19803-328. 24X Fiche 50-295,82/10/19, 8210260399
- 8210260233 Forwards LER 82-029/03L-0 ORAEBER,K L. Commonwealth Edison Co. 82/10/20 KEPPLER.J.9 Region 3. Defice of Director 1p. 15803:029 24x Fiche:50-295,82/10/20.8210260233

### DOCKETED ITEMS

- --8210260254 LER 82-029/03L-0 on 820920, logic relay NC41H-XA associated w/power range X10X reactor trip for train A malfunctioned nonconservatively Caused by plunger pin shifting to one side & binding against relay housing ROHDE.J E Commonwealth Edison Co 82/10/20 Region 3, Defice of Director ip 18903 030 24X Fichs 50-295.82/10/20, 8210260233
- DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3 F Security, medical, emergency & fire protection plans
- 8209170101 Forwards minor revisions to proposed physical security plan Revisions withheld (ref 10CFR73 21) MILLS,L M Tennessee Valley Authority 82/08/31 DENTON,H R Office of Nuclear Reactor Regulation. Director 2pp 14910 081 24X Fiche 50-259.82/08/31.8209170101
- 8210290236 Forwards security plan table of contents Table of contents withheld (ref 10CFR73 21)
  KAKMER, D S Tennessee Valley Authority 82/10/19 DENTON, H R
  Office of Nuclear Reactor Regulation, Director 1p 15788 362 24X
  Fichs 30-259, 82/10/19,8210230236
- 8210250244 Forwards revisions to physical security plan Revisions withheld (ref 100FR73 21)
  KAMMER.D S Tennessee Valley Authority 82/10/19 DENTON.H R
  Office of Nuclear Reactor Regulation, Director 1p 15789 345 24)
  Fiche 50-250,82/10/19.8210250244

#### G Adjudicatory correspondence

- 9210120291 Response to ASLAB 820920 order to provide any supplemental info re questions posed to util Authorization is for 5-yr storage of low level radwasts w/o limit on use of modules for interim use on backup basis RAMBON.R J Hearing Branch 4 82/10/08 8pp 15452 071 24X Fiche 50-259.82/10/08,8210120291
- --8210120299 Affidavit of P Loysen re application for storage of low level radwaste No restriction requested or contemplated limiting use of modules only to interim use on backup basis LOYSEN.P Advanced Feel & Spent Fuel Licensing Branch 62/10/08 23pp 15652 079 24X Fiche 50-259.82/10/08.8210120291
- --8210120308 Affidavit of JR McGrath Timely request for renswal of facility license filed for Beatly.NV low level radvaste disposal facility NV State Board of Health voted not to renew facility license McGRATH, JR Assistant Director for State Agreements Programs 62/10/08 2pp 15452 102. 24X Fiche 50-259,82/10/08,6210120291
- --8210120316 Affidavit of SN Balomon Southeast Interstate Low Level Radwaste Mgt Compact agreed to close Barnwell,80 facility on 921231 & open new site on 911231, Certificate of Svc encl. SALOMON.8 N Assistant Director for State Agreements Programs 82/10/08 4pp 15652 104. 24X Fiche.30-259,82/10/08,8210120291
- 8210250063 Telecopy message of motion for ASLAB to grant 30-day extension to respond to ASLB 820920 order. Time necessary to explore settlement possibilities of all matters in controversy PYLE:R B Pyle, R B. 82/10/20 Docketing & Services Branch 1p 15787:061 24X Fiche 50-259,82/10/20.8210250063.
- 8210260427 Motion for extension of time until 821121 to respond to 820920 order Time necessary to explore possibilities of settlement Certificate of 8vc enc. PYLE.R B Pyle, R.B 82/10/20. Atomic Bafety and Licensing Appeal Penel 2pp 15806 036 24X Fiche 50-239, 82/10/20, 8210260429

### P Operating license stage documents & correspondence

- 8210070255 Forwards response to NRC request for add1 info on NUREO-05:2. "Control of Heavy Loads of Nuclear Power Plants "
  HILLS.L.H. Tennessee Valley Authority. 82/09/28 VASBALLO.D B Operating Reactors Branch 2 Sopp. 13635 243 24X
  Fiche 50-259.82/09/28.8210070255
- 8210080218 Forwards add1 into in response to NRC 820808 request re NUREO-0797. Item II KAS. 24, "Adequate of Space Cooling for HPCI & RCIC " MILLES.L.K Tennessee Valley Authority 82/10/04 DENION, H. R Office of Nuclear Reactor Regulation, Director, 2pp. 15638:091. 24X Piche: 50-259.82/10/04,8210080218.

- 8210130142 Forwards description of final mode & changes to BHR screw sys & short-term interim commitments for Unit 2 Hode will be implemented for Unit 2 before startup from Reload 4 outage & subsequent Units i & 3 outages
  MILLS.L M Tennessee Valleg Authority 82/10/06 DENTON.H R
  Office of Nuclear Reactor Regulation. Director 4pp 15673 004
  24X Fiche 50-259.82/10/06.8210130142
- 8210250076 Forwards revision to 821006 implementing procedures
  HILLS-L M Tennessee Velley Authority 82/10/15 DENTON H R
  Office of Nuclear Reactor Regulation, Director ip 15793 018 7
  Fiche 50-257.82/10/15.8210250096
- --8210250101 Revised implementing procedures # Tennessee Valley Authority 82/10/15 14pp 15793 059 24: Ficher 50-259, 92/10/15, 8210250096
- @ Inspection reports. IE Bulletins & correspondence
- 8210080015 Addi response to FOIA request for 19 categories of information reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
  FELTON-J M Division of Rules and Records 82/07/12 UDELL-8 & Critical Mass Energy Project 9pp 15665 027 24%
  Fiche 50-000-82/07/12-8210080015
- --8210080118 Systematic assessment of licensee performance notes ry facility evaluation for App 1979-Mar 1980

  NRC No Detailed Affiliation Given BO/03/31 App 19667 315 24X Fiche 50 000.82/07/12.8210080015
- 8210150105 Notifies that corrective actions re IE Insp Repts 50-259/81-13, 50-260/81-13 & 50-296/81-13 delayed Procedure DPM N80E3 re exam of CSSO (tems to be revised by 820915 DOMER, J A Tennessee Valley Authority 82/07/13 G'REFLLY, J P Region 2, Office of Director ip 15701 159 24X Fiche 50-259, 82/07/13, 8210150105
- 8210220151 Provides supplemental response to NRC ltr re violations noted in IE Into Repts 50-259/82-10, 50-260/82-10 to 50-259/82-10 by of procedures Manual N82A3 will not be revised until 821001 due to scope of effort involved MILLS-L M Tennessee Valley Authority 82/08/18 0'REILLY. J F Region 2, Office of Director ip 15778 104 24% Fiche: 50-259, 82/08/18, 8210220151
- 8210010035 Confirms 82070B site meeting to discuss recent violations re radwaste shipments Agenda encl
  O'REILLY,J P. Region 2. Office of Director 82/09/03 PARRIS.HE
  Tennessee Valley Authority 2pp 15565 166 24X
  Fiche 50-259,82/09/03,8210010035
- 8210910430 Forwards IE Insp Repts 50-259/82-25, 50-260/82-25 & 50-296/82-25 on 820810-11 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 82/09/0 PARRIEL,H 0 Tennessee Valley Authority 2pp 15570 211 24% Fiche 50-259, 82/09/03, 8210010430
- --8210010432 IE Insp Repts 50-297/82-25, 50-240/82-25 t 50-296/82-2 820810-11 No noncompliance noted Major areas inspected reactor secondary containment integrity problem & MStV testing 8ROOKS, E H , JAPE, F. Division of Engineering & Technical Froj 82/08/27 4pp 15970 213 24X Fiche 50-259, 82/09/03, 82(00)
- 8210150399 Forwards IE Insp Repts 50-289/82-28, 50-260/82-28 & 50-296/82-28 on 820830-0903 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/09/20 PARRIS, H 9 Tennessae Valley Authority 2pp 15704 029 24% Fiche: 50-259, 82/09/20, 8210150399
- --8210150406 IE Insp Repts 50-259/82-28.50-260/82-28 & 50-296/82-36 820930-0903 No noncompliance noted Major areas inspected inservice inservice to string program & inservice to string program review QIRARD, E. H., BLAKE, J. Division of Engineering & Technical Programs. 82/09/16 4sp 15704-031 24X Fiche 50-259.62/07/8210150399.
- 8210010097 Approves revised commitment dates for Item 25 of App Ct IE Insp Repts 50-259/81-19.50-260/81-19 & 50-296/81-19 & Item C.2 of App A to IE Insp Repts 50-259/82-12.50-260/82-12 & 50-296/82-12.50-260/82-12 & 50-296/82-12 & IE Insp Repts 50-259/82-12.50-260/82-12 & Security Authority Programs 82/09/22 PARRIS, M. G. Tennessee Valley Authority, 1p 15565 C91 24X Fiche: 50-259, 82/09/22; 8210010097

1

- --8210010104 Requests extension to respond to App C. Item 25 in IE Insp Repts 50-259/81-19, 50-260/81-19 & 50-296/81-19 & Item C 2 in IE Insp Repts 50-259/82-12, 50-260/82-12 & 50-296/82-12 Responses will be submitted by 630101 & 8211011, respectively MILLS.L M Tennessee Valley Authority 82/09/01 0'REILLY, J P Region 2. Office of Director 1p 15565 002 24X Fichs 50-259, 92/09/22, 8210010097
- F210010326 Forwards summary of 820908 enforcement meeting w/util to discuss corrective actions re leakage during shipment of low level waste & util plans for improving employee training O'REILLY, JP Region 2. Office of Director 82/09/22 PARRIS, H & Tennessee Valley Authority 4pp 15569 188 24% Fiche 50-259, 82/09/22, 8210010326
- 210010290 Act receipt of supplemental 920901 ltr informing NRC of steps taken to correct Violation B noted in IE Insp Repts 50-259761-26. 50-260/82-26 & 50-297/81-26. 50-260/82-26 & 50-297/81-26. ENIS.R C Division of Project & Resident Programs 82/09/24 PARRIS.R C Tennessee Valley Authority ip 15573 183 24X Fiche 30-259. 82/09/24. 8210010290
- -8210010304 Forwards revised response to NRC 811028 ltr re Violation B meted in IE Insp Repts 50-259/82-26.50-260/82-26 & 50-276/82-26 Corrective actions R factor returned to within limits & revision to Tech Spec approved MILLS-L K Tennessee Valley Authority 82/09/01 O'REILLY, J P Region 2. Office of Director 3pp 19573 184 24X Fiche 50-259, 82/09/24/8210010290
- 110220370 Forwards IE Insp. Repts 50-259/82-29, 50-240/82-29 & 50-296/82-29 on 820904-10 No noncompliance noted WERRELLI.D M Division of Project & Resident Programs B2/09/30 PARRIES N G Fencessee Valley Authority 2pp 15779 220 24X Fiche 50-259, 82/09/30, 8210220390
- B21022040i IE Insp Repts 50-259/B2-29, 50-260/82-29 & 50-296/82-29 on B20906-10 No nancompliance noted Major areas inspected Unit 2 refueling 5 maint outage & procedural compliance of health physics-related practices by workers CQLLINS, T R , BARR, K P Division of Engineering & Technical Programs 82/09/27 5pp 15779 222 24X Fiche 50-259, 82/09/20, 8210220390
- 10080217 Forwards revised request for relief from Inservice Insp 7 retraccessible welds in piping penetrations & under rigid pipe restraints Bost effort visual exam will be performed during sys hydrostatic pressure test dILLS/L M Tennesses Valley Authority 82/10/04 DENTON, H. R 3ff3/c of Nuclear Reactor Regulation. Director 3pp 15638 083 PAX Fiche 50-259,82/10/04.8210080219
- 0150218 Forwards update of present work & schedule for mplementation of insperequired under IE Bulletins 79-02 & 9-14 Phase II evaluation will not be completed until 40801
  ILLS.L M Tennessee Valley Authority 82/10/07 0'REILLY.J Pegion 2. Office of Director 2pp 18705 276 24X iche 50-259, 02/10/07,8210180318
- 3170233 IE Bullatin 82-03, "Stress Corrosion Cracking in Thick-all. Large-Diameter, Stainless Steel, Recirculation System at BMR Plants "Svc list encleavement Bullation System and Stronger C Director's Office, Office of Inspection and Storicement 82/10/14 Consolidated Edison Co of New York 15pp 15810 125 24X Fiche 50-000, 82/10/14, 8208170238
- taportable occurrences, LERs & related correspondence
- \*120129 Advises of need for in-depth evaluation of potential for acceptable interaction between control rod drive sys & nessential control air sys Mergin of safety inherent in censed design basis should be promptly restored CHELSON.C Director's Office 80/08/18 DENTON, H. R Office of clear Reactor Regulation. Director Spp 15692, 150 24X che. 50-296. 80/08/18,8210120129
- 01000B Responds to FOIA request for 19 categories of documents reclear reactor events & safety problems. Forwards documents sted in App A LTON. J H Division of Rules and Records. 82/06/28 UDELL.R. A itical Mass Energy Project 15pp 15727 005 24% cha 50-000.82/06/28.8210010008.

- --8112210338 Forwards description of events & resulting action re high circulating current associated w/inverter output due to lack of circulat tuning IB circular or info notice should be issued to address issue
  HELTEMES.C J Director's Office 81/12/10 JORDAN.E L
  Director's Office 4pp 15731 361. 24X Fiche 50-000,82/06/28,8210010008
- --8210060082 "Bummary of Ofc of Analysis & Evaluation of Operational Data Analysis & Evaluation of Browns Ferry Unit 3 Partial Failure to Scram Event of 800628 " LANIK.O Director's Office 81/11/30 22pp 15731 263 24x Fiche 50-000, 82/06/28, B210010008
- 8210080015 Add1 response to FDIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 8) FELTON, J M Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project 9pp 15645 027 24X Fiche 50-000, 82/07/12, 8210080015
- --8210080197 NRC operations ctr usage chart re events at facilities NRC - No Detailed Affiliation Given 82/07/12 ip 15468 221 24X Fiche 50-000.82/07/12,8210080015
- 8210060265 Forwards LER 82-042/03L-0 OREGI-H J Tennesses Valley Authority 82/09/28 O'REILLY, J P Region 2, Office of Director. 1p 15621 O/4 24X Fichs 50-276.82/09/28.8210060265
- --8210060270 LER 82-042/03L-O an 820831, diesel generator 3C right bank air starters failed to develop min rpm Caused by loose bolts on right bank air start valve 853-3 Bolts tightened PORTER.M.R. Tennessee Valley Authority. 82/09/28 Region 2. Office of Director 2pp 15621 077 24X Fiche 50-296,82/09/28,82/090285
- 8210130157 Forwards LER 82-043/03L-0 OREEN.H J Tennessee Valley Authority 82/10/07 O'REILLY, J P Region 2. Office of Director 1p. 15673 077. 24X Fichs 50-296.82/10/07.8210130157
- --8210130162 LER 92-043/03L-0 on 920909,400-volt reactor motor operated valve board 3DN motor-generator set removed from svc when generator/flywheel ball bearing became noisy Caused by lack of adequate lubricant film on bearing Bearing replaced AARDN.J.A Tennessee Valley Authority 82/10/07 Region 2, Office of Director 2pp 15673 078 24X Fiche 50-296,82/10/07,8210130157
- 8210270231 Forwards updated LER 82-037/01X-1 GREEN H J Tennessee Valley Authority 82/10/14 O'REILLY, J.P. Region 2. Office of Director ip 15853 231 24X Fiche 50-296, 82/10/14,8210290231
- --8210290232 Updated LER 82-037/01X-1 on 820824, during instrumentation callbr for core standby cooling sys suppression clamber, callbr valve on level switch L8-73-57A found open rendering switches inoperable Caused by open valve Valve closed IRBY-B J Tennessee Valley Authority 82/10/13 Region 2, Office of Director 2pp 15853,232 24X Fiche 50-296,82/10/14, 8210290231
- T Hearing transcripts on non-antitrust matters
- 8210070133 Testimony of JW Hutton answering ASLAB questions on low level radwaste mgt options Availability of adequate space to dispose of low level wastes in next 5 yrs uncertain Centificate of Svc encl HUTTON, JW Tennessee Valley Authority 82/10/01, 12pp 13627 031 24X Fiche 50-239,82/10/01,8210070133
- DOCKET 50-298 COOPER NUCLEAR STATION

  F Security, medical, emergency & fire protection plans
- 8210010058 Forwards rept of change to safeguards plan, Revision O. Rept withheld (ref 10CFR2.790 & 10CFR73.21). PILANT.J.M Nebraska Public Power District. 82/09/13. VASSALD.D.B Deprating Reactors Branch 2 1p 15567/153 24X Fiche 50-296.82/09/13.8210010058
- 8210130318 Forwards changes to Revision 1 to safeguards plan, Changes withheld (ref 10GFR2 790 & 10GFR73 21)
  FILANT.J.M. Nebreska Public Power District 82/10/04, VASSALD, D. B. Operating Reactors Branch 2 2pp 15678 160 24X
  Fiche: 50-298,82/10/04,8210130318

- 8210180320 Forwards QE proprietary unique analysis repts for facility Repts withheld (ref 10CFR2 790) SIEOEL.B. Operating Reactors Branch 2 82/10/04 BUBRAMONIAN.N Franklin Institute/Franklin Research Center ip 15746.018 24X Fiche 50-298.82/10/04.8210180320
- 8210260217 Forwards response to NRC 820809 ltr forwarding notice of violation & proposed imposition of civil penalty & order modifying license Magnitude of enforcement action not warranted QONEB.C R Nebraska Public Power District 82/10/07 DEYQUNG.8 C Director's Offica. Office of Inspection and Enforcement. 84pp 15804-081. 24X Fiche 50-298,82/10/07.8210260217.
- 8210220254 Submits update to 820416 response to Generic Ltr 82-05, confirming operability & installation of post-TMI requirement per NURGO-0707. Item II F i re accident monitoring instrumentation, noble ges & indine particulate PILANT. J H Nebreska Public Power District 82/10/18 EISENHUT, D Ø Division of Licensing ip 15774 228 24X Fiche 50-298, 82/10/18, 8210220254
- 8210240278 Forwards IE Safeguards into Rept 50-278/82-28 on 920830-0701. Notice of violation withheld (ref 10CFR73 21), MADSEN. O.L. Division of Resident, Reactor Project & Engineering Programs, 82/10/22 PILANT, JN Nabrasia Public Power District, 2pp 15801-358 24X Fiche, 50-278, 82/10/22, 82/0260298
- --8210260301 IE Bafaguards Rept 50-298/82-28 on 820830~0701 Nancompliance noted details withheld (ref 10CR73 21)
  CALDHELL: R A. KELLY, J A F. Region 4. Diffice of Director 82/10/14 Ip. 15801.350 24X Fiche 50-298.82/10/22.8210260298

#### P Operating license stage documents & correspondence

- 8210120584 Forwards order modifying 810113 order. extending completion 2101203B4 Forwards order modifying BiOil3 order.sxtending completion data for installation of plant mods needed to comply w/ NUREO-O661.App a to start of Fuel Cyle 9. VASBALLD.D.B. Operating Reactors Branch 2 82/09/15. PILANT, J H. Natraska Fubiic Power District. 2pp. 15484:209 24X Fiche:50-298.82/09/15.82i0120584.
- --82(0120590 Order modifying 8101(3 order, extending completion date for installation of plant mode needed to comply w/NUREO-0666.

  App A to start of Fuel Oggle 9.
  E19EKNUT.D.O. Division of Licensing. 82/09/15. Nebreska Public Power District. Spp. 15684:21i. 24X Fiche: 50-298,82/09/15.
- 8210270308 Informs that integration of NUAEO-0737, Item II. M. 3.27 "Common Ref Level" & Item 1.0.1, "Control Room Design Revieu," per util 820930 commitment will eliminate operator confesion resulting from changing water level. VABBALLO.D.B. Operating Reactors Branch 2. 82/10/12, PILANT, J. M. Nebraska Fublic Power District. 2pp. 15836:337. 24x Fichs: 50-298, 82/10/12, 8210270308.
- 82:0220284 Bubmits update to 820416 response to Generic Ltr 82-05, confirming operability & installation of poet-THI requirement per NUREG-0737, Iben II.F. I re-accident monitoring initiumentation, moble see k joins particulate. PiLANT.J.M. Nebraeks Public Power District. 82/10/18. EJSENNUT.B.O. Division of Licensing. Ip. 15774: 228. 24X Ficha: 50-278, 82/10/18:8210230304.
- 8210260028 Forwards revisions to 820329 Relief Requests RP-02 & RP-04 rs inservice insp/testing requirements for pumps & valves. PILANT.J.M. Nebreaks Public Fewer District. 82/10/19. VABBALLO.D.B. Operating Reactors Branch 2. 4pp. 15799:344. Rex Fiche: 50-278.82/10/19.8210260328.
- B210290333 Submits justification for continued plant operation rs QE dc motor controllers. Fallure of QE controllers due to hersh environ will not affect eats shutdown Controllers will operate satisfactorily after exposure to redistion doss, FILANT, J. M. Nebraska Public Rower District. 82/10/22, VASSALIG. D. B. Operating Reactors Branch 2. ip. 15883:066. 24% Fiche: 80-298, 82/10/23, 8210290323.

#### Q. Inspection reparts: IE Bulletins & correspondence

0208190233 IE Into Notice 60-35, Suppl 1, "Leaking & Dislodged I-185 Implant Seeds, " Svc list entl, COSS.L. I. Division of Fuel Facilities, Haterials & Safaguards SA(10/06) Consolidated Editor Co. of New York. 64pp. 1874 S4X Fisher 80-000, SB(10/04, SE0S19020). 18741: 250.

- 8210260217 Forwards response to NRC 820809 ltr forwarding notice of violation & proposed imposition of civil penalty & order modifying license Magnitude of enforcement action not
- WATTAINED UNDER CR Nebraska Public Power District 82/10/07 DEYDUMD, P.C Director's Office, Office of Inspection and Enforcement 84pp 15804 081 24% Fichs 50-278,82/10/07,8210240217
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Inici-Wall, Large-Diameter, Stainless Steel, Recirculation Sus Wall, Large-Diameter Stainless Steel Rectriculation Sys Piping at BMR Plants " Bkv list end DEYQUNG,R C Birector's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- 8210220130 Ack receipt of 820910 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-278/82-14 MADSEN. 0 L Division of Resident, Reactor Project & Engineering Programs 82/10/14 PLANT. JM Nebraska Public Power District ip 15778 118 24x Fiche 50-298.82/10/14.8210220130
- -8210220136 Responds to NRC 820813 ltr re violations noted in IE!, Rept 50-298/82-16 Corrective actions entry ways into affected area posted locked or observable to radiographer Disciplinary action taken re Procedure 7 4 4.Revision 12 PILANT.J M. Nebraske Public Power District 82/09/10 MADSEN.Q L. Division of Resident, Reactor Project & Engineering Programs 3pp 15778 119 24X Fiche 50-298,82/10/14,8210221X
- 8210260328 Forwards revisions to 820329 Relief Requests RP-02 ± 67 cre inservice insp/testing requirements for pumps & valves PfLANT\_JM Nebrasks Public Power District 82/10/19 VASSALLO,D B Operating Reactors Branch 2 4pp 15799 344 THE Ficher 50-298, 82/10/19, 8210260328
- 8210260298 Forwards IE Safeguards Insp Rept 30-298/82-28 on 620830-0901 Notice of violation withheld (ref 10CFR73 21) MADSEN, O.L. Division of Resident, Reactor Project & Engineering Programs 82/10/82 PILANT, U.M. Nebraska Public Power District 15801 358 24X Fiche 50-298,82/10/22,8210260298
- --8210260301 IE Bafeguards Rept 50-278/82-28 on 820830-0901 Nantcq noted details withheld (ref 100FR73 21) CALDUELLAR A., KELLY, J A F Region 4, Office of Director 82/10/14 lp, 15801 360 24% Fiche 50-278,82/10/22,82102
- 8. Reportable occurrences, LERs & related correspondence
- 9210010008 Responds to FOIA request for 19 categories of documentary nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J H Division of Rules and Records 82/06/28 UDEL Critical Hass Energy Project, 15pp 15727, 005 24X Fiche: 50-000, 82/06/28, 8210010008.
- DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2 F. Security, medical, emergency & fire protection plans
- 8210040119 Discusses revision of plant emergency response proceding 210040117 Discusses revision of plant emergency response are specifying necessary precautions required before Jost-accident re-entry into auxiliary bldg or facade, in response to 820914 request for info re NUREG-0737. Item II D. 2. FAY.C. M. Misconsin Electric Power Co. 82/09/24 DEMICH. Diffice of Nuclear Reactor Regulation, Director, CLARA, 8 A Operating Reactors Branch 3, 2p 15581.201. 24X Fiche: 50-266.82/09/24,8210040119 DENTON-H R
- 8210050272 Forwards add1 info requested in NRC 820716 telcon to support util 820630 App R exemption request. Eight oversite drawings encl. Aperture cards are available in PDR, FAY. C. M. Hisconsin Electric Fower Co. 82/09/29, DENYON H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 13pp, 15606-047. 24X Fiche: 50-266, 82/09/29, 8210050272.
- 8210080054 Forwards addl info re proposed mode for emergency sypt CYT. PAY: C H. Witconsin Electric Power Co 82/09/30. DENTON, H. A. Office of Nuclear Reactor Regulation. Director. 1699 13:003 22 24X Ficha: 50-266, 82/09/30, 8210050084.
- 8210270256 Releases public version of revised emergency plan implementing procedures. FELTON.J.M. Division of Rules and Records. 82/10/08. Pecual Management Branch, 1p. 15834.001. 24X Fiche 50-268,82/10/64 8210270256.

- --B210270259 Forwards public version of revised emergency plan implementing procedures including Procedures EPIP 1 1 re unitial classification.EPIP 1 3 re estimation of source term & EPIP 1 4 re radiological dose evaluation FAY.C W. Hisconsin Electric Power Co. 82/09/10. DENTON, H.R. Office of Nuclear Reactor Regulation. Director CLARK, R.A. Operating Reactors Branch 3 4pp. 15834 002. 24X Fiche 50-264, 82/10/08, 8210270256
- B210150471 Forwards addl info re 820630 requests for exemption from 1CCFR50 App R concerning Fire Area 9.control room & vertical cable trays, in response to 821001 & Od tolcons w/k-RC W/16 oversite drawings Aperture cards in PDR FAY-C H Histonsin Electric Pawer Co 82/10/11 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 12pp 15734 350 24X

#### G Adjudicatory correspondence

- 8210050251 Hemorandum \*\* order granting summary disposition of all WI Environ Decade issues except issue of demonstration of adequacy of eddy current testing to detect cracking BLOCH. P.B. KLINE, J.R. PAXTON, H.C. Atomic Safety and Licensing Board Panel 82/10/01 Wisconsin's Environmental Decade 19pp 15610-306 24X Fiche 50-266.82/10/01.8210050251
- B210200027 Notice of B21117-20 evidentiary hearing in Two Rivers.Wl re adequacy of inservice nondestructive testing of sleeves proposed to be used to regain corrected steam generator tubes Prehearing conference to be held after hearing BLOCK P B Atomic Safety and Licensing Board Panel 82/10/15 ip 15756 325 24X Fiche 50-266,82/10/15.8210200027
- 8210220242 Notice of relocation of 821117-20 hearing from Two Rivers,WI to Milwaukee, WI Limited appearance statements will be taken at original location on 821117
  BLOCK PB Atomic Safety and Licensing Board Panel 82/10/21 1p 15775 351 24X Fichs 50-266,82/10/21,8210220242
- P Operating license stage documents & correspondence
- B210210009 Recommends review of design of interconection between redundant safety-related electrical load groups Design should be modified to assure full compliance w/Reg Guide
  1 A HICHECSON.C Director's Office 80/08/27 DENTON.H R DIRECTOR DIRE
- 52100:1000B Responds to FOIA request for 19 categories of documents remuciear reactor events & safety problems Forwards documents
  Listed in App A
  FELTON.J M Davision of Rules and Records 82/06/28 UDELL,R A
  Cratical Mass Energy Project 15pp 15727 005 24X
  Fiche 50-000.82/06/28.8210010008
- --8002140204 Forwards evaluation of proposed Tech Specs change to operate facility at 2250 or 2000 psia Proposed changes are acceptable W/o enci CMECK.P S Reactor Safety Branch 79/12/26 SCHWENCER.A Operating Reactors Branch 1 (Pre 800428) 6pp 15727 030 24X Fiche 50-000,82/04/28,8210010008
- S210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B
  FELTON, J M Division of Rules and Records 82/08/10 LONG, D J Winthrop, Stimson, Futnam & Roberts 9pp 15645 063 24X
  Fichs 50-000, 82/08/10, 8210070007
- --B1 £0290050 Advises that technical reviewers providing input for SER must be available to testify at 811029-31 hearings Schedule & agenda info enci
  CLARK:R A Operating Reactors Branch 3 81/10/20 MURPHY.E.
  NEHEMIAS.J , MO.T NRC No Detailed Affiliation Given 3pp
  15645 271 24% Fiche 30-000:82/08/10:8210070007.

- 8210040414 Forwards Amends A3 & 68 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amends revise inservice insp Tech Space CLARK, R A Operating Reactors Branch 3 82/08/31 FAY.C W Misconsin Electric Power Co 5pp 15597 134 24X Fiche 50-266, 82/08/31,8210040414
- --8210040420 Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively, revising language of Tach Specs re inservice insprequirements of safety class components to conform w/10CFR50 55
  CLARK, R A Operating Reactors Branch 3 82/08/31 16pp 15597 139 24X Fichs 50~266.82/08/31.8210040414
- --8210040425 Safety evaluation supporting Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively # Office of Nuclear Reactor Regulation. Director 82/08/31 4pp 15597 155 24X Fichs 50-266.82/08/31.8210040414
- --B210040427 Notice of issuance & availability of Amends 63 & 68 to Licenses DPR-24 & DPR-27.respectively CLARK,R A Operating Reactors Branch 3 82/08/31 3pp 15597 179 24% Fiche 50-266,82/08/31.8210040414
- 8210050005 Advises that error analysis of reactor vessel water level instrumentation sys requested in NRC 820619 ltr will be available by 830115
  FAY.C W Hisconsin Electric Power Co 82/09/29 DENTON,H R Office of Nuclear Reactor Regulation, Director CLARK,R A Operating Reactors Branch 3 ip 15605 208 24%
  Fiche 50-266, 82/09/29, 8210050005
- 8210050055 Forwards info requested in NRC 820630 ltr re implementation of TMI Item II B 2. "Post-Accident Sampling Sys " Add1 requirements re backup power sources for lab are beyond scope of original NUREO-0737 implementation schedule SURSTEIN, S. Misconsin Electric Power Co. 82/09/30 DENTON. H.R. Office of Nuclear Reactor Regulation. Director CLARK, P.A. Operating Reactors Branch 3. 21pp. 15603 307. 24X. Fiche 50-266, 82/09/30, 8210050055
- 8210050222 Application to amend Licenses DPR-24 & DPR-27, revising spent fuel pool poison surveillance specimen location & clarifying conditions for operating power-operated relief valves FAY, C H. Wisconsin Electric Power Co. 82/09/30 DENTON, H. R. Office of Nuclear Reactor Regulation. Director, 3pp. 15609-056-24% Fiche 50-266, 82/09/30, 8210050222
- --8210050231 Proposed Tech Specs revising spent fuel pool poison surveillance specimen location & clarifying condition for operating power-operated relief valves

  \* Wisconsin Electric Power Co 82/09/30 3pp 15609 059 24X
  Fiche 50-266.82/09/30.8210050222
- 8210290426 Forwards Amends 64 & 69 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amands modify operation & surveillance testing requirements of containment purge supply & exhaust valves COLBURN, T 0 Operating Reactors Branch 3 82/10/04 FAY, C W Wisconsin Electric Power Co 4pp 15863 143 24% Fiche 50-266, 82/10/04, 6210290426
- --8210270431 Amends 64 & 67 to Licenses DPR-24 & DPR-27, respectively, modifying operation & surveillance testing requirements of containment purge supply & exhaust isolation valves & terminology of Tech Spec 15 4.4 on testing, CLARK.R A Operating Reactors Branch 3 82/10/04 12pp 15863,154 24% Fiche 50-266.82/10/04.8210270426
- ---8210270426 Safety evaluation supporting Amends 64 & 67 to Licenses DPR-24 & DPR-27, respectively 4 Office of Nuclear Reactor Regulation, Director 82/10/04 5pp 15863 146 24X Fiche 50-266, 82/10/04/8210270426
- --8210290441 Notice of issuance & availability of Amenés 64 & 69 to Licenses DFR-24 & DFR-27.respectively CLARK,R A Operating Reactors Branch 3 82/10/04 2pp. 15863 151 24X Fiche 50-266, 82/10/04.8210290426
- 8210190284 Advises of mod to RCB gas vent sys to prevent operation of power operated valves during normal plant operation.per 821012 telcon Physical restraining device fitted on or over valve operator switch FAY.C W Hisconsin Electric Power Go 82/10/15 DENTON.H.R Office of Nuclear Reactor Regulation, Director .CLARK.R.A Operating Reactors Branch 3 ip 15742:177 24X Fiche 50-266.82/10/15.8210190284

- 8210270274 Forwards Amends 65 & 70 to Licenses BPR-24 & BPR-27, respectively, safety evaluation & notice of issuance & availability Amend allows relaxation of monthly turbine stop & governor valve tests during end of cycle operation COLBURN.TO Operating Reactors Branch 3 82/10/15 FAY.C W Wisconsin Electric Power Co 3pp 15836 316 24% Fiche 50-266.82/10/15.8210270274
- --B210270297 Amends 65 5 70 to Licenses DPR-24 & DPR-27, respectively, allowing relaxation of monthly turbine stop & governor valve tests during end of cycle operation CLARK, R A Operating Reactors Branch 3 82/10/15 7pp 15836 319 24% Fiche 50-266,82/10/15,8210270294
- --8210270302 Safety evaluation supporting Amends 65 & 70 to Licenses DPR-24 & DPR-27, respectively 4 Office of Nuclear Reactor Regulation, Director 82/10/15 2pp 15836 325 24% Fitchs 50-266.82/10/15.8210270294
- --8210270303 Notice of issuance & availability of Amends 65 & 70 to Licenses DPR-24 & DPR-27, respectively CLARK, R A Operating Reactors Branch 3 82/10/15 2pp 15836 327 24X Fishs 50-266, 82/10/15, 8210270294
- 8210260476 Application to amend Licenses DFR-24 & DFR-27, revising Tech Spec re administrative control of high radiation areas FAY, C W Wisconsin Electric Power Co 82/10/19 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 15806 833 24X Fiche 50-266, 82/10/19, 8210260476
- --8210260479 Proposed Tech Spec changes incorporating revisions re administrative control of high radiation areas • Misconsin Electric Power Co 82/10/19 ip 19806 235 24X Fich 50-266,82/10/19,8210260476
- G210280295 Application to amend Licenses DPR-24 & DPR-27, changing Tech Specs re requirements for periodic leakage rate testing of containment airlock doors Class I & II amend fees encl FAY-C W Wisconsin Electric Power Co 82/10/21 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 15837 272 24X Ficher 50-266/82/10/21/8210280295
- ~-8210280298 Tech Spec Change Request 82, changing requirements for periodic leakage rate testing of containment air lock doors + Hisconsin Electric Power Co 92/10/21 4pp 15837 275 24X Fiche 50-266.82/10/21 B210280295
- 8210290294 Provides results of confirmatory analysis demonstrating that unacceptable radioactive release from containment would not take place as result of small break LOCA in which operator action required Radioactive release negligible FAY.C.H. Wisconsin Electric Power Co. 82/10/22 CLARK, R.A. Operating Reactors Beanch 3 ip 19853 195 24X Fichs 50-266,82/10/22,8210290294
- Q Inspection reports. IE Bulletins & correspondence
- 8107270156 Forwards add1 info in response to IE Bulletin 60-il re masonry walls Thirteen repts & 109 oversite drawings encl Aperture cards are available in PDR FAYs.U Hisconsin Electric Power Co. 81/07/17. DENTON,H R Office of Nuclear Reactor Regulation Director. CLARK,R Operating Reactors Branch G. 19pp. Available at NTIS 09151.026 24X Fiche 50-266.81/07/17.8107270156
- --8107270161 "Model Contribution to Dynamic Analysis Results "
  \* Computerh Engineering Services Inc R553 02, 81/07/31 115pp
  09151-045 24X Fiche 50-266.81/07/17.8107270156
- --8107270166 "Cyclic Loading Tests of Masonry Bingle Piers, Vol 1 Height to Width Ratio of 2 " HIDALGO.P A , HAYES,R.L , MCNIVEN,H D California, Univ of, Berkeley UCB/CERC-7B/27 Vol 7B/11/30 | Hipp Available at NTIB 09151-15B 24X Fiche 50-266.81/07/17.8107270156
- --8107270169 "Cyclic Loading Tests of Masonry Bingle Piers.Vol 2 Height to Width Ratio of 1." CMEN.B J : HIDALGO.P A : MAYEB.R L California, Univ of, Bertsley. USP/EERC-78/28 VO2 78/12/31. 188pp 09151 298 #4X Fiche. 50-266.81/07/17.8107270156
- --8107270174 "Cyclic Loading Tests of Mesonry Bingle Plers, vol 3 Height to Width Ratio of 0.5."
  HIDALGO, P.A., MAYES, R.L., MCNIVEN, H.D. California, Univ. of, Berkeley UCB/EERC-79/12 VO3 79/05/31. 154pp Available at NTIS 09152 124. 24X Ficher 50-266.81/07/17.8107270156.

- --8107270178 "Shaking Table Study of Single-Story Masonry Houses, Vall Yest Structures 1 & 2 "

  GULKAM, P. MAYES, R. L. CLONGH, R. W. California, Univ. of, Serialli, UCD/EERC-79/23 VOI 79/09/30 275pp Available at NYIS

  G9152 277 24X Fiche 50-266, 81/07/17, 8107270156
- --BiO7270182 "Shaking Table Study of Single-Story Masonry Houseshol 2-Test Structures 3 & 4 " GULKAN,P. MAYES,R.L. CLCUGH.R.W. California, Univ. of Berbeley UCB/EERC-79/24 VO2 79/09/30 300pp 09153 iB4 24X Fiche 50-266,81/07/17.8107270156
- ~-Bi07270185 "Shaking Table Study of Single-Story Masonry Houses(Vi) Summary, Conclusions & Recommendations "
  CLOUGH: R W , MAYES: R L , GULKAN: P California, Univ of, Berksiy, UCB/CERC-79/25 VO3 79/09/20 (10pp Available at NTIE 09154 078 24X Fiche 50-266, 81/07/17, 8107270156
- --8107270888 "Cuclic Shear Tests of Masonry Piers, Vol 3 Task Results "
  MAYES, R L , OMATE, Y , CLOUGH, R W California, Univ of, Berseleg
  EERC 76-8 76/05/31 105pp 09154 182 24X
  Fichs 50-266, 81/07/17, 8107270156
- --BIO7270191 "Cyclic Shear Tests of Masonry Piers, Vol 2 Analysis of Test Results " MAYEG.R L. GMATE, Y. CLOUCH, R W Celifornia, Univ of Certifie EERC 76-16 76/06/30 78pp 09154 288 24X Fiche 50-26, 81/07/17, 8107270154
- ---Bi07270194 "Strength of Timber Roof Connections Bub yetted to Cyclic Loads "

  6ULKAN.P., MAYES.R.L., CLOUGH.R.W. California, Univ. of, Berain, UCB/EERC-78/17 78/09/30 171pp 09195 009 24X Fiche 50-266.81/07/17.8107270196
- "-8107270176" Literature Survey Transverse Strength of Hasoniy Walls" GMATE.Y. MAYES.R L., CHEN.S J. California, Univ. of Derials, UCB/EERC-77/07 77/03/31 149pp 09155 140 24X Fiche 50-266.81/07/17.8107270156
- --8107270198 "Literature Survey Compressive Tensile Bond & Sher of Masonry "
  MYES, R L , CLOUGH, R W California, Univ of Derkaley EERC 75-15 75/06/30 212pp 09155 286 24X Fiche 50-266,81/07/| 8107270136
- --8107270197 "State-of-the-Art in Seismic Shear Strength of Hast-s, Evaluation & Review "
  HAYES: R L. (CLOUGH: R W California: Univ of, Berteley Eff. 75-21 75/10/31 147pp 09156 135 24X Fiche 50-266.81/074/19107270156
- 82:0070007 Responds to FDIA request for eight categories of rerording steem generators & steem turbines App A documents provided in R Vdell FOIA Request 81-313 Forwards documents listed in App R.
  FELTON, J M Division of Rules and Records 82/08/10 LOMP, D J Winthrop. Stimson. Putnam & Roberts 9pp 15645 060 24K Fiche 50-000, 82/08/10,8210070007
- --8210070139 Forwards tabulated data on steam generator into be approximated to licensees

  FPPOLITO.T Operating Reactors Assessment Branch 82/04/01

  VAROA-B Operating Reactors Branch 1. 5pp 15645 131 241

  Fiche 50-000,82/08/10,8210070007
- ~-B210070172 Forwards info re steam generator integrity & imposits operating PMRs, per 750920 & 21 requests Details of integrity including defect indications tube plugging criteria & luses glugged will not be provided except for Point Deach I OOLLER.K R Division of Reactor Licensing (MRR-1975 only) 75/03/24, MACCARY.R Division of Technical Review (MRR-1910 only) 5pp 15445 196 24X Fiche 50-000, 82/08/10, 8210070007
- 8210040414 Forwards Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of Issuance & availability Amends revise inservice insp Tech Bpec CLARK, R A Dperating Reactors Branch 3, 82/08/31 FAY, Wisconsin Electric Power Co 5pp 15597 194 24X Ficher 50-266, 82/08/31,8210040414
- --8210040420 Amends 63 & 68 to Licenses DPR-24 & DPR-27.respectively revising language of Tech Specs re inservice insported programmers of safety class components to conform W/10CFR90.55
  CLARK.R.A. Operating Reactors Branch 3 82/08/31 16ff 13597 139 24X Fichs.50-266.82/08/31.8210040414
- --8210040425 Bafaty evaluation supporting Amends 63 & 68 to Littles DPR-24 & DPR-27, respectively. \* Office of Nuclear Reactor Regulation, Director 82/08/31 & 15597-155. 24X Fichs 50-266.82/08/31.8210040414

- --E205210571 "Point Beach Nuclear Plant Units 1 & 2 Inservice Insp Program Technical Evaluation Rept" Science Applications, Inc. NRC-03-82-096 SAI-186-028-22 82/05/15 NRC - No Detailed Affiliation Given 20pp 15597 159 24X Fiche 50-266, 82/08/31,8210040414
- --P210040427 Notice of issuance & availability of Amends 63 & 68 to Licenses DPR-24 & DPR-27.respectively CLARY.R A Operating Reactors Branch 3 82/08/31 3pp 24X Fiche 50-266.82/08/31.8210040414
- --9210050194 Natice of violation from Insp on 820503-04 & 0615 MEPPLER.J G Region 3. Office of Director 62/09/15 3pp 15611 118 24X Fiche 50-266. 82/09/15.8210050186
- --8210050205 IE Insp Repts 30-266/82-12 & 50-301-82-12 on 820503-04 & Obi5 Moncompliance hoted failure to control access to high radiation areas & failure to follow approved procedures LOVENDALE, P c , HAGUE, R L , GREGER, L R Region 3, Office of Director 82/07/13 8pp 15611 121 24X Fiche 50-266,82/07/15,8210050186
- 8210050256 Requests relief from ASME Section XI, inservice insprequences frequency of reactor vessel interior exam FAY.C II Bisconsin Electric Power Co 82/09/29 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 4pp 15610 286 24X Fiche 50-266, 82/09/29, 8210050256
- 9210190669 Forwards IE Insp Repts 50-266/82-20 & 50-301/82-80 on B20914-16 No noncompliance noted LITTLE:N S Division of Engineering & Technical Programs B2/10/04 BURSTEIN:S Wissonsin Electric Power Co 2pp 15738 152 24X Fiche 50-266 82/10/04 821019069
- --8210190675 IE Insp Repts 50-266/82-20 & 50-301/82-20 on 820914-16 No noncompliance noted Major areas inspected surveillance & callbr procedures & performance history HASSF.R A . PEGCHEL.J M . HAWKING.F C Division of Engineering & Technical Programs 82/09/29 App 15738 154 24X Fichs 50-266.82/10/04.8210190669
- 8208190293 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Byc list encl COBB-t I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24< Fiche 50-000,82/10/06,8208190233
- 8208190238 IE Builetin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Paping at BWR Plants "Svc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co, of New York 135pp 15810 125 24% Fiche 50-000, 82/10/14, 8208190238
- A Periodic operating reports & related correspondence
- E210150150 Forwards monthly operating repts for Sept 1982 FAV.C N Hisconsin Electric Power Co B2/10/11 Office of Nuclear Reactor Regulation, Director Ip 15697 074 24X Fiche 50-226.82/10/11.8210150150
- --E210150158 Monthly operating repts for Sept 1982 FAY: C W Hisconsin Electric Power Co 82/10/04 8pp 15697 075 24X Fiche 50-266:82/10/11,8210150150
- S Reportable occurrences, LERs & related correspondence
- B210120380 Advises that operator action necessary to protect B&W plants from excessive feedwater transients B&W plants do not employ high steam generator level turbine or reactor trips to protect against transients CRESNELL. J S Director's Office. 80/09/12 HICHELBON, C. Director's Office 34pp 15689 286 24X Fiche 50-327, 80/09/12, 8210120380
- 9210060325 Forwards updated LER 82-005/01T-0 FAY.C W Hisconsin Electric Power Co 82/09/28, KEPPLER, J G. Region 3, Office af Director ip 15616 022 24X Fiche 50-301,82/09/28,8210060325

- --8210060333 Updated LER 82-005/01T-1 on 820727, discovered 2 of 3 level instruments on C boric acid storage tank powered from common source Cause not determined due to poor early maint of documents Wining corrected
  FAY, C W Wisconsin Electric Power Co 82/09/28 Region 3, Office of Director 5pp 15616.023 24X Fiche 50-301,82/09/28, 8210060328
- T Hearing transcripts on non-antitrust matters
- 8210080052 Transcript of 821006 telephone conference to discuss rescheduling of hearing in Mashington.DC Pp 1.342-1.352 \* Atomic Safety and Licensing Board Panel 82/10/06 12pp 15643 224 24X Fiche 50-266.82/10/06.8210080052
- DOCKET 50-302 CRYSTAL RIVER NUCLEAR FLANT, UNIT 3

  F Security, medical, emergency & fire protection plans
- 8210270227 Forwards IE Safeguards Insp Rept 50-302/82-17 on 820706-09 & notice of violation. Notice of violation & rept details withheld (ref 100FR73. 21)
  LEWIS.R C Division of Project & Resident Programs 82/07/26
  HANCOCK.J A Florids Power Corp 2pp. 15823.007 24X
  Fiche 50-302.82/07/26.8210270227
- --8210270239 IE Safeguards Insp Rept 50-302/82-17 on 820705-09 Noncompliance noted failure to initiate adequate compensatory measures Details withheld (ref 10CFR73 21) PERNY, C. MCOUIRE, D. R. Division of Engineering & Technical Programs 82/07/22. 1g 15823 009. 24% Fiche.50-302,82/07/26, 8210270229
- B210260370 Ack receipt of 820825 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-302/82-17 Encl containing safeguards info withheld (ref 10GR73 21)
  LEMIS.R C Division of Project & Resident Programs 82/09/17 HANCOCK, J A Florida Power Corp 2pp, 15804 255 24X
  Fiche 50-302,82/09/17,8210260370
- --8210260377 Forwards response to NRC 820726 ltr re violations noted in IE Safeguards Insp Rept 50-302/82-17. Details withheld (ref iOCFR73 21 & iOCFR2 770)
  BAYMARD, F Y. Florida Pawer Corp 82/08/25 O'REILLY, J P Region 2, Office of Director ip. 15804 257 24% Fiche 50-302, 82/09/17, 8210260370
- 8210010379 Ack receipt of 820907 ltr informing NRC of steps taken to correct swargency planning deficiencies noted in IE Insp. Rept 50-302/82-08 LEWIS,R.C. Division of Project & Resident Programs 82/09/20. HANCOCK, J.A. Florida Power Corp. Ip. 15573-053 24% Fiche 50-302, 82/09/20, 8210010379.
- 8210010044 Ack receipt of 820901 ltr informing NRC of steps taken to correct emergency preparedness deficiency noted in IE
  Emergency Preparedness Appraisal Rept 50-302/81-14
  LEWIS.R C Division of Project & Resident Programs 82/09/22.
  HANCOCK, J.A. Florida Power Corp ip 19548-320 24X
  Fithe \$0-302, 82/09/22, 8210010044
- --8210010049 Responds to NRC 810911 ltr re emergency preparedness deficiency noted in IE Emergency Preparedness Appraisal Rept 50-302/81-14. Corrective actions new meteorological tower to be built west of plant.

  MARDIS.D G. Florida Power Corp. 82/09/01 D'REILLY, J. F. Region 2. Office of Director 1p 15565 321. 24X Fiche. 50-302, 82/09/22, 8210010044
- 8210260008 Releases public version of revised radiological emergency response plan
  FELTON-J.M. Division of Rules and Records. 82/10/05. Document Management Granch. 1p. 15811.001. 24X Fiche 50-302,82/10/05, 8210260008.
- --8210260010 Forwards public version of Revision 1 to radiological emergency response plan, in response to NRC 820408 ltr 8AVNARD, P Y. Florida Fower Corp. 82/09/28. O'REILLY, J. P. Region 2. Office of Director ip 15811 002. 24X Fiche: 50-302, 82/10/05, 8210260008
- --8210260012 Public version of Revision 1 to radiological emergency response plan.
  4 Florida Power Corp. 82/08/27, 388pp. 15811 003 24X Ficha: 50-302,82/10/05,8210260008

- 8210260309 Ack receipt of 821015 ltr informing NRC of steps taken to correct violations noted in IE Safeguerds Insp Rept 50-302/82-17
  - S05-302/02-17 LEMIS.R C Division of Project & Resident Programs 62/10/22 HANCOCK.J A Florida Pover Corp ip 15802 361 24X Fiche 50-302,62/10/22,6210260309
- ~-8210260310 Responds to NRC 820917 ltr re violations noted in IE Safequards Insp Rept 50-302/82-17 Corrective actions withheld (ref 100FR2 790 & 100FR73 21) BAYNARD.P Y Florida Power Corp 82/10/15 D'REILLY,J P Region 2, Office of Director ip 15802 362 24X Fichs 50-302,82/10/22,8210260309
- P Operating license stage documents & torrespondence
- 8210180010 Forwards request for addl info re Unresolved Safety Issue B-24 re operability of purge valves STOLE, J F Operating Reactors Branch 4 B2/09/20 HANCOCK, J A Florida Power Corp 7pp 15717 353 24X Fiche 50-302, B2/09/20, B2t0180010
- 8210180035 Advises that plant emergency feedwater automatic initiation to flow indication sys comply w/NRC long-term safety-grade requirements w/exception re control room indication of overriding automatic initiation capability STOLZ-J F Operating Reactors Branch 4 82/09/27 HANCOCK, J A Florida Power Corp 7pp 15746 260 24% Fiche 50-302,82/09/27,8210180035
- --8208190290 "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication, Crystal River Unit 3." technical evaluation rept KAUCHER. J E Franklin Institute/Franklin Research Center NRC-03-79-118 TER-C5257-282 82/08/17 KENDALL.R NRC Na Datailed Affiliation Given 16pp. 15746 267, 24X Fiche 50-302,82/09/27,8210180035
- 8210060198 Submits update to 801106 responses to interim reliability evaluation program study recommendations No further comments offered BAYMARD.P Y Florida Power Corp 82/09/29 STOLZ.J F Operating Reactors Branch 4 5pp. 15614 010 24% Fiche 50-302,82/09/29,82/090198
- 8210060263 Submits primary test results re yearly goal for containment purging timesper TMT Action Item II E 4 2, based on data collected during 30-day test period which began on 820723 BAYNARD.P Y Florida Power Corp. 82/09/29 STOLZ, J.F. Operating Reactors Branch 4 2pp 15821 063 24% Fiche 50-302,82/09/29, S210040263
- 8210150216 Requests exemption from 10CFR50 44(c)(3)(iii) requiring reactor vessel head high point vent Alternative methods for vant performance provided in util 810130 submittal, in response to NUREO-0737, Itam II B.1 BAYNARD, P Y Florida Power Corp. 82/10/12. 8TOLZ, J.F. Operating Reactors Branch 4. 3pp. 15705-283. 24X Fiche 50-302,82/10/12, 8210130216.
- 8210190691 Provides add1 info re dose calculations for NUREQ-0737, Item
  II B 2. " Design of Plant Shielding & Environ Qualifications
  of Equipment for Spaces/Bys Which May Be Used in PostAccidant Operations "
  Y Floride Power Core B2/10/12 BT0 2-15 Communications
  - Y Florida Power Corp 82/10/12 STOLZ, J F Operating 'ranch 4. 2pp 15736 201 24X Ficha, 50-302, 82/10/12,

'erm work schedule re NUREQ-0630,
'iddels for LOCA Analysis." not
is to incomplete short-term
id w/NRC approval of rept
irp 82/10/14 LAINAS, 0 C, Assistant
i, 1p, 13738-145 24X
Al

fvisors licensed at senior
: & NUREO-0737.
'rent candidates

EISENHUT, D Q Division

itian

Operating /10/18:

- 8210260436 Forwards revision to 820219 submittal re calculations a measurements of bus voltages used to demonstrate adequacy of electrical distribution sys
  BAYNARD.P Y Florida Power Corp 82/10/19 STOLZ.J F Operati
  Reactors Branch 4 45pp 15806 246 24X Fithe 50-302.82/10/19.
  8210260436
- 8210240422 Requests concurrence w/interim plan to maintain lines [3]] for chemistry control in once-through steam generators in high energy line state during each startup until Refuel V Condition reported in LER 82-058 Amend fee will be tent BAYNARD, P Y Florida Power Corp 82/10/22 SYOLZ, J F Optical Reactors Branch 4 2pp 15806 312 24X Fiche 50-302,62/10/22 8200260422
- 8210260454 Updates status of safe-end task force action plan Task force activities expected to be concluded by 821231 Final rept & recommended implementation plans will be submitted by 830121 BAYNARD, P Y Florida Power Corp 82/10/22 BTOLZ, J F Datato Reactors Branch 4 3pp 15807 120 24X Fiche 50-302, 82/10/22
- 8210260497 Submits responses to Encl 1. Questions 1 & 2 in MRC 82.70 if the Generic Item 8-24, "Operability of Purge Valves" Wifive oversize drawings Aperture cards are available in PDR BAYNARD, P Y Florida Power Corp 82/10/22 STOLZ. J F Operat. 8 Reactors Branch 4 Jpp 15805 244 24X Fiche 50-302,02/10/22 8210260497
- a Inspection reports, IE Bulletins & correspondence
- 8210080015 Addi response to FOIA request for 19 categories of left nuclear reactor events & safety problems Forwards documents I isted in App A Documents in App B completely withheld light FOIA Examption 5)
  FELTON-J M Division of Rules and Records 82/07/12 UDFIL-M & Critical Mass Energy Project 9pp 18665 027 24%
  Fiche 50-000,82/07/12,8210080015
- --8210080125 Bystematic assessment of licenses performance note; re facility evaluation for May 1979-Apr 1980 \* NRC - No Detailed Affiliation Oliven 80/04/30 7pp 15667 327 24X Fiche 30-000, 82/07/12,8210080015
- B210270229 Forwards IE Safeguards Insp Rept 50-302/B2-17 on 020742 & notice of violation Notice of violation & rept details withheld (rep 10CFR79 21)

  LEWIS-R C Division of Project & Resident Programs B2/07/21 HANCOCK, J A Florida Power Corp 2pp 15823 007 24x
- --BR10270239 IE Bafeguards Insp Rept 50-302/B2-17 on 040704 07
  Noncompliance noted failure to initiate adequate
  compensatory measures Details withheld (ref 100FR73 21)
  PERNY.C. MCQUIRE.D R Division of Engineering & Tachnical
  Programs 82/07/22 ip 15823 007 24X Fiche 50 302.67/1.a.
  8210270229
- 8210260370 Ack receipt of 820825 ltr informing NRC of steps talining correct violations noted in IE Safeguards Insp Rept 50-302/82-17 Encl containing safeguards info withheld (ref 100FR73 21)
  LENIS, R.C. Division of Project & Resident Programs 82/09/11
  HANCOCK, J.A. Florida Power Corp. 2pp 15804 255 24x
  Fiche 50-302,82/09/17,8210260370.
- 8210010379 Ack receipt of 820907 itr informing NRC of slaps latex correct emergency planning deficiencies noted in IE less Rept 50-302/82-08
  LEMIS:R C Division of Project & Resident Programs #2/09/22 HANCOCK, J. A Florida Power Corp 19, 19573 053.
- 8210010044 Ack receipt of 820901 ltr informing NRC of steps talest correct emergency preparedness deficiency noted in IC Emergency Preparedness Appraisal Rept 50-302/81-14 LEWIS.R.C. Division of Project & Resident Programs 82/01/22 HANCOCK, J.A. Florida Power Corp ip 15565:320 28x Fiche 50-302,82/09/22,8210010044

- --E210010049 Responds to NRC 810911 ltr re emergency preparedness deficiency noted in IE Emergency Preparedness Appraisal Rept 50-302/81-14 Corrective actions new meteorological tower to be built west of plant MARDIS.D G Florida Power Corp 82/09/01 0'REILLY, J P Region 2. Office of Director 1p 15559 321 24X Fiche 50-302,82/09/22,8210010044
- 8208190233 |E Info Notice 80-35, Suppl t. "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards. 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000.82/10/06.8208190233
- 9208190238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick-Hall. Large-Diameter. Stainless Steel. Recirculation Sys
  Piping at BNR Plants "Svc list encl
  OEYGUNG.R C Director's Office. Office of Inspection and
  Enforcement 82/10/14 Consolidated Edison Co of New York
  115pp 15810 125 "24X Fiche 50-000.82/10/14.8208190238
- 8210280309 Ack receipt of 821015 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-302/82-17

  LEMIS.R C Division of Project & Resident Programs 82/10/22.

  HANCDCK.J A Florida Power Corp 1p 15802 361 24X

  Fiche 50-302. 82/10/22.8210260309
- --6210260310 Responds to NRC 620917 ltr re violations noted in IE Safeguards Insp Rept 50-302/62-17 Corrective actions withheld (ref 10CFR2 790 & 10CFR/3 21) EAVNARD, P Y Florida Power Corp 62/10/15 G'REILLY, J P Region 2. Office of Director ip 15802 362 24X Fiche 50-302, 82/10/22, 8210260309
- S Reportable occurrences, LERs & related correspondence
- 8004020420 Discusses decay heat closed cycle cooling water pump motor being out of spec Caused by inadequate lubrication Problem highlights volnerability of nuclear power plants to inadequate lubrication Specs & work order encl ORMSTEIN.H L Director's Office 80/03/20 MICHELSON,C Director's Office 4pp 15649 239 24X Fiche 50-302,80/03/20,8001020420
- 8210120380 Advises that operator action necessary to protect I&W plants from excessive feedwater transients B&W plants do not employ high steam generator level turbine or reactor trips to protect against transients
  CRESWELL, J & Director's Office 80/09/12 MICHELSON, C
  Director's Office 34pp 15689 286 24X Fiche 50-302,80/09/12, 62:0120380
- 8010230435 Forwards summary of 800930 transient, alligator clip event While at 100% power, instrument test leads fell causing feedwater runback & control rod insertion CRNSTEIN.H L Director's Office 80/10/08 MICHELBON,C Director's Office 30p 15692 265 24% Fiche 50-302,80/10/08, RM10330230
- 3012290iiB Discusses conclusions of engineering evaluation of stram generator overfill transients at C-E & Westinghouse plants
  LAMNING. H D Director's Office 80/10/29 MICHELBON, C Director's
  Diffice 3pp 15692 262 24% Fiche 50-000:80/10/29.8012290iiB
- 3210010000 Responds to F01A request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON. J M Division of Rules and Records 82/06/28 UDELL, R. A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000 82/06/28.8210010008
- --B106150555 Informs that ESFAS relay failure reviewed to determine significant number of failures, safety consequences & qualifications of ESFAS relays Failure considered simple isolated event & does not warrant further action LAINAS.0 C Assistant Director for Safety Assessment B1/05/05. EISEMHUT, D 0 Division of Licensing 2pp 15730 137 24X Fiche 50-000,82/04/28,8210010008
- --8109080417 Concludes that no add1 actions are required re engineered eafeguards relay failures Various relays, including new Crydon relays, should be monitored as watch list items Failures after Sept 1981 outage should be reviewed CHIRAMALM Director's Office 81/08/28 MICHELSON, C Director's Office 2pp 13730 128 24% Fiche 30-000, 82/06/28, 8210010008

- --8210010161 Discusses potential problem re Saquoyah reactor pressure nozzle, supplementing 800222 memo Underclad cracks found by use of ultrasonic equipment Addl stems of recent origin discussed Related sno encl
  DENTON.H R Defice of Nuclear Reactor Regulation, Director 80/02/28 AMEARNE.J. GILINSKY,V., KENNEDY,P. Commissioners 7pp 15727 178 24X Fiche 50-000,82/04/28,8210010009
- 8210130310 Forwards LER 82-045/03L-0
  HANCDCK. J A Florida Power Corp 82/10/01 D/REILLY. J P Region
  2. Office of Director 1p 15478 338 24X Fishe 50-302.82/10/01.
  8210130310
- --B210130319 LER B2-045/03L-0 on B20704, emergency feedwater ultrasonic flow indicator FM-313-FI discovered insperable & train B arbitrarily declared insperable Caused by failed power supply. Power supply replaced & indicator repaired FORD, E W Florida Power Corp 92/10/01 Region 2, Office of Director 2pp 15678 339 24% Fiche 50-302, 82/10/01, 8210130310
- 8210130520 Forwards LER 82-057/03L-0 HANGUCK, J A Florida Power Corp 82/10/01 D'REILLY, J F Region 2. Office of Director 1p 15682 352 24X Fiche 50-302.82/10/01.
- --B210130530 LER 82-057/03L-0 on 820527.containment isolation valve in svc water sys (SWV-49) not stroke time tested following maint Caused by personnel failure to include stroke time testing in work request Naint planners instructed FORP.E W Florida Power Corp. 82/10/01 Region 2, Office of Director 2pp 15682 353 24X Fiche 30-302,82/10/01.8210130520
- 8210190677 Forwards LER 92-058/01T-0 LUTKEHAUS, T C Florida Power Corp 82/10/08 O'REILLY. J P Region 2. Office of Director 1p 15738 162 24X Fiche 50-302,82/10/08, 8210190677
- --8210190487 LER 82-058/01T-0 on 820724, valve lineups identified which allow once through steam generator drain lines to be used for blowdown operations & also allows high energy fluid through lines Caused by inadequate review of sys design WILSDN.K R Florida Power Corp 82/10/08 Region 2, Office of Director 2pp 15738 163 24X Fiche 50-302,82/10/08,8210190677
- 8210190271 PNO-II-82-313 on 821014.rise in airborne radioactivity levels in reactor bldg detected Caused by leak in vicinity of reactor coolant drain tank Unit shut down & will be out of svc for about 3 wks to investigate & repair leak ROGGE, J.F., BROWNLEE, V.L. Rogion 2, Office of Director 82/10/15. 2p 15737 241 24% Fiche 50-302,82/10/15,8210190271
- 8210220052 Forwards LER 82-059/03L-0.

  HANCOCK.J A Florida Power Corp 82/10/15 O'REILLY.J P Region 2. Office of Director 1p 15778 207 24% Fiche 50-302,82/10/15,82/0220052
- --8210220086 LER 82-059/031-0 on 820915 valve DHV-iii on decay heatline B failed to control flow Caused by inoperable flow switch Switch replaced & calibr & DHV-iii functionally tested u/satisfactory results. HUGHES.P.O Florida Power Corp 82/10/15 Region 2, Office of Director 2pp 15778: 208 24X Fiche 50-302,82/10/15,8210220052
- 8210290186 RO 82-058.high energy lines exist in reactor bldg Study on restraining lines for pips whip completed. Alternatives under review Requests approval to maintain lines until Refuel 5 BAYNARD. PY Florida Power Corp 82/10/22 STOLZ. J. F. Operating Reactors Branch 4 2pp 15853 309 24% Fiche 50-302, 82/10/22, 8210290186
- 8210290312 Informs that special rept supposedly enc1 in 821001 submitted LER 82-045 determined to be more useful as basis of Tech Spec change request to be submitted at later date. BAYKARD. P V Florida Power Corp. 82/10/25. O'REILLY, J P. Region 2. Office of Director 1s 15853.138 24X Fiche 50-302,82/10/25. 82/10/25.
- DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8209290125 Releases gublic version of revised generating station emergency plan corporate command our emergency plan implementing procedure.
  FELTON, J M. Division of Rules and Records 82/09/16 Document Management Branch 1p. 15564,122 24X Fiche: 50-000,82/09/16,8209290125.

- --B209290189 Forwards public version of Revision 4 to generating station emergency plan corporate command ctr Emergency Plan Implementing Procedure EOF-3. "Environ/Emergency Coordinator "Receipt form enc! PAJOHGKI.J E Commanwealth Edison Co 82/09/01 DENTON, H R NRC No Detailed Affiliation Given ip 15564.123 24X Fiche 50-000, 82/09/16, 8209290125
- --8209270225 Public version of Revision 4 to generating station emergency plan corporate command ctr Emergency Plan Implementing Procedure EOF-3, "Environ/Emergency Coordinator" PAVGMSKI.J E Commonwealth Edison Co 82/08/31 11pp 13544 124 24X Fiche 50-000, 82/09/16, 8209270125
- 8210080029 Releases public version of revision to emergency plan implementing procedure FELTON, J H Division of Rules and Records 82/09/22 Document Management Branch ip 15669 207 24X Fichs 50-295,82/09/22, equipped 200
- --B210080030 Forwards public version of Revision 3 to Emergency Plan Implementing Procedure EPIP 550-3. "Radiological Supplies for Medical Emergencies "Receipt form enci PLIML.0 Commonwealth Edison Co 82/09/07 DENTON, H R NRC ~ No Debailed Affiliation Given ip 15569:308 24X Fiche: 50-295,82/09/22,82(0080029
- B210050207 Forwards revised exemption requests from provisions of iOCFR50, App R. Bection III. 0 2 re post-fire shutdown capability, per 820917 telicon LENTINE, F G Commonwealth Edison Co B2/10/01 DENTUN, H R Office of Nuclear Reactor Regulation, Director. 30pp. 15611 086 24X Fiche 50-295.82/10/01.8210050207.
- 8210130376 Advises that installation of offsite dose calculation syn program fully operational tracking model & operational A-model will be delayed until 821231 to complete prime computer installation EMART7.E D Commonwealth Edison Ca 82/10/06 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 15682 078 24X Fiche 50-000, 82/10/06, 8210130376
- 8210290047 Releases public vertion of revisions to Qued Cities, Zion & Dresden emergency plan annexes & revised generating station amergency plan telephone directory. FELTON, J H Division of Rules and Records B2/10/08 Document Management Branch 1p. 15877 313 24X Fiche 50-000, 82/10/08, B210290047.
- --B210290040 Forwards public version of Revision 3 to Quad Cities & Zion emergency plan annexes. Revision 2 to Dresden emergency plan annex. Revision 0 to Byron emergency plan annex & revised generating station emergency plan telephone directory MODRE.R D. Commonwealth Edison Co. 82/07/30. DENTON, H R NRC No Detailed Affiliation Given Spp. 15877 314 24% Fiche 50-000, 82/10/08. B210290047
- ---8210370077 Public version of Revision 3 to Quad Cities & Zion emergency plan annexes. Revision 2 to Dresden smergency plan annex & Revision 0 to Byron smergency plan annex & Revision 0 to Byron smergency plan annex & Commonwealth Edison Co 82/06/30 325pp 15877,319 24X Fiche, 50-000, 82/10/08, 8210270047.

- 8210280419 Releases public version of revised emergency plan implementing procedure FELTON. J H Division of Rules and Records 82/10/12 Doctor-6 Hanagement Branch 1p 15860 001 24X Fiche 50-295, 62/10/12, 8210280419
- ~-8210280424 Forwards public version of Revision 5 to Emergency Fial Implementing Procedure 110-1. "Station Director " Procedure inchenge request & receipt forms encl PLING. G Commonwealth Edison Co 82/09/17 DENTON.H.R HRC Page 114 April 12 Page 12 Pag
- --8210280427 Public version of Revision 5 to Emergency Plan Implessive Procedure 110-1. "Station Director " Revised index encl # Commonwealth Edison Co 82/09/16 5pp 15860 004 24x Fiche 50-295.82/10/12.8210280419
- 8210280442 Releases public version of revised emergency plan implementing procedure FELTON. JM Division of Rules and Records 82/10/12 Decest Management Branch. ip 15859 001 24X Fiche 50-295.82/10/12.
- --8210280445 Forwards public version of Revision 4 to Emergency Play implementing Procedure EPIP 550-2. "Environ Emergency Kit & Emergency Operations Facility Radiological Equipment Receipt form encl PLIML 0 Commonwealth Edison Go 82/09/10. BENTGM: IF Not 1 Detailed April iation Given ip 15859 002 24X Fiche 50-295,82/10/12,8210280442
- ~-8210280447 Public version of Revision 4 to Emergency Plan Implementing Procedure EPIP 550-2. "Environ Emergency Kit & Emergency Operations Faculity Radiological Equipment" Procedure change request form enci # Commonwealth Edison Co. 82/09/03 8pp 15057 003 24x Fiche 50-295,82/10/12.8210280442
- B21022035B Provides info re organization & performance of dapts responsible for rediation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs.

  TRAMM.T.R Commonwealth Edison Co 82/10/14 DENTON.H.R DFF of Nuclear Reactor Regulation, Director 9pp 15776 287 241 Fiche 50-000, 82/10/14,821022035B
- 8210280405 Notification of 821028-29 meetings w/util & DNL in Privio MD to discuss & resolve questions on proposed exemption to App R WIGOINTON D Operating Reactors Branch 1 82/10/22 VARGA 9 a Operating Reactors Branch 1 2pp 15859 327 24X Fiche 80-295.82/10/22.8210280405
- H General correspondence
- 8210210235 Comments on facility operation NRC should deny util permission to use high burnup nuclear fuel Evidence supporting continued operation of facility should be provided to public GUIGO.C Follution & Environmental Problems. Inc B2/10/13 Director's Office, Office of Inspection and Enforcement 59: 15766.259 24X Fiche 50-295.82/10/11.8210210235
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- 8210270408 Comments on probabilistic risk assessment per BLP21 math. General mathods & principles employed in analysis of possible earthquake shaking & site appear to apply modern state of art techniques.

  TRIFUNAC.M D Southern Californie, Univ of TRIFUNAC.M D AMAIVISOTY Committee on Reactor Safeguards 82/02/23 QRISMITT. ACR8 Advisory Committee on Reactor Safeguards 3pp 15022324 Ficher 30-295,82/02/23,82/0274048.
- P. Operating license stage documents & correspondence
- 8007150303 Notifies that review will be conducted of Offshore feet short-term risk studies using various resources, in respent to 800605 request Evaluation will be submitted by 800922 MATTSON.R J. Division of Bafety Technology 80007702 EIBENHUT, D. Q. Division of Licensing. 2pp. 02952 SOI. 244 Fiche 50-247, 80/07/02, 8007150303.
- 82:0070007 Responds to FOIA request for eight categories of emericant steam generators & steam turbines App A documents provided in R Udell FOIA Request Bi-GIG Forwards documents listed in App B.

  FELTON.J M Division of Rules and Records 82/08/10 LOM. BJ Winthrop. Stimson. Putnam & Roberts 9pp. 13645:063 241 Fiche: 50-000. 82/08/10.8210070007

- -8203110403 Forwards response to JD Dumele, chairman of Pollution Control Board, State of IL. questions in 820127 ltr
  JOHNISTON, H V Assistant Director for Materials & Qualifications Engineering 82/02/22 LAINAS. G Assistant Director for Safety Assessment 2pp 15645 126 24X Fiche 50-000, 82/08/10. 8210070007
- 239160503 Supple 820831 ltr re 820908 meeting at Region 3 ofc Recent operation of Unit 2 w/two inoperable auxiliary feedwater pumps added to agenda MEPPLER, J G Region 3. Office of Director 82/09/03 REED, C Commonwealth Edison Co ip 14904 087 24X Fiche 50~295.82/09/03, 8209160503
- 210040218 Requests reaffirmation of technical basis for operation at 200% gower Significant financial penalties incurred due to operation in overly conservative manner STIEDE. W. L. Commonwealth Edison Co. 82/09/27 DEYGUNO. R. C. Director's Office. Office of Inspection and Enforcement 3pp 15583 115 24% Fiche 50-295,82/09/27,8210040218
- 210080111 Forwards completion status & revised schedule for improvements made to control room display since 1980 rept, per 900229 confirmatory order LENTINE; F G Commonwealth Edison Co 82/10/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 15640 022, 24X Fiche 50-295, 82/10/04, 8210080111
- 210120105 Requests delay of implementation due dates re NUREO-0737, Items II B 2. "Plant Shielding," II B 3, "Post-Accident Sampling" & II F 1 1. "Noble Gas Effluent Monitor "SHARTZ.E D Commonwealth Edison Co 82/10/04 EISENHUT, D Q Division of Licensing 5pp 15651 237 24% Fiche 50-000,82/10/04. 8210420105
- 'IO260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calcutation Manual" GOLDEN.J C Commonwealth Edison Co 82/10/06 CASE,E 0 Office of Nuclear Reactor Regulation, Director 2pp 15805-137 24X Fiche 50-000. B2/10/06
- 8210260542 Revision 3 of Chapter 9 of "Offsite Dose Celculation Manual"

  Commonwealth Edison Co 82/09/30 83pp 15805 139 24X
  Fithe 50-000, 82/10/04, 8210260526
- 10220399 Suppls 820414 response to Franklin Research Ctr 811005 draft technical evaluation rept re control of heavy loads (NUREO-0612), per 820824 & 25 telcons
  LENTINE,F 9 Commonwealth Edison Co 82/10/12 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 15777 329 24% Fiche 50-275,82/10/12,8210220399
- 10170443 Forwards addl info re NUREG-0737, Item II B 3, "Post-Accident Sampling Sys." in response to NRC 820722 ltr
  Util currently pursuing possibility of developing procedure to estimate core damage via Westinghouse pumers group SHARTZ.E D Commonwealth Edison Co 82/10/13 EISENHUT.D 0 Division of Licensing 15pp 15741 187 24X Fiche 50-295,82/10/13,8210/190443
- 10270344 Notification of 821115-16 meetings Wutil in Olen Ellyn, IL to discuss bases for current inservice testing proposed exemption, including alternatives to required inspections Fig. 10210702 VAROA, S.A. Diperating Reactors Branch i B2/10/22 VAROA, S.A. Diperating Reactors Branch i 2pg 15851,354 24X Fich 50-295,82/10/22,8210270344

# Inspection reports, IE Bulletins & correspondence

- 10070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines.App A documents provided in R Udell FOIA Request 81-013 Forwards documents listed in App B FELTON.J M Division of Rules and Records 82/08/10. LONG.D.J.
- TELTON.J H Division of Rules and Records 82/08/10. LONG.D.J. finthrop. Stimson, Putnam & Roberts. 9pp. 15645.063 24X Tiche 50-000.82/08/10.8210070007
- 3210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees
  IFPOLITO T Operating Reactors Assessment Branch 92/04/01
  VARQA, 8 Operating Reactors Branch 1 5pp 15645
- 3210070172 Forwards info re steam generator integrity & insps at all operating PHRs.per 750320 & 21 requests. Details of insps. including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Basch i. GOLLER.K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY.R R Division of Technical Review (NRR-1975 only) 5pp 15645 196 24X Fichs 50-000.82/08/10.8210070007.

- 8210190568 Forwards IE Enforcement Conference & Insp Repts 50-295/82-19 & 50-304/82-17 on 820717-0909 & natice of violation SPESSARD, R L Division of Project & Resident Programs REED, C Commonwealth Edison Co 2pp 15736 112 24X Fiche 50-295, 82/09/30, 8210190568
- --8210190579 Notice of violation from insp on 820717-0831 \* Division of Project & Resident Programs 82/09/30 ip. 15736 113 24X Fiche 50-295, 82/09/30, 8210190568
- --8210170597 IE Enforcement Conference & Insp Repts 50-295/82-17 & 50-304/82-17 on 820717-0707 Noncompliance noted failure to follow 800227 confirmatory order requiring expeditious shutdown whenever auxiliary feedwater sys inoperable (WATERS, J R, SCHNEIDER, O O, REVES, L, Region 3, Dffice of Director 82/07/22 9pp 15736.114, 24% Fiche.50-295,82/09/30,8210190568
- 8210060359 Ack receipt of 820910 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-237/81-39, 50-249/81-32, 50-254/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29 SPESSARD, R L Division of Project & Resident Programs, 82/10/01 REED, C Commonwealth Edison Co Ip 15618 354 24X Fichs. 50-000, 82/10/01, 8210060359
- --B2100A03A7 Responds to NRC B20712 ltr re violations noted in IE Insp Repts 50-237/B1-39,50-249/B1-32,50-254/B1-23,50-2A5/B1-23, 50-295/B1-31 & 50-304/B1-29 Corrective actions training for mgt priorities re plant availability will be conducted REED.C Commonwealth Edison Co B2/09/10. KEPPLER, J O Region 3, Office of Director 13pp 1541B 353 24X Fiche 50-000,B2/10/01,B210040359
- 8210080178 Forwards listing of piping sys which fail to mest FBAR requirements, per NRC 800818 confirmatory action ltr. IE Bulletin 79-14 operability evaluation updates will not be provided for Dresden & Guad Cities Final update by Dec 1982. RAUSCH.T. J. Commonwealth Edison Co. 82/10/01 KEPPLER.J Q. Region 3, Office of Director App 15640:187. 24X Fichs 50-000.82/10/01, 8210080178
- 8208190233 IE Info Natice 80-35, Suppl 1, "Leaking & Dislodged I-125 implant Seeds " Svc list encl COSB, L. I. Division of Fuel Facilities, Materials & Sefeguards 82/10/06 Consolidated Edison Co. of New York 66pp 15761 250, 24X Fichs 50-000, 82/10/06,8208190233
- 8210190613 Act receipt of 820910 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/82-14 & 50-304/82-13 Interpretation of Tech Spec 1 0. D unacceptable SPESSARD.R L Division of Project & Resident Programs 82/10/07 REED. C Commonwealth Edison Co. 1p 15739 361 24X Fichs 50-295,82/10/07,8210170613
- --8210190624 Responds to NRC 820813 ltr re violations noted in IE Insp. Repts 50-295/82-14 & 50-304/82-13. Disputes NRC classification of 820625 reactor trip. Trip inadvertent Interpretation of Tech Spec 1 0 D encl.
  SYIEDE, W. Commonwealth Edison Co. 82/09/10 KEPPLER, J. 2 Region 3, Office of Director. 4pg 15740, OO1. 24X Fichs 50-275, 82/10/07, 8210190613.
- 820B19023B IE Builetin 82-03. "Btress Corrosion Cracking in Thick-Wall, Large-Diemeter. Stainless Steel, Recirculation Sys Piping at BHR Plants " Syc list encl DEYOUNO, R C. Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co. of New York 115pp. 15810 125 24X Fiche 50-000, 82/10/14, 820819023B
- B210270344 Notification of B21115-16 meetings w/util in Olen Ellyn, IL to discuss bases for current inservice testing proposed exemption including alternatives to required insps. WIGOINTON. D. Operating Reactors Branch 1. B2/10/22, VARCA, B. A. Operating Reactors Branch 1. B2/10/22, VARCA, B. A. Fiche: 50-275, 82/10/22, 8210270344
- R Periodic operating reports & related correspondence
- 8210150405 Forwards monthly operating repts for Sept 1982.

  GRAEGSER.K. L. Commonwealth Edison Co. 82/10/06. Director's Office. Office of Inspection and Enforcement 1p. 15704.003 24X Fiche: 50-295, 82/10/06. 8210130405
- --8210150411 Monthly operating repts for Bept 1982. AUSTIN:9 Commonwealth Edison Go 82/10/06. 11pp. 15704:004. 24X Fiche. 50-295, 82/10/06, 8210150405.

### S Reportable occurrences, LERs & related correspondence

- 8210070422 Recommends IE issue info notice to inform licenses of possible inadequate surveillance for proper tuning of output capacitance for certain inverters Recommendation based on 810505 & 28 sola output transformer shorts HELTEMES.C J Director's Office 81/12/10 JORDAN.E L Division of Resident & Regional Reactor Inspection 4pp 15644 285 24% Fiche 50-295,81/12/10.8210070482
- 8210010008 Responds to F01A request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records. 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82706/28.8210010008
- --Bi12210538 Forwards description of events 2 resulting action re high circulating corrent associated W/Lnverter output due to lack of circuit tuning IE circular or info notice should be issued to address issue
  HELTEMES.C J Director's Office 81/12/10, JORDAN.E L
  Director's Office 4pp 15731 361 24X Fiche.50-000,82/06/28,8210010008
- --8203090469 Responds to request to evaluate Bil211 trip of two inservice auxiliary freeGuster pumps from low suction Installation of time relay on starting circuitry of motor friven auxiliary feedwater pumps will eliminate problem ZUKOR.D Director's Office 3pp 15750 359 24X Ficher 50-000, 82/06/28, 8210010008
- --B210050075 Summary of 810513 operating reactor events Assting LAINABLC C Assistant Director for Safety Assessment B1/05/18 EISENHUT.D Q Assistant Director for Licensing App 15729 160 24X Fichs. 50-304, 82/06/28,8210010008
- 92(0040116 Forwards LER 82-021/03L-0 CRAESSER, K.L. Commonwealth Edison Go B2/09/24 KEPPLER, J O Region 3, Office of Director 1p 1558( 191 24X Fiche 50-304, 82/09/24, 8210040116
- --B210040121 LER 82-021/03L-0 on 820827, during running of 2A turbine driven auxiliary feedwater pump, flow observed on pump 2 discharge header Caused by improper procedure implementation Procedure will be revised JOHNSON.0 Commonwealth Edison Co 82/09/24, Region 3, Office of Director 19 19581 192 24X Fiche 50-304,82/09/24, 8210040116
- 8210060262 Forwards LER 82-022/03L~0 GRAEGSER,K. L. Commonwealth Edison Co. 82/09/30 KEPPLER,J & Region 3, Office of Director 1p. 15621 045 24X Fiche 50-304, 82/09/30, 8210060262
- --B210060267 LER 82-022/03L-0 on B20903, containment spray diesel-driven pump 20 failed to start during remote control room startup for mechanical maint Caused by sticty underspeed switch in closed position due to impurities Switch self-cisaned SHIM. K Commonwealth Edison Co B2/09/30, Region 3, Office of Director in 15621 066 24% Fiche 50-904, 82/09/30, 8210060262
- 82:0180167 Forwards LER 82-023/03L-0. ORAESSER, K L Commonwealth Edison Co 82/10/07 KEPPLER, J 0 Region J, Office of Director 1p 157(8 182 24X Fiche 50-304, 82/10/07, 8210180167
- --8210180175 LER 82-023/03L-0 on 820907.28 steam generator level channel 2L-549 did not track Caused by failure of transmitter (Fiveher/Porter 1302495kBABBB-NS). Transmitter replaced investigation ongoing CANTHELL-P E Commonwealth Edison Co 82/10/07 Region 3: Office of Director ip 15718 183 24X Fiche: 50-304, 82/10/07, 8210180167
- B210260219 Forwards LER 82-024/01T-0 9RAESSER, K. Commonwealth Edison Co 82/10/19, KEPPLER, J. & Region 3, Office of Director, ip 15804:262, 24X Fiche. 50-304, 82/10/19, 8210260219
- --B210260223 LER 82-024/01T-0 on 820928, while taking RCB solid, dilution occurred via incorrect makeup when conteinment integrity was not intact w/shutdown margin Caused by personnel error Operator reinstructed T'NIEMI.W D. Commonwealth Edizon Co. 82/10/19. Region 3, Office of Director. 2pp 15804:269, 24X Fiche. 50-304,82/10/19.

- NOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT
- F Security, medical, emergency & fire protection plans
- 8209170061 Forwards draft vital area definition rept for fittlity Div of Safeguards will review technical basis for rept during 880927-1001 sits visit M/o encl VAROA.5 A Operating Reactors Branch 1 82/09/08 Olester.C w Hisconsin Public Service Corp 1p 14910 106 24x Fitchs 50-305.82/09/08.8209170061
- 8210120505 Ack cooperation in planning Div of Safeguards 020927-111 regulatory effectiveness review Team will evaluate overall effectiveness of security program to determine if safeguards regulations yield acceptable level of protection EISENHUT.D 0 Division of Licensing 82/09/20 OLESLER.C Whistonish Public Service Corp Spp 15672 076 24X Fiche 50-305, 82/09/20, 8210120505
- 8210080201 Forwards IE Safety Evaluation Rept 50-305/82-17 (uring #, 1982 No noncompliance noted HIND, J.A. Division of Emergency Preparedness & Operational 8.pp. 82/09/22 GIESLERC W. Misconsin Public Service Corp. 2pp. 15640 090 24X Fiche 50-305,82/09/22,8210080201
- --8210080204 IE Safety Evaluation Rept 50-305/82-17 during Aug 1622 No noncompliance noted Major areas inspected amergency plan dtd Nov 1981 PAGLIARO, J A . AXELSON.W L Division of Emergency Preparational Operational Support 82/09/20 32pp 15640 092 24x Fiche 50-305, 82/09/22, 8210080201
- 8210130300 Forwards Revision 3 to security force training be qualification manual Revision withheld (ref. 10CFR2.740) OIEBLER: C. W. Misconsin Public Service Corp. 82/09/29 DEMICA: 1 Office of Nuclear Reactor Regulation, Director. 2pp. 156/8.2.1 24X Fiche 50-305.82/09/29,8210130300
- 8210050102 Forwards IE Bafeguards Insp Rept 50-305/82-16 on 621821-2 & notice of violation Notice of violation withheld (ref 100FR73 21) MILLER, J. R. Division of Engineering & Technical Programs 52.2 OIESLER, C. W. Wissonsin Public Barvice Corp. 2pp. 15403 595.2 Fiche 50-305, 82/09/30, 9210050102
- --8210050110 IE Safeguards Insp Rept 50-305/82-14 on 6208/3 27
  Noncompliance noted failure to certify qualifications for security force members, Datails withheld (ref 100F873 2))
  BELANGER, J. L., CREED, J. R. Region 3, Office of Director \$2 50
  1p. 15603 297 24% Fiche 50-305,82/09/30.8210050102
- B210130581 Provides info re changes to facility fire protection commitments Revised and schedule submitted in Attachment 1 of util 820804 itr should be considered most current k accurate schedule OIEBLERIC W Wisconsin Public Bervice Corp 82/10/00 PATCA-Office of Nuclear Resctor Regulation, Director 2pp 15679 CM 24X Ficha 50-305,82/10/08,8210130581
- 8210280423 Forwards one-time exemption from 10CFR50 App E.requiry emergency preparedness exercise be conducted annually EISENHUT, D G Division of Licensing 82/10/15 GIEBLER.C W Misconsin Public Service Corp 2pp 15860 014 24X Fiche: 50-305, 82/10/15, 8210280423
- --9210280425 One-time exemption from 10CFRSO App E. requiring 4m\* semergency preparadness exercise Next exercise schedulif for 831101 EISENNUT. P Q Division of Licensing 82/10/15 Niggania Public Service Corp 3pp 15860 016, 24X Fiche 50-305-88/12
- P Operating license stage documents & correspondence
- 8210010179 Application to amend License DPR-43, revising Title Series reorganization of nuclear dept GESLER, C. W. Misconsin Public Service Corp. 82/09/27 DM.: Nuclear Reactor Regulation, Director. 2pp. 15567-287 241 Fiche, 50-305, 82/09/27, 8210010179.
- --8210010186 Proposed Tech Specs reflecting organization builty, corporate nuclear engineering staff, clarifying frequency of meetings & line of authority for nuclear safety review a audit committee & showing functional responsibilities whiseometry Public Service Corp. 82/09/27 13pp 15567 穿 24X Fiche: 50-305,82/09/27,8210010179

- 8210G60312 Advises that analyses of plant-specific safety & relief valve discharge piping per NUREO-0737. Item II D 1 require more time than proposed in 820712 Ite Item resolution will be identified & implementation schedule provided by 821115 GIESLERIC W Misconsin Public Service Corp 82/09/27 EISENHUT, D O Division of Licensing ip 18619 189 24X Fiche 50-305, 82/09/27, 8210060312
- 8210130600 Informs that review of 810831 & 0915 responses to Generic Letter 81-01. "Qualifications for Insp.Exam & Testing & Audit Personnel." completed Commitments & exceptions to Pevisson 1 to Reg Guides 158 & 1 144 acceptable VARGA. S A Operating Reactors Branch 1 82/09/28 GIESLER. C W Hiscomsin Public Service Corp 2pp 15692 345 24X Fiche 30-305, 82/09/28, 8210130600
- G210210395 Forwards safety evaluation of Cameric Issue B-24, "Containment Purging During Normal Plant Operation "
  MUREG-0737, Item II E 42 will be completed by purge & vent
  review Technical evaluation encl
  VAROA: S A Operating Reactors Branch 1 B2/09/30 GIESLER, C W
  Hiscomain Public Service Corp 9pp 15772 314 24X
  Fiche 50-305,82/09/30.8210210395
- --8210210403 Safety evaluation of containment purging & venting during normal operation Request for add1 info re QA program encl \* HRC No Detailed Affiliation Given 82/09/30 4pp 15772 323 24X Fiche 50-305, 82/09/30, 8210210395
- --8210210410 Safety evaluation of facility override of containment purge isolation Licenses should demonstrate that override condition automatically removed upon clearing initial signal or provide sys level annunciation

  \* NRC No Detailed Affiliation Given 82/09/30 2pp 15722 327 24% Fiche 50-305. 82/09/30.8210210395
- --8010070320 "Technical Evaluation of Electrical Instrumentation & Control Design Aspects of Override of Containment Purge Valve Isolation & Other Engineered Safety Features for Kewavnee Nuclear Power Plant "
  HACKEIT. D 8 E0&0, Inc E90-1183-4168 60/09/30 NRC No Detailed Affiliation Oiven 23pp 15772 329 24X Fichs 50-305,82/07/30.8210210395
- B210070108 Comments on MRC proposed generic requirements for steam generators Opposes requirements, favoring mgt control program corrently in effect Program should be at volition of util mgt & notice requirements
  GIESLER.C W Wisconsin Public Service Corp B2/10/04
  IPPOLITO,T A Operating Reactors Assessment Branch App 15628 070 24X Fiche 50-305,82/10/04.8210070108
- 8210190489 Forwards progress update on implementing NUREO-0737, Items II B 3.II B 4.II F 1 3.II F 1 6 % III D 3 4 GTESLER.C W Wisconsin Public Service Corp 82/10/14 EISENHUT, D G Division of Licensing 4pp 15735 331 24% Fiche-50-305,82/10/14,8210170489
- G Inspection reports, IE Bulletins & correspondence
- 8210070007 Responds to FDIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FECTON J M Division of Rules and Records 82/08/10 LONO, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000,82/08/10,8210070007
  - Fiche 50-000, 82/08/10, 8210070007
- ~-B210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees
  IPPOLIYO. T Operating Reactors Assessment Branch 82/04/01
  VAROA. S Operating Reactors Branch 1 5pp 15645, [31 24X
  Fiche 50-000, 82/08/10, 8210070007
- --8210070172 Forwards info re steam generator integrity & insps at all operating PMRs.per 750320 & 21 requests Details of insps. including defect indications, tube plugging criteria & tubes plugged until not be provided except for Point Beach i OCLEER K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY.R Division of Technical Review (NRR-1975 only) 5pp 15645 196 24% Fichs 50-000,82/08/10,8210070007
- 8210080201 Forwards IE Bafety Evaluation Rept 50-305/82-17 during Aug 1982 No noncompliance noted HIND.J A Division of Emergency Preparedness & Operational Bupport 82/09/22 0IESLER, C W Wisconsin Public Service Corp 2pp 85640 090. 24X Ficha 50-305,82/09/22,8210080201

- --8210080204 IE Safety Evaluation Rept 50-305/82-17 during Aug 1982
  No noncompliance noted Major areas inspected emergency
  plan dtd Nov 1981.
  PAGLIARD. J A. AXELSON. W L Division of Emergency Preparadness &
  Operational Support 82/09/20 32pp 15640:092 24X
  Fichs 50-305.82/09/22.8210080201
- 8210040328 Forwards util 820917 response to NRC 820715 questions re IE Bulletin 80-04, inadvertently sent to Region 3 OIESLER.C W Misconsin Public Service Corp 82/09/29 VARGA, B A Operating Reactors Branch 1 ip 15419:028 24X Fichs. 50-305, 82/09/29, 8210040328
- 8210050102 Forwards IE Safeguards Imap Rept 50-305/82-16 on 820823-27 & notice of violation Notice of violation withheld (ref 100FR73 21)
  MILLER.J R. Division of Engineering & Technical Programs 82/09/30, GIESLER.C.W Misconsin Public Service Corp 2pp 15603 275 24X Fiche 50-305,82/09/30,8210050102.
- --8210050110 IE Safeguards Insp Rept 50-305/82-16 on 820823-27 Noncompliance noted failure to certify qualifications for security force members Details withheld (ref 100FR73 21) BELANGER.J L., CREED.J R Region 3, 02fice of Director 82/09/28 1p 15603 297 24X Fiche 50-305,82/09/30,8210050102
- 8210080174 Forwards confirmatory measurements program data addendum sheet for IE Insp Rept 50-305/82-08, closing out Open Item 50-305/82-08-01.
  PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 82/10/05 01E8LEA, C. W. Wisconsin Public Service Corp 1p 15640 157 24X Fiche 50-305, 82/10/05, 82/10/05, 82/10/05.
- --B210080177 Addendum to IE Insp Rept 50-305/82-08 consisting of confirmatory measurements program data sheet re Br-89 & Sr-90 samples Bamples below companison limits \* Region 3. Office of Director B2/10/05 ip. 15440 i58 24X Fichs 50-305,82/10/05.B210080174
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Syc list encl CD88.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 64pp. 15741 280 24X Fichs 50-000, 82/10/06, 8208190233.
- 8210190532 Confirms schedule for 821018 enforcement conference at Region 3 ofcs to discuss potential escalated enforcement actions re recent identification of capped containment pressure sensing lines

  KEPPLER. J O Region 3. Office of Director 82/10/13 MATHEWS. E. R. Wisconsin Public Service Corp. 1p. 15751 254 24X

  Fiche 50-305.82/10/19.8210190532
- 8210280223 Forwards IE Insp Rept 50-305/B2-13 on 820701-0831 & notices of violation & deviation STREETER, J.F. Division of Project & Resident Programs 82/10/13 0168LER.C W. Hisconsin Public Service Corp. 2pp. 15839 279 24X Fiche 50-305.82/10/13.8210280223
- --B210280226 Notice of violation from insp on 820701-0831 STREETER, J. F. Division of Project & Resident Programs. B2/10/13 ip 15839 281. 24X Fiche. 50-305.822/10/13.821028023
- --82102B0229 Notice of deviation from insp on 820701-0831.
  STREETER, J.F. Division of Project & Resident Programs B2/10/13
  ip 15839 282 24% Fiche 50-305,82/10/13,82102B0223.
- --9210280232 IE Insp Rept 50-305/82-13 on 820701-0831 Moncompliance noted failure to maintain control of combustible matts & to issue operations mamo as of 820820 NELSUN.R.L. , REYES.L. A. Division of Project & Resident Programs 82/10/06 10pp. 15839.283 24X Fiche 50-305.82/10/13,8210280223
- 8208190238 IE Bulletin 82-03, "Btress Corrosion Cracking in Thick-Mail.Large-Diamster.Stainless 8teel.Recirculation 8ys
  Piping at BWR Plants " Svc list encl
  DEYQUNO.R C Director's Office. Office of Inspection and
  Enforcement. 82/10/14 Consolidated Edison Co of New York
  115pp 15810-125. 24X Fiche-50-000.82/10/14.8208190238.
- 8210240161 Confirms schedule for 821022 enforcement conference w/util to discuss potential escalated enforcement action re recent identification of capped containment pressure sensing lines. SPEBSARD.R L Bivision of Project & Resident Programs 82/10/15 MATHEWS.E.R. Misconsin Public Service Corp. 1p 15799 007. 24X Fichs. 50-303.82/10/15.8210240161

### B Reportable occurrences. LERs & related correspondence

- B210120182 Discusses findings to numerous failures of containment isolation valves All failures resulted from inoperable ASCO Series 8320 solenoid valves, usually due to oil in air supply Valves undergoing qualification
  LANNINO, H D Director's Office 80/08/22 Director's Office 2pp 19692 216 24X Fiche 50-295.80/08/22.8210120182
- 8210040194 Forwards LER 82-028/03L-0 & updated 81-036/03X-1 GIEBLER.C W Hisconsin Public Service Corp 82/07/24 KEPPLER.J G Region J. Office of Director 1p 15582 317 24X Fiche 50-305.82/07/24.8210040156
- --8210040159 LER 82-028/03L-0 on 920825.damper on Train A failed open causing zone special ventilation fan to start automatically Caused by bad coil on solenoid controlling exhaust filter inlet damper Coil replaced BERNHOFT.S L. Wiscomein Public Service Corp. 82/09/24 Region 3. Office of Director ip. 15582-318 24X Fiche 50-305.82/09/24. R210040155.
- --B210040162 Updated LER 81-036/03X-from 811103.neter drive auxiliary feeduater lube oil pump continued to run when pump iA stopped Caused by excessive wear & misslignment of switch linkage mechanism Morn parts replaced BELANT.J L. Misconstin Public Service Corp 82/09/21 Region 3. Office of Director 2pp 15382 319 24X Fiche 50-305.82/09/24. R21004015A
- 8210190353 Forwards LERs 82-029/01X-1 & 82-031/03L-0 QIESLER.C W Wisconsin Public Service Copp 82/10/11 XEPPLER,J 0 Region 3, Office of Director. 1p 15742 607 24X Fiche 30-305.82/10/11.8210190353
- --8210190358 LER 82-029/01X-1 on 820927.discovered that monthly testing requirements exceeded for containment radiation monitors R-11 & R-12 Caused by postponement of test due to backup radiation monitor being out of svc & personnel oversight # Misconsin Public Service Corp 82/10/11 Region 3. Office of Director. 2pp 15742 108 24X Fichs 50-305,82/10/11.8210190383
- --8210170356 LER 82-031/03L-0 on 820913 train IB of shield bldg vent failed to switch to recirculation mode after drawing vacuum Recirculation damper failed to open due to broten hydraulic pump on electro-hydraulic damper actuator. Operator replaced BERNHOFT.8 L. Wisconsin Public Service Corp. 82/10/13 Region 3, Office of Director. 1p 15742 110 24X Fiche 50-305,82/10/11,82(0190393)
- 8210260260 Forwards LER 82-030/01T-0 01ESLER, C.W Hisconsin Public Service Corp 82/10/18 KEPPLER, J 0 Region 3. Office of Director ip 15799 348 24X Ficks 50-305, 82210260260
- --8210260263 LER 82-030/01T-0 on 821004, sensing lines on all six containment pressure transmitters found capped off inside, rendering transmitters imperable. Caused by refueling caps inadvertently placed on ends of sensing lines Caps removed. MARCHI.M L. Wisconsin Public Service Corp. 82/10/18 Region 3. Office of Director ip 15797 349. 24% Fiche 50-305,82/10/18. 8310200260

#### V Operator Examinations

í

8210050263 Describes implementation of senior reactor operator upgrade training to comply w/NUREO-0737/ltem I.A 2 1. "Senior Reactor Operator Qualifications " All potential candidates cannot be examined until Hay/June of 1983 OIESLERIC W Wisconsin Public Service Corp. 82/09/29, DENTON, H R Office of Nuclear Research Regulation. Director 3pp 15609; 193 24X Fiche: 50-305, 82/09/29, 82/0030263

- --8210040354 iE Insp Repts 50-282/82-15 & 50-304/82-15 on 820324 its noncompliance noted Major areas inspected previous deficiencies in prompt notification/warning sys PATTERSON, J.P. Division of Emergency Preparedness & Optralicas' Support 82/09/09 App 15593 358 24X Fiche 50-202.02/07: 8210040345
- 8210080184 Forwards revised Page 4 reflecting NRC guidance on activation of public alert & notification system 821014 emergency plan exercise WARDLE C Northern States Power Co 82/09/28 AXFISBN N. Fs., 3, 88fice of Director 2pp 15640 175 24X Fiche 50 202 02/03/35
- 8210120589 Notification of 821001 meeting w/licenses.BNL b fraistry, Planning & Mgt. Inc in Betheeda, MD to discuss requests for exemption from 19CFR50.App R requirements re fire protection
  DIIANNI.D C Operating Reactors Branch 3 82/09/20 (LARF # # Operating Reactors Branch 3 2pp 15672 346 24X Fiche 50-282.82/09/28.8210120589
- 8210260374 Ack receipt of FEMA 820526 ltr re evaluation of affairs amorgancy preparedness for facility exercise & associated final exercise evaluations Offsite emergency preparedness deficiencies should be addressed by util HIND.J A Division of Emergency Preparedness & Operational C pt. 82/10/21 OILBERTS.D E Northern States Power Co 255 156-4 24X Fiche-50-282.82/10/21,8210260374

### P Operating license stage documents & correspondence

- 8210040123 Submits supplemental info re util 820414 request for the Licenses DPR-42 & DPR-60 "LOCA ECCS Limiting Break & Exposure Sensitivity Analysis for ENG XN-1 & XN-2 Relogation Prairie Island I "applies to both Units I & 2 MUSCLF.D Northern States Power Co 82/09/24 Office & France Regulation. Director Ip 15581:203 24x Fiche 50-282, 82/09/24, 8210040123
- 8210050319 Forwards response to Core Performance Branch P24014 12 Te methods of monitoring core power distributions for Cycle 7 operation
  MUSOLF.D Northern States Power Co 82/09/29 (lifter # P : 3 Reactor Regulation, Director 13pp 15610 268 44x
  Fiche 50-282, 82/09/29, 8210050319
- 82:0130260 Discusses implementation of NRC guidelines for warrary hours, provided in Generic Ltr 82-12 Revised guidelines for warrary been implemented, w/exceptions of 72-h per what imitation a relief from control board duties
  MUSDLF, D. Northern States Power Co. 82/10/07 (Iffice at two or Reactor Regulation, Director, 2pp. 15676 012 24x
  Fiche: 50-000. 82/10/07. 82:10130260
- 8210260154 Advises that mods required by NUREQ-0737. Item [1] the "Control Room Habitability," will not be completed until 830315 due to delays in receipt of math 4 sampling equipment.

  MUBDLF.D Northern States Power Co 82/10/22 Uffice of the Regulation, Director 3pp. 18799 012 24x

  Fiche: 50-282, 82/10/22, 8210260154
- O Inspection reports, IE Bulletins & correspondence
- B210070007 Responds to FDIA request for eight categories (/ 24.7 is steam generators & steam turbines App A documents provines in R Udell FDIA Request 81-313 Forwards documents issues in R App B FELTON, J. M Division of Rules and Records. B2/00/10 1046 24 Hinthrop, Stimson, Putnam & Roberts 9pp. 15645 063 245 Fiche 50-000, 82/08/10, 8210070007
- ---B210070139 Forwards tabulated data on steam generator in: 1 to a facilities. Data should be provided to licensees IPPOLITO.T. Operating Reactors Assessment Branch \$7.54 & VARQA:S Operating Reactors Branch 1 5pp | 13445 | 131 244 Fiche. 50-000, 82/08/10, 8210070007.

- --8210070172 Forwards info re steam generator integrity & insps at all operating PHRs.per 780320 & 21 requests Details of insps. including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach 1. GCLLER.K R Division of Reactor Licensing (NRR-1975 only)
  75/03/24 MACCARY,R R. Division of Technical Review (NRR-1975 only)
  5pp 15645 196 24X Fiche 50-000,82/08/10,8210070007
- 8210040345 Forwards IE Insp Repts 50-282/82-15 & 50-306/82-15 on
- --8210040354 IE Insp Repts 50-282/82-15 & 50-304/82-15 on 820824-25 No noncompliance noted Major areas inspected previous deficiencies in prompt notification/warning aus deficiencies in prompt notification/warning aus PATTERSON, J P. AXELSON, W L. Division of Emergency Preparedness & Operational Support 82/09/09, 4pp 15593 358 24X Fichs 50-282,82/09/10,8210040345
- B210130563 Forwards "Inservice Insp-Exam Summary, Prairie Island Nuclear Generating Plant-Unit II.820601-0709" "
  MUSDLF.D Northern States Power Co 82/10/05 Office of Nuclear Reactor Regulation, Director 1p 15683 118 24X Fiche-50-304,82/10/05,8210130363
- 9210130563
- 6208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 implant Seeds " Syc list encl COBB.t I Division of Fuel Facilities, Materials & Safeguards 622/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000.82/10/06.8208190233
- 8210190432 Ack receipt of 820915 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/82-11 & 50-304/82-11 SO-306/682-11
  SPESBARD.R L Division of Project & Resident Programs 82/10/07
  LARSON.C E Northern States Power Co 1p. 18741 182 24X Fiche 50-282,82/10/07,8210190432
- --8210170439 Responds to NRC 820817 ltr re violations noted in IE Insp Repts 50-282/82-11 & 50-306/82-11 Corrective actions startup program changed to normalize flux difference channels LARSON, C E Northern States Power Co 82/09/15 BTREETER Division of Project & Resident Programs 2pp 15741 183 Fiche 50-282,82/10/07.8210190432 STREETER , J F
- 8210150249 Ack receipt of 820928 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/82-13 & 50-306/82-13 STRECTER, J F Division of Project & Resident Programs 62/10/08 LARSON, C. E Northern States Power Co. 1p 18704 361. 24X Fiche 50-282,82/10/08,8210180289
- --8210150255 Responds to NRC 820902 ltr re violations noted in IE Insp Repts 50-282/82-13 & 50-306/82-13 Corrective actions dissel generator test procedures will be revised by 821201 & investigative rept will be discussed w/operators
  LARBON.C E Northern States Power Co 82/09/28 STREETER.J F
  Division of Project & Resident Programs 2pp 15704.362 24X
  Fiche. 50-282, 82/10/08, 82/0150249
- 8210280164 Forwards IE Insp Repts 50-282/82-16 & 50-304/82-16 on 820701-17 & notice of vigistion STREETER, J.F. Division of Project & Resident Programs 82/10/13 LARSON, C. E. Northern States Power Co 2pp 15837 179, 24X Fiche, 50-282, 82/10/13, 8210280144
- --8210280171 IE Insp Repts 50-282/82-16 & 50-306/82-16 on 820901-17.
  Noncompliance noted failure to post no smoking sign in safety-related quipment areas & operators found smoking.
  DUBRY: N E., REYEB.L Division of Project & Resident Programs
  82/10/12. App. 15837-202 24X Fiche. 50-282, 82/10/13, 8210280164
- 8208190238 IE Bulietin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at SWR Plants." Syc list encl DEYGUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co. of New York 115pp. 15810,125, 24X Ficher 50-000,82/10/14,8208190238,

- S Reportable occurrences. LERs & related correspondence
- 8210190726 Forwards LER 82-017/03L-0 MUSDLF,D Northern States Power Co 82/10/08 Region 3, Office of Director 1p 15737-144 24X Fiche 50-306.82/10/08,8210190726
- ~~8210190745 LER B2~017/03L~0 on 820908, two undervoltage relays found to trip outside tolerance band of 90 plus or minus 2% of nominal voltage Cause not stated Relays recalibr HUNSTAD, A A Northern States Power Co. 82/10/08 Region 3. Office of Director 1p 15737 145 24% Fiche 50-306,82/10/08.
- DOCKET 50-309 HAINE VANKEE ATOMIC POWER PLANT F Security, medical, emergency & fire protection plans
- 8210070054 Forwards Amend 64 to License DPR-36 & notice of issuance & availability Amend requires meint of safeguards contingency & guard training & qualification plan
  HEITMER: K. L. Operating Reactors Branch 3 82/09/15 GARRITY, J H
  Haine Yankes Atomic Power Co. 4pp 15646 351 24X
  Fiche 50-309,82/09/15,8210070054
- ~-8210070059 Amend 64 to License DPR-36.including requirement to maintain Commission approved guard training & qualification plan CLARK.R A Operating Reactors Branch 3 82/09/15 2pp 15646 355 24X Piche: 50-309, 82/09/15, 8210070054
- ~-8210070040 Notice of assuance & availability of Amend 64 to License DPR-36 CLARKIR A Operating Reactors Branch 3 82/09/15 2pp 24% Fiche 50-309,82/09/15,8210070084 15646 357
- 8210050013 Releases public version of Vol II of emergency plan FELTON.J M. Division of Rules and Records 82/09/16 Docum Management Branch 1p 15622 221 24X Fiche 50-309,82/09/16,8210050013. Document
- ~-8210050015 Forwards public version of Vol II of emergency plan Receipt form encl \* Maine Yankee Atomic Power Co 82/08/30 EISENHUT, No Detailed Affiliation Given. 2pp 15622 222 24X Fiche 50-309.82/09/16.8210050013 EISENHUT, D 0 NRC -
- ~~8210050018 Public version of Vol II of emergency plan # Maine Yankee Atomic Power Co 82/07/12 21ipp 15622 224 24X Fiche 50-309,82/09/16,8210050013
- 8210210136 Forwards IE Insp Rept 50-309/82-12 on 820726-30 No. noncompliance noted Region 1, Office of Director 82/10/06 RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 15766 107, 24x Fiche. 50~309, 82/10/06, 8210210136
- --8210210142 IE Insp Rept 50-309/82-12 on 820724-30 No noncompliance noted Major areas inspected follows of emergency preparedness items from 810708-15 appraisal WOJNAB E. J. CROCKER: H W Division of Emergency Preparedness & Operational Support. 82/09/30. 1ipp. 15746 109 24X Fiche 50-309,82/10/06.8210210136
- 8210210313 Forwards IE Bafaguards Insp Rept 50-309/82-11 on 820719-21 ARTIN.T T Division of Engineering & Technical Programs B2/10/07
  RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 15764-227 24x
  Fiche: 30~309, B2/10/07, B210210313
- --8210210316 Notice of violation from insp on 820719-21 \* Division of Engineering & Technical Programs 82/10/07 ip 15764 229 24X Fiche: 50-309, 82/10/07, 8210210313
- --8210210321 IE Bafeguards Insp Rept 50-309/82-11 on 820719-21.
  Noncomplience noted failure to establish SNM control & accounting procedures to assure that sources & detectors received, controlled, inventoried & shipped properly.
  KUBHNER, H L., 2009/A. T. Division of Engineering & Technical Programs 82/09/14 7pp. 15764.230. 24X Fithe 50-309.82/10/07, 8210210313
- B210130178 Ack receipt of B20527 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-309/81-02 Corrective actions withheld (ref 100FR73 21), MARTIN.T.T Division of Engineering & Technical Programs B2/10/08 RANDAZZA.J.B. Maine Yankse Atomic Power Co 2pp. 15873 020 24% Fiche.50-309, 82/10/08, 8210130178.

1.7

1;

- B2102800B7 Advises of recent changes to B2060l security plan, including moving portion of perimeter security fence & observation tour to provide addl area within protected area Changes do not decrease effectiveness of plan GARRITY. J H. Maine Yankus Atomic Power Co. 82/10/21 DENTON, H. R. Office of Nuclear Reaction Regulation. Director. 1p. 15837-184 24X Fichs 50-309, 82/10/21, 8210280087
- G. Adjudicatory correspondence
- 8210050236 Response apposing NRC & util objections to Sensible HE Power B20830 addl specific contentions NRC & util stds sought to be imposed are unfairly & improperly restrictive of intervenor right to be heard MILLER.D S Sensible Maine Power MILLER.D S Miller.D S 88031616 Maine Power MILLER.D S Miller.D S 88031616 Maine Power MILLER.D S Miller.D S 82/09/30 Atomic Safety and Licensing Board Panel 13pp 15608 349 24X Fiche 50-309.82/09/30.8210050236
- 8210060170 Response opposing NRC & util 820915 replies to State of ME 820830 addl contentions All contentions should be admitted Certificate of Svc encl AMERIS.P Maine. State of 82/09/30 Atomic Safety and Licensing Board Fanel 24pp 13613 240 24X Fiche 50-309,82/09/30,8210040190
- 8310080049 Forwards 10CFR2 Subpart B per 820926 request GUTIERREZ.J M Hearing Branch 3 82/10/01 MILLER D 8 Miller D 5 5pp 15843 030 24x Fiche 50-309,82/10/01.8210080049
- 8210130314 Answer opposing Sensible ME Power 820924 motion for clarification & mod of ASLD 820412 order on admissibility of contentions Filing is untimely & forbidden by regulations Certificate of Svc encl DIGNAN.T 0 , GADLR K Haine Vankee Atomic Power Co DIGNAN,T 0 Ropes & Gray 82/10/09 Atomic Safety and Licensing Board Panel 4pp 15678 151 24X Fiche 50-309,82/10/08,8210130314
- 62:0150:034 Forwards ASLB 82:0915 partial initial decision in Big Rock Point spent fuel pool amend proceeding Same procedure re EIS should be used in instant case GUTIERREZ.J H Hearing Branch 3 82:10/13 LAZO.R H . HAND.C H . MORRIS.P A Atomic Safety and Licensing Board Panel 2pp 15697 346 24x Fiche 50-309,82:10/13.82:10:50134
- 9210200065 Reply apposing NRC & applicant opposition to Sensible HE Power motion for util disclosure Motion should not be characterised as premature discovery info requested basic & essential to proceeding Certificate of Svc encl MILLER, D S Sensible Maine Power MILLER, D S Miller, D S 82/10/13 Atomic Sefety and Licensing Board Panel 5pp 15757 201 24X Fische 50-309, 82/10/16,8210200065
- 9210150460 Response opposing Sensible HE Power 820924 motion for clarification & mod of ASLB 820412 order ruling on admissibility of Power proposed contentions Motion merely repeats arguments already rejected Certificate of Svc encl CUTIERREZ. J H Hearing Branch 3 82/10/14 Atomic Safety and Licensing Board Panel App (\$703 106 24% Fiche 50-309,82/10/14,8210150460
- 8210260457 Forwards Safe Power for HE.EG Garrett, JS Green & J Jerabek request for issuance of show cause order to licensee HURRAY, P L Hurray, Plumb & Hurray MURRAY, P L Safe Power for Maine 82/10/20 Director's Office, Office of Inspection and Enforcement ip. 15807 123 24% Fiche 50-309, 82/10/20, 8210260457
- --8210260465 Safe Power for ME,EO Garrett, JB Green & J Jarabet request for issuance of show cause order to licensee Adequate financial bacting must be shown to raise capital required to continue operations & to make capital investment HURRAY, P L Safe Power for Haine KURRAY, P L Hurray, Plumb & Hurray 82/10/20 Director's Office, Office of Inspection and Enforcement 699 15807 124 24% Fiche 50-309, 82/10/20.
- 8210280227 Comments on HRC B21013 ltr to ASLB re contentions Decision on merits in Big Rack Point case does not affect admissibility of contentions in instant case AHRENS, P Maine. State of 82/10/20 LAZD, R M, HAND, C. H, MORRIS, P A Atomic Safety and Licensing Board Panel 3pp. 15837 083 24X Fiche 50-309, 82/10/20, 8210280227
- 8210290303 First set of interrogatories & requests for documents
  Centificate of Syc encl
  MILLER, D 8 Sensible Mains Power MILLER, D 8 Miller, D 6
  82/10/25 Maine Yantes Atomic Power Co 8pp 15853 170 24X
  Fichs 50-309, 82/10/25,8210290303

- H General correspondence
- 9210240202 Requests response to listed questions re assignment of personnel during shutdown & nature of work personnel will be conducting at plant BARROWS. J Haine Nuclear Referendum Committee B2/10/21 CLARK.R A Operating Reactors Branch 3 lp 15804 270 24% Fiche 50-307.82/10/21.8210260202
- P Operating license stage documents & correspondence
- 8210040074 Advises that Items 1,2 & 3 of NRC Confirmatory Action to 82-01 have been satisfied per util 820202.22 & 0308 ltrs. Approval for facility restart requested GARRITY, J H. Kaine Yankee Atomic Power Co. 82/03/12 HAYNES.8¢ Region 1, Office of Director CLARK, R. A. Operating Reactors 8rs 3 2pp 15581 141 24X Fiche 50-309,82/03/12,8210040074
- 821001000B Responds to FOIA request for 19 categories of documents in nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/20 UDELL.R s Critical Mass Energy Project 15pp 15727 005 24X Fiche 30-000.82/06/28.8210010008
- --8204270048 Recommends prompt attention be given to problem of fire coolant pump closure stud corrosion detected at facilities Response by 820415 requested EISENHUT.D O Division of Licensing 82/03/24 HANAUER, 8 H. Division of Systems Integration (post 811005) 3pp 66005 2.2 24X Fiche 50-000.82/66/28.8210010008
- 8210040077 Advises that refueling water storage tank level setpoint for automatic recirculation actuation signal should not by changed in short term.per 820727 itr
  OARRITY, J H Maine Yankee Atomic Power Co 82/07/28 HANKS.RI
  Region I, Office of Director 2pp 15581 270 24X
  Fiche 50-307,82/07/28/8210040077
- 8210040217 Submits add1 info to 820727 ltr re refueling unter string tank temp upper limit & water level lower limit Reanalysis of NPSH for ECCS performance included safeguards pumps, fluid sys & calculations of piping sys

  GARRITY, J H Hains Yankee Atomic Power Co 82/07/29 NAYMES I(
  Region 1, Office of Director 2pp 15583-118 24X

  Fiche 50-309, 82/07/29,8210040217
- 8209210514 Requests addl info re responses to NUREO-0737 Item
  III D 3 4. "Control Room Habitability " Response requested
  within 40 days of receipt of Itr
  CLARK, R A Operating Reactors Dranch 3 82/09/01 GARRITY, J \*
  Katne Yankse Atomic Power Co 2pp 14947 201 24X
  Fiche 50-307, 82/09/01,8209210514
- --B209210523 Informs of acceptability of control room habitalities on licensee responses to NUREG-0737. Item III D 3 4 Conclusion based on present plant sys & presumes implementation of effective HVAC mods HVRPHY.D W Battelle Hemorial Institute. Pacific Northwest Leboratory. FIN B-2323 82/03/23 HULHAN.L 0 Accident Evaluation Branch 3pp 14947 203 24X Fiche 90-309,82/09/3. S209210514.
- 8210050497 Forwards Amend 63 to License DPR-36, safety evaluation is notice of issuence & availability Amund changes Tech Specimaking limiting conditions for operation more restrictive increasing surveillance requirements for ventilation sys NELSON, C.C. Operating Reactors Branch 3 82/09/07 GARRITY, J. Haine Yankee Atomic Power Co. 3pp. 15626-304 24X Fiche: 50-309, 82/09/07,8210050497.
- --8210050503 Amend 63 to License DPR-36, changing Tech Specs to site limiting conditions for operation more restrictive & increasing surveillance requirements for ventilation & filter sys.

  CLARK, R. A. Operating Reactors Branch 3 82/07/07 14;; 13626 307. 24% Fiche 50-309, 82/09/07, 8210050497
- --8210050505 Bafety evaluation supporting Amend 63 to Litense DPE-2 \* Office of Nuclear Reactor Regulation, Director 82/09/67 11pp 15626,321 24X Fiche, 50-309,82/09/07,8210050497
- ---8210050509 Notice of issuance & availability of Amend 63 to lived BPR-36 CLABK.R A Operating Reactors Branch 3 82/09/07 2pp 18828:332. 24% Fichs.80-309,82/09/07,8210050497

- 8210040413 Requests add1 info re 810403 proposed mod to Tech Specs concerning snubber surveillance Response requested within 30 days CLARKIR A Operating Reactors Branch 3 82/09/14 GARRITY, J H Maine Yankee Atomic Power Co. 2pp 15597 235 24X Fiche 50-309, 82/09/14,8210040413
- B210040423 Advises that util response to NUREO-0737. Item II K 3 3:
  "Reporting Relief & Safety Valve Failures & Challenges."
  acceptable
  HELTNER: K L Operating Reactors Branch 3 82/09/15 QARRITY, J H
  Maine Yankee Atomic Power Co 2pp 15597 239 24X
  Fiche 50-309, 82/09/15.8210040423
- E210070054 Forwards Amend 64 to License DPR-36 & notice of issuance & availability Amend requires maint of safeguards contingency & guard training & qualification plan
  HEITNER, K L Operating Reactors Branch 3 B2/09/15 GARRITY, J H
  Maine Yankee Atomic Power Co 4pp 15646 351 24X
  Fiche 50-309, B2/09/15, 8210070054
- --8210070059 Amend 64 to License DPR-36, including requirement to maintain Commission approved guard training & qualification plan CLARK.R A Operating Reactors Branch 3 82/09/15 29p. 15646 355 24X Fiche 50-309, 82/09/15,8210070054
- --8210070060 Notice of issuance & availability of Amend &4 to License BPR-36 CLAMAR A Operating Reactors Branch 3 82/09/15 2pp 15646 357 24X Fiche 50-309, 82/09/15, 8210070054
- 8210250267 Forwards qudit rept re procedures & training on pressurized thermal shock containing specific recommendation for training program Requests summary of plans in response to recommendations within 45 days CLARK.R A Operating Reactors Branch 3 82/09/23 GARRITY, J H Haine Yankee Atomic Power Co 34pp 15807 341 24X Fishe 50-309, 92/09/23, 8210250267
- 6210060171 Application for amend to Tech Specs App A re Gycle 7 core performance analysis RANDAZZA, J B Maine Yankee Atomic Power Co 82/09/29 Office of Nuclear Reactor Regulation, Director 3pp 15614 068 24X Fische 50-309, 82/09/29, 821006017
- -8210060173 Proposed changes to Tech Specs re Cycle 7 core performance analysis 4 Maine Yankee Atomic Power Co 82/09/29 36pp 15614 071 24X Fiche 50-309,82/09/29,8210060171
- 8210290160 Notification of changed location for 821013 meeting w/utils in Bethesda, MD to discuss Cycla 7 reload package HEITNER.K L. Operating Reactors Branch 3 82/10/05 CLARK, R A Operating Reactors Branch 3 ip 15876 228 24X Fiche 50-309, 82/10/05, 8210290160
- B210270165 Notification of B21013 meeting w/utils in Bethesda.MD to discuss Cycle 7 reload package #EZITMERK L Operating Reactors Branch 3 B2/10/05 CLARK.R A Operating Reactors Branch 3 2pp 15865 340 24X Fiche 50-309.82/10/05.8210270165
- 83210130252 Proposed Change 94 to License DPR-36. App A Mod renders RCB power-operated relief valves temporarily inoperable during hydrostatic testing when setpoint approached Approval requested prior to startup of Cycle 7

  RANDAZZA.J B Maine Yankee Atomic Power Co 82/10/07 CLARK,R A Operating Reactors Branch 3 3pp 15678 042 24X

  Fiche 50-309, 82/10/07, 8210130252
- --8210130254 Proposed Tech Spec Pages 3 3-1 through 3 3-3, rendering RCS power-operated relief valves temporarily inoperable during hydrostatic testing when setpoint approached # Haine Yankes Akomic Power Co 82/10/07 3pp 15678 045 24X Fiche 50-309,82/10/07,8210130252
- 8210130283 Proposed Change 95 to License DPR-36, modifying Tech Specs to satisfy generic concerns re containment purge & vent sys & tests required to verify valve operability for on-line purge & leakage rate of isolation valves
  RANDAZZA.J.B Maine Yantee Atomic Power Co 82/10/07 CLARK.R A Operating Reactors Branch 3 3pp 15678:297 24X
  Fiche 50-309, 82/10/07,8210130283
- --8210130286 Proposed Tach Spec changes re containment purge & vent sys & tests required to varify valve operability for on-line purge & leatage rate of isolation valves \* Maine Yanter Atomic Power Go 82/10/07 5pp 15678 300 24X Fiche 50-307, 82/10/07, 8210130283

- 8210130360 Application to amend App A of License DPR-36.consisting of Proposed Change 92.modifying Tech Specs to restrict apperations when reactor protective sys channels & ESF actuation sys sensors bypassed.

  RANDAZZA, J B Maine Yankee Atomic Power Co. 82/10/07 CLARK, R A Operating Reactors Branch 3 2pp 15679 117 24X Fiche 50-309, 82/10/07, 8210130360
- --8210130369 Proposed changes to Tech Spec 3 9. restricting operations when reactor protective sys channels & ESF actuation sys sensors bypassed 4 Maine Vankee Atomic Power Co 82/10/07 App. 15679 119 24x Fiche 50-309.82/10/07.8210130360
- 8210270008 Forwards Revision 2 to "Inservice Insp & Testing Program " GARRITY.J H Maine Yankes Atomic Power Co 62/10/12 CLARK.R A Operating Reactors Branch 3 ip 15822 134 24X Fiche 50-309.82/10/12.8210270008
- --8210270007 Revision 2 to "Inservice Insp & Testing Program " JONES.D L Maine Yankee Atomic Power Co 62/09/21 133pp 15822 135 24X Fiche 50-309,82/10/12,8210270008
- 8210220203 Forwards addl info re "Environ Qualification of Safety-Related Electrical Equipment," Item A 1 MM W/o encl OARRITY, J H Maine Yankes Atomic Power Co 82/10/18 CLARK, R A Operating Reactors Branch 3 3pp 15776:354 24X Fiche 50-309, 82/10/18,8210220203
- 8210250078 Clarifies NUREO-0737, Item II I 4 1, "Training for Mitigating Core Damage," per NRC 820914 request All replacement licensed operators & shift technical advisors receive training prior to assuming duties OARRITY. J H Maine Yankee Atomic Power Co 82/10/18 CLARK, R A Operating Reactors Branch 3 2pp 15787 109 24X Fiche 50-309, 82/10/18, 8210250078
- 8210220212 Informs that saturation monitor upgrading delayed due to equipment availability Rosemount resistance temp detectors (RTD) will be used in conjunction wisteres temp detectors adequate backup in case of loss of RTD indication OARRITY, J H. Maine Yankes Atomic Power Co. 82/10/19 CLARK, R A Operating Reactors Branch 3 2pp 15776-229 24X Fiche 50-309, 82/10/19, 8210220212
- 8210260420 Advises that installation of isolation valves in letdown, steam generator blowdown & auxiliary steam lines will not be completed during 1982 refueling due to late squipment delivery. Installation to be completed by next outage OARRITY, J H Maine Yankee Atomic Power Co. 82/10/21 CLARK, R A Operating Reactors Branch 3 ip. 15806 314 24X Fiche 50-309, 82/10/21, 8210260420
- 821028016: Advises that seismic design review re auxiliary feedwater sys seismic qualification will not be completed as committed to in util 810805 ltr but in accordance w/plan presented in util 820621 ltr.

  GARRITY, J H Maine Yankee Atomic Power Co 82/10/22 CLARK, R A dperating Reactors Branch 3 lp 15837:209 24X

  Fiche 50-309,82/10/22,8210280161.
- Q Inspection reports, IE Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON-J M Division of Rules and Records 82/08/10. LONG.D.J Hinthrop. Stimson. Putnam & Roberts. 9pp 15445 063 24X Fiche: 50-000.82/08/10.8210070007
- --8210070172 Forwards info re steam generator integrity & insps at all operating PWRs, per 7503R0 & 21 requests Details of insps, including defect indications, tube glugging criteria & tubes glugged will not be provided except for Point Beach ; OOLLER: K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY.R. Division of Technical Review (NRR-1975 only) 5pp. 15445.194 24X Fiche 50-000,82/08/10.8210070007.
- B210070357 Forwards IE Enforcement Conference Rept 50-309/82-14 on 820602 & 0714 No noncompliance noted Enforcement action gending & will be forwarded under separate cover.
  8TAROSTECKI,R Division of Project & Resident Programs 82/09/20 RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 15634 062 24X Fiche. 50-309, 82/09/20, 8210070357.
- --B2100703B1 IE Enforcement Conference Rept 50-309/82-14 on 820602 & 0714. No noncompliance noted, Major areas discussed NRC concerns to design change control & event reporting weaknesses identified in IE Insp Rept 50-309/82-05. SMETLAND, P. GALLO, R. Division of Project & Resident Programs 82/09/09, 2pp. 15634 064. 24X Fiche. 50-309, 82/09/20, 8210070337

- 8210060302 Responds to 820708 request for add1 info re control element assembly & fuel assembly fretting waar insps OARRITY. J H Haine Yankse Atomic Power Co 82/09/28 CLASK.R A Operating Reactors Branch 3 4ps 15619 202 24X Fiche, 50-309, 82/09/28, 8210060302
- 8210150398 Forwards response to NRC request for add1 info re IE Bulletin 80-11. "Masonry Hall Design " All required mods installed by 820301. Math error detected which requires strengthening of wall will be accomplished at 1982 outage GARRITY, J H Mains Yankee Atomic Power Co 82/09/30 CLARK.R A Operating Reactors Branch 3 78pp 15703 286 24X Fiche 50-309, 82/09/30, 8210130398
- 620B190233 IE Info Notice 60-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 62/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000.82/10/06.8208190233
- 8210210136 Forwards IE Insp Rapt 50-309/82-12 on 820726-30 No noncompliance noted ALLAN, J H Region 1, Office of Director B2/10/06 RANDAZZA, J B Maine Vankes Atomic Power Co 2pp 15766 107 24X Fiche 50-309, 82710704. 8210210136
- --B210210142 IE Insp Rept 50-309/82-12 on B20726-30 No noncompliance noted Hayor areas inspected follows of emergency preparendass; items from B10908-15 appressal.

  MIJNAS, E. J., CROCKER, H. W. Division of Emergency Preparedness & Operational Buppart B2/09/30 11pp 15766-109 24X

  Fiche 50-309,82/10/06.8210210136
- 8210210313 Forwards IE Safeguards Insp Rept \$0-309/82-11 on 820719-21 to notice of violation MARTIN.T To Division of Engineering & Technical Programs #82/10/07 RANDAZIA.U B Naine Yantes Atomic Power Co 2pp 15764 227 24X Fichs 50-309.82/10/07.8210210313
- --8210210316 Notice of violation from insp on 820719-2[ \* Division of Engineering & Technical Programs 82/10/07 ip 15764 229 24% Fiche 50-209, 82/10/07,8210210313,
- --8210210321 IE Bafeguards Insp Rept 50-309/82-11 on 820719-21
  Noncompliance noted Failure to establish SMM control & accounting procedures to assure that sources & destotans raceived controlled, inventoried & shipped properly MUSHMER.W.L., ODDY, A.T. Division of Engineering & Technical Programs 82/09/14 7pp. 15764-230. 24X Fiche 50-309,82/10/07,8210210313
- 8210130178 Ack receipt of 820527 ltr informing NRC of steps taken to correct violations noted in JE Safeguards Insp Rept 50-309/81-02 Corrective actions withheld (ref 100FR73 21). MARTIN, T.T. Division of Engineering & Technical Programs 82/10/08 RANDAZA, J B. Mains Vanies Atomic Power Co 2pp 15673 020 24X Fichs: 50-309, 82/10/08, 8210130178
- 821027000B Forwards Revision 2 to "Inservice Insp & Testing Program" OARRITY.J.H Mains Yenkee Atomic Power Co 82/10/12 GLARK.R A. Operating Reactors Branch 3 1p 15822 134 24X Fiche 30-309.82/10/12.821027000B.
- --8210270009 Revision 2 to "Inservice loss & Testing Program "
  JUNES,D L Maine Yankes Atomic Fower Co. 82/09/21, 133pp
  15822.135 24K Fiche.50-309,82/10/12.8210270008
- 8208170238 IR Builetin 82-03, "Street Corrosion Cracking in Thick-Wells.Large-Diameter, Stainless Steel, Recirculation Sysfring at BAR Plants," Svc list encl.

  DEYOUNO, R. C. Director's Office, Office of Inspection and Enforcement, 82/10/14 Consolidated Edison Co of New York 115pp. 15810-125, 24X Fiche 50-000,82/10/14,8208190238
- 8210260144 Forwards add1 info re IE Bullstin 80-11. Two add1 mesonry walls identified in fuel bidg One wall located south of spent fuel pool k one wall adjacent to ventilation penthouse. Design adequacy will be re-evaluated.

  GARRITY. J. H. Maine Yankee Atomic Power Co 82/10/21. CLARK. R. A Operating Reactors Franch 3. 2pp. 15799.089. 24x

  Fiche 50-309.82/10/21.8210260144
- S Reportable occurrences, LERs & related correspondence
- 8210270165 Forwards LER 81-005/03L-0 WOOD,E C Hains Yankse Atonic Power Co 81/05/26 Region 1, Philadelphia, Uffice of the Director (81/03/01), 1p. 15822, 355 24X Fiche: 50-309, 81/05/26, 8210270165

- --B210270177 LER Bi-005/03L-0 on 810509, one of three RAS actuation switches failed to close Caused by matl incompatibility. Switch replaced w/improved model utilizing stainless sized in place of 6rass 4 Haine Yantes Atomic Power Co. 81/05/26 Region 1, Philadelphia. Office of the Director (81/03/01) 1p 15022 3% 24% Fiche 50-309, 81/05/26, 8210870165
- 8210290267 Part 21 deficiency rept re potential galling problem Still stem & bonnet of 1 25-inch & larger Ai05 carbon steel & Ai82-F22 valves supplied Feb 1981-Aug 1982 Valves should be serviced & stem &/or bonnet replaced ISABELLE, L D Convel, Inc 82/10/11 HAYNES, R C Region | . Cir of Director 17pp 15854 232 24X Fiche 50-000, 82/10/11, 82/1090267
- 8210210015 Forwards LER 82-027/03L-0 M00D.E C Haine Yankee Atomic Power Co 82/10/12 Region 1, i Office of Director 1p 15766 021 24X Fiche 50-309, 82/10/12, 8210210015
- --8210210018 LER 82-027/03L-0 on 920929, containment isolation signal steam generator blowdown valve 80-T-32 failed to fully close Caused by loose scrip ladged between disk & seating surface Parts replaced NELSON, R H. Naine Vankee Atomic Power Co. 82/10/12 Region Office of Director ip 15766-022 24X Fiche 50-309,62/10/12 8210210015
- B210260193 Forwards LER 82-026/03L-0 WODD, E C Maine Yankse Atomic Power Co B2/10/18 Hapton I. Office of Director 1p 15804 272 24X Fiche 50-309.02/10/18 B210280193
- --B210260200 LER 82-026/03L-0 on B20924 one steam generator safity a failed to operate & two valves operated above Tech Byec 1 inits during test Caused by instrument drift Cause of instrument drift unknown NELSON, R H Haine Yankee Atomic Power Co 82/10/10 Heging Office of Director 2pp 15804 273 24X Fiche 50-309,62/10,18210260193
- 8210260199 Forwards LER 82-028/03L-0 WOOD, E.C. Haine Yankee Atomic Power Co. 82/10/18 Region t Office of Director ip 15799 148 24X Fiche 50-309,02/10/18 8210260199
- --8210260208 LER 82-028/03L-0 on 820929, containment isolation bit. Treset resulted in unexpected opening of control element drive mechanism cooler return valve Caused by open coil in Agastat EEF reset panel valve suitch control relay NELSON.R H Maine Yankse Atomic Power Co 82/10/18 Regard Office of Director 2pp 15797 149 24X Fiche 50-309.87/17 (8210260199
- 8210260327 LER 82-029/017-0 scheduled eddy current tests of steed generator 2 tubes revealed small number of tubes exceeding tube plugging limit
  GARRITY.J H. Maine Yankee Atomic Power Co 82/10/18 Rigids Office of Director ip 15801.362 24X Fiche 50-309.gg/16/18 8210260327.
- 82:0290343 LER 82-029/01T-1 addy current tests on steam generater? tubes revealed 10 tubes exceeding tube plugging limit Caver? by short radius bend tube degradation Condition also reported by similar C-E plant OARRITY. J H Maine Yankee Atomic Power Co 82/10/19 Rigis: Office of Director ip. 15853 028 24X Fiche 50-309.82/10/19 Rescoroses
- DOCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2

  F Security, medical, emergency & fire protection plane
- 8210250245 Forwards 1982 FEMA/NRC observed exercise scenario for & exercise Revisions reflect changes agreed upon during 82240 meeting w/NRC & FEMA ZUPKO, J. H. Public Service Electric & Qas Co. of New Jersas 82/09/16. HAYMER,R C. Region i. Office of Director 149st 15789:002 24X Fiche 50-272,82/09/16.8210250245
- 8210260518 Forwards exemption from requirements of IOCFR30 48 reprotection of safe shutdown capability VAROA S.A. Operating Reactors Branch 1, 82/09/16 UOERITE & Public Service Electric & Gas Co. of New Jersey 3pp 15836 is 24X Fiche 50-272.82/09/16.8210260518.
- --8210260521 Exemption from requirements of 10CFR50 48 refire Proof safe shutdown capability.
  EISENHUT, D. O. Division of Licensing 82/09/16 Public Rev.
  Electric & Gas Co of New Jersey, 4pp. 15830 171 24x
  Fichs: 50-272, 82/09/16, 8210260518.

- --B210Z60524 Safety evaluation supporting licenses request for exemption from requirements of 10CFR50 48 re fire protection of safe shutdown capability
  - Office of Nuclear Reactor Regulation, Director 82/09/16 3pp 15930 175 24X Fiche 50-272,82/09/16,8210260518
- 9210050431 Forwards exemption from requirements of Section IV F 1 of App E to 10CF850, to allow next full-scale emergency preparedness exercise at facility to be conducted on or about 820797 yearsting 820707 request VARCA-S A Operating Reactors Branch 1 82/09/23 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 3pp 15636 227 24X Fische 50-272, 82/09/23, 8210060431
- --8210060433 Exemption from requirements of Section IV F 1 of App E to 10CFR50. to allow next full-scale emergency preparedness exercise at facility to be conducted on or about 820929 Evaluation enci
  ELSENHUT. D 0 Division of Licensing 82/07/23 Public Service Electric & Oas Co of New Jarsey 5pp 15636 230 24% Fiche 50-272.82/09/23.8210060431

## P Operating license stage documents & correspondence

- B21003000B Responds to FOIA request for 19 categories of documents ru nuclear reactor events & safety problems Forwards documents Listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000. B2/06/28.B21001000B
- --8008050265 Discusses addl required info to better define potential for
- Cracking in reactor vessel notiles
  ADDNAN.V B Assistant Director for Materials & Gualifications
  Engineering 80/05/05 TEDESCO.R L Assistant Director for
  Licensing 2pp 15727 176 24X Fiche 50-000,82/06/28,8210010008

  -8203310089 Forwards mamb re equipment malfunctions during 820114
  turbine load reduction operation Following review of
- --8203310087 Forwards memo re equipment malfunctions during 820114 turbine load reduction operation Following review of final rept from licensee & Region 1,will complete evaluation of event for generic implications MICHELSUN.C Director's Office 82/03/15 JORDAN.E L Division of Engineering & Quality Assurance ip 15745 050 24X Fiche 50-000,82/06/28,8210010008
- -- \$203310094 Summary of \$20204 meeting re evaluation of sequence of events of Salem \$20114 load reduction transient.operators actions.lessons learned & future remodial actions to be taken
  TREMAN.N K Director's Office \$2/02/22 MICHELSON.C
  Director's Office 2pp 15734 034 24X Fichs 50-000.82/06/28, \$210010008
- 8210050485 Forwards documentation of satisfactory completion of requirements contained in 790921 ltr re TMI Action Item II E i Loncerning auxiliary feedwater sys VARGA:S A Operating Reactors Branch i 82/09/20 UDERITZ.R A Public Service Electric & Oas Co of New Jersey 3pp. 15626 277 24x Fiche 50-272,82/09/20,8210050485
- --82i0050490 "Suppl to Bafety Evaluation Rept for Salem Units 1 & 2 Implementation of Recommendations for Auxiliary Feedwater Eys " Office of Nuclear Reactor Regulation, Director 82/09/20 3pp 13626 280 24X Fiche 50-272.82/09/20.8210050485
- B2:0130603 Advises that installed monitoring sys required by TMI Action I tems II F 1 4. II F 1 5 & II F 1 6 acceptable & items considered closed VAROA: S A Operating Reactors Branch I 82/09/28 UDERITZ, R A Publit Service Electric & Oas Co of New Jersey 2pp. 15672,347 24X Fichs 50-279.82/09/28.8210130603
- B210170047 Informs that util rod exchange methodology not approved because of calculational content of reactivity measurement New submittal or return to boron dilution method requested, VARQA: SA Operating Reactors Branch 1 82/09/29 UDERITZ, RA Public Service Electric & Gas Co of New Jersey 3pp 15761 O41 24X Fiche 50-272,82/09/29.8210190047
- 8210190507 Application for amend to Licenses DPR-70 & DPR-75, revising core limits, fractional thermal power factor limit, performance of RCB water inventory belance & boron concentration & contained vol limits.

  LIDEN.E A Public Service Electric & Gas Co of New Jersey 82/10/05 VARQA, B A Operating Reactors Branch 1 2pp 15863,124 24X Fichs 50-272,82/10/05,8210190507.

- ~-8210190515 Proposed Tech Space supporting application to amend Litenses DPR-70 & DPR-75, revising core limits, fractional power factor limit, perforance of RCS water inventory balance & boron concentration & contained vol limits Public Service Electric & Oas Co of New Jersey 82/10/05 17pp 15863 126 24X Fichy 50-272,82/10/05.8210190507
- 8210270136 License Change Requests 82-17-20-21 & 22 to Licenses DPR~70 & DPR-75 Changes involve inservice insp of snubbers, steam generator insp ports, containment ventilation valve insp & surveillance functional testing
  LINDEN.E A Public Service Electric & Cas Co of New Jersey
  82/10/07 VAROA.S A Operating Reactors Branch 1 3pp 15807 026
  24% Fiche 50-272,82/10/07,8210270136
- ~-8210270142 Progosed Tech Spec changes re inservice insp of snubbers, installation of steam generator insp ports, pressure drop test & reactor trip instrumentation \* Public Service Electric & Gas Co of New Jersey 82/10/07 8pp 15927 029 24X Fiche 50-272.82/10/07.9210270134
- 8210180007 Advises that design changes satisfying concerns expressed in 820917 request for addl info re reactor protection sys/ESF actuation sys initiated Tech Specs will be modified to address setpoint changes
  LIDEN.E A Public Service Electric & Oas Co of New Jersey
  82/10/08 VAROA, B A Derating Reactors Branch 1 ip 18720 024
  24X Fiche 50-272.82/10/08.8210180009
- 8210270352 Forwards Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively, safety evaluation & notice of issuance & availability Amend revises process & effluent monitors to agree w/existing plant conditions
  ROSS: W J Operating Reactors Branch i 82/10/18 UDERITZ,R A Public Service Elactric & Oas Co. of New Jersey 2pp 15934-318 24X Fiche.50-272.82/10/18.8210270352
- --8210270355 Amends 48 % 13 to Licenses DPR-70 % DPR-75, respectively, revising process & effluent monitors to agree w/existing plant conditions
  VAROA. 5 A Operating Reactors Branch 1 82/10/18 14pp, 15894 320 24X Fiche 50-272, 82/10/18, 8210270352
- --8210270360 Safety evaluation supporting Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively 4 Office of Nuclear Reactor Regulation, Director 82/10/18 App 15834 334 24X Fichs 50-272,82/10/18,8210270352
- --B210270344 Notice of issuance & availability of Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively VARCA: S A Operating Reactors Dranch | B2/10/18 2pp 19834 340 24X Fiche 50-272, 82/10/18.8210270332
- O Inspection reports, IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 17 categories of info re nuclear reactor events & safety problems. Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5).
  FELTONIJ M. Division of Rules and Records 82/07/12 UDECL.R A Critical Mass Energy Project 9pp 15655 027 24X
  Fiche 50-000. 82/07/12, 8210080015
- ---8210080150 Systematic assessment of licensee performance notes re facility evaluation for Sept 1979-Aug 1980 \* NRC - No Detailed Affiliation Given 80/08/31 Spp 15668 043 24% Fiche-50-000, 82/07/12, 8210080015
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B.
  FELTON.J M Division of Rules and Records 82/08/10. LONG.D J. Winthrop. Stimson, Putnam & Roberts. 9pp 13645 063 24% Fiche 50-000, 82/08/10, 8210070007
- --B210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensess IPPOLITO.T Operating Reactors Assessment Branch. 82/04/01. VARAA 6 Operating Reactors Branch 1. 5pp. 15645.131. 24X Fiche 50-000,82/08/10,8210070007.
- 821012032B Responds to violations noted in IE Insp Repts 50-272/82-17 & 50-311/82-17 on 820707-0803. Corrective actions administrative procedure will be revised so future temporary design changes are removed on timely basis UDERITZ, R. A. Public Service Electric & Oas Co. of New Jersey. 82/09/28. HAYNES, R.C. Region 1, Office of Director. 87ARDSTECKI, R. Division of Project & Resident Programs. 5pp 15452:125 24X Fichs. 50-272, 82/09/28, 821012032B

- 8210060302 Responds to 820708 request for add1 info re control element assembly & fuel assembly fretting wear insys OARRITY. J H Mains Yantse Atomic Power to 82/09/28 CLARK.R. A Operating Reactors Branch 3 490 15619 202 24X Fiche 50-309.82/09/28,8210060302
- 8210150398 Forwards response to NRC request for additinfore IE Bulletin 80-11. "Masonry Hell Design " All required mods installed by 820301 Math error detected which requires strengthening of wall will be accomplished at 1982 outage GARRITY, J H Maine Yankes Atomic Power Co 82/09/30 CLARK, R A Operating Reactors Branch 3 78pc 15703 286 24% Fiche 50-307, 82/09/30, 8210150378
- 820Bi90233 IE Info Notice 80-35, Suppl i: "Leaking & Dislodged I-125 Implant Stads " Svc list encl COBBL I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 19761 250 24X Fiche 50-000: 82/10/06: 8208190233
- 8210210135 Foruards IE Insp Rept 50-309/82-12 on 820786-30 No noncompliance noted ALLANJ M Region I. Office of Director 82/10/06 RANDAZZA, J B Maine Yankee Atomic Fower Co 2pp 15765 107 24X Fiche 50-309, 82/10/06, 8210210135
- --8210210142 IE Insp Rept 50-309/82-12 on 820726-30 No noncompliance noted Major eress inspected followup of smergency preparendess items from 810908-15 appreisal HOJNAS.E J. CRUCKER.H W Division of Emergency Prepareduses & Operational Support 82/09/30 11pp 19766 109 24% Fiche 50-309, 82/10/04, 8210210136
- B2102:03:3 Forwards IE Bafeguards Insp Rept 50-307/82-81 on 820719-21 & notice of violation HARTIN.T T Bivision of Engineering & Technical Programs 82/10/07 RANDAZIA.J B Maine Yantee Atomic Power Co 2pp 15764 227 24% Fiche 50-309.62/10/07.8210210313.
- --B210210316 Notice of violation from insp on 820719-21

  \* Division of Engineering & Technical Programs 62/10/07 ip
  15764 229 24% Fiche 80-309,82/10/07.8210210313
- --8210210321 IE Safeguards Into Rept 50-309/82-i1 on 820719-21 Noncompliante noted failure to establish SNN control & accounting procedures to essure that sources & detectors received controlled inventoried & shipped properly KUSHNER.H L , GODY.A T. Division of Engineering & Technical Programs 82/09/14. 7pp 15764.230, 24X Fiche-50-309.82/10/07, 9210210313
- 8210130178 Atk receipt of 820527 ltr informing NRC of steps taten to correct violations noted in IE Safeguards Insp Rept 50-309/81-02 Corrective actions withheld (ref 100FR73.R1). HARTIN.T T. Division of Engineering & Technical Programs 92/10/08 RANDAZZA.J B Mains Yankse Atomic Power Co 2pp 15673 020 RAX Fichs: 50-309.82/10/08,8210130178
- 821027000B Forwards Revision 2 to "Inservice Insp & Yesting Program"

  CARRITY J H Heine Yentee Atomic Power Co 82/10/12 CLARK:R A.

  Operating Reactors Branch 3 19. 15822 134. 24X

  Fiche. 90-309-82/10/12,8210270008
- --BQ10270009 Revision 2 to "Inservice Insp & Testing Program"

  JONES, D. L. Maine Yankas Atomic Power Co. 82/09/21. 133pp

  15822:135. 24X Fiche: 50~309, 82/10/12, 8210270008.
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainlass Steal, Recirculation Sys Piping at BHR Plants " Syc list encl DEYOUNG, S. C. Director's Office, Office of Inspection and Enforcement, 82/10/14 Consolidated Edison Co. of New York 115pp. 13810:125 R4X Fiche 50-000,82/10/14,8208190238
- 8210260144 Forwards add1 info re IE Bulletin 80-11 Two add1 mesonry walls identified in fuel bids One wall located south of spent fuel pool is one well adjacent to ventilation penthouse Design adequacy will be re-evaluated GARRITY. J.H. Haine Yantee Atomic Power Co. 82/10/21. CLARK. R.A. Operating Reactors Branch 3. 2pp. 15799-089 24X Fiche. 50-309. 82/10/21. 8210260144.
- S Reportable occurrences, LERs & related correspondence
- B210270165 Forwards LER 81-005/031-0 MODD, E. C. Maine Yankee Atomic Power Co. 81/05/26, Region 1, Philadelphia, Office of the birector (81/03/01) 1p. 15822: 355. 24X Fiche, 50-309, 81/05/26, 8210270165

- --9210270177 LER 81-005/03L-0 on 810509, one of three RAS actuation switches failed to close Caused by math incompatibility Suitch replaced w/mproved model utilizing stain)ssx steel in place of brass w Haine Yankee Atomic Power Co Bi/05/26 Region 1. Philadelphia. Office of the Director (81/03/01) ip 15622 Jis 24X Fiche 50-309, 81/05/26, 8210270165
- 8210290267 Part Q1 deficiency rept to potential gallang problem it atom & bonnet of 1 25-inch & larger A105 carbon step) & A182-F22 valves supplied Feb 1981-Aug 1982 Valves should be serviced & stem %/or bonnet replaced IEA8ELLE, L D Conval. Inc 82/10/11 HAYNES, R & Region 1 6/2 of Director 17pp 15854 232 24X Fiche 50-000,62/10/11.
- 8210210015 Forwards LER 82-027/03L-0 NGDO.E C Maine Yankse Atomic Power Co 82/10/12 Region 1. Office of Director is 15766 021 24X Fichs 50-309,82/10/12 8210210015
- --9210210018 LER 62-027/03L-0 on 920929, containment isolaten \*\*\*\*\*
  safety injection actuation signal steam generator blowicun
  valve BD-T-32 failed to fully close Caused by loosa \*\*\*\*
  Indeed between disk & seating surface Parts replaced
  NELSON.R H Haine Yankee Atomic Power Co 82/10/12 Reg..\*\*\*
  Diffice of Director Ip 15766 022 24% Fische 50-109, 02/12/12
  8210210015
- 8210260193 Forwards LER 82~026/03L-0 W000/E C Maine Yankee Atomic Power Co 82/10/10 Region & Office of Director 1p 15804 272 24X Fiche 50~309,82/10/18 8210260193
- --B210260200 LER 82-026/03L-0 on B20924 one steam generator calety. Asiled to operate & two valves operated above Tech Oper Limits during test Caused by instrument drift Cause of instrument drift unknown NBLBON.R H Maine Yankee Atomic Power Co (12/10/10 Pign-Office of Director 2pp 15804-273 24% Fiche 30-30% 62/11 6210260193
- 6210240199 Forwards LER 82-028/03L-0 WQQD:E C Maine Yankee Atomic Power Co 82/10/19 Region' Office of Director in 18799 148 24X Fiche 50 70% NJ/10/11 8210220199
- --8210260208 LRR 82-028/03L-0 on 820929, containment isolation e.g. reset resulted in unexpected opening of control element drafve machenism cooler return valve Caused by open coil in Agastat EBF reset panel valve switch control relay NELBON, R H Hains Vankse Atomic Power Co 92/10/10 Ret. Office of Director 2pp 15799.149 24X Fichs 50 NOV. 62/1/1 8210260199
- 8210260327 LER 82-029/01T-0 scheduled eddy current tests of steel generator 2 tubes revealed small number of tubes exceeding tube plugging limit GARRITY. J.H. Haine Yankse Atomic Power Co. 62/10/16 Fest. Office of Director ip. 15801 362. 24X Fichs. 30-309 64/17/16 6210260327
- 8210290343 LER 82-029/017-1.eddy turrent tests on steam generally tubes revealed 10 tubes exceeding tube slugging limit Caulil by short radius bend tube degradation Constitut also reported by similar C-E plant GARRITY.J.H. Haine Vankes Atomic Power Co. 82/10.19 Pag. Office of Director ip. 15853 028. 24% Fiche 50-309.83/11 8210290343.
- DOCKET 50-311 SALEN NUCLEAR GENERATING STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8210230245 Forwards 1982 FEMA/NRC observed exercise scenario for exercise. Revisions reflect changes agreed upon during 820420 meeting w/NRC & FEMA RUPKO J.M. Fubic Bervice Electric & Gas Co. of New Jerses 82/09/16. HAYNES, R.C. Region 1, Office of Director 14859 13789: 002. 24% Fiche: 50-278, 82/09/16, 8210250245
- B210260518 Forwards exemption from requirements of 104f850 회대 대 protection of safe shutdown capability VARQALS.A. Operating Reactors Branch 1. B2/09/16 UD(제기)[[ PUBIC Bervice Electric & Oas Co of New Jersey Opp 1원22# 24K Fiche: 50-272,82/09/16,8210260518
- --8210260821 Exemption from requirements of 10CFR50 48 rr 41/2 pc. of table shutdown capability EIBENHUT.D O Division of Licensing. 82/09/16 Pushicar Electric & Oas Co of New Jersey 4pp. 15830 171 \$41 Fiche: 50-272, 82/09/16, 8210260518.

- --8210260524 Safety evaluation supporting licenses request for exemption from requirements of 10CFR50 48 re fire protection of safe soutdoon canability
  - \* Office of Nuclear Reactor Regulation, Director 82/09/16 3pp 15830 175 24X Fiche 50-272,82/09/16,8210260518
- 8210050431 Forwards exemption from requirements of Section IV F 1 of App E to 10CFR50 to allow next full-scale emergency preparedness exercise at facility to be conducted on or about 820929; granting 820709 request VAROA. S A Operating Reactors Branch 1 82/09/23 UDERITZ. R A Fublic Service Electric & Gas Co of New Jersey 3pp 15636 227 24X Fiche 50-272.82/09/23.8210060431
- --8210060433 Exemption from requirements of Section IV F 1 of App E to 10CFR50, to allow next full-scale emergency preparedness exercise at facility to be conducted on or about 820729 Evaluation encl EISENHUT. D 0 Division of Licensing 82/07/23 Public Service Electric & Oas Co of New Jersey 5pp 15636 230 24X Fiche 50-272,82/07/23,8210060431

### P Operating license stage documents & correspondence

- 821001000B Responds to FDIA request for 19 categories of documents re nuclear reactor events & safety problems forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A
  - FELTON, J H Division of Rules and Records 82/06/28 UDELL, R A Critical Mass Energy Project 15pp 15727 005 24X Fische 50-000,82/06/28,8210010008
- --B008050265 Discusses addl required info to better define potential for cracking in reactor vessel hollies of the ModNAR. V S Assistant Director for Materials & Gualifications Engineering B0/05/05 TEDESCO, R L Assistant Director for Licensing 2pp 15727 176 24X Fiche 50-000, 82/06/28,8210010008
- --8203310089 Forwards memo re equipment malfunctions during 820114 turbine load reduction operation Fallowing review of final rept from licensee & Region 1, will complete systuation of event for generic implications MICHELSDN.C Director's Office 82/03/15 JORDAN,E L. Division of Engineering & Quality Assurance 1p 15745 050 24X Fiche \$0-000,82/06/28.8210010008
- --8203310094 Summary of 820204 meeting re evaluation of sequence of events of Salem 820114 load reduction transient, operators actions; lessons learned & future remedial actions to be taken

  TREHAN, N K Director's Office 82/02/22 MICHELSON, C
  Director's Office 2pp 15734 036 24X Fiche 50-000, 82/06/28, 8210010008
- 8210050485 Forwards documentation of satisfactory completion of requirements contained in 790921 ltr re TMI Action Item II E 1 concerning auxiliary feedwater sys VARQA.8 A Operating Reactors Branch 1 82/09/20 UDERITZ, R A Public Service Electric & Oas Co of New Jersey 3pp 15626 277 24x Fiche.00-272.82/09/20.8210050485
- --8210050490 "Suppl to Safety Evaluation Rept for Salem Units i & 2 Implementation of Recommendations for Auxiliary Feedwater Sys "
  - Office of Nuclear Reactor Regulation, Director 82/09/20 3pp 15626 280 24% Fiche 50-272,82/09/20,8210050485
- 8210130603 Advises that installed monitoring sys required by TMI Action Items II F 1 4, II F 1 5 & II F 1 6 acceptable & items considered closed
  - VARQA: 5 A Operating Reactors Branch 1 92/09/28 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp. 15692:349 244 Fiche 50-272:82/09/28.8210130603
- B210190047 Informs that util rod exchange methodology not approved because of calculational content of reactivity measurement New Submittal or return to boron dilution method requested VARQA. S. A. Operating Reactors Branch 1 B2/09/29 UDERITZ, R. A. Public Service Electric & Oas Co. of New Jersey Spp. 15761 041 24X Fiche 50-272.82/09/29,8210190047.
- 8210190507 Application for amend to Licenses DPR-70 & DPR-75, revising core limits, fractional thermal power factor limit, performance of RCS water inventory balance & boron concentration & contained vol limits
  LIDEN.E A Public Service Electric & Gas Co of New Jersey 82/10/05 VAROA: S A Operating Reactors Branch 1 2pp. 15863.124, 24X Fiche 50-272,82/10/05,8210190507

- --8210190515 Proposed Tech Specs supporting application to amend Licenses DPR-70 & DPR-75 revising core limits fractional power factor limit parformance of RCS water inventory balance & boron concentration & contained vol limits

  \* Public Service Electric & Gas Co of New Jersey. 82/10/05
  17pp 15863 126 24% Fichs 50-272,82/10/05,8210190507
- 8210270136 License Change Requests 82-17-20-21 & 22 to Licenses DPR-70 & DPR-75. Changes involve inservice insp of snubbers, steam generator insp ports, containment ventilation valve insp & surveillance functional testing
  LINDEN,E A. Public Service Electric & Gas Co. of New Jersey.
  82/10/07 VARQA,E A. Operating Reactors Branch i. 3pp. 15827-026-24X Fich. 50-272,82/10/07,8210270136
- ---B210270142 Proposed Tach Spec changes Te inservice insp of snubbers, installation of steam generator insp ports, pressure drop test & reactor trip instrumentation a Public Service Electric & Oas Co of New Jersey B2/10/07 Bpp 15927 029 24% Fiche 50-272, B2/10/07. B210270136
- 8210180007 Advises that design changes satisfying concerns expressed in 820917 request for addlinfo re reactor protection sys/E6F actuation sys initiated Tech Specs will be modified to address setpoint changes LIDEN,E A Public Service Electric & Gas Co of New Jersey 82/10/08 VARQA,S A Operating Reactors Branch 1 lp 15720.024 24X Fiche 50-272.82/10/08.8210180007
- 8210270352 Forwards Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively, safety evaluation & notice of issuance & availability Amend revises process & effluent monitors to agree w/existing plant conditions.

  ROSB: W J Operating Reactors Branch | 82/10/18 UDERITZ,R A Public Service Electric & Oas Co. of New Jersey 2pp | 15834 318 24X Fiche 50-272,82/10/18,8210270352
- --8210270355 Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively, revising process & affluent monitors to agree w/existing plant conditions VARGA, 8 A Operating Reactors Branch 1. 82/10/18 14pp 15834 320 24X Fiche 50-272, 82/10/18, 8210270352
- --8210270360 Safety evaluation supporting Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively # Office of Nuclear Reactor Regulation, Director 82/10/18, App. 15834 334 24X Fiche 50-272-82/10/18,8210270352
- --8210270366 Notice of issuance & availability of Amends 48 & 13 to Licenses DPR-70 & DPR-75, respectively VARQA,B A Operating Reactors Branch 1 82/10/18 2pp 15834 340 24% Fiche: 50-272, 82/10/18,8210270352
- O Inspection reports: IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 17 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
  FELTON.J M. Division of Rules and Records, 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665:027 24X
  Fiche 50-000.82/07/12.8210080015
- --8210080180 Systematic assessment of licensee performance notes re facility evaluation for Sept 1979-Aug 1980 • NRC - No Detailed Affiliation Given 80/08/31 Bpp 15668 043 24X Fiche:50-000, 82/07/12, 8210080015
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines.App A documents provided in R Udell FOIA Request Bi-313 Forwards documents listed in App B FELTON.J. H. Division of Rules and Records. 82/08/10, LONG.D.J. Winthop. Stimson, Putnem & Roberts. 9pp. 15645-063 24X Fichs 50~000,82/08/10,8210070007
- --8210070139 Forwards tabulated data on steam generator insp & maint at Accilities. Data should be provided to licensees.

  IPPOLITO.T. Operating Reactors Assessment Branch 82/04/01.

  VAROA.8. Operating Reactors Branch 1 5pp 15645:131 24X

  Ficher 50-000, 82/08/10, 8210070007
- 3210120328 Responds to violations noted in IE Insp Repts 50-272/82-17 & 50-311/82-17 on 820707-0803 Corrective actions. administrative procedure will be revised to future temporary design changes are removed on timely basis. UDERITZ-R.A. Public Bervice Electric & Oas Co. of New Jersey. 92/09/28 HAYNES, C. Region 1, Office of Director STAROBIECKI, R. Division of Project & Resident Programs. Spp. 15652, 125 24% Fichs 50-272, 82/09/28, 8210120328

'nΥ

1

1 1

1 1

1

- 820B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Byc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Constildated Edison Co of New York 66pp 15761 250 24X Fiche 50-000.82/10/06,820B190233
- 8210210405 Forwards IE Insp Repts 50-272/82-20 & 50-311/82-20 on 820816-20 No noncompliance noted MARTIN.T.T. Division of Engineering & Technical Programs 82/10/06 UDERITY.R.A. Public Service Electric & Gas Co. of New Jersey 2pp 15769 036 24X Fiche 50-272,82/10/06,8210210405
- --8210210451 IE Insp Repts 50-272/82-20 & 50-311/82-20 on 820816-20 No noncompliance nated Hajor areas inspected qualification & training radiological surveys radiation exposure permits, posting, licensee audits & exposure control HOSEY.C M. ROWELC & OREENNAN.E Q. Division of Engineering & Tachnical Programs 82/09/30 5pp 13763-038 24X Fiche 50-272,82/10/06.8210210435
- 8210210464 Forwards IE Insp Repts 50~272/82~25 & 50~311/82~24 on 820901~27 & notice of violation STAROBIECKIAR Division of Project & Resident Programs. 82/10/06 UDERITIAR A Public Service Electric & Gas Co of New Jersey 2pp 13763 016 24X Fiche 30~272,82/10/06.8210210464
- --8210210469 Notice of violation from insp on 820701-27
  \*\* Region i, Office of Director 82/10/06 ip 15763,020 24X
  Fiche: 50-272,82/10/06,8210210464
- --8210210477 IE Insp Repts 50-272/82-25 & 50-311/82-24 on 820901-27 Noncompliance noted trip breaters closed w/o two operable source range instruments in svc & failure to submit 30-day LER NORRHOLH, L. J. SUMMERS, R. TRIPP, L. E. Division of Project & Resident Programs 82/10/04 15pp 15763 021 24X Fiche 50-272,82/10/06,8210210464
- B210270136 License Change Ruquests B2-17-20-21 & 22 to Licenses DPR-70 & DPR-75 Changes involve inservice insp of snubbers, steam generator insp ports, containment ventilation valve insp & surveillance functional testing LINDEN, E A Public Bervice Electric & Gas Co of New Jersey B2/10/07 VARGA, B.A. Deparating Reactors Branch ( 3pp 15827 026 24X Fiche: 50-272,82/10/07,8210270136
- --8210270142 Proposed Tech Spec changes re inservice insp of snubbers, installation of steam generator insp ports, pressure drop test it reactor trip instrumentation

  Public Service Electric & Gas Co of New Jersey 82/10/07

  8pp 15827 029. 24X Fiche 50-272,82/10/07,8210270136
- 820B19023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hall.Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list encl. DEYOUNDER C Director's Office, Office of Inspection and Enforcement. 82/10/14. Consolidated Edison Co of New York 115pp 15810-125 24X Ficher 50-000, 82/10/14, 820B19023B
- 8210280221 EN-82-034 on 821027, notice of violation & proposed imposition of civil panalty in amount of \$40,000 issued reinadequate vital physical area barrier ROSAND.R., AXELRAD.J Director's Office. Office of Inspection and Enforcement 82/10/22 ip 15837 087 24% Fiche 50-272.62/10/22, paragraphysical
- R Periodic operating reports & related correspondence
- 8210200010 Forwards monthly operating rept for Bept 1982 MIDURA: H J Public Service Electric & Qas Co. of New Jersey. ice, Office of Inspection and Enforcement. 30-31:82/10/10.8210200010

f New Jersey. 2/10/10,8210200010

- 8210010008 Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON.) M Division of Rules and Records 82/06/28 UDELL.R & Critical Mass Energy Project 15pp 15727 005 24% Fiche 50-000.82/06/28,8210010008
- --8210050124 Summary of 810610 operating reactor events meeting LAINAS, C.C. Assistant Director for Safety Assessment 01/06/17 ; EISENNUT. D.O. Division of Licensing Spp 15729 217 241 Fichs 50-000, 82/06/28, 8210010008
- 8210010045 Forwards LER 82-095/03L-0 Detailed event analysis shell MIDURA, H J Public Service Electric & Qas Co of New Jergay 82/09/16 HAYNES, R C Region 1, Office of Director 3pp 15565 137 24X Fiche 50-311,82/09/16,8210010045
- --9210010047 LER 82-095/03L-0 on 820831. surveillance revealed that do not placed in valve 21 MS46 of auxiliary feedwater systems line 23 Caused by sheared off stud which attaches valve dist to hanger Engineering analysis conducted HELLER.R Public Service Electric & Gas Co of New Jersey 82/09/16 Region 1, Office of Director 19 15565 140 246 Fiche 50-311,82/09/16.8210010045
- 8210010123 Forwards LER 82-092/01T-0 Detailed event analysis and MIDURA: H J : HELLER: R Public Service Electric & Qas Co of New Jersey 82/09/16. HAYNES: R C Region I, Office of Director 1, 13566 014 24X Fiche 50-311.82/09/16.8210010123
- --B21001012B LER 82-092/01T-D on 82090B, svc water last discovered st containment fan coil unit 21 Caused by erosion of motor cooling coils Motor cooler replaced & fan coil tested satisfactorily HELLER, R Public Service Electric & Gas Co of New Jarsey 82/09/16 Region 1. Office of Director 1p 15566 810 248 Fiche 50-311.82/09/168210010123
- 8210010144 Forwards LER 82-096/03L-0 Detailed event analysis and MDURA, H J Public Service Electric & Oas Co of New Jerry 82/09/16 HAYNES, R C Region 1. Défice of Director 3ep 15567 240 24X Fiche 50-311,82/09/16,8210010144
- --B210010150 LER 82-096/03L-0 on 820831, containment fan ceil unit 23 declared inoperable when operator received indication of low svc water flow Caused by silt buildup in cooling coils flow control valve cycled & unit tested satisfactorily HELLER, R Public Service Electric & Cas Co of New Jersey 82/09/16 Region 1. Office of Director ip 13367 243 [4] Fiche 50-311,82/09/16.8210010144.
- 8210010237 Forwards LER 82-090/03L-0 Detailed event analysis and MIDURA, H. J. Public Service Electric & Cas Co. of New Jersey 82/09/16 HAYNES, R.C. Region 1, Office of Director 3sp 15574 018 24X Fiche 50-311,82/09/14,8210010237.
- --8210010239 LER 82-070/03L-0 on B208R2, operator discovered less enter 100-ft elevation containment air lock outer door Caused by rubber seal partially leaving retaining groove due to personnel closing door w/excessive force Seal replaced HELLER, R Public Service Electric & Cas Co of New Jersiy B2/09/16 Region i, Office of Director ip 15574 021 au Fiche, 30-311, 82/09/16, 8210010237
- 8210010344 Forwards LER 82-074/03L-0 Detailed event analysis and HIBURA, H J. Public Service Electric & Qas Co of New James 82/07/16 HAYNES, R C. Region 1. Office of Director Sas 15567-229. 24X Fiche 50-311,82/09/16,8210010344
- --8210010355 LER 82-094/03L-0 on 820825,2C vital bus underveltage free failed to trip at required setpoint Causad by setpoint drift Channel declared operable & Action Statement 3.3 % Action 14 terminated HELLER, R. Public Service Electric & Gas Co. of New Jerse 82/09/16. Region 1, Defice of Director 1p. 15569-232 Franche: 50-311, 82/09/16, 8210010344
- B210010407 Forwards LER B2-08B/O3L-0 Detailed event analysis inti MIDURA.H.J Public Service Electric & Oas Co. of New Jersey B2/09716 HAYMES.R.C Region 1. Office of Director Jap 15572-203. 24X Fiche 50-311, B2/09/16, B210010407
- --8210010412 LER 82-088/03L-0 on 820824, containment fan teil weit 20 declared inoperable after low svc water flow observat Causad by air regulator being out of adjustment. Air regulator adjusted & fan coil unit satisfactorily tested.

  HELLER, R Public Service Electric & Gas Co. of New Javist 82/09/16 Region 1, Office of Director 1p 15572 204 24 Fichs. 50-311, 82/09/16. 8210010407

- 8210010419 Forwards LER 82-093/017-0 Detailed event analysis encl HIDURA.H J Public Service Electric & Oas Co of New Jersey 82/097/16 HAYNES.R C Region 1. Office of Director App 15569 338 24x Fiche 50-311,82/097/16.8210010419
- --8210010423 LER 82-093/01T-0 on 820910, containment fan coil unit 21 declared inoperable when svc water leak discovered Caused by erosion of cooling coil Leaking coil blanked off Design change submitted to replace coils w/erosion resistant matl HELLER.R Public Service Electric & Oas Co of New Jersey 82/09/16 Region 1, Office of Director 1p 15569 342 24% Fachs 50-311,82/09/16.8210010419
- 8210010455 Forwards LER 82-102/03L-0 Detailed event analysis encl HIDURA:H J Public Service Electric & Gas Co of New Jersey 82/09/16 HAYNES:R C Region 1. Diffice of Director 3pp 15570 001 24x Fiche 50-311,82/09/16.8210010455
- --B21001046: LER 82-102/03L-0 on B20823.130-ft elevation containment air lock declared inoperable after excessive leakage discovered past inner door seals Caused by closing door w/excessive force Seal replaced installation of snubbers proposed HELLER: R Public Service Electric & Cas Co of New Jersey B2/09/16 Region 1. Office of Director 1p 15570 004 24% Fiche 50-311,82/09/16.8210010455
- S210070221 Forwards LER 82-101/01T-0 Detailed event analysis encl MIDURA:H J Public Service Electric & Oas Co of New Jersey 82/09/22 HAYNES:R C Region 1, Office of Director App 15637 156 24X Fiche 50-311,82/09/22,8210070221
- --B210070231 LER 82-101/01T-0 on 820916.svc water leakage discovered in cooling coils of containment fan coil unit 21 Caused by excessive erosion of cooling coils by silt Coils repaired New design coils will be installed during next refueling FRAMHAR Public Service Electric & Oas Co of New Jersey B2/09/22 Region 1. Office of Director ip 15637:160 24X Fiche 50-311,82/09/22.8210070221
- 8210070246 Forwards LER 82-099/03L-0 Detailed event analysis encl MIDURA: H J Public Service Electric & Gas Co of New Jersey 82/09/22 HAYNES,R C Region 1. Office of Director 3pp 13534 293 24x Fiche 50-311.82/09/22.8210070246
- --8210070248 LER 82-079/03L-0 on 820902, control room operator received indication of low svc water flow on containment fan coil 23 Caused by slit buildup in cooling coils 8vc water flow control isolation valve cycled HELLER.R Public Service Electric & Gas Co of New Jersey 82/09/22 Region 1, Office of Director ip 15634 294 24X Fiche 50-311,82/09/22,8210070246
- B210070249 Forwards LER B2-100/017-0 Detailed event analysis encl MIDURAH J Public Service Electric & Gas Co of New Jersey B27097/22 HAYNES,R C Region 1, Office of Director 4pp 15834 288 24X Fiche 50-311,827097/22,8210070249
- --8210070252 LER 82-100/01T-0 on 820915, svc water leak of approx 0 3 gpm discovered on cooling coil of containment fan coil 22 Caused by excessive erosion of cooling coil by silt in svc water. Leaking coil repaired FRAHN.R Fublic Service Electric & Gas Co of New Jersey. 62/09/22 Region 1 Office of Director ip 15694 292 24X Fiche 50-311,82/09/22.8210070249
- 8210070254 Forwards LER 82-061/03X-1 Detailed event analysis encl HIDURA:H J Public Service Electric & Gas Co of New Jersey 82/09/22 HAYNE9:R C Region 1. Office of Director 3pp 15634 283 24X Fiche 50-311.82/09/22.8210070254
- --821007025B LER 82-061/03/-1 on 820716.steam generator level channel II indication erratic Caused by leakage past packing on Root valve 218F28 Valve repacked & leakage stopped FRAMH.R Public Service Electric & Gas Co of New Jersey 82/07/22 Region i, Office of Director ip 15634.286 24X Fiche 50-311,82/07/22.8210070254
- 8210070351 Forwards LER 82-078/03L-0 Detailed event analysis encl MIDURA: H J Public Service Electric & Oas Co. of New Jersey 82/07/22 HAYNES, R C Region 1, Office of Director 2pp 15634 047 24X Fichs 50-311,82/09/22,8210070351
- --B210070359 LER 82-098/03L-0 on 820901.indication of low syc water flow received on containment fan coil unit 21 Caused by silt build-up in cooling coils 8vc water flow control valve cycled & coil unit tested satisfactorily HELLER.R Public Service Electric & Gas Co of New Jersey B2/09/22 Region 1. Office of Director ip 15634 050 24X Fiche 50-311,82/09/22.8210070351

- B210070371 Forwards LER 82-012/03X-1 Detailed event analysis encl MIDURA:H J Public Service Electric & Qas Co of New Jersey 82/09/22 HAYNES:R C Region 1. Office of Director 3pp 15433.027 24X Fichs 50-311,82/09/22.8210070371
- --8210070377 LER 82-012/03X-1 on 820209, steam generator level channel 2 displayed erratic behavior, indicating drift Apparently caused by intermittent ground on signal lead. Ground eliminated by lifting leads while troubleshooting problem FRAHM.R Public Service Electric & Qas Co of New Jersey 82/09/22 Region 1, Office of Director ip 15634 030 24% Fiche 50-311,82/09/22,8210070371
- 8210130164 Forwards LER 82-103/03L-0 Detailed event analysis encl MIDURA,H J Public Service Electric & Qas Co of New Jarsey 82/09/29 HAYNES,R C Region i. Office of Director 3pp 15473 057 24X Fichs 50-311,82/09/29,8210130164
- --8210130170 LER 82-103/03L-0 on B20704, while running auxiliary alarm summary, control breaker alarm observed for containment spray pump 21 Causad by opened 4 kv breaker HL contact Breaker racked out & pump declared operable FRAHM-R Public Service Electric & Gas Co of New Jersey 82/09/29 Region 1, Office of Director 1p 15673-060 24X Fiche 50-311,82/09/29.8210130164
- 82:0130219 Forwards LER 82-097/03L-0 Detailed event analysis encl MIDURA,H J Public Service Electric & Gas Co of New Jersey 82/09/29 HAYNES,R C Region 1. Office of Director 3pp 156/5 265 24X Fiche 50-311,82/09/29,8210130219
- ---8210130227 LER 82-097/03L-0 on 820910.RCS water inventory not performed within specified time interval Caused by failure of surveillance to make allowance for routine unavoidable transients practuding inventory performance FRAHM.R Public Service Electric & Cas Co of New Jersey 82/09/29 Region 1. Office of Director ip 15675 268 24X Fiche 50-311.82/09/29.8210130219
- 8210130340 Forwards LER 82-105/03L-0 Detailed event analysis encl MIDURA,H J Public Service Electric & Qas Co of New Jersey 82/09/29 HAYNES,R C Region 1. Office of Director 3pp. 18682-046 24X Fiche 50-311,62/09/29,6210130340.
- --8210130345 LER 82-105/09L-0 on 82090B, svc water flow to containment fan coil unit 22 found less than required by Tech Specs. Caused by silt deposited in cooling coils restricting svc water flow Pressure control valve cycled to flush out silt FRAHM.R Public Service Electric & Cas Co of New Jersey 82/09/29 Region in Office of Director ip 15682 049 24X Fiche 50-311,82/09/29.8210130340
- 8210130351 Forwards LER 82-107/01T-0 Detailed event analysis encl MIDURA, H J Public Service Electric & Oas Co of New Jersey 82/09/29 HAYNES, R. C. Region 1. Office of Director 4gp 15680 315. 24X Fichs 50-311.82/07/29,8210130351
- --82i0i30358 LER 82-109/01T-0-on 820923.svc water leakage of approx 0 5 gpm discovered on containment fan coil unit 21 cooling coil Caused by erosion by silt in svc water Leaks repaired w/blanked fiange & Beliona metal filler.
  FRAHM.R. Public Service Electric & Gas Co of New Jersey 82/09/29 Region 1 Office of Director ip 15680-319 24X Fiche 50-311,82/09/29.8210130351
- 8210150057 Forwards LER 82-086/03L-0 Detailed event analysis encl MIDURA,H J Public Service Electric & Oas Co of New Jersey. 82/09/29 HAYNES,R. C Region 1, Office of Director 3pp 15698 300 24x Fiche 30-311.82/09/29,8210150057
- --8210150065 LER 82-086/03L-0 on 820915, water observed dripping from oil level sightglass on svc water pump motor Caused by failed motor bearing oil cooler due to accelerated erosion & corrosion Failed cooler repaired.

  FRAHMIR Public Service Electric & Oas Co. of New Jersey 82/07/27 Region 1, Office of Director 1p. 15698,303, 24X Fiche 50-311,82/09/29,8210150087.
- 8210150109 Forwards LER 82-104/03L-0. Detailed event analysis encl MIDURA: H J. Public Service Electric & Oas Co of New Jersey. 82/09/29 HAYNES, R C. Region i. Office of Director 3pp. 15697 059 24X Fiche 50-311,82/09/29,8210150109
- --B210150118 LER 82-104/03L-0 on 820708, vital bus 2A would not transfer automatically from one 4 kV transformer to another. Caused by dirt in undervoltage relay Relay cleaned FRAHMAR. Public Service Electric & Qas Co of New Jersey 82/07/27. Region 1. Office of Director. Ip 15697 062 24X Fiche 50-311, 82/09/29, 8210150107

- 8210190088 Forwards LER 82-073/017-0 MIDURA.H J Public Service Electric & Gas Co of New Jersey 82/09/30 HAYNES.R C Region 1. Office of Director 1p 15701 198 24X Fiche 50-3(1,82/09/30.8210150088
- --8210150093 LER 82-073/01T-0 on 820813, during containment entry, 1 5 gpm syc water leak discovered on containment fan coil Unit 23 Causad by failed cooling coil due to erosion by silt particles Leak repaired w/8elitona metal filler FRAHM.R Public Service Electric & Cas Co of New Jersey 82/08/16 Region 1. Office of Director ip 15701 199 24X Fiche 50-311, 82/09/30. 8210150088
- 8210150097 Forwards corrected LER 82-075/01T-0 MIDURA,H J Public Service Electric & Qas Co of New Jersey 82/09/30 HAYNES,R C Region 1. Office of Director 1p 15707 302 24x Fichs 50-31; 82/09/30: 8210150099
- --8210)50320 Corrected LER 82-075/017-0 on 820814.1 gpm svc water heak discovered on containment fan coil unit 22 Cause not determined. Unit repaired by blanking flanges in svc water piping to coil New design coils will be installed FRAHM.8 Public Service Electric & Qas Co of New Jersey 82/08/18 Region 1. Office of Director in 15707-303 24% Fiche 50-311,82/09/30.8210150099
- 8210180311 Forwards corrected LER 82-074/01T-0 HIDDRAIH J Public Service Electric & Cas Co of New Jersey 82/09700 HAYNES R C Region 1. Office of Director 1p 15701.343 24% Fichs 50-311.82/09/30.8210150311
- --8210150337 Corrected LER 82-074/017-0 on 820813.control operator discovered increased leakage to containment sump Caused by coil failures due to silt particles in svc water Leak repaired by blanking flanges
  FRAHM.R Fublic Service Electric & Cas Co of New Jersey 82/09/18 Region 1. Office of Director 1p 15701:344 24X Fiche 50-311,82/09/30.8210150311
- 8210070243 Telecopy message of LER 82-331/01P on 821002, during routine power operation, see water leak discovered inside containment bldg on containment fan coil unit 23 Cause undetermined Rept will be submitted per IE Bulletin 80-24 MIDURA:H J Public Service Electric & Oas Co of New Jersey 82/10/04 HAYNES,R C Region 1, Office of Director 1p 15649 243 24% Fiche: 50-311.82/10/04.8210070243
- 8210080241 LER 82-113/01P on 621005, during routine operation, syc water leak discovered inside containment on fan coil 22 Cause unknown Investigation in progress Rept will be submitted per IE Bulletin 60-24 MIDURA-H.J Public Service Electric & Cas Co of New Jersey 82/10/04 HAYNES, R C Region I, Office of Director 1p 15638 077 24X Fiche-50-311.82/10/04.8210080241
- 8210080294 LER 82-112/01P on 821005, svc water discovered leating at rate of 1 gallon per minute inside containment bldg on fen coil unit 21 Cause not stated Leak isolated Investigation continuing Detailed rapt forthcoming MIDURAH J Public Bervice Electric & Oas Co of New Jersey 82/10/06 HAVMESR C. Region 1, Office of Director ip. 15638:295 24% Fiche 30-311,82/10/06,8210080296
- G210250053 Forwards LER G2-106/03L-O Detailed event analysis encl #IDURALN J Public Service Electric & Gas Co of New Jarsey B2/10/06 HAVNESR C Region 1. Office at Director 3pp 19767.086 24X Fiche 50-311.82/10/06.8210250053
- --9210250057 LER 82-106/03L-0 on 820913,six broken links discovered on circulator travelling screen 21A Possibly caused by stress-induced cracking.Links replaced Design change request issued to consider stainless atsel links FRAMM.R. Public Service Electric & Oas Co of New Jersey, 82/10/06 Region 1, Office of Director. Ip 15787.089 24X Fiche 50-311,82/10/06,8210250053.
- 9210250392 Forwards LER 82-108/03L-0 Detailed event analysis encl. MIDURA, H. J. Public Service Electric & Gas Co., of New Jersey 82/10/06. HAYNES, R. C. Region 1, Office of Director. App 15790.072. 24x Fiche. 50-311.82/10/06.8210250382
- --8210250389 LER 82-108/03L-0 on 820915 % 17.RPI 104 discovered reading greater than 12 steps lower than bank demand indication. Caused by combination of RPI module calibr drift & change in actual rod position signal output. FRAMM.R. Public Service Electric & Gas Co. of New Jersey 82/10/06 Region 1. Office of Director, ip. 15790:076. R4X Fiche: 50-311,82/10/06.8210250382

- 8210190644 LER 82-119/01P on 821008.1 gpm svc water leak discovered to containment fan coil unit 21 Leak isolated Investigation in propress Detailed rept will be submitted per IE Bulletin 80-24
  HIDURA:H J Public Service Electric & Oas Co of New Jersey 82/10/12 HAYNES:R C Region 1, Office of Director jp 15737 213 24X Fache 50-311.82/10/12.8210190644
- 8210190651 LER 82-120/01P on 821011.0 5 gpm svc water lesk distorred on containment fan coil unit 21 Leak isolated Investigation in progress Detailed rept will be submitted per IE Bulletin 60-24 MIDURA, H J Public Service Electric & Cas Co of New Jersey 82/10/12 HAYMES, R C Region 1. Office of Director 1p 15737 212 24X Fiche 50-311.82/10/12.8210190451
- S210280123 Forwards LER 113/01T-0 Detailed event analysis encl MIDURA: H J Public Service Electric & Gas Co of New Jersey 82/10/15 AAYNES: R C Region 1. Office of Director App 15837 158 24X Fiche 50-311.82/10/15.8210280123
- -821028012B LER 82-113/01T-0 on 821005, small svc water leak distance on cooling couls of containment fan coul unit 22 Caused by erosion of cooling couls by sult in svc water Coul repaired w/Belzona metal filler FRAHM. Public Service Electric & Oas Co of New Jarsey 82/10/15 Region I, Office of Director ip 15837 162 248 Fiche 50-311, 82/10/15, 8210280123
- B210280152 Forwards LER 82-112/01T-0 Detailed event analysis encl MIDURA.H J Public Service Electric & Gas Co of New Jersey B2/10/15 HAYNES.R C Region 1. Office of Director Ipp #5837 221 24% Fiche \$0-311.82/10/15.8210280152
- --8210280155 LER 82-112/017-0 on 821005, svc water leak of 1 0 gis from flange in piping discovered on containment fan coll unit 21 Caused by removal of blank following Belzona repair Flange retorqued FRAHM.R Public Service Electric & Gas Co of New Jersey 82/10/15 Region 1, Office of Director 1p 15837 224 241 Fiche 50-311,82/10/15,8210280152
- 8210260335 LER 82-122/01P on 821018, svc water leak of approx 0.4 pps discovered on containment fan coil unit 24 Leak isolated Detailed rept to be submitted MIDURAH J Public Service Electric & Oas Co of New Jarsey 82/10/19 HAYNES, R C Region i, Defice of Director ip 15804 275 24X Fiche 50-311,82/10/19,8210240335
- DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

  F Security, medical, emergency & fire protection plans
- 8210010057 Provides clarification of 820920 telcon re TMI Action Itself III A 1 i Radiological surveys that cannot be performed by NRC-supplied equipment will be performed by util staff MATTIMOE, J J Bacramento Municipal Utility District 82/09/22 EISSEMHUT.D 0 Division of Licensing 2pp 19565 117 24X Fiche, 50-312, 82/09/22, 8210010057
- 8210270314 Forwards Amend 40 to License DPR~54 & notice of issuance & availability Amend adds License Condition 2 C (10) reimplementation of IAEA safeguards
  8TOLZ.J F Operating Reactors Branch 4 82/09/29 MATTIMOE.J J Sacramento Municipal Utility District 4pp 15836 341 24X Ficher 50-312, 82/09/29, 8210270314.
- --8210270317 Amend 40 to License DPR-54, adding License Condition 2 three implementation of IAEA safeguards STOL7.1 F Operating Reactors Brench 4 82/09/29 5pp 15836.345. 24X Fiche 50-312, 82/09/29, 8210270314
- --8210270320 Notice of issuance & availability of Amend 40 to Littose DRR-54 8TOL7.J.F. Operating Reactors Branch 4 82/09/29 2pp 15836 350 24X Fiche: 50-312, 82/09/29, 8210270314.
- 8210190228 Forwards "Systematic Assessment of Licenses Performance Rancho Seco." for Jul 1981-Sept 1982 Performance analyses for listed functional areas requested by 821112
  STERNBERO, D. M. Division of Resident, Reactor Project & Engineering Programs. 82/10/14 YOUNO.T. CANTER. H. D'BRIEN. J. Region 5. Office of Director 2pp 13742 201 24X Fiche 50-312,82/10/14. 8210190228.
- --8210190231 "Bystematic Assessment of Licensee Performance, SMD Byuk Beco," for Jul 1981-Sept 1982 # Region 5, Office of Director, 82/10/31, 24pp 15742 203 A Fiche 50-312, 82/10/14, 8210190228

# **DOCKETED ITEMS**

- S210250055 Forwards Amend 11 to security plan Amend withheld fref 100F873 21)
  MATTIMUE.J J Sacramento Municipal Utility District 82/10/15
  STGLZ.J F Operating Reactors Branch 4 lp 15787 048 24X
  Fichs 50-312, 82/10/15, 8210250055
- 2 Adjudicatory correspondence
- E210940073 Order directing NRC to provide results of NRC reviews of util revised reliability analysis of proposed mods to apublishing feedwater sys & Brookhaven rept on analysis by E21201

  FOPPAINS.B A Atomic Safety and Licensing Appeal Panel B2/09/30 2pp 15581 O35 24X Fishe 50-312,82/09/30,8210040093
- E210190370 Notice of RL Black withdrawal of appearance & RP Lessy appearance in proceeding Certificate of Svc encl PLACK.R L . LESSY.R P Hearing Branch 3 82/10/15 4pp 15741 207 24X Fiche 50-312,82/10/15.8210190370
- 62101903Bi Advises that NRC will provide results of reviews of reliability study of modified auxiliary feedwater sys by 821201 even though util intends to install sys in mid-1984, not Jan 1983, as anticipated 6LACK.R L. Hearing Branch 3 82/10/15 ROBENTHAL, A S , KOHL, C N , 8UCK. J K Atomic Safety and Licensing Appeal Panel 2pp 15740 346 24% Fiche 50-312,82/10/15,8210190381
- P Operating license stage documents & correspondence
- 2210180195 Forwards safety evaluation supporting adequaty of station electrical distribution voltages, based on 820421 submittal Requests verification of test schedule within 45 days of 1tr receipt STOLZ-JF Operating Reactors Branch 4 82/09/20 MATTIMOE, JJ Sacramento Municipal Utility District 3pp 15747 329 24X Fiche 50-312, 82/09/20, 8210180195
- --8210180201 Safety evaluation supporting adequacy of station electric distribution sys voltages subj to completion of proposed mods

  4 Operating Reactors Branch 4 82/09/20 7pp 15747 332 24X
  Fiche 50-312,82/09/20,8210180195
  - Fiche 50-312, 82/09/20, 8210180195
- --8205170006 "Technical Evaluation of Adequacy of Station Electric Distribution Sys Voltages for Rancho Seco Nuclear Generating Station Unit 1." selected issues program MHITE.R L. Lawrence Livermore Laboratory FIN A-0250 UCID-19143 81/11/10 Assistant Director for Operating Reactors 14pp Available at NTIS \$5.00 15747 339 24X Fiche 50-312,82/09/20,8210180195
- E210190594 Application to amend License DPR-54, revising Tech Spers to allow for replacement of existing fuel storage racks w/high density poisoned storage racks MATTIMUE, J J Sacramento Municipal Utility District 82/09/28 Division of Licensing 2pp 15739 106 24X Fiche, 50-312, 82/09/28, 8210190594
- --8210190598 Proposed Tech Specs allowing for replacement of existing fuel storage racks w/high density poisoned storage racks \* Sacramento Municipal Utility District 82/09/28 ip. 15739 108 24X Fiche 50-312,82/09/28,8210190594
- --8210170603 "Licensing Rept for Spent Fuel Storage Capacity Expansion "

  \* Sacramento Municipal Utility District 82/06/30 165pp
  15739 110 24% Fiche 50~312,82/09/28,8210170574
- 9210270314 Forwards Amend 40 to License DPR-54 & notice of issuance & availability Amend adds License Condition 2 C (10) re unp kementation of IAEA safeguards GTOLZ.J F Operating Reactors Branch 4 82/09/29 MATTIMDE.J J Sacramento Municipal Utility District 4pp 15836 341 24X Fiche 50-312, 82/09/29, 8210270314
- --8210270317 Amend 40 to License DPR-54, adding License Condition 2 C (10) re implementation of IAEA safeguards
  STGLZ-J F Operating Reactors Branch 4 82/09/29 Spp.
  15836 345 24X Fiche 50-312, 82/09/29, 8210270314
- --8210270320 Notice of issuance & availability of Amend 40 to License DPR-54 S¥CLI.JF Operating Reactors Branch 4 82/09/29, 2pp 15836-350 24X Fiche 50-312,82/09/29,8210270314,
- B210050220 Forwards "Transient Assessment Rept for Rancho Seco Reactor Trip on B10807," per request HATTINGE.J. J. Sacramento Municipal Utility District 82/09/30 HINGES Operating Reactors Branch 4 44pp. 15611 029 24X Fiche.50-312.82/09/30.8210050220

- 8210130175 Advises that diesel generator room supply & exhaust fans will be moved to Block 4 to resolve NRC concerns arising from sequencing auxiliary feedwater pump anto bus at 35-s No diesel generator sequential loading test will be performed MATTIMOE.J J Sacramento Municipal Utility District 82/10/05 STOLZ.JF Operating Reactors Branch 4 3pp. 15673-026 24X Fiche 50-312, 82/10/05.8210130175
- 8210150519 Discusses NRR actions taken under Task Interface Agreement 82-20 for steam generator auxiliary feedwater header damage Licensee authorized to resume power operation at Ocones 3
  EISENMUT.D Q Division of Licensing 82/10/06 OLSMINSKI, J Division of Engineering & Technical Programs 1p 15717 261 24X Fiche 30-000, 82/10/06. 8210150519
- 8210190331 Forwards add1 info requested 820712 re TMI Item II B 3, "Post-Accident Sampling Sys" MATTIMOE, J J Sacramento Municipal Utility District 82/10/13 STOLZ) F Operating Reactors Branch 4 19pp 18742 066 24X Fiche 50-312, 82/10/13, 8210190331
- 8210190228 Forwards "Systematic Assessment of Licensee Performance, SMUD Rancho Seco," for Jul 1981-Bept 1982 Performance analyses for listed functional areas requested by 821112 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/30/14 YOUNG, T. CANTER, H. G'ORIEN, J. Region 5, Office of Director 2pp 19742 201 24X Fiche 50-312,82/10/14, 8210190228
- --B210190231 "Systematic Assessment of Licensee Performance, SMUD Ranchu Seco," for Jul 1981-Sept 1982 \* Region 5, Office of Director 82/10/31 24pp 15742 203 24X Fiche 50-312,82/10/14.8210190228
- 8210190381 Advises that NRC will provide results of reviews of reliability study of modified auxiliary feedwater sys by 821201 even though util intends to install sys in mid-1984, not Jan 1983, as anticipated DLACK, R L Hearing Branch 3 82/10/15 ROSENTHAL, A B, KOHL, C N, 8UCK, J H Atomic Safety and Licensing Appeal Panel 2pp 15740 346 24% Fishe 50-312,82/10/15.8210190381
- 8210250074 Responds to B&W potential deficiency rept re effects of ring settings on Dresser safety valves Two Model 31759A Dresser valves operable per Tech Specs Short inlet pipe configuration expected to remain stable during B&W testing MATTIMOE.J.J. Sacramento Municipal Utility District 82/10/19. STOLZ.J.F. Operating Reactors Branch 4 2pp 15787 07: 24X Fiche 50-312,82/10/19.8210250094
- 8210260231 Documents util position re mafety valve operability. Volve performance cannot be quantitatively determined for given ring settings Preliminary D&W evaluation confirms util position pending more rigorous analysis per NUREO-0737 MATTIMOE. J. J. Sacramento Municipal Utility District 82/10/21 STOLZ. J. F. Operating Reactors Branch 4 (p. 15803-229-24X Fiche 50-312. 82/10/21. 821026031
- 8210280228 Comments on NRC safety evaluation of NUREO-0737, Items II E 1 2 1 & II E 1 2 R re auxiliary feedwater automatic initiation & flow indication transmitted by 820907 itr Safety grade flow instrumentation info due by Jan 1983 MATTIMOE, J. J. Bacramento Municipal Utility District 82/10/22 870LZ, J. F. Operating Reactors Branch 4 2pp 15837:028 24X Fiche 50-312,82/10/22,8210280228.
- 8210280163 EN-82-020A notice of order imposing civil monetary penalty issued to util Proposed action was based on two items of noncompliance Both items resulted from failure to properly return safety-related equipment to svc CRAIG, J. AKELRAD, J. Director's Office, Office of Inspection and Enforcement 82/10/26 ip. 15837:208. 24X Fichs 50-312,82/10/26,8210280163
- Q Inspection reports. IE Bulletins & correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems. Forwards documents listed in App A. FELTON.J M. Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project. 15pp. 13727 005. 24X Fiche 30-000.82/06/28.8210010008.
- --8111191042 Comments on draft IE circular re MSIV failures to close Problem w/control air for MSIV may be part of larger spectrum of problems for many valves MICHELSON.C Director's Office. 81/10/01. JGRDAN.E.L. Division of Resident & Regional Reactor Inspection 1p. 19700:335, 24X Fiche. 50-000,82/06/28,821001008.

- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON.J H Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X Fiche 30-000.82/07/12.6210080015
- --B2100B014B Systematic assessment of licentee performance notes re facility evaluation for 790415-B00415 e NRC - No Detailed Affiliation Ouven B0/04/15 Spp 1564B 035 24X Fiche 50-000, 82/07/12, 82100B0015
- 8210070007 Responds to FDIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON.J H Bivision of Rules and Records 82/08/10 LONG.D J Minthrop. Stimson. Putnam & Roberts 9pp 15645 063 24X Fiche 50-000-82/08/10,8210070007
- --8210070172 Forwards info re steam generator integrity & Insps at all operating PWRs, per 750320 & 21 requests Details of insps. including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach i GOLLER, K.R. Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY, R.R. Division of Technical Review (NRR-1975 only) 5pp 15645 196 24X Fiche 30-000, 82/03/10, 8210070007
- 8210060330 Forwards IE Insp Rept 50-312/82-35 on 820804-0914 No noncompliance noted STERNBERG, D H Division of Resident, Reactor Project & Engineering Programs 82/09/23 MATYIM3E, J. Secremento Municipal Utility District 2pp 15419 036 287 Fiche 50-312,82/09/23,8210060330
- --8210060336 IE Insp Rept 50-312/82-35 on 820804-0914 No noncompliance noted Major areas inspected operational safety verification, surverillance observations, mgt meeting & LER followup CANTER, H L . 0'IRIEN, J . YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/09/22 Spp 15619 038 24X Fiche 50-312,82/09/23,8210060330
- 8210190605 Forwards IE Insp Rept 50-312/82-33 on 820907-10 No noncompliance moted BOOK.H O Division of Radiological Bafety & Safeguards Program 82/09/30 MATTIMOE.J J Sacramento Municipal Utility District 2pp 15737 275 24X Fiche 50-312,82/09/30.8210190405
- ---B210190612 IE Insp Rept 50-312/82-33 on B20907-10 No noncompliance noted Major areas inspected organization & staffing, transportation activities.plant tour & health physics appraisal followup of computer based multichannel analyser NORTH.H B. WEMBLAWSKIFA A. BOOK.H E. Division of Radiological Safety & Safety 83-79 care appraisa B2/09/29 10pp 15739 277 24X Fiche 50-312,82/09/30.8210190605
- 8210070278 Ack receipt of BROB24 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-312/82-20 STERNSERO.D. M Division of Resident Reactor Project & Engineering Programs 82/10/04 HATTIMOE.J J Secrements Municipal Utility District 1p 15634 171 24X Fiche 50-312.82/10/04.8210070278
- -- 8210070287 Responds to NRC 820727 ltr re violations noted in IE Insp Rept 50-312/82-20 Corrective actions: 011son 8haker not maintained by Deneration Engineering therefore EII G-6 not applicable NCR-8-2671 dispositioned on 820327 MATTIMOE, J. Barramento Municipal Utility District 82/08/24 ENSELMEN, R. H. Region 5. Office of Director 2pp 15634 172 24X Fiche 50-312,82/10/04,8210070278
- 8210070290 Ack receipt of 820920 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-312/82-32 STERNBERO, D H Division of Resident, Reactor Project & Engineering Programs. 82/10/04 MATTIMED D H Sacramento Hunscips! Utility District 1p 15634 180. 24% Fichs 50-312.82/10/04.8210070290
- ---8210070294 Responds to NRC 820901 ltr re-violations noted in IE Insp. Rept 50-312/82-32 Corrective actions.ell GA Class I Tech Specs on overall contract spacs will include statement re-100FR21 regulations
  MATTIMOE, J. J. Sacramento Municipal Utility District 82/09/20.
  STERNBERO, D. M. Division of Resident. Reactor Project & Engineering Programs 2pp 18634 181 24x Fiche 50-312/82/10/04/8210070290
- 8210070319 Ack receipt of 820909 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-312/82-28 STERNBERG, D M. Division of Resident, Reactor Project & Engineering Programs 62/10/04, MATTIMUE, J. Bacramenta Municipal Utility District 1p. 15634-110. 24X Fiche 50-312,82/10/04,8210070319.

- --8210070331 Responds to NRC 820816 itr re-violations noted in it in Rept 50-312/82-28 Corrective actions QA manual revised to define commercial grade spare parts & receiving insperiored on all Class I & commercial grade spare parts MATTIMOE. J. J. Sacramento Municipal Utility District 82/09/u9 STERNBERO. D. M. Division of Resident. Reactor Project & Enginter Programs 2pp 15634 iii 24X Fiche 50-312.82/10/04.82100731
- 820B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Disladged 1-125 Implant Seeds " Svc list encl CDBs.t. I Division of Fuel Facilities, Materials & Gafeguards 82/10/06 Consolidated Edison Co of New York 46pp 15741 2-24/
- 820B19023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hall:Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- 8210190228 Forwards "Systematic Assessment of Licensee Performance.5 Rancho Beco." for Jul 1981-Sept 1982 Performance analyses for listed functional areas requested by 821112 STERNBERG.D M Division of Resident. Reactor Project & Engineering Programs 82/10/14 YOUNG.T. CANTER.H. D'BRIEN.J Region 5 Office of Director 2pp 15742 201 24X Fiche 50-312.82/10/14.8210190228
- --8210170231 "Systematic Assessment of Licensee Performance, SHJD Pr Seco." for Jul 1981-Sept 1982 \* Region 5. Office of Director 82/10/31 24pp 15742 203 Fiche 50-312, 82/10/14-8210170228
- R Periodic operating reports & related correspondence
- 8210190278 Forwards menthly operating rept for Sept 1902 RODRIGUEZ,R J Sacramento Municipal Utility District B2/10/13 Director's Office, Office of Inspection and Enforcement | 15742 178 24X Fiche 50-012,82/10/13,8210190278
- --0210190285 Monthly operating rept for Sept 1902 CDLOMBB.R Sacramento Municipal Utility District 82/10/08 £ 15742 179 24X Fiche 50-312.82/10/13.8210190278
- S Reportable occurrences, LERs & related correspondence
- 6210120114 Advises of immediate need for imposing specific requirements re operational restrictions for Class IE 120-volt ac vital instrument buses in operating plants HICHELSON.C Director's Office 80/07/15 DENTON.H R Office 8 Nuclear Reactor Regulation, Director 1p 15689 165 24x Fiche 50-000, 80/07/15,8210120114
- B012290118 Discusses conclusions of engineering evaluation of stars generator overfill transients at C-E & Westinghouse plants LANYING.W D. Director's Office B0/10/29, MICHELSON-C Directs Office. 3pp 13672 262 24X Fiche 50-000, B0/10/29, B012299119
- 82:0070412 Discusses problems caused by entry of desiccant into instrument & control air lines Util should examine sys & determine source & extent of contamination MICHELSON, C Director's Diffice B1/09/15 DENTON, H R Office Nuclear Reactor Regulation, Director STELLO, V Director's Office of Inspection and Enforcement Spp 19637 301 24X Fiche. 50-312, 81/09/15, 8210070412.
- 8210010008 Responds to FOIA request for 19 categories of documents:
  nuclear reactor events & safety problems Forwards documents
  listed in App A
  FELION.J M Division of Rules and Records 82/06/28 UMELL, R &
  Critical Mass Energy Project 15pp 15727 005 24%
  Fiche 50-000, 82/06/28, 8210010008
- --8109280036 Immediate action memo re desiccant contemination of all lines. Recommends issuance of bulletin requiring all licenses experienced w/air sys contamination to furnish info MICHELSON, C Director's Office 81/09/15 DENTON, R 0/Hcc Nuclear Reactor Regulation, Director 2pp 15730 241 248 Fiche 80-312, 82/06/28, 8210010008
- --8201300388 Discusses loss of HPI lube oil cooling at facilité failure of monthly operability test of HPI to detect clogging of qualified lube oil coolers Test deficients API be more critical than event Issue to be addressed by EF PELLET. J. Director's Office. 82/01/13, MICHELBON.C Director Office 3pp. 15732.254, 24X Fiche 50-000.82/06/28.821001000

- 8210250386 Forwards LER 82-026/04T-0 Detailed event analysis submitted MATTIMDE. J Secremento Municipal Utility District 82/10/15 ENGELMEN. R H Region 5. Office of Director 1p 15790 090 24X Fiche 50-312. 82/10/15.8210250386
- --B210250390 LER 82-026/04T-0 on 821006, review of plant effluent records disclosed pH reading of 6 2 for less than 15 minutes on 820918 Caused by leaks at two elbows in acid line running from storage tank to turbine bldg Leaks repaired COLOMBD.R U Sacramento Municipal Utility District 82/10/14 Region 5, Office of Director 1p 15790 091 24X Fiche 50-312,82/10/15,8210250386
- 8210250138 PNO-V-82-042 on B21014.RCS leakage of 1 15 gpm into reactor coolant drain sys through RCS loop drain valves discovered Leakage stands at 0 49 gpm Media interest expected VGU.0.T. CANTER.H Region 5. Office of Director 82/10/18 1p 15787 119 24X Fiche 50-312.82/10/18.8210250138
- DODAET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8210010175 Forwards IE Safeguards Insp Repts 50-313/82-25 & 50-318/82-22 on 820818-20 No noncompliance noted SEIDLE.W C Division of Resident, Reactor Project & Engineering Programs 82/09/16 CAVANAUGH.W Arkansas Power & Light Co 2pp 15567 282 24X Fichs 50-313,82/09/16,8210010175
- 8210190497 Forwards IE Insp. Repts 50-313/82-11 & 50-368/82-09 on 820318-20 No noncompliance noted EFIDLE:N C Division of Resident, Reactor Project & Engineering Programs 82/09/28 CAVANAVBH.W Arkansas Power & Light Co 2pp
- --8210190516 IE Insp Repts 50-313/82-11 & 50-368/82-09 on 820518-20 No noncompliance noted Major areas inspected licensee performance & capabilities during full-scale exercise of whereency plans & procedures
  ROMRER D M . HUNNICUIT.D M Division of Resident, Reactor Project & Engineering Programs 82/09/24 17pp 15735-346 24X Fiche 50-313/82/09/28/8210190497
- 6210070395 Updates 811021 response to Generic Ltr 81-04, "Emergency Procedure & Training for Station Blackout Events " Seal return isolation is possible during blackout & is provided for in procedures

  MARSHALL JR Arkansas Power & Light Co 82/10/04 EISENHUT, D 0
  Division of Licensing 2pp 15663 341 24X Fiche 50-313,82/10/04, 82/10070395
- 821C150073 Forwards add! info ry safe shutdown capability, in response to MRC 820903 request MARSHALL.JR Arkansas Power & Light Co 82/10/05 CLARK,R.A Operating Reactors Branch 3 STOLZ,JF Operating Reactors Branch 4 72pp 15496 349 24% Fiche 50-313,82/10/05,8210150073
- 8210280108 Releases public version of amend to emergency plan FELTON, J M Division of Rules and Records 82/10/12 Document Management Branch 1p 15862 236 24% Fiche 50-313,82/10/12, 8210280108
- --8210280112 Forwards public version of Amend 6 to amergency plan MARSHALL, J.R. Arkansas Power & Light Co. 82/10/04 COLLINS, J. Region 4. Office of Director DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director 1p. 15862-237 24X Fiche 50-313,82/10/12,8210280108
- ---8210280114 Public version of Amend 6 to emergency plan # Arkansas Power & Light Co 82/09/20 3pp 15862,238 24X Fiche 50-313,82/10/12.8210280108
- #210220377 Categorizes open items identified in IE Emergency
  Preparedness Repts 50-313/82-11 & 50-368/82-07 by need for
  immediate consideration & type of response acceptable
  Notification of expected response date due within 10 days
  SEIDLE, N C Division of Resident, Reactor Project & Engineering
  Programs B2/10/19 CAVANAUGH, W. Arkansas Power & Light Co 4p
  15779 175 24X Fiche, 50-319, 82/10/19, 8210220377

- 8210260178 Ack receipt of 820727 ltr requesting addl time to respond to violations noted in Emergency Preparedness Appraisal Repts 50-316/82-22 & 50-366/82-21 Response to App C due by 830501.

  SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/10/19 CAVANAUGH. W Arkansas Power & Light Co Ip 15797 037. 24X Fiche 50-313,82/10/19.8210260178
- ---B210260180 Responds to NRC B20625 itr re App C to IE Emergency Preparedness Appraisal Repts 50-313/82-22 & 50-368/82-21 Deficiencies resolved in emergency plan amends & implementing procedure revisions CAVANAUGH.W Artansas Power & Light Co B2/09/29 COLLING.J T Region 4, Office of Director 4pp 15799,038 24X Fiche 50-313,82/10/19.8210260178
- P Operating license stage documents & correspondence
- 8210010008 Responds to FOIA request for 17 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82706/28.8210010008
- --8106100203 Discusses Evaluation of HPSI pump operability w/o svc water Operability of HPSI pumps w/o svc water not adequately justified based on info submitted by licensee IMBRO.E Director's Office 81/05/22 Director's Office 4pp 15729 185 24X Fiche 50-000.82/06/28.8210010008
- 8210190008 Responds to 820831 submittal re Tech Spec revision for snubber surveillance License amend application should be submitted to incorporate applicable portion of 801120 model Tech Specs within 60 days CLARK, R A Operating Reactors Brench 3 82/09/21 CAVANAUGH, WArkensas Power & Light Co 2pp 15760.301 24X Fiche 50-313,82/09/21,8210190008
- 8210290140 Forwards Amend 69 to License DPR-51, safety evaluation & notice of issuance & availability Amend revises Tech Bracs to require chloring detection & protection capability for control room VISSING 0 B Operating Reactors Branch 4 82/09/21 CAVANAUCH, W Arkansas Power & Light Co 2pp 15876 209 24X Fiche 50-313, 82/09/21.8210290140
- --B210290143 Amend 69 to License DPR-51, amending Tech Specs to require chlorine detection & protection capability for control room STOLZ, J F Operating Reactors Branch 4 B2/09/21 Spp. 15876:211 24X Fiche 50-313, 82/09/21,8210290140
- --8210270146 Safety evaluation supporting Amend 69 to License DFR-51 \* Office of Nuclear Reactor Regulation, Director 82/09/21 2pp 19876 217 24X Fiche 50-313,82/09/21,8210290140
- --B21029014B Notice of issuance & availability of Amend 69 to License ppR-51.
  STOLZ.J F Operating Reactors Branch 4 82/09/21 2pp 15876-221 24X Fiche 50-313, 82/09/21, 8210290140.
- 8210040107 Application for amend to License DPR-51, changing 820317 Tech Spec change request to allow higher steam line break instrumentation & control sys setpoint.
  CAVAMAUOH, W. Arkanses Power & Light Co. 82/09/29 STQLZ, J. F. Operating Reactors Branch 4. 2pp. 15581 017. 24X Fiche. 30-313, 82/09/29, 8210040109
- ---8210040111 Proposed revised Tech Spsc 3.4 2 re steam line break instrumentation & control sys 4 Arkansas Power & Light Co 82/09/29 Spp 15581:019. 24X Fiche: 50-313.82/09/29.8210040109.
- 82:0150002 Forwards response to 820120 & 0301 requests for addl info re RCB high point vents Credible missiles generated by failure of RCB vent valves not postulated based on valve design. Leak detection provided for by monitoring pressure.

  MARBHALL, J R Arkansas Power & Light Co 82/10/06 BTOLZ, J F. Operating Reactors Branch 4 CLARK, R.A. Operating Reactors Branch 3 4pp. 15696 309 24X Ficher 50-313,82/10/06,8210150002.
- 82:01:50494 Submits info re status of waste gas sys & schedule for installation of redundant hydrogen/oxygen analyzers.
  Conceptual diagram of proposed upgraded waste gas sys redundant analyzer panel encl.
  MARSHALL.J R. Arkansas Power & Light Co 82/10/12 8TOLZ,J F.
  Operating Reactors Branch 4 CLARK,R.A Operating Reactors Branch 3 4pp. 15714,184. 24X Fizhe 50-313,82/10/12,8210150494.

- 8210220114 Formalizes proposals made at 820729 meeting U/BLW owners group re NUREO-0737. Item II K 3 30. "Revised Small Break LOCA Methods to Show Compliance w/10CFR50. App K "MARSHALL.J R Arkansas Power & Light Co 82/10/13 DENTON.H R Office of Nuclear Reactor Regulation. Director 15pp. 15778 149. 24X Fiche 50-313.82/10/13.8210220114
- 8210250206 Discusses operability of Dresser Hodel 31739A pressurizer safety in util & vendor documentation Ring settings should not cause valve chatter & mechnical damage Analytical models being developed for plant-specific data MARSHALL.JR Arkansas Power & Light Co 82/10/19 STOLZ.JF Operating Reactors Branch 4 2pp 15789 306 24% Fiche 50-313, 82/10/19, 8210250206
- 8210260192 Forwards add1 response to 820618 open items re emergency feedwater sys.per 820722 Itr Functional test required every 18 months causes addition of heavily oxygenated water into oncerthrough steam generator.

  MARSHALL.J R Arkansas Power & Light Co 82/10/20 STGLZ.J F Derating Reactors Branch 4 App 15799 021 24X Fiche: 50-313, 82/10/20, 8210260192
- O Inspection reports, IE Bulletins & correspondence
- 6210080015 Addl response to FOIA request for 19 categories of info re nuclear reactor evants & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FGIA Exemption 5) FELTON, J H Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000, 82/07/12, 8210080015
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request Bi-3i3 Forwards documents listed in App 8 FELTON, J M Division of Rules and Records. 82/08/10 LONO, D J Hinthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000,82/08/10,8210070007.
- 8210010175 Forwards IE Safeguards Insp Repts 50-313/82-25 & 50-368/82-22 on 820818-20 No noncompliance noted SEIDLE, W C Division of Resident: Reactor Project & Engineering Programs 82/09/16 CAVANAUGH, W Arkenses Power & Light Co 2pp 13567 282 24% Fiche: 50-313,82/09/16,8210010175
- --821001017B IE Safeguards Insp Repts 90-313/62-25 & 50-368/62-22 on 820818-20 No noncompliance noted Hajor areas inspected; security organization mgt.physical berriers & access control of packages Details withheld (ref 10CFR2 770).
  EVANS.C A : KELLY, J. A.F. Division of Vendor & Technical Programs 82/09/14. 1p 15567.284. 24X Fiche:50-313.82/09/16.8210010175.
- 8210190497 Forwards IE Insp Rapts 50-313/82-11 & 50-368/82-09 on 820518-20. No noncompliance noted SEIDLE:W C Division of Resident: Reactor Project & Engineering Programs. 82/09/28 CAVANAUGH.W. Artenses Power & Light Co. 2pj 19735:344 24% Fichs 30-313,82/09/28,8210190497.
- --B210190516 IE Insp Repts 50-313/82-11 & 50-368/82-09 on B20518-20 No nancompilance noted Major areas inspected; licensee performance & capebilities during full-scale exercise of emergency plans & procedures.

  ROHRER, D M., HURNIGUTT, D M. Division of Resident, Reactor Project & Engineering Programs. B2/09/24. 17pp 15735-346 24X Fishe 50-313, B2/09/28, B210190497.
- 8210120246 Ack receipt of 820211 itr Informing NRC of steps taten to correct violations noted in IE Insp Repte 50-313/81-30 & 50-346/81-29.

  BEIDLE: W C Division of Resident, Reactor Project & Engineering Programs, 82/10/01 CAVANAUGH: W Arkansas Power & Light Co 1p. 15452-110 24% Fiche 50-313.82/10/01,8210120246.

- --8210120252 Responds to NRC 820104 ltr re violations noted in [E [\*s] Repts 50-313/81-30 & 50-388/81-29 Corrective actions forest training sessions will be conducted w/appropriate station personnel to stress importance of individual responsibility MARSHALL, J R Ariansas Power & Light Co 82/02/11 MADSEN.Q L Division of Resident, Reactor Project & Engineering Programs Cy, 15652 lil 24X Fiche 50-313,82/10/01.8210120246
- 8210220270 Forwards IE Insp Repts 50-313/82-12 & 50-348/82-25 on 820524-27 No moncompliance noted SEIDLE: W C Division of Resident, Reactor Project & Engineering Programs 82/10/05 GAVANAUGH. W Arkansas Power & Light Co 2,, 15775 001 24X Fiche 50-313/82/10/05/8210220270
- --B21022028i lE Insp Repts 50-313/B2-12 & 50-368/B2-25 on E20324-27 monocompliance noted Major areas inspected radiochemistry program.including organization, staffing, training program, sample collection & sample treatment & analysis NICHOLAS, J B . MURRAY.B Region 4. Office of Director B2/09/19 25pp 15775 003 24X Fiche 50-313,82/10/05,8210220270
- B208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodes [ ]: Implant Seeds " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 66pp [5761 2:) 24X Fiche 50-000,82/10/06,8208190233
- 6210;2024; Ack receipt of 620715 itr informing NRC of steps taken is correct violations noted in IE insp Repts 50-313/80-20 & 50-346/80-20 SEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs 82/10/06 CAVANAUGH, W. Arkansas Power & Light Co. I; 15652 113 24X Fishe 50-313.82/10/06/821012024;
- --8210120247 Provides status update on gaseous radidactive wasts signeds, in response to violations noted in IE Insp Repts 50-319/80-20 & 50-368/80-20 High airborne activity incidents in auxiliary bldgs significantly reduced MARSHALL-J R Artenses Power & Light Co 92/07/15 GCID.E.W.C Division of Resident. Reactor Project & Engineering Programs Jp 13652 114 24X Fiche 50-313,82/10/06,8210120241
- 820B190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Mail:Large-Diameter:Stainless Steel, Recirculation Bys Piping at BUR Plants "Svc list encl DEYOUNG:R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp. 15810 125. 24X Fiche 50-000,82/10/14,820B190238
- 0210220377 Categorizes open items identified in IE Emergency
  Proparedness Repts 50-313/82-11 & 50-368/82-07 by need for
  immediate consideration & type of response acceptable
  Notification of expected response date due within 10 days
  EEIDLE: H C. Division of Resident Reactor Project & Engineering
  Programs 82/10/17 CAVANAUOH, Warkensas Fower & Light Ce 6,
  15779 175 24X Fiche 50-313,82/10/19.8210220377
- 8210240178 Ack receipt of 820929 ltr requesting addl time to serptiviolations noted in Emergency Preparedness Appraisal Repts 50-313/82-22 & 50-368/82-21 Response to App C due by 830501 SEIDLE, R C. Division of Resident, Reactor Project & Engineering Programs 82/10/19 CAVANAUOH, W Arkansas Power & Light to 1: 13799:037 24% Fiche 50-313,82/10/19,8210240178
- --9210260180 Responds to NRC 820625 ltr re App C to IE Emerginty
  Preparedness Appraisal Repts 30-313/82-22 & 50-368/82-21
  Deficiencies resolved in emergency plan amends &
  implamenting procedure revisions
  CAVANAUGH.W. Arksness Power & Light Co 82/07/29 COLLINS J.
  Region 4. Office of Director 4pp 15799 038 24X
  Fiche: 50-313,82/10/19,8210260178
- S Reportable occurrences. LERs & related correspondence
- 8210120380 Advises that operator action necessary to protect \$4936 from excessive feedwater transferts. 884 plants do not employ high steam generator level turbine or reactor trips to protect against transients

  CREBNELL, J. S. Director's Office 80/09/12 MICHELBON. C
  Director's Office 34pp 15689:286 24X Fiche 50-302.80/09/12
  8210120380.
- 8012290118 Discusses conclusions of engineering evaluation of these generator overfill transients at C-E & Westinghouse plants LANNINO, W D. Director's Office. 80/10/29 MICHESON C Stratu Office. 3pp. 15692.262 24X Fiche 50-000, 80/10/29, 80122018
- 8210070104 Speech entitled "Pressure Boundary Degradation Dui to Fu Seal Failure at AR Nuclear One," presented at ninth meeting of Committee on Safety of Nuclear Installations on 811103-04 in Peris France. LANNINO, W. D. BROWN.E J. Director's Office 81/11/03 99 15449:174. 24X Fiche 50-313.81/11/03.8210070104

## DOCKETED ITEMS

- 821COLCOOR Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A
  FELTON, J M Div FELTON, J M Division of Rules and Records 82/06/28 Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28,8210010008 82/04/29 UDELL.R A
- --- B111040084 "Pressure Boundary Degradation Due to Pump Seal Failure
- --8203100549 Recommends explicit verification that seismic qualification COSTODARY Recommends explicit verification that seismic qualific for all protective devices used in control & protection circuitry for diesel generator units performed w/devices in energized/de-energized & tripped/nontripped states MICHELSON, C Director's Defice B 82/02/24 VOLLMER, R H Divi of Engineering MATTSON, R J Division of Systems Integration (post B11005) 2pp 15732 320 24X Fiche 50-000, B2/04/2B, E38/04/0008 VOLLMER R H Division 521001000B
- 8210120145 "Abnormal Transient Operating Quidelines as Applied to Apr 1931 Overfill Event at AR Nuclear One Unit 1" FELLETI,J L Reactor Operations Analysis Branch 82/08/31 19pp 24x Fiche 50-313,82/08/31.8210120145
- 8210130513 Forwards LER 82-025/03L-0 MARSHALL.J R Arkansas Power & Light Co 82/09/26 SEIDLE,W C Division of Resident, Reactor Project & Engineering Programs 1, 13682 238 24x Fiche 50-313,82/09/26.8210130513
- --6210130522 LER 82-025/03L-0 on 820828, electrical jumpers discovered across trip contacts or shutdown bupass high pressure trip bistables for A & D reactor protection sys channels Caused by personnel error Jumpers removed ROGERS, P Arkansas Power & Light Co 82/09/26 Region 4, Office of Director 2pp 15682 239 24X Fiche 50-313, 82/09/26, 8210120513 8210130513
- 8210130212 Forwards LER 82-027/03L-0 MARSHALL, JR Arkansas Power & Light Co 82/09/30 BEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 1p 15675 237 24x Fiche 50-313,82/09/30,8210130212
- --8210130214 LER 82-027/03L-0 on 820714.RCS leak rate calculated at 3 4 gpm. in excess of Tech Spec Caused by low breakway torque valves, deteriorated gasket & eroded manuay cover All defective parts repaired or replaced ROGERS.P Arkansas Power & Light Co 82/07/30 Region 4, Office of Director 2pp 15675 238 24X Fiche 50-313,82/07/30, 8210120212
- 9210130382 Forwards LER 82-026/03L-0 MARSHALL, JR Arkansas Power & Light Co 82/07/30 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs ip 15680 336 24% Fiche 50-313,82/07/30,8210130382
- --8210130388 LER 82-026/03L-0 on 820901, installed hose real (HR-49) found not visually inspected per Tech Specs Caused by lack of communication, leading to omission of HR-49 from insp ROCERS, P Arkansas Power & Light Co 82/09/30, Region 4, Uffice of Director 2pp. 15680 337 24X Fiche 50-313.82/09/30, 8210130382
- 8210190517 Forwards LER 82-028/03L-0 MARSHALL, J R Arkansas Power & Light Co 82/10/07 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 15751 244 24X Fiche 50-313,82/10/07,8210190517
- ---8210190526 LER 82-028/03L-0 on 820909.dissel driven fire pump (P-48) ELOLIVOZED LER ME-UZEM/USL-O on 820909, diesel driven fire pump (P-68 failed to start when using B battery bank during surveillance Cause by normal end of syc life Batteries charged & later replaced ROGERS, P Antansas Power & Light Co 82/10/07 Region 4, Office of Director 2pp 15751 245 24X Fiche 50-313,82/10/07, 8210190517
- DOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1 F. Security, medical, emergency & fire protection plans
- B210040387 Forwards IE Insp Repts 50-315/82-08 & 50-314/82-08 on 820412-16.0514 & 0610 Deficiencies referred to Ofc of Tryestigation for review & investigation with or with the programs. Horselfully, C & Division of Engineering & Technical Programs. 82/09/22. DDLAN.J E Indiana & Michigan Electric Co 2pp 15615 350 24X Fiche 50-315,82/09/22,8210060387

- --8210050393 IE Insp Repts 50-315/82-08 & 50-316/82-08 on 820412-16.0514 8 OdiO Deficiencies noted inadequate fire protection of safe shutdown capability, inaccurate statements, inadequate snucoum capabilisty, macturate statements, inadequate procedure for alternate sale shutdown & inadequate lighting GROBE, J A , STONE, J C , HAUGHNEY, C J Division of Engineering & Technical Programs 62/09/17 27pp 15615 352 24X Fiche, 50-315, 62/09/22, 8210060387
- 8210080129 Releases public version of revised emergency plan procedures
  FELTON, J M Division of Rules and Records 82/09/22 Docum
  Management Branch 1p 15863 293 24X Fiche 50-315,82/09/22, Document
- ---B210080132 Forwards public version of Revision 1 to Emergency Plan Procedures PMP 2081 EPP 012, "Offsite Radiological Monitoring" & Revision 1 to PMP 2081 EPP 026, "Use of Stable Iodine for Thyroid Blocking During Radiation Emergency " Indiana & Michigan Electric Go 82/07/13 NRC No Detailed Affiliation Given 1p 15663 274 24X Fiche 50-315.82/07/22, 8210080129
- --8210080136 Public version of Revision 1 to Emergency Plan Procedures PMP 2081 EPP 012, "Offsite Radiological Monitoring" & Revision 1 to PMP 2081 EPP 026, "Use of Stable Iodine for Thyroid Blocking During Radiation Emergency " Index encl " Indiana & Hichigan Electric Co 82/09/13 20pp 15663-295 24% Fiche 50-315,82/09/22,8210080129
- 8210010362 Forwards revision to modified amended security plan re key & lock control program Revision withheld (ref 10CFR73 21)
  HUNTER,R S Indiana & Hichigan Electric Co 82/09/27 DENTON,H R
  Office of Nuclear Reactor Regulation, Director 2pp 15574,158
  24X Fiche 50-315,82/09/27.8210010362
- 8210150894 Releases public version of revision to plant manager procedure/emergency plan procedure FELTON, J M Division of Rules and Records 82/09/30 Docum Management Branch ip 15716;350 24X Fiche 50-315,82/09/30, Document R210150594
- --8210150604 Forwards public version of Revision 3 to Plant Manager Procedure/Emergency Plan Procedure App A. "Telephone Numbers for Key Plant Personnel" 4 Indiana & Hichigan Electric Co 82/07/23 NRC - No Detailed Affiliation Given Ip 15716 351, 24X Fiche 50-315,82/09/30,
- --8210150614 Public version of Revision 5 to Plant Manager Procedure/ Emergency Plan Procedure App A, "Telephone Numbers of Key Plant Personnel" \* Indiana & Michigan Electric Go 82/09/23 21pp 18716.352 24X Fiche 50-315, 82/09/30, 8210150594
- 8210190036 Releases public version of procedure temporary sheet to emergency plan procedure FELTON.J.M Division of Rules and Records 82/10/01. Documen Management Branch. 1p 15761 034 24X Fiche 50-315,82/10/01. Document 821019003A
- --8210190040 Public version of procedure temporary sheet to
  Emergency Plan Procedure PMP 2081 EPP 020. "Activation &
  Operation of Technical Support Ctr " Revised index encl
  VINCE, S. SIMMS, R. CAMPBELL, D. Indiana & Michigan Electric Co
  82/09/17 2pp 15761 035. 24X Fiche 50-315,82/10/01,8210190036
- 8210190652 Forwards FEMA 820909 1tr.final avaluations of offsite smergency preparedness exercises conducted on 801009 & 820330 for State of MI & Berrien County & State of MI response. Recommendations for offsite preparedness requested HIND.J A. Division of Emergency Preparedness & Operational Support 82/10/12. HERINO.R F American Electric Power Service Corp HERINO.R.F Indiana & Michigan Electric Co. 2pp 15737.149 24X Fiche 50-315, 82/10/12.8210190652
- 8210280378 Releases public version of revision to emergency plan procedure. FELTON, J. M. Division of Rules and Records 82/10/12 Docum Management Branch 1p 15859 238 24X Fiche, 50-315, 82/10/12,
- --B2102B03B0 Forwards public version of Revision 3 to emergency plan procedure App 8 re hosp assistance plan \* Indiana & Michigan Electric Co 82/10/01. NRC No Detailed Affiliation Given ip 15859 239. 24X Fithe. 50-315, 82/10/12, 8210280378
- --8210280383 Public version of Revision 3 to emergency plan procedure App B re hosp sesistance plan.

  # Indiana & Michigan Electric Co. 82/10/Oi. 17pp. 15859:241
  24X Fiche: 50-315, 82/10/12, 8210280378.

- 6210280399 Releases public version of revised emergency plan procedures. FELTON.J M Division of Rules and Records. 82/10/12 Document Management Branch 1p 15839 261 24X Fiche 50-315,82/10/12. 8210280399.
- ~-8210280408 Forwards public version of revised emergency plan procedures, including Procedures PMP 2081 EPP 004 re protective action guides & protective actions & PHP 2081 EPP 009 re health physics procedures thousand a Michigan Electric Co 82/09/27. NRC ~ No Detailed Affiliation Given in 18859, 262 24X Fiche-50-315, 82/10/12, 6210280399
- --8210280413 Public version of revised emergency plan procedures, including Procedure PMP 2081 EPP 004 Te protective action guides & protective actions & PMP 2081 EPP 009 Te health physics procedures Procedures index end a Indiana & Michigan Electric Co β2/09/29 57pp 15839:263 24X Fiche.50-315.82/10/12.8210280379

#### [ Financial information

- \$210070279 Forwards Annual Financial Rapt for 1981 & projected cash flow for 1982 HERING, R.F. Indiana & Michigan Electric Co. 82/10/04 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 15634, 185 24X Fiche 50-315,82/10/04,8210070279.
- --8210070286 "ID & Ml Electric Co.Annual Financial Rept 1981 "

  \* American Electric Power Service Corp \* Indiana & Michigan
  Electric Co 82/10/04 32pp 15634 187 24X
  Fiche: 50-315, 82/10/04, 8210070279
- J Insurance & indemnity information
- 8210040313 Forwards Endorsement 54 to NELIA Policy NF-204 & Endorsement
  44 to MAELU Policy MF-79
  BUCKLES.J Marsh & KcLennan, Inc., M & M Nuclear Consultants, Inc
  Div 82/09/27 SALTMAN,J Assistant Director for State & Licensee
  Relations 3pp, 15586 168 248 Fiche 50-315.82/09/27,8210040313
- P Operating license stage documents & correspondence
- 821005053B Forwards Amends 59 % 42 to Licenses DPR-58 % DPR-74, respectively, tafety evaluation & notice of issuance & availability Amends revies Tech Brecs to reflect (installation or replacement of valves to improve operation CILIMBERG, R & Operating Reactors Branch 1. B2/09/09. DOLAN, J Indiana & Michigan Electric Co 2pp 15637:172 24X Fiche 50-315, 82/09/09, 821005053B
- --B210050541 Amends 59 & 42 to Licenses DPR-58 & DPR-74, respectively, revising Tech Specs to reflect installation or replacement of valves to promote improved operation VARGAS A. Operating Reactors Branch 1 82/09/09 24pp 15637 174 24X Fiche 50-315,82/09/09.8210050538
- --8210050544 Bafety evaluation supporting Amends 59 t 42 to Licenses DPN-55 t DPR-74 respectively Clifice of Nuclear Reactor Regulation, Director 82/09/09, 29p 18637,200 24X Fishs: 50-315,82/09/09,8210050538
- --8210050546 Notice of issuance & availability of Amends 59 & 42 to Licenses DPR-58 & DFR-74, respectively. GROTENHUIS, M. Operating Reactors Branch i 62/09/09 200. 13637-202. 24X Fiths 50-315, 82/09/09,8210030538.
- 8210040415 Forwards Amends 61 & 44 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & to reflect revised PDC-11 and codures

- ~-8210040419 Notice of issuance & sverlability of Amends 61 & 44 t. Licenses DPR-58 & DPR-74, respectively VAROA. S A Operating Reactors Branch 1 82/09/15 2pp 15597, 132 24X Fiche 50-315, 82/09/15, 8210040415
- 8210040428 Forwards request for addl info re hydrogen control jesuic for ice condenser plants Response requested by 821015 VAROA B A Operating Reactors Branch | 82/09/16 DOLAN.J Indiana & Michigan Electric Co | 10pp | 13597 252 24X Fiche 50-315, 82/09/16,8210040428
- 8210120557 Forwards Amend 62 to License DPR-58 & notice of issuance & availability Amend extends until 821009.permissibly operation in Kodes 2 & 3 w/one safety injection pump inaperable VAROA: 8 A Operating Reactors Branch 1 82/09/17 DOLAN J Indiane & Michigan Electric Co 3pp 15684 218 24X Fiche 50-315,82/09/17,8210120557
- --8210120560 Amend 62 to License DPR-58, extending until 823009 permissible operation in Modes 2 & 3 w/one safety injection pump inoperable VARGA. S A Operating Reactors Branch 1 82/09/17 App 15584 221 24X Fiche 50-315, 82/09/17, 8210120557
- --9210120565 Notice of issuance & availability of Amend 62 to Lice of DPR-58
  VAROA, B A Operating Reactors Branch 1 82/09/17 2pp
  15684 225 24X Fiche 50-315,82/09/17,8210120557
- 8210040212 Discusses inconsistency in ECCS analysis Yech Spet val.e.?

  70 F used as temp for safety injection flow water determined nonconservative Refueling water storage tank temp raised to BO F per Tech Spec requirement SHITH. W O Indiana & Michigan Electric Co 82/09/24 KEPPLER.J; Region 3. Office of Director ip 15583 123 24% Fiche. 50-315, 82/09/24, 8210040212
- 8210050138 Forwards documents as Phase I b of response to Siction 21 of Encl 3 to DO Eisenhut 801222 ltr re control of heavy loads Westinghouse analysis of lifting arrangement for reactor vessel head & Upper Internals expected by 830315 HUNTER: R 8 Indiana & Michigan Electric Co 82/09/29 DEHTON #8 dffire of Nuclear Resolve Tropic Dentity #8 1 Philosophy #8 1 Philo
- 8210050159 Application for amend to Licenses DPR-88 & DPR-74.projii; Tach Spec changes for placement of new post-accident containment hydrogen monitoring sys to satisfy NUREG-0797. Item 18 F 1.6 & to remove existing equipment from syc HUNTER: R S Indiana & Michigan Electric Co 92/09/29 DENTON AI Office of Nuclear Resolvent Regulation. Director 2pp 15503 149 24X Fichs 20-315,82/09/29,8210050159
- --0210050160 Proposed Tech Spec 3/4.6 4 re combustible gas control # Indiana & Michigan Electric Co 82/09/29 3pp 15603 151 24X Fiche 50-315.82/09/29.8210050159
- 8210050349 Forwards add1 info re hydrogen mitigation & control if facilities Util continues to work w/TVA & Duke Power Co toward completion of executive summary rept on ice condenser hydrogen R&D program HWNTER: R S Indiana & Michigan Electric Co 82/09/30 ENTOW HI Office of Nuclear Reactor Regulation, Director 126pp 155101% 24X Fiche 50-315,82/09/30,8210050349
- 8210080194 Comments on regulatory performance improvement program Comments can be dealt w/by revising program description to take full credit for mot review efforts Util views on comments will be discussed at meeting scheduled for 82:1014 KEPPLER. J. O. Region 3. Office of Director 62/10/01 20LAN. J. E. American Electric Power Service Corp DOLAN. J. E. Indiana & Firl & Electric Go. 2pp 15640 188 24X Fiche 50-315.82/10/01.6210963
- 8210060253 Discusses 820707 mgt mesting & forwards Systematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16 KEPPLER, J.O. Region 3. Office of Director 82/10/04 DCAN.J.E American Electric Power Co. Inc. DDLAN.J.E. Indiana & Alcheja Power Co. 3pp. 13620,198, 24% Fichs 50-315,82/10/04,92108033
- --8210060254 Systematic Assessment of Licensee Performance fepts
  50-315/82-16 % 50-316/82-16 on 801001-820401 Major arest
  examined: util regulatory performance
  w Region 3. Office of Director, 82/06/30 7pp, 15620 201 24;
  Fiche: 50-315, 82/10/04, 8210060253.

- --8210060255 Responds to NRC 820625 Systematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16 Twelve previously trained operators hired & computerized radiation exposure maint sys & security access control sys installed HUNTER, R B Indiana & Michigan Electric Co 82/07/27 KEPPLER, J G Region 3, Office of Director 35pp 15620 208 24x Fishe 50-315,82/10/04,8210060253
- 9210150491 Confirms 820922 telean re masonry walls Addl info required within 45 days to complete review VARGA: S A Operating Reactors Branch 1 82/10/04 DOLAN, J Indiana & Michigan Electric Co 3pp 19717 275 24X Fiche 50-315, 82/10/04, 8210150491
- 8210250340 Forwards Amends 63 & 45 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & azailability Amend revises Tech Specs changing surveillance requirements for boron & safety injection sys CILIMEERG, R L. Operating Reactors Branch 1 82/10/04 DDLAN, J Indiana & Michigan Electric Co 2pp 15807 259 24X Fiche 50-315, 82/10/04, 8210250340
- --8210250393 Amends 43 & 45 to Licenses DPR-58 & DPR-74, respectively, changing Tech Specs re surveillance requirements for boron & safety injection sys & updating core flux VARGA. B A Operating Reactors Branch i 82/10/04 73pp 15807 261 24X Fiche 50-315,82/10/04,8210250340
- --8210250394 Safety evaluation supporting Amends 63 & 45 tp Licenses DPR-59 & DPR-74: respectively \* Office of Nuclear Reactor Regulation, Director 82/10/04 5pp 15807 334 24X Fiche 50-315,82/10/04,8210250340
- --8210250395 Notice of issuance & availability of Amends 63 & 45 to Licenses DPR-58 & DPR-74.respectively VARON.5 A Operating Reactors Branch i 82/10/04 2pp 15807 339 24X Fiche 50-315.82/10/04.8210250340
- B2:0150434 Forwards safety evaluation re main steam line break w/continued feedwater addition & contractor technical evaluation rept H/o technical evaluation rept WARGA-S A Operating Reactors Branch I B2/10/05 DOLAN, J Indiana & Michigan Electric Co 2pp 15716-090 24X Fiche 50-315.62/10/55,82/0150484
- --9210150437 Safety evaluation re main steam line break w/continued feedwater addition

   Operating Reactors Branch 1 82/10/05 7pp 15716 092 24X Fichs 50-315.82/10/05.8210150434
- 6210220476 Submits followup to 820907.17 & 24 ltrs re emergency relief requests from Tech Spec 3 5 2 Repairs of north safety injection pump completed within alloted relief time granted by Amend 62 Amend fee encl HUMTER.R S Indiana & Michigan Electric Co 82/10/15 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15779 001 24X Fiche 50-315,62/10/15,62/0220478
- 8210250228 Forwards proprietary responses to five of 16 questions per NRC 820730 request for add1 info re hydrogen control issues for ice condenser plants.particularly CLASIX computer program Responses withheld (ref 100FR2 790)
  HUNTER: R B Indiana & Michigan Electric Co 82/10/15 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp. 15789 339 24X Fiche 80-315.82/10/15,8210250228
- 8210220373 Advises that util will reload w/Mestinghouse 15x15 optimized furl assemblies during Cycle 8 scheduled for 830831 Meeting w/NRC requested on 82103 to clearly define licensing review schedule HUNTER.R 8 Indiana & Michigan Electric Co 82/10/18 DENTON,H R Office of Nuclear Reactor Regulation. Director 3pp 18777, 309 24X Fiche 50-315,82/10/18,8210220393
- BR10260081 Notification of B21103 meeting w/utils in Bethesda, MD to discuss use of Westinghouse optimized fuel assemblies in Cycle 8 operation H109IN16N:D. Operating Reactors Branch 1 82/10/21 VAR9A: 8 A Operating Reactors Branch 1 3pp 15814 321 24X Fiche 50-315.82/10/21.8210260081.
- G Inspection reports, IE Bulletins & correspondence
- B210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON.J. M Division of Rules and Records B2/08/10. LONG.D J Winthrop. Stimson. Putnam & Roberts: 9pp 15645:063 24X Fiche.50-600.82/08/10.8210070007

- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensess IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VAROA.S Operating Reactors Branch 1 Spp 15645 131 24X Fichs 50-000,82/08/10,8210070007
- 8210060387 Forwards IE Insp Repts 50-315/82-08 & 50-316/82-08 on 820412-16:0514 & 0610 Deficiancies referred to Ofc of Investigation for review & investigation for review & investigation NORELIUS.C E Division of Engineering & Technical Programs 82/07/22 DOLAN,JE Indian & Michigan Electric Co 2pp 15613 350 24% Fiche 50-315.82/09/22.8210060387
- --8210060393 IE Insp Repts 50-315/82-08 & 80-316/82-08 on 820412-16.0514 & 0610 Deficiencies noted inadequate fire protection of safe shutdown capebility, inaccurate statements, inadequate procedure for alternate safe shutdown & inadequate lighting OROBE, J A. STONE, J C. HAVOHNEY, C J Division of Engineering & Technical Programs 82/09/17 27pp 15615 352 24% Fichs 50-315.82/09/22, 8210060387
- 8210050274 Ack receipt of 820914 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/82-12 & 30-316/82-12 & 5TREETER, J F Division of Project & Resident Programs 82/09/24 DOLAM, J E American Electric Power Service Corp DOLAM, J E Indiana & Michigan Electric Ca 1p 18609 187 24% Fiche 50-315, 82/09/24, 8210050274
- --8210050276 Responds to NRC 820816 ltr re violations noted in IE Insp Rapts 50-315/82-12 & 50-316/82-12 Corrective actions plant manager will issue memo to plant depts by 820930 re procedures for installation of new design changes HERINO, R F Indiana & Michigan Electric Co 82/09/14 KEPPLER, J Q Region 3, Office of Director 3pp 15609 188 24x Fiche 50-315,82/09/24.8210050274
- 8210060253 Discusses 820707 mgt meating & forwards Systematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16 KEPPLER.J G Region 3. Office of Director 82/10/04 DOLAN.J E American Electric Power Co , Inc DDLAN.J E Indiana & Michigan Power Co 3pp 15620 198 24% Fichs 50-315,82/10/04,8210060253
- --8210060254 Bystematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16 on 801001-820401 Major areas examined util regulatory performance \* Region 3, Office of Director 82/06/30 7pp 15620 201 24x Fiche, 50-315, 82/10/04, 8210060253
- --9210060256 Responds to NRC 820625 Systematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16 Tuelve previously trained operators hired & computerized radiation expasure maint sys & security access control sys installed HUNTER, R S Indiana & Michigan Electric Co 82/07/27 KEPPLER.J O Region 3, Office of Director 35pp 15620 208 24X Fiche. 50-315,82/10/04.8210060253
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06.8208190233
- 820B19023B IE Bulletin 82-03, "Stress Corresion Cracking in Thick-Wall, Large-Diameter: Stainless Steel, Recirculation Bys Piping at BWR Plants "Svc list encl. DEYGUNO; R C Director's Office Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125, 24X Fichs 50-000, 82/10/14, 820B19023B
- 82:0150388 EN-81-047A on 82:014.order imposing civil monetary penalty in amount of \$52,000 issued to licenses re violations concerning fire protection program & containment integrity. One violation withdrawn & two modified CRAIO, J. AXELRAD, J. Director's Office, Office of Inspection and Enforcement 82/10/14 ip 15721 307 24% Fiche 50-315,82/10/14,82:0150388
- R Periodic operating reports & related correspondence
- 8210190676 Forwards Sr-87 & Sr-90 data not completed by contractor until after due date for submittal of semiannual radioactive effluent release rept for Jan-June 1982 HUNTER, R 8 Indiana & Michigan Electric Co: 82/10/01 KEPPLER, J 0 Region 3, Office of Director 2pp 15/38:197, 24X Fichs: 50-315, 82/10/01, 8210190676
- --8210170695 "Effluent & Waste Disposal Semiannual Rept-1982, Gaseous Effluents-Elsyated Release," Sr-89 & Sr-90 data omitted from original 820827 submittel # Indiana & Michigan Electric Co. 82/10/01. 10pp. 15738.199. 24X Fiche: 50-315,82/10/01.8210190676.

- S Reportable occurrences. LERs & related correspondence
- 8210080015 Addi response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON.J H Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9p 15645-027 24X Fiche 30-000.82/07/12.8210080015
- --B210080197 NRC operations ctr usage chart re svents at facilities \* NRC - No Detailed Affiliation Olven B2/07/12 ip 15668 221 24X Fiche 50-000, B2/07/12, B210080015
- 8210040073 Forwards LER 82-076/03L-0 SMITH.W O Indiana & Michigan Electric Co 82/09/22 KEPPLER.J O Region 3. Office of Director ip 15883 193 24X Fiche 30-315.82/09/22.8210040073
- 8210040199 Forwards LERs 82-077/01T-0 & B2-078/03L-0 SMITH.H.Q Indiena & Michigan Electric Co 82/09/24 KEPPLER.J Q Region 3. Office of Director ip 15583 131 24X Fiche 50-315.82/09/24.8210040199
- --8210040203 LER 82-078/03L-0 on 820825, unplanned gas release detected by vent stack gaseous monitor R-26 reading Caused by water overflowing from liquid waste holdup tanks into room vents & vent sys KRAUSE, D Indiana & Michigan Electric Co 82/09/24 Region 3, Office of Director 1p 15583 132 24X Fiche: 50-315,82/09/24, 8210040159.
- --9210040205 LER 82-077/01T-O on 820910 required surveillance testing following installation of design change on control room ventilation sys had not been performed Caused by unresolved status of design change sys issues

  BEILKAN, T P Indiana & Michigan Electric Co 82/09/24 Region 3. Office of Director 1p 15593 133. 24X Fichs 50-315,82/09/24.
- 8210040300 Forwards LER 82-079/01T-0 BMITH, W Q. Indiana & Michigan Electric Co B2/09/29 KEPPLER, J Q Region 3, Offica of Director. 1p 15619 298, 24X Ficha 30-315.82/09/29.8210060300
- --B210060307 LER B2-079/01T-0 on 820915, during low power physics testing program following end of Octle 6 refuting unit entered Mode 2 w/overpower & overtemp delta-T bistable in monconservative configuration Caused by unclear procedure FALMER.R.A. Indiana & Michigan Electric Co 82/09/29. Region 3. Office a Director 6pp. 15619 299 24% Fiche: 50-315, 82/09/29.8210060300
- 8210190749 Forwards LER 82-080/01T-0 SMITH.W 9 Indiana & Michigan Electric Co 82/10/07 KEPPLER.J. O Region 3. Office of Director Ip. 15737.092, 24X Fiche 50-315.82/10/07.8210190749
- --8210190757 LER 82-080/01T-0 on 820923, discovered analysis for safety injection flow water temp used value of 70 F Value of 80 F used in containment spray water temp analysis. Action taken to maintain restorage water temp above 80 F BELLMAN, T P Indiana & Michigan Electric Co 92/10/07 Region 3, Office of Director. 4pp. 15737 093 24X Fiche: 50-315, 82/10/07, 82/10/9749
- 82:0190572 Forwards LERs 82-08:/03L-0 & 82-082/03L-0 SMITH, W 9. Indiama & Michigan Electric Co. 82/10/08 KEPPLER, J. Q. Region 3. Office of Director 1p. 15736:099 24X Fiche: 80-315.82/10/08.8210190572.
- --B210190578 LER 82-081/03L-0 on 820908, during routine turbine bldg tour, operator discovered CD dissel room carbon dioxide (CO2) systemated w/no names on entry board & no personnel in room. Caused by personnel arror Proper use of CO2 sys discussed. PALMER.R.A. Indians & Michigan Electric Co. 82/10/08. Region 3. Office of Director 1p. 15736, 100. 24X Fiche 50-315, 82/10/09, 8210190572.

- --8210190588 LER 82-082/03L-O on 820908, low pressure carbon dissides, for AB diesel generator room discovered isolated w/no fire watch posted contrary to Tech Specs Responsible individual undetermined Personnel trained in fire door PIEHL: R H Indiane & Hichigan Electric Co 82/10/08 Report Office of Director ip 15736 101 24X Fichs 50-315,82/10/09 8210190572
- 8210190266 Forwards LER# 82-083/03L-0 & 82-085/03L-0 SMITH.W 0 Indiana & Michigan Electric Co 82/10/12 REPPLER.J ( Ragion 3, Office of Director 1p 15742 189 24X Fiche 50-315, 82/10/12, 8210190266
- --8210190277 LER 82-083/03L-0 on 820921.during hot standby following refueling leak observed on isolation valve C8-422N Caused by failure of 2-inch Orinnell Grade M diaphragm Diaphragm replaced HIZMER.P 0 Indiana & Michigan Electric Co 82/10/12 Arging 3. Office of Director 1p 15742 190 24X Fiche.50-315.82/L<sup>2</sup>/13 8210190266
- --8210190287 LER 82-085/03L-O on 820927, during hot standby following refueling, steam generator 2 stop dump valve MRV-221 removed from svc Caused by need to correct seat leekage Valve disc, seat & stem replaced HIZNER, D Q Indiana & Michigan Electric Co 82/10/12 Rep: 1 3, Office of Director 1p 15742 191 24X Fiche 50-315,82/11 3 8210190265
- 8210190340 Forwards LER 82-084/04L-0 SMITH, W Q Indiana & Michigan Electric Co 82/10/12 KEPPLER.J¢ Region 3. Office of Director 1p 15742 123 24X Fiche, 50-315, 82/10/12.8210190340
- --8210190342 LER 82-084/04L-0 on 820912, unplanned gas release detectr.
  elevated went stack gaseous monitor Caused by leak on wasts
  gas oxygen analyzer Leak repaired
  RMRPHY, C. E. Indiana & Michigan Electric Co. 82/10/12 Rejus
  3, Office of Director 1p 15742 124 24% Fiche 50-313.82/10.1
- 8210190380 Forwards LERs 82-086/03L-0, 82-087/03L-0 & 82-088/03L-5 SMITH, W 0 Indiana & Michigan Electric Co 82/10/13 KEPPLCR.J. F Region 3, Office of Director ip 15740 359 24X Fiche 55-315, 82/10/13, 8210190380
- --8210170387 LER 82-086/03L-0, on 820914 & 16, supply breater for heat trace circuits found tripped Cause unknown. Monitoring of panel will continue until cause can be determined PALMER.R. A Indiana & Michigan Electric Co 82/10/13 Rep. 3, Office of Director 1p 15740 360 24% Fiche, 50-315,82/L . 8210190380
- ---B210190404 LER 82-087/03L-0 on 820920, containment gaseous radiates monitor channel (ER8-1305) failed high forcing removal of containment air particulate monitor channel from svc Caused by defective I/O card Card replaced PALMER.R. A Indiana & Michigan Electric Co 82/10/13 Regia 3, Office of Director ip 15740.361. 24X Fiche 50-315.82/LC. 8210190380
- DOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2 F. Security, medical, emergency & fire protection plans
- 8210060387 Forwards IE Insp Repts 50-315/82-08 & 50-315/82-08 an 820412-16,0514 & 0610 Deficiencies referred to Ofc of Investigation, NORELIUB, C E. Division of Engineering & Technical Programs 82/07/22 DOLAN, J. E. Indians & Hichigan Electric Co. 239 19615-350 24X Fichs. 50-315,82/09/22,8210060387
- --82100A0393 IE Insp Repts 50-315/82-08 & 50-316/82-08 on 820412-162 & OA10. Deficiancies noted inadequate fire protection of safe shutfown capability inaccurate statements: inadequate procedure for alternate safe shutfown & inadequate lighting OROBE, J.A.; CHAN.T.L.; EBERLY, R Division of Engineering & Technical Programs, 82/09/17 27pp. 15615:352, 24% Fiche: 50-315,82/09/22,8210040387.

- 2:0030129 Releases public version of revised emergency plan procedures FELTON.J M Division of Rules and Records 82/09/22 Document Management Branch 1p 15663 293 24X Fiche 50-315, 82/09/22, 8210080129
- E210080132 Forwards public version of Revision 1 to Emergency Plan procedures PMP 2081 EPP 012, "Offsite Radiological Hamitoring" & Revision 1 to PMP 2081 EPP 026, "Use of Stable 1 addine for Thyroid Blocking During Radiation Emergency " Indiana & Michigan Electric Co 82/09/13 NRC No Detailed Affiliation Olven 1p 15663 294 24X Fiche 50-315.82/09/22, 82/0080127
- B210080136 Public version of Revision 1 to Emergency Plan Procedures PAP 2081 EPP 012, "Offsite Radiological Monitoring" & Revision 1 to PMP 2081 EPP 026, "Use of Stable Iodine for Thyroid Blocking During Radiation Emergency "Index encl a Indiana & Michigan Electric Co 82/09/13 20pp 15463 295 24% Fiche 50-315,82/09/22,8210080129
- 10010352 Forwards revision to modified amended security plan re key & lock control program Revision withheld (ref 10CFR73 21)
  HUNTER R S Indiana & Michigan Electric Co 82/09/27 DENTON, H R Oppice of Nuclear Reactor Regulation, Director 2pp 15574 158 24X Fiche 50-315.82/09/27,8210010362
- 1D150594 Releases public version of revision to plant manager procedure/emergency plan procedure
  FELTONIA J Bivision of Rules and Records 82/09/30 Document
  Management Branch ip 15716 350 24X Fiche 50-315,82/09/30,
- B210150604 Forwards public version of Revision 3 to Plant Manager Procedure/Emergency Plan Procedure App A, "Telephone Numbers for Key Plant Personnel" # Indiana & Michigan Electric Co B2/09/23 NRC No Detailed Affiliation Given ip 15716 351 24X Fiche 50-315.82/09/30.
- 3210150616 Public version of Revision 5 to Plant Manager Procedure/ Emergency Plan Procedure App A, "Telephone Numbers of Key Plant Personnel" \* Indiana & Michigan Electric Co 82/09/23 21pp 15716 352 24X Fiche 50-315,82/09/30,8210150594
- I-0190036 Releases public version of procedure temporary sheet to emergency plan procedure "ELTON: J M Division of Rules and Records 82/10/01 Document famagement Branch 1p 15761 034 24X Fiche 50-315:82/10/01. 3210190036
- 3210190040 Public version of procedure temporary sheet to Emergency Plan Procedure PMP 2081 EPP 020. "Activation & Operation of Technical Support Ctr " Revised index enc. VINCE, 8 , SIMMS, R . CAMPRELL, D Indians & Michigan Electric Co. B2/09/17. 2pp 13761 035 24X Fiche 50-315,82/10/01,8210190036
- O190652 Forwards FEMA 820909 ltr.final evaluations of offsite "mergency preparedness exercises conducted on 801009% pt 200330 for State of MI Berrien County & State of MI exposes Recommendations for offsite preparedness requested fIND. J A Division of Emergency Preparedness & Operational Support 12/10/12 HERINO, R F American Electric Power Service Corp (ERINO, R F Intina & Michigan Electric Co 2pp 15737:149. 24X 14che 50-315, 82/10/12,8210190652
- OZ80378 Releases public version of revision to emergency plan FOCEdure ELTON, J K Division of Rules and Records 82/10/12 Documen [Amagement Branch 1p 15859 238 24% Fiche 50-315, 82/10/12, )210280378.
- 210280380 Forwards public version of Revision 3 to emergency plan
  Procedure App B re hosp assistance plan

  Tindiana & Michigan Electric Co 82/10/01 NRC No Detailed
  Affiliation Given 1p 15859 239 24X Fiche 50-315,82/10/12,

  □ 210280378
- PIO280383 Public version of Revision 3 to emergency plan procedura App 8 te hosp assistance plan # Indiana & Michigan Electric Co 82/10/01 17pp. 15859,241. 24% Ficha 50-315,82/10/12,8210280378
- O280399 Releases public version of revised emergency plan
  FDCedures
  FTON, J M Division of Rules and Records 82/10/12 Document
  Enagement Branch ip 15859 261 24X Fiche 50-315,82/10/12,
  REO280399

- --8210280408 Forwards public version of revised emergency plan procedures including Procedures PHP 2081 EPP 004 reprotective action guidas & protective actions & PMP 2081 EPP 007 re health physics procedures

  \* Indiana & Michigan Electric Co 62/09/29 NRC No Detailed Affiliation Olven 1p 15859 262 24X Ficha 50-315,82/10/12. 8210280399
- --8210280413 Public version of revised emergency plan procedures, including Procedure PMP 2081 EPP 004 re protective action guides & protective actions & PMP 2081 EPP 009 re health physics procedures Procedures index encl

  \* Indiana & Michigen Electric Co 82/09/29 57pp 15859 263 24X Fichs 50-315.82/10/12,8210280399
- I Financial information
- 8210070279 Forwards Annual Financial Rept for 1981 & projected cash flow for 1982
  HERING,R F Indiana & Michigan Electric Co 82/10/04 DENTON.H R
  Office of Nuclear Reactor Regulation, Director 2pp 15634,185.
  24X Fiche 50-315,82/10/04,8210070279
- --8210070286 "ID & HI Electric Co.Annual Financial Rept 1981."

  4 American Electric Power Service Corp # Indiana & Michigan Electric Co. 82/10/04 32pp. 15634 187 24X
  Fiche 50-315.82/10/04.8210070279
- J Insurance & indemnity information
- 8210040313 Forwards Endorsement 54 to NELIA Policy NF-206 & Endorsement 44 to MAELU Policy MF-79
  8UCKLES, J. Marsh & McLennan, Inc., H & M Nuclear Consultants, Inc. Div. 82/09/27, SALTZMAN, J. Assistant Director for State & Licensee Relations 3pp 15986.168 24% Fiche.50-315, 82/09/27, 8210040313.
- P Operating license stage documents & correspondence
- 821005053B Forwards Amends 59 & 42 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability Amends revies Fech Specs to reflect installation or replacement of valves to improve operation CILIMBERO.R.L. Operating Reactors Branch 1. 82/09/09 DDLAN.J. Indiana & Michigan Electric Co. 2pp 15637 172 24X Fiche 50-315,82/09/09,8210050538
- --8210050541 Amends 59 & 42 to Licenses DPR-58 & DPR-7A, respectively, revising Tech Bpscs to reflect installation or replacement of valves to promote improved operation VAROA+S A Operating Reactors Branch i 82/07/09 26pp. 13537, 174 24X Fichs 50-315, 82/07/09, 8210050538.
- --8210050544 Safety evaluation supporting Amends 57 & 42 to Licenses DPR-58 & DPR-74, respectively.

  d Office of Nuclear Reactor Regulation, Director 15637:200 24X Fichs 50-315.82/09/09.8210050838
- --B210050546 Notice of issuance & availability of Amends 59 & 42 to Licenses DPR-58 & DPR-74, respectively OROTENHUIS, M. Operating Reactors Branch i B2/09/09 2pp. 15637 202. 24% Fichs 50-315, 82/09/09, 8210050538.
- 8210040415 Forwards Amends 61 & 44 to Licenses DPR-58 & DPR-74, respectively, sefety evaluation & notice of issuance & availability. Amends revise Tech Specs to reflect revised LDCA enalysis for Unit i & Suppl 2 to PDC-II procedures, CILIMBERG,R L Operating Reactors Branch i. 82/09/15. DDLAN, J. Indiana & Michigan Electric Co. 2pp 15597.098 24X Fiche: 50-315.82/09/15.8210040415
- --8210040417 Amends 61 & 44 to Licenses DPR-58 & DPR-74, respectively, revising Tech Spacs to reflect revised LOCA analysis for Unit i & implementation of Suppl 2 to PDC-II power distribution control procedures for Units 1 & 2. VAR6A-8 A. Operating Reactors Branch 1. 82/09/15. 29pp 15597.100. 24X Fiche.80-315.82/09/15.8210040415.
- ---8210040418 Bafety evaluation supporting Amends 61 & 44 to Licenses DPR-58 & DPR-74, respectively " Office of Nuclear Reactor Regulation, Director, 82/09/15, 3pp, 15597 129. 24X Fichs, 50-315,82/09/15,8210040415,
- --8210040417 Notice of issuance & evallability of Amenda 61 & 44 to Licenses DPR-58 & DPR-74, respectively. VARQA-8.A Operating Reactors Branch 1. 82/09/15. 2pp 15597:132 24% Fiche: 50-315, 82/09/15,8210040415

- 8210040428 Forwards request for addl info re hydrogen control issues for ice confenser plants Response requested by 821015 VARQA.5 A Operating Reactors Branch 1, 82/09/16 BOLAN.J Indiana & Mitchigan Electric Co 10pp 15597
- 8210050138 Forwards documents as Phase I b of response to Section 2 1 of Encl 3 to DO Eisanhut 801222 ltr re control of heavy loads Nestinghouse analysis of lifting arrangement for reactor vessel head & upper internals expected by 830315 HUNTER, R S Indiana & Michigan Electric Co. 82/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director. 31pp 15406 027 24% Fiche: 50-315, 82/07/27, 8210050138
- B210050157 Application for amend to Licenses DPR-58 & DPR-74, proposing Tach Spec changes for placement of new post-accident containment hydrogen monitoring sys to satisfy NUREG-0737. Item II F. 1 & & to ramove existing equipment from svc NUNTER.R S Indiana & Nichigan Electric Co 82/09/29 DENTON.H R. Office of Nuclear Reactor Regulation. Director 2pp 15605 149 24X Fiche 50-315, 82/09/29, 8210050159
- --8210050160 Proposed Tech Spec 3/4 6 4 re combustible gas control • Indiana & Michigan Electric Co 82/09/29 3pp 15605 151 24% Fiche 50-315.82/09/29.8210050159
- 8210120230 Forwards proprietary Suppl 1 to XN-NF-82-37(P), "DC Cook Unit 2.Cycle 4 SAR, Thermal-Hydraulic Analysis," providing add1 analysis of steady-state thermal margins during Cycle 4 operation Rept withheld (ref 10CFR2 790) CHANDLER, J C Exxon Nuclear Co. Inc (subs of Exxon Corp.) 82/09/29 EISENHUT, D O Division of Licensing 4pp 15656-079 24X Fiche 50-316,82/09/29,8210120230
- 8210050211 Second suppl to 820407 application for Cycle A reload & uprate license amend Further changes to App A Tech Specs necessary to allow Cycle A operation w/Erron Nuclear Cofusi at 3,411 MHt
  HUNTER,R B Indiana & Michigan Electric Co 82/09/30 DENTON.H R
  Office of Nuclear Reactor Regulation, Director 11pp. 15611 246
  24/ Fiche 50-316,82/09/30.8210050211.
- 82:0050349 Forwards add1 info re hydrogen mitigation & control at facilities Util continues to work w/TVA & Duke Fower Cotoward completion of executive summary rept on ice condenser hydrogen R&D program HUNTER, R 8 Indiana & Michigan Electric Co 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation. Director 126pp. 15410.126 24X Fiche 50-315.82/09/30.8210050349
- 8210080194 Comments on regulatory performance improvement program Comments can be dealt w/by revising program description to take full credit for mgt review afforts Util views on comments will be discussed at meeting scheduled for 821014 KEPPLER.J O. Region 3. Office of Director \$2/10/01 DNLAN.J E. American Electric Fower Service Corp DOLAN.J E. Indians & Michigan Electric Co. 2pp 19640 188 24X Fiche: 50-315, 82/10/01, 8210080194
- 8210060253 Discusses 820707 mgt meeting & forwards Systematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16. KEPPLER.J G. Region 3. Office of Director 82/10/04 DDLAN.J E American Electric Power Co. Inc. 3pp. 15620.198 24X Fiche.50-315.82/10/04.8210060253.
- --8210060254 Systematic Assessment of Licenses Performance Repts 50-315/82-16 & 50-316/82-16 on 801001-820401. Hajor areas examined util regulatory performance \*\* Region 3, Office of Director, 82/06/30 7pp 15620,201, 24X Fiche: 50-315,82/10/04,8210060253
- --8210050255 Responds to NRC 820625 Systematic Assessment of Licensee Performance Repts 50-315/62-16 & 50-316/82-15. Tusive previously trained operators hired & computatived radiation exposure maint sys & security access control sys installed HUNTER.R S Indiana & Michigan Electric Co. 82/07/27. XEPPLER.J G. Region 3. Defice of Director, 35pp. 15620,208. 24X Fiche:50-315,62/10/04,8210060253
- 8210150491 Confirms B20922 telcon re masonry walls. Addl info required within 45 days to complete review VAROA. B A. Operating Reactors Branch 1. 82/10/04. DOLAN. J Indiana & Michigan Electric Co. 3pp 15717: 275. 24X Fiche: 50-315.82/10/04.8210150491.
- 8210230340 Forwards Amands 63 & 45 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability. Amend reviess Tech Space changing surveillance requirements for boron & safety injection sys CILIMBERO, R. L. Operating Reactors Branch 1, 82/10/04 DOLAN, J. Indiana & Michigan Electric Co. 2pp. 15807:259, 24X Fichs: 50-315, 82/10/04, 8210250340.

- ---8210250393 Amends &3 & 45 to Licenses DPR-58 & DPR-74, respectively changing Tech Space re surveillance requirements for boron & safety injection sys & updating core flux VARQA: A Operating Reactors Branch 1 82/10/04 73pp 15807 261 24X Fiche 50-315,82/10/04,8210250340
- --8210250394 Safety evaluation supporting Amends 63 & 45 to Cicines DPR-58 & DPR-74: respectively # Office of Nuclear Reactor Regulation, Director 15807 334 24X Fiche 50-315.82/10/04,8210250340
- --8210250395 Notice of issuance & availability of Amends 63 & 45 & Licenses DPR-58 & DPR-74.respectively VAROA.S A Operating Reactors Branch 1 82/10/04 2pp 13807 339 24X Fiche 50-315,82/10/04,8210250340
- BQ1015C434 Forwards tafety evaluation re main steam line break w/continued feedwater addition & contractor technical avaluation rept W/o technical evaluation rept WARQA-S A Operating Reactors Branch 1 B2/10/05 DOLAN, J Indiana & Michigan Electric Co 2pp 13716.090 24X Fiche. 50-315, 82/10/05.8210150434
- --B210150437 Safety evaluation re main steam line break w/continued feedwater addition # Operating Reactors Branch 1 82/10/05 7pp 15716 092 200 Fiche 50-315, 82/10/05, 8210150434
- GRI0130123 Forwards proprietary "Users Manual for PTSPHR2-FORTRAN Program for Simulation of PHR Plant Transients" & Suppl 1 to manual Affidavit supporting proprietary classification of documents encl Manuals withheld (ref 10CFR2 779)
  CHSLEY, 0 F Exxon Nuclear Co. Inc (subs of Exxon Corp.)
  82/10/08 THOMAS, C.O. Standardization & Special Projects Granc)
  4pp 15673 097 24X Fiche 50-316, 82/10/08, 8210130123
- 8210150033 Forwards Revision 1 to XN-NF-82-32(P), "Plant Transient Analysis for DC Cook Unit 2 Reactor at 3,425 MMt." including DNB analysis method changes to support Cycle 4 operation Revision withheld (ref 100FR2 790) OHSLEY.0 F Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 82/10/08 EISENHUT.0 9 Division of Licensing 1p 15715 267 24X Fiche 50-316.82/10/08.8210150033
- 8210250228 Forwards proprietary responses to five of 16 questions per NRC 820730 request for add1 info re hydrogen control issues for ice condenser plants, particularly CLASIX computer program Responses withheld (ref 100FR2, 790) HUNTER, R 8 Indians & Michigan Electric Co 82/10/15 DENION k4 0ffice of Nuclear Reactor Regulation, Director 2pp 15789 337 24X Fiche 50-315, 82/10/15, 8210250228.
- O Inspection reports: IE Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight categories of records a steam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B.
  FELTON. J H Division of Rules and Records B2/08/10 L0M9.0 J Hinthrop, Stimson, Putnam & Roberts, 9pp 15445,063 24% Fiche: 50-000,82/08/10,8210070007
- --8210070139 Forwards tabulated data on steam generator insplanants Aacilities. Data should be provided to licensess IPPOLITO, T. Operating Reactors Assessment Branch 62/04/05 VAROA: 8 Operating Reactors Branch 1 5pp 13645,131 24K Fiche 50-000,82/08/10.8210070007
- 8210040387 Forwards IE Insp Repts 50-315/82-08 & 50-314/82-06 on 820412-16,0514 & Odio Deficiencies referred to Dfc df Investigation for review & investigation NORELIUS, C. E. Division of Engineering & Technical Program 82/09/22, DBLAN, J. E. Indiana & Michigan Electric Go. 299 15615,350 24K Fichs 50-315,82/09/22,8210060387
- --8210060393 IE Insp Repts 50-315/82-08 & 50-316/82-08 on 9204[2-18.2 & 0610 Deficiencies noted inadequate fire protection of laft shutdown capability, inaccurate statements, inadequate procedure for alternate safe shutdown & inadequate lighting GROBE, J.A., STONE, J.C., HAUGHNEY, C.J. Division of Engineering Technical Programs 82/09/17 27pp 15615-352 24% Fiche. 50-315, 82/09/22, 8210060387.
- 8210080274 Ack receipt of 820914 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/82-12 & 50-316/82-12.

  STREETER, J.F. Division of Project & Resident Programs 82/89/M DOLAN, J.E. American Electric Power Service Corp. DOLAN, J.E. Indiana & Michigan Electric Co. 1p. 15609:187. 24X
  Fiche: 50-315, 82/09/24, 8210080274

- --E210030276 Responds to NRC 820816 ltr re violations noted in IE Insp. Repts 50-315/82-12 & 50-316/82-12 Corrective actions plant canager until issue nemo to plant depts by 820930 reprocedures for installation of new design changes HERING, R.F. Indiana & Michigan Electric Co. 82/09/14 MEPPLER. J.G. Region 3. Office of Director 3pp. 15609 188 24% Fiche 50-315,82/09/24,8210050274
- 8210050253 Discusses B20707 mgt meeting & forwards Systematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-315/82-16 & FEPPLER, J G Region 3. Office of Director 82/10/04 DDLAN, J E American Electric Power Co, Inc. DDLAN, J E. Indiana & Michigan Power Co. 3pp. 15620-198 24X Fiche 50-315,82/10/04,8210060253
- --8210060254 Systematic Assessment of Licensee Performance Repts 50-315/82-16 & 50-316/82-16 on 801001-820401 Major areas examined util regulatory performance, \* Region 3, Office of Director 82/06/30 7pp 15620 201 24x Fiche 50-315,82/10/04,8210060253
- --B210060256 Responds to NRC 820625 Systematic Assessment of Licensee Ferformance Repts 50-315/82-16 & 50-316/82-16 Twelve previously trained operators hired & computerized radiation exposure maint sys & security access control sys installed FUNNIER.R 5 Indiana & Michigan Electric Co B2/07/27 MEFFLER, J G Region 3, Office of Director 35pp 15620-208 24X Fiche 50-315,82/10/04.8210060253
- -208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 leplant Seeds " Svc list encl COBB.L ( Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,62/10/06.8208190233
- 1208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hall-Large-Diameter: Stainless Steel. Recirculation Sys Piping at 8MR Plants "Svc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000, 82/10/14.8208190238
- 210150388 EN-8;-047A on 821014, order imposing civil monetary penalty in amount of \$52,000 issued to licenser re violations concerning fire protection program & containment integrity One violation withdraum & two modified CRAIG.J. AXELRAD,J Director's Office. Office of Inspection and Enforcement 82/10/14 ip 15721 307 24X Fiche 50-315,82/10/14, 8210150388

## Periodic operating reports & related correspondence

- 210190676 Forwards Sr-87 & Sr-90 data not completed by contractor until after due date for submittal of semiannal radioactive effluent rolease rept for Jan-June 1982 HUMTER.R S Indiana & Michigan Electric Co 82/10/01 KEPPLER.J 9 Region 3. Office of Director 2pp 18738 197 24X Fiche 50-315, 82/10/10,8210170676
- -8210190685 "Effluent & Waste Disposal Semiannual Rept-1982, Gaseous Effluents-Elevated Release: " 8r-89 & Sr-90 data omitted from original 820827 submittal signal & Michigan Electric Co 82/10/01 10pp 15738 199 24X Fiche 50-315.82/10/01.8210190676
- Reportable occurrences. LERs & related correspondence
- 210040321 Forwards LERs 82-072/03L-0 & 82-075/03L-0 SMITH.H 0 Indiana & Michigan Electric Co 82/07/22 KEPPLER,J 0 Region 3, Office of Director 1p 15586 171 24X Fiche 50-316, 82/07/22, 8210040321
- 8210040327 LER 82-072/03L-0.on 820824, reactor trip occurred as result of facilure in 120-volt ac vital bus Caused by burned out resistor (R1) & diode (D1) on oscillator board & essociated fuse Dscillator board & fuse replaced FALMER.R A Indiana & Michigan Electric Co. 82/09/22 Region 3. Office of Director 1p. 15586 172 24X Fiche.50-316,82/09/22,8210040321
- 8210040330 LER 82-075/03L-0 on 820824, following reactor trip, RCS dose equivalent & I-131 concentration exceeded 1.0 uCi/g steady state limit. Caused by inadvertent removal from svc of chemical & vol control sys mixed bed damineralizer. PALMER.R A Indiana & Michigan Electric Co 82/09/22 Region 3, Office of Director App 15586 173 24X Fiche 50-316. 82/09/22.82 10040321
- '10040201 Forwards updated LER 82-084/03X-1 SHITH: 44 9 Indiane & Michigan Electric Co 82/09/23 KEPPLER: J. 9. Region 0. Office of Director. 1p 15583'161 24X Fichm: 50-316. 82/09/23. 8210040201

- --8210040207 Updated LER 82-064/03X-1 on 620724.Loop 3 overtemp Delta-T trip setpoint found high Caused by setpoint drift Naw module installed calibr & verified operational Loop returned to ave PALMER.R A. Indiana & Michigan Electric Co 62/09/23 Region 3, Office of Director 1p 15583 162 24X Fiche 50-316,62/09/23, 8210040201
- 8210060277 Forwards LER 92-076/03L-0 SMITH:N 0 Indiana & Michigan Electric Co 82/09/29 KEPPLER,J Q Region 3. Office of Director 1p 15621 168 24X Fiche 50-316.82/09/29.8210060277
- --8210060313 LER 82-076/03L-0 on 820915, discovered diesel room AB carbon dioxide sys isolated w/no personnel in room Cause not stated Signs posted cautioning personnel to restore carbon dioxide sys when exiting Administrative action taken LAMP.M S Indiana & Michigan Electric Co 82/09/29 Region 3, Office of Director 1p 15621 169 24% Fiche 30-316,82/09/29, 8210060277
- 8210080189 PND-III-82-105 on B20930 facility shut down for 3 days to repair weld crack in 1-inch feedwater drain between containment penetration for steam generator 1 & last feedwater check valve. REYEG.L. STREETER.J. SPESSARD.R Region 3. Office of Director 82/10/01 1p. 1540-180 24X Fiche 50-316.82/10/01.8210080189
- 8210180120 Forwards LERs 82-077/03L-0 & 82-078/03L-0, SMITH,W O Indiana & Michigan Electric Co 82/10/05 KEPPLER,J Q Region 3, Office of Director 1p 15719-325 24X Fiche 50-315,82/10/05,8210180120
- --8210180123 LER 82-077/03L-0 on 820907, equalizing valve on inner door of upper containment personnel airlock found leaking slightly during containment antry Cause unknown Valve actuating mechanism adjusted PIEHL, R H, Indiana & Michigan Electric Co 82/10/05. Region 3, Office of Director ip 19719-326 24X Fiche 50-314,82/10/05, 8210180120
- ---B210180127 LER 82-078/O3L-0 on 820718 & 20.RCB dose equivalent I-131 concentration exceeded 1 0 uCi/g steady-state limit Caused by RCS dose equivalent I-131 spiked to max of 1 76 uCi/g PALMER, R A Indiana & Michigan Electric Co B2/10/05 Region 3. Office of Director 4pp 18717 327 24X Fiche 50-316, 82/10/05,8210180120
- 8210190727 Forwards LER 82-080/03L-0 SMITH.W 0 Indian & Michigan Electric Co 82/10/08 KEPPLER.J Q Region 3. Office of Director 1s 15736 298 24X Fiche 50-316.82/10/08.8210190727.
- --B210190735 LER B2-080/03L-0 on B20909, west component cooling water HX outlet valve CMO-420 removed from svc due to leak Caused by elastomer seat being pulled loosed from valve body Valves returned to manufacturer WIZNER, D 0 Indiana & Michigan Electric Ca B2/10/08 Region 3, Office of Director 2pp 15736-279 24X Fiche 50-316, 82/10/08,82/10/90727.
- DUCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8203050387 Forwards IE Insp Repts 50-317/82-02 & 50-318/82-02 un 820106-0202 & notice of violation STAROSTECKI/R. Division of Project & Resident Programs 82/02/16 LUNOVALLA.E Baltimore Oas & Electric Co 2pp 12134 298. 24X Fiche: 50-317: 82/02/16, 8203050387
- --B210190714 IE Insp Repts 50-317/82-02 & 50-318/82-02 on 820105-0802 Noncompliance noted failure to adequately control special processes associated w/repair of saltwater piping & failure to properly neutralize regenerative waste ARCHITZEL.R.E. MCCABE.E.C. Division of Project & Resident Programs. 82/02/12, 11pp 15751 024 24X Fiche 50-317.82/02/16.8203050387
- 8210210544 Releases public version of revised emergency response plan implementing procedures.
  FELTON, J. M. Division of Rules and Records. 82/07/23 Document Hanagement Branch. 1p 15782 330. 24X Fiche 50-317,82/09/23,8210210544.
- --8210210545 Forwards public version of revised emergency response plan implementing procedures including Procedures EPIP 5.5 re exercises, test & drills & EPIP App B, 2 re maps & charts \* Baltimore, Oas & Electric Co 82/07/15. CLARK, R. A Operating Reactors Branch 3 ip 15782-331, 24X Fiche: 50-317, 82/09/23, 8210210544

- --8210210551 Public version of revised emargency response plan implementing procedures including Procedures EPIP 5 5 reservises. test & drills & EPIP App B 2 remaps & charts List of effective pages enci e Baltimore Gas & Electric Co 82/09/15 20pp 15782 332 24x Fichs 50-317,82/09/23.8210210844
- 8210120134 Forwards third suppl to 790914 fire protection safety evaluation, resolving Item 3 2 1, Fire Harands Analysis "Ninety-day period to inform of installation schedule for source range flux monitoring instrumentation acceptable CLARK, R A Operating Reactors Brench 3 82/09/27 LUNDVALL, A. E. Baitimore Gas 4 Electric Co ip 13492 137. 24X Fiche 50-317, 82/09/27, 8210120134
- --B210120139 Safety evaluation canciluding that proposed fire protection dusign meets requirements of App R to IOCFR50. Items III G 3 & III L re safe shutdown in event of fire FIGRAVANTER, N. HARRISON, G., JAFFE, D. Deresting Reactors Branch I B2/09/27 9pp 15692 158 24X Fiche. 50-317. B2/09/27, 8210120134
- 8210150423 Application for amend to Litenses DPR-53 & DPR-49 consisting of Revision 10 to security plan, allowing devitalization of vital areas during cold outages Plan withheld (ref 100FR73 21)

  BQMMAKER:N J Baltimore Ges & Electric Co 82/10/07. CLARK:R A Operating Reactors Branch 3 3pp. 15704, 021 24X Fichs 80-317, 82/10/07. 9210150423
- 8210180005 Submits update of util progress in closing THT Action Items I C J.JJ F 1 & JJJ. A 1 2.

  LUNDVALL.A E Baltimore Oas & Electric Co 82/10/12 CLARK.R A. Operating Reactors Branch 3 3pp 15720 028 24X

  Fichs 50-317.
- P Operating license stage documents & correspondence
- B21001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON-J M Division of Rules and Records 62/06/28 UDELL,R A Critical Mass Energy Project 15pp. 15727:005 24X Fiche:50-000.82/06/28.8210010008
- --8204270048 Recommends prompt attention be given to problem of reactor coolant pump closure stud corrosion detected at facilities Response by 820415 requested EISENHUT, D.Q. Division of Licensing. 82/03/24, HANAUER, S.H. Division of Bystems Integration (post 811005). 3pp 66035 222 24X Fichs 50-000, 82/06/28,8210010008
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 82/07/12, UDBLL.R A Critical Mass Energy Project, 9pp. 15665, 027, 24X Fiche 50-000.82/07/12,8210080015
- --8210080064 Trip rept of 820207 visit to NRR in Bethesda, MD & 820208-10 site visit re installation of 10-inch automatic isolation valve in main feedwater sus Bpsc 6750-M-253 for nuclear carbon steel gate, globe & check valves & related info encl. BEARDEN, R G. 6049, Inc. 82/03/22 47pp 15665:192, 24X Fiche: 50-000, 82/07/12, 8210080015

- --B210070125 Safety evaluation supporting Amends 75 & 56 to Licent BPR-53 & DPR-69: respectively JAFFE, D H Office of Nuclear Reactor Regulation, Director B2/09/24 4pp 15645 043 24X Fiche 50-317, B2/09/20, B21007
- --8210070130 Notice of issuance & availability of Amends 75 % 56 ( Liceness DPR-93 & DPR-69, respectively CLARK.R A Operating Reactors Branch 3 82/09/20 2pp 15645-047. 24X Fiche 50-317, 82/09/20-8210070106
- 8210180124 Forwards proprietary & nonproprietary versions of "Res. of Eddy Current Testing on Ouide Tubes at Calvert Cliffs I After Cycle 5"

  LUNDVALLA E Baltimore Oas & Electric Co 82/09/22 CLARK, R Operating Reactors Branch 3 2pp 15719 097 24X

  Fiche 30-317, 82/09/22, 8210180124
- --8210180133 Nonproprietary version of "Results of Eddy Current To on Quide Tubes at Calvert Cliffs I After Cycle 5 " • Combustion Engineering. Inc CEN-216(8) B2/08/31 7pp 15719 097 24X Fiche 50-317.82/09/22.8210180124
- B210270412 Forwards Amends 77 & 58 to Licenses DPR-53 & DPR-67, respectively safety evaluation & notice of issuance & availability Amends revise Tech Spec Table 3 7-4 which lists soubsers that require periodic insp & testing JAFFE.D H Operating Reactors Branch 3 82/09/23 LUNDVALLIA Baltkmore Qas & Electric Co 3pp 15869 273 24% Fiche 50-317.82/09/23,8210290412
- --8210270428 Amends 77 & 58 to Licenses DPR-58 & DPR-69, respective revising Tech Spec Table 3 7-4 which provides lists of safety-related hydraulic shock suppressors (snubbers) which require periodic insplict testing CLARK, R A Decreting Reactors Branch 3 82/09/23 24pp 15863:276 24X Fiche 50-317, 82/09/23,8210290412
- --8210270437 Bafety evaluation supporting Amends 77 & 58 to License BFR-53 & DFR-69, respectively 4 Office of Nuclear Reactor Regulation, Director 82/09/23 15863:302 24X Fiche 50-317,82/09/23.8210290412
- --8210290444 Notice of issuance & availability of Amends 77 t 88 to Licenses DPR-58 & DPR-69, respectively CLARK.R A Operating Reactors Branch 3 82/09/23 2pp 18863:305. 24X Fiche 50-317, 82/09/23,8210290412
- 8210130338 Application to amend Licenses DPR-53 & BPR-59, revising Tech Specs re pressurfier limiting condition for operation & associated surveillance requirements.

  LUNDVALL: A E Baltimore Oas & Electric Co 82/09/29 CLASK,R A Operating Reactors Branch 3 Spp 15680 268 24X Fiche 50-317,82/09/29,8210130338.
- --8210130342 Proposed Tech Specs 3 4 4 & 4, 4 4 re RCS pressuriter + Baltimore Oas & Electric Co 82/09/29, 44pp 15680 271 p Fiche, 50-317, 82/09/29, 8210130338
- 8210180423 Application for amend to Licenses DPR-53 & DPR-69 (ensity of Revision 10 to security plan, allowing devitalization of vital areas during told outages. Plan withheld (ref 10CFR70, 21)
  BOMMAKER, N. J. Baltimore Gas & Electric Co. 82/10/67. CLARK, R & Operating Reactors Branch 3 3pp. 15704-021 24X
  Fiche 30-317, 82/10/07, 8210150423.
- 8210180005 Submits update of util progress in closing TMT Action lies I C. 1, II.F 1 & III.A 1 2. LUNDVALL.A.E Baltimore Oas & Electric Co. B2/10/12 CLAM.R.A. Operating Reactors Branch 3. 3pp 15720:028 24X Fiche; 50~317, 82/10/12, 8210180005
- 821020010B Notification of 821025 meeting w/util in Betheward Notificates control of heavy loads.

  JAFFE, D H Operating Reactors Branch 3. 82/10/18 CLARKA A Operating Reactors Branch 3. 2pp 15767, 304. 24X

  Fiche: 50-317, 82/10/18,821020010B

- 1 Inspection reports. IE Bulletins & correspondence
- 6203050387 Forwards 16 Insp Repts 50-317/82-02 & 50-318/82-02 on 820108-0202 & notice of violation STAROSIECKI.R Division of Project & Resident Programs 82/02/16 LUCOVALL.A E Baltimore Gas & Electric Co 2pp 12134 298 24X Fichs 50-317, 82/02/16, 8203050387
- --R210190702 Natice of violation from insp on B20106-0202 STAROSTECKI,R Division of Project & Resident Programs B2/02/16 2pp 15751 022 24X Fiche 50-317,82/02/16,8203050387
- --9210390714 IE Insp Repts 50-317/82-02 & 50-318/82-02 on 820104-0202 Nancomptiance noted failure to adequately control special processes associated w/repair of saltwater piping & failure to properly neutralize regenerative waste ARCHITZEL, R E . HCCABE, E C Division of Project & Resident Programs 82/02/12 lipp 15751 024 24X Fiche 50-317,82/02/16.8203050387
- E2:0070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON. J M Division of Rules and Records 62/08/10 LONG, D J Hishthrep, Stimson, Putnam & Roberts 7pp 15645 063 24X Fiche 50-000.82/08/10,8210070007
- --8210070172 Forwards info re steam generator integrity & insps at all operating PURs, per 750320 & 21 requests Details of insps. Including defect indications, tube plugging criteria & tubes plugged will not be provided except for Point Beach i QDLLER, K R Division of Reactor Licensing (NRR-1975 only) 75/03/24 MACCARY, R Division of Tachnical Review (NRR-1975 only) 5pp 15645 196 24X Fiche 50-000,82/08/i0,8210070007
- #210060079 Forwards IE Insp Repts 50-317/82-06 & 50-318/82-06 on E20315-16 & notice of violation MARTINET T Division of Engineering & Technical Programs 82/09/17 LUNDVALL.A E Baltimore Oas & Electric Co 2pp 15614 345 24X Fiche 50-317,82/09/17,8210060099
- --B210060104 Notice of violation from insp on 820315-16 • Division of Engineering & Technical Programs 82/09/17 2pp 15614 347 24X Fiche 50-317,82/09/17,8210060099
- --8210060127 IE Insp Repts 50-317/82-06 & 50-318/82-06 on 820315-16
  Noncompliance noted failure to establish adequate
  procedures, failure to follow radiation protection procedures
  & failure to make necessary radiological surveys
  PLUMILE, K E , GREENMAN, E Q Division of Engineering & Technical
  Programs 82/09/17 10pp 15614 349 24X Fiche 50-317,82/09/17,8210060099
- E210070105 Forwards Amends 75 % 56 to Licenses DPR-53 % DPR-69, respectively, safety evaluation & notice of issuance & availability Amends correct typographical errors reinservice insp & valve testing

  JAFFE.D H Operating Reactors Branch 3 82/09/20 LUNDVALL.A E Baltimore Gas & Electric Co 3pp 15645 006 24X

  Fiche 50-317, 82/09/20, 8210070106
- -- 8210070117 Amends 75 & 56 to Licenses DPR-50 & DPR-69, respectively, correcting typographical errors re inservice insp & valve testing & allowing start up of reactors w/inoperable but isolated power operated relief valves
  CLARK, R A Operating Reactors Branch 3 82/09/20 34pp, 15645 009 24X Fiche 50-317,82/09/20.8210070106
- B210180124 Forwards proprietary & nonproprietary versions of "Results of Eddy Current Testing on Guide Tubes at Calvert Cliffs I After Cycle 5 "
  LUMBYALL.A E. Baltimore Cas & Electric Co 82/09/22 CLARK.R A Operating Reactors Branch 3 2pp 15719 097. 24X Fiche 50-317.82/09/22,8210180124
- --B210180133 Nonproprietary version of "Results of Eddy Current Testing on Guide Tubes at Calvart Cliffs I After Cycle 5 "

  « Combustion Engineering, Inc. CEN-216(8) 82/08/31 7pp 15719 099 24X Fichs 50-317.82/07/22.8210180124.
- 8210150214 Forwards IE Insp Repts 50-317/82-23 & 50-318/82-19 on 820810-0914 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 82/09/27 LUNDVALL.A E Baltimore Cas & Electric Co 2pp 15705-234, 24X Fiche: 30-317, 82/09/27, 8210150214

- --8210150235 IE Insp Repts 50-317/82-23 & 50-318/82-19 on 820810-0914 Noncompliance noted radiological event not declared nor appropriate response taken & procedures not properly implemented ARCHITZEL.R E. TRIMBLE.D C. MCCABE, E.C. Division of Project & Resident Programs 82/09/27 18pp. 15705 238 24X Fiche 50-317,82/09/27.8210150214
- 9210060240 Forwards notice of violation re IE Insp Repts 50-317/82-07 50-318/82-07 on 820413-051! Violation A re operation w/hydrogen analyzers inoperable needs no response Violation B re inadequate review requires full response 8TAROSTECKI.R. Division of Project & Resident Programs 82/07/29 LVNDVALLA E Baltimore Qas & Electric Co 3pp 15619 322 24X Fiche 50-317,82/09/29,8210060240
- --8210060243 Notice of violation from into on 820413-0511 Noncompliance noted plant operated w/hoth hydrogen analyzers inoperable plant operating safety review committee performed inadequate review on 800924 & approved revision w/o correct criteria \* Region i. Defice of Director 82/09/29 2pp 15619:325 24x Fiche 50-317,82/09/29,8210060240
- 8210070159 Requests approval for excluding reactor vessel closure studs at facilities, per IE Bulletin 82-02 & Ray Guide 1.65
  Bolting mail complies w/recommended mails
  LUNDVALL, A E Baltimore Gas & Electric Co 82/10/01 DEYDUNO, R C Director's Office, Office of Inspection and Enforcement 3pp
  15627 013 24X Fiche 50-317,82/10/01,8210770159
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Beeds." Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York. 64pp 15761 250 24X Fiche 50-000,82/10/06.8208190233
- 8210130099 Ack receipt of 820917 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/82-20 & 50-318/82-17
  MARTIN.T T Division of Engineering & Technical Programs 82/10/06 LUNDVALL, A E Baltimore Oas & Electric Co 1p 15473 104 24X Fiche 50-317, 82/10/06, 9210130099
- --82:0130:103 Responds to NRC 8208:19 ltr re violations noted in IE Insp. Repts 50-317/82-20 & 50-318/82-17 Corrective actions: Operating Instruction AD Procedure 2 & Instruction 302 revised LUMDVALLA E Beltimore Gas & Electric Co 82/09/17. MARTIN.T T. Division of Engineering & Technical Programs 4pp 13673 105 24% Fiche 50-317.82/10/06/82:10130079
- 8210190797 Ack receipt of 820915 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/82-18 & 50-318/82-16.
  SYAROSTECKI.R Division of Project & Resident Programs 82/10/12 LUNDVALLIAE Baltimore Gas & Electric Co. 1p 15736-314 24X Fiche 30-317, 82/10/12.8210190797
- --B210190803 Responds to NRC 820816 ltm re violations noted in IE Insp. Repts 50-317/82-18 & 50-318/82-16 Corrective actions. Instruction-112 revised to ensure essential equipment will not be inadvertantly removed from svc FTI-107 also revised LUNDVALLA E Baltimore Oas & Electric Co. 82/09/15 STAROSTECKI, R. Division of Project & Resident Programs 2pp. 15736-315. 24X Fiche: 50-317, 82/10/12,8210190797
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants." Set list encl DEYGUNO, R.C. Director's Defice, Defice of Inspection and Enforcement. 82/10/14. Consolidated Edison Co of New York. 115pp 15810:125. 24X Piche, 50-000, 82/10/14.8208190238.
- R Periodic operating reports & related correspondence
- 8210210328 Forwards monthly operating repts for Sept 1982 LOTITO,E M Baltimore Qas & Electric Co. 82/10/15. Director's Office, Office of Inspection and Enforcement 1p. 15762 003. 24X Fiche 50-317, 82/10/15. 8210210328
- --8210210457 Monthly operating repts for Sept 1982. LOTITO.E. Baltimore Gas & Electric Co. 82/10/15. 10pp. 15762.004. 24X Fiche: 50-317, 82/10/15, 8210210328.
- 5 Reportable Occurrences, LERs & related correspondence
- 9210280305 Forwards LER 81-019/03L-0 RUSSELL,L.S. Baltimore Cas & Electric Co. 81/04/10 ORIER, B H, Region 1, Philadelphia. Office of the Director (81/03/01). 1p. 13838-361 24X Fichs. 50-317, 81/04/10, 8210280305

- B210280313 LER B1-019/03L-0 on B1031i.experienced failurg of one containment hydrogen analyzer (0-AE-6519) Caused by defective analyzer (Belphi B1A-1AiE) zero adjustment potentiometer. Analyzer replaced HENDERLICH, R. L., RIZZO, P. G. Baltimore Oas & Electric Co. B1/04/10 Region 1. Philadelphia, Office of the Director (81/03/01) 1p 15838 362 24X Fiche 50-317,81/04/10,8210280305
- 210280203 Forwards LER 81-023/03L-0 RUSSELL.L B Baltimore Gas & Electric Co 81/04/16 ORIER, B H Region 1. Philadelphia. Office of the Director (81/03/01) 1p 15837 290 24% Fichs 50-017.81/04/16.8210280203
- -8210280205 LER 81-023/03L-0 on 810317.ventilation exhaust damper in cable spreading room did not that Caused by reversal of Units 1 & 2 control circuits Control & indication circuits reworted HEIBEL.R P Baltimore Cas & Electric Co 81/04/16 Region 1. Philadelphia, Office of the Director (81/03/01) 1p 15837 291 24X Ficher 50-317, 81/04/16, 8210280203
- 210280263 Forwards LER 81~021/03L-0 RUBSELL, L B Baltimore Cas & Electric Co. 81/04/16 QRIER, 8 H Region 1. Philadelphis. Office of the Director (81/03/01) ip 19837 307 24X Ficher 50-317.81/04/16,8210280263
- -8210280267 LER 81-021/03L-0 on 810320, w/coolant charging jump 12 inoperable due to sticking discharge relief valve, jump 13 taken out of svc for repair Caused by loss of nitragen jump 13 Valve repaired & desurger charged MENDERLICH, R. L. HUSESY, D. E. Baltimore Cas & Electric Co. 81/04/16, Region 1. Philadelphia. Office of the Director (81/03/01) 2pp. 15837 308 24X Fiche 50-3(7.81/04/16, 8210280263
- 210280296 Forwards LER 81-020/03L-0 RUSSELL.L B Baltimore Gas & Electric Co 81/04/16 ORIER.B.H Region 1. Philadelphia, Office of the Director (81/03/01), lp 18837 279 24% Fiche 50-217.81/04/16.8210280296
- -8210280301 LER Bi-020/03L-0 on 810320 containment normal sump drain, i-MOV-5463, exceeded max closing time of 13-s Caused by valve operator open limit switch out of adjustment Bultch adjusted.

  DAVIS, B K, RIZZO, P O Baltimore Gas & Electric Co Bi/04/16 Region i, Philadelphia, Office of the Director (81/03/01). ip 15837 280 24% Fichs 50-317.81/04/16.8210280296
- 8210280249 Forwards LER 81-022/03L-0 RUSSELL.L.B Baltimore Oas & Electric Co 81/04/23 ORIER.B H Region I. Philadelphia. Office of the Director (81/03/01). ip 15837.051 24X Fiche.50-317.81/04/23.8210280249
- --8210280255 LER 81-022/03L-0 on 810324,ESF actuation sys degraded voltage relay found inoperable. Caused by bind in relay output contacts Contact lever streightened & spring tension increased to hold positioned lever # Baltimore Gas & Electric Co 81/04/23. Region 1, Philadelphia, Office of the Director (81/03/01). 2pp. 15837-052 24X Fiche 50-317,81/04/23,8210280249
- 8210270279 Forward: LER 81-024/03L-0 RUSBELL,L.B Baltimore Gas & Electric Co. 81/05/01, GRIER.B.H Region 1, Philadelphia: Office of the Director (81/03/01) 1p 15828,285. 24X Fiche:50-317,81/05/01,8210270279
- --82(0270280 LER 81-024/03L-0 on 810404.during routine shutdown. MRIV 12 closing time exceeded Tech Space Caused by contemination of valve actuation sys hydraulic fluid resulting in sticking check valves Finer filters will be used.

  DAVIS.S.M. WEIR.P.J Baltimore Gas & Electric Co. 81/05/01 Region i. Philadelphia. Office of the Director (81/03/01). 1p 15828-286. 24x Fiche 50-317,81/05/01,8210270279
- 8210280318 Forwards updated LER 81-021/03L-1 RUBSELL, L B Baltimore Cas & Electric Co 81/03/12. QRIER, B. H Region 1, Philadelphia, Office of the Director (81/03/01) 1p 19838; 358 24X Fiche: 50-317, 81/05/12, 8210280318
- 8210270266 Forwards LER 81-032/03L-0 RUBSELL L B. Baltimore Gas & Electric Go. 81/05/20. ORIER, B.H. Region I. Philadelphia, Office of the Director (81/03/01) 1p. 18829:043. 24% Fiche:50-317.81/05/20.8210270266.

- --B210270269 LER BI-032/03L-0 on BI0420, reactor protective sys charming highpower thermal margin/low pressure & axial shape indeptrip units bypassed Caused by need to replace transmitter j-TT-112D which drifted high LAGIEWBKE, J B , RIZZO 0 Baltimore Oas & Electric Co 81/05/20 Region 1. Philadelphia (Bfice of the Director (Bi/03/01) 1; 15827 044 24X Fiche 50-317, 81/05/20, 8210270266
- 8210270274 Forwards LER 81-033/04T-0 RUSSELL,L B Baltimore Gas & Electric Co 81/05/20 GRIER & H Region 1. Philadelphia. Office of the Director (81/03/01) ip 15823-001 24x Fiche 50-317,81/05/20,8210270274
- --B210270275 LER B1-033/04T-0 on B10506. during normal operation suts. operator discovered waste neutralizing Tank 12 drain valve leaking Caused by small amounts of particulate matter lodged between valve seat & wedge Valve flushed & closed Baltimure Qas & Electric Co 81/05/20 Region 1, Philadelphia, Office of the Director (B1/03/01) 2pp 15823 07; 24X Fichs 50-317,81/05/20,8210270274
- 8210270252 Forwards LER 81-030/03L-0 RUSBELL.t. B Baltimore Gas & Electric Co 81/05/22 QRIER B Region I. Philadelphia Office of the Director (81/03/01) ip 15827 231 24% Fichs 50-017,81/05/22,8210270252
- --8210270257 LER 81-030/03L-0 on 810424 reactor protection sys (hardontainment pressure trip unit & EBF actuation sys channel 2D containment pressure sensor placed out of syc to replace E/E convertor Isolator failure might be due to mod work a Baltimore Oas & Electric Co 81/05/22 Region 1, Philadelphia, 0ffice of the Director (81/03/01) ip 15629 20 24X Fichs 30-317,81/05/22,8210270252
- 8210270276 Forwards LER 81-031/01T-0 Detailed event analysis encl RUSSELL-L B Baltimore Oas & Electric Co 81/05/22 ORIER 9 H Region 1, Philadelphia. Office of the Director (81/03/01) 2pp 15828 282 24X Fiche 50-317,81/05/22.8210270272
- --B210270278 LER 81-031/01T-0 on 810518, both auxiliary bldg 10-ft elevation firs hose stations isolated w/o water supply. Caused by instructional error & operator unfamiliarity w/isolation valves Personnel counseled.

  # Baltimore Oas & Electric Co 81/05/22 Region L. Philadelphia. Office of the Director (81/03/01) ip 15828 2.4 24X Fichs 50-317,81/05/22,8210270276
- 8210270272 Forwards LER 81-031/03L-0 RUSSELL.L B Baltimore Cas & Electric Co 81/06/01 GRIER, # Ragion 1, Philadelphia, Office of the Director (81/03/01) 1, 15828-280 24% Fiche 30-317.81/06/01.8210270272
- ~-B210270273 LER 81-031/03L-0 on 810308 during attempt to put eserging siesel generator il back in svc after FCR 80-1013 installation, generator failed to reach rated speed Caused by sticking fuel racks & operating linkages Linkages repaired LAOJEHEKI, J S. HUSEBY, D E. Baltimore Oas & Electric Co. 81/06/01 Region in Philadelphia, Office of the Director (81/03/01), ip 15828 281 24X Fiche 50-317.81/06/01.821027%%
- 8210270244 Forwards LER 81-035/03L-0 Detailed event analysis end RUBBELL, L B Baltimore Oas & Electric Co Bi/O6/05 QRIER, 9 Region 2, Philadelphia, Office of the Director (81/03/01) 2; 15822 344. 24X Fiche 50-317, 81/06/05. 8210270244
- --B210270248 LER 81-035/03L-0 on 810506 one cell of 125-volt it virta chase battery 12 found below Tech Blee min. Cause unknown Cell disconnected & will be replaced # Battimore Cas & Electric Co. 81/06/05 Region 1. Philadelphia. Office of the Director (81/03/01) 19 (5922 34) 24X Fiche 50-317,81/06/05,8210270244.
- 8210090017 "Rept on Galvert Cliffs Unit | Loss of Svc Hater on 80028 | IMBRO,E.V | Director's Office. 81/12/31 | 40pp | 15669:007 | 41 | Fiche. 50-317.81/12/31.8210080017
- 8210040142 Forwards LER 82~051/03L=0 RUSSELL.L B Baltimore Oas & Electric Co. 82/07/24 KAYKS:Ef Region 1: Office of Director 1p 15583 085. 24% Fichs.50-317:82/09/24.8210040142.
- --B210040144 LER 82-051/03L-0. on 820827.plant air header isolatint mi inside containment.1-PA-1040. found open. Caused by valve being inadvertently left open while securing plant air to containment on 820822 Standing instruction issued LA01EMBKI. J. 8. Baltimore Qas & Electric Co 82/09/24 Rep. 1. Office of Director. 2pp 15583-086. 24x Fiche 50-317. 82/09/24,8210040142.

- 8210060385 Forwards LER 82-053/03X-1 & corrected Prompt Rept RO 82-53 Repts appropriate for Unit 1 only FUSSELLL B Baltimore Oas & Electric Co 82/09/27 HAYNES.R C Region 1. Office of Director 1p 15615 347 24X Fiche 50-317.82/09/27,8210060385
- -- 6210050390 LER 82-053/03.4-i on 620910, hydrogen analyzer D-AE-6519 adjusted out of callbr during initial training exercise, rendering unit inoperable Caused by erroneous adjustment step in chemistry procedure Procedure revised BILLS.J M Baltimore Gas & Electric Co 62/09/27 Region 1, Uffice of Director ip 15615 348 24X Fiche 50-317, 62/09/27, 62/09/28
- --8210050394 Corrected RO 82-53 on 820910, during Mode i operation, hydrogen analyzer unintentionally adjusted out of calibr, rendering unit inoperable Instrument recalibr & returned to wid Rept applicable to Unit i only RUSSELL. B. Baltimore Oas & Electric Co. 82/09/13 HAYNES, R. C. Region 1. Office of Director ip. 15615-349 24X Fiche 50-317.82/09/27.8210060385
- 8210130461 Forwards LER 82-056/03L-0 RUSSELL.L B Baltimore Qas & Electric Co 82/09/30 HAYNES.R C Region 1. Office of Director 1 p 15682 138 24X Fiche 50-317.82/09/30,8210130461
- --8210130465 LER 82-056/03L-0 on 920707, containment particulate & gaseous RMS tample pump tripped & would not restart Caused by failure of shaft coupling due to excessive wear created by corrosion of gump vanes Coupling replaced LAGIENSKI, J S. LUDWIO, P. G. Baltimore Qas & Electric Co. 82/09/30 Region; Office of Director ip 15692 139 24X Fiche 50-317,82/09/30.8210130461
- 8210130543 Forwards updated LER 82-023/01X-1 RUSSELL:L B Baltimore Gas & Electric Co 82/09/30 HAYNES:R C Region 6. Office of Director ip 15682 279 24X Fiche 50-317. 82/09/30.8210130543
- --8210130558 Updated LER 82-023/01X-1 on 820514.unplanned dilution of RCB in excess of 0.5% delta K/K experienced Caused by perforated six tubes in steam generator 11 % 1 tube in steam generator 12 Tube support plate rim cut HENDERLICH, R. L., JENNINGS, R. T. Baltimore Gas & Electric Co 82/09/30 Region 1. Office of Director 3pp 15682 280 24X Fiche 50-317,82/09/30.8210130543
- 8210130568 Forwards LER 82-054/03L-0 RUSSELL.L B Baltimore Qas & Electric Co 82/09/30 HAYNES,R C Region 1. Office of Director ip 15679 114. 24X Fitchs 50-317,82/09/30,8210130368
- -- B210130578 LER B2-054/03L-0 on B20B31.12 auxiliary feedwater pump governor linkage vibrated loose, rendering pump inoperable Caused by loose nut connecting governor lever to connecting rod backed off pin causing pin to come out Pin reinserted JUNGE.M A. L-MEUREUX.R W Baltimore Gas & Electric Co 82/09/30 Region 1. Office of Director 1p 15679 115 24X Fiche 50-317,82/09/30,8210130568
- 8210190290 Forwards updated LER 80-041/01X-1 RUSSELL,L B Baltimore Oas & Electric Co 82/10/06, HAYNES.R C Region 1. Office of Director ip 13742 172 24X Fichs 50-317,82/10/06,8210190290
- --B210190296 Updated LER B0-041/01X-1 on B00821,5 minutes after svc,water head tanks went from normal operating level to full.isophase bus duct cooling low flow alarm received Caused by air compressor failure due to cracked after cooler tubes DAVIS,8 M. HUSEBY.D E Baltimore Oas & Electric Co B2/10/05 Region 1. Office of Director 2pp 15742 173 24X Fiche 50-317,82/10/06,8210190290
- B210190730 RO on 820827. Ouster samples showed detectable levels of concentration of Ag-iiom Caused by natural tendency of caysters to concentrate environ silver Radioactive releases for first half of 1982 within allowable limits.
  FUHRMAN, G R. Baltimore Osa & Electric Co 82/10/11 HAYNES, R C Region i. Defice of Director 2pp 15736 270 24X
  Fiche 50-317, 82/10/11, 8210190730
- B210250154 Forwards LER 82-052/03L-0. RUSSELL.L. B Baltimore 0as & Electric Co 82/10/13 HAYNES:R C Region [, Office of Director p 15788, 230 24X Fiche 50-317, 82/10/13, 8210250154.

- --8210250160 LER 82-052/03L-0 on 820913 & 20. emergency diesel generator 11 failed to achieve required rom within 10-s Caused by losse connector on speed switch D-88-4848 Connector tightened & lock-wired PAVIS, 0 8 , BASSO, L F Baltimore Gas & Electric Co 82/10/13 Region 1, Office of Director 2pp 15788 231 24% Fiche 50-317,82/10/13.8210250154
- DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 8210180039 Forwards fee for 820830 Class III license amend request for relief from inservice insp program requirements FABRIZIO.R F Baltimore Cas & Electric Co 82/10/13 MILLER,W O License Fee Management Branch ip 15/20 020 24% Fiche 50-318,82/10/13,8210180039.
- F Security, medical, emergency & fire protection plans
- 8203050387 Forwards IE Insp Repts 50-317/82-02 & 50-318/82-02 on 820106-0202 & notice of violation. STAROSTECKIR Division of Project & Resident Programs 82/02/16 LUNDVALLA.E Baltimore Cas & Electric Co 2pp 12134 298, 24X Fiche 50-317, 82/02/16, 8203050387
- --82i0190714 IE Insp Repts 50-317/82-02 & 50-318/82-02 on 820104-0202 Noncompliance noted failure to adequately control special processes associated w/repair of saltuater piping & failure to properly neutralize regenerative waste ARCHITZELR & Division of Project & Resident Programs 82/02/12 1ipp 24X Fiche 50-317.82/02/16.8203050387
- 9210210544 Releases public version of revised emergency response plan implementing procedures
  FELFON. JM Division of Rules and Records 82/07/23 Document Management Branch 1p 15782 330 24X Fiche 50-317,82/07/23, 8210210544
- --8210210546 Forwards public version of revised emergency response plan implementing procedures, including Procedures EPIP 5 5 re exercises, test & drills & EPIP App B 2 re maps & charts # Baltimore Oas & Electric Co 82/09/15. CLARK.R A Operating Reactors Branch 3 ip 19782 331 24X Fiche: 50-317,82/09/23,801020984
- --8210210551 Public version of revised emergency response plan implementing procedures including Procedures EPIP 5 5 re exercises test & drills & EPIP App B 2 re maps & charts List of effective pages encl.

  # Baltimore 088 & Electric Co 82/09/15 20pp 15782 332 24x Fiche 50-317,82/09/23.8210210544
- 8210120134 Forwards third suppl to 790914 fire protection safety evaluation, resolving Item 3 2 1, "Fire Hazards Analysis "
  Ninety-day period to inform of installation schedule for source range flux monitoring instrumentation acceptable CLARK, R A. Operating Reactors Branch 3 82/09/27 LUNDVALL, A. E. Baltimore Gas & Electric Co. ip. 15492, 157 24X
  Fiche 50-317, 82/09/27, 8210120134
- --8210120137 Bafety evaluation concluding that proposed fire protection design meets requirements of App R to 100FR50, Items III 0.3 & III.L re safe shutdown in event of fire FIORAVANTE, M., MARRISONO 0. JAFFE. D Operating Reactors Branch 1. 82/09/27 9pp 15692/158 24X Fiche 50-317,82/09/27,8210120134.
- B210150423 Application for amend to Licenses DPR-53 & DPR-67 consisting of Revision 10 to security plan, allowing devitalization of vitel areas during cold outages Plan withheld (ref 100FR73 21)

  BOMMAKER, N J Baltimore Cas & Electric Co. 82/10/07 CLARK, R, A. Operating Reactors Branch 3 3pp. 15704, 021 24X

  Fiche' 30-317, 82/10/07, 82/0150423.
- 8210180005 Submits update of util progress in closing TMI Action Items I C.1.II F 1 & III.A.1 2 LUNDVALLA E. Baltimore Oas & Electric Co 82/10/12. CLARK.R.A. Operating Reactors Branch 3 3pp 13720 028 24X Fiche.50-317,82/10/12,8210180005
- P Operating license stage documents & correspondence
- 9210010008 Responds to FDIA request for 19 categories of documents remoclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL, R. A. Critical Mass Energy Project 15pp. 15727 005. 24X Fiche 50-000, 82/06/28, 8210010008

- --8204290048 Recommends prompt attention be given to problem of reactor coolent pump closure stud corrosion detected at facilities Response by 820415 requested EISENHUT.D 0 Division of Licensing 82/03/24 HANAUER.8 H Division of Systems Integration (post 811005) 3pp 66035 222 24X Fiche 50-000,82/06/28.8210010008
- 82:0080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON, J. H. Division of Rules and Records 62/07/12, UDELL, R A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000, 82/07/12, 8210080015
- --B210080064 Trip rept of 820207 visit to NRR in Bethesda.MD & B20208-10 site visit re installation of lo-inch automatic isolation valve in main feaduater sys Spec 6750-H-233 for nuclear carbon steel gaterglobe & check valves & related info encl BEARDEN.R Q E0040, Inc 82/03/22 47pp 15665 192 24X Fiche-50-000.82/07/12.8210080015
- 8010070106 Forwards Amends 75 & 56 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & motics of issuance & availability Amends correct typographical errors reinservice inespite type testing JAFFE D H Operating Reactors Branch 3 82/09/20 LUNDVALL.A E Baltimore Gas & Electric Co 3pp 15645.006 24X Fiche: 50-317.82/09/20,8210070106
- --8210070117 Amends 75 & 56 to Licenses DPR-53 & DPR-69, respectively. correcting typographical styrors re inservice insp & valve testing & allowing start up of reactors w/insperable but isolated power operated relief valves.

  CLARK.R A. Operating Reactors Branch 3 82/09/20 34pp 15645 007 24X Fiche 50-617.82/09/20.8210070106
- ~-B210070125 Safety evaluation supporting Amends 75 & 56 to Licenses BPR-53 & BPR-49, respectively JAFFE,D H Office of Nuclear Reactor Regulation, Director B2/09/24 4pp 15645.043 24X Fichs 50-317,82/09/20,9210070106
- ~~8210070130 Notice of issuance & availability of Amends 75 & 54 to Licenses DPR-53 & DPR-69, respectively CLARK, R A Operating Reactors Branch 3 82/09/20 2pp 13545 047 24X Fiche 50-317, 82/09/20, 8210070104.
- 8210270412 Forwards Amends 77 & 58 to Licenses DPR-89 & DFR-69, respectively, safety evaluation & notice of issuance & availability. Amends revise Tech Bpec Table 3 7-4 which lists snubbers that require periodic insp & testing JAFFE, D H Operating Reactors Branch 3 82/09/29 LUNDVALL: A E Battimore Oas & Electric Co Spp. 15869, 273 RAX Fiche 50-317, 82/09/23.8210290412
- --8210290428 Amends 77 & 58 to Licenses DPR-58 & DPR-69, respectively, revising Tech Spec Table 3 7-4 which provides lists of safety-related hydraulic shock suppressors (snubbers) which require periodic insp & tasting CLARK, R A Operating Reactors Branch 3, 82/09/23 26pp 13863:276 24X Piche, 50-017, 82/09/23,8210290412
- --8210290439 Safety avaluation supporting Amends 77 & 58 to Licenses DPR-53 & DPR-69, respectively \* Offics of Nuclear Reactor Regulation, Director, 82/09/23 Spp 15863-302 24% Fichs 50-217.02/09/23.0210290412.
- --8210290444 Notice of issuance & availability of Amenda 77 & 58 to Licenses DPR-58 & DPR-69:respectively CLARK, R A. Operating Reactors Branch 3. 82/09/23 2pp 15863.305. 24X Fiche 50-317.82/09/23.8210390412.
- 8210130338 Application to amend Licenses DPR-53 & DPR-69, revising Teck Specs re pressuriter limiting condition for operation & associated surveillance requirements.

  LUNDVALL: A E. Beltimore Cas & Electric Co. 82/09/27. CLARK: R. A Operating Reactors Branch 3, 3pp. 15680 268, 24X

  Fiche: 50-317, 82/09/29, 8210130338
- --8210130342 Proposed Tech Specs 3 4 4 4 4.4 re RCS pressurizer.

  \* Beltimore Qas & Electric Co. 82/09/29. 44pp. 15680.271. 24x
  Fiche: 50-317,82/09/29.8210130338
- 8210150423 Application for amend to Licenses DPR-53 & DPR-69 consisting of Revision 10 to security plansallowing devitalization of vital areas during cold outages, Plan withheld (ref 10CFR/3, 21)
  BOWMAMER.N.J. Baltimore Cas & Electric Co. 82/10/07, CLARK.R A. Operating Rectors Branch 3 Sps 15704:021 24X
  Fiche: 50-317, 82/10/07, 8210150423,

- 8210180005 Submits update of util progress in closing THI Action Items I C 1.II.F 1 & III A 1 2 LUNDVALL.A E Baltimore Gas & Electric Co 82/10/12 CLARK.R A Operating Reactors Branch 3 3pp 15720 028 24X Fiche 50-317.82/10/12,8210160005
- 8210220378 Application to amend License DPR~69, changing 878 for operation of Cycle 5 at rated power of 2,700 MWt LUNDVALL.A E. Baltimore Gas & Electric Co 82/10/15 CLARK.R & Operating Reactors Branch 3 2pp 19760 017 24x Fiche 50-318.92/10/15.8210220378
- --8210220385 Proposed STS changes for Cycle 5 operation at rated proposed 2.700 HWt 
  \* Baltimore Oas & Electric Co 82/10/15 152pp 15780 024 24; F(che 50-318,82/10/15,8210220378
- 821020010B Notification of 821025 meeting w/util in Dethesda, MD to discuse control of heavy loads JAFFE, D H Operating Reactors Branch 3 82/10/18 CLARK, R A Operating Reactors Branch 3 2pp 15767 304 24X Fithe \$0-317, 82/10/18, 821020010B
- 8210260299 Forwards Cycle 5 reload amend fee LIPPOLD,W J Baltimore Oas & Electric Co 82/10/21 CLARK,R & Operating Reactors Branch 3 ip 15803 211 24X Fiche 50-318.88/10/21.8210260299
- Q Inspection reports, IE Bulletins & correspondence
- 82030503B7 Forwards IE Insp Repts 50-317/82-02 & 50-318/82-02 en 820106-0202 & motice of violation STAROSTECKI.R Division of Project & Resident Programs 82/82/16 LUNDVALL, A E Baltimore Oas & Electric Co 2pp 12134 298 241 Fiche 50-317, 82/02/16, 8203050387
- --8210190702 Notice of violation from insp on 820104-0202 STAROBTECKI.R Division of Project & Resident Programs 82/02/16 2pp 15751 022 24X Fiche 50-317.82/02/16.8203050387
- --8210190714 IE Insp Repts 50-317/82-02 & 50-318/82-02 on 820104-022 Noncompliance noted failure to adequately control special processes associated u/repair of saltwater piping & failure to properly neutralize regenerative waste ARCHITZEL,R E , MCCABE,E C Division of Project & Resident Programs 82/02/12 iipp 15751 024 24% Fiche 50-317.82/02/16 8203050387
- 8210060099 Forwards IE Insp. Repts 50-317/82-06 & 50-318/82-06 pn 820318-16 & notice of violation, MARTIN.T.T Division of Engineering & Technical Programs 82/0° LUNDVALL.A,E Baltimore Oas & Electric Co 2pp 15614 345 ; Fiche 50-317, 82/07/17, 82/0060099
- --8210060104 Notice of violation from insp on 820315-16 \* Division of Engineering & Technical Programs 82/09/17 2, 15614 347 24X Fiche 50-317, 82/09/17, 8210060099
- --8210060127 IE Insp Repts 50-317/82-06 & 50-318/82-06 on 820315-16 Noncompliance noted failure to establish adequate procedures; failure to follow radiation protection procedures & failure to make necessary radiological surveys PLUMILEE.K E., GREENMAN.E. O Division of Engineering & Fethnice Programs. 82/09/17 10pp 15614 349 24X Fiche 50-317.82/07 8210060099
- 8210070106 Forwards Amends 75 & 56 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability. Amends correct typographical errors reinservice insp & valve testing.

  JAFFE, D. H. Operating Reactors Branch 3 82/09/20 LUNOVALLAF Baltimore Oas & Electric Co. 3pp. 15645-006 24X Fiche: 50-317, 82/09/20, 8210070106
- --B210070117 Amends 75 & 36 to Licenses DPR-53 & DPR-69, respectively correcting typographical errors re inservice insp & valve testing & allowing start up of reactors w/inoperable but isolated power operated relief valves CLARK, R A. Operating Reactors Branch 3 B2/09/20 1466 19645 007. 24X Fiche. 50-317, 82/09/20. B210070104
- B210150214 Forwards IE Insp Repts 50-317/82-23 & 50-318/82-19 en 820810-0914 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 63/09/27 LUNDVALL, A E. Baltimore Gas & Electric Co 2pp 15705 234 211 Fiche: 50-317, 62/09/27, 621015021
- --8210150226 Notice of violation from insp on 820810-0914 # Bivision of Project & Resident Programs. B2/09/27, 291 15705-236 24X Fichs: 80-317, B2/09/27, B210150214

- --8210150235 IE Insp Repts 50-317/82-23 & 50-318/82-19 on 820810-0914 Moncompliance noted radiological event not declared nor appropriate response taken & procedures not properly implemented ARCHITZEL,R E , TRIMBLE,D C., MCCABE,E C Division of Project & Resident Programs 82/09/27 18pp 15705 238 24X Fiche 50-317,82/09/27,8210150214
- B210060240 Forwards notice of violation re IE Insp Repts 30-317/82-07 & 50-318/82-07 on 820413-0511 Violation A re operation whydrogen analysers inoperable needs no response Violation B re inadequate review requires full response STAROSTECKI.R Division of Project & Resident Programs 82/07/29 LUNGVALLA E Baltimore Gas & Electric Ca 3pp 15619 322 24X Fiche 50-317.82/09/29,8210060240
- 6210070159 Requests approval for excluding reactor vessel closure stude at facilities.per IE Bulletin 82-02 & Reg Outde 1 65
  Bolting matl complies w/recommended matls
  LU/IDVALL, A E Baltimore Gas & Electric Co 92/10/01 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 13527 013 24X Fiche 50-317, 82/10/01, 8210070159
- B209190233 (E Info Notice 80-35, Buppl 1, "Leaking & Dislodged I-125 Trplant Beeds " But list encl G08B.L I Division of Fuel Factlities, Materials & Safeguards 82710706 Consolidated Edison Co of New York 66pp 15761 250 24x Fiche 50-000.82/10/06.8208190233
- B210130099 Ack receipt of 820917 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-317/82-20 & 50-318/82-17 MARIEN.TT Division of Engineering & Technical Programs 82/10/06 LUNDVALL.A E Baltimore 0as & Electric Co ip 19673 i04 24X Fiche 50-317,82/10/06.8210130099
- --B21013010G Responds to NRC B20B19 ltr re violations noted in IE Insp Repts 50-317/82-20 & 50-319/82-17 Corrective actions Operating Instruction.AD Procedure 2 & Instruction 302 revised UNIDVALL.A E Baltimore Gas & Electric Co 82/09/17 MARTIN.T T Division of Engineering & Technical Programs 4pp 15673 105 24X Fithe 50-317.82/10/06.8210130099
- 6210190797 Ack receipt of 820915 ltr informing NRC of steps taken to correct violations mated in IE Insp Repts 50-317/82-18 & 50-318/82-14 Accepted to the standard of Project & Resident Programs 82/10/12 LUMBVALL, A E Baltimore Gas & Electric Co ip 15736 314. 24X Fiche 50-317, 82/10/12, 8210190797
- ---8210190803 Responds to NRC 820816 ltr re violations noted in IE Insp Repts 50-317/82-18 & 50-318/82-16 Corrective actions Instruction-112 rovised to ensure essential equipment will not be inadvertently removed from svc FTI-107 also revised. LUNDVALL.A E Baltimore Gas & Electric Co 82/09/15 STAMOSTECKI,R Division of Project & Resident Programs 2pp 15736 315 24X Fiche 50-317, 82/10/12,8210190797
- 82:0188039 Forwards for 820830 Class III license amend request for relief from inservice insp program requirements. FABRIZIOLR F Baltimore Gas & Electric Co 82/10/13 MILLER, W O License Fee Kanagament Branch ip 15720 020 24X Fische 50-318,82/10/13,8210180039
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hail, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BMR Plants "Svc list enci DEYQUNO.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 128 24X Fiche 50-000,82/10/14,8208190238
- A Periodic operating reports & related correspondence
- 8210210328 Forwards monthly operating repts for Sapt 1982 LOTITO,E M Baltimors Oas & Electric Co 82/10/15 Director's Office, Office of Inspection and Enforcement 1p. 15762 003 24X Fichs 50-317,82/10/15,8210210328
- -- 6210210457 Monthly operating repts for Sept 1982 LOTITO, E Baltimore Cas & Electric Co. 92/10/15. 10pp 15762 004 24X Fiche 50-317, 82/10/15, 8210210328
- S. Reportable occurrences, LERs & related correspondence
- B210280194 Forwards LER 81-014/03L-0 RUSSELL, L B Baltimore Oas & Electric Co 81/04/03 GRIER, B H. Region 1, Philadelphia, Office of the Director (81/03/01) 1p. 15837-030 24X Fiche 50-318.81/04/03.8210R80194

- --8210280200 LER 81-014/03L-0 on 810305,4-kV buses 21 & 24 ESF actuation sys degraded voltage relays found out of calibr Cause unknown Trip setpoints readjusted Relays will be tested at increased frequency DAVIS,9 M. RIZIO.P O Baltimore Das & Electric Co 81/04/03 Region 1. Philadelphia. Office of the Director (81/03/01) 2pp 15837 031 24x Fichs 50-318,81/04/03,8210280194
- 8210280277 Forwards LER 81-013/03L-0 RUSSELL,L B Baltimore Gas & Electric Co B1/04/03 GRIER, B H Region 1. Philadelphia, Office of the Director (81/03/01) 1p 15837 044 24x Fiche 50-318.81/04/03.8210280279
- --8210280284 LER 81-013/03L-0 on 810304, while installing instrumentation, temporary shunt opened, causing loss of power to low pressure safety injection pump 22 k momentary loss of shutdown cooling flow Caused by opened lead on one end of shunt WENDERLICH, R L RIZZO, P B Baltimore Oas & Electric Co B1/04/03 Region I. Philadelphia, Office of the Dir.ctor (81/03/01) 2pp 15837 045 24X Fiche 50-318,81/04/03. R210280279
- 8210280191 Forwards LER 81-012/03L-0 RUSSELL,L B Baltimore Gas & Electric Co Bi/04/08 GRIER, B H Region I, Philadelphia, Office of the Director (81/03/01) 1p 15837 064 24X Fiche 50-318,81/04/08,8210280191
- --B210280175 LER 91-012/03L-0 on 810309, while personnel were exiting containment bldg via hormal personnel hatch, both doors were open simultaneously Caused by broken cam follower in door operator Maint on clutches incorporated into procedures \* Baltimore Gas & Electric Co 81/04/08 Region 1, Philadelphia, Office of the Director (81/03/01) 2pp 15837 045 24X Fiche 50-318,81/04/08,8210280191
- 8210280336 Forwards LER 81-015/03L-10
  RUSBELL.L B Baltimore Cas & Electric Co 81/04/17 ORIER.B H
  Region i, Philadelphia, Office of the Director (81/03/01) 1p
  19838 324 24X Fiche 50-318,81/04/17.8210280336
- --B2102B0341 LER B1-015/03L-O on B10319, results of routine sample of boric acid storage tank 21 revealed boric acid concentration greater than Tech Bpec limit, reducing borated warer sources to one Cause undetermined

  # Baltimore Oas & Electric Co 81/04/17 Region 1.
  Philadelphia, Office of the Director (81/03/01) 2pp 15838 325 24X Fiche 50-318,81/04/17,8210280336
- 8210270237 Forwards LER 81-022/03L-0 RUSSELL,L B Baltimore Cas & Electric Co 81/05/15 QRIER, B H Region i, Philadelphia, Office of the Director (81/03/01) 1p 15828 275 24X Fiche 50-318,81/05/15,8210270237
- --8210270241 LER 81-022/03L-0 on 810419, during power increase, containment gaseous & particulate radioactivity monitoring sys sample failed Caused by broken motor coupling Motor coupling replaced

  Baltimore Qas & Electric Co 81/05/15 Region 1.
  Philadelphia, Office of the Director (81/03/01) 2pp 15828 276 24% Fiche 50-318,81/05/15,8210270237
- 8210040216 Forwards LER 82-042/03L-0 RUSSELL,L B Baltimore Gas & Electric Co 82/09/23 HAYNES;R C Region 1, Office of Director 1p 15586 132 24X Fiche. 50-318. 82/09/23. 8210040216
- --8210040226 LER 82-042/03L-0 on 820824, inner door on normal personnel hatch to containment would not shut completely Caused by broken cam follower to handwheel Inner door repaired Matis upgraded WENDERLIGH, R.L., WEIR, P.J. Baltimore Gas & Electric Co. 82/09/23 Region 1, Office of Director 1p 15586 133 24X Fiche 50-318,82/09/23,8210040216
- 9210040066 Forwards LER 92-041/03L-0 RUSSELL,B Baltimore Gas & Electric Co 82/09/24 HAYNES,R C Region 1, Office of Director 1p 15581 235 24X Fiche 50-318, 82/09/24, 8210040066
- --8210040069 LER 82-041/03t-0 on B20826, excessive leak rate discovered past containment personnel air lockout & door gasket. Caused by decrease in force holding door shut Door operating mechanism adjusted to increase pressure

  JUNGE, M. A. Baltimore Gas & Electric Co. 82/09/24 Region 1,
  Office of Director 1p 15581, 236, 24X Fiche, 50-318, 82/09/24,
  8210040066.
- 8210040211 Forwards LER 82-040/03L-0 RUSSELL,L. B Baltimore Qas & Electric Co B2/09/24 HAYNES,R C Region 1, Office of Director ip 15587.177 24X Fichs. 50-318, 82/09/24, 8210040211

- --8210040219 LER 82-040/03L-0 between 820825 t 26, pressuriter level deviated slightly from program level by more than 5% during normal startup operations Caused by loading of main turbins generator.RCS temp swings of 10 degrees not uncommon UNIGE.H A . WEIR.F J Baltimore Cas tellectric Co 82/09/24 Region 1. Office of Director. ip 15587 178 24% Fiche 50-318,82/09/24.8210040211
- 8210190730 RO on 820827, ogster samples showed detectable levels of concentration of Ag-110m Caused by natural tendency of ogsters to concentrate environ silver Radioactive releases for first half of 1982 within allowable limits FUHRMAN, G R Baltimore Gas & Electric Co. 82/10/11 HAYNES, R C Region 1. Dffice of Director 2pp 15736 270 24X Fiche 50-317, 82/10/11, 8210190730
- 8210250088 Forwards LER 82-044/03L-0 RUSSELL,t. B. Baltimore Gas & Electric Co 82/10/15 HAYNES.R C Region i. Office of Director 1p 15787 058 24X Fiche 50-318.82/10/15.9210250089
- --8210250095 LER 82-044/03L-O on 820915, emergency dissel generator 21 tripped during testing Caused by common low jacket cooling water pressure switch isolation valve left closed following maint Valves opened PAVIS, G S , BASEG, L F Baltimore 0as & Electric Co B2/10/15 Region 1, Office of Director 2pp 15787 059 24X Fiche, 50-318, 82/10/15, 8210250088
- 8210280134 Forwards LER 82-046/03L-0 RUSSELL,L B Baltimore Cas & Electric Co. 82/10/20 HAYNES,R C Region i, Office of Director 1p 15837 239 24X Fiche 30-0318.8210/20,8210280134.
- --8210280141 LER 82-044/03L-0 on 820920, reactor protective sys channel C trip unit for high pressurizer gressure tripped due to failed low trip bistable power supply, Model DRA15-750/15-7508 Cause unknown Power supply replaced LAOIENSKI, J B. RAYNOR, J W. Baltimore Qas & Electric Co 82/10/20 Region 1. Office of Director 1p 15837 240 24X Fiche 50-318, 82/10/20, 8210280134
- DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8210050491 Forwards exemption from annual emergency plan exercise requirements of 10CFR50.App E re level of govt participation STOLI, J F Operating Reactors Branch 4 82/09/14 HUKILL, H D Ceneral Public Utilities OPU Bervice Corp. 7pp 15626 291 PAX Fiche 30-289.82/09/14.8210050491.
- --B210050495 Exemption from annual amergency plan requirements re level of govt participation in exercises ETSEMHUT. D. Division of Licensing B2/09/14. General Public Utilities - QFU Service Corp 4pp 15626 298 24X Fiche: 50-289, 82/09/14, 8210050491
- 8210190180 Notification of contract execution "TMI-2 Fire Protection Evaluation," awarded to Rolf-Jensen & Associates, Inc. FLEEMOR. C. Technical Assistance Contracts Branch FIN B-8632 82/09/29 VOLLMER, R H , NOLAN, F Division of Engineering. If 15758:118 24X Fiche: 50-320, 82/09/29, 8210190180
- --8210190185 Contract, "TMI-2 Fire Protection Evaluation," awarded to Rolf Jensen & Associates, Inc. WEBB.44 A Rolf Jensen & Associates, Inc. MATTIA.M J. Technical Assistance Contracts Branch, FIN B-8632 B2/09/29, 8pp. 15758:119. 24X Fiche, 50-320, 82/09/29, 8210190180

# O Adjudicatory correspondence

- 8210040021 Notice of withdrawal of appearance in proceeding. LEMIS:8 H Hearing Branch 2 82/09/29. 2pp 15581:260. 24X Fiche 50-320,82/09/29.8210040021.
- B2i0i50486 Motion to modify Tech Boscs formally to conform w/B20924 amend of NRR Director 800211 order-allowing separation of fuel handling bldg air cleanup exhaust sys & suxiliary bldg air cleanup exhaust sys & suxiliary bldg air cleanup exhaust sys Acceptable of Sec. MILCOVE: N N Hearing Branch 2 82/10/14. Atomic Safety and Licensing Board Panel. 170p 18714 193 24X Fiche. 50-320.82/10/14. 8210150486

- 8210210266 Response to NRC 821014 motion to conform proposed Tech Spattached to NRR 800211 order w/820924 amend to order Licensee does not oppose motion, assuming formal amend awaits outcome of prospective hearing W/Certificate of Syc RIDONAY, D.A. Metropolitan Edison Co. RIDONAY, D.A. Shaw, Pitterpotts & Trowbridge 82/10/18. Atomic Safety and Licensing Boar Panel 5pp. 15766 232 24X Fiche 50-320, 82/10/18, 8210210266
- B210210173 Motion to extend period of time for Commission to review ALAB-672 Certificate of Svc encl TROUBRIDGE.0 F Metropolitan Edison Co TROUBRIDGE.0 F Shaw. Pittman. Potts & Troubridge B2/10/20 Commissioners 4pp 15766
- --8210210177 Request for extension to 821115 to file motion for reconsideration & mod of 820715 ALAB-672 Certificate of Swc encl TROMBRIDGE, O.F. Hetropolitan Edison Co. Pittman. Potts & Troubridge 82/10/20 Atomic Safety and Licensing Appeal Panel 5pp 15766 064 24X
- B210220313 Order granting util B20914 request for leave to file petition for reconsideration of portion of ALAB-692 sub; to Commission granting util B20914 request to extend period for sua sponts review TOMPXINS.B A Atomic Bafety and Licensing Appeal Panel B2/10/20 Hetropolitan Edison Co 2pp 15776 177 24X Fichs 50-320, B2/10/20-B210220313
- 8210270174 Memorandum & order granting NRC motion to conform propose. Tech Specs to NRR Director 820924 order amending 800211 order, separating fuel handling bldg air cleaning exhaust sys & auxiliary bldg air cleanup exhaust sys Tech Specs WOLF, J. F., PARIS, O. H., SHON, F. J. Atomic Safety and Licensing Sear. Panel 82/10/25 Office of the Executive Legal Director 3pp 15823 011 24X Fiche 50-320,82/10/25,8210270176
- 8210270170 Order extending time until 821112 for Commission to act to review ALAB-692 CHILK.S. J. Office of the Secretary of the Commission 82/10/28 Commissioners ip 15822 348 24X Fiche 50-320.82/10/26, 8210270170
- J Insurance & indemnity information
- 8210150147 Forwards Endorsements 53 & 54 to MAELU Policy HF-73 & Endorsements 61 & 62 to NELIA Policy NF-220 GERETY, HF General Public Utilities OPU Service Corp 82/10/v1 SALTZMAN, J Antitrust & Economic analysis Branch (Utility Finence) 5pp 15697 359 24X Fiche 50-289, 82/10/07, 8210150147
- P Operating license stage documents & correspondence
- 8210050466 Requests installation of speakerphone at THI info ofc KERR V S Telecommunications Branch 80/01/30 ACCARDO, V 8+11: Pennsylvania ip 15625-236 24X Fiche 50-320-80/01/30.82105648
- 8210080061 Comments on info gleaned from preoperational testing legics entries of 770905-12 Installation of reactimeter in all plants prior to startup testing suggested Logbook entries and I ORNSTEIN, H L Director's Office 81/07/16 Director's Office 25pp 15669 326 24% Fiche 50-320.81/07/16.8210080061
- 8210120406 "Recently Evaluated Preoperational Test Precursor of Mi-1 Accident," for presentation at ANS 1982 Power Div Topical Meeting in Charleston, 8C, 820328-31 ORNSTEIN, H. L. Director's Office. 82/03/31 24pp. 15691 143 2U Fiche 50-320, 82/03/31, 8210120406.
- 8210Q10D0B Responds to FOIA request for 19 categories of decuments nuclear reactor syents & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL.R & Critical Mass Energy Project 15pp 15727.005. 24X FIChe 50-000, 82/06/28, 8210010008.
- 8210060473 Requests submittal of implementation schedules for completing removal of EPICOR-II prefilter & submerged demineralizer sys ion exchange wastes, for defueling reactor core & for removal of reactor coolant wastes DENTON, H. R. Office of Nuclear Reactor Regulation, Directed 82/07/08 ARNOLD, R. C. General Public Utilities GPU Service (F) 3pp. 15636-220 24X Fiche 50-320,82/07/08,8210060473.
- 9210050537 Speech entitied, "Regulatory Aspects of TMI Cleanus" LO.R., BELLAMY.R. TMI Program Office. 82/09/20, 6pp. 15537:44 24X Fiche: 50-320, 82/09/20, 8210050537

- S210260535 Forwards amend of order, safety evaluation & proposed Tech Specs Amend changes Tech Specs to allow for operations to prepare for recovery mode activities SMYDER, B. J. TMI Program Office 82/09/24 KANGA, B.K. General Public Utilities - GPU Service Corp. 2pp. 15830-333 24X Fische 50-320, 82/09/24, 8210260535
- ~~ E210260538 Amend of order changing Tech Specs to define which equipment would provide adequate ventilation capability for fuel headling & auxiliary bldgs
  CASELE Q Office of Nuclear Reactor Regulation. Director 82/09/24 General Public Utilities OPU Service Corp App 15820 335 24X Fiche 50~320.82/09/24.8210260535
- ~~8210260547 Safety evaluation supporting Tech Specs change defining equipment to provide adequate ventilation capability for fuel handling & auxiliary bldgs

  # Office of Nuclear Reactor Regulation, Director 82/09/24 5pp \$15830 339 24X Fiche 50-320,82/09/24,8210260535
- ~~B210260552 Proposed Tech Spec changes re fuel handling auxiliary bldg air ventilation ileanup sys → Office of Nuclear Reactor Regulation, Director 62/09/24 3pp 15930 344 24X Fiche 50-320.82/09/24.8210260535
- 8210270328 Informs that proposal to conduct extended decontamination effort acceptable Procedures used to implement decontamination effort subj to approval Rationale for approval & discussion of evaluation encl SN/DER.8 J THI Program Office 82/09/24 KANGA.8 K General Public Utilities GPU Service Corp 7pp 15834 351 24X Fiche 50-320.82/09/24.8210270328
- 8210190052 Requests attendance at 820928 meeting to discuss actions to obtain actual RCS gas space info & future plans for establishing inert gas atmosphere in drained RCS portions which need not be vanted BARRETT.L H TMI Program Office 82/09/27 KANGA,8 K General Public Utifities 09V Service Corp 2pp 15761 044 24X Fiche 50-320, 82/09/27, 8210190052
- 8210040200 Informs of newly established dairy farm yielding calculated dose or dose commitment greater than several farms currently monitored by land use census Farm added to radiological monitoring program KANGA.8 K Oeneral Public Utilities OPU Service Corp 82/09/28. SNYDER,8 J TMI Program Office ip 15583 163 24X Fiche 50-320.82/09/28.8210040200
- 8216070220 Advises of installation of pressure relief device for longterm storage of spent submorged demineralizer sys liner vent hoses KANGA. 8 K. General Public Utilities - GPU Service Corp. 82/10/04 BARRETT. L. H. TMI Program Office. 2pp. 15697-161. 24X Fiche 50-320, 82/10/04:8210070220
- B230070365 Notifies of planned operations which will cause containment waste uater inventory to exceed 50,000 gallons in response to MRC 820420 itr KANGA.B K Deneral Public Utilities QPU Service Corp. 82/10/04 BARREIT, L M TMI Program Office ip 15634 035 24X Fiche 50-320,82/10/04.8210070365
- B210130583 Revision i to Recovery Operations Plan Change Request
  18. Revision will permit opening of both equipment hatch
  airtock doors in order to allow excessive length tools &
  equipment to be transported into containment
  KANNOA:8 K General Public Utilities GPU Service Corp
  BARRETTL H TMI Program Office 12pp 15679 063 24X
  Fiche 50-320, 62/10/06, 6210130583
- --B2101305B4 Tech Spec 4 6 1 re primary containment integrity - General Public Utilities - GPU Service Corp 82/10/06. 2pp 15879 075 24% Fiche 50-220, 82/10/06, B2101305B3
- B210150043 Provides results of sampling program to determine RCS hydrogen evolution, in response to 820927 ltr Based on preliminary evaluation, combustible gas mixture will not occur in loop high points in foresseable future KANGA: B K Deneral Public Utilities GPU Service Corp B2/10/08 BARRETT, L H THI Program Office 3pp 15701 129 24X F1che: 50-320, 82/10/08,8210150043

- 8210150085 Forwards polar crans functional description & response to Item 4 of 820401 ltr re crane maint Checklist of specific items for crane maint to be evaluated KANDA:B K General Public Utilities GPU Service Corp 82/10/12 BARRETT,L H TMI Program Office. 27pp 15701 214 24X Fiche 50-320, 82/10/12.8210150085
- 8210190570 Ferwards Revision 0 to "Safety Evaluation for Submerged Demineralizer Sys Liner Recombiner & Vacuum Outgassing Sys "
  Sys satisfactorily tested by Rockwell Hanford Operations KANGA, I K General Public Utilities GPU Service Corp 82/10/13 BARRETT, L H TMI Program Office 2pp 15736 103 24X Fiche 50-320, 82/10/13; 8210190570
- --8210190577 Revision 0 to "Safety Evaluation for Submerged Demineralizer Sys Liner Recombiner & Vacuum Outgassing Sys " « General Public Utilitie» - OPU Service Corp 82/10/31 7pp 19736 105 24% Fiche 50-320, 82/10/13,8210190970
- 8210200012 Advises of status of EPICOR prefilter liner inserting Analyses indicate that hydrogen generator rate can be adequately determined for nonarrtight liners by concentration of hydrogen at initial sampling & leak rate KANGA: B K General Public Utilities GPU Service Corp 82/10/14 BARRETT, L H TMI Program Office 2pp 15752 328 24X Fiche 50-320, 82/10/14,8210200012
- O Inspection reports, IE Bulletins & correspondence
- 8210260225 Ack receipt of 820902 itr in response to violations noted in IE Insp Rept 50-320/82-06 Info not previously available to inspector during insp Recent investigation revealed new facts that could after item of noncompliance STAROSTECKI, R Division of Project & Resident Programs 62/09/28 KANOA, B K General Public Utilities OPU Service Corp. 2pp 15830 347 24X Fichs 50-320,82/09/28,8210260225
- --B210260236 Responds to NRC B20730 ltr re violations noted in IE Insp Rept 50-320/82-06 Apparent violation re broken lid holddown ring on drum happened during transport Util not responsible KANOA.3 K General Public Utilities - OPU Service Corp B2/09/02 HAYNES,R C Region i, Office of Director 4pp 15830 351 24X Fiche 50-320,82/09/28,8210260225.
- B20B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-128 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards B2/10/06 Compolidated Edison Co. of New York 66pp. 15761 250 244 Fichs 50-000, B2/10/06, B208170233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Syc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche: 50-000, 82/10/14, 8208190238
- R. Periodic operating reports & related correspondence
- 8210070063 Forwards TMI Program Ofc weekly status rept for wk of 820829-0903 BARRETT.L.H TMI Program Office. 82/09/03 DENTON.H R. Office of Nuclear Reactor Regulation. Director SNYDER.D.J TMI Program Office 8pp. 15649 186 24X Piche: 50-320.82/09/03.8210070063
- 82:0070:50 Forwards THI Program Ofc weekly status rept for wk of 820704-11. BARRETT, L H THI Program Office, 82/07/13 DENTON, H. R. Office of Nuclear Reactor Regulation, Director SNYDER, B. J THI Program Office opp. 15644-359, 24X Fiche, 50-320, 82/07/13, 82:0070150
- 8210190127 Forwards TMI Program Ofc weekly status rept for wk of 820912-18. BARRETT, L. H TMI Program Office 82/09/20, DENTON, H. R. Office of Nuclear Reactor Regulation, Director 7pp 15741:230 24X Fiche 50-320, 82/09/20, 8210190127
- 8210190012 Forwards TMI Program Ofc weekly status rept for wk of 820919-25.
  8ARRETT, L. H. TMI Program Office 82/09/27. DENION, H.R. Office of Nuclear Reactor Regulation. Director 7pp. 15760:321 24% Fiche 50-320, 82/09/27, 8210190012
- 8210070226 Forwards results of program to detect radioactive water leakage to groundwater at facility. Data includes computer graphs of britium concentrations, computer tables of gamma scan data & first & second quester strontium results KANGA. B K. General Public Utilities GPU Bervice Corp 82/10/06 BARRETT, L.H THI Program Office 40pp. 15634:308 24X Fiche: 50-320, 82/10/06,8210070226.

- S Reportable occurrences. LERs & related correspondence
- BO12290118 Discusses conclusions of engineering evaluation of steam generator querfill transients at 6-E & Hestinghouse plants LANKING!N D Director's Office 80/10/29 MICHELSON.C Director's Office 3pp 15692 262 24X Fichs 50-000.80/10/29.8012290118
- 8210150280 Forwards LER 81-013/01L-0 HOVEY.O X Metropolitan Edison Co 81/08/08 QRIER.B H Region I, Philadelphia. Office of the Director (81/03/01) ip 15701 340 24% Fiche 50-320,81/08/08.8210150280
- --B210150289 LER 81-013/01L-0 on 810508, incore thermocouple L11 exhibited erratic behavior Cause undetermined due to condition of incore anstrumentation Condition monitored to determine long-term effect on safety CHAPLIN.8 D Hetropolitan Edison Co 81/06/05 Region 1, Philadelphia, Office of the Director (81/03/01) 2pp 18701.341 24X fiche 50-320, 81/06/08.8210150280
- 8210080024 Forwards chronology of 770905-12 events in which steam bubble formed during preoperational testing GRNSTEIN.H L Director's Office 81/07/08 MICHELSON.C Director's Office 9pp. 15669 294 24X Fiche 50-320.81/07/08, p21089024.
- 8210010008 Responds to FDIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A
  FELTON. J M Division of Rules and Records 82/06/28 UDELL.R A
  Critical Mass Energy Project 15pp 15727 005 24X
  Fiche 30-000, 82/06/28, 8210010008
- --B210010161 Discusses patential problem re-sequeyah reactor pressure norrie.supplementing 800222 memo Undercled Cracks found by use of ultresonic equipment Additisems of recent origin discussed Related info enci DENTON, H.R. Office of Nuclear Reactor Regulation, Director 80/02/28 AMERANE, J. Commissioners 9pp 15727 178 24X Fiche 50-000, 82/06/29, 8210010008
- --B210040374 Forwards LER 80-20/03L & R0 269/80-9 re failure to open auriliary feedwater valve & failure of fire detection sys, respectively Addi attention may be warranted BENDER, M. ACRS Advisory Committee on Reactor Safeguards 80/05/23 FRALEY,R F ACRS Advisory Committee on Reactor Safeguards 1p 19727 272 24X Fiche. 50-000, 82/06/28, 8210010008
- --B210050161 Forwards add1 info re events at facility during preoperational testing on 770905-12 Failure of condensate polishers caused resin to clog strainers from closed cooling water pumps
  ORNBTEIN.H L Director's Office 81/07/08 MICHELSON.C
  Director's Office 9pp. 15729 346 24X Fiche.50-000,82/06/28,8210010008.
- --8210060460 "Recently Evaluated Preoperational Test Precursor of TM1-2 Accident," presented at ANS 1982 Power Div topical meeting on 820328-31 ORNSTEIN.H L Director's Office 82/03/28, 24pp 15745 049 24X Fiche 50-000,82/04/28,8210010008.
- 6210070265 PNO-TMI-82-020 on B21005 game poather apprehended on util property it turned over to state police & Game Commission. No vital areas threatened Security increased Licensee will issue press release

  MIEBE. J. BELLAMY.R Region 1, Office of Director 82/10/06 ip 15624 306 24% Fichs 50-289,82/10/06:8210070265.
- 8210280124 LER 82-008 has been canceled. COLLINS:M General Public Utilities - OPU Service Corp. 82/10/19. Region 1. Office of Director. 1p 15837.021. 24X Fiche 50-320.82/10/19.8210280124
- 8210280127 LER 82-002 has been canceled COLLINS.M Opneral Public Utilities OFU Service Corp. 82/10/19. Region 1. Office of Director. 1p 15837 023 24X Fiche 50-320.82/10/19.8210280127.
- DOCKET 50-321 EDWIN I HATCH NUCLEAR PLANT, UNIT 1
  F Security, medical, emergency & fire protection plans
- 6210190013 Releases public version of revised emergency plan implementing procedure FELTON-J.H Division of Rules and Records 82/09/29 Document Management Branch. 1p 15760.328. 24X Fichs: 50-321, 82/09/29, 8210190013.

- --8210190016 Forwards public version of Revision 4 to Emergency f Implementing Procedure HNP-8026, "High Radiation Area Entrance Control" SORRELLIE C Georgia Power Co 82/09/23 Office of Nucls Reactor Regulation. Director 1p 15760 329 24X Fiche 50-321,82/09/29,8210190013
- --8210170017 Public version of Revision 4 to Emergency Plan Repli Procedure HNP-8026. "High Radiation Area Entrance Control " # Georgia Power Co 82/09/22 12pp 15760 330 24x Fiche 50-321.82/09/29.8210190013
- 8210190042 Releases public version of pages to emergency plan-FELTON.J M Division of Rules and Records 82/10/01 Decur Management Branch ip 15761 037 24X Fiche 50-321,82/10/01, 8210190042
- --8210190046 Forwards public version of Pages M-1 & M-2 to partill plan SORRELL.E C Georgia Power Co 82/09/22 Office of Nucli Reactor Regulation. Director 1p 15761 038 24X Fiche 50-321.82/10/01.8210190042
- --8210190051 Public version of Pages M-1 & M-2 to emergency plan \* Georgia Power Co 82/03/31 2pp 15761 039 24X Fichs 50-321.82/10/01.8210190042
- 8210080227 Forwards IE Safeguards Insp Repts 50-321/82-31 & 50-366/82-29 on 820920-23 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/10/06 XELLY.R J Georgia Power Co 2pp 19638 057 24X Fiche 50-321.82/10/06.8210080227
- --8210080228 IE Safeguards Insp Repts 50-321/82-31 & 50-366/82-29 B20920-29 No noncompliance noted Hajor areas inspected physical barraers, lighting, assessment aids, detection aids, access control & vehicles Details withheld (ref 10CFR73 21) MODRE, D E . MCGUIRE, D R Division of Engineering & Technical Programs 82/10/05 ip 15638 059 24X Fiche 50-321,82/10 8210080227
- P Operating license stage documents & correspondence
- 8210120099 Lists LERs re HPCI & RCIC sys failures not included in NUREO/CR-1205 on LERs related to pumps Probabilistic Analysis Branch should correct classification deficiencies CRNSTEIN.H L Director's Office 80/07/10 BERNERG.R H Probabilistic Analysis Staff (Pre 801119) 2pp. 15689 170 2 Fiche 50-321, 80/07/10,8210120099
- 8210050330 Forwards schedule for qualification testing of analog transmitter trip sys, in response to 801001 request OUCHALL T Georgia Power Co 82/09/28 EISENHUT, D 0 Office Nuclear Reactor Regulation, Director 3pp 15610 258 241 Fiche 50-321, 82/09/28, 8210050330
- 8210150329 Application to amend License DPR-57, consisting of inler change to Tech Spec re maint of secondary containment for period of upcoming refueling outage Proposed mod allows more efficient access to torus area by workers
  SECKMAN, J T. Georgia Power Co. 62/10/06 Dffice of Nuclsar Reactor Regulation. Director Spp. 15701 323 24X
  Fiche: 50-321, 82/10/06, 8210150329
- --8210150333 Proposed temporary changes to Tech Spac re asint of secondary containment for period of upcoming refueling outage # Osongia Power Co. 82/10/06. 8pp 15701 326 24x Fiche 50-321, 82/10/06, 8210150329
- Q Inspection reports, IE Bulletins & correspondence
- 8210010113 Forwards IE Insp Repts 50-321/82-26 & 50-366/82-25 en 820809-13, No noncompliance noted DANGE, H C Division of Project & Resident Programs 82/09/07 KELLYR J Georgia Power Co 2pp 15567 206 24X Fiche 50-321, 82/09/07, 8210010113
- ---8210010118 IE Insp Repts 50-321/82-26 & 50-366/82-25 on 820007:18 noncompliance noted Major areas inspected lab GC program chemistry procedures, airborne efficient sampling & accountability & mobile lab.

  EVANS: C D , MONTOMERY, D M Division of Emergency Preparadents Operational Support. 82/09/02 lipp 15567 208 24X Fiche: 50-321,82/09/07.8210010113
- 8210010235 Forwards IE Insp Rept 50-321/82-27 on 820818-19 Mononcompliance noted DANCE, H.C. Division of Project & Resident Programs 82/09/69 KELLY, R.J. Georgia Fower Co. 2pp. 15574 022 24X Fiche: 50-321, 82/09/08, 8210010235.

ů,

- --8210010240 IE Insp Rept 50-321/82-27 on 820818-19 No noncompliance noted Major areas inspected followup of RO 50-321/82-40 re 820703 reactor trip JAPE,F. HERDT,A R Division of Engineering & Technical Programs 82/09/02 7pp 15574 024 24X Fiche 50-321,82/09/08,8210010235
- 9210010309 Forwards IE Insp Repts 50-321/82-28 & 50-366/82-26 on 210010307 Forwards It insp kepts 30-361/62-26 & 30-365/62-26 on 820727-0827 No noncompliance noted BANCE, H C Division of Project & Resident Programs 82/09/10 EELLY, R J Georgia Power Co 2pp 15568 274 24X Fiche 50-321, 82/09/10, 8210010309
- --8210010327 IE Insp Repts 50-321/82-28 & 50-366/82-26 on 820727-0827 No PIOUTOSE/ IE Imp Repts SUPSE/REPES SUPSE/REPES OF BEOFERMAN mancangliance noted Major areas inspected Tech Bec-corpliance, operator performance, overall plant operations, GA practices & station & corporate mgt practices ROCERS.R.F., HOLMES-RAY.P. BROWNLEE.V.L. Division of Project & Resident Programs 92/09/10 App 15568 276 24X Fichs 50-521,82/09/10,8210010309
- 8210010019 Ack receipt of 820907 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-321/82-19
  O'REILLY. J P Region 2. Diffice of Director 82/09/16 KELLY.R J Georgia Power Co ip 15565 300 24% Fiche 50-321,82/09/16.
- --8210010022 Responds to NRC 820806 itr re violations nated in IE Insp Repts 50-321/82-19 & 50-366/82-19 Corrective actions Repts 30-32/192-17 50-366/82-17 Corrective actions procedures being revised to include tighter controls on changes to fuel movement data packages
  BECKHARK-JT Georgia Power Co 82/09/07 O'REILLY, J P 12, Office of Director 3pp 15565-301 24X fiche 50-321, 62/09/16, 8210010019 Region
- --B210010025 Forwards IE Insp Repts 50-321/82-19 & 50-366/82-19 en B20421-0525 & natice of violation O'REILLY, JP Region 2, Office of Director 82/08/06 KELLY, R J Georgia Power Co 2pp 15565 304 24X Fichs 50-321,82/09/16,
- --0210010031 IE Insp Repts 50-321/82-17 & 50-366/82-19 on 820421-0525 Plancompliance noted fuel loaded into core w/o all control rods fully inserted ROCERS.R F Division of Project & Resident Programs BROWNLEE,V L Region 2, Office of Director 82/07/ 15965 307 24% Fiche 50-321,82/09/16,8210010019 82/07/29 7pp
- 9210040047 Ack receipt of check in payment of civil penalty proposed on B20713 Corrective measures described in 820812 & 0907 ltrs will be examined in future insp AYELRAD. J A Director's Office, Office of Inspection and Enforcement 82/07/23 KELLY, R J Georgia Power Co 2pp 15577 290 24X Fiche 50-321,82/07/23,8210040047
- 3208190233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COUBLE I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 64pp 15761:250 24x Fishe 50-000,82/10/06,8208190233
- #210080227 Forwards IE Safeguards Insp Repts 50-321/82-31 & 21002022/ rowards it saregoands into repeat 20 of 30-362/82-29 on 820720-23 No moncompliants noted.

  DANCE H C Division of Project & Resident Programs 82/10/06

  KELLY R J Georgia Power Co 2pp 15638:057 24X

  Fichs 50-321.82/10/06.8210080227
- -82\$0080228 IE Safeguards Insp Repts 50-321/82-31 & 50-366/82-29 on 620920-23 No noncompliance noted Hajor areas inspected physical barriers, lighting, assessment aids, detection aids, access control & vehicles Details withheld (ref 10CFR73 21), MODRE, D E . MCQUIRE, D R Division of Engineering & Technical Programs 82/10/05 ip 15638 059, 24X Fiche 50-321,82/10/06, 6210080227
- 1208190238 IE Bulletin 82-03, "Strees Corrosion Cracking in Thick-CORTUGUE LE BULISTEN HZ-03, "Stress Corresion Cracking in Thick Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piging at BWR Plants "Syc list encl DEYBUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York. \$15pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- 125 0220277 Ack receipt of 820927 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/82-24 & 50-366/82-22 ELLY:R C Division of Project & Resident Programs KELLY:R J Georgia Power Co ip. 15775 028. 24X Fiche 50-321.82/10/14.8210220277

- --8210220287 Responds to NRC 820823 ltr re violations noted in IE Insp Repts 50-321/82-24 & 50-366/82-22 Corrective actions written plan will be prepared to schedule & integrate lecture series to meet add1 training needs OUCHAL I Georgia Power Co 82/09/27 O'REILLY, J P Region E Office of Director 4pp 1575 029 24x Fichs 50-321,82/10/14.
- --8210220292 Forwards IE insp Repts 50-321/82-24 & 50-366/82-22 on 820726-30 & notice of violation LEWIS,R C Division of Project & Resident Programs 82/08/23 XELLYR J Georgia fower Co 2pp 15775 033 24X Fiche 50-321,82/10/14.8210220277
- --8210220299 Notice of violation from insp on 820726-30 \* Division of Project & Resident Programs 82/08/23 2pp 15775 035 24X Fiche 50-321,82/10/14-8210220277
- --8210220307 IE Insp Repts 50-321/82-24 & 50-366/82-22 on 820726-30 Noncompliance noted failure to provide GA indoctrination scheduled preplanned lecture series based on evaluation of annual licensed operator exams
  SKINNER.P H , JACKSON.L H , UPRIGHT.C M Division of Engineering & Technical Programs 82/08/19 8pp 15775 037 24X
  Fiche 50-321.82/10/14.8210220277
- R Periodic operating reports & related correspondence
- 8210130129 Forwards monthly operating repts for Sept 1982 NIX.H C Georgia Power Co 82/10/07 Director's Office of Inspection and Enforcement ip 15673 029 24X Fiche 50-321.82/10/07.8210130129
- --8210130132 Monthly operating repts for Sept 1982 SMITH.J A Georgia Power Co B2/10/07. 9pp 15673 030 24X Fiche 50-321.82/10/07:8210130129
- S Reportable occurrences, LERs & related correspondence
- 8210120171 Discusses 810406 discovery that undervoltage relays of 2101/201/1 Discusses MIOMO discovery that undervoiting relays or second offsite source would not operate preventing closure of all dissel generator breaters Licensee will be proposing design mod to correct problem of non-Class IE interlock CHIRAMAL M Director's Office 81/04/21, Director's Office 3pp. 15692;202 24X Fiche 50-321,81/04/21,8210120171.
- 8210010008 Responds to FDIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents Tisted in App A

  FELTON J M Division of Rules and Records. 82/0/
  Critical Mass Energy Project 15pp 15727 005

  Fiche 50-000.82/06/28.8210010008 82/04/28 UDELL,R A
- --- \$103120107 Summary of \$10107 operating reactor events meeting W/o encl agenda LAIMAB.O C Division of Licensing, 81/01/19 EIBENHUT, D O Division of Licensing 3pp 15727 361, 24X Fiche 50-000. 82/06/28, 821001000B
- --Bi04270103 Discusses IE daily rept for 810406 re alternate offsite source interlock w/emergency diesel generators at Unit i Licensee will propose mod to correct non-Class IE interlock preventing automatic operation of safety sys CHIRAMAL, M Director's Office 81/04/21 Director's Office, 3pp. 15729 041 24X Fiche 50-000.82/06/28.8210010008
- --8210010083 Recommends ACRS action on recent LERs re HPCI fail: auto start after MSIV failure & single cooling supply line on RHR pump motors
  BDEHNERT: P ACRS - Advisory Committee on Reactor Safeguard:
  80/06/13 KERR:W ACRS - Advisory Committee on Reactor
  Safeguards 1p 15727 138 24X Fiche 50-000,82/06/28,821(
- 8210130256 Forwards LER 82-074/03L-0 NIX.H C Georgia Power Co 82/09/28 O'REILLY, J. P Region Office of Director. 1p 15678 048. 24X Fiche 50-321, 82/09/3
- ---8210130258 LER 82-074/03L-0 on 820901. HPCI steam pressure con switches ArC & D actuated at less than 107 3 psig Caused by component failure due to setpoint drift Switches calibr & function tested TIPPS, S. B Geor Director 2pp eted Georgia Power Co - 82/09/28 - Region 2: Offic Spp - 15678 049 - 24X Fiche: 50-321, 82/09/28, 8210
- 8210220384 Forwards LER 82-071/03L-0. NIX.H C Georgia Power Co. 82/09/28. O'REILLY, J. P Region Office of Director 1p 15779 167 24X Fiche: 50-321, 82/09/ 8210220384

- --B210220388 LER B2-071/03L-0 on B20931, primary containment atmosphere concentration O2 exceeded Tech Spec requirements Caused by personnel failure to secure standby gas treatment sys in time while venting drywell Personnel counseled TIPPS, 8 B Qeorgia Fouer Ca B2/09/28 Region 2, Office of Director 2pp 15779 168 24X Fiche 50-321, B2/09/28, B210220384
- 8210220219 Forwards LER 82-082/03L-0 NIA:H C Georgia Power Co 82/10/07 O'REILLY, J P Region 2, Office of Director 19 15776:242 24X Fiche: 50-321.62/10/07. 8210220219
- --8210220222 LER 82-082/03L-0 on 820911,LPCI A inverter tripped Unit placed in 7-day limiting condition for operation. Caused by failure of output filter capacitor Six fuses & 2 output filter capacitors replaced Inverter placed in svc on 820913 TIPPS,S B Georgia Power Co 82/10/07 Region 2. Office of Director ip 15776 243 24x Fiche 30-321,82/10/07,8210220219.
- 8210290327 Forwards updated LER 80-016/03X-1 NIX.H C Osorgia Power Co 82/10/12 0'REILLY. J F Region 2. Office of Director 1p 15853 108 24X Fichs 50-321.82/10/12.
- --8210270334 Updated LER 80-016/03X-1 on 800129, investigation of IE Bulletin 79-27 revealed that breaker control power to swing diesel B motor control ctr fed by non-Class IE vital ac sys Caused by design error SUKNER, H L Georgia Power Co 82/10/12 Region 2, Office of Director ip 15853 109 24X Fiche 50-321, 82/10/12, 8210270327
- 8210290373 Forwards updated LER 82-054/03X-1 NIX.H C Georgia Power Co 82/10/12 Region 2. Office of Director ip 15853 022 24% Fiche 50-321.82/10/12.8210290373
- --8210290375 Updated LER 82-054/03X-i on 620428,at 100% power. RHR syrwater pump C failed operability & flow requirements Caused by normal wear to impeller seal & casing wear rings Pump removed rebuilt, installed & tested successfully TIPPS-8 B Georgia Power Co 92/10/12 Region 2, Office of Director ip 15853 023 24X Fichs 50-321,82/10/12,8210290373
- 8210290096 Forwards LER 82-083/03L-0 NIX.H C. Georgia Power Co 82/10/14 O'REILLY.J P Region 2. Office of Director ip 15853 389. 24X Fiche 50-321.82/10/14. 8210290096
- --8210270105 LER 82-083/03L-0, on 820715.00 review disclosed installation of non-0 part in level switch on A loop core spray discharge line Caused by ineffective administrative procedures. Part ordered Required 0 functions not affected TIPPS.8 B Georgia Power Co 82/10/14 Region 2, Office of Director 1p 15853 360 24X Fiche.50-321.82/10/14.8210270096
- 8210270262 Forwards LER 82-086/03L-0 NIX, H C. Osongia Power Co 82/10/14 O'REILLY, J P Region 2, Office of Director ip 15854 074 24X Fiche. 50-321, 82/10/14, 62102702702
- --8210270272 LER 82-086/03L-0 on 820917.attempt to place torus cooling in syc failed due to lack of syc water flow Caused by loose bolts in valve operator coupling allowing coupling spring pin to break Pin replaced & bolts tightened TIPPS.8 B Georgia Power Co 82/10/14 Ragion 2. Office of Birector ip 15854.095 24X Fiche.50-321,82/10/14.8210270262
- 8210270326 Forwards LER 82-084/03L-0 NIX.H C Georgia Power Co. 82/10/14 O'REILLY.J P Region 2-Office of Director 1p. 15853 062 24X Fiche 50-321.82/10/14-8210270326
- --8210290329 LER 82-084/03L-0 on 820916, channel B main steam line radiation monitoring instrument failed Cause unknown Bpare instrument installed, calibr & tested TIPPS, 8, 8 oergia Power Co. 82/10/14 Region 2, Office of Director ip 15853 063 24X Fiche 50-321,82/10/14,8210290326.
- 8210270347 Forwards LER 82-091/03L-0 NIX,H G Osongia Power Co 82/10/21 O'REILLY, J P Region 2. Office of Director 1p 15853.026 24X Fiche 50-321.82/10/21, 8210270347.
- --B210270359 LER 82-091/03L-0 on 820928, spec release order change to liquid radwaste monitor instrument FT&C procedure lacked plant review board evaluation Caused by personnel error TIPPS 8 B Georgia Power Co 62/10/21 Region 2, Office of Director 1p 15853-027 24X Fiche 50-321.82/10/21,8210270349

- DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION
- A Application/construction stage documents & correspondence
- B21001000B Responds to FOIA request for 19 categories of documents in nuclear reactor events & safety problems Forwards documents listed in App A FELTON J M Division of Rules and Records 82/06/28 UDELL.R.A Critical Mass Energy Project 15pp 15727 005 24x Fichs 50-000.82/06/28.8210010008
- --B00B050265 Discusses addl required info to better define potential cracking in reactor vessel nozzles nonzeles nonzele
- 820829099 FOIA request for documents re shipment of radioactive is' mfg by OE at Wilmington: NC, transported by Tri-State Hater Transit: which traveled through NY on or about 820725 & received at facility SHARISON: 8 S New York: State of 82/09/14 Office of Administration in 15758 242 24X Fiche 50-022, 82/09/14, 82/0870099
- 8210050488 Forwards requests for add1 info re instrumentation & control.containment sys & environ qualification of safety-related electrical equipment Schedule for submitting required info requested within 7 days M/o andls SCHMENGER.A Licensing Branch 2 82/09/20 POLLOCK.M 8 Ling Island Lighting Co. 3pp. 15626-286 24X Fiche 80-322,92/09/20. 8210050488
- 8210190019 Responds to FOIA request for documents re shipment of radioactive matl mfg by GE at Wilmington NC & transported by Tri-State Motor Transit to facility on 820725 Forwards DOF/ NRC Form 741 handwritten note FELTON J M Division of Rules and Records 82/10/06 CHARISON New York, State of ip 15758 243 24X Fiche 50-922.82/10:15 8210190019
- --8210190464 "DGE & NRC Nuclear Matl Transaction Rept "
  # NRC No Detailed Affiliation Given \* Energy, Dept of
  82/09/09 38pp 15758 245 24X Fiche 50-322, 82/10/08.621(16)
- 8210280240 Provides NRC responses to Judge Morris 820914 questirs based on NRC 820629 response to earsier ABLB info requists Questions involve Unresolved Safety Issues A-44, A-86, A 42 & A-24. TMI Item 1 A i. i & Item 63 REPKA-D A Hearing Branch 3 82/10/06 BRENNER-L. CARPENTES HORRIS.P. A Abonic Safety and Licensing Board Panel 17sp 24% Fiche 30-322, 82/10/06, 8210280240
- 8210210510 Responds to 820831 request to delay installation of hist radiation signal for purge valves, (NUREO-0737, Item II E 4 2(7)) until fuel load Justification insufficient Re-evaluation requested SCHWENCER: A Licensing Branch 2 82/10/13 POLLOCK. N B Lsty Island Lighting Co 2pp 15782 278 24X Ficha 50-322.82/10/13 8210210510
- E NRC Safety Evaluation Report (SER), suppls & correspondents
- 8210190385 Forwards NRC 821013 response to util justification fir '.
  installation of high radiation closure signal for purgs
  valves info relevant to SER Open Item II E 4 2 & Suffoli
  County Contention 23 H/o encl.
  REPKA-D A Hearing Branch 3 82/10/15 BRENNER.L. CAPPATER.
  HORRISP A Atomic Safety and Licensing Board Fanel 23p
  13741 214. 24X Ficher 50-322,82/10/15.8210190385
- F Becurity, medical, emergency & fire protection plans
- 8210150055 Forwards IE Emergency Preparedness Appreheal Right % 32-18 on 820820-0902. App A. significant emergency preparedness findings & App D improvement items 8HITH, C. H. Division of Emergency Preparedness & Operational Sales 82/09/30 POLLOCK, M. B. Long Island Lighting Co. 1031 15-13-24X Fiche 50-382, 82/09/30, 8210150055

- 6210260033 Releases public Version of revised into for facility emergency plan FELTON. J H Division of Rules and Records 82/10/08 Document Management Branch ip 15857 145 24X Fiche 50-322,82/10/08, 82/10280033
- ~-8210280036 Forwards public version of revised info for facility exergency plan, including updated cross-ref list, revised plan pages & radiological emergency evacuation plan Revised plan pages will be included in next amend SMITH.J L. Long Island Lighting Co. 82/09/24 DENTON.H R. Office of Nuclear Reactor Regulation. Director 2pp 15857 146-24X Firms 50-322,82/10/08.8210280033
- ~-R210280039 Forwards public version of revised info for facility erergency plan including updated cross-ref list, revised plan pages & radiological emergency evacuation plan Revised plan pages will be included in next amend EMITH.J L Long Island Lighting Co 82/09/01 DENTON, H R OPFICE of Nuclear Reactor Regulation. Director 2pp 15857 148 24X Fiche 50-322,82/10/08,8210280033
- --8210280041 Public version of radiological emergency evacuation plan. consisting of updated cross-ref list, revised pages & offsite dose assessment methodology Thirteen oversize maps encl Aperture cards available in PDR MAGNUS, D Long Island Lighting Co MAGNUS, D KLD Associates, Inc. 82/08/27 213pp 15857 150 24X Fiche 50-322,82/10/08,8210280033
- #210290125 Forwards IE Insp Rept 50-322/82-24 on 820907-10 No noncompliance noted MARTIN: TT Division of Engineering & Technical Programs #82/10/15 POLLOCK: M S Long Island Lighting Co 2pp 15853 322 24X Fich 50-322, 82/10/15, 8210290125
- G. Adjudicatory correspondence
- B20B290094 FOIA request for CRAC & CRAC 2 analyses for facilities CURRAN.D Harmon & Weiss B2/09/10 Office of Administration 1p 15626 239 24% Fiche 50-000.82/09/10,8208290094
- 8210200036 Stipulation of Suffolk County Contention 25/Shoreham
  Opponents Coalition Contention 19(a) we preservice &
  inservice insp & reactor pressure vessel integrity
  Certificate of Svc encl
  BURDENICK, B M Hearing Branch 3 IRHIN, D P Long Island Lighting
  Co SHAW, J T Shoreham Opponents Coalition 82/09/17 lipp
  15755 345 24x Fiche 50-322, 82/09/17, 8210200036
- 8210040011 Forwards NRC 820903 ltr to util transmitting IE Insp Rept 50-322/82-14 BORDENICK.B M Hearing Branch 3 82/09/27 BRENNER.L, CARPENTER.J L, MORRIS.P A Atomic Bafety and Licensing Board Panel 45p 15581 328 24x Fiche 50-322,82/09/27,8210040011
- B2:C010395 Supplemental status rept on Emergency Planning Contentions &C & 7A per ASLB B20907 supplemental preheating conference order Certificate of Svc enci MCMURRAY.C M Suffolk County, NY MCMURRAY.C M Kirkpatrick, LIC
- 8210010386 Supplemental memorandum & order granting util motion to compel discovery on Suffolk County emergency planning documents Executive privilege does not apply to county emergency planning steering committee meeting minutes BRENNER. L Atomic Safety and Licensing Board Panel 82/09/29 Suffolk County, NY App 15574.140, 24X Fiche 50-522,82/09/29, 8210010356
- B2100505B2 Responds to FOIA request for CRAC & CRAC 2 analyses for facilities No analyses exist for Shoreham Nuclear Plant Analyses for CRBR furnished under FOIA 82-344
  FELTON.J H Division of Rules and Records 82/09/29 CURRAN.D Harmon & Weiss 1p 15626 240 24X Fiche 50-000.82/09/29, 82/10050582
- B210040063 Forwards NRC 820916 ltr to util % util 820812 ltr to NRC re IE Insp Rept 50-322/82-13 BGRDENICK.B M Hearing Brench 3 B2/09/30 BRENNER.L, CARPENTER.J L, MORRIS.P A Atomic Safety and Licensing Board Panel App 15581 237 24X Fiche 50-322.82/09/30,8210040063

- 8210050189 Notice of relevant & matl new info re type of accident involving internal flooding which may lead to higher probability than calculated in draft probabilistic risk assessment Certificate of Svc encl BROWN. H H Suffolk County. NY BROWN. H H Kirkpatrick. Lockhart. Hill. Christopher & Phillips 82/09/30 6pp 13603 301 24X Fichs 50-322,82/09/30,8210050189
- 8210050383 Motion to suppl sponsorship of Suffolk County testimeny on Contentions 12-15 re compliance w/NRC GA/GC requirements. Add1 witnesses will bring relevant expertise to proceeding Certificate of Svc & prof qualification encl LANPHER.L C Suffolk County, NY LANPHER.L C Kirkpatrick, Lockhart, Hill, Christopher & Phillips 82/09/30 Atomic Safety and Licensing Board Panel 16pp 15608 235 24X Fiche: 50-322, 82/09/30,8210050383
- 8210050243 Forwards NRC 820913 ltr to util transmitting IE Mgt Meeting Rept 50-322/82-25 on 820826 BDRDENICK, B H Hearing Branch 3 82/10/01 BRENNER, L , CARPENTER, J L , MORRIES, J L Atomic Safety and Licensing Board Panel 4pp 15611 178 24X Fiche 50-322, 82/10/01, 8210050243
- 8210060187 App B to ASLB 820707 supplemental prehearing conference order on Phase i re emergency planning, listing admitted Phase i contentions

  \*\*Atomic Safety and Licensing Board Panel 82/10/04 16pp 15613: 212 24X Fiche 50-3R2,82/10/04,8210060187
- 8210280251 Forwards IE Emergency Preparedness Appreisal Rept 50-322/82-19 BLACK.R L Hearing Branch 3 82/10/04 BRENNER,L, CARPENTER,JL, MORRIS.P A Atomic Safety and Licensing Board Panel 2pp. 15838 204 24% Fiche 50-322.82/10/04.8210280251
- 8210120307 Motion for further ASLB direction on conduct of QA cross-examination Steps listed to ensure fair & efficient litigation of QA issues Centificate of Stc and EARLEY.A F Long Island Lighting Co EARLEY.A F Hunton & Williams. 82/10/05 Atomic Sefety and Licensing Board Panel.
- B210280234 Forwards 1E Insp Rept 50-322/82-23 BORDENICK/B H Hearing Branch 3 82/10/06 BRENNER,L, CARPENTER,J L, MORRIS,P A Atomic Safety and Licensing Board Panel 4pp 15837 067 24% Fichs 50-322, B2/10/06/B210280234
- 8210280240 Provides NRC responses to Judge Morris 820914 questions based on NRC 820629 response to earlier ABLB info requests questions involve Unresolved Bafety Issues A-44.A-42.4 A-24.TMI Item 1 A 1 1 k Item 63
  REPKA-D A Hearing Branch 3 82/10/06 BRENNER,L, CARPENTER,J L, MORRIS, P A Atomic 83efty and Licensing Board Penel 17pp. 15845:177 24X Fiche 50-322,82/10/06,8210280240.
- 8210150234 Notifies that North Shore Committee Against Nuclear & Thermal Pollution & util have resolved Committee Contentions EP 11(D)(F)(E) & EP 12(A) Committee will not file testimony on Contentions EP 11(A)(B)(C) but will cross-examine SHAPIRO.R Commer & Shapiro SHAPIRO.R North Shore Committee Against Nuclear & Thermal Pollution 82/10/08. BRENNER, L, CARPENTER, J L, MORRIS, P A Atomic Safety and Licensing Board Panel 1p 19706 040 24X Fiche 50-322,82/10/08,8210150234
- 8210280209 Forwards Region i 820927 ltr to util re IE Insp Repts 50-322/82-10 & 50-322/82-11 & util 820701 & 19 ltrs. BURDENICK, B H Hearing Branch 3 82/10/08 BRENNER, L . CARPENTER, J L ., MORRISP, A Atomic Safety and Licensing Board Panel 4pp 15837 091. 24X Fiche 50-322,82/10/08,8210280209
- 8210150117 Advises that NMSS recommended Suffolk County not pursue 820916 request re NRC initiation of discussions w/F81 to explore ways to make F81 fingerprint identification svc available to util 80RDENICK.8 M Hearing Branch 3 82/10/12 MILLER.M 8 Kirkpatrick. Lockhart Hill. Christopher & Phillips. MILLER,M 8. Suffolk County, NY. 2pp. 15698:016. 24X Fiche.50-322,82/10/12, e2:04510117.
- 82i0150279 Forwards written testimony on Phase I amergency planning Contentions EP 1(B).2(A).2(B).4.5(A).5(B).7(B).10(B).10(C).11(A).11(B).11(C).13 4 Stipulations will be gent as soon as received.4/o testimony CHRISTMAN.J.N Long Island Lighting Co. 82/10/12 BRENNER.L. CARPENTER.J.H., MORRIS.P.A. Atomic Safety and Licensing Board Panel 4pp. 157i5:055. 24X Fiche:50-322.82/10/12.8210150279
- --8210150296 Forwards proposed settlement agreements on Emergency Planning Contentions 1(A).3.5(C).7(A),8,9,10(A),11(D),11(E),11(F) & 12(A) MCCLESHEY,K.E. Hunton & Williams 82/10/12 BRENNER,L., HORRIS,P.A., CARPENTER,J H. Atomic Sefety and Licensing Board Fanel. ip 15715 059 24X Fiche 50-322,82/10/12.8210150279.

- ---B210150309 Stipulation on Suffolk County Contention EP 1(A) re effect of weather on strens Util documented that effects of extreme weather taken into consideration in design of BLACK.R L Hearing Branch 3 MCCLESKEY.KE Long Island Lighting Co SHAPIRD.R North Shore Committee Against Nuclear & Thermal Pollution 82/10/12 6pp 15715 060 24X Fiche 50-322,82/10/12,82/0150279
- --B210150324 Stipulation on Suffolk County Contention EP 3 re federal resources Flant emergency plan to be amended to respond to concerns
  BLACK,R L Hearing Branch 3 MCCLESKEY,K E Long Island Lighting
  Co SHAPIRO,R North Shore Committee Against Nuclear & Thermal
  Pollution 82/10/12 4pp 15715 066 24% Fiche 50-322,82/10/12,
  8210150279
- --B210150337 Stipulation on Suffolk County Contention EP 5(C) renotification of response organization & emergency personnel Plant smergency plan to be amended as listed BLACK.R L. Hearing Branch 3 MCCLEEKEY.K E. Long Island Lighting Co. SHAPIRO.R North Shore Committee Against Nuclear & Thermal Pollution 82/10/12 4pp 15715 070 24X Fiche 50-322.82/10/12, 8210150279.
- --8210150351 Bigulation on Suffolk County Contentions EP 7(A) & EP 8 re onsite response organization & emergency operations facility, respectively Plant emergency plan to be amended as BLACK, R L Hearing Brench 3 MCCLESKEY, K E Long Island Lighting Co SHAPIRO, R North Shora Committee Against Nuclear & Thermal Pollution 82/10/12 4pp 15715 074 24x Fiche 50-322,82/10/12,8210150279
- --8210150365 Stipulation on Suffolk County Contention EF 9 re-radiological exposure flant emergency plan to be amended as listed
  BLACK, R.L. Hearing Branch 3 MCCLESKEY, K.E. Long Island Lighting
  Go SHAPIRG, R. North Shore Committee Against Nuclear & Thermal
  Pollvition 62/10/12 7pp 15715.078 24X Fiche. 50-322, 82/10/12.
  8210150279
- --8210150393 Stipulation on Suffolk County Contention 10(A) re field monitoring team Fourth replacement field monitoring team will be available to replace or relieve other three trams BLACK.R L. Hearing Branch 3. MCCLESKEY.K E. Long Island Lighting Co. SHAPIRO.R. North Shore Committee Against Nuclear & Thermal Pollution 82/10/12 App. 13715.085. 24X Fiche:30-322.82/10/12.8210150279
- --8210150402 Stipulation on North Shore Committee Against Nuclear & Thermal Pollution Contention EP 11(D) re redundant nower Thermal Pollution Contention EP 11(B) re redundant power supplies Backup diesel generator power provided to radios used by util as backup communication BLACKUR RL Hearing Branch 3 MCCLESKEY.K E Long Island Lighting Co. SHAPIRO.R North Shore Committee Against Nuclear & Thermal Pollution B2/10/12 3pp 15715 088 24X Fiche 50-322,82/10/12,8210150279
- --8210150410 Btipulation on North Bhore Committee Against Nuclear & Thermal Poliution Contention EP ii(E) re communications through baspers Util commits to training personnel reresponse to beapers if telephone sys overloaded.

  BLACK.R.L. Hearing Branch 3 MCCLESKEY.K E Long Island Lighting Co BHAPIRO.R. North Shore Committee Against Nuclear & Thermal Pollution 82/10/12 Jpp. 15715 091 24X Fiche 50-322.82/10/12, 8210150279.
- --8210150422 Bispulation on North Shore Committee Against Nuclear & Thermal Pollution Contention EP 11(F) re communication through nati alert warning sys. Concerns re coverage & load BLACK.R L Hearing Branch 3. MCCLESKEY.K E Long Island Lighting Co SHAPIRO.R North Shore Committee Against Nuclear & Thermal Pollution 82/10/12 2pp 15715 094 24X Ficher 50-322, 82/10/12, 821050279.
- 210150527 Stipulation on North Shore Committee Against Nuclear & Thermal Pollution Contention EP 12(A) re personnel assignments re communication notification Util commits to provide seven communicators Certificate of Suc encl BLACK, R L. Hearing Branch 3, MCCLESKEY, K E. Long Island Lighting Co SHAPIROIR, North Shore Committee Against Nuclear & Thermal Pollution 82/10/12 App. 15715 094. 24X Fiche 50-322,82/10/12,8210/150279. --- 8210150527 Stipulation on North Shore Committee Against Nuclear &
- 8210200076 Notification of corrections to Suffolk County Exhibits 51 & LANPHER, L C Suffolk County, NY. LANPHER, L C, Kirtpatrick, Lockhart, Hill, Christopher & Phillips. 82/10/12. 3pp 15754:173 24X Fichs. 50-922.82/10/12.8210200076.

- --B2102000B3 Response opposing Requests 1 & 3 in util B21005 motion for further ASLB direction on conduct of cross-examination Mixts designated for use are relevant Opposes predetermined deadline by which County cross-examination must be complete LANPHER.L C Suffolk County, NY LANPHER.L C Kirkpatrich. Lockhart, Hill: Christopher & Phillips B2/10/15 Atomic Safety and Licensing Board Panel 45pp 15754 176 24X Fichs 50-322,82/10/12,8210200076
- --92102000B9 Submittal of GA/GC info in Subparagraphs (a)-(c),Page 15 of util 821005 motion for further ASLB direction conduct of of util B21005 motion for further Mala utraction conduct of CA cross-examination Certificate of Svc encl LANPHERL C Suffall County, NY LANPHERL C Kirkpatrict. Lockhart, Hill, Christopher & Phillips 82/10/11 1:79pp 15734 221 24% Fiche 50-322, 82/10/12.8210200076
- 8210200003 Response to Suffolk County 821002 motion to suppl GA witten panel Request is out of time, is impermissible attempt to suppl County direct testimony & is different from earlier approved game! suppls Certificate of Svc enc!

  ELLIS, T 8 Long Island Lighting Co ELLIG, T 8 Hunton & Hilliams 82/10/14 Atomic Safety and Licensing Board Panel [2pp 15754, 348 24X Fiche 50-322, 82/10/14, 8210200003
- 8210180099 Notice of withdrawal of appearance in proceeding Certificate of Svc encl Branch 3 82/10/15 4pp 15719 305 24x Fiche.50-322.82/10/15,8210180099
- B210190385 Forwards NRC 821013 response to util justification for late installation of high radiation closure signal for purge valves info relevant to SER Open Item II E 4 2 & Suffolk County Contention 23 H/o encl
  REPKA.D A Hearing Branch 3 82/10/15 BRENNER,L. CARPENTER,J L
  HDRRIB.P A Atomic Safety and Licensing Board Panel 2pp
  13741 214 24X Fiche 30-322.82/10/15.8210190385
- 8210250058 Forwards stipulation re Suffolk County Phase | Contention EP 6
  MCHURRAY, C M. Kirkpatrick, Lockhart, Hill, Christopher & Phillips
  MCHURRAY, C M. Suffolk County, NY 82/10/19 BRENNER, L ,
  CAMPENTER, J H , MORRIS, P A Atomic Bafety and Licensing Boarf Part,
  tp 15787 094 24% Fiche 50-322,82/10/17.8210250058
- --8210250059 Stigulation on Suffolk County Contention EP & retraining emergency personnel Wading River fire dept trained per util emergency plan Certificate of Bvc encl BORDENICK. B Hearing Branch 3 MCCLEGKEY.K E Long Island Lighting Co SHAPIRO,R North Shore Committee Against Nuclear Lighting Co SHAPIRO,R North Shore Committee Against Nuclear Lighting 82/10/15 Spp 15787 095 24X Fiche 50-322,82/10/19.8210250058
- 8210270283 Forwards Buffolk County Deputy Executive F Junes 821020 memo to Buffolk county legislators re brief slippage in date scheduled for completion of county radiological emergency response plan. Related correspondence HCMURRAY.C.M. Kirkpatrick, Lockhart, Hill. Christopher & Phillips MCMURRAY.C.M. Buffolk County, NY 82/10/26 BRENNER.L., CARPENTER.J.H., MORRIS.P.A. Atomic Bafety and Licensing Board Paril 2pp 15854 067 24X Fiche 50-322,82/10/26,8210290283

#### H General correspondence

- 8210070034 Provides responses to constituent T Hayes 820611 questions re fuel storage & transport

  DIRCKS.H J Office of the Executive Director for Operations
  82/09/17 CARNEY, H. House of Rep. 17pp 15645 347 24X
  Fiche 50-322, 82/09/17, 8210070034.
- 8210260409 Forwards Middle Country Central School Board 821004 resolvery regularies missis country central school Board SELOO4 resolvetion opposing plant opening until acceptable asfety std can be met & acceptable evacuation plan developed AMAKG, V. Suffolk County, NY 82/10/07 NRC - No Datailed Affiliation Given. 2pp. 15803.317 24X Fiche 50-322.82/10/07. 8210260409.
- Q Inspection reports, IE Bulletins & correspondence
- 8210040258 Ack receipt of 820701 & 19 ltrs informing NRC of stage line to correct violations noted in IE Insp Repts 50-322/82-10 &
- 50-322/82-11

  MARTIN T. T. Division of Engineering & Technical Programs
  POLLOCK: M 8 Long Island Lighting Co 2pp. 15589-078

  Fiche 50-322, 82/09/27, 8210040258.
- --B210040274 Responds to NRC 820524 1tr re violations noted in IE Ins 1 2100402/4 Masponds to NRC Bu0044 for re violations notes in it.
  Rept 50-322/82-10. Corrective actions procedure for leak rati
  test panel rotometer calibr revised. Severity Level V
  violation contested
  POLLOCK, M S Long Island Lighting Co 82/07/01. MARIN-T T
  Division of Engineering & Technical Programs Spp. 15587 086
  24X Fiche. 50-322, 82/09/27, 8210040258

# **DOCKETED ITEMS**

- --8210040361 Responds to NRC 820618 ltr re violations noted in IE Insp Rept 50-322/82-11 Corrective actions scope & frequency of battery svc modified POLLOCK.M S Long Island Lighting Co 82/07/19 MARTIN.T T Division of Engineering & Technical Programs 4pp 15589 085 24X Fishe 50-322,82/09/27,8210040258
- \$210150055 Forwards IE Emergency Preparedness Appraisal Rept 50-322/ \$2-18 on \$20920-0902, App A, significant emergency preparedness findings & App D improvement items \$MITH.O H Division of Emergency Preparedness & Operational Support \$2/09/30 POLLOCK.M B Long Island Lighting Co iOpp. 15701 061 244 Fiche. 50-322, 82/09/30, 8210150055
- --5210150059 IE Emergency Preparedness Appraisal Rept 50-322/82-18 on 520820-0902 Corrective actions required to complete emergency preparedness training program TERC.N M . CROCKER.H W Division of Emergency Preparedness & Operational Support 82/09/30 40pp 15701 071 24X Fichs 50-322,82/09/30,8210150055
- 5210050243 Forwards NRC 820713 ltr to util transmitting IE Mgt Mesting Rept 50-322/82-25 on 820826 BURDENICK, B M Hearing Branch 3 82/10/01 BRENNER, L., CARPENTER, J. L., HORRIS, J. L. Atomic Safety and Licensing Board Panel 4pp 15611 178 24X Fiche 50-322.82/10/01.8210050243
- E2D8190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds "Svc list encl
   C080. L I Division of Fuel Facilities, Materials & Safeguards
   B2/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fichs 50-000.82/10/06, 8208190203
- 2210290350 Forwards IE Insp Rept 50-322/82-22 on 820823-27. No moncompliance noted MARTIN, I T Division of Engineering & Technical Programs 82/10/06 FOLLOCK: M S Long Island Lighting Co 2pp 15853 067 24X Fiche 50-322, 82/10/06, 8210290350
- --B210290354 IE Insp Rept 50-322/82-22 on 820823-27 No noncompliance noted Hajor areas inspected preoperational test program status.including program implementation, procedure review, procedure verification, test withouting & evaluation results NICHOLAS, H H, BETTENHAUSEN, L Division of Engineering & Technical Programs 82/10/05 9pp 15853 069 24X Fiche 50-322,82/10/06,8210290350
- 8210290341 Forwards IE Insp Rept 50-322/82-21 on 820729 No noncompliance noted MARTINIT Division of Engineering & Technical Programs 82/10/12 FOLLOCKIM S Long Island Lighting Co 2pp 19853 056 24% Fiche 50-322, 82/10/12, 8210290341
- --8210290344 IE Insp Rept 50-322/82-21 on 820729 No noncompliance noted Major areas inspected health physics personnel training to qualification program HHITE.J R. GREEMAN.E G. Region 1. Office of Director 82/10/08 App. 15853 058 24X Fiche 50-322.82/10/12,8210290341
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall.Large-Diameter, Stainless Steel, Recirculation Sys
  Piping at BWR Plants " Svc list encl
  DEYOUNG.R C Director's Office, Office of Inspection and
  Enforcement 82/10/14 Consolidated Edison Co of New York.
  115pp 15810 125 24K Fiche 50-000, 82/10/14,8208190238
- 8210290084 Forwards IE Insp Rept 50-322/82-19 on 820719-0813 & notice of violation 
  MARTIN.T T Division of Engineering & Technical Programs 
  POLLOCK.M S Long Island Lighting Co 2pp 15854 032 24X
  Fiche 50-322,82/10/15,8210290084
- --8210290089 Notice of violation from insp on 820719-0813 # Division of Engineering & Technical Programs 82/10/15 ip. 13884 034 24X Fiche 50-322, 82/10/15,8210290084
- --B210270073 IE Insp Rept 50-322/82-17 on 820717-0813 Noncompliance noted two radiographs did not have required panetrameters & proper dispositions KERCH.H W. HARRIS.R H. DIERR.J P. Region 1. Office of Director 82/07/17 10pp 15854 035 24% Fiche 50-322,82/10/15.8210270084
- B210290125 Forwards IE Insp Rept 50-322/82-24 on 820907-10 No moncompliance noted MARTINIT Division of Engineering & Technical Programs 82/10/15 POLLOCK, M 8 Long Island Lighting Co 2pp 15853, 322, 24X F1che: 50-322, 82/10/15,8210270125

- --8210270132 IE Insp Rept 50-322/82-24 on 820907-10 No noncompliance noted Major areas inspected actions on previous inspection/prevention program in areas of administrative controls & cable separation requirements RICHARDS.8 A , PLISCO.L R , BETTENHAUSEN.L Region 1, Office of Director 82/09/29 7pp 15853 324 24X Fiche 50-322,82/10/15,8210270125
- 8210260134 Ack receipt of 821007 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-322/82-15 STARDSTECKI.R Division of Project & Resident Programs POLLOCK.M S Long Island Lighting Co 2pp 15779 093 24X Fiche 50-322.82/10/20.8210260134
- --B210260141 Responds to NRC 820830 ltr re violations noted in 1E Insp Rept 50-322/82-15 Corrective actions startup mgt meeting held 820917 to revised documentation for all testing & PT 654 007 revised to incorporate exceptions POLLOCK.M B Long Island Lighting Co 82/10/07 STAR08YECKI.R Division of Project & Resident Programs 7pp. 15799.095 24X Fiche: 50-322,82/10/20,8210260134
- S Reportable occurrences. LERs & related correspondence
- 8210070384 Deficiency rept re analogue controllers supplied by Bailey Controls Co Initially reported on 820827. Circuit will be completed prior to fuel load.per E & DCR F-42213 & CCF M50/06
  MILLIOAN.M H Long Island Lighting Co 82/09/28, GRIER, B. H Region 1, Office of Director 3pp. 15633 346 24X Fiche 50-322. 82/09/28, 8210070384
- 8210280285 Interim deficiency rept re jacket water pump shaft failures on emergency standby diesel generators Initally reported on 820917 Design mods to jacket water pump shaft-impeller assembly underway Alterations to shaft expected MILLIGAN.M H Long Island Lighting Co 82/10/15 HAYNES.R.C Region 1. Defice of Director 3pp. 15837 040. 24X Fiche 50-322, 82/10/15,8210280285
- T Hearing transcripts on non-antitrust matters
- 8210150168 Testimony of MO Schiffmacher & WF Renz re Phase I emergency planning Contention 1(B) on prompt notification sys.Prof qualifications encl. SCHIFFMACHER, W, RENZ, WF Long Island Lighting Co. 82/10/12 21pp 15707 315. 24X Fiche 50-322,82/10/12,8210150168.
- --8210150178 Testimony of RE Linnemann & ML Hiele re Phase I emergency planning Contention 2(A) on adequate medical svs Prof qualifications & supporting documentation encl. LINNEMANN.R E, MIELE,N L Long Island Lighting Co. LINNEMANN.R E Radiation Management Corp. B2/10/12 32pp. 15707:336 24X Fiche 50-322,82/10/12,8210150168
- --8210150188 Testimony of NJ DiMascio & E Lieberman re Phase I emergency planning Contention 2(B) on ground transportation to hosp Prof qualifications & supporting documentation encl One aperture card available in FDR DIMASCIO, N, J, LIEBERMAN, E, Long Ieland Lighting Co. LIEBERMAN, E, KLD Associates, Inc. 82/10/12, 43pp. 1570B-006 24X Fiche 50-022,82/10/12,6210150168
- --5210150206 Testimony of B Aidikoff, HM Blauer, M Cordaro, E Lieberman & J Rivello re Phase I emergency planning Contention 4 on protective actions. Prof qualifications & supporting documentation encl Six aperture cards available in PBR AIDIKOFF, B, BLAUER, H H, CORDARO, M Long Island Lighting Co 82/10/12, 170pp. 13708.051. 24X Fiche. 50-322,82/10/12, 8210150168
- --8210150223 Testimony of MC Cordero, RR Dynes, DS Mileti & J Rivello re Phase I emergency planning Contention 5(A) on role conflict Prof qualifications encl CORDARO, M. C., DYNES, R. R., MILETI, D. S. Long Island Lighting Co 82/10/12 78pp 15708 222, 24X Fiche, 50-322, 82/10/12, 8210150168
- --8210190240 Testimony of NJ DiMascio & E Lisberman re Phase I emergency planning Contention 5(8) on traffic congestion affecting onsite emergency workers & offsite util personnel reporting to site Prof qualifications & supporting documentation encl. DIMASCIO, N J., LIEBERHAN.E. Long Island Lighting Co LIEBERHAN.E. KLD Associates, Inc. 82/10/12 34pp. 15708.299, 24X Fiche. 50-322,82/10/12,8210150168
- --B210150250 Testimony of HM Blauer, M Cordero & J Rivello re Phase I mergency planning Contention 7(B) on ability to augment procedures within 30 minutes Prof qualifications & supporting documentation encl.
  BLAUER, H. M., CORDARO, M., RIVELLO, J. Long Island Lighting Co. 82/10/12 40pp. 15708:333, 24X Fiche 50-322,82/10/12,8210150168.

- --8210150257 Testimony of HM Biguer, MC Cordaro & JF Schmitt re Phase I EULIDOXD7 Testimony of HM Blauer.MC Cordaro & JF Schmitt re Phase amergency planning Contention 10(B) on real time monitors Prof qualifications & supporting documentation encl BLAUER.H M . CORDARO.M.C . SCHMITT.JF Long Island Lighting Co 82/10/12 289pp 15709 031 24X Fiche 50-322.82/10/12.8210150168
- --8210150265 Testimony of JF Schmitt & JS Baron re Phase I emergency planning Contention 10(C) on accident assessment & monitoring Prof qualifications & supporting documentation BARON, J S Long Island Lighting Co BARON, J S Stone & Webster Engineering Corp 82/10/12 30pp 15709 321 24X Fiche 50-322.82/10/12.8210150168
- --B210150272 Testimony of MF Renz & P Friedman re Phase I emergency planning Contention (1(A), (B) & (C) on communications u/offsite response organizations Prof qualifications & supporting documentation enci RENZ.W F. FRIEDMAN.P Long Island Lighting Co 62/10/12 57pp 15709:351 24% Fiche 50-322.82/10/12,8210150168
- --8210150281 Testimony of JA Notaro & RL Poltrino re Phase I emergency planning Contention 13 on interim safety parameter display sys Prof qualifications & supporting documentation encil NOTARO, J A , POLTRINO, R. L. Long Island Lighting Co POLTRINO, R. L. Btone & Webster, Inc. 82/10/12 63pp 15710 046 24X Fiche 50-322,82/10/12,8210150168
- --8210150290 Testimony of JB Baron, MC Cordaro, NJ DiMascio, JN Hamawi, LP Pocalujka & JF Schmitt re Phase I emergency planning Contention 14 on accident & dose assessment models H/ Certificate of Svc Five aperture cards available in PDR BARON, JS , CORDARO, MC , DIMASCIO, NJ Long Island Lighting Co 82/10/12 117pp 15710 126 24% Fiche 50-322,82/10/12, 8210150168
- 9210150370 Transcript of 921012 hearing in Bethesda. MD Pp 11,309-11.484 Supporting documentation encl # Atomic Safety and Licensing Board Panel 82/10/12 194pp 15704 069 24X Fiche 50-322.82/10/12.8210150370
- 8210260232 Testimony of AC Kanen, JR Johnson, S Cole & KT Erikson on Contentions EP 28 & 58 re traffic congestion fasues. KANEN, A C. JOHNBON, J. H. COLE, E Suffolk County, NY 82/10/12 337pp. 15802 001 24X Fiche 50-322,82/10/12.8210260232 337pp. 15802 001
- --8210260239 Testimony of KT Erikson & 8 Cole on Contention EP 5A re role conflict ERIXBON.K T, COLE.B Buffolk County, NY. ERIKBON.K T Yalw Univ 82/10/12 95pp 15802 178 24X Fiche 50-322,82/10/12.
- --8210260242 Testimony of GC Minor on Contentions EP 108 & EP 10C re radiation monitoring & EP 14 re dose assessment MINDR. O C Suffolk County, NY 82/10/12 13pp 15802, 273, 24X Fithe 50-322, 82/10/12, 8210260232
- --8210260246 Testimony of FC Finleyson on Contention EP 14 re-accident assessment & dose assessment models.Certificate of Bvc encl. FINLAYSON, F. C. Buffolk County, NY 82/10/12 50pp 15802-286. 24% Fiche 50-322, 82/10/12,8210260232.
- 8210150166 Transcript of 821013 hearing in Bethesda, MD. Pp 11, 485-11.669-\* Atomic Sefety and Licensing Board Panel 82/: 15698 025. 24% Fiche 50-322,82/10/13,8210150166 82/10/13, 188pp.
- 8210180037 Transcript of 821014 hearing in Bethesda, MD Pp 11,670~ 11.882 Supporting documentation encl. \* Atomic Safety and Licensing Board Panel 82/10/14, 299pp 15720:327, 24X Fiche.50-322.82/10/14.8210180037
- 8210190338 Transcript of 821015 hearing in Bethesda, MD Pp 11,883-12:021. \* Atomic Sefety and Licensing Board Panel. 82/10/15 138pp 15742,322 24X Fiche: 50-322,82/10/15,8210190338
- 8210270004 Transcript of 821027 hearing in Bethesda, MD
- # Atomic Safety and Licensing Board Panel, 82/10/27 174pp. 15856:331 24X Fiche, 50-322,82/10/27,8210290004.

- DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents as nuclear reactor events & safety problems Forwards documents Critical Mass Energy Project 1: Fiche 50-000, 82/06/28, 8210010008
- --8008050265 Discusses addl required info to better define potential for 00000260 Discusses add required into to deter define potential foracking in reactor vessel norites
  NOONAN.V S Assistant Director for Materials & Qualifications
  Engineering 80/05/05 TEDESCO.R L Assistant Director for
  Licensing 2pp 15727 176 24X Fiche 50-000.82/06/28.8210010003
- 8210040429 Informs of decision to partially refund fees remitted w/ 800821 application to extend latest CP completion dates MILLER. H O License Fee Management Branch 82/09/21 FURBUSH.M Pacific Gas & Electric Co ip. 15597 262 24X Fiche 50-275.82/09/21.8210040429
- 8210130056 Responds to 820727 request for status rept on design verification program & briefing on proposed Phase II of program Info discussing background & current status encl DIRCKS,W J Qffice of the Executive Director for Operations 82/09/24 PALLADINO,N J. GILINSKY,V, AHEARNS,J F Commission 15692 284. 24X Fichs 50-275.82/09/24.8210130056
- 8210050144 Responds to Generic Ltr 82-12 re plant staff working hours Util administrative procedures address revised working CRANE.P A Pacific Gas & Electric Co 82/10/01 MIRAGLIA.F J Licansing Branch 3 lp 15605 161 24X Fiche 50-275.82/10/01, 8210050144
- 821025016B Forwards RH Engelken 820915 memo re RF Reedy. Inc exit meeting concerning GA audits for consideration in evaluation of GA program EIBENHUT, D. Q Division of Licensing 82/10/06 COOPER, H E Teledyne Engineering Bervices. 2pp 1580B 009 24X Fiche 50-275, 92/10/06, 8210250168
- --9210250392 Summary of 820910 meeting w/util & RF Reedy, Inc re GA as of in-house design GROELKEN.R H Region 5, Office of Director 82/09/15 DENTON: HR Office of Nuclear Reactor Regulation. Director 3,1 15808:011. 24% Fiche 50-275,82/10/06,8210250168
- 8210250240 Forwards independent design verification program community. riordokano rumeros inicependente design ventrication program tol Phase I final rept Rept should contain detailed descriptions of scope.criteria.methodology & models for all structures. sus & components sys & components COOPER.W.E Teledyne Engineering Services 82/10/07 DENTON-HR Office of Nuclear Reactor Regulation, Director ENGELECH, A H Region 5. Office of Director MANEATIB.O.A Pacific Oas & Elicibil Co 16pp 18789:150 24X Fiche 50-275, 82/10/07, 8210230240
- 8210080123 Notifies of 821007 meeting w/util in Ban Francisco.CA to discuss status of Phases I & II. instrument test rig for verification of corrective action & NRC 820819 ltr re fuel load.
  - + Teledyne Energy Systems 82/10/08 Teledyne En ip. 15640 129 24X Ficher 50-275,82/10/08,8210080123 Taledyne Energy System
- 8210290446 Staff requirements memo re 821007 affirmation/discussion to vote on extension of const completion dates for HPP88, purging of classified math in ALAB-653 & emergency preparedness & risks associated w/fuel loading CHILK, B. J. Office of the Secretary of the Commission 82/10/06 Office of the Secretary of the Commission 2pp 15863 189 242 Fiche 50-000, 82/10/08, 8210290446.
- 8210190470 Provides info re ownership of Bachtal Power Corp FRIEND.H B Bechtal Corp. 82/10/11. MIRAGLIA.F. J. Licensin Branch S. ip 15740.181 24X Fiche 50-275.82/10/11.8210190470
- 8210270351 Advises that Bechtel Power Corp is entity responsible for work on project Ownership held by officers of Bechtel Oroup, Inc. OFFICENCY HE Pacific Gas & Electric Co FRIEND, H B Becket (off 62/10/1). MIRAQLIA: F.V. Licensing Branch 3 ip. 15834-358 20 Fiche: 50-275, 82/10/11, 8210270351
- 8210150389 Suppl to 820719 application for amend to License PR-75 m security plan Encl withheld (ref 100FR73 21).

  CRANE, P A Pacific Gas & Electric Co 82/10/12. DENTON, M R .

  MIRAOLIA Office of Nuclear Resctor Regulation. Director 239 15703; 279 24% Fiche 50-275, 82/10/12, 8210150389.

- E210250291 Clarifies 821007 statement re required sys, structures & components for plant operating modes for independent design verification program COOPER.H E Teledyne Engineering Services 82/10/12 EISENHUT, D o Division of Licensing App 15790 191 24X Fiche 50-275,82/10/12, 8210250291.
- 5210290097 Requests explanation of process & chronology of events in which Teledyne discussed const QA review of plant w/util. Bethtel & S&W Info required to determine presence of conflict of interest Meeting requested EROWN, H H Kirkpatrick, Lockhart, Hill, Christopher & Phillips BRDMN, H H California, State of 82/10/12 COOPER, W E Teledyne Engineering Services 2pp 15859 361 24X Fiche 50-275,82/10/12,821029097
- S210290214 Provides NRC recommendation re Phase II of independent design verfication program Phase II program plan & requirement that Phase II revisu/evaluations be completed prior to fuel load/lou power decision approved DIRCKS.W J Office of the Executive Director for Operations SECY-82-414 82/10/13 61pp 15876 261 24X Fichs 50-275, 82/10/13,8210290214
- 8210190583 Advises that two former Bechtel employees will be retained on independent design verification program Individuals do not violate procedure on conflict of interest & will not verify work participated in as Bechtel employee COOPER.H E Teledyne Engineering Services 82/10/14 DENTON.H R Office of Nuclear Reactor Regulation. Director ENGELKEN,R H Region 5. Office of Director MANEATIB.O A Pacific Qas & Electric Co 3pp 15791 184 24X Fiche 50-275.82/10/14.8210190583
- 8210190584 Provides preliminary response to 820701 request for review of seven points re validaty of BNL results & generic implications in final rept concerning analysis of facility COOPER.H E Teledyne Engineering Services 82/10/15 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 15791 187 24X Fiche 50-275,82/10/15,8210190584
- B210250210 Identifies concerns resulting from review of URS/Blume containment annulus structure model evaluation Concerns resulted in issuance of EUI Files 3004 & 3007
  WRAY, R Teledyne Engineering Services B2/10/15 MANEATIS, 0 A Pacific Cas & Electric Co 4pp 1578B 292 24X
  Fiche 50-275, B2/10/15,8210250210
- 6210250318 Comments on Region 5 820915 memo re Phase II of independent design verification program.per 821006 request Change in Phase II not indicated COPPER.H E Teledyne Engineering Services 82/10/15 EISENHUT.D.O Division of Licensing 5pp. 15790 048 24X Fiche 50-275,82/10/15,
- F Security, medical, emergency & fire protection plans
- 6210210033 Releases public version of revised emergency plan implementing procedures
  FELTCN:J M Division of Rules and Records 82/10/01 Document Management Branch 1p 15782 091 24X Fiche 50-275,82/10/01, 82:10210033
- --B210210044 Forwards public version of revised amergency plan implementing procedures, including Procedure EP M-3 re chlorins release, EP M-5 re Tsunemi warning & EP M-8 re containment emergency personnel hatch CRANE, PA Pacific Gas & Electric Co 82/09/23 ENGELXEN, RH Region 5, Office of Director 3pp 15782 092 24X Fiche 50-275,82/10/01,8210210033
- -- 8210210048 Public version of revised emergency plan implementing procedures, including Procedure EP M-3 re chlorine release, EP M-5 re Tsunami warning & EP M-8 re containment emergency personnel hatch = Pacific Oas & Electric Co 82/09/13 84pp, 15782 095, 24X Fiche 50-275,82/10/01.8210210033
- B210150389 Suppl to 820719 application for amend to License DPR-76 re security plan. Encl withheld (ref 10CFR73 21). CRANE, P.A Pacrfic Gas & Electric Co. 82/10/12. DENTON, H.R Office of Nuclear Reactor Regulation, Director, 2pp 15703, 279 24x Fiche 50-275,82/10/12,8210150389
- G Adjudicatory correspondence
- 92:502:90447 Responds to 820512 petition requesting action under 10CFR2 206 For reasons stated in enclosed Director's Decision.getition denied DENTON.H R Office of Nuclear Reactor Regulation, Director 82/09/22. REYNOLDB.J. Center for Law in the Public Interest 5pp, 15863:166 24X Fiche:50-275.82/09/22.8210290449

- --8210270451 Director's Decision DD-82-10 denying Ctr for Law in Public Interest 820512 petition requesting NRC issue order to util to submit amend to DL to cover GA & GC issues DENTON, H R Defice of Nuclear Reactor Regulation, Director 82/09/22 7pp 15863 171. 24X Fiche 50-275,82/09/22,8210270449
- --8210290454 Notice of issuance of Director's Decision DD-62-10 under 100FR2 206 denying petition by Ctr for Law in Public Interest request to require util to submit amend to DL to cover GA & GC issues DENTON, H R Office of Nuclear Reactor Regulation, Director 82/09/22 3pp 10863 178 24X Fiche 50-275,82/09/22,8210270449
- 8210040102 Order extending time until 821005 for Commission to act to review ALAB-661 (CHILK 8 J Office of the Secretary of the Commission 82/09/30 Commissioners 1p 15581 025 24X Fiche 50-275,82/09/30,8210040102
- 8210050218 Reply to applicant & NRC 820924 briefs re status of pending appeals from authorization of low power operation No adequate factual basis exists to support A8LB dismissal of Joint Intervenor QA contention as moot M/Certificate of Svc. REYNOLDB, J. R. Joint Intervenors-Diablo Canyon REYNOLDB, J. R. Center for Law in the Public Interest 82/09/30 Atomic Safety and Licensing Appeal Panel 8pp 15611 237 24X Fichs 50-275, 82/09/30,8210050218
- 8210060220 Reply brief to other party briefs re mootness of low power contentions Emergency planning issues & certain other issues moot Certificate of Svc encl LOCKE.R F Pacific Gas & Electric Co 82/09/30 Atomic Bafety and Licensing Appeal Panel opp. 15620.190. 24X Fiche 50-275,82/09/30.8210060220.
- 8210040097 Reply to Governor Brown & Joint Intervenors 820924 filings in response to ABLB 820902 order on mootness of low power issues Emergency planning issues & some low power contentions mooted Certificate of Svc encl
  JONES, B W Hearing Branch i 82/10/0f Atomic Safety and Licensing Appeal Panel 9pp 15591 026 24% Fiche: 50-275, 82/10/01, 8210040097
- 8210050180 Reply brief to util & NRC 820924 briefs re moothess of low power issues, per ABLB 820902 order Issues not moot. Controversy still exists & issue is of practical significance Certificate of 8vc encl.

  BROWN, H. H. California, State of, BROWN, H. Kirkpatrick, Lockhart, Hill, Christopher & Phillips 82/10/01 Atomic Safety and Licensing Appeal Panel 8pp 15603 345 24% Fiche: 80-275, 82/10/01, 8210050180
- B210060186 Request for leave to withdraw certain exceptions to ASLB 820831 initial decision ASLB 820927 clarification of & local jurisdiction acquiescence to preconditions re BOPs render exceptions unnacessary Cartificate of Svc encl HASBELL, D.F. Hearing Branch 1 82/10/04 Atomic Bafety and Licensing Appeal Panel 5pp. 13613 193 24X Fiche 50-275.82/10/04, 8210060186
- 8210070145 Order extending time until 821008 for Commission to act to review ALAB-681. CHILK, S. J. Office of the Secretary of the Commission 82/10/05 Commissioners 1p. 15627 076 24X Fiche. 50-275, 82/10/05. 8210070145.
- 8210130272 Forwards San Luis Obispo County Board of Supervisors 820927 action approving San Luis Obispo County nuclear power plant emergency response plant & Stats of CA Senate Bill 1473 amending govt code. Certificate of Svc encl CRANE.P A Pacific Gas & Electric Co 82/10/06 BUCK, J. H., JOHNSON, M. R. HOORE, T. S. Atomic Safety and Licensing Appeal Panel. 6pp 15678 284, 24X Fiche 50-275,82/10/06.8210130272
- 8210120332 Order CLI-82-30 directing all natl security classified info be expunded from ALAB-653 & underlying record. Info not essential to ASLAB opinion & expunction would not prejudice any party or public.
  CHILK.S.J. Office of the Secretary of the Commission 82/10/08 2pp. 15652-108. 24X Fiche 50-275,82/10/08,8210120332.
- 8210130327 Order extending time until 821026 for Commission to act to review ALAB-681 CHILK, S. J. Office of the Secretary of the Commission. 82/10/08. Commissioners 1p. 15678 282. 24X Fiche: 50-275,82/10/08, 0210120207
- 8210210422 Order extending time until 821105 for Commission to act to review NRR Director 820922 deniel of Joint Intervenors 100FR2, 206 request. CHILK, 8 J. Office of the Secretary of the Commission 82/10/18, Commissioners, 1g. 19763,083 24X Fichs, 50-275,82/10/18, 8210210422

- 1

- 1

 $\rho^{\pm}$ 

iτ

1

8210280245 Hemorandum in response to util 820924 motion for clarification of ABLB 820831 initial decision Decision supports conclusion of law on adequacy of offsite emergency planning. MCLF, J.F. Atomic Safety and Licensing Spard Panel 82/10/24 2pp 15837 055 24X Fiche 50-275,82/10/26.8210280245

#### H Ceneral correspondence

- 8210220363 Advises that 821010 ltr requesting util recalculate seismic safety sys at plants will be sent to all parties OILINSKY.V Commissioners 82/10/20 SCHULKE.9. Affiliation Unknown 19 15779 201 24K Fiche 50-275.82/10/20.8210220363
- --8210220369 Urges util be forced to recalculate entire seismic safety sys at plant SCHULKE: S Affiliation Unknown 82/10/10 OILINSKY,V Commissioners ip 15779 202 24X Fiche 50-275,82/10/20, 8210220343.
- Q Inspection reports. IE Bullstins & correspondence
- 8210040133 Forwards IE Insp Repts 50-275/82-24 & 50-323/82-13 on 820724-30,0814-20 & 0830-0901 No noncompliance noted BIBHOP. I W Division of Resident, Reactor Project & Engineering Programs 82/09/17 CRANE.P.A Pacific Cas & Electric Co 2pp 15614 307. 24X Fiche-50-275,82/09/17,8210060133
- --8210060141 IE Insp Repts 50-275/82-26 & 50-323/82-13 on 820726-30, QBI6-20 & 0830-0901 No noncompliance noted Hajor areas inspected sate tour & mod to piping & electrical raceway supports resulting from revised annulus estimic spectra BURDOIN.JF . 2WETZIG.0 B Division of Resident, Reactor Project & Engineering Programs. 82/09/17 9pp 15614 311 24X Fichs 50-275,82/09/17,82i0060133
- 820B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl CDBB.L 1 Division of Fuel Facilities, Materials & Safeguards 82/10/06. Consolidated Edison Co of New York & 6pp 15761 250 24X Fiche: 50-000, 82/10/06, 820B190233
- 8208190238 IE Bullstin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Swy list enc!
  DEYGUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14, Consolidated Edison Co of New York 115pp 15810 125, 24X Fiche, 50-000, 82/10/14, 8208190238
- 8210280324 Forwards IE Insp Repts 50-275/82-30 & 50-323/82-14 on 820914-16 No noncompliance noted BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 82710714 CRANG.P A Pacific Qas & Electric Co 2pp 15839 019 24X Fiche 50-275,82/10/14.8210280324
- --8210280330 IE Insp Repts 50-275/82-30 & 50-323/82-14 on 820914-16 No noncompliance noted Major areas inspected implementation of independent verification program, including independent equalifications of personnel & implementation of GA program HORRILL-P J., ECKHARDT. J H., BISHDP. T N. Division of Resident, Reactor Project & Engineering Programs. 82/10/08 dpp 19839 O21. 24X Fiche: 50-275, 82/10/14, 8210280324
- R. Periodic operating reports & related correspondence
- 92i0250247 Bubmite Semimonthly Progress Rept 20 for 820902-1008. No open item repts issued, but two open item repts identified Individuals completed acceptable statements re-potential or apparent conflicts of interest REEDY.R F R.F Reedy. Inc. 82/10/08 DENTON,H R. Office of Nuclear Reactor Regulation. Director. ENGELKEN,R H Region 5, Office of Director MANEATIS, 9 A. Pacific Gas & Electric Co. 2pp. 15788 342. 24X Fiche 50-275,82/10/08,8210250247.
- 8 Reportable occurrences, LERs & related correspondence
- 8210250055 PNO-V-82-043 on BR1016.unusual event declared when grass fire started in 500 kV switchyard On B21017.three 500 kV circuits tripped.resulting in loss of all offsite power. Second unusual event declared.
  STERNBERG.D. M. Region 5. Office of Director. 82/10/16. ip. 15787:100. 24X Fiche 50-275.82/10/16.8210250035.
- T Hearing transcripts on non-antitrust matters
- 8210290370 Unofficial transcript of 821020 public discussion of Phase II revarification program in Washington, DC, Pp 1-113 Supporting documentation encl. \* Commissioners. 82/10/20, 144pp. 13865 095. 24X Fiche: 50-275, 82/10/20, 8210290370.

- 8210220416 Forwards transcript of Commission 821020 meeting to receive NRC briefing on proposed scope of Phase II of independent design verification program & 821019 meeting w/ util & participants re program & SECY-62-414 W/o encl CHILK-6 J Diffice of the Secretary of the Commission 82/10/21 Office of the Executive Legal Director ip 15779 211 24% Fiche 50-275, 82/10/21.8210220416
- DOCKET 50-324 BRUNSHICK STEAM ELECTRIC PLANT, UNIT 2

  F Security, medical, emergency & fire protection plans
- 8209140148 Forwards "Fire Protection of Cable Spreading Room,"
  evaluating quantity of transient combustibles necessary to
  cause ignition of most limiting cable Info supple 810306
  exemption request
  HOME, P. W. Carolina Power & Light Co. 62/09/08 DENTON, H. 8. 0//w.
  of Nuclear Reactor Regulation, Director 2pp 14782 001 24x
  Fiche 50-324, 82/09/08, 8209140148
- --8209140153 "Fire Protection of Cable Spreading Room"
  4 Carolina Power & Light Co 82/08/31 61p 14782 004 24t
  Fiche 50-324,82/09/08.8209140148
- 8210060316 Forwards revised Sections 5 & 6 to "Safe-Shutdown Capability Assessment & Proposed Mods"

  ZIMMERMAN, S R Carolina Power & Light Co 82/10/01 DENION, H R
  Office of Nuclear Reactor Regulation, Director ip 15616 033 Ac
  Fiche 50-324, 82/10/01, 8210060316
- --8210060323 Revised Sections 5 & 6 to "Bafe-Shutdown Capability Assessment & Proposed Mods " -- Carolina Power & Light Co 82/10/01 706pp 15616 034 241 Fiche 50-324, 82/10/01.8210060316
- 9210130295 Forwards responses to BNML & NRC Questions 1-6 result 820804 radiation shielding study for proposed emergency operations facility/technical support ctr Written concurrence requested by 821025 ZIMMERMAN.8 R Carolina Power & Light Co 82/10/11 VASSALLD.DJ Operating Reactors Denoth 2 3pp 15678 240 24X Fiche 50-324,82/10/11,8210130275
- 8210220489 Ack receipt of 821006 Itr informing NRC of steps talen to correct violations noted in IE Insp Repts 50-324/82-30 & 50-325/82-30

  VERRELLI.D M Division of Project & Resident Programs 02/10/18

  UTLEY, E E Carolina Power & Light Co 1p 15779 087

  24X
- --B210220492 Responds to NRC 820907 ltr re violations noted in IE Pr;
  Repts 50-324/82-30 & 50-325/82-30 Corrective actions
  technician counseled re compliance w/Maint Instruction
  MI-10-2J Fire Protection Procedure FP-14 will be revised
  DIETZ.6 R Carolina Power & Light Co 82/10/06 O'REJLLY.JP
  Region 2. Office of Director 2pp. 15779 088 24X
  Fiche 50-324, 82/10/16, 8210220489
- --8210220496 Notice of violation from insp on 820715-0815 \*\* Division of Project & Resident Programs 82/09/07 1 15779:092 24X Fichs:50-324, 82/10/18,8210220489
- --8210220503 IE Insp Repts 50-324/82-30 & 50-325/82-30 on 020715-0815 Noncompliance moted on 820805; safety-related equipment Msin1 Instruction MI 10-21 incorrectly performed & Fire Protection Procedure FF-14 Step III A improperly implemented on 820718 MYERB: B D , GARNER: L. W., CHABE, J Division of Project & Resife's Programs 82/09/03, 9pp. 15779 093 24X Fichs 50-324,82/10/13 8210220489
- 8210280275 Forwards corrected pages to rept submitted in conjuction u/820708 cable spread room examption request & Pages A. 3-7-A 3-10 inadvertently omitted, ZIMMERMAN, 8 R Carolina Power & Light Co 82/10/22 DENIGN. R Office of Nuclear Regulation, Director 1p 15837 295 24 Fichs. 50-324, 82/10/22, 8210280275
- ---8210280278 Corrected & add1 pages to "Fire Protection of Cab)\* Spreading Room." \* Caroline Power & Light Co 62/10/22 Spp 15837 278 24 Fiche: 50-324, 82/10/22, 8210280275
- H General correspondence
- 8210010028 Requests NRC direct all official correspondence to EE Uliv. util vice-president, due to 820730 retirement of JA Janes JONES, J A Carolina Power & Light Co 82/07/27 DENYON, H R. Office of Nuclear Reactor Regulation, Director, ip. 15385 314 Particle: 50-000, 82/07/27, 8210010028

- 8210130323 Requests changes to distribution list for NUREG-0020, 'Licensed Operating Reactors - Status Summary Rept "
  ZIMMERMAN, S R Carolina Power & Light Co 82/10/11 BESBE, M R
  ADP Systems Development Branch 2pp 15683 361 24X
  Fiche 50-000, 82/10/11,8210130323
- P Operating license stage documents & correspondence
- 8207180044 FOIA request for all internal non-public documents, memos, evaluation repts & other math dealing w/nuclear plant operations MCINNIS, D. News & Observer 82/08/17 Office of Administration ip 15860 064 24X Fiche 50-000,82/08/17,8207180044
- 6210040006 Forwards revised Tech Specs to Amend 72 to License DPR-62, correcting errors in total peaking factor values for Cycle 5.
  - VASSALLO.D B Operating Reactors Branch 2 82/08/30 JONES, J A Carolina Power & Light Co 2pp 15577 275 24K Fiche 50-324, 82/08/30, 8210040006
- --8210040007 Revised Yech Specs to Amend 72 to License DPR-62, correcting errors in total peaking factor values for Cycle 5

   Operating Reactors Branch 2 82/08/30 1p 15577 277 24X
  Fiche 50-324,82/08/30,8210040006
- 8210120626 Advises that proposed interim changes for shift technical advisor training program acceptable up to Apr 1783 VASSALLO, D B Operating Reactors Branch 2 82/09/15 JONES, J A Carolina Power & Light Co 3pp 15672 266 24X Fichs 50-324, 82/09/15, 8210120626
- 8210280013 Responds to FDIA request for all internal non-public documents memos, evaluation repts & other math dealing w/ nuclear plant operations Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/09/17 MCINNIS. D News & Observer 5pp 15860 065 24X Fiche 50-000, 82/09/17, 82-10380013
- --7905270357 Augmented offgas sys shall be used at all times & util should be informed COLLINS-J T Effluent Treatment Systems Branch 79/05/03 TPPOLITO-T A Operating Reactors Branch 3 (Pre 790525) 1p 15860 087 24X Fiche 50-000.82/09/17.8210280013
- --7912280014 Advises of util 791025 interim commitment for demonstrating compliance w/400FR190 Commitment acceptable but must include direct radiation per section 6 of NUREO-0473. Revision 2 BANGART: Effluent Treatment Systems Branch 79/11/23 IPPOLITO.T Operating Reactors Branch 3 (Fre 800428) ip. 15860 088 24X Fiche 50-000, 82/09/17, 8210280013
- --8101140002 Confirms 801126 teleon re possible willful violation of reporting requirements IE lacks specific details necessary to make referral determination WARD. W J Office of Inspection & Enforcement. Office of the Director 80/12/02 FORTUNA: R Office of Inspector & Auditor \$p 15860 095 24X Fiche:50-000,82/09/17.8210280013
- --81 04290774 Notifies that applicant should be informed that major change to raduate treatment sys will require 100FRSO 90 review Requests info to show conformance w/App I & mod can meet acceptance criteria of SRP in NUREO-0800 GAMMILL-W P Effluent Treatment Systems Branch 81/04/06 EPPOLITO.T A. Operating Reactors Branch 2. 1p. 15860:226 24X Fiche 50-000,82/09/17,8210280013
- --- 81 12020885 Forwards request for addl licensee info re proposed second expansion of spent fuel pool & estimate of vol of soild waste generated by scrapping existing racks Info needed by 81118

  KREGER, W. E. Assistant Director for Radiation Protection 81/10/27. NOVAK, T. Assistant Director for Operating Reactors 2pp 15840 231 24X Fiche. 50-000, 82/09/17, 8210280013
- --Bi 12300287 Forwards Effluent Treatment Bys Branch safety evaluation input re spent fuel pool expansion application.per review of util 800416 submittal KREOSR.W E Assistant Director for Radiation Protection El/11/27. NOVAK.T H Assistant Director for Operating Reactors. 13pp 15860 249 24% Fiche 50-000,82/09/17,8210280013
- --B2011202B0 Advises that Billi2 ltr recommended improvement of dose fine to calculation methodology & licensee accepted by Bill25 ttr Other edit changes assured new methodology use every Bi days & nuclide dose factor inclusion in ETB.

  GAMMILL.W P Radiological Assessment Brench Bill2/08 [PPOLITO: TA Operating Reactors Branch 2 ip. 15840 264 24) Fiche 50-000, 82/09/17, 8210280013

- --8203080197 Advises that replacing Phrase 12 "Consecutive Months" w/phrase "Calendar Yr" in Tech Bpec 2.5.2 b acceptable Change would reduce recordseping MDUSTON,R W Assistant Director for Radiation Protection 82/02/11 NDVAN,T H Assistant Director for Operating Reactors 2pp 15861 014 24X Fiche 50-000,82/09/17,8210280013
- --8205170128 Advises that review of NUREO-0737, Item II F 1, has been satisfactorily completed & considered closed HQUSTON, R W Assistant Director for Radiation Protection 82/04/16 NOVAK, T M Assistant Director for Operating Reactors. 1p 18861 040 24X Fiche 50-000, 82/09/17, 8210280013
- --8206220591 Submits backgrouped info on conversation w/util re 82016 loss of RHR syc water event at facility.LER 82-005/01T MOLF.TR Director's Offics 82/06/04 RUBIN.S Director's Office 5pp. 15861 326 24X Fiche 50-000.82/09/17,8210280013
- --9207120140 Trip rept of 820324 visit to facility re aquipment environ qualification problems List of site visit/meeting participants & related info encl EL-ZEFTANY, M., WOLF, T. R. Director's Office 82/07/04 KICHELSON.C. Director's Office 12pp 15861-314 24X Fiche 50-000, 82/09/17, 8210280013
- --8210280021 Recommends that facility conlant activity limits be changed to conform w/BTS
  E18ENHUT,D Q. Division of Operating Reactors 74/07/06.
  GDLLER.K R Assistant Director for Operating Reactor Projects (Pre 791030). 3pp 15860-074 24X Fiche 50-000,82/09/17,8210280013
- --8210280024 Advises that util 7805(8 response to proposed plans for correcting problems concerning augmented offgas sys unacceptable Effluent Tech Specs should be amended COLLING, J Y Effluent Treatment Systems Branch 78/06/02 LEAR, O Operating Reactors Branch 78/06/02 LPB60 077 24X Fiche 50-000, 82/09/17, 8210280013
- ---8210280027 Notifies that commitment schedule for implementing operable augmented offgas sys unacceptable Thermal recombiners for use in EWR offgas sys will not satisfy criteria COLLING.J T Effluent Treatment Systems Branch. 78/07/06 (PPDLITO.T Operating Reactors Branch 3 (Pre 800428) 3pp 15860 079 24X Fiche 50-000, 82/07/17,8210280013.
- --8210280031 Requests technical assistance to review recent events at facilities & to assess safety & environ significance STELLO, V Division of Operating Reactors, 78/08/03 MULLER, D Division of Site Safety & Environmental Analysis 2pp. 15860.084 24X Fiche 50-000,82/09/17,8210280013
- ---8210280047 Notifies that potential for criminality found re Region 4 investigation resulting from W Ward 801202 memo constraing facility FORTUNA:R A Office of Inspector & Auditor 80/12/03. Office of Inspector & Auditor 80/12/04. 82/09/17.8210280013
- --8210280095 Assumes responsibility for review of Case 81-17 for criminality No criminality indicated Case should be closed.

  BMITH, R M Office of Inspector & Auditor, 82/08/24 Office of Inspector & Auditor, 82/08/24 Office of S210280013.
- --8210280100 Notifies that on 820224.C Alderson advised that rept sent repossible willful violation of reporting requirements & falsification of QA & guard qualification records at facilities

  RESNER, M E Office of Inspector & Auditor 82/03/01 Office of Inspector & Auditor. Ip 15861 039. 24X Fiche, 80-000, 82/09/17, 821038013.
- 8210010051 Ack receipt of 820823 ltr requesting temporary relief from commitments re training of shift technical advisors. Program approved & request forwarded to NRR for evaluation O'REILLY, J.P. Region 2. Office of Director 82/09/20 JONES, J. A Carolina Power & Light Co. 1p 15565:322. 24X Fiche 50-000. 82/09/20, 82/0010051
- 8210050362 Application to amend Licenses DPR-71 & DPR-62, revising Tech Specs to clarify requirements for verifying operability of scram discharge vol vent & drain valves. Class I & II license amend fees encl EURY, L W Carolina Fower & Light Co 82/09/29, VASBALLD, D B Operating Reactors Branch 2 2pp 15608:345 24X Fiche:50-324,82/09/29,8210050362
- --B210050371 Proposed Tech Spec 4. 1. 3. 1. 1 re surveillance requirements verifying operability of scram discharge vol vent & drain valves.

  \* Caroline Power & Light Co 82/09/29 2pp 15608.347 24x Fiche: 50-324,82/09/29,8210050362.

- 8210270110 Advises that plant venting capability acceptable to resolve NUREO-0737. THI Item II B i re high point vents VASSALLO, D B Operating Reactors Branch 2 82/10/01 JONES, J A Carolina Power & Light Co 3pp 15866 338 24X Fiche 50-324,82/10/01,8210270110
- --8210290113 "Operating Reactors TMI Lessons Learned NUREG-0737 Response Evaluations (Program II):Project 1:RCB Vents for Brunswick 1 & 2," final technical evaluation rept e Laurence Livermore Laboratory FIN A-0246-2 82/07/15 BUTCHER.E . BARNHART.B Division of Licensing 4pp 15866 341 24X Fiche 50-324.82/10/01.8210290110
- 8210150030 Forwards submittal schedule for responses to NRC 820909 issues re THI Action Items II F 1,4,5 % 6 % II E 4 2 7. Tech Spec revisions, containment vent & purge, electrical distribution sys voltages & control of heavy loads ZIMMERMAN, S. R. Carolina Power & Light Co 82/10/12 VASSALLO, D 3 Operating Reactors Branch 2 2pp 15701-268 24X Fiche 50-324,82/10/12,8210150030
- 8210260244 Advises that response to NRC 820827 request to justify differences between existing control room & NUREO-0737. Item III D 3 4 suggestions will be provided by 830131. Requests re-evaluation of improvement cost-benefits EURYL H Carolina Four & Light Co 82/10/21 VASSALLO.D B Operating Reactors Branch 2 1p 15799 353 24X Fiche 50-324.82/10/21.8210260244
- 8210260323 Application for amend to Licenses DPR-71 & DPR-62.clarifying portions of 810521 submittal re hydraulic snubber surveillance EURY, L W Carolina Power & Light Co 82/10/21 VASBALLO.D B Operating Reactors Branch 2 2pp 15799 338 24X Fiche 50-324,82/10/21.8210260323
- --8210260325 Revised Tech Specs re hydraulic snubber survaillance + Carolina Power & Light Co. 82/10/21 2pp 15799 340. 24) Fiche 50-324,82/10/21.8210260323
- 8210260405 Withdraws request for amend to Licenses DPR-71 & DPR-62, revising Tech Spec re reportability of inoperable reed switches in rod position indication sys to reduce number of routine LERs EURYL W Carolina Power & Light Co 82/10/22 VASSALLO, D B Operating Reactors Branch 2 2pp. 15806 239, 24X Fiche 30-324, 82/10/22, 8210260405
- Q Inspection reports: IE Bulletins & correspondence
- 8210080015 Addl response to FOIA request for 17 categories of info re nuclear reactor evants & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON,J M Division of Rules and Records. 62/07/12 UDELL.R A Critical Mass Energy Project 9pp. 15665.027 24X Fiche 50-000.82/07/12.8210080015
- --B210080122 Bystematic assessment of licensee performance notes refacility evaluation for Apr 1979-Mar 1980.

  NRC No Datailed Affiliation 91ven 80/03/31 App 15667 321 24% Ficher 50-000, 82/07/12, 8210080015.
- 8210010132 Forwards IE Insp Repts 30-324/82-31 t 50-325/82-27 on 820807-13 No noncompliance noted VERRELLI.D.M Division of Project t Resident Programs 82/09/01, JONES, J A Carolina Power t Light Co. 2pp 15567:230, 24X Fiche: 30-324, 82/09/01, 8210010132
- --B210010137 IE Insp Repts 50-324/B2-31 & 50-325/B2-27 on B20B09-13 No noncompliance noted. Major areas inspected ALARA, redirective mat1 transportations radioactive liquid effluent monitoring & nat1 control ALBRIOHT, R. H., BARR, K. P. Division of Engineering & Technical Programs 82/08/31 5pp. 15567 232. 24X Fiche 50-324, 82/09/01, B210010132
- B210010112 Forwards summary of B20824 enforcement meeting at Region 2 ofc re status of action items contained in B20702 & 20 confirmation of action itrs
  O'REILLY, J. P. Region 2, Office of Director. B2/09/03 JONES, J.A.
  Carolina Power & Light Co. 1p. 15566-029 26X
  Fiche 50-324.82/09/03,8210010112

- ---8210010124 Summary of 820824 meeting w/util in Atlanta, GA re status of action items contained in 820702 & 20 confirmation of action ltrs Util committed to formally submit long-term program details in Nov 1982

  LEMIS.R C Division of Project & Resident Programs 82/09/03

  Division of Project & Resident Programs 2pp 15566 030 24%

  Fichs 50-324,82/09/03.8210010112
- 8210010170 Ack receipt of 820816 response to 820716 notice of violation of civil penalties Rept on major program objectives to be submitted by 82101 should provide sufficient info re testing aspects of training programs AXELRAD, J Enforcement Staff 82/09/15 JONES, J A Carolina Pc., at Light Co 2pp 15568 109 24X Fiche 50-320.82/09/15,8210310172
- --8210010193 Forwards IE Insp Repts 50-324/82-02 & 50-325/82-02 63 820104-07. Enforcement action addressed to util in 820715 litr LEWIS,R C Division of Project & Resident Programs 82/07/16 JONES, J A Caroline Power & Light Co 2pp 15568 124 24K Fiche 50-325,82/09/15.8210010170
- --8210010206 IE Insp Repts 50-324/82-02 & 50-325/82-02 on 820106-07 Noncompliance noted Unit 1 instrument D-1 inoperable & level channel not tripped between 811226-31 GARNER.L. JULIAN.C. BURGER.C. Division of Project & Resident Programs 82/05/13 6pp 15568 126 24X Fichs 50-325,82/09/15 8210010170
- 8210010171 Ack receipt of B20702 & 0903 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts
  50-324/82-18 & 50-325/82-18
  VERRELLI, D M Division of Project & Resident Programs 82/09/86
  JONES, J A Carolina Power & Light Co 1p 15568 091 24X
  Fiche 50-324, 82/09/16, 8210010171
- ---8210010183 Suppls 920702 response to NRC 920604 ltr re violations rin IE Insp Repts 50-324/8R-18 & 50-325/8R-18 Corrective actions responsible operators counseled & 1A-1 bettsry charger clearance removal reviewed DIETZ.C R Carolina Power & Light Co 82/09/03 G'REILLY.J F Region 2. Office of Director. 3pp 15568 092 24X Fichs 50-324,82/09/16.8210010171
- --8210010188 Responds to NRC 820604 ltr re violations noted in IE 1/4; Repts 50-324/82-18 & 50-325/82-18 Corrective actions double verification program established on 820601 DIETZ, C.R. Carolina Power & Light Co. 82/07/02 O'REILLY, J.P. Region 2. Office of Director . 2pp. 15568-095 24X Fiche 50-324-82/09/16; 8210010171
- --B210010194 Forwards IE Insp Repts 50-324/82-18 & 50-325/82-18 4s 820415-0515 & notice of violation LDNG,F.J Division of Project & Resident Programs 82/05/04 UDNES,J A. Carolina Power & Light Co 2pp 15568 097 241 Fiche
- ---8210010199 Notice of violation from insp on 820415-0515 \* Region 2, Office of Director 82/06/04 1p 15568 099 241 Fiche 50-324,82/09/16,8210010171
- --8210010205 IE Insp Repts 50-324/82-18 & 50-325/82-18 on 920415-05.1 Noncompliance noted Operating Procedure DP-43 & tag readyll for Cleanance 1-459 inadequately implemented MYERB, D Q , QARNER, L W, BURGER, C W Division of Project k Resident Programs 82/06/04, 9pp 15568 100 24X Fiche, 50-324, 82/09/16, 8210010171
- 8210010336 Advises that IE Insp Rept 50-325/82-36 was inedvertently labeled 50-325/82-30 VERRELLI, D.M. Division of Project & Resident Programs 62/07/16 JONES, J.A. Caroline Power & Light Co. 1p 15571 001 241 Fichs: 50-324, 82/07/16, 8210010336
- ---8210010340 Forwards IE Insp Repts 50-324/82-32 & 50-325/82-36 to 820824-27, No noncompliance noted VERRELLIP. M Division of Project & Resident Progress 62/07/3 JONES, J A Caroline Power & Light Co 2pp 15578 CO2 24f Fiche: 50-324, 82/09/16, 8210010336
- --8210010350 IE Insp Repts 50-324/82-32 & 50-325/82-36 on 820824 27 k noncompliance noted Major areas inspected pre-startup reviews, comporate nuclear sefety reviews, post-maint testing & plant mods involving Tech Bacc changes FREDRICKSON,P., JACKSON,L.H., UPRIGHT.C.M. Division of Engineer & Technical Programs. 82/09/10 4pp 15571 004 24X Fiche: 50-324,82/09/16,8210010336

- 8210010391 Ack receipt of 820907 Itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-25 & 50-325/82-25
  - 50-329/82-25 LENIS.R C Division of Project & Resident Programs 82/09/22 JONES J A Carolina Power & Light Co ip 15572 269 24X Fiche 50-324.82/09/22.8210010391
- --B210010399 Responds to NRC B20813 ltr re violations noted in IE Insp. Repts 50-324/82-25 & 50-325/82-25 Corrective actions plant operating procedures rewritten & signoffs added Operations engineer responsible for procedure changes.

  DIETZ.C.R. Carolina Power & Light Co. B2/09/07 O'REILLY, J.P. Region 2, Office of Director 2pp 15572 270 24X
  Fische 50-324,82/09/22,8210010391
- --8210010405 Forwards IE Insp Repts 80-324/82-25 & 50-325/82-25 on 820615-0715 & notice of violation LEWIS.R C Division of Project & Resident Programs 82/08/13 JONES.J A Carolina Power & Light Co 2pp 15572 272 24X Fiche 50-324.82/09/22.8210010391
- --9210010410 Notice of violation from insp on 920615-0715 \* Division of Project & Resident Programs 82/08/13 2pp 15572 274 24% Fiche 50-324, 82/09/22,8210010391
- --B210010415 IE Insp Repts 50-324/82-25 & 50-325/82-25 on B20515-0715 Noncompliance noted failure to implement & maintain aperating procedures for startup & shutdown MYERS,D O. GARNER,L W., STETKA,T Division of Project & Resident Programs B2/08/12 13pp 15572 276 24X Fiche 50-324,82/09/22,8210010391
- BZ10150100 Ack receipt of 820913 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-26 & 50-325/82-26 LENIS.R C Division of Project & Resident Programs 82/09/24 JONES.J A Carolina Power & Light Co ip 15701 164 24X Fiche 50-324,82/09/24,8210150100
- -8210150106 Responds to NRC 820817 ltr re violations noted in IE lnsp Repts 50-324/82-26 & 50-325/82-26 Corrective actions new comprehensive post-testing program being developed DIETZ.C R Carolina Power & Light Co 82/09/13 O'REILLY, J P Region 2. Office of Director 2pp 15701 165 24X Fiche 50-324,82/09/24,8210150100
- B210150113 Forwards IE Insp Repts 50-324/B2-26 & 50-325/B2-26 on B20712-16 & notice of violation LEMIS.R C Division of Project & Resident Programs B2/09/17 JUNES.J A Carolina Power & Light Co 2pp 15701 167 24X Fiche 50-324,82/09/24,8210150100
- -8210150120 Notice of violation from insp on 820712-16 + Division of Project & Resident Programs 82/08/17 2pp 15701 169 24X Fiche 50-324, 82/09/24,8210150100
- -8210150132 IE Insp Repts 50-324/82-26 & 50-325/82-26 on 820712-14. Noncompliance noted failure to provide measures to preclude bypa-sing required testing EKINNER.P H , JACKSON.L H , UPRIGHT.C M Division of Engineering & Technical Programs 82/08/19 7pp 15701-171 24X Fiche 50-324.82/09/24,8210150100
- 210150108 Forwards IE Insp Repts 50-324/82-35 & 50-325/82-35 on E20908-10 No noncompliance noted VERRELLI,D H Division of Project & Resident Programs 82/09/24 JONES,J A Carolina Power & Light Co 2pp 15701 149 24X Fiche 50-324,82/09/24,8210150108
- -8210150114 IE Insp Repts 50-324/82-35 & 50-328/82-35 on 820908-10 No noncompliance noted Major areas inspected review & evaluation of changes to inservice insp program & program for document control & data retention COLEY, J L., BLAKE, J J Division of Engineering & Technical Programs 82/09/21 3pp 15701 151 24X Fiche 50-324,82/09/24,8210150108
- 210150162 Forwards IE Insp Repts 50-324/82-33 & 50-325/82-31 on B20901-03 & 10 No honcompliance noted VERRELLI,D M Division of Project & Resident Programs B2/09/24 JONES,J A Carolina Power & Light Co 2pp 15707-304 24X Fiche 50-324,82/09/24,8210150162
- -8210150170 IE Insp Repts 30-324/82-33 & 50-325/82-31 on 820701-03 & 10. No noncompliance noted Major areas inspected IE Bulletin 79-14. "Setsmic Analysis for As-Built Safety-Related Piping Sys "

  ANO. W P , BLAKE, J Division of Engineering & Technical Programs 82/09/23 Spp 15707 306 24X Fiche. 50-324, 82/09/24, 8210150162

- 8210150008 Ack receipt of 820819 & 0915 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-23 & 50-325/82-23 LEMIS R.C. Division of Project & Resident Programs 82/09/30 JONES JA. Carolina Power & Light Co. 1p 15698 349 24X Fiche 50-324.82/09/30.8210150008
- --8210150016 Revises response to NRC ltr re violations noted in IE Insp. Repts 50-324/82-23 & 50-328/82-23 Corrective actions assessment of inservice insp. program in progress Violation will be fully addressed by 821231
  DIETZ.C R Carolina Power & Light Co. 82/09/15 D'REILLY.J P. Rejion 2. Office of Director 2pp. 15698 350 24X
  Fiche 50-324,82/09/30,8210150008
- --82i0150023 Responds to NRC 920719 ltr re violations noted in IE Insp Repts 50-324/82-23 & 50-325/82-23 Corrective actions post-maint testing program revised & inservice insp program under review DIETZ.C R Carolina Power & Light Co 82/08/19 D'REILLY.J P Region 2. Diffice of Director 3pp 15698 352 24X Fiche-50-324.82/09/30.8210150008
- --8210150034 Forwards IE Insp Repts 50-324/82-23 & 50-325/82-23 on 820615-18 & notice of violation LEWIB:R C Division of Project & Resident Programs 82/07/19 JONES, J A Carolina Power & Light Co 2pp 15698.355 24X Fiche 50-324,82/09/30,8210150008
- --B210130040 Notice of violation from insp on B20615-18 LEMIS.R.C Division of Project & Resident Programs 82/07/17 Zpp. 15698 357 24% Fiche 50-324.82/07/30.8210150008
- --8210150063 IE Insp Repts 50-324/82-23 & 50-325/82-23 on 820615-18
  Noncompliance noted failure to re-establish baseline data
  for RHR svc water pump & to include main steam giping in
  inservice insp program
  BLAKE, J. J. ECONOMOS, N. Division of Engineering & Technical
  Programs 82/07/15 4pp 15698 359 24% Fiche 50-324, 82/07/30,
  8210150008
- 8210220139 Forwards IE Insp Repts 50-324/82-38 & 50-325/82-38 on 820907-10 No noncompliance noted.

  VERRELLI,D M Division of Project & Resident Programs 82/10/04 JONES, J A Carolina Power & Light Co 2pp 15778 107 24X Fiche: 50-324, 82/10/04, 8210220139.
- --B210220147 IE Insp Repts 50-324/82-38 & 50-325/82-38 on 820707-10 No noncompliance noted Major areas inspected followop insp of NRC & licensee identified tasks to be completed prior to startup WHITENER, H L , KRUG, H E , JAPE, F Division of Engineering & Technical Programs 82/09/30 Spp 15778 109 24X Fiche 50-324,82/10/04/8210220139
- 8210220169 Forwards IE Insp Repts 50-324/82-34 & 50-325/82-33 on 820815-0915 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/10/04 JDNES, J A Caroline Fower & Light Co. 2pp 15778,045, 24X Fiche' 50-324,82/10/04,8210220169
- --8210220173 IE insp Repts 50-324/82-36 & 50-325/82-33 on 820815-0915 No noncompliance noted Major areas inspected review of LERs, operational sefety verification & audit of surveillance & maint activities.

  HYERS, D 0 : OARNER, L W : BURGER, C : Division of Project & Resident Programs : 82/10/01 | 8pp : 15778 047 | 24X Fiche: 50-324,82/10/04,8210220169
- 8210130036 Ack receipt of 820816 & 0924 ltrs informing NRC of steps taken to correct violations noted in IE Inep Repts 50-324/82-20 & 50-325/82-20.

  LEMIS.R C. Division of Project & Resident Programs, 82/10/05, JONES.J.A. Carolina Power & Light Co ip 15701:135 24X Fiche. 50-324, 82/10/05, 8210150036.
- --921015003B Supple 820816 response to NRC 820719 ltm re violations noted in IE Insp Repts 50-324/82-20 & 50-325/82-20 Add1 info re revision to Procedure GRAB 80-1 to assure timely corrective actions to future audit findings provided.

  DIETZ, C. R. Carolina Power & Light Co. 82/09/24 O'REILLY, J. P. Region 2, Office of Director. 2pp 15701-136. 24X Fichs 50-324, 82/10/05, 8210150036
- --8210150045 Responds to NRC 820717 ltr re violations noted in IE Insp Repts 50-324/82-20 % 50-325/82-20 Corrective actions. Frocedure CGAD 80-1 revises & frequency of plant audits increased to reduce audit scope. DIETZ, C.R. Carolina Power & Light Co. 82/08/16, 0/REILLY, J.P. Region 2: Office of Director 3pp 15701.138 24X Fiche. 50-324, 82/10/05, 8210150036

100

g B

1

to j

- 8210150048 Forwards IE Insp Repts 30-324/82-20 & 50-325/82-20 on 820507-08 & notice of violation W/o notice of violation LEMIS.R C Division of Project & Resident Programs 82/07/19 JONES J A Carolina Power & Light Co 2pp [5701 ]41 24X Fichs. 50-324,82/10/05,8210150036
- -8210150052 IE Insp Repts 50-324/82-20 4 50-325/82-20 on 820407-08 Noncompliance moted failure to establish measures to assure groupt corrections to adverse GA conditions & failure to distribute audit within required timefram BELISLE, GA, UPRIGHT, CH Division of Engineering & Technical Programs 82/07/15 4pp 15701 143 24X Fache 50-324.82/10/05, 8210150036
- 8210150288 Ack receipt of 820714 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/62-21 & 50-324/62-21 & 50-324/62-21 Degree of the state of the state
- --8210150295 Responde to NRC 820818 ltr re violations noted in IE Insp Repts 50-324/82-2t & 50-325/82-2t Corrective actions relief valves which can communicate w/primary containment added to Type C testing program & review of leakage continuing DIETZ.C R Carplina Power & Light Co 82/09/14 J'REFLLY, J P Region 2, Office of Director 2pp 15706 127 24X Fichs 50-324, 82/10/05, 8210150288
- B208190233 IE Info Notice 80-35, Suppl t, "Leaking & Dislodged I~125 Implant Seeds " Svc list and COBB.L I Division of Fuel Facilities, Materials & Sefeguards 82/10/06 Consolidated Edison Co of New York & App 15761 250 24% Fich \$ 50-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corresion Cracking in Thick-Wall, Large-Diameter: Stainless Steel: Recirculation Bys Piping at BWR Plants " Svc list encl DEYOUNG: R C Director's Office. Office of Inspection and Enforcement 82/10/14 Cangolidated Edison Co of New York [15pp 15810 125 24% Fiche 50-000,82/10/14:8208190238
- 8210220489 Ack receipt of 821006 ltr informing NRC of steps taken to correct violations noted in LE Insp.Repts 50-324/82-30 t 50-325/82-30
  VERRELLI.D M Division of Project & Resident Programs 82/10/18
  UTLEV.E E Carolina Power t Light Co [p 15779 087 24X
  Fichs 50-324,82/10/18,8210220489
- --8210220492 Responds to NRC 820907 ltr re violations noted in IE Insp Repts 30-024/82-30 t 50-325/82-30 Corrective actions technician cousseled re compliance withint instruction MI-10-2J Fire Protection Procedure FP-14 will be revised DIETZ.C R Carolina Power t Light to 82/10/06 t/PELLLY.J P Region 2. Office of Director 2pp 15779 098 24% Fichs 50-324,82/10/18.6210220489
- ~-B210220494 Forwards IE Insp Repts 50~324/B2-30 & 50-325/B2-30 on 820715-0815 & notice of violation VERRELLI, D M Division of Project & Resident Programs 82/09/07. JONES, J.A. Garolina Power & Light Co. 2pp. 15779 090 24X Fichs 50-324, 82/10/18, 8210220489
- --8210220496 Notice of violation from insp on 820715-0815
  \* Bivision of Project & Resident Programs, 82/09/07 15779,092 24% Fiche; 50-324,82/10/18,8210220489
- --8210220503 IE insp Repts 50-324/82-30 & 50-325/82-30 on 820715-0815 Noncompliance noted:on 820805.mafety-related equipment Maint Instruction KI 10-2J incorrectly performed & Fire Protection Procedure FP-14 Step III A improperly implemented on 820718 MYERS.D U , GARNER.L.N , CHASE.J. Division of Project & Resident Programs 82/09/03 9pp 15779 093. 24X Fiche 50-324,82/10/18,8210220489
- S Reportable occurrences, LERs & related correspondence
- 8210150291 Forwards LER B1-016/03L-0.
  DIETZ.G.R Garolina Power & Light Co 81/02/27 HAYNES, J.P.
  Region 2. Atlanta, Office of the Director (81/03/01) ip.
  15706, 129. 24% Fiche: 30-324.81/02/27.8210150291.
- --8210150308 LER 81-016/03L-0:on 810207, primary containment atmospheric organ analyzer indicated upscale Caused by deterioration of inlet rubber tubing due to age, allowing ambient air to enter & six w/analyzer cample flow
  PASTYA:M. J Carolina Power & Light Co 81/02/27. Region 2, Atlanta, Office of the Biretter (81/03/01) 2pp 15706-130. 24%
  Fiche 50-324,81/02/27,8210150271.

- B210150041 Forwards LER 81-032/03L-0 DIETZ:C F Carolina Power & Light Co 81/03/25 O'REILLY, J P Region 2. Atlanta. Office of the Director (81/03/01) 1p L5701 132 24X Fiche 50-324,81/03/25.821015004
- --B210150046 LER 81-032/03L-0 on 810223, while performing requires in as result of diesel generator 2 being out of svc for maint diesel generator 3 declared inoperable due to low control air pressure Caused by mitaligned valve disc PASTVAN-NJ Carolina Power & Cight Co 81/03/25 Regic 2 Atlanta, Office of the Director (81/03/01) 2pp 13701 133 in Fiche 50-324,81/03/25,8210150041
- 82(0070416 Trip rest of 810617 site visit to collect info of loss of RHR Baffle plate dividing water box of RHR HX 1A failed allowing svc water to bypass HX tubes Caused by excessive differential pressure across baffle plate.

  IMBRO.E. GIANELLI, J Director's Office 81/07/22 Distributed Office 19pp 15637 308 24X Fiche 50-324,81/07/22,8210070419
- 8210070442 Discusses 810714 dissel generator trip caused by operator of temp control manual bypass valve LER did not contain sufficient info Further action recommended CHIRAMAL. M Director's Office 81/12/07. MICHELEON. C Direct. Office 1p 15637-345 24X Fiche 50-324, 81/12/07, 8210070442
- S210010008 Responds to FDIA request for 19 categories of documents nuclear reactor events & safety problems Forwards documents listed in App A FELTON. J M Division of Rules and Records 82/06/20 UFELL.FR Critical Mass Energy Project 15pp 15727 005 24x Fishs 30-000.82/06/28.8210010008
- --BiO730016B Discusses findings gathered during 810617 silp wis; in facility loss of RHR capability during Apr & May 1981 Util has committed to mod of wash screen wash sys by 1982 Attendance listinglicinator outage info & drawings and facility for the SI/07/22 Director's Office 81/07/22 Director's Office 1980 15730 056 24% Fiche 50-000;82/06/28;8210010006
- --8201050061 Discusses LER 81-66 pe facility diesel generator pluste water temp control valve & manual bupass valve No further action recommended CHIRAMAL, H Director's Office 81/12/07 MICHELSON, C Director's Office 1p 15731.344 24X Fiche 50-000.82/01/23 8210101008
- E209150164 "Brunswick Nuclear Power Station Unit 2 Loss of RMR 5.: Water on 820116 - Engineering Evaluation Rept " WOLF TR Reactor Operations Analysis Branch 82/08/31 17;; 15611 263 24% Fiche 50-324,82/08/31,8209150164
- 8210010170 Ack receipt of 820816 response to 820716 notice of vist. & groposed imposition of civil penalties Rapt on major program objectives to be submitted by 821101 should provide sufficient info retesting aspects of training programs AXELRAD, J Enforcement Staff 82/09/15 JONES, J Copplicate & Light Go Spp 15568 109 24X Fiche 50-325,82/09/15.8210; T
- --B210010206 IE Insp Repts 50-324/B2-02 & 50-325/B2-02 on B20105.11
  Noncompliance noted Unit 1 instrument D-1 inoperable & level channel not tripped between 811226-31
  GARNERIC , JULIAN, C, BURGER, C Division of Project & Revision Programs 82/05/13. App 1556B 126 24X Fiche 50-325.82%
- 8210010298 Forwards updated LER 82-083/03L-1.
  DIETZ: G R Cerolina Power & Light Co 82/09/21 0'REFLLY.JF
  Region 2. Office of Director ip 15568:325, 24X
  Fichs. 50-324, 82/09/21, 8210010298
- --8210010303 Updated LER 82-083/03L-1 on 820715, performants of N %:
  revealed that drywall to torus vacuum breakers X18A, C & E
  were leaking excessively, Caused by accumulation of dirk,
  scale & silicone base sealant on valve seating surfaces
  PABTVA:M J Caroline Power & Light Co 82/09/21 Regist D
  Office of Director, 1p 15568-326 24X Fiche 50-328,827578210010298
- 8210010473 Forwards LER 82-107/03L-0 DIETZ: C R. Carolina Power & Light Co 82/09/24, G'REILLY.Jf Region 2, Office of Director 1p 15572:170 24X Fiche 50-324.82/09/24,821001043
- ---B210010475 LER 82-107/03L-0. on 820826; review of fire proteins: findicated storage hithst weighing device had not undergone periodic calibr Cause by failure to recognize accuracy restraint needs.
  PABTVA: M. J. Carolina Power & Light Co. 82/09/24 Regula Office of Director. ip. 15572 171, 24X Fiche 50-324,82/0772 painoloans

- 8210050320 Forwards updated LER 82-107/03L-1 DIET7/C R Carolina Power & Light Co 82/07/29 O'REILLY, J P Ragion 2. Office of Director ip 15619 015 24X Fiche 50-324, 82/09/29, 8210060320
- --9210060327 Updated LER 82-107/03L-1 on 820826, review of fire protection carbon dioxide sys surveillance procedures indicated storage bottle weighting device did not have periodic calibr Caused by failure to recognize need for accuracy restraints. PASTVA.H J Carolina Power & Light Co. 82/07/29 Region 2, Office of Director ip 15619 016 24X Fiche 50-324, 82/09/29, 8210060320
- 8210080221 Forwards LER 82-095/03L-0 DIETZ.C R Carolina Power & Light Co 82/09/29 O'REILLY.J P Region 2. Office of Director ip 15638 047 24X Fiche 50-324.82/09/29,8210080221
- --8210080230 LER 82-095/03L-0 on 820903, discovered that most recent ILRT esceeded specified tosting interval Caused by improper scheduling Scheduling program revised to reflect correct scheduling criteria PASTVA:N J Carolina Power & Light Co B2/09/29 Region 2. Office of Director ip 15638 048, 24X Fiche 50-324, B2/09/29, 8210080221
- B210190754 Forwards LER 82-106/03L-0 Detailed event analysis encl DIETZ.C R Carolina Power & Light Co 82/10/08 O'REILLY.J P Region 2. Office of Director 2pp 15737 097 24X F1che 50-324.82/10/08.8210190754
- --8210190762 LER 82-106/03L-0 on 820917, while reviewing surveillance procedures, determined that emergency bus degraded voltage channel function test not sufficient to verify operability of emergency bus degraded voltage relays Test revised PASTVA.M J Carolina Power & Light Co 82/10/08 Region 2, Office of Director ip 15737 099 24X Fiche 50-324,82/10/08,8210190754
- 8210190300 PND-II-92-109 on 821010, steam & water leak of 20 to 40 gallons per minute found in cracked weld of nonsafety-related heaker drain pipe Plant shut down 80s 2-D could not be manually transferred from generator to transformer HEHL.C W . BURGER.C W Region 2. Office of Director 82/10/12 2pp 15742 159 24X Fiche 50-324,82/10/12,8210190300
- 8210190659 PND-II-82-110 on 821010 relief valve failed to reclose after testing w/reactor critical Reactor manually scrammed & unusual event declared Caused by failure of actuation solenoid Unit in cold shutdown during repairs.

  HEPL.C W . BURGER.C W Region 2. Office of Director. 82/10/12 ip 15737 146 24X Fiche 50-324,82/10/12,8210190459
- 8210260269 Forwards corrected LER 82-108/03L-0 DIETZ.C R Carolina Power & Light Co 82/10/14 O'REILLY, J. P Region 2. Office of Director 1p 15803 226 24X Fiche 50-324, 82/10/14, 8210260269
- --B21026031B Corrected LER 82-10B/03L-0 on B20921.discovered fire house station RW-49 inoperable due to disconnected hose Cause unknown Hose reconnected Retraining programs will be revised to stress correct use of fire fighting equipment PASTVA.M J Carolina Power & Light Co B2/10/14 Region 2. Office of Director 2pp 15803 227 24X Fiche 50-324,82/10/14,8210260269
- 8210190748 Forwards LER 82-108/03L-0 DIETZ.C R Capolina Power & Light Co 82/10/15 D'REILLY, J. P Region 2. Office of Director 1p 15737, 083. 24X Fiche 50-324, 82/10/15, 8210190748
- --E210190759 LER 82-108/03L-0 on 820921, fire hose station RW-49 inoperable due to disconnected fire hose Cause not stated Hose reconnected Employees instructed re use of fire fighting equipment for nonemergency use PASTVA. M J. Carolina Power & Light Co 82/10/15 Region 2, Office of Director ip 15737 084 24X Fiche 50-324, 82/10/15, 82/10/190788.
- 9210250205 Interim Part 21 rept Detailed status of corrective actions taken will be sent by 821020
  SARSTEN.0 E United Engineers & Constructors: Inc. (subs of Raythson Co ) 82/10/15 Director's Office: Office of Inspection and Enforcement ip 13797 151 24X Fiche 30-324,82/10/15,8210260205
- 3210290336 Fr wards updated LER 82-018/03L-2 DIETZ.C R Carolina Power & Light Co 82/10/15 O'REILLY, J. P Region 2, Office of Director ip 15853 053, 24x Fiche 50-324, 82/10/15, 8210290336

- --8210270342 Updated LER 82-018/03L-2 on 820120, drywell floor drain flow integrator 1-016-FG-K601 continuously indicated sump flow w/no pumps running Caused by integrator square root converter & flow transmitter out of calibr PASTVA.N J Carolina Power & Light Co 82/10/15 Region 2, Office of Director 2pp 15853 054 24X Fiche 50-324,82/10/15,8210270336
- 8210290243 Forwards LER 82-112/03L-0 DIETZ. C R Carolina Power & Light Co 82/10/21 0'REILLY, J P Region 2. Office of Director ip 15853 120. 24X Ficha 50-324, 82/10/21,8210290243
- --8210370246 LER 82-112/03L-O on 820929, suppression chamber water temp recorder 2-CAC-TR-778 discovered intermittently recording temps on chart recorder Caused by out of adjustment recorder print actuation solemoid Solemoid adjusted.

  PASTVA.H J Carolina Power & Light Co 82/10/21. Region 2, Office of Director ip 15853-121 24X Fiche 50-324,82/10/21, 8210290243
- 8210290079 Forwards LER 82-113/03L-0 DIETZ-C R. Carolina Power & Light Co 82/10/22 O'REILLY, J P Region 2. Office of Director ip 15854:012 24X Fiche:50-324,82/10/22,8210290079
- --8210270099 LER 82-113/03L-0·on 821003, foring reactor startup coolant analysis, reactor coulant conductivity exceeded Tech Specs Caused by breakdown of reactor water cleanup sys resins Resins allowed to decompose & reactor conductivity reduced PASTVA. M. J. Carolina Power & Light Co. 82/10/22 Region 2, Office of Director Rep. 15854-013 24X Fiche: 50-324, 82/10/22, 8210290079
- DOGKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8209140148 Forwards "Fire Protection of Cable Spreading Room," evaluating quantity of transient combustibles necessary to cause ignition of most limiting cable Info aupple 810304 exemption request HOME:P W Carolina Power & Light Co 82/09/08, DENTON, H R Office of Nuclear Reactor Regulation, Director, 2pp 14782,001 24X Fiche: 50-324, 82/09/08, 8209140148
- --8209140153 "Fire Protection of Cable Spreading Room" + Caroline Power & Light Co 82/08/31. δ1: 14782 004. Ω4χ Fiche: 50-324, 82/09/08, 8209140148
- 8210040316 Forwards revised Sections 5 & 6 to "Bafe-Bhutdown Capability Assessment & Proposed Mods" ZIMMERMAN.S R Carolina Power & Light Co 82/10/01 DENTON.H R Office of Nuclear Reactor Regulation: Director. 1p. 15616:033 2/4X Fiche 50-324,82/10/01,8210060316
- --8210060323 Revised Sections 5 & 6 to "Safe-Shutdown Capability Assessment & Proposed Mode" \* Carolina Power & Light Co 82/10/01 706pp 15616:034 24x Fiche:50-324,82/10/01,8210060316.
- 8210130295 Forwards responses to BNHL & NRC Questions 1-6 re util 820804 radiation shielding study for proposed emergency operations facility/technical support ctr Written concurrence requested by 821025 2 INMERNAN.S R Carolina Power & Light Co 82/10/11 VABBALLO.D IS Operating Reactors Branch 2 3pp. 15678 240 24X Fiche. 50-324, 82/10/11.8210130275
- 8210220489 Ack receipt of 821006 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-30 & 50-324/82-30 WERRELLI, D M Division of Project & Resident Programs UTLEV, E E Carolina Power & Light Co. Ip. 15779 087. 84X Fiche, 50-324, 82/10/18, 8210220889
- --8210220492 Responds to NRC 820907 ltm re violations noted in IE Insp. Repts 50-324/82-30 & 50-325/82-30. Corrective actions. technician counseled re compliance w/Maint Instruction MI-10-20 Fire Protection Procedure FP-14 will be revised DIETZ, C.R. Caroline Power & Light Co 82/10/06 O'REILLY, J. P. Region 2, Office of Director 2pp 15779 088, 24X Fiche 50-324, 82/10/18, 8210220489
- --8210220496 Notice of violation from insp on 820715-0815, \* Division of Project & Resident Programs. 82/09/07. 1p 15779.092. 24X Fichs.50-324.82/10/18.8210220489.

- --8210220503 IE Insp Repts 50-324/82-30 & 50-325/82-30 on 820715-0815 Noncompliance noted on 820805.safety-related equipment Haint Instruction HI 10-2J incorrectly performed & Fire Protection Procedure FP-14 Step III A improperly implemented on 820718 HYERS D 0 . BURGER C Division of Project & Resident Programs 82/09/03 9pp 15779 093 24X Fiche 50-324.82/10/18.8210220489
- 8210280275 Forwards corrected pages to rept submitted in conjuction w/820908 cable spread room examption request & Pages A 3-7-A 3-10 inadvertantly omitted ZIMMERHAN.8 R Carolina Power & Light Co 82/10/22 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 19837-295 24X Fichs 50-324.82/10/22,8210280275
- --8210280278 Corrected & add1 pages to "Fire Protection of Cable Spreading Room"

  4 Caroline Power & Light Co 82/10/22 8pp 15837 296 24X
  Fichs 50-324.82/10/22.8210280275

#### H Ceneral correspondence

- 8210010028 Requests NRC direct all official correspondence to EE Utley, util vice-president due to 820930 retirement of JA Jones JONES. JA Carolina Power & Light Co 82/09/27 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 15865 314 24X Fiche 50-000.82/09/27.8210010028
- 8210130323 Requeste changes to distribution list for NUREG-0020, "Licensed Operating Reactors Status Summary Rept "ZIMMERMAN.B R Carolina Power & Light Co 82/10/11 BEESE, M R, APP Systems Development Brench Rep 15683 361 24X Fiche 50-000,82/10/11,8210130323
- P Operating license stage documents & correspondence
- 82071B0044 FOIA request for all internal non public documents, memos, evaluation repts & other mat1 dealing w/nuclear plant operations MCINMIS, D. News & Observer 82/09/17 Office of Administration in 15860 044 24% Fiche 50-000.82/08/17,82071800044
- 8210120626 Advises that proposed interim changes for shift technical advisor training program acceptable up to Apr 1983.

  VASSALLO, D.B. Operating Reactors Branch 2 82/09/15 JONES. J A Carolina Power & Light Co. 3pp 15672 266 24X

  Fiche 50-324.62/09/15.6210120626
- 8210280013 Responds to FDIA request for all internal, non-public documents, memos, evaluation repts & other matl dealing w/ nuclear plant operations Forwards documents listed in App A. FELTON, J M Division of Rules and Records 82/09/17, MCINNIB, D. Naws & Observer Spp 13860 065 24X Fiche 50-000,82/09/17, purposence.
- --7905290397 Augmented offgas sys shall be used at all times & util should be informed COLLING.J T. Effluent Treatment Systems Branch 79/05/03 IPPOLITO.T A Operating Reactors Branch 3 (Pre 790625) ip 18860 087. 24X Fiche
- --7912280014 Advises of util 791025 interim commitment for demonstrating compliance w/40CFR190 Commitment acceptable.but must include direct radiation per section 6 of NUREO-0473.Revision 2 BANGART.R Effluent Treatment Bystems Branch 79/11/23 IFPOLITO.T. Operating Reactors Branch 3 (Pre 800420) ip 15860 088 24X Fichs 50-000.82/09/17,8210280013.
- --Signit40002 Confirms Bgit26 teleon repossible willful violation of reporting requirements IE lacks specific details necessary to make referred determination HARD. H. J. Office of Inspection & Enforcement, Office of the Director Bg/12/02 FORTUMA.R Office of Inspector & Auditor ip 15860 095 24X Fiche, 50-000, 82/09/17,8210220013
- --BIO4290774 Notifies that applicant should be informed that major change to reducate treatment sys will require IOCFRSO 90 review Requests info to show conformants w/App I & mod can mast acceptance criteria of SRP in NUREO-OBOO.

  OMMILL.N P. Effluent Treatment Bystems Branch. B1/04/06 IPPOLITO.T. A Operating Reactors Branch 2. ip. 15860:226. 24X Fiche:50-000,82/09/17,8210280013
- --Bii2020885 Forwards request for add1 licenses info re proposed second expansion of spent fuel pool & estimate of vol of solid waste generated by scrapping existing racks Info needed by SIIIS KREGER, W. E. Assistant Director for Radiation Protection. 81/10/27 NOVAK, T. Assistant Director for Operating Reactors, 2pp 15860;231 24X Fiche 50-000, 82/09/17, 8210280013.

- --8112300287 Forwards Effluent Treatment Sys Branch safety evaluation put re spent fuel pool expansion application, per review of util 800416 submittal KREGER, WE Assistant Director for Radiation Protection 81/11/27 NOVAK, TM Assistant Director for Operating React 13pp 15860 249 24X Fiche 50-000, 82/09/17, 8210280013
- --B201120280 Advises that 811112 ltr recommended improvement of finingact calculation methodology & licensee accepted by 811125 ltr Other edit changes assured new methodology use every 31 days & nuclide some factor inclusion in ETS GAMMILLW P Radiological Assessment Branch. 81/12/08 IPPDLITO.TA Operating Reactors Branch 2 lp 15869 264 Fiche 50-000, 82/07/17, 8210280013
- --8203080197 Advises that replacing Phrase 12 "Consecutive Honths' w/phrase "Calendar Yr" in Tech Spec 2 5 2 b acceptable Change would reduce recordseeping HOUSTON.R H Assistant Director for Radiation Protection 82/02/11 NOVAK.T H Assistant Director for Operating React: 2pp 15861 014 24X Fiche 50-000,82/09/17.8210280013
- --8205170128 Advises that review of NUREO-0737, Item II F 1-has bee satisfactorily completed & considered closed HOUSTON,R W Assistant Director for Radiation Protection 82/04/16 NOVAK,T H Assistant Director for Operating React: ip 15861 040 24X Fiche 50-000,82/07/17,8210280013
- --8206220591 Submits background info on conversation w/util re 82 loss of RHR svc water event at facility.LER 82-005/01F HOLF, TR Director's Diffice 82/06/04 RUBIN.B Director's Office 5pp 15861 326 24X Fiche 50-000,82/09/17.821028061
- --B207120140 Trip rept of B20324 visit to facility re equipment exqualification problems List of site visit/meeting participants & related info encl EL-ZEFTAWY, M. MOLF, T. R. Director's Office B2/07/06 MICHCLBON. C. Director's Office 12pp 15861 314 24x Fiche 50-000, 82/09/17, 8210280013
- --8208310034 Forwards draft info notice re deficiencies in air filt & ventilation sys. Notice based on radioactive resin release at Pilgrim 1 & on four related events at other plants involving deficiencies in maint & testing of filter sys. MATTSON.R J. Division of Systems Integration (post 611605) 82/08/05 JORDAN.E L. Division of Engineering & Quality Assurance 5pp 15861 024 24X Fiche 50-000, 82/09/17,8210785
- --8209150162 Forwards "Brunswick Nuclear Power Station Unit 2 Less :

  Byc Water on 820116 Engineering Evaluation Rept " Event is of minor significance & should not be classified as AD WDLF, TR Director's Office 82/08/25 MICHELSON, C Directs: Office 1p 15861 331 24X Fiche 50-000,82/09/17,8210260013
- --8210280024 Advises that util 780518 response re proposed plans for correcting problems concerning augmented offgas systematic problems concerning augmented offgas systematic problems for the special problems of the speci
- --B2102B0027 Notifies that commitment schedule for implamenting agric. augmented offgas sys unacceptable Thermal recombiners for use in BKR offgas sys will not satisfy criteria GOLLINS.J T Effluent Treatment Systems Branch 78/09/06 IPPOLITO.Y Operating Reactors Branch 3 (Pre 80042B) 3pp 19860.079. 24X Fiche 50-000.82/09/17.82102B0013
- ---B210280047 Notifies that potential for criminality found re Regissé investigation resulting from W Ward 801202 memo controling facility
  FORTUNA, R.A. Office of Inspector & Auditor 80/12/03 Office Office
- --B2102B0095 Assumes responsibility for review of Case Bi-17 for criminality No criminality indicated Case should be closed SMITH.R.M. Office of Inspector & Auditor B2/08/24 Office Inspector & Auditor Ip 15861 027 24X Fiche 50-000, 82/09/17. B2102B0013
- --B210280100 Notifies that on 820224.C Alderson advised that repisming possible willful violation of reporting requirements & falsification of GA & guard qualification records at facilities.

  RESNER, M E Office of Inspector & Auditor 82/03/01 0ffirst Inspector & Auditor 82/03/01 0ffirst 189ector & Auditor 92/03/01 0f

- 82:0010051 Ack receipt of 820823 ltr requesting temporary relief from commitments re training of shift technical advisors Program approved & request forwarded to NRR for evaluation O'REILLY, J.P. Region 2, Office of Director 82/09/20 JONES, J.A. Carolina Power & Light Co. ip. 15565-322 24X Fiche 50-000, 82/09/20, 8210010051
- B210050362 Application to amend Licenses DPR-71 & DPR-62 revising Tech Specs to clarify requirements for verifying operability of scram discharge vol vent & drain valves Class I & II license amend fees encl EURY.L W Carolina Power & Light Co B2/07/29 VASSALLO.D B Operating Reactors Branch 2 2pp 15408 345 24X Fische 50-324, B2/07/29, B210050362
- --8210050371 Prposed Tech Spec 4 1 3 1 1 re surveillance requirements verifying operability of scram discharge vol vent & drain valves

  « Carolina Power & Light Co 82/09/29 2pp 15608 347 24X Fiche 50-324,82/09/29,8210050362
- B210270110 Advises that plant venting capability acceptable to resolve MUREG-0737. TMI [tem II B I re high point vents VASSALLO.D B Operating Reactors Branch 2 82/10/01, JGNES.J A Carolina Power & Light Co 3pp 15846 338 24X Fichs 50-324.82/10/01.8210270110
- --8210290113 "Operating Reactors TMI Lessons Learned NUREC-0737
  Response Evaluations (Program II)) Project 1.8C8 Vents for
  Brunswick 1 & 2," final technical evaluation rept
  + Lawrence Livermore Laboratory FIN A-0246-2 82/07/15
  BUTCHER.E . BARNHARTIB Division of Licensing 4pp 15866-341
  24X Fiche 50-324,82/10/01,8210290110
- B210:50030 Forwards submittal schedule for responses to NRC 820909 issues re TMI Action Items II F 1.4.5 % & & II E 4 2 7. Tech Spec revisions, containment vent & purge, electrical distribution sys voltages & control of heavy loads ZIEMERMAN.S R Carolina Power & Light Co 82/10/12 VASSALLO, D B Operating Reactors Branch 2 2pp 15701 268 24X Fische 50-324, 82/10/12, 8210150030
- B210260244 Advises that response to NRC 820827 request to justify differences between existing control room & NUREO-0737. Item JII D 3 4 suggestions will be provided by B30131 Requests re-evaluation of improvement cost-benefits
  EURY.L W Carolina Power & Light Co 82/10/21 VASSALLO, D B Operating Reacture Branch 2 1p 15799 353 24X
  Fiche 50-324, 82/10/21, 8210260244
- B210260323 Application for amend to Licenses DPR-71 & DPR-62 clarifying portions of B10321 submittal re hydraulic snubber surveitlance EURY.L W Carolina Power & Light Co 82/10/21 VASSALLG.D B Operating Reactors Branch 2 2pp 15759 338 24X Fiche 50-324, 82/10/21.8210260323
- --B210260325 Revised Tech Specs re hydraulic snubber surveillance # Carolina Power & Light Co 82/10/21 2pp 15797.340 24 X Fiche 50-324,82/10/21.8210260323
- B210240405 Hithdraws request for amend to Licenses DPR-71 & DPR-62, revising Tech Spac re reportability of inoperable reed switches in rod position indication sys to reduce number of routine LERs
  EURY, L W Carolina Power & Light Co B2/10/22 VARBALLO, D. B
  Operating Reactors Branch 2 2pp 15806 239 24X
  Fische 50-324, 82/10/22, 8210260405
- --8210260410 Proposed revisions to Tech Spec 6 9 1 re monthly reportability of safety/relief valve challenges. Tech Spec supersedes 820407 submittal # Carolina Power & Light Co 82/10/22 2pp 15806 241 24X Fichs 50-324,82/10/22,8210260405.
- 3 Imspection reports, IE Bulletins & correspondence
- 3210080015 Addl response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents 1 isted in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON.J M. Division of Rules and Records 82/07/12 UDELL,R A Critical Mass Energy Project 9pp 15645 027 24X Fiche 50-000.82/07/12,8210080015
- --- B2100B0122 Systematic assessment of licensee performance notes re #acility evaluation for Apr 1979-Mar 1980 # NRC - No Detailed Affiliation Given 80/03/31. App 15667 321. 24X Fiche. 50-000, 82/07/12,8210080015

- 8210010132 Forwards IE Insp Repts 50-324/82-31 & 50-325/82-29 on 820809-13 No noncompliance noted VERRELLI, D.M. Division of Project & Resident Programs 82/09/01 JONES, J.A. Carolina Power & Light Co. 2pp 15567, 230 24X Fichs 50-324, 82/09/01,8210010132
- --8210010137 IE Insp Repts 50-324/82-31 % 50-325/82-29 on 820809-13 No noncomplience noted Major areas inspected: ALARA; radioactive mat! transportation, radioactive liquid effluent monitoring % mat! control ALBRIGHT, R H , BARR, K P Division of Engineering & Technical Programs 82/08/31 5pp 15567:232. 24X Fiche 50-324,82/09/01,8210010132
- 8210010112 Forwards summary of 820824 enforcement meeting at Region 2 ofc restatus of action items contained in 820702 & 20 confirmation of action ltrs
  O'REILLY, J.P. Region 2. Office of Director 82/09/09 JONES, J.A.
  Carolina Power & Light Co. ip. 15566 029 24X
  Fiche 50-324, 82/09/03, 8210010112
- --8210010126 Bunmary of 820824 meeting w/util in Atlanta, GA re status of action items contained in 820702 & 20 confirmation of action item Util committed to formally submit long-term program details in Nov 1982

  LEMIS, R C Division of Project & Resident Programs 82/07/03

  Division of Project & Resident Programs. 2pp 15566 030, 24X

  Fiche 50-324,82/07/03,8210010112
- 8210010170 Ack receipt of 820816 response to 820716 notice of violation & proposed imposition of civil penalties, Rept on major program objectives to be submitted by 821101 should provide sufficient info re testing aspects of training programs AXELRAD, J. Enforcement Staff. 82/09/15 JONES, J.A. Carolina Power & Light Co. 2pp. 15568 109. 24X Fichs 50-325,82/09/15,8210010170
- --8210010193 Forwards IE Insp Repts 50-324/82-02 & 50-325/82-02 on 820105-07 Enforcement action addressed to util in 820715 ltr LEWIS, R. C. Division of Project & Resident Programs. 82/07/16 JONES, J. A. Caroline Power & Light Co. 2pp. 15569:124. 24X Fiche 50-325, 82/09/15, 8210010170
- --8210010206 IE Insp Repts 50-324/82-02 & 50-325/82-02 on 820106-07 Noncompliance noted Unit 1 instrument D-1 inoperable & level channel not tripped between 811226-31.

  OARNER, L., JULIAN, C., BURGER, C. Division of Project & Resident Programs 82/05/13 6pp 15568 126 24X Fiche 50-325,82/07/15,821010170.
- 8210010171 Ack receipt of 820702 & 0903 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-18 & 50-325/82-18 VERRELLI, D M Division of Project & Resident Programs 82/09/16 JONES, J A Carolina Power & Light Co. ip. 15568 091. 24X Fiche 50-324,82/09/16,8210010171
- --8210010183 Suppls 820702 response to NRC 820404 ltm re violations noted in IE Insp Repts 50-324/82-18 & 50-325/82-18 Corrective actions:responsible operators counseled & IA-1 battery charger clearance removal reviewed DIETZ.C R Carolina Power & Light Co 82/09/03 D'REILLY, J. P. Region 2. 04/1ce of Director. 3pp 15568:092, 24X Fiche 50-324,82/09/16,8210010171
- --8210010188 Responds to NRC 820604 ltr re violations noted in IE Insp Repts 50-324/82-18 & 50-325/82-18. Conrective actions: double verification program established on 820601 DIETZ,CR Carolina Power & Light Co. 82/07/02. G'REILLY, J. P Region 2: Office of Director. 2pp 15568:095 24X Fichs: 50-324,82/09/16:8210010171
- ---8210010194 Forwards IE Insp Repts 50-324/82-18 & 50-325/82-18 on 820415-0515 & notice of violation LONG, F. Division of Project & Resident Programs 82/06/04, JONES, J. A. Carolina Power & Light Co. 2pp 15568:097, 24X Fichs:50-324,82/09/16.8210010171.
- --8210010199 Notice of violation from insp on 820415-0515. \* Region 2, Office of Director 82/06/04 ip 15568:099. 24X Fiche 50-324,82/09/16:8210010171
- --8210010205 IE Insp Repts 50-324/82-18 & 50-325/82-18 on 820415-0515.
  Noncompliance noted Operating Procedure OP-43 & tag removal for Clearance 1-459 inadequately implemented MYERS, D. O. OARNER, L. W., BURGER, C. W., Division of Project & Resident Programs 82/06/04. 9pp 15568:100 24X Fichs 50-324, 82/09/16, 8210010171

- 8210010336 Advises that IE Insp Rept 50-325/82-36 was inadvertently labeled 50-325/82-30 verRELLI.D M Division of Project & Resident Programs 82/09/16 JONES.J A Carolina Power & Light Co 1p 15571 001 24X Fiche 50-324, 82/09/16, 8210010336
- --B210010340 Forward: IE Insp Repts 50-324/82-32 & 50-325/82-36 on B20824-27 No noncompliance noted VERRELLI.D H Division of Project & Resident Programs B2/09/10 UDNES.J A Carolina Power & Light Co 2pp 15571 002 24X Fiche 50-324.82/09/16.8210010336
- --8210010350 IE Insp Repts 50-324/82-32 & 50-325/82-36 on 820824-27 No noncompliance noted Major areas inspected pre-startup reviews.corporate nuclear safety reviews.post-maint testing & plant mode involving Tech Spec changes PREDRICKSON.P., JACKSON.L.H., UPRIGHT.C.M. Division of Engineering & Technical Programs 82/09/10 4pp 15571 004 24X Fichs.50-324,82/09/16,8210010336
- 8210010391 Ack receipt of 820907 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-25 & 50-325/82-25 LEHIS.R C Division of Project & Resident Programs 82/09/22 JONES. J A Caroline Power & Light Co ip 15572 269 24X Fiche 50-324.82/09/22.8210010391
- --8210010379 Responds to NRC 820813 Itr re violations noted in IE Insp. Repts 50-324/82-25 & 50-325/82-25 Corrective actions plant operating procedures rewritten & signoffs added Operations engineer responsible for procedure changes DIETZ, C.R. Carolina Power & Light Co. 82/09/07 O'REILLY, J.P. Region 2, Office of Director 2pp 15572 270 24X Fichs 50-324,82/09/22,8210010391
- --8210010405 Forwards IE Insp Repts 50-324/82-25 & 50-325/82-25 on 820615-0715 & notice of violation LEHIS, R C Division of Project & Resident Programs 82/08/13 UNKES, J A Caroline Power & Light Co 2pp 15572 272 24X Fiche 50-324, 82/09/28, 8210010371
- --8210010410 Notice of violation from insp on 820618-0715 \* Division of Project & Resident Programs 82/08/13, 2pp 15572-274 24X Fiche-50-324,82/09/22,8210010391
- --8210010415 IE Insp Repts 50-324/82-25 & 50-325/82-25 on 820615-0715 Noncompliance noted failure to implement & maintain operating grocedures for startup & shutdown MKERS.D.O. GARNER.L.W., STETMA.T. Division of Project & Resident Programs 82/08/12 13pp 15572 276 24X Fiche.50-324,82/09/22,8210010391.
- B210150100 Ack receipt of B20913 ltr informing NRC of steps taten to correct violations noted in IE Insp Repts 50-324/82-26 & 50-325/82-26 LEWIS.R C Division of Project & Resident Programs B2/09/24 UONES.J A Caroline Power & Light Co ip 15701 164. 24X Fiche 50-324. 82/09/24.8210150100
- --82i0150106 Responds to NRC 820817 Itr re violations noted in IE Insp Repts 50-324/82-26 & 50-325/82-26 Corrective actions new comprehensive post-testing program being developed DIETZ.C R Carolina Power & Light Co 82/09/13 O'REILLY, J P Region 2. Office of Director 2pp. 13701:165, 24X Fiche 50-324,82/09/24,8210150100
- --8210150113 Forwards IE Insp Repts 50-324/82-26 & 50-325/82-26 on 820712-16 & notice of violation LEMIS.R C Division of Project & Resident Programs. 82/08/17 JUNES.J A Carolina Power & Light Co. 2pp 15701:167 24X Fiche 50-324.82/09/24.8210150100
- --8210150120 Notice of violation from insp on 820712-16 \* Division of Project 4 Resident Programs 82/08/17 2pp. 15701-169 24X Ficher 50-324, 82/09/24, 8210150100
- --8210150132 IE Insp Repts 50-324/82-26 & 50-325/82-26 on 920712-16
  Noncompliance noted failure to provide measures to preclude
  bypassing required testing.

  SKINNER: P H : JACKBON.L. H., UPRIGHT.C M. Division of Engineering &
  Technical Programs 82/08/19, 7pp 15701 171 24X
  Fiche 50-324,82/09/24,8210150100
- 8210150108 Forwards IE Insp Repts 50-324/82-35 & 50-325/82-35 on 820908-10 No noncompliance noted VERRELLI,D M. Division of Project & Resident Programs, 82/09/24, JUNES,J.A. Carolina Power & Light Co. 2pp. 15701 149 24X Fiche 50-32 ,82/09/24,8210150108

- --8210150114 IE Insp Repts 50-324/82-35 & 50-325/82-35 on 820708-10 si noncompliance noted Major areas inspected review & evaluation of changes to inservice insp program & program for document control & data retention COLEY. J. L. BLAKE. J. Division of Engineering & Technical Programs 82/09/21 3pp 15701 151 24% Fiche 50-324/82/09/24 92(0150108)
- 8210150162 Forwards IE Insp Repts 50-324/82-33 & 50-325/82-31 on 820901-03 & 10 No noncompliance noted VERRELLI.D M. Division of Project & Resident Programs 82/09/24 JONES.J A Carolina Power & Light Co 2pp 15707 304 24X Fiche 50-324.82/09/24.8210150162
- --8210150170 IE Insp Repts 50-324/82-33 & 50-325/82-31 on 820901-03 & No noncompliance noted Major areas inspected IE Bulletin 77-14, "Seismic Analysis for As-Built Safety-Related Piping Sys"

  ANO.41 P. BLAKE, J. Division of Engineering & Technical Progress 62/09/23 5pp 15707 306 24X Fiche 80-324.62/09/24.8210150142
- 821015000B Ack receipt of 820819 & 0915 ltrs informing NRC of eteps taken to correct violations noted in IE Insp Repts 50-324/82-23 & 50-325/82-23 LEHIS:R C Division of Project & Resident Programs 82/09/30 JONES:J A Cerolina Power & Light Co ip 1569B 349 24x Fiche 50-324, 82/09/30, 82/015000B
- -8210150016 Revises response to NRC ltr re violations noted in [E [r], Repts 50-324/82-23 & 50-325/82-23 Corrective actions assessment of inservice insp program in progress Violation will be fully addressed by 821231
  DIETZ.C R Carolina Power & Light Co 82/09/15 D'REILLY, J P Region 2. Office of Director 2pp 15698 350 24X
  Fichs 50-324, 82/09/30, 8210150008
- --8210150023 Responds to NRC 820719 itr re-violations noted in IE [\*\*\*] Repts 50-324/82-23 & 50-328/82-23 Corrective actions post-maint testing program revised & inservice insp program under review
  DIETZ.C R Carolina Power & Light Co 82/08/19 O'RE[Lt.J.P Region 2. Office of Director 3pp 15698-352 24X Fiche 50-324.82/09/30.8210150008
- --8210150034 Forwards IE Insp Repts 50-324/82-23 & 50-325/82-23 on 820615-18 & notice of violation LEWIS:R C Division of Project & Resident Programs 92/07/19 JONES:J A. Carolina Power & Light Co 2pp. 15698 355 241 Fichs 50-324:82/09/30:8210150008
- --8210150040 Notice of violation from insp on 820615-18 LEMIS.R C Division of Project & Resident Programs 62/07/19 2pp 15678 357 24% Fiche 50-324,82/09/30,8210150008
- --8210150063 IE Insp Repts 50-324/82-23 & 50-325/82-23 on 820615-19
  Noncompliance noted failure to re-establish baseline data
  for RHR svc water pump & to include main steam piping in
  inservice insp program
  BLAKE, J J , ECONOMOS, N Division of Engineering & Technical
  Programs 82/07/15 4pp 15698 359 24X Fiche S0-324-82/09/33.
- 8210220139 Forwards IE Insp Repts 50-324/82-38 & 50-325/82-38 on 820907-10 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/10/Ct JONES, J. A Carolina Power & Light Co 2pp 15778 107 24X Fiche: 50-324, 82/10/04,8210220139
- --8210220147 IE Insp Repts 50-324/82-38 t 50-325/82-38 on 820907-11% monocompliance hoted Major areas inspected followup insp et NRC & licensee identified tasks to be completed prior to startup
  WHITENERH L., KRUGHE, JAPE F Division of Engineering & Technical Programs. 82/09/30 5pp 15778 109 24X
  Fiche, 50-324,82/10/04,8210220139
- 8210220149 Forwards IE Insp Repts 50-324/82-36 & 50-325/82-33 on 820815-0915 No noncompliance noted VERRELLI.D.M Division of Project & Resident Programs 82/16/84 JUNES.J.A. Carolina Fower & Light Co 2pp 15778 045 241 Fiche: 50-324, 82/10/44,8210220149
- --8210220173 IE Insp Repts 50-324/82-36 & 50-325/82-33 on 82685-4918 noncompliance noted Major areas inspected, review of LERs, operational safety verification & audit of surveillance & maint activities

  MYERS.D D . GARNERL W., BURGER.C. Division of Project & Resident, Programs. 82/10/01 Bpp 15778 047, 24X Fiche 50-324.82/10/3 8210220169.

- 9210150036 Ack receipt of 820816 & 0924 itrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-20 & 50-325/82-20 LEMIS.R C Division of Project & Resident Programs 82/10/05 JONES, J A Caroline Power & Light Co 1p 15701 135 24X Fichs 50-324, 82/10/05, 8210150034
- --8210150038 Supple 820816 response to NRC 820719 ltr re violations noted in IE Insp Repts 50-324/82-20 & 50-325/82-20 Addl info re revieion to Procedure COAD 80-1 to assure timely corrective actions to future audit findings provided DIETZ:C R Carolina Power & Light Co 82/09/24 O'REILLY, J P Region 2. Office of Director 2pp 15701 136 24X Fiche 50-324,82/10/05,8210150036
- --8210150045 Responds to NRC 820719 ltr re violations noted in IE Insp Repts 50-324/82-20 & 50-325/82-20 Corrective actions Procedure CQAD 80-1 revised & frequency of plant audits increased to reduce audit scope DIETI.C R Carolina Power & Light Co 82/08/16 O'REILLY.J P Region 2. Office of Director 3pp 15701 138 24X Fichs 50-324,82/10/05,8210150036
- --8210150048 Forwards IE Insp Repts 50-324/82-20 & 50-325/82-20 on B20507-08 & notice of violation W/o notice of violation LEMIS.R C Division of Project & Resident Programs 82/07/19 JONES.J A Carolina Power & Light Co 2pp 15701 141 24X Fiche 50-324,82/10/05.8210150036
- --8210150052 IE Insp Repts 50-324/82-20 & 50-325/82-20 on 820607-08 Moncompliance noted failure to establish measures to assure prompt corrections to adverse QA conditions & failure to distribute audit within required timeframe BELISLE.0 A., UPRIGHT, C M Division of Engineering & Technical Programs 82/07/15 4pp 15701 143 24X Fiche 50-324/82/10/05, 9210150036
- 9210150288 Act receipt of 820714 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-21 & 50-325/82-21 UERRELLID M Division of Project & Resident Programs 82/10/05 JONES, J A Carolina Power & Light Co. 1p. 15706 126 24X Fiche 50-324,82/10/05,8210150288
- --9210130295 Responds to NRC 820818 ltr re violations noted in IE Insp Repts 50-324/82-21 & 50-325/82-21 Corrective actions relief valves which can communicate w/primary containment added to Type C testing program & review of leakage continuing DIETX.C R Carolina Power & Light Co 82/09/14. O'REILLY, J P Region 2. Office of Director 2pp 15706.127 24X Fiche 50-324,82/10/05.8210150288
- 1208170233 IE Info Notice 80-35, Suppl i, "Leaking & Dislodged I-125 Implant Seeds " Syc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06,8208190233
- 20B19023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter: Stainless Bteel, Recirculation Sys Piping at BMR Plants." Svc list encl DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co. of New York 115pp 18810 125 24X Fiche 50-000, 82/10/14,8208190238
- 210220489 Ack receipt of 821006 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-324/82-30 & 50-323/82-30.

  VERRELLI.D.M. Division of Project & Resident Programs 82/10/18

  UTLEY,E E Carolina Power & Light Co. ip 15779.087 24X

  Fiche 50-324,82/10/18,8210220489
- -8210220492 Responds to NRC 820907 ltr re violations noted in IE Insp Repts 50-324/82-30 & 50-325/82-30 Corrective actions: technician counseled re compliance w/Maint Instruction MI-10-2J Fire Protection Procedure FP-14 will be revised DIETZ. C.R. Caroline Power & Light Co. 82/10/06 O'REILLY. J P Region 2. 04fice of Director 2pp 15779 088 24X Fiche 50-324,82/10/18,8210220489
- 9210220494 Forwards IE Insp Repts 50-324/82-30 & 50-325/82-30 on 820713-0815 & notice of violation.

  VERRELLIA M Division of Project & Resident Programs 82/09/07 JCMES. JA Cerolina Power & Light Co 2pp 15779-090 24X Fiche. 50-324, 82/10/18, 8210220489
- -9210220496 Notice of violation from insp on 820715-0815 \* Division of Project & Resident Programs. 82/09/07, ip 15779 092. 24X Fiche, 50-324, 82/10/18,8210220489.

- --8210220503 IE Insp Repts 50-324/82-30 & 50-325/82-30 on 820715-0815
  Noncompliance noted on 820805, safety-related equipment Maint
  Instruction MI 10-2J incorrectly performed & Fire Protection
  Procedure FP-14 Step III A improperly implemented on 820718
  MYERS.D O. GARNER.L W. CHASE.J Division of Project & Resident
  Programs 82/09/03 930 15779 093 24X Fiche 50-324,82/10/18,8210220889
- 8 Reportable occurrences, LERs & related correspondence
- 8210070416 Trip rept of 810617 site visit to collect info re loss of RHR Baffle plate dividing water box of RHR HX 1A failed allowing svc water to bypass HX tubes Caused by excessive differential pressure across baffle plate IMBRO, E. 01ANELLI, J. Director's Office 81/07/22 Director's Office 19pp 15697 308 24X Fiche 50-324.81/07/22.8210070416
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000,82/06/28,8210010008
- --8107300168 Discusses findings gathered during 810617 site visit re facility loss of RHR capability during Apr & May 1781 Util has committed to mod of wash screen wash sys by 1783 Attendance list,chlorinator outage info & drawings encl IMBRO.E Director's Office 81/07/22 Director's Office 17pp 15730 056 24X Fiche 50-000.82/06/28,8210010008
- 8209160299 Forwards LER 82-095/031-0 DIETZ, C.R. Carolina Power & Light Co. 82/08/31 O'REILLY, J.P. Region 2, Office of Director 1p. 14894 178 24X Fiche 50-325.82/08/31.8209160299
- --B209160311 LER 82-095/03L-0 on 820803 review revealed that RHR shutdown cooling suction valves F008 & F009 & vessel head spray valves F022 & F023 not tested on quarterly basis per inservice insp requirement Caused by program logic error POULKIR M Carolina Power & Light Co 82/08/31 Region 2. Office of Director 1p 14894 179 24X Fiche 50-325,82/08/31,8209160299
- 8210010170 Ack receipt of 820816 response to 820716 notice of violation & proposed imposition of civil penalties Rept on major program objectives to be submitted by 821101 should provide sufficient info re testing aspects of training programs AXELRAD, J. Enforcement Staff 82/07/15 JONES, J. A. Carolina Power & Light Co. 2pp. 19368 107 24X Fiche 50-325,82/09/15,8210010170
- --B210010206 IE Insp Repts 50-324/82-02 & 50-325/82-02 on 820104-07 Noncompliance noted Unit 1 instrument D-1 inoperable & level channel not tripped between 811226-31 OARNER, L. Division of Project & Resident Programs 82/05/13 6pp 15568 126 24% Fiche 50-325,82/09/15,8210010170
- 8210280013 Responds to FOIA request for all internal non-public documents, memos, evaluation repts & other matl dealing w/ nuclear plant operations Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/09/17 McINNIG. D News & Observer Spp 15860 065 24X Fiche 50-000,82/09/17,8210280013
- --7811200399 LER#1-78-051 on radioactive release reviewed in response to 780803 request Finds LER does not indicate root cause of the event malfunction of concentrated waste tank heaters due to corrosion Forwards recommendations for personnel COLLING. J T Effluent Treatment Systems Branch 78/10/06 KNIOHTON. G. Environmental Evaluation Branch (Pre 790625) 3pp 15860 082 24X Fiche 50-000.82/09/17.8210280013
- 8210080181 Forwards LER 82-101/03L-0
  DIETZ,C R Carolina Power & Light Co 82/10/01 D'REILLY, J P
  Region 2, Office of Director 19 15640 170 24X
  Fithe 50-325,82/10/01,8210080181
- --8210080183 LER 82-101/03L-0 on 820920, valve time testing not covered in operability test of loops A & B of LPCI/RHR sys PTS 08 2.20 & 26. Caused by personnel oversight during procedural development Procedures revised.

  PASTVA, M J Carolina Power & Light Co 82/10/01. Region 2, Office of Director ip. 15640:171. 24X Fiche 50-325, 82/10/01, 8210080181
- 8210080220 RO on 821001, analysis confirmed that pipe support P8-6647 could fail during selimic event Support Upgraded to meet requirements
  DIETZ, C R Carolina Power & Light Co. 82/10/01 G'REILLY, J P. Region 2, Office of Director Ip 15638:090 24X
  Fithe: 50-323, 82/10/01.8210080220.

1

. .

11

4 G ;

11

- 8210130477 Forwards updated LER 82-093/03L-1 DIETZ.C R Carolina Power & Light Co 82/10/04 O'REILLY, J P Region 2. Office of Director 1p 15682 163 24X Fiche 50-025, 82/10/04, 82/10/130477
- --8210130483 Updated LER 82-093/03L-1 on 820813, review revealed inability of reactor protection sys logic functional test PT-01 1 10 to provide for electrical continuity testing of input signal contacts of backup scram logic circuitry solenoids PASTVA.M J Carolina Power & Light Co 82/10/04 Region 2, Office of Director 1p 15682 164 24X Fiche 50-325,82/10/04, 0220.2020.2020.2020.
- 6210130489 Forwards updated LER 82-024/03L-1 DIETZ.C R Carolina Power & Light Co 82/10/04 O'REILLY.J P Region 2. Office of Director Ip 15684 193 24X Fichs 50-025.82210/04.8210130489
- --B210130497 Updated EER 82-024/03L-1 on 820214 & 0220.open position indication for drywall to suppression vacuum breaker X18H not achievable Caused by failure of vacuum breaker to stroke pen fully Cause of 820220 event not determined PASTVA.M J Carolina Power & Light Co 82/10/04 Region 2, Office of Director 1p 15684 194 24X Fiche 50-325,82/10/04, pents/03086
- 8210190666 Forwards LER 82-100/01T-0 DIET7.C R Carolina Fower & Light Co 82/10/11 O'RETLLY,J P Region 2. Office of Director 1p 15737 254 24X Fiche 50-325.82/10/11.8210190666
- --8210190674 LER 82-100/017-0 on 621001, determined that tailpipe for safety relief valve FOI3H could fail during seismic event Addl analysis not performed Addl support (PS-6647) added where tailpipe passes through deflector plate FOULK, R M Carolina Power & Light Co 82/10/11 Region 2, Diffice of Director 1p 15737 255 24X Fiche 50-325, 82/10/11, pp.10160444
- 8210290346 Forwards supplemental LER 82-024/03L-2 DIETZ, C R Carolina Power & Light Co 82/10/13 O'REILLY, J P Region 2, Office of Director 1p 15883 106 24X Fiche 50-025, 82/10/13, 8210270346
- --8210290352 Supplemental LER 62-024/03L-2 on 620214, during periodic test, discovered that open position indication for drywell to suppression vacuum breaker XIBM could not be achieved Caused by failure of vacuum breaker to fully stroke open PASTVA. N J Carolina Power & Light Co 82/10/13 Region 2. Office of Director 1p 15953 107 24X Fiche 50-325, 82/10/13, 8210290344
- 8210260205 Interam Part 21 rept Detailed status of corrective actions taken will be sent by 821020
  SARSTEN,O E United Engineers & Constructors. Inc (subs of Raythean Co ) 82/10/15 Director's Office, Office of Inspection and Enforcement 1p 15797 151 24X Fiche 50-324,82/10/15,8210260205
- 8210260294 RO while performing insp of fire dampers per 820518 commitment discovered ventilation duct located at penetration seal D0-2-034 on 23-ft elevation of diesel generator bidg did not have insp door DIETZ, C R. Caroline Power & Light Co. 82/10/15, D'REILLY, J P. Region 2, Office of Director ip 15803 025 24X Fiche 50-325, 92/10/15, 8210260294
- 9210290325 Forwards updated LER 92-001/03L-1 DIETZ.C R Carolina Power & Light Co 92/10/15 O'REILLY, J P Region 2. Office of Director lp 15859 048 24X Fiche 50-025.82/10/15.8210290325
- ---8210290331 Updated LER 82-001/03L-1 on 820118, surveillance revealed drywell equipment drain flow, 1-916-FG-K603 continuously indicating sump flow who pumps running Caused by Integrator square root converter & flow transmitter out of calibr. PABTVA.M J. Carolina Power & Light Co 82/10/15 Region 2, Office of Director 2pp 18853 049 24X Fiche 50-325,82/10/15,82102F0325
- 8210260256 Forwards LER 82-104/03L-0 DIETZ.C.R Carolina Power & Light Co 82/10/18 O'REILLY, J P Region 2. Office of Director 1p 15803 101. 24x Fiche 50-325.82/10/18.8210260256
- --8210260266 LER 82-104/03L-0 on 821001, excess flow check valve 1-821-F047c failed to seat & isolate as required Probably caused by line crud deposit in valve seat Line flushed & valve satisfactorily tested FASTVA:M J Carolina Power & Light Co 82/10/18 Region 2, Office of Director 1p 15803 102 24X Fiche, 50-325, 82/10/18, 8210260256

- 8210260344 Forwards LER 82-103/03L-0 DIETZ.C R Carolina Power & Light Co 82/10/18 O'REILLY, J P Region 2. Office of Director 1p 15804 244 24X Fichs 50-225.82/10/18.8210260344
- --8210260368 LER 82-103/03L-0 on 820924, required semiannual functions test of primary containment air lock interlock mechanism not addressed in procedures Caused by personnel oversight during initial review of Tech Specs PASTVA, M J Carolina Power & Light Co 82/10/18 Region 2. Office of Director 2pp 13804 245 24X Fiche \$0-325,82/10/18 PRI0260344
- DOCKET 50-327 SEGUDYAH NUCLEAR PLANT, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8209170068 Forwards revised pages to proposed physical security plantransmitted by 820623 ltr Pages withheld (ref 10CFR2 790) MILLS, L. H. Tennessee Valley Authority 82/09/01 ADENSAM, E. Licensing Branch 4 ip 14910 105 24X Fiche 50-327.82/09/01, 8209170068
- 8210060347 Forwards status rept of meteorological program for reviews
  "Saquoyah Nuclear Plant Nowcast Manual"
  MILLS.L M Tennessee Valley Authority 82/10/01 ADENSAM.E
  Licensing Branch 4 5pp 15619 056 24X Fiche 50-327,82/10/01.
  8210060347
- --8210060352 "Sequoyah Nuclear Plant Nowcast Manual "
  # Tannessee Valley Authority 82/07/30 70pp 15619 06: 24
  Fishe 50-327, 82/10/01, 8210060347
- 8210260245 Forwards IE Safeguards Insp Repts 50-327/82-26 & 50-328/82-26 on 821006-08 No noncompliance noted VERRELLI, D Division of Project & Resident Programs 02/10/22 PARRIS, H G Tennessee Valley Authority 2pp 15799 136 24X Fichs 50-327, 82/10/22, 8210260245
- --8210260265 IE Insp Repts 50-327/82-26 & 50-328/82-26 on 021006 08 to noncompliance noted Major areas inspected review of security plan b implementing procedure; security organization-mgt/personnel/response Details withheld (ref 10CFR73 21) MODRE, D E . MCOURE, D R Division of Engineering & Technical Programs 82/10/22 ip 15799 138 24X Fiche 50-327.82/10/22. \$210260245
- P Operating license stage documents & correspondence
- 8210010008 Responds to FOIA request for 19 categories of decumints in nuclear reactor events & safety problems Forwards documints listed in App A FELTON, J M Division of Rules and Records 82/06/28 UNELLER & Critical Mass Energy Project 15pp 15727 005, 24X Fiche 50-000, 82/06/28, 8210010008
- --8008050265 Discusses add1 required info to better define patricular cracking in reactor vessel notiles
  NOONAN, V 8 Assistant Director for Materials & Gualification
  Engineering 80/08/05 TEDESCO, R L Assistant Director for Licensing 2pp 19727 176 24X Fiche 50-000.82/06/28.8210010wl
- --Bi03050987 Discusses 810126 loss of annunciation event at facility Caused by capacitor shorting Licensee will review event at addressed in IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Bus During Operation " CHIRAMAL M Director's Office 81/01/30 Director's Office ip 15728 002. 24X Fiche.50-000.82/06/28.8210010008
- 8210040426 Forwards request for add1 info re hydrogen control Coordinated util response suggested by mid-Oct 1982; since subj is generic to ice condenser plants W/o encl. NOVAK, T.M. Assistant Director for Licensing 82/09/17 PAPRILLE Tennessee Valley Authority, 1p 15597-251 24% Fiche 50-327, 82/09/17,8210040426
- 8210210542 Notification of 820727 meeting u/licenses in Saddy-Dairy) to discuss proposed delays in license requirements STAHLE.C Licensing Branch 4 82/09/24 ADENBAM.E 0 Licensing Branch 4 2pp 15782:328 24X Fiche 50-327,82/09/24,821021042.
- 8210120284 Forwards "Executive Summary Rept on Adequacy of Parasist Hydrogen Mittigation Sys for Sequoyah Nucleaf Plant," in response to RL Tedesco 820413 lth.
  MILLS.L H Tennesses Valley Authority, 82/09/27 ADENSALE Licensing Branch 4, 1p 15653 078, 24% Fiche: 50-327, 82/09/27, 8210120284

- --P210120287 "Executive Summary Rept on Adequacy of Permanent Hydrogen Hitigation Sys for Sequoyah Nuclear Plant " \* Tennessee Valley Authority 82/09/30 3ipp 15653 079 24X Fiche 30-327,82/09/27.8210120284
- E21CO50216 Informs that updated FSAR will be submitted in Jan 1983, in response to NRC request NLLS.L H Tennessee Valley Authority 82/09/30 ADENSAM, E Licensing Branch 4 ip 15611 236 24X Fiche 50-327, 82/09/30, 8210050216
- 5210190110 Forwards request for add1 info on equipment temp response to Aydrogen burns Coordinated util response suggested since to the condenser plants ADENSAM.E G Licensing Branch 4 B2/10/01 PARRIS.H O Tempssee Valley Authority 4pp 15761 226 24X Fiche 50-327.82/10/01. 6210190110
- 8210130150 Forwards add1 info re 820715 application for amend of Licenses DFR-77 & DFR-79 concerning steam generator water level low-low reactor trip setpoint MILLS.L.M. Tennessee Valley Authority 82/10/07 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15673 082 24X Fiche 50-327.82/10/07.8210130150
- 6210180117 Forwards request for deferral of ASME Section XI requirement to hydrostatically pressure test replacement portions of essential raw cooling water sys Withree oversize drawings Aperture cands are available in FDR MILLS.L M Tennessee Valley Authority 82/10/13 ADENSAM.E Licensing Branch 4 7pp 15718 134 24X Fiche 50-327.82/10/13.8210180117
- 8210260148 Forwards proprietary response to NRC 820809 request for infore CLASIX code Encl withheld (ref 10CFR2 790)

  KAMMER, D.S. Tennessee Valley Authority 82/10/18 ADENSAM, E
  Licensing Branch 4 1p 15797 055 24X Fiche 50-327, 82/10/18,
  B210260148
- 8210260228 Forwards revised figures for incorporation into App B, peaking factor limit rept to reload safety evaluation for Cycle 2 reload operations
  KAMMER, B B Tennessee Valley Authority 82/10/19 DENTGN, H R,
  Office of Nuclear Reactor Regulation, Director 7pp 15806 317
  24X Fiche 50-327,82/10/19,8210260228
- G Inspection reports. IE Bulletins & correspondence
- 5210070007 Responds to FDIA request for eight categories of records resteem generators & steam turbines App A documents provided an R Udell FOIA Request 81-313 Forwards documents listed in App 3 FELTON. / M Division of Rules and Records 82/08/10 LONO, D J Winthrop, Stimson, Putnem & Roberts 9pp 15645-063 24X Fiche 50-000, 82/08/10, 8210070007
- --9210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees IPPOLITO, T. Operating Reactors Assessment Branch 92/04/01 VARGA.S. Operating Reactors Branch 1 5pp 15645 131 24X Fishe 50-000.82/08/10,8210070007
- J21D010474 Forwards corrected notice of violation, revising notice issued w/18 Insp Repts 50-327/82-18 & 50-328/82-18 on 820706-0805

  LEWIGLR C Division of Project & Resident Programs 82/09/17

  PARRIS.H 0 Tennessee Valley Authority 2pp 15572 172 24X

  Fiche 50-327, 82/09/17, 8210010476
- -8210010477 Corrected notice of violation from insp on 820706-0805 Noncompliance noted activities affecting safety-related function of critical systety-cures & components not accomplished per drawings

  Division of Project & Resident Programs 82/09/17 1p 15572 174 24% Fiche 50-327, 82/09/17, 8210010476
- 210010130 Ack receipt of 820830 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-05 & 50-328/82-05
  LEHTER C Davision of Project & Resident Programs. 82/09/20 PARRIS.H O Tennessee Valley Authority ip 15566 009 24X Fiche 50-327.82/09/20.8210010130
- -8210010135 Reponds to NRC 820807 ltr re violations noted in IE Insp. Rep ts 50-327/82-05 & 50-328/92-05 Corrective actions program infitiated to schedule temporary employees for training in QA area KAMMER, D.S. Tennessee Valley Authority 82/08/30. O'REILLY, J. P. Region 2. Office of Director 3pp 15566-010. 24X Fiche 50-327, 82/07/20, 8210010130.

- 8210150225 Ack receipt of 820921 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-14 & 50-328/82-16 LEWIS.R C Division of Project & Resident Programs 82/10/05. PARRIS.H © Tennessee Valley Authority ip 15706-061 24X Fiche 50-327/82/10/05.8210150225
- --8210150231 Responds to NRC 820820 ltr re violations noted in IE Insp Repts 50-327/82-16 & 50-328/82-16 Corrective actions delinquent QA audit findings identified & corrective action escalation program developed MILLS.L M Tennessee Valley Authority 82/09/21 D'REILLY, J P Region 2. Office of Director 5pp 19706.062 24X Fiche 50-327.82/10/05.8210150225
- --8210150237 Forwards IE Insp Repts 50-327/82-16 & 50-328/82-16 on 820712-16 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/08/20 PARRIS.H O Tennesses Valley Authority 2pp 15706 087 24X Fichs 50-327.82/10/05.8210150225
- --8210150245 Notice of violation from insp on 820712-14 \* Region 2, Office of Director 82/08/20, 2pp 15706 069 24X Fiche 50-327,82/10/05,8210150225
- --8210150256 IE Insp Repts 50-327/82-16 & 50-328/82-16 on 620712-16
  Noncompliance noted operations GA manual not reviewed by
  GA staff & no measures established to assure that GA
  procedures & revisions implemented
  BELISLE,O A , FREDRICKSON,P , UPRIGHT,C M Division of Engineering
  & Technical Programs 82/08/18 12pp 15706 071 24X
  Fiche 50-327,82/10/05.8210150225
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds" Svc list encl COBB.L I Division of Evel Facilities, Materials & Bafeguards. 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fichs 50-000.82/10/06.8208190233
- B208170238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consultdated Edison Co of New York, 115pp. 15810 125 24X Fiche 50-000, 82/10/14, 8208170238.
- 8210220469 Ack receipt of 821005 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-327/82-19 & 50-328/82-19 Page 182/10/18 Page 182/18 Page 1
- --B210220474 Responds to NRC B20903 ltr re violation noted in IC Insp Repts 50-327/82-19 & 50-328/82-19 Corrective actions all affected analysts reminded to record data on T1-37 log sheet per Oaseous Effluent Requirements Procedure B1-415 MILLS.L M Tennesses Valley Authority B2/10/05. D'REILLY, J.P. Region 2. Office of Director 2pp 15779.104 24X Fiche 50-327, 82/10/18.8210220469
- --9210220480 Forwards IE Insp Repts 50-327/82-17 & 50-328/82-17 on 820816-20 & notice of violation VERRELLI, D M Division of Project & Resident Programs. 82/09/03 PARRIS, H G Tennessee Valley Authority 2pp 15779-106 24X Fiche. 50-327, 82/10/18, 8210220469
- --8210220482 Notice of violation from insp on 820814-20 \* Division of Project & Resident Programs 82/07/03, lp (5779,108 24% Fishe, 50-327,82/10/18,8210220469.
- --8210220485 IE Insp Rept\* 50-327/82-19 & 50-328/82-19 on 920816-20. Noncompliance noted on 820727, noble gas release rates not recorded on TI-37 log sheet B 35 for all effluent radiation monitors declared inoperable due to power failure. COLLINS,T R, BARR,K P Division of Engineering & Technical Programs 82/09/02 7pp 15779 109 24X Fiche 50-327,82/10/18,8210220469
- 8210260245 Forwards IE Safeguards Insp Repts 50-327/82-26 & 50-328/82-26 on 821006-08. No noncompliance noted, VERRELLI, D Division of Project & Resident Programs. 82/10/22 PARRISH G Tempssee Valley Authority 2pp 15799 (36, 24X Fiche. 50-327, 82/10/22, 8210260245
- --8210260265 IE Insp Repts 50-327/82-26 & 50-328/82-26 on 821006-08. No honcompliance noted Major areas inspected: review of security plan & implementing procedure, security organization-mgt/personnel/response. Details withheld (ref 10CFR73.21). MGGRE, B. E. MGGURE, D. R. Division of Engineering & Technical Programs. 82/10/22 ip 15799. 138 24X Fichs 50-327, 82/10/22, 8210260245

- S Reportable occurrences, LERs & related correspondence
- 8210120380 Advises that operator action necessary to protect BkW glants from excessive feedwater transients BSW plants do not employ high steam generator level turbine or reactor trips to protect against transients CRESECLLJ S Director's Office 80/09/12 MICHELSON, C Director's Office, 34pp 19889 286 24X Fichs 50-327,80/09/12, CRESECTOR'S Office.
- 8210070122 Discusses 810126 loss of annunciation Event began w/loss of non-Class IE sys which supplies power to cammon annunciators inverter failure caused by capacitor short resulting in two wave-shaping SCR failures CHIRAMAL.H Director's Office 81/01/30 Director's Office ip 15449 003 24X Fiche 50-327.81/01/30.8210070122
- 821001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fichs 50-000.82/06/28.8281001000B
- --B010210037 Forwards 800505 memo re underclad cracking in reactor vessel norcles Review re safety aspects & compliance w/Bection IX of ABHE Code concludes that groblem should not be included on generic issues list BAER.R L Safety Program Evaluation Branch 80/07/17 KINTNER.L L Licensing Branch 2 Ip 15727 175 24% Fiche 50-000, 82/06/28, 8210010008
- --Billi80001 Recommends comprehensive assessment of plant operating conditions to determine specific predetermined time related sequences of occurrence to emergency buses SRP should be revised re design features ASME.F Director's Office Bi/10/16 MICHELSON.C Director's Office App 15731 049 24X Fiche 50-000.82/06/28,8210010008
- --B210010161 Discusses potential problem re Bequoyah reactor pressure noizle, supplementing B00222 memo Underclad cracks found by use of otherents equipment Addl items of recent origin discussed Related info encl DENTON, H R Office of Nuclear Reactor Regulation, Director B0/02/28 ABEARNEJ, O'GLINSKY, V, KENNEDY, P Commissioners 9pp 15727 178 24X Fiche 50-000, 82/06/28,8210010009
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 82/07/12 UDELL.R.A Critical Mass Energy Project 9pp. 15645 027 24X Fiche 50-000.82/07/12.8210080015
- --920519042B Forwards engineering evaluation rept. "Inadvertent Loss of Reactor Coolant Events at Begungh Nuclear Plant, Units 1 & 2 "Rept contains recommendations which should be incorporated in ongoing Task Interface Agreement 81-15 LANNIND, H. D. Director's Office 82/05/11 MICHELSON. C. Director's Gffice 1p 15876 140 24X Fiche 50-000, 82/07/12, 8210080015
- --8205190441 "Inadvertent Loss of Reactor Coolant Events at Sequoyah Nuclear Plant, Units 1 & 2," engineering evaluation rept LANNING, W D Director's Office 82/05/31. 23pp 15666-096. 24X Fiche: 50-000, 82/07/12,8210080015.
- --82:0080197 NRC operations of usage chart re events at facilities.
  4 NRC No Datailed Affiliation Given 82/07/12 ip 15648-221, 24X Fiche 50-000,82/07/12,8210080015.
- 821001010B Forwards LER 82-107/01T-0 GREEN.H J. Tannesse Valley Authority. 82/09/24. D'REILLY, J P. Region 2. Office of Director. 1p. 15566.037. 24X Fiche 50-327.82/09/24,8210010108
- --8210010115 LER 82-107/01T-0:an 820911, annulus door (A65) & access door (A64) left open.causing both trains of amergency gas treatment sys to be declared inoperable. Caused by inoperablity of interlocks on doors.

  CARVER, A M , HARDINO, M R Tennesses Valley Authority. 82/09/24.

  Region 2, Defice of Director. 3pp. 15566:038 24X
  Fiche. 50-327,82/09/24,8210010108
- 8210060217 Forwards LER 82-111/03L-0 OREEN.H.J. Tennesses Valley Authority 82/07/30, G'REILLY, J.P. Region 2. Office of Director. 1p. 15620:196, 24X Fiche: 50-327, 82/09/30, 8210060219

- --8210060221 LER 82-111/03L-0 on 820903.while in Mode 1, one contain pressure channel for remote shutdown monitoring instrumentation failed to meet surveillance requirements Caused by closed sense line isolation valve ROBERS.H R, MARDING.M R Tennessee Valley Authority 82/09/3 Region 2, Office of Director ip 19620 197 24X Fiche 50-327.82/09/30.8210060219
- 8210130442 Forwards LER 82-108/03L-0 QREEN, H J Tennessee Vailey Authority 82/10/05 D'REILLY, J P Region 2, Office of Director 1p 15681 187 24X Fichs 50-327, 82/10/05, 8210130442
- -8210130452 LER 82-108/03L-0 on 820907, during Mode 1, level channel LT-63-50 on refueling water storage tank declared inoperable Caused by transmitter out of tolerance due to instrument drift Loop recalibr ROOSRB, H R , HARDING, M R Tennessee Valley Authority 82/10/0 Region 2, Office of Director 1p 15681 188 24X Fiche 50-327, 82/10/05, 8210130442
- 8210130317 RD 82-003 on 820731, fire detector 74F in fire Zone 70 alarmed due to steam leak in spent resin storage tank area Fire zone removed from svc until 820909 Steam leak repaired & zone placed back in svc QREEN, H J Tennessee Valley Authority 82/10/07 O'REILLY, J P Region 2, Office of Director 2pp 15478 341 24X Fiche. 50-327, 82/10/07, 8210130317
- 8210220081 Forwards LER 82-112/03L-0 GREEN,H J Tennessee Valley Authority 82/10/08 O'REILLY,JP Region 2. Office of Director 1p 15779 072 24X Fiche 50-327,82/10/08.8210220081
- --8210220085 LER 82-112/03L-0 on 820911, upper head injection sys factored inoperable due to failure to meet surveillance requirements Gaused by total dissolved nitrogen & air in accumulator exceeding 80 std cubic feet limit ROGERS, HR, HARDING, MR Tennesses Valley Authority 82/10/08 Region 2. Office of Director 2pp 15779 073 24X Fiche 50-327,82/10/08,8210220081
- 8210190712 RO 82-4 on 821012.biological shield blocks removed from equipment hatch for refueling outage breaching fire barrier penetration Verification of fire detector operability established.

  GREEN.H J. Tennessee Velley Authority 82/10/12 D'REILLY, J P Region 2. Office of Director 2pp 15738 139 24X Fiche: 50-327, 82/10/12.8210190712
- 8210190378 Forwards LER 82-117/03L-0 GREEN.H J Tennessee Valley Authority 62/10/14 O'REILLY.JP Region 2. Office of Director 1p 15741 216 24X Fiche 50-327, 62/10/14.8210190378
- --8210190386 LER 82-117/03L-0 on 820914 during 81-220 test on fire year 18-8 start circuit, time delay setpoint on relay 182 found out of 5% tolerance of 120-s Cause not stated Time delay setpoint readjusted to within 5% tolerance ROMINE.W D , HARDING M R Tennessee Valley Authority 62/10/13 Region 2. Office of Director ip 15741 217. 24% Fiche 50-327,82/10/14,8210190378
- 8210290277 Forwards LER 82-116/03L-0 OREEN.H J Tennesse Valley Authority, 82/10/14 O'REILLY, J P Region 2. Office of Director 1p 15853 140 24X Fiche 50-327, 82/10/14:8210290277
- --8210290279 LER 82-116/03L-0 on 820916.both trains of RHR sys inequals due to inadvertent closing of RHR suction valve 1-FCV-74-2 Caused by removal of power fuses to allow work on output relays RHR pump stopped & valve reopened w/auxiliary power ROOERS.H.R., HARDINGM R Tennessee Valley Authority. 82/10/14 Region 2. Office of Director. 2pp 15853 141. 24% Fiche 50-327,82/10/14,8210290277
- DDCKET 50-928 BEQUOYAH NUCLEAR PLANT, UNIT 2
  F. Becurity, medical, emergency & fire protection plans
- 820917006B Forwards revised pages to proposed physical security flat transmitted by 820623 ltr Pages withheld (ref 100FR2.790). HILLS.L.M. Tennesses Valley Authority 82/09/01. ADENSAME Licensing Branch 4 ip. 14910:105 24X Fiche:50-327, 82/09/01, 820917006B.
- 8210060347 Forwards status rept of mateorological program for review?
  "Sequoyah Muclear Plant Noucast Manual."
  MILLS, L. M. Tennesses Valley Authority. 82/10/01. ADENSAME
  Licensing Branch 4. Spp. 15619:056 24X Ficher 50-327, 82/10/01,
  8210060347.

- -- \$210050352 "Sequoyah Nuclear Plant Nowcast Manual"

  \* Tennesses valley Authority 82/09/30 70pp 15619 061 24X
  Fiche 50-327,82/10/01,8210060347
- E210250245 Forwards IE Safeguards Insp Repts 50-327/82-26 & 50-327/82-26 on 821005-08 No noncompliance nated \\ \frac{\f
- P Operating license stage documents & correspondence
- E210040426 Forwards request for additinfoire hydrogen control Coordinated util response suggested by mid-Oct 1982; since subjits generic to ice condenser plants W/o encl MOVAK.T M Assistant Director for Licensing 82/09/17 PARRIS.H Q Tennessee Valley Authority 19 15597 251 24X Fiche 50-327, 82/09/17,8210040426
- E210120284 Forwards "Executive Summary Rept on Adequacy of Permanent Hydrogen Hitzgation Sys for Sequoyah Nuclear Plant." in response to RL Tedesco 820413 itr
  HILLS, L M Tennessee Valley Authority 82/09/27 ADENSAM.E
  Licensing Branch 4 ip 15653 078 24X Fiche 50-327,82/09/27,6210120284
- --8210120289 "Erecutive Summary Rept on Adequaty of Permanent Hydrogen Mitigation Sys for Sequoyah Nuclear Plant " Fennessee Valley Authority 62/09/30 Sipp 15653 079 24X Fiche 50-327,82/09/27,8210120284
- 3210050216 Informs that updated FSAR will be submitted in Jan 1983, in response to NRC request MILLS.L M Tennessee Valley Authority 82/09/30 ADENSAM.E Licensing Brench 4 ip 15611 236 24X Fiche 50-327, 82/09/30, 8210050216
- 32:0190ii0 Forwards request for add1 info on equipment temp response to hydrogen burns Coordinated util response suggested since subj generic to ice condenser plants.

  ADENSAME 0 Licensing Branch 4 82/10/01 PARRIS.H 9 Tennessee Valley Authority 4pp 15761 226 24X Fiche, 50-327, 82/10/01. 62:10190ii0
- 121013Q150 Forwards add1 info re 820715 application for amend of Licenses DPR-77 & DPR-79 concerning steam generator water level low-low reactor trip setpoint MILLS, L.H. Tennesses Vailey Authority 82/10/07 DENTON, H.R. Dffice of Nuclear Reactor Regulation, Director 2pp. 15673 082 24% Fiche 50-327,82/10/07,8210130150
- :210180117 Forwards request for deferred of ASME Section XI requirement to hydrostatically pressure test replacement portions of essential rew cooling water sys W/three oversize drawings Aparture cards are available in FDR MFLLB,L M Tennessee Valley Authority 82/10/13 ADENSAM.E Licensing Branch 4 7pp 15718 134 24X Fiche 50-327,82/10/13,8210180117
- 1210260148 Forwards proprietary response to NRC 820809 request for inco re CLASIX code Encl withheld (ref 10CFR2 790)
  KAMMER, D 8 Tennessee Valley Authority 82/10/18 ADENSAM, E
  Licensing Branch 4 ip 15799 055 24X Fiche 50-327, 82/10/18, 8210240148
- laspection reports, IE Bulletins & correspondence
- 21007Q007 Responds to FDIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FDIA Request 81-319 Forwards documents listed in App B FELYGN. J M Division of Rules and Records 82/08/10 LONG, D J. Winthrop, Stimson, Putnam & Roberts. 9pp 15645.063, 24X Fiche 50-000, 82/08/10, 8210070007.
- -B210070139 Forwards tabulated data on steam generator insp & maint at Facilities. Data should be provided to licensees IPPOLITIO.T. Operating Reactors Assessment Branch B2/04/01 VAROA.S Operating Reactors Branch 1 5pp. 15645-131 24X Fiche 50-000,82/08/10,8210070007

- 8210010476 Forwards corrected notice of violation, revising notice issued w/IE Insp Repts 50-327/82-18 & 50-328/82-18 on 820706-0805

  LEWIS, R. C. Bivision of Project & Resident Programs 82/09/17

  PARIS, H. O Tennessee Vallay Authority 2pp 15872 172 24X

  Fiche 50-327,827/09/17,8210010476
- --8210010477 Corrected notics of violation from insp on 820705-0805 Noncompliance noted activities affecting safety-related function of critical sys structures & components not accomplished per drawings \* Division of Project & Resident Programs 82/09/17 ip 15572:174 24X Fiche 50-327,82/09/17,8210010476
- 8210010130 Ack receipt of 820830 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-05 & 50-328/82-05 DEWIS,R C Division of Project & Resident Programs 82/09/20 PARRIS.H 9 Tennessee Valley Authority 1p. 15566 009 24X Fiche 50-327.82/09/20,8210010130
- --8210010135 Reponds to NRC 820809 ltr re violations noted in IE Insp Repts 50-327/82-05 & 50-328/82-05 Corrective actions pregram initiated to schedule temporary employers for training in QA area KAMMER, D S Tennessee Valley Authoraty 82/08/30 O'REILLY, J P Region 2. Office of Director 3pp. 15566 010 24X Fiche 50-327, 82/09/20, 8210010130
- 8210150225 Ack receipt of 820921 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-16 & 30-328/82-16 LEWIS, R. C. Division of Project & Resident Programs 82/10/05, PARRIS, H. Q. Tennessee Valley Authority 1p 15706:061, 24X Fiche 50-327, 82/10/05, 8210150225
- --8210150231 Responds to NRC 820820 ltr re violations noted in IE Insp Repts 50-327/82-16 & 50-328/82-16 Corrective actions delinquent GA audit findings identified & corrective action escalation program developed MILLS.L M Tennessee Valley Authority 82/07/21 0'REILLY, J. P Region 2, Office of Director 5pp 15706 062 24X Fichs. 50-327, 82/10/05,8210150225
- --8210150237 Forwards IE Insp Repts 50-327/82-16 & 50-328/82-16 on 820712-16 & notice of violation LEWIS.R.C Division of Project & Resident Programs, 82/08/20 PARRIS.H Q Tennessee Valley Authority 2sp 15706:067. 2AX Fiche 50-327,82/10/05.8210150225.
- --8210150245 Notice of violation from insp on 820712-16
  \* Region 2, Office of Director 82/08/20, 2pp, 15706,069, 24x
  Fichs 50-327,82/10/05/8210150225,
- --8210150256 IE Insp Repts 50-027/82-16 & 50-028/82-16 on 620712-16 Noncompliance noted operations GA manual not reviewed by GA staff & no measures established to assure that GA procedures & revisions implemented BELISLE, O A., FREDRICKSON.P., UPRIGHT, C N Division of Engineering & Technical Programs. 82/08/18. 12pp 15706.071. 24x Fiche 50-327, 62/10/05, 8210150225.
- 9208190233 IE Info Notice 80-35, Suppl t, "Leaking & Dislodged I-125 Implant Seeds " Syc list encl COBS.L I Division of Fuel Facilities, Materials & Safeguerds, 82/10/06 Consolidated Edison Co of New York 66pp. 15761-250 24X Fiche: 50-000,82/10/06,8208190233
- 8208190238 IE Bulletin B2-03, "Btress Corrosion Gracking in Thick-Wall:Large-Diameter: Stainless Steel, Recirculation Syspiping at BWR Plants," Svc list encl.
  DEYOUND; R.C. Director's Office, Office of Inspection and Enforcement, 82/10/14. Consolidated Edison Co. of New York, 115pp 15810:125 24X Fiche 50-000, 82/10/14,8208190238
- 8210220469 Ack receipt of 821005 itr informing NRC of steps taken to correct violation nated in IE Insp Repts 50-327/82-19 to 50-328/82-19.

  LEMIS, R. C. Division of Project & Resident Programs. B2/10/18, PARRIS, H. O. Tánesses Valley Authority. 1p. 15779:103, 24% Fiche. 50-327, 82/10/18, 8210220469
- --8210220474 Responds to NRC B20903 itr re violation noted in IE Insp. Repts 50-327/82-19 & 50-328/82-19. Corrective actions all affected analysts reminded to record data on TI-37 log sheet per Gaseous Efficient Requirements Procedure 81-415 HILLS.L M Tennessee Valley Authority. 82/10/05. O'REILLY, J P. Repion 2. Diffice of Director 2pp. 15779-104. 24X Fiche: 50-327, 82/10/18: 8210220469

- --8210220480 Forwards IE Insp Repts 50-327/82-19 & 50-328/82-19 on 820816-20 & notice of violation VERRELLI, D M Division of Project & Resident Programs. 82/09/03 PARRIS, H Q Tennessee Valley Authority 2pp 15779 106 24X Fiche 50-327, 82/10/18, 8210220469
- --8210220482 Notice of violation from insp on 820814-20 e Division of Project & Resident Programs 82/09/03 ip 15779 108 24X Fiche 50-327,82/10/18,8210220469
- --8210220485 IE Insp Repts 50-327/82-19 & 50-328/82-19 on 820816-20 Noncompliance noted on 820727. noble gas release rates not recorded on TI-37 log sheet 8 35 for all effluent radiation contintors declared inoperable due to power failure COLLING.T R , BARR.K.P Division of Engineering & Technical Programs 82/09/02 7pp 15779 109 24% Fichs 50-327, 82/10/18, 8210220469
- 8210260245 Forwards IE Bafaguards Insp Repts 50-327/82-26 & 50-328/82-26 on 821006-08 No noncompliance noted, VERRELLI.D. Division of Project & Resident Programs, 82/10/22 PARRIS, H G Tennessee Valley Authority 2pp 15799 136, 24X Fiche 50-327, 82/10/22, 8210260245
- --8210260265 16 Insp Repts 50-327/82-26 to 50-328/82-26 on 821006-08 No noncompliance noted Major areas inspected review of security plan & implementing procedure security organization-mgt/personnel/response Details withheld (ref 100FR73 21) MOORE, D.E., MCGUIRE, D.R. Division of Engineering & Technical Programs. 82/10/22 ip 15799.138 24X Fiche 50-327.82/10/22, 8210260245

### 8 Reportable occurrences: LERs & related correspondence

- 8210080015 Add1 response to FOIA request for 17 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A. Documents in App B completely withheld (ref FOIA Exemption 5) FELTON, J.M. Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665:027 24X Fiche, 50-000:82/07/12,8210080015
- --8205190428 Forwards engineering evaluation rept. "Inadvertent Loss of Reactor Coolant Events at Sequoyah Nuclear Plant Units 1 & 2 " Rept contains recommendations which should be incorporated in ongoing Task Interface Agreement 81-15.

  LANKING.W D Director's Office 82/05/11. MICHELSON.C Director's Office 1p 15876-140. 24% Fiche.50-000,82/07/12,8210080015
- --8205190441 "Inadvertent Loss of Reactor Coulant Events at Sequoyah Nuclear Plant, Units 1 & 2." engineering evaluation rept LANNING, U D Director's Défice. 82/05/31, 23pg 15666 096. 24X Fiche, 50-000, 82/07/12, 8210080015
- 8210130572 Forwards LER 82-110/03L-0 OREEN H J. Tennessee Valley Authority 82/10/05 D'REILLY, J P. Region 2. Office of Director ip 15679:104 24X Fiche-50-328, 82/10/05, 8210130572

- --8210270074 LER 82-115/01T-0 on 821002, inner & outer doors of upper containment personnel airlock were open simultaneously due to letch bar blocking outer door open Caused by door swing operating chain being out of adjustment, Chain adjusted KRRK.0 B , HARDINO, M R Tennesses Valley Authority 82/10/14 Region 2, Opfice of Director 2pp 15854 010 24X Fiche 30-328, 82/10/14, 8210270071
- 8210260188 Forwards LER 82-118/03L-0 GREEN, H J Tennessee Valley Authority 82/10/20 O'REILLY, J P Region 2, Office of Director ip 15799 032 24X Fishe 50-328, 82/10/20, 8210260188
- --8210260196 LER 82-118/03L-0 on 820921, diesel generator operability essential raw cooling water valves 1-FCV-67-66 & 68 failed to open on diesel generator 1A-A start signal Caused by circuit breakers being left open during testing ROMINE.W D. HARDING!N R. Tennessee Valley Authority. 82/10/20 Region 2. Office of Director ip 15799 033 24X Fiche 50-328,82/10/20,8210260188
- 8210290274 Final rept for Deficiencies B & E & seventh interim rept for Deficiencies A & D re control of procurement activities Initially reported on BIO316 Final corrective actions noted Next rept expected by 830428 MILLS, L M Tennessee Valley Authority 82/10/21 O'REILLY, J P Region 2. Office of Director 4pp 15853 143 24% Fiche 50-000, 82/10/21, 8210290274

#### DOCKET 50-329 HIDLAND PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8207070419 Forwards application for Amend 106 to CP & DL applications, consisting of Revision 44 to FBAR Three hundred nimety-four drawings encl Aperture cards are available in PDR CDGK, J. H. Consumers Power Co. 82/06/28 DENTON, H. R. Dffice of Nuclear Reactor Regulation. Director 2pp 13776 028 24% Fiche 80-329, 82/06/28. 8207070419
- ---8207070422 Application for Amend 106 to CP & DL applications, consisting flavision 44 to FBAR CODK.J N Consumers Power Co 82/06/28 20pp 13796 030 24% Fiche 50-329, 82/06/28, 8207070419.
- B2100B0D15 Add1 response to FOIA request for 19 categories of information nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Examption 5)
  FELTON J M Division of Rules and Records 82/07/12 UDELLIR A Critical Mass Energy Project 9pp 15665 027 24%
  Fiche: 50-000.82/07/12.6210080015
- 8210010437 Provides add1 info to 820812 ltr re cooperative evaluation program w/NRC.per NRC 820720 request Program provides capability for rapid response to NRC concerns & supports near-term approval of Itam II K. 3.30.

  CODK. J. W. Consumers Power Co. 82/09/10 DENTON, H. R. Division of Licensing. 6pp 15570 205 24% Fiche 80-329, 82/09/10.8210010437
- 8210290228 Forwards Amend 108 to application for GPs & OLs, consisting of Revisions & & 3 to security plan & safeguards contingency glann-respectively. Plans withheld (ref 10CFR73 21).
  COOK, J W Consumers Power Co. 82/09/23 DENTON, H R Division of Licensing 2pp 18853-284 24% Fiche-80-329, 82/09/23, 8210200228
- --8210270229 Application for Amend 108 to application for CPs to O.s. consisting of revised drawings for security plan & safeguards contingency plan, Drawings withheld (ref 10CFR73, 21)
  CCDK, J.W. Consumers Power Co. 82/09/28, 1p 15853-286 24X
  Fiche: 50-327, 82/09/23, 8210270228.
- B210220511 Forwards WPPBS 820825 & 0909 & CPC 820812 ltrs re 8kW pumprs group 820720 meeting w/NRC re resolution of NUREO-0737. Item II K. 3.30 on small break LOCA methods Appropriate action should be taken ADENBAM. E O Licensing Branch 4. 82/10/04 SHERON. B. W Reacter Systems Branch. ip. 15786-091. 24X Fiche 50-000, 82/10/04, 8210220811.
- 8210120276 Forwards independent design adequacy review & "Perforents Objectives & Criteria for Const Project Evaluations." INPO preliminary rept.
  COOK.J.M. Dute Power Co. 82/10/05, DENTON, H.R. D#fice of Nucleir Reactor Regulation, Director KEPPLER, J.G. Region G. Office of Director. 30pp 15651:322 24X Fiche:50-329,82/10/05,82101802/6

- -5210120281 "Performance Objectives & Criteria for Const Project Exaluations," preliminary rept Institute of Nuclear Power Operations 82/09/30 67pp 15651 352 24% Fiche 50-329,82/10/05,8210120276
- RIOIGO267 Requests additinfo resutil position on Reg Guide 158, Revision 1, "Qualification of Nuclear Power Plant Insp. Esen & Testing & Audit Personnel" ADEX-SAM.E 0 Licensing Branch 4 B2/10/05 COOK, JW Consumer Power Co 4pp 15746 007 24X Fiche 50-329,82/10/05,8210180267
- PiGl3G264 Forwards Amend 109 to application for CPs & OLs, consisting of Revision 45 to FSAR CCGM, J W Consumers Power Co 82/10/07 DENTON, H R Office of Auclear Reactor Regulation, Director 3pp 15676 015 24X Fiche 50~329, 82/10/07, 8210130264
- 8210130266 Amend 109 to application for CPs & OLs.consisting of Pevision 45 to FSAR COOK, J W Consumers Power Co 82/10/11 2pp 15676 018 24X Fishe 50-329,82/10/07,8210130264
- E0150441 Discusses reasons why deletion of requirement for four point proof jacking of feedwater isolation valve pit is essential fact of remedial action to be achieved prior to excavation because feedwater isolation valve pit
  HARNICK.R F Region 3. Office of Director 82/10/08 HILLER.D B
  Consumers Power Co 2pp 15703 151 24X Fiche 50-329.82/10/08.
  8210150441
- 10190354 Forwards Affidavit of Svc re Amend 109 (Revision 45 to FSAR) 10190364 Forwards Arridavit or over the moments of the total application for CPs & OLs SULLIVAN, T J. Consumers Power Co. 82/10/15 DENTON, H.R. ( Nuclear Reactor Regulation, Director ... 3pp. 15740 318 24X Fiche 50-329, 82/10/15, 8210190364 Office of
- 10210294 Forwards Revision 1 to NUS-4146, "Analysis of Flammable Concentrations at Midland Nuclear Plant From Natural Gas Pipeline Breaks," in response to NRC 820823 request for
- CODX.J H Consumers Power Co 82/10/19 DENTON.H R Office of Nuclear Reactor Regulation, Director 9pp 15764 104 24X Fiche 50~329.82/10/19.8210210294
- 8210210301 "Proposed Cas Pipeline Leak Detection Sys " 870NEA.M A Stoner Associates. Inc 82/10/12 22pp 15764 112 24X Fiche 50-329,82/10/19,8210210294
- 8210210306 "Analysis of Flammable Concentrations at Midland Nuclear Plent From Natural Gas Pipeline Breaks," Revision i Beven oversize drawings encl Aperture cards available in PDR AATHAN.S J. FULFORD.P J. KAISER, Q D. NUS Corp. NUS-4146 R01 B2/10/07 58pp 15764 135 24X Fiche 50-329,82/10/19,8210210294
- NAC Safety Evaluation Report (SER), supple & correspondence
- 10010278 Forwards "Feilure Mode & Effects Analysis of Midland Non-Nuclear Instrumentation & Integrated Control Sys." in response to FSAR Questions 30 56-30 59. Info completes review of SER Confirmatory Item 22 COCK.J W Consumers Power Co 82/09/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15574.077 24X Fichs 50-329, 62/09/23, 8210010278
- 8210010284 "Failure Mode & Effects Analysis of Midland Non-Nuclear Instrumentation & Integrated Control Bys " ENZINNA:R B., WINKB:R W., BWARTZELL, B.D. Babcock & Wilcox Co BAN-1743 82/07/31 61pp 15874,079 24X Fiche.50-329,82/09/23, 8210010278
- 10190920 Forwards proprietary reactor test data per SER, in support of util position re estimates of full power yrs estimated to result in drop in upper shelf energy UH Taylor affidevit enc t Test data withheld (ref 106FR2 790 & 106FR9 12) COOK, J W Consumers Power Co 82/10/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp. 15795 022 24X Fichs 50-329, 82/10/05, 8210190520
- LO200079 Notification of 821109 meeting w/util, Stoner Associates & NUS in Bethesda: MD to discuss SER Open Item 1 re onsite natural gas pipeline. HEERNAN: R W Licensing Branch 4 82/10/13 ADENBAM, E, 0 Licensing Branch 4 89p 15767:317. 24X Fiche: 50-329, 82/10/13, 8210200099
- #0270039 Notification of 821020 meeting w/util & Summit Nuclear in Bethesde.HD to discuss SER confirmatory Item 26 re independent safety angineering group ##ERNAN.R W Licensing Branch 4 82/10/19 ADENBAM.E 0 Licensing Branch 4. 3pp. 18836:270 24X Fiche 50-329,82/10/19,8210270039.

- 8210210030 BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF MIDLAND PLANT, UNITS 1 AND 2 Docket No. 50-329 And 50-330 (Consumers Power Company)

  © Office of Nuclear Reactor Regulation, Director NUREG-0793

  ©2/10/31 16Bpp Available at NRC 99 50 15785 015 24X
  Fiche 50-329, 82/10/31, 8210210030
- F Security, medical, emergency & fire protection plans
- 8210130004 Releases public version of nuclear accident apps to emergancy preparedness plan are made and flact apps to amergancy preparedness plan FELTON, J M Division of Rules and Records 82/09/23 Docum Hanagement Branch 1p 15695 001 24% Fiche 50-329,82/09/23. 8210130004
- ---B210130005 Forwards public version of nuclear accident apps to Bay, Saginaw & Midland County, MI emergency preparedness plans COOX.J W Consumers Power Co B2/09/08 DENTON.H R Office of Nuclear Reactor Regulation. Director 4pp 15495 002 24X Fiche 50-329,82/09/23,8210130004
- --9210130007 Public version of nuclear accident apps to Bay, Baginaw & Midland County, HI emergency preparadness plan \* Consumers Power Co 82/09/01 437pp 15695 006 24% Fiche 50-327, 82/09/23.8210130004
- 8210290228 Forwards Amend 108 to application for CPs & OLs.consisting of Revisions & & 3 to security plan & safeguards contingency plan, respectively Plans withheld (ref 10CFR73 21) COOK.J H Consumers Power Co 82/09/23 DENTON, H R Division of Licensing 2pp 15853 284 24X Fiche 50-329, 82/09/23, 8210290228
- --8210290229 Application for Amend 108 to application for CPs & OLs, consisting of revised drawings for security plan & safeguards contingency plan Drawings withheld (ref 10CFA73 21) 10UFM/3 <1/CODK.J H Consumers Power Co 82/09/28 1p 15853 286 24X Fiche 50-329,82/09/23.8210290228
- 821008018B Informs that activities performed 820925 considered emergency measures to ensure safe fire protection of facility Remedial stop work order not violated HARNICK, F Region 3, Office of Director 82/10/05 COOK, J W Consumers Power Co 1p 15640.179 24X Fiche 50-329,82/10/09,001009018B
- Q Adjudicatory correspondence
- 8210220294 Comments on petition for rulemaking PRM-50-328 re electromagnetic pulse in nuclear power plants Requests that 10CFR30 be amended to require provision for design features for protection against attacks & destructive acts MARSHALL, W H Mapleton Intervenors 82/08/31 Office of Secretary of the Commission 2pp 15776 066 24X Fiche 50-329, 82/08/31, 8210220294 Office of the
- 8210040087 Response opposing B Stamiris 820904 motion for partial initial decision on QA adequacy Underpinning excavation work will not be authorized unless NRC satisfied w/util QA proposals Certificate of Svc encl WILCOVE, M N Hearing Branch 2 82/09/24 Atomic Safety and Licensing Board Panel 9pp. 15584.223 24X Fiche 50-329,82/09/24,8210040087
- 8210050221 Response to M Binclair resubmitted contention on Table 8-3 Contention should be deferred until Commission issues policy statement Certificates of Bvc enci MEBT.A.E Consumers Power Co. WEBT.A.E Isham, Lincoln & Beale 82/09/28 Atomic Safety and Licensing Board Panel 8pp 15609.062 24% Fichs 50-329.82/09/28,8210050221
- 8210050223 Motion to comps! M Sinclair to respond to applicant 820830 request for admission of truth of relevant matters of fact or atternatively, to deem matters of fact admitted Certificate of Svc enci Related correspondence STEPTOE, P. Consumers Power Co. STEPTOE, P. Isham, Lincoln & Beals 82/09/28 Atomic Safety and Licensing Board Panel 5pp. 15610:339. 24% Fichs. 50-329, 82/09/28, 8210050223
- --8210050229 Request for admission of truth of relevant matters of fact re Contention 5 Certificate of Evc encl.
  MILLER.M. I Consumers Power Co. MILLER.M I. Isham, Lincoln & Beale 82/08/30. Sinclair.M. 4pp 15610 344 24X
  Fiche: 50-329, 82/09/28, 8210050223.

- 8210050230 Responses opposing B Staminis 820913 addendum to 820824 cost benefit contention Good cause for late filling not benefit contention Good cause for sets filing not demonstrated Certificate of Svc encl REST.A E Consumers Power Co MEST.A E Isham, Lincoln & Beals 82/09/28 Atomic Safety and Licensing Board Panel. 3pp 13511 019 24% Fiche 80-329,82/09/28,8210050230
- 8210010062 Response apposing M Sinclair resubmitted Contention i Court of Appeals.DC Circust decision does not affect contention deferral Court stayed effect of decision until Commission deterral Court staged errect or decision until Commission policy statement issued Certificate of Svc and HILCOVE. H N Hearing Branch 2 82/09/29 Atomic Safety and Licensing Board Panel Spp 15565 004 24X Fiche 50-329.82/09/29.8210010062
- 8210010254 Memorandum memorializing 820927 teleon re board notification on soils remedial QA procedures that may affect ASLB consideration of B Staminis motion for partial initial decision on QA adequacy in soils remedial work HARBOUR, J Atomic Safety and Licensing Board Panel 82/09/27 2pp 15374 058 24X Fichs 50-329.82/09/27.8210010254
- 8210040018 Response to remainder of M Sinclair revised contentions of Undouble Heaponse to remainder or in Bincheir revises content based on discovery No objection to Revised Contentions 6.24 & portions of 56 Opposes Contentions 24.43 & portions of 56. Wincotice of eppearance & Certificate of Byc.
  Wincotice of eppearance & Certificate of Byc.
  WincovE, M N. WRIGHT, N A Hearing Branch 2. 82/09/30 & Safety and Licensing Board Panel. 17pp 15581 280 24X
  Fiche 50-329, 82/09/30, 8210040018
- 8210050215 Response to M Sinclair 820920 revised contentions. Set II Objects to Contentions 34(a), 37 & 43 & portions of Contentions & 5.7 Util nonconformance rept & Certificate of Svc enct STEPTOE, P.P. Consumers Power Co. STEPTOE, P.P. Isham, Lincoln & Beale. 82/09/30 Atomic Safety and Licensing Board Panel 13pp 15611 073 24X Fiche 50-329, 82/09/30, 82:0030215
- 8210050238 Forwards changed interrogatories as motion to compel discovery responses, addressing same issues as 820830 interrogatories M/o enci Related correspondent Safety and Licensing STANIRIS.8 Stamiries. B. 82/09/30 Atomic Safety and Licensing Board Panel. 1p 15609-050 24X Fichs 50-329,82/09/30,8210050238
- 8210050240 Motion to compel answers from util to 820830 revised interrogatories re Contention 1b ASLB 820814 ruling on decommissioning supports need for comparative analysis of decommissioning estimates Related correspondence.

  BTAMIRIS, B. Stamiria, B 82/09/30 Atomic Safety and Licensing Board Panel. 3pp 15610.336, 24% Fiche: 50-327, 82/09/30, 8210050240
- 8210060193 Response opposing M Sinclair resubmitted Contention 56 on station blackout Contention lacks requisite basis & specificity to stand alone Certificate of Svc encl.

  BRUNNER, J E. Consumers Power Co. 82/09/30 Atomic Safety and Licensing Board Panel. App. 15614.237, 24X Fiche.50-329,82/09/30,8230043439
- 8210050246 Forwards AJ Boos 820930 revised affidavit, correctly identifying contention as Binclair Contention 6.8vc list encl. Related correspondence.
  BRUNNER: J E. Consumers Fower Co. 82/10/01 BTAMIRIB, B. 89 E. Consumers Power Co. 82/10/01 STAMIRIB, B. Stamiris, 15509-081 24X Fiche, 50-329, 82/10/01, 8210050245
- 8210070378 Objections to util refusal to enswer 8 Stamiyis Interrogation to through 11 & 18 Jasues relevant to scope of contentions. Heeting should be scheduled to finalize decomissioning plans. Related correspondence.

  HARSHALL, H H Mapleton Intervenors MARSHALL, H. H Mershell, H. H B2/10/02 Atomic Sefty and Licensing Beard Pehel. 2pp 15433 248 24X Fiche: 50-329, 82/10/02, 8210070398
- 8210070132 Motion to compel util to answer second set of interropatories based on new info Interrogatories are narrow in scope, based on new info Interrogatories are narrow in scope, based on new info in FES & directly relevant to admitted Contention 5, Related correspondence
  BISHOP, L. L. Bincleir, M. BISHOP, L. L. Bishop, L. L. 82/10/04
  Atomic Safety and Licensing Board Panel 3pp. 13627:043, 24X
  Fiche, 50-327, 82/10/04, 8210070132.
- 8210070136 Responses to applicant & NRC 820903 & NRC 820910 responses to M Sinclair revised contentions Limiting Contention 31 to litigation of util compliance w/existing requirements Contention 32 amended.

  BISHOP.L L. Sinclair.M. BISHOP.L L. 81shop. L.L. 82/10/04. Atomic Bafety and Licensing Board Panel. [1pp. 15627:020 24X Fiche: 30-327, 82/10/04, 8210070136.

- 8210040229 Order allowing M Sinclair to reply to NRC & util 820930 respenses to Sinclair 820920 revised contentions by 821015 B Stamiris may reply to applicant 820923 & 28 & NRC 820928 respenses to Stamiris contention by 821016 BECHHOEFER C Atomic Safety and Licensing Board Panel 82/10/0: STAMIRIG.8 Stamiris 8 SINCLAIR M Sinclair M 2pp 15620 24X Fiche 50-329.82/10/05.8210060229
- 8210070140 Response to request for production of documents SINCLAIR, Binclair, H SINCLAIR, H Bishop, L L 82/ 13627 080 24% Fiche 30-329, 82/10/06.8210070140 82/10/04
- 8210080062 Advises that NRC will voluntarily respond to B Staniris 210080062 Advises that NRC uill voluntarily respond to B Staairis M Binclair 820913 & 20 interrogatories, respectively Objections to interrogatories for reasons other than noncompliance u/100FR2 720(h) not waived WRIOHT, N A Hearing Branch 2 82/10/06 BECHMOEFER, C . HARBOYS COMAN, F. P. Atomic Safety and Licensing Board Panel 2pp 15643 277 24X Fiche 50-329, 82/10/06, 8210080062
- 8210130482 Notice of appearance in proceeding Certificate of Svc en STAHL.D M Consumers Power Co STAHL.D M Isham. Lincoln & Bea 82/10/06 4pp 15682 170 24X Fiche 50-327,82/10/06.8210330482
- 8210080046 informs of agreements between parties re NRC request the util not take depositions of listed persons & discovery on M Sinclair & B Stamiris tontentions alleging deficiencies Tack Co GA
  PATON, W D
  Hearing Branch 2 82/10/07 BECH4HOEFER, C. COMAN, F |
  HARBOUR, J
  Atomic Safety and Licensing Board Panel Rpp
  15643 035 24% Fiche 50-329,82/10/07,8210080066
- 8210130304 Hemorandum memorializing 821006 telcon re issuante of 82 issues to be considered at hearings, identification of witnesses, discovery & new contentions BECHHOEFER.C Atomic Gafety and Licensing Board Panel 82/10/08 4pp 15678 343 24X Fithe 50-329,82/10/08,8210130304
- 8210130421 Notice of resumption of evidentiary hearings in consolidated OL/OM proceeding on 821027 & continuing on 821028-30 & 1101-05 to extent necessary Hearings to be held in Midland.MI BECHHOEFER.C Atomic Safety and Licensing Board Panel 82/10/09 ip 15680 245 24% Fiche 50-327.82/10/08,8210130421
- 8210180212 Response to 8 Stamiris 820930 motion to compel responses revised interrogatories. Util has no objection to responding voluntarily to amended interrogatories Certificate of Svc encl. Related correspondence BRUNNER, J.E. Consumers Power Co 82/10/12 Atomic Safety and Licensing Board Panel 3pp 15718 103 24X Fiche 50-329,82/10/1 8210180212
- 8210200041 Response opposing util 820928 motion to compet response to violeurous response opposing util 820928 motion to compet response util 820930 requests for admissions from M Sinclair Sinclair 820914 response raised relevant objections Certificate of 820 snc1 Related correspondence BIGHOP.L.L. Binclair.M. BIGHOP.L.L. Harmon & Weiss 82/10/13 Atomic Safety and Licensing Board Panel 5pp 15754, 435 247 Piche 30-329, 82/10/13, 8210200061 82/10/13
- 8210200054 Roply to NRC & applicant responses to M Sinclair revises Contentions 6.34.37.43.56 & 57 Contention 6.bases (a).(b) b (d).(4). Contention 43 & Contention 56.Basis 3.withdrawn (d):441.Contention 43 & Contention 50: Bees 3: Western and Certificate of Svc encl BIGHOP: L. Binclain: M. BISHOP: L. Harmon & Weiss B2/10/15 Atomic Bafety and Licensing Board Penel 7pp 15755 076 24K Fiche. 50-327: 82/10/15:8210200054
- 8210210970 Response to util 820923 & NRC 820928 response to 8 Sizeir riodicard Response to Util 820923 & NRC 820928 response to 8 Sizeir new contention based on FES. Gross misrepresentation of overall costs & benefits to public represented by cost/ benefit analysis demands redress STAMTRIS, B Stamiris, B, 82/10/15 Atomic 8afety and Licansing Board Panel 9pp 18763, 168 24X Fiche; 50-329, 82/10/15,821621837
- 8210200051 Lists sections of SER & BER Suppl 2 NRC will sponsor at testimony re issues to be covered at 821027-1105 hearings Testimony re issues to be addressed during second wk of hearings will be filed on 821022.

  MILCOVE, M N. Hearing Branch 2 82/10/18. BECHHOEFER.C., HARBOUR.J. COMAN.F.P. Atomic Befety and Licensing Board Panel Opp. 15756-042 24% Fichs:50-329.82/10/18.8210200051
- 8210210427 Order extending time until 821026 for Commission to solle review ALAB-691 CHIEK, 8. J Office of the Secretary of the Commission 82/10/18 Commissioners, 1p 15762-271 24X Fichs, 50-329, 82/50/18: 8210210427.

- B210210290 Notice of rescheduled evidentiary hearings for 821115-20 & 22-23 EECHHOEFER, C Atomic Safety and Licensing Board Panel B2/10/19 B3 15765 073 24X Fiche 50-329, 82/10/19, 8210210290
- 6210220381 Response opposing M Sinclair 821004 motion to compel applicant to answer Sinclair second set of interrogatories based on neu info Interrogatories vague.incomprehensible & Irrelevant W/Certificate of Svc Related correspondence. ERUNNER. J E Consumers Power Co 82/10/19 Atomic Bafety and Licensing Board Panel 14pp 15780 176 24X Fiche 50-329.82/10/19, 8210220381
- 6210220322 Mamorandum & order rejecting WH Marshall 820710 contentions haved on SER & dismissing Contention 5 6ER contentions filed late w/o any justification Marshall failed to revise Contention 5 per ASLB 770223 order after FES issued BECHMOEFER.C Atomic Safety and Licensing Board Panel 82/10/20 MARSHALL.W H Marshall.W H 9pp 15776 029 24X Fiche 50-329, 82/10/20,8210220322
- P210260364 Forwards LERs as attachments to NRC 820728 responses to M Sinclair interrogatories MFLCOVE, M Mearing Branch 2 82/10/25 BISHOP, L L Harmon & Weiss BISHOP, L Sinclair, M 1p 15804, 165 24X Fache 50-329, 82/10/25, 8210260364
- 2:0270161 Order extending time until 821029 for Commission to act to review ALAB-691 CHILK. S J Office of the Secretary of the Commission 82/10/26 Commissions ip 15823 010 24X Fiche 50-329,82/10/26

# Utilaty Final Safety Analysis Report (FBAR) & amends

- 207070419 Forwards application for Amend 106 to CP & QL applications. consisting of Revision 44 to FBAR Three hundred ninety-four drawings encl Aperture cards are available in PDR COOK. J H Consumers Power Co 82/06/28 DENTON H R Office of Nuclear Reactor Regulation, Director 2pp 13796 028 24X Fiche 50-329, 82/06/28, B207070419
- -8207070422 Application for Amend 106 to CP & GL applications, consisting of Revision 44 to FSAR COOK, J H Consumers Power Co 82/06/28 20pp 13796-030, 24X Fiche 50-329, 82/06/28, 8207070419
- 8207070428 Revision 44 to FSAR M/394 oversize P&IDs, electrical & instrumentation control drawings, piping isometrics, revision sheets & facing sheets Aperture cards are evailable in PDR + Consumers Power Co. 82/04/30, 3933pp 13794 038 24X Fiche 50-329, 82/04/28, 8207070419
- '10130264 Forwards Amend 109 to application for CPs & OLs.consisting of Revision 45 to FSAR
  COOK.J U Consumers Power Co 82/10/07 DENTON.H.R. Office of Nuclear Reactor Regulation, Director 3pp. 15676.015 24X
  Fiche 50-329.82/10/07.8210130264
- 8210130266 Amend 109 to application for CPs & OLs, consisting of Revision 45 to FBAR CODK.JW Consumers Power Co 82/10/11 2pp. 15676 018 24X Fiche: 50-329, 82/10/07, 8210130264
- 9210130267 Revision 45 to FBAR

  \* Consumers Power Co BE/09/30 626pp, 15676.020 24X
  Fich 50-329, 82/10/07, 8210130264
- 10590364 Forwards Affidavit of Svc rs Amend 109 (Revision 45 to FSAR) to application for CPs & OLe SULLIVAN, T J Consumers Power Co 82/10/15, DENTON, H, R. Office of Nuclear Reactor Regulation, Director 3pp 15740, 318 24X Fiche: 50-329, 82/10/15, 8210190364

### Advisory Committee on Reactor Safeguards reports & correspondence

LO270417 Summary of ACRS Subcommittee on Midland Plant Units 1 & 2 320602 meeting in Washington DC re application for GL & ACRS - Advisory Committee on Reactor Sefeguards 82/08/16 3CRS - Advisory Committee on Reactor Sefeguards 25pp. 15833, 287 24X Fichs 50-329, 82/08/16, 8210270417.

- 8210270433 Summary of ACRS Subcommittee on Midland Plant Units 1 & 2 820520-21 meetings in Midland.MI re application for OL \* ACRS - Advisory Committee on Reactor Safeguards 82/08/14 ACRS - Advisory Committee on Reactor Safeguards 78pp 15835 059 24X Fiche 50-329:82/08/16.8210270433
- 8210280034 Summary of 266th ACRS meeting on 820603-05 in Washington.DC re Midland OL review.pressure vessel integrity.seismic events in emergency planning.control room habitability & Subcommittee on Energy Research & Production questions > ACRS Advisory Committee on Reactor Safeguards 82/10/08 ACRS Advisory Committee on Reactor Safeguards 40pp 15862 297 24% Fiche 30-329.82/10/08.8210280034

## Q Inspection reports. IE Bulletins & correspondence

- B210080015 Add1 response to FDIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON.J.M. pivision of Rules and Records 82/07/12 UDELL,R.A Critical Mass Energy Project 9pp 15665 027 24X Fiche. 30-000, 82/07/12, 8210080015
- ---8203040536 Comments on 011218 corrections to facility assessment contained in NUREQ-0834 re hearings & discussion of systematic assessment of license performance Revision to NUREQ inappropriate issue classed MOSELEY, N C Systematic Assessment of Licenses Performance Review Group 82/01/04 MESSMAN,R H NRC No Detailed Affiliation Given ip 15668 256 24% Fisher-50-000 82/07/12.8210080015
- --8203040538 Forwards performance element summary for Jul 1979-June 1980 in response to ABLB request for testimony on systematic assessment of license performance in general & facility assessment in particular WESBMAN,R H Director's Office. Office of Inspection and Enforcement 81/12/18 MOSELEY.N C Systematic Assessment of Licensee Performance Review Group. 2pp. 15648-254 24X Fiche 50-000,82/07/12,8210080015
- --8210080161 Systematic assessment of licensee performance notes re facility evaluation for Jul 1979-June 1980 \* NRC - No Detailed Affiliation Given 80/06/30 8pp. 15688 071 24% Fiche 80-000, 82/07/12,8210080015.
- 8210050139 Forwards IE Insp Repts 50-329/82-18 & 50-330/82-18 on 820713-0829 & notice of violation MARNICK, R. F. Region 3, Office of Director 82/09/22, COOK, J W. Consumers Power Co. 2pp 15605, 193 24X Fiche: 50-329, 82/09/22, 8210050139.
- --8210050144 Notice of violation from insp on 820713-0825.
  WARNICK, F Region 3. Office of Director 82/07/22 3pp
  15605:195 24X Fiche, 80-329,82/09/22,8210050139.
- --8210050154 IE Insp Repts 50-329/82-18 & 50-330/82-18 on 820713-0825. Noncompliance noted failure to translate requirements into drawings.inadequate procedure & failure to accomplish activities in accordance W/drawings.
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-IR5 Implant Seeds," Syc list encl COBF.L I Division of Fuel Facilities, Materials & Safaguards 82/10/06 Consolidate Edison Co. of New York 66pp 19761.280 24X Fiche.50-000.82/10/06.8208190233.
- 8210190739 Forwards IE Insp Repts 50-329/82-20 & 50-330/82-20 on 820820-0920, No noncompliance noted WARNICK: F Region 3, Office of Director 82/10/06, COOK, J M Consumers Power Co 2pp 15737,076 24X Fiche 50-329,82/10/06,8210190739
- --8210190750 IE Insp Repts 50-329/82-20 & 50-330/82-20 on 820820-0920, No noncompliance noted Major areas inspected: remedial soils work activities training for soils activities, matls used by Zack Go & protective tagging procedures 8UR0E86,8 L., COOK, R. J., QARDNER, R N Region 3, Office of Director 82/10/06, 5pp. 15737:078, 24X Fiche: 50-329, 82/10/06, 8210190739
- 820B190298 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Mall.Large-Diameter. Stainless Steel. Recirculation Sys Piping at BNR Plants "Svc list encl.
  DEYQUNO.R.C Director's Diffice. Office of Inspection and Enforcement 82/10/14. Consolidated Edison Co. of New York.
  115pp 15810-125. 24X Fiche: 50-000, 82/10/14, 820B19023B

#### DOCKETED HEMS

- 8210260190 Ack receipt of \$20930 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-329/82-03, 50-330/82-03, 50-329/82-05 & 4 50-350/82-06
  S0-350/82-06
  WARNICK, R. F. Region S. Office of Director 82/10/20 CDUM. U m 82/10/20 COOK. J W
- IE Inso Repts 50-327/82-03,50-330/82-03,50-327/82-05, 50-330/82-05,50-327/82-06 & 50-330/82-06 Corrective actions addi controls initiated since soldier piles installed COOK, J W Consumers Power Co. 82/09/30 KEPPLER, J. Q Region 3, Office of Director 4pp 15799 026 24X Fiche 50-329, 82/10/20, 9210240190
- 8210290377 Ack receipt of 820930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/82-07 & 50-320/82-07.

  MARNICK, 8 F. Region 3, Office of Director 82/10/26 COOK, J. W. Consumers Power Co. ip 19853 008 24X Fiche 50-329,82/10/26.
- --8210290380 Responds to NRC 820715 itr re-violations noted in IE Insp. Repts 50-329/82-07 & 50-330/82-07 Corrective actions QC will inspect all hangers installed prior to 810101 Sample of hangers installed after 820101 will also be inspected COOK.J W Consumers Power Co 82/09/30 KEPPLER.J O Region 3, Office of Director 1p 15853-009 24X Fiche 50-329.82/10/26, GRANDONNY RESPONDER. 8210290377
- 8210290154 Ack receipt of 821015 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/82-06 & 50-320/82-06 WARNICKLR F Region 3, Office of Director 82/10/27 COOK, J W Consumers Power Co. ip 15853 336 24% Fichs 50-329,82/10/27, 2010/80/64
- --8210290163 Responds to NRC 820426 ltr re violations noted in IE Insp Repts 50-329/82-04 & 50-330/82-06 Corrective actions: complete reinsp of electrical cables expected by end of Apr comp. 1983 COOK.J H Consumers Power Co 82/10/15 KEPPLER, J C. Region 3. Dffice of Director 2pp 15853.337 24X Fiche: 50-329, 82/10/27,
- R. Pariodic operating reports & related correspondence
- 8210030248 "GA Program Mgt Corrective Action Repts.Nonconformance Rapts, Quality Action Requests & Audit Finding Repts." Aug 1782 # Bechtal Corp 82/09/31 1.4 Fiche: 50-329, 82/08/31, 8210050248 1,427pp 15598:001. 24X
- 8210080115 Forwards 39th quarterly rept for Oct-Dec 1982, per ALAB-106. COOK. J. W. Gonsumers Power Co. 82/09/30 BEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 54pp 15440:024 24 Fichs. 30-329.82/09/30.821008015.
- 8 Reportable occurrences, LERs & related correspondence
- 9210070107 Board Notification 82-94 informs of Zack Co potential Part 21 rept on HVAC welder record discrepancies. NOVAK.T. F. Assistant Director for Licensing. 82/09/16. Safety and Licensing Board Panel. 4pp. 15649:202. 24X Fichs. 30-329.82/09/16.8210070107.
- 8210040337 PNO-III-82-100: on 820924, stop work order issued for angaing proparatory remedial soils work as result of insp which identified problems w/certification testing of GC personnel per confirmatory action its issued on BEO927.

  GANDNER, B. HAFER, M., WARNICK, R. Region 3, Office of Director, 82/09/27 ip. 15583:130. 24% Fiche: 50-329,82/09/27,8210040337.
- 6210050143 Interim deficiency rept re accident temp effects on containment level measurement. Detailed design & analysis of mods continuing. Effort integrated N/work required to selve SER Confirmatory Issue 16 (IE Bulletin 79-21).

  COOK. J. W. Consumers Power Co. 82/09/28. KEPPLER, J. G. Region 3. Office of Director. 2pp. 15605;165. 24X Fichs: 50-329, 82/09/28. 8210050143
- 8210240121 Interim Deficiency Rept 82-09 re quality program & mfg deficiency affecting Victoreen radiation monitoring equipment. Initially reported on 820917. Caused by poor contranship & GA breakdown. Next rept expected by 820107. COOK. J. W. Consumers Power Co. 82/10/15 KEPPLER, J. 9. Region 3. Office of Director. Spp. 12799:048. 24x Fiche: 50-329, 82/10/15.

- 8210280076 Interim Deficiency Rept 9 re underrated terminal strips on Limitorque valve operators Initially reported on 810115 Underrated terminal blocks replaced w/Marathon 300 series blocks Next rept will be sent by 830131 COOK, J W Consumers Power Co 82/10/22 KEPPLER, J O Region 3, Office of Director 11pp 15837 147 24X Fiche 50-329,82/10/22.
- T Hearing transcripts on non-antitrust matters
- 8210130265 Testimony of AJ Hendron re evaluation of ultimate load carrying capacity of dissel generator bldg footings Prof qualifications, supporting documentation & Certificate of Syc enci MENDRON, A J Consumers Power Co HENDRON, A J Illinois, Univ of, Urbana-Champaign 82/10/08 119pp 15477 285 24X Fichs 50-0329, 82/10/08, 8210130265
- 8210130494 Testimony of AJ Handron re evaluation of seismic shakedown settlement of dissel generator bldg in event of earthquake Prof qualifications & supporting documentation entitle HEADRON. A J Consumers Power Co HENDRON. A J Illinois, Univ od. Urbane-Champaign 82/10/08 75pp 15684 014 24X Fiche 50-229.82/10/08.8210130494
- --8210130505 Testimony of DF Lewis on behalf of applicant re undergree, piping Affidavit & supporting documentation encl LEWIS.D F Consumers Power Co LEWIS.D F Bechtel Corp 82/10/07 80pp 15694 097 24X Fiche 50-329, 62/10/08,8210130496
- 8210260527 Testimony of WO Corley re cracking in svc water purp Structure

  CORLEY, W O Consumers Power Co CORLEY, W G Portland Cement
  Association 82/10/14 Sipp 15804 315 24X Fiche 50-329,
- 8210260504 Testimony of A Boos, EM Burke, JP Gould & P Shunmugarel re BDOS: A : BURKE, E M. : GOULD J F Consumers Power Co 62 80pp 15805 035 24X Fiche 50-329.82/10/25.8210260504 82/10/25
- DOCKET 50-330 HIDLAND PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8207070419 Forwards application for Amend 106 to CP & OL applications, consisting of Revision 44 to FBAR Three hundred ninety-four oversize drawings encl Aperture cards are available in PDR COOK, J W Consumers Power Co 82/06/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 13796-028 24X Fichs 30-329, 82/06/28, 8207070419
- --8207070422 Application for Amend 10A to CP & CL applications con of Revision 44 to FEAR COOK, J. W. Consumers Power Co 8 Fiche: 50-329, 82/06/28, 8207070419. 82/06/28 20pp 13796 030 :
- 8210080015 Add1 response to FDIA request for 19 categories of info nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5).
  FELTON. J. M Division of Rules and Records 82/07/12 UDELL.R / Critical Mass Energy Project 9pp 15665 027. 24X Fiche 50-000, 82/07/12, 8210080015.
- 8210010437 Provides addl info to 820812 ltr re cooperative evaluate program w/NRC, per NRC 820720 request Program provides exaluse program provides capability for rapid response to NRC concerns & supports near-term approval of Item II K. 3, 30, GCOK.J.W. Consumers Power Co. 82/09/10, DENTON, H. R. Division Licensing. 6pp. 15570-205 24X Fiche 50-329, 82/09/10, 821001643
- 8210290228 Forwards Amend 108 to application for CPs & CLs, consists of Revisions 6 & 3 to security plan & safeguards contingency plan, respectively, Plans withheld (ref 10CFR73 21) CODK, J.W. Consumers Power Co 82/07/23 DENTON, H. R. Division Licensing. 2pp. 15853'284. 24X Fiche: 50-329,82/09/23,821029029
- --8210270227 Application for Amend 108 to application for CPs & OLi consisting of revised drawings for security plan & sefequence contingency plan Drawings withheld (ref 10CFR73, 21). COOK, J. W. Consumers Fower Co 82/09/28, ip. 15853-286 24X
  - Fiche: 50-329, 82/09/23, 8210290228,

- \$21022051 Forwards MPPSS 820825 & 0909 & CPC 820812 ltrs re B&W camers group 820720 meeting w/NRC re resolution of MVREO-0737. Item II K 3 30 on small break LOCA methods Apgropriate action should be taken ADEMSAM.E Q Licensing Branch 4 82/10/04 SHERON, B W Reac Egstems Branch 1p 15786 091 24X Fiche 50-000,82/10/04. 8210220511
- \$210120276 Forwards independent design adequacy review & "Performance Objectives & Criteria for Const Project Evaluations." INPO Preliminary rept
  CCGM.J W Duke Power Co B2/10/05 DENTON,H R Office of Nuclear
  Reactor Regulation, Director KEPPLER.J O Region J. Office of
  Director JOpp 19651 322 24X Fiche 50-329, 82/10/05, 8210120276
- ~~B2101202Bi "Performance Objectives & Criteria for Const Project Evaluations," preliminary rept \* Institute of Nuclear Power Operations 82/09/30 67pp 1565: 352 24% Fiche 50-327,82/10/05.8210120276
- 8210180267 Requests addl info re util position on Reg Guide 1 58, Revision 1, "Qualification of Nuclear Power Plant Insp, Exam & Testing & Audit Personnel" ADENSAMSE 0 Licensing Branch 4 B2/10/05 COOK.J W Consumer Power Co 4pp 15746 007 24% Fiche 50-327,82/10/05,8210180267
- 8210130244 Forwards Amend 109 to application for CPs & OLs, consisting of Revision 45 to FSAR COCK, J H Consumers Power Co 82/10/07 DENTON, H R Office of Muclear Reactor Regulation, Director 3pp 15676 015 24X Fiche 50-329, 82/10/07, 8210130264
- -8210130266 Amend 109 to application for CPs & OLs, consisting of Revision 45 to FBAR COOR, J. W. Consumers Power Co. 82/10/11 2pp 15676 018 24X Fiche 50-329,82/10/07,8210130244
- S21015044) Discusses reasons why deletion of requirement for four point proof jacking of feedwater isolation valve pit is essential part of remedial action to be achieved prior to excavation beneath feedwater isolation valve pit WARNICK.R F Region 3, Office of Director 82/10/08 MILLER.D B Consumers Power Co 2pp 15703 151 24% Fiche 50-329,82/10/08, 8210150441
- 9210210294 Forwards Revision 1 to NUS-4146, "Analysis of Flammable Concentrations at Midland Nuclear Plant From Natural Gas Papeline Breaks," in response to NRC 820823 request for
- COUK.J H Consumers Power Co 82/10/19 DENTON.H R Office of Nuclear Reactor Regulation, Director 9pp 15764 104. 24X Fache 50-329.82/10/19.8210210294
- --8210210301 "Proposed Gas Pipeline Leak Detection Bys "
  SYONER, M A Stoner Associates, Inc 82/10/12 22pp 15764 112
  24X Fiche 50-329,82/10/19,8210210294
- --B210210305 "Analysis of Flammable Concentrations at Midland Nuclear Plant From Natural Qas Pipeline Breaks." Revision I Seven oversite drawings encl Aperture cards available in PDR. NATHAN.S J., FULFORD.P J. KAISER.O D NUS COTP NUS-4146 ROI 62/10/07 58pp 15764 135 24X Fiche 50-329,82/10/19,8210210294.
- NAC Safety Evaluation Report (SER), supple & correspondence
- 210010278 Forwards "Failure Mode & Effects Analysis of Midland Acon-Nuclear Instrumentation & Integrated Control Sys." in response to FSAR Questions 30 56-30 59 Info completes review of SER Confirmatory Item 22 COOK. J W Consumers Power Co. 82/09/23 DENTON. H R Office of Muclear Reactor Regulation. Director 2pp 15574 077 24X Fiche 30-327, 82/09/23, 8210010278
- -- B210010284 "Failure Mode & Effects Analysis of Midland Non-Nuclear Instrumentation & Integrated Control Bys " ENZINNAR B., WINKS,R.W., BHARTZELL,B.D. Babcock & Wilcox Co. BAM-1743 82/07/31 61pp 15574 079, 24X Fiche: 50-329, 82/09/23, 8210010278.
- #250190520 Forwards proprietary reactor test data per SER, in support of util position re estimates of full power yes estimated to result in drop in upper shelf energy. JH Taylor affidavit enc? Test data withheld (ref 100FR2 790 & 100FR9, 12) CODK, J W Consumers Power Co 82/10/05 DENTON, H R Dffice of Muclear Reactor Regulation, Director 7pp 15735,022, 24% Fiche 50-329,82/10/05,8210190520
- :25020099 Notification of 821109 meeting w/util,8toner Associates & AWS in Bethesda,MD to discuss 8ER Open Item 1 re onsite natural gas pipeline HERNAN.R W Licensing Branch 4. 82/10/13. ADENSAM.E 0, Licensi Branch 4 3pp. 19767.317 24X Fiche 50-329.82/10/13.8210200099.

- 8210270039 Notification of 821020 meeting w/util & Summit Nuclear in Bethesda, MD to discuss SER confirmatory Item 26 re independent safety engineering group HERNANAR W Licensing Branch 4 82/10/19 ADENBAM, E 0 Licensing Branch 4 3pp 15836 290 24X Fiche 50-329, 82/10/19, 8210270039 Licensing
- 8210210030 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF MIDLAND PLANT, UNITS 1 AND 2 Docket Nos. 50-329 And 50-330. (Consumers Power Company) ### Office of Nuclear Reactor Regulation, Director NURE9-079: 82/10/31 168pp Available at NRC. #9 50 15785 015 24X fiche 50-329, 82/10/31, 8210210030 NUREG-0793
- F Security, medical, emergency & fire protection plans
- 8210130004 Releases public version of nuclear accident apps to mergency preparedness plan grand Records. 82/09/23 Bocum FELTON. J M Division of Rules and Records. 82/09/23 Bocum Management Branch ig 15895 801 24% Fiche: 50-329, 82/09/23, 8210130004
- --8210130005 Forwards public version of nuclear accident apps to Bay. Saginaw & Midland County, MI emergency preparedness plans CODX.J H Consumers Power Co 82/09/08 DENTON.H R Office of Nuclear Reactor Regulation, Director 4pp 15695,002 24% Fiche 50-329,82/09/23,8210130004
- --B210130007 Public version of nuclear accident apps to Bay, Baginaw & Midland County, MI emergency preparedness plan \* Consumers Power Co B2/09/01 437pp 15695:006 24X Fich\* 50-329, 82/09/23, 8210130004.
- 8210270228 Forwards Amend 108 to application for CPs & OLs, consisting of Revisions 6 & 3 to security plan & safeguards contingency plan, respectively Plans withheld (ref 10CFR73 21), CDCK.J W Consumers Power Co 82/07/23 DENTON, H R Division of Licensing, 2pp 15853-284 24X Fichs 50-327, 82/07/23, 8210270228
- --82(0270227 Application for Amend 108 to application for CPs & DLs, consisting of revised drawings for security plan & safeguards contingency plan. Drawings withheld (ref 10CFA73 21) COOK, J W. Consumers Power Co E Fiche 50-329, 82/09/23, 8210290228 82/09/28, 1p, 15853 286
- 8210080188 Informs that activities performed 920925 considered emergency measures to ensure safe fire protection of facility Remedial stop work order not violated WARNICK, R.F. Region 3, Office of Director 92/10/05 COOK, J.W. Consumers Power Co. ip 15640 179 24X Fiche 50-329,82/10/05.
- O Adjudicatory correspondence
- 8210220294 Comments on petition for rulemaking PRM-50-328 re electromagnetic pulse in nuclear power plants. Requests that 10CFR50 be amended to require provision for design features for protection against attacks & destructive acts MARSHALL, W.M. Mapleton Intervenors 82/08/31 Office of Secretary of the Commission. 2pp. 15776:066 24X Fiche. 50-329, 82/08/31, 8210220294 Office of the
- 8210040057 Response opposing B Stamiris 820904 motion for partial initial decision on GA adequacy. Underpinning excavation work will not be authorized unless NRC satisfied w/util GA proposals. Certificate of 8vc encl WILCOVER N Hearing Branch 2, 82/09/24. Atomic Safety and Licensing Board Panel 9pp. 15584 223, 24X Fiche 50-329,82/09/24,8210040057
- 8210050221 Response to M Sinclair resubmitted contention on Table 8-3 Contention should be deferred until Commission issues policy statement. Certificates of Svc enci WEST, A E. Consumers Power Co. MEST, A E. Isham, Lincoln & Beela 82/09/28 Atomic Safety and Licensing Board Panel. Spp. 13609 062. 24X Fiche: 50-329, 82/09/28, 8210050221.
- 8210030223 Motion to compal M Sinclair to respond to applicant 820830 request for admission of truth of relevant matters of fact or alternatively, to deam matters of fact admitted Cartificate of Svc encl Related correspondence.
  STEPTDE.P. Consumers Power Co. STEPTDE.P. Isham, Lincoln & Beals, 82/09/28 Atomic Safety and Licensing Board Panel. Spp. 15610.339. 24X Fichar 50-329, 82/09/28, 8210050223.
- ---B210050229 Request for admission of truth of relevant matters of fact re Contention 5 Certificate of Bvc enci. MILLER,M.I. Consumers Power Co. MILLER,M.I. Isham, Lincoln & Beale. 82/08/30. Sinciair,M. 4pp. 15610:344. 24X Fiche:50-329,82/09/28:8210050223,

- 8210050230 Responses opposing B Stamiris 620713 addendum to 820824 cost benefit contention Good cause for late filing not demonstrated Caytificate of Svc encl WEST.A E Congumers Power Co WEST.A E Islam, Lincoln & Beals 82/09/28 Atomic Safety and Licensing Board Panel Spp 13611 019. 24X Fichs 50-329,82/09/28,8210050230
- 8210010062 Response apposing H Sinciair resubmitted Contention I Court of Appeals: DC Circuit decision does not affect contention deferral. Court stayed effect of decision until Commission policy statement issued Certificate of Svc encl WILCOVE.H N Hearing Branch 2 82/09/29 Atomic Bafety and Licensing Board Fanel 5pp 15565 004 24X Fiche 50-329,82/09/29,8210010062
- 8210010254 Hemorandum memorializing 820927 telcon re board notification on soils ramedial GA procedures that may affect ASLB consideration of B Stamirts motion for partial initial decision on GA adequacy in soils ramedial work HARBOUR, J Atomic Safety and Licensing Board Panel 82/09/29 2pp 15574 058 24% Fiche 50-329,82/09/29,8210010254
- B21004001B Response to remainder of M Sincleir revised contentions based on discovery No objection to Revised Contentions 6.34 & portions of 56 Upposes Contentions 34.43 & portions of 56 Up/notice of apparance & Certificate of Evc.
  MILCOVE,M N., WRIOHT,N A. Hearing Branch 2, 82/09/30 Atomic Safety and Licenting Board Panel 17pp 15581 280 24% Fiche 50-329,82/09/30,8210040018
- 8210050215 Response to M Sinclair 820920 revised contentions, Set 11 Objects to Contentions 34(a),37 & 43 & partions of Contentions & 57 Util nonconformance rept & Certificate of Svc encl
  STEPTOE,P P Consumers Power Co STEPTOE,P P Isham, Lincoln & Beale 82/07/30 Atomic Sefety and Licensing Board Panel 13pp. 15611:073 24X Fiche \$0-329.82/09/30.8210050215
- 8210050238 Forwards changed interrogatories as motion to compel discovery responses, addressing same issues as 820830 interrogatories M/o encl Related correspondence STANIRIG, 8. Stamiris, B. 82/09/30 Atomic Safety and Licensing Board Panel. 19 15609.050 24X Fiche 50-329,82/09/30,8210050238
- 8210050240 Motion to compel answers from util to 820830 ravised interrogatories re Contantion ib ASLB 820814 ruling on decommissioning supports heed for comperative analysis of decommissioning estimates. Related correspondence STAMIRIS. Stamiris. 8 82/09/30 Atomic Safety and Licensing Board Panel 3pp 13610:336 24X Fiche: 50-329, 82/09/30, 9210050240
- 8210060193 Response apposing M Binclair resubmitted Contention 56 on station blackout Contention lacks requisite basis & specificity to stand alone Certificats of 8vc encl BRUNNER. J E. Consumers Power Co. 82/09/30 Atomic Safety and Licensing Board Panel. App. 13614-237 24X Fiche. 50-329,82/09/30,6210040193
- 8210050246 Forwards AJ Boos 820930 revised applicavit, correctly identifying contention as Bincleir Contention 6 Svc list and Related correspondence aRUNNERF.J. E. Consumers Power Co. 82/10/01 8TAMIRIS.B. Stamiris, B. 3pp. 15609 081 24X Fiche 50-329, 82/10/01, 8210050246
- 8210070378 Objections to util refusal to answer B Stamiris
  Interrogatories 6 through 11 & 18 Issues relevant to scope
  of contentions. Meeting should be scheduled to finalize
  decomissioning plans. Related correspondence.
  MARSHALL.W H Mapleton Intervenors. MARSHALL.W.H. Marshell, W.H.
  82/10/02. Atamic Safety and Licensing Board Panel. 2pp.
  13633,248 24% Fiche.50-327,82/10/02.8210070398
- 8210070132 Motion to compal util to enswer second set of interrogatories based on new into Interrogatories are narrow in scope, based on new into in FES & directly relevant to admitted Contention 5. Related correspondence.

  BISHOP.L.L Sinclair.M. BISHOP.L.L Bishop, L.L 82/10/04. Atomic Safety and Licensing Board Panel. 3pp. 15627:043 24X Fiche 50-329, 82/10/04.8210070132.
- 8210070136 Responses to applicant & NRC 820903 & NRC 820910 responses to M Sinclair revised contentions. Limiting Contention 31 to litigation of util compliance w/existing requirements. Contention 32 manufad 815HOP.L.L. Sinclair.M. BIEHOP.L.L. Bishop. L.L. 82/10/04. Atomic Safety and Licensing Soard Panel. 11pp. 15627:020 24X Fichs: 50-327, 82/10/04, 8210070136.

- 6210060229 Order allowing M Sinclair to reply to NRC & util 620930 responses to Sinclair 620920 revised contentions by 621015 8 8 Stantris may reply to applicant 620923 & 28 & NRC 620928 responses to Stamtris contention by 621015 BECHHOSFER.C Atomic Safety and Licensing Soard Penel 62/10/05 STAMIRIS.B. Stantris. 8 SINCLAIR.M Sinclair.M 2pp 15620 010 24X Fichs 50-329.82/10/05.8210050229
- 8210070140 Response to request for production of documents.

  81NCLAIRM Sinclair, M Sinclair, M Bishop, L B2/10/06 4pp
  18527,080 24X Fiche 50-329,82/10/06,8210070140
- B2100B0062 Advises that NRC will voluntarily respond to B Stamiris & K Sinclair B20913 & 20 interrogatories, respectively Objections to interrogatories for reasons other than noncompliance w/10CFR2 720(h) not waived WRIGHT, N A Hearing Branch 2 B2/10/06 BECHHOEFER, C . HARBOVR, J . COHAN, F P Atomic Safety and Licensing Board Panel 2pp 15643-277 24X Fiche 50-329,82/10/06.8210080062
- 8210130492 Notice of appearance in proceeding Certificate of Svt Intl SYAHL, D M Consumers Power Co. SYAHL, D M Isham, Lincoln & Beale 82/10/04, 4pp 15682 170 24X Fiche 50-329, 82/10/05, 8210130402
- 8210080066 Informs of agreements between parties re NRC request that util not take depositions of listed persons & discovery on M Bincleir & B Stamiris contentions alleging deficiencies in Zack Co GA PATON, N D Hearing Branch 2 82/10/07 BECHHOEFER, C , COMAN, F P , HARBOUR, J Atomic Safety and Licensing Board Pane) 2pp 15643 035 24% Fiche 50-329,82/10/07,8210080066
- 8210130304 Memorandum memorializing 821004 telcon re issuance of BER. issues to be considered at hearings, identification of witnesses discovery & new contentions 82CH-0HOEFER.C Atomic Sefety and Licensing Board Panel 62/10/08 4pp 15678 343 24X Fichs 50-329,82/10/08,8210130304
- 8210130421 Notice of resumption of evidentiary hearings in consolidated OL/OH proceeding on 821027 & continuing on 821028-30 & 1101-05, to extent necessary Hearings to be held in Midland, MI BECH-POEFER, C Atomic Safety and Licensing Board Panel 82/10/OB ip. 15480 245 24% Fiche 50-329,82/10/OB,821013042
- BRIO180212 Response to B Stamiris 820930 motion to compal responses to revised interrogatories. Util has no objection to responding voluntarily to amended interrogatories. Certificate of Svc enci Related correspondence
  BRUNNER, J. E. Consumers Power Co. 82/10/12. Atomic Safety and Licensing Board Panel. 3pp. 1571B 103. 24X Fiche 50-329.82/10/12-6210180212
- 8210200061 Response opposing util 920928 motion to compal response to util 920830 requests for admissions from M Binclair Binclair 820914 response raised relevant objections Certificate of 80cc entl Related correspondence BISHOP, L. L. Sinclair, M. BISHOP, L. L. Harmon & Weiss 82/10/13 Atomic Safety and Licensing Board Penel. Spp. 13734-135 24% Fiche 30-329, 82/10/13, 8210200061.
- 8210200054 Reply to NRC & applicant responses to M Sinclair rivised Contentions 6.34, 37, 43, 56 & 37 Contention 6.5asss (a), (b) & (d)(4), Contention 43 & Contention 56, Basis G. withdrawn Cartificate of Svc enci BISHOP.L L Sinclair M. BISHOP.L L Harmon & Heise 82/10/15 Atomic Bafety and Licensing Board Panel 7pp 15755, 076 24% Fiche: 50-327, 82/10/15,8210200054.
- 8210210370 Response to util 820923 & NRC 820928 rasponse to B Steelijs new contention based on FEB Opens misrepresentation of overall costs & benefits to public represented by cost/benefit analysis demands redrest STAMERS.B. Stamfris. B 82/10/15 Atomic Sefety and Licenting Board Panel 9pp. 13763-168 24% Fiche-50-029,82/10/15.8230210310
- 8210200051 Lists sections of BER & SER Suppl 2 NRC will spenies as tastimony re issues to be covered at 821027-1105 hearings. Testimony re issues to be addressed during second wt of hearings will be filed on 821022.

  MILGOVERM.N Hearing Branch 2. 82/10/18 BECHHDEFER.C. HARBOURJ.J. COMAN.F F Atomic Safety and Licensing Board Pappl 4pp 13756:042 24X Fiche:50-329.82/10/18.8210200031
- 8210210427 Order extending time until 821026 for Commission to act to review ALAB~691. CHILK:B.J Office of the Secretary of the Commission 82/10/18 Commissioners. ip. 15762:271 24X Fiche: 50-329:82/10/18. 8210210427.

- B210210290 Notice of rescheduled evidentiary hearings for B21115~20 & 22~23 BECHHDEFER.C Atomic Safety and Licensing Board Panel 82/10/19 p 15765 073 24X Fiche 50~329.62/10/19.6210210290
- 8210220381 Response opposing M Sinclair 821004 motion to compet applicant to answer Sinclair second set of interrogatories based on new info Interrogatories vague, incomprehensible terrelevant H/Certificate of Svc Related correspondence BRUNNER. J E Consumers Power Co 82/10/19 Atomic Sefety and Licensing Board Panel 14pp 15780 176 24X Fiche 50~329,82/10/19,821020381
- 8210220322 Memorandum & order rejecting WH Marshall 820910 contentions based on SER & dismissing Contention 5 88R contentions filed late u/o any justification Marshall failed to revise Contention 5 per ASLB 790223 order after FES issued 88CHHUEFER, C Atomic Safety and Licensing Board Panel 82/10/20 MARSHALL, W H Marshall, W H 9pp 15776 027 24X Fiche 50-029, 82/10/20, 8210220322
- 8210260364 Forwards LERs as attachments to NRC 820728 responses to M Sinclair interrogatories HILCOVE, H N Hearing Branch 2 82/10/25 BISHOP, L L Harmon & Heiss BISHOP, L L Sinclair, M ip 15804 145 24X Fiche 50-329, 82/10/25, 8210260364
- 8210260388 Forwards info in response to JW Cook 820714 ltr to H Denton re environ qualification of electrical & mechanical equipment HICCOVE.N N Hearing Branch R 82/10/25. BRUNNER, J E Consumers Fower Co 4pp 15803 344 24X Fiche 50-327, 82/10/25, 8210260388
- 8210270161 Order extending time until 821029 for Commission to act to review ALAB-691 CHILK 5 J Office of the Secretary of the Commission 82/10/26 Connissioners ip 15823 010 24X Fiche 50-329,82/10/26
- K Utility Final Safety Analysis Report (FBAR) & amends
- E207070419 Forwards application for Amend 104 to CP & OL applications, consisting of Revision 44 to FSAR Three hundred minety-four drawings and Aperture cards are available in PBR COOK.J W Consumers Power Co. B2/06/28 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp. 13776 028 24% Fiche 50-327, B2/06/28, B2/07070419
- --6207070428 Revision 44 to FBAR W/394 oversize P&IDs, electrical & instrumentation control drawings, piping isometrics, revision sheets & facing shoets Aperture cards are evaluable in PDR & Consumers Power Co. 82706/30 3953pp 13796,038 24X Fiche 50-329,82/06/28,8207070419
- 8210130264 Forwards Amend 109 to application for CPs & OLs, consisting of Revision 45 to FBAR COOK J & Consumers Power Co 82/10/07 DENTON, H R. Office of Nuclear Reactor Regulation, Director 3pp. 15676-015. 24X Fiche 50-329, 82/10/07, 8210130264
- --9210130267 Revision 45 to FBAR
  # Consumars Power Co B2/07/30 626pp, 15676,020 24X
  Ficha 50-329,82/10/07,8210130264
- 8210190364 Forwards Affidavit of Svc re Amend 109 (Revision 45 to FSAR) to application for CPs & OLs SULLIVAN.T J Consumers Power Co 82/10/15 DENTON.H.R Office of Nuclear Reactor Regulation, Director 3pp 15740 318, 24X Fichs 50-329, 82/10/15, 8210190364
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8210270417 Summary of ACRS Subcommittee on Midland Plant Units 1 & 2 820602 meeting in Washington; BC re application for DL \*\* ACRS ~ Advisory Committee on Reactor Safeguards 82/08/16 ACRS Advisory Committee on Reactor Safeguards 82/08/16 ACRS Advisory Committee on Reactor Safeguards 25pp. 15833'287 24% Fiche 50-329,82/08/16,8210270417.
- B210270433 Summary of ACRS Subcommittee on Midland Plant Units 1 & 2 820520-21 meetings in Midland,MI re application for OL \* ACRS - Advisory Committee on Reactor Safeguards. B2/08/16 ACRS - Advisory Committee on Reactor Safeguards. 78pp 15835 059 24% Fiche 50-329,82/08/16.8210270433
- B210280034 Summary of 266th ACRB meeting on B20603-05 in Washington DC re Midland OL review, pressure vessel integrity, seismic events in emergency planning, control room habitability & Subcommittee on Energy Research & Production questions # ACRS Advisory Committee on Reactor Bafeguards B2/10/08. ACRS Advisory Committee on Reactor Bafeguards B2/10/08. 24X Fiche. 50-329. B2/10/08. B210280034.

### G Inspection reports, IE Bulletins & correspondence

- 8210080015 Addit response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5).
  FELTON, J H Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project 9pp 15665 027 24X
  Fiche 30-000, 82/07/12, 9210080015
- --9203040536 Comments on Bil218 corrections to facility assessment contained in NUREG-0934 re hearings & discussion of systematic assessment of license performance Revision to NUREG inappropriate Issue closed MOSELEY, N.C. Systematic Assessment of Licensee Performance Review Group 92/01/04 WESSMAN,R H. NRC N.D. Detailed Affiliation Given ip 15668-256 24% Fithe 50~000,82/07/12,8210080015
- --8203040538 Forwards performance element summary for Jul 1979-June 1980 in response to ASLR request for testimony on systematic assessment of license performance in general & facility assessment in particular.

  MESSMAN.R H Director's Office, Office of Inspection and Enforcement 81/12/18 MOSELEY, N C Systematic Assessment of Licenses Performance Review Oroup 2pp 15468 254 24X Fiche 50-000,82/07/12,8210080015
- --8210080151 Systematic assessment of licensee performance notes refacility evaluation for Jul 1979-June 1980

  NRC No Detailed Affiliation Given 80/05/30 Spp 15568 071 24% Fiche 50-000,82/07/12,8210080015
- 6210050139 Forwards IE Insp Repts 50-329/82-16 & 50-330/82-18 on 820713-0825 & notice of violation WARNICK R F. Region 3, Office of Director 82/09/22 CQQX, J W. Consumers Power Co 2pp 15605 193 24X Fiche 50-329,82/09/22,
- --B210050146 Notice of violation from insp on 820713-0825. WARNICK,R F. Region 3, Office of Director 82/07/22 3pp 15605 195 24X Fiche 50~329,82/09/22,8210050139
- --8210050154 IE Insp Repts 80-329/82-18 & 50-330/82-18 on 820713-0825 Noncompliance noted, failure to translate requirements into drawings, inadequate procedure & failure to accomplish activities in accordance w/drawings OARDNER, R N , LANDSHAN, R B , SHAFER, M D Region 3, Office of Director 82/09/21 7pp 15605 198 24X Fiche, 50-327, 82/09/22, 82/0050137
- 820Bi90233 IE Info Notice 80-35, Suppl i, "Leaking & Disloyed I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards, 82/10/06 Consolidated Edison Co of New York AApp 15741:250 24X Fiche 50-000,82/10/06,820B190233
- 8210190737 Forwards 16 Insp Repts 50-329/82-20 t 50-330/82-20 on 820820-0920 No noncompliance noted WARNICK, R.F. Region 3, Office of Director 82/10/04 COOK, J M Consumers Power Co 2pp 13737 074 24X Fiche: 50-329, 82/10/04, 82/10190739
- --B210190750 IE Insp Repts 50-329/82-20 & 50-330/82-20 on 820820-0920 No noncompliance noted Major areas inspected:remedial soils work activities training for soils activities, matts used by Zaci to 5 protective tagging procedures BURGESS B L . COOK.R J. GARDNER.R N Region 3. Office of Director 82/10/06 5pp 15737 078 24K Fiche:50-329.82/10/06, 8210190739.
- 8208190238 IE Builetin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl. DEYQUNG, R. C. Director's Office, Office of Inspection and Enforcement. 82/10/14. Consolidated Edison Co. of New York 185pp 15810 125. 24% Fiche. 50-000, 82/10/14, 8208190838
- B210240190 Ack receipt of 820930 ltr informing NRC of steps taken to correct violations noted in IE lnes Repts 50-329/82-03, 50-329/82-05, 50-329/82-05, 50-329/82-06 & 50-330/82-06 & 10-330/82-06 & 10-329/82-06 & 10-
- --B210260195 Responds to NRC 820426.0902 & 22 ltrs re violations noted i; IE Insp Repts 50-329/82-03.50-330/82-04.50-329/82-05, 50-330/82-05.50-329/82-06 & 50-330/82-06. Corrective actions: additiontrols initiated since soldier piles installed. CCOK, J. W. Consumers Fower Co. 82/09/30. KEPFLER, J. G. Region 3, Office of Director. App. 15799.026, 24X Fiche: 50-329,82/10/20,8210260190

. 1

14

14

Ы

1.

į,

ı İi

- 8210290377 Ack receipt of 820930 ltr informing NRC of steps taten to correct violations nated in IE Insp Repts 30-329/82-07 & 50-330/82-07 WARNICK: R F. Region 3. Office of Director 92/10/26 CCOK. J W Consumers Power Co Ip. 15853-008 24X Fiche 50-329, 82/10/26,
- --8210290380 Responds to NRC 820715 ltr re violations noted in IE Insp. Repts 50-329/82-07 & 50-330/82-07. Corrective actions GC will inspect all hangers installed prior to 810101. Sample of hangers installed after 820101 will also be inspected COOK.J H Consumers Power Co. 82/09/30 KEPPLER.J O Region 3. Office of Director ip 15853 009 24% Fiche 50-329,82/10/26. 6910990377
- 8210290134 Ack receipt of 821015 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/82-06 & 50-330/82-06 HARNICK, R F Region 3, Office of Director 82/10/27 COOK, J W. Consumers Power Co
- --B210290163 Responds to NRC B20426 itr re-violations noted in IE Insp Repts 50-329/B2-06 & 50-330/B2-06 Corrective actions: complete reinsp of electrical cables espected by end of Apr COOK, J W Consumers Power Co 82/10/15 KEPPLER, J O Region 3 Office of Director 2pp 15893.337 24X Fiche 50-329.82/10/27, 8210270154. Region 3,

# R Periodic operating reports & related correspondence

- 82(0050240 "GA Program Mgt Corrective Action Repts. Nonconformance Repts. Quality Action Requests & Audit Finding Repts." Aug 82/08/31 1,427pp 15598 001 24X
  - \* Bechtel Corp 82/09/31 1.45 Fiche, 50-329, 82/08/31, 8210050248
- 8210080115 Forwards 39th quarterly rept for Oct-Dec 1782, per ALAB-106 COOK J W Consumers Power Co. 82/09/30, DEYDUNG.R.C Birector's Office, Office of Inspection and Enforcement 54pp 15640 026 2/ Fiche 30-027, 82/09/30, 821008015

#### S Reportable occurrences. LERs & related correspondence

- 8210070107 Board Notification 82-94 informs of Zack Co potential Part 21 rept on HVAC welder record discrepancies. NOVAK.T M Assistant Director for Licensing 82/09/16 Atomic 8afety and Licensing Board Panel 4pp. 15649 202 24X Fiche 50-329, 82/09/16,8210070107
- 8210040337 PNG-III-82-100 on 820924 stop work order issued for ongoing preparatory remedial soils work as result of insp which identified problems wice etification testing of GC personnel per confirmatory action its issued on 820927 OARDNER.R. BHAFER.H. MARNICK.R. Region 3. Office of Director. 82/07/27. jp 15883-130 24X Fiche.50-329.82/09/27, 8210040337.
- 8210050143 Interim deficiency rept re accident temp effects on containment level measurement Datailed design & analysis of mode continuing, Effort integrated w/work required to solve SER Confirmatory Issue 16 (IE Bulletin 79-21).

  COSK.J.W. Consumers Power Co. 82/09/28. KEPPLER.J.O. Region 3, Office of Director 2pp. 15605 165 24X Fiche. 30-329, 82/09/28, 8210050143.
- 8210260121 Interim Deficiency Rept 82-09 re quality program & mfg deficiency affacting Victorean radiation monitoring equipment. Initially reported on 820917, Caused by poor workmanship & GA breakdown Next rept expected by 820107 CODK. J W Consumers Power Co 82/10/15 KEPFLER, J 9 Region 3, Office of Director 8pp. 15799 068 24X Fiche. 50-329, 82/10/15, 82/10/15, 82/10/15 8210260121.
- 8210280076 Interim Deficiency Rept 9 re underrated terminal strips on Limitorque valve operators Initially reported on 810115 Underrated terminal blocks replaced w/Marathon 300 series blocks. Next rept will be sent by 830131 COOKJ W. Consumers Power Co. 82/10/22 KEPPLER, J O. Region 3, Office of Director. 11pp. 15837 147. 24X Fiche 50-329,82/10/22,821020074 8210280076

#### T Hearing transcripts on non-antitrust matters

8210130265 Testimony of AV Hendron re evaluation of ultimate load carrying capacity of diesal generator bldg footings. Prof qualifications, supporting documentation & Certificate of Svc encl. HENDRON: A J. Consumers Power Co HENDRON: A.J Illinois, Univ of, Urbane-Champaign 82/10/08 119pp. 15677: 285. 24X Fiche: 50-327, 82/10/08, 8210130265

- 8210130494 Testimony of AJ Hendron re evaluation of saismic shakedown sattlement of diesel generator bldg in event of earthquete Prof qualifications & supporting documentation end HENDRON. A J Consumers Power Co HENDRON. A J Illinois. Univ cf. Urbana-Champaign 82/10/08 75pp 15684 014 24X Fiche 50-327.62/10/08.8210130494
- --8210130505 Testimony of DF Lewis on behalf of applicant re undergreed piping Affidavit & supporting documentation encl LEHIB, D F Consumers Power Co LEHIB, D F Bechtel Corp B2/10/07 80pp 15894 077 24% Fiche 50-329, 82/10/08, 8210130494
- 8210260527 Testimony of WG Corley re cracking in svc water pump CORLEY, W O Consumers Power Co CORLEY, W O Portland Coment Association 82/10/14 81pp 15804 315 24X Fiche 50-329, 92/10/14, 8210260527
- 8210260504 Testimony of A Boos, EM Burke. JP Gould & P Shunmugarel re avc water pump structure Aperture cards available in PDR 8008, A . BURKE, E M . GOULD, J P Consumers Power Co 92/10/25 809p. 15805 035 24X Fiche 50-327
- DOCKET 50-331 DUANE ARNOLD ENERGY CENTER F Security, medical, emergency & fire protection plans
- 8210120392 Releases public version of emergency response organization nobification list
  FELTON, J M Division of Rules and Records 82/09/24 Decum
  Management Branch 1p 15691 108 24X Fiche 50-331,82/09/24. 8210120392
- --8210120399 Forwards public version of emergency response organisation notification list Encl list should be incorporated into Emergency Plan Implementing Procedure EPIP 1 2 MEYER, K A Iowa Electric Light & Power Co 82/09/13 DENION, H & Office of Nuclear Reactor Regulation, Director 15pp 15691.199 24X Fiche 50-331,82/09/24,8210120392
- 821005030B Forwards IE Bafeguards Insp Rept 50-331/82-10 on 020421-25 & notice of violation 4/o notice of violation MLLER.J R. Division of Engineering & Technical Programs 82/07/20 ARNOLD I low Electric Light & Power Co 2pp 15610 090 241 Fiche.50-331.82/09/29.8210050308
- --8210050311 IE Safeguards Insp Rept 50-331/82-10 on 82062:-25 Noncompliance noted failure to maintain adequate detection aids & to provide adequate access control Details withheld (ref 100FR73 21) (ref 100FR73 21) CHRIBTOFFER,0 . CREED.J R Region 3. Office of Director 82/09/27 2pp 15610 092 24% Fiche 50-331.82/09/29.8210050000
- 8210260461 Confirms rescheduling of 1783 annual exercise to 821027 ROOTAL D. Idwa Electric Light & Power Co. 82/10/12 KEPPLER. J 9 Region 3. Office of Director 1p. 15806, 223 24X Fiche. 50-331. 82/10/12.8210260461
- P. Operating license stage documents & correspondence
- B21012003B Requests listing of all submittals re inservice testing program within 30 days in order to complete review VABBALLO,D.B. Operating Reactors Branch 2. 82/09/24. ARNOLD.D lows Electric Light & Power Co. 2pp 15689
- 8210130050 Requests remittence of add1 fee for review of 820820 application proposing Tach Spac change for delay in implementation of surveillance requirements for functional testing of machanical snubbers.

  DIGOS, R. M. License Fee Management Branch 82/09/28 ARMOLD, DIGOS Electric Light & Power Co. 1p. 15694, 360 24% Fiche: 50-331, 82/09/28, 8210130050.
- 8210130509 Forwards "Regulatory Performance Improvement Program," in response to 820604 request for plan to upgrade regulatory partormance LIU.L. I awa Electric Light & Power Co B2/09/30 Region 3, Office of Director 2pp, 15682, 194. Fiche: 50-331, 82/09/30, 8210130509. 82/09/30 | 82.194. 24X
- --8210190517 "Regulatory Performance Improvement Program "

   Inum Electric Light & Power Co 82/09/30, 31pp. 15882 194
  24X Fiche 30-331.82/09/30.8210130309

- 'ZIO(50160 Responds to NRC 820809 ltr re schedule for providing addl info on NUREO-0737. Item II B 3. "Post-Accident Bampling "Updated comparison of post-accident sampling sys against criteria of NUREO-0737 will be submitted 821101 FOOT: D. Iowa Electric Light & Power Co 82/10/08 DENTON.H Office of Nuclear Reactor Regulation, Director 2pp 15698 304 24% Fichs 50-231,82/10/08,8210150160
- -210260489 Forwards for review "MSIV Local Leak Rate Testing," per 1005R50.App J & Reg Guide 10 1 MINECK.D L lowa Electric Light & Power Ca 82/10/15 DENTON,H R Office of Nuclear Reactor Regulation, Director 10 15807 130 24X Fiche 50-331,82/10/15,8210260489
- -8210260495 "MSIV Local Leak Rate Testing "

  lowa Electric Light & Power Co 82/10/15 93pp 15807 131 24% Fiche 50-331,62/10/15,8210260489
- 12 10240138 Requests revision of scheduled commitment dates for PAUREO-0737, Item II F 1. "Accident Monitoring " Five of six Progineering mad packages completed Bys should be operational by end of Nov 1982 RODT, L b lower Electric Light & Power Co 82/10/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 15799 092 24X Fiche 50-331, 82/10/18,8210260138
- Inspection reports. IE Bulletins & correspondence
- -210040202 Forwards IE Insp Rept 50-331/82-15 on 820809-13.16 & 23 & motice of violation
  PAPERIELLO, C. J. Division of Emergency Preparedness & Operational
  Support 82/09/10 ARNOLD, D. Iowa Electric Light & Power Co. 2pp
  15283 146 248 Fiche 50-331/82/09/10.8210040202
- --B210040204 Notice of violation from insp on 820809-13,16 t 23 PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 82/09/08 ip 13583 148 24X Fiche 50-331,82/09/10, 8210040202
- --8210040208 IE Insp Rept 50-331/82-15 on 820809-13.16 & 23 Moncompliance moted failure to include gamma spectrometer in QC program & absence of calibr procedures

  JANUSKA: A 0 , ROZAK, 8 , BCHUMACHER, M C Region 3, Office of Director 82/09/08 12pp 15583 149 24% Fiche 50-331.82/09/10.8210040202
- B21009030b Ack receipt of 820909 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-331/82-07
  SPESSA9D, L Division of Project & Resident Programs. 82/09/24
  ARNOLD. D. lous Electric Light & Power Co Ip 19610-084. 24X
  Fiche 50-331, 82/09/24, 8210050306
- --8210050307 Responds to NRC 820810 ltr re violations noted in IE Insp Rept 50-331/82-07 Corrective actions operators retrained & re-examined, operations manual modified & integrated plant sperating instructions changed ROUTL D Joua Electric Light & Power Co 82/09/09 KEPPLER: J Q Region 3. Office of Director 5pp 15610 085 24% Fiche 50-331.82/09/24,8210050306
- 8210050309 Forwards IE Safeguards Insp Rept 50-331/82-10 on 820621-25 & notice of violation W/o notice of violation MILLER.J R Division of Engineering & Technical Programs. 82/09/29 ARNOLD.D I Jowa Electric Light & Power Co 2pp 15610 090 24X Fichs.50-331.82/09/29.8210050308
- -- E210050311 IE Befeguards lnsp Rept 80-331/82-10 on 820621-25 Noncompilance noted failure to maintain adequate detection aids & to provide adequate access control Details withheld (ref 10CFR73 21). CHR18TDFFER.O., CREED, J. R. Region 3. Office of Director 82/09/27 2pp 18610 092 24X Fichs 50-331.82/09/29, 8210050308
- B210190360 Forwards IE Insp Rept 50-331/82-04 on 820208-12,0308-10 & 0525-28 & notice of violation MORELIUS, C E Division of Engineering & Technical Programs, 82/10/05 ARNLD, D Towa Electric Light & Power Co, 2pp. 15740 324 24% Fithe 50-331,82/10/05,8210190360
- -- B210190362 IE Insp Rept 50-331/82-04 on 820208-12,0308-10 & 0525-28 Nancompliance noted failure to meet Tech Spec requirements. Section 3 re facility audits & failure to implement requirements of 10CFR50 App B.Criterion XVIII & V. HULZMER, M M, SHAFER, W D, HAMKINS, F C Division of Engineering & Technical Programs 82/10/01. 15pp. 15740-332. 24% Ficher 50-331,82/10/05,8210190360.

- B20B190233 IE Info Notice B0-35. Buppl i. "Leaking & Dislodged I-125 Implant Seeds." Svc list encl COBS.L I. Division of Fuel Facilities. Materials & Bafaguards 82/10/06 Consolidated Edison Co of New York & App 15761 250 24X Fichs 50-000.B2/10/06.8208190233
- 8210130546 Forwards addl info re IR Bulletin 80-11; "Masonry Wall Design," consisting of Revision 1 to 180-day final rept All outstanding requests for info answered Info demonstrates structural adequacy of masonry walls RRDT.L.D lowe Electric Light & Power Co 82/10/06 DENTON,H R Office of Nuclear Reactor Regulation, Director 62pp. 15682 290 24% Fichs 50-331.82/10/06.8210130546
- 8210250336 Forwards IR Insp Rept 50-331/82-11 on 820719-22 & notice of violation NORELIUS, C E Division of Engineering & Technical Programs 82/10/07 ARNOLD, D Iowa Electric Light & Power Go 2pp 15790 311 24% Fishe 50-331,82/10/07,8210250336
- --8210250342 Notice of violation from idsp on 820719-22 NORELIUS.C E Division of Engineering & Technical Programs 82/10/07 2pp 15790 313 24K Fiche 50-331.82/10/07.8210280386
- --8210250350 IE Insp Rept 50-331/82-11 on 820719-22 Moncompliance noted failure to establish ref speeds for inservice testing of RCIC & HPCI pumps & inadequate preoperational testing of most to RHR syc water sys performed under Design Change 760 CONNAUGHTON, K. HAHKINS, F. C. Division of Engineering & lechnical Programs 82/09/23 7pp 15790 315. 24X Fiche 50-331,82/10/07,8210250336
- 8210190643 Ack receipt of 820928 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-331/82-00 STREETER, JF Division of Project & Resident Programs 62/10/13 ARNOLD.D lows Electric Light & Power Co 1p 15737 214 24X Fichs 30-331,82/10/13,8210190643
- --8210190664 Responds to NRC 820827 ltr re violations noted in II: Imap Rept 50-331/82-08 Corrective actions administrative procedures to be revised to include monthly review of document change form log to identify changes RDDT.L D lowe Electric Light & Power Co. 82/09/28, KEPPLER.J.Q Region 3. Office of Director 2pp 15737 218 24x Fiche 50-331/82/10/13.8210190643
- 820B19023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diemeter, Stainless Btool-Recirculation Mys Piping at BHR Flants " Svc list and! DEYGUNG: R C Director's Office, Office of Inspection and Enforcement 82/10/14, Compolidated Edison Cn of New York, (18pp. 15810-125, 24x Ficher 50-000, 82/10/14, 820819023B
- R Periodic operating reports & related correspondence
- 6210200093 Forwards monthly operating rept for Bept 1982 MINECK,D L. Ipwa Electric Light & Power Co. 62/10/13 Director's Office, Office of Inspection and Enforcement ip 15737 216 24x Fiche: 50-331, 82/10/13, 8210200093.
- --8210200096 Monthly operating rept for Best 1982 WATEGM. M & I Town Electric Light & Power Co 62/10/13 7pp 15757:217 24X Fiche 50-331, 82/10/13, 8210200093
- 8. Reportable occurrences. LERs & related correspondence
- 8210010008 Responds to FDIA request for 19 categories of documents re nuclear reactor events t safety problems Forwards documents fisted in App A FELTON.J M Division of Rules and Records. 82/06/28, UDELL.H.A Critical Mass Energy Project 15pp. 13727:005. 24X Fiche:50-000,82/06/28,8210010008.
- ~-8203120103 Submits engineering evaluation re loss of river water eys loop. One loop of river water sys became inoperable due to closged filter.

  HOLF: TR Director's Office, 92/03/01 Director's Office 3pp. 15793 154 24% Fiche: 50~000, 82/05/28, 8210010008.
- 8210040369 Forwards LER 82-056/01T-0. MINECK.D L lows Electric Light & Power Co. 82/09/24 KEPPLER.J.Q Region 3. Office of Director. ip. 15587.130, 24X Fiche: 50-331.82/09/24.8210040369.
- --8210040376 LER 82-056/01T-0: on 820912. HPIC area stram leak alarm activated by temp differential switch TDB-2250A: resulting from leak due to teap difference between ventilation intake & exhaust. Caused by false signal due to resistor failure HILL: K.L. fowa Electric Light & Power Co. 82/09/24. Region 3, Office of Director. 3pp 15587. 132. 24K Fichs. 80-331, 82/09/24.

- 8210130133 Forwards LER 82-057/03L-0 MINECK.D L fows Electric Light & Power Co 82/10/01 KEPPLER.J G Ragian 3, Office of Director 1p 15673 095 24X Fiche.50-331.82/10/01.8210130133
- --B210130137 LER 82-057/03L-0 on B20702, during normal operation, while investigating river water intake sys 10-102 trouble alarm, mode switch HS-29058 found in off position Caused by lack of procedural guidance Procedures under review HILL, K. Inwa Electric Light & Power Co 82/10/01 Region 3. Office of Director 1p 15673 076 24% Fiche 30-331.82/10/01, 8210130133
- 8210130393 Forwards LER 82-058/03L-0 MINECK.D L Tows Electric Light & Power Co 82/10/01 KEPPLER.J G Region 3. Office of Director 1p 15680 360 24X Fiche 50-331.82/10/01.8210130393
- --8210130398 LER 82-058/03L-0.on 820910, river water supply sys traveling screen IF-368 would not run in auto or continuous mode Caused by low discharge pressure for screen wash pump Permissive pressure switch PB-2903 recalibr
  HILL, K L Iowa Electric Light & Power Co 82/10/01 Region 3, GPfice of Director 1p 15680 361 24X Fiche: 50-331,82/10/01, 8210130393
- 8210130585 Forwards LER 82-057/03L-0 MINECK.D L I Juma Electric Light & Power Co 82/10/01 KEPPLER.J Q Region 3, Office of Director Ip 15679 061 24X Fiche 50-331, 82/10/01.8210130585
- --8210130590 LER 82-059/03L-0 on 920910, worken in reactor core isolation cooling (RCIC) room reported marked increase in room temp Caused by broken drive belt in RCIC room cooling unit IV-AC-15A due to random failure
  HILL,K L Iowa Electric Light & Power Co 82/10/01 Region 3, Office of Director 1p 15679 062 24X Fiche 50-331,82/10/01,8210130585
- 8210250251 Forwards LER 82-063/03L-0 MINECK.D L. Jows Electric Light & Power Co. 82/10/11 KEPPLER.J G Region 3. Office of Director ip 15791 158 24X Fiche 50-331.82/10/11.8210250251
- --8210230261 LER 82-063/03L-0.on 820927. reactor bldg isolation damper iV-AD-1783, reducing transport of airborns contamination from reactor bldg, failed to close upon receipt of isolation signal Caused by rust on pieton & cylinder HILL.K L. Iowa Electric Light & Power Co. 82/10/08 Region 3 Office of Director ip 1579:159 24X Fiche.50-331,82/10/11.
- 8210250289 Forwards LER 82-062/03L-0 NINECK.D L Idwa Electric Light & Power Co 82/10/11 KEPPLER.J G Region 3. Office of Director 1p 18791 162 24X Fiche.50-331.82/10/11.8210250289
- --B210250300 LER 82-062/03L-0, on 820922, surveillance testing pressure differential suitch PB8-4304, controlling reactor bldg to suppression chamber vacuum breaker CV-4304) tripped below Tech Spec 11mit, Caused by instrument drift Suitch recallor HTLL.K L lowa Electric Light & Power Gc. 82/10/11 Region 3, Office of Director 1p 15791 163. 24X Fiche: 50-331, 82/10/11, 82/10230289
- 8210250384 Forwards LER 92-061/03L-0 MINECK.D L. Idwa Electric Light & Power Co 82/10/12 KEPPLER, J Q Region 3. Office of Director ip 15790.080 24X Fiche 50-331, 82/10/12,8210250384.
- --8210250387 LER 82-061/03L-0 on 820914.RHR svc water pumps 1P-22A & 1P-22D failed to meet Tech Spec requirements Caused by excessive clearances between pump inpellers & casing wear rings due to pump wear. Impellers adjusted & pumps tested.
  HILL, K. L. Inwa Electric Light & Power Co. 82/10/12 Region 3 Office of Director. 1p. 15790 089. 24X Fiche: 50-331.82/10/12, 82/10/250384
- DOCKET BO-333 JAMES A. FITZPATRICK NUCLEAR POWER PLANT
  F Security, medical, emergency & fire protection plans
- 8210030083 Forwards "Dispersion Hodel Description for Nine Hile Point/ James A Fitzpatrick Nuclear Stations:" upgraded meteorological sys description per TMI Action Item III A.2 BAYNE.J.P. Power Authority of the State of New York. 82/10/01. VASBALLO.D.B. Operating Reactors Branch 2 2pp. 18604:235 24X Fiche: 50-333. 82/10/01.8210030083

- --8210050085 "Dispersion Model Description for James A Fitzpatrick/Nins Hile Point Nuclear Stations" + Power Authority of the State of New York 82/10/01 17pp 15504 257 24X Fiche 50-333.82/10/01.8210050083
- 8210260334 Act receipt of 820805 ltr informing NRC of steps taken to correct violations noted in IE Health Physics Appraisa)
  Rept 50-333/80-20 Full ALARA program implementation prior to 1983 refueling outage understood
  MARTIN.T T Division of Engineering & Technical Programs 82/10/21
  MCNEILL.C A Power Authority of the State of New York 2pp 15802 342 24X Fiche 50-333/82/10/21/8210260334
- --8210260338 Suppls response to NRC 820120 & 0702 ltrs re items noted in IE Health Physics Appraisal Rept 50-333/80-20 Corrective actions schedule for technician retraining setablished & engineering controls will be part of ALARA program MCNEILL.C A Power Authority of the State of New Yors 82/08/05 HARTIN.T T Division of Engineering & Technical Programs 3pp 19902 344 24X Fichs 50-334, 82/10/21,8210260334

### H Gameral correspondence

- 8210190713 Informs that SS Zullo & RA Burns authorized to sign util ltrs to NRC. BAYNE.J.P Power Authority of the Btate of New York B2/10/13 Office of Nuclear Reactor Regulation, Director 2pp 15738, 209 24X Fiche 50-000, 82/10/13, 8210190713
- P Operating license stage documents & correspondence
- 8210290410 Discusses add1 considerations that should be addressed in future proposed Tech Spec mods to 115 kV offsite (reserve) ac power sys, in response to util 820914 request VASSALLO, D B Operating Reactors Branch 2 82/10/04 SINCLAIR.L W Power Authority of the State of New York 5pp 15863 250 24K Fiche 50-333,82/10/04,8210290410
- 82:0130031 Forwards addl payment required for 820604 application to amend Tach Specs re mgt organization structure, per NRC 82:0714 ltr Addl payment made under protest pending final determination of legality of fee schedule 84YNE.JP Power Authority of the State of New York 82/10/08 HILLER,W G License Fee Management Branch 3pp 15701-265 24X Fiche: 50-000.82/10/08,8210150031
- 8210200028 Forwards 820226 submittal re results of review of NVREO-0612. "Control of Heavy Loads"

  BAYNE,J P Power Authority of the State of New York 82/10/15
  VASSALLO,D. Licensing Branch 2 ip 15756 056 24X
  Fiche 50~333,82/10/15.8210200028
- --8210200039 Forwards results of second phase review of heavy load handling operations & response to Sections 2 2,2 3 & 2 4 of Enci 3 to 801222 ltr Consequences of certain load drops do not meet NUREG-0612 guidelines.

  BANNE, J P Power Authority of the State of New York, 82/02/26 VASSALLO, D Operating Reactors Branch 2 65pp 15756 057 24K Fiche 50-338, 82/10/15.8210200028.
- 8210200074 Forwards response to 820806 request for add) info ra NUREO-0737. Item II D. i, "Relief & Safety Valve Test Requirements" BAYNE.J.P Power Authority of the State of New York 82/10/15 VASBALLO.D B Operating Reactors Branch 2, 17pp 15757 263 24K Fiche: 50-333, 82/10/15.8210200074
- Q Inspection reports, IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of Info ranctear reactor events & safety problems Forwards documents listed in App A. Documents in App B completely withheld (ref FOIA Exemption 5) FELTON, J M. Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project. 9pp. 15665:027 24X Fiche:50-000,82/07/12,8210080015.
- --92100B0134 Bigstematic assessment of licenses parformance notes #s facility evaluation for Dec 1979-Nev 1980 # NRC - No Detailed Affiliation Given. 80/11/30 9pp 13667.349. 24X Fiche.50-000,82/07/12,8210080015.
- 8210040317 Forwards partial response to NRC 820414 request for additinfo re inservice insp program. Response to Items 8 & 10 will be provided by 821208 or approx 30 days after start of next scheduled outage
  84YNC, J.P. Power Authority of the State of New York, 82/09/28
  VASBALLO, D. B. Operating Reactors Branch 2 10pp 15586 157 241
  Fiche 50~333, 82/09/28, 8210040317.

- E210070362 Forwards Page 12A to 820914 IE Insp Rept 50-333/82-19.
  inadvertently omitted due to administrative error
  STAROSTECKI.R Division of Project & Resident Programs 82/10/04
  MCHELL.C A Power Authority of the State of New York 19
  15634 038 24X Fiche 50-333.82/10/04.8210070362
- --B210070367 Page 12A to IE Insp Rept 50-333/82-19 on 820914, inadvertently amitted from original rept
  \*\* Region 1. Office of Director 82/10/04 ip 15634 039 24X Fiche 50-333,82/10/04,8210070362
- 8208190233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged I-125 Implant Seeds " Svc list and COBB.L. I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 244 Fichs 50-000,82/10/06.8208190233
- 8210150271 Ack receipt of 820917 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/82-15
  STAROSTECKI: R Division of Project & Resident Programs 82/10/07
  MCHELL.C A Power Authority of the State of New York 1p
  15703 237 24X Fichs 50-333.82/10/07.8210150271
- --8210150283 Responds to NRC 820820 ltr re violations noted in IE Insp Rept 50-333/82-15 Corrective actions solid radwaste sys procedure revised issue dates of maint procedures reviewed & security guards instructed to monitor more closely MCNEILL.C A Power Authority of the State of New York 82/09/17 STAROBTECKI.R Division of Project & Resident Programs 6pp 15703 238 24X Fiche 50-333, 82/10/07,8210150271
- 8210210100 Forwards IE Insp Rept 50-333/82-i1 on 820901-30, No nencempliance nated STAROSIECKLIR Division of Project & Resident Programs. 82/10/07 FITZPATRICK, J Power Authority of the State of New York 2pp 15765 307 24X Fichs 50-333.82/10/07.8210210100
- --8210210115 IE Insp Rept 50-333/82-11 on 820901-30 No noncompliance noted Major areas inspected action on previous insp findings. LER review, operational safety verification, surveillance & maint observations & NUREO-0737 items LINVILLE.J.C., DOERFLEIN.L.T., KISTER.H.B. Region 1. Office of Director 82/10/06 12pp 15765 309 24X Fiche 50-333.82/10/07, 8210210100
- 8208170238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants "Svc list encl DEYDUNOR C. Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche, 50-000, 82/10/14,8208170238
- 8210190411 Forwards inservice insp summery rept for Winter 1981-82 outage & two metallurgical analyses. "Metallographic Investigation of Type 304 Btainless Eteel Schedule 80 Pipe " Results of insps acceptable EAYNE.J P Power Authority of the State of New York 82/10/15 VASSALLO.D B Operating Reactors Branch 2. 2pp 15743-103 24 Fische 30-333, 82/10/15,8210190411
- --B210190420 "Metallographic Investigation of Type 304 Stainless Steel Schedule 80 Pipe " BUCHHEIT.R D Battelle Memorial Institute, Columbus Laboratories, 82/03/25, 18pp 15743 105 24X Fiche 50-333,82/10/15,8210190411
- --B210190428 "Investigation of Flaws on Inside Surface of Type 304 Stainless Steel Schedule 80 Pipe " \* Battelle Memorial Institute, Columbus Laboratories 82/07/30, 51pp 15743, 123. 24% Fiche, 50-333,82/10/15,8210190411
- B210240334 Ack receipt of 820805 ltr informing NRC of steps taken to correct violations noted in IE Health Physics Appraise!
  Rept 50-333/80-20 Full ActARA program implementation prior to 1783 refueling outage understood.
  MARTIN.T T Division of Engineering & Technical Programs #2/10/21 MARTIN.T Division of Engineering & Technical Programs #2/10/21 15802:342. 24X Fichs 50-333, 82/10/21,8210240334.
- --3210260338 Bupple response to NRC 820120 & 0702 itrs re items noted in IE Health Physics Appraisal Rept 50-333/80-20 Corrective actions schedule for technician retraining established & engineering controls will be part of ALARA program MGNEILL, C.A., Power Authority of the State of New York, 82/08/05 MARTIN, T.T. Division of Engineering & Technical Programs, 3pp. 15802.244. 24X Ficha: 50-333, 82/10/21, 8210260334

- R Periodic operating reports & related correspondence
- 821020001B Forwards updated monthly operating rept for Jan 1982 MCNEILL, C A Power Authority of the State of New York 82/02/03 Management Information Branch 1p 15756 122 24X Fiche 50-333, 82/02/03, 821020001B
- --8210200024 Updated monthly operating rept for Jan 1982 ZUFELT.E Power Authority of the State of New York 82/02/28 12pp 15756 123 24X Fiche 50~333,82/02/03,8210200018
- B210120240 Forwards monthly operating rept for Sept 1982
  MCNEILL, C A Power Authority of the State of New York
  Director's Office. Office of Imspection and Enforcement 19
  15682 116 24% Fiche 50-303,82/10/04,8210120240
- --8210120243 Monthly operating rept for Bept 1982 COOK, J. Power Authority of the State of New York 82/10/04 7pp 15652 117 24X Fiche 50-333,82/10/04,8210120240
- S Reportable occurrences: LERs & related correspondence
- 8210040324 Forwards LER 82-042/03L-0 MCNEILL, C A Power Authority of the State of New York 82/09/21 HAYNES, R C Region 1, Office of Director 1p 15586 185 24X Fiche 50-333.82/09/21.8210040324
- --8210040332 LER 82-042/03L-0 on 820826, testing of control rod hydraulic control unit accumulator pressure & level switches & pressure indication revealed &8 of 411 instruments out of calibr or not operating properly Caused by instrument drift KEITH.H N Power Authority of the State of New Yort 82/09/21 Region 1. Office of Director 2pp 15586 186 24X Fiths 50-333,82/09/21,8210040324
- 8210060285 Forwards LER 82-043/03L-0 MCNEILL,C A. Power Authority of the Btate of New York 82/09/24 HAYNES.R C Region 1. Office of Director 1p 15621 069 24X Fichs 50-333, 82/09/24, 8210060285
- --8210060292 LER 82-043/03L-0 on 820902, MBIV D inboard 10% switch would not reset when tested to satisfy Tech Spec 3 i-1 Caused by drift between switch operator & striker plate Switch striker plate modified XEITH, H N Power Authority of the State of New York 82/09/24 Region I, Dffice of Director ip 15621 070 24% Fiche 50-33, 92/09/24, 8210060285
- 8210220519 Discusses 820501 event re oscillation of frequency & output power in emergency diesel generator sys Root cause of diesel generator failures unknown Efforts on flow blockage of cooling water to safety sys adequately address problem CHIRAMAL.M Reactor Operations Analysis Branch 82/10/01 SEYFRIT.K V Reactor Operations Analysis Branch 7pp 13786.077 24X Fiche 50~333.82/10/01.8210220519
- 8210190069 Forwards LER 82-044/03L-0 MCNEILL, C A Power Authority of the State of New York 82/10/07 HAYNES.R C. Region 1. Office of Director 1p 15742 134 24X Fiche 50-333, 82/10/07, 8210190069.
- --8210190077 LER 82-044/03L-0.on 820909, motor operator electrical breaker tripped while attempting to cycle LPCI injection valve Caused by electrical motor fault resulting in isolation failure created during attempted valve cycling FERNANDEZ.W. Power Authority of the State of New York Region 1, Office of Director 1p 15742 135 24% Fiche: 50-333, 82/10/07, 8210190069.
- 8210220255 PND-I-82-066 on 821018, Guadrex Corp shielded van transporting four empty spent fuel racks to Oak Ridge.TN collided w/automobile in North Syracuse.NY Radiation surveys did not identify any damage to packaging CLEMONS.P.: OREENMAN.E., BRUNNER.E Region i, Office of Director. 82/10/19, 1p. 15775 358 24X Fiche.50-333.82/10/19,8210220255
- 8210260170 Forwards LER 82-018/03X-1 MCNEILL.G.A Power Authority of the State of New York B2/10/19 HAYMES.R.C Region i, Office of Director. ip 15799:050 24X Fithe 50-333, 82/10/19, B210260170.
- --8210260175 LER 82-018/03X-1. on 820419, surveillance testing indicated four smote detectors inoperable Causad by failure to terminate connecting cabling properly due to inadequate procedure preparation & review Procedure to be revised.

  \*\* Power Authority of the State of New York. 82/10/19
  in Office of Director 4pp 15799.051 24X Fichs.50-333, 82/10/19.8210260170

- 8210260306 RO on 820628, combustion in offgas sys observed Caused by improper valve lineup allowing more gas to recombiner than district flow rate could support Incident discussed w/shift supervisor & training will be developed MCNEILL, C A Fower Authority of the State of New York 82/10/19 HAYNES, R C Region i. Office of Director 3pp 15803 009 24X Fiche 50-333, 82/10/19, 8210260306
- 8210260378 Forwards Updated LER 82-028/03X-1 MCNEILL.C A Power Authority of the State of New York 82/10/19 HAYNES, R C Region 1. Office of Director ip 15804:252 24X Fiche 50-333, 82/10/19, 8210260378
- --8210260386 Updated LER 82-028/03X-1 on 820701 drywell equipment drain sump flow integrator found out of calibr & could not be adjusted Caused by abnormal friction in drive gear train New gears purchased to rebuild unit.

  # Power Authority of the State of New York 82/10/19 Region 1 Office of Director 2pp 15804 253 24X Fiche 50-333, 82/10/19.82108/0378

### DOCKET 50-334 BEAVER VALLEY POHER STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 9210010013 Forwards add1 info requested on 820726 re changes to guard training & qualification plan. Enfo withheld (ref 10CFR2, 790 & 10CFR2, 790 B. 10CFR2, 790 & 10CFR2, 790 CAREY, J. J. Duquesne Light Co. 82/09/20 VAROA: 8 A. Assistant Director for Operating Reactors. 1p. 15565 147 24X Fiche, 50-334, 82/09/20, 8210010013
- 8210080045 Notification of 820930 meeting w/util in Bethesda,MD to discuss upgrading of meteorological sys TAM.P S. Operating Reactors Branch i. 82/09/23 VARQA, B A Operating Reactors Branch i 2pp 15669 317 24X Fiche, 50-334, 82/09/23, 8210080045
- 8210180016 Releases public version of revised emergency preparedness implementing procedures FELTON. J M Division of Rules and Records 82/09/29 Document Management Brench 1p 15717-318 24X Fiche 50-334,82/09/29, 8210180014
- 8210260122 Releases public version of revised emergency plan implementing procedures. FELTON.J K Division of Rules and Records. 82/10/08 Document Hamagement Branch 1p. 15812 031 24X Fiche: 50-334,82/10/08. 8210260122.
- --8210260125 Forwards public version of revised emergency plan implementing procedures, including Procedures EPP/IP i.i renotification, i.2 recommunications & dissemination of info & i.3 returnover status chacklist SIEBER. J D Duquesne Light Co 82/09/i4, VAROA.S. A. Operating Rectors Branch i. Spp. 15812.032. 24X Fichs. 50-034, 82/i0/08.8210260122
- --821026012? Public version of revised amergancy plan implementing procedures including Procedures EPP/IP 1 ire notification, 12 re communications & dissemination of info & 1.3 re turnover status checklist LACEV.W J Duquesne Light Co. 82/09/15, 834pp. 15812-035, 24X Fither 50-334, 82/10/08-8210260126
- 8210280411 Informs that proposed changes to access control program contained in licenses 820702 ltr acceptable. Final approval cannot be granted until necessary changes to physical security plan submitted.

  VAROA.S.A. Operating Reactors Branch 1 82/10/08, CAREY, J. J. Duquesne Light Co. 2pp. 15859 334. 24K Fiche: 50-334, 82/10/08, 82/
- 8210260458 Forwards supplemental info per 821014 discussion clarifying exemptions previously documented in fire protection App R review Section 11.2. "Reactor Containment" & Section 11.6. "Primary Auxiliary Bidg."

  CAREY, J. J. Duquesne Light Co. 82/10/22 VARGA, 8. A. Operating Reactors Branch 1 9pp 15806 200, 24X Fichs, 50-334, 82/10/22, 8210260458
- P Operating license stage documents & correspondence
- 8210120120 Advises that no further oft action planned re 800521 inoperability of RHR sys for 5-h since pipe crack study group will issue rept in 2 wts. Sys inoperability due to weld leak reperir effort LANNING, W. D. Director's Office 80/08/04, Director's Office, 1p 13692-254, 24% Fiche: 50-334, 80/08/04, 8210120120.

- 8210050487 Forwards request for additinfors proposed changes to Teth Spets for leak rate testing of certain isolation valvas using water in lieu of air or nitrogen Response requested within 30 days of receipt of itr VARQA.S A Operating Reactors Branch 1 82/09/21 CAREY. J Duquesne Light Co 3pp 15626 283 24X Piche 50-334, 82/09/21, 8210050487
- 8210050165 Forwards util summary of efforts re rod position indication sys per 820713 commitment & 820720 ltr Westinghouse companion rept expected by mid-Oct CAREY, J J Duquesne Light Co 82/09/29 VAROA, 8 A Operating Reactors Branch i 2pp 15605 122 24X Fiche 50-334, 82/09/29, 0210080145
- ~-821005016B "Beaver Valley Power Station,Unit 1 Analog Ros Position Indication Sys." special rept ORADA.K D . BIEBER.J D Duqueens Light Co 82/08/31 20pp 13605 124 24X Fiche 50-334.82/07/27.8210050165
- 8210130561 Forwards addl info re proposed changes to Tech Boecs for leak rate testing of certain isolation valves using water in lieu of gas.in response to NRC 820721 request 1/27 oversize drawings Aperture cards are available in PDR CAREY, J J Duquesne Light Co 82/10/05 VARQA, 8 A Operating Reactors Branch 1 35pp 15679 015 24X Fiche 50-334,82/10/05,82/10/30564
- 8210150312 Forwards "Cycle 3 Startup Test Rept " Rept summarizes test performed & verifies Cycle 3 reload core design date after criticality & calibr of excore instrumentation at several different power levels CAREY. J. Duqueene Light Co 82/10/05 HAYNES.R C Region 1. Office of Director ip 15701 345 24X Fiche 50-334.82/10/05. 8210150312
- --8210150316 "Cycle 3 Startup Test Rept "

  \* Duquesne Light Co 82/10/05 5pp 15701,346 24x
  Fiche 50-334,82/10/05,8210150312
- 8210190747 Forwards add1 info re two-loop operation per NRC 820817 request. Westinghouse reviewing Question 7 against analysis CAREV. J Duquesne Light Co 82/10/08 VARCA: 8 A Operating Reactors Branch I. 6pp 15737 135. 24X Fichs 50-334, 82/10/08, 8210190747
- 8210270267 Forwards revised application for amend to License DFR-66. consisting of Proposed Change Request 36 Revision 3, incorporating radiological effluent Tech Spaces into App A Offsite dose calculation manual & App B will follow CAREY, J. Duquesne Light Co 82/10/22 VARGA, B A Operating Reactors Branch 1. Ip 15828 287 24% Fiche 50-334,82/10/22,8210270267
- --B21027026B Revised application for emend to License DPR-66, incorporating proposed rediological effluent Tech Specs into App A. GAREY, J. J. Duquesne Light Co. B2/10/R2 ip 15828, 268 24x Fiche 50-334, B2/10/22, B210270267.
- --8210270271 Proposed radiological effluent Tech Bpets \* Duquesne Light Co 82/10/22 116pp 15828 289 24x Fiche 50-334,82/10/22,8210270267
- Q Inspection reports: IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of inf nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5), FELTON.U.M. Division of Rules and Records 82/07/12, UOELL.R Chitical Mass Energy Project 9pp. 15665-027, 24X Fiche: 30-000, 82/07/12, 8210080015.
- --B2100B0114 By stematic assessment of licensee performance notes factIIIty evaluation for Bept 1979-Aug 1980 \* NRC No Detailed Affiliation Given B0/0B/21 16pp. 15667 299 24X Fithe 50-000, 82/07/12, 82100B0015
- B210070007 Responds to FOIA request for eight categories of recent steam generators & steam turbines App A documents provided in R Udell FOIA Request B1-313 Forwards documents listed in App B.
  FELTON, J.M. Division of Rules and Records. B2/0B/10 LONG, D. Winthrop, Btimson, Putnam & Roberts, 9pp 15645:063 24X Fiche: 50-000, 82/0B/10, 8210070007
- --8210070139 Forwards tabulated data on steam generator insp & eat facilities. Data should be provided to licensess IPPOLIYO.T. Operating Reactors Assessment Branch, 82/04/01 VAROA.S. Operating Reactors Branch 1. 5pp. 15645.136. 24X Fiche: 50~000, 82/08/10.8210070007

- 3170233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Filat Seeds " Svc list encl.
  333.L 1 Division of Fuel Facilities, Haterials & Safeguards 2710/06 Consolidated Edison Co of New York 66pp 19761-250 ft Fiche 50-000,82/10/06,8208190233
- C21023: Forwards IE Insp Rept 50-334/82-21 on 820816-20 No categoriance noted ARTIM T Y Division of Engineering & Technical Programs. 82/10/06 CAREY, J J Duguesny Light Co 2pp 15766 274 24X sche 50-334,82/10/06:82102/0231
- 210210236 IE Insp Rept 50-334/82-21 on 820816-20 No noncompliance roted Hajor areas inspected administrative controls for safety-related maint maint program & activities surveillance testing & calibr programs & housekeeping & classifices testing & calibr programs & housekeeping & classifices testing & calibr programs & housekeeping & classifices of Birector. Studience. Region 1, Office of Birector. 82/09/23 25pp 15766.296. 24X Ficher 50-334.82/10/06.8210210231
- O150G15 Ack receipt of 820930 ltr informing NRC of steps taken to errect violations noted in IE Insp Rept 50-334/82-6.

  1/AROSECKI.R Division of Project t Resident Programs 82/10/08.

  APEV.J J Duquesne Light Co 19. 18698.328 24X

  1che 50-334.82/10/08.82/050015.
- i210150018 Responds to NRC 820830 ltr re violations noted in IE Insp. Rept 50-334/82-16 Corrective actions: detector cables of M-NI41 reconnected in correct position & maint manual changed to insert caution re proper handling CAREY. J Duquesne Light Co. B2/09/30, BTAROBTECKI, R Division of Project & Resident Programs App. 15690,329, 24X Fiche 50-334,82/10/08,8210150015
- IOR20184 Advises that revised completion date for evaluation of calibr radiation beam uniformity is \$21031, per IC Health Physics Appraisal Rept 50-334/81-05.
  CAREY, J. Duquesne Light Co. 62/10/08 HAYNCB, R.C. Region 1, Diffice of Director. 2pp 15776-244 24X Fiche 30-334,62/10/08,8210220184
- OB190238 IE Bulletin B2-03, "Btress Corrosion Cracking in Thick-Wall-Large-Diameter, Stainless Steel-Recirculation Bys
  Figure at BHR Plants " Syc list encl
  DEYOUNDER C Director's Office, Office of Inspection and
  Enforcement B2/10/14 Consolidated Editon Co of New York
  115pp 15810 128 24X Fiche: 50-000, 02/10/14, 8208190238

### Persodic operating reports & related correspondence

- 210050076 Forwards revised Page 4 of "1981 Rept of Facility Changes, Tasts & Experiments "CAREY.J Duguesne Light Ca 82/07/23 HAYNGS, R C Region 1, Office of Director 1p 15615 329 24X Fiche 50-334, 62/07/23, 3210101010
- -821006003; Revised Page 4 of "198; Rept of Facility Changes, Texts & Eiperiments."

  + Duquesne Light Co 82/09/23 ip. 15415 330 24%
  Fiche 50-334, 82/09/23, 8210040076
- 210060088 Forwards NFDES discharge monitoring repts for Aug 1982 FEITKNECHT,C Duquesne Light Co 82/09/28 REID,R W Operating Reactors Branch 4. 2pp 15615 022 24X Fichs 50-004, 82/09/28. 821006088
- -8210060096 NPDES discharge monitoring repts for Aug 1982 SIEEDL L Duquesne Light Co 82/09/29 14pp. 15615:024 R4X Fishe 50-334,82/09/28,8210060088
- 5 Reportable occurrences, LERs & related correspondence
- 3210280307 LER 81-025/03L-0 on 810216, increased isskage from reactor collant (RC) loop 1A RTD manifold hot leg valve RC-20 reported. Caused by attempted maint to repair valve. Temp channels returned to avc.

  LACEY.M 8 Duquesne Light.Co 81/03/17 Region i, Philadelphia, Office of the Director (81/03/01) Rpe. 18837-283 24X Fiche 50-334, 81/03/17, 8210280307
- 8210040065 LER 81-028/00k-0. on 810219, during power operation results of surveillance test revealed reactor coolant leskage of 2.09 gpm Caused by failure of gland flange on valve Split gland flange used as mod to repair valve Mork completed 810221, LACEY.W S Duqueshe Light Co. 81/03/20 Region ir Philadelphia, Dffice of the Director (81/03/01) 2pp. 15081, 218. 24X Fiche 50-334, 81/03/20, 8210040065

- 8210280271 LER 81-027/03L-0.on 810218, at 78% power, all three chlorine detectors failed to meet min electrolyte drip nate criteria specified in surveillance tast Caused by dirty wicks which prevented flow of electrolyte. Nicks cleaned. LACEY. N. B. Duquene Light Co. 81703/20 Region 2, Atlanta, Office of the Director (81/03/01), 2pp. 15837-314 24% Fiche. 50-934, 81/03/20, 8210280271
- 8210280280 LER Bi-024/03L-0 on 810218.RCS loop flow channel indication failed to meet min flow surveillance check requirement Caused by transmitter delta pressure transducer diaphragm leakage Transmitter replaced LACEY.W B Duquesne Light Co Bi/03/20 Region i, Philadelphia, Office of the Director (81/03/01) 2pp 15837 047 24X Fiche 50-334, 81/03/20, 8210280280
- 8210130077 Forwards LERs 81-59/03L & 81-71/03L re tripping of battary charger output breaker 2 on thermal overload during surveifiance testing Recommends that licenses complete appropriate analyses & mods to prevent recurrence MICHELBON.C Director's Office 82/02/23 HAYNES.R C Region J. Office of Director. 2pp 13696 245 24% Fiche 50-334,82/02/23,82/0130077
- 8210010008 Respands to FDIA request for 17 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Crifical Mass Energy Project 15pp 15727 005 24X Fiche. 50-000, 82/06/28, 8210010008
- --8210050124 Summary of 810610 operating reactor events meeting LAINAS, O.C. Assistant Director for Safety Assessment 81/06/17 EISENRUT, D. G. Division of Licensing 5pp 15729, 217 24X Fichs. 50-000, 82/06/28, 8210010008
- ~-8210060432 Discusses inadequate switchgear cooling at facility
  Implications of event suggest that loss of ventilation sys
  could have potential safety significance requiring add1
  generic review by NRC
  MICHELSON, C Director's Office. 82/02/23 HAYNES, R. C Region 1,
  Office of Director. 2pp 15732.304 24X Fiche: 50-000, 82/06/28,
  82/00/0908
- 8210180179 Forwards LER 82-037/03L-0 LACEY.M. 8 Duquesne Light Co 82/09/27 HAYNES.R C Region 1. Office of Director. 2pp 15705, 262 24x Fiche 50-334,82/09/27, 8210180179
- --B21018020B LER B2-037/03L-0 on B20921.stwam generator 1A level protection channel III signal comparator 10-FNA76A declared inoperable dus to faulty actuation & trip setpoint drift found during surveillance testing Hagan comparator replaced & Duguesne Light Co. B2/09/27 Region 1, Office of Director 2pp. 15705-264 24X Fiche, 50-334, 82/09/27, 8210180199.
- 8210150185 Ferwards LER 82-035/03L-0 LACEY.H. 6 Duqueane Light Co. 82/09/30 HAYNES, R.C. Region 1, Office of Director. 2pp. 15707 255 24X Fishe: 50-334, 82/09/30: 8210150185.
- --B210150201 LER 82-D35/03L-0 on 820917 delta flux exceeded required target band Caused by low heater drain tank level, leading to load reduction, Control rods borated out to return delta flux to within target band.

  LACEY.H S. Duque she Light Co B2/09/30, Region 1, Office of Director 2pp. 15707 257 24X Fiche. 50-334, 82/09/30, 8210150185
- 8210190274 Forwards LER 82-034/03L-0 LACEY.W. B Duquesn's Light Co. 82/10/04 HAYNES, R C. Region I. Défice of Director. 2pp. 15742 185. 24X Fiche 50-334.82/10/04, 8210190274
- --8210190282 LER 82-034/03L-0: on 820915, during surveillance test containment vacuum pump failed required discharge flow rate. Caused by buildup of dirt & debris in discharge line. Line cleaned & suction & discharge filters replaced. LACEY.M.S. Duquesme Light Co. 82/10/04, Region 1, Office of Director 2pp 15742: 187, 24X Piche 50-334, 82/10/04, 8210190274
- 8210210006 Forwards LER 82-032/03L-0
  LACEY.N.S. Duquesne Light Co 82/10/07. HAYNES:R.C. Region i:
  Office of Director 2pp 15766:023. 24x Fiche: 50-334, 82/10/07,
  8210210006.
- --8210210010 LER 82-032/03L-0 on 820908, fire hose protection in intake structure lost when fire main tuptured in redundant underground supply leader Caused by overtorquing of flangs setscrews initiating crack.

  \*\*Buquesne Light Co. G2/10/07 Region i, Office of Director.

  \*\*2pp 15766,025. 24X Fiche.30-334,82/10/07,8210210006.

- 8210210065 Forwards LER 82-033/03L-0 LACEY, N B. Duquesne Light Co 82/10/08 HAYNES, R C. Region I. Office of Director 2pp. 15765 341 24X Fichs 50-334,82/10/08.
- --8210210072 LER 82-033/03L-0 on 820911 operators unable to reclose steam supply trip valve TV-MS-1058 of turbins driven auxiliary feedwater pump FM-P-2 Caused by washer lodged in valve trim
  - feeducer pump reverse seems by seems to the control of the control
- 8210240163 Forwards updated LER 81-091/01X-1, LACEY.N S Duqueens Light Co 82/10/11 HAYNES,R C Region 1, Office of Director. 2pp 15799 003 24X Fiche 50-334,82/10/11, 8210260163
- --8210260167 Updated LER 81-091/01X-1.on 811029.break in redundant underground 12-inch supply header resulted in loss of fire unter sys Caused by external finger corrosion along pips bottom Total sys piping change-out not warranted \* Duquerna Light Co 82/10/11 Region 1, Office of Director 2pp 15797-005 24X Fichs.50-334.82/10/11.8210260163
- 8210240203 Forwards LER 82-040/03L-0 LACEY, N S Duquesne Light Co 82/10/14, HAYNES, R. C Region 1, Office of Director. 3pp. 15804 248 24X Fichs 50-334,82/10/14,
- --8210260226 LER 82-040/03L-0 on 820919, alarm status lights & visual 210260226 LER 82-040/03L-0 on 820919.alarm status lights & visual display on core cooling monitor found extinguished. Caused by loase connection. Connection repaired Monitor to be tested & inspected in conjunction w/Westinghouse kit installation # Duquesum Light Co 82/10/10 Region 1, Office of Director ip 15804: 251 24X Fiche: 50-334, 82/10/14, 8210260203
- 82102A0478 Forwards LER 82-036/03L-0 LACEY,W 8 Duquesne Light Co 82/10/14. HAYNE8,R.C Region 1, Office of Director. 2pp 15807 253. 24X Fiche 50-334,82/10/14. B21026047B.
- --8210260487 LER 82-036/03L-0 on 820619, diesel engine cooling water inlet 210260487 LER 82-036/03L-D on 820619, deset engine cooling water in & outlet temps exceeded max allowable values rendering diesel generator 2 inoperable Caused by fouling of cooling water HX tubes. Tubes cleaned. LACEY.H. 8 Duquesme Light Co 82/10/14. Region 1, Offics of Director 2pp. 15807-255, 24X Fichs 50-334,82/10/14,8210260478.
- 8210220447 PNO-1-82-065 on 821018, reactor tripped on high level in steam generator due to erratic operation of feedwater control valve. Resulting feedwater isolation tripped motor-driven main feedwater pumps & auxiliary pumps started.
  NORRHOLN.L . KEINIO:R Region 1. Office of Director. 82/10/18 1p. 15778 245. 24X Fiche: 5G-334.82/10/18.8210220447.

DOCKET 50-335 ST. LUCIE PLANT, UNIT 1 F Security, medical, emergency & fire protection plans

- B210010155 Forwards IE Insp Repts 50-335/B2-28 & 50-389/B2-37 on S20B09-13.No noncompilance noted DANCE.H.C. Division of Project & Resident Programs B2/09/08. URRIO:R E Florida Power & Light Co. Epp. 15565:326 24X Fiche, 50-335, 82/09/08, 8210010155
- --8210010159 IE Insp Repts 50-335/82-28 & 50-389/82-37 on 820809-13 No noncompliance noted Megor areas inspected:followup on semegency preparedness approfised at exercise findings HUFFMAN.O.N., JENKINS, O.R. Division of Emergency Preparedness & Operational Support. 82/09/02 [8pp. 15565:328. 24% Fichs.50-338, 82/09/08, 9210010155.
- 8210030559 Releases public version of emergency preparedness open FELTON.J.M. Division of Rules and Records. 82/09/16. Docum Management Branch 1p 15637-220. 24X Fiche.50-335.82/09/16. 8210050859
- --8210050567 Bubmite public version of clarification of emergency preparedness planning open items of emergency action levels, staffing augmentation & unannounced drills.

  UHRIO,R.E Florida Fower & Light Co. 82/09/03. EISENHUT, D. Q. Division of Licensing. 2pp. 15637; 221. 24K Fiche: 50-335, 82/09/16,8210030559.
- 821019037: Forwards Revision 1 to 10CFR50. App R fire protection review, correcting typographical & aditorfal arrors. WHRIO.R E Florida Power & Light Co. 82/10/12, EISENHUT, D. O Division of Licensing. 1p. 15741:218. 24X Fiche: 50-335.82/10/12, 8210190371.

- --8210190374 Revision 1 to 10CFR50.App R firs protection revise 4 Florida Power & Light Co 82/10/12 200pp 15741 219 241 4 Floride Power & Light Co 82/ Fiche 50-335,82/10/12,8210190371
- 8210190440 Extends invitation to observe 821019 demonstration of emergency response sys at Technology for Energy Corp. Knozville, TN UNRIG,R E Florida Power & Light Co 82/10/12 EISENHUT, D Q Division of Licensing ip 15741 186 24% Ficha 50-000, 82/10/12.
- 8210260376 Ack receipt of 821013 ltr informing NRC of steps taken to correct violations noted in IE Bafeguards Insp Rept 50-335/62-30 LEUIS.R C Division of Project & Resident Programs 82/10/22 UHRIO.R.E Florida Power & Light Co 1p 15806 138 24X Fiche 50-335,82/10/22,8210260376
- --82102&0391 Responds to NRC 820913 ltr re violations noted in IE 8ereguards Insp Rept 50-935/82-30 Corrective actions withheld (ref 10CFR3 21) UHRIG.R E Florida Power & Light Co 82/10/13 0'REILLY, J P Region 2, Office of Director 1p 15804 139 24X Fiche 50-335, 82/10/22.8210260376
- --82i0260510 Forwards IE Safaguards Insp Repts 50-335/82-30 t 50-387/82-41 on 820816-20 t notice of violation Notice of violation t rept details withheld (ref 100FR73 21) LEMIS.R C Division of Project & Resident Programs 82/6 UHRIG.R E Florida Power t Light Co. 2pp 15806 140 Fiche. 50-335, 82/10/22, 8210260376
- ELVECUDID IN Safeguards Insp Rept 50-335/82-30 & 50-389/82-45 on 820816-20. Noncompliance noted failure to comply wisecurity plan re vehicle control alarms & compensatory action Details withheld (ref 10CFR73 21).

  GODDER R. BTANSBERRY.W.: HCQUIRE.D.R. Region 2, Office of Director 82/09/10 2pp 15806 142 24X Fiche-50-335,82/10/22,8210260376. --8210260515 IE Safeguards Insp Rept 50-335/82-30 & 50-389/82-41 on
- P Operating license stage documents & correspondence
- 8210040049 Forwards Amend 53 to License DPR-67 & safety evaluation Amend deletes current Tech Spec requirements to periodically test insulation of certain Class IE electrical underground cables for environ damage CONNER.E.L. Derating Reactors Branch 3 82/09/21 UHRIG.R E Florida Power & Light Co Zpp. 15577:278 24X Fiche 50-335,82/09/21,8210040043
- --B210040044 Amend 53 to License DPR-67, deleting current Tech Bpet requirements to periodically test insulation of certain Class IE electrical underground cables for environ damage CLARKoR A Operating Reactors Branch 3 B2/09/21 Spp CLARK.R A Operating Reactors Branch 3 82/09/2 18577-280 24X Fiche 50-335.82/09/21.8210040043,
- --8210040046 Safety evaluation supporting Amend 53 to License DPR-67
  # Office of Nuclear Reactor Regulation, Director 82/09/21 3;
  15577; 285 24X Fiche: 50-335, 82/09/21, 8210040043
- 8210250048 Forwards corrected version of Amend 53 to License DFR-67 & safety evaluation. Tech Spec pages omitted from earlier version.

  CONNERS.E.L. Operating Reactors Branch 3 82/09/21 UHRIG.R E Florida Power & Light Co 2pp. 15798:350, 24X

  Fiche. 30-335, 82/09/21, 8210250048
- --B210250030 Corrected version of Amend 53 to License DPR-67 deleting requirement to test insulation of certain Class IE electrical undeground cables for environ damage. Tech Spacs omitted from earlier version.

  CLARKIR.A Operating Reactors Branch 3 82/09/21 7pp 15798:332, 24X Fichs 50-335,82/09/21,8210250048
- --- BZ10250051 Corrected version of safety evaluation supporting Amend 53 to License DPR-67 # Office of Nuclear Reactor Regulation: Director. 82/09/21. 2pp 15798-339, 24% Fiche: 50-335, 82/09/21, 8210250048
- 8210050061 Forwards 820930 cover ltr to Franklin Research Ctr re affl info concerning equipment qualification.per NRC 820217 UMRIG.R.E Florida Power & Light Co 82/09/30, CL Operating Reactors Branch 3 4pp. 15603:238. 24X Fiche: 50-335.82/09/30,8210050061.

- \$210050288 Informs that requirements stated in Genevic Ltr 82-12 restaff working hours adequately enforced by incorporation in affainistrative procedures Amend to Tech Specs unnecessary at present time
  U-RIG.R E Florida Power & Light Co 82/09/30 EISENHUT, D Q.
  Division of Licensing 1p 15619 212 24X Fiche 50-335,82/09/30,8210060288
- E210260351 Notifies of acceptability of 820108 response to NUREG-0737. Item II k S 25, "Loss of AC Power to Reactor Coolant Pump Stals "
  CLARK.R A Operating Reactors Branch S 82/09/30 UHRIQ.R E Florida Power & Light Co 2pp 15830 347 24X Fich# 50-335, 82/09/30, B210260551
- E210190310 Advises of request for proposal to provide criteria for special lifting devices to demonstrate equivalency w/ Guideline 4 of NUREQ-0612. "Control of Heavy Loads " Addl time will be provided as soon as possible re 821007 telcon, CASTO.RE Florida Fower & Light Co 82/10/12 CLARK, R A Caerating Reactors Branch 3 2pp 15742 148, 24X Fichs 50-335.82/10/12,8210190310
- O Imagentian reports. IE Bulletins & correspondence
- E210220451 Responds to 820802 telcon request for add1 info re IE Insp Rept 50-335/82-17 Repts of inservice insps will be submitted within 90 days of completion Repts of previous insps available at corporate of M/o encl U4R10.RE Florida Power & Light Co 82/08/19, U'REILLY, J P Region 2. Office of Director 2pp 18778.246 24X Fiche 50-335,82/08/19,8210220451
- 8210010155 Forwards IE Insp Repts 50-335/82-28 & 50-389/82-37 on E20899-13 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/08 UARTIO.R E Florida Power & Light Co 2pp 15565 326 24X Féche 50-335, 82/09/08, 8210010155
- --8210010159 IE Insp Repts 50-335/82-28 & 50-389/82-37 on 820809-13 No noncompliance noted Major ereas inspected followup on emergency preparedness appraisal & exercise findings HUFFHAN, O N., JENKINS, G R. Division of Emergency Preparedness & Operational Support 82/09/02 18pp 15565 328 24X Fichs 50-335,82/09/08.8210010155
- B210010075 Ack receipt of 820813 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/82-17
  LEWIS:R C Division of Project & Resident Programs 82/09/15
  UHRIO:R E Florida Power & Light Co ip 15567 170 24X
  Fiche 50-335,82/09/15,8210010075
- --9210010078 Ack receipt of 820722 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/82-17 Supplemental response due by 820812 LEVIS.R C Division of Project & Resident Programs 82/08/13 UHRIG.R E Fiorida Power & Light Co. ip 15567 171 24X Fiche 50-335,82/09/15.8210010075
- -- 8210010084 Act receipt of & responds to violations noted in IE Insp Rept 50-335/82-17 on 820511-14 No proprietary info Corrective actions vendor requested to expedite issuance of steam generator insp info UHRIO.R E Florida Power & Light Co 82/07/22 G'REILLY, J P Region 2. Office of Director 2pp 15367 172 24X Fiche 50-335,82/09/15,8210010075
- --B210010092 Notice of violation from insp on 820511-14 = Division of Project & Resident Programs 82/06/18, ip 15957 176 24X Fich 50-339, 82/09/15, 18210010075
- --8210010096 IE Insp Rept 50-335/82-17 on 820511-14 Noncompliance noted strem generator & other inservice insp repts not submitted in specified time

  GIRARD,E H , ECONOMOS, N Division of Engineering & Technical Programs 82/06/11 7pp 15567-177 24X Fiche 50-335,82/09/15,8210010075
- B210010142 Ack receipt of 820825 ltr informing NRC of steps taken to correct violations noted in 1E Inap Rept 50-335/82-01 DANCE/H C Division of Project & Resident Programs B2/09/17 UFRIOR.E Florida Power & Light Co ip 15567:247 24X Fiche:50-335,82/09/17,8210010142,

- --82:00:0163 Responds to NRC 820406 ltr re violations noted in IE Insp. Rept 50-335/82-01 Corrective actions personnel verbally reinstructed re insp of design documents for proper erections, implementation & documentation UHRIG.R E Florida Power & Light Co. 82/08/25 0'REILLY, J.P. Region 2. Office of Director App 15547:248 24% Fiche 50-335,82/09/17.8210010142
- 8210150345 Forwards IE Insp Repts 50-335/82-31 & 50-389/82-38 on 820830-0903. No noncompliance noted.
  DANCE: H C. Bivision of Project & Resident Programs 82/09/22.
  URRIGA RE Florida Power & Light Co 1p. 15704 322. 24X
  Fiche. 50-335. 82/09/22.8210150345
- --S210150358 IE Into Repts 50-335/82-31 & 50-389/82-38 on 820830-0903. No nancompliance noted Major areas inspected radioactive liquid & passous effluent releases reactor coolant chemistry & radioactive transportation activities. WRAY, J R . BARR, K P. Division of Engineering & Technical Programs 82/09/17 10pp 15704 323 24x Fichs, 50-335, 82/09/22, 8210150345
- 8210080264 Forwards response to IE Bulletin 80-11, "Masonry Well Design." supplementing response to NRC 820805 request for add1 info.
  URRIO.R E Florida Fower & Light Co 82/10/04 CLARK,R A Operating Reactors Branch 3. 57pp 15698, 129, 24X
  Fiche 50-335,82/10/04,8210080264
- 8208190233 IE Info Notice 80-35, Suppl 1: "Leaking & Dislodged I-125 Implant Seeds " Svc list ancl COSB: L I Division of Fuel Facilities, Materials & Safeguards. 82/10/06 Consolidated Edison Co of New York. 66pp 15761,250.
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Walls-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants." Sys list encl. BEYOUND, R C Director's Office, Office of Inspection and Enforcement. 82/10/14 Consolidated Edison Co of New York. 115pp. 15810-125 24X Fiche. 50-000.82/10/14,8208190238
- 8210220280 Act receipt of 820930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/82-11 & 50-389/82-34 DANCE,H.C Division of Project & Resident Programs B2/10/15, UHRIG,R E. Florids Power & Light Co ip. 15775:084. 24X Fichs 50-335,82/10/15,8210220280
- --8210220286 Responds to NRC 820901 ltr re violations noted in IE Insp Rept 50-335/82-11 Corrective actions, Equipment Clearance Order 1-8-30 corrected & personnel reinstructed, UHRTO-R E Florida Power & Light Co 82/09/30 O'REILLY, J. P. Region 2, Office of Director. 2pp. 15775.085 24X Fiche 50-335,82/10/15,82102202880
- --8210220291 Forwards IE Insp Rapts 50-335/82-11 k 50-389/82-34 on 820711-0810 & notice of Violation DANCE H.C Division of Project & Resident Programs 82/09/01. WHRIG.R.E. Florida Power & Light Co 2pp. 15775:087. 24X Fichs 50-335,82/10/15,8210220280.
- --8210220297 Notice of violation from insp on 820711-0810. \* Division of Project & Resident Programs 82/09/01 ip 15775 OB9 24X Fiche: 50-335, 82/10/15, 8210220280.
- --9210220303 IE Insp Repts 50-335/82-11 & 50-389/82-34 on 820711-0810 Noncompliance notation 820805. Equipment Clearance Order L-8-30 incorrectly identified suction & discharge drain valves Y-2317 & Y-2327 for charging pump A ELROD. 8 A , 8188, H E. , JULIAN.C. A. Division of Project & Resident Programs. 82/08/31 10pp. 15778:090 24X Fiche 50-335.82/10/15, 8210220280
- 8210260376 Ack receipt of 821013 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-335/82-30.

  LEWIB, R C Division of Project & Resident Programs, 92/10/22. UWIB, R C. Floride Power & Light Co. ip. 15806.138, 24% Fiche 50-335.82/10/22,8210260376.
- --8210240391 Responds to NRC 820913 ltr re violations noted in IE Safeguards Insp Rept 50-335/82-30, Corrective actions withheld (ref 10CR73.21), UNRIG.R.E Florida Power & Light Co. 82/10/13 O'REILLY, J. P. Region 2, Office of Director, 1p. 15806:139, 24X Fiche. 50-335, 82/10/22, 8210240374.

1

ļ

- --B210260510 Forwards IE Safeguards Insp Repts 50-335/82-30 & 50-389/82-41 on 820816-20 & notice of violation Notice of violation & rept details withheld (ref 10CFR73 21) LEHIGH C Division of Project & Resident Programs. 82/09/13 URRIO,R E Florida Power & Light Co 2pp 15806:140 24% Fiche:50-335,82/10/22,8210260376
- --8210260515 IE Bafeguards Insp Rept 50-305/82-30 & 50-389/82-41 on 820816-20 Noncompliants noted, failure to comply w/security plan re vehicle control.alarms & compensatory action Details withheld (ref 10CFR73 21).

  GOODE, R., STANSBERRY, W., MOULRE, D. R. Region 2, Opfice of Diractor 82/09/10 2pp 15806-142 24X Fich. 50-335,82/10/22,8210260376

# 8 Reportable occurrences, LERs & related correspondence

- 8210150035 Forwards LER 81-002/03L-0 BCHMIDT, A D Florida Power & Light Co. B1/02/20. Q'REILLY, J P Region 2, Atlanta. Office of the Director (81/03/01) ip 15701.147 24X Fiche: 50-335, 81/02/20, 8210150035
- --8210150039 LER 81-002/03L-0 on 810122, digital data processing system to the processing system of the processing system of the processing system of the processing system of the process of control stement assembly pulse counting backup position indication caused by software problem Problem under investigation PACE.P. L. Florida Power & Light Co. 81/02/20 Region 2. Atlanta, Office of the Director (81/03/01) ip 15701 148 24X Fiche 50-335,81/02/20.8210150035
- 8210010164 Forwards LER 82-045/43X-0 WILLIAMS, J W Florids Power & Light Co 82/09/24 O'REILLY, J P Region 2. Office of Director ip 15567 279 24X Fiche 50-335, 82/09/24, 8210010164
- --BR10010174 LES B2-045/43X-0 on BR0913, wash trough used to decontaminate respirators & similar items found not draining into radwaste sys Caused by error resulting from personnel turnover Drain rerouted Dunp area surveys will continue. PACE, P. L. Florida Power & Light Co. 82/09/24 Region 2, Office of Director. 2pp 15567-280. 24X Ficha 50-335,82/09/24,8200.0044
- 8210070425 "Rept on Saint Lucis I Natural Circulation Cooldown on B00611."
  IMBRO,E V. Director's Office. 82/09/24, 28pp 15644,289 24: Fichs 50-335.82/09/24,8210070425
- 8210130552 Forwards LER 82-040/03L-0 HILLIAMS, J W Florids Power & Light Co. 82/10/04. O'REILLY, J P. Region 2, Office of Director 1p. 15684-007 24X Fiche:50-335.82/10/04.8210130552
- --9210130562 LER B2-040/03L-0'on 820902, short caused generator breakers to open & synchronizing inhibit timer to start Caused by personnel short circuiting relay during generator negative sequence relay testing. Protection design reviewed PACE, P Floride Power & Light Co. 82/10/04. Region 2, Office of Director. Sop. 15484:008 24X Fiche: 50-335, 82/10/04, 8210130352.
- 8210130456 Forwards LER 82-041/03L-0 HILLIAMS, J W. Florida Power & Light Co. B2/10/06. D'REILLY, J.P. Region 2, Office of Director, 1p 15682:147. 24X Fiche: 50-335.82/10/06.8210130456.
- --B210130452 LER 82-041/03L-0 on B20907, at 99% power, reactor/turbine trip occurred resulting in brief loss of vital buses & iodine spike, Caused by motor auxiltary contact initiating false loss of load & inhibit signals.

  PACE: P.L. Fiorida Power & Light Co. B2/10/06, Region 2, Office of Director, App 15682: (48. 24% Fiche. 50-335, 82/10/06, B210130436.
- 8210260357 Forwards LER 82-044/03L-0 HILLIANB.J.M. Florida Power & Light Co. 82/10/15, O'REILLY.J.P. Region 2, Office of Director, 1p. 15803:178, 24X Fiche:30-335.82/10/15.8210260357.
- --8210260349 LER 82-044/03L-01 on 820923 pulse counting function for 21 control element assemblies found deleted during normal testing, Caused by personnel error. Nethods for alerting operators investigated. PACEP.L. Florida Power & Light Co. 82/10/15, Region 2, Office of Director ip, 15803:179, 24% Fiche: 50-335, 82/10/15, 8210260357.

- DOCKET 50-336 HILLSTONE NUCLEAR POWER STATION, UNIT 2
  F. Security, medical, emergency & fire protection plans
- 8210210597 Informs of new format for submittals containing safeguards info 8Afaguards info should be submitted similar to proprietery info Cover ltr should not contain safeguards info. Actual info should be in attachment CLARKOR A Operating Reactors Branch 3 82/09/27 CQUNBIL, W C Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 15784 316 24% Fichs. 50-336.82/09/29.8210210587.
- --8210210174 IE Insp Repts 50-245/82-17 & 50-336/82-19 on 820808-0725 he noncompliance noted Major areas inspected plant & refueling operations, equipment alignments & readiness, radiation protection & physical security

  BHEDLOSKY, J T Division of Project & Resident Programs 82/10/05 15pp. 15764,043 24X Fiche 30-245,82/10/07,8210210182
- P Operating license stage documents & correspondence
- 8210280013 Responds to FOIA request for all internal non-public documents, memos, evaluation repts & other matt dealing w/ nuclear plant operations. Forwards documents listed in App A FELTON, J. M. Division of Rules and Records 82/09/17 MCIANIS.D. Naws & Observer 5pp 15860 065 24X Fichs 50-000, 82/09/17, 8210280013
- ---8210280031 Requests technical assistance to review recent events at facilities & to assess safety & environ significance STELLO.V Division of Operating Reactors 78/08/03 HULLER.D Division of Sits Backy & Environmental Analysis 2pp 15860 004 24% Fichs. 50-000.82/09/17.8210280013
- B210010207 Forwards "Haddam Nack Plant Procedure AOF 3 2-22-C RCS Venting of Noncondensible Gases" & "Hillstone Nuclear Power Station RCS Venting Procedure OP 2398," in response to THI Action Plan Item II B.1, "RCS High Point Vents" COUNSIL.W O. Connecticut Yankes Abomic Power Co. COUNSIL.W, O. Northeast Nuclear Energy Co. (subs of Northeast Utilities) COUNSIL.W, O. Northeast Nuclear Energy Co. (subs of Northeast Utilities) COUNSIL.W, O. Northeast Utilities B2/09/22 CRUTCHFIELD.D Dorating Reactors Branch 5 CLARK, R.A. Operating Reactors Branch 3. 3pp 15568:048 24X Fichs: 50-000.82/09/22, 8210010207
- --B210010214 Revision 2 to "Millstone Nuclear Power Station Unit 2 Plan Procedure OP 2398 RCS Venting Procedure." SCACE.S.E. Northeast Nuclear Energy Co (subs of Northeast Utilities) B2/08/20. 11pp 15568-062 24X Fiche 50-000,82/09/22,8210010207.
- 82:00:00312 Requests that processing of B20812 license amend application he postponed. Revised application changing radiological effluent Tech Specs will be docketed on or about 82:11:5 for both facilities.

  CDUNSIL.H.O. Connecticut Yankse Atomic Power Co COUNSIL.W 9 Northeast Nuclear Energy Co. (subs of Northeast Utilities).

  CDUNSIL.H.Q. Northeast Utilities 82:09/22. CLARK,R.A. Operating Reactors Branch 3. CRUTCHFIELD. Departing Reactors Branch 3. CRUTCHFIELD. Departing Reactors Branch 5.

  3pp. 15574-047. 24X Fiche 50-000.82/09/22.8210010312
- 9210050179 Application for amend to License DPR-65 revising Tech Spec 3, 1 2, 2 to require both boric acid tanks & corresponding facility dependent flow paths to be operable in modes in which operability is required for ECCS.

  CDUNGEL.W. Q. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). GZ/09/24.

  Utilities). COUNBIL.W Q. Northeast Utilities. GZ/09/24.

  CLARK,R.A. Operating Reactors Branch 3. 2pp. 18603:383 24X

  Fichs: 50-336, 82/09/24, 8210050179
- --8210050187 Proposed revision to Tech Spec 3.1.2 R, requiring both boric acid tanks & corresponding facility dependent flow paths to be operable in modes in which operability is required for ECCS.

  \*\* Northeast Nuclear Energy Co. (subs. of Northeast Utilities), 82/09/24, 3pp. 15603:355, 24X Fiche 50-336,82/09/24,8210050179
- 8210040237 Application to amend License DPR-65, revising Tech Spect Faboric acid flow path requirements as utilized in reactivity control sus & ECCS.
  COUNBIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities, 02/09/24.
  Util(ties), COUNBIL, W. O. Northeast Utilities, 02/09/24.
  CLARK, R. A. Operating Reactors Banch 3, 2pp. 15619:351, 24X
  Fiche: 50-336.82/09/24,8210060237.

- --R210060239 Proposed Tech Specs restoring two boron injection Plow paths & one associated heat tracing circuit \* Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/09/24 App 15619 393 24X Fiche 50-336, 82/09/24
- 8210030090 Provides justification for addl time needed to complete valve mod resulting from plant shielding review, per RAMEG-0737. Item II B 2 Const for mod scheduled to begin in early Jan 1983 Completion expected by Apr., prior to startup COURSIL.H 0 Northeast Nuclear Energy Co (subs of Northeast Utilities 82/09/28 CLARK PA Operating Reactors Brench 3 2pp 15604 239 24X Fiche 50-336, 82/09/28.8210050070
- 8210220020 Advises of resolution of seismic qualification of auxiliary feedwater sys Sys able to perform designed safety-related function after SSE to assure safe plant shutdown CLARK, R A Operating Reactors Branch 3 82/09/30 COUNSEL, W C Mortheast Nuclear Energy Co (subs of Northeast Utilities) 2pp 15786 309 24X Fiche 30-336,82/09/30,8210220020
- --8210220022 Safety evaluation supporting seismic qualification of Aurillary feedwater sys \* Operating Reactors Branch 3 82/09/30 App 15786 311 24X Fitchs 50-336.82/09/30, 8210220020
- B210130331 Discusses revision of administrative procedures to incorporate revised working hour guidelines & provisions for authorizing deviations per B2020B & O615 requests, TMI Teem I A 1 3, "Shift Hanning" & Deneric Ltr 62-12 COUNSIL.W Q, CAGNETYAJ P Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W Q Connecticut Yankee Atomic Power Co 82/10/01 EISEMHUT, D Q Division of Licensing 3pp 15677 127 24X Fiche 50-000,82/10/01.8210130331
- O Inspection reports: IE Bulletine & correspondence
- B2:01:50699 Forwards request for add1 info to complete review of 80:104 reaponse to IE Bulletin 80-11, "Masonry Wall Dasign."
  Heaponse expected within 60 days of 1tr receipt CLARK.R A Operating Reactors Branch 3 82:709/28 CGUNBIL. H.O Connecticut Yanker Atomic Pawer Co CGUNBIL.H O. Northeast Nuclear Energy Co (subs of Northeast Utilities) 13pp 15716 100. 24% Fichs 50-000.82/09/28,82:10150699.
- 8210070352 Ack receipt of 820714 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/82-10 & 50-336/82-14
  MARTIN.T.T. Division of Engineering & Technical Programs 82/10/05.
- TARTIN.T.T Division of Engineering & Technical Programs 82/10/05 COUNSIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 1p. 15634-051 24X Fiche 50-245,82/10/05,8210070352.
- --8210070356 Responds to NRC B20Bi3 ltr re violations noted in IE Insp
  Repts 50-245/82-10 & 50-336/82-14 Corrective actions:
  controlled documents updated & Unit I control room drawing
  deficiencies corrected
  CGUNSIL, W O. Northeast Nuclear Energy Co (subs of Northeast
  Utilities) CGUNSIL, W Q Northeast Utilities 82/09/14
  MARIIN, T T Division of Engineering & Technical Programs 3pp
  15634 052 24X Fiche 50-245, 82/10/05, 8210070352
- B2OB190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds." Evc list encl COBB.L 1 Division of Fuel Facilities, Materials & Safsquards. 82/10/06 Consolidated Edison Co. of New York 66pp 15761:250 24X Fiche 50-000.82/10/06.8208190233
- 8210190472 Forwards inservice insp rept of insp conducted during Dec 1981-June 1982 for insp period of Apr 1979-Aug 1982 MRDCZKA:E J Northeast Nuclear Energy Co (subs of Northeast Utilities). 82/10/06 HAYNES, R C Region i, Difice of Director. 1p 15740 182 24X Fiche 50-336,82/10/06:8210190472.
- -- SRIO190474 Inservice insp rept on Dec 1981 to June 1982 for period Apr 1977 to Aug 1982 Rept describes exame performed on Class II piping sys. Northeast Nuclear Energy Co (subs. of Northeast Utilities). 82/08/13 12pp 15740 183. 24X Fiche 50-336/82/10/06/8210190472,
- 8210210182 Forwards IE Insp Repts 50-245/82-17 k 50-336/82-19 on 820808-0925 No noncompliance noted.

  STAROSTECKI.R Division of Project & Resident Programs. 82/10/07.
  COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 19766.041. 24X Fichs.50-245/82/10/07/8210210182
- --821021019A IE Insp Repts 50-245/82-17 & 50-336/82-17 on 820808-0925, No noncampliance noted Major ereas inspected, plant & refueling operations, equipment alignments & readiness, radiation protection & physical security.

  SHEDLOSKY, J. T., LIPINSKI, D.R., ELASBER, T. C. Division of Project & Resident Programs 82/10/05 15pp. 15766-043, 24% Fiche 50-245,82/10/07,8210210182.

- 820B19023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Bteel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYGUNG-R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810; 125 24X Fiche 30-000, 82/10/14-820B19023B
- 8 Reportable occurrences, LERs & related correspondence
- 9210090018 "Rept on Millstens Unit 2 Loss of 123-Volt DC Bus Event on 810102 "
  CHIRAMAL, H., IMBRO, E., GIANELLI, J. Director's Office 81/11/30 26pp 15667 047 24% Fiche 50-336,81/11/30,8210080018.
- 8210130065 Discusses investigation of relative frequency of valve overtravel engmalise that could result in potential centrifugal pump runout exceeding NPBH No safety problems observed in operation w/NPBI valves manually open IMBRO.E V. Reactor Operations Analysis Branch 82/02/22 MICHELBON.C Director's Office 4pp 13676-268 24X Fiche-50-336.82/02/22,8210130065.
- 82i0010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records. 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727-005, 24X Fiche: 50-000.82/06/20.8210010008
- --8;12010310 "Rept on Millstone Unit 2 Loss of 128-Volt DC Bus Event on 810102 " CHIRAMALM, IMBRO,E, 01ANELLI,J Director's Office, 81/11/30 26pp 18731 065, 24% Fiche, 50-000, 82/06/28, 8210010008.
- --8210060430 Summarizes investigation of LER 50-336/81-26 re relative frequency of valve overbravel abnormalities that could result in potential centrifugal pump runout exceeding NPSH INBRO,E.V Director's Office 82/02/22, MICHELSON, G. Director's Office 4pp. 15732 293 24X Fiche 50-000:82/06/28,8210010008
- 8210010376 Forwards LER 82-036/Q3L-0.
  MR00ZKA,E,J Northeast Nuclear Energy Co (subs. of Northeast Utilities). HR00ZKA,E J Northeast Utilities, 92/09/22, HAYWELR, C Region 1. Office of Director 1p. 13573-051. 24X Fiche 50-336-82/09/22,8210010376
- --B210010385 LER 82-036/03L-0 on B20825, at 100% power level during routine packing replacement of charging pump, crack discovered in charging pump block Cause not determined. Fump block to be replaced & failure amalysis performed. CRIBCIONE, J. L. Northeast Nuclear Energy Co. (subs. of Northeast Utilities), 82/09/22, Region 1, 0ffice of Director. 1p. 15573 052, 24% Fiche 50-336, 82/09/22, 8210010376.
- 8210130228 Forwards LER 82-037/03L-0.

  MROCZKA,E J Northeast Nuclear Energy Co (subs. of Northeast Utilities) MROCZKA,E J Northeast Utilities 82/10/01

  HAYNES,R. C Region 1. Office of Director. 1p. 13675:226 24X

  Fiche 30-336,82/10/01,821013028
- --8210130232 LER 82-037/03L-0:on 820902.while at 100% power, quarterly surveillance test revealed blocking valve 2-RC-403 would not close Probable cause attributed to failure to adjust packing for proper valve function.

  STADMICK 8 Northwast Nuclear Energy Co. (subs. of Northeast Utilities). 82/10/01. Region 1: Office of Director. 19. 15675:227 24X Fiche 50-326, 82/10/01.8210130228
- 8210210165 Forwards LER 82-037/03L-0 MRGCZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MRGCZKA,E J. Northeast Utilities 82/10/13. MAYNES,R C. Ragion 1. Office of Director 1p. 15746:075 24X Fichs 50-036, 82/10/13, 8210210155
- --8210210160 LER 82-039/03L-0. on 820914, packing for operator shaft in primary containment outer air lock door leaked & test pressure could not be maintained Caused by normal cyclic weat. Packing tightened.

  KOMOSKY. G. Northeast Nuclear Energy Co. (subs of Northeast Utilities). 82/10/13. Region 1. 0701c of Director, ip. 15766 076. 24X Fichs. 50-336, 82/10/13, 82102101055
- 8210220060 Forwards LER 82-038/03L-0, Detailed event analysis encl HROCZKA,E J. Northeast Nuclear Energy Co. (aubs. of Northeast Utilities) HROCZKA,E.J. Northeast Utilities 82/10/14, HAYNES,R.C. Region 1, Office of Director Rpp. 15778:197, 24X Fiche: 50-336, 82/10/14,8210220060

- --B210220064 LER B2-03B/03L-0 on B2091B, surveillance testing indicated activity of 0 99 uCi dose equivalent I-131 in primary coolant Caused by small number of degraded fuel pins BORCHERT-R Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/14 Region i, Office of Director ip 15778 199 24X Fiche 50-336,82/10/14,8210220060
- 8210260432 Forwards LER 82~040/03L-0 MROCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities). MROCZKA,E J Northeast Utilities. 82/10/17 HAYNES, R C. Region 1, Office of Director 1p 15806, 271. 24X Ficha: 50~336, 82/10/17, 8210260432
- --B210260441 LER B2-040/03L-0:on S2091B, acceptance criteria not met when containment personnel sirlock test performed Caused by leaking gasket on inner sirlock door. Oasket replaced & successful leak test performed BUFFY, B Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/10/17. Region is Office of Director ip. 15806-292 24X Fiche: 50-336, 82/10/17. 8210260432

### DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8210250208 Forwards "Full-Scale Emergency Exercise North Anna Power Station Sept 1982, Exercise Manuel," per NRC 820127 ltr. LEABBURG. R. H. Virginia Electric & Power Co. 82/08/30 0'REILLY.J.P. Region 2, Office of Director. ip 15791 205 24X Fiche: 50-338, 82/08/30, 8210250208
- --B210250212 "Full-Scale Emergancy Exercise, North Anna Power Station, Sept 1982: Exercise Manual " • Virginia Electric & Power Co 82/08/27 243pp 15791 206. 24% Fiche. 50-338, 82/08/30.8210250208
- 8210010125 Forwards revised security training & qualification plans Plans withheld. LEASBURG,R.H Virginia Electric & Power Co. 82/09/17. DENTON,H.R Office of Nuclear Reactor Regulation. Director. VAROA. B.A. Operating Reactors Branch I. ip 15566.013 24X Fiche 30-000.82/09/17.8210010125
- 8210130105 Releases public version of emergency response plans FELTON, J. H. Division of Rules and Records 82/09/28. Document Management Brench. 1p 15693:001 24X Fiche: 50-338.82/09/28.8210130105.
- --B210130112 Forwards public version of emergency response plans for Louise, Spotsylvania, Carolina, Hanover & Grange Counties, VA LEASBURG, R H. Virginia Electric & Power Co. B2/09/20 O'REILLY, J.P. Region 2: Office of Director, ip. 15693, 002 24X Fiche, 50-338, 82/09/28, 9210130105
- --8210130114 Public version of facility emergency response plans consisting of radiological emergency response plans for Louiss.8potsylvants.Caroline.Hanover & Orange Counties.VA. \* Virginia Electric & Power Co. 82/08/30. 432pp. 15693-004 24X Fiche.50-338.82/09/28.8210130105.
- 8210050076 Submits correction to 820628 Revision 3 to response to NUREO-0737. Item I D 2. "Safety Parameter Display Sys "Correction should be included in schedular exceptions pertaining to emergency response capabilities.

  LEABBURG.R.H. Virginia Electric & Power Co B2/09/29. DENTON.H.R Office of Nuclear Reactor Regulation. Director. EIBENHUT.D.9. Division of Licensing. Ip. 13603:185 24X Fichs. 50-000, 82/09/29, B210050076
- 8210050335 Forwards revised pages to App R post-shutdown review. Revised pages concern results of study which calculated time evaluable after stuck open power operated relief valve event before unsafe condition reached. LEASBURG.R.H. Virginia Electric & Power Co. B2/09/30, DENTON.H.R. Office of Nuclear Reactor Regulation, Director. CLARK.R.A. Operating Reactors Branch 3. Gpp 15610:095, 24X Fiche: 50-339, 82/09/30, 8210050335.
- 8210220454 Forwards IE Insp Repts 50-338/82-33 & 50-339/82-33 on 820918 No noncompliance noted.
  DANCE.H.C. Bivision of Project & Resident Programs, 82/10/04.
  LEASBURG.R.H. Virginia Electric & Power Co. 2pp. 15779:135 24X
  Fichs. 50-338, 82/10/04, 8210220454.

--8210220461 IE Insp Repts 50-338/82-33 & 50-339/82-33 on 820918.No noncompliance noted Major areas inspected, full-scale radiological exercise.

HUFPHANIG.N., MARSTON.R.R., JENKINS.G.R. Division of Engineering & Technical Programs. 82/09/30. 11pp. 15779:137 24X
Fiche.80-338.82/10/04.8210220454

### O Adjudicatory correspondence

- 8210260348 Petition of Concerned Citizens of Louise County for leave to intervane & request for hearing re proposed license amend to authorize receipt & storage of Surry spent reactor fuel at North Anna Certificate of Svc secl DOUGHERTY, J B Dougherty, J B 82/10/22 Commissioners 8pp 15803 180 24X Fiche 50-338.82/10/22.8210260348
- 8210260355 Petition of Concerned Citizens of Louisa County for leave to intervene & request for hearing re proposed license amend authorizing increase in capacity of spent fuel pool Notice of appearance & Certificate of Svc encl DOUGHERTY, J B. Dougherty, J B. 82/10/22 Commissioners 7pp 15802.350 24x Fiche 50-338,82/10/22,8210260355
- 8210260367 Petition of County of Louisa, VA & Board of Supervisors of County of Louisa, VA to intervene re proposed license amend to permit receipt & storage of 300 spent fuel assemblies from Surry Certificate of Svc encl.

  CDLEMAN, J.M. Louisa County, VA CDLEMAN, J.M. Beveridge, Feirbants, & Diamond 82/10/22 County, VA CDLEMAN, J.B. 15803.111 24X Fiche, 50-338, 82/10/22, 8210260367
- 8210260373 Petition to intervene of County of Louisa, VA & Board of Supervisors of County of Louisa, VA re proposed license anend to expand fuel storage capacity Certificate of Svc encl COLEMAN, J M Louisa County, VA COLEMAN, J M Beveridge, Fairbants, & Diamond 82/10/22 Commissioners 15pp 15803 143 24X Fichs 50-338, 82/10/22, 8210260373
- B210280238 Notice of ASLS constitution. BJ Wolferchairman & J K] in F G A Ferguson, members LAZO, R M Atomic Bafety and Licensing Board Panel B2/10/26 2pp 15837.060 24X Fiche 50-338, B2/10/26, B210280238
- B210280300 Notice of ASLB constitution, SJ Wolfe, chairman & J Kline & OA Ferguson, members LAZD, R M Atomic Bafety and Licensing Board Panel, 82/10/26, 2pp 15837 281, 24X Fiche, 50-338, 82/10/26, 8210280300.
- P Operating license stage documents & correspondence
- 8208090114 Application for amend to Licenses NPF-4 & NPF-7, authorizing receipt & storage of 500 spent fuel assemblies from Surry Units 1 & 2 Rept entitled "Spent Fuel Storage" enci LEASBURO, R. H. Virginia Electric & Power Co. 82/07/13. DENTON: H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors System Co. 2010 15567, 244. 24X Fiche: 50-338, 82/07/13, 8208090114.
- --B210010246 Proposed Yech Spacs allowing receipt & storage of 500 spant fuel assemblies from Burry # Virginia Electric & Power Co. B2/07/13. 4pp 15569.246 24r Fichet 50-338, 82/07/13, 8208090114.
- --8210010247 "Spent Fuel Storage "

  \* Virginia Electric & Power Co 82/07/31. 86pp 18569 251 24r
  Fiche, 50-328, 82/07/13, 8208090114.
- 8210040277 Advises of plans for const of new 230 kV transmission lins to connect North Anna power station to Louisa substation No Tech Spac or ETS change required.

  LEARBURGOR, H. Virginia Electric & Power Co 82/09/27 DENTON: HR Office of Nuclear Reactor Regulation. Director CLARK.R. A Operating Reactors Stranch 3. 2pp. 15591.204 24X

  Fiche. 50-338. 82/09/27.8210040277
- --8210040285 Responds to util 761109 ltr informing that 740102 k 740408 ltrs did not constitute application for const of 230 kV transmission line from Morth Anna to Louiss Bubstation Ref to line has been removed from FEB addendum YOUNOBLOOD, B. J. Environmental Projects Branch 2 76/11/26 PROPFITT, N. L. Virginia Electric & Power Co. Spp 15591.206 241 Fiche: 50-338, 82/09/27, 8210040277.
- --B210040270 Advises that util 740102 & 76060B ltrs to NRC do not constitute application for const of 230 kV transmission lins from North Anna to Louisa. Application: if required, will be filed prior to DL issuance for Unit 2.

  PROPFITT.M. L. Virginia Electric & Power Co 76/11/09.

  RUBCHE. B. C. Office of Nuclear Reactor Regulation, Director YOUNGBLOOD, B. J. Environmental Projects Branch 2. ip. 15591:212

  24X Fiche: 50-238, 82/09/27, 8210040277.
- --8210040297 Forwards add1 info & answers to questions in NRC 750920 ltr re 230 kV transmission line. PROFFITT: M. L. Virginia Electric & Power Co. 76/08/30, RUBCHE, B. C. Dffice of Nuclear Reactor Regulation. Director YOUNGBLOOD, B. J. Environmental Projects Branch 2. 6pp. 15591 213 24X Fiche: 50-338,62/09/27,6210040277.

- ~-9210040301 "Mgt of Transmission Line Rights of Way "

  \* Enviro Audits 76/07/31 77pp 15591 219 24X
  Pichs 80-338,92/09/27,8210040277
- --8210040307 Requests add1 info by 740830 to complete assessment of environ impact of 230 kV transmission line YOUNOBLOOD, B J Environmental Projects Branch 2. 76/08/20 PROFFITM L Virginia Electric & Power Co 2pp 15591 294 24) Fishs 50-338,82/09/27,8210040277
- ~-9210040315 Forwards one oversize topographical map & application to VA State Corp Commission for approval & certification of North Anna to Louisa transmission line;in response to NRC 760630 request Aperture card is available in PDR PROFFITT, W L Virginia Electric & Power Co 76/07/06 RVSCHE.B C Office of Nuclear Reactor Regulation, Director 29pp 15591/298 24X Fiche 50-338.62/09/27.6210040277
- --B210040320 Advises of need for NRC evaluation of environ impact of const & operation of North Anna Gordonsville 230 kV transmission line, per util 740102 & 760608 ltrs. Addl info needed by 760707
  YDUNOBLOGO, B J Environmental Projects Branch 2 76/06/30
  PROFFITT, W L. Virginia Electric & Power Co 2pp 15591 327 24X
  Fiche 50-338,82/09/27,8210040277
- --B210040325 Advises that proposed 230 kV transmission line between North Anna & Louise need not be evaluated in amend to environ rept for North Anna i & 2 Line is not part of North Anna utilization facility RAGONE, 8 Virginia Electric & Power Co 74/01/02 MULLER, D R Atomic Energy Commission 2pp 13591 329 24X Fisch \$0-338,82/09/27,8210040277
- 8210120215 Application to amend Licenses NPF-4 & NPF-7, revising Tech Specs re staff working hours Request does not involve Unreviewed safety question per 100FR50 59 LFASBURG, R H Virginia Electric & Power Co 82/10/01 DENTON, H R D#fice of Nuclear Reactor Regulation, Director 1p. 15692-150 24X Fiche 50-338, 82/10/01, 8210120215
- --B210120225 Proposed Tach Bpecs revising staff working hours Provision does not permit shift crew position to be unmanned upon shift change due to late or absent oncoming shift crewman.

  \* Virginia Electric & Power Co 82/10/01 App 15652.151. R4X Fiche 80-338,82/10/01,8210120215
- 8210120265 Informs of implementation status of NUREQ-0737. Item II B 2, "Plant Shielding" per NRC 820517 request All required work completed LEASBURG, R H Virginia Electric & Power Co 82/10/01. DENTON-H R Office of Nuclear Reactor Regulation. Director EISENHUT, D 0 Division of Licensing 2pp 15651 230 24X Fiche 50-000.82/10/01, 8210120265.
- 8210:2027 Forwards errate to Topical Rept VEP-FRD-33, "VEPCO Reactor Core Thermal-Hydraulic Analysis Using COBRA IIIc/MIT Computer Code "

  LEASBURG, R H. Virginia Electric & Power Co. 82/10/04 DENTON, H R. Office of Nuclear Reactor Regulation, Director EISENHUT, D Q. Division of Licensing 2pp 15652 330. 24% Fichs.50-000, 82/10/04, 8210120297
- ---8210120305 Errata to "VEPCO Reactor Core Thermal Hydraulic Analysis
  Using COBRA-IIIc/MIT Computer Code "

  Virginia Electric & Power Co VEP-FRD-33 ERR. 82/10/04 lp.
  15652 332 24% Fiche 50-000.82/10/04.8210120297
- 8210290042 Forwards safety evaluation & technical evaluation rept re analysis of main steam line break w/continued feedwater addition Analysis acceptable W/o technical evaluation, CLARK,R A Operating Reactors Branch 3 82/10/04. LEASBURG,R H Virginia Electric & Power Co 1p. 15877, 271 24X Pichs 50-338,82/10/04,8210290042.
- --8210270071 Safety evaluation re main steam line break w/continued faedwater addition Containment overpressurtiation will not result & auxiliary feedwater pumps can function during event.

  # Office of Nuclear Reactor Regulation. Director 82/10/04. App 15877 272 24X Fichs. 50-238. 82/10/04, 8210270042
- B210290414 Forwards Amend 42 to License NPF-4, safety evaluation & notice of issuance & availability Amend revises everage RCS temp at currently licensed thermal power level. ENGLE.L.R. Operating Reactors Branch 3 82/10/04 LEASBURG.R.H. Virginia Electric & Fower Co. 4pp 15863: 255, 24X Fichs. 50-338, 82/10/04, 8210290414.

- --8210290416 Amend 42 to License NPF-4, revising average RC8 temp from 380 3 F to 582 8 F at current licensed thermal power level of 2,785 My CLARK, R A. Operating Reactors Branch 3, 82/10/04 9pp 15863 259, 24X Fichs 50-338,82/10/04,8210290414
- --8210270418 Sefety evaluation supporting Amend 42 to License NPF-4

  \* Office of Nuclear Reactor Regulation: Director 82/10/04 3pp.
  15863 268 24X Fiche 50-338,82/10/04,8210270414.
- --8210270421 Notice of issuance & availability of Amend 42 to Litense NPF-4 CLARK, R.A. Operating Reactors Branch 3 82/10/04 2pp 15853:271 24X Fiche 50-338,82/10/04,8210270414
- 8210270238 Forwards documents providing details of exams & evaluations performed by util & Westinghouse on failure of guide tube support pins main loop isolation valve guide & RCS thermal sleeves.

  LEASBURG.R H Virginia Electric & Power Co 82/10/12 DENTON, H. R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 7pp 15829 180 24X Fiche 50-338, 82/10/12.8810270288
- --8210270260 "North Anna Unit 1 Loose Thermal Bleeve Safety Evaluation," Descriptions of impact of postulated blockage on 1981 model LOCA analysis & operator awareness surveillance program encl.

  \* Westinghouse Electric Corp. 28630 | 82/09/30 44pp. 15829-187 24X Fiche 30-338,82/10/12.8210270258
- 8210220011 Bubmits addl info to 820713 request for amend to Licenses NPF-4 & NPF-7, Number of storage locations in meutron absorber spent fuel storage rack changed to 1,737 Fuel pool temps changed in Table 7 i LEASBURGOR.H Virginia Electric & Power Co 82/50/18 DENTON.H R. Office of Nuclear Reactor Regulation, Director. CLARK,R A Operating Reactors Branch 3. Spp 15778 211 24X Fiche; 30-338, 82/10/18, 8210220011
- 8210220178 Comments on evaluation of significant dynamic loads in determining capacity of slings used per NUREO-0612 Rating can be safely expressed in terms of max static load LEASBURG: H Virginia Electric & Power Co. 92/10/18 DENTON, H. R Office of Nuclear Reactor Regulation, Director. EISENHUT, D Q. Division of Licensing. 2pp 15777:293 24X Fiche: 50-000, 82/10/18, 8210220178
- 8210260133 Forwards revised Table 7-1 to "Bummary of Info in Support of Increasing Spent Fuel Storage Capacity at North Anna Units 1 & 2 " Rept originally submitted w/820820 request for amend to Licenses NPF-4 & NPF-7 to replace storage racks LEASBURO, R H Virginia Electric & Power Co 82/10/21 DENTON. H R. Office of Nuclear Reactor Regulation, Director. CLARK, R A Operating Reactors Branch 3 2pp. 15799 102 24% Ficher 50-338, 82/10/21, 8210260133.
- ~-8210260136 Revised Table 7-1 to "Bummary of Info in Support of Increasing Spent Fuel Storage Capacity at North Anna Units i & 2."

  + Virginia Electric & Power Co. 62/10/21, ip. 15799 104 24X Fiche: 50-338, 82/10/21, 8210260133
- 8210270160 Advises that work re removal of RCB flow splitter plates completed. Ltrs from Westinghouse supporting continued operation of facility w/splitter plates removed encl LEASBURG, R. W. Virginia Electric & Power Co. 92/10/25. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 74pp. 15830.044 24X Fiche: 50-338, 82/10/25.8210270160.
- 8210270204 Forwards Hestinghouse "North Anna Unit 1 Steam Generator Impacted Tube Ends Recovery Evaluation," photographs of steam generator A & C demaged tube sheets & summaries of end damage repairs & reactor coolant pump failure LEASBURG, R.H. Virginia Electric & Power Co. 82/10/26 DENTON, H R. Operating Reactors Branch 3. 2pp. 15822-268. 24X Fiche: \$0-338, 82/10/26, 8210270204.
- --8210270208 "North Anna Unit 1 Steam Generator Impacted Tube Ends Recovery Evaluation" PAXBUN.E., KELLER.H T., CHENG.W.W. Westinghouse Electric Corp. AEA-FRPE-282 82/10/31 68pp 15822:270 24X Fichs:50-338.82/10/26.8210270204.

1

ł

### Q Inspection reports, IE Bullatins & correspondance

- 8210220200 Responds to NRC ltr re violations noted in IE Insp Repts 50-338/82-08 & 50-339/82-08 Corrective actions health physics technician counseled re correct procedures for entering high radiation area LEASBURG-R H Virginia Electric & Power Co 82/07/29 O'REILLY, J.P. Region 2, Deffice of Director 5pp 15777:265. 24X Fiche 50-338, 82/07/29, 8210220200
- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 91-313 Forwards documents listed in App B FELTON.J. M Division of Rules and Records. 82/08/10 LENG, D J Winthrop. Btimson, Putnam & Roberts. 9pp 15645:063 24% Fiche 50-000, 82/08/10,8210070007
- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licenses.

  IPPOLITO. T Operating Reactors Assessment Branch 82/04/01

  VAROA.E. Operating Reactors Branch 1. 5pp 13645, 131. 24X

  Fiche 50-000,82/08/10,8210070007
- 8210010221 Forwards IE Insp Repts 50-339/82-18 & 50-339/82-18 pn 820709-0805. No noncompliance noted DANCE.K.C. Division of Project & Resident Programs. 82/09/31 LEASBURG.R.H. Virginia Electric & Power Co 2pp. 15567 338 24X Fichm 50-338, 82/09/31.8210010221.
- --8210010225 IE Insp Repts 50-338/82-18 & 50-339/82-18 on 820709-0805 No noncompliance noted Major areas inspected LERs, refueling & outage activities, surveillance & maint activities, operations & followup on significant events.

  JOHNSON, D. F. SHYMLUCK, M. B. JULIAN, C. Division of Project & Resident Programs 82/08/31 (1pp. 15567:340 24X)
  Fiche 50-338,82/08/31,8210010221
- 8210010300 Forwards IE Insp Repts 50-339/82-28 & 50-339/82-28 on 820816-19 No noncompliance noted.

  DANCE, H C Division of Project & Resident Programs 82/09/03, LEASBURG, R H. Virginia Electric & Power Co. 29p 15568-317 24X Fiche 50-338, 82/09/03, 8210010300.
- --B210010314 IE Insp Repts 50-338/82-28 & 50-339/82-28 on B20816-19.No noncompliance noted Major areas inspected:thermal sleave removal; reactor collent loop stop valves; tap screw fractures & broken control rad guide tube support pins YORK: J. W. BLAKE, J. J. Division of Engineering & Technical Programs B2/09/02 opp 15569, 319, 24X Fiche:50-338,82/09/03,8210010300
- 8210190187 Forwards IE Insp Repts 50-338/82-30 & 50-339/82-30 on 820831-0903 No noncompliance noted, BANCE.H C. Division of Project & Resident Programs. 82/09/23 LEASBURG.R.H Virginia Electric & Power Co 2pp. 15707-262 24X Fichs 50-338, 82/09/23, 8210150187.
- --8210150194 IE Inep Repts 50-338/82-30 & 50-339/82-30 on 880831-0903. No noncompliance hoted Mejor areas inspected generator step-up transformer failure on 820822 & licensee recommendations & inspector follows items.

  RUFFIA B : CONLONITE. Division of Engineering & Technical Programs. 82/09/17. 4pp. 15707.264. 24X Fiche 50-338,82/09/23,8210150187.
- 8210220454 Forwards IE Insp Rests 50-338/82-33 & 50-339/82-33 on 820918. No noncompliance moted.

  DANCE, H. C. Division of Project & Resident Programs. 82/10/04. EARSUMO, R. H. Virginia Electric & Power Co 2pp 15779:135. 24X Fichs. 50-338, 82/10/04, 9210220454.
- --8210220461 IE Inep Regts 50-338/82-33 t 50-339/82-33 on 820918.No noncompliance noted Major areas inspected full-scale radiological exercise. 
  RWFFAN.9. N. MARBTON, R.R., JENKINS, Q.R. Division of Engineering & Tachnical Programs. 82/09/30. 11pp. 15779:137. 24X Fiche, 50-338, 82/10/04, 8210220454
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dielooged I-125 Implant Seeds." Svc list encl. CQBB,L.I. Division of Fuel Facilities, Materials & Gafeguards 82/10/06 Consolidated Edison Co. of New York. 66pp. 15741-250, 24X Fiche. 50-000, 82/10/06, 8208190233.
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thirt-Hall.Large-Diameter Stainless Steel Rectroulation Sysfiping at 84R Plants," Syc ligt encl.
  DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement, 82/10/14, Consolidated Edison Co. of New York 115pp 15810; 125. 24X Fiche; 50-000, 82/10/14, 8208190238.

- 8 Reportable occurrences. LERs & related correspondence
- 8009240202 Forwards analysis of 800523 trip & subsequent safety injection at facility Some operating nuclear plants lack controls restricting starting of electrical motors while smergency dissel generator is undergoing load tests HICHELBON.C Director's Office 80/08/20 JORDAN.E L Division of Reactor Operations Inspections. 3pp 13670 018 24X Fichs 50-338,80/08/20,8009240202
- B210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems. Forwards documents listed in App A FELTON. J. H Division of Rules and Records 82/06/28 UDELL. R A Critical Mass Energy Project 15pp 13727 005 24X Fiche 30-000, 82/06/28, 8210010008
- --BiliiBOOOI Recommends comprehensive assessment of plant operating conditions to determine specific predetermined time related sequences of occurrence to emergency buses SRP should be revised re-design features.

  ASHE-F Director's Office Bi/10/16 MICHELBON, C Director's Office 4pp. 15731-049 24X Fiche 50-000.82/06/28,8210010008
- 8210010140 Forwards LER 82-038/03L-0 CARTHRIGHT.W R. Virginia Electric & Power Co 82/09/22 O'REILLY.J.P. Region 2. Office of Director ip 15565 346 24X Fiche: 80-338, 82/09/22, 8210010140
- --8210010145 LER 82-058/03L-0. on 820826, manipulator crane area monitor RM-RMS-162 failed to meet acceptance criteria of periodic calibr & declared inoperable Caused by instrument drift greater than 3% responses requirement Assembly replaced CARTHRIGHT.W.R. Virginia Electric & Power Co. 82/09/22 Region 2, Dffice of Director 3pp. 15565-347 24X Fiche 50-338, 82/09/22,8210010140
- 8210010163 Forwards LER 82-059/03L-0 CARTWRIGHT: W R. Virginia Electric & Power Co 82/09/22 U'REILLY.J P. Region 2: Office of Director ip. 15867 274 24X Fiche. 80-338: 82/09/22: 8210010163
- --8210010168 LER 82-059/03L-0. on 820827, ventilation vent 8 gaseous radiation detector response found to exceed calibr test acceptance criteric Caused by gradual daterioration of shotomultipliar tube 8 preamplifier. Parts replaced CARTHRIGHT, W R Virginia Electric & Power Co. 82/09/22 Region 2, Office of Director 2pp 15567-275 24X Fiche-50-338, 82/09/22, 8210010163
- 8210010209 Forwards LER 82-050/03L-0. CARTHRIGHT, H. R. Virginia Electric & Power Co. 82/09/22 U'REILLY, J. P. Region 2. Office of Director ip 13567 334, 24X Fiche 50-33B,82/09/22,8210010209,
- --8210010219 LER 82-050/03L-0'on 820826, fire doors A80-1 & A80-2 between Units 1 & 2 rod control rooms & auxiliary bldg & fire doors A59-1 & A59-2 between Units 1 & 2 cable vault rooms & auxiliary bldg found not in periodic teating program. CARTHRIGHT. H. R. Virginia Electric & Power Co 82/09/22, Region 2. Office of Director. 1p. 15567-335 24X Fiche 50-338,82/09/22,8210010809.
- 82102R0227 Forwards LER 82-057/03L-0. CARTHRIGHT. W.R. Virginia Electric & Power Co 82/10/07 O'REILLY.J.P. Region 2. Office of Director. ip 15775.126 24X Fiche: 50-338.82/10/07.8210220227.
- --8210220234 LER 82-057/03L-0.on 820910, satpoint for turbins impulse pressure comparator in instrument procedure found incorrect. Caused by typographical error during procedure revision. Procedure corrected & card pecalibr CARTHRIOHILM.R Virginia Electric & Power Co. 82/10/07. Region 2. Q4fice of Director Spp. 13775-127. 24X Fiche.50-338, 82/10/07,8210220227
- 8210190264 Forwards LER 82-062/03L-0 CARTHRIOHT, W. R. Virginia Electric & Power Co. 82/10/12. O'REILLY, J. P. Region 2. Office of Director. ip. 15742:192 24X Fiche: 50-338:82/10/12:8210190264.
- --8210190270 LER 82-062/03L-0:on 820917.cold leg injection line check valve found w/five corroded bolts. Caused by small lesk at body to bonnet gasket. Stude & bonnet gasket replaced. CARTHRIGHT. H. R. Virginia Electric & Power Co. 82/10/12. Regian 2. Office of Director. 2pp. 13742:193 24X Fiche: 50-338. 82/10/12.8210190264.
- 8210190329 Forwards LER 82-061/03L-0.
  GARTHRIGHT W.R. Virginia Electric & Power Co. 82/10/12.
  O'REILLYJ,F. Region 2. Office of Pirector. 1p 15742:061. 24K
  Fiche; 50-338, 82/10/12, 8210190329.

- 8210190337 LER 82-061/03L-0 on 820917, during chemistry log review, specific activity of primary coolent exceeded Tech Specs Caused by digration of I-131 through pinhole lasks in fuel cladding Specific activity returned to acceptable limits CARTHRISHT, W. Virginia Electric & Power Co. 82/10/12 Region 2. Office of Director 4pp 15742 062 24X Fichs 50-338, 82/10/12,8210190329
- 110290337 Forwards LER 82-045/03L-0 CATHRIGHT WR Virginia Electric & Power Co 82/10/13 D'REJLCY, J P. Region 2. Office of Director ip 15853 029, 24X Fichs: 50-338,82/10/13,8210290337
- 8210290347 LER 82-065/03L-0 on 820919, routine recalibr of pressurizer level transmitter LT-1-461, revealed transmitter out of tallibr Caused by instrument drift Transmitter replaced. New transmitter calibr successfully CARTHRIOHT, N.R. Virginia Electric & Power Co. 82/10/13 Region 2. Office of Director ip 15853 030 24X Fiche 50-338, 82/10/13, 82/10230337
- 210280270 Forwards LER 82-063/03L-0 CARTHRIGHT H R Virginia Electric & Power Co 82/10/19 D'RETLLY, J.P. Region 2, Office of Director 1p 15803, 215 24X Fiche 50-338, 82/10/19, 8210260290
- -8210250293 LER 82-063/03L-0 on 820924, ambient temp signal conditioner & control room delta temp recorder responses found to exceed calibr procedure acceptance criteria. Caused by instrument drift instruments recalibr CARTHRIGHT. HR Virginia Electric & Power Co 82/10/19 Region 2. Office of Director 3pp 15803 216 24X Fiche 50-338, 82/10/19, 82/10/260290
- OCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

  Security: medical, emergency & fire protection plans
- \*210250208 Forwards "Full-Scale Emergency Exercise North Anna Power Station Sept 1982 Exercise Menuel," per NRC 820129 ltr LEASBURG.R H Varginia Electric & Power Co 82/08/30 D'REILLY.J P Region 2. Office of Director 1p 15791.205 24X Fiche 50-338, 82/08/30, 8210250208
- --8210250212 "Full-Stale Emergency Exercise North Anna Power Station, Sept 1982:Exercise Manual " # Virginia Electric & Power Co 82/08/27 243pp. 13791: 206 24X Fichs 50-38.82708/30.8210250208
- B210030125 Forwards revised security training & qualification plans Plans ustabled.

  LEASBURG.R Wirginia Electric & Power Co. 82/09/17, DENTON, H. R. Office of Nuclear Reactor Regulation, Director ip 15366:013. 24X Fiche 50-000, 82/09/17, 8210010125
- 8210130105 Releases public version of emergency response plans.
  FELTON, J M Division of Rules and Records 82/09/28 Document
  Management Branch ip 15693 001 24X Fiche, 50-338, 82/09/28,
  8210130105
- --8210130112 Forwards public version of emergency response plans for Louiss. Spotsylvenia. Cerolina, Henover & Orange Counties. VA LEABBURG. R. H. Virginia Electric & Power Co 82/09/20 O'REILLY. J P Region 2. Office of Director. 1p 15693-002. 24X Fiche-50-338, 82/09/28, 8210130105.
- --B210:30:14 Public version of facility emergency response plan, consisting of radiological emergency response plans for Louisa Spotsylvania Caroline Hanover & Orange Counties, VA Virginia Electric & Power Co 82/08/30 632pp 15693; 004, 24x Fiche 50-338,82/09/28,8210130105.
- 8210050076 Submits correction to 820628 Revision 3 to response to NUREG-0737. Item I D 2. "Safety Parameter Display Sys."
  Correction should be included in schedular exceptions gertaining to emergency response capabilities.
  LEASBURG, R H Virginia Electric & Power Co. 82/09/29. DENTON, H.R Office of Nuclear Reactor Regulation, Director. 1p. 24X
  Fiche: 50-000, 82/09/29, 8210050076.
- B210050335 Forwards revised pages to App R post-shutdown review Revised pages concern results of study which calculated time available after stuck open power operated relief valve event before unsafe condition reached LEABBURO, R H. Virginia Electric & Power Co. 82/09/30. DENTON: H R, Office of Nuclear Reactor Regulation, Director, CLARK, R.A. Operating Reactors branch 3 Spp. 15610.093. 24X
  Fichs 50-338.82/09/30,8210050335

- 8210220454 Forwards IE Insp Rapts 50-338/82-33 & 50-339/82-33 on 820918 No noncompliance noted DANCE, H C. Division of Project & Resident Programs 82/10/04 LEASBURG, R M. Virginia Electric & Power Co. Rap. 15779, 135, 24X Fiche: 80-338, 82/10/04.8210220454
- --8210220461 IE Insp Repts 50-339/82-33 & 50-339/82-33 on 820918 No noncompliance noted Major areas inspected full-scale rediciogical exercise.

  HUFFMAN 9 N. Division of Engineering & Technical Programs 82/09/30. 11pp. 15779.137. 24X Fiche.50-338.82/10/04,8210220454.
- 9 Adjudicatory correspondance
- 8210260348 Petition of Conternsd Citizens of Louisa County for leave to intervene & request for hearing re proposed license amend to authorize receipt & storage of Surry spent reactor fuel at North Anna Certificate of Siv encl DOUGHERTY, J B Dougherty, J B 82/10/22 Commissioners Spp. 13503 180 24X Fiche 30-338,82/10/22,8210260348.
- 82:0260355 Petition of Concerned Citizens of Louise County for leave to intervene & request for hearing re-proposed litense amend authorizing increase in capacity of spent fuel pool Notice of appearance & Ceptificate of Svc encl. DOUGHERTY, J B. Dougherty, J B. 82/10/22 Commissioners. 7pp 15802 350 24% Fishe 50-338,82/10/22,8210260355.
- 8210260367 Petition of County of Louisa, VA & Board of Supervisors of County of Louisa, VA to Intervene re proposed license amend to permit receipt & storage of 500 spent fuel assemblies from Surry Certificate of Svc encl
  COLEMAN. J M Louisa County, VA COLEMAN, J M Beveridge, Fairbanks, & Diamond 82/10/22 Commissioners 13pp. 15803.111. 24%
  Fiche. 50-338, 82/10/22, 8210260367.
- 8210260373 Petition to intervene of County of Louisa.VA & Board of Supervisors of County of Louisa.VA re proposed license amend to expend fuel storage capacity Certificate of Svc enci.

  COLEMAN.J.M Louisa County.VA COLEMAN.J.M Beveridge, Fairbanks, & Diamond. 82/10/22. Commissioners. 15pp 15803,143, 24X Fiche: 30-338.82/10/22.8210260373.
- 8210280238 Notice of ASLB constitution BJ Wolferchairman & J Kline & GA Ferguson, members LAZO.R.M Atomic Sefety and Licensing Board Panel. 82/10/26 2pp. 18837 060 24% Fiche 50-338,82/10/26/8210280238
- 8210280300 Notice of ASLB constitution SJ Wolfe, chairman & J Kline & GA Ferguson, members.
  LAZO,R.M. Atomic Safety and Licensing Board Panel. 82/10/26. 2pp. 15837:281. 24X Fiche 50-338,82/10/26,8210280300
- P. Operating license stage documents & correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems. Forwards documents listed in App A FELTON.J M Division of Rules and Records. 82/06/28 UDELL.R.A. Critical Mass Energy Project. 15pp. 15727 005 24x Fiche.50-000.82/06/28.8210010008
- --B008050265 Discusses addl required into to better define potential for cracking in reactor yeasel nozzles.

  NOONAN, V. B Assistant Director for Materials & Gualifications Engineering B0/05/05. TEDESCO, R. L. Assistant Director for Licensing. 2pp. 13727:176. 24X Fiche. 50-000.82/06/26,8210010008.
- 8208090114 Application for amend to Licenses NPF-4 & NPF-7, authorising receipt & storage of 300 spent fuel assemblies from Surry Units 1 & 2. Rept entitled "Spent Fuel Storage" encl. LEASSURG.R.H. Virginia Electric & Power Cb 82/07/10, DENTON, H R, Office of Nuclear Reactor Regulation. Director. CLARK, R. A. Operating Reactors Branch 3, 209 15569:244, 24% Fiche: 50-338, 82/07/13, 8208090114.
- ---8210010246 Proposed Tech Specs allowing receipt & storage of 500 spent fuel assemblies from Surry

  \* Virginia Electric & Power Co 82/07/13 App. 15569.246. 24x
  Fichs 50-338,82/07/13.8208070114.
- --8210010247 "Spent Fuel Storage,"

  4 Virginia Electric & Power Co. 82/07/21, 8App. 155A9,251, 24x
  Fiche 50-338,82/07/13,8208090114.

- 82:0010103 Forwards application for amend to License NPF-7, to complete License Conditions 2 C(15)(h)(4) & 2 C(h)(15)(2) by end of second refueling outage LEABBURG.R H Virginia Electric & Power Ca 82/09/27 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Brench 3. 3pp 15567.185 24X Fiche 50-339, 82/09/27, 8210010103
- --8210010107 Application for amend to License NPF-7, changing completion dates of License Conditions 2 C(15)(h)(4) & 2 C(h)(15)(2) to end of second refueling outage \* Virginia Electric & Power Co 82/09/27 6pp 15567,188 24X Fiche: 50-339, 82/09/27, 8210010103
- 8210040277 Advises of plans for const of new 230 kV transmission line to connect North Anna power station to Louise substation No Tech Spec or ETS change required LEASBURGOR H Virginia Electric & Power Co 82/09/27 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Generating Reactors Branch 3 2pp 15591 204 24X Fiche 50-338,82/09/27,8210040277
- --8210040285 Responds to util 761107 ltr informing that 740102 & 760408 ltrs did not constitute application for const of 230 %V transmission line from North Anna to Louisa Bubstation Ref to line has been removed from FEB addendum YOUNOBLOOD, B. J. Environmental Projects Branch 2 76/11/26 PROFFITT. W. Urigfine Electric & Power Co Spp 15591.206 24X Fichs 50-338,82/09/27,8210040277
- --B210040270 Advises that util 740102 & 760608 ltrs to NRC do not constitute application for const of 230 kV transmission line from North Anna to Laufsa Application. If required, will be filed prior to OL issuance for Unit 2
  PROFFITT, W L, Virginia Electric & Power Co 76/11/09, RUBCHE, B C Office of Nuclear Reactor Regulation, Director YOUNDBLOOD, 8 J Environmental Projects Branch 2 1p 15591 212 24X Fiche. 50-338, 82/09/27, 8210040277
- --B210040297 Forwards add1 info & answers to questions in NRC 740820 ltr re 230 kV transmission lime PROFFITT, W L Virginia Electric & Power Co. 76/08/30 RUSCHE, B C. Dffice of Nuclear Reactor Regulation, Director YUNOBLO
- --8210040301 "Mgt of Transmission Line Rights of Way "

  Enviro Audits, 76/07/31, 77sp 15591:219 24X
  Fiths 50-338,82/09/27,821004027.
- --8210040307 Requests add1 info by 760830 to complete assessment of environ impact of 230 tV transmission line. YOUNGELOOD, B J Environmental Projects Branch 2 76/08/20 PROFFIT, W L Virginia Electric & Power Co 2pp 15591,276 24X Fiche. 50-338, 82/09/27, 8210040277.
- --8210040315 Forwards one oversite topographical map & application to VA State Corp Commission for approval & certification of North Anna to Louise transmission line in response to NRC 760630 request Aperture card is available in PDR.
  PROFFITT, W L Virginia Electric & Power Co 76/07/06.
  RUSCHE, B C Office of Nuclear Reactor Regulation, Director 29pp. 13591.298 24X Fiche 50-338, 82/09/27, 8210040277.
- --B21004032B Advises that proposed 230 kV transmission line between North Anna & Louisa need not be avaluated in amend to environ rept for North Anna 1 & 2.Line is not part of North Anna utilization facility.

  RACONE: 8 Virginia Electric & Power Co 74/01/02 MULLER, D. R. Atomic Energy Commission. 2pp. 15591: 329 24X Fiche: 50-338, 82/09/27, 8210040277.
- 8210120215 Application to amend Licenses NPF-4 & NPF-7, revising Tech Space re staff working hours. Request does not involve unreviewed safety question per 10CFR80. 39 LEABBURO, R. H. Virginia Electric & Power Co. 82/10/01. DENTON, FI R Office of Nuclear Reactor Regulation. Director. 1p. 15652.150. 24x Fiche 50-338,82/10/01,8210120215.
- --B210120225 Proposed Tech Specs revising staff working hours. Provision does not permit shift crew position to be unmanned upon shift change due to late or absent oncoming shift crewman. 
  \* Virginia Electric & Power Co 82/10/01. 4pp 13652:151. 24x Fiche. 30-338, 82/10/01. 8210120215.
- 8210120265 Informs of implementation status of NUREO-0737. Item II. B.2, "Plant Shielding" per NRC 820517 request. All required work completed.
  LEASURG.R.H. Virginia Electric & Power Co. 82/10/01, DENTON. H.R. Office of Nuclear Reactor Regulation, Director, 2pp. 15651-230. 24X Fiche. 50-000.82/10/01.8210120265.

- 8210120297 Forwards errata to Topical Rept VEP-FRD-33. "VEPCO Reactor Core Thermal-Mydraulic Analysis Using COBRA IIIc/HIT Computer Code." LEABBURG, R H Virginia Electric & Power Co 82/10/04 DENTON.K R Office of Nuclear Reactor Regulation, Director 2pp 15652 330 24X Fiche 50-000,82/10/04.8210120297
- --8210120309 Errata to "VEPCO Reactor Core Thermal Hydraulic Analysis Using COBRA-||IIc/MIT Computer Code " • Virginia Electric & Power Co VEP-FRD-33 ERR 15652 332 24% Fichs 30-000, 82/10/04,8210120297
- 8210270042 Forwards safety evaluation & technical evaluation rept ra analysis of main steam line break w/continued feedwater addition Analysis acceptable H/o technical evaluation CLARK,R A Decrating Reactors Branch 3 82/10/04 LEASBURO,R H Virginia Electric & Power Co 1p 15877 271 24X Fiche 80-938, 82/10/04, 82/10270042
- --B210290071 Bafety evaluation re main steam line break w/continued feedwater addition Containment overpressurization will not result & auxiliary feedwater pumps can function during event
  - \* Office of Nuclear Reactor Regulation, Director 82/10/04 6j; 15877 272 24X Fiche 50-338,82/10/04,8210290042
- 8210190321 Bubmits supplemental info re B20318 & 0927 requests for relief concerning License Condition 2 C(15)(h)(4) Qualified pressure switches unavailable Nonqualified switches will be installed by B21031 Qualification expected by Jan 1993 LEABBURO,R H Virginia Electric & Power Co 82/10/13 DENTOM.H R Office of Nuclear Reactor Regulation. Director CLARK,R A Operating Reactors Branch 3 1p 15742.058 24X Ficher 50-339, 82/10/13, 8210190321
- 8210220011 Submits addl info to 820713 request for amend to Licenses NPF-4 k NPF-7 Number of storage locations in neutron absorber spant fuel storage rack changed to 1.737 Fuel pool temps changed in Table 7 i
  LEABBURG, R. H. Virginia Electric & Power Co. 82/10/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director CLARK, R. A. Operating Reactors Branch 3 3p 15778 211 24X Ficher 50-338, 82/10/18, 8210220011
- 8210220178 Comments on evaluation of significant dynamic toads in determining capacity of slings used per NUREO-0612 Rating can be safely expressed in terms of mar static load LEABBURG,R H Virginia Electric & Power Co 82/10/18 DENTON.M.I Defice of Nuclear Reactor Regulation, Director 2pp 15777 243 24X Fiche 50-000.82/10/16.8210220178
- B210260133 Forwards revised Table 7-1 to "Bummary of Info in Support a Increasing Spent Fuel Storage Capacity at North Anna Units to 2." Rept originally submitted w/820820 request for amend to Licenses NPF-4 & NPF-7 to replace storage racts LEASBURG.R H Virginia Electric & Power Co 82/10/21 DENTOLS & Office of Nuclear Reactor Regulation, Director CLARK,R A Operating Reactors Branch 3 2pp 15799:102 24X Fichs: 50-338, 82/10/21, 8210260133.
- --8210260136 Revised Table 7-1 to "Summary of Info in Support of Increasing Spent Fuel Storage Capacity at North Anna Units 1 & 2 "

  \*\* Virginia Electric & Power Co. 82/10/21 1p 15799.104. 248 Fichs 50-338.82/10/21.8210260133
- Q Inspection reports, IE Bulletins & correspondence
- 8210220200 Responds to NRC ltr re violations noted in IE Inep Hepts 50-338/82-08 & 50-339/82-08 Corrective actions health physics technician counseled re correct procedures for entering high radiation area.

  LEASBURG: R H. Virginia Electric & Power Co 82/07/29.

  O'REILLY.J.P. Region 2: Office of Director. 5pp 15777.265 242 Fiche: 50-338.82/07/29.8210220200
- 8210070007 Responds to FOIA request for sight categories of recents a steam generators & steam turbines. App A documents provided in R Udell FOIA Request 81-313. Forwards documents listed in App B.

  FELYON, J. M. Division of Rules and Records 82/08/10 LOM9.D J Winthrop, Stimson, Putnam & Roberts, 9pp 15645.063. 24% Fiche: 50-000, 82/08/10, 8210070007.
- --8210070137 Forwards tabulated data on steam generator inep & meint it facilities. Data should be provided to licensess IPPOLITO, T. Operating Reactors Assessment Branch. 82/04/01 VAROA.S. Operating Reactors Branch 1. Spp. 15645,131 241 Fiche: 50-000,82/08/10,8210070007.

- 8210010221 Forwards IE Insp Repts 50-339/82-18 & 50-339/82-18 on 820709-0803 No noncompliance noted CARCE-H C Division of Project & Resident Programs 82/08/31. LEASBURG.R H Virginia Electric & Power Co 2pp 15567 338 24X Fichs 50-338.82/08/31.8210010221
- --8210010225 IE Insp Rupts 50-338/82-18 & 50-339/82-18 on 820709-0805 No noncompliance noted Major areas inspected LERs, refueling & outage activities, surveillance & maint activities, operations & followup on significant events
  JOH/830N,D F . BHYMLOCK,M B . JULIAN,C Division of Project & Resident Programs 82/08/31 11pp 15567 340 24X
  Fichs 50-338,82/08/31,8210010221
- B210010300 Forwards IE Insp Napts 50-339/82-28 & 50-339/82-28 on B20816-19 No noncompliance noted DANCE:H C Division of Project & Resident Programs 82/09/03 LEASBURG:H C Virginia Electric & Power Co 2pp 15568 317 24X Fichs
- --B210010314 IE Insp Repts 50-338/82-28 & 50-339/82-28 on B20816-19 No noncompliance noted Major areas inspected thermal sleeve removal reactor coolent loop stop valves, cap screw fractures & broken control rod guide tube support pins YORK, J W. SLAKE, J J Division of Engineering & Technical Programs 82/09/02 6pp 15568 319 24X Fiche 50-338,82/09/03,8210010300
- 8210150187 Forwards IE Insp Repts 50-338/82-30 & 50-339/82-30 on 820831-0703 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/07/23 LEASBURG.R H Virginia Electric & Power Co 2pp 15707-262. 24X Fiche 50-338,82/07/23,8210150187
- --8210150194 IE Insp Repts 50-338/82-30 & 50-339/82-30 on 820831-0903 No noncompliance noted Major areas inspected generator step-up transformer failure on 820822 & licensee recommendations & inspector followup items
  RUFF.A B , CONCON.T E Division of Engineering & Technical Programs 82/09/17 4pp 19707-264 24X Fichs 50-338-82/09/23, 8210150187
- 8210220454 Forwards IE Insp Repts 50-338/82-33 & 50-339/82-33 on 820918 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/10/04. LEASBURG.R H Virginia Electric & Power Co 2pp 15779-135. 24X Fiche: 50-338, 82/10/04, 8210220454
- --8210220461 IE Insp Repts 50-338/82-33 & 50-339/82-33 on 820918 No noncompliance noted Major areas inspected full-scale radiological exercise HUFFMAN.0 N . MARBTON.R R . JENKINB.0.R. Division of Engineering & Technical Programs 82/09/30 isp i3779 i37. 24X Fiche 50-338,82/10/04.8210220454
- 8208190233 IE Info Notice 80-35, Suppl i. "Leaking & Dislodged I-125 Implant Seeds " Svc list encl CD88-L I Division of Fuel Facilities, Materials & Safeguerds 82/10/06 Consolidated Edison Co of New York & App 15761 250, 24X Fiche 50-000,82/10/06.8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Hall. Large-Diameter. Stainless Steel. Recirculation Sys Piping at BMR Plants " Svc list encl DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York #15pp 15810 125 24X Fiche. 80-000. 82/10/14, 8208190238.
- 8 Reportable occurrences, LERs & related correspondence
- 8210080047 Trip rept of 810709 site visit to view extent of famage caused by failure of B phase main transformer Transformers not designed to withstend severe electrical short circuits inside transformer CHIRAMAL, M Director's Office 81/07/14, MICHELSON, C Director's Office 3pp 15470-012, 24X Fiche 50-337,81/07/14,8210080067
- 821001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems.Forwards documents listed in App A FELTON.J M Division of Rules and Records. 82/06/28. UDELL.R A Critical Mass Energy Project. 15pp. 15727,005 24X Fiche.50-000,82/06/28,8210010008
- --B010210037 Forwards 800505 memo re underclad cracking in reactor vessel nozzles. Review re safety aspects & compliance w/Section IX of ABME ode concludes that problem should not be included on generic issues list.

  BACR.R L Safety Program Evaluation Branch 80/07/17 KINTNER.L L Licensing Branch 2. ip. 15727 175 24X Fiche 50-000, 82/06/28, 8210010008

- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5). FELTON.J M Division of Rules and Records 82/07/12 UDELL.R. A Critical Mass Energy Project 9pp. 15665 027 24X Fiche 50-000.82/07/12.8210080015
- --8210080197 NRC operations of usage chart re events at facilities \* NRC - No Detailed Affiliation Given 82/07/12 ip 15668-221 24X Fiche 50-000-82/07/12.8210080015
- 8207230301 Forwards LER 82-027/03L-0. CARTHRIGHT: Wirginia Electric & Power Co 82/07/13 D'REILLY, J P. Region 2. Office of Director ip 13998 329 24X Fiche 50-339,82/07/13,8207233301
- --B207290303 LER 82-027/03L-O on 820620 & 23 sxial flux difference want less than -5X from target on two occasions Caused by inability to establish stable axial flux difference target in new core CATKRIGHT, W Virginia Electric & Power Co 82/07/13 Region 2, Office of Director 3pp, 13998 330 24X Fiche 50-339, 82/07/13.8207230301
- 8210010233 Forwards LER 82-059/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co 82/09/22 G'REILLY,T P. Region 2. Office of Director 1p 15574 031 24X Fiche 80-339,82/09/22,8210010233
- --8210010236 LER 62-059/03L-O on 820830, steam generator B steam flow channel IV, providing steam line break & loss of heat sink grotection, failed high Cause not determined Channel placed in tripped condition Problem cleared during troubleshooting GRTHRIGHT, W R Virginia Electric & Power Co. 82/09/22 Region 2, Diffice of Director 3pp 15574 032. 24X Fiche 50-339, 82/09/22,8210010233
- 9210080182 Forwards LER 92-061/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co 82/09/30 O'REILLY, J P Region 2: Office of Director ip 15640:172 24X Fiche 30-339,82/09/30:8210080182
- 8210220415 Forwards LER 82-062/03L-0 CARTWRIGHT.W R. Virginia Electric & Power Co. 82/10/07 O'REILLV, J.P. Region 2. Office of Director. 1p. 15778-355. R4X Fiche: 50-339, 82/10/07, 8210220415.
- --B210220421 LER 82-062/03L-0.on 820710 & 13, fire door 854-7 found not providing definitive seal for control ruom pressure boundary. Caused by out-of-plumb door installation Door removed, stops adjusted & door replaced CARTHRIGHT, M.R. Virginia Electric & Power Co 82/10/07 Region 2, Office of Director. 2pp 15778:354 24X Fiche: 50-337, 82/10/07.8210220415
- 8210220441 Forwards LER 82-060/03L-0. CARTHRIGHT: W.R. Virginia Electric & Power Co. 82/10/07. O'REILLY, J.P. Region 2. Office of Director. 1p. 15778:353, 24X Fiche:50-339,82/10/07.8210220441.
- --8210220450 LER 82-060/OSL-0; on 820914, w/Unit 2 at 98% power, fire door 854-9 between emergency switchgear room & cable vault found blocked open w/o fire watch. Cause unknown Block removed & door persolitity verified.
  CARTHRIGHT, W. R. Virginia Electric & Power Co 82/10/07. Region 2, Office of Director. ip. 15778: 354. 24% Fiche: 50-339, 82/10/07, 8210220441.
- 8210260281 Forwards LER 82-043/03L-0. CARTHRIGHT, W.R. Virginia Electric & Fower Co 82/10/19. U'REILLY, J.P. Region 2. Office of Director, ip 15801;352 24X Fiche: 50-339, 82/10/19, 8210260281.
- --B210260287 LER 82-063/03L-0:on 820926, individual rod position indication for rod 8-08 in control bank D deviated from group demand position by greater than 12 steps ω/no rod motion. Causad by instrument drift. Instrument recalibr. CARTHRIGHT, M.R. Virginia Electric & Power Co. 82/10/19 Region 2, Office of Director 2pp 15801:353, 24% Fiche:50-339, 82/10/19,8210260281.

- 8210260346 Forwards LER 82-065/03L-0 CARTURIOHT W R Virginia Electric & Power Co 82/10/19 O'REILLY, J P Region 2, Office of Director ip. 15803 188 24X Fiche: 50-339, 82/10/19, 8210260346
- --8210260360 LER 82-065/03L-0. on 821007, control power for A casing cooling pump found de-emergized due to open circuit breaker Cause unidentified Circuit breaker closed CARTHRIGHT, N. R. Virginia Electric & Power Co. 82/10/19 Region 2, Office of Director 2pp 15903:189 24X Fiche 50-337, 82/10/19, 82/10/19, 82/10/19, 82/10/19, 82/10/19, 82/10/19
- DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 8210040377 Responds to 820715 ltr.Requests application be amended to include high drywall temp & design of level indication sys w/respect to leak or break of single instrument tap or sensing line Addl info needed to verify acceptability YOUNOBLOOD, B J Licensing Branch 1. 82/09/21. TAUBER, H Detroit Edison Co 4pp 15597.203. 24X Fiche 50-341,82/09/21,8210040377.
- 8210010456 Forwards "Inservice Testing Program" for pumps & valves for 120-month insp period beginning w/fvel load per 10CFR50 55a. Rept supersedes Revision O submitted w/fl0803 itr TAUBER.H Detroit Edison Co 82/09/22 KINTNER.L L Division of Licensing ip. 15570 011 24X Fiche. 50-341,82/09/22,8210010456
- --8210010460 "Inservice Testing Program "
  CLAUSG.J.M., MARTIN.J.B. NUTECH (Nuclear Technology, Inc.)
  DET-16-0201 R01 82/07/0B 161sp. 15570 012 24X
  Fiche 50-341.82/09/22:8210010456
- 8210120026 Summary of S20715 meeting w/util re facility QA concerning recent design & const deficiencies. Applicant considering another independent design review re core spray sys XINTNER, L. L. Licensing Branch i S2/09/22. Licensing Branch i 7pp 15689 189 24X Fiche 50-341.82/09/22.8210120026
- 82:0120627 Forwards safety evaluation of plant-unique analysis rept for Mark I containment long-term program, technical evaluation rept of program audit & BNL technical evaluation of analysis rept LAIN48.0 C. Assistant Director for Operating Reactors. 82/09/23 NOVAN.7.H Assistant Director for Licensing. 1p 15684.241 24X Fiche: 50-341.82/09/23,8210120627
- --8210120636 Bafety evaluation accepting plant-unique analysis rept for nment long-term program Possible as in simple vent downcomer lateral load tified. \*--1\*ed Affiliation Given 82/09/23 12pp. \*he 50-341,82/09/23,8210120627.

t Long-Term Program - Structural int," technical

(nstitute/Franklin Research 82/08/25 NRC - No 584:254. 24X

- --B210120642 "Technical Evaluation of Fermi-2 Plant-Unique Analysis Rept" # Brookhaven National Laboratory NRC-20-82-213, BNL-04261, 82/09/30, NRC - No Detailed Affiliation Given 40pp 13684:300 24K Fiche:50-341,82/09/23,8210120627
- 8210010289 Forwards Amend 44 to application for DL.consisting of Amend 44 to FBAR.
  LANDORAF, L.C. LeBosuf, Lamb, Leiby & Hacrae LANDORAF, L.C. Detroit Edison Co. 82/09/30 DENTON, H.R. Offics of Nuclear Reactor Regulation.
- --B210010295 Amend 44 to application for OL. HEIDEL.C.M. Detroit Edison Co B2/09/28. ip. 15573:188. 24X Fiche: 30-34;62/09/30.8210010289.
- 8210080046 Confirms points agreed upon at NRC Caseload Forecast Panel 820824-26 site visit to assess plant const schedule. TAUBER.H. Detroit Edison Co. 82/10/01. DENYON.H R. Office of Nuclear Reactor Regulation, Director. 2pp. 15643:279. 24X Fiche: 50-341.82/10/01.8210080046.

- 9210130158 Forwards Cartificate of Svc cartifying svc of Amend 44 to amended & substituted application for licenses MATERGIS R Detroit Edison Co 82/10/06 Office of Nuclear Reactor Regulation, Director 3pp 15673 074 24x Ficher 50-241.02/10/06.8210130158
- 8210180188 Responds to NRC request for clarification of util 820715
  Itr re errors in BWR water level indication, Existing
  emergency operating procedures adequate for successful
  termination of bounding event resulting in ref leg flashing
  TAUSER: H Detroit Edison Co 82/10/11 KINTNER: L Division of
  Licensing. 3pp 15719 120 24X Fiche 50-341,82/10/11,8210180189
- 8210220414 Submits schedule for resolution of open items re Mark 1 containment. If resolution not apparent within 3 months of fuel load, will will work w/NRC to provide adequate justification for interim operation TAUBER.H Detroit Edison Co. 82/10/15 KINTNER.L L Division of Licensing. 3pp 15779.148 24X Fichs 50-341.82/10/15,8210220414
- 8210280222 Forwards Class II fee for application to amend CPPR-B7 MATERS, B R Detroit Edison Co 82/10/22 DIGGS, R M License Fee Management Branch 1p 15837 090 24X Fiche 50-341,82/10/22, 821028022
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8210150639 Forwards status of add1 Mark I containment issues for supplemental BER input identified since Mark I containment long-term program

  LAINAS.0 C Assistant Director for Operating Reactors. 82/10/06

  NOVAK.T M Assistant Director for Licensing ip 15715 290 24k

  Fiche 30-341.82/10/06.829
- F Becurity, medical, emergency & fire protection plans
- 8210230195 Forwards summary evaluation of Mar 1982 evacuation time estimates. Several deficiencies noted Enumeration of special facilities missing & should be provided URBANIK.T. Texas A & M Univ 82/09/23 SIMONDS.J Division of Emergency Preparedness ip 15788'304. 24X Fichs 50-341,82/09/23 8210250195
- --8210250198 "Evaluation of Evacuation Time Estimate "
  \* Texas A & M Univ 82/09/23 ip 15788 305 24x
  Fiche.50-341,82/09/23,8210250195
- 8210130284 Forwards maps documenting location of NRC monitoring stations consisting of 3B offsite environ TLDs deployed around facility W/o encl.

  KREUGRR.E. Detroit Edison Co. 82/09/24. OEBTMANN.M J Region 3. Office of Director ip. 15678 263 24X Fichs.50-341,82/09/24,8210130284.
- O Adjudicatory correspondence
- B2100400B2 Forwards NRC response to Citizens for Energy & Employsent B20904 answer. Name inadvertently omitted from Certificate of Bvc W/o encl.

  MODDHEAD, C. F. Hearing Branch 1. B2/09/30 MINOCK, J. Minock, J. MINOCK, J. Citizens for Energy & Employment. ip 15581: 266 241 Fiche: 50-341, 82/09/30, 8210040082
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8210010287 Forwards Amend 44 to application for OL, consisting of Aerni 44 to FSAR.
  LANDORAF.L C. LeBosuf, Lamb, Leiby & MacRas. LANDORAF.L C Dstrop Edison Co. 82/09/30. DENTON:H R. Offics of Nuclear Reactor Regulation. Director. 1p. 15573.187. 24X Fiche:50-341.62/09/30.8210010289
- --8210010275 Amend 44 to application for OL HEIDEL, C. M. Detroit Edison Co 82/09/28 ip. 15573, 168 241 Fiche. 50-341, 82/09/30, 9210010289.
- --8210010297 Amend 44 to FBAR \* Detroit Edison Co. 82/09/30, 80pp 15573:189 24X Fiche: 50-341, 82/09/30, 8210010289.

# DOCKETED ITEMS

Applient Committee on Reactor Bafeguards reports & correspondence

10270398 Comments on analyses evaluating capability of facility bloogical shield to withstand asymmetric loadings resulting from double ended pips broak at reactor vessel notile safe makes per 701023 & 1204 requests 100A85, Z. Franklin Institute/Franklin Research Center ZUDANS, ACSS - Advisory Committee on Reactor Safeguards 80/05/30 ALDERMANK ACSS - Advisory Committee on Reactor Safeguards 1832 348 24X Fiche 50-341,80/05/30,8210270398

inspection reports. IE Bulletins & correspondence

- 10010456 Forwards "Inservice Testing Program" for pumps & valves for 120-month insp period beginning w/fuel load per 100FR50 55a Rept supersedes Revision O submitted w/810803
- TABBER H Detroit Edison Co. 02/09/22 KINTNER L L Division of Licensing | p | 19570 011 | 24% Fichs, 50-341,82/09/22,8210010456
- 8210010460 "Inmervice Testing Program" (LAMBS-JH , MARTIN-JB NUTCCH (Nuclear Technology, Inc.) DET-16-0201 RO1 82/07/08. 161pp 15570:012 24X First 50-341,82/09/22/8210010456
- 10130368 Forwards IE Insp Rept 50-341/82-11 on 620721-23 & 27-30 No noncompliance noted LITICE 8 B Division of Engineering & Technical Programs 82/09/27. IELLS DA Detroit Edison Co 2pp 15482:100. 24X Fichs 50-341, 82/09/27, 8210130368
- 0210130374 IE Insp Rept 50-341/82-11 on 820721-23 & 27-30 No noncompliance noted Major areas inspected 10CFRSO 55e repts. electrical hanger reinsp. GA records. relay coordination activities & deviation disposition request MATOU.K R., WILLIAMS.C C. Region 3, Office of Director 82/09/10 11pp 15682 102 24X Fiche 50-341,82/09/27,8210130368
- 210190303 Bubmits list of tubes plugged in each steam generator Collowing inservice inspa CROUSE, R P Yoledo Editon Co 82/10/04 KCPPLER, J. Q Region 3, Office of Director ip 15742 158 24X Fiche 50-341,82/10/04, 6210190303
- 208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L. Division of Fuel Facilities, Materials & Gafeguards, 82/16/06 Censolidated Edison Co of New York, 66pp, 15761:250, 24X Fichs 50-900-82/10/06,8208190233
- 2001301BA Clarifies NRC position concerning procedures for admitting MRC personnel to facility Lists of authorized personnel
- ent. KEPPLER, J.O. Region 3, Office of Director, 82/10/06 WELLB, D. A. Detroit Edison Co. 4pp. 15674 137 24X Fiche 50-341, 82/10/06, 0210130186
- 210250072 Forwards IE Insp Rept 50-341/82-12 on 820701-0831 & notice of violation. BRESSARD, R. L. Division of Project & Resident Programs HELLS, D. A. Detroit Edison Co. 2pp. 15789 341 24X Fichs. 50-341, 82/10/07, 8210250072 R2/10/07.
- -8210250075 Notice of violation from insp on 820701-0831 SPESBARD.R L. Division of Project & Resident Programs. 82/10/07. 2pp 15787-343 24X Fiche 50-341,82/10/07,8210250072
- -8210230080 IE Insp Hept 50-341/82-12 on 820701-0831 Noncompliance noted failure to accomplish activities per GA procedure to provide appropriate procedure & to perform resudit to verify corrective action implementation.
  LITTLE.B H , KONKLIN-J E Division of Project & Resident Progrems 82/10/07 7ap. 19789.345. 24X Fiche: 50-341,82/10/07,8210250072
- 210150322 Forwards responses to IE Bulletin 79-15, "Long-Term Operability of Deep Draft Pumps." Responses will be incorporated in FBAR amend Related procedures also encl. TAVEER: H Detroit Edison Co 82/10/11 KINTNER: L. Office of Nuclear Reactor Regulation, Director 8pp 15702:001 24X Fiche: 50-341, 82/10/11,8210150322.
- -8210150326 "Goulds Pumps, Inc Type I Menual, Emergency Equipment Byc Water Pumps " \* Coulds Pumps, Inc 77/07/14, 53pp 15702,009 24X Fiche 80-341,82/10/11,8210150322
- -8210150330 "Coulds Pumps: Inc Type I Manual: Diesel Generator Svc Water \* Goulds Pumps. Inc 77/11/22 91pp. 15702-062. 24X Fiche: 50-341, 82/10/11. 8210150322.

- --8210150335 "Instruction Manual, RHR Byc Water Pumps, Enrico Fermi Atomic
- --8210150343 "Seismic-Stress Analysis of ASME Section III Class 3 Pumps "
  + McDonald Engineering Analysis Co ME-227 75/09/03 54pp
  15702.209. 24 Fiche 50-341.82/10/11.8210150322
- --8210150346 "Selemic-Stress Analysis ASME Section III Class 3 Pumps "
  \* McDonald Engineering Analysis Co ME-230 75/09/03 56pp
  18702 244 244 Fichs 30-241, 82/10/11, 82101503922
- ---8210150352 "Belamic-Stress Analysis Rept RHR Syc Water Pumps " \* McDonald Engineering Analysis Co. ME-146 74/01/28 40pp 15702 320 24X Fiche 50-341,82/10/11:8210150322
- 8210190696 Ciarifies check valve info re inservice insp of pressure isolation valves:psr 810603 ltr Design features provide better protection than check valve position monitoring for sys Info will be included in future FBAR amend TAUBER:H Detroit Edison Co 82/10/11 KINTNER:L L Division of Licensing 2pp 15736 198 24X Fiche 50-341.82/10/11.8210190696
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants "Svc list encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement. 82/10/14 Consolidated Edison Co of New York 115pp. 15810-125 24X Fiche 50-000,82/10/14.8208190238
- 8210260372 Ack receipt of 820924 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-341/82-08 NORELIUS, C E. Division of Project & Resident Programs 82/10/18 HELLB, D. A. Detroit Edison Co ip 15804-233 24X Fiche 50-341,82/10/18,8210260372
- --B2102603B2 Responds to NRC 820B10 ltr re violations noted in IE Imap Rept 50-341/82-08 Corrective actions snubber reduction program accepted & implemented on 820609. All documentation forwarded to NRC upon completion HELLS, D A Detroit Edison Co 82/09/24. BPESBARD, R L Division of Project & Resident Programs 5pp 15804-234, 24% Fiche 50-341,82/10/18,8210260372
- 8 Reportable occurrences, LERs & related correspondence
- B210040127 Interim deficiency rept re defective 1-inch pips couplings & caps mfg by Capital Mfg Co Initially reported on 820810 Installed couplings will be given visual insp & liquid penetrant exam Next rept expected by 830107 WELLS, D. A Detroit Edison Co. B2/09/09 KEPPLER, J O Region 3, Office of Director. 2pp 15581 210. 24X Fichs 50-341,82/09/09,8210040127.
- 8210040084 Interim deficiency rept re load-carrying capability of certain drywell structural steel Intially reported on 820084, fix involving reinforcing of affected members considered. Interim or final rept expected by 820120 MELLS, D. A. Detroit Edison Co. 82/09/22 MEPPLER, J. G. Region 3, Office of Director. ip. 1958: 265. 24X Fiche: 50-341, 82/09/22, 8210040084.
- B210190332 Final deficiency rept re cracking of 3/4-inch carbon steel pipe. Initially reported on B20430. Manufacturer installed eddy current tester to aid in GC of pipes. Faulty sections of pipe replaced HELLS, D. Detroit Edison Co. 82/09/24. KEPPLER. J. G. Region G. Office of Director. 3pp. 15742:088. 24% Fiche: 50-341,82/09/24,8210190332
- B210190657 Interim deficiency rept re defective pipe support strut suivel bearings. Initially reported on B20514.Add1 inspectors will be developed per IE Circular 81-05 Next rept will be submitted by 820204. HELLB, D. A. Detroit Edison Co. B2/10/08 KEPPLER, J. Q. Region 3, Office of Director. 2pp 15737 147. 24X Fiche 50-341,82/10/08,82/0190657.
- 8210250191 Final deficiency rept re stainless steel piping 8A 312TP316 & 8A 312TP316HF installed in lieu of required 8A 312TP316L. Initially reported on 820317 Deviation disposition requests written No instrument sample lines affected. MELLS,D.A. Detroit Edison Go 82/10/12 KEPPLER.J.O. Region 3, Office of Director. 2pp. 15788.298. 24X Fiche.30-341,82/10/12,8210250191.

#### DOCKET 50-344 TROJAN NUCLEAR PLANT

- F Security, medical, emergency & fire protection plans
- 8210070012 Requests concurrence u/plan to issue license amend incorporating encl license condition re implementation of UB/IAEA sefeguards agreement Notification of Info desired to be withheld requested within 30 days Encls withheld CLARK.R A Operating Reactors Branch 9 82/09/24 WITHERS.B D Portland General Electric Co 3pp 15646 223 24X Fiche 50-344.82/09/24.8210070012
- B210190020 Releases public version of revision to radiological emergency response glan implementing procedure FELTON.JM Division of Rules and Records. B2/10/01 Document Management Branch ip 15761:001 24X Fiche 50-344.82/10/01.
- ---8210190024 Forwards public version of Revision 3 to Rediological Emergency Response Plan Implementing Procedure EP-7. "Operation of Technical Support Ctr" Receipt form encl. PUZEY, A M Portland General Electric Co 82/09/22 CLARK, R A Office of Nuclear Reactor Regulation, Director ip 15761 002 24X Fiche 50-344,82/10/01.8210190020
- --8210190026 Public version of Revision 3 to Radiological Emergency Response Plan Implementing Procedure EP-7. "Operation of Tachnical Support Ctr" YUNDT.C P Portland General Electric Co 82/09/20. 28pp 18761 003 24X Fiche 50-344,82/10/01.8210190020
- 8210280210 Forwards request for addl info re changes to physical security plan & safeguards contingency plan in response to 820719 itr Encl withheld (ref 100FR73 21).

  CLARK,R A Operating Reactors Branch 3 82/10/26 HITHERS, 8 D Portland Operal Electric Co ip 15837 106 24X Fiche 50-344, 82/10/26, 8210280210

## P Operating license stage documents & correspondence

- 8210010053 Forwards systematic assessment of licenses performance data package to be used in preparing performance analyses Analyses should be prepared following format of encl NRC App OB16,Part VI. Section IV Analyses due 821008 STERNBERO, D H Division of Resident, Reactor Project & Engineering Programs 82/09/24, JOHNSON.P H: MALIROS: M H; CILLIS, M Region 5, Office of Director 18pp 15565 119 24X Fiche 50-344,82/09/24, 2210010053
- B210040163 Advises that containment hydrogen monitors installed & calibr for hydrogen concentrations betwen 0 & 10% per TMI Action Item II F. I. Main steam line monitors installed, however, calibr delayed until 921101 due to repairs.

  WITHERS, B D Portland General Electric Co 82/09/28, EISENHUT, D Q Division of Licensing 2pp 15582.032 24% Fiche 50-344,82/09/28,8210040163
- 8210150354 Bummary of B20928-30 meeting & site visit w/util & Bechtel re masonry wall design Addl info requested re in-plane response effects on out-of-plane responses & documentation of verification of programs
  TRAMMELL.C M Operating Reactors Branch 3 82/10/05 Operating Reactors Branch 3, 5pp. 15715.353 24X Fiche.50-344,82/10/05,8210150354

#### G. Inspection reports. IE Bulletins & correspondence

- 8210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines. App A documents provided in R Udell FOIA Request 81-313. Forwards documents listed in App B.
  FELTON.J. M. Division of Rules and Records. 82/09/10. LDNG, D. J. Winthrop, Stimson, Putna & Roberts 9pp 15645:063. 24X Fiche. 50-000, 82/08/10.8210070007.
- --B210070139 Forwards tabulated data on steam generator insp & maint at facilities. Data should be provided to licensees.

  IPPOLITO,T. Operating Reactors Assessment Branch. 82/04/01.

  VAR9A:8 Operating Reactors Branch 1 5pp 15645:131. 24X

  Fiche: 50-000, B2/08/10, 8210070007
- 8210130597 Ack receipt of 820908 ltr forwarding payment of civil penalty imposed by NRC 820812 order AXELRAD. A. Director's Office. Office of Inspection and Enforcement. 82/09/17. WITHERS B.D. Portland General Electric Co. 2pg 15692:343 24X Fiche.50-344.82/09/17.8210130597.

- 8210010053 Forwards systematic assessment of licensee performance fata package to be used in preparing performance analyses Analyses should be prepared following format of encl NRC App 0516.Part VI. Section IV Analyses due 821008 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/09/24 JOHNSON, P H. MALTROS.M H., CILLIG.M. Region 5, Office of Director 18pp 15565 119 24X Fiche 50-344.82/09/24.
- H210190549 Forwards IE Insp Rept 50-344/82-21 on H20712 No nancompliance noted STERNBERG, D M Division of Resident, Reactor Project & Engineering Progrems B2/10/01 WITHERB, B D Portland General Electric Co 2pp 15735 001 24% Fiche 50-344, 82/10/01, B210190549
- --8210190556 IE Insp Rept 50-344/82-21 on 820712 No noncompliance noted Major areas inspected program for welding pressurier surge line ECKHARDT. J H. DODDS.R T Division of Resident, Reactor Project & Engineering Programs 82/10/01 3pp 15735 003 24X Fiche 50-344,82/10/01.8210190549
- 8210080249 Ack receipt of 820923 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-344/82-24 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/10/05 WITHERS, B D Portland General Electric Colp 15638 093 24X Fiche 50-344.82/10/05.8210080249
- --B2100B0253 Responds to NRC 820903 ltr re violations noted in [E lmsp Rept 50-344/82-24 Corrective actions maint procedures revised to reflect change from motor to air operators on four auxiliary feedwater pump steam supply valves WITHERB: B D Portland General Electric Co 82/07/23 ENOELKEN.R H Region 5, Office of Director 4pp 15638 094 24: Fiche 50-344.82/10/05.8210080249
- 8208190233 IE Info Notice 80-35, Suppl 1: "Leaking & Dislodged I-125 implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards. B2/10/06 Consolidated Edison Co of New York 66pp 13761: 250 24X Fich: 50-000, 82/10/06, 8208190233
- 921019073; Forwards IE Insp Rept 50-344/82-26 on 820809-9903 & notice of violation CREMS, J. . Division of Resident, Reactor Project & Engineering Programs 82/10/06 WITHERS, B.D. Portland General Electric Co 2pp 15737 065 24% Fiche 50-344, 82/10/06, 821019073;
- ---8210190733 Notice of violation from insp on 820809-0903 DDDDB,R.T Division of Resident, Reactor Project & Engineering Programs 82/10/06 2pp 15737 067 24X Fiche 50-344,82/10/06, 8210190731.
- --B210190743 IE Insp Rept 50-344/82-R6 on 820809-0903 Noncompliance noted sefety injection sys actuation logic inoperable from 820818-R0 MALHROSAN H, DODDS.R T. Division of Resident, Reactor Project & Engineering Programs 82/09/16 7pp 15737-069 24X Fiche 50-344,82/10/06,8210190731
- B210290413 Forwards safety evaluation of licensee 800430 & 920317 responses to IE Bulletin 80-04. "Analysis of PMR Main Bteamline Break M/Continued Feedwater Action " Licensee responses acceptable CLARK.R A Operating Reactors Branch 3 82/10/07 WITHERS & D Portland General Electric Co 2pp. 15863 241 24X Fiche. 50-344. 82/10/07. 9210270413
- --B210290417 Bafety evaluation accepting licensee 800430 & B20317 analyses of main steamline break w/continued feedwater action No further action re IE Bulletin 80-04 required.

  \* Office of Nuclear Reactor Regulation, Director 82/10/07 7pp 15862-243. 24% Fichat 50-344-82/10/07.8210290413
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants." Svc list encl.
  DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement, 82/10/14 Consolidated Edison Co of New York
  115pp 15810:125, 24X Fiche 50-000, 82/10/14, 8208170238
- S. Reportable occurrences, LERs & related correspondence
- 8210250084 Forwards LER 82-018/03L-0 Detailed event analysis enci. YUNDT.C P., STEELE,R.L. Portland General Electric Co. 82/10/11. ENGELKEN,R H. Region 5. Office of Director 3pp. 15787:077 241 Fiche. 50-344, 82/10/11, 8210250084

- -\$210250093 LER 82-018/03L-0 on 820918, during normal operation, steam pressure transmitter PT-524 on steam generator B failed high: causing associated protection sys bistable to trip & steam flow instrument FI-522 to fail high Cause unknown SAtR.0 0 Portland General Electric Co 82/10/11 Region 5, Office of Director ip 15787 080 24% Fiche 50-344,82/10/11, B230250084
- 4210250164 Forwards LER 92-017/03L-0 Detailed event analysis ently YUND7.0 P. BTEELE,R L. Portland General Electric Co. 82/10/11 ENGELKEN.R H. Region 5. Office of Director 3pp. 15787-330, 24X Fichs 50-044, 82/10/11, 8210250164
- -B210250175 LER B2-017/03L-0 on B20916, boron concentration in north borst acid storage tank decreased below Tech Boec level Caused by dilution due to two leaking valves South tank Level raised above BTS limit Valves repaired BAIR:0 0 Portland General Electric Co B2/10/11 Region 5, Office of Director in 15787 333 24X Fiche 50-344,82/10/11,8210250164
- Security, dedical, emergency & fire protection plans
- 3210070003 Releases public version of revised administrative memo & revised emergency plan supporting procedures
  FELTON.JH Division of Rules and Records 82/09/17 Document
  Management Branch 1p 19646 222 24X Fiche 50-346,82/09/17,
  8210070003
- --8210070005 Forwards public version of Revision 17 to Administrative Memo 42-17. "Rediation Monitoring Teams" & Revision 150 to managency plan supporting procedures index Receipt form entl

  Toledo Edison Co 62/09/08 NRC No Detailed Affiliation Given 1p 15646 218 24% Fiche 50-346,82/09/17,8210070003
- --8210070006 Public version of Revision 17 to Administrative Memo 42-17, "Radiation Monitoring Teams" & Revision 150 to emergency plan supporting procedures index MURRAY: TD Toledo Edison Co 82/09/30 2pp 15646,219 24X Fichs 50-346,82/09/17,8210070003
- B210050235 Requests add1 info re intended use of drawings & reactor safeguards program prior to submittal of info requested in 920924 ltr Request appears to duplicate Sandia Nat1 Labs program
  CROUSE.R P Toledo Edison Co 82/09/28 STOLZ, J F Operating Reactors Branch 4 1p. 15609 052 24X Fiche 50-346,82/09/28, 8210050235.
- 8210250286 Forwards IE Safety Evaluation Rept 50-346/82-26 on 820901-30 No noncompliance noted H1NO.JA Division of Emergency Preparedness & Operational Support 82/10/07 CROUSE, RP Toledo Edison Co 2pp 15791, 106 24X Fiche 50-346, 82/10/07, 8210250286
- --8210250297 IE Safety Evaluation Rept 50-346/82-26 on 820901-30 No moncompliance noted Major areas inspected site emergency plan PLOSKI, T J , AXELSON, W L , PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 82/10/06 37pp 15791 108 24X Fiche 50-346.82/10/07.8210250286
- 8210190623 Forwards revision to Industrial Security Plan AD 1808
  Revision withheld (ref 100FR2 770)
  CROUSE, R P Toledo Edison Co 82/10/12 STOLZ, J F Operating
  Reactors Branch 4 ip 15739, 360 24% Fiche 50-346, 82/10/12,
  8210190623
- P Operating license stage documents & correspondence
- S210210348 Confirms 620716 telephone authorization of amend to License NPF-3 by adding one-time note to Tech Spec Table 4 3-11 resteam & feedwater rupture control sys instrumentation aurveillance requirements
  LAINAB.0 C Assistant Director for Operating Reactors, 82/09/20, CROUSE.R.P. Toledo Edison Co 2pp 15784:274 24X Fichs 50~346,82/09/20,8210210548
- --8210210550 Amended Tach Spec Table 4 3-11 re steam & feedwater rupture control sys instrumentation surveillance requirements.

  4 Assistant Director for Operating Reactore 82/09/20 1p. 13784 278 24X Fiche 50-246, 82/09/20, 8210210548
- -- B210210353 Safety evaluation supporting change to Tech Spec Table 4 3-11 re steam & feedwater rupture control sys instrumentation surveillance requirements LAINAS, 9 C Assistant Director for Operating Reactors. 82/09/16, 1p. 15784: 279 24X Fiche: 50-346, 82/09/20, 9210210548

- --8210210556 Application for smergency change to Tech Spac Table 4, 3-11, extending steam line pressure low switch surveillance period by 94-h. until midnight 820916 Safety evaluation encl PETERS.R F Toledo Edison Co. 82/09/17 DEADAZIO, A Office of Nuclear Reactor Regulation, Director 2pp 15784 280 24X Fichs 50-346, 82/09/20.8210210548
- --8210210559 Proposed change to Tech Spec Table 4 3-11, extending steam line pressure - low switch surveillance period by 96-h, until midnight 620916 \* Toledo Edison Co 82/09/17 ip 15784 282 24X Fiche 50-346,82/09/20.6210210548
- 8210120001 Requests add1 info re secondary water chemistry monitoring & control by 821108 Info pertains to 791003 proposed amend to delete existing Tech Spec on secondary water chemistry & incorporate model license condition
  870LZ.JF Operating Reactors Branch 4 82/09/22 CRQUSE.R P Toledo Edison Co 4pp 15689 183 24X Fiche.50-346.82/09/22, 82/0120001
- 8210040049 Informs that Class IV fee should be submitted for final review of 820715.30,0806 to is submitted to 10088 R to License Fee Management Branch. 82/09/23 CRGUSE, R P Toledo Edison Co. ip 15577 292 24X Fiche 50-346.82/09/23.8210040049
- 8210180025 Requests review of enci Franklin Research Ctr draft technical evaluation rept prepared on util 820101 responses to request for info re NUREC-0612. "Control of Heavy Loads at Nuclear Power Plants"

  DE AGAZIO.A W Operating Reactors Branch 4 82/09/23 CROUSE.R P Toledo Edison Co. 2pp 15717 278 24X Fiche 50-346.82/09/23. 8210180025
- --8210180026 "Control of Heavy Loads (C-10). Toledo Edison Co. Davis-Besse Nuclear Power Station, Unit 1, " draft technical evaluation rapt BOMBERGER.C Franklin Institute/Franklin Research Center. NRC-03-79-118 TER-05287-530 82/08/27 CLEMENSON, F NRC - No Detailed Affiliation Given, 38pp 15717 280 24X Fiche 50-346, 82/09/23-8210180025
- 8210050304 Responds to 820727 itr re NUREO-0737.Item II X 2 10. "Anticipatory Reactor Trip Bys (ARTB) " Adaquate features available to alert operator to remove bypass when automatic bypass removel not required CROUSE, R F Toledo Edison Co 82/09/27 STOLZ, J F Operating Reactors Branch 4 2pp. 15510 266 24X Fiche 30-344, 82/09/29, 8210050304
- 82:0050333 Advises that schedule for responding to NUREO~0737. Item II B.3. "Post-Accident Sampling Sys:" will be provided by Mar 1983. In response to 820721 request CROUSE.R.P. Toledo Edison Co. 82/07/27 870L7.J F. Licensing Branch 4. ip. 15610 094 24X Fiche 50-346.82/09/29.8210050333
- 8210050310 Forwards application to amend License NPF-3, revising Tech Spec Table 4 3-11 re steem & feedwater rupture control sys instrumentation surveillance requirements CROUSE, R. P. Toledo Edison Co. 82/09/30. BTOLZ, J. F. Operating Reactors Branch 4 ip 15601:352 24X Fiche 50-346,82/09/30, 8210030310
- --8210050313 Application to amend License NPF-3, revising Tach Spac Table 4.3~11 re steam & feedwater rupture control sysinstrumentation surveillance requirements. CROUSE, R P Toledo Edison Co. 82/09/30 ip. 15601,353, 24X Fiche 50-346,82/09/30.8210050310
- --8210050318 Proposed revision to Tech Bacc Table 4 3-11 re steam & feedwater rupture control sys instrumentation surveillance requirements. Safety evaluation encl \* Yoledo Edison Co 82/09/30 3pp 15401 354 24X Fiche 50-344,82/09/30.8210050310
- 8210150519 Discusses NRR actions taken under Task Interface Agreement 82-20 for steam generator auxiliary feedwater header damage. Licensee authorized to resume power operation at Ocones 3.

  EISENHUT, D © Division of Licensing 82/10/06 DLBHINSKI, J Division of Engineering & Technical Programs. 1p 15717.261 24x Fiche: 50-000, 82/10/06, 82/0150519.
- 8210180135 Forwards fee for review of once through steam generator repairs & auxiliary feedwater sys mods.
  CROUSE.R.P Toledo Edison Co. 82/10/08 MILLER, W.D. License Fee Management Branch. 2pp. 15719 338. 24X Fiche 50-346, 82/10/08, 8210180135.

- 8210210225 Responds to 810629 ltr stating that no license amend application needed to incorporate model Tech Base for snubber surveillence Response unacceptable since ANSI/ABME OM-4 not completed Amend requested STOLZ.JF Operating Reactors Branch 4 82/10/13 CROUSE.R P Toledo Edison Co 2pp 15774 339. 24X Fiche 50-346.82/10/13.8210210225
- 8210270317 Advises that proposed Tech Spec changes requested by 800410 itr not received Model Tech Specs re definition of term "operable-operablity" forwarded Proposed Tech Spec changes requested by 821108
  STOLL.JF Operating Reactors Branch 4 82/10/13 CR0UBE.R P Toledo Edison Co 2pp 15836 352 24X Fiche 50-346.82/10/13.8210270319
- --B210270325 Model Tech Specs re definition of term "operableoperability" & limiting conditons for operations & associated bases Time to place plant in hot standby relaxed to 6-h & cold shutdown within subsequent 30-h \* Operating Reactors Branch 4 B2/10/13 3pp 15836 354 24X Fiche 30-346,82/10/13,8210270319
- B210270372 Forwards Amend 46 to License NPF-3, safety evaluation & notice of issuance & availability Amend permits one-time extension to surveillance period for steam line pressure-low instrument STOLZ, JF Operating Reactors Branch 4 82/10/13 GROUSE, R P Toledo Edison Co. 2pp. 15834 250 24X Fiche 50-346, 82/10/13, poin0270372
- --8210270382 Amend 46 to License NPF-3, permitting one-time extension to surveillance period for steam line pressure-law instrument STOLZ, J F Operating Reactors Branch 4 B2/10/13 4pp 15834 253 24X Fiche 50-346.82/10/13.8210270372
- --8210270386 Bafety evaluation supporting Amend 46 to License NPF-3.

  \* Office of Nuclear Reactor Regulation, Director 82/10/13 6pp 1884 258 24X Fiche 50-246, 82/10/13, 8210270372
- --82102703B7 Notice of issuance & availability of Amend 46 to License NPF-3 STOLZ.J.F Operating Reactors Branch 4 82/10/13 2pp 15834 261 24X Fiche 50-346,82/10/13.8210270372
- 9210210458 Forwards, under separate cover-application for amend to License NFF-3 Amend increases setpoint margin for power-operated relief valves, revises bases on auxiliary feedwater sys & alters trip setpoints to account for instrument arror CROUSE.R P Toledo Edison Co 82/10/14 STOLE.J F Operating Reactors Branch 4 18pp 15763 047 24% Fithe 50-346,82/10/14,82/0210458
- 8210260283 Application to amend License NPF-3, revising Tech Specs to reflect changes to setpoints for pressurizer electromatic relief & code safety valves, auxiliary feedwater sys & trip setpoints for borated water storage tank level MURRAY, T.D. Toledo Edison Co. 82/10/14 STGLZ, J.F. Operating Reactors Branch 4 18pp. 15803, 124 24% Fiche 50-346, 82/10/14, 82102A0289
- 8210220013 Responds to 820713 ltr requesting implementation schedule for mods to ECCB evaluation models Mods will be undertaken as extension of NURSO-0737. Item II K 3 31. Schedule will be provided 60 days after NRC approval of Item II K 3.30. CROUSE: R. P. Toledo Edison Co 82/10/19 NOVAK.T M Assistant Director for Operating Reactors Ip 15778 210 24X Fiche: 50-346, 82/10/19, 8210220013
- 8210290378 Forwards Amend 48 to License NPF-3, safety evaluation & notice of issuance & availability Amend changes calculational method to determine max allowable high flux trip setpoint when one or more safety values inoperable DE AGAZIG, A W Operating Reactors Branch 4, B2/10/20, CROUSE, R. P. Toledo Edison Co. 2pp 15865: 247 24X Fiche: 50-346, 82/10/20, 8210290378.
- --B2102903B2 Amend 4B to License NPF-3, reflecting change in calculational method for determining max allowable high flux trip setpoint when one or more tafety valves on steam generator inoperable.

  BYOLZ. JF Operating Reactors Branch 4 B2/10/20. 7pp. 15865 252, 24X Fiche: 50-346.82/10/20,8210290378
- --8210290385 Safety evaluation supporting Amend 4B to License NPF-3 \* Office of Nuclear Reactor Regulation Director 82/10/20, 3pp 15863 259 24% Fiche: 50-344, 82/10/20, 8210290378
- ---8210290387 Notice of issuance & availability of Amend 48 to Licensa NPF-3 STGLZ:J,F Operating Reactors Branch 4 82/10/20. 2pp. 15865 262. 24X Fiche: 50-346:82/10/20:8210290378

- 8210260268 Responds to NRC 821007 ltr requesting confirmation that manual valves used to isolate air start motors & fuel supply of emergency dissel generators during maint are controlled by locked valve procedure Procedure AD 1839 02 applicable CROUSE, P Toledo Edison Co 82/10/21 8TOL.7. J Dermating Reactors Branch 4 1p 15805 221 24X Fiche 50-346.82/10/21.
- Q Inspection reports, IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
  FELTON.J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X
  Fiche 80-000, 82/07/12, 8210080015
- --B21008012B Bystematic assessment of licensee performance notes re facility systuation for Nov 1979-Dct 1980 \* NRC - No Detailed Affiliation Given B0/10/30 15pp 15647 334 24% Fiche 50-000, 82/07/12, 8210080015
- 8210060314 Responds to IE Bulletin 81-01, "Burveillance of Mechanical Bubbers " Bnubbers inspected during recently completed refueling outage Nine snubbers identified as nonconforming CROUSE, R P Toledo Edison Co 82/09/14 KEPPLERIJ O Region 3, Office of Director. 6pp 15619 216 24X Fiche 50-346,82/09/14,8210060314
- 8210030253 Ack receipt of 820708 ltr informing NAC of steps taken to correct violations noted in IE Insp Rept 50-346/82-18
  BTREETERJ F Division of Project & Resident Programs BP/09/24
  CROUSE:R P, Toledo Edison Co 1p 15610 291 24X
  Fiche 50-346,82/09/24,8210050253
- --8210050258 Responds to NRC 820810 ltr re-violations noted in IE fing Rept 50-346/82-18 Corrective actions operations supervisor discussed event wishift supervisors stressing importance of strict procedure compliance to review of locked value status CROUSE.R P Toledo Edison Co 82/09/08 STREETER.J F Division of Project & Resident Programs 2pp 15410 292 24X Fiche 50-346,82/09/24,8210050253
- 8210080285 Ack receipt of 820907 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-344/82-03 NORELIUS.C E Division of Engineering & Technical Programs 82/10/04. CROUSE.R P Toledo Edison Co ip 15638 315 24X Fiche 50-344,82/10/04.8210080285
- --8210080288 Responds to NRC 820816 ltr re violations noted in RE Inta Rept 50-346/82-03 Corrective actions GA program will be updated to include review of regulatory requirements be commitments CROUSE: R P. Toledo Edison Co 82/09/07 NORELIUS, C E Official Programs 2pp 15638 316 24X Fichs 50-346,82/10/04,8210080285
- 8208190233 IE Info Notice 80-35, Suppl 1. "Leaking & Disladges [-125 Implant Beeds," Svc list encl.
  COBB.L.I. Division of Fuel Facilities, Materials & Safeguerds 82/10/06 Consolidated Edison Co of New York 66pp. 15761 250 24X Fiche 50-000, 82/10/06, 8208190233
- 8210250286 Forwards IE Befety Evaluation Rept 50~346/82-26 on 820901-30 No noncompliance noted HIND J A Division of Emergency Preparedness & Operational Bupport 82/10/07 CRUMBER P Toledo Edison Co 2pp. 15791-106 24X Fiche 50-346,82/10/07,8210250286
- --8210250297 IE Safety Evaluation Rept 50-346/82-26 on 820901-30 No noncompliance noted. Major areas inspected. sits emergency plan.
  PLOSKI.T J , AXELSON.W L , PAPERIELLO.C J Division of Emergency Preparedness & Operational Support. B2/10/06 37pp 15791 106 24X Fiche: 50-346/B2/10/07,B210250286
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Syspiping at BMR Plants " Syc list encl DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 13810 125 24X Fichs. 50-000, 82/10/14,8208190238
- 8 Reportable occurrences, LERs & related correspondence
- 8012290118 Discusses conclusions of engineering evaluation of steen generator overfill transients at C-E & Westinghouse plants LANNING D Director's Office 80/10/29, MICHELSON, C Director's Office 3pp. 15692,262 24X Fiche 50-000:80/10/29.8012290188

- e21CO70115 Discusses LER 79-062/03L-1 re auxiliary feedwater sys prassure suitches On 790321.several suitches would not activate Failure caused by corrosion due to misapplication of static O ring suitches C+ERAMAL.M Director's Office 81/12/07 MICHELSON, C Director's Offace 3pp 15649-216 24X Fiche 50-346,81/12/07,8210070115
- \$210070940 Concludes that problem of misapplication of static O ring disphragm-type switches is indigenous to Davis-Besse plant Corrective action to replace Buna-N switches w/stainless steel switches adequate CHIRAMALM Director's Office 81/12/07 HICHELSON, C Director's Laffice 3pp 15644 341 24X Fiche 50-344, 81/12/07, 8210070460
- 3210-010008 Respands to FOIA request for 19 categories of documents respectively related to App A FELTON. J M Division of Rules and Records 82/06/28 UDELL.R A. Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82/06/28.8210010008
- --BilliB0001 Recommends comprehensive assessment of plant operating conditions to determine specific predetermined time related sequences of occurrence to emergency buses SRP should be revised re design features

  ASHE.F Director's Office 81/10/16 MICHELBON.C. Director's Office 4pp 15731 049 24X Firme 50-000:82/04/28.8210010008
- --B201190538 Evaluates LER 79-062/03L-1 re auxiliary feedwater sys pressure switches Misapplication of static D-ring diaphragm type sustches was limited to facility Replacement w/stainless steel diaphragm switches seems adequate CHIRAMAL M Director's Office 81/12/07 MICHELBON, C Director's Office 3pp 65825 291 24X Fich# 50-000,82/06/28, B210010008
- 8210050323 Forwards LER 82-041/03L-0 MURRAY.T D Toledo Edison Co 92/09/22 KEPPLER.J Q Region 3. Office of Director 19 15608 221 24% Ficha 50-346.82/09/22, 8210050323
- --8210050327 LER 82-041/03L-0 on 820821, setpoints of three main steam safety valves found out of tolerance Caused by normal valve aging four valves immediately reset & third valve adjusted at reduced main steam pressure.

  D'REILL.J Toledo Edison Co 82/09/23 Region 3. Office of Director 3pp 15608 222 24X Fiche 50-346,82/09/22,8210050323.
- B210050355 Forwards LER 82-042/03L-0 MURRAY.T D Tolede Edison Co B2/07/24 KEPPLER.J O Region 3 Office of Director ip 13609 042 24X Fiche 50-346,82/07/24, B210050335
- --B210050361 LER 82-042/03L-O on 820827, once-through steam generator 1 fevel exceeded Tech Spec limit on full-range instrumentation Caused by operator error during plant shutdown on 820823 Operators cautioned Toledo Edison Co 82/09/24 Region 3, Office of Director 3pp 13509 043 24X Fiche 50-346,82/09/24,8210050335.
- 8210130356 Forwards LER 82-031/03X-2 MURRAY.T D Toledo Edison Co 82/09/28 KEPPLER, J O Region 3, Office of Director 1p 15479 012 24X Fiche 50-346,82/09/28, B210130356
- --8210130366 LER 82-031/03x-2 on 820625 & 0706. fire barrier doors 500 & 426 found slightly open On 820629, fire barrier & negative pressure door 302 found slightly open. Caused by closure mechanism failure to seat doors tightly due to design error. MOLFE, R Toledo Editon Co 82/09/28. Region 3, Office of Director 2pp 15679 013 24X Fichs. 50-346, 82/09/28, 8210130356
- 8210130404 Forwards LER 82-043/03L-0
  MURRAY, T D Toledo Edison Co 82/09/29, KEPPLER, J Q Region 3,
  Office of Director ip 15681 164 24X Fiche, 50-346,82/09/29,
  8210130404
- B210130124 Forwards LER 82-044/03L-0 BURRAY, T D Toledo Edison Co 82/09/30 KEPPLER, J G. Region 3, Office of Director ip 15673 040 24x Fiche, 50-346, 82/09/30, 8210130124

- --8210130128 LER 82-044/03L-0 on 820916, review revealed that steam & feedwater rupture control sys monthly surveillance Procedure ST 5031.14 not completed in time allotted in Tech Specs Caused by personnel error Test completed HERNER, B U Toledo Edison Co 82/09/30 Region 3, Office of Director 3pp 15573 041 24x Fiche 50-346-82/09/30.8210130124
- 8210180131 Forwards LER 82-045/03L-0 MURRAY, T D Toledo Edison Co 82/10/04 KEPPLER, J G Region 3, Office of Director 1p 13717 335 24X Fiche 50-346, 82/10/04, 8210180131
- --8210180137 LER 82-045/03L-O on 820904.auxiliary feedwater pump 1-1, suction valve FW786 observed closed for no apparent reason w/o aperator touching close button Cause unknown Valve reopened.

  LONG, W Foledo Edison Co
  Director 2pp. 15719 336 24X Fiche 50-344,82/10/04,8210180131
- 8210190254 Forwards LER 82-046/03L-0 MURRAY.T D Toledo Edison Co 82/10/07 KEPPLER, J Q Region 3, Office of Director 1p 15742 143, 24X Fiche 50-346,82/10/07, 8210190254
- --8210170261 LER 82-046/03L-0 on 820708, high decay heat flow alarm received Decay heat flow pump 2 & high pressure injection flow Pump 2 found not running Caused by failure of 24-volt dc gower supply for buffer cards Power supply replaced ISLEY.T Toledo Edison Co 82/10/07 Region 3. Office of Director. 2pp 15742 144 24X Fichs 50-046.82/10/07.8210190254.
- 8210190358 Forwards revised LER 79-076/03X-1 HURRAY, T D. Toledo Edison Co 82/10/11 KEPPLER, J. Q Region 3. Office of Director 1p. 15742 078 24X Fiche 50-346,82/10/11, 8210190358
- --8210190359 Revised LER 79-076/03X-1 on 790708, core flood tank 1-1 level alarm received Caused by faulty amplifier in level transmitter LT-GF3B2, resulting in incorract reading Amplifier replaced & transmitter recalibr BORYSIAK, M., RICHTER, L. Toledo Edison Co. 82/10/11. Region 3, Office of Director 2pp 15742 099 24X Fiche 50-346,82/10/11. 8210190358
- 8210250270 Forwards LER 82-047/03L-0 MURRAY.T D Toledo Edison Co 82/10/12. KEPPLER.J Q. Region 3 Office of Director. 1p 19791 045. 24X Ficha: 50-346,82/10/12, 8210250270
- --8210250279 LER 82-047/03L-0 on 820913 & 15 containment radiation trip occurred Caused by component failure of output radiation monitor RE-2004 on safety features actuation sys Chennel 1 Operational amplifier & output transistor replaced ELDRED, D T roledo Edison Co 82/10/12 Region 3, Office of Director 3pg 18791 046 24X Fiche 80-346, 82/10/12, 8210230270,
- 8210250226 Forwards LER 82-048/03L-0 MMRRAY,T.D Toledo Edison Co 82/10/14 KEPPLER.J & Region 3, Office of Director. Ip 15788:358 24X Fichs 50-346.82/10/14. 8210250226
- ~-8210250231 LER 82-048/03L-O on 820917, during flushing of vent line on concentrate atomage tank, open fire door 1014 blocked w/ temporary hose. Caused by personnel error General orientation training modified to require training on fire doors SENIUK,P Toledo Edison Co 82/10/14. Region 3, Office of Director 3pp. 15788:359 24X Fiche: 50-346.82/10/14.8210250226.
- 8210280075 Forwards LER 82-049/03L-0.

  MURRAY: T D Toledo Edison Co 82/10/19, KEPPLER: J 9, Region 3, Office of Director 1p 15837:165, 24% Fiche 50-346,82/10/19, 8210280075
- --8210280078 LER 82-049/03L-0 on 820920 & 22, Chennels 2 & 3 on containment post-accident rediation monitor RE 4597BA were reading high Caused by problem in microprocessor software.

  New set of software installed & faulty actuator replaced, ELDRED, DT Toledo Edison Go. B2/10/19 Region 3, Office of Director. 2pp. 15837 166. 24X Fiche: 50-346,82/10/19,8210280075
- DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 8210010196 Ack receipt of 820827 ltr re emergency exercise scheduled for Feb 1983
  STOHR, J. Division of Emergency Preparedness & Operational Support. 82/09/17 MCDONALD, R.P. Alabama Power Co. 1p. 15570 360 24X
  Fiche: 50-348, 82/09/17, 8210010196.

- 8210010195 Forwards Revisions 4 & 5 to security plan Revisions withheld CLAYTON, F L Alabama Power Co 82/09/21 VAROA, 8 A NRC No Detailed Affiliation Given ip 15567 313 24X Fiche 50-348, 82/09/21, 8210010195
- 8210190066 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 82/10/01 Document Management Branch Ip 15761 060 24X Fiche 50-348,82/10/01,82/10/90064
- --8210190073 Public version of emergency plan implementing procedures, including Procedures FNP-0-EIP-11 re handling of injured personnel & FNP-0-EIP-18 re site area emergency Procedure request forms enci
  4 Alabama Power Co 82/09/21 35pp 13761 061 24X
  Fiche 50-348, B2/10/01.8210190066
- 8210180004 Forwards IE Safeguards Insp Repts 50-348/82-23 & 50-364/82-22 on 820921-24 No mencompliance noted VERRELLI.D Division of Project & Resident Programs 82/10/12 MCDDNALD.R P Alabama Power Co 2pp 15720 025 24X Fiche.50-348.82/10/12.8210180004
- --8210180007 IE Bafeguards Insp Repts 50-348/82-23 & 50-344/82-22 on 820921-24 No noncompliance noted Major areas inspected security plan & implementing procedures & security organization Details withheld (ref 100FR70, 21) STANSBERRY, W W , MCGUIRE, D R Division of Engineering & Technical Programs 62/10/08 lp 15720 027 24X Fiche 50-348,82/10/12,8210180004
- 8210280158 Application for amend to Licenses NPF-2 & NPF-8, revising Tech Specs to require audit on emargency preparedness program every 12 months, per 10CFR90, 54(t) & Generic Ltr 82-17 No amend fee required SER enci CLAYTON, F L Alabama Power Co 82/10/25 VARGA, S A Dffice of Nuclear Reactor Regulation, Director 2pp 15837 194, 24X Fichs 50-348, 82/10/25,8210280158
- --8210280165 Proposed Tech Specs, Section 6 5 2 8 requiring audit of emergency preparedness every 12 months, per 10CFR50 54(t) & Oeneric Ltm 82-17 4 Alabama Power Co 82/10/25 3pp 15837-196, 24X Fichs 50-348, 82/10/25, 8210280158

## M Antitrust correspondence

- 9210060179 Notifies of Debevoise & Plimpton change of address as of 621001 Affirmation of Svc encl \* Debevoise & Plimpton 62/10/01 3pp. 15614 108. 24X Fiche 50-349, 82/10/01, 8210060179
- P Operating license stage documents & correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems. Forwards documents listed in App A. FELTON.J M. Division of Rules and Records 82/06/28 UDELL.R. A Critical Mass Energy Project 15pp 15727, 005 24X Fichs 50-000.82/06/28.8210010008.
- --8008050265 Discusses addl required into to better define potential for cracking in reactor vessel nozzles.

  NOONAN, V. S. Assistant Director for Materials & Qualifications Engineering. 80/05/05, TEDEBCG.R L. Assistant Director for Licensing. 2pp 15727-176 24X Fiche: 50-000, 82/06/28, 8210010008
- 8210010227 Confirms B208RO telcon arrangements re 820730 meeting w/util in Region 2 ofc to discuss fuel rod degradation resulting from baffle water-jet impingement Proposed agenda encl. OfREILLY,J.F. Region 2, Office of Director. 82/09/03, MCDONALD,R P Alabama Power Co. 2pp 15527:336, 24X Fiche:50-348,82/09/03,8210010227.
- 8210280158 Application for amend to Licenses NPF-2 & NPF-8, revising Tech Specs to require audit on emergency preparedness program every 12 months, per 10CFR50. 544t) & Generic Ltr 82-17. No amend fee required SER entl CLAYTON, F. L. Alabama Power Co. 82/10/25, VAROA, S. A. Office of Nuclear Reactor Regulation, Director 2pp. 13837.194, 24% Fiche: 50-349, 82/10/25, 8210280158.
- --B210280165 Proposed Tech Specs, Section 6.5, 2.8 requiring audit of emergency preparedness every 12 months, per 10CFR50, 54(t) & Generic Ltr B2-17

  \* Alabama Fauer Co. 82/10/25, 3pp. 15837; 196, 24X
  Fiche: 50-348, 82/10/25, 8210280158,

- Q Inspection reports, IE Bulletins & correspondence
- 8210070007 Responds to FOIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FDIA Request 81-313 Forwards documents listed in App B FELTON, J M Division of Rules and Records 62/08/10 LONG, D J Winthrop, Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000, 82/08/10, 8210070007
- --8210070137 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VAROA.S Operating Reactors Branch 1 5pp 19645 131 24% Fiche 50-000.82/08/10.8210070007
- 8210010204 Forwards IE Insp Repts 50-348/62-21 % 50-364/62-20 on 820802-06 No noncompliance noted DANCE-H C Region 2. Office of Director 82/08/30 MCDONALD.R P Alabama Power Co 2pp 13567 314 24X Fiche 50-348,82/08/30,8210010204
- --8210010208 IE Insp Repts 50-348/82-21 & 50-364/82-20 on 820802-06.No noncompliance noted. Major areas inspected gipe supports & restraints & Types B & C containment leak rate testing BROXS, E . JAPE. F Division of Engineering & Technical Programs 82/08/25 4pp 15567 316 24X Fiche 50-348, 82/08/30. 8210010204
- 8210010043 Concurs w/actions outlined in util 820812 ltr re insparequired by IE Builetin 79-13, except in areas of re-radiographing steam generator feedwater notile-to-pipe & weld retention of records
  LEWIS.R C Division of Project & Resident Programs 82/09/13 MCDONALD.R P Alabama Power Co 2pp 15570 361 24X Fiche 50-348, 82/09/13,8210010043
- 8210150072 Ack receipt of 820709 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/82-19 & 50-364/82-18

  DANCE: H C Division of Project & Resident Programs 82/10/04

  MCDDNALD: R P Alabama Power Co ip 15701 253 24X

  Fiche: 50-348. 82/10/04. 8210150072.
- --B210150074 Responds to NRC B20818 ltr re violations noted in lE Insp. Repts 50-348/82-19 & 50-364/82-18 Corrective actions Form NRC-3 posted at low level raduaste bldg CLAYTON.F L Alabama Power Co 82/09/09 DANCE.H C Region 2. Office of Director 2pp 15701 254 24X Fiche 50-348,82/10/04.8210150072.
- --8210150078 Forwards IE Insp Repts 50-348/82-19 & 50-344/82-18 on 820726-30 & notice of violation DANCE, H C Division of Project & Resident Programs. 82/08/18 MCDONALD, R. P Alabama Power Co 2pp 15701-256 24X Fiche. 50-348, 82/10/04, 8210150072
- --8210150082 Notice of violation from insp on 820726-30 \* Division of Project & Resident Programs 82708718 1: 1:5701 288 24% Fiche 50-348,8270/04/8210150072
- --8210150086 IE Insp Repts 50-348/82-19 & 50-364/82-18 on 820726-30 Noncompliance noted Form NRC-3. "Notice to Employers," not posted in new low level waste storage Facility. PEERY, W. H. BARR, K. P. Division of Engineering & Tachnical Programs 82/08/16 5pp 15701, 259, 24X Fichs 50-348, 82/10/04, 8210150072.
- B210220229 Forwards IE Insp Repts 50-348/82-22 & 50-364/82-21 on B20816-0915. No noncompliance noted DANCE.H G. Division of Project & Resident Programs B2/10/04 MCDCNALD,R P. Alabame Fouer Co 2pp 15776.233. 24X Fiche: 50-348, B2/10/04, B210220229.
- --8210220232 IE Insp Repts 50-348/82-22 % 50-364/82-21 on 8208]6-0913 No noncompliance noted Major areas inspected monthly survaillance & maint observation operational safety verification, plant trips % LERs.
  BRADFORD, N. H., BROWNLEE, V.L. Division of Project & Resident Programs 82/10/04 7pp 15776 235, 24% Fiche 50-348, 82/10/04, 8210220229.
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Beeds," Syc list encl. COB9.L I. Division of Fuel Facilities, Materials & Gafeguards 82/10/06. Consolidated Edison Co. of New York. &&pp 15761-250 24X Fichs:50-000.82/10/06,8208190233.
- 8210180004 Forwards IE Safeguards Insp Repts 50-348/82-23 & 50-364/82-22 on 820921-24. No noncompliance noted, VERRELLID. Division of Project & Resident Programs, 82/10/11 MCDONALD.R P Alabama Power Co. 2pp. 15720,025, 24X Fiche: 50-348,82/10/12,8210180004.

- ---P210180007 IE Safeguards Insp Repts 50-348/82-23 & 50-344/82-22 on 820-81-24 No noncompliance noted Major areas inspected. Security plan & implementing procedures & security arganization Details withheld (ref 10CFR73, 21) STAMSBERRY, W W , MCGUIRE, D R Division of Engineering & Technical Programs 82/10/08 1p 15720 027 24% Fiche 50-348,82/10/12, 8210180004
- 6209190238 IE Bulletin B2-03, "Stress Corrosion Cracking in Thick-Mallitarge-Diameter-Stainless Steel, Recirculation Sys
  Piping at BMR Plants " Svc list encl
  DEYOUNO, R C Director's Office, Office of Inspection and
  Enforcement B2/10/14 Consolidated Edison Co of New York
  115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- E210280410 Nutrification of 821029 meeting w/util.Franklin Research Ctr & Bechtei in Bethesda,MD to review calculations & cathodology re IE Bulletin 80-11. "Masonry Walls " AEEVESE A Operating Reactors Branch 1 82/10/20 VARGA, B. Operating Reactors Branch 1 2pp 15859 332 24X Fithe 50-348,82/10/20,8210280410
- R Periodic operating reports & related correspondence
- E210190722 Forwards monthly operating tept for Sept 1982 CLAYTON.F.L Alabama Power Co 82/10/12 Management Information Sranch ip 15736 301 24% Fiche 50-348.82/10/12.8210190722
- S Reportable occurrences, LERs & related correspondence
- 621GO70470 Discusses 810317 inadvertent actuation of sefety injection sys Event caused by operator error during surveillance testing & raises concern of potential common mode failure for dissel engines w/turbocharges CH1RAMAL,M Director's Office 81/04/24 HICHELSON,C Director's Office 2pp 15044 249 24% Fiche 50-348,81/04/24,8210070470
- B21Q-070111 Reviews purge valve info contained in T Austin 810306 memo Primary tachnical issue relates to valve operability during expected accident conditions Vital areas of concern not addressed in info include lower torque margin for closure BROWN,E J Director's Office 81/07/24 MICHELSON,C Director's Office 4pp 15646 359 24X Fiche 50-348,81/09/24,8210070111
- 821001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R.A Critical Mass Energy Project 15pp 15727 005, 24X Fiche 50-000, 82/06/28, 8210010008
- --BR10050027 Discusses proposed watch list item potential common mode failure of diesel generators AEOD sequence coding & search procedure (SCSP) will be revised to include "fire" as searchable item to enable monitoring of similar events CHIRAMAL, M Office of Management and Program Analysis B1/04/24, MICHELSON, C Office of Management and Program Analysis Rpp 15729 044 24 Ficher 50-000, 82/06/28, 821001000B
- B210010129 Forwards LERs 82-037/03L-0 & 82-052/03L-0 CLAYTON.F L Alabama Power Co 82/09/27 Region 2, Office of Director 1p 15567 227 24X Fiche.50-348.82/09/27,8210010129.
- --8210010139 LER 82-032/03L-0 on 820831, during control room emergency ventilation performance test, 8 train emergency air cleanup sys failed to meet acceptance criteria Caused by failure of charcoal filter to meet efficiency requirements.

  HATRSTON, W. 0 Alabama Power Co 82/09/27 Region 2, Office of Director 1p 15567 228 24X Fiche 50-348, 82/09/27, 8210010127,
- --82100i0i47 LER 82-037/03L-0 on 820905.A train auto trip logic for high steam generator differential pressure declared inoperable when failed cord indication received by automatic tester Caused by failure of universal card.Card replaced HAIRSTON.W 0 Alabama Fower Co 82/09/27 Ragion 2, Office of Director. 1p 15567 229 24X Fiche 50-348.82/09/27,8210010129,
- 82[0190609 Forwards LER 82-053/03L-0 CLAYION.F L Alabama Power Co 82/10/08 Region 2, Office of Director. ip 15740 007. 24X Fiche, 50-348, 82/10/08, 8210190609,
- --B21019064 LER B2-053/03L-0.on B20912, containment atmosphere particulate radioactivity monitoring sys R-11 declared inoperable due to filter paper not advancing, Caused by failure of paper drive motor Motor replaced.

  HAIRSTON.W. Q. Alabama Power Co. B2/10/08. Region 2, Office of Director 1p. 13740:008 24X Fiche: 50-348, 82/10/08, 8210190609

- 8210260453 Forwards LERs 82-054/03L-0.82-055/03L-0.82-039/03L-0 & 82-040/03L-0
  CLAYTON, F. L. Alabama Power Co. B2/10/18 Region 2, Office of Director. 19 15806 195 24X Fiche 50-348,82/10/18,8210260453
- --8210260463 LER 82-054/03L-0 on 820920, flow transmitter FT-497 failed low Caused by failure of N.P printed circuit card in 7300 process control sys Card replaced & instrumentation koop associated w/transmitter returned to svc HAIRSTON.H Q Alshama Power Co 82/10/18 Region 2. Office of Director 1p 15806 196 24X Fiche 50-348, 82/10/18, 8210260453
- --8210260470 LER 82-055/03L-0 on 820921, train B chloring detector declared inoperable due to nonadvancing detector tage Caused by faulty tage drive motor, Motors & light diffusion disc replaced.

  HAIRBTON, H O. Alabama Power Co. 82/10/18 Region 2, Office of Director 19 15805 197 24X Ficher 50-348, 82/10/18, 82/10260453
- --8210260480 LER 82-039/03L-0 on 820919, svc water to component cooling water HX 2C isolated Caused by dislodged pin holding worm drive gear allowing differential pressure across valve disc to close valve Pin reinstalled & secured.
  HAIRSTON.H.O. Alabama Power Co 82/10/18 Region 2. Office of Director 1p 19805 198 24X Fiche 50-348,82/10/18,8210260453
- --8210260490 LER 82-040/03L-0 on 820919, loss-of-voltage protection channel associated w/82F sequencer phase 2-3 declared inoperable Caused by facture of loss-of-voltage relay 27XF1 during testing Relay cleaned HAIRSTON.H 9 Alabama Power Co 82/10/18 Region 2. Office of Director ip 15804 199 24X Ficher 50-348, 82/10/18, 8210240453
- DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B210190134 Forwards questions relactions of DE River Basin Commission in Point Pleasant Diversion Project.per 820831 invitation. SCHWERNGER.A. Licensing Branch 2 82/09/16 HANBLER. 0 Delaware River Basin Commission 5pp 15761.239 24X Fiche.50-352.82/09/16,8210190134
- 8210030479 Forwards request for addl info re environ review, 9chedule for responding to questions requested within 7 days SCHWENGER, A Licensing Branch 2 82/09/21 BAUEH, E O Philadelphis Electric Co 11pp 15626, 263. 24% Fiche: 50-352, 82/09/21, 8210050479
- 8210040362 Forwards responses to 820708 potentially generic concerns re adequacy of design margins of QE Mark II pressure suppression containment sys KEMPER.J. 8 Philadelphia Electric Co 82/09/30. BCHMENCER.A. Licensing Branch 2 50pp 15589 028. 24X Fiche 50-352.82/09/30, 8210040362
- 8210050326 Forwards supplemental util comments on Del-Aware Unlimited request for suppension or revocation of CP & corrected Page 14 of 820703 comments.

  CONNER.T.B Conner & Wetterhahn 82/07/30, DENTON, H R, Office of Nuclear Reactor Regulation, Director 2(pp. 15608:162, 24X Fiche: 50-352:82/07/30:8210050326
- 8210190311 Summary of 820624-25 meetings w/util in Pottstown,PA re applicant response to NRC 820323 info request concerning probabilistic risk assessment. Attendee list encl ABELSON.H Licensing Branch 2. 6pp 15746 011 24X Fiche: 50-352,82/10/05,8210180311.
- 8210290167 Notification of 821019-22 meetings w/util t Bechtel in Ban Francisco, CA to discuss structural engineering design audit ABELSON:H Licensing Branch 2. 82/10/05. BCHHENCER.A. Licensing Branch 2. 4pp. 15876-230 24X Fiche: 50-952:82/10/05,8210290167.
- 8210150124 Forwards Revision 5 to "Probabilistic Risk Assessment" for facility, consisting of responses to NRC 820810 request for add1 infe & corrections to typographical errors BRADLEY,E J. Philadelphia Electric Co 82/10/12 BCHWENCER, A R. Licensing Branch 2, ip. 15704:134. 24X Fiche: 50-352, 82/10/12, 8210150124.
- ~~8210150133 Revision 5 to "Probabilistic Risk Assessment."

  \* Philadelphia Electric Co 62/09/30. 214pp 15706:136. 24X
  Fiche:50-352,82/10/12:8210150126.
- 8210260158 Advises that response to Licanse Qualifications Branch 820901 request for add1 info will be submitted via FSAR revision in Dec.1982
  BRADLEY.E.J. Philadelphia Electric Co. 82/10/22. SCHWENGER, A. Licensing Branch 2. 2pp. 15799.010. 24X Fiche: 50-352, 82/10/22, 8210220158

- C Utility Environmental Report (ER), amends & correspondence
- 8210150397 Forwards Affidavit of Svc re distribution of Ravision 10 to FBAR & Ravision & to environ rapt, per NRC 810706 ltr BRADLEY,E J Philadelphia Electric Co. 82/10/12 DENTON.H. R Office of Nuclear Reactor Regulation, Director 5pp 15703 281 24% Ficha 50-352,82/10/12,8210150397
- F Security, medical, emergency & fire protection plans
- 8207170147 Forwards util response to NRC 82072B comments on physical security plan Response withheld (ref 10CFR2 790). Affidavit requesting that response be withheld from public disclosure enci BRADLEY.E J Philadelphia Electric Co. 82/09/13, DENTON, H R Office of Nuclear Reactor Regulation. Director. 4pp. 14907. 250 24X Fishs 50-382.82/09/13, 8209170149
- @ Adjudicatory correspondence
- 8210180204 Application for approval of patition to amend Contentions V-22.V-23 & V-24 Info new & relevant Certificate of Evc encl.

  809ARMAN, R. J. Del-Aware Unlimited, Inc. BUQARMAN, R. J. Eugerman, R. J. 82/09/20 Commissioners & pp. 15718-141 24X

  Fiche 50-352.82/09/20,8210180204
- --82(0180208 Trial brief supporting request to smend Contentions V-22, V-23 & V-24 New info re Merrill Creek.DE River Basin Commission findings of inadequate water to supply diversions & Unit 2 cancelstion available Certicate of Sec encl SUGARMAN, R J Dal-Aware Unlimited, Inc BUGARMAN, R J S2/07/20 Atomic Safety and Licensing Board Panel 30pp 13734 320 24X Fiche 50-352,82/07/20,8210180204
- 8210010244 Response opposing DE River Basin Commission motion to quash subposea Intervenor does not seek add1 testimony from G Hansler but believes deposition inadmissible. Certificate of Svc encl Related correspondence SUGARMAN, R J Del-Aware Unlimited, Inc BUGARMAN, R J Sugarman, R J 82/09/27 Commissioners Spp. 13568; 280. 24% Fiche, 50-352, 82/09/27, 8210010244
- 8210180217 Motion to strike EH Bourguard testimony re impacts of intake of biological species. No expertise shown by witness re subjunter of testimony Related correspondence SUOARMAN, R. J. Bul-Aware Unlimited, Inc. BUOARMAN, R. J. Bugarman, R. J. 82/09/27 Commissioners 2pp 15718, 101 24X Fiche 50-352:82/09/27:8210180217
  - for change of hearing schedule, for consolidation all use & to strike NRC testimony, ASLB should inclusion to Commission Certificate of Svc

ted. Inc. SUGARMAN.R.J Sugarman, s. 16pp. 15718.064 24%

mansion of proceedings & Truence of initial

BUÇARMAN, R. J. 15718: 080.

- 8210180224 Motion to strike MT Masnik testimony due to prejudice, bias & fact that testimony not based on FEB Related correspondence 8U0ARMAN, R. J. Bel-Aware Unlimited, Inc. 8U0ARMAN, R. J. Bugarman, R. J. 82/09/27, Commissioners, 3pp. 15718:061, 24X Fiche, 50-352, 62/09/27, 6210180224.
- 8210180253 Motion to strike J Lear testimony. Testimony shows extreme bias & goes beyond witness statement of purpose. Related correspondence.

  SUGARMAN.R. J. Bel-Aware Unlimited. Inc. BUGARMAN.R.J. Bugarman.R.J. B2/09/27
- 8210040087 Advises that NRC witness A Policostro will be available to testify only on 821004-05. Testimony should be scheduled out of turn.
  HODBOON.A.P. Hearing Branch 2, 82/09/29, BRENNER, L., MORRIB.P.A., COLE.R.F. Atomic Bafety and Licensing Board Panel. 2pp. 15581:037 24X Fiche:50-952,82/09/29,8210040087.
- B210050326 Forwards supplemental util comments on Del-Aware Unlimited request for suspension or revocation of CP & corrected Page 14 of 820703 comments.

  CONNER.T.B Conner & Nebterhahn. B2/09/30. DENTON, M.R. Office of Nuclear Reactor Regulation. Director. 21pp. 15608;162. 24X Fiche: 50-352:82/09/30,8210050326

- 8210050088 Response opposing Del-Aware 820927 motion to striks MRC testimony of J Lehr & MT Maenik. Del-Aware concerned wivelight to be accorded testimony, not requirements for receipt Notice of appearance & Certificate of Evc encl HDDDDN.A.P Hearing Branch 2 82/10/01 Atomic Safety and Licensing Board Panel App 15604 276 24X Fiche. 50-352.82/10/08210050088
- B210050197 Answer opposing Del-Aware Unlimited, Inc B20927 action for mod to hearing schedule, for consolidation or to strike NRC testimony Del-Aware estopped from asserting impropristy or illegality of AGLB authority on cooling water contentions CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn. 82/10/01 Atomic Bafety and Licensing Board Panel 26pp. 15611.129 24X Fiche 50-352, 82/10/01, 8210050197
- B210050382 Response in opposition to Del-Aware 820927 motion to stritestimony of EH Bourquard re design, configuration & const of Point Pleasant intake Assertions do not affect relevance of testimony or witness qualifications.

  CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Weterhahn. B2/10/01 Atomic Safety and Licensing Board Famil 4pp 15508 277 24% Fichs 50-352/82/10/01/8210050382
- 8210070197 Requests schedule for submitting discovery rept be postponed until all necessary parties available Counsel for all parties involved in hearing on water issues Related correspondence DORSEY, J. A. Limerick Ecology Action 82/10/04 BRENNERL COLERF, MORRIS, P. A. Atomic Bafety and Licensing Board Panel 2pp 15634-267 24X Fichs 50-352,62/10/8210070197
- B210280207 Forwards Commonwealth of PA Public Util Commission 82082 order, Corps of Engineers 820924 notice of intent to issue germit & Commonwealth of PA Dept of Environ Resources 820902 permits HODODON, A P Hearing Branch 2. 82/10/13, BRENNER, L., MORRIS, P. COLE, R.F. Atomic Bafety and Licensing Board Panel 79pp. 15839 057 24X Fiche 50-352, 82/10/13, 8210280207.
- 8210200040 Response opposing Del-Aware modified Contention V-24
  Contention goes beyond scope of contentions as initially
  submitted & lacks adequate basis & specificity
  Certificate of Syc encl.
  HODODON, A.P. Hearing Branch 2 82/10/15 Atomic Safety and
  Licensing Board Panel 10pp 15755.094. 24X Fiche: 50-352.82/IC
  8210200040
- 8210200066 Answer opposing Del-Aware Unlimited, Inc revised proposed Contention V-24, Buby of contention previously litigated, rejected by ABLB & irrelevant Certificate of Byc encl CONNER, T.B Philadelphia Electric Co. CONNER, T.B Conner & Wetterhahn 82/10/15 Atomic Sefety and Licensing Board Panel 33pp. 15754: 140. 24X Fiche 30-352, B2/10/15, B210200066
- 8210210383 Confirmatory memorandum & order extending time for util, & Limerick Ecology Action to file joint rept on informal discovery until 830124

  BRENNER: A tomic Safety and Licensing Board Panel 82/10/20 15763-201. 24X Fiche. 50-352, 82/10/20, 8210210383.
- 8210220332 Confirming memorandum & order.confirming ABLB 621004 day of Dal-Aware Unlimited. Inc 620927 motion to postpone hearings starting on 821004.ABLB will not be addressing ultimate cost/benefit during hearings.

  BRENNER.L Atomic Safety and Licensing Board Panel 92/10/20 Dal-Aware Unlimited, Inc. 5pp. 15775.359. 24%

  Fiche: 50-352, 82/10/20, 8210280332

- 8210130465 Opposes issuance of CL DEAN,V. Affiliation Unknown 82/09/14, BRENNER,L. Atomic Bafi and Licensing Board Panel. 2pp. 15703:048. 24X Fiche: 80-382, 82/09/14, 8210150465
- K. Utility Final Bafety Analysis Report (FSAR) & amends
- 9210150397 Forwards Affidavit of Byc re distribution of Revision & FSAR & Revision & to environ rept.per NRC 810706 ltr BRADLEY.E.J. Philadelphia Electric Go 82/10/12. DENION.H.R Office of Nuclear Reactor Regulation, Director 5pp 15703.291 24X Fiche: 50-352,82/10/12.8210150397

- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8207180085 Forwards comments on probabilistic risk assessment study in response to 820518 request Lack of completeness noted in consideration of initiating events Total of 3 man-days consideration of initiating events foot of manuage espended in review DAVIS,P R Affiliation Unknown DAVIS,P R ACRS - Advisory Committee on Reactor Bafeguards 82/09/05 DKRENT,D ACRS - Advisory Committee on Reactor Safeguards 5pp 15852-038 24X Fichs 50-352,82/09/09,8207180085
- ù Inspection reports, IE Bulletins & correspondence
- 8210089015 Addl response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOLA Exemption 5) 82/07/12 UDELL,R A
- FELTON, J H Division of Rules and Records 82 Critical Mass Energy Project 7pp 15665, 027 Fishe 50-000, 82/07/12, 8210080015
- --- \$105040420 Discusses review of util response re insp rept unresolved 105040420 Discusses review of util response re insp rept unresolved them identified during post-tensioning fuel pool girders Capacity of anchorage sys is capable of meeting design requirements Unresolved item can be closed JORDAN E L Director's Office 81/OJ/24 MARYIN, T Region 1, Philadelphia, Office of the Director 2pp 15668 125 24X Fich | 50-000, 82/07/12, 8210080015.
- 8210040224 Forwards "Limerick Generating Station Unit 1 Preservice Insp Pragram Plan for Nuclear Piping Bys." Vols 1 & 2. in response to NRC 810706 supplemental request for add info KEMPER.J S Philadelphia Electric Co 82/09/24 BCHMENCER.A Licensing Branch 2 3pp 15591 331 24X Fiche 50-352.82/09/24. 82100408224
- --8210040228 "Preservice Insp Program Plan for Nuclear Piping Sys." Vols 1 & 2 Twenty-two oversize drawings encl Aperture cards are available in PDR 

  \* Nuclear Energy Service, Inc. 82/07/12 737pp. 18891.334 24X
  Fichs 50-352,82/09/24,8210040224
- 8210210069 Forwards IC Insp Repts 50-352/82-12 & 50-353/82-09 on BOOODS FORWARD II has rept 30-332/de-12 & 30-332/de-07 bil BOOODS-10 No noncompliance noted MARTIN.T P Division of Engineering & Technical Programs 82. KENPER.J B Philadelphia Electric Co. 2pp. 15765.334 24X Fiche 30-352,82/10/05,8210210069
- --8210210082 IE Insp Repts 50-352/82-12 & 50-353/82-09 on 820908-10. No noncompliance noted Major areas inspected foundation & backfill matts supporting & proximate to safety-related structures VARELA, A A , DURR, J P Division of Engineering & Technical Programs 82/09/26 5pp. 15765-336 24X Fiche 50-352,82/10/05,8210210069
- 8208190233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged I-125 Taplant Seeds. " Svc list encl.

  COSB.L I Division of Fuel Facilities, Materials & Bafeguerds.

  B2/10/04 Consolidated Edison Co. of New York 66pp 15761,250

  24% Fiche 50-000.82/10/06.8208190233.
- 8210290208 Forwards IE Insp Repts 50-352/82-11 & 50-353/82-08 on B20816-0917 No noncompliance noted
  STAROBTECKI,R Division of Project & Resident Programs 82/:
  KEMPER.J S Philadelphia Electric Co. 2pp. 15853:275 24X
  Fiche 80-352.82/10/08.8210290208 82/10/08
- --8210270210 IE Insp Repts 50-352/82-11 & 50-353/82-08 on 820816-0917 No noncompliance noted Major areas inspected electrical cable pulling-housekeeping-welding & small-bore pipe supports CHAUDHARY.8.K., MCCABE.E C. Division of Project & Resident Programs 82/10/16. 2pp 15853 277. 24% Fiche 50-352,82/10/08,8210270208
- 8210220367 Ack receipt of B20921 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-352/82-10
  MARTIN-T.Y Division of Engineering & Technical Programs 82/10/1
  KEMPERIJ.S Philadelphia Electric Co. 1p. 15779-194 24X
  Fiche.50-352,82/10/13,8210220367. 89/10/19.
- --8210220374 Responds to NRC 820824 ltr re-violations noted in IE Insp Rept 50-352/82-10 Corrective actions: 100% insp of all Rapt 30-332/82-10 Corrective actions: 100x insp or air previously inspected instrument supports performed & training course on instrument installation conducted, REMPER, J. B., Philadelphía Electric Co., B2/07/21. HA Region I. Office of Director. App. 15779, 195. 24X Fiche. 50-352, 82/10/13, 8210220367. HAYNES, R. C.

- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Well-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants "Syc list encl DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement, 82/10/14 Consolidated Edison Co. of New York 115pp 15810 125 24X Fiche: 50-000, 82/10/14, 8208170238.
- T Hearing transcripts on non-antitrust matters
- 8210060234 Transcript of 821004 hearing in Norristown PA Pp 738-961 Supporting documentation encl
  A Atomic Sefety and Licensing Board Panel 82/1
  15621 226 24X Fiche 50-352,82/10/04.8210060234 82/10/04 299pp
- 8210070097 Transcript of 821005 hearing in Norristown, PA Pp 962-1, 274 Supporting documentation enci.

  \* Atomic Bafety and Licensing Board Panel B2/10/05 360pp
  1527 354 24X Fiche 50-329, B2/10/05, B210070097
- 8210080050 Transcript of 821006 hearing in Norristown, PA Pp 1,275-1:531. Supporting documentation encl \* Atomic Safety and Licensing Board Panel 82/10/06 349pp. 15643:297 24X Fichs 50-332,82/10/06.8210080050
- 8210120183 Transcript of 821007 hearing in Norristown, PA Pp 1.532-1.728

  \* Atomic Bafety and Licensing Board Panel 82/1
  15655.215 24% Fiche 50-352,82/10/07.8210120183 82/10/07 199pp.
- 8210130239 Transcript of 821008 OL hearing in Morristown, PA Pp 1,729-
- 10130237 (Tankscript of Below of Maring In North County Parp 2,025 Supporting documentation encl \* Atomic Safety and Licensing Board Panel 82/10/08 323pp 15674:162. 24X Fiche 50-352.82/10/08.8210130239.
- 8210200020 Transcript of 821018 hearing in Betheada, MD Fp 2,026-2,236 Supporting documentation encl. \* Atomic Safety and Licensing Board Panel 82/10/18 221pp 15736 331 24% Fiche 30-332,82/10/18,8210200020.
- 8210210104 Transcript of 821019 hearing in Bethesda, MD, Pp 2,237-2,505 Bupporting documentation encl

  Atomic Safety and Licensing Board Panel 82/1
  15766 360 24% Fiche 50-352,82/10/19,8210210104. 82/10/19. 283pp
- B210250115 Transcript of 621021 hearing in Bethesda, MD Pp 2,738-3,077. Supporting documentation enci # Atomic Safety and Licensing Board Panel 82/10/21. 376pp 1579 074 24X Fiche 50-352,82/10/21,8210250115.
- 8210260130 Transcript of 821022 hearing in Bethesda, MD Pp 3,078-3,374 Supporting documentation encl.

  \* Atomic Bafety and Licensing Board Panel. 82/10/22. 303pp.
  15801 046 24X Fiche 50-352.62/10/22.8210260130.
- 8210270062 Transcript of 821025 hearing in Bethesda, MD. Pp 3,375-3,741 Supporting documentation encl \* Atomic Safety and Licensing Board Panel, 82/ 15823-035. 24% Fiche: 50-352, 82/10/25, 8210270042 82/10/25 561pp.
- 8210280173 Transcript of 821026 hearing in Bethesda, MD Pp 3,742-4,038. Supporting documentation encl.

  \* Atomic Safety and Licensing Board Panel. 82/10/26. 312pp.
  18842 136. 24X Fiche 50-352,82/10/26.8210280173.
- DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8210190134 Forwards questions relactions of DE River Basin Commission in Point Pisasant Diversion Projection 820831 invitation. SCHMENCER, A Licansing Branch 2. 82/09/16. HANSLER, O. Delaware River Basin Commission Spp. 15761: 239. 24% Fiche: 30-352, 82/09/16. 8210170134
- 8210050479 Forwards request for addl info re environ review Schedule for responding to questions requested within 7 days SCHWENCER.A. Licensing Branch 2. 82/09/21 BAUER.E.O Philadelphia Electric Co. 11pp. 15426:263. 24X Fiche.50-352,82/09/21.8210050479.
- 8210040362 Forwards responses to 820708 potentially generic concerns re adequacy of design margins of 9E Mark II pressure suppression containment sys.

  KEMPER.J.S. Philadelphia Electric Co. 82/09/30. BCHWENCER, A. Licensing Branch 2. 50ps. 15589.028. 24X Fiche 50-352,82/09/30,8210040362.

- 8210090326 Forwards supplemental util comments on Dal-Aware Unlimited request for suspension or revocation of CP & corrected Page 14 of 820903 comments

  CONNER, T B Conner & Wetterhahn 82/09/30 DENTON; H R Office of
  - CURMEN, I B Conner & Metterhahn B2/09/30 DENTON, H R Off Nuclear Reactor Regulation, Director 21pp. 15608 162 24X Fiche 50-352,82/09/30.8210050326
- 8210180311 Summary of 820624-25 meetings w/util in Pottstown,PA re applicant response to NRC 820323 info request concerning probabilistic risk assessment Attendee list encl
  ABELGON,H Licensing Branch 2 82/10/05 Licensing Branch 2 6pp 15746 011 24% Fiche 50-352-82/10/05-8210180311
- 8210290167 Notification of 821019-22 meetings w/util & Bechtel in San Francisco.CA to discuss structural engineering design audit ABELSON:H Licensing Branch 2 82/10/05 SCHWENCER.A Licensing Branch 2 4pp 15876 230 24X Fiche 50-352,82/10/05,8210290167
- 8210150126 Forwards Revision 5 to "Probabilistic Risk Assessment" for factility consisting of responses to NRC 820810 request for addl info & corrections to typographical errors BRABLEY, E. J. Philadelphia Electric Co. 82/10/12 SCHMENCER, A.R. Licensing Branch 2 1p 15704 134 24X Fiche 50-352, 82/10/12, 8210150124
- --8210150133 Revision 5 to "Probabilistic Risk Assessment " \* Philadelphia Electric Co 82/09/30 214pp 15706 136 24X Fiche: 50-352, 82/10/12, 8210150126
- 8210240188 Advises that response to License Qualifications Branch 820701 request for add1 info will be submitted via FBAR revision in Dec.1982 PRADLEY,E J Philadelphia Electric Co 82/10/22 BCHHENCER,A Licensing Branch 2 299 15799 010 24% Fiche.50-352,82/10/22, 8210240158
- C Utility Environmental Report (ER), amends & correspondence
- G210150397 Forwards Affidavit of Svc re distribution of Revision 10 to FBAR & Revision 6 to environ rept.per NRC B10706 ltr BRADLEY.E J Philadelphia Electric Co B2/10/12 DENTON.H R Office of Nuclear Reactor Regulation, Director 24K Fishe 50-352,82/10/12,82/0150397 500
- F Security, medical, emergency & fire protection plans
- 8209170149 Forwards util response to NRC B20728 comments on physical security plan Response withheld (ref 10CFR2 790) Affidavit requesting that response be withheld from public disclosure BRADLEY, E J BRADLEY, E J Philadelphia Electric Co 82/07/13 DENTON, H. R Office of Nuclear Reactor Regulation, Director 4pp 14907 250, 24% Fichs. 50-352, 82/09/13, 8209170149.
- O Adjudicatory correspondence
- 8210180204 Application for approval of patition to amend Contentions V-22.V-23 & V-24 Info new & relevant Certificate of Syc
- BUQARMAN, R. J 48718.141 24X SUGARMAN, R J SUGARMAN,R J Del-Amare Unlimited, Inc BUGARMAN,R R J. 82/09/20 Commissioners 6pp 15718,141 Fiche.30-332:82/09/20,8210180204 Sugarman,
- --9210180208 Trial brief supporting request to amend Contentions V-22, V-23 & V-24. New info re Merrill Creek.DE River Basin Commission findings of inadequate water to supply diversions & Unit 2 cancelation available. Certicate of Syc encl.

  8U0ARMAN.R.J Bal-Aware Unlimited, Inc. BU0ARMAN.R.J Superman, R.J. 82/09/20 Atomic Bafety and Licensing Board Panel. 30pp. 15734: 320. 24% Fiche. 50-352, 82/09/20, 8210180204.
- 8210010244 Response opposing DE River Basin Commission motion to quash subposts Intervenor does not seek addl testimony from Q Hamsler but believes deposition inadmissible Certificate of Svc encl Related correspondence.
  SUGARMAN,R J. Del-Aware Unlimited, Inc. SUGARMAN,R.J. Sugarman,
  R J. 82/09/27 Commissioners. 3pp. 15568-280 24X
  Fiche: 50-352: 82/09/27, 22:10010244
- 8210180217 Motion to strike EH Bourguard testimony re impacts of intake of biological species No expertise shown by witness re subjunction of testimony Related correspondence.

  8UGARMAN, R. J. Del-Aware Unlimited, Inc. SUGARMAN, R. J. Sugarman, R. J. 82/09/27. Commissioners. 2pp 157(8, 101, 24x)

  Fiche. 50-352, 82/09/27, 8210180217

- \$210180223 Motion for change of hearing schedule for conscildation all water cooling issues & to strike NRC testimony ABLB should certify issue of inclusion to Commission Certificate of Svc encl Related correspondence SUOARHAN.R J Del-Aware Unlimited, Inc SUOARHAN.R J E R J 82/09/27 Commissioners 16pp 15718 064 24X Fiche 50-352.82/09/27,8210180223
- ~-B210180226 Brief supporting motion for suspension of proceedings tonselidation or to strike NRC testimony Issuance of initial decision before full NEPA consideration will substantially prejudice Del-Aware interests to public in general BUGARMAN,R J, NEILL, J M Del-Aware Unlimited, Inc BUGARMAN,R J SUGARMAN,R J B2/09/27 Commissioners 21pp 15718,080 24X Fiche 50~352,82/09/27,8210180223
- 8210180224 Motion to strike MT Masnik testimony due to prejudice bias b fact that testimony not besed on FES Related correspondence SUGARHAN, R.J. Bel-Aware Unlimited. Inc. SUGARHAN, R.J. Sugarran, R.J. 82/09/27, Commissioners. 3pp. 15718-061 24X Fiche 50-352, 82/09/27, 8210180224
- 8210180253 Motion to strike J Lear testimony Testimony shows estrand bias & goes beyond witness statement of purpose Related correspondence,
  SUGARMAN.R J Del-Aware Unlimited, Inc SUGARMAN.R J
  RJ 82/09/27 Commissioners 3pp 15718 056 24X
  Fichs 50-352: 82/09/27, 8210180253
- 8210040087 Advises that NRC witness A Policostro will be available to testify only on 821004-05 Testimony should be scheduled out. HODODON, A P Hearing Branch 2 82/09/29 BRENNER, L., MORRIB. P.A. OLE, R F Atomic Safety and Licensing Board Panel 2pp 24x Fiche 50-352,82/09/29,8210040087
- 8210030326 Forwards supplemental util comments on Del-Aware Unificited request for suspension or revocation of CP & corrected Page 14 of 820903 comments CONNER. T B Conner & Watterhahn 82/09/30 DENTON. H CONNER, T B Conner & Wetterhahn 82/09/30 DENION, H R 094 Nuclear Reactor Regulation, Director 21pp 15608 162 24x Fichs. 50-352.82/09/30, 8210050326 Office of
- 8210050088 Response opposing Del~Aware 820927 motion to atrike NRC testimony of J Lehr & MT Masnik Del-Aware concerned w/weight to be accorded testimony not requirements for receipt Natice of appearance & Certificate of Svc encl HODODONA P Hearing Branch 2 82/10/01. Atomic Safety and Licensing Board Panel 6pp 15604 276 24% Fiche 50-352, 82/10/01.
- 8210030197 Answer upposing Del-Aware Unlimited Inc 820927 motion for mot to hearing schedule for consolidation or to strike NRC testimony, Del-Aware estopped from asserting impropriety or iliagality of ABLB authority on cooling water contentions CONNER: T B. Philadelphia Electric Co. CONNER: T B. Cooner & Wetterhahn 82/10/01. Atomic Safety and Licensing Board Panel 26pp. 15611 129 24X Fiche 50-352.82/10/01.8210050197
- 8210050382 Response in opposition to Del-Aware 820727 motion to strite testimony of EH Bourquard re design.configuration & const of Point Pleasant intake Assertions do not affect relevance of testimony or witness qualifications CONNERT B. Philadelphia Electric Co. CONNERT B. Conner & Hetterhahn 82/10/01 Atomic Bafety and Licensing Board Patel 4pp 15608.277 24X Fiche 50-352,82/10/01,8210050392
- 8210070199 Requests schedule for submitting discovery rept be postponed until all necessary parties available, Counsel for all perties involved in hearing on water issues, Related correspondence,
  DORSEY, J. A. Dorsey, J. A. DORSEY, J. A. Limerick Ecology Action
  82/10/04 BRENNER, L., COLE, R. F., MORRIB, P. A. Atomic Bafaty and
  Licensing Board Panel. 2pp 15634, 267 24X Fiche. 50-332, B2/10,
  8210070199.
- 8210280207 Forwards Commonwealth of PA Public Util Commission B2061 order, Corps of Engineers 820924 notice of intent to issue permit & Commonwealth of PA Dept of Environ Resources 820902 permits of Commencer of the Second Sec
- 8210200040 Response apposing Del-Aware modified Contention V-24 Contention goes beyond scope of contentions as initially submitted & lacks adequate basis & specificity. Centificate of Box enci.

  HODDON's A.P. Hearing Branch 2, 82/10/15, Atomic Gafety and Licensing Board Panel 10pp 15755:074. 24X Fiche 50-352.82/10, 8210200040.

- 8210200066 Answer opposing Del-Aware Unlimited, Inc revised proposed Contention V-24 Subj of contention previously litigated, rejected by ASLB & irrelevant Certificate of Svc encl CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Hetterhahn 82/10/15 Atomic Safety and Licensing Board Panel 33pp 15754 140 24% Fiche 50-352, 82/10/15,8210200066
- 8210210383 Confirmatory memorandum & order extending time for util.NRC & Limerick Ecology Action to file joint rept on informal discovery until 830124

  BRENNER, L Atomic Safetty and Licensing Board Panel 82/10/20 3pp 15763 201 24X Fiche 50-352.82/10/20.8210210383
- 8210220332 Confirming memorandum & order confirming ASLB 821004 denial of Del-Aware Unlimited Inc 820927 motion to postpone hearings starting on 821004 ASLB will not be addressing ultimate cost/benefit during hearings BRENNER, L Atomic Safety and Licensing Board Panel 82/10/20 Del-Aware Unlimited, Inc 5pp 15775 359 24% Fiche 50-352, 82/10/20, 8210220332

- B210150469 Opposes issuance of OL BEAN,V Affiliation Unknown 82/09/14 BRENNER,L Atomic Safety and Licensing Board Panel 2pp 15703 048 24X Fiche 50-352,82/09/14,8210150465.
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8210150397 Forwards Affidavit of Syc re distribution of Revision 10 to FSAR & Revision 6 to environ rept.per NRC 810706 ltr BRADLEY,E J Philadelphia Electric Co 82/10/12 DENTON.H R Office of Nuclear Reactor Regulation, Director 5pp 15703 281 24X Fiche 50-325,82/10/12,8210150397
- O Advisory Committee on Reactor Safeguards reports & correspondence
- B2071800B5 Forwards comments on probabilistic risk assessment study in response to 820518 request Lack of completeness noted in consideration of initiating events Total of 3 man-days expended in review DAVIS.P R. Affiliation Unknown DAVIS.P R ACRS Advisory Committee on Reactor Safeguards 62/09/05 OKRENT.D ACRS Advisory Committee on Reactor Safeguards 5pp 15852 038 24X Fiche 50-352.82/09/05.8207180085
- O Inspection reports, IE Bulletins & correspondence
- 8210040224 Forwards "Limerick Oenerating Station Unit 1 Preservice Insp Program Plan for Nuclear Piping Sys." Vols 1 & 2, in response to NRC 810706 supplemental request for add info KEMPER. J 8 Philadelphia Electric Co 82/09/24 SCHWENCER. A Licensing Branch 2 Spp. 15591 331 24X Fiche 50-352.82/09/24, B210040224
- 9210210069 Forwards IE Insp Repts 50-352/82-12 & 50-353/82-09 on BZ0908-10 No noncompliance noted.

  MARTIN T T Division of Engineering & Technical Programs 82/10/05 KEMPER-J B. Philadelphia Electric Co 2pp 15765-334. 24X Fiche 50-352, 82/10/05. 8210210069.
- --B2102100B2 IE Insp Repts 50-352/82-12 & 50-353/82-09 on 820908-10 No noncompliance noted Major areas inspected foundation & backfill matts supporting & proximate to safety-related structures

  VARELA:A A , DURR, J P Division of Engineering & Technical Programs. 82/09/26 Spp 15765-336 24X Fichs.50-352.82/10/05, 8210210069.
- 8208170233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Beeds," Syc list encl.
  CD89,L I. Division of Fuel Facilities, Materials & Bafeguards 82/10/06, Consolidated Edison Co of New York 66pp. 15761 250, 24X Fiche. 50-000.82/10/06.8208190233
- 8210290208 Forwards IE Insp Repts 50-352/82-11 & 50-359/82-08 on 820816-0917 No noncompliance noted STAROSTECKIR. Division of Project & Resident Programs. 82/10/08 KEMPER. J 8 Philadelphia Electric Co 2pp. 15853 275 24X Fiche. 50-352, 82/10/08.8210290208.
- --8210270210 IE Insp Repts 50-352/82-11 & 50-353/82-08 on 820816-0717 No noncompliance noted Major areas inspected electrical cable pulling, houstkeeping, welding & small-bore pine supports CHAUDHARY, 8, K., MCCA8E, E. C. Division of Project & Resident Programs 82/10/16. 2pp. 15853; 277 24X Fichs. 80-352, 82/10/08, 8210270208.

- S208190238 IE Bulletin 82~03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list enc! DEYQUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fichs 50-000, 82/10/14, 9208190238
- T Hearing transcripts on non-antitrust matters
- 8210060234 Transcript of 821004 hearing in Norristown.PA Pp 738-964 Supporting documentation encl \* Atomic Safety and Licensing Board Panel 82/10/04 299pp 15621 226 24X Fichs 90-392,82/10/04.8210060234
- 8210070097 Transcript of 821005 hearing in Norristown,PA Pp 962-1,274 Supporting documentation enci \* Atomic Safety and Licensing Doard Panel 82/10/05 360pp 15627 354 24% Fiche 50-352,82/10/05,8210070097
- 8210080050 Transcript of 821006 hearing in Norristown, PA Pp 1,275-1,531 Supporting documentation encl # Atomic Safety and Licensing Board Panel 82/10/06 349pp 15643 297 24% Fiche 50-352.82/10/06.8210080050
- 8210120183 Transcript of 821007 hearing in Norristown.FA Pp 1.532-1.728 \* Atomic Safety and Licensing Board Pane? 82/10/07 199pp 15655 215 24X Fiche 50-352.82/10/07.8210120183
- 8210130239 Transcript of 821008 QL hearing in Norristown.PA Pp 1.729-2.025 Supporting documentation enci \* Atomic Safety and Licensing Doard Panel 82/10/08 323pp 15674 162 24% Fiche 50-352.82/10/08.8210130239
- B210200020 Transcript of B21018 hearing in Bethesda, MD Pp 2,026-2,236 Supporting documentation enci \* Atomic Safety and Licensing Board Panel B2/10/18 221pp 15756 331 24X Fiche 50-352,82/10/18.8210200020
- 8210210104 Transcript of 821019 hearing in Bethesda, MD Pp 2,237-2,505 Supporting documentation encl \* Atomic Safety and Licensing Board Panel 82/10/19 283pp 15766 360 24X Fiche 50-352,82/10/19.8210210104
- 8210250115 Transcript of 821021 hearing in Bethesda, MD Pp 2,738-3,077 Supporting documentation encl \* Atomic Safety and Licensing Board Panel 82/10/21 374pp 15773 074 24% Fiche 50-352.82/10/21.8210250115
- 8210260130 Transcript of 821022 hearing in Bethesda.MD Pp 3,078-3,374 Supporting documentation encl \* Atomic Safety and Licensing Board Panel 82/10/22 303pp 15801 046 24% Fiche 30-352.82/10/22.8210260130
- 8210270062 Transcript of 821025 hearing in Bethesda, MD Pp 3,375-3,741 Supporting documentation encl \* Atomic Safety and Licensing Board Panel 82/10/25 561pp, 15823 035 24X Fiche 50-352,82/10/25,8210270062,
- 8210280173 Transcript of 821026 hearing in Bethesda, MD, Pp 3, 742-4, 038 8upporting documentation encl \* Atomic Safety and Licensing Board Panel 82/10/26 312pp 15842 134 24X Fiche 30-352, 82/10/26, 8210280173
- DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

  Q Inspection reports, IE Bulletins & correspondence
- 8210060318 Ack receipt of 820819 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-354/82-07 STAROSTECKI,R. Division of Project & Resident Programs, 82/09/30 MARTINIT,J Public Service Electric & Oas Co of New Jersey, 1p 15616 028 24X Fiche 50-354.82/09/30,8210060318
- --9210060326 Responds to NRC 820722 ltr re violations noted in IE Insp. Rept 30-354/82-07 Corrective actions vendor procurement quality supplier plan amended to require bend testing of Nelson stude per AMB DI. I requirements

  MARTIN.T J Public Service Electric & Gas Co of New Jersey. 82/08/19. HAYNES.R.C Region 1. Office of Director. 4pp. 15616 029 24X Fiche 50-354.82/09/30.8210060318
- 8210210091 Forwards IE Insp Rept 50-354/82-10 on 820830-0903, No noncompilance noted.

  MARTIN.T.T Division of Engineering & Technical Programs. 82/10/05 MARTIN.T.J Public Service Electric & Gas Co. of New Jersey. 2pp 18765-321. 24X Fiche: 50-354, 82/10/05, 82/10/1091

- --8210210097 IE Insp Rept 50-354/82-10 on 820830-0903 No noncompliance noted Major areas inspected electrical & instrumentation review of design procedures & licenses sys to implement & control field design changes
  FINKELIA E , BETTENHAUSEN.L Division of Engineering & Technical Programs 82/09/23 App 15765 323 24X Fiche 50-354,82/10/05,8210210091
- 8208190233 IE Info Notice 90-35. Suppl 1, "Leaking & Disladged I-125 Implant Speeds" Syc 13st end. COBBL 1 Division of Fuel Facilities, Materials & Safeguarda 82/10/06 Consolidated Edison Co of New York 66pp 13761 250 24X Fiche 50-000, 82/10/06. 8208190233
- 8210210109 Forwards IE Insp. Rept. 50-354/82-11 on 820908-10 & notice of violation
  MARTINIT T Division of Engineering & Technical Programs 82/10/06
  MARTINIT J Public Service Electric & Oas Co. of New Jersey 2pp. 19766-034 24X Fiche 50-354,82/10/06,8210210109
- --8210210117 Notice of violation from insp on 820908-10 \* Region 1, Office of Director 82/10/06 1p 15766 036 24X Fiche 50~354,82/10/06,8210210109
- --8210210125 IE Insp Rept 50-354/82-11 on 820908-10 Noncompliance noted failure to follow procedure re reactor pressure vessel internal cleanliness during const GRAY.E H Region 1. Office of Director B2/10/04 4pp 13766 037 24X Fishe 50-354, 82/10/06, 8210210109
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYBUND, R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000,82/10/14.8208190238
- DOCKET 50-355 MOPE CREEK NUCLEAR STATION, UNIT 2

  G Inspection reports. IE Bulletins & correspondence
- B208190233 R Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 6App 15761 250 24% Fiche 50-000, 82/10/06, 8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall. Large-Diameter. Steinless Steel, Recirculation Sys
  Piping at BWR Plants " Svc list encl
  DEYOUND.R C Director's Office. Office of Inspection and
  Enforcement 82/10/14 Consolidated Edition Co of New York
  115pp 15810 125 24% Fiche 50-000, 82/10/14.8208190238

# DOCKET 50-358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

344 Forwards request for add1 info re seismic loading used in analysis of scram discharge vol piping BLOOD, B J Licensing Branch 1 82/09/23, BCROMANN, E. A. nati Gas & Electric Co 3pp 15691 098 24X 50-356, 82/09/28, 8210120344

32 Amend 139 to application for OL, consisting of Revision B7 to ubmittal includes response to NRC 82070B & 22 ltrs remargins of Mark I & II containment sys & piping ion criteria, respectively
NN.E A Cincinnati Gas & Electric Co 82/09/30 DENTON, H
of Nuclear Reactor Regulation, Director 2pp 15609, 295, che 50-338, 82/09/30, 8210050332

94 Forwards info addressing implementation of interim actions ntrol of heavy loads discussed in NUREQ-0612 All mactions will be completed prior to fuel loading at ty ... BR Cincinnati Oas & Electric Co. B2/10/07 DENTON, H of Nuclear Reactor Regulation, Director ip, 15678:310, 24X 50-338, 82/10/07:6210130274

0297 Tech Specs 3 9 7 & 4 9 7 re crane travel spent fuel storage incinnati Gas & Electric Co 81/06/04 App 15678.311 24X e 50-358.82/10/07,8210130294

IB7 Forwards Certificate of Svc for Amend 139 to application for e in form of Revision B7 to FSAR
INNEA Cincinnati Cas & Electric Co 82/10/09 DENTON, H, R
of Nuclear Reactor Regulation, Director 2pp 15704, 056
che 50-358, 82/10/08, 8210150387

- 8210180154 Forwards supplemental info to 820407 ltr re setatic qualification of equipment Info consists of rept. "Seismic Gualification Rept on ITE Series 5600 Motor Control Ctr "

  SYLVIA, 8 R Cincinnati Gas & Electric Co 82/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 15738 184 Priche 50-358, 82/10/13, 8210180154
- --8210180163 "Beismic Guelification Rept on ITE Beries 5600 Mctor Cont Ctr." Revision 1 + Structural Dynamics Research Corp 11410 R01 82/10/07. 272pp 15718 185 24X Fichs 50-358, 82/10/13, 8210180154
- 8210290330 Requests, within 20 days of receipt notarized list of all relevant documentation & repts prepared for 820708-07 meetings re welder qualifications
  KEPPLER.J O Region 3. Office of Director 82/10/27 EDROHAMS.E.A.
  Cincinnati Qua & Electric Co. 2pp. 15853 051 24X
  Fiche. 50-358. 82/10/27. 8210290330
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8210260498 Forwards revised rept "Selsmic-Stress Analysis of Horlacht Pumps." in response to SER Item 3 10 re specific concerns w/reactor bidg closed cooling water pumps (80P2) BORGMANN.E A Cincinnati Oas & Electric Co 82/10/21 DENICH, M F Office of Nuclear Reactor Regulation, Director 1p 15806-324. 2 Fiche 50-358, 82/10/21.8210260488
- --8210260493 "Seismic-Stress Analysis of Horizontal Pumps F MCDONALD,C K McDonald Engineering Analysis Co MC-884 82/08/30 9ipp 15806 325 24X Fiche 50-358,82/10/21,821026048
- G Adjudicatory correspondence
- 82:0070402 Brief in support of revised exceptions to ASLD 820621 initial decision Certificate of Bvc encl CONNER.T B Concert Gas & Electric Co CONNER.T B Conner & Wetterhahn 82/10/04 Atomic Safety and Licensing Appeal Panel 57pp 18433 250 24X Fiche 50-358,82/10/04.8210070402
- 8210150449 Motion for leave to file reply brief to applicant & NRC responses to Miami Power Project 820820 petition to reconsider & vacate 820730 order directing ASLB to dismiss Project eight proposed contentions.

  BERNABELL Miami Valley Power Project BERNABELL Government Accountability Project 82/10/11 Commissioners ip 15703 [Miami Valley Power Project BERNABELL Miami Valley Power Project BERNABELL Government Accountability Project 82/10/11.
- --B210150457 Reply to applicant & NRC responses to Mismi Valley Power
  Project 820820 petition to reconsider & vacate 820730 order
  directing ASLB to dismiss Project eight proposed
  contentions Cartificate of Svc enci
  DEVINE.T. BERNABELL. Mismi Valley Power Project DEVINE.T.
  Government Accountability Project 82/10/11 Commissioners
  60pp 15703 165 24X Fichs 50-358,82/10/11,8210150449
- 8210210391 Forwards suppl to Miami Valley Power Project 820820 paths; to suspend facility const
  DEVINE.T Miami Valley Power Project DEVINE.T Government
  Accountability Project 82/10/18 PALLADING.N., GILINSKY.V.,
  AKEARNE.J F Commissioners 1p 15764 049 24X
  Ficher 50~398.82/10/18.8210210391
- --B210210400 Suppl to Miami Valley Power Project 820820 patition to suspend facility const. Including add bases for immediate suspension of const & requested remedy Cartificate of Size encl
  DEVINE, T Miami Valley Power Project DEVINE, T. Qovernment Accountability Project 82/10/18, Commissioners 30pp 15764 050, 24X Fiche, 50-358, 82/10/18, 8210210391
- 8210270277 Motion to strike Miami Valley Power Project 821011 Fally brief supplementing petition for reconsideration of Commission 820730 order & reply to NRC & util responses No permission given to file brief. Cartificate of Byr encl WETTERHAHN, M. J. Cincinnati Cas & Electric Co. HETTERHAHN, M. J. Conner & Wetterhahn 82/10/26. Commissioners App. 15633 094 24X Fiche 50-358,82/10/24,8210270299

# H General correspondence

8209270242 Forwards TH Applegate itr to NJ Palladino per telcon request. KEPPLER: J O Region G. Office of Director 82/07/24 HEEKEY, P Shaw. Pittmen. Potts & Troubridge. 1p. 14974 165 24X Fiche: 50-358, 82/07/24, 8209270242

19

- 8209270271 Comments on alleged NRC attempt to cover up teriousness of problems at facility Subj will be brought to attention of Congress & Administration
  APPLEGATE.T W Affiliation Unknown 82/09/24 PALLADINO, N J
  Commissionners ip 14994 166 24X Fiche 50-358, 82/09/24.
- 219060423 Addl response to FDIA request for tape recordings of F Olt; 610223 & Osol4 interviews & any other recordings re Zimmer investigation Forwards three tapes of Govt Accountability Project 810226 meeting & R Daker 810303 interview M/o encis fELTON, J M Division of Rules and Records 82/09/29 HICKEY, J P Shaw, Pittman, Potts & Troubridge 1p 15636-253 24X Fische 50-356, 62/09/29, 8210060423

# Utility Final Sofety Analysis Report (FSAR) & amends

- 210090332 Amend 139 to application for OL. consisting of Revision 87 to FSAR Submittal includes response to NRC 820708 & 22 ltrs refestion margins of Mark I & II containment sys & piping ibration criteria, respectively UDROMANULE A. Cincinnati Oas & Electric Co. 82/09/30 DENTON.H Diffice of Nuclear Reactor Regulation. Director 2pp 15609 295 24% Fiche 50-386,82/09/30,821005032
- CIOI50387 Forwards Certificate of Svc for Amend 139 to application for license in form of Revision 87 to FBAR SDRGMANN, C A Cincinnati Gas & Electric Co 82/10/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15704 056 24% Fiche 50-358,82/10/08,8210150387
- 1 Inspection reports, IE Bulletins & correspondence
- 5210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
  FELTON.J M Division of Rules and Records 82/07/12 UDELL,R A Critical Mass Energy Project 9pp 15645 027 24X
  Fiche 50~000.82/07/12.8210080015
- --8210080170 Systematic assessment of licensee performance notes re facility evaluation for Oct 1979-Sept 1980 \* MRC - No Petailed Affiliation Given 80/09/30 9pp 15668 107 24X Firhe 50-000.82/07/12,8210080015
- 8210080166 Forwards IE Insp Rept 50-358/82-14 on 820831 & 0901-02 & 07 No noncompliance noted PAFERIELLO,C J Division of Emergency Preparedness & Operational Support 82/09/22 BORGMANN,E A Cincinnati Gas & Electric Co 2ps 15640 144 24X Fiche 50-358,82/09/22,8210080166
- --8210080171 IE Insp Rept 50-358/82-14 on 820831 & 0901-02 & 07 No noncompliance noted Major areas inspected prespectational environ monitaring & protection, mgt controls & internal dudits & program implementation & results GESTHANN-M J . ROZAK.S . SCHUMACHER.M Region 3, Office of Director 82/09/21 8pp 19640 146 24% Fiche 50-358.82/09/22, 8210080166
- 6208190233 IE lnfo Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Syc list enci CGBBrt. 1 Division of Fuel Facilities, Materials & Safeguards 62/10/06 Consolidated Edison Co of New York 66pp 15761,250 24% Fiche 50-000,82/10/06,8208190233
- 6208190238 IE Bulletin 82-03, "Btress Carrosion Cracking in Thick-Wall. Large-Diameter. Stainless Steel, Recirculation Sys Piping at BNR Plants " Svc list encl DEYGUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14, Consolidated Edison Co of New York \$15pp 15810 125 24% Fiche 50-000, 82/10/14,8208190238
- 8210190635 Advises of 821019 enforcement conference meeting in Cincinnati.OH to discuss recent insp findings.per 821012 telcon w/util KEPPLER.J 9 Region 3. Office of Director. 82/10/15 BOROMANN.E A Cincinnati Oas & Electric Co 1p 13740.053 24X Fiche 50-038.82/10/15.8210190635
- B210290278 Ack receipt of B20723 & 0824 ltrs informing NRC of add1 steps taken to correct violations noted in NRC 820621 ltr & IE Insp Rept 50-358/81-27 NORELUB, C E Division of Engineering & Technical Programs. B2/10/26 BDROMANN.E A Cincinnati Cas & Electric Co 3pp 15854 249 24% Fichs 50-358,82/10/26,8210290278

- --8210290281 Supplements 820824 response to violations noted in IE Insp. Rept \$0-358/81-27 Twelve of 34 pipe lugs in process of penetrant eram Twenty-two remaining welds due penetrant inspected BORG/MANN.E A Cincinnati Cas & Electric Co 82/09/30 KEPPLERIJ G Region 3, Office of Director 1p 15854 252 24X Fiche 50-358,82/10/26.8210290278
- --0210290285 Amends response to B20723 ltr per B20621 review & comments in initial 820223 response Sampling program for RHR sys inadequate BOROMANNE A Cincinnati Qas & Electric Co B2/08/24 KEPPLER.J Q Region 3. Office of Director 4pp 15854 253 24x Fiche 50-358,82/10/26,8210290278
- --8210290290 Responds to 820602 1tr rp review & comments per 820223 interim ltr concerning adequacy of shop & field welds Full compliance will be achieved by 821001 & will resolve autual concerns for Items 1.2 & 6 of IE Insp Rept 50-359/81-27 BORGMANN.E A Cincinnati Oas & Electric Co 82/07/23 NORELIUS.C E Division of Engineering & Technical Programs Spp 15854 257 24% Fiche 50-358,82/10/26.8210290278
- 8210290330 Requests within 20 days of receipt notarized list of all relevant documentation & repts prepared for 820708-09 meetings re welder qualifications
  KEPPLER, J G Region 3, Office of Director 82/10/27 BOROMANN, E A Cincinnati Oas & Electric Co 2pp 15853 O51 24X
  Fiche SO-358,82/10/27,8210290330
- S Reportable occurrences, LERs & related correspondence
- B210050137 Interim deficiency rept re nonconforming Kerotest packless diaphragm seal values Values appear to be open per indication of handwheel posteion, but are actually closed Resolution undetermined Finel rept expected by 821115 BORGMANN.E A Cincinnati Qas & Electric Co 82/09/20 KEPPLER, J Q Region 3. Office of Director 2pp 15605 050 24X Fiche 50-358, 82/09/20, 8210050137
- 8210060271 Interim deficiency rept re Item M-33 fittings w/high-stress stamp Util performing documentation reviews & field walkdowns to identify field installed fittings which may be stamped improperly Next rept will be submitted 830131 BDROMANN,E A Cincinnati Gas & Electric Co 82/09/22 XEPPLER,J Q Region 3, Office of Director 200 15621 083 24X Fiche 50-358,82/09/22,8210060271
- 8210130372 Interim deficiency rept re possible carbon steel in stainless welds Analysis of weld by Metcut. Inc scheduled to be completed 821008 Results will be provided to NRC by 821115 BUROMANN, E A Cincinnati Gas & Electric Co 82/09/22 KEPPLER, J G Region 3, Office of Director 2pp 15681 167 24X Fiche 50-358,82/09/22,8210130372
- 8210060358 Interim deficiency rept re Item M-46 on turning vane failures in HVAC sys Extension of 2 wks until B21014 requested to complete further analysis required for scheduled interim rept BOROMANN.E A Cincinnati Qas & Electric Co 82/09/30 KEPPLER, J G Region 3, Office of Director 1p 15618 353 24X Fiche 50-358, 82/09/30, 8210060358
- 8210150443 Interim deficiency rept re diesel generator control logic Initially reported on 820909 Preliminary engineering evaluation concludes that sequence can be corrected by tripping diesel generator w/ESF actuation signal BORGMANN,E A Cincinnati Gas & Electric Co 82/09/30 KEPPLER, J G Region 3, Office of Director 3pp 15703 153 24X Fiche 30-358, 82/09/30, 8210150443
- 8210060309 Deficiency rept re Item E-27 concerning improperly incorporated DDC Item determined not reportable per 10CFR50 55(a) BDRGMANN,E A Cincinnati Gas & Electric Co 82/10/01 KEPPLER,J Q Region 3, Office of Director 1p 15619 194 24X Fiche 50-358,82/10/01,8210060309
- 8210190627 PNO-III-82-111 on 821011.util issued stop work order for all assential work activities performed by Catalytic, Inc. involving structural steel & welding rework IE may meeting w/util planned during wk of 821018 to discuss insp findings SCHWEIBINZ.E , HUNTER.D . WARNICKR. Region J. Office of Diractor 82/10/13 1p 15740 033 24X Fiche 50-358,82/10/13,8210190627
- 8210260279 Interim deficiency rept re turning vane failures in HVAC sys Three addit failures discovered since 820702 Failures believed to be fatigue induced Failed vanes repaired Testing to continue Next rept by 830115
  BOROMANN.E.A Cincinnati Oas & Electric Co 82/10/13 KEPPLER, J Q Region S, Office of Director 2pp 15803 220 24X
  Fiche 50-358,82/10/13,8210260279

#### DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8210290063 Forwards "Evaluation & Action Plan for San Onofre Nuclear Cenerating Station Units 2 & 3 re TMI Incident " DRAKE, J H Southern California Edison Co 79/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15859 052 24% Fiche 50-361,79/08/16.8210290063
- --8210290069 "Evaluation & Action Plan for San Onofre Nuclear Generating Station Units 2 % 3 re TMT Incident " 4 Southern California Edison Co 79/08/31 4Spp 15859 054 248 Fiche 50-361.79/08/16.8210290063
- B210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J H Division of Rules and Records B2/06/28 UDELL, R A Critical Mass Energy Project 15pp 18727 005 24X Fiche 30-000, B2/06/28, 8210010008
- --B008050265 Discusses addl required into better define potential for cracking in reactor vassel notiles
  NDDNAN,V S Assistant Director for Materials & Qualifications
  Engineering 80/05/05 TEDESCO.R L Assistant Director for
  Licensing 2pp 15727 176 24X Fiche 50-000.82/06/28.8210010008
- F Security, medical, emergency & fire protection plans
- 8210190625 Forwards Revision 7 to physical security plan Revision withheld (ref 10CFR73 21)
  BASKIN.K P Southern California Edison Co 82/10/15 EISENHUT.D G Office of Nuclear Reactor Regulation. Director ip 15740 035 24X Fiche 50-206.82/10/15.0210790625
- G Adjudicatory correspondence
- 8210040009 Notifies that LJ Chandler will represent NRC at oral argument per ASLAB 820908 order SN Perry of FEMA will be available CHANDLER.L J Hearing Branch 2 82/09/24 SHDEMAKER.C J Atomic Safety and Licensing Appeal Panel 1p 15581 315 24X Fiche 50-361.82/09/24.8210040009
- 8210050267 Memorandum & order setting medical arrangements question for hearing Listed questions should be answered by all parties, providing expert testimony where required Issue of terminating procedures will be certified to Commission KELLEY, J. L. Atomic Safety and Licensing Board Panel 82/10/01 8pp 19611 195 24% Fiche 50-361.82/10/01.8210050267
- 8210060184 Memorandum & order certifying question to Commission of feasibility of ASLB continuing proceeding initiated by ABLB 821001 order
  KELLEY, J. L. Atomic Safety and Licensing Board Panel 82/10/05
  Commissioners 4pp 15613 181 24X Fiche 50-361,82/10/05,8210040184

- 8210180075 Brief re medical svcs issues certified by Commission order No advance planning required by 10CFR50 47(b)(12) for medical svcs for general public Necessary arrangements can be made on ad hoc basis Certificate of Svc encl CHANDLER, L J Hearing Branch 2 82/10/14 Commissioners 28pp 15719 270 24x Fiche 50-361:82/10/14.8210180095
- 8210220240 Response supporting util 821008 objections to ASLB 621001 preheating memorandum & order re-medical arrangements Scheduling of any bearing should await guidance from Commission, resolving certified issues W/Certificate of Syc CHANDLER.L J. Hearing Branch 2 62/10/20 Atomic Safety and Licensing Board Panel 7pp 15775-131 24X Fiche 50~761,82/10/20,8210220240
- P Operating license stage documents & correspondence
- B210010212 Forwards Amend 8 to License NPF-10, safety evaluation be notice of issuance & availability Amend changes date for operability of post-accident sampling syste Jan 1983 be revises associated Tech Specs (per TMI Action Item [] [] [] EISENHUT.D O Division of Licensing 82/09/17 DIETCH.R Bouthers California Edison Co COTTON.6 D. BERNATH.L San Diego Cas & Electric Co 4pp 15567 320 24% Fiche 50-361,82/09/17,8210010212
- --8210010215 Amend 8 to License NPF-10, changing date for operability of post-accident sampling sys to Jan 1983 & revising associated Tech Specs (per Tril Action Item II 8 3) EISENHUT, D Q Division of Licensing 82/09/17 5pp 1556/ 124 24X Fichs 50-361,82/09/17,8210010212
- --8210010222 Safety evaluation supporting Amend 8 to License NPF-10

  \* Office of Nuclear Reactor Regulation, Director 82/09/17 3pp
  15547 329 24X Fiche 50-341.82/09/17.8210010212
- --8210010229 Notice of issuance & availability of Amend B to License NPF-10 KERRIGAN,J Licensing Branch 3 82/09/17 2pp 1994/ 132 24x Fiche 50-361,82/09/17,8210010212
- 821021049B Confirms 82070B telephone authorization of Tech Spec changes as requested by 820907 & OB 1trs re reactor coolant flow-tow contained in Table 2 2-1 NOVAK, T M Assistant Director for Licensing 82/09/27 DIFTCH, R Southern California Edison Co COTTON, OD, BERNATH, L Bain Diego Gas & Electric Co 3pp 15772 350 24X Fichs 50-161, 82/09/27,
- 8210040117 Proposed Change NPF-10-46 to Tech Spec 3 3 4 re turbine overspeed protection Change will allow entry into Modes 3 & 2 while preventing possibility of turbine overspeed by requiring MSIVs & bypasses to be closed MASKIN K P Southern California Edison Co 82/07/30 KERHICAN. J & Licensing Branch 3 ip 15614 334 24X Fiche 50-361.02/07/30.8210060117
- --8210060119 Proposed Change NPF-10-46 to Tech Spec 3 3 4 allowing entry into Modes 3 & 2 while preventing possibility of turbing overspeed

  \* Sauthern California Edison Co 82/09/30 Ip 15614 335 24g Fiche 50-361, 82/09/30, 8210060117
- 8210070164 Forwards evaluation of Unit 2 license conditions relative to potential applicability to Unit 3 license conditions.in response to NRC request BASMIN.K P Southern California Edison Co 82/10/04 KIARIGAN.J E Licensing Branch 3 App 15627 009 24X Fiche 50-361.B2/10/04, 8210070164
- 8210060368 Outlines augmented shift manning requirements for period of initial criticality of Unit 3. for 1-month period after initial attainment of 100% power on Unit 2 & to control rotation of operators between units, per 820920 meeting DIETCH, R Southern California Edison Co 82/10/05 DENTON, N R Office of Nuclear Reactor Regulation, Director 2pp 13519 053 24X Fiche 50-361.82/10/05, 8210060368
- 8210070082 Discusses use of radwaste solidification sys Unit 2 license condition does not prevent util from using Chem-Nuclear Sys. Inc process to solidify wet solid radwaste produced at Unit 1 Safety evaluation will be performed

  BASKIN.K P Southern California Edison Co 82/10/05
  CRUTCHFIELD, D Operating Reactors Branch 5 2pp 15628, 162 24x

  Fiche 50-206, 82/10/05, 8210070082
- 8210130571 Forwards Amend 9 to License NPF-10:safety evaluation & notice of issuance & availability. Amend changes Tech Specs to allow operation in Modes 2 & 3 w/turbine overspeed protection sys inoperable
  KERRIOAN, J Licensing Branch 3 82/10/07, DIETCH, R Southern California Edison Co. COTTON, G D. BERNATH.L. San Diego Ges & Electric Go. 3pp. 15679 090 24X Fiche 50-361.82/10/07, 82:013057;

- --8210130573 Amend 9 to License NPF-10, changing Tech Specs to allow operation in Modes 2 & 3 w/turbine overspeed protection sys imperable
  - Figh 50-361 82/10/07 8210130571
- --8210130577 Safety evaluation supporting Amend 9 to License NPF-10 \* Office of Nuclear Reactor Regulation, Director 82/10/07 2pg 15679 097 24X Fich 50-361.82/10/07.8210130571
- ---B21G1305B2 Notice of issuance & availability of Amend 9 to License
  - NON-10 NERGES.V Licensing Branch 3 82/10/07 5pp 15679 099 24X Fiche 50-361 82/10/07.8210130571
- 2210190560 Forwards corrected page to rept re small earthquake swarm which occurred on 811110 Revised info does not alter conclusions stated in rept

  PAS/fil A P Southern California Edison Co 82/10/15 KERRIGAN.J D

  Licensing Branch 3 2pp 15734 137 24X Fiche 50-361,82/10/15, 8210190560
- 6210190534 Notifies that info gained during Unit 2 natural circulation test program will be incorporated into overall Unit 2 % 3 operating training program, per NUREG-0737, Item I G I Listed tests will not be repeated for Unit 3 SASKIN, F P Southern California Edison Co 82/10/18 XERRIGAN, J D Licensing Branch 3 2pp 15751 314 24X Fiche 50-361, 82/10/18, 8210190534
- 6210260416 Forwards Application 13 to amend License NPF-10, revising App A Tech Specs to change response time for ECCS miniflew valves
  DIETCH.R Southern California Edison Co 82/10/21 DENTON.H R
  Office of Nuclear Reactor Regulation. Director 2pp 15806 294
  24x Fiche 50-361.82/10/21,8210260416
- --6210260424 Application 13 to amend License NPF-10, revising App A Tech Specs to change response time for ECCS miniflow valves DIETCHLR Southern California Edison Co 82/10/21 10pp 15805 296 24X Fiche 50-361,82/10/21,8210260416
- O Inspection reports, IE Bulletins & correspondence
- E21 G010042 Confirms 821021 mgt meeting in Rosemead, CA to discuss systematic assessment of licensee performance Anticipated meeting attendees & agenda encl CREMS, J. L. Division of Resident, Reactor Project & Engineering Programs 82/09/27 PAPAY, L. T. Southern California Edison Co Gpp 15565 317 24% Fiche 50-206, 82/09/27, 8210010042
- 원교10(90476 Forwards IE Insp Repts 50-361/82-27 & 50-362/82-19 on 원교20905-17 No noncompliance nuted BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/10/05 PAPAY,L T Southern California Edison Co 4pp 15740 245 24X Fiche 50-361,82/10/05,8210(190478

- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Stoel, Recurculation Sys Piping at BMR Plants." Syc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- 8210250222 Ack receipt of 820927 ltr informing NRC of steps taken to correct violations noted in IE Inap Repts 50-361/82-25 & 50-362/82-16
  BISHOP,T W Division of Resident, Reactor Project & Engineering Programs 82/10/18 PAPAY,L T Southern California Edison Co J 15789 326 24x Fiche 50-361,82/10/16.8210250222
- --3210250227 Responds to NRC 620831 ltr re violations noted in IE Insp Repts 50-361/82-25 & 50-362/82-16 Corrective actions Operating Instruction 5023-2-4 revised on 620831 to include proper caution PAPAYL T Southern California Edison Co 62/09/29 ENGELKEN.R H Region 5, Office of Director 4pp 15789 327 24x Fiche 50-361.62/10/16.6210250222
- S Reportable occurrences. LERs & related correspondence
- 8210050151 Forwards LER 82-080/03L-0 Detailed event analysis submitted RAY.H B Southern California Editon Co 82/09/22 ENGELKEN.R H Region 5. Office of Directon 2pp 15609 053 24X Ficha 50-361.82/09/22.8210050151
- --8210050234 LER 82-080/03L-0 on B20823.during Made 4 feeder breaker testing after returning breaker 2A0101 to svc. feeder breaker 2A0104 failed to open Cause unidentified Event considered isolated No further attion deemed necessary RAY.H B Southern California Edison Co 82/09/22 Region 5. Office of Director 1p 15A09 055 24X Fiche 50-361.82/09/22, 8210050151
- 8210050261 Forwards LER 82-076/03L-0 Detailed event analysis submitted RAY, H 9 Southern California Edison Co 82/09/23 ENGELKEN.R H Region 5. Office of Director 2pp 15609 196 24X Fiche 50-361, 82/09/23, 8210050261
- --8210050266 LER 82-096/03L-0 on 920825.ECCS subsystem high pressure safety injection pump 2P-017 failed to develop 1.400-psia discharge pressure during operability test Caused by excessive leakage past miniflow bypass valve 82-1204-MU-184 RAY.H B Southern California Edison Co 82/09/23 Region 5. Office of Director 1p 15609 198 24X Fiche 50-361,82/09/23.8210050261
- 8210050381 Forwards LER 82-103/03L-0 Detailed event analysis submitted RAY.H B Southern California Edison Co 82/09/23 ENGELKEN.R H Region 5, Office of Director 2pp 15608 251, 24X Fiche 50-361, 82/07/23, 8210050381
- ---8210050390 LER 82-103/03L-0 on 820825, but leg sample isolation valve ZHV-0517 breaker 2BJ-23 tripped on overload in attempt to close valve during semiannual ESF subgroup relay test Caused by burned out operator motor Motor replaced RAY.H B Southern California Edison Co. 82/09/23 Region 5, Office of Director ip 15608 253 24% Fiche 50-361,82/09/23,8210050381,
- 82:005000B Forwards LER 82-098/03L-0 Detailed event analysis submitted RAY.H B Southern California Edison Co 82/09/24 ENGELKEN.R H Region 5. Office of Director. 2pp 15605 205 24X Fiche 50-361.82/09/24.821005000B

- --8210050024 LER 82-097/03L-0 on 820925, condentate storage tank T-121 water level fell below Tech Spec limit Caused by madequate makeup water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAY, H B Southern California Edison Co 82/09/24 Region 5, Office of Director ip 15804 345 24% Fiche 50-361,82/09/24, 8210050016
- --8210050029 LER 82-102/02L-O on 820827.condensate storage tank T-121 water level fell below Tech Spec limit Caused by imadequate makeup water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAY. H B Boutharn California Edison Co 82/09/24 Region 5. Office of Director ip 15604 346 24X Fiche 50-361,82/09/24. 82/0050016
- -8210050032 LER 82-104/03L-0 on 820901, contensate storage tank T-121 water level fell below Tech Spec limit Caused by inadequate mateup water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAY. H B Southern California Edison Co B2/09/24 Region 5, Office of Director 1p 15604 347 24X Fiche 50-361,82/09/24, 221050014
- --B210050037 LER B2-106/03L-O on B20903, condensate storage tank T-121 water level fell below Tech Spec limit Caused by imadequate makeup water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAY.H B Southern California Edison Co B2/09/24 Region 5, Office of Director ip 15404 348 24X Fiche 50-361,82/09/24, R910050016
- --821005004i LER 82-108/03L-O on 820830, condensate storage tank T-121 water level fell below Tech Spec limit Caused by inadequate makeup water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAY.H B Southern California Edison Co 82/09/24 Region S, Office of Director 1p 15504 349 24X Fiche 50-361,82/09/24, 8240050014
- --8210050044 LER 82-107/03L-0 on 82090A, condensate storage bank T-121 water level fell below Tech Spec limit Caused by inadequate makeup water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAY.H B Southern California Edison Co 82/09/24 Region 5, Office of Director ip 13604 350 24X Fiche 50-361,82/09/24,8210050016
- --8210090048 LER 82-110/03L-0 on 820712, condensate storage tank T-121 water level feel below Tech Spec limit Caused by inadequate makeup water control to tank & too restrictive Tech Spec limit Tech Spec change & automatic level control proposed RAY.H B Bouthern California Edison Co 82/09/24 Region 5, Office of Director lp 19404 351 24X Fiche 50-361,62/09/24, 8210050016
- --9210050050 LER 92-111/031-0 on 920709, condensate storage tank 7-121 water level fell below Tech Spec limit Caused by inadequate makeup water control to tank & too restrictive Tech Spec limit Fech Spec change & automatic level control proposed RAY.H B Southern Galifornia Edison Co 82/09/24 Region 5, Office of Director lp. 15604 352 24% Fiche 50-361,82/09/24,82/09509/6

- --8210130274 LER 82-099/017-0 on 820913. Train A control room emerging air cleanup sys failed to start after receiving spurious toxic gas isolation signal Caused by improper positioning of kirk tey on breaker 280418 of fan E418
  RAY.H B Southern Callfornia Edison Ca 82/09/27 Regions 5.
  Office of Director ip 15678 354 247 Fiche 50-361.82/09/27.
  B210130269
- B210130278 Forwards LER 82-076/03L-1 Detailed event analysis submitted RAY, H B Southern California Edison Co 82/09/30 ENDELKEM, H H Region 5, Office of Director 2pp 15678 t67 24x Fiche 50-341.82/09/30,8210130278
- --B210130285 LER 82-076/03L-1 on 820725, steam generator indicator 2PDI-0979-1 failed channel check test & was placed in types to condition prior to Mode 2 entry Caused by Inadvertently valved out indicator RAY.H B Southern California Edison Co 82/09/30 Reg 2 010 5 07fice of Director 1p 15678 169 24X Fichs 50 361,82/09/30,8200130028
- B210130497 Forwards LER 82-105/03L-0 Detailed event analysis submitted RAY, H B Southern California Edison Co 82/09/30 CNGFLML #4. # || Region 5, Office of Director 2pp 15683 097 24X Fiche 50-361.82/09/30.8210130499
- --BR1013050B LER B2-105/03L-0 on B20831, during Mode 2 operations, aviiling feedwater pump 2P-504 declared inoperable Caused by leady threaded plug on pump discharge casing Threads cleaned, graffoll applied & plug reinstalled RAY.H B Southern California Edison Co 82/09/30 Region 5. Office of Director ip 15683 099 24X Fichs 50-161, 82/09/30, B210130499
- 8210130469 Forwards LERs 82-107/03L-0.82-119/03L-0.862-121/03L-0. Detailed event analysis submitted RAY.H B. Southern California Edison Co. 82/10/0. FNGH M6 P2.R H. Region 5. Office of Director 2pp. 15682 155 24X Fiche 50-261.82/10/0.82/10/10469
- --8210130478 LER 82-107/03L-0 on 820902, condensate storage tarik T-120 water level fell below Teth Spec limit while in Mode 2 Caused by inadequate makery water control Corrective actions include better planning & Limely water transfer RAY.H B Southern California Eduson Co 82/10/01 Region 5, Office of Director ip 15682 157 24X Fishe 50-161, 122/10/01, 8210130449
- --8210130485 LER 82-119/03L-0 on 820919, condensate storage Lamb I-120 water level fell below Tech Spec limit while in Node 2 Caused by inadequate makeup water control Corrective actions include better planning & timely water transfer RAY-M B Gouthern California Edison Co 82/10/01 Region 3. Office of Director 1p 15682 158 24X Fiche 50-361, R2/10/01, R201030449
- --8210130493 LER B2-121/03L-0 on B20920, condensate storage tank 1-120 water level fall below Tech Spec limit while in Mode 2 Caused by inadequate makeup water control Corrective actions include better planning & timely water transfer RAY. H B Bouthern California Edison Co 82/10/01 Region 5. Office of Director ip 15682 157 24X Fiche 50-361.82/10/01.82/10/30469
- 8210190309 Forwards LERs 82-116/03L-0,82-117/03L-0 & 82-112/0 TL 0
  Detailed event analysis encl
  RAY.H B Southern California Edison Co 82/10/08 EMGELMEN.R H
  Region 5, Office of Director 2pp 15742 150 24X
  Fiche 50-361,82/10/08,8210190309
- ~-8210190317 LER B2-116/03L-0 on 820917, condensate storage tank I-120 water level fell below Tech Spec limit Caused by inadequate makeup water control to tank T-121 & overly restrictive Tech Spec I hand Period Bayes Canif. Daying & Tech Spec Change proposed RAV.H B Southern California Edison Co 82/10/00 Region 5. Office of Director ip 15742 152, 24X Fiche 50-361,02710/68-8210190309
- ~-B210190323 LER 82-117/03L-0 on 820918, condensate storage tanh 1-10 water level fell below Tech Spet limit Caused by inadequate makeup water control to tank T-121 & overly restrictive Tech Spec thing breign & Tech Spec change proposed RAY.H B Southern California Edison Co 82/10/08 Ragion 5 02/10/09 0309 process of Director 1p 15742'153 24X Fiche 50-361.827/10/8.
- ~-8210190328 LER 82-112/03L-0 on 820910, condensate storage tamk 1-12 water level fell below Tech Spec limit Caused by inadequate makeup water control to tank T-121 & overly restrictive Tech Spec Limit Design & Tech Spec change proposed RAY.H B Southern California Edison Co 82/10/08 Region Office of Director ip 15742 154. 24X Fiche 50-351, 82/10/08 8210190309.

- 8210250137 Forwards LER 82-118/03L-0 Detailed event analysis submitted RAY.H B Southern California Edison Co 82/10/15 ENGELKEN.R H Region 5. Office of Director 2pp 15787 002 24X Fiche 50-361. 82/10/15. 8210250137
- --B210250140 LER 82-118/O3L-0 on 820917, low nitrogen actuator pressure discovered in steam generator feedwater isolation valve 2HV-4052 Caused by leakage at plug to check valve located on accumulator Temporary instrument valve installed RAY.H B Southern California Edison Co 82/10/15 Region 5. Office of Director ip 15787 004 24X Fiche 50-361.82/10/15, 6210250137
- 8210250207 Notifies that followup repts to LERs 82-094 & 82-103 will be provided by 821130 Delay due to add1 evaluation needed for corrective action RAY,H B Southern California Edison Co 82/10/15 ENGELKEN,R H Region 5, Office of Director 1p 15787 362 24X Fichy 50-361, 82/10/15, 8210250207
- ©210259214 Forwards LER 82-115/03L-0 Detailed event analysis submitted RAY.H B Southern California Edison Co 82/10/15 ENGELKEN,R H Region 5. Office of Director 2pp 15788 289 24X Fiche 50-361.82/10/15.8210250214
- --021025021B LER 82-115/03L-0 on 020916. during Mode 2 operation, control etement assembly 47 slipped & dropped in excess of 7 inches Caused by defective timing card Affected solid state chip replaced RAY. H. B. Sauthern California Edison Co. 82/10/15 Region 5, Office of Director 1p. 1578B 291 24X Fiche 50-361, 82/10/15, 8210250214
- 8210250269 Forwards LER 82-113/03L-0 Detailed event analysis submitted RAN.H B Southern California Edison Co 82/10/15 ENGELKEN.R H Regison 5. Dff/cc of Director 2pp 15791 042 24X Fiche 50-361.82/10/15.8210250269
- --B210250273 LER 82-113/03L-0 on 820916, routine operator insp during gaseous waste processing revealed interstage rupture disc of waste gas compressor CO10 breached Caused by excess buildup of interstage pressure within compressor Disc replaced RAY, H B Southern California Edison Co B2/10/15 Region 5, Office of Director 1p 15791 044 24X Fiche 50-361, B2/10/15, B2102500A9
- 8210280080 Forwards LER 82-114/017-0 Detailed event analysis submitted RAV.H B Southern California Edison Cp 82/10/19 ENGELKEN.R H Region 5, Office of Director 2pp 15837 168 24X Fiche 50-361.82/10/19.8210280080
- --8210280086 LER 82-114/01T-0 on 821017, during surveillance testing in Mode A.containment cooling fan 2E-402 failed to start Caused by faulty fan breaker Breaker replaced RAY, H B Southern California Edison Co 82/10/19 Region 5, Office of Director 1p 15837 170 24X Fichs 50-361,82/10/19, 8210280080
- T Hearing transcripts on non-antitrust matters
- 8210130209 Transcript of 821006 oral argument in Ban Diego,CA Pp 1-144 \* Atomic Safety and Licensing Appeal Panel 82/10/06 (45pp 15673 126 24X Fiche 50-361.82/10/06.8210130209
- V Operator Examinations
- 8210210184 Summary of 820914 & 20 meetings w/util re util 820802 request that NRC waive required written & oral tests & grant Unit 3 reactor operator & senior reactor operator licenses to currently licensed Unit 2 operators RODD, H Licensing Branch 3 82/10/01 Licensing Branch 3. App 15772 353 24X Fiche 50-361,82/10/01,8210210184
- DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8210290063 Forwards "Evaluation & Action Plan for San Gnofra Nuclear Generating Station Units 2 & 3 re TMI Incident " BRAKE,J H Southern California Edison Co 79/08/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18857-052 24X Fiche 50-361,79/08/16,8210270063

- --8210290049 "Evaluation & Action Plan for San Onofre Nuclear Generating Station Units 2 & 3 re TMI Incident " \* Southern California Edison Co 79/08/31 48pp 15859 054 24X Fiche 50-361,79/08/16.8210290063
- 8210010008 Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents
  Iisted in App A
  FELTON, J M Division of Rules and Records 82/06/28 UDELL, R A
  Critical Mass Energy Project 15pp 15727 005 24X
  Fiche 30-000, 82/06/28, 8210010008
- --800B050265 Discusses add1 required into to better define potential for cracking in reactor vessel noticles
  NODMAN.V 8 Assistant Director for Materials & Qualifications
  Engineering 80/05/05 TEDESCO.R L Assistant Director for Licensing 2p 15727 176 24X Fiche 50-000,82/06/28,8210010008
- 8210050492 Discusses plan of action for issuance of DL Operator licensing & Tech Spec preparation could impact 821015 fool load date Lists areas needing review to determine whether license conditions are required NOVAK,T M Assistant Director for Licensing 82/09/17 FISENHUT.D 0 Division of Licensing 2pp 15626 302 24X Fiche 50-362, 82/09/17.8210050492
- 8210180258 Notification of 820920 meeting w/util in Bethesda.MD to discuss operator staffing & licensing ROOD.H Licensing Branch 3 82/09/17 XERRIGAN.J Licensing Branch 3 4pp 15746 321 24X Fichs 50-362.82/09/17.8210180258
- 8210070164 Forwards evaluation of Unit 2 license conditions relative to potential applicability to Unit 3 license conditions in response to NRC request BASKIN.K P Southern California Edison Co 82/10/04 KERRIGAN.J D Licensing Branch 3 4pp 15627 009 24X Fiche 50-361,82/10/04, 2210/0144
- 821006036B Outlines augmented shift manning requirements for period of initial criticality of Unit 3.for 1-month period after initial attainment of 100% power on Unit 2 & to control rotation of operators between units, per 9207820 meeting DIETCH.R Southern California Edison Co 82/10/05 BENTON. H R Office of Nuclear Reactor Regulation, Director 2pp 15619 053 24% Fiche 50-361,82/10/05.8210060368
- 8210170560 Forwards corrected page to rept re small earthquake swarm which occurred on 811110 Revised info does not alter conclusions stated in rept BABKIN.K P Southern California Edison Co 82/10/15 KERRIGAN.J D Licensing Branch 3 2pp 15736 137 24X Fiche 50-361.82/10/15, 8210170560
- 8210190534 Notifies that info gained during Unit 2 natural circulation test grogram will be incorporated into overall Unit 2 & 3 operating training program.per NUREO-0737. I tem 1 0 i Listed tests will not be repeated for Unit 3

  BABKIN.K P Bouthern California Edison Co 82/10/18 KERRIGAN. J D Licensing Branch 3 2pp 15751 314 24X Fiche 50-361.82/10/18. 8210190534
- F Security, medical, emergency & fire protection plans
- 8210190625 Forwards Revision 7 to physical security plan Revision withheld (ref 10CFR73 21)
  868KIN/K P Bouthern California Edison Co 82/10/15 EIC Office of Nuclear Reactor Regulation, Director 1p 157 24K Fiche. 50-206. 82/10/15. 8210190625
- Q Adjudicatory correspondence
- 8210040009 Notifies that LJ Chandler will represent NRC at or argument.per ASLAB 820908 order SW Perry of FEMA will be available CHANDLER.L J Hearing Branch 2 82/09/24 8HDEMAKER.C J Safety and Licensing Appeal Panel 1p 15581 315 24X Ficher 50-361.82/09/24.8210040009
- 8210050267 Memorandum & order setting medical arrangements qualified questions should be answered by all parties, providing expert testimony where required Issue of termineting procedures will be certified to Commission KELLEY, J. Atomic Bafety and Licensing Board Panel 82/18pp 15611 155 24% Fiche 50-361.82/10/01.8210050267
- 8210040184 Memorandum & order certifying question to Commissifeasibility of ABLB continuing proceeding initiated by ABLI 821001 order
  KELLEY, J. L. Atomic Safety and Licensing Board Panel. 82/1 Commissioners. 4pp 13613 181. 24X Fiche 30~361,82/10/0! 8210040184

- 8210130309 Objections to ASLB 82:001 memorandum & order re medical arrangements Order proposes hearing on issues beyond scope of Commission emergency planning regulations & requires evidence beyond NUREO-0654 stds Declaration of Svc encl PIGOTT.D R Southern California Edison Co PIGOTT.D R Orrick. Herrington & Sutcliffe 82/10/08 Atomic Safety and Licensing Board Panel 11pp 15678 170 24X Fiche 50-361.82/10/08.8210130309
- 8210150454 Position on ASLB request for Commission direction on whether to proceed to hearings Further hearings on medical sycs issue should be deferred pending Commission determination & issuance of guidance Declaration of Syc enc! PIGOTT.D R Bouthern California Edison Co PIGOTT.D R Orrick, Herrington & Sutcliffe 82/10/13 10pp 15703 112 24X Fiche 50~361.82/10/13.8210150454
- 8210150482 Brief re certified questions on definition & implementation of 100FR50 47(b)(12) re medical svcs Applicant interprets 100FR50 47(b)(12) as applying to individuals who are contaminated & traumatically injured. W/Declaration of Svc PIGOTT, D.R. Sauthern California Edison Co. PIGOTT, D.R. Orrick. Herrington & Butcliffe 82/10/13 20pp 15703 008 24X Fichs 50-341, 82/10/13, 8210150482
- 8210150470 Brief re required medical svcs for general public in response to Commission Order CLI-82-27 Agrees w/ASLB re definition of contaminated injured individuals per 10CFR50 47(b) (12) Certificate of Svc encl MCCLUNG.C E GUARD MCCLUNG.C E Gallagher. P M MCCLUNG.C E Flemming. Anderson. McClung.C E Flemming. Anderson. McClung.C E 10/13 34pp 15713 110 24X Fiche 50-361.82/10/13.8210150470
- 8210180095 Brief re medical sycs issues certified by Commission order No advance planning required by 100FR50 47(b)/(12) for medical sycs for general public Necessary arrangements can be made on ad hoc basis Certificate of 8vc encl CHANDLER, L J Hearing Branch 2 82/10/14 Commissioners 24pp 15719 270 24X Fiche 50-361,82/10/14(821018095
- 8210220240 Response supporting util 821008 objections to ASLR 821001 prehearing memorandum & order re medical arrangements 8cheduling of any hearing should await guidance from Commission, resolving centified issues W/Certificate of 8vc CHANDLER, L. J. Hearing Branch 2 82/10/20. Atomic Safety and Licensing Board Panel 7pp 15775 13t 24X Fichs 50-261,82/10/20,821020240
- O Inspection reports: IE Bulletins & correspondence
- 8210060109 Forwards IE Insp Rept 50-362/82-17 on 820823-0903 No noncompliance noted BISHOP: T W Region 5, Office of Director 82/09/16 PAPAY, L T Southern California Edison Co 2pp. 15414 336 24X Fiche 50-362, 82/09/16, 8210060109
- --8210060124 IE Insp Rept 50-362/82-17 on 820823-0903 No noncompliance noted Major areas inspected operational staffing & staff training-comparison of as-built plant to FBAR description, test program records-safety committee & test results SIEWART, J P Region 5, Office of Director KIRSCH.D F Division of Resident, Reactor Project & Engineering Programs 82/09/16 Spp 15614 338 24X Fiche 50-362,82/09/16,8210060109
- 8210010267 Forwards list of open items that require resolution before finding of readinass for operation may be endorsed by Region 5 per Insp Procedure 94300B Licensee established 821115 as fuel load date.
  ENGELMENTR H Region 5, Office of Director 82/09/24 TAYLOR, J M, Division of Resident, Reactor Project & Engineering Programs, 7pp 15573 114 24% Fiche 50-362,82/09/24,8210010267
- 8210010042 Confirms 821021 mgt meeting in Rosemead, CA to discuss systematic assessment of licensee performance Anticipated meeting attendees & agenda encl. CREMBIA L. Division of Resident, Seactor Project & Engineering Programs 82/09/27 PAPAYL. T. Bouthern California Edizon Co. Spp. 15565;317 24X Fiche: 50-206,82/09/27 8210010042
- 8210190478 Forwards IE Insp Repts 50-361/82-27 & 50-362/82-19 on 820905-17 No noncompliance noted BISHOP.T W Division of Resident. Reactor Project & Engineering Programs 82/10/05 PAPAYLLT Southern California Edison Co 4pp 15740:245. 24x Fiche 50-361.82/10/05.8210190478
- --8210190501 IE Insp Repts 50-361/82-27 & 50-962/82-19 on 820905-17. No noncompliance noted Major areas inspected TMI action plan requirements, Unit 2 low power level testing data review & precritical testing data review KIRSGH.D F , MENDONCA.M. Division of Resident, Reactor Project & Engineering Programs. 82/10/05, 14pp 15740; 249 24X Fiche: 50-361, 82/10/05, 82/0190478

- 820B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Speds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safegyards B2/10/06 Consolidated Edison Co of New York 66pp 15761 25 24x Fiche 50-000.82/10/06.8208190233
- 8210250173 Forwards IE Insp Rept 50-362/82-20 on 820913-17 No noncompliance noted 800K.H E Division of Radiological Safety & Safeguards Program 82/10/08 PAPAY.L T Southern California Edison Co 2pp 15787 134 24X Fiche 50-362.82/10/08.8210250173
- --8210250178 IE Insp Rept 50-362/82-20 on 820913-17 No noncompliance noted Hajor areas inspected preoperational radiation protection program, ALARA, environ monitoring program, sqlid, liquid & gassous radwaste mgt & status of NUREG-0737 items CILLIS, N. WENSLAMBKI.F. A. BUDK.H. E. Division of Radiological Safety & Safeguards Program 82/10/08 16pp 15787 136 24% Fichs 50-362,82/10/08.8210250173
- 820819023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall. Large-Diameter. Stainless Steel. Recirculation Sys. Piping at BUR Plants " Svc. list encl.
  DEYOUNG. R.C. Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co. of New York.
  115pp 15810 125 24X Fiche 50-000. 82/10/14.820819023B
- 8210250222 Ack receipt of 820929 ltr informing NRC of steps taken to correct violations noted in IE Insp.Repts 50-361/82-25 & 50-362/82-16
  BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/10/18 PAPAYL, T Southern California Edison Cn: 15789 326 24X Fiche 50-361.82/10/18.8210250222
- --8210250227 Responds to NRC 820831 ltr re violations noted in It In Repts 50-361/82-25 & 50-362/82-16 Corrective actions Operating Instruction 5023-2-4 revised on 820831 to include proper caution PAPAY, LT Southern California Edison Co 82/09/29 ENGELMEN.R H Region 9, Office of Director 4pp 15789 327 ; Fiche 50-361, 82/10/18, 8210850222
- 8 Reportable occurrences, LERs & related correspondence
- B210190250 PND-V-82-041 on B21006.Los Angeles Times investigative reporter contacted Region 5 re former Bechtel Power Corp 60 inspector addl allegations concerning welding practices Investigation of allegations planned KIRBCH, D F, DISHOP, T W Region 5, Office of Director 19 15742 195 24X Fiche 50-361,68710714,88210190250
- T Hearing transcripts on non-antitrust matters
- 8210130209 Transcript of 821006 oral argument in San Diego, CA Pp 1-lA \* Atomic Safety and Licensing Appeal Panel 82/10/06 145pp 15673 126 24% Fiche 50-361,82/10/06.8210130209
- V Operator Examinations
- 8210210184 Summary of 820914 & 20 meetings w/util re util 820802 request that NRC waive required written & oral tests & grant Unit 3 reactor operator & senior reactor operator licenses to currently licensed Unit 2 operators ROBD: H Licensing Branch 3 82/10/01 Licensing Branch 3 6pp 15772 353 24% Fishe 50-361,82/10/01,8210210184
- DOCKET 50-363 FORKED RIVER NUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 8210070102 Forwards info resolving 14 Tech Spec open items discussed at 820913 meeting Marked-up Tech Specs encl BABKIN, K P Southern California Edison Co B2/10/04, KERRIGAN, J Licensing Branch 3 36pp 15649 244 24X Fiche 50~363,82/10/04. B210070102
- DOCKET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- B210010008 Responds to FDIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTQN.J M Division of Rules and Records. B2/06/28 UDELL.R A Critical Mass Energy Project 13pp 18727 008 24X Fiche: 30-000, 82/06/28.8210010008

- --8008050265 Discusses addl required info to better define potential for cracking in reactor vessel notiles NDONAN, V S Assistant Director for Materials & Qualifications Engineering 60/05/05 TEDESCO.R L Assistant Director for Licensing 2pp 15727 176 24X Fiche 50-000.82/06/28.8210010008
- F Security, medical, emergency & fire protection plans
- S210010196 Ack receipt of B20B27 ltr re emergency exercise scheduled for Feb 1983
  STONR, J. Division of Emergency Preparedness & Operational Support B2/09/17 MLDDNALD R P. Alabama Power Co. 1p. 19570-360 24X
  Fiche 50-348
- B210010195 Forwards Revisions 4 ? 5 to security plan Revisions uithheld
  CLAYTON.F L. Alabama Power Co. 82/09/21 VARGA.S A. NRC No Detailed Affiliation Given ip 15567 313 24X
  Fiche 50-348, 82/09/21, 8210010195
- B210190066 Releases public version of revised emergency plan implementing procedures
  FELTON. J M Division of Rules and Records B2/10/01 Document Management Branch 1p 15761 060 24X Fiche 50-34B.B2/10/01. (2210190066
- E210180004 Forwards IE Safeguards Insp Repts 50~348/82-23 & 50~364/82-22 on 820921-24 No noncompliance moted VERRELLI.D Division of Project & Resident Programs 82/10/12 MCDDMAD.R P Alabama Power Co 2pp 15720 025 24% Fiche 50~348,82/10/12,8210180004
- --B210180007 IC Safeguards Insp Repts 50-348/82-23 & 50-364/82-22 on B20921-24 No noncompliance noted Major areas inspected security plan & implementing procedures & security organization Details withheld (ref 10CFR73 21) STANSBERRY, W Division of Engineering & Technical Programs 82/10/08 1p 15720 027 24X Fiche 50-348,82/10/12,8210180004
- ©210280158 Application for amend to Licenses NPF-2 & NPF-8, revising Tech Specs to require audit on emergency preparadness program every 12 months, per 1007850 54(t) & Generic Ltr 92-17 No Amend fee required SER encl CLAYTON, FL Alabama Power Co 82/10/25 VAR9A, S A Office of Nuclear Reactor Regulation, Director 2pp (5837-174 24X Fiche 30-348, 82/10/25, 8210280158
- ---8210280165 Proposed Tech Specs, Soction 6 5 2 8 requiring audit of emergency preparadness every 12 months, per 10CFR50 54(t) & Generic Ltr 82-17

  A Alabama Power Co 82/10/25 3pp 15837 176 24X fishe 50-348,82/10/25.8210280158
- M Antitrust correspondence
- B210060179 Notifies of Debevoise & Plimpton change of address as of 821001 Affirmation of Byc encl # Debevoise & Plimpton B2/10/01 3pp 15614 108 24X Fishe 50-348.82/10/01.8210060179
- P Operating license stage documents & correspondence
- B210010227 Confirms B20820 telcon arrangements re B20730 meeting w/util in Region 2 ofc to discuss fuel rod degradation resulting from baffle water-yet impingement Proposed agenda enci O'REILLY, J P Region 2, Office of Director B2/09/03 MCDONALD, R P Alabama Power Co 2pp 15567 336 24X Fiche 50-348, B2/09/03, 8210010827
- 6210040038 Forwards Amend 17 to License NPF-8, safety evaluation & notice of issuance & availability Amend extends for one-time only-visual surveitlance interval for inaccessible hydraulic snubbers until 821022 refueling outage REEVES,E A Operating Reactors Branch 1 82/09/22 CLAYTON.F L Alabama Power Co 2pp 15577 264 24X Fiche 50-364,82/09/22,8210040038
- ---8210040039 Amend 17 to License NPF-B, extending for one-time only.

  visual surveillance interval for inaccessible hydraulic
  snubbers until next refueling outage scheduled to begin
  821022

  VARGA. B A Operating Reactors Branch 1 82/09/22 4pp
  15577 266 24X Fiche 50-364, 82/09/22, 8210040038

- --8210040040 Safety evaluation supporting Amend 17 to License NPF-8 + Office of Nuclear Reactor Regulation, Director B2/09/22 Spp 15577 270 24X Fiche 50-364.82/09/22.8210040038
- ~-8210040041 Notice of issuance & availability of Amend 17 to License NPF-8 VARGA, S A Operating Reactors Branch 1 82/09/22 2pp 15577 273 24% Fiche 50~364,82/09/22,8210040038
- B210050066 Commits to functional testing of circuit breakers, completing outstanding issue or B20726 request for extension of License Condition 2 C (19)(b)
  CLAYTON, F L Alabama Power Co B2/09/27 VARGA, B A Office of Nuclear Reactor Regulation, Director 2pp 15603 227 24X
  Fiche 50-364, 82/09/27, 8210050066
- B210050089 Informs that installation of water tight fittings on Victoreen radiation detectors per TMI Action Item II F i will be delayed until next refueling outage.contingent upon receipt of mati
  CLAYTON.F L. Alabama Power Co. B2/09/30 VARGA.S A. Office of Nuclear Reactor Regulation, Director 3pp. 15604 241 24X
  Fiche 50-364.82/09/30.8210050089
- 8210130527 Forwards proprietary & nonproprietary versions of "Evaluation of Impact of Reduced Testing of Turbine Valves." WCAP-10161 & WCAP-10162, respectively Proprietary version withheld (ref 10CFR2 790) CLAYTON, F.L. Alabama Power Co. 82/10/08 VAROA, S.A. Office of Nuclear Reactor Regulation, Director Spp. 15683 006 24X Fichs 50-364,82/10/08,8210130527
- --8210130535 Nonproprietary version of "Evaluation of Impact of Reduced Testing of Turbine Valves" RAHE, E P Westinghouse Electric Corp WCAP-10162 82/09/30 77pp 15683 011 24X Fiche 50-364,82/10/08,8210130527
- 8210150338 Application for one-time change to Tech Spec 3/4 4 7 2. modifying leak test acceptance criteria Change necessary to preclude potential for delay in return to power from refueling outside CLAYTON.F.L. Alabama Power Co. 82/10/11 VARGA.S.A. Office of Nuclear Reactor Regulation, Director 5pp 15705 344 24X Fiche 50-364.82/10/11.8210150338
- --8210150344 Proposed Tech Spec Pages 3/4 4-17 & 3/4 4-19 re RCS operational leakage & RCS pressure isolation valves Safety evaluation encl
  + Alabama Pawer Co 82/10/11 App 15705 351 24X Fiche 50-364,82/10/11,8210150338
- 8210250090 Application to amend License NPF-8, deleting license conditions redundant to generic regulatory items Change does not involve unreviewed safety question Safety evaluation encl
  CLAYION.F L Alabama Power Co 82/10/19 VARQA.S A Office of Nuclear Reactor Regulation. Director 8pp 15787 101 24X
  Fiche 50-364,82/10/19,8210250090
- 8210260418 Advises that util confident that current emergency procedure provides adequate guidance for cooldown under natural circulation conditions Full compliance w/License Conditions 2 C (9)(b) & 2 C (12)(c) demonstrated CLAYTON.F L Alabama Power Co 82/10/21, VARGA, 8 A Office of Nuclear Reactor Regulation, Director. 2pp 15806 315 24X Fichs 50-364,82/10/21,8210260418
- B210260437 Bubmits final documentation of full compliance w/License Condition 2 C (12)(b) re safety-grade means for RCS depressurization per Technical Posttion RBS 5-1.Revision 1 CLAYTON.F L Alabama Power Co B2/10/21 VAROA.S A Office of Nuclear Reactor Regulation. Director 2pp 15806 244 24X Fiche 50-364.82/10/21.8210260437
- B210280282 Advises that revised Westinghouse performence Gode PAD-3 3 as described in MCAP-B270. Addendum 1, adequately defines fuel burnup for successive fuel cycles CLAYTON.F L Alabama Power Go 82/10/22 VARGA.S A NRC No Detailed Affiliation Given ip 15837 043, 24% Fiche 50-344.82/10/22,8210280282
- 8210280158 Application for amend to Licenses NPF-2 & NPF-8, revising Tech Specs to require audit on emergency preparedness program every 12 months, per 10CFR50 54(t), & Generic Ltr 82-17 No amend fee required SER encl CLAYTON, FL Alabama Power Co 82/10/25 VAROA, B. A Office of Nuclear Reactor Regulation, Director 2pp 15837 194 24X Fiche. 50-348, 82/10/25, 8210280158

- --8210280165 Proposed Tech Specs. Section 6.5 2 8 requiring audit of emergency preparedness every 12 months, per 10CFR50 54(t) & Generic Ltr 82-17

  \* Alabama Power Co. 82/10/25 3pp. 15837 196 24X
  Fichs 50-348, 82/10/25, 8210280158
- Q Inspection reports: IE Bulletins & correspondence
- 9210070007 Responds to FOIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FOIA Request 81-313 Forwards documents listed in App B FELTON.J M Division of Rules and Records 82/08/10 LONG.D J

FELTON. J M Division of Rules and Records 82/08/10 LONO, D J Hinthrop, Stimson, Putham & Roberts 9pp 15645 063 24X Fiche 50-000, 82/08/10, 8210070007

- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VAROA.8 Operating Reactors Branch 1 3pp 15645 131 24X Fiche 50-000, 82/08/10, 82:0070007.
- 8210010204 Forwards IE Insp Repts 50-348/82-21 & 50-364/82-20 on 820802-06 No nancompliance noted DANCE, H C Region 2. Office of Director 82/08/30 HCDONALD, R P Alabama Power Co 2pp 15567 334 24X Fiche 50-348, 82/08/30, 8210010204
- --8210010208 IE Insp Repts \$0-348/82-21 & 50-364/82-20 on 820802-06 No noncompliance noted Major areas inspected pipe supports & restraints & Types B & C containment leak rate testing BROOKS E : JAPE F Division of Engineering & Technical Programs 82/08/25 4pp 15567 316 24% Fiche 50-348,82/08/30,8210010204
- 8210010043 Concurs w/actions outlined in util 920812 ltr re insparequired by IE Bulletin 79-13-except in areas of re-radiographing steam generator feedwater nozile-to-pipe & weld retention of records
  LEWIS.R C Division of Project & Resident Programs 82/09/13 MCDONALD.R F Albama Power Co 2pp 15570 361 24X
  Fiche 50-348.82/09/13.8210010043
- 82101\$0072 Ack receipt of B20909 itr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-388/82-17 &
- ~~8210190074 Responds to NRC 820818 itr re-violations noted in IE Insp. Repts 50-364/82-19 & 50-364/82-18 Corrective actions Form NRC-3 posted at low level radwaste bldg CLAYTON,F L Alabama Power Co 82/09/09 DANCE,H C Region 2, Office of Director 2pp 15701 254 24X Fiche 50-348,82/10/04,82(0150072
- ~~B210150078 Forwards IE Insp Repts 50-348/82-19 & 50-364/82-18 on 820720-30 & notice of violation DANCE.H C Division of Project & Resident Programs 82/08/18 HDD0NALD.R P. Alabama Power Co 2pp 15701 256 24% Fiche 50-348,82/10/04,8210150072
- --8210190082 Notice of violation from insp on 820724-30 \*\* Division of Project & Resident Progrems 82/08/18 tp 15701.258 24x Fiche 50-348.82/10/04.8210150072
- --8210150086 IE Insp Repts 50-348/82-19 & 50-364/82-18 on 820726-30 Noncompliance noted Form NRC-3. "Notice to Employees," not posted in new low level waste storage facility FEERY, M. M. BARR. K. P. Division of Engineering & Technical Programs 82/08/16 5pp 15701 259 24X Fiche 50-348,82/10/04, 8210150072
- 8210220229 Forwards IE Insp Repts 50-348/82-22 & 50-364/82-21 on 820816-0915 No noncompliance noted. DANCE:H C Division of Project & Resident Programs 82/10/04 MCDONALD.R P Alebama Power Co 2pp 15776 233 24X Fichs 50-348, 82/10/04, 8210220229
- --8210220232 IE Insp Repts 50-348/82-22 & 50-344/82-21 on B20Bi6-0915 No noncompliance noted Major areas inspected; monthly surveillance & maint observation operational safety verification.plant trips & LERs BRADFORD, M. H. BROWNLEE, V.L. Division of Project & Resident Programs B2/10/04 7pp 15776 235 24X Fiche 50-348, 82/10/04, 8210220229,
- B208190233 IF Info Notice 80-35. Suppl 1. "Leaking & Dislodged I-125 Implant Seeds " Svc list encl. COBB.L. I Division of Fuel Facilities. Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fithe 30-000.82/10/06.8208190233

- 8210180004 Forwards IE Sareguards Insp Repts 50-348/82-23 & 50-364/82-22 on 820921-24 No nuncompliance noted VERRELL(,D Division of Project & Resident Programs 82/10/12 MCDQNALD,R P Alabama Power Co 2pp 15720 025 24% Fiche 50-348, 82/10/12, 8210180004
- --8210180007 IE Safeguards insp Repts 50-348/82-23 \$ 50-364/82-22 un 820921-24 No noncompliance noted Major areas inspected security plan & implementing procedures & security organization betails withheld (ref 100FR73 21) STANSBERRY, W W MCGUIRE, D R Division of Engineering & Technical Programs 82/10/08 lp 15720 027 24X Fiche 50-348,82/10/12,8210180004
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BUR Plants " Svc list encl OEYOUNG, R C Director's Office, Office of Inspection and Enforcement 62/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- 8210280410 Notification of 821029 meeting w/util Franklin Research (tr. bechtel in Bethesda MD to review calculations & methodology re [E Bulletin 80-tl. "Masonry Walls" REEVES, E.A. Operating Reactors Branch | 82/10/20 VARGA, S. Operating Reactors Branch | 82/10/20 VARGA, S. Fiche 50-348, 82/10/20, 8210280410
- R Periodic operating reports & related correspondence
- 8210190767 Forwards monthly operating rept for Sept 1982 CLAYTON,F L Alabama Power Co B2/10/12 Management Information Branch 1p 19734 238 24% Fiche 50-364,82/10/12,821019076*)*
- --8210190773 Monthly operating rent for Sept 1982 HAIRSTON H O Alabama Power Co 82/10/04 Bpp 15736 239 24) Fiche 50-364,82/10/12:8210190°67
- 5 Reportable occurrences, LERs & related correspondence
- 9210070111 Reviews purge valve info contained in T Austin 810306 memo Primary technical issue relates to valve operability during expected accident conditions Vital areas of concern not addressed in info include lower torque margin for closure DROMNE J Director's Office 81/09/24 MICHELBON C Director's Office 4pp 15646 359 24X Fichs 50-348.81/09/24,8210070111
- 8210010008 Respands to FOIA request for 17 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mase Energy Project 15pp 15727 005 24x Fichs 50-000.82/06/28.8210010008
- --8210090124 Summary of Bi0610 operating reactor events meeting LAINAS.0 C Assistant Director for Safety Assessment 81/06/1/EISENRUT, D G Division of Licensing 5pp 15729 217 24X Fiche 50-000,82/06/28.8210010008
- 8210010129 Forwards LER: 82-037/03L-0 & 82-052/03L-0 CLAYTON: F L Alabama Power Co 82/09/27 Region 2, Office of Birector 1p 18567 227 24% Fich: \$0-340:82/09/27.8210010129
- ---\$210010147 LER 82-037/03L-0 on 820905.A train auto trip logic for high steam generator differential pressure declared inoperable when failed cord indication received by automatic tester Causad by failure of universal card Card replaced HAIRBTON, W Q Alabama Power Co 82/07/27 Region 2, Office of Director 1p 15967 289 24X Fiche 50-348.82/09/27.8210010129
- 8210260453 Forwards LERs 82-054/03L-0182-055/03L-0,82-037/03L-0 82-040/03L-0 CLAYYON,F L. Alabama Power Co. 82/10/18 Region 2, Office of Director ip 15806 195 24X Fiche 50-348/82/10/18/8210260453
- --8210260480 LER 82-039/03L-0 on 820919, svc water to component cooling water HX 2C isolated Caused by dislodged pin holding worm drive year allowing differential pressure across valve disc to close valve Pin reinstalled & secured HAIRSTON. W 0 Alabama Power Co 82/10/18 Region 2, Office of Director ip 15806 198 24X Fiche, 50-348, 82/10/18, 8210260453
- --8210260490 LER 82-040/03L-0 on 820919, loss-of-voltage protection channel associated w/B2F sequencer phase 2-3 doclared inoperable Caused by failure of loss-of-voltage relay 27XF1 during testing Relay cleaned HAIRSTON, H. O. Alabama Power Co. 82/10/18 Region 2, Office of Director Ip. 15806 199 24X Fichs 50-348,82/10/18,8210260455

- 용교 10290289 Forwards LER 82-033/03L-1 CLAYTON.F L Alabama Power Co 82/10/19 Region 2. Office of Director 1p 15894 073 24% Fiche 50-364.82/10/19.8210290289
- -- B210270292 LER 82-033/03L-1 on 820817, breaker to containment isolation valve inadvertantly opened Caused by personnel error white implementing tagging order Breakers positioned & returned to svc
  HAIRSTON.W Q Alabama Power Co 82/10/19 Region 2, Office of Director Ip 18854-0/4 24X Fiche 50-364, 82/10/19.8210270289

COCKET 50 366 EDWIN 1 HATCH NUCLEAR PLANT, UNIT 2

F Security, medical, emergoncy & fire protection plans

- ₽≥10060275 Application to amend License NPF-5, deleting App A Tech Specs on bidg settlement & withdrawing 781201,790814 & 1008 submittals re differential & total settlement values based on consolidation settlement BECKHAM. J T Georgia Power Co 82/09/27 Office of Nuclear Reactor Regulation. Director 5pp 15621 172 24% Fithe 50-366, 82/09/27, 8210060275
- --8210060278 Tech Specs 3/4 7 7 re penetration fire barriers 4 Georgia Power Co 82/09/27 ip 15621 177 24X Fiche 50 366.82/09/27.8210060275
- E-210190013 Releases public version of revised emergency plan implementing procedule FELTCN.JM Division of Rules and Records 82/09/29 Document flanagement Branch ip 15760 328 24X Fiche 50-321.82/09/29, 8210190013
- --8210190016 Forwards public version of Revision 4 to Emergency Plan [mplementing Procedure HNP-8026, "High Radiation Area Entrance Control " SORRELL,E C Georgia Power Co 82/09/23 Office of Nuclear Reactor Regulation, Director 1p 15760 329 24X Fiche 50-321,82/09/29,8210190013
- --82(01700)7 Public version of Revision 4 to Emergency Plan Implementing Procedule HNP-8026. "High Radiation Area Entrance Control" « Georgia Power Co 82/07/22 12pp 15760 330 24% Fiche 50-321,82/07/29,82(01700)3
- © 210190042 Releases public version of pages to emergency plan FELTON.J M Division or Rules and Records 82/10/01 Document Management Branch 1p 15761 037 24X Fiche 50-021.82/10/01, 8210190042
- 8210170046 Forwards public version of Pages M-1 & M-2 to emergency plan SURRELLE C Georgia Power Co 82/09/22 Office of Nuclear Reactor Regulation. Director 1p 15761 038 24X Fiche 50-321,82/10/01.8210190042
- --8210190051 Public version of Pages M-1 & M-2 to emergency plan \* Georgia Power Co 82/03/31 App 15761 039 24X Fiche 50-321,82/10/01,8210190042
- E321080227 Forwards IE Sateguards Insp Repts 90-321/82-31 & 50-366/82-29 on 820920-23 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/10/06 RELLY.R J Georgia Power Co 2pp 15638 057 24X Fiche 50-321, 82/10/06, 8210080227
- ---8210080228 IE Safeguards Insp Repts 50-321/82-31 & 50-344/82-27 on 820920-23 No noncompliance noted Major areas inspected physical barriers, lighting, assessment aids, detection aids, access control & vehicles Details withheld (ref 100FR/3 21) MODRE, D E Division of Engineering & Technical Programs 82/10/05 1p 15638 059 24X Fiche 50-321, B2/10/06, 8210080227
- P Operating license stage documents & correspondence
- ©210060275 Application to amend License NPF-5, deleting App A Tech Specs on bldg settlement & withdrawing 781201.790814 & 1008 submittals re differential & total settlement values based on consolidation settlement BECKHAM. J T Georgia Power Co €2/09/27 Office of Nuclean Reactor Regulation, Director 5pp 15621 172 24X Fiche 50-366. 52/09/27. 8210060275
- ---8210060278 Tech Specs 3/4 / 7 re penetration fire barriers a Georgia Power Co 82/09/27 lp 15621 177 24X Fiche 50-366, 82/09/27, 8210060275

- 8210050330 Forwards schedule for qualification testing of analog transmitter trip sys.in response to 801001 request GUCHALL T. Georgia Power Co. 82/09/28 EISENHUT.D.G. Office of Nuclear Reactor Regulation, Director 3pp 18610 288 24X Fiche 50-321.82/09/28.8210050330
- 8210060231 Forwards remittance & copies omitted from 820927 ltr re bldg settlement BECKHAMIJ V Georgia Power Co 82/10/01 Office of Nuclear Reactor Regulation, Director fp 15620 012 24X Fiche 50-366,82/10/01,8210060231
- 8210120047 Application to amend App A of License NPF-5, changing Tech Spec Figures 3 2 3-1 & 3 2 3-2 to reflect changes in operating limit min critical power ratios resulting from reanalysis of pressurriation transients by GE BECKHAH. J T Quorgia Power Co 82/10/04 Office of Nuclear Reactor Regulation. Director 29p 15651 242 24X Fiche 50-366. 82/10/04. 8210120047
- --8210120050 Proposed Tech Spec Figures 3 2 3-1 & 3 2 3-2, reflecting changes in operating limit min critical power ratios \* Georgia Power Co 82/10/04 3pp 15651 244 24X Fiche 50-366,82/10/04,8210120047
- 8210220270 Forwards corrected Page 6-4 for 820611 Tech Spec change request re designation of unit status for shift manning requirements Original submittal inadvertently reversed OUCHALL T Georgia Power Co 82/10/15 Office of Nuclear Reactor Regulation, Director ip 15775 049 24X Fichs 50-366,82/10/15,8210220270
- --8210220278 Corrected Page 6-4 to 82061; Tech Spec change request re designation of unit status for shift manning requirements # Georgia Power Co 82/10/15 ip 15775 050 24X Fiche 50-364,82/10/15.8210220270
- Q inspection reports, [E Bulletins & correspondence
- 8210010113 Forwards IE Insp Repts 50-321/82-26 & 50-366/82-25 on 820809-13 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/07 KELLY,R J Georgia Power Co 2pp 15567 206 24X Fiche 50-321,82/09/07,8210010113
- --8210010118 IE Insp Repts 50-321/82-26 & 50-366/82-25 on 820809-13 No noncompliance noted Major areas inspected lab GC program. chemistry & radiochemistry procedures, airborne effluent sampling & accountability & mobile lab EVANS.C D . MONTGOMERY.D M Division of Emergency Prepared noss & Operational Support 82/09/02 11pp 15567 208 24x Fiche 50-321,82/09/07.8210010113
- 8210010309 Forwards IE Insp Repts 50-321/82-28 & 50-366/82-26 on 820727-0827 No noncompliance moted DANCE, H C Division of Project & Resident Programs 82/09/10 KELLY, R J Georgia Power Co 2pp 19568 274 24X Fichs 50-321, 82/09/16, 8210010309
- --8210010327 IE Insp Repts 50-321/82-28 & 50-364/82-26 on 820727-0827 No noncompliance noted Major areas inspected Tech Spec compliance noted Major areas inspected Tech Spec compliance, operator performance, overall plant operations, GA practices & station & corporate mgt practices as tation & corporate mgt practices ROSERS, R F , HOLMES-RAY, P , BROWNLES, V L Division of Project & Resident Programs 82/09/10 App 15368 276 24% Fichs 50-321,82/09/10.8210010309
- 8210010019 Ack receipt of 820907 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-321/82-19 O'REILLY, J P Region 2. Office of Director 82/09/16 KELLY, R J Georgia Power Co 1p 15565 300. 24X Fiche 50-321,82/09/14, 8210010019
- --8210010022 Responds to NRC 820806 ltr re violations noted in IE Insp Repts 50-321/82-19 & 50-366/82-19 Corrective actions procedures being revised to include tighter controls on changes to fuel movement data packages BECKHAM, J T Georgia Power Co 82/09/07 Q'REILLY, J P Region 2, Office of Director 3pp 15565-301 24X Fiche 50-321, 82/09716,8210010019
- --8210010025 Forwards IE Insp Repts 50-321/82-19 & 50-366/82-19 on 820421-0525 & notice of violation O'REILLY, J P Region 2. Diffice of Director 82/08/06 KELLY, R J Georgia Power Co 2pp 15565 304 24X Fiche 50-321, 82/09/16, 8210010019

- ~~8210010031 IE Insp Repts 50-321/82~19 & 50-364/82-19 on 820421-0525 Nuncompliance noted fuel loaded into core w/o all control rods fully inserted ROGERS.R F. Division of Project & Resident Programs BROWNLEE, V. L. Region 2. Office of Director 82/07/29 7ap 15555 307 24x Fiche 50-321.82/09/16.8210010019
- 8210040047 Ack receipt of check in payment of civil penalty proposed on 820713 Corrective measures described in 820812 & 0907 ltrs will be examined in future insp AXELRAD. J A Director's Office Office of Inspection and Enforcement 82/09/23 KELLYR J Georgia Power Co 2pp
  - 15577 290 24X Fiche 50-321,82/07/23,8210040047
- 820B190233 |E info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Syc list encl COBD.L I Division of Fuel Facilities, Materials & Safeguards B2/10/06 Consolidated Edison Co of New York 44pp 15751 250 82/10/06 Consolidated Edison Co of New York 66pp 24X Fiche 50-000, 92/10/06, 8208(90233 15741 250
- 8210080227 Forwards IE Safeguards Insp Repts 50-321/82-31 & 50-366/82-29 on 820920-23 No noncompliance noted DANCE: H C Division of Project & Resident Programs 82/1 KELLY, R J Georgia Power Cq 2pp 15638 057 24X Fiche 50-321.82/10/06.8210080227
- ---8210080228 IE Safeguards Insp Repts 50-321/82-31 & 50-366/82-29 on 820920-23 No poncompliance noted Major areas inspected physical barriers, lighting, assessment aids, detection aids, access control & vehicles Details withheld (ref 10CFR73 21) MOORE, D.E. MCGUIRE, D.R. Division of Engineering & Technical Programs 82/10/05 ip 15638 059 24% Fichs 50-321,82/10/06,8210080227
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list enc!

  DEYQUNO.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- 8210220277 Ack receipt of 820927 ltm informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/82-24 & 50-366/82-22 LEMIS.R C Division of Project & Resident Programs KELLY.R J Georgia Power Co 1p 15775 028 24X Fithe 50-321, 82/10/14,8210220277
- --8210220267 Responds to NRC 820823 ltr re violations noted in IC Insp. Repts S0-321/62-24 & 50-364/82-22 Corrective actions written plan will be prepared to schedule & integrate lecture series to meet additeraining needs.
  GUCMAL T Georgia Power Co. 82/09/27 O'REILLY. J.P. Region 2. Office of Director 4pp 15775 029 24X Fishe 50-321,82/10/14, 6210220277
- --8210220292 Forwards 1E Insp Repts 50-321/82-24 & 50-366/82-22 on B20726-30 & notice of violation LEMIS R C Division of Project & Resident Programs KELLY-R J Georgia Power Co 2pp 15775 033 24X Fiche 30-321,82/10/14.8210220277 82/08/23
- ---8210220299 Notice of violation from insp on 820724-30 4 Division of Project & Resident Programs 82/08/23 2pp 15775 035 24X Firbs 50-321.82/10/14.8210220277

- S Reportable occurrences, LERs & related correspondence
- 6210120171 Discusses 610406 discovery that undervoltage relays of second offsite source would not operate, preventing closure second dissel generator breakers Licensee will be proposing design mod to correct problem of non-Class IE interlock CHIRAMAL.M Director's Office 81/04/21 Director's Office 82/04/21,8210120171
- 621001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A Fisher 50-000, 82/06/28, 8210010008 82/06/28 UDCLE.K A
- --8104270103 Discusses IE daily rept for 810406 re alternate offsity source interlock w/emergency diesel generators at Unit 1 Licensee will propose mod to correct non-Class IF interlock preventing automatic operation of safety sys CHIRAMAL, M Director's Office 81/04/21 Director's Office 3pp 15727 041 24X Fiche 50-000.82/06/28.8210010008
- --9210010083 Recommends ACRS action on recent LERs in HPCI failure to auto start after MSIV failure & single cooling supply line on RHR pump motors BOEHRERT,P ACRS Advisory Committee on Reactor Safeguard's 80/06/13 KERR.W ACRS Advisory Committee on Reactor Safeguards 1p 15727 138 24X Fiche 50-000.82/06/28.8210010000
- --8210010089 Discusses failures of HPCI & RCIC sys subsequent to 790601 event culminating in 790627 loss of both sys BBEHNERT.P ACRE Advisory Committee on Reactor Safeguards 79709706 KERR W ACRS Advisory Committee on Reactor Safeguards 2pp 15727 142 24X Fiche 90-000.82706728.
- --8210010095 Forwards PNO-79-139 re faiture of RCIC & HPCI sys following Jow Water level reactor scram

  BOEHNERT, P ACRE - Advisory Committee on Reactor Safeguards

  79/06/29 KERR, W ACRE - Advisory Committee on Reactor

  Safeguards 1p 15727 t44 24X Fiche 50-000.02/06/28.8210010008
- --8210010099 Requests detailed rept on PNO-79-139 re failure of backup tore cooling sys Generic implications required

  KENNEDY,R T Commissioners 79/06/07 ODESICK, C V Office of
  the Executive Director for Operations 1p 1972/ 153 24X Fiche 50-000,82/06/28,8210010008
- --B210010105 Reiterates 790407 request for detailed rept re failure of backup core cooling sysper PND-79-139 & PND-79-196
  Response requested by 790703
  KENNEDY.R T Commissioner 79/07/02 GDSSICK.L V Office of the Executive Director for Operations 1p 15727 154 24X
  Fiche 50-000,02/06/28.0210010008
- --B210010109 Forwards response to 790607 request for info re failure of backup cooling sys Corrective measures will be followed to assure reliable state of operational readiness STELLD.V Office of Inspection & Enforcement, Office of the Director 79/07/02 KENNEDY:R T Commissioners 5pp 15727 157 24X Fiche 50-000.82/06/28,8210010008
- ---B210040367 Requests info re LER 80-111/03L-0 concerning isolation of HPCI sys at facility Nature of nonrepetitive event HPUT sys at facility Nature of nonrepetitive event questioned MDELLER.D W ACRS - Advisory Committee on Reactor Safeguards 80/09/16 MCCRELESS.T ACRS - Advisory Committee on Reactor Safeguards 2pp 15727 261 24X Fiche 50-000.82/06/28, 8210010008
- 82:00:0094 Forwards LER 82-083/03L-0 NIX.H C Deorgia Power Co 82/09/21 O'REILLY, J P Region 2, Office of Director 1p 15565 256 24X Fiche 50-366, 82/09/21, 82:00:100:0094
- --8210010098 LER 82-083/03L-0 on 820825.w/plant in hot shutdown.reactor Altonoral Let M2-983/03.-0 on 820825, w/plant in hot shutdown, reacts bldg to suppression chamber vacuum breaker had no closed indication & declared inoperable Caused by lonse limit switch mount bracket & out of adjustment actuator TIPPS, B B Georgia Power Co 82/09/21 Region 2, Office of Director 2pp 15565 257 24% Fiche 50-366,82/09/21,8210010094
- 82:0050080 Forwards LER 82-091/03L-0 NIX.H C Georgia Power Co 82/09/23 O'REILLY.J P Region 2, Office of Director ip 15604 252 24X Fiche 50-366,82/09/23.

- -8210050084 LER 82-091/03L-0 on 820825, during scram recovery, H ADS safety relief valve failed to open manually & diywell pressure & temp exceeded Tech Specs Cause unknown Pressure & tenp returned to allowable levels 11PPS: S B Georgia Power Co 82/09/23 Region 2, Office of Director 2pp 15604 253 24X Fiche 50-364.82/09/23,8210050080
- B210060246 Forwards LER 82-090/03L-0 NIX.H C Georgia Power Co 82/09/23 O'REILLY, J P Region 2, Office of Director 1p 15619 317 24X Fiche 50-366, 82/09/23,
- --8210060248 LER 82-090/03L-0 on 820831, during quarterly surveillance, B oxygen analyzer failed to calibr due to instrument rluctuation Caused by worm pump head assembly on sample pumps Upper " lower pump heads replaced Analyzer recalibr BULNER, H.C. Georgia Power Co. 82/09/23 Region 2, Office of Director 2pp 15619 J18 24X Fiche 50-366, 82/09/23, 8210060244
- 8210040287 Forwards LER 82-100/031-0 N(X,H C Georgia Power Co 82/09/23 O'REILLY, J P Region 2, Giftce of Director 1p 15619 213 24X Fiche 50-366,82/09/23,
- -8210000289 LER 82-100/03L-0 on 620828, while performing RCIC turbine enhanced disphragm pressure instrument FTAC procedure, two inspectative switches discovered Caused by component failure due to water damage Switches replaced TIPPS.5 S Georgia Power Co 82/09/23 Region 2, Office of Director 2pp 15019 214 24X Fishe 50-366, 82/09/23, 6210060287
- 8216060317 Forwards updated LER B2-079/03X-1 Nfx.H C Georgia Power Co 82/09/23 O'REILLY.J P Region & Office of Director 1p 15618 J45 24X Fiche 50-366.82/09/23. 0210060317
- 8210060324 Updated LER 82-079/03X-1 on 820727.diesel generator C tripped after 37 minutes of normal operation during surveillance test Caused by failure of connecting rod Solver Tanke (1882 cases by Allore by Connecting Flow TIPPS, S.B. Georgia Power Co. 82/09/23 Region 2, Office of Director 2pp 15418 346 24% Fiche 50-346, 82/09/23, 8210040317
- 6210080834 Forwards LER 82-102/03L-0 N14,H C Georgia Powor Co 82/09/28 O'REILLY, J.P. Region 2: Difice of Director 1p 15638-074 24X Fiche 50-366,82/09/28,
- --8210090240 LER 82-102/03L-0 on 820830. w/unit steady-state at 2,258 NWT. elogoe40 Len 82-1027031-0 on Bave30.b/mit steady-state at 2,238 f discovered 820812 scheduled monthly fire hose station safety-related areas surveillance procedure not completed before 820819 grace period expiration TIPPS:8 8 Georgia Power Co 82/09/28 Region 2, Office of Director 2pp 15638-075 24X Fiche 50-366,82/09/28,8210080234
- 3210130183 Forwards LER 62-101/03L 0 NI4, H C Georgia Power Co 82/09/28 O'REILLY, J P Region 2, Office of Director ip 15673 009 24X Fiche 50-366,82/09/28.
- --8210130185 LER 82-101/03L 0 on 820829, inboard MSIV in loop C failed closed Caused by improper stem to disk thread engagement Disk & stem assembly replaced in both C loop MSIVs Valves tested & returned to svc TIPPS:S B Georgia Power Co 82/09/28 Region 2. Office of Director 2pp 15673 010 24% Fiche 50-366.82/09/28.8210130183
- 8210130406 Forwards LER 82-109/03L-0 NICH C Georgia Power Co 82/09/28 O'REILLY, J P Region 2, Office of Director 1p 15680 261 24X Fiche 50-366.82/09/28. 8210130406
- --B210130414 LER 82-109/03L-O on B2090B, performance of RCIC preventative maint procedure disclosed inoperability of RCIC trip & throttle valve & RCIC sys Caused by closure of turbine trip & throttle valve Trip & throttle valve opened TIPPS.5 B Georgia Pouer Co B2/09/28 Region 2. Office of Director 2pp 15680 262 24X Fiche 50-366/82/09/28.8210130406
- 9210130541 Forwards updated LER 82-008/03X-2 NIX.H C Opengia Power Co 82/09/28 O'REILLY, J P Region 2, Office of Director 1p 15683 301 24X Fiche 50-366.82/09/28. 8210130541
- --8210130549 Updated LER 82-008/03X-2 on 820126.during steady-state on Belizo, during steady-state operation its control rod drive accumulator low pressure alarm switches found in need of calibr Caused by instrument drift Betpoints reset Fill valves being overhaused TIPPS-8 0 Georgia Power Co 82/09/28 Region 2, Office of Director 2pp 15683 302 24X Fiche 50-366, 82/09/28, 8210130541

- 8210130220 Forwards LER 82-110/03L-0 NIX.H C Georgia Pawer Co 82/09/30 O'REILLY, J P Region 2. Getice of Director ip 15675 232 24X Fiche 50-366, 82/09/30.
- --8210130223 LER 82-110/03L-0 820909.during steady-state operation. Performance of monthly drywell procedure disclosed integrator output outside acceptable range Caused by instrument drift Drywell equipment drain sump pumps secured TIPPS.S B Quorgia Power Co 82/09/30 Region 2. Office of Director 2pp 15675 233 24X Fiche 50-366,82/09/30,8210130220
- 8210190504 Forwards LER 82-107/03L-0 NIC, H.C. Georgia Power Co. 82/10/05 O'REILLY, J.P. Region 2, Office of Director ip 15736 001 24X Fiche 50-366, 82/10/05, 6210190504
- --8210190511 LER 82-107/03L-0 on 820904. w/unit at 1,831 MWt.unreviewed 210190511 LER 82-107/03L-0 on 82090A, Junit at 1,831 MMt.unreviews spec release order discovered Caused by personnel oversight Personnel reinstructed on importance of complying w/Tech Spec 4 B 3 c Procedure reviewed & signed TIPPS.S B Georgia Power Co 82/10/05 Region 2, Office of Director ip 15736 002 24X Fiche 50-346.82/10/05,8210190504
- 8210170575 Forwards LER 82-108/03L-0 NIA:H C Georgia Power Co 82/10/05 O'REILLY, J P Region 2, Office of Director 1p 15737 337 24X Fichs 50-366, 82/10/05, 6210170575
- --8210190402 LER 82-108/03L-0 on 820907, discovered that monthly surveillance procedure re emergency buses 2E,2F & 20 undervoltage relay instrument FT not performed by 820902 per Tech Specs Caused by personnel error Personnel counseled TIPPS.S B Georgia Power Co 82/10/05 Region 2, Office of Director 1p 15739 338 24X Fiche 50-366,82/10/05,8210190595
- 8210290357 Forwards updated LER 79-098/01X-1 HIX.H C Georgia Power Co 82/10/07 O'REILLY, J P Region 2, Office of Director 1p 15853 086 24X Fiche 50-365,82/10/07, 8210270357
- --8210290364 Updated LER 79-098/01X-1 on 790902 plant engineering personnel reviewed wirting diagrams & confirmed problem w/HPCI cable separation Caused by design error HPCI cable rerouted per Design Change Request 79-380 on 810822 SUMMER, M L Georgia Power Co 82/10/07 Region 2, Dffice of Director 2pp 15853 087 24X Fiche 50-366,82/10/07,8210290357
- 8210270374 Forwards LER 82-111/03L-0 NIX.H C Georgia Power Co 62/10/12 O'REILLY.J P Region 2. Office of Director 1p 15853 010 24X Fiche 50-366.82/10/12.
- --8210290381 LER 82-111/03L-0 on 820918, shift technical advisor ran P+1 (periodic core performance log) w/o benefit of OD-1 (low power range munitor) P+1 indicated FRP of 0 627 & core max fraction of limiting power density of 0 653 SUMMER, H L Georgia Power Co 82/10/12 Region 2, Office of Director ip 15853 011 24X Fiche 50-366, 82/10/12, 8210290374
- 8210290206 Forwards LER 82-105/03L-0 riugyuzvo rorwands Lek 62-109/03L-0 NICH C Georgia Power Co 82/10/14 O'REILLY, J P Region 2, Office of Director ip 15853 291 24X Fiche 50-366,82/10/14, 8210290206
- --8210290207 LER 82-105/03L-0 on 820918, during selection of rods to EIDEFUZUY LEK METIODUSETO ON MECUTIO AUTING selection of rods to increase power, rod out permissive light went out. Caused by blown power fuse Fuse replaced TIPPS.8 B Georgia Power Co 62/10/14 Region 2, Office of Director Ip 15853 292 24% Fiche 50-366,82/10/14,8210290206
- 8210290075 Forwards LER 82-106/03L-0 NIX.H C Georgia Power Co 82/10/19 D'REILLY, J. P Region 2: Office of Director 1p 15853 149 24X Fiche 50-366,82/10/19, 8210290075
- --8210290080 LER 82-106/03L-0 on 820922, during steady-state operation.
  RCIC sys supply valve position indicator lights found
  extinguished Caused by breaker being turned off Breaker
  turned on Investigation initiated
  TIPPS.S B Georgia Power Co 82/10/19 Region 2, Office of
  Director ip 15853 150 24X Fiche 50-366.82/10/19,8210290075
- DOCKET 50-367 BAILLY GENERATING STATION G Adjudicatory correspondence
- 8210040022 Notice of withdrawal of appearance in proceeding LEWIS, S.H. Hearing Branch 2 82/09/29 3pp 15581 257 24X Fiche 50-367, 82/09/29, 8210040022

- G Inspection reports. IE Bulletins & correspondence
- 6210050162 Forwards notice of site inspito be conducted on 821018 in conjunction w/ongoing restoration work per ASLB 820506 order terminating proceedings on application for CP extension SHORB.E M Northern Indiana Public Service Co. 82/10/01 DENTON.HR Diffice of Nuclear Reactor Regulation. Director Spp. 15605 144 244 Fische 50-367.82/10/01.8210050162
- S Reportable occurrences, LERs & related correspondence
- 6210050512 Responds to FBIA request for insp & enforcement records re accidents of F Lawson & H Dillon at Facility. Union Electric CP & other NRC safety matls or manuals Forwards two documents Renaining records available in PDR FELTON. J M Division of Rules and Records 62/09/21 IQOE. M V Igoe. V M 2pp 15426-244 24X Fiche 50-000, 82/09/21, 8210050512
- --8210050518 Region 3 daily rept for 780807 4 Region 3. Chicago. Office of the Director 78/08/07 ip 15526 246 24X Fiche 50-000.62/09/21.8210050512
- DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2

  F Security, medical, emergency & fire protection plans
- 8210010175 Forwards IE Safeguards Insp Repts 50-313/82-25 & 50-368/82-22 on 820818-20 No noncompliance noted SEIDLE.W C Division of Resident, Reactor Project & Engineering Programs 82/09/16 CAVANAUOH.W Arkansas Fower & Light Co 2pt 15567 282 24% Fiche 50-313,82/09/16.0210010175
- --8210010178 [E Safeguards Insp Repts 50-313/02-25 & 50-369/82-22 on 820039-20 No noncompliance noted Major areas inspected security organization mgt.physical barriers & access control of packages Details uithheld (ref 100FR2 790) EVANS.C A Division or Vendor & Technical Programs 62/09/14 Lp 15567 284 24X Fiche 50-313/82/09/16/8210010175
- 8210190497 Forwards IE Insp Repts 50-313/82~11 & 50-348/82-09 on 820518-20 No noncompliance noted SEIDLE,N C Division of Resident, Reactor Project & Engineering Programs 82/09/28 CAVANAUGH,N Arkansas Power % Light Co 2pp 24X Fiche 50-313,82/09/28.8210190497
- -8210190516 IE Insp Repts 50-313/82-11 % 50-368/82-09 on 620518-20 No noncompliance noted Major areas inspected licenses ince & capabilities during full-scale exercise of y plans & procedures

  M. Division of Resident, Reactor Project & Engineering 82/09/24 17pp 24X Fiche 50-313,82/09/28,8210190497

- 8210260178 Ack receipt of 820929 ltr requesting addl time to respond to violations noted in Emergency Piepuiedness Appraisal Repts 50-31962-22 & 50-368/82-21 Response to App C due by 830501 SEIDLE: W.C. Division or Resident. Reactor Project & Engineering Programs 82/10/19 CAVANAUGH.W. Arkansas Power & Light Co. Ip 15799-037 24X Fiche 50-313.82/10/19.8210260178
- --8210260180 Responds to NRC 820625 ltr re App t to IE Emergency
  Preparedness Appraisal Repts 50-313/82-22 & 50-368/82-21
  Deficiencies resolved in emergency plan amends & implementing procedure revisions
  CAVAHAUGH, W. Arkansas Power & Light Co. 82/09/29 COLLING. & f
  Region 4, Office of Director 4pp 15799 038 24X
  Fiche 50-313,82/10/19 8210260178
- P Operating license stage documents & correspondence
- B21001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events 7 safety problems Forwards documents listed in App A FELTON, J H Division of Rules and Records 82/06/28 UDELL, P A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000, 82/06/28, 8210010008
- --B106100203 Discusses evaluation of HPSI pump operability w/o svc uater Operability of HPSI pumps w/o svc water not adequately justified based on info submitted by licensee IMBRO.C Director's Office 81/05/22 Director's Office App 15727 185 24X Fiche 50-000/82/06/28/8210010008
- 8210190908 Responds to 820831 submittal re Tech Spec revision for snubber surveillance Liceuse amend application should be submitted to incorporate applicable position of 801120 model Tech Specs within 60 days CLARK, R.A. Operating Reactors Branch 3 82/09/21 CAVANAUGH, W. Arlansas Power & Light Co. 2pp. 15760-301 24X Fiche 50-313,82/09/21,8210190008
- 8210130409 Responds to NRC 810619 ltr transmitting Amend 24 to license NFF-6 re-served reactor contant pump shaft event reanalysis Event description & results of Cycle 2 seried rotor event encil MARSHALL, JR Ankansas Power & Light Co 82/10/05 CLARK, R A Operating Reactors Branch 3 8pp 15601 010 24% Fiche 50-368, 82/10/05, 8210130409
- B210200022 Provides preliminary info as result of fuel insp that revealed need to modify some Batch C fuel assemblies to provide add! space for arial growth of fuel rods SCHEMER.A E Combustion Engineering, Inc. 82/10/05 DEVEUING.R C Director's Office. Office of Inspection and Enforcement 2pp 15753-004 24% Fiche 50-366,82/10/05,82/0200022
- B210150002 Forwards response to B20120 % 0301 requests for addl info re RCB high point vents Gredible missiles generated by failure of RCB vent valves not postulated based on valve design Leak detection provided for by monitoring pressure MARSHALL, J.R. Arkansas Power & Light Co. B2/10/06 STOL2, J.F. Operating Reactors Branch & CLARK, R.A. Operating Reactors Branch 3 4pp. 15696 309 24X Fiche 50 313,82/10/06,8210150002
- 8210150494 Submits info re status of waste gas sys & schedule for installation of redundant hydrogen/oxygen analyzers Conceptual diagram of proposed upgraded waste gas sys redundant analyzer panel enc!
  MARBHALL, J. R. Arkansas Power & Light Co. 82/10/12 STDLZ, J. F. Dperating Reactors Branch 4 CLARK, R. A. Dperating Reactors Branch 3 4pp (5714-184 24X Fiche 50-313,82/10/12,8210150494
- B210250159 Application to amend License NPF-6, changing Tech Specs to allow for removal of surveillance capsule & analysis of specimen CAVANAUGH.W Arkansas Power & Light Co B2/10/19 CLARK.R A Operating Reactors Branch 3 3pp 15787 313 24X Fichs 50-368.82/10/15.8210250159
- --8210250161 Proposed Tech Spec change allowing for removal of surveillance capsuls & analysis of specimen \* Arkansas Power & Light Co 82/10/15 1p 15787 316 24y Fichs. 50-368, 82/10/15, 8210250159
- 8210270101 Forwards nine revised oversize P&IDs Drawing transmittal list encl Aperture cards are available in PDR SHIVELY.G Arkaness Power & Light Co 82/10/16 NRC ~ No Detailed Affiliation 01/00 2pp 15829 325 24X Fische 50-368.82/10/18.8210270101

# **DOCKETED ITEMS**

### Q Inspection reports. IE Bulletins & correspondence

- 6210080015 Add1 response to FOIA request for 19 categories of infolia nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
  FELTON.J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15645 027 24X
  Fiche 50-000.82/07/12.8210080015
- --#108130198 Forwards special IE Insp Rept 50-368/81-17 on B10514-16 No noncompliance noted BAER.R L Division or Resident & Regional Reactor Inspection B1/0//17 MADSEN.O L Division of Resident. Reactor Project & Vendor Inspection Ip 15668 171 24% Fiche 50-000.82/07/12, 8210080015
- £210080112 Systematic assessment of licensee performance notes re facility evaluation for 790101-800819 4 NAC - No Detailed Affiliation Given 80/08/19 App 15667 291 24X Firbe 50-000, 82/07/12-8210080015
- R2(0010175 Forwards IE Safeguards Insp Repts 50-313/82-25 & 50-368/82-22 on 820818-20 No noncompliance noted SEIDLE.W C Division of Resident, Reactor Project & Engineering Programs 82/09/16 CAVANAUGH.W Arkansas Power & Light Go 20, 15567 282 24X Fichs 50-313.82/09/16.8210010175
- --8210010178 IE Safequards Insp Repts 50-313/82-25 & 50-368/82-22 un 820818 20 No noncompliance noted Major areas inspected security organization mot physical barriers & access control of packages Details withheld (ref 100FR2 790) EVANS, C.A. KELLY, J.A.F. Division of Vendor & Technical Programs 82/09/14 1p 15567 284 24% Fiche 50-313,62/09/16,8210010175
- 87:0190497 Forwards (E Insp Repts 50-313/82-11 & 50-368/82-09 on 820518-20 No noncompliance noted SEIDLE.W C Division or Resident, Reactor Project & Engineering Programs 82:09/28 CAVANAUOH W Alkansas Power & Light Co 200 15735 344 24X Fiche 50-313.82/09/28.8210190497
- 9210190516 It. Insp Repts 50-313/82-i1 & 50-368/82-09 on B205i8-20 No noncompliance noted Major areas inspected licensee performance % capabilities during full-scale exercise of energoncy plans & pracedures
   ROHRER, D.M., HUNNICUTT D.M. Division of Resident, Reactor Project & Engineering Programs 82/09/24 17pg 15735-346 24x
   Fichs 50-313,82/09/28,8210190497
- G21D12O246 Ack receipt of 82D211 ltr informing NRC of steps taken to correct violations noted in IE than Ropts 50-31J/81-30 & 50-368/81-29
  SEIDLE-W C Division or Resident. Reactor Project & Engineering Programs 82/10/01 CAVANAUGH.W Arkansas Power & Light Co ip 15652 110 24x Fichs 50-313.82/10/01.821012O246
  - 8210120252 Responds to NRC 820104 itr re-violations noted in It Insp.
    Reprs 50 313/81-30 / 50-368/81-27 Corrective actions formal
    training sessions will be conducted w/appropriate station
    personnel to stress importance of individual responsibility
    MARSHALL J R Arkansas Power & Light Co 82/02/11 MARSEN.G L
    Division of Resident, Reactor Project & Engineering Programs 2pp
    15652 111 24X Fiche 50-313/82/10/01/8210120244
- SE10200022 Provides preliminary info as result of fuel insp that revealed need to modify some Batch C fuel assemblies to provide adult space for axial growth of fuel ruds SCHERER, A E Combustion Engineering, Inc. 82/10/05 DEYOUNG, R C Director's Orfice. Office of Inspection and Enforcement 2pp 19783-004 24x fiche 50-366.82/10/05,8210200022
- 82:0220270 Forwards IE Insp Repts 50-313/82-12 & 50-368/82-25 on 820524-27 No noncompliance noted SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82:10/05 CAVANAUGH, W Alkensas Power & Light Ca 2p; 15775 001 24X Fiche 50-313.82/10/05.8210220270
- --82102202BI IE Insp Repts 50-313/82-12 & 50-348/82-25 on B20524-27 No noncompliance noted Major areas inspected radiochemistry program, including organization, staffing, braining program, sample collection & sample treatment & analysis NICHOLAS, J B, MURRAY B Region 4, Office of Director 82/09/09 25pp 19775 003 24X Fiche 50-313,82/10/05.8210220270
- 8208190233 JE Info Notice 80-35, Suppl 1. "Leaking & Dislodged I-125 implant Seeds " Svc list encl COBB. I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fich 50-000, 82/10/06, 8208190233

- 8210120241 Ack receipt of 820715 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/80-20 & 30-368/80-20 & SEIDLE-W C Division of Resident, Reactor Project & Engineering Programs 82/10/06 CAVANAUGH.W Arkensas Power & Light Co ip 19652 113 24X Fiche 50-313, 82/10/06, 8210120241
- --8210120247 Provides status update on gaseous radioactive waste sys mods.in response to violations noted in IE Imap Repts 50-313/80-20 & 50-366/80-20 High airborne activity incidents in auxiliary bldgs significantly reduced MARSHALL J R Arkansas Power & Light Co B2/07/15 SEIDLE, W C Division of Resident Reactor Project & Engineering Programs Spp 15652 114 24X Fiche 50-313,82/10/06.8210120241
- 8208190238 IE Bulletin B2-03, "Btress Carrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Pining at BWR Plants "See list encl BEYOUND, R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fichs 50-000, 82/10/14, 8208190238
- 8210220377 Categorizes upen items identified in IE Emergency Preparedness Repts 50-313/82-11 & 50-348/82-07 by need for immediate consideration & type of response acceptable Notification of expected response date due within 10 days SEIDLE. U C Division of Resident, Reactor Project & Engineering Programs 82/10/19 CAVANAUGH.W Arkansas Power & Light Co 4pp 19779 175 24X Fiche 50-313,82/10/19,8210220377
- 821026017B Ack receipt of 820929 ltr requesting addl time to respond to violations noted in Emergency Preparedness Appraisal Repts 50-3168/82-21 Response to App C due by 930501 SEIDLE.W C Division of Resident, Reactor Project & Engineering Programs 82/10/19 CAVANAUGH.W Arkansas Pourr & Light Co Ip 15799 037 24X Fiche 50-313.82/10/19.8210260178
- --8210260180 Responds to NRC 820625 ltr re App C to IE Emergency
  Preparedness Appraisal Repts 50-313/82-22 & 50-368/82-21
  Deficiencies resolved in emergency plan amends &
  implementing procedure revisions
  CAVANAVOH, W. Arkansas Power & Light Co. 82/07/27 COLLINB, J T
  Region 4, Office of Director 4pp 15799 038 24X
  Fiche 50-313, 82/10/19,8210260178
- B Reportable occurrences, LERs & related correspondence
- 2012270118 Discusses conclusions of engineering evaluation of steam generator overfull transfents At C-E & Westinghouse plants LANNING.II D Director's Office 80/10/29 HICHELSON.C Director's Office 3pp [5692-262 24X Fiche 50-000.80/10/29.8012270118]
- G210080028 Advises that Sept 1980 blockage of flow by silt to bearing oil coolers & seal water coolers of all high pressure safety injection pumps considered AD Util failed to justify pump operability w/o water IMBRO.E Director's Office 61/05/22 Director's Office 4pp 15667 303 24% Fishs 50-368, B1/05/22, B210080028
- 8210190009 Discusses repetitive failures of emergency feedwater flow valves at facility due to valve operator hydraulic problems Recommends that hydraulic valve operators be added to branch watch list IMBRO.E V Reactor Operations Analysis Branch 82/02/24 MICHELSON.C Director's Office 3pp 15760 303 24X Fiche 50-368.82/02/24.8210190009
- 82:00:0008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents issted in App A FELTON, J M Division of Rules and Records 82/06/28 UDECL, R A Critical Mess Energy Project 15pp 15727 008 24X Fiche 50-000, 82/06/28, 82:00:10008
- --8107010161 Discusses inoperability of instrumentation due to extreme cold weather IS should issue suppl to IS Bulletin 79-24 requesting Tech Spec changes which require daily surveillance during extreme weather MICHELSON.C Director's Office 81/06/15 DENTON.H R Office of Nuclear Reactor Regulation, Director 5pp. 15727 208 24X Fiche 50-000, 82/06/28, 82/001000B
- ---8203120016 Discusses repetitive failures of emergency feedwator flow value as reported in LERs due to valve operator hydraulic problems LERs encl
  IMBRO,E V Director's Office 82/02/24 MICHELBON,C Director's Office 74pp 15732 308 24X Ficher50-000,82/06/28,8210010008

- 8210050346 Confirms 820922 telcon w/NRC resident inspector re discovery that clearance between top of fuel rods & bottom of upper flow plate on batch C fuel assemblies may not prevent pin contact Mod planned LER 82-030/017-0 will follow LEVINE, J M Arkansas Power & Light Co 82/07/23 COLLINS, J Region 4, Office of Director 1p 15610 125 24X Fiche 50-368, 82/09/23, 8210050346
- 9210190545 Forwards LER 82-030/017-0
  MARSHALL.J R Arkansas Power & Light Co 82/10/06 SEIDLE.W C
  Division of Resident. Reactor Project & Engineering Programs | 1p
  15735 006 24% Fight 50-365,82/10/06,8210190545
- --P210190558 LER B2-030/017-0 on B20722, measurements revealed shoulder gap clearances on certain batch C fuel assemblies may not be sufficient to prevent pin contact Gaused by design models & annealed guide tubes growing at lesser rate ROOERS, P Arkansas Power & Light Co B2/10/06 Region 4, Office of Director App 15735 007 24x Fiche 50-366, 82/10/06, 82/
- 8210250292 Ferwards LER 82-031/01T-0
  MARSHALL.J R Arkanss Power & Light Co 82/10/13 SEIDLE.W C
  Division of Resident, Reactor Project & Engineering Programs is
  15790 064 R4X Fiche 50-368.82/10/13.8210250292
- --8210250298 LER 82-031/01T-0 on 821001 after disassembling emergency feedwater sump turbine steam supply check valve for insp. disc studenut washer & locking pin discovered missing Caused by vibration fatigue Parts replaced ROGERS, P. Arkansas Power & Light Co. 82/10/13 Region 4. Office of Director 4pp 15770-065 24X Fiche 50-368-82/10/13, 8210250292
- 8210260120 Forwards LER 62-029/03L-0 MARSHALL, J R Arkansus Power & Light Co 82/10/15 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs In 15799 072 24X Fiche 50-368, 82/10/15, 8210260120
- ---8210260123 LER 82-029/03L-O on 820918 four electrical cables discovered pulled through fire curtain Caused by personnel error while performing station battery capacity test Personnel unaware of fire curtain in wall opening Maint personnel counseled ROSERS, P. Arkansas Power & Light Co. 82/10/15. Region 4. Office of Director 2pp 15799 077 24X Fiche 50-368.82/10/15, S210260120
- 8210260474 PND-1V-82-038 insp of svc water sys identified deficiencies in pipe supports Deficiencies include hanger installation not in accordance w/design.incorrect as-built drawings & workmanship defects
  JOHNSEN.W D Region 4. Office of Director 82/10/20 ip 15806 236 24X Fiche 50~368.82/10/20.8210260474
- DOCKET 50-369 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 8210010008 Responds to FDIA request for 19 categories of documents re nuclear reactor events 0 safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records #2/06/28 UDELL.R A Crifical Mass Energy Project 15pp 19727 ODS 24X Fiche 50-000.82/06/28.8210010008
- ~-8008050265 Discusses addl required info to better define potential for cracking in reactor vessel notice.

  NOD/MAN.V S Assistant Director for Materials & Qualifications Engineering 80/05/05 TEDESCO.R L Assistant Director for Licensing 2pp. 15727 176 24X Fiche 50~000,82/06/28,821001000B
- F Security, medical, emergency & fire protection plans
- 9210150006 Ack receipt of B20723 ltr informing NRC of steps taken to correct improvement items noted in IE Emergency Preparedness Appraisal Rept 50-369/02-06
  LEWIS.R C Division of Project & Resident Programs B2/08/13 PARKER.W D. Duke Power Co ip 15698 214 24%
  Fiche 50-369, 82/08/13, B210150006
- ---8210130012 Forwards response to NRC 820625 ltr re improvement items noted in IE Emergency Preparedness Appraisal Rept 50-369/82-06 on 820301-12 Corrective actions lesson plans for emergency response training complete PARKER, M O Duke Power Co 82/07/23 D'REILLY, J. P. Region 2, Office of Director 10pp 15698 215 24X Fiche 50-369,82/08/13,8210130006

- --8210150020 Forwards IE Emergency Preparedness Appraisal Rept 50-369/82-06 on 820301-12 No violations deviations or emergency preparedness deficiencies noted O'REILLY, J P Region 2. Office of Director 82/06/25 PARKER, U O Duke Power Co 7pp 19698 225 24X Fiche 50-369, 82/08/13, 8210150006
- --8210150025 IE Emergency Preparedness Appraisal Rept 50-369/82-06 on 820301-12 No violations or deficiencies noted Major areas imagected evaluation of adequacy of emergency preparedness program Evaluation encl SIMONDS, G E. JENNINS, G R. Division of Emergency Preparedness & Operational Support 82/06/22 46pp 15698 226 24x Fiche 50-369,82/08/13,8210150006
- 8210150014 Forwards IE Insp Rept 50-369/82-31 on 820830-0903 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/09/24 TUCKER, H B Duke Power Co 2pp 15698 333 24X Fiche 50-369, 82/09/24,8210150014
- --8210150021 IE Insp Rept 50-369/82-31 on 820830-0903 No noncompliance noted Major areas inspected emergency preparedness MARSTON, R R, JENKINS, O R Division of Emergency Preparedness & Operational Support 82/09/23 11pp 15698 335 24X Fiche 80-369,82/09/24,8210150014
- B210190097 Releases public version of revised emergency plan inplementing procedures FELTON.J M Davision of Rules and Records B2/09/29 Document Management Branch lp 15761-127 24X Fiche 50-369,82/09/29, 8210190097
- --8210190103 Forwards public version of revised emergency plan implementing procedure, including Procedure AP/0/A/5500/27 recare & transportation of contaminated injured individuals from site to offsite medical facility TUCKER, H B Duke Power Co 82/09/15 DENTON, H R Office of fuciear Reactor Regulation. Director 2pp 15761 128 24x Fiche 50-369,82/09/29,8210190097
- --0210190108 Public version of revised emergency plan implementing procedures, including Procedure AP/0/A/5500/27 re care & transportation of contaminated injured individuals from site to offsite medical facility GLOVER. HS Duke Power to 82/08/30 92pp 15761 130 24X Fiche 50-369, 82/09/29, 82/0190097
- B210070072 Notifies that local alarms missing from control room fire james will be installed by 830701.per Jan 1979 fire protection review Issue not considered significant safety concern TUCKER-H B Duke Power Co 82/09/30 DENTON, H R . ADENSAM C Office of Nuclear Reactor Regulation. Director 1p 15628 164 24) Fiche 50-369, 82/09/30, 8210070072
- 8210180254 Responds to util 820520 ltr re Revision 13 to physical security plan Changes consistent w/provisions of 100FR50 54(s) ADENSAM E 0 Licensing Branch 4 82/09/30 TUCKER H B Duke Power Ca 2pp 15745 337 24% Fiche 50-369.82/09/30.8210180254
- B210150518 Forwards revised McQuire Nuclear Station Fire Protection Review " Submittal supersedes all previous revisions TUCKER.H D Duke Power Co 82/10/07 DENTON.H R . ADENSAM.E Q Office of Nuclear Reactor Regulation, Director 1p 15714 219 24K Fiche 50-369, 82/10/07, 8210150518
- 82(0270132 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/10/08 Document Machine Baranch 1p 15835 136 24X Fiche 50-369,82/10/08,82/10/20132
- ---8210270137 Forwards public version of revised emergency plan implementing procedures, including Procedure EP/0/A/5000/05 re notification of unusual event, EP/0/A/5000/06 re alert & EP/0/A/5000/08 re general emergency TUCKER, H B Duke Power Co 82/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15835 137 24X Fiche 50-369,82/10/08,8210270132
- --8210270144 Public version of revised emergency plan implementing procedures, including Procedure EP/0/A/5000/05 re notification of Unysual event EP/0/A/5000/06 re alert & EP/0/A/5000/08 re general emergency OLOVER.M 8 , OLLBERT.O D Duke Power Co 82/09/13 82pp 15835 139, 24X Fiche 50-369, 82/10/08,8210270132

# DOCKETED ITEMS

- B210280016 Releases public version of revised emergency plan FELTON, J. M. Division of Rules and Records 82/10/12 Document Nanagement Branch ip 15863 006 24X Fiche 50-369, 82/10/12, B210280014
- --8210280017 Forwards public version of Revision 7 to emergency plan TUCKER.H B Duke Power Co 82/09/28 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15863 007 24X Fiche 50-369,82/10/12-8210280016
- --8210280020 Public version of Revision 7 to emergency plan MCINTOSH.H D. Duke Power Co. B2/09/30 28pp 19863 009 24X Fishe 50-369,82/10/12-8210280016

- 8210130046 Responds to 820712 ltr request that NRC continue to send copies of correspondence to util on McGuiro Bince McGuiro proceedings complete t documents in LPDR, request denied ADENSAM, E.O. Licensing Branch 4 82/09/28 RILEY, J.L. Carolina Environmental Study Group ip 15696 284 24X Fiche 50-000, 82/09/28, 8210130046
- K Utility Final Safety Analysis Report (FSAR) & amends
- 82(0040254 Forwards application to amend License NPF-9 & CPPR-84, consisting of Revision 43 to FSAR & Revision 6 to "Evaluation of Effects of Postulated Pipe Failures Dutside Containment for McGuire Nuclear Station"

  TUCKER, H B Duke Power Co 82/10/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 3pp 15975 032 24X Fiche 50-369, 82/10/01.8210040254
- --8210040273 Application to amend License NPF-9 & CPPR-84, consisting of Revision 43 to FSAR & Revision 6 to "Evaluation of Effects of Postulated Pipe Faltures Outside Containment for McGuire Nuclear Station"

  TUCKER, H B Duke Power Co 82/10/01 16pp 15595 035 24X Fiche 50-369, 82/10/01, 8210040254
- --B210040277 Revision 5 to "Evaluation of Effects of Postulated Pipu Failures Dutside Containment for McGuire Nuclear Station" \* Duke Power Co MDS/PDG-77-1 B2/10/01 3pp 15595 051 24x Fiche 50-369.82/10/01.8210040254
- --8210040286 Revision 43 to FBAR Fourteen aperture cards available in PDR

  # Duke Power Co 82/10/01 303pp 15595 054 24X
  Fiche 50-369,82/10/01,8210040254
- 8210130262 Forwards figures to Revision 43 to FSAR, included in 821001 application for Amend 69 to License NFF-9 & CPR-84 Subjusti Inadvertently omitted TUCKER, H B Duke Power Co 82/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E Q Licensing Branch 4 1p 15675 293 24X Fiche 50-369, 82/10/07, 8210130262
- --8210130263 Figures for Revision 43 to FSAR + Dute Power Co. 82/10/07 42pp 15675 294 24X Fich 50-369.82/10/07, 8210130262
- P Operating license stage documents & correspondence
- \$210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records \$2706/28 UDELL, R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000.82706/28.821001000B
- B210040424 Forwards request for add1 info or hydrogen control Coordinated util response suggested by mid-Oct 1982, since sub; is generic to ice condenser plants NOVAK.T M Assistant Director for Licensing B2/09/17 TUCKER.H B Duke Power Co 10pp 15897 241 24X Fiche 50-369, 82/09/17, 831004024
- 8210180389 Notifies that 770330 application requesting extension of const completion dates exempt from fee requirements since no review commenced on application prior to issuance of OL Refund forthcoming MILLER, W O License Fee Management Granch 82/09/24 PARKER, W C Duke Power Co ip 15746 389 24X Fiche 50-369,82/09/24,8210180389

- 8210040254 Forwards application to amend License NPF-9 & CPPR-84, consisting of Revision 43 to FSAR & Revision 6 to "Evaluation of Effects of Postulated Pipe Failures Outside Containment for McGuire Nuclear Station"
  TUCKER. H 8 Duke Power Co 82/10/01 DENTON H R Office of Nuclear Reactor Regulation. Director ADENSANE 6 Licensing Branch 4 3pp 15595 032 24X Fiche 50-369.82/10/01.8210040254
- --8210040273 Application to amend License NPF-9 & CPPR-84, consisting of Revision 43 to FSAR & Revision 6 to "Evaluation of Effects of Postulated Pipe Failures Outside Containment for McGuire Nuclear Station"
  TUCKER.H B Ouke Power Co 82/10/01 16pp 15595 035 24X
  Fiche 50-369, 82/10/01, 8210040254
- --8210040279 Revision 6 to "Evaluation of Effects of Postulated Pipe Failures Outside Containment for McGuire Nuclear Station" \* Duke Power Co MDS/PDG-77-1 82/10/01 3pp 15595 051 74X Fiche 50-369, 02/10/01.8210040254
- 8210130262 Forwards Figures to Revision 43 to FSAR, included in 821001 application for Amend 69 to Licemse NPF-9 & CPPR-84 Subj mat] inadvertently omitted TUCKER. H B Duke Power Co 82,710/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAN, E G Licensing Branch 4 ip 15675 293 24X Fiche 50-369,82/10/07.82/10/130282
- 8210130467 Responds to Generic Ltr 82-16 re NUREG-0/37 Tech Specs for Unit 1 will be upgraded to latest NRC requirements 2 combined w/Unit 2 Tech Specs upon issuance of Unit 2 OL in Mar 1983
  TUCKER, H B Duke Power Co 82/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E Q NRC No Detailed Affiliation Given ip 15682 154 24x
  Fiche 50-367.82/10/07.8210130467
- 8210280407 Requests info demonstrating that Unit 2 equipment meets same sersmic & dynamic qualification requirements as Unit i Info requested by 821027 ADENBAM: E 0 Licensing Branch 4 82/10/08 TUCKER.H B Duke Power Co 2pp 15859 327 24X Fiche 50-369.82/10/08,8210280407
- 8210250304 Forwards revised requests for relief from hydrostatic testing requirements on feedwater sys for steam generators & Unit 1 safety injection sys ASME Code Section XI impractical TUCKER.H B Duke Power Co 82/10/19 DENTON.H R Office of Nuclear Reactor Regulation, Director 8pp 15790 205 24X Fiche 50-369,82/10/19,8210250304
- 8210260331 Application for amend to License NPF-9, changing Tech Spet re containment penetration Type C leak rate tests Amend requires exemption from 1007R50. App J THIES, A C Duke Power Co 82/10/21 DENTON: H R Office of Nuclear Reactor Regulation. Director ADENSAM: E C Licensing Branch 4 3pp. 15803 198 24X Fiche 50-369.82/10/21,8210260331
- --8210260336 Proposed change to Tech Spec 4 6 1 2d, requiring that Type C ponetration tests be performed at 24-month interval, deviating from 10GFR90.App J requirement to perform test during each refueling shutdown a Duke Fower Co 92/10/21 4pp 15803 201 24X Fiche 50-369.82/10/21,8210260331
- O Inspection reports, IE Bulletine & correspondence
- 82:10070097 Responds to FDIA request for eight categories of records resteam generators & steam turbines App A documents provided in R Udell FDIA Request 81-313 Forwards documents listed in App B. FELTON, J M. Division of Rules and Records 82/08/10 LONG, D.J. Winthrop. Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000.82/08/10.8210070007
- --8210070139 Forwards tabulated data on steam generator insp & maint at facilities Data should be provided to licensees IPPOLITO.T Operating Reactors Assessment Branch 82/04/01 VARGA:S Operating Reactors Branch | 5pp 15645 131 24X Fiche: 50-000:82/08/10:8210070007
- 8210130006 Ack receipt of 820723 ltr informing NRC of steps taken to correct improvement items noted in IE Emergency Preparedness Appraisal Rept 50-364/82-06

  LEMIS.R.C. Division of Project & Resident Programs 82/08/13

  PARKEN, W. D. Duke Power Co. ip 156-78-214 24X

  Fiche 50-367, 82/08/13, 8210150006

- --8210190012 Forwards response to NRC 920625 ltr re improvement items noted in IE Emergency Preparedness Appraisal Rept 50-369/82-06 on 820301-12 Corrective actions lesson plans for emergency response training complete PARKER. H O Duke Power Co 62/07/23 O'REILLY, J P Region 2, Office of Director 10pp 15698 215 24X Fiche 50-369.82/08/13, 9210150006
- --8210150020 Forwards IE Emergency Preparedness Appraisal Rept 50-369/82-06 on 820301-12 No violations deviations or emergency preparedness deficiencies noted O'REILLY, J P Region 2. Office of Director 82/06/25 PARKER, H O Dute Power Co 7pp 15698 225 24X Fache 50-369, 82/08/13, 8210150006
- --8210150025 IE Emergency Preparedness Appraisal Rept 50-369/82-06 on 820301-12 No violations or deficiencies noted Major areas inspected evaluation of adequacy of energency preparedness program Evaluation encl SIMONDS.0 E . JENKINS.0 R Division of Emergency Preparedness & Operational Support 82/06/22 46pp 15698-226 24X Fiche 50-369.82/08/13.8210150006
- 8210010424 Forwards IE Insp Repts 50-369/82-29 % 50-370/82-23 on 820726-0820 No noncompliance noted DANCE.H C D[vision of Project & Resident Programs 82/09/08 TUCKER,H B Duke Power Co 2pp 15569 343 24% Fiche 50-369, 82/09/08,82100[0424
- --8210010436 [E Insp Repts 50-369/82-29 & 50-370/82-23 on 820726-0820 Na noncompliance noted Major areas inspected maint, surveillance hot functional test.operational safety verification, significant event following plant transients BEMIS.P R , MCPKINS.P , GRYANT, J C Division of Project & Resident Programs 82/09/08 App 15569 345 24X Fiche 50-369.82/09/08, 8210010424
- 8210010451 Forwards IE Insp Repts 50-369/82-28 & 50-370/82-22 on 820817-20 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/08 TUCKER.H B Duke Power Co 2pp 18572 297 24X Fiche 50-369, 82/09/08, 8210010451
- --8210010459 IE Insp Repts 50-369/82-28 & 50-370/82-22 on 820817-20 No noncompliance noted Major areas inspected preoperational test procedure review & test uitnessing JOHNSON, A H , WHITENER, H L , JAPE, F Division of Engineering & Technical Programs 82/09/07 6pp 13572 299 24X Fiche 50-369, 82/09/08/8210010451
- 8210010282 Ack receipt of IE Insp Rept 50-369/82-27 No proprietary info
  100 TUCKER. H. B. Duke Power Co. 82/09/10 O'REILLY, J. P. Region 2, Office of Director 1p. 15573 109 24X Fiche 50-369,82/09/10,8210010282
- 8210010090 Ack receipt of IE Insp Repts 50-364/82-26 & 50-370/82-20 No proprietary info TUCKER, H B Dute Power Co 82/09/15 O'REILLY, J P Region 2, Office of Director ip 15565 259 24X Fiche 50-369, 82/09/15, 8210010090
- 8210150014 Forwards IE Insp Rept 50-369/82-31 on 820830-0903 No noncompliance noted DANCE, It G Division of Project & Resident Programs 82/09/24 TUCKER, It B Duke Pawer Co 2pp 15698-333 24X Fichs 50-369, 82/09/28.8910150

- 8210220202 Ack receipt of IE Insp Repts 50-369/82-28 & 50-370/82-22 No proprietary info TUCKER. H B Dute Power Co 82/10/08 O'REILLY, J P Region Positive of Director ip 15776 357 24X Fiche 50-369.82/10/00, 6210230282
- 8210220204 Ack receipt of IE Insp Repts 50-369/82-29 \$ 50-170/82 \$ 10 proprietary info TUCKER. H B Duke Power Co 82/10/08 O'REILLY, J P Region 2 Office of Director 1p 15776 352 24X Fiche 50 369, 82/10/00 8210220204
- 8208190238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at 8WR Plants "Svc list encl DEYGUNDS C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15910 (25 24X Fiche 50-000, 82/10/14, 8209190238
- A Periodic operating reports & related correspondence
- 8210190742 Forwards monthly operating rept for Sept 1982 TUCKER.H B Duke Power Co 82/10/15 Director's Office. Office of Inspection and Enforcement 1p 15737 085 24X Fiche 50-369, 82/10/15.8210190742
- --8210190751 Monthly operating rept for Sept 1982 REAVIS.J A Duse Power Co 82/10/15 6pp 15/3/ 086 24% Fiche 50-369.82/10/15.8210190742
- S Reportable occurrences, LERs & related correspondence
- 6210010000 Responds to FDIA request for 19 categories of documents in nuclear reactor events % safety problems forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDE(U.# A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000, 82/06/28,8210010008
- --Bi10050018 Requests addl info from util re Bi0914 safety injectic. a natural circulation event during performance of loss of control room test info needed includes data just prior to trip & up to 1-h following event SANDS.S P Director's Office Bi/09/22 BIRKEL.R Licensing Branch 1 ip 15730 272 24X Fiche 50-000.B2/06/28.B2(0)160-01
- ~-8210050124 Summary of 810610 operating leactor events meeting LAINAS: 0 C Assistant Director for Safety Assessment (\$1/66/1/ EISENHUT.D G Division of Licensing 5pp 15729 21/ 24X Fiche 50-000, 82/06/28.8210010008
- 8210010424 Forwards IE Insp Repts 50-369/82-29 & 50-370/82-2) on 820726-0820 No noncompliance noted DARCE, H C Division of Project & Resident Programs 82/04/00 TUCKER, H B Duke Power Co 2pp 15569 343 24X Fiche 50-369, 82/09/08, 8210010424
- ~-8210010436 IE Insp Repts 50-369/82-29 \$ 50-370/82-23 on 820/36-3610 ks noncompliance noted Major areas inspected maint, surveillance, hot functional test operational safety verification, significant event followup & plant transients BEMIS.P R , HOPKINS.P , BRYANT.J C Division of Project & Resident Programs 82/09/08 App 15569 345 24% Fichs 50-369.62/09/08 B210010424
- 8210130177 Forwards LER 82-059/03L-0 Detailed event analysis encl TUCKER-H B Duke Power Co 82/10/01 0'REILLY, J P Region 3 Office of Director 3pp 15673 022 24X Fiche 50-369/82/10/01. 8210130177
- --B210130180 LER 82-069/03L-0 on 820903, investigation of several spirits fire detection seys zone alarms resulted in sys being declared inaperable Caused by water in data gathering panel creating ground condition affecting entire sys NARDUCL/P B Duke Power Co B2/10/01 Region 2, Diffice of Director 1p 15673 025 24X Fiche 50-369.82/10/01.8210130177
- 8210220318 Forwards LER 82-070/03L-0
  TUCKER, H B Duke Power Co 82/10/15 O'REILLY, J P Region 2.
  Office of Director 1p 15776 043 24X Fiche 50-369,82/10/15
  - --B210220327 LER B2-070/03L-0 on B20916 one of two required oxygen analyzers failed to alarm after simulated high oxygen concentration generated Caused by misposition of toggle switch Switch returned to correct position MARDOCI-P.B Oute Power Co B2/10/15 Region 2. Office of Director Ip 15776 044 24X Fiche 50-369.82/10/15.8210220316

- DOCKET 50-370 WILLIAM 8 MCGUIRE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- Rai001000B Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents

  13 sted in App A
  FELTON, J II Division of Rules and Records 82/04/28 UDELL, R A
  Critical Mass Energy Project 15pp 15727 005 24X
  Fishe 50-000, 82/04/28, 8210010008
- --8008050265 Discusses additequired info to better define potential for cracking in reactor vessel noirles
  NDOVARN. S Assistant Director for Materials & Qualifications
  Engineering 80/05/05 TEDESCOR & Assistant Director for Licensing 2pp 15727 176 24X Fiche 50-000.822/06/28.8210010008
- B210040424 Forwards request for add1 info re hydragen control Coordinated wtil response suggested by mid-Oct 1982, since subjis generic to the condenser plants and MAKIT IN Assistant Director for Licensing 82/09/17 TUCKER. H B Buke Power Co. 10pp. 1559/ 241 24X Fiche 50-369, 82/09/17, 8210040424
- G210180389 Notifies that 790330 application requesting extension of const completion dates exempt from fee requirements since no review commenced on application prior to 1 sewance of OL Refund forthcoming MILLER. If O License Fee Management Branch 82/09/24 PARKER, W.C. Dure Power to 1p 15746-359 24X Fishs 50-369.82/09/24.
- 6210040254 Forwards application to amend License NPF-9 & CPPR-84, consisting of Revision 43 to FSAR & Revision 6 to Evaluation of Effects of Postulated Pipe Failures Outside Containment for McQuire Nuclear Station "
  IUCKER.H B Duke Power Co 62/10/01 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 15595 032 24X Fiche 50-369, 82/10/01.0210040254
  - 8910040273 Application to amend License NPF-9 & CPPR-84, consisting of Revision 43 to FSAR & Revision 6 to "Evaluation of Effects of Postulated Pipe Failures Outside Containment for AcCourte Nuclear Station" Outside Containment for TUCKER. H R Duke Power Co 82/10/01 16pp 15595 035 24X Fiche 50-369, 82/10/01, 8210040254
  - (210040279 Revision & to "Evaluation of Effects of Postulated Pipe Failures Dutside Containment for McGuire Nuclear Station" \* Duke Power Co. MDS/PDG 77-1 82/10/01 3pp 15995-051 24X Fiche 50 369 82/10/01/8210040254
- 5210130262 Forwards figures to Revision 43 to FSAR, included in 821001 application for Amend 69 to License NPF-9 & CPPR-84 Suby mail induvertently omitted TULKER, It b. Duke Power Co. 82/10/0/ DENTON, H.R. Office of Nuclear Reactor Regulation, Director in 24% Fiche 50-369, 82/10/0/ 8210130262
- 821028040/ Requests info demonstrating that Unit 2 equipment meets same serbmic & dynamic qualification requirements as Unit ! Info requested by 821027
  ADENSAM, E. G. Licensing Branch 4 82/10/08 TUCKER, H. B. Duke Power Co. 2pp. 15859 327 24X Fiche 50-369, 82/10/08, 8210280407
- 621018012t) Forwards list of important differences in Unit 1 & 2 design features. In support of review of proposed OL for Unit 2 TUCKER, H B Duke Power Co 62/10/11 DENTON-H R Office of Nuclear Reactor Regulation, Director ADENBAM, E O Operating Reactors Branch 4 2pp 15719 333 24X Fiche 50-370.82/10/11, 6210180128
- E210250304 Forwards revised requests for relief from hydrostatic testing requirements on feedwater sys for steam generators & Unit 1 safety injection sys ASME Code Section XI impractical TUCKER.H B Duke Power Co 82/10/19 DENTON.H R Office of Nuclear Reactor Regulation, Director 8pp 15790-205 24X Firms 50-369, 82/10/19,8210250304
- F Security, medical, emergency & fire protection plans
- 0210190097 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/09/29 Document Management Branch ip 15761 127 24X Fiche 50-369.82/09/29, 82/019097

- --8210190103 Forwards public version of revised emergency plan implementing procedure, including Procedure AP/0/A/5500/27 recare & transportation of contaminated injured individuals from site to offsite medical facility TUCKER.H B Duke Power Co 82/09/15 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15761 128 24X Fiche 50-369.82/09/29.8210190097
- --8210190108 Public version of revised emergency plan implementing procedures, including Procedure AP/O/A/5500/27 recare & transportation of contaminated injured individuals from site to effsite medical facility GLOVER, MS Duke Power Co 82/08/30 92pp 15761 130 24X Fiche 50-367,82/09/27,8210190097
- 8210070072 Notifies that local alarms missing from control room fire romes will be installed by 830701.per Jan 1979 fire protection review Issue not considered significant safety concern TUCKER.H B Duke Power Co 62/09/30 DENTON.H R. ADENSAM, E G Defice or Nuclear Reactor Regulation, Director 1p 15628 164 24% Fiche 50-369, 82/09/30, 8210070072
- 82:0180254 Responds to util 820520 itr re Revision 13 to physical security plan Changes consistent w/provisions of 10CFR50 54(p) ADENSAM, E 0 Licensing Branch 4 82/09/30 TUCKER, H B Duke Power Co 2pp 15745 337 24X Fiche 50-369.82/09/30.8210180254
- 8210150518 Forwards revised McGuire Nuclear Station Fire Protection Review "Submittal supersedes all previous revisions TUCKER, H B Duke Power Co 82/10/07 BENTON, H R , ADENSAM, E Q Office of Nuclear Reactor Regulation, Director ip 15714 219 24X Fiche 50-369, 82/10/07, 8210150518
- --8210150922 Revised "McQuire Nuclear Station Fire Protection Review "
  4 Duke Power Co 82/07/30 179pp 18714 220 24X
  Fiche 50-369.82/10/07.8210150518
- 8210270132 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 82/10/08 Document Management Branch ip 15835-136 24X Fichs 50-269,82/10/08, 8210270132
- --8210270137 Forwards public version of revised emergency plan implementing procedures including Procedure EP/O/A/5000/05 re notification of unusual event EP/0/A/5000/06 re alert & EP/0/A/5000/08 re general emergency TUCKER. H B Duke Power Co. 82/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp. 15835 137 24X Fiche 50-369, 82/10/08, 8210270132
- --B210270144 Public version of revised emergency plan implementing procedures, including Procedure EP/0/A/5000/05 re notification of unusual event.EP/0/A/5000/06 re alert & EP/0/A/5000/08 re general emergency gLOVER.M S , GJLBERT.6 D Duke Power Co B2/09/13 82pp 15835 139 24X Ficher 50-369, 82/10/08, 8210270132
- 8210190740 Forwards evaluation of facility concerning applicable requirements of iOCFR50. App R Device locations & cable routes omitted due to similarity w/Unit 1
  TUCKER, H B Duke Power Co 82/10/12 DENTON, H. R Office of Nuclear Reactor Regulation, Director ADENSAM, E 0 Licensing Branch 4 Spp (5736-250 24X Fiche 50-370, 82/10/12, 8210190740
- 8210280016 Releases public version of revised emergency plan FELTON.J M Division of Rules and Records 82/10/12 Document Management Branch 1p 15863 006 24% Fiche 50-369.82/10/12, 8210280016
- --8210280017 Forwards public version of Revision 7 to emergency plan TUCKER.H B Duke Power Co 82/09/28 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15863 007 24X Fiche 50-364.82/10/12,8210280016
- --8210280020 Public version of Revision 7 to emergency plan MCINIOSH, H D Buke Power Co 82/09/30 28pp 15863 009 24X Fiche 50-369,82/10/12,8210280016

#### H Conerat correspondence

8210130046 Responds to 920712 ltr request that NRC continue to send copies of correspondence to util on McGuire Bince McGuire proceedings corplete & documents in LPDR request denied ADENSAM, E. O. Licensing Branch 4 82/07/28 RILEY, J.L. Carolina Environmental Study Oroup 1p 15496 284 24X Fiche 50-000, 82/07/28, 8210130046

- K Utility Final Safety Analysis Report (FSAR) & amends
- B210040254 Forwards application to amend License NPF-7 & CPPR~84, consisting of Revision 43 to FSAR & Revision 4 to "Evaluation of Effects of Postulated Pipe Failures Qutside Containment for McQuire Nuclear Station"

  TUCKER.H B Dute Power Co 82/10/01 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM,E C Licensing Branch 4 3pp 15595 032 24% Fiche 50~369.82/10/01.8210040254
- --8210040286 Revision 43 to FSAR Fourteen aperture cards available in PDR

\* Duke Power Co 62/10/01 303pp 15595 054 24X Fiche 50-369,82/10/01:8210040254

- 8210130262 Forwards figures to Revision 43 to FSAR, included in 821001 application for Amend 67 to License NPF-7 & CPPR-84 Subj mati inadvertently omitted TUCKER.H B Dute Power Co. 82/10/07 DENTUN.H R Office of Nuclear Reactor Regulation. Director ADENSAN.E G Licensing Branch 4 ip 15475 293 244 Fiche 50-369, 82/10/07, 8210130262
- --8210130263 Figures for Revision 43 to FSAR \* Duke Pauer Co B2/10/07 42pp 15675 294 24X Fiche 50-369,82/10/07,8210130262
- Q Inspection reports, IE Bulletins & correspondence
- 8210010424 Forwards IE Insp Repts 50~369/82-29 & 50~370/82-23 on 820726-0820 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/09/08 TUCKER, H B Duke Power Co 2pp 15569 343 24X Fiche 50~369, 82/09/08, 8210010424
- -B210010434 IE Insp Repts 50-369/82-29 & 50-370/82-23 on 820726-0820 No noncompliance hoted Major areas inspected maint. surveillance, hot functional test operational safety verification, significant event followup & plant transients BEMIS.P R. MCPMINS.P. BRYANT.J C Division of Project & Resident Programs 82/09/08 App 15569 345 24X Fiche 50-369.82/09/08, 8210010424
- 8210010451 Forwards IE Insp Repts 50-369/82-28 & 50-370/82-22 on 820317-20 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/08 TUCKER.H B Duke Power Co 2pp 15572 297 24X Fiche 50-369, 82/09/08, 8210010451
- --8210010459 IE Insp Repts 50-369/82-28 & 50-370/82-22 on 820817-20 No noncompliance noted Major areas inspected preoperational test procedure review & test witnessing JDHNSUN A H . WHITENER, R L . JAPE, F Division of Engineering & Technical Programs 82/09/07 App 15572 299 24X Fiche 50-369, B2/09/08, 8210010451
- 8210010070 Ack receipt of IE Insp Repts 50-369/82-26 & 50-370/82-20 No proprietary infa TUCKER-N B Duke Power Co 82/09/15 O'REILLY, J. P. Regian 2, Office of Director 1p 15565 259 24X Fiche 50-369, 82/09/15, 8210010090
- 8210010387 Ack receipt of IE Insp Rept 50-370/82-19 No proprietary info TUCKER, H B Duke Power Co 82/09/15 O'REILLY, J P Region 2, Office of Director 1p 15549 211 24X Firhe 50-370, 82/09/15, 8210010387
- 8210150053 Forwards IE Insp Rept 50-370/82-25 on 820831-0903 No noncompliance noted DANCE-H C Division of Project & Resident Programs 82/09/22 TUCKER.H B Duke Power Co 2pp 15701 119 24X Fiche 50-370, 82/09/22, 8210150053
- --8210150062 IE Insp Rept 50-370/82-25 on 820831-0903 No noncompliance noted Major areas inspected preoperational test procedure reviews & witenessing JOHNSON, A H., JAPE, F. Division of Engineering & Technical Programs 82/09/15 4pp 13701 121 24X Fiche 50-370,82/09/22,8210150053
- 8210010093 Ack receipt of IE Insp Rept 50-370/82-21 No proprietary info TUCKER. H. B Duke Power Co 82/09/23 O'REILLY, J.P. Region 2, Diffice of Director ip 15565 003 24X Fiche 50-370, 82/09/23, 8210010093
- 8210150116 Forwards IE Insp Repts 50-369/82-32 & 50-370/82-26 on 820831-0903 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/09/24, TUCKER,H 8 Duke Power Co 2pp 15698 018 24X Fiche 50-369,82/09/24,8210150116

- --82i0150123 IE Insp Repts 50-369/82-32 & 50-370/82-26 on 82083i-0903 No noncompliance noted Major areas inspected licensee actions on previous enforcement matters, licensee identified items & hanger weld fabrication ECONOMOS.N., BLAKE, J. Division of Engineering & Technical Programs 82/08/22 Spp 15698 020 24% Fiche \$0-369.82/09/24, 8210150116
- 8210220328 Forwards IE Insp Rept 50-370/82-28 on 820914-17 No noncompliance noted DANGE.H C Division of Project & Resident Programs 82/09/29 TUCKER.H B Duke Power Co 2pp 15776 145 24X Fiche 50-370,82/09/29,8210220328
- --8210220337 IE Insp Rept 50-370/82-28 on 820914-17 No nencompliance noted Hajor areas inspected preoperational test procedure to task package reviews

  JOHNSON:A H Division of Project & Resident Programs JAPE. F Division of Engineering & Technical Programs B2/09/28 App 15776-147 24X Fithe 50-370, 82/09/29,8210220328
- 8208190233 IE Info Notice 80-35, Suppl 1, "Loaking & Dislodged 1 125 Implant Seeds " Svc list encl COBBL I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000.82/10/06.8208190233
- 8210220202 Ack receipt of 16 Insp Repts 50-369/82-28 & 50-370/82-22 No proprietary info TUCKER: N B Duke Power Co 82/10/08 O'REILLY, J P Regian 2, Orfice of Director 1p 15776 357 24% Fishe 50-349, 82/10/08, 8210220202
- 8210220206 Ack receipt of 1E Inap Repts 50-369/82-29 & 50-370/82-23 No proprietary info TUCKER, HB Duke Power Co 82/10/08 O'REILLY, J P Region 2, Office of Director 1p 15776-352 24X Fiche 50-369,82/10/08, 8210220206
- 8208190238 IE Bulletin B2-03, "Stress Corresion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants "Svo list end!
  DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co. of New York 115pp 15810-125 24X fiche 50-000.82/10/14.8208190238
- S Reportable occurrences, tERs t related correspondence
- 8210010424 Forwards IE Insp Repts 50-369/82-29 & 50-3/0/82-23 on 820726-0820 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/07/08 TUCKER, H B Date Power Co 2pp 15569 342 24X Fiche 50-369, 82/09/08, 8210010424
- --8210010436 IE Insp Repts 50-369/82-29 % 50-370/82-23 on 820726-0820 noncompliance noted Major areas inspected maint, surveilance, hot functional (est toperational) safety verification, significant event followip & plant transients BEMIS:PR Division of Project & Resident Programs 82/09/08 6pp 15569 345 24% Fiche 50-369, 82/09/08.8210010424
- 8210290045 Significant Deficiency Rept SD 370/82-05 re-problem w/65PS on-line testing circuits Initially reported on 820920 Test procedures revised to ensure relay test circuits in SSPS operate properly
  TUCKER.H B Duke Power Co 82/10/20 G'REILLY.J P Region 2.
  Office of Director 3pp 15853 331 24X Fiche 50-370,82/10/20,8210290045

# DOCKET 50-373 LABALLE COUNTY STATION, UNIT 1

- A Application/construction stage documents & correspondence
- E21001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records B2/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24x Fichs 50-000, 82/06/28, 821001000B
- --8008050265 Discusses addl required info to better define potential f cracking in reactor vessel noizles NOONAN.V S. Assistant Director for Materials & Gualifications Engineering 80/05/05 TEDESCO.R L Assistant Director for Licensing 2pp 15727:176 24X Fiche 50-000,82/06/28,8210010008

- f Security, medical, emergency & fire protection plans
- 8209270125 Releases public version of revised generating station emergency plan corporate command ctr emergency plan toplementing procedure FELION. J M Division of Rules and Records 82/09/16 Documentagement Branch 1p 15564 122 24X Fiche 50-000, 82/09/16

- -8209290189 Furwards public version of Revision 4 to generating station emergency plan corporate command ctr Emergency Plan Implementing Procedure EUF-3, "Environ/Emergency Coordinator " Receipt form encl PAJDWSNI.J E Commonwealth Edison Co 82/09/01 DENIUN, H R NRC No Detailed Affiliation Given 1p 15564 123 244 Fiche 50-000.82/09/16.8209290125
- 8209290225 Public version of Revision 4 to generating station emergency plan corporate command the Emergency Plan Implementing Procedure EGF-3, "Environ/Emergency Coordinator PAJONSKI J E Commonwealth Edison Co 24X Fiche 50-000, 82/09/14, 8209290125
- \$16060379 Forwards IE Inso Rept 50-373/82-19 on 820317-19,24-26 & 0409 No noncompliance noted
  | |TTLE.W S Division of Engineering & Technical Programs 82/09/21
  | REFD, C Commonwealth Edison Co 2pp 15618 330 24X
  | Fich 50-373.82/09/21.82/0060379
- H2100603B4 IE Insp Rept 50-373/82-19 on 820317-19.24-24 & 0408 No erovocase in Insp Rept 30-3/3/06-17 on 82031/-17,24-26 & 0408 f nencumpliance noted Major areas inspected licensee action on previous insp findings to fire protection program HENDEZ, R. GROBE, J. Witt IAMG, C.C. Division of Engineering & Technical Programs 82/07/14 13pp 15518 332 24X Fiche 50-373,82/09/21,82100603/9
- 710050052 Ack receipt or 920723 ltr informing NRC of steps taken to correct violations noted in IE Safequards Insp Rept  $59{\text -}377/92{\text -}39$
- MILLER, J. R. Division of Engineering & Technical Programs 82/09/30 REED, C. Communucalth Edison Co. 2pp. 15605-188 24X Fiche 50-373,82/09/30.8210050052
- P210059056 Forwards response to NRC 020824 ltr re viplations noted in IE Safeguards Insp Rept 50-373/82-39 Response withheld (ref\_loCFR73\_21) DEL GEORGE, L. G. Commonwealth Edison Co. 82/09/23 KEPPLER, J. G. Røgion 3, Office of Director. 2pp. 15605 190. 24X Fiche 50-373,82/09/30.8210050052
- 10130376 Advises that installation of offsite dose calculation sus program fully operational tracking model & operational Armodel will be delayed until 828231 to complete prime A-model with be delayed until BERMI to complete prime computer initalization SMARTZLE D. Commonwealth Edison Co. 82/10/06 DENTON, H.R. D of Nuclear Reactor Regulation, Director 2pp 15682-098 24X Fiche 50-000, 82/10/06/8210130376 Difice
- 10290047 Releases public version of revisions to Guad Cities. Zion & TOWN UNIT WELLS BY PUBLIC VERSION OF POVISIONS to Quad Cities, Zinesselven emergency plan annexes & revised generating station emergency plan telephone directory FELTON. J M Division of Rules and Records 82/10/08 Docum Management Branch 1p 15877 313 24X Fiche 50-000,82/10/08,82/10290047 Document
- 82182900m0 Forwards public version of Revision 3 to Guad Cities & Zion 210290000 Forwards public version of Mayision to Guad Cities & 21c emorgancy plan annerss. Revision 2 to Drasden emergency plan anners. Revision O to Dyron emergency plan annex t revised generating station emergency plan telephone directory MODRE.R D Communuelth Edison Co 82/07/30 DENTON.H R NRC - No Detailed Affiliation Given Spp 15877 314 24X Fichs 30-000.82/10/08.8210290047
- 821029008B Public version of revised generating station emergency plan telephone directory GALLE.D.P. Commonwealth Edison Co. 82/08/12 43pp 15878 218 24x Fiche 50-000,82/10/08.8210290047
- 10220358 Provides info re organization & performance of depts responsible for radiation protection activities; per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs
  IRAMM, T.R. Commonwealth Edison Co. 82/10/14 DENTON, H.R. Co. No. 1982 Reactor Regulation, Director 9pp 15776 287 24 24%

- G Adjudicatory correspondence
- 8210040366 Responds to appeal re denial of FOIA request for four 210040366 Responds to appeal re denial of FULA request for four affidavite concerning allegations of improper const practices at facility Forwards requested info Page 4 of E Greve affidavit withheld (ref FOIA Exemption 7) DIRCKS W J Office of the Executive Director for Operations 82/08/24 STEP10E.P F Isham Lincoln & Beale 2pp 15997 303 24% Fiche 50-373.82/08/24,8210040366
- --8210040375 Forwards four affidavits re safety problems at facility Proprietary info deleted from two affidavits DEVINE, T Institute for Policy Studies 82/05/11 FDRTUNA.R Director's Office, Office of Inspection and Enforcement 1p 15597 315 24X Fiche 50-373,82/08/24,8210040366
- --8207140491 Affidavit re results of sloppy concrete pours, hales & honeycombs in concrete Accumulated debris not disposed of prior to pour & too much concrete poured at one time Worker health not main concern of supervisors
  SWARTZ,D W Affiliation Unknown 82/06/24 10pp 15597 316 24X Fiche 50-373, 82/08/24, 8210040366
- ---8207140494 Affidavit re safety-related const flaws in installation of pipes & supports Pipes & hanger supports not placed as pipes & supports Pipes & hanger supports not placed as specified GREVE.E Affiliation Unknown 82/04/22 App 15597 326 Fichs 50-373,82/08/24.8210040366 24 Y
- ~-8207140497 Affidavit re damage to fire protection equipment such as sprinklers throughout plant during const Concerns raised over core drillings of concrete reinforcement bars in containment walls & pedestal Hangers not as specified \* Affiliation Unknown 82/04/21 App 15597 332 24X Fiche 30-373,82/08/24.8210040366
- --8207140500 Affidavit re sloppy workmanship leading to const damage Const crews core drilled through reinforcement bars, containment wall & reactor vessel pedestal around 694 foot elevation of Unit 1 \* Affiliation Unknown 82/04/21 3pp 19597 338 24X \* 1chs 50-373, 82/08/24 8210040366

- 8210070042 Responds to 820816 Itr re third party review Forwards Itr responding to util selection of CF Braun & program for review of HVAC sys NOVAK,T M. Assistant Director for Licensing 82/09/10 MCRELLA,5 L. Affiliation Unknown 2pp 15646 226 24 Fiche 50-373,82/09/10,8210070042
- --8210070045 Responds to 820813 ltr re third party review Forwards ltr responding to util selection of CF Braun & program for review of HVAC sys W/o stated encl NOVAK.TM Assistant Director for Licensing 82/09/10 DEVINE, T Affiliation Unknown 1p 15646 228 24% Ficha 50-373,82/09/10, 82
- --8210070051 Responds to 820813 ltr re third party review Forwards ltr responding to util selection of CF Braun & program for review of HVAC sys W/o stabed encl NOVAK.T M Assistant Director for Licensing 82/09/10 HOWARD, A T Affiliation Unknown ip 19848 229 24% Fiche 50-373,82/09/10.8210070042
- --BRIO070055 Responds to 8208R4 ltr re third party review Forwards ltr responding to util selection of CF Breun & program for review of HVAC sys W/o stated encl NOVAK.T M Assistant Director for Licensing 82/09/10 0D001E.V B Illinois, State of 1p 15646 230 24X Fiche 30-373,82/09/10.8210070042
- --8210070061 Responds to 820824 ltr re third party review Forwards ltr responding to util selection of CF Braun & program for review of HVAC sys W/o stated encl MOVAK, T M. Assistant Director for Licensing 82/09/10 ROREM, B L. Affiliation Unknown Ip 15646 231 24X Fiche 50-373,82/09/10,8210070042
- --B210070066 Responds to B20824 ltr re third party review Forwards ltr responding to util selection of CF Braun & program for review of HVAC sys Revisions also encl NOVAK.T M. Assistant Director for Licensing B2/09/10 000DL.E M. Citizens Against Nuclear Power 1p 15646 232 24X Fiche 50-373.82/09/10.8210070042

## P Operating license stage documents & correspondence

- 8208040341 Forwards INEL draft technical evaluation rept based on util response to 801222 generic ltr. "Control of Heavy Loads "
  Conference call to resolve open items planned in approx 4 wits W/o encl
  SCHMENCER.A Licensing Branch 2 82/07/02 DELGEGROE, L O Commonwealth Edison Co 2pp 14978 002 24X Fiche 50-373,82/07/02,8208040341
- 8210010015 Discusses util 920824 & 27 technical proposals for independent HVAC sys review required by License Condition 2 C (33)(b) Selection of CF Braun as reviewer acceptable Listed comments on program should be considered NDVAK. T H Assistant Director for Licensing 82/09/08 REED. C Commonwealth Edison Co. 4pp. 15577-242 24X Fiche 50-373,82/09/08,8210010015
- 8210040221 Forwards Revision 10 to "Mark II Design Assessment Rept" containing Confirmatory assessment of containment design adequacy for pool dynamic loads developed in conjunction w/long-term program described in NOREG-0808 SCHROEDER.C W Communwealth Edison Co 82/09/24 SCHHENCER.A Licensing Branch 2 2pp 15587 179 24% Fiche 50-373,82/09/24,8210040221
- --8210040223 "Mark II Design Assessment Rept." Revision 10 \* Commonwealth Edison Co 82/09/30 82pp 15587 181 24X Fiche 50-373.82/09/24.8210040221
- 8210050097 Forwards evaluation of draft BMR owners group rept re alternative design mods of automatic depressurization sys (ADS) logic Incorporation of manual ADS inhibit switch w/timer recommended SCHROEDER:C W Commonwealth Edison Co 82/09/30 SCHMENCER.A Licensing Branch 2 30pp 15604 353 24X Fiche 50-373,82/09/30,82/055097
- 8210130241 Responds to NRC 820706 request for add1 info re high energy line breaks on postulated nonsafety power buses nonsafety control sys or monsafety sensors, including instrument line failures
  SCHROEDER.C W Commonwealth Edison Co 82/10/04 SCHHENCER.A Licensing Branch 2 11pp 15674 151 24X Fiche 50-373,82/10/04,8210130241
- 8210130233 Informs that EMD MI 9644 mod re diesel generator prelubp oil pump mod is superior to NRC proposed fix & meets functional requirements of License Condition 2 C 21 b Prelube would deprade reliability of diesel generators SCHROEDER.C W Commonwealth Edison Co 82/10/06 SCHWENCER.A Licensing Branch 2 App 15675 220 24X Fiche 50-373,82/10/06,8210130233
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" GOLDEN, JC Commonwealth Edison Co 82/10/06 CASE,E 0 Office of Nuclear Reactor Regulation, Director 2pp 15805 137 24X Fiche 50-000,82/10/06,8210260526
- --8210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual"

  \* Commonwealth Edison Co 82/09/30 83pp 15805 139 24X Fiche 50-000, 82/10/06. 8210260526
- 6210260151 Forwards supplemental response to EG&O draft technical evaluation rept of util 820622 itr re N.REO-0612. "Control of Heavy Loads at Nuclear Power Plants"

  SWARTZ-E D Commonwealth Edison Co 62/10/19 EISENHUT, D O Division of Licensing 17pp 15803 300 24X Fiche 50-373, 82/10/19, 8210260151
- Q Inspection reports, IE Bulletins & correspondence
- 8210060379 Forwards IE Insp Rept 50-373/82-19 on 820317-19,24-26 & O408 No noncompliance noted LITTLE MS Division of Engineering & Technical Programs 82/09/21 REED: C Commonwealth Edison Co 2pp 15618 330 24X Fiche 50-373
- --8210060384 IE Insp Rept 50-373/82-17 on 820317-19,24-26 & 0408 No noncompliance noted Major areas inspected licensee action on previous insp findings re fire protection program HENDEZ,R, QROBE,J, HILLIAMS,C C Division of Engineering & Technical Programs 82/07/14 13pp 15618 332 24X Fiche. 50-373, 82/09/21, 8210060379
- 8210190589 Forwards IE Mgt Meeting Repts 50-373/82-44 & 50-374/82-12 on 820830 & 0913 No noncompliance noted LITTLE. H 8 Division of Engineering & Technical Programs 82/09/29 REED: C Commonwealth Edison Co 2pp 15739 287 24X Fichs 50-373,82/09/29,8210190589

- --B21019060! IE Mgt Meeting Repts 50-373/82-44 & 50-374/82-12 on 620830 & 0913 No noncompliance noted Major areas discussed voids found in wall at 710 5-ft elevation on Colomn Line 16 JACKEN, IN , LIPINSKI, R. Division of Engineering & Technical Programs 82/09/20 16pp 15739 289 24X Fiche 50-373, 82/09/29, 8210190589
- 8210050052 Ack receipt of 820923 ltr informing NRC of stops taken to correct violations noted in IE Safeguards Insp Rept 50-073/82-39
  MILLER, J. R. Division of Engineering & Technical Programs 82/09/30 REED. C. Commonwealth Edison Co. 2pp 15605 188 24%
  Fiche 50-073, 82/09/30, 82/0050052
- --B210050056 Forwards response to NRC B20824 ltr re violations noted in IE Safeguards (map Rept 50-373/82-39 Response withheld (ref 10CFR73 2!)

  DELOEDROEL O Commonwealth Edison Co B2/09/23 KEPPLER, J C Region 3, Office of Director 2pp 15605 170 24X

  Fiche 50-373, B2/09/30, B210050052
- 8210060266 Ack receipt of 820916 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Rept 50-373/82-37 SPESSARD.R L. Division of Project & Resident Programs 82/10/04 REED.C Commonwealth Edison Co. 1p 15621 079 24X Fiche 50-373.82/10/04.8210060266
- --821006026B Responds to NRC B20B17 itr re-noncompliance noted in II Insp Rept 50-373/82-37 Corrective actions training conducted on B20709 w/entire instrument maint shop, covering LAP 300-9 & LIP 6M-62 which was documented for training records DEL0E086E.L O Commonwealth Edison Co 02/07/16 KEPPLER, J G Region 3, Defice of Director 3pp 156/21 080 24X Fiche 50-373,82/10/04.8210060266
- 82101906B2 Forwards IE Insp Rept 50-373/82-42 on \$20006-0901 No noncompliance noted LITTLE, W B Division of Engineering & Technical Programs D2/10/04 REED, C Commonwealth Edison Co 2pp 1573B 146 24X Fiche 50-373, 82/10/04,8210190682
- --8210190694 IE Insp Rept 50-373/82-42 on 820806-0901 No noncompliance noted Major areas inspected startup testing review of startup test results; complete review of safety relief valve b special startup test procedure MAURA,F, ROBINSON D, JACKIH,I Division of Engineering & Technical Programs 82/09/29 4pp 15738 148 24X Fiche 50-373,82/10/04.8210190682
- 8208190233 IE Info Notice BO 35, Suppl 1, "Leaking & Dislodged I-12b Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15/61 200 24% Fiche 50-000.82/10/06.8208190233
- B210250105 Forwards IE Insp Repts 50-373/82-41 & 50-374/82-09 on 820802-31 & notice of violation STREETER. J F Division of Project & Resident Programs D2/10/07 REED. C Commonwealth Edison Co. 2pp 15787 152 24X Fiche 50-373,82/10/07.8210250105
- --9210250109 Notice of violation from insp on B20B02-31 STREETER J F Division of Project & Resident Programs B2/10/07 Sp 15787 154 24X Fiche 50-373. B2/10/07. B210250105
- --8210250116 IE Insp Repts 50-373/82-41 & 50-374/82-09 on 820802-31 Noncompliance noted unsupervised trained performed reactivity manipulations GULDEMOND, W 9 . WRIGHT, 0 . MADISON, A Division of Project & Resident Programs 82/10/04 9pp 19787-1955 24X Fiche 50-373, 82/10/07, 8210250105
- 820B19023B IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BWR Plants " Svc list encl DEYGUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- 9210280122 Ack receipt of 820920 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-373/82-30 Corrective actions acceptable SPESSARD,R L. Division of Project & Resident Programs 82/10/22 REED.C. Commonwealth Edison Co. 2pp 15837 108 24X Fiche 80-373,82/10/22,8210280122
- --8210280125 Forwards response to NRC 820819 ltr re violations noted in IE Insp Rept 50-373/82-30 Corrective actions onsite review conducted on 820524 to determine abnormal trend in LERs associated w/personnel errors t lifted leads relanded DELOEDROEL O Commonwealth Edison Co 82/07/20 KEPPLER, J 0 Region 3, Office of Director 7pp 15937 110 24X Fiche 50-373,82/10/22,8210280122

## R Periodic operating reports & related correspondence

- 8210130200 Forwards monthly operating rept for Sept 1982 DIEDERICH G J Commonwealth Edison Co 82/10/07 Management Information Branch Lp 19675 243 24X Fiche 50-373, 82/10/07. 8210130200
- --8210130215 Monthly operating rept for Sept 1982 LLRICH-J Commonwealth Edison CO 82/10/07 14pp 15675 244 24% Fiche 50-373, 82.10/07, 8210130200
- S Reportable occurrences LERs & related correspondence
- G\_10040131 Forwards LER 82-098/03L-0 DIEDERICH G J Commonwealth Edison Co 82/09/15 KEPPLER J G Region 3. Office of Director 1p 15581 215 24X Fiche 50 373 82/09/15.8210040131
- 0210040134 LER B2-098/03L-0 on 02002A.distovered that rigid restraint installed on line IRI67AB-1/2 Inch in place of snubber Caused by mechanical contractor design & installation error Snubber installed & evaluation completed SPENCER.D Commonwealth Edison Co 022/09/15 Region 3, Office or Director 2pp 15501 216 24% Fiche 50-373,02/09/15, 8210040131
- #21(060251 Forwards LER #2 097/03L-0 DIEDERICH, G J Commonwealth Edison Co #2/09/20 KEPPLER, J @ Region 3 Office of Director 1p 15621 201 24X Fiche 50 373.82/09/20.82(0060251
- -B7100A0252 LER 82-099/O3L-0 on 820830.svc water liquid process radiation monitor drifted high % declared inoperative Caused by electronic failure of gamma detector Work request initiated to correct problem LUETT.M Commonwealth Edison Co 82/09/20 Region 3, Office of Director 2pp 15821 202 24% Fithe 50-373,82/09/20,8210060251
- S210190462 Forwards NPDES noncompliance repts FIEDERICH.G J. Commonwealth Edison Co. 82/09/29 KEPPLER, J.G. Hegion 3. Office of Director 2pp. 15951 141 24X Fichs 50 373 82/09/29, 8210190462
- 8210190465 NPDFS noncompliance notification on 820801.total suspended solids 5 from in outfall ODIC low yol waste radwaste discharge tanks exceeded allowable limits Caused by mechanical problems w/radwaste evaporators s Commonwealth Edison Co 82/09/29 ip 15951 143 24X Fiche 50-733.82/07/29.8210190462
- -82(019048) NPDES noncompliance notification on 820910.oil & grease in outfell 001c low vol waste radwaste discharge tanks exceeded allowable limit Caused by mechanical failure of radwaste evaporator resulting in poor quality water \* Commonwealth Edison Co. 82/09/29 lp 19740 (80 24% fiche 50 373,82/09/29,8210190462
- 821019048/ Forwards NPDES noncompliance repts OIEDERICH, 0 J Commonwealth Edison Co 82/09/29 KEPPLER, J G Region 3, Office of Director 2pp 15735 325 24X Fiche 50 373,82/09/29,8210190487
- -8210190494 NPDES pencumpliance notification on 820903 total iron in outfall OOLc low vol waste regeneration wastes solution discharge tank exceeded allowable limit Caused by temporary hydrogen peroxide sys hot operating properly Commonwealth Edison Ca 82/09/29 Ip 15735 327 24X Fichs 50-373,82/09/29.8210190487
- 8210170498 Forwards NPDES noncompliance repts
  DIEDERICH O J Commonwealth Edison Co 82/09/29 KEPPLER, J 9
  Region 3, Office of Director 2pp 19735 340 24X
  Fiche 50-373,82/09/29,8210170449
- --8210190503 NPDES noncompliance notification on 820913, 9H at outfall ODIC low vol waste wastewater treatment facility fell but of specs Caused by acid waste generated from Unit 2 const activities Work request initiated to install pH monitor Commonwealth Edison Co 82/09/29 1p 15735 343 24X Fiche 50-373,82/09/29,8210190498
- 8210190509 Forwards NPDES noncompliance repts
  DIEDERICH, G. J. Commonwealth Edison Co. 82/09/29 KEPPLER, J. G. Regian 3, Office of Director 2pp. 15740 199 24X
  Fiche 50-373, 82/09/29, 8210190809

- --8210190514 NPDES noncompliance notification on 820914, total suspended solids & iron at outfall Odic low vol waste wastewater treatment facility exceeded allowable limits Caused by upset pH due to Unit 2 const activities

  \* Commonwealth Edison Co 82/09/29 ip 15740 202 24X Fiche 50-373, 82/09/29, 8210190509
- 8210190522 Forwards NPDES noncompliance repts
  DIEDERICH.O J Commonwealth Edison Co 82/09/29 KEPPLER.J G
  Region 3. Office of Director 2pp 15751 319 24X
  Fiche 50-373.82/09/29,8210190522
- --8210190525 NPDES noncompliance notification on 820909, total iron at outfall Odic low vol waste wastewater treatment facility exceeded allywable limit Caused by upset pH due to Unit 2 const activities Work request initiated to install monitor 4 Commonwealth Edison Co 82/09/29 ip 15751 321 24X Fiche 50-373, 82/09/29.8210190522
- 8210200002 Forwards NPDES noncompliance repts for facility DIEDERICH G J Commonwealth Edison Co 82/09/29 KEPPLER. J G Region 3. Office of Director 2pp 15756 327 24X Fiche 50-373, 82/09/29, 8210200002
- --8210200007 NPDES noncompliance notification on 820914, buildup of resin fines & other fine solids carried through strainers & sumps into discharge tank Gause not stated Regenerative waste solution discharge tank will be cleaned \* Commonwealth Edison Co 82/09/29 ip 15756 330 24X Fiche 50-373, 82/09/29. 8210200002
- 8210130234 Forwards LER 82-107/03L-0 DIEDERICH O J Commonwealth Edison Co 82/09/30 KEPPLER, J G Region 3, Office of Director 1p 15675 216 24X Fiche 50-373, 82/09/30, 8210130234
- ~-B210130236 LER B2~107/03L~O on 820812.control rad drive pump A tripped off on low suction pressure & control rad drive pump B failed to start Gaused by low CY storage tank level & valve 10D109 condensate/CBI reject being abnormally closed WINTERHOFF, D. Commonwealth Edison Co. B2/09/30 Region 3, Office of Director 3pp. 15675-217. 24X Fiche 50-373,82/09/30, 82/0130234
- 82:0190344 Forwards LER 82-103/03L-0 DIEDERICH O J Commonwealth Edison Co 82/10/04 KEPPLER J Q Region 3. Office of Director ip 15737 245 24X Fiche 50-373 82/10/04 8210190344
- --B210190346 LER B2-103/03L-0 on B20919. Hi Rad alarm sounded Operator checked chart recorder & noticed A RRM svc water radiation monitor read gounscale Alarm caused by trip in power supply to monitor Power supply reset KAY. D L Commonwealth Edison Co B2/10/04 Region 3. Office of Director 2pp 19737 246 24% Fiche 50-373, B2/10/04. B210190344
- 8210190050 Forwards LER 82-104/03L-0 DIEDERICH/O J Commonwealth Edison Co 82/10/05 KEPPLER, J Q Region 3, Office of Director 1p 18742 136 24X Fichs 50-373, 82/10/05, 8210190050,

- 8210190606 Revised Final Deficiency Rept B2-10 re RCIC underground piping Replacement piping work complete except for tie to Unit 1 RCIC sys inside bldg which requires 4-day outage Work will be completed during first available outage SCHROEDER.C W Commonwealth Edison Co 82/10/00 KEPPLER.J G Region 3. Office of Director 1p 15739 353 24X Fiche 50-373.82/10/08.8210190606
- 8210250152 Forwards LER 82-102/03L-0 DIEDERICH 6 J Commonwealth Edison Co 82/10/15 KEPPLER.J 6 Region 3. Office of Director 1p 15789 311 24X Fichs 50-373.82/10/15.8210250152
- -8210250163 LER 82-102/O3L-O on 820916, reactor vessel low water lovel scram setpoint BPIS-IB21-N0248 found out of callbr Caused by instrument drift Required tolerance under revision instrument to be callbr weekly WINTERHOFF, D Commonwealth Edison Co 82/10/15 Region 3, Office of Director 2pp 15789 312 24X Fiche 50-373,82/10/15,8210250152
- 8210260210 Forwards LER 82-110/03L-0 DIEDERICH.O J Commonwealth Edison Co 82/10/18 KEPPLER.J 0 Region 3. Office of Director 1P 15804 266 24X Fiche 50-373.82/10/18.8210260210
- --B210260221 LER B2-110/O3L-O on B20920, standby liquid control tank level measured low Caused by evaporation Trending of evaporation rate initiated under AIR 1-B2-513 Tank level raised \* Commonwealth Edison Co B2/10/19 Region 3, Office of Director 2pp 15804 267 24% Fiche 50-373,82/10/18,B210260210
- 8210260227 Forwards LER 62-111/03L-0 DIEDERICH, 0 J Commonwealth Edison Co 82/10/18 KEPPLER, J G Region 3. Office of Director 1p 15804 259 24X Fiche 50-373, 82/10/18, 8210260227
- --B21026023B LER B2-111/O3L-0 on B20927, high airborne activity discovered in raduaste reboiler room Caused by insufficient weld penetration of tee between valves IB21-F592 & IB21-F592 Tee cut out & replaced Reboiler returned to svc + Commonwealth Edison Co B2/10/18 Region 3, Office of Director 2pp 15804 260 24% Fiche 50-373, B2/10/18, B210260227
- 8210260311 Forwards LER 82-108/03L-0 DIEDERICH 0 J Commonwealth Edison Co 82/10/18 KEPPLER J 9 Region 3 Office of Director 1p 15799 355 24X Fichs 50-373, 82/10/13, 8210260311
- --8210260313 LER 82-108/03L-0 on 820920, LIS-NB-187, ADS accumulator backup N2 channel functional & calibr discovered not performed as specified by Tech Spec Caused by surveillance procedure not entered into program Procedure revised WINTERHOFF, D. Commonwealth Edison Co. 82/10/18 Region 3, Office of Director 2pp 15799 356 24X Fiche 50-373,88/10/18,8310340311
- 8210260115 Forwards LER 82-114/01T-0 DIEDERICK 6 J Commonwealth Edison Co 82/10/19 KEPPLER, J G Region 3, Office of Director ip 15799 109 24X Fiche 50-373, 82/10/19, 8210260115
- --B21026011B LER 92-114/01T-0 on B21005, installed configuration of HVAC duct hanger 1382 did not match design Drawing M-1538 Caused by misinterpretation of FCR by draftsman Sargent & Lundy Drawing M-1538 will be revised prior to 821008 OIEBEKER, J Commonwealth Edison Co 82/10/19 Region 3, Office of Director 2pp 15799 110 24% Fiche 50-373,82/10/19, 8210260115

- --8210260321 LER 82-106/03L-0 on 820920, during performance of LOB-PC-QI, valve 1833-F019 did not close Caused by foreign mat1 blocking valve open Outboard isolation valve 1833-F020 closed Blockage removed prior to work initiation HIETALA, J Commonwealth Edison Co 82/10/19 Region 3. Office of Director 2pp 15799 336 24X Fiche 50-373.82/10/19, 22/10/317
- T Hearing transcripts on non-antitiust matters
- B210210508 Forwards Commission determination statement releasing B20622 transcript of discussion of full power QL Pp 1-66 CMILK, SJ Office of the Secretary of the Commission B2/10/0', Public Document Branch 2pp 15784 204 24% Fiche 50-373,82/10/05,8210210508
- --8210210512 Transcript of 820622 closed meeting in Washington, DC rediscussion of full gover OL Pp 1-66

  \* Commissioners 82/06/22 70pp 15/84 206 24x
  Fiche 50-373,82/10/05.8210210508
- DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL, R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000, 82/06/28, 8210010008
- --8008050265 Discusses addl required info to better define potential for cracking in reactor vessel notiles NODNAN,V S Assistant Director for Materials & Qualifications Engineering 80/05/05 TEDESCO.R L Assistant Director for Licensing 2pp 15727 176 24% Fiche 50-000.82/06/28.8210010008
- 8208040341 Forwards INEL draft technical evaluation root based on util response to 801282 generic ltr. "Control of Heavy Loads "Conference call to resolve open items planned in approx 4 wks W/o enci SCHWENCER.A Licensing Branch 2 82/07/02 DELGEORGE.L G Commonwealth Edison Co 2pp 14978 002 24% Fiche 50-373,82/07/02,8208040341
- B210040221 Forwards Revision 10 to "Mark II Design Assessment Rept" containing confirmatory assessment of containment design adequacy for pool dynamic loads developed in conjunction w/ long-term program described in NUREO-0808 SCHROEDER.C W Commonwealth Edison Co 82/09/24 SCHWENCER.A Licensing Branch 2 2pp 15587 179 24X Fiche 50-373,82/09/24.8210040221
- --8210040223 "Mark II Design Assessment Rept." Revision 10 \* Commonwealth Edison Co 82/09/30 B2pp 15587 181 247 Fiche 50-373.82/09/24.8210040221
- 9210050097 Forwards evaluation of draft BMR owners group rept re alternative design mods of automatic depressurization sys (ADS) logic Incorporation of manual ADS inhibit switch w/timer recommended SCHROEDER, C W Commonwealth Edison Co B2/09/30 SCHWENCER, A Licensing Branch 2 30pp 15604 353 24X Fiche 50-373,82/09/30, 8210050097
- 8210130241 Responds to NRC 820706 request for add1 info re high energy line breaks on postulated nonsafety power buses, nonsafety control sys or honsafety sensors, including instrument line failures
  8CHRDEDER, C W Commonwealth Edison Co 82/10/04 SCHWENCER, A Licensing Branch 2 11pp 15674 151 24X Fiche 50~373,82/10/04, 8210130241
- 8210130233 Informs that EMD MI 9644 mod re diesel generator preluhe oil jump mod is superior to NRC proposed fix & meets functional requirements of License Condition 2 C 21 b Prelube would degrade reliability of diesel generators SCHROEDER, C W Commonwealth Edison Co 82/10/06 BCHWENCER, A Licensing Branch 2 6pp 15675 220 24X Fichs 50-373,82/10/06,8210130233
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" QULDEN, J C Commonwealth Edison Cp 82/10/06 CASE, E 0 Office of Nuclear Reactor Regulation, Director 2pp 15805-137 24X Ficha 50-000, 82/10/06

- B210260542 Revision 3 of Chapter 9 of 'Offsite Dose Calculation Manual" \* Commonwealth Edison Co 62/09/30 83pp 15805 139 24X Fiche 50-000 82/10/06,8210260526
- 8210260151 Forwards supplemental response to EG&G draft technical evaluation rept of util 820622 ltr re NUREG-0612. "Control or Heavy Loads at Nuclear Power Plants "
  SMARTZ.E D Commonwealth Edison Co 62/10/19 EISENHUT, D G
  Division of Licensing 17pp 15803 300 24X Fiche 50-373, 82/10/19, 6210240151
- F Security medical emergency & fire protection plans
- 6.0% 90125 Releases public version of revised generating station emergency plan corporate command ctr emergency plan implementing procedure FELTON J M Division of Rules and Records 82/09/16 Document Management Branch ip 19564-122 24X Fiche 90-000,82/09/16, 2003-90125
  - 8209270189 Forwards public Mension of Revision 4 to generating station omergancy plan comporate Lommand of Emergency Plan Implementing Procedure (DF-3 "Environ/Emergency Coordinator" Receipt form encl PAJWOKL DE Communication Edison to 82/09/01 DENTON, H.R. NRC No Detailed Affiliation Circo Ip 15964-123 24X Fiche 50-000 86/09 to 82/990125
  - 8207270.25 Public version of Revision 4 to generating station emergency plan corporate command Ctr Emergency Plan Implementing Procedure EOU 3. "Environ/Emergency Coordinator" PAJUMBNI J E (demonwealth Edison Co 82/08/31 [1pp 15564 12] 24/ Firms 50-000, 07/07/16, 8209290175
- Sciol 2017a Advises that installation of offsite dose calculation synprogram fully operational tracking model & operational A model will be delayed until 821231 to complete prime computer installation SWARTZ E D. Commonwealth Edison Co. 82/10/06 DENION, R. Offsice un Nuclear Reactor Regulation. Director 2pp. 15682 098 247 inche 50 000 82/10/06.81013 30376
- Larguago: 47 Releases public version of revisions to Quad Cities. Zion & Urgsden emergency plan anierses & revised generating station emergency plan telephone directory rection / M. Division or Rules and Records 82/10/08 Document Management Branch ip 1587/313 24% Fiche 50-000.82/10/08. U210290047
  - M210270060 Forwards public version of Revision 3 to Quad Cities & Zion emergency plan annexes Revision 2 to Dresden emergency plan annex Revision 0 to Nyron emergency plan annex & revised generating station emergency plan telephone directory MUGRE R D. Commonwealth Edison Co. 82/07/30 DENTON, H.R. NRC No Detailed Affiliation Given 5pp. 15877-314 24X Fiche 50 000 82/10/08 8/10290047
  - 8210290088 Public version of revised generating station emergency plan telephone directory GALLE D P Commonwealth Edison Co 82/08/12 43pp 15878 218 24X Fiche 50-000 62/10/08/8210290047
- 0210220358 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 connitment Training coordinator assigned in Apr 1982 to improve health physics training programs TRAMMITR Commonwealth Edison Co 82/10/14 DENTON, HR Office or Nuclear Reactor Regulation, Director 9pp 15776-287 24X Fiche 50-000, 82/10/14, 8210220358

# G Adjudicatory correspondence

- 6210040366 Responds to appeal re denial of FOIA request for four affidavits concerning allegations of improper const practices at facility Forwards requested info Page 4 of E Greve affidavit withheld (ref FOIA Exemption 7) DIRCKE, W J Office of the Executive Director for Operations 82/08/24 STEPTOE.P P Isham. Lincoln & Beale 2pp 15597 303 24 Fiche 50-374.82/08/24.6210040366
- --8210040375 Forwards four affidavits re safety problems at facility Proprietary info deleted from two affidavits DEVINE,T Institute for Policy Studies 82/05/11 FORTUNA,R Director's Office. Office of Inspection and Enforcement 1p 15597-315 24X Fiche 50-374,62/06/24,6210040366

- --8207140491 Afridavit re results of sloppy concrete pours,holes & honeycombs in concrete Accumulated debris not disposed of prior to pour & too much concrete poured at one time Worker health not main concern of supervisors
  SWART2.D W Affiliation Unknown 82/06/24 10pp 15597 316 24X Fiche 50-374,82/08/24,8210040366
- --8207140494 Affidavit re safety-related const flaws in installation of pipes & supports flipes & hanger supports not placed as specified GREVE.E Affiliation Unknown 82/04/22 App 15597 326 24X Fiche 50-374,82/08/24,8210040366
- --8207140497 Affidavit re damage to fire protection equipment such as sprinklers throughout plant during const Concerns raised over core drillings of concrete reinforcement bars in containment walls & pedestal Hangers not as specified # Affiliation Unknown 82/04/21 6pp 19597 332 24% Fiche 50-374,82708/24,8210040366
- --8207140500 Affidavit re sloppy workmanship leading to const damage Const crews core drilled through reinforcement bars, containment unil % reactor vessel pedestal around 694 foot elevation of Unit 1 # Affiliation Unknown 82/04/21 3pp 15597 338 24X Fiche 50-374,82/08/24,8210040366
- 9210260501 Advises of State of IL intent to file comments on concrete element design margin summary Comments will be incorporated into IOCFR2 206 show cause request GOODIC, J S Illinois, State of 82/10/15 DENTON, HR Office of Nuclear Reactor Regulation, Director 1p 15806 209 24X Fiche 50-374, G2/10/15, 8210260501
- G Inspection reports, IE Bulletins & correspondence
- 8210190601 [E Mgt Hesting Repts 50-373/82-44 & 50-374/82-12 on 820830 & 0913 No noncompliance noted Major areas discussed vaids found in wall at 710 5-ft elevation on Column Line 16 JACKIW, I N. LIPINSKI, R Division of Engineering & Technical Programs 82/09/20 16pp 15739 289 24X Fiche 50-373,82/09/29,8210190589
- 6208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000,82/10/06.8208190233
- 8210250105 Forwards IE Insp Repts 50-373/82-41 & 50-374/82-09 on 820802-31 & notice of violation STREETER, J F Division of Project & Resident Programs 82/10/07 REED.C Commonwealth Edison Co 2pp 15787 152 24X Fiche 50-373,82/10/07,8210250105
- --8210250109 Notice of violation from insp on 820802-31 STREETER, J. F. Division of Project & Resident Programs 82/10/07 1p 19787 154 24% Fiche 50-373,82/10/07.8210250105
- --8210250116 IE Insp Repts 50-373/82-41 & 50-374/82-09 on 820802-31 Noncompliance noted unsupervised trainer performed reactivity manipulations GULDEMUND.N 0 . WRIGHT.0 . MADISON.A Division of Project & Resident Programs 82/10/04 Pp 15787 155 24X Fiche 50-373.82/10/70.8210250105
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Mall, Large-Diameter: Stainless Steel: Recirculation Sys Piping at BMR Plants " Svc list encl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 13810 125 24% Fische 50-000.82/10/14/8208190238
- 8 Reportable occurrences, LERs & related correspondence
- 8210190&06 Revised Final Deficiency Rept 82-10 re RCIC underground piping Replacement piping work complete except for tie to Unit 1 RCIC sys inside bldg which requires 4-day outage Work will be completed during first available outage SCHROEDER, C H Commonwealth Edison Co 82/10/08 KEPPLER, J G Region 3, Office of Director 1p 15739 353 24X Fiche 50-373,82/10/08,8210190606

- DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

  A Application/construction stage documents & correspondence
- 8209220135 Forwards pump & valve inservice test plan for approval Requests relief from ASME Code Section XI per 10CFR50 55a MAURIN.L V Louisiana Power & Light Co 82/09/13 NOVAK.T H Assistant Director for Licensing 4pp 14938 001 24X Fiche 50-392.82/09/13,8209220135
- --8209220137 Response to provisions of 10CFR50 55a(g) inservice testing plan for Class 1,2 & 3 pumps & valves.Revision 0

  + Louisiana Power & Light Co 82/08/16 21ipp 14938 005 24X Fiche 50-382,82/09/13 8209220135
- 6210180255 Forwards description of open items found as result of review of 820625 submittal re-purge valve operability Schedule for response requested MERRIGAN, J.D. Licensing Branch 3 82/09/23 MAURIN, L.V. Louisianu Power & Light Co. 4pp. 15746-239 24X Fiche 50-382,82/09/23, 6210180255
- 8210040110 Requests test exception to delete stuck control rod physics test Test has potential for placing reactor in unsafe configuration

  MAURIN.L V Louisiana Power & Light Co B2/09/27 NOVAK, T N Assistant Director for Licensing 3pp 15580 347 24X
  Fiche 50-382, 82/09/27, 8210040110
- 8210040191 Summarizes 820903 site meeting re pending revision to FSAR, Chapter 14 MAURIN.L V Louisiana Power & Light Co 82/09/27 NOVAK, T M Assistant Director for Licensing 2pp 15583 187 24% Fiche 50-382, 82/09/27, 8210040191
- 8210260532 Notifies of acceptance of Revision A of Torrey Pines Technology GA program plan EISENHUT.D O Division of Licensing 82/09/28 MCLENDON, G D Louisiana Power & Light Co 2pp 15830 191 24X Fiche 50-382.88/09/28.8210260532
- 8210210317 Forwards portions of Franklin Research Ctr technical evaluation rept "Control of Heavy Loads" is ANSI 8td NI4 4-1978 to assist in preparing response on special lifting devices, per 820921 conference call commitment KERRIGAN.JD Licensing Branch 3 82/09/29 MAURIN.LV Louisiana Power & Light Co. 5pp. 15782-082 24X Fiche 50-382,82/09/29.
- 9210260285 Notification of 821003-05 meeting w/util in Taft,LA to audit facility training program
  BLACKS Licensing Branch 3 82/09/29 KERRICAN,J Licensing Branch 3 3pp 15830-153 24% Fiche 50-382,82/09/29,8210260285
- 8210150347 Forwards Revision B to "Independent Design Review of Waterford Steam Electric Station Unit 3 Emergency Feedwater Sys." Program plan MCLENDON O Louisiana Power & Light Co B2/10/04 NOVAK, T M Assistant Director for Licensing 2pp 15704 282 24X Fiche 50-382, 82/10/04, 8210150347
- --8210150353 Revision B to "Independent Design Review of Waterford Steam Electric Station Unit 3 Emergency Feedwater Sys," program plan \* Torrey Pines Technology 82/09/13 18pp 15704 284 24X Fache 50-382,82/10/04.8210150347
- 8210250355 Forwards response to 820513 Human Factors Engineering audit of facility control room Revised rept will be issued 821104
  Util purchasing full scope control room simulator to study recommended changes
  MAURINIAL V Louisiana Power & Light Co 82/10/20 NOVAKIT M
  Assistant Director for Licensing 7pp 15770 036 24X
  Fichs 50-382,82/10/20,8210250355
- F Security, medical, emergency & fire protection plans
- 8210040168 Forwards suggested dates & schedule for conducting emergency preparedness drills exercise for score & appraisal for facility HAURIN:L V Louisiand Power & Light Co 82/09/24 NOVAK: Y M Division of Licensing 2pp 15582 315 24X Fiche 30-382,82/09/24. 8210040168
- B210010370 Forwards summary of five qualification tests, ANI acceptance itrs & excepts from five qualification test repts Repts include "Fire Qualification Test on Silicone Foam Floor Parabration Seals"

  MAURIN.L V Louissana Power & Light Co B2/09/28 NOVAK, T M Assistant Director for Licensing 161pp 15569 001 24X

  Fichs 50-382, 82/09/28, 8210010370

- 8210260362 Forwards revised tert of Facility info safety brochure Revision improves readability & reflects comments received from NRC & FEMA Test will be incorporated into printer proof by 821122 per ASLB requirement Comments requested by 821103 MAURINIL V Louisiana Power & Light Co 82/10/22 NOVAK, T M Division of Licensing 20pp 15803 158 24% Fische 50-382,82/10/22,8210260742
- G Adjudicatory correspondence
- 8210010435 Certifies svc on 820924 of applicant response to comments of parties on emergency public info blockure Svc list encl RIDSNAY, D.A. Louisiana Fower & Light Co. 82/09/27 2pp 15570 203 24% Fiche 50-382.82/09/27, 8210010435
- 8210040059 Memorializes 820928 telcon between ASIB, NRC & Joint Intervenors deferring 820929 telcon to set hearing date until Joint Intervenors pleadings on emergency into brochure riled

  TURK, S.E. Hearing Branch 1 82/09/29 HOLFF, S.J., JORDAN, W.H., FOREMAN, H. Atomic Safety and Licensing Board Panel 2pp 15581 252 24% Fiche 50-362, 82/09/29, 8210040059
- B210050366 Motion to dismiss license application for failure to comply w/discovery Intervenors unable to prepare adequately for defense of interests against impact of facility on lives & livelihoods GROESCH.O.L. Joint Intervenors-Waterford B2/09/29 Atomic Safety and Licensing Board Panel 2pp 15609 013 24X Fiche 50-3B2/02/09/29/8210050366
- -8210050372 Request for production & copy of certain documents
  Documents should be delivered within 15 days in order to
  avoid prejudicing intervenors in subsequent proceedings
  GROESCH O. L. Joint Intervenors Naterford 82/07/29 Louisiana
  Power & Light Co. 2pp. 15609-015 24X Fiche 50-382.82/07/29,
  8210050366
- -8210050378 Hotion to disallow introduction of second evacuation brockers grant judgment on first brockers & allow new evidence & testimony to be presented on synergism & evacuation contentions Cortificate of Svc encl gROESCH, O. L. Joint Intervenors-Naterford B2/09/29 Atomic Safety and Licensing Board Panet Ripp 15/09 01/ 24x Fiche 50-382,82/09/27,8210050366
- 8210040061 Advises that NRC does not oppose Joint Intervenois loquert for cross-examination of NRC & FEMA employees no 800901 affidavits Cross-examination must relate to scope of direct testimony which may be introduced by IRC &/or FEMA TURK S E Hearing Branch 1 82/09/30 WOLFE, 5 / JOHDAN, W H . FOREMAN, H Atomic Safety and ticensing Board Panel 2pp 1998 250 24% Fiche 90-382.82/09/30.8210040061
- 8210060188 Response opposing Joint Intervenors 020729 mutton re uti) emergency info brochure & reopened hearings Ruling un adequacy of util emergency info brochure should be deferred Certificate of Soc encl
  TURK.S E Hearing Branch | 82/10/04 Atomic Gafety and Licensing Board Panel | 11pp | 19613-227 | 24X Fiche 50-362.62/10/0.0210060188
- 6210070124 Response opposing Joint Intervenors 820729 motion to reoper Requests not founded in fact or law & fly in face of any sense of administrative discipline & procedural regularity Some requests defy logic Certificate of Svc encl CRURCHILL, B. W. Louisiana Power & Light Co. CRURCHILL, B. W. Shaw, Pittman, Potts & Trombridge 82/10/04 Atomic Safety and Licensing Board Panel. 15pp. 15627-046-24X Fiche 50~382,62/10/04 8210070124
- B210070197 Memorializes B21001 telcon w/NRC, util, Joint Intervenors & ASLB NRC & applicant to file responses to Joint Intervenors motions by 821006 Svc list enc!
  RIDOMAY, D A Shau, Fittman, Potts & Troubridge RIDOMAY, D A Louisians Power & Light Co B2/10/04 WDLFE, B J Atomic Safety an Licensing Board Panel 5pp 15634 269 24% Fiche 50-382, 82/10/04, 8210070197
- 8210080070 Objections to Joint Intervenors 820927 request for production of documents 5 opposition to motion to dismiss application for failure to make discovery NRC regulations for discovery not followed W/Certificate of Svc TURK.8 E Hearing Branch 1 82/10/06 Joint Intervenors-Waterford 14pp 15643 016 24X Fiche 50-382,82/10/66 8210080720
- 8210080086 Erratum to applicant 821004 response to Joint Intervenors motion to reopen record Certificate of Svc enc!
  CHURCHILL, B W Louisiana Power & Light Co CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge 82/10/06 Atomic Safety and Licenting Beard Panel 3pp 15640 217 24X Fiche 50-382,82/10/06,8210080086

- 8210080070 Response apposing Joint Intervenors 820927 motion to dismiss for failure to make discovery to objections to request for production of documents Discovery requests prohibited by Commission rules Commission rules CHUPCHILLS W. Louisiana Power & Light Co. CHURCHILLS W. Shaw. Pattnan. Potts A. Trombridge 62/10/06. Atomic Safety and Licensing Board Panel 13pp. 15640-223 24X Fiche 50-382,82/10/06, W210080096
- 8210210372 Hemorializes 821013 conforence call w/Joint Intervenors te procedures for appealing ASLB actions Svc list and RIDQWAY.D A Shaw. Pittman. Polts & Troubridge RIDQWAY.D A Louisiana Power & Light Co 82/10/18 WOLFE.S J Atomic Safety and Licensing Board Panel 4pp 1576J 164 24X Fiche 50-382,82/10/18, 0210210372
- 6.10210404 Hemorandum & order denying Joint Intervenors 820929 motion to dismiss for failure to make discovery & granting portion of motion requesting production } copying of documents WGLFE/S J Atomic Safety and Licensing Board Panel 82/10/18 Joint Intervenors-Waterford 9pp 15765 135 24X Fiche 50-382 82/10/18.2210210404
- 8210210412 Menorandum \* order granting portion of util 820923 motion, allowing util initially proposed public info brochure to be withdrawn \* reopening record to receive evidence on adequacy of util revised brochure WOLFF.S J. Atomic Safety and Licensing Board Panel 82/10/18 Louisiana Power & Light Co. 11pp 15765-088 24x Fiche 50-382-82/10/18-8210210412
- B210210152 Forwards JU Benton S AL Lookabough affidavit re emergency into brockure Affidavit identical to 820901 affidavit but includes lookabagh signature TURK S E. Hearing Branch I. 82/10/19 WOLFE, S J., JORDAN, W H., FOREMAN, H. Atomic Safety and Litensing Board Panel. 3pp 15726-077 24X Fiche 50-382,82/10/19,82102(0)52
- -B210210159 Arfidavit of JW Denton t At Lookabaugh re emergency info brockure Util has revised brockure incorporating FCNA comments Guidance criteria on ed info on radiation met BFWTON J W . LOOKABAUGH A L NRC - No Detailed Affiliation Given BEWTOM J W . LOOKABAUGH A L NRC - No Detailed Affiliation Given BEWTOM J W . LOOKABAUGH A L NRC - No Detailed Affiliation Given BEWTOM J W . LOOKABAUGH A L NRC - No Detailed Affiliation Given BEWTOM J W . LOOKABAUGH A L NRC - No Detailed Affiliation Given BEWTOM J W . LOOKABAUGH A L NRC - No Detailed Affiliation Given 19746 080 24% Firhe 50-382 G2/10/19.8210210152
- 8210210466 Order admitting three exhibits into evidence to be cited in upcoming partial initial decision on Unresolved Safety Issues A 45 re abutdown PHR & A-46 re seismic qualitication of equipment WOLFELS J Atomic Safety and Licensing Board Panel 82/10/19 2pp 15/63 047 247 Fiche 50 382 82/10/19 8210210466
- 6210220477 Advises that time for Commission to act to review ALAB-690 expired Commission declined review Decision became final agency action on 821018 URLE-S J. Office of the Secretary of the Commission 82/10/21 Orfice of the Executive Legal Director 1p 15779 129 24X fiche 50-782.02/10/21.0210220473
- 6210250288 Informs of util pending application for SNM license Util requested license be effective as of 830131 until plant (IL 15500d No ASLB action necessary IVRK, S.E. Hearing Branch 1 82/10/22 FOREMAN, H., WOLFE, S.J., JORDAN, W.H. Atomic Safety and Licensing Board Panel 1p 15791 164 24x Firene 50-382, 82/10/22, 8210250288
- 8210260423 Advises that author 621018 ltr memorializing 621013 telcon should have included FEMA representative Cassidy as participant Svc list encl HIDGMAY.D A Shaw. Pittman, Potts & Trombridge RIDGMAY.D A Louisiana Power & Light Co 82/10/22 WOLFE,B J Atomic Bafety and Licensing Board Panel 2pp 15806 050 24% Fiche 50-382,82/10/22,6210260423
- 8210280387 Provides list of correspondence from applicant to NRC & FEMA since record closed on 820512 Some ltrs & svc list encl flelated correspondence CHURCHILL,8 H Shaw, Pittman. Potts & Trowbridge CHURCHILL,8 H (Louisiana Power & Light Co 82/10/25 GROEBCH, G Affiliation Unknown 8pp 15845 169 24X Fiche 50-382,82/10/25,82(0280387)

### H General correspondence

8210210167 Requests copying syds for endl documents Record reppened to admit into evidence BZOBZ7 ltr & appended affidavit.util 820910 response & 820909 attachment W/o endls WCLFE.8 J Atomic Safety and Licensing Board Panel 82/10/19 Alderson Reporting ip 15766 074 74X Fiche 50-382,82/10/19,8210210167

- K Utility Final Safety Analysis Report (FSAR) & amends
- 8210270190 Forwards Amend 29 to FSAR.addressing organization & training program
  MAURINLE V Louisiana Power & Light Co 82/10/20 Office of Nuclear Reactor Regulation. Director 3pp 15827 268 24X
  Fiche 50-382.822/10/20.8210270190
- --8210270193 Amend 29 to FSAR Twenty-five aperture cards available in PDR + Louisiana Power & Light Co 82/10/31 308pp 15827 274 24X Fiche 50-382,82/10/20.8210270190

### M Antitrust correspondence

- 8210270327 Forwards notice of finding of no significant antitrust changes & time for filing request for le-evaluation TOALSTON.A Antitrust & Economic analysis Branch (Utility Finance) 82/10/14 COMBS.T Docketing & Bervices Branch ip 15836 359 24X Fiche 50-382.82/10/14.8210270327
- --0210270332 Notice of issuance & availability of notice of finding of no significant antitrust changes & time for filing request for re-evaluation TOALSTON, A Antitrust & Economic analysis Branch (Utility Finance) 82/10/12 3pp 15836 360 24% Fiche 50-382/82/10/14. 8210270327
- O Inspection reports. IE Bulletins & correspondence
- 821012005B Forwards IE Insp Rept 50-382/82-12 on 820503-07 No noncompliance noted MADSEN,G L Division of Resident. Reactor Project & Engineering Programs 82/09/24 MAURIN,L V Louisiana Power & Light Co 2pp 15653 110 24X Fiche 50-382,82/09/24,8210120058
- --8210120073 IE Insp Rept 50-382/82-12 on 820503-07 No nancompliance noted Major areas inspected chemistry/radiachemistry program including organization, staffing, qualifications, training, facilities, equipment & lab instrument calibr NICHOLAS. J B. MURRAY. B Division of Resident. Reactor Project & Engineering Programs 82/09/01 46pp 15653 112 24X Fiche 50-382,82/09/24.8210120058
- 8210190431 Forwards IE Insp Rept 50-382/82-18 on 820816-20 & notice of violation MADSEN.O L Division of Resident, Reactor Project & Engineering Programs 82/09/30 MADRIN.L V Louisiana Power & Light Co 2pp 18741 154 24% Fichs 50-382,82/09/30,8210190431
- --8210190437 Notice of violation from insp on 820816-20 \* Division of Resident. Reactor Project & Engineering Programs 82/09/30 [p 1574] 156 24X Fiche 50-382,82/09/30,8210190431
- --8210190452 IE Insp Rept 50-382/82-18 on 820816-20 Noncompliance noted failure to follow procedures/instructions for control of weld insp/documentation of safety-related structural steel platforms

  JOHNSON, C E , ROBERDS, J , CROSSHAN, N A Division of Resident,
  Reactor Project & Engineering Programs 82/09/21 9pp

  15741 157 24X Fiche 50-382,82/09/30,8210190431
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dielodged I-125 Implant Seeds " Svc list encl CDBp.L I Division of Fuel Facilities, Materials & Safeguards 82/10/04 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BNR Plants " Svc list encl DEYOUNO, R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York (15pp 15810 125 24X Fichs 50-000, 82/10/14,8208190238
- S Reportable occurrences, LERs & related correspondence
- 8210040078 Interim Significant Const Deficiency Rept 62 re insp & acceptance of undersized field welds in 1/2-inch stainless steel sampling schedule 160 piping Initially reported on 820820 Mercury Co will build up welds by 821282 MAURINI, V Louisiana Power & Light Co 82/09/20 CDLLINS, J T Region 4, Office of Director 3pp 15581 267, 24% Fichs 50-182,82/09/20,8210040078.

- 8210130174 Interim deficiency rept re possible failure of GE Type MFA relays Initially reported on 820513 Corrective action not completed Final rept will not be submitted until 830430 MAURIN, L. V. Louisiana Power & Light Co. 82/09/30 COLLINS, J. T. Region 4. Office of Director ip 15673 045 24X Fiche 50-382, 62/09/30, 8210130174
- 6210130245 Second interim dericiency rept re Significant Const
  Deficiency 43 on main/emergency feedwater sys Corrective
  action not completed Final rept will be submitted by
  621222
  MAURIN.t V Louisiana Fower & Light Co 82/09/30 COLLING.J T
  Region 4, Office of Director 1p 15678 [0] 24X
  Fiche 50-382.82/09/30,8210130245
- 8210130564 Second interim deficiency rept on Significant Const Deficiency 48 re design application of break flanges at elevated temps Corrective action described in 820326 rept not completed Nert rept to be submitted by 830117 MAURIN, C. V. Louisiana Power & Light Co. 82/09/30 COLLINS, J. T. Region 4. Office of Director to 15663 300 24X Fiche 50-382,82/09/30,6210130564
- 8210130243 Second interim deficiency rept re reactor containment bldg liner plate nuclear coating failure Corrective action not yet completed final rept to be submitted by 830323 MAURIM.L V Louisiana Power & Light Co 82/10/01 COLLINS, J T Region 4. Office of Director 1p 15678 100 24X Fiche 50-382:82/10/01.8210130243
- 8210130551 Fourth interim Significant Const Deficiency Rept 33 rechilled water pipe supports Corrective action not yet complete Final rept expected by 83031 MAURIN, L V Louisiana Power & Light Co 82/10/01 CGLLINS, J T Region 4, Office of Director ip 15684 013 24x Fiche 50-382, 82/10/01, 8210130551
- 8210190542 Interim deficiency rept re Potential Reportable Deficiency 86 on disparity in UMS tornado case test results Initially reported on 820830 Equipment not significantly impacted at 104 F Deficiency not reportable per 10GFR50 55(e) MAURIN,L V Louisiana Power & Light Co 82/10/06 MADSEN.G L Division of Resident, Reactor Project & Engineering Programs 3pp 15751 330 24% Fiche 50-382,82/10/06.8210190542
- 8210190345 First interim deficiency rept re Significant Const Deficiency 63, "Procurement of Spare/Replacement Parts" Further info detailing investigation & evaluating questionable purchase orders will be provided by 830418 MAURIN.L V Louisiana Power & Light Co 82/10/08 COLLING, J T Region 4, Office of Director 3pp 13742 095 24X Fiche 50-382,82/10/08,8210190345
- 8210250217 Third interim deficiency rept re inadequate clearance between process piping sys & box type pipe supports & restraints Nineteen hansers remain to be reworked Final rept will be transmitted by 830708 HAURIN-L V Louisiana Power & Light Co 82/10/15 COLLINS, J T Region 4, Office of Director ip 15788 337 24X Fiche 50-282, 82/10/15, 8210250217
- 8210250242 Interim Significant Const Deficiency Rept 32 re failure to perform stress analysis for welded pipe support attachments prior to fabrication Initially reported on 810816 Eleven hangers need reworking Final rept will be sent by 830624 MAURIN.L V Louisians Power & Light Co 82/10/15 CULLINS, J T Region 4. Office of Director ip 15788 338 24x Fiche 50-382,82/10/15,8210250242

- DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1
- € 188C Safety Evaluation Report (SER), supple & correspondence
- 8210040052 Responds to SER, Suppl 3, Section 3 if 5(1) relaging & implementation of surveillance & maint program Procedures written & schedules will be completed by 821005 CURTIS.N W. Pennsylvania Power & Light Co. B2/09/24 SCHWENCER.A Licensing Branch 2. 3pp. 15581 308 24% Fiche 50 387,82/09/74,6210040052
- 921013034) Updates 920924 response to SER Suppl 3. Section 3.11.5(1) resurve() lance 5 maint program, per License Condition C(IB)(a) Schedules complete for components requiring surveillance/ replacement during first yr operation CURTIS,N W. Pennsylvania Power 5 Light Co. 82/10/06 SCHWEN(ER A Licensing Branch 2. Ip. 15679-137 24% Fiche 50-387, 82/10/06 82(013034)
- F Security, medical, emergency & fire protection plans
- \$210010417 Forwards description of actions to be taken to correct deficiencies in physical security plan.per \$20701-02 discussions Revised plan Forthcoming Encl withheld (ref 100FR73 21)
  CURTISM W Pennsylvania Power & Light Co \$2/09/16 SCHWENGER.A Licensing Branch 2 ip 15572 1/5 24X Fiche 50-307.62/09/16.
- 9210210234 Notification of 821005 meeting w/util in Allentown.PA to discuss station blackout test plan PERCH.R L. Licensing Branch 1 92/07/27 YOUNGBLOOD.B J Licensing Branch 1 3pp 15774 333 24X Fiche 50-387,82/09/2/,8210210234
- 8210190158 Releases public version of emergency plan implementing procedure FELTON.J M Division of Rules and Records 82/09/20 Document Management Branch 1p 15758 020 24% Fiche 50-387,82/09/28, 8210190158
- --8210190166 Forwards public version of Revision O to Emergency Plan Implementing Procedure EP-IP-048, "Estimation of Core Damage During Emergency "Receipt form enc! \* Pennsylvania Power & Light Co 82/09/17 NRC - No Detailed Affiliation Olven Ip 15758 02: 24% Fiche 50-387,82/09/28, 8210190158
- --8210190173 Public version of Revision O to Emergency Plan Implementing Procedure EP-IP-048. "Estimation of Core Damage During Emergency " Revision 6 to procedure manual table of contents encl
  \* Pennsylvania Power & Light Co 82/09/17 25pp (5758 023 24% Ficha 50-387, 82/09/28, 82(0)190158
- 8210060199 Advises that emergency operations facility & technical support ctrls operational Status of emergency response computer sys provided in 820916 ltr CURTIS,N W Pennsylvania Power & Light Co 82/10/01 SCHWENCER, A Licensing Branch 2 1p 15614 015 24% Fiche 50-387, 82/10/01, 82100A0199
- 8210130430 Responds to inquiry re supplemental interim findings on adequacy of offsite emergency preparedness for facility State & local emergency plans adequate Conditions should be imposed to assure completion of corrective actions KRIMM.R W Federal Emergency Management Agency 82/10/04 ORIMES.B K Division of Emergency Preparedness ip 15681 192 244 Fiche 50-387.82/10/04,8210130430
- 8210290201 Forwards IE Insp Rept 50-387/82-30 on 820712-15 No noncompliance noted MARTIN.TT Division of Engineering & Technical Programs 82/10/08 KENYON.B D Pennsylvania Power & Light Co 2pp 15854 015 24X Fiche.50-387,82/10/08.8210290201
- --8210290207 IE Insp Rept 50-387/82-30 on 820712-16 No noncompliance noted Major areas inspected security sys power supply access control, lighting assessment aids detection aids & communications Details withheld (ref 10CFR73 21) DUNLAPJM, 90DY,A T Region 1, Office of Director 82/10/04 ip 15854 017 24X Fiche 50-387,82/10/08,8210290201
- 8210250256 Forwards application for Amand IJ to License NPF-14 & proposed Yech Spec changes Amend deletes Fire Zone 1-6A in access area from Tech Specs CURTIS, N W Pennsylvanua Power & Light Co 82/10/19 SCHWENCER, A Licensing Branch 2 ip 15791 153 24X Fiche 50-387, 82/10/19, 8210220256

- --8210250264 Application for Amend 11 to License NPF-14, deleting File Zone 1-6A from Tech Spec 3 7 6 2 re sprinkler sys CURTIS.N W Pennsylvania Pawer & Light Co 82/10/19 1p 15791 154 24X Fiche 50 387.82/10/19.8210250256
- --8210250276 Proposed Tech Spec changes re spray & sprinkler systallowing for continuous fire watch u/backup fire suppression equipment
  - equipment

    \* Pennsylvania Power & Light Co #2/10/19 1p 15791 155 24X
    Fiche 50-387. 82/10/19. 8210250256
- 8210290230 Application for Amend 13 to License NPF-14, revising License Condition 2 D to reflect Changes J.K.L & M. revision to Chapter 11 & security training & qualification plan including Revision 1 & Change A Class II amend fee encl KENYON, D D Pennsylvania Power & Light Co 82/10/25 SCHWENCER, A Licensing Branch 2 2pp 15853 181 24% Fiche 50-387, 82/10/25, 8210290230
- 8210290318 Advices that mod to fire resistant wrap matl on cable trays in Fire Zone 1-2D remote shutdown panel completed per util 820831 commitment Mod satisfies License Condition C(7)
  - requirements
    CURTIS N W Pennsylvania Power & Light Co 62/10/25 SCHWENCE
    Licensing Branch 2 ip 15853 100 24X Fiche 50-387,82/10/25,
    8210290318 82/10/25 SCHUENCER, A

### } Adjudicatory correspondence

1210280258 Order directing util to inferm ASLB, by 821103, of how util will inclement change of leak rate menitoring sys per hearing testimony NRC to inform ASLB, by 821110, of related lech Specs % relationship to MNECO-0313. Revision 1 ICM/KINS.8 A Atomic Saroty and Licensing Appeal Panel 82/10/24 Pennsylvania Power & Light Co. 3pp 15837 024 24X Fiche 50-387, 82/10/24, 8210280298

### General correspondence

- 210220351 Advises that 821006 telegram opposing facility will be sent
- to all parties
  to all parties
  GILINSKY.V Commissioners 82/10/20 DALTON.C Affiliation
  Unknown ip 15779 127 24X Fiche 50-387.82/10/20,8210220351
- -8210220357 Opposes granting facility OL since no suitable evacuation
  - plan erists
    DALTON,C Affiliation Unknown 82/10/06 GILINSKY,V
    Commissioners 1p (5779 (28 24X Piche 50-387,82/10/20,

### Insurance & indemnity information

- '\$0220102 Forwards Endorsements 15.16 & 17 to NELIA Policy NF-262 CURTIS.N W Pennsylvania Power & Light Co 62/10/18 SCHWENGER Licensing Branch 2 5pp 15778 172 24X Fiche 50-387,82/10/18, 8210220102 SCHWENGER, A
- 10220175 Forwards Endorsements 1-4 to MAELU Policy MF-107 CURTIS.N W Pennsylvania Power & Clight Co 62/10/18 SCHWENCER.A Licensing Branch 2 lp 15778 001 24X Fiche 50-387.82/10/18, 5210/20175
- Operating license stage documents & correspondence
- l0210417 Forwards action plan for investigation of small pipe program concerns per 820730 meeting commitment KERYON.9 D Pennsylvania Power & Light Co 82/08/04 MARTIN.T T Jivision of Engineering & Technical Programs 12pp 15769 074 24x Tiche 50-387.82/08/04.8210210417
- 1006039! Forwards rept of outlined actions & conclusions resulting from util investigation & Commission concerns re-small pipe programmer 820811, 18, 25 & 27 meetings (ERYDN, B D Pennsylvania Power & Light Co 82/09/10 MARTIN, T T livision of Engineering & Technical Programs 120pp 15415-195-14X Fiche 50-387, 82/09/10, 821006039!
- 0180274 Summary of 820909 meeting w/util.Teledyne Engineering Sycs TEB),Bechtel & Nutech re conclusion of TES final rept ssued on review of feedwater sys inside containment List
- Attandees encl
  RSH.R L Licensing Branch i 82/09/24 Licensin
  5 15746 336 24X Fiche 50-387.82/09/24.8210180274 ERSH, R L Licensing Branch 1
- 0190153 Summary of 820909 meeting w/util & Stannard & Co re onfiguration of gas pipeline near plant site ERCH.R L Licensing Branch 1 82/09/24 Licensing Branch 1 pp 15761 246 248 Ficho 50-387/82/09/24.8210190153

- 8210210303 Notification of 820929 senior mgt meeting w/util in BethesdarMD to discuss plant status PERCH.R L. Licensing Branch 2 82/09/27 YOUNDBLOOD,B J Licensing Branch 1 3pp 15774 357 24X Fiche 50~387.82/09/27,
- 8210050325 Discusses effects of change in diesel generator start time from 10-s to 25-s on LOCA analysis in FSAR Chapter 6.3 Large recirculation discharge break peak clad temp not affected by delayed start time CURTIS.N W. Pennsylvanta Power & Light Co. 82/09/29 SCHWENCER.A Licensing Branch 2 3pp 15608 212 24X Fiche 50-387.82/09/29.8210050320
- 8210050370 Provides interim justification for operability of feedwater sys check valves Calculations & ASME/ANSI stds provide adequate assurance that guillotine break of feedwater piping would not occur as result of operational transient CURTIS.N W Pennsylvania Power & Light Co 82/09/29 SCHWENCER.A Licensing Branch 2 2pp 15609 046 24X Fiche 50-387.82/09/29, 8210050370
- 8210210244 Requests written response addressing specific & general 210210244 Requests written response addressing specific & gissues noted in Teledyne final rept on independent design review of plant feedwater sys inside containment NDVAK.TM Assistant Director for Licensing 82/09/30 Pennsylvania Power & Light Co 2pp 15774 331 24X Fiche 50-387, 82/09/30,8210210244 82/09/30 CURTIS N W
- 8210210288 Advises that util revised process control program containing methodology & parameters for solidification of radwasts acceptable Program meets Tech Spec 6 (3) in requirement YOUNOBLOOD, B. J. Licensing Branch 1 82/09/30 CURTIS.N W Pennsylvanta Power & Light Co. 2pp. 15774 345 24X Fiche 50-387, 82/09/30,8210210288
- 8210130122 Advises that final rept on automatic depressurization sus enuivable Advises that Final rept on automatic depressurization sy scheduled for completion in Oct Option 4 of BWR owners group will be implemented Detailed design info will not be generated until NRC approval is received CURTIS, N W Pennsylvania Power & Light Co 82/10/01 BCHWENCER Licensing Branch 2 3pp 15473 001 24% Fiche 50-387,82/10/01,0210130122 BCHWENCER, A
- 8210240241 Forwards rept of systematic assessment of licenses Performance & related correspondence HAYNES,R C Region 1, Office of Director 82/10/01 KAUFMAN, J T Pennsylvania Power Co 3pp 15803 056 24% Fiche 50-387,82/10/01. 8210260241
- --0210260247 Systematic assessment of licensee performance for Mar 1981-Feb 1982 Overall performance acceptable \* Region 1, Office of Director 82/06/01 31pp 15803 059 24x Fiche 50-387, 82/10/01.8210260241
- --8210260257 Advises of completion of systematic assessment of licenses performance & notifies of 820617 site meeting to discuss assasment STAROSTECKI,R Division of Project & Resident Programs KAUFMAN,J T Pannsylvania Power & Light Co 2pp 158 24X Fiche 50-387,82/10/01,0210260241 15803 090
- --B210260270 Responds to 820604 systematic assessment of licensee performance Items discussed include licenseed operators, health physics & chemistry staffs, operating procedures, punch list status & open items
  CURTIS,N W Pennsylvania Power & Light Co B2/07/02
  STAROSTECKI,R Division of Project & Resident Programs 9pp 15803 092 24X Fiche 50-387, 82/10/01,8210260241
- 8210080083 Forwards responses to Phase 2 finding & observations in final rept of Teledyne independent design review Program results re as-built reconciliation process will be available CURTIS N W Pennsylvanis Power & Light Co 82/10/04 SCHWENCER. A Licensing Branch 2 Bpp 15640 211 24X Fiche 50-387,82/10/04, 82/10680683
- 8210270115 Forwards Amond 3 to License NPF-14, safety evaluation & notice of issuance & availability Amend changes Tech Specs re essential svc water pump timer settings & dissel surveillance equipment
  YOUNOBLOOD. B. J. Licensing Branch 1 82/10/04 CURTIS, N W Pennsylvania Power & Light Co. 2pp 15866 345 24X
  Fiche 50-387, 82/10/04, 8210270115
- --8210270128 Amend 3 to License NPF-14, changing Tech Specs re essential syc water pump timer settings & diesel surveillance requirement YOUNGBLOOD B J Licensing Branch 1 B2/10/04 7pp 15864 347 24X Fiche 50-387,82/10/04.8210290118

- --B210290130 Safety evaluation supporting Amend 3 to License NPF-14

   Office of Nuclear Reactor Regulation, Director 82/10/04 2p

  15956 354 24X Fiche 50-387.82/10/04.8210290115
- --8210290136 Notice of issuance & availability of Amend 3 to Licensi NPF-14 KANE.W F Licensing Branch ! 82/10/04 2pp [5866-356 24X Fiche 50-387,82/10/04,8210290115
- 8210250010 Staff requirements memo summarizing 820730 discussion to possible vote on full power OL Decision deferred pending investigation review. Generally of the Commission 82/10/05 Uffice of the Secretary of the Commission 82/10/05 Uffice of the Secretary of the Commission 1p 15808 180 24X Fiche 50-387.82/10/05.8210250010
- 8210080142 Forwards application for Amend 9 to License NPF-14 adding into to minimite equipment damage due to high drywell temp KENYON. B D Pennsylvania Power & Light Co 82/10/06 SCHHENLER. A Licensing Branch 2 2pp 15640 131 24X Fiche 50-3B7. 82/10/06. 9210080142
- --B210080146 Application for Amend 9 to License NPF-14, adding info to minimize equipment damage due to high drywell temp KENYON, B D Pennsylvania Power & Light Co B2/10/06 tp 15640 153 24X Fiche 50-387, 62/10/06/8210080142
- --8210080151 Marked-up proposed Tech Specs re minimizing equipment damage due to high drywell temp 4 Pennsylvania Power & Light Co 82/10/06 5pp 15640 134 24% Fiche 50-387,82/10/06.8210080142
- 5210190297 Forwards plan for expanded reconciliation sampling program to show adequacy of engineering judgments made in large pipe design process Final rept will be available 821112 Raquests NRC allow operation up to 35% power CURTIS:N W Pennsylvania Power & Light Co 82/10/14 BCHMENCER, A Licensing Branch 2 App 15742 168 24% Fiche 50-387,82/10/14,8210190297
- 8210250256 Forwards application for Amend 11 to License NPF-14 & proposed Tech Spec changes Amend deletes Fire Zone 1-6A in access area from Tech Specs CURTIS,N W Pennsylvania Power & Light Co 82/10/19 SCHWENCER, A Licensing Branch 2 1p 15791 153 24X Fiche 50-387, 82/10/19, 9210250256
- --8210250264 Application for Amend II to License NPF-14, deleting tive Zone 1-6A from Tech Spec 3 7 6 2 re sprinkler sys CURTIS, N W Pennsylvania Power & Light Co 82/10/19 ip 13791 154 24X Fiche 50-387, 82/10/19, 8210250256
- ~-9210250276 Proposed Tech Spec changes re spray & sprinkler sys.allowing for continuous fire watch w/backup fire suppression equipment

  \* Pennsylvania Power & Light Co 82/10/19 lp 15791 155 24X
  Fiche 80-387.82/10/19.8210250256
- 8210250367 Forwards application for Amend 10 to License NPF-14, changing Tech Spec Table 3 8 4 1-1 to include more conservative Type 2 molded case circuit breakers & to add previously omitted Type 3 molded case circuit breakers CURTIGN W Pennsylvania Power & Light Co 82/10/19 SCHWENCER, A Licensing Branch 2 2pp 15790 179 24X Fishe 50-387, 82/10/19, 8210250367

- 8210260366 Forwards application for Amend 12 to Lictuse NPF-14, changing Tech Specs 4 if 2.7 i.4 ii 2.7 g.b Page 3/4 8-18 re radioactive effluents, main condenser b electrical power sys CURTIS.N W. Pennsylvania Power b Light Co. 82/10/22 SCHWENTR.A Licensing Branch 2 ip 15804 239 24X fiche 50-387,82/10/22,8210260366
- --B210260379 Application for Amend L to License NPF 14, changing (ech Specs 4 1) 2.7 f.4 11 2.7 2.7 Page 3/4 8-18 re ladicactive effluents, main condense; felectrical power systems of the control of th
- --8210260385 Proposed changes to Tech Speck 4 11 2 7 1.4 11 2 7 2 2 Page 3/4 B-18 re radioactive effluents, main condusser % electrical power sys \* Pennsylvania Power \* Light Co #2/10/22 3pp 15804 241 212 Fiche 50-387, 82/10/22 8210260366
- 8210290230 Application for Amend 13 to License NPF-14, revising licence Condition 2 D to reflect Changes J K L & M. revision to Chapter 11 & security training & qualification plan including Revision 1 & Crange A Class II amend fee encl KENVON. 3 D Pennsylvania Power 2 Light Co B2/10/25 SCHMINCE. A Licensing Branch 2 2pp 15050 180 14X Fichu 50-307.82/10/7.
- Q Inspection reports: IE Bulletins & correspondence
- B210260241 Forwards rept of systematic assessment of licensee performance & related correspondence HAVNES, C. Region to Office of Director 192/10/01 MAUFMAN, ) I Pennsylvania Power Co. 3pp. 15803 096. 24X fiche 50 187.62/10/01 M21026024
- --g210260247 Systematic assessment of licensee performance for Mail 1981-Feb 1982 Overall performance acceptable Pregion 1, Office of Director 82/04/01 31pp 15803 059 211 Fiche 50-387, 82/10/01.8210260241
- --8210260257 Advises of completion of systematic discussment of license, performance & notifies of 820617 site meeting to discuss assessment
  STAROSTECKI,R Division of Project & Resident Programs 62/06/04
  KAUFMAN,U T Pennsylvania Power 1 light to 2pp 15801 090
  24X Fiche 50-087, 62/10/01.8210260241
- --8210260270 Responds to 820604 systematic assessment of liconsequerformance Items discussed include licensed operators, health physics & chemistry staffs, operating procedures, punch list status & open itoms
  CURTIS.N W Pennsylvania Power & Light to 82/07/02
  STAROSTECKI.R Division of Project & Hosident Programs 9pp
  15803 092 24X Fichs 50-387, 82/10/01, (2)10260241
- 8208170233 IE Info Notice 80 35, Suppl 1, "Leaking & Disladged I-l2" Implant Seeds " Svc list encl COBD.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York & &pp 15761 2"8 24K Fiche 50-000,82/10/06,8208170233
- B210290201 Forwards IE (nsp Rept 50-387/B2-J0 on 820712-19 No noncompliance noted MARTIN, T T Division of Engineering & Technical Programs 82/10/08 KENYON, B D Pennsylvania Power & Light Co 2µp 15854 015 //4x Fiche 50-387, 82/10/08, 82/10290201
- --B210290207 IE Insp Rept 50-387/82-30 on 820712-14 No moncompliance noted Major areas inspected security sys power supply access control.lighting assessment aids detection aids & communications Details withheld (ref 1007R73 R1) DUNLAP.J M. GODY.A F. Region I. Office of Director 82/10/86 p 15854 017 24% Fiche 50-387,82/10/06,82102990201
- 820B190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BMR Plants " Bvc list enc! DEYQUNG, R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 80-000, 82/10/14,8208190238
- S Reportable occurrences, LERs & related correspondence
- B210010177 Forwards LER 82-014/03L-0 KEIBER: HW Pennsylvania Power & Light Co B2/09/22 HAYNES: R C Region 1. Office of Director 1p 15567 285 24X Fiche 50-387: B2/09/22: 8210010177

- --82:0010180 LER 82-014/03L-0 on 820824, prior to initial criticality, unit taken from Operational Condition 5 to 4 w/o shutdown cooling mode of RHR in operation, as required by Tech Spec Initial startup procedure systematic procedure startup procedure with the startup procedure Light Co 82/09/21 Region I. Office of Director 1p 15567 286 24X Fiche 50-387,82/09/22, 821010127
- 8210010228 LER 82-016/01P on 820918, turbine bidg vent monitor systemble gas nonitor declared out of svc Grab sampling once per 8-h initiated Mechanical vacuum pump in svc until 820920 contrary to Tech Specs Cause not stated PEISER. H W Pennsylvania Power & Light Co 82/09/22 HAYNES. R C Region 1, Office of Director ip 15568 261 24x Fiche 50-387, 82/09/22,8210010228
- 82:0010393 Forwards LER 92-015/03L-0 VEISER:H W Pennsylvania Power & Light Co 82/09/22 HAYNES:R C Region t. Office of Director 1 15572 264 24X Fiche 50-387, 82/09/22:8210010393
- --8210010402 LER 82-015/03L-0 on 820824, from start of initial fuel load until 820825, spray pond level & temp not monitored Caused by omtasion of Tech Spec 4 7 1 3 requirements from procedures Procedure rewritten

  KUCZYNSKI.L A Pennsylvania Power & Light Co 82/09/22 Region
  1. Office of Director 1p 15572 265 24X Fiche 50-387, 82/09/22, 8210010393
- B210040086 Forwards LER 92-017/03L-0
  KEISER.H W Pennsylvania Power & Light Co 82/09/24 HAYNES,R (
  Region 1, Office of Director 1p 15981 015 24X
  Fiche 50-387,82/09/24,8210040086
- --8210040083 LER 82-017/03L-0 on 820826, sprinkler sys for fire zone 1-5A was out of syc Detector reset initiated on fire protection panel in control room, but required reset of priorities (RSP) not performed RSP initiated KUCZYNSKI.L A Pennsylvania Power & Light Co 82/09/24 Region 1. Office of Director 1p 15581 016 24X Fiche 50-387,82/09/24,8210040086
- 5210040118 Forwards LER 62-012/01T-0 KEISER, H W Pennsylvania Power & Light Co 82/09/24 HAYNES, R & Region 1. Office of Director 1p 19581 193 24X Fiche 50-387, 82/09/24, 8210040118
- --8210040122 LER 82-012/01T-0 on 820910.potential existed for overload of Class IE electrical sys due to concurrent loading of emergency syc water pumps & either RHR or core sprey pumps during interimediate LOCA Caused by inadequate evaluation CISEMHULF T Pennsylvania Power & Light Co 82/09/24 Region 1. Office of Director 2pp 15581 194 24X Fiche 50-387, 82/09/24, 8210040118
- 8210130352 Forwards LER 82-080/03L-0 KEISER:H W Pennsylvania Power & Light Co 82/10/01 HAYNES:R C Region L Office of Director | p 15679 125 24X Fiche 50-387:82/10/01.8210130352
- --8210130361 LER 82-020/03L-0 on 820903, after both RHR sys trains removed from syc.pressure & temp were not recorded Caused by operator misjudgment Operators instructed to log & follow all action statements
  HITCHELL,D & Pennsylvania Power & Light Co 82/10/01 Region
  1. Office of Director 1p 15679 126 24X Fiche 50-387,82/10/01.
  8210130352
- --8210130371 LER 82-018/03L-0 on 820702. w/mode switch in refuel, three out of four source range monitors were inoperable Caused by inadvertent stressing of cables during undervessel work Procedure revised to reduce cable wear HITCHELL.D 0 Pennsylvania Power & Light Co 82/10/01 Region 1. Office of Director ip 15682 114 24X Fiche 50-387,82/10/01,8210130363
- 8210130377 Forwards LER 82-019/017-0 KEISER, H W Pennsylvania Power & Light Co 82/10/01 HAYNES, R C Region 1. Office of Director 19 15681 006 24X Fiche 50-387, 82/10/01,8210130377
- --8210130389 LER 82-019/01T-0 on 820920, during power ascension testing, furbine bldg vent monitor sys became inoperable Caused by failure to remove mechanical vacuum pump from svc Pump stopped & steam jet sir ejectors placed in svc HITCHELL.D G Pennsylvania Power & Light Co 82/10/01 Region 1. Office of Director ip 15681 007 24X Fiche.50-387.82/10/01, 8210130377

- 8210130405 PND-I-82-064 on 821006, anchor for 6-inch RHR sys line found to have weld one-third specified length Failure of support would overstress containment penetration Authorization to axceed 5% power postponed MCCABE.E C , KEIMIO Region 1, Office of Director 82/10/07 ip 15680 260 24% Fichs 50-387.82/10/07.8210130405
- 8210210440 Forwards LER 82-021/03L-0 KEISER.H W Pennsylvania Power & Light Co 82/10/08 HAYNES,R C Region 1, Office of Director ip 15763 045 24X Fiche 50-387,82/10/08,8210210440
- --8210210446 LER 82-021/03L on 820910, while performing surveillance of rod worth minimizer, selection error indicating light did not operate properly Gaused by one 28-volt conductor being pulled loose from light assembly due to stress MITCHELL, D O Pennsylvania Power & Light Co 82/10/08 Region 1. Office of Director ip 15763 046 24% Fiche 50-387,82/10/08,8210210440
- B210210285 Forwards LER 82-019/03L-0 KEISER: H W Pennsylvania Fower & Light Co 82/10/11 HAVNES: R C Region 1. Office of Director 1p 15765 086 24X Fiche 50-387, 82/10/11, 8210210285
- --8210210293 LER 82-019/03L-0 on 820912 during startup testing.

  Operational Condition 2 entered prior to completion of required daily survaillances Caused by incorrect identification of condition Event will be reviewed MITCHELL, D.C. Pennsylvania Power & Light Co. 82/10/11 Region 1. Office of Director 1p. 15765-087 24X Fiche 50-387, 82/10/11, 8210210285
- 8210210433 Forwards reissued LER 82-016/017-1 KEISER:H W Pennsylvania Power & Light Co 82/10/11 HAYNES:R C Region 1. Office of Director 1p 15763 015 24X Fiche 50-387,82/10/11,8210210433
- ---8210210436 Reissued LER 82-016/017-1 on 820920, mechanical vacuum pump left in svc after vantilation monitoring sys noble gas monitor became inoperable on 820918 Caused by operator not noting all parts of applicable action statements MITCHELL, D O Pennsylvania Power & Light Co 82/10/11 Region 1. Office of Director 2pp 15763 016 24% Fiche 50-387, 82/10/11.8210210433
- 82(0210020 Final deficiency rept re improper field mounting of Agastat 7000/E7000 relays Initially reported an 820702 Carner mounted screws & relays will be reworked by 821026 Also reported per Part 21 CURTIS,N W Pennsylvania Power & Light Co 82/10/12 HAYNES,R C. Region 1. Office of Director 4pp 15766 017 24X Fiche 90~307,82/10/12.8210210020
- 6210210137 Final deficiency rept re pump motor start times for emergency svc water, core spray & RHR sys Initially reported on 820710 Low pressure vessel interlock deleted from RHR & core spray pump start Also reported per Part 21 CURTIS,N W Pennsylvania Power & Light Co 62/10/12 HAYNES,R C Region J. Office of Director. 4pp 15766 103 24X Fiche 50-387,82/10/12,8210210137
- 8210250347 LER 82-026/01P-0 confirms 821013 telcon re faílure to complete graunding of reactor protection sys cabling prior to fuel loading as required by License NPF-14 KEISER, H W Pennsylvania Power & Light Co 82/10/14 HAYNES, R C Region 1. Office of Director 1p 15790 047 24X Fiche 50-387, 82/10/14, 8210250347
- 8210250357 LER 82-028/01P-0 confirms 821013 telcon re inability to comply w/action statement Chlorine detectors inoperable Action statement requires one control room emergency putside air supply sys in recirculation mode KEISER.H W Pennsylvania Power & Light Co 82/10/14 HAYNES,R.C Region 1. Office of Director. 1p 15791 015 24X Fiche 50-387.82/10/14.8210250357.
- 8210250369 Forwards LER 82-022/03L-0
  KEISER, H W. Pennsylvania Power & Light Co 82/10/14 HAYNES, R. C
  Region 1. Office of Director 1p 15790 137 24X
  Fiche 50-387, 82/10/14, 8210250369
- --B210250377 LER B2-022/03L-0 on B20916, while cleaning control rod drive (CRD) suction strainers CRD pumps tripped Caused by low suction pressure due to pressure fluctuations from cycling condensate reject valve Suction trip logic modified MITCHELL.D 0 Pennsylvania Power & Light Co 82/10/14 Region 1. Dffice of Director lp 15790 138 24X Fiche 50-387, 82/10/14, 8210250369

- 8210250381 Forwards LER 82-023/03L-0 VEISER:N W Pennsylvania Power & Light Co 82/10/14 HAYNES:R C Region I. Ofrice of Director Ep 15790 134 24X Fiche 50-387, 82/10/14,82(0250381
- --B210250385 LER 82 023/03L-O on B20915 during startup testing of steam relief valve acoustic monitoring systhmee monitors failed to operate correctly Event was instial calibr of monitors using steam Monitors adjusted tested & placed in svc MITCHELL.D 0 Pennsylvania Power & Light Co B2/10/14 Region 1. Orfice or Director ip 15790 135 24X Fiche 50-387.82/10/14.6210250381
- 8210260537 LER 82-024/01P-0 on 821015, potential for unanalyzed accident resulting from single failure of spray pond bypass valve reported Redundancy provided by automatic transfer to 8 loop on failure of A loop pumps to start MEISER.H W Pennsylvania Pouer A Light Co 82/10/18 HAYNES.R (Region 1, Office of Director 1p 15805 136 24X Fiche 50-387,82/10/18.8210260507
- B210E80215 Forwards LER 82-027/03L-0 VEISER-H W Pennsylvania Power \* Light Co 82/10/19 HAYNES-R ( Region 1. Office of Director 1p 15837 004 24Y Fiche 50-387,82/10/19 8210280215
- ~-6210280219 LER 82-027/03L-0 on 820920 two drywell/suppression chamber vacuum breakers gave false position indications during stroking Caused by loose couplings connecting limit switch to vacuum relief valve shaft Set screw replaced MITCHELL.D G Pennsylvania Power & Light Co 62/10/17 Region 1. Orfice of Director 19 15837 005 24X Fiche 50-387, 82/10/17, 8210280215
- T Hearing transcripts on non-antitrust matters
- 8210130113 Unoffical transcript of 820930 public meeting in Washington, DC re briefing on full power GL amend Pp 1-97 Supporting documentation encl 

  \* Commissioners 82/09/30 158pp 15696 083 24X Fiche 80-387, 82/09/30, 8210130113
- ( Onsite Storage of Lou Level Waste
- G210270411 Notafication of contract execution, Mod 3 to "Environ Assessment of Low Level Waste Storage at PA Power & Light Co. Susquehanna Steam Electric Station "Contractor Science Applications. Inc FLEENORS of Administrative Contracts Branch NRC-02-81-064 B2/09/30 DAVIS.J , LOYSEN.P Office of Nuclear Material Safety & Safeguards, Director 1p 15833 277 24X Fiche 50-387,82/09/30, 8210270411
- --8210270413 Mod 3.extending period of performance to 830131.revising billing instruction info & substituting Namual Chapter 3202. to "Environ Assessment of Lou Level Waste Storage at PA Power & Light Co.Susquehanna Steam Electric Station "ARCHER.C D Science Applications, Inc. HAGAN, T.F. Technical Assistance Contracts Branch NRC-02-81-044 82/09/30 2pg 15833 278 24X Fiche 50-387, 82/09/30.8210270411
- DOCKET 50-388 SUGGUEHANNA STEAM ELECTRIC STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 8210210417 Forwards action plan for investigation of small pipe program concerns per 820730 meeting commitment
  KENYON,8 D Pennsylvania Fower & Light Co 82/08/04 MARTIN.T T
  Division of Engineering & Technical Programs 12pp 15765 074 24x
  Fiche 50-387, 82/08/04, 8210210417
- 8210060391 Forwards rept of outlined actions & conclusions resulting from util investigation & Commission concerns re small pipe programper 82081; 18,25 & 27 meetings

  KENYON, B D Pennsulvania Power & Light Co 82/09/10 MARTIN, T T Division of Engineering & Technical Programs 120pp 15615 195 24% Fiche 50-387, 82/09/10, 8210060391
- 8210260241 Forwards rept of systematic assessment of licenses performance & related correspondence HAYNES.R C Region i. Office of Director 82/10/01 KAUFMAN, J T Pennsylvania Power Co 3pp 15803 056 24X Fiche 50-387.82/10/01, 82/10260241
- --8210260247 Systematic assessment of licensee performance for Mar 1981-Feb 1982 Overall performance acceptable. \* Region 1, Office of Director 82/06/01 Sipp 15803 059 24X Fiche 50-387,82/10/01.8210260241

- --8210260257 Advises of completion of systematic assessment of linense, performance A notifies of 820617 site mueting to discuss assessment
  STAROSTECKI,R Division of Project \* Resident Programs 86/06/04
  KAUFHMALU T Pennsylvania Puwer & Light Co 2pp 15803 (99)
  24X Fiche 50-367, 82/10/01 8210260241
- -8210260270 Responds to 820604 systematic assessment of licensee performance [tems discussed include licensed operators, health physics "chemistry staffs operating procedures punch list status & open items
  CURTIS.N W Pennsylvania Power / Light (a 82/0//02 STARDSTECKE R Division of Project & Resident Programs 9pp 15803 092 24% Fichs 50 387.82/10/01.8210260241
- F. Security, medical emergency & fire protection plans
- 2210010417 Forwards description of actions to be taken to correct dericine cees in physical security plan per 820701 62 discussions Revised plan forthcoming Each withheld cref 100F873 21)
  CURTISH W Pennsylvania Power 5 Light Co. 82709716 SCHMINGI Licensing Branch 2 lp. 15572 175 24K Fiche 50 JB7 82709716
  2210010417
- GZ10190158 Releases public version of emergency plan implementing procedure FELTON.J M. Division of Rules and Records. U2/09/28 Document Management Branch 1p. 15758-020, 24x Fiche 50, 307, 82/09/28, 82/09/0158
  - 8210190166 Forwards public version of Revision 0 to Emergency Plai Implementing Procedure CP-IP-048. "Estimation of Core Danage During Emergency "Receipt form enc." \* Pennsylvania Power 'Light Co 62/09/1/ NRC No Detaile Affiliation Given to 15758 021 74x Fiche 50-387,82/097/8, 8210190158
- 9210190173 Public version of Revision O to Emergency Plan Implementari Procedure EP-IP-048, "Estimation of Core Damage During Emergency "Revision o to procedure manual table of contents encl 4 Pennsylvania Power & Light Co 82/09/17 25pp 19/58 0.1 24X Fiche 50-387.82/09/28.0210190158
- 8210130430 Responds to inquiry re supplemental interim findings on adequacy of offsite emergency preparedness for facility State & local emergency plans adequate Conditions should be imposed to assure completion of corrective actions. RRIMM: R W Federal Emergency Management Agency GP/10/04 GRIMES B K Division of Emergency Preparedness 1p 15681 172 24X Fiche 50-387,82/10/04,8210130430
- G Adjudicatory correspondence
- 8210280278 Order directing util to inform ASLB, by 821103, of how util will implement change of leak rate monitoring sys per hearing testimony NRC to inform ASLB, by 821110, of related Tech Specs & relationship to NURFG-0313, Revision 1 TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 82/10/26 Peinsylvania Power & Light Co 3pp 15837 024 24X Fiche 50-387, 82/10/26, 8210280258
- H General correspondence
- 8210220351 Advises that 821006 telegram opposing facility will be sent to all parties GILINSKY.V Commissioners 82/10/20 DALTON.C Affiliation Unknown ip 15779 127 24X fiche 50-387,82/10/20,8210220351
- --8210220357 Opposes granting facility OL since no suitable evacuation plan exists DALTON.C Affiliation Unknown 82/10/06 GILINEKY.V Commissioners ip 15779 128 24X Fiche 50-387,82/10/20, 8210220351
- Q Inspection reports, IE Bulletins & correspondence
- 8310260241 Forwards rept of systematic assessment of licensee performance & related correspondence HAYNES,R C Region I. Office of Director 82/10/01 KAUFNAN.J T Pennsylvania Power Co 3pp 19803 056 24X Fiche 50-387,82/10/01, 8210260241
- ---8210260247 Bystematic assessment of licensee performance for Mar 1981-Feb 1982 Overall performance acceptable 4 Region 1. Office of Director 82/06/01 31pp 15803 059 240 Ficha 50-387,82/10/01.8210260241

- --8210260257 Advises of completion of systematic assessment of licensee performance & notifies of 820617 site meeting to discuss . . coesmant
  - assessment STARQSTECKI,R Division of Project & Resident Programs KAUFHAN,J T Pennsylvania Power & Light Co 2pp 158 24% Fish 50-287,82/10/01,8210260241 15803 090
- --8210260270 Responds to 820604 systematic assessment of licensee performance Items discussed include licensed operators, health physics & chemistry staffs, operating procedures, punch list status & open items CURTIS.N.W. Pennsylvania Power & Light Co 82/07/02 STAROBTECKI.R Division of Project & Resident Programs 9pp 15803 092 24% Fiche 50-387, 82/10/01,82/026024!
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Disladged 1-125 Implant Seeds " Syc list encl COBBL I Division of Fuel Facilities, Materials & Safegua 82/10/06 Consolidated Edison Co of New Yark & Cop 1 82/10/06 Consolidated Edison Co of New York 66pp 24% Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEVOUNO.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000,82/10/14.8208190238
- S Reportable occurrences. LERs & related correspondence
- 8210010268 Interim deficiency rept re inadequate clearance in Pacific Scientific shock suppressors & ITT Grinnell pipe clamps
  Initially reported on 820820 Final rept will be submitted by 830201 Also reported per Part 2!
  CURTIS.N W. Pennsylvania Power & Light Co. 82/09/23 HAYNES, R. C. Region 1, Office of Director App. 15573 110 24X
  Fiche 50-388, 82/09/23, 8210010268
- 3210210020 Final deficiency rept re improper field mounting of Agastat 7000/87000 relays initially reported on B20702 Corner mounted screws & relays will be reworked by 821026 Also mounted streams a relays will be received by Galozo Hi reported per Part 21 CURTIS N W Pennsylvania Power & Light Co 82/10/12 Region 1, Office of Director App 15766 017 24X Fiche 50-287,02/10/12,8210210020 82/10/12 HAYNES, R C
- 210210137 final deficiency lept re pump motor start times for emergency svc water.core spray & RHR sys Initially reported on 820910 Low pressure vessel interlock deleted from RHR & core spray pump start Also reported per Part 21 CURTISIN W Pennsylvania Power & Light Co 82/10/12 HAYNI Region 1, Office of Director 4pp 15764 103 24X Fiche 50-387,82/10/12.8210210137 82/10/12 HAYNES R C

# Onsite Storage of Low Level Waste

- 210270411 Notification of contract execution, Mod 3 to "Environ Assessment of Low Level Waste Storage at PA Power & Light Co. Susquehanna Steam Electric Station " Contractor Science Applications, Inc FLEEHORK C M Administrative Contracts Branch NRC-02-81-064 82/09/30 DAVIS, J , LOYSEN.P Office of Nuclear Material Safety & Safeguards, Director ip 19803 277 24% Fiche 50-387,62/09/30,
- -8210270413 Mod 3, extending period of performance to 830131, revising billing instruction info & substituting Manual Chapter 3202, to "Environ Assessment of Lou Level Naste Storage at PA Power & Light Co. Susquehama Steam Electric Station "ARCHER, C D Science Applications, Inc. HAGAN, T F Technical Assistance Contracts Branch NRC-02-81-044 82/09/30 2pp 15833 278 24X Fiche 50-387, 82/09/30,8210270411

## CKET 80-389 BT LUCIE PLANT, UNIT 2

Application/construction stage documents & correspondence

10190014 Forwards background info for meeting to discuss engineering verification program & measures used to assure program independence W/o encls
NERSES, V Licensing Branch 3 82/09/09 DENTON. H R Office of Vuctear Reactor Regulation, Director EISENHUT, D Q Division of Licensing VOLLMER.R H Division of Engineering 2pp 15760 316 24% Fiche 50-389,82/09/09.8210190014

i0080340 Discusses NRC understanding of core load schedule List of licensing actions not yet resolved to NRC satisfaction encl. dOVAN,T M Assistant Director for Licensing 82/09/10 UHRIO,R E lorida Power & Light Co Spp 15663 323 24X Tiche 50-389, 82/09/10, 8210080340 UHRIG R E

- 8210010017 Forwards response to findings identified in 820831~0901 audit of electrical area UHRIG.R E Florida Power & Light Co 82/09/24 EISENMUT, D G Division of Licensing 3pp 15565 144 24% Fiche 50-389, 82/09/24,
- 8210040394 Forwards minutes of 820723 meeting w/util & C-E task Force managers in Windsor,CT re engineering verification program BLODGETTATH Ebasco Services. Inc. (subs. of Enserch Corp.) 62/09/29 E19ENHUT D © Division of Licensing Opp. 15584-190 24X Fiche 50-389,82/09/29 8210040334
- 8210210028 Authorizes use of ASME Code Case N=316 for application in const of components Use of code case should be documented in RERRIGAN, J D Licensing Branch 3 82/09/27 UHRIG.R E Flor Power & Light Co 2pp 15782 201 24% Fiche 50-389.82/09/29. 8210210028
- 8210210251 Notification of 821000 meeting w/util in Bethesda, MD to discuss procedure for leak testing pressure isolation valves Meeting agenda encl NERSES, V Licensing Branch 3 82/09/29 KERRIOAN, J Licensing Branch 3 4pp 15774 327 24X Fiche 50-389, 82/09/29, 8210210251
- 8210050416 Forwards Suppl 1 to "Near-Term OL Summary Human Engineering Rept on St Locie Unit 2 Control Room" UHRIO,R E Florida Power & Light Co 82/77/30 EISENHUT.D 0 Division of Licensing 1p 15607 125 24X Fiche 50-389.82/09/30.
- --8210050419 Suppl 1 to "Near-Term OL Summary Human Engineering Rept on St Lucie Unit 2 Control Room" 4 Florida Power & Light Co 82/09/07 179pp [5607-126 24X Fiche 50-389, 82/09/00.8210050416
- 6210060276 Forwards training program on Loose parts monitoring sys-which properly qualifies plant personnel to operate sys Submittal completes action to satisfy NRC request URRIOR E Florida Power & Light Co 82/09/30 EISENHUT D 0 Division of Licensing 2pp 15621 170 24% Fiche 50-389.62/09/70,
- 821006028B Informs that requirements stated in Generic (Ltr 82-12 re staff working hours adequately enforced by incorporation in administrative procedures Amend to Tech Specs unnecessary at present time

  OHRIO, R E Florida Power & Light Co 82/09/30 EISENHUT, D G

  Division of Cicensing lp 15619 212 24X Fiche 50-339, 82/09/30. H2100A02HB
- 8210180268 Trip rept of caseload forecast panel 820608-10 site visit to assess const progress Meeting agenda & attendance list enci NERSES,V Licensing Branch 3 82/10/01 Licensing 8pp 15746-328 24X Fiche 50-389,82/10/01,8210180246 Licensing Branch 3
- 821021057: Forwards final NRR input for plant Cycle 3 systematic assessment of licensee performance evaluation Contributors listed NERGES V Licensing Branch 3 02/10/01 EIGENHUT, D 0 Division Licensing 6pp 19784-318 24X Fiche 50-389, 02/10/01, 0210210591
- B210130289 Forwards util responses to NRC concerns to inadequate core cooling instrumentation, per 820914 telcon w/NRC Gualification testing of heated junction thermocouple sys scheduled for completion by 821015

  UHRIGHR E Florida Power & Light Co 82/10/05 EIBENHUT, D G Division of Licensing 4pp 15478 304 24X Fiche 50-389,82/10/05,82710/0588
- 8210270339 Forwards status of control room design review Requests addl info re progress w/implementing corrections for human engineering discrepancies & control room man-machine operations
  KERRIOAN.J D Licensing Branch 3 82/10/07 UHRIG.R E Flor
  Power & Light Co 7pp 19851 342 24X Fiche 50-389.82/10/07. Florida Power & Light Co 8210270339
- 8210130301 Forwards list of engineering & constitems that are not expected to be completed at core load & justification for aperation prior to completion of items UHRIO, R E Florida Power & Light Co 82/10/08 EIBENHUT, D Q Division of Licensing 19pp 15678 184 24X Fiche 50-389, 82/10/ Division of Licensing 19pp 8210130301 24X Fiche, 50-389, 82/10/08,
- 8210190348 Forwards addl info re onsite ac power sys bus tie interlocks
  UHRIO.R E Florida Power & Light Co 82/10/12 EIBENHUT.D 0
  Division of Licensing 2pp 15797 243 24% Fiche 50-389,82/10/12.

### DOCKETED HEIVIS

- 8210250313 Informs that all generic itrs through 82-14 applicable to facility have been reviewed & required responses submitted UHRIG.R E Florida Power & Light Co 82/10/20 EISENHULD 0 Division of Licensing 1p 15790 063 24X Fiche 50-389.82/10/20, 8210250313
- B210260114 Forwards minutes of B21006-07 meeting w/util.Ebasco & C-b task force managers re engineering verification program BLODOETT: TH Ebasco Services. Inc (subs of Enserch Corp.) B2/10/20 EISENHUT. DO Division of Liceneing App. 15799 112 244 Fiche 50-389,82/10/20,8210260114
- 6210280254 Forwards proprietary "Final Assessment of St Lucie 2 Fuel Structural Integrity Under Faulted Conditions."

  CEN-187(15)-P. Revision 1-P 8 "St Lucie 2 Fuel & CEA Design Summary Evaluation Rept." CEN-222(1)-P Repts withheld UHRIO.R E Florida Power & Light Co 82/10/26 EISENHUT.D 0 Division of Licensing 7pp 15845-316 24X Fiche 50-389,82/10/26,8210280254
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8210180263 Notification of 821005 meeting w/util & C-E in Windsor,Cl to discuss review of closeout of SER Section 4.2, "Fuel Sys Design," open items WERSES,V Licensing Branch 3. 82/09/28 KERRIGAN.J D. Licensing Branch 3. 3pp 15746-325 24X Fiche 50-389,82/09/28.8210180263
- 8210180237 Requests add1 info refuel analysis in order to complete review of SER confirmatory issue RERRIGAN.J D Licensing Branch 3 82/10/01 UHRIG.R E Florida Power & Light Co 2pp 15746 258 24% Fiche 50-389,82/10/01. 8210180237
- 8210180257 Forwards Alden Research Lab. "Performance Evaluation of Containment Sump at Full-Scale, St Lucie Nuclear Power Station 2 Submittal completes commitment to provide SER confirmatory info on vertex testing UHRIO.R E Florida Power & Light Co 82/10/06 EISENHUT.D 0 Division of Licensing 19 15678 051 24X Fiche 50-389,82/10/06,8210130257
- --8210130287 "Performance Evaluation of Containment Sump at Full-Scale, Bt Lucie Nuclear Power Station 2" DUROIN.W W Alden Research Laboratory 106-82/M7KF 82/09/30 41pp 15578.052 24X Fichs 30-389/82/10/06/82/0130257
- 8210280067 Forwards proprietary "Response to NRC Questions on Implementation of St Lucie Unit 2 Rod Saw & Orid Spacing Penalties" to resolve action items identified in SER (NUREG-0843). Hithheld (ref IOCFR2, 790). UHRIO, R E Florida Power & Light Co 82/10/25 EISENHUT, D G. Division of Licensing 6pp 15837 241 24% Fiche 50-389,82/10/25, 2310280047
- F Security, medical, emergency & fire protection plans
- #8210010185 Forwards IE Insp. Repts 50-338/82-28 & 50-389/82-37 on 820809-13. No noncompliance noted. DANCE/H C. Division of Project & Resident Programs 82/09/08. URRIO.R.O Florida Power & Light Co. Epp. 15565-326 24X Fichs. 50-335.82709/08.8210010155

- 8210190056 Forwards request for addl into re 10CFR50.App R Sections III 0 % III L Info required to complete review of fire protection of safe shutdown capability KERRIGAM, J D Licensing Branch 3 82/09/29 UHRIG.R E Flaida Power & Light Co. 3pp 15761-046 24X Fiche 50-389,82/09/29,8210190056
- B21013034B Forwards response to Question 410 52 re fire protection requirements URRIO, R E Florida Power & Light Co B2/10/07 EISENHUT, D G Division of Licensing 2pp 15682 036 24% Fiche 50-389, 82/10/07, B21013034B
- 8210260376 Ack receipt of 821013 ltr informing NRC of steps taken to correct violations noted in IE Sareguards Insp Rept 50-335/82-30

  LEMIS R C Division of Project & Resident Programs 82/10/22 UMRIO R E Florida Power & Light Co ip 15806 iJB 24V
  Fiche 50-335.82/10/22 8210260376
- --8210260510 Forwards IE Safeguards Insp Repts 50-335/82-30 t 50-389/82-41 on 820816-20 t notice of violation Notice of violation to rept details withheld (ref 10CFR73 21) LEWIS.R C Division of Project to Resident Programs 82/09/13 UMR10.R E Florida Power to Light Co 2pp 15806-140 24x Fichs 50-335.82/10/22-8210260376
- --B210260515 IC Bafeguards Insp Repts 335/B2-30 &50-369/B2-41 on 820B16-20 Moncompliance noted failure to comply wiscourity plan re vehicle control alarms & compensatory action Details withheld (ref 10CFR/3 21) gODDE, R Region 2. Office of Director B2/09/10 2pp 15806 142 24X Fiche 50-335, B2/10/22, B210260376

### M Antitrust correspondence

- 6210120416 Notification of contract execution, Mod 2 to "Economic Assistance for 8t Lucia 2 Antitrust Proceeding ([]) "Contractor JM Kuhlman MCLEAREN. T Technical Assistance Contracts Branch FIN 8-7543 62710705 DENTON. HR Office of Nuclear Reactor Regulation. Director 1p 18689 222 24X Fiche 50-389.82/10/05.8210120416
- --8210120423 Mod 2.deobligating funds.to "Economic Assistance for 8t Lucie 2 Antitrust Proceeding (II) "
  KUHLMAN.J M Kulhman. J M HAGAN.T F Technical Assistance Contracts Dranch FIN 0-7543 92/10/05 ip 15687 223 24x Fiche 50-389.02/10/05.B210120416
- O Inspection reports. IE Bulletins & correspondence
- 9210220214 Advises that weld re-exam completed on 920621, in response to IE Insp Rept 50-389/82-13 Results made available to site inspector

  UHRIO.R E Florida Power & Light Co 92/08/12 O'REILLY.J P
  Region 2. Office of Director ip 15777 394 24X
  Fiche 50-389/82/08/12.9210220214
- 9210010213 Forwards IE Insp Rept 50-387/82-40 on 920817-20 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/08/31 UHR10, R E Florida Power & Light Co 2pp 15568 043 24X Fiche 50-389, 82/08/31, 8210010213
- ---8210010216 IE Insp Rept 50-389/82-40 on 820817-20 No noncompliance noted Major areas inapected instrumentation cable termination until work & work activities, cable to termination GC records & followup on licensee identified items (MERRIHEATHER, N., CONLON, T.E. Division of Engineering & Technical Programs 82/08/27 3pp 15568-045 24X Fiche 80-389,82/08/31,8210010213
- B210010155 Forwards IE Insp Repts 50-335/B2-28 & 50-389/B2-37 on B20B09-13 No noncompliance noted DANCE, H C Division of Project & Resident Programs B2/09/08 UHRIO, R.E. Florida Power & Light Co 2pg 15565-326 24X Fichs 80-335, 82/09/08, 8210010155
- --8210010169 IE Insp Repte 50-335/82-28 & 50-389/82-37 on 820809-13 % noncompliance noted Major areas inspected follows on emergency preparedness appraisal & exercise findings HUFFMAN, G. N., JENKINB-0 R Division of Emergency Preparedness & Operational Support 82/09/02 18pp 15565-328 24X Fichs. 50-335,82/09/08,8210010155

- 9210120655 Forwards draft input to systematic assessment of licenses performance for review & comments Comments should be submitted by 920910, for consideration in final rept W/o
- encl NERBER V Licensing Branch 3 82/09/09 EISENHUT, D 0 Division of Licensing MATTSON, R L Division of Systems Integration (post 811005) THOMAS, H Division of Human Factors Safety ip 19672 334 24X Fiche 50-389, 82/09/09, 8210120655
- 3210010301 Forwards IE Insp Rept 50-389/82-41 on 820824-27 No nancompliance noted DANCE,H C Division of Project & Resident Programs 82/09/10, UHRIO,R E Floride Power & Light Co 2pp 15568 310 24X Fiche 50-389, 82/09/10,8210010301
- -8210010305 IE Insp Rept 50-389/82-41 on 820824-27 No noncompliance noted Major areas inspected safety-related pipe support & restraint sys & seismic analysis for as-built safety-related piping sys
  YORK, J W. BLAKE, J Division of Engineering & Technical
  Programs 82/09/08 5pp 15568 312 24X Fiche 50-389,82/09/10,8210010301
- 210150345 Forwards IE Insp Repts 50-335/82-31 & 50-389/82-38 on 820830-0903 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/09/22 UHRIO, R E Florida Power & Light Co 1p 15704 322 24X Fiche, 50-335, 82/09/22, 8210150345
- -B210150388 IE Insp Repts 50-335/82-31 & 50-387/82-38 on 820830-0903 No noncompliance noted Major areas inspected redicactive liquid & gaseous effluent releases, reactor coolant chemistry & radioactive transportation activities WRAY.J R. BARR.K P Division of Engineering & Technical Programs 82/09/17 10pp 15704 323 24% Fiche 50-335,82/09/22, 8210150345.
- '10:50262 Forwards IE Insp Rept 50-389/82-42 on 820830-0903 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/09/27 UNR30.R E, Florida Power & Light Co 2pp 15703 26: 24X Fiche 50-389.82/09/27.8210150262
- 82:0150269 IE Insp Rept 50-389/82-42 on 820830-0903 No noncompliance noted Major areas inspected preoperational test procedure review, test witnessing & test procedure verification & plant tour TAYLOR, P. A. JAPE, F. Division of Engineering & Technical Programs 82/09/23 4pp. 15703 263 24X Fiche 50-389, 82/09/27, 82:0150262
- 10210591 Forwards final NRR input for plant Cycle 3 systematic assessment of licensee performance evaluation. Contributors listed MERSES, V Licensing Branch 3 82/10/01, EISENHUT, D Q Division of Licensing App 15784 318. 24X Fishe 50-389, 82/10/01, 8210210591
- 00190293 IE Info Notice 80-38, Suppl 1, "Leaking & Dislodged I-125 mplant Seeds." Svc list encl
  1088, L 1. Division of Fuel Facilities: Materials & Gafeguards
  12/10/06 Consolidated Edison Cp of New York 66pp 15761 250,
  14X Fiche: 50-000; 82/10/06; 8208190293
- 8190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-"all.Large-Dlameter, Stainless Steel, Recirculation Bys iping at BWR Plants "Svc list end! EYQUNO, R.C. Director's Office, Office of Inspection and nforcement 82/10/14 Consolidated Edison Co. of New York 15gp. 15810 125. 24X Fichs 50-000, 82/10/14, 8208190238.
- 0220280 Ack receipt of 820730 ltr informing NRC of steps taken to orrect violations noted in IE Insp Repts 50-335/82-11 & 0-385/82-34
  ANCE,H C. Division of Project & Resident Programs 82/10/15
  -RIOR E. Florida Power & Light Co. ip. 15775 084 24X
  iche. 50-335, 82/10/15, 8210220280.
- 210220291 Forwards IE Insp Repts 50-335/82-11 & 50-389/82-34 on 820711-0810 & notice of violation.
  DANCE, H C. Division of Project & Resident Programs 82/09/01 UHRIG. R.E. Floride Power & Light Co. 2pp 15775 087, 24% Fichs 50-335,82/10/15,8210220280
- '10220303 IE Insp Repts 50-335/82-11 & 50-389/82-34 on 820711-0810 Noncompliance noted on 820805, Equipment Clearence Order L-8-30 incorrectly identified suction & discharge drain valves V-2317 & V-2327 for charging pump A. ELROD, 8 A , BIBB, H. E. , JULIAN, C A Division of Project & Resident Programs. 82/08/31. 10pp. 15775:090 24X Fiche: 50-335, 82/10/15, 8210220280.

- 8210260376 Ack receipt of 821013 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-335/82-30 LEWIS,R C Division of Project & Resident Programs 82/10/22 UHRIO,R E Florida Power & Light Co ip 15806-138 24X Fichs, 50-335,82/10/22,8210260376
- ~-8210260510 Forwards JE Safeguards Insp Repts 50-335/82-30 & 50-387/82-41 on 820816-20 & notice of violation Notice of violation to rept details withheld (ref 10CFR73 21) LEMIS.R C Division of Project & Resident Programs 82/07/13 UHR10.R E Florida Power & Light Co 2pp 15806 140 24X Fiche 30-335,82/10/22.8210260376
- ~-8210240515 IE Safeguards Insp. Rept 50-335/82-30 & 50-389/82-41 on 820816-20 Nancompliance noted failure to comply w/security plan re vehicle control alarms & compensatory action Details withheld (ref 10CR73 21)
  60DDE,R · STANSBERRY W · MCGUIRE, D R Region 2, Office of Director 82/09/10 2pp 15806 142 24X Fiche 50-335.82/10/22, 8210260376
- R Periodic operating reports & related correspondence
- 8210040072 Forwards joint Ebasco & C-E task force program weekly status summary for 820920-25
  BLODOETT.TH Ebasco Services. Inc. (subs. of Enserch Corp.)
  82/09/24 EISENHUT.D Q Division of Licensing App. 15581 272
  24% Fichs 50-389, 82/09/24.8210040072
- 8210060371 Forwards const/startup progress rept for Aug 1982 Target fuel load date of 821028 still valid URRIO.R E Florida Power & Light Co 82/10/01 EIGENHUT.D G Division of Licensing 2pp 15618 328 24X Fichs 50-387.82/10/01, 8210060371
- 8210150431 Forwards weekly status summary of joint Ebasco & C-E verification program for 821004-08
  BL000ETT.T H Ebasco Services. Inc (subs of Enserch Corp.)
  B2/10/08 EISENHUT.D O Division of Licensing 4pp 15704-015
  24X Fiche 50-389,82/10/08,8210150431
- 8210260466 Forwards joint Ebased & C-E task force engineering verification program weekly status summary for 821011-15 BLODGETT H Ebased Services. Inc (subs of Enserch Corp.) 82/10/15 ElseNHUT.O Division of Licensing 4pp 15807 225 24X Fiche 50-389.82/10/15.8210260466
- 8210250317 Forwards const/startup monthly progress rept for Sept 1982 UHRIG R E Florida Power & Light Co 82/10/19 EISENHUT, D Q Division of Licensing 2pp 15790 292 24X Fiche 50-389, 82/10/19, 8210250317
- S Reportable occurrences. LERs & related correspondence
- 8210060236 Final deficiency rept re undersize fillet welds Initially reported on 820831 Insp program revised & all undersized flange & socket fitting welds will be repaired QC breakdown not responsible for event UHRIO.R E Florida Fower & Light Co 82/09/30 O'REILLY, J P Region 2, Office of Director 3pp 15619 397 24X Fiche 50-389,82/09/30.8210060236
- 8210130070 Final deficiency rept re incorrect shaft bearings on diesel generator motors 2A1 & 2A2 Initially reported on 820826 Shaft bearings replaced w/self-aligning bearings. Not reportable per 10CF#80 55s.but reportable per Part 21 UHRIOR E Florida Power & Light Co 82/10/01 0'REILLY, J P Region 2, Office of Director. 2pp 18473 119 24% Fiche 50-389.82/10/01.8210130090
- B210130536 Interim deficiency rept re fan belts on diesel generators 2A & 28 Initially reported on B20210 Final rept will be submitted by 821130 UHRIG.R E Florida Power & Light Co B2/10/01 O'REILLY, J P. Region 2, Office of Director Ip 15682 193, 24X Fiche, 50-387, 82/10/01/8210130536
- 8210220167 Interim deficiency rept re failure of reactor shutdown cooling bypass valves to respond to command signals initially reported on 820400 Util still reviewing problem final rept will be submitted by 821030.

  UHRIO, R E Florida Fower & Light Co 82/10/04. O'REILLY, J. P. Region 2, Office of Director ip 15776 362, 24X Fiche: 50-389, 82/10/06,8210220167

#### DOCKET 50-390 WATTS BAR NUCLEAR PLANT. UNIT 1

- A Applacation/construction stage documents & correspondence
- 210010038 Responds to FDIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON.J H Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 19727 005 24x Fishe 50-000.82/06/28.8210010008
- -8008050265 Discusses add1 required info to better define potential for cracking in reactor vessel notiles
  NODWAN.V S Assistant Director for Materials & Qualifications
  Engineering 80/05/05 TEDESCO.R L Assistant Director for
  Licensing 2pp 15727 176 24X Fiche 50-000,82/06/28,8210010008
- 210180331 Forwards evaluation of Apr 1982 site audit of safety-related electric & mechanical equipment Resolution of specific concerns in single submittal requested NOVAK.T M. Assistant Director for Licensing 82/09/23 PARRIS.H & Tennessee Valley Authority 39pp 15746 282 24X Fiche 50-390,82/09/23.8210180331
- 110190084 Summary of 820917 meeting w/util & Black & Veatch in Bethesda, MD re applicant plans to perform independent design verification of auxiliary feedwater sys Attendance list & viewgraphs encl
  KENYON, T. U. Operating Reactors Branch 4 82/10/01 Const.
- VERYON.T J Operating Reactors Branch 4 82/10/01 Operating Reactors Branch 4 13pp 15761 102 24% Fiche 50-390, 82/10/01 8210190084
- 10280208 Forwards revised FSAR Section 17 2.consisting of Table 17 2-1.listing critical structures sys tomponents Infountil be included in Anend 48 to FSAR MILLS.L M Tennessee Valley Authority 82/10/25 ADENSAM.E Licensing Branch 4 14pp 15839 293 24X Fiche 50-390,82/10/25, 8210280208

# NRC Safety Evaluation Report (SER), suppls & correspondence

- 10050405 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF THE WATTS BAR NUCLEAR PLANT.UNITS: AND 2 Docket Nos 50-390 And 50-391 (Tennessee Valley Authority) # Office of Nuclear Reactor Regulation, Director NUREG-0847 801 82/09/30 29pp Available at NRC \$4.50 19825 299 24X Fiche 50-390.82/09/30,8210050405
- Security, medical, emergency & fire protection plans
- 10220225 Requests NRC perform preliminary review of util program for watchtower power block security concept Meetings suggested for 82102-03 as part of review Agenda encl HLLS.L M Tennessee Valley Authority 82/10/18 EISENHUT, D C Division of Licensing 2pp 15776-226 24X Fiche 50-390,82/10/18,8710220225
- O260189 Confirms that evacuation time estimate study reviewed by oth local & TN state authorities Population density & listribution info provided by TN Dept of Civil Defense based in 1980 census

  ILLS.L. K. Tennessee Valley Authority 82/10/20 ADENSAM, E. Q. Licensing Branch 4 2pp 15799 030 24X Fiche 30-000.82/10/20, 50189

- @ Inspection reports. IE Bulletins & correspondence
- B210080015 Add1 response to FOIA request for 19 categories of infole nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
  FELTON.J M Division of Rules and Records 82/07/12 UDFil.N A Critical Mass Energy Project 9pp 15665 027 24X
  Fiche 50-000.82/07/12,8210080015
- --8210080167 Systematic assessment of licensee performance nutes to racility evaluation for Aug 1979-Jul 1980 4 MRC - No Detailed Affiliation Given 80/07/31 App 15868 101 24X Fiche 50-000,82/07/12,8210080015
- B210220223 Bubmits add1 into to B20324 response to 1E Insp Rept 50-390/82-03 Revision of FSAR Table 14 2-1 & Chapter 9 will not be complete until 821015 MILLS.L M Tennessee Valley Authority B2/08/11 O'REILLY, J.P. Region 2, Office of Director ip 15776 210 24X Fiche 50-390,82/08/11,82/0220223
- 5210010452 Forwards IE Insp Repts 50-390/62-31 & 50-391/62-28 on 620824-27 No noncompliance noted VERRELLI, D.M. Division of Project & Resident Programs 62/09/09 PARRIS, H.Q. Tennessee Valley Authority 2pp 15572 305 24x Fiche 50-390, 62/09/09, 6210010452
- --8210010462 IE Insp Repts 50-390/82 II & 50-391/82-20 on H20024-2/ No noncompliance noted Major areas inspected instrumentation, installation & nonconforming lepts & conceptual design requirements HUNT.H D . CCNLON.T E Division of Engineering & Technical Programs 82/09/07 App 155/2 JOT 24X Fiche 50 390.82/09/09 8210010492
- 8210150304 Forwards IE Insp Repts 50-390/02-32 & 50-391/02-29 on 820824-27 No noncompliance noted VERRELLI, D.M. Division of Project & Resident Programs 62/09/60 PARRIS, H.G. Tennessee Valley Authority 2pp 15707 295 24x Fiche 50-390, 82/09/10, 8210150304
- --8210180315 IE Insp Repts 30-390/82-32 & 50-391/82-29 on 0208-4 07 No noncompliance noted Major areas inspected engineering design work MCFARLAND, C.R. DEBRAGE, A.C. UPRIGHT, C.H. Division of Picifect & Resident Programs 82/09/10 5pp 15707 297 24X Fiche 50-390,82/09/10,8210180304
- 8210150923 Forwards IE Insp Repts 50-390/02-30 & 50-391/82-27 on 820721-0820 No noncompliance noted Programs 02/04/16 VERRELLID M Division of Project & Resident Programs 02/04/16 PARRIGH 0 Tennessee Valley Authority 2pp 15/21 270 24X Fiche 50-390, 62/09/16, 6210150323
- --B210150331 IE Insp Repts 50-390/B2-30 & 50 391/B2-27 on 820721-0020 k noncompliance noted Major areas inspected literases action on previous insp findings & review of periodic & special repts HEATHERLY, T. L., QUICK, D.R. Division of Project & Resident Programs B2/09/16 5pp 19721 272 24X Fiche 50-390,82/09/16,8210150323
- 8210010333 Act receipt of 820826 itr informing NRC of steps taken to correct violations noted in IC lnsp Repts 50-390/01-03 & 50-391/81-03 William of Project & Resident Programs 62/09/17 PARRIGLE OF Tennessee Valley Authority 1p 15568 238 24X Fichs 50-390, 82/09/17,8210010333
- --B210010341 Supple response to NRC 020414 ltr re violations noted in IE Insp Repts 50-390/BI-03 & 50-391/BI-03 Corrective actions leak integrity of body bonnet joint verified prior to startup & component tolerance will be confirmed MILLS, L M Tennessee Vallen Authority 82/00/21

ri

10

- 3210220315 Forwards IE Insp Repts 50-390/82-34 & 50-391/82-31 on 820914-17 No noncompliance noted VERRELLI D M Division of Project & Resident Programs 82/09/30 PARRIS. K G Tennesses Valley Authority 2pp 15776 038 24X Fiche 50-390.82/09/30.8210220315
- -82(0220323 IE In>p Repts 50-390/82-34 & 50-391/82-31 on 820914-17 No noncompliance noted Major areas inspected instrumentation cable / termination.observation of work.work activities, review of quality records & licensee identified items RUFF.A B . CONLON.T E Division of Engineering & Technical Programs 62/09/29 3pp 15776-040 24X Fiche 50-390.82/09/30, 8210220315
- F10150207 Ack receipt or 820825 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-18 & 50-390/82-18 Model info requested by 820923 talcon VERRELLI.D M Division of Project & Resident Programs 82/10/04 PARRIS.H C Tennesses Valley Authority ip 15706 083 24X Fishe 50-390, 82/10/04, 8210150209
- 8210190230 Responds to NRC 860707 ltr re violations noted in IF Insp. Repts 50-390/82-18 & 50.391/82-15 Corrective actions personnel instructed in application of EP 1 26 to limited OA sys. MILLS, L. M. Tennessee Valley Authority 62/09/24 0 REILLY, J. P. Region 2. Office of Director 4pp 15706 084 24X Fiche 50-390, 62/10/04, 8210150209
- B2[015024] Responds to NRC B20702 ltr re violations noted in IE insp. Repts 50-390/82-18 & 50 391/82-15 Corrective actions program to instruct all personnel in all procedures affecting design work implemented. MILE.L M. Tennessee Valley Authority B2/08/25 O'REILLY.J P. Region 2. Office of Director 3pp. 15706-088 24X Fiche 50-390.82/10/04-82/0150209
- b210:70251 Responds to NRC #20707 irr reviolations noted in IE Insp Repts 50-390/82-18 & 50 391/82-15 Corrective actions EP 1 28. "Control of Documents Affecting Quality," will require independent verification of procurement spaces MLLLS,L M Tennessee Valley Authority 82/08/20 0'REILLY,J P Region 2. Diffice of Director 3pp 15706 091 24X Fishe 50-390.82/10/04-8510150209
- 62:0150260 Discusses IE Insp Repts 50-390/82-18 & 50-391/82-15 on #20421-0520 & forwards corrected App A Institute of #forwards corrected App A Institute of #forwards corrected App A Institute of #forwards forwards of Project & Resident Programs 82/07/07 PARMIS, #forwards Parmessee Valley Authority 2pp 15706 094 24X Fiche 50-390,82/10/04 @210150209
- 710159268 Corrected notice of violation from insp on B20421-0520 Noncompliance noted nonconforming condition rept not initiated for recignized diesel generator tube oil deficiencies 4 Region 2, Office of Director 82/07/07 2pp 15706 096 24x Fiche 50-390.82/10/04.8210150209
- \*210150278 Forwards IE Insp Repts 50-390/82-18 & 50-391/82-15 on 820421-0520 & notice of violation LEM/S.R C Division of Project & Resident Programs 82/06/08 PARRIS. H G Tennessee Valley Authority 2pp 15706 098 24X Fiche 50-390.82/10/04.8210150209
- 210150205 Notice of violation from insp on 820421-0520 \* Region 2 Office of Director 82/05/08 2pp 15706 100 24x Fichs 50-370.827/10/48.8210150207
- 2101503D3 IE Insp Rept» 50-390/82-18 & 50-391/82-15 on 820421-0520 Moncompliance noted failure to design for environ effects, follow corrective action procedures & conduct adequate addits MCDDNALD, J. A. HEATHERLY, T. L., QUICK, D. R. Division of Project & Resident Programs 82/06/08 6pp 15706 102 24X Fiche 50-390,82/10/04,8210150209
- 8190203 IE Info Notice 80-35, Suppl 1, "Leaking & Distudged I-125 mplant Seeds " Svc list encl
  DBB, L I Division of Fuel Facilities, Materials & Bafeguards
  2/10/06 Consolidated Edison Co of New York 66pp 15761 250
  4x Fiche 50-000.82/10/06.8208190233
- ):50349 Forwards Pages 5 & 6 to 1E Insp Repts 50-390/82-32 & D-391/82-29 inadvertently omitted from 820910 transmittal IRRELLI.D M Division of Project & Resident Programs 82/10/07 MRIS.H & Tennessee Valley Authority 2pp 15704,318, 24X lche 50-390,82/10/07.8210150349
- 10150355 Pages 5 & 4 to IE Insp Repts 50-390/82-32 & 50-391/82-29 inadvertently omitted from B20910 transmittal \* Region 2. Office of Director 82/10/07 2pp 15704 320 24X Fichs 30-390, 82/10/07, 8210150349

- 8208190238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Bys Piping at BWR Plants " Svc list encl DEYCUNG, R Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 1(5pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- 8210220459 Ack receipt of 820715 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/81-26 & 50-391/91-24
  VERRELLI. D M Division of Project & Resident Programs 82/10/18
  PARRIS.H O Tennessee Valley Authority 1p 15779 133 24X
  Fiche 50-390, 82/10/18.8210220459
- 9210220466 Advises that corrective actions per violations noted in IE insp. Repts 50-390/81-26 & 50-391/81-24 will be completed by 921103 MILLS:L M Tennessee Valley Authority 92/09/15 G'REILLY:J P Region 2. Office of Director ip 15779 134 24X Fiche 50-390,82/16/18,8210220459
- 8210220472 Ack receipt of 820924 ltr informing NRC of steps taken to correct violations noted in IE Insp. Ropts 50-390/82-18 & 50-391/82-15 VERRELLI, D.M. Division of Project & Resident Programs 82/10/18 PARRIS.H 9 Tennesse Valley Authority 1p 15779 102 24X Fiche 50-390.82/10/18.8210220472
- S Reportable occurrences, LERs & related correspondence
- 8210080168 Sixth interim deficiency rept re qualification of epoxy grout for safety-related applications Initially reported on 820827 Support ands or add supports recommended Drawing revisions in gragness Completion expected by mid-May 1783 MILLS.L M Tennesses Valley Authority 82/09/23 0'REILLY, J P Region 2. Office of Director 3pg 15640 i54 24X Fiche 50-390.82/09/23.8210080168
- 8210050316 First interim deficiency rept re incorrect insulation weights used in piping analysis Initially reported on 820829 QA document being prepared to substantiate insulation data Naxt rept will be submitted by 830423 MILLS.L.M. Tennesses Valley Authority 82/09/24 O'REILLY, J.P. Region 2. Office of Director 2pp 15610 281 24X Fiche 50-390.82/09/24.8210050316
- 8210080247 Third & final deficiency repts re resolution of unanticipated vibratory loading concerns Initially reported on B11228 Program developed to insure piping sys operate within design parameters Next rept provided by 821217 MILS, L M Tennesse Valley Authority 82/07/24 0'REILLY, J P Region 2. Defice of Director 3pp 15638, 104 24% Fiche 50-000, 82/09/24,8210080247
- 6210050062 First interim deficiency rept re failure to consider seismit & inertial loadings on ladders Initially reported on 620826 Ladder, platform or walkway found deficient will be modified or stiffened Next rept expected by 630124 MILLS.L M Tennessee Valley Authority 62/09/27 0'REJLLY.J P Region 2. Office of Director 20p 15603 236 24X Fiche 50-390.62/09/27.8210050042
- 8210050079 Second interim deficiency rept re potential for setpoint program for averpressure mitigating sys to exceed 10CFR50. App 0 requirements Initially reported on 820521 Vtil procuring solenoid-actuated valves Next rept by 830331 MILLS.L M Tennessee Valley Authority 82/09/27 O'REILLY, J P Region 2. Office of Director 2pp 15603 242 24X Fiche 50-390, 82/09/27, 8210050099
- 8210050114 Add1 info to final deficiency rept re seismic supports for auxiliary feedwater control valves initially reported on 800624 Corrective actions on Unit 1 completed 820831 Unit 2 valves will be installed during normal const schedule MILLS.L. M Tennesse Valley Authority 82/09/27 O'REILLY, J P Region 2. Office of Director 1p 15603 256 24% Fiche 50-390,82/09/27,8210050114
- 8210050293 First interim deficiency rept re six sheared motor pinion beys in Limitorque Model 50-0-25 motor operators Initially reported on 820830 Valves w/motor operators being tabulated. Next rept will be submitted by 821122 MILLS.L M Tennessee Valley Authority 82/09/28 0'REILLY.J P Region 2, Office of Director 2pp 15609 070 24X Fiche 50-000.82/09/28,8210050293
- 8210050158 Second interim rept re-undocumented minor mode to structural & miscellaneous steel Initially reported on 820510 Approx 93% of 250 features had preliminary insp/punchlist completed Next rept to be submitted by 830228 MILLS.L M Tennesses Valley Authority, 82/09/29 O'REILLY, J P Region 2. Office of Director 2pp 15605:154 24X Fiche 50-390, 82/09/29,8210050158

- 8210050280 First interem deficiency rept resolid-state protection systest procedures Initially reported on 820831 Util reviewing Westinghouse proposal for interim procedural change which would provide for failure detection Next rept by 821210 MILLS.L M Tennessee Valley Authority 62/09/29 O'REILLY.J P Region 2. Office of Director 2pp 15621 164 24X Fiche 50-390, 82/09/29, 82(0060280)
- 8210060205 Fourth interim deficiency root re inadequate loading criteria for structural steel & supports Initially reported on 81117 General notes revised to clarify drawings Field mapping of platform steel continuing Next rept by 830310 MILLS.L M Tennessee Valley Authority 82/09/30 0'REILLY, J P Region 2. Office of Director 2pp 15614 041 24X Fiche 50-390, 82/09/30, 8210060205
- 8210060279 First interim deficiency rept re selection of undersized away struts Initially reported on 820901 Selection methods & adequacy of Bergen-Paterson struts under evaluation Next rept expected by 830225 MILLS.L M Tennessee Valley Authority 82/09/30 Q'REILLY, J P Region 2, Office of Director 2pp 15621 166 24X Fiche 50-390, 82/09/30, 8210060279
- 8210080255 First interim deficiency rept re inadequate QA program for masonry block work Instally reported on B20902 Const personnel investigating & replying to audit Next rept due on B21214 MfLLS.L M Tennessee Valley Authority B2/10/01 G'REILLY, J P Region 2, Office of Director 2pp 15638 186 24% Fiche 50-390.82/10/01.8210080255
- 8210080280 First interim deficiency rept re interpretation of radiograph test film on wolded pipe by Swepca Tube Corp Initially reported on 820701 Evaluation continuing Next rept will be submitted on 830217 MILLS.L M Tennesse Valley Authority 82/10/01 G'REILLY.J P Region 2. Office of Director 2pp 19638 201 24X Fiche 50-390, 82/10/01, 8210080280
- 8210080291 First interim deficiency rept re failure to terminate cables iPS111. IPS112. IPM1850. IPM1852. IPM1857. IPS152 & IPS153 Initially reported on 820901 Cables terminated & personnel retrained Next rept will be submitted by 821123 MILLS.L M Tennessee Valley Authority 82/10/01 O'REILLY.J P Region 2. Office of Director 2pp 15638 308 24X Fiche 50-390. 82/10/01.8210080291
- 8210080160 First interim deficiency rept re corrosion in high pressure fire protection sys Initially reported on 820903 Corrosion analysis in progress to determine potential deficiencies in safety-related areas Next rept expected by 830531 MILLS.C.M. Tennessee Valley Authority 82/10/04 0'REILLY, J.P. Region 2. Office of Director 2pp 15640 142 24X Fiche 50-000.82/10/04.8210080160
- 82(0080310 First interim deficiency pept rellack of piping sys analysis tracking Initially reported on 820902 Util investigating corrective actions to ensure engineering change notices are not closed out until work is completed MILLS.L. M. Tennesses Valley Authority 82/10/04 0'REILLY, J.P. Region 2. Office of Director 2 pp. 15698-042 24X Fiche 50~390.62/10/04.8210080310
- 8210130247 Sixth interim deficiency rept re differential settlement of rock supported structures Initially reported on 810707 Individual safety-related components at interfaces of structures being evaluated. Next rept by 830504 MILLS.L. H. Tennesses Valley Authority 82/10/05 D'REILLY, J.P. Region 2. Office of Director ip 15676 009. 24X Fiche 50-390, 82/10/05,8210130247
- 8210130384 Suppl to finel deficiency rept re essential raw cooling water seismic support Initially reported on 810506 Completion of Bergen-Patterson review expected by 821101 Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 82/10/05 O'REILLY, J.P. Region 2. Office of Director ip 15681:003 24X Fiche 50-390, 82/10/05.8210130384
- 82:0130560 Second interim deficiency rept re frequency criteria for piping supports. Initially reported on 820713 Investigation continuing Next rept expected by 82:1220, MILLS.L.M. Tennesses Valley Authority 82:10/05 0'REILLY, J.P. Region 2. Office of Director. ip 15683-299 244

- 821022009B First interim deficiency rept re qualification of process piping w/instrument lines attached Initially reported on 820909 Affected piping being reanalyzed to account for effect on instrument linux piping Next rept by 830429 MILLS.L H Tennessee Valley Authority 82/10/08 0'REILLY, J.P. Region 2. Office of Director 2pp 15777 362 24X Fiche 50-390, 82/10/08, 82/10/20098
- B210190307 Final deficiency rept re failure to meet pipe support luq criteria Initially reported on B20607 Lug parameter limit discrepancy corrected MILLS.L H Tennessee Valley Authority B2/10/12 O'REILLY. J P Region 2. D
- 8210290328 Second interim deficiency rept re use of nonconservative calculational method to evaluate General Const Spec 0-32 spacing violations (initially reported on 820528 Next rept uill be sent by 030528 Mills. In Tennessee Valley Authority 82/10/12 O'REILLY, J P Region 2, Office of Director 2pp 15853 064 24% Fishe 50-000.82/10/12.8210290328
- 8210190337 First Interim Deficiency Rept 50-390/82-100 re as-built & as-analyzed configuration discrepancies Initially reported on 820910 Response to IE Bulletin 79-14 will be carried out in two phases insp & review of findings Next rept by 830325 MILLS.C.M. Tennessee Valley Authority 82/10/13 G'REICLY.JP Region 2. Office of Director 2pp 15742 102 24X Fiche 50-390, 82/10/13, 8210190357
- 8210290236 Third interim deficiency rept to potentially overstressed embedded plates Instially reported on 820412 Investigation continuing & const activities deferred until sufficient info gathered to determine completion of project MILLS.L M Tennessee Valley Authority 82/10/14 O'REILLY, J P Region 2, Office of Director 2pp 15853 229 24X Fiche 50-000.82/10/14.8210270236
- 8210290052 Second interim deficiency rept re use of incorrect response spectra in Gilbert/Commonwealth piping analysis Initially reported on 820426 Reanalysis continuing Next rept expected by 820422 Also reportable per Part 21 MILLS.L.H. Tennessee Valley Authority 82/01/15 0'REJLLY, J.P. Region 2, Office of Director ip 15853 334 24X Fiche 50-390,82/10/15,82(0290052
- 8210270178 Sixth interin deficiency rept to rerouting of high pressure fire protection piping Initially reported on 810130 Three areas may contain worst case condition No deficiencies identified in two areas Nert rept provided by 821210 MILLS.C.H. Tennessee Valley Authority 82/10/15 0'REILLY.J.P. Region 2. Office of Director 1p 15853 311 24% Fiche 50-390, 82/10/15, 8210270178
- 8210260320 First interim deficiency rept we addition of locking devices to handwheel operated valves Initially reported on 820916 Comst activities deferred Analyses of locking devices continuing Next rept will be sent by 820310 MILLS, L.M. Tennessee Valley Authority 82/10/18 0'REILLY, J.P. Region 2, Office of Director 2pp 15602 359 24X Fiche 50-000, 82/10/18, 8210260320
- 8210260451 Fourth interim deficiency rept re failure to include documented piping insulation insps in GC program Initially reported on 811007 Const Specs N30-881 & N3C-912 revised to provide scope of insp requirements Next rept by 830425 MILLS, L.M. Tennessee Valley Authority 82/10/18 0'REILLY, J.P. Region 2, Office of Director 2pp 15807 104 24X Fiche 50-390, 82/10/18, 8210260451
- 8210260186 Second interim deficiency rept re underdesign of essential raw cooling water intake pumping station doors & hatches Initially reported on 820407 Flathead screws added to door frame for reinforcement Next rept expected by 830331 MILLS, L.M. Tennesses Valley Authority 82/10/19 D'REILLY, J.P. Region 2. Office of Director 2pp 15799 034 24X Fiche 50-390, 82/10/19, 8210240186
- 8210260370 Eighth interim deficiency rept re improper classification of essential raw cooling water sus piping & components Initially reported on Bi0324 Investigation ongoing Next rept will be submitted by B30427 MILLS.L H Tennessee Valley Authority 82/10/19 D'REILLY.J P Region 2, Office of Director ip 15803 104 24X Fiche 30-390. 82/10/19.8210260390
- 8210260100 Second interim deficiency rept re lack of seismic analysis on auxiliary bldg platform initially reported on 820426 Documentation for all attachments to suspect platforms being investigated Next rept expected by 830217 MILLS,L M. Tennessee Valley Authority 82/50/20. D'REILLY,J P Region 2. Office of Director 2pp 15799 122. 24X Fiche 50-390,82/10/20.8210260100

024040B Second interim deficiency rept re patentially deficient alve yoke holddown nut Initially reported on 820601 Util waiting Hestinghouse resolution for NSSS valves Also eportable per Part 21

Waising Hestinghouse Resolution for Made values Kiss eportable per Part 21 RLLS.L M Tennessee Valley Authority 82/10/20 O'REILLY, J P egian 2 Office of Director 2pp 15803 109 24X 1chs 50-390. 82/10/20.8210/260408

0290266 Fourth interim deficiency rept re failure of Limitorque stor operators during valve closure initially reported on 20126 Westinghouse, Limitorque & util investigating problem sit rept expected an 830128 Part 21 considered applicable ILLS, L. M. Tennessee Valley Authority 82/10/21 0'REILLY, J.P. 31an 2. Office of Director ip 15854 046 24X iche 50-390, 82/10/21, 8210290266

1290274 Final rept for Deficiencies B & E & seventh interim rupt for ificiencies A & D re control of procurement activities initially reported on 810316 Final corrective actions noted it rept expected by 839428 LLS.L M Tennessee Valley Authority 82/10/21 O'REILLY, J P gion 2, Office of Director 4pp 15853 143 24% che 50-000.82/10/21.8310290274

### ET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

pplication/construction stage documents & correspondence

18050265 Discusses add1 required info to better define potential for racking in reactor vessel noziles (MONAN, V S. Assistant Director for Materials & Gualifications ngineering 80/05/05 TEDESCO.R L. Assistant Director for icensing 2pp 15727 176 24X Fiche \$0-000.82/06/20.8210010008

90084 Summary of 820917 meeting w/util & Black & Veatch in hesda. MD re applicant plans to perform independent design iffication of auxiliary reedwater sys Attendance list & wgraphs encl 1 yON. T. J. Operating Reactors Branch 4 82/10/01 Operating ctors Branch 4 13pp 1576/ 102 24X Fiche 50~390,82/10/01.

3020B Forwards revised FSAR Section 17 2. consisting of Table 2-1, listing critical structures, sys & components Info to the included in Amend 48 to FSAR .S.L M Tennessee Valley Authority 82/10/25 ADENSAM.E insing Branch 4 14pp 15839 293 24X Fiche 50-370, 82/10/25. XE020B

# : Safety Evaluation Report (SER), supple & correspondence

10405 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF THE S BAR NUCLEAR PLANT, UNITS 1 AND 2 Docket Nos 50-390 And 191 (Tennessee Valley Authority)

Iffice of Nuclear Reactor Regulation, Director NUREG-0847 S01 9/30 29pp Available at NRC \$4 50 15625 299 24X e 50-390, 82/09/30, 8210050405

# urity, medical, emergency & fire protection plans

0225 Requests NRC perform preliminary review of util program for htower power black security concept Meetings suggested B21102-03 as part of review Agenda encl S.L M Tennessee Valley Authority 82/10/18 EISENHUT, D 9 sion of Licensing 2pp 15776-226 24X Fiche 50-390.82/10/18, 220225

0174 Forwards revised security plansincluding updated table of ints & revised Page A-5 Revision withheld (ref 873-21)
3.L M Tennessee Valley Authority 82/10/20 ADENSAM.E sing Branch 4 ip 15799-048 24X Fiche 50-390, 82/10/20, 260174

189 Confirms that evacuation time estimate study reviewed by local & TN state authorities Population density & ibution info provided by TN Dept of Civil Defense based 180 census

LL M Tennessee Valley Authority 82/10/20 ADENSAM.E 0 sing Branch 4 2pp 15799 030 24X Fiche 30-000, 82/10/20.

- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8208290018 Summarizes 268th ACRS meeting on 820812-14 in Washington, DC re full power CLs for Grand Culf I & Watts Bar I & II, systematic evaluation & integrated reliability assessment of Olma & control room habitability
  SHEWMON, P ACRS Advisory Committee on Reactor Safeguards
  82/08/06 PALLADINO, N J Commissioners 3pp 15447 233 24X
  Fiche 50-000.82/08/26.8208270018
- Q Inspection reports. IE Bulletins & correspondence
- 8210080015 Addl response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000,82/07/12,8210080015
- --8210080167 Bystematic assessment of licensee performance notes refacility evaluation for Aug 1979-Jul 1980

  + NRC No Detailed Affiliation Given 80/07/31 App
  15668 101 24% Fiche 50-000, 82/07/12, 8210080015
- 8210010452 Forwards IE Insp Repts 50-390/82-31 & 50-391/82-28 on 820824-27 No noncompliance noted VERELLID M Division of Project & Resident Programs 82/09/09 PARREB.H 0 Tennessee Valley Authority 2pp 15572 305 24X Fiche 50-390,82/09/09,8210010452
- --8210010462 IE Insp Repts 50-390/82-31 & 50-391/82-28 on 820824-27
  No noncompliance noted Major areas inspected
  instrumentation, installation & nonconforming repts &
  conceptual design requirements
  KUNT.M D . CONLON.T E Division of Engineering & Technical
  Programs 82/09/07 4ep 15572 307 24X Fiche 50-390,82/09/0
- 8210150304 Forwards IE Insp Repts 50-390/82-32 & 50-391/82-29 on 820824-27 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/09/10 PARRIS:H 0 Tennesses Valley Authority 2pp 15707 295 24X Fiche 50-390,82/09/10,8210150304
- --8210150315 IE Insp Repts 50-370/82-32 & 50-371/82-29 on 820824-27 noncompliance noted Major areas inspected engineering design work HCFARLAND, C.R. DEBBAGE, A.G., UPRIGHT, C.M. Division of Project Resident Programs 82/09/10 50p 19707 297 24X Fiche 50-370,82/07/10,8210150304
- B210160323 Forwards 1E Insp Repts 50-390/82-30 & 50-391/82-27 on B20721-0820 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs B2/09/16 PARRIS, H Q Tennessee Valley Authority 2pp 15721 270 24X Fichs 50-390, 82/09/16, 8210150323
- --82j0150331 IE Insp Repts 50-390/82-30 & 50-391/82-27 on 820721-08F noncompliance noted Major areas inspected licensee action on previous insp findings & review of periodic & special repts HEATHERLY, T.L., QUICK, D.R. Division of Project & Resident Programs 82/09/16 5pp 15721 272 24X Fichs 50-390,82/09/18210150323
- 8210010333 Ack receipt of 820826 ltr informing NRC of steps taken to carrect violations noted in IE Insp Repts 50-390/81-03 & 50-391/81-03.

  VERRELLI.D M Division of Project & Resident Programs 82/09/17 PARRIS H 0 Tennessee Valley Authority 1p 15568 238 24X Fiche 50-390, 82/09/17.8210010333
- --8210010341 Supple response to NRC 820414 1tr re violations noted in IE Insp Repts 50-390/81-03 & 50-391/81-03 Corrective actions: leak integrity of body bonnet joint verified prior to startup & component tolerance will be confirmed MILLS, L M Tennessee Valley Authority 82/08/26 O'REILLY, J F Region 2, Office of Director 3pp 15568-239 24X Fiche 50-390,82/09/17.8210010333
- 8210150026 Forwards Page 4 of IE Insp Repts 50-390/82-32 & 50-391/82 on 820824-27, omitted from 820910 submittal due to administrative oversight M/o and 10 out of the submittal trace oversight M/o and VERRELLI.D M. Division of Project & Resident Programs 82/09/28, PARTIS.H 0 Tennessee Valley Authority 2pp 13696 337 24X Fiche, 50-390, 82/09/28, 8210150026
- B210050344 Forwards response to Questions 0121 20 & 0121 22 per 920: request for info re preservice insp program MILLS.L.M Tennesses Valley Authority. 82/09/29. ADENBAN.E Licensing Branch 4 4pp. 15610 121 24X Fiche 50-390.82/09/29. 8210050344.

- --8210220323 IE Insp Repts 50-390/82-34 & 50-391/82-31 on 820914-17 No noncompliance noted Major areas inspected instrumentation cable & termination, observation of work work activities, review of quality records & licensee identified items RUFF.A B . CONLON.T E Division of Engineering & Technical Programs 82/09/29 3pp 15776 040 24X Fiche 50-390, 82/09/30, 8210220315
- 8210150209 Ack receipt of 820825 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-18 & 50-391/82-15 Add1 info requested by 820923 telcon VERRELLI.D M Division of Project & Resident Programs 82/10/04 PARRIS.H 9 Tennessee Valley Authority in 15706 083 24X Fiche 50-390,82/10/04,8210150209.
- --8210150230 Responds to NRC 820707 ltr re violations noted in IE Insp Repts 50-370/82-18 & 50-391/82-15 Corrective actions personnel instructed in application of EP 1 26 to limited OA 348 MILLS.L M Tennessee Valley Authority 82/09/24 O'REILLY, J P Resion 2. Office of Director 4pp 15706 084 24X Fichs 50-390.82/10/04/8210150209
- --B210150241 Responds to NRC 820702 htm re violations noted in IE Insp. Repts 50-390/82-16 & 50-391/82-15 Corrective actions program to instruct all personnel in all procedures affecting design work implemented MILLS.4 M. Tennessee Valley Authority 82/08/25 O'REILLY.J.P. Region 2. Office of Director 3pp 15706 088 24X Fishs 50-390, 82/10/04,8210150209.
- --821015025: Responds to NRC 820707 ltr re violations noted in TE Insp Repts 50-390/82-18 & 50-391/82-15 Corrective actions EP 1 28. "Control of Documents Affecting Quality," will require independent verification of procurement apecs HILLS.L M Tennessee Valley Authority 82/08/20 (1/REILLY, J P Region 2. Office of Director 3pp 15706 091 24X Fiche 50-390.82/10/04.8210150209
- --8210150240 Discusses IE Insp Repts 50-390/82-18 & 50-391/82-15 on 820421~0520 & forwards corrected App A (notice of violation)

  LEMIS.R C Division of Project & Resident Programs 82/07/07 PARRIS.H C Tennssee Valley Authority 2pp 15706 094 24X Fiche 50-390, 82/10/04, 8210150209
- --8210150268 Corrected notice of violation from insp on 620421-0520 Noncompliance noted nonconforming condition rept not initiated for recognized diesel generator tube oil deficiencies

  \* Region 2, Office of Director. 82/07/07 2pg 1570& 098 24X Fiche 50-390,82/10/04.8210150209
- --8210150278 Forwards IE Insp Repts 50-370/82-18 & 50-391/82-15 on 820421-0320 & notice of violation LEMIS: RC Division of Project & Resident Programs 82/06/08 PARRIS: H 0 Tennessee Valley Authority 2pp 15706 098 24X Fiche 50-39(9.82/10/04) 82/10150209
- --8210150286 Notice of Violation from insp on 820421-0520, \* Region 2, Office of Director 82/06/08 2pp 15706 100 24: Fiche 50-390.82/10/04.8210150209
- --8210150303 IE Insp Repts 50-390/82-18 & 50-391/82-15 on 820421-0520 Noncompliance noted failure to design for environ effects, follow corrective action procedures & conduct adequate audits

  HCDGNALD-J A , HEATHERLY.T L , GUICK, D R Bivision of Project & Resident Programs 82/06/08 6pp 15706 102 24X
  - 1. "Leaking & Dislodged 1-125 5. Materials & Safeguards 66pp 15741.250

> 50-391/82-29 .5704:320 24X

- 8208190238 IE Suiletin B2-03, "Stress Corrosion Cracking in Thick-Wall.Large-Diameter:Stainless Steel:Recirculation Sys Piging at SWR Plants "Syc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edizon Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- 82/0220459 Ack receipt of 820915 ltr informing MRC of steps taken to correct violations noted in IE Insp Repts 50-390/81-26 & 50-391/81-24 VERRELLI.D M Division of Project & Resident Programs 82/10/10 PARRIS.H G Tennessee Valley Authority in (5779 133 24% Fiche 50-390, 82/10/18.8210220459
- --8210220466 Advises that corrective actions per violations noted in 12 Insp Repts 50-390/81-26 & 50-391/81-24 will be completed by 82103 HILLS.L M Tennessee Valley Authority 82/09/15 O'REILLY, J.P. Region 2. Office of Director 10 15779 134 24x Fichs 50-390,82/10/18,8210220459
- 8210290472 Act receipt of 820924 ltr informing NRC of steps taken to correct violations noted in IE losp Repts 50-390/82-18 & 50-391/82-15 VERRELLI, D M Division of Project & Resident Programs 82/10/18 PARRIS, H G Tennessee Valley Authority 1p 15779 102 24% Fiche 50-390, 82/10/18.8210220472
- S Reportable occurrences, LERs & related correspondence
- 8210080168 Sixth interim deficiency tept re qualification of epoxy grout for safety-related applications Initially reported on 820827 Support mods or add supports recommended Drawing revisions in progress Completion expected by mid-May 1983 MILLBILM Tennessee Valley Authority 82/09/23 0'REILLY, J. P. Region 2, Office of Director 3pp 15640 154 24X Fishe 50-390, 82/09/23, 8210080168
- 8210050316 First interim deficiency rept re incorrect insulation weights used in piping analysis Initially reported on 820825 OA document being prepared to substantiate insulation deta Next rept will be submitted by 830423 MILLS.L M Tempessee Valley Authority 82/07/24 O'REILLY.J P Region 2. Office of Birector 2pp 15610 281 24x Fiche 50-390.82/09/24.8210050316
- G210080247 Third & final deficiency repts re resolution of unanticipated vibratory loading concerns Initially reported on B11228 Frogram developed to insure piping sys operate within design parameters Nort rept provided by B21217 MILLS: L Tennessee Valley Authority B2/07/24 O'REILLY, J p Region 2, Office of Director Sap 15638 104 24% Fiche 50-000, B2/09/24, B210080247
- 8210050042 First interim deficiency rept re failure to consider seiseic & inertial loadings on ladders Initially reported on 920824 Ladder, platform or walkway found deficient will be modified or stiffened Next rept expected by 830124 MILLS: L M Tennessee Valley Authority 82/09/27 0'RCILLY. J P Region 2. Office of Director 2pp 15603 236 24x Fiche 50-390,82/09/27.9210050062
- 8210080114 Addl info to final deficiency rept re seismic supports for auxiliary feedwater control valves Initially reported on 800624 Corrective actions on Unit 1 completed 820831 Unit 2 valves will be installed during normal const achequie MILLS.L M Tennessed Valley Authority 82/09/27 0 REILLY, J.P. Region 2, Office of Director 1p 13603 256 24X Fiche 30-390, 82/09/27, 8210050114
- 8210050293 First interim deficiency rept re six sheered motor pinion keys in Limitorque Model 80-0-25 motor operators Initially reported on 820830 Valves w/motor operators being tabulated Next rept will be submitted by 821122 MILLB-L M Tennessee Valley Authority 82/07/28 O'REILLY, J P Region 2. Office of Director 2pp 13409 070 24x Fiche 50-000.82/09/28.8210050293
- 8210080158 Second interim rept re undocumented minor mode to structural & miscellaneous stael Initially reported on 820510 Approx 75% of 250 features had preliminary insp/punchlist completed Next rept to be submitted by 830228 MILLB/L Tennesses Valley Authority, 82/09/29 Q'REILLY, J P Region 2. Office of Director, 2pp 15605 154 24X Fichs 50-390, 82/09/29,8210050158
- 8210040280 First interim deficiency rept re solid-state protection systems procedures Initially reported on 820831 Util reviewing Mestinghouse proposal for interim procedural change which would provide for failure detection Next rept by 821210 MILLEL M Tennessee Valley Authority 82/09/29 0'REILLY.JF Region 2. Office of Director 2pp 15621 164 24X Fiche: 50-390, 82/09/29.8210060280

- 8210060205 Fourth interim deficiency rept re inadequate loading criteria for structural steel 5 supports Initially reported on 81117 General notes revised to clarify drawings Field mapping of platform steel continuing Next rept by 830310 MILLS.L M Tennessee Valley Authority 82/09/30 O'REILLY, J P Region 2. Office of Director 2pp 15614 04: 24% Fiche 50 390.82/09/30,8210060205
- 8210060279 First interim deficiency rept re selection of undersized sway struts initially reported on 820901 Selection methods & adequacy of Bergen-Paterson struts under evaluation Next rept espected by 830225 MICLS L M Tennessee Valley Authority 82/09/30 O'REILLY, J P Region 2. Office of Director 2pp 15621 166 24X Fiche 50 390, 82/09/30, 8210060279
- 02:10080255 First interim deficiency rept re inadequate QA program for masonry block work Initially reported on 820902 Const personnel investigating & replying to audit Next rept due on 82:214
  MILLS.L M Tennassee Valley Authority 82/10/01 D'REILLY, J P
  Region 2. Office of Director 2pp 15608 116 24x
  Fiche 50-390,82/10/01,821080255
- 8210080280 First interim deficiency rept re interpretation of radiograph test film on welded pipe by Swapco Tube Corp Initially reported on 820901 Evaluation continuing Next rep; will be submitted on 830219 MILLS.L M Tennessee Valley Authority 82/10/01 O'REILLY, J P Pagion 2. Office of Director 2pp 15638 201 24% fiche 50-390.82/10/01,8210080280
- E. 10080271 First interim deficiency cept re failure to terminate cables iPSiII. IPSI[2.] PMI850. IPMI852.] PMI857. IPBIS2 & IPSI53 initially reported on 820901 Cables terminated & personnel retrained Next rept will be submitted by 821123 MILG.L M Tennessee Valley Authority 82/10/01 0'REILLY, J.P. Region 2 0ffice of Director 2 Pp 1563H 308 24% Fiche 50-390. 82/10/01.8210080291
- 82:10080160 First interim deficiency rept re corresion in high pressure tire protection sys Initially reported on 820903 Corresion analysis in progress to determine potential deficiencies in safety-related areas Next rept expected by 830531 MILLS-L M Tennessee Valley Authority 82:710/04 0'REILLY, J P Region 2. Office of Director 2pp 15640 142 24X Fiche 50-000, 82:710/04,8210080160
- 6210080310 First interim deficiency rept rellack of piping systamalysis tracking Initially reported on 820902 Util investigating corrective actions to ensure engineering change notices are not closed out until work is completed MILLS-L M Tennessee Valley Authority 82/10/04 0/REILLY, J P Region 2. Office of Director 2pp 15638 042 24% Fiche 50 390.82/10/04.8210080310
- 32:0130247 Sixth interim deficiency rept re differential settlement of rock supported structures Initially reported on 810707 individual safety-related components at interfaces of structures being evaluated Next lept by 830504 MILLS.L.M. Tennesses Valley Authority 82/10/05 O'REILLY, J.P. Region 2. Office of Director 1p. 15676 009 24X Fiche 50-390, 82/10/05 8210130247
- i210130560 Second interim deficiency rept re frequency criteria for piping supports Initially reported on 820713 Investigation continuing Next rept expected by 821220 HILLS, L. M. Tennessee Valley Authority 82/10/05 0'REILLY, J.P. Region 2, Office of Director ip 15683 299 24X Fiche 50-390, 82/10/05, 8210130360
- 210130379 Third interim deficiency rept re incorrect pipe support design by EDS Initially reported on 811119 Util requested EDS to be more thorough in review of isometric models & analysis results Also reportable per Part 21 MILLS.L. M. Tennessee Valley Authority 82/10/06 0'REILLY, J. P. Region 2, Office of Director 2pp 15682:096 24X Fiche 50-390.82/10/06.8210130379
- 210220098 First interim deficiency rept re qualification of process piging w/instrument lines attached Initially reported on 820907 Affected piging being reanalyzed to account for sefect on instrument line piging Next rept by 830427 MILLS:L.M. Tennessee Valley Authority 82/10/08 O'REILLY, J.P. Region 2. Office of Director 2pp 15777, 362 24X Fiche 50-390, 82/10/08, 8210220098
- '10190307 Final deficiency rept re failure to mest pipe support lug criteria Initially reported on 820607 Lug parameter limit discrepancy corrected MILLS.L.M. Tennessee Valley Authority 82/10/12 O'REILLY, J.P. Region 2. Office of Director 2pp 15742 155 24X Fiche 50-370, 82/10/12, 8210190307

- 8210290328 Second interim deficiency rept re use of nonconservative calculational method to evaluate General Const Spec 0-32 spacing violetions Initially reported on 820528 Next rept uill be sent by 830528 MILLS.L.M. Fennessee Valley Authority 82/10/12 0'REILLY.J.P. Region 2. Office of Director 2pp 15853 064 24X Fiche 50-000.82/10/12.8210290328
- 8210270049 Supplemental final deficiency rept re defective 6 9 kV GE circuit breaker Instally reparted on 811218 Repaired breaker not reinstalled by 821001 due to revised delivery date Breaker to be in place by 821231 MILLS.L M Tennessee Valley Authority 82/10/14 D'REILLY, J P Region 2. Office of Director in 15853 335 24X Fiche 50-391,82/10/14,8210270049
- 8210270236 Third interim deficiency rept re potentially overstressed embedded plates Initially reported an 820412 Investigation continuing & const activities deferred until sufficient info gathered to determine completion of project MILES, L.M. Tennesses Valley Authority 82/10/14 0'REJLLY, J.P. Region 2. Office of Director 2pp 15853 229 24X Fiche 50-000,82/10/14,8210270236
- 8210290052 Second interim deficiency rept re use of incorrect response spectra in 0/1bert/Commonwealth piping analysis Instially reported un 820426 Reanalysis continuing Next rapt expected by 820422 Also reportable per Part 21 MILLSIL M Tennessee Valley Authority 82/01/15 0'REJLLY, J P Region 2: Office of Director ip 15853 334 24X Fiche 50-370,82/10/15.8210290052
- 8210270178 Sixth interim deficiency rept re renouting of high pressure fire protection piping Initially reported on 810130 Three areas may contain worst case condition No deficiencies identified in two areas Next rept provided by 821210 MILLS.L M Tennessee Valley Authority 82/10/15 O'REILLY.J P Region 2. Office of Director 1p 15853 311 24X Fiche 50-390, 82/10/15.8210270178
- 8210260320 First interim deficiency rept re addition of locking devices to handwheel operated valves Initially reported on 820916 Const activities deferred Analyses of locking devices continuing Next rept will be sent by 820310 MILLO.L M Tennessee Valley Authority 82/10/18 O'REILLY, J P Region 2. Office of Director 2pp 15802 339 24X Fiche 50-000, 82/10/18, 8210260320
- 8210260451 Fourth interim deficiency rept to failure to include documented piping insulation insps in GC program Initially reported on 811007 Const Spaces N30-881 & N3C-912 revised to provide scope of insp requirements Next rept by 830425 MILLS.L M Tennesses Valley Authority 82/10/18 D'REILLY, J P Region 9. Office of Director 2pp 15807 104 24X Fiche 50-390, 82/10/18, 8210260451
- 8210260186 Second interim deficiency rept re underdesign of essential raw cooling water intake pumping station doors & hatches Initially reported on B20407 Flathead screws added to door frame for reinforcement Next rept expected by B30301 MILLS:L M Tennessee Valley Authority 82/10/19 0'REILLY, J P Region 2, Office of Director 2pp 13/79/034 24X Fiche 50-390, 82/10/19,8210260186
- 8210260370 Eighth interim deficiency rept re improper classification of essential raw cooling water sys piping & components Initially reported on 810324 Investigation ongoing Next rept will be submitted by 830427 MILLS.L M Tennessee Valley Authority 82/10/17 O'REILLY, J P Region 2, Office of Director ip 15803 104 24X Fiche: 50-970, 82/10/17, 8210260370
- 8210260100 Becond interim deficiency rept re lack of seismic analysis on auxiliary bidg platform Initially reported on 820426 Documentation for all attachments to suspect platforms being investigated Next rept expected by 830217 MILLS, L M Tennessee Valley Authority 82/10/20 D'REILLY, J P Region 2. Office of Director 2pp 15799, 122 24X Fiche 50-390, 82/10/20, 8210260100
- 8210240408 Second interim deficiency rept re potentially deficient valve yoke holddown not Initially reported on 820601 Util awaiting Westinghouse resolution for NSSS valves Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 82/10/20 0'REILLY, J P Region 2. Office of Director 2pp 15803 107, 24% Fiche 50-370, 82/10/20, 8210260408
- 8210270266 Fourth interim deficiency rept re failure of Limitorque motor operators during valve closure initially reported on 820126. Hestinghouse. Limitorque & util investigating problem Next rept expected on 830128 Part 21 considered applicable HILLB.L M. Tennessee Valley Authority 82/10/21 0'REILLY, J P Region 2. Office of Director in 15854 046 24X Fiche 50-370.82/10/21,8210270266

- 8210290274 Final rept for Deficiencies B & E & seventh interim rept for Deficiencies A & D re control of procurement activities initially reported on 810316 Final corrective actions noted Next rept sysected by 830428 MILLS.L M Tennessee Valley Authority 82/10/21 O'REILLY, J F Region 2. Office of Director 4pp 15853 (43 24X Fiche 50-000, 82/10/21, 8210290274
- DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 921001000B Responds to FOIA request for 19 categories of documents re nuclear reactor events 2 safety problems Forwards documents Listed to App & FELTON.J M Division of Rules and Records 82/04/28 UDELL.R A Critical Mass Energy Project 15pp 15727 005 24X Fichs 50-000.82/06/28.8210010008
- --8008050265 Discusses add1 required info to better define potential for cracking in reactor vessel noirles
  NDONAN, V S Assistant Director for Materials & Qualifications
  Engineering 80/05/05 TEDESCO.R L Assistant Director for
  Licensing 2pp 13727 176 24X Fichs 50-000.82/06/28,8210010008
- € MRC Safety Evaluation Report (SER), supple & correspondence
- B210050175 Supple B20723 & 0824 ltrs re documentation to illustrate that pressurizer safety valve position indication sys is seismically qualified, per SER, Suppl 4 Info completes responses needed to resolve Licensing Condition 8 & 23C DIXON.OH South Carolina Electric & 6as Co B2/09/29 DENTON.H R Office of Nuclear Reactor Regulation, Director 7pp 15404 117 24X Fiche 50-395, 82/09/29, 821009/29, 821009/29.
- F Security, medical, emergency & fire protection plans
- 9210050324 Documents steps taken to fulfill commitments made in Section 8 | 2 of radiation emergency plan re emergency drills & precises Relief from requirement to hold another full-scale stercise prior to full power operation requested DIYON.O N South Carolina Electric & Gas Co 82/09/23 DENTUN.H R Office of Nuclear Reactor Regulation. Director 6pp (5508-215-24X Fiche 50-395.82/09/23.8210050324
- B210050242 Notifies that full scale emergency drill will not be conducted until Mar 1983 due to unavailability of FEMA personnel.per B20923 commitment DIYON.O W. South Carolina Electric & Gas Co. 82/09/29 DENTON.H R Dffice of Nuclear Reactor Regulation, Director 1p. (5619-321 24X Fiche 50-395.82/09/29.8210060242
- 9210060248 Ack receipt of 920929 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-395/82-45
  LEWIS.R C Division of Project & Resident Programs 82/10/06
  DIXON, O W South Carolina Electric & Gas Co ip 15638 098 24X
  Fiche 90-395/82/10/06/8210080248
- --8210080250 Responds to NRC 820831 ltr re violations noted in IE Safeguards Insp Rept 50-395/82-45 Corrective actions withheld (ref 10CFR73 21) DIXON.O N South Carolina Electric & Gas Co 82/09/29 O'REILLY, J P Region 2. Office of Director 2pp 15638 099 24) Fiche 50-395,82/10/04.8210080248
- --9210080254 Forwards IE Safeguards Insp Rept 30-395/82-45 on 820806 & notice of violation Notice of violation withheld (ref 10CFR73 21)

  LEMIS.R C Division of Project & Resident Programs 82/08/31 DIXON, OW South Carolina Electric & Gas Co 2pp 19638, 101 24% Fiche 50-395, 82/10/26, 8210080248

- 8210250312 Confirmatory action ltr re 821007 discussions at site concerning volumerability of security computer sys noted during 821004-08 insp Enc) withheld (ref 10CFR73 21) KEPPLER, J.G. Region 3, Office of Director 82/10/18 DDLAN, J.E. American Electric Power Service Corp. DDLAN, J.E. Indiana & Michigan Electric Co. 2pp. 15790 189 24% Fiche 50-395,82/10/18,8210250162
- B210260172 Provides current completion schedule for installation of fire barriers & detectors Fire barriers will be installed by B21115 & fire detectors by end of first quarter 1983 D1XON.O W South Carolina Electric & Gas Co B2/10/21 BENION H & Office of Nuclear Reactor Regulation. Director 1p 15797 049 24X Fiche 50-395.82/10/21.8210260172
- 8210260157 Application to amend License NPF-12 in response to General Ltr 82-17. Changing Tech Specs re emergency plan implementing procedures audits DIXON.O W South Carolina Electric & Gas Co 82/10/22 DENION.N M Office of Nuclear Reactor Regulation. Director 1p 15799 008 24/ Fiche 50-395-82/10/22, 8210260159
- --8210260166 Proposed Fech Spec changes re frequency of emergency plan & implementing procedures audits + South Carolina Electric & Gas Co GP/10/22 ip 15799 007 24% Fiche 50 395.82/10/22,8210260159
- G Adjudicatory correspondence
- 9210150458 Second suppl to motion to reapen record for reconsideration of motion for stay, allowed per ABLB B20924 memorandum \*\* order Bids for stay met CM Anderson engineering rept recontainment cadwelds encl BURSEY.B Bursey, B 62/10/07 Atomic Safety and Licensing Board Panel 23pp 15705 006 24% Fiche 50 375.82/10/07.8210150458
- 8210150217 Memorandum confirming ruling at 821008 telcon denying intervenor 821007 motion for reconsideration of ASLB denial of motion to stay implementation of initial decision authorizing issuance of full-term CL GROBBHAN.H Atomic Safety and Cicensing Board Panel 82/10/1. 3pp 15705 280 24X Fiche 50-395.82/10/12.8210150217
- 8210250229 Memorandum & order denying B Dursey motion to reopen record on cadwelding Intervenor Pailed to systain burdem of demonstrating existence of genuine issue of safety significance NRC investigation rept to be placed in LPDR GROSSMAN, H. Atomic Safety and Licensing Board Panel 82/10/2/ BURSEY, B. Bursey, D. Spp. 15789 331 24% Fiche 50-395,82/10/22,8210250229
- H Ceneral correspondence
- 8210210443 Expresses concern w/allegations of compromised const.Ri. stds for cadwelds & inadequacy of response to allegations Hearings should be reopened to examine & refute allegations before granting further facility licenses BASB. J. Affiliation Unknown 82/10/12 OROBBMAN.H. Atomic Safet and Licensing Board Fanel. 3pp. 15763-073-24X Fiche 50-395.82/10/12.8210210443
- P Operating license stage documents & correspondence
- 9210090307 Summary of 820915 meeting w/util & Dames & Moore in Bethesda: MD re confirmatory seismic analysis program Licensee must provide program & schedule for resolving License Condition 25 & ACRS commitment KANE. HF Licensing Branch | 82/09/24 Licensing Branch | 6pp | 15663 332 | 24X Fiche 50-395,82/09/24.8210080309
- 8210050210 Advises that Westinghouse performed stress evaluation of main reactor coolant loop apping withermal sleeves removed Noziles qualified to withstand all applicable design transients
  DIXON,D W. South Carolina Electric & Qas Co. 82/09/29 DENTON.N. Office of Nuclear Reactor Regulation, Director. 3pp. 15611 260 24X Fishe 50-395,82/09/29,8210050210
- 8210080276 Requests resolution of provision to remove & reinstall USG SMA-1 per 820924 ltr re confirmatory program for pad test CLARK,N E , WHORTON.R B South Carolina Electric & Gas Co 82/10/01 JACKBON.R NRC No Detailed Affiliation Oliven 2pp 1963B 300 24% Fiche 50-395,82/10/01,8210080276
- 8210120248 Forwards proprietary & nonproprietary versions of "Interia Power Operation Evaluation Rept " Proprietary version withheld (ref 10CFR2 790) DIXON.O H Bouth Carolina Electric & Gas Co. 82/10/04 DENTON.H Office of Nuclear Reactor Regulation. Director 9pp 15456 055 24X Fiche. 50-395, 82/10/04.8210120248

- --8210120250 Nonproprietary version of "Interim Power Operation Evaluation Rest
  - Evaluation Rept 4 Hestinghouse Electric Corp 02/09/30 15pp 15656-064 24X Ficks 50-395,82/10/04.8210120248
- 82(0)80156 Application to amend License NPF-12 changing Tech Specs re thermal design flow fire detection instruments &
  - thermal design flow-rise detection instruments a overpressure protection sys DIYON.O W South Carolina Electric & Gas Co 82/10/08 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 15719 170 24x Fiche 50-395, 82/10/08. 0210180156
- 8210180162 Proposed Tech Spec changes re thermal design flow, fire detection instruments? averpressure protection sys
   South Carolina Electric & Gas Co 62/10/08 54pp 15719 173 24% Fiche 50-395, 82/10/08, 8210180156
- E.10190352 Forwards Technical Rept B2-1, "Seismic Activity Near VC Surmer Nuclear Station Jan-Mar 1982" & "Geological Studies in Area of Induced Seismicity at Monticello Reservoir, BC, " fourth technical rept
- DI(ON, O W South Carolina Electric & Gas Co 82/10/12 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 15735 079 24x Fiche 50-395 82/10/12,8910190392
- --B210190444 "Seismic Activity Near VC Summer Nuclear Station. Jan-Mar 1982: Technical Rept B2-1 TALWANI F Bouth Carolina, Univ of B2-1 B2/03/31 17pp 15735 030 24x Fiche 50-395,82/10/12,8210190352
  - 8210197457 "Geologic Studies in Area of Induced Seismicity at Monticella Reservoir.SC." fourth technical rept Thirteen oversize figures enci Aperture cards are available in PDR SECOR D T. PITCHER.D M., PECK L S. South Carolina Electric & Gas Co. 82706730 153pp. 15735-048 24X Fiche 50-375,82710712,8210190352
- 9210190505 Forwards cover iti inadvertently omitted from 921004 submittal of interim power operation evaluation rept pl(QN,O W South Carolina Electric & Gas Co 92/10/12 DENTON.H N Office of Nuclear Realtor Regulation. Director ip 15795-310 24x Fiche 50-395 82/10/12 82(0)90505
- -02-1017050B Forwards affidavit requesting interim power operation evaluation rept be withheld (ref 10CFR2 790) WIESEMANN.R A Westinghouse Clectric COTP 02/09/30 DENION.H R Office of Nuclear Reactor Regulation, Director 0pp 157.35 011 24x Fiche 50-395.02/10/12,0210190505
- 8210190553 Responds to Generic Ltr 82-16 re NUREG-0737 Tech Specs All TMI items discussed in Encl 1 of generic Iti implemented DI(CH), O W South Carolina Flectric C Gas Co 82/10/12 DENION, H R Orfice of Nuclear Resutor Regulation. Director 1p 15735 013 24x Fiche 50-395,82/10/12 8210(9055)
- 8210190492 Forwards "Independent Design Verification Turbine Driven Portion Emergency Feedwater Sys." final rept DUNIOP,P Stone & Webster Engineering Corp 02/10/15 DENTON,H R Office of Nuclear Reactor Regulation, Director ip 16030 245 24x Fiche 50 395,82/10/15,8210190492
- 11210190500 "Independent Seismic Design Verification Turbine Driven Portion Emergency Feedwater Sys." final rept One overbize drawing enci Aperture card is available in PDR # Stone & Webster Engineering Corp 82/10/15 105pp 16030 046 24X Fiche 50-395.82/10/15,8210190492
- 82[0190513 Forwards response to questions re DG O'Brien, Inc Qualification Rept ER-307 for briarial plugs for containment penetrations Cable failure not result of plug design or configuration since plug passed test when encl in conduit DI/QN/D W South Carolina Electric & Oas Co BZ/10/15 DENTON, HR Office of Nuclear Reactor Regulation. Director 15pp 15737 224 24% Fiche 50-395,82/10/15,8210190513
- 6210250330 Application for amend to License NPF-12, providing acceptable tolerances to be used in procurement of sample gases used for callbr of associated instruments & parmitting entry into Mode 2 on 821020

  DI (OH, D W South Carolina Electric & Gas Co 82/10/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p (5790 004 244 Fiche 50-395,82/10/19 8210250330
- --B210250339 Proposed Tech Specs providing acceptable telerances to be used in procurement of sample gases used for callbr of associated instruments & permitting entry into Mode 2 on B21020
  - # South Carolina Electric & Gas Co 82/10/19 4pp 15790 005 24X Fiche 50-395,82/10/19,8210250330

- 82(0260140 Request for temporary relief from Tach Spec requirements re containment hydrogen monitors in order to allow entry into Mode 2 under action statement for initial criticality Relief will prohibit delay of initial criticality DIXON.O W South Carolina Electric & Gas Co 82/10/20 DENTON.H R Office of Nuclear Reactor Regulation, Director ip 15797 091 24X Fiche 50-395.82/10/20.8210260140
- 8210260157 Application to amend License NPF-12 in response to Generic Ltr 82-17, changing Tech Specs re emergency plan implementing procedures audits
  DIXON, O W South Carolina Electric & Gas Co 82/10/22 DENTON, H R
  Office of Nuclear Reactor Regulation, Director ip 15797 008
  24% Fiche 50-395,82/10/22,8210260159
- --8210260166 Proposed Tech Spec changes re frequency of emergency plan & implementing procedures audits + South Carolina Etectric & Gas Co 62/10/22 ip 15799 009 24% Fiche 50-375,82/10/22.8210260159
- O Inspection reports, IE Bulletins & correspondence
- 8210010167 Revises 810707 & 1116 responses to 1E Bulletin 81-02;
  "Failure of Oate Type Valves to Close Against Differential
  Pressure " Valve 81300 in Table I to 81116 let not modified
  since valve net functional requirements as configured
  DIXON, D W South Carolina Electric & Gas Co 82/09/08
  O'REILLV.J P Region 2. Office of Director 2pp 15567 277 24X
  Fiche 50-395,82/09/08,8210010167
- B2(0010466 Forwards IE Insp Rept 50-395/82-41 on B20701-0B13 No nancompliance noted DANCE,H C Division of Project & Resident Programs 82/09/08 D)(ON,D W South Carolina Electric & Oas Co 2pp 15972 153 24% Fiche 50-395, B2/09/08, 82(0010466
- --8210010469 IE Insp Rept 50-395/82-41 on 820701-0813 No noncompliance noted Major areas inspected plant tour, open item review. TMI action plan item review & surveillance test procedures performance SKOLDS. J. L. BROWNLEE, V. L. Division of Project & Resident Programs 82/09/08 (1pp 15572 155 24% Fiche 50-395,82/09/08,8210010466
- 8210010467 Forwards IE Insp Rept 50-395/82-47 on 820806-07.12 & 13 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/09/09 DIXON, D W South Carolina Electric & Cas Co 2pp 15572, 165 24X Fiche 50-395, 82/09/09. 8210010467
- --8210010472 IE Insp Rept 50-395/82-47 on 820806-07.12 & 13 No noncompliance noted Major areas (aspected initial fuel loading BURNETT, P T , JAPE, F Division of Engineering & Technical Programs 82/09/02 3pp 15572 169 24X Fiche 50-395,82/09/09,8210010467
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COSB:L ! Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24/
- 8210080248 Ack receipt of 820929 itr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-399/82-45.

  LEMISH R C Division of Project & Resident Programs 82/10/06 DIXON, 0 W South Carolina Electric & Gas Co ip 15438 078 24) Fiche 50-399, 82/10/06.8210080248
- --8210080250 Responds to NRC 820831 ltr reviolations noted in IE Bafeguards Insp. Rept 50-395/82-45 Corrective actions withheld (ref 100FR73 21) DIXON.O W South Carolina Electric & Gas Co 82/07/29 O'REILLY, J. P. Rejon 2, Office of Director 2pp 15638 099 24X Fiche 50-395,82/10/06.8210080248
- --8210080254 Forwards IE Safeguards Insp Rept 50-395/82-45 on 820806 & notice of violatian Notice of violation withheld (ref 10CFR73 21)

  LEMIB.R C. Division of Project & Resident Programs 82/08/31
  DIXON, U South Carolina Electric & Gas Co 2pp 15638 101-24X Fiche 50-395.82/10/06.8210080248
- --8210080259 IE Safeguards Insp Rept 50-395/82-45 on 820806 Noncompliance noted failure to control designated vehicles Details withheld (ref 10CRR73 21) SKOLD8, J L , MCOUIRE, D R Division of Engineering & Technical Programs. 82/08/26 ip 15638 103 24X Fiche 50-395,82/10/06,8210080248

p

- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall.Large-Diameter.Stainless Steel.Recirculation Sys Piping at BMR Plants " Svc list enc! DEYGUNG,R C Director's Office. Office of Inspection and Enrorcement 82/10/14 Consolidated Ediston Co of New York 115pp 15810 125 24x Fiche 50-000.82/10/144.8208190238
- 8210250312 Confirmatory action ltr re 821007 discussions at site concerning vulnerability of security computer sys noted during 821004-08 insp Encl withheld (ref 10CFR73 21) KEPLER, J G Region 3, Office of Director 82/10/18 DDLAN, J E American Electric Power Service Corp BDLAN, J E Indiana & Michigan Electric Co 2pp 15790 189 24X Fiche 50-395, 82/10/18, 8210250312
- 5 Reportable occurrences. LERs & related correspondence
- 8210010348 Final significant deficiency rept re penetration gap requirements of safety-related piping sys initially reported on 820726 Mods to piping penetrations for insulation &/or sealing handled through field change request program DIXON.O W South Carolina Electric & Gas Co 82/09/22 O'REILLY.J P Region 2. Office of Director 2pp 15573 103 24% Fiche 50-395, 82/09/22 8210010348
- 8210220340 Forwards LER 82-005/03L-0 Detailed event analysis encl DIXON.O W South Carolina Electric & Gas Co 82/10/15 O'REILLY.J P Region 2. Office of Director 3pg 15776 261 24X Fishe 50-395.89210/15.8210220340
- --8210220346 LER 82-005/03L-0 on 820916, five smoke detectors at 400-ft & 412-ft elevations of control bldg disabled, rendering preaction sprinkler sqs automatic actuation capability inoperable Caused by need to perform welding in 400-ft area KOON.A R South Carolina Electric & Gas Co 82/10/15 Region 2, Office of Director 1p 15776 264 24X Fiche 50-395, 82/10/15, 82/2020740
- 8210220438 Forwards LER 82-004/03L-0 Detailed event analysis encl DIXON.0 W South Carolina Electric & Gas Co 82/10/15 O'REILLY, J P Region 2, Office of Director 4pp 15778 258 24X Fiche 50-395, 82/10/15, 82/0220438
- --8210220443 LER 82-004/03L-0 on 820915, test signal generated causing B train RHR header isolation valve to shut & isolate suction Pump manually tripped Surveillance test procedure revised to line up alternate RHR train w/valve locked out FIELDS.C South Carolina Electric & Cas Co 82/10/15 Region 2, Office of Director ip 15778 262 24X Fiche 50-395,82/10/15,821020438
- 8210270284 Forwards LER 82-006/03L-0 Detailed event analysis encl DIXON.O W South Carolina Electric & Gas Co 82/10/21 O'REILLY, J P Region 2, Office of Director 3pp 15853 136 24X Fishe 50-395,82/10/21,8210290284
- --8210270286 LER 82-006/03L-0 on 820922, several high range monitors failed high Caused by moisture accumulation in detector preamp connections Plant completed initial fuel load but was not critical. Monitors replaced except RM-G179 FIELDS, C South Carolina Electric & Gas Co 82/10/21 Region 2. Dffice of Director ip 15853 137 24X Fiche 50-395.82/10/21, 8210290284
- 8210290335 Forwards LER 82-007/03L-0 Detailed event analysis encl DIXON 0 W South Carolina Electric & Gas Co 82/10/21 TLYJ P Region 2. Office of Director 4pp 15853 035 24X 70-395, 82/10/21, 8210290335

- DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- 8210070141 Forwards "MA Nuclear Project 2 Environ Equipment Qualification Rept for Safety-Related Equipment," Vols 1,2 & 3, in response to NRC 800221 Itr Rept will be incorporated into FSAR ampnd BOUCHEY, 0 D Washington Public Power Supply System 82/09/18CHMENCER, A Licensing Branch 2 Ip 15630 360 244 Fiche 50-397, 82/09/15, 8210070141
- B210130188 Advises that manual block valve CAS-VX-82e will be utilized as containment isolation valve in lieu of relocating check valve on air line to inside containment Change will be incorporated in future FSAR amend BUUCHEY, 0 D. Hashington Public Power Supply System B2/09/20 SCHHENCER.A Licensing Branch 2 2pp 15674 114 24X Fichs 50-397, 82/09/20, 8210130188
- B210040223 Forwards corrections & clarifications to Amend 23 to FSAR Section 8 3 re-onsite power sys Next FSAR amend will be revised to include encl corrections
  BOUCHEV.C D. Hashington Public Power Supply System 82/09/22
  SCHMENCER.A. Licensing Branch 2 68pp 15620 117 24X
  Fiche 50-397.82/09/22.8210060223
- 8210080068 Forwards NRC position paper closing out Licensing Review Group II channel box deflection issue SCHMENCER. A Licensing Branch 2 82/09/22 FCRGUSON, R L Washington Public Power Supply System Spp 15647 355 24X Fiche 50-297. 82/09/22,8210080068
- 8210050348 Forwards final response to 820708 concerns re adequacy of design margins of Mark II containment sys Issues raised by QE do not represent significant safety concerns for facility
  80UCHEY.O D Washington Public Power Supply System 82/09/24
  8CHWENCER.A Licensing Branch 2 10pp 15610 104 24X
  Fiche 50-397.82/09/24,8210050348
- 8210290227 Notification of 821006 meeting w/util in Bethesda.MB to discuss cable separation criteria concerns AULUCK.R Licensing Branch 2 82/09/27 BCHWENCER, A Licensing Branch 2 3pp 15876 326 24% Fiche 50-397, 82/09/27, 8210290227
- 8210040255 Forwards add1 info re organizational changes in preparation for ACRB 821004 meeting Formal revisions to FSAR & operational QA program description will be submitted upon completion GUCHEY, 0 D Washington Public Power Supply System 62/09/28 SCHWENCER, A Licensing Dranch 2 ip 15595 009 24% Fiche 50-397, 82/09/28, 8210040255
- 8210190764 Forwards update to pump & valve inservice test program planper util 820708 ltr W/2i oversite drawings Aperture cards are available in PDR BOUCHEV.0 D Washington Public Power Bupply System 82/10/07 SCHWENCER.A Licensing Branch 2 ip 15799 161 24X Fiche 50-397.82/10/07.8210190764
- ~~8210260113 Revision | to "Pump & Valve Inservice Test Program Plan"
  HOYLE.T. RENBERGER.D. MARTIN.J. Washington Public Power Supply
  System 82/08/28 157pp 15779 162 24% Fiche 50-397.82/10/07.
- 8210290446 Staff requirements memo re 821007 affirmation/discussion & vote on extension of const completion dates for MPPSS, purging of classified mat! in ALAB-453 & emergency preparedness & risks associated offul loading CHILK: 8 J Office of the Secretary of the Commission 82/10/08 Office of the Secretary of the Commission 2pp 15863, 188 24% Fiche 50-000, 82/10/08, 8210290446
- B210210327 Confirms B21005 telcon re use of ABME Code Case N-310-1, "Certification of Bolting Matia Section III, Div J. Class 1, 2,9:MC \$ CS " Util will implement code case as agreed BOUCHEY. O D Washington Public Power Supply System B2/10/11 BCHMENCER. A. Licensing Branch 2 2pp 19764 216 24X Fiche 50-397, 82/10/11, 8210210327
- 8210270072 Notification of 821110 meeting w/util in Bethesda.MD to discuss adequacy of GA program in light of recent deficiencies disclosed at several plants AULUCK R Licensing Branch 2 82/10/19 SCHWENCER.A Licensing Branch 2 3pp 13836 293. 24X Fichs 50-397.82/10/19.8210270072

- 6210260442 Requests representation at Mar 1983 environ site visit & at 830502 question & answer period LENIS.M D Washington, State of 82/10/20 WHEELER, L NRC No Detailed Affiliation Given 1p 15806 153 24X Fiche 50-397, 82/10/20, 8210260442
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 6210060319 Commits to implementing mod of control logic on pressure interlocks of low pressure ECCS injection valves by fuel load Commitment dependent on timely equipment delivery Info closes SER Outstanding Issue 1 7(8)
  BNUCHEY, & D. Washington Public Power Supply System 62/09/28
  SCHWENCER.A Licensing Branch 2 2pp 15619 013 24X
  Fiche 50-397, 62/09/28, 6210060319
- 6210090124 Requests revision to Suppl 2 of BER.NUREG-0892, Sections 4 2 3 2(7), 4 2 3 3(1) & 4 2 3 3(3) to indicate resolution of cladding rupture concern & to reflect that PCT margin is not required BBUCHEY 6 D. Washington Public Power Supply System 82/09/30 SCHWENCER.A Licensing Branch 2 1p 15405 041 24X Fiche 50~397, 62/09/30, 8210050124
- 8210050156 Forwards marked-up correct Table 1 2 of SER (NUREO-0892) re comparison of facility principal design features to similar facilities.per ACRS Subcommittee on INNP-2 meeting BOUCHEY.O D Mashington Public Power Supply System 82/09/30 SCHMENGER.A Licensing Branch 2 3pp 15605-156 24X Fiche 50-397, 82/09/30.8210050156
- 6210190574 Forwards supplemental response to NUREQ-0612, "Control of Heavy Loads." Revision 1 to close out SER Outstanding Issue 30 80UCHEY. 6 0 Mashington Public Power Supply System 82/10/04 SCHWENCER. A Licensing Branch 2 22pp 15736 005 24X Fiche 50-397. 82/10/04.8210190576
  - 2210190582 "Reactor Vessel Head Removal & Replacemont" + Washington Public Pour Supply System 61/12/17 16pp 15736 030 24X Fiche 50-397, 62/10/04/8210190576
- ELICZIGO49 Forwards recommendations on proposed plant operating procedure changes, equipment mods & discussion of design basis ashfall Advance warning alrangements in Section II A rolfill commitment per supplemental SER Section 25 i 3 i BOUCHEY, O D Washington Public Power Supply System 82/10/0-SCHMENGER, A Licensing Branch 2 4pp 15745-345 24X Fiche 50-397, 82/10/4,82/102/0049
- 6210210148 Informs that hydrostatic test of diesel engine auxiliary piping to 125% of design pressure performed in response to supplamental SER Item 9 S 4 1, Open Item 15 & FSAR Question 040 084 Exemption requested for intake 5 exhaust lines SBUCHEY. C D Hashington Public Power Supply System 82/10/04 SCHMENCER. A Licensing Branch 2 3pp 15764 087 24X Fiche 50~397. 82/10/04/8210210148
- 8210210276 Advises that Section 14 2 14 3 17 will be amended to remove any left to containment bot pipe penetration testing SER Outstanding lasue 21 (NREG-0872) closed w/o need for acceptance criteria Diagrams repenetration assembly encl SOUCHEY. O D Washington Public Power Supply System 82/10/04 SCHWENGER. A Licensing Branch 2 6pp 15766 124 24X Fiche 50-397. 82/10/04.8210210276
- F Security, medical, emergency & fire protection plans
- 9210060445 Forwards "One-Hour ASTM Ell9 Fire Simulation Facility Fire Tests Water Hose Stream Impact Tests & Electrical Circuitry Continuity Tests on Nuclear Facility Class IE Cable Trays & Conduit Test "Rept withheld (ref 10CFR2 790) UDUCHEY, G D Washington Public Power Supply System 82/09/20 SCHMENCER, A Licensing Branch 2 3pp 15615 001 24X Fiche 50-397, G2/09/20, 8210060445
- 8210130194 Submits addl info to suppl test rept data in util 820802 & 0920 ltrs to NRC re Thermo-Lag 330-1, subliming coating envelope sys (ITL Rept 82-5-355A) for fire protection of cable raceway sys discussed in App R BOUCHEY. O D Washington Public Power Supply System 82/10/04 SCHWENCER, A Licensing Branch 2 4pp 15674 [4] 24X Fiche 50-397. 82/10/04.8210130194

- 821021004? Forwards recommendations on proposed plant operating procedure changes equipment mods & discussion of design basis ashfall Advance warning arrangements in Section II A rulfill commitment per supplemental SER Section 2.5 i 3 i 30UCHEY.0 D Washington Public Power Supply System 82/10/04 SCHWERGER, A Licensing Branch 2 App 15765 345 24X Fiche 50-397, 82/10/04,8210210049
- 8210190708 Forwards Test Rept 82-5-3558, "Three-Hour Fire Endurance Tests on Thermo-Lag 330-1 Subliming Coating Envelope Sys for WPPSS Nuclear Projects" (Va encl BOUCHEY.C D Mashington Public Power Supply System 82/10/05 SCHWENCER.A Liconaing Branch 2 3pp 19736 151 24X Fiche 50-397, 82/10/05.8210190708
- 82t0130575 Notifies of meeting w/Yakima Indian Nation tentatively scheduled on 82t022 to discuss emergency plan coordination. In response to NRC 820914 request GUUCHEY.0 D Hashington Public Power Supply System 82/10/06 SCHWENCER.A Licensing Dranch 2 ip 15679 108 24X Fische 50-397, 82/10/06,8210130575
- G Adjudicatory correspondence
- 8210130336 Order CLI-82-27, referring Coalition for Safe Power petitions for hearing to ASLB ABLB chairman should appoint ASLB to determine whether 10Cr82 714 requirements met & to conduct required hearing Wiseparate views of Commissioner Glinsky CHILK, S.J. Office of the Secretary of the Commission 82/10/08 21pp 15681 350 24X Fichs 50-397, B2/10/08,8210130336
- 6210200056 Notice of ASLB constitution H Grossman.chairman & EE Hill & LW Little.members
  COTTER.B P Atomic Safety and Licensing Board Panel 62/10/14
  2pp 15755 027 24X Fiche 50~397, 82/10/14.8210200056
- 0210180147 Lists changes to be made in Commission 821008 Order. CLI-82-29 STUCKY.8 W Docketing & Services Branch 82/10/19 Office of the Executive Legal Director Ip 15719 266 24X Fiche 50-397, 82/10/15.8210180147
- 8210290315 Notice of ASLB reconstitution H Grossmen, chairman & OD Bright & J Harbour, members LAZO,R M Atomic Safety and Licensing Board Panel 82/10/25 2pp 15893 078 24X Fiche 50-397,82/10/25,8210290315
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8210080075 Forwards Amend 26 to FBAR
  BDUCHEY.0 D Washington Public Fower Supply System 82/09/28
  SCHWENCER.A Licensing Branch 2 2pp 15640 338 24x
  Fiche 50-597. 82/09/28.8210080095
- --8210080100 Amend 2A to FSAR

  + Washington Public Power Supply System 82/07/31, 757pp
  15640 339 24X Fiche 50-397, 82/09/28, 8210080095
- 8210210045 Forwards transmittal ltr % Certificate of 8vc for Amend 26 to FSAR 4/0 transmittal ltr 8DUCHEY, 0 D Washington Public Power Supply System 82/10/05 SCHWENCER, A Licensing Branch 2 2pp 15765-352 24x Fiche 50-397, 82/10/05, 8210210045
- Q Inspection reports: IE Bulletins & correspondence
- 8210080195 Forwards revised corrective actions to NRC notice of violations 79-10/01,79-10/03,80-09/09 & 80-08/22 noted in IE Insp Rept 50-397/61-22 All future liquid penetrant exams will be performed by Dechtel approved subcontractor MATLOCK.R O Washington Public Power Supply System 82/04/16 ENGELERIN,R H. Region 5, Office of Director 3pp 15640 190 24X Fiche.50-397,82/04/16,8210080195.
- 8210190646 Provides additinfoire preservice inspiprogram plan for scram discharge sys per 820812 telcon Boundary diagram for control rod drive sys encl BOUCHEY, O D Washington Public Power Supply System 82/09/22 SCHWENCER, A Licensing Branch 2 Spp 15739 101 24% Fiche 50-397, 82/09/22,8210190646
- 8210190366 Forwards IE Insp Rept 50-397/82-18 on 820816-31 No noncompliance noted STERNGERO,D M Division of Resident, Reactor Project & Engineering Programs 82/09/28 MATLOCK,R Q Washington Public Power Supply System 2pp 15741.166 24X Fiche 80-397/82/09/28/8210190366

- --8210190348 IE Insp Rept 50-397/82-18 on 820816-31 No noncompliance noted Major areas inspected reactor pressure vessel noted Major areas inspected reactor pressure vessel highrotest mechanical contractor records review program & corrective activities & work reverification program TOTH.A D. DODDS.R T Division of Resident. Reactor Project & Engineering Programs 82/09/27 14pp 15741 168 24X Fiche 50-397,82/09/28,8210190366
- 8210190562 Forwards IE Insp Rept 50-397/82-22 on 820830-0903 No nencompliance noted STERNBERG.D M Div Division of Resident, Reactor Project & Engineering Programs 82/09/28 MATLGCK, R G Hashington Public Power Sup System 2pp 15735 126 24x Fiche 50-397, 82/09/28, 8210190562
- --8210190569 IE Insp Rept 50-397/82-22 on 820830-0903 No noncompliance noted Major areas inspected facility organization, preoperational testing operational GA program & independent 1050 insp WillETT,D J , DDDDS.R Division of Resident, Reactor Project & Engineering Programs 82/09/27 Spp 15736-130 24% Fiche 50-397,82/09/28,8210190562
- 8260190465 Forwards IE Insp Rept 50-397/82-17 on 820726-30,0809-13 & 210140003 Pormands to Insp Rept 30-47/762-17 on 8/67/28-30, 0809-13 & 0830-0903 No noncompliance noted STERNOERO.D M Division of Resident, Reactor Project & Engineering Programs 82/10/01 MATLOCK.R & Washington Public Power Supply System 2pp 19737 256 24X Fiche 50-397/82/10/01/8210190665 STERMOLIS Programs 82 Prottom 200
- Project & Engineering Programs 82/09/30 9pp (5737-258 Fiche 50-397,82/10/01.8210190665
- 8210070279 Ack receipt of 820831 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-397/82-14 STERNBERG, D H Division of Resident, Reactor Project & Engineering Progrems 82/10/04 MAZUR, D W Washington Publis Power Supply System 1p 15634 236 24% Fiche 50-397, 82/10/04,8210070297
- --8210070302 Responds to NRC 820802 ltr re violations noted in It Insp Rept 50-397/82-14 Corrective actions Dechtel procedures reviewed to ensure that AE approvals obtained & GC Administrative Instruction 15 issued MATLOCK, R O Washington Public Power Supply System 82/08/31 STERNBERO.D M Division of Resident. Reactor Project & Engineering Programs 6pp 15634 239 24X Fiche 50-397,82/10/04,8210070299
- 8208190233 IE Info Notice 80-35. Suppl 1: "Leaking & Distanged 1-125 Implant Seeds "Syc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 64pp 1576 24% Fiche 50-000.82/10/06.8208170233 15761 250
- 8210280241 Forwards IE Insp Repts 50-397/82-20 & 30-13720/82-01 on 820831-0903 & notice of violation BOOK-H E Division of Radiological Safety & Safeguerds Program 82/10/12 MATLOCK-R O Mashington Public Power Supply System 2pp 15837 325 24X Fichs 50-397, 82/10/12, 8210280241
- --B210280244 Notice of violation from insp on B20831-0903 WENSLAWSKI, F A Division of Radiological Safety & Safeguards Fragram 82/10/12 ip 15837 327 24% Fiche: 50-397, 82/10/12,
- --8210280248 IE Insp Repts 50-397/82-20 & 30-13720/82-01 on 820831-0903 Noncompliance noted receipt of radioactive math not award to the second of the second

- 8210080304 Interim deficiency rept to improper installation of concrete erpansion anchors & unacceptable concrete & grout work Initially reported on 820403 Corrective actions continuing Next rept will be submitted on B21218 MATLOCK: R G Washington Public Power Supply System 82/09/28 ENGELKEN, R H Region 5. Office of Director Dpp (5638-325-24x Fiche 50-397: 82/09/28, 8210880304
- 82(0130217 Final deficiency rept re high resistance cable grounding of 4 kV diesel generators initially reported on 820506 Manufacturers advised that equipment can operate for indefinite period w/line-to-ground fault w/o damage MATLOCK R O Washington Public Power Supply System 82/09/20 EMGELERIA R Region 5. Office of Director 3pp 15675 240 21K Fiche 50-397,82/09/28.6210130217
- 6210080275 Final deficiency rept re 4 la kV breakers DG (-7 % DG 2 h 2 interim deficiency rept re emergency diesel generators DG-1 & DG-2 airstart circuits Initially reported on 820870 % 0708 respectively Next rept will be submitted by 821220 MATLOCK.R G Washington Public Power Supply System 82/09/30 ENGELKBUR H Region 5 Office of Director 3pp 15638 302 Dic Fiche 50-397,82/09/30,8210080275
- DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1 A Application/construction stage documents & currespondence
- B210130033 Summary of 820816-19 meeting w/util.Ebasco & Westinghouse re design review of instrumentation & control sys for racilities Followup meeting scheduled for 820914-16 in New York City, NY LICITRA.E A Licensing Branch 3 82/09/08 Licens Spp 15696 272 24X Fiche 50-400.82/09/08.8210(30053 Licensing Branch 9
- 8210010051 Ack receipt of 820823 1th requesting temporary relief from commitments retraining of shift technical advisors Program approved & request forwarded to NRR for evaluation O'REILLY, J P Region 2, Office of Director 82/09/20 JG Carolina Power & Light Co ip 15565 322 24X 82/09/20 JONES J A Fiche 50-000, 82/09/20, 8210010051
- 6210270324 Requests add1 info re instrumentation & control sys Info should be in form of response to IE Bulletin 79-21 re level measurement errors due to environ temp effects on level instrument ref legs Requests submittal date within 2 wks KERRIGAN-J D Licensing Branch 3 62/09/23 JONES, J.A. Carolin Power & Light Co. 2pp. 15836-357 24X Fiche 50-400.82/09/23, 8210270324
- 8210210035 Forwards request for addl info on FSAR Section 440-0. "Reactor Sys "

  KERRIOAN: J Licensing Branch 3 82/09/29 JONES, J A Carolina
  Power & Light Co 9pp 15773 262 24X Fiche 50-400,82/09/29. 8210210035
- 8210210258 Notification of 821012 meeting w/util & Ebasco in Bethrsis. MD to discuss review of RCPB matls
  KADAMBIN P Licensing franch 3 82/09/29 KERRIGAN J Licensing a
  Branch 3 3pp 15774 324 24% Fiche 50-400.82/09/29.8210210258
- 8210210320 Summary of 620914-16 meetings w/util.Westinghouse & blasco at Ebasco of the design review of instrumentation & control sys Attendance list encl. LICITERA. E.A. Licensing Branch 3 82/09/29 Licensing Branch 3 4pp 15782 087 24% Fiche 50-400.82/09/29, 8210210320
- 8210090106 Forwards 21 responses to Reactor Bys Branch (440 Series) questions discussed at Reactor Bys Branch safety review meeting held on 820921 Remaining 17 Items will be addressed in near future MCDUFFIE, M A Carolina Power & Light Co 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 27pp 15603 261 24X Fiche 50~400, 82/09/30, 8210050104
- 8210050125 Forwards responses to Instrumentation & Control Bys Branch 820730 questions re FSAR, confirming info discussed during 820814-17 & 0914-16 meetings ROUFFIE. M A Carolina Power & Light Co 82/09/30 DENTON. H R Office of Nuclear Reactor Regulation, Director 3App 19404 282 247 Fibe 50-400 82/09/30 BRONCH 24X Fiche 50-400, 82/09/30, 8210050125
- 8210210312 Summary of 820921 meeting w/applicant,Westinghouse,Ebasco t EGMO at site re Reactor Sys Branch 820424 questions concerning FBAR Attendance list encl KADAMBI.N P Licensing Branch 3 82/10/01 Licensing Branch 3 4pp 19782 078 24X Fiche 50~400,82/10/01,8210210312

- 8210150305 Advises that commercial operation date for Unit 1 changed from Fall 1985 to Spring 1986 No funds to be allocated in 1983 for const work on Unit 2 Most of requested rate hike disallowed W/Certificate of Svc Related correspondence FLYNN, 8 F Carolina Power & Light Co 82/10/06 KELLEY, J L . URIGHT. 0 0, CARPENTER. J H Atomic Safety and Licensing Board Panel 4pp 15701 336 24% Fiche 50-400,82/10/06.82/10/50305
- 8210130647 Notification of canceled 821012 meeting w/util & Ebasco in Bethesda: MD to perform review of RCPB matl KADAHBI.N P Licensing Branch 3 82/10/08 KERRIGAN.J Licensing Branch 3 3pp 15715 305 24X Fiche 50-400.82/10/08.8210150647
- 8210190512 Submits const completion schedule. Unit 1 scheduled for operation in Spring 1936, resulting in 6-month delay in fuel load Schedule for Unit 2 completion due Dec 1982 Present licensing review schedule should be maintained MCDUFFIE.M A Carolina Power & Light Co 82/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 15735, 309 24X Fiche: 50-400, 82/10/14, 8210190512
- B210260462 Bubmits formal clarification of responses to safety review questions from Containment Sys Branch (480 Beries)
  MCDUFFIE,M A Carolina Power & Light Co B2/10/20 DENYON,H R
  Dffice of Nuclear Reactor Regulation, Director 7pp 15806 052
  24X Fiche 50-400,82/10/20,8210260462
- --8210260481 Informs that Topical Rept AAF-TR-7101, "Design t Testing of Fam Cooler-Filter Sys for Nuclear Applications," acceptable Partial "Equipment Qualification Data Packages" encl TEDESCO, R. Atomic Energy Commission, Deputy Director for Yechnical Review (Pre-1975) 72/11/10 FISH.J F American Air Filter Co 54pp 15806 061 24% Fiche 50-400,82/10/20.

# Utility Environmental Report (ER), amends & correspondence

- 210200002 Forwards responses to environ rept review Questions 240 3. 291, 13 & 291 15, comparing environ impact on Buckhorn Creek of operation of one unit w/o Cape Fear River Makeup Bys MCDUFFIE: M A Caroline Power & Light Co 82/10/19 DENTON, H R Office of Nuclear Rescotor Regulation. Director 21pp 15737 308 24X Fiche 50-400:82/10/15.8210200032
- 210200084 Forwards Amend 4 to environ rept. Summary of changes encl MCBWFFIE.M A Carolina Power & Light Co 82/10/15 DENTON. H R Office of Nuclear Reactor Regulation. Director 2pp 15753 212 24% Fiche 50-400, 62/10/15, 6210200084
- -8210200086 Amend 4 to environ rept Aperture cards available in PDR # Caroline Power & Light Co. 82/10/15 279pp 15793 214 24; Ficher 50-400, 82/10/15, 8210200084.
- 210280054 Forwards affidavit re distribution of Amend 4 to environ rept.

  ZIMMERHAN,8 R Carolina Power & Light Co., 82/10/25 RISENHUT, D. & Division of Licensing. 5pp 15837.256 24X Fiche: 50-400,82/10/25,8210280054.
- NRC Draft/Final Environmental Statements, suppls & correspondence
- 102(0212 Notifies of schedule change for DEB Reservoir reanalysis has lead to delay in receipt of hydrological info. Statement will be issued by 82(217. NOVAK, T. M. Assistant Director for Licensing 82/10/12 UTLEY, E Caroline Power & Light Co 2pp 15774'336 24X Fichs 50-400, 82/10/12, 82(02)0212

### Security, medical, emergency & fire protection plans

- 10010037 Forwards request for addi info.based on review of 820626 industrial security plan safeguards contingency plan & security personnel training & qualification plan Encl withheld (ref 100FR2 790) (ERRIGAN, J. D. Licensing Branch 3 82/09/20 JONES, J. A. Carolina Pawer & Light Co. 2pp. 15565 315 24X Fishe, 50-400, 82/09/20, 3210010037.
- 10010349 Ack receipt of 820902 ltr informing NRC of steps taken to orrect violation noted in IE Insp Repts 50-400/82-24 & ...
  30-401/82-24 Response insufficient to determine if orrective action adequate
  EMISER G. Division of Project & Resident Programs 82/09/22
  EMISER J.A. Carolina Power & Light Go 2pp 15569 213 24%
  Iche: 50-400, 82/09/22, 8210010349

- --8210010397 JE Insp Repts 50-400/82-24 & 50-401/82-24 on 820620-0720 Noncompliance noted failure to identify & correct nanconforming conditions on two field welds on Class IE electrical cable tray supports MACKELL, 0 F , BURGER.C W Division of Project & Resident Programs 82/08/03 9pp 15569 220 24% Fiche 50-400.82/09/22.8210010349
- Q. Adjudicatory correspondence
- B210120103 Add1 response to FOIA request for nine categories of records generated by present MRC Commissioners, primarily Chairman Palladino & Commissioner Roberts & White House Forwards App B documents

  FELTON, J. M. Division of Rules and Records B2/07/12 UDELL. R A Critical Mass Energy Project 3pp 15690 117 24X

  Ficha 50-000, 82/07/12, 8210120103
- --8210120123 Forwards memorandum & order re Council of NC objection to util request for exemption to perform certain site preparation work Memorandum addresses exemption question & sets out history of Commission regulation. Section 50:12 ROBERTS. T. M. Commissioners 81/12/09 PALLADING, N., OILINSKY, V., BRADFORD, J. Commissioners ip 15570:124

  24X

  Fiche 80-000,82/07/12,8210120103
- --8210120132 Memorandom & order re Council of NC objection to util request for exemption per revised NEPA regulation to perform certain site preparation work NEPA does not bar preliminary work Site preparation work properly authorized SENDER, P.C. Atomic Energy Commission, 74/06/11 Atomic Energy Commission 8pp. 15690 125 24X Fiche 50-000, 82/07/12.
- B210010328 Supplemental statement re validity of psychological stress contentions Late filing criteria not applicable If contentions not admitted, encl. arguments should be considered amends to original contentions READ.D F. Chapel Hill Anti-Nuclear Group Effort 82/09/17 Atomic Safety and Licansing Board Panel 14pp 15969 174 24x Fiche.50-400, 82/09/17,8210010328
- 8210010337 Suppl to Chapel Hill Anti-Nuclear Group Effort/Environ Law Project 820713 renewed & reformed motion to postpone proceedings, originally submitted on 820316 Suppl based on new info Certificate of Svc encl.

  READ, D.F. Chapel Hill Anti-Nuclear Group Effort 82/09/24 Atomic Safety and Licensing Board Panel 7pp 15549 166 24X Fiche 50-400. 82/09/24,8210010337
- B210130192 Requests clarification of docket numbers for Harris & Perry plants Hixup may be causing prejudice to intervenors since documents go to incorrect LPDR HIATT.B.L. Ohio Citizens for Responsible Energy 82/10/04 Docketing & Bervices Branch. 1p 15707.260. 24X Fiche 50-000.82/10/04.8210180192
- 8210150305 Advises that commercial operation date for Unit 1 changed from Fall 1985 to Spring 1986. No funds to be allocated in 1983 for comet work on Unit 2 Most of requested rate hike disallowed H/Certificate of Styr Related correspondence FLYNN, S F Carolina Power & Light Co. 82/10/06 KELLEY, J. L., BRIGHT, O D. CARPENTER, J. H. Atomic Safety and Licensing Board Panel 4pp. 15701.336. 24X Fiche 50-400.82/10/06.8210150305
- 8210150340 Objections to ASLS 820922 prehearing conference memorandum & order Certificate of Svc encl. READ.D F Chapel Hill Anti-Nuclear Group Effort 82/10/08 Atomic Safety and Licansing Board Panel 7pp 15705-357 24X Fiche. 50-400, 82/10/08, 8210150340
- 8210200053 Responds to ASLB B20922 order ruling on contention & svc of documents, Ruling on Contention IVc & on motion re svc of documents should be reconsidered Arrangements for svc unacceptable since parties unrelated, W/Certificate of Bvc. WILSUN,R D. Wilson, R. 82/10/14. 5pp. 15753.088 24X Fishe 50-400, 82/10/14.8210200053
- 8210210348 Response to ASLE 820922 memorandum & order Objects to portion of order dealing w/svc of documents & comments on security plan & structure of discovery process Notice of appearance & Certificate of 8vc and RUNKLE, J D Conservation Council of North Carolina RUNKLE, J, D Affiliation Unknown. 82/10/14 6pp. 15764 204 24X Fiche 50-400, 82/10/14, 8210210348
- 8210200007 Forwards objections to & requests for clarification of ASLB 820722 memorandum & order & response to Chepel Hill Anti-Nuclear Group Effort supplemental statement repsychological stress contentions Certificate of Syc encl BAXTER, T A Shaw, Pittman, Potts & Troubridge, BAXTER, T A Carolina Power & Light Co. 82/10/15 KELEY, J L, BRIGHT, O D. CARPENTER, J M. Atomic Safety and Licensing Board Panel, App 15755:001 24X Fiche 50-400, 82/10/15, 8210200009

# DOCKETED ITEMS

- --8210200013 Response opposing Chapel Hill Anti-Nuclear Group Effort 820927 supplemental statement re psychological stress contentions ASLB obligated to follow Commission policy statement on psychological stress issues BAXTER. T A Carolina Power & Light Co BAXTER. T A Shaw. Pittman. Potts & Trombridge 82/10/15 Atomic Safety and Licensing Board Panel 5pp 15755-005 24X Fiche 50-400. 82/10/13:8210200009
- --B210200021 Objections to & requests for clarification of ASLB B20922 memorandum & order Addl info re util plans on proposed Cape Fear River intake facility provided Ruling on & Eddleman Contention 132 should be clarified to specify bases O'WEILL, J.H. Carolina Power & Light Co. O'NEILL, J.H. Shaw, Pittman, Potts & Troubridge B2/10/15. Atomic Safety and Licensing Board Panel 17pp 15755 010. 24x Fiche 50-400, 82/10/15, B210200009
- 8210210308 Notice of appearance in proceeding Certificate of Syc encl GREENBLATT.D Eddleman, N GREENBLATT.D Greenblatt, D 82/10/15 Atomic Safety and Licensing Board Panel 3pp 15764 241 04X Fiche 30-400.82/10/15.8210210308
- 8210210376 Objections to ASLB 820922 memorandum & order reflecting decisions made at prehearing conference Objects to rulings on eye of util documents, contentions & cancelation of Unit 2 Certificate of Syc enc! EDOLEMAN, W Eddleman, W 82/10/15 14pp 15763 150 24X Fiche 50~400, 92/10/15, 8210210376
- 82:02:0417 Response to ASLB 820722 memorandum & order re use of security plan experts as witnesses CREENBLATT.D Eddisman. W PAYNE.M T Kudzu Alliance RUNKLE.J Chapel Hill Anti-Nuclear Group Effort 82/10/15 4pp 15763 076 24X Fiche 50-400,82/10/15.8210210419
- 8210200062 Forwards consolidated list of admitted & deferred contentions per ASLB 820722 order Agreement should be reached on wording b numeration to facilitate bearings & avoid misunderstandings W/o enc!

  BARTH,C A Rearing Branch | 82/10/18 RUNKLE,J Conservation Council of North Carolina EDDLEMAN,W Eddleman, W READ,D F Chapel Hill Anti-Nuclear Group Effort | 19 18756 (52 24% Fiche 50-400,82/10/18,8210200062
- 8210250068 Complains about svc of documents & LPDR copy machine EDDLEMAN.W EddJeman, W 82/10/19 KELLEY,JL, CARPENTER,JH, BRIGHT,G O Atomic Safety and Licensing Board Panel 2pp 15787-045 24X Fichs 50-400.82/10/19.8210250068
- H General correspondence
- 8210010028 Requests NRC direct all official correspondence to EE Utley, util vice-president, due to 820930 retirement of JA Jone JONES, J A Carolina Power & Light Co 62/09/27 DENTON, H R Office of Nuclear Reactor Regulation, Director jp 15565-314 24X Fiche 50-000, 62/09/27, 8210010028
- 8210130323 Requests changes to distribution list for NUREG-0020, "Licensed Operating Reactors - Status Summary Rept" 21MMERMAN, 8 R Carolina Power & Light Co 82/10/11 BEEBE, M R ADP Systems Development Branch 2pp 15683 361 24x Fiche 50-000, 82/10/11, 8210130323
- Q Inspection reports. IE Bulletins & correspondence
- 92100100B6 Forwards IE Insp Repts 50-400/82-29 & 50-401/82-29 on 82830-0902 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/09/13 JONES, J A Carolina Power & Light Co 2pp 15565 260 24x Fiche 30-400, 82/09/13, 821/0010086

- 8210010347 Ack receipt of 820702 ltr informing MRC of steps taken to correct violation noted in IE Insp Repts 50-400/82-24 % 50-401/82-24 Response insufficient to determine if corrective action adequate LEWIS.R C Division of Project & Resident Programs 82/09/22 JUNES.J A Carolina Power & Light Co 2pp 15567 213 24% Fiche 50-400.82/09/22.8210010349
- -8210010360 Responds to NRC 820804 ltr re violation noted in [E liip Repts 50-400/82-24 & 50-401/82-24 Corrective actions Hanger ED 2622 & Item 1436-10 reinspected & repaired New inspector under training in GC welding required to pass written insp PARSONS,R M Carolina Power & Light Co 82/09/02 O'REILLY, J.P. Region 2. Office of Director 2pp 15569 215 24X Fiche 50-400, 82/09/22, 8210010349
- --8210010368 Forwards IE Insp Repts 50-400/82-24 \$ 50-401/82-24 on 820620-0720 \$ notice of violation LEHIS,R C Division of Project & Resident Programs 82/08/04 JQNES, J A Carolina Power & Light Co 2pp 15569 217 24% Fiche 50-400,82/09/22.8210010349
- -8210010373 Notice of violation from insp on 820620-0720 \* Division of Project & Resident Piograms 82/08/04 ip 15569 219 24X Fiche 50-400.82/09/22.8210010349
- --8210010397 IE Insp Repts 50-400/82-24 & 50-401/82-24 on 820620-0/20 Nancompliance noted failure to identify & correct nonconforming condutions on two field welds on Class IE electrical cable tray supports MACWELL, 0 F, BURGER, C M DIVISION of Project & Resident Prograss 82/08/03 9pp 15569 220 24X Fiche 50-400,882/09/22.82(001049
- 8210320160 Forwards IE Insp Repts 50-400/82-30 & 50-401/82-30 on 820820-0910 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 82/10/04 JDNES,J A Carolina Power & Light Co 2pp 15778 072 24X Fiche 50-400, 82/10/04, 8210220160
- --8210220163 IE Insp Repts 50-400/82-30 % 50-401/82-30 on 820820-0910 h. noncompliance noted Major areas inspected followup on previously (dentified items.concrete.piping & personnel training MAXWELL, 0 F , BURGER, C W Division of Project & Resident Programs 82/09/30 6pp 157/8 074 20% Fiche 50-400, 82/10/04, 8210220160
- 8208190233 IE Info Notice 80~35, Suppl I, "Leaking & Dislodged [-12" implant Seeds " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 2"40 24X Fiche 50~000.82/10/06.8208190233
- 8210220127 Ack receipt of 820923 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/82-26 & 50-401/82-26 LEMIS.R C Division of Project & Resident Programs 82/10/12 UTLEV.E E Carolina Power & Light Co 1p 15778 122 24X Fiche 50-400, 827.10/12.8210220127
- --8210220132 Responds to NRC 820830 ltr re violations noted in [] Insp. Rept 90-400/82-26 Corrective actions refresher training course conducted for rebar inspectors PARSONS,R H Carolina Power & Light Co 82/09/23 d'REILLY, J P Region 2. Office of Director 2pp 15778 123 24X Fiche 50-400,82/10/12,8210220127
- --8210220137 Forwards IE Insp Repts 50-400/82-26 & 50-401/82-26 on 820802-06 & notice of violation LEWIS.R C Division of Project & Resident Programs 82/08/30 JONES.J A Garolina Power & Light Co 2pp 15778 125 24X Fiche 50-400,82/10/12,8210220127
- ~~8210220141 Notice of violation from insp on 620802-04 \* Division of Project & Resident Programs 82/08/30 ip 15778 127 24X Fiche 50-400, 82/10/12,8210220127
- --B210220145 IE Insp Repts 50-400/82-26 & 50-401/82-26 on 820802-06 Noncompliance noted failure to analyte cut rebars for acceptability (MRIGHT.R W. DEBBAGE, A G. UPRIGHT.C M. Division of Engineering & Technical Programs 82/08/25 13pp 15778 128 24X Fiche 50-400,82/10/12.8210220127
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall-Large-Diameter, Btainless Etcel. Recirculation Sys Figing at BMR Plants " Svc list encl DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125. 24X Fichs 50-000.82/10/14.8208190238

- S Reportable occurrences (ERs & related correspondence
- =210180141 Part 21 rept re seismic pipe hangers previously accepted by GC weld inspector Initially reported on 820913 Hangers will be reinspected reworked \* correctly documented Final rept espected by 830701
  CHIANGI, N J Carolina Power & Light Co 82/09/13 O'REILLY, J N
  Region 2, Office of Director 4pp 19719 226 24x Fiche 50-400, 82/09/13, 8210180(4)
- 6210180193 Part 21 rept re raulty pipe support shop welds Initially remotted on 820813 Insp criteria being reviewed Deficient supports reformed to Bergen-Falerson for insp Next rept Supports reformed to bergen reasons for this we will be completed by 830701
  CHIANGIN J Carolina Power & Light Co 82/09/
  Region 2. Office of Director 4pp 15719 114
  Fiche 50-400. 82/09/13.8210180193 82/09/13 0'REILLY, J P
- S210080180 Deficiency rept is use of ASTM-A307 nuts & bolts for bolted connection in lieu of required ASTM-A325 nuts & bolts initially reported on 820903 Ebasco Sycs currently evaluating problem All boils replaced/reinspected
  PARSONS,R M Carolina Power\* Light Co 82/09/30 O'REILLY,J P
  Region 2, Office of Director to 15640 169 24X
  Fiche 50-400, 82/09/30 8210080180
- 6210080283 Interim deficiency tept re sheared pinion keys on Limitarque valve motor operators Initially reported on 820903
  Restinghouse discussing problem w/Limitorque Final rept will be submitted by 930401 Also reported per Part 21
  PARSONS:R M Carolina Power & Light Cu 82/10/01 O'REILLY.J P Region 2. Office of Director 3pp 15638 320 24x
  Fiche 50-400, 82/10/01, 8216080283
- AZIO130567 Addendum 2 to 820319 deficiency rept re inadequately welded studs on embedded strip plates Addendum provides info re shipment of embeds (Type II strip plates & crane rail shipment or embeds (type it strip places a craft rai places) & any associated problems PARSON,R M Carolina Power & Light Co. 82/10/05 | Region 2, Office of Dijector Spp. 15683 113 24x Fiche 50-400,82/10/05,8210130567
- 6210220484 Interim deficiency lept re defective guvernor drive coupling in emergency diesel engine-generator sets from transamerica DvLaval Instrally reported on 620909 (oupling will be replaced Also reportable per Part 21 PARSONS.R M Carolina Power / Light Co 62/10/07 D'REILLY.J P Region 2. Office of Director 4pp 15779 079 24X Fiche 50-400.82/10/07.6210270484
- 8210220075 Interim deficiency ropt ie design error in solid state protection sys Initially reported on 820909 Westinghouse continuing to review design & has revised tost procedures to verify contact clasure Also reported per Part 21 PARSONS.R M Canalina Power / Light Co. 82/10/08 G/REILLY, J.P. Region 2. Office of Director App. 157/8 185 24X Fiche 50-400, 82/10/08, 621-220075
- 8210220412 Final deficiency rept re grout concrete interface failure on equipment pad frame Initially reported on 820909 Embed frame rengred Concrete surb chipped completely out & surb A reame replaced

  Arabons.R M Carolina Power & Light Co 82/10/08

  Region 2. Ofrice of Director App 15778 358 24X

  Fiche 50-400, 82/10/08, 8210220412
- 6210270260 Interim deficiency rept re gaps between mating surfacus of connections between structural steel members which also had A470 bolts w/A325 nuts Initially reported on 820618 Ebasco Svcs. Inc evaluating problem
  PARRONS-R M Carolina Power & Light Co 82/10/13 O'REILLY, J P
  Region 2. Office of Director 1p 15853 194 24X
  Fiche 50-400.82/10/13.8210270240
- 9210290258 Interim deficiency rept re grease between mating surfaces of structural connection designed as friction connection initially reported on 820915 Ebasco Svcs. Inc currently evaluating problem Results expected by 830415 PARSONS:R M Carolina Power & Light Co 82/10/14 0'REILLY, J P Region 2. Office of Director 1p 15853 197 24X Fiche 50-400.82/10/14.8210290258
- 8210260398 Final deficiency rept re use of ASTM A307 bolts in lieu of ASS bolts specified in containment recirculating summ is cover structural steel Initially reported on 820903 Yield stress would not be ercesded Matter not reportable PARSONSIR M Carolina Power & Light Co 82/10/15 D'RE Region 2. Office of Director 1p 15806 135 24X Fiche 80-400.82/10/15.8210260398 D'REILLY, J P

- DOCKET 50-401 BHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2 A Application/construction stage documents & correspondence
- 8210130053 Summary of 820816-19 meeting w/util/Ebasco & Westinghouse re design review of instrumentation & control sys for facilities Followup meeting scheduled for 820914-16 in New York City, NY
- New York City, NY LIGITRA-E A Licensing Branch 3 82/09/08 Licensing Branch 3 5pp 15594 272 24% Fiche 50-400,82/09/08,8210130053
- 821001005) Ack recoipt of 820823 itr requesting temporary relief from commitments re training of shift technical advisors Program approved & request forwarded to NRR for evaluation D'REILLY, J.P. Region 2, Office of Director 92/09/20 JON Carolina Power & Light Co. ip 15565 322 24x

  Fiche 50-000,82/09/20,8210010051 82/09/20 JONES J A
- 8210270324 Requests add) info re instrumentation & control eys Info should be in form of response to IE Bulletin 79-21 re level measurement errors due to environ temp effects on level instrument ref legs Requests submittal date within 2 wks KERRIGAN.J D Licensing Branch 3 82/09/23 JONES.J A Caroli KERRIGAN, J D. Licensing Branch 3 82/09/23 JONES, J A. Caro Power & Light Co. 2pp. 15836-357 24% Fiche 50-400,82/09/23, 8210270324
- 8210210035 Forwards request for addl info on FSAR Section 440-0. "Reactor Sys "
  "Reactor Sys "
  KERRIGAN J Licensing Branch 3 82/09/29 JONES JA Caroli
  Power & Light Co 9pp 15773 262 24% Fiche 50-400.82/09/29,
  8210210035
- S210210258 Notification of 921012 meeting w/util & Ebasco in Bethesda. MD to discuss review of RCPB matls KADAHBI,N P Licensing Branch 3 82/09/27 KERRIGAN, J Licensing Branch 3 3pp 15774 324 24X Fiche 50-400,82/09/29,8210210258
- B210210320 Summary of B20914-16 meetings w/util.Westinghouse & Ebasco at Ebasco ofc re design review of instrumentation & control sys Attendance list encl
  LICITRALE A Licensing Branch 3 82/07/27 Licensing Branch & 4pp 15782 087 24X Fichs 50-400.B2/07/29.8210210320
- 8210050106 Forwards 21 responses to Reactor Sys Branch (440 Søries) questions discussed at Reactor Sys Branch safety review meeting held on 820921 Remaining 17 (tems will be addressed in near future MCDUFFIE,M A Carolina Power & Light Co 82/09/30 DENTON,H R Office of Nuclear Reactor Regulation. Director 27pp 15603 261 24x Fiche 50-400,82/09/30.8210050106
- 6210050125 Forwards responses to Instrumentation & Control Sys Branch 820730 questions re FSAR, confirming info discussed during 820916-19 & 0914-16 meetings MCDJFFIE, M A Carolina Power & Light Co 82/09/30 DENYON, H R Office of Nuclear Reactor Regulation, Director 56pp 15604 282 24% Fiche 50-400.82/09/30,8210050125
- 8210210312 Summary of 820921 meeting w/applicant, Westinghou E020 at site re Reactor Sys Branch 820426 questions concerning FBAR Attendance list encl
  KADAMBIN P Licensing Branch 3 B2/10/01
  4pp 15782 078 348 Fish 80-400 87446

- --B2102604B1 Informs that Topical Rept AAF-TR-7101. "Design & Testing of Fan Cooler-Filter Sys for Nuclear Applications," acceptable Partial "Equipment Qualification Data Packages" encl TEDESCO.R L. Atomic Energy Commission, Deputy Director for Technical Review (Pre-1975) 72/11/10 FISH, J.F. American All Filter Co. 54pp 15806-061 24% Fiche 50-400-82/10/20. 6210260462
- C Utility Environmental Report (ER), amends & correspondence
- 8210200032 Forwards responses to environ rept review Questions 240 3, 271 13 b 271 15, comparing environ impact on Buckhorn Creek of operation of one unit u/o Cape Fear River Makeup Sys MCDUFFIE, M A Carolina Power & Light Co 62/10/15 DENTON, H R Diffice of Nuclear Reactor Regulation, Director 21pp 15757 308 24X Fiche 50~400, 82/10/15.8210200032
- 5210200084 Forwards Amend 4 to environ rept Summary of changes encl MCDUFFLE.M A Carolina Power & Light Co 92/10/15 DENTON, H R Office of Nuclear Reactor Regulation: Director 2pp 15753 212 24X Fiche 50-400.82/10/15.8210200084
- --8210200086 Amend 4 to environ rept Aperture cards available in PDR \* Carolina Power & Light Co 82/10/15 279pp 15753 214 24X Fiche 50-400,82/10/15,8210200084
- 8210280054 Forwards affidavit re distribution of Amend 4 to environ rept ZIMMERMAN, S.R. Carolina Power & Light Co. 82/10/25 EISENHUT, D.G. Division of Licensing 5pp 15837 256 24X Fiche 50-400, 82/10/25, 8210380054
- D NRC Draft/Final Environmental Statements, supply & correspondence
- 8210210212 Notifies of schedule change for DES Reservoir reanalysis has lead to delay in receipt of hydrological info Statement will be issued by 821217
  NOVAK.T M Assistant Director for Licensing 82/10/12 UTLEY.E Carolina Power & Light Co 2pp (5774 336 24X Fiche 50-400, 8210/12, 8210210212
- F Security, medical, emergency & fire protection plans
- 8210010037 Forwards request for additinfo.based on review of 820626 industrial security plan, safeguards contingency plan & security personnel training & qualification plan Encl withheld (ref 10CFR2 770)

  KERRIOAH, J D Licensing Branch 3 82/09/20 JONES, J A Carolina Power & Light Co. 2pp. 15565 315 24X Fiche 50~400,82/09/20,8210010937
- 8210010349 Ack receipt of 820902 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-400/82-24 & 50-401/82-24 Response insufficient to determine if corrective action adequate LEMIS.R C Division of Project & Resident Programs 82/09/22 JDMSS.J A Carolina Power & Leight Co 2pp 15569 213 24% Fiche 50-400.82/09/22.8210010349
- --8210010397 IE Insp Repts 50-400/82-24 & 50-401/82-24 on 820620-0720 Noncompliance noted failure to identify & correct nonconforming conditions on two field welds on Class IE electrical cable tray supports MACUELL. G F Division of Project & Resident Programs 82/08/03 9pp 15569 220 24% Fiche 50-400.82/09/22,8210010349
- G Adjudicatory correspondence
- 8210120103 Add1 response to FOIA request for nine categories of records generated by present NRC Commissioners primarily Chairman Palladino & Commissioner Roberts & White House Forwards App B documents FELTON.J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 3pp 15690 117 24X Fiche 50-000.82/07/12.8210120103
- --8210120123 Forwards memorandum & order re Council of NC objection to util request for exemption to perform certain site preparation work Memorandum addresses exemption question & sets out history of Commission regulation. Section 50 12 ROBERTS.T M Commissioners 81/12/07 PALLADINO, N Commissioners 1p 15690 124 24X Fiche 50-000, 82/07/12, 8210120103
- --B210120132 Hemorandum & order re Council of NC objection to util request for exemption per revised NEPA regulation to perform certain site preparation work. NEPA does not bar preliminary work Site preparation work properly authorized BENDER.P C Atomic Energy Commission 74/06/11 Atomic Energ Commission 390-1105 24X Fiche, 50-000, 82/07/12, 82/01/20103

- 8210010328 Supplemental statement re validity of psychological stress contentions. Late filing criteria not applicable If contentions not admitted, encl arguments should be considered amends to original contentions. READ, D.F. Chapel Hill Anti-Nuclear Group Effort 82/09/17 Atomic Safety and Licensing Board Panel 14pp 15569 174 24X Fiche 50-400, 82/09/17, 5210010328
- 6210010337 Suppl to Chapel Hill Anti-Nuclear Group Effort/Environ law Project 620713 renewed % reformed motion to postpone proceedings, originally submitted on 820316 Suppl based on new info Certificate of Svc encl READ, D F Chapel Hill Anti-Huclear Group Effort 82/09/24 Atomic Safety and Licensing Board Panel 7pp 15569 166 24X Fiche 50-400, 82/09/24, 8210010337
- 8210150192 Requests clarification of docket numbers for Harris & Perry plants Hizup may be causing prejudice to intervenors since documents go to incorrect LPDR HIATT, 8 L Ohio Citizens for Responsible Energy 82/10/04 Docketing & Services Branch 1p 15707 260 24X Fiche 50-000,82/10/04,8210150192
- 6210190305 Advises that commercial operation date for Unit 1 changed from Fall 1785 to Spring 1986 No funds to be allocated in 1783 for const work on Unit 2 Most of requested rate hike disallowed W/Certificate of Svc Related correspondence FLYNN, S F Carolina Power / Light Co 82/10/06 KELLEY, J L, BRIGHT, G O, CARPENIER, J H Atomic Safety and Licensing Noard Parel App 15701 336 24X Fiche 50-400.82/10/06.8210150305
- 8210150340 Objections to ASLB 820922 prehearing conference memorandum 3 order Certificate of Svc encl READ, D.F. Chapel Hill Anti-Nuclear Group Effort 82/10/08 Atomic Safety and Licensing Board Panel 7pp 15705-357 24y Fiche 50-400, 82/10/08, 8210150340
- B210200093 Responds to ASLB 670922 order ruling on contention & five orderweets Ruling on Contention IVC % on motion re-sec of documents should be reconsidered Arrangements for sec ounacceptable since parties unrelated W/Certificate of Sec WILSON:R D Wilson: R 82/10/14 Spp 15753 088 24% Fiche 50~400. 62/10/14:8210200053
- B2102(0348 Response to ASLB B20922 memorandum & order Objects to portion of order dealing w/svc of documents & comments on security plan & structure of discovery process Notice of appearance & Certificate of Svc encl RUNKLE, J D Conservation Council of Noith Carolina RUNKLE, J D Arfiliation Unknown 82/10/(4 6pp 15764 204 24X Fiche 50-400,82/10/14,8210210348
- 821020009 Forwards objections to & requests for clarification of ASLB 820922 memorandum & order & response to Chapel Hill Anti-Nuclear Group Effort supplemental statement repsychological stress contentions Certificate of Svc encl BAXTER, T A Shaw, Pittman, Patts & Troubridge BAXTER, T A Carolina Power & Light Co @2/10/15 KELLEY, J L , BRIGHT, G O . CARPENTER, J H Atomic Safety and Licensing Board Panel App. 15755 001 24X Fiche 50-400, 82/10/15, 6210200009
- --8210200013 Response opposing Chapel Hill Anti-Nuclear Group Effort B20927 supplemental statement re psychological stress contentions ASLB obligated to follow Commission policy statement on psychological stress issues BAXTER.T A Carolina Power & Light Co BAXTER.T A Shaw. Pittman. Potts & Troubridge B2/10/15 Atomic Safety and Licensing Board Panel Spp 15755 005 24X Fiche 50-400. B2/10/15.8210200009
- --8210200021 Objections to \$ requests for clarification of ASLB 820922 memorandum \$ order Addl info re util plans on proposed Cape Feer River intake facility provided Ruling on H Eddleman Contention 192 should be clarified to specify bases O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw. Pittman, Potts & Trowbridge 82/10/15 Atomic Safety and Licensing Board Panel 17pp 15785 010 24X Fiche 50-400,82/10/15,8210200009
- 8210210308 Notice of appearance in proceeding Certificate of Svc entl OREENBLATT.D Eddieman W OREENBLATT.D Greenblatt. D 82/10/15 Atomic Bafety and Licensing Board Panel 3pp 15764 241 24X Fiche 30-400.82/10/13.8210210308
- 8210210376 Objections to ASLB 820922 memorandum & order reflecting decisions made at prehearing conference Objects to rulings on syc of util documents contentions & cancelation of Unit 2 Certificate of Syc encl EDDLEMAN.W. Eddleman. W 82/10/15 14pp 15763 150 24X Fiche 50-400, 82/10/15.8210210376

- 52:02:0419 Response to ASLB 820922 memorandum % order re use of security plan experts as withesses GREENBLATT D Eddleman W PAYNE, M T Kudzu Alliance RUNKLE, J Chapel Hill Anti-Muclear Group Effort 82/10/15 4pp 15763 076 24% Fiche 50-400.82/10/15.8210210419
- 5010700042 Forwards consolidated list or admitted & deferred contentions per ASLB 820922 order Agreement should be reached on wording 5 numeration to facilitate heatings & avoid misunderstandings N/a encl BARTH.C A Heating Branch 1 82/10/18 RUNKLE.J Conservation Council or North Carulina EDDLEMAN.N Eddleman.W READ.D F Chapel Hill Anti-Nuclear Group Erfort ip 1575a 152 24X Fiche 50-400.82/10/18.8210200062
- 6210250048 Complains about sic of documents & LPDR copy machine EDDLEMAN.W Eddleman.W 82/10/19 WELLEY.JL, CARPENTER,JH, BRICHT,C O Atomic Safety and Licensing Board Panel 2pp 15787-045 24X Fiche 50-400,82/10/19.8210250068

### H General correspondence

- 6210010028 Requests MRC direct all official correspondence to EE Utley, util vice-president, due to 820730 retirement of JA Jone
  JCFE, J A Carolina Power & Light Co 82/09/27 DENTGN, H R
  Office of Nuclear Reactor Regulation, Director (p. 15565-314 24X)
  Fiche 50-000, 82/09/27, 6210010028
- 5210130323 Requests changes to distribution list for NUREG-0020. Licensed Operating Reactors Status Summary Rept "
  ZIMMERMAN.5 R Carolina Power tight to 82/10/11 DEEBE, M R
  ADP Systems Development Branch 2pp 15683 361 24X
  Fiche 50-000, 82/10/11, 8210130323
- q Inspection reports. IE Dulletins & correspondence
- -B210010091 IE Insp Repts 50-400/82-29 & 50-401/82-29 on B20830-0902 Nu noncompliance noted Major areas inspected const progress; safety-related piping. RCPB piping steel structures & reactor vessel internals KLEINSORGE, N P., BLAYE J.J. Fivision of Engineering & Technical Programs 82/09/10 10pp 19565-262 24X Fiche 50-400.82/09/13, 6210010006
- F210010102 Forwards IE Investigation Repts 50~400/82-23 & 50~401/82 23 on 820605-23 No noncompliance noted GYREICLY, J.P. Region 2, Grice of Director 82/09/13 JONES, J.A. Carolina Power & Light Co. 2pp. 15566-041 24X Fiche 50~400, 82/09/13, 8210010102
- --3210010111 IE Investigation Repts 50-400/82-23 & 50-401/82-23 on G20606-23 No noncompliance noted Major areas investigated ellegations re forging of GC inspector initials on weld data rept VORSE, J Y , URYC.B , ALDERSON, C E. Region 2, Office of Director 82/09/09 3pp 15566-043 24% Fiche 50-400,82/09/13,8210010102
- 5210010309 Ack receipt of 920902 ltr informing NRC of steps taken to currect violation noted in IE lnsp Repts 50-400/82-24 & 50-401/82-24 Response insufficient to determine if corrective action adequate LEMIS.R C Division of Project & Resident Programs 82/09/22 JONES.J A Carolina Power & Light (a 2pp 15569 213 24% Fiche 50-400.82/09/22.8210010349
- -8210010360 Responds to IRC 820804 ltr re violation noted in IE Imp Repts 50-400/82-24 & 50-401/82-24 Corrective actions Hanger ED 2622 & Item 1436-10 reinspected & repaired New inspector under training in GC welding required to pass written imap PARSONG/R M Carolina Power & Light Co 82/09/02 D'REILLY/J P Region 2. Office of Director 2pp 15569 215 24X Fichs 50-400, 82/09/22/8210010349
- --8210010368 Forwards IE Insp Repts 50-400/82-24 & 50-401/82-24 on 820620-0720 & notice of violation LEWIB, RC Division of Project & Resident Programs 82/08/04 JDNES. J A Capelina Power & Light Co 2pp 15569 217 24X Fiche 50-400.82/09/22.8210010349
- --8210010397 IE Insp Repts 50-400/82-24 & 50-401/82-24 on 820620-0720 Noncompliance noted failure to identify & correct nonconforming conditions on two field welds on Class IE electrical cable tray supports

  MACNELL, 0 F, BURGER, C M DIVISION of Project & Resident Programs 82/08/03 9pp 15567 220 24% Fiche 50-400, 82/09/22, 8210010349

- 8210220160 Forwards IE Insp Repts 50-400/82-30 & 50-401/82-30 on 820820-0910 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/10/04 JDNES.J A Carolina Power & Light Co 2pp 15778 072 24X Fiche 50-400, 82/10/04, 8210220160
- --8210220163 IE Insp Repts 50-400/82-30 & 50-401/82-30 on 820820-0710 No noncompliance noted Major areas inspected fullowup on previously identified items, concrete, piping & personnel training MAXMELL, OF, BURGER, C W Division of Project & Resident Programs 82/07/30 dpp 15778 074 24% Fiche 50-400,82/10/04,8210220160
- 820Bi90233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/04 Consolidated Edison Co of New York 64pp 15761 250 24< Ficha 50-000-82/10/06.8208190233
- 8210220127 Ack receipt of 820923 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-400/82-26 & 50-401/82-26 CEHIS.R C Division of Project & Resident Programs 82/10/12 UTLEY.E E Carolina Power & Light Co ip 15778 122 24X Fiche 50-400.82/10/12.8210220127
- ---B210220137 Forwards IE Insp Repts 50-400/82-26 & 50-401/82-26 on B20802-06 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/08/30 JONES.J A Carolina Power & Light Co 2pp 15778 125 24X Fiche 50-400,82/10/12,8210220127
- --B210220145 IE Insp Repts 50-400/B2-26 & 50-401/B2-26 on 820802-06 Noncompliance noted failure to analyze cut rebars for acceptability WRIGHT,R W , DEBRAGE,A O , UPRIGHT,C M Division of Engineering & Technical Programs 82/08/25 13pp 15778 128 24X Fiche 50-400.82/10/12.8210220127
- 6208190238 IE Builetin 82-03. "Stress Corresion Cracking in Thick-WallsLarge-Diameter Shainless Steel, Recirculation Sys Piping at BWR Plants "Svc list encl DEYGUNO, R C Director's Diffice. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- S Reportable occurrences. LERs & related correspondence
- 8210180193 Part 21 rept re faulty pipe support shop welds Initially reported on 820813 Insp criteria being reviewed Deficient supports returned to Bergen-Paterson for insp Next rept will be completed by 830701 CHIANDI.N J Carolina Power & Light Co 82/09/13 D'REILLY, J P Region 2. Office of Director 4pp 15719 [14 24X Fiche 50-400, 82/09/13, 8210160193
- 210080180 Deficiency rept re use of ASTM-A307 nuts & bolts for bolted connection in lieu of required ASTM-A325 nuts & bolts Initially reported on 820903 Ebasco Svcs currently evaluating problem All bolts replaced/reinspected PARSONS.R M Carolina Power & Light Co 82/09/30 D'REILLY, J P Region 2. Office of Director 1p 15640 169 24X Fiche 50-400, 82/09/30, 82(0080180
- 8210080283 Interim deficiency rept re sheared plain keys on Limitorque valve motor operators Initially reported on 820703 Westinghouse discussing problem w/Limitorque Final rept will be submitted by 830401 Also reported per Part 21 PARSONS,R M Carolina Power & Light Co 82/10/01 O'REILLY, J P Region 2, Office of Director 3pp 15638 320 24X Fiche 50~400, 82/10/01, 82/10080283
- 8210130567 Addendum 2 to 820319 deficiency rept re inadequately welded study on embedded strip plates Addendum provides info re shipment of embeds (Tupe II strip plates & crane rail plates) & any associated problems
  PARSON,R M Carolina Power & Light Co 82/10/05 O'REILLY, J P
  Region 2, Office of Director Spp. 15683 113 24X
  Fiche 50-400,82/10/05,8210130567
- 8210220484 Interim deficiency rept re defective governor drive coupling in smergency diesel engine-generator sets from Transamerica DeLaval Initially reported on 820909 Coupling will be replaced Also reportable per Part 2! PARSONS.R M Carolina Power & Light Co 82/10/07 O'REILLY, J P Region 2. Office of Director 4pp 15779 079 24X Fiche 50-400, 82/10/07, 8210220484

- 6210220075 Interim deficiency rept re design error in solid state protection sys Initially reported on 820909 Westinghouse continuing to review design & has revised test procedures to verify contact closure Also reported per Part 21 PARSONS.R M. Carolina Power & Light Co. 82/10/08 D'REILLY.J P. Region 2. Orfice of Director. 4pp. 15778-185 24X Fiche 50-400, 82/10/08-8210220075
- GETOZZO412 Final deficiency ight re grout concrete interface failure on equipment pad Frame Initially reported on 820909 Embed frame removed Concrete curb chipped completely out // curb // riame replaced FARSONS, R H Carolina Power & Light Co 82/10/08 Q'REILLY, J P Region 2, Office of Director 4pp 15778 358 24X Fiche 50-406, 82/10/08, 62/02/20412
- 8210290259 Interim deficiency rept to grease between mating surfaces of structural connection designed as friction connection initially reported on 820915 Ebasco Svos, inc currently evaluating problem Rosults espected by 830415 PARSONS.R M Carolina Power & Light Co 82/10/14 D'REILLY, J PRegion 2, Office of Director ip 19833 197 24X Fiche 50-400,82/10/14.82108/90258
- 8210260398 Final deficiency royt he use of ASTM A307 bolts in lieu of A325 bolts specified in containment rectrculating sump I cover structural steel Initially reported on 820703 Yield stress would not be exceeded Matter not reportable PARSONS,R M Carolina Power & Light Co 82/10/15 0'REILLY, J P Region 2, Office of Director 1p 15806 135 24X Fiche 50-400,82/10/15,8210260398

DOCKET 59-402 SHEARGN HARRIS NUCLEAR POWER PLANT, UNIT 3

- O Adjudicatory correspondence
- 8210120103 Add1 response to FD]A request for nine categories of records generated by present RRC Commissioners, primarily Chairman Palladino 1 Commissioner Roberts & White House Forwards App B documents
  App B documents
  FELTON J H Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project 3pp 15690 [17 24X Fiche 50-000, 82/07/12 82/0120103
- --8210120123 Forwards memorandum % order re Council of NC objection to util request for exemption to perform certain site preparation work Hemorandum addresses exemption question & sets out history of Commission regulation. Section 50-12 ROBERTS.T H. Commissioners 81/12/09 PALLADIND.N. Commissioners 1p 15/90-124 24% Fiche 50-000.82/07/[2, 82/0120103
- --B210120102 Hemolandum & order re Council of NC objection to util request for exemption per revised NEPA regulation to perform certain site preparation work NEPA does not bar preliminary work Site preparation work properly authorized BENDER.P C. Atomic Energy Commission 74/06/11 Atomic Energy Commission 74/06/11 Atomic Energy Property Strike 50-000,82/07/12, RP010120103

DRIFFT 50-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4

request for name categories of records signers, primarity Chairman " "hite House Forwards

> rds 82/07/12 UDELL:R A 190 [17 24X

> > NC abjection to

e.

--8210120132 Memorandum & order re Council of NC objection to util request for exemption per revised NEPA regulation to perform certain site preparation work NEPA does not bar preliminary work Site preparation work properly authorized BENDER.P C Atomic Energy Commission 74/06/11 Atomic Energy Commission 9pp 15690-125 24X Fiche 50-000.82/07/12.8210(2010)

DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3

- A Application/construction stage documents & correspondence
- 6210070016 Forwards request for add1 info re 820708 application for CP extension of Unit 3 Info needed to assess environ impact of allowing CP for Unit 4 to expire ADENSAM.E O Licensing Branch 4 82/09/22 FERGUSON.J H Virginia Electric & Power Co 3pp 15646 301 24X Fiche 50-404,82/09/22.8210070016
- B210040277 Advises of plans for const of new 230 kV transmission line to connect North Anna power station to Louisa substation NO Tech Spec or ETS change required LEASBURG, R H Virginia Electric & Power Co. B2/09/27 DENTON, H R Office or Nuclear Reactor Regulation. Director CLARK, R A Operating Reactors Brainh 3 2pp 15591 204 24x Fiche 50-338, 82/09/27. 8210040277
- ~-8210040325 Advises that proposed 230 kV transmission line between Naiji Anna & Louisa need not be evaluated in amend to environ rept for North Anna 1 & 2 Line is not part of North Anna utilization facility RAGONE: S Virginia Electric & Power Co 74/01/02 MULLER.D R Atomic Energy Commission 2pp 15591 329 24X Fiche 50-338.82/09/27.8210040277
- 8210180418 Advises that RL Tedesco no longer employed by NRC T Novil is Assistant Director for Licensing ADENSAM.E G Licensing Branch 4 82/10/01 FERGUSON.J H Virginia Electric & Power Co 2pp 15745 288 24X Fiche 50-404,82/10/01 8210180418
- O Inspection reports, IE Bulletins & correspondence
- 8210010380 Forwards IE Insp Rept 50-404/82-10 on 820830-0702 No noncompliance noted DANCE/N C Division of Project & Resident Programs 82/07/13 LEASBURG, R H Virginia Flettric & Power Co Rpp 15573 081 24X Ficha 50-404,82/09/13,8210010380
- --8210010384 IE Insp Rept 50-404/82-10 on 920830-0902 No noncompliante noted Major areas inspected storage, preventive maint, measuring & test equipment calibr & followup on licensee identified items

  MERFINEATHER, N., CONLON, T.E. Division of Engineering & Technical Programs 82/09/09 4pp 15573-083 24X Fiche 50-404, 82/09/13, 8210010380

DOCKET 50-409 NORTH ANNA POWER STATION, UNIT 4

- A Application/construction stage documents & correspondence
- 8210070016 Forwards request for add1 info re 820708 application for CP sxtension of Unit 3 Info needed to assess environ impact of allowing CP for Unit 4 to expire ADENBAM. F. O. Licensing Branch 4 82/09/22 FERGUSON. J. H. Virginia Electric & Power Co. 3pp. 19646-301 24X Fichs 50-404.82/09/22.8210070016
- 8210040277 Advises of plans for const of new 230 kV transmission line to connect North Anna power station to Louisa substation
  No Tech Spec or ETS change required
  LEASBURG, R H Virginia Electric & Power Co 82/09/27 DENFON.H R
  Office of Nuclear Reactor Regulation, Director 2pp 13591 204
  244 Fich 50-336,82/09/27,8210040277
- ~~8210040325 Advises that proposed 230 kV transmission line between Nerli Anna & Louisa need not be evaluated in amend to environ rept for North Anna I & 2 Line is not part of North Anna utilization facility RAGONE: 8 Virginia Electric & Power Co 74/01/02 MULLER, D X Atomic Energy Commission 2pp 15591 329 24X Ficha 50-338,82/09/27,8210040277

1

### DOCKET SO-409 LA CROSSE BOILING WATER REACTOR

- F Security, medical, emergency & fire protection plans
- 6210040184 Forwards IE Investigation Rept 50-409/82-09 on 620615-17 No noncompliance noted HIMO.J A Division of Emergency Preparedness & Operational Support 62/09/09 LINDER, F.W. Dairyland Power Cooperative 2pp 15582 001 24x Fiche 50-409/82/09/09/8210040184
- -8210040185 IE Investigation Rept 50-409/82-09 on 820615-17 No noncompliance noted Major areas inspected procedures & records & personnel interviews re health physics technicians listed in 820308 emergency plan. Revision 1 PHILLIP, G. A., PAGLIARO, J. A., WARNICK, R. F. Region 3, Office of Director 82/09/02 27pp 15582 CO3 24X Fiche 50-409, 82/09/09, 8210040184
- 621G040152 Forwards response to 820510 request for add1 info re rewrite or Section 8 of fire protection rule 10CFR50 48 Revised procedures re complete loss of electrical power temerency reactor cooldown from outside control room enci LINDER.F. Dairyland Power Cooperative 82/09/28 CRUTCHFIELD.D Operating Reactors Branch 5 70pp 15582 353 24X Fiche 50-409.82/09/28.8C10040152
- 8210130365 Forwards info re containment leak testing.per NRC 820824 request Info withheld (ref 10CFR73 21)
  LINDER,F Dairyland Power Cooperative 82/09/28 CRUTCHFIELD.D Operating Reactors Branch 5 1p 15630 246 24x
  Fiche 50-409.82/09/28.8210130365
- t-2[0]50497 Forwards IE Insp Rept 50-409/82-12 on 820701-0831 No noncompliance noted STREETER, J.F. Division of Emergency Preparedness & Operational Support 82/09/28 LINDER, F.W. Dairyland Power Cooperative 2pp 15721 280 24% Fichs 50-409,82/09/28,8210150497
- --B210150502 IE Insp Rept 50-409/82-12 on 820701-0831 No noncompliance noted Hajor areas inspected operational safety verification, menthly maint k surveillance observation, LER fullewup & fire protection/provention annual insp BRANCH, M W Division of Emergency Preparedness & Operational Support WALKER, R D Region 3, Office of Director 82/09/21 Jpp 15721 282 20% Fiche 50-409/822/09/28,8210150497
- 92(0050339 Provides status of technical support ctr & emergency operations facility Basic technical support ctr & emergency operations facility established & used in emergency erercises
  L1/DFR.F Dairyland Powel Cooperative 82/09/29 EISENHUT, D @ Division of Licensing 2pp (5610-114 24X Fichs 50-409.82/09/29.
- 8210280045 Releases public version of revised emergency plan & revised emergency plan implementing procedures FELTON. JM Division of Rules and Records 82/10/08 Document Management Branch 1p 15861 347 24X Fiche 50-409.82/10/08.
- -9210280048 Forwards public version of Revision 3 to emergency plan & revised implementing procedures including Procedures EPP-2 re organization & operations during emergencies & EPP-14 re emergency plan training LINDER.F Dairyland Power Copperative 82/09/27 CRUTCHFIELD.D Operating Reactors Branch 5 ip 15841 348 24X Fiche 50-409, 82/10/08, 8210280045
- -8210280051 Forwards public version of Revision 3 to emergency plan & revised emergency plan implementing procedures, including Procedures EPP-1 re organization & operations during emergencies & EPP-14 re emergency plan training LINDER, F Dairyland Power Cooperative 82/09/15 KEPPLER, J G Region 3, Office of Director 2pp 15861 347 24X Fichs 50-409, 82/10/08, 8210280045
- --8210280053 Public version of Revision 3 to emergency plan \* Dairyland Power Cooperative 82/09/03 26pp 15861 351 24X Fiche 50-409,82/10/08,8210280045
- --8210280055 Public version of revised emergency plan implementing procedures including Procedures EPP-2 re organization & operations during emergencies & EPP-14 re emergency plan training LINDER.F Dairyland Power Cooperative 82/09/03 114pp 15862 015 24X Fiche 50-409.82/10/08.8210280045

- 8210220176 Responds to NRC 820915 ftr re IE Emergency Preparedness Insp. Rept 50-409/82-11 on 820803 Corrective actions Tech Spec change to energency operating facility data acquisition sysmill be installed & operating during Oct 1982
  LINDER: F. Dairyland Power Cooperative 82/10/11 HIND, J. A. Division of Emergency Preparedness & Operational Support 9pp 15777-295 24X Fiche 50-409, 82/10/11, 8210220176
- 8210250349 Forwards revisions to physical security, contingency & training & qualification plans Revisions withheld (ref 10CFR73 21)

  LINDER: F Dairyland Power Gooperative 82/10/20 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 15790 045 24x
  Fishe 50-409, 82/10/20, 8210250349
- 8210260371 Requests that R Walker be added to Enci 1 of 820715 ltr to provide for unescorted access to vital & protected areas KEPPLER, J O Region 3. Office of Director 82/10/20 LINDER, F W Dairyland Power Couperative 1p 15803 106 24X Fiche 50-409, 82/10/20. 8210260371
- 8210290129 Forwards IE Safeguards Insp Rept 50~409/82-16 on 820920-24 & notice of violation betails & notice of violation withhold (ref 100FR73 21)
  MILLER, J. R. Division of Engineering & Technical Programs 82/10/26 LINDER, F. W. Dairgland Power Cooperative 2pp 15853 355 24X Fiche 50~409, 82/10/26.8210290129
- --8210290137 IE Safeguards Insp Rept 50-409/82-16 on 820920-24
  Noncompliance noted security equipment not alarm equipped & not tested properly Details withheld (ref 1007R73 21)
  PIRTLE-0 L. OREED.J R Region 3. Office af Director 82/10/20
  2pp 15853 357 24% Fiche 50-409.82/10/26.8210290129
- J Insurance & indemnity information
- 8210220007 Responds to NRC 820812 questions re util request for exemption from requirements of 10CFR50 54(w) concerning property insurance
  LINDER.F Dairyland Power Cooperative 82/09/13 SALTZMAN. J
  Assistant Director for State & Licensee Relations 5pp 15778 214
  24X Fichs 50-409,82/09/13,8210220009
- P Operating license stage documents & correspondence
- 8210010369 Forwards revised Page 36g to Tech Specs, per 820915 proposed amend to License DPR-45 LINDER, F Dairyland Power Cooperative 82/09/23 CRUTCHFIELD, D Operating Reactors Branch 5 1p 15574 291 24X Fiche 50-409, 82/09/23, 8210010389
- ---B210010374 Revised proposed Page 34g to Tech Specs re radioactive gaseous effluent monitoring instrumentation # Dairyland Power Cooperative 82/09/23 1p 15574 292 24X Fiche 50-409.82/09/23, B210010389
- 82/0040067 Forwards safety evaluation of util 820305 to 0826 assessments of SEF Topic XV-1, "Decrease in Feedwater Temp, Increase in Feedwater Flow to Increase in Steam Flow " Evaluation will be basic input to integrated safety assessment Topic complete CRUTCHFICLD.D Operating Reactors Branch 5 82/09/29 LINDER, F Dairyland Power Cooperative 15pp 15581 220 24X Fiche 50-409, 82/09/29, 8210040067
- 8210050065 Informs that preliminary review of submittal re TMI Action Item II K 3 17. "Rept on Outages of ECCS" completed Add1 info required to complete review requested within 30 days of receipt of ltr GRUTCHFIELD. D. Operating Reactors Branch 5 82/09/29 LINDER,F Dairyland Power Cooperative 2pp 15603 229 24X Fiche 30-409,82/09/29.8210050065
- --8210050068 "ECCS Repts (F-47), TMI Action Plan Requirements, Dairyland Power Cooperative, LACBMR, "request for add info VUSBURY,F M., OVERBECK, G J Franklin Institute/Franklin Research Center NRC-03-81-130 RAI-C5506-196 82/08/25 CHOM,E NRC-No Detailed Affiliation Given 5pp 15603 231 24X Fichs 50-409, 82/09/27, 8210050065
- 8210050067 Application to amend License DPR-45, revising Tech Specs re safety valves installed on RCS. LINDER, F Delryland Fower Cooperative 82/07/29 CRUTCHFIELD, D Operating Reactors Branch 5 5pp 15603 196. 24X Fiche 50-407, 82/09/29, 8210050067
- --8210050070 Proposed Tach Specs re-safety valves installed on RCS
  \* Dairyland Power Cooperative 82/09/29 26pp 19603 201 24x
  Fiche 50-409,82/09/29,8210050067

- E210130326 Comments on proposed scope of Phase III of SEP as reflected in individual topic definitions appended to 820909 ltr Staff encouraged to develop & implement means to incorporate positive attributes of Phase III in licensee/NRC interface KACICH.R M SEP Dwners Group 82/10/07 EISENHUT, D @ Division of Licensing 7pp 15682 179 24X Fichs 50-000.82/10/07,8210130326
- 8210180183 Provides guidance & clarification for response to NUREC-0737. Item IT 8 3 "Post-Accident Sampling Sys;" per 820630 request for additinfo CRUTCHFIELD. D. Operating Reactors Branch 5 82/10/07 LINDER.F Dairyland Power Comperative 3pp 15718 179 24X Fiche 50-409, 82/10/07.8210180183
- 8210220272 Forwards final topic evaluation for sys aspects of safe shutdown requirements for SEP Topics V-10 A.V-11 B & VII-2, "RHR Reliability," "RHR Interlock Requirements," & "Sys Required for Safe Shutdown," respectively CRUTCHFIELD.D. Operating Reactors Branch 5 82/10/07 LINDEK, F Dairyland Power Cooperative 53pp 15775 140 24% Fiche 50-409, 82/10/07, 8210220272
- 8210150203 Forwards completed Table Loriginally submitted w/NRC 82082/ evaluation of SEP Topic VI-4, "Containment Isolation Sys" Containment mode made since 1964 comply w/DRN--NSIC-5 LINGER: Dairyland Power Copperative 82/10/08 CRUTCHFIELD D Operating Reactors Branch 5 Jpp 15701 320 24x Fiche 50-407:82/10/08.8210150203
- 8210150375 Forwards safety avaluation re SEP Topic XV-9, "Startup of Inactive Loop or Recirculation Loop at Incorrect Temp "Plant in conformance w/SRP Sections 15 4 4 & 15 4 5 requirements & analysis acceptable CRUTCHFIELD.D Operating Reactors Branch 5 82/10/12 LINDER, F Dairyland Power Cooperative 7pp 15715 166 24X Fiche 50-409, 82/10/12, 82/0150375
- B210190446 Provides unresolved safety issue status, in response to 820606 request
  LINDER:F Dairyland Power Cooperative 82/10/13 LAINAS.0 C
  Assistant Director for Safety Assessment 7pp 15740 162 24X
  Fiche 50-409, 82/10/13.8210190446
- 8210200015 Forwards evaluation of SEP Topic VI-1. "Organic Matls & Post-Accident Chamistry" Design meets licensing criteria for topic based on consideration of unique noncirculating ECCB design.
  CRUTCHFIELD. B Operating Reactors Branch 5 82/10/14 LINDER:F Dairyland Power Cooperative App 15757 334 24X Fichs 80-409.82/10/14.8210200015
- 8210200025 Forwards evaluation of SEP Topic XV-16. "Radiological Consequences of Failure of Small Lines Carrying Primary Coolant Dutside Containment LACBUR " Facility meets current licensing criteria for topic CRUTCHFIELD.D Operating Reactors Branch 5 82/10/14 LINDER.F Dairyland Power Cooperative Spp 15755 028 24X Fiche 50-407.82/10/14.8210200025
- 8210200031 Forwards evaluation of SEP Topic XV-20. "Radiological Consequences of Fuel Damaging Accidents " Evaluation will be included in integrated safety assessment Thyroid dose at exclusion area boundary within 10CFR100 requirements CRUTCHFIELD.D Operating Reactors Branch 5 62/10/14 LINDER.F Dairyland Power Cooperative Spp 15757 329 24X Fiche 50-409.82/10/14.8210200031
- 8210200038 Forwards evaluation of SEP Topic XV-19, "LDCA Resulting From Spectrum of Piping Breaks Within RCPB (Radiological) LACSHR," Util mests current licensing criteria for topic CRUTCHFIELD, D. Operating Reactors Branch 5 82/10/14, LINDER, F Dairyland Pouer Cooperative 5pp 15757 299 24X Fiche 50-407, 82/10/14, 8210200038
- 8210220449 Forwards safety evaluation & supporting technical rept for licensee BIEQOB proposed electrical sys design mods & Tech Spec changes re degraded grid voltage protection Proposed changes acceptable SEP Topic VIII-I A complete.

  CRUTCHFIELD. D. Operating Reactors Branch 5 82/10/14 LINDER, F. Dainyland Power Cooperative 7pp 15778 339 24X

  Fichs 50-409, 82/10/14.8210220449
- 8210200016 Forwards evaluation of SEP Topic II-2 C re atmospheric transport & diffusion characteristics for accident analysis. Section V X/Q values appropriate for estimating exposures & should be used in all but steam line break calculations CRUTCHFIELD. Operating Reactore Branch 5 82/10/15 LINDER, F Dainyland Power Cooperative 4pp 15752 357 24X Fiche 50-409, 82/10/15, B210200016

į

; ;

- 8210210246 Advises NUREG-0737. [tem II K 3 27. "Common Ref Level." complete since util committed to eliminate potential operator confusion when changing water level instrumentation by integrating Items II K 3 27 L I D 1 CRUTCHFIELD. D Operating Reactors Branch 5 82/10/15 LINDER. pairyland Power Cooperative 2pp 15766 245 24X Fiche 50-409. 82/10/15.8210210246
- 8210260317 Advises that TMI Itoms II B 3 % II F i 2. "Reactor Versel Liquid" % "Stack Effluent Sampling Sys," respectively, were campleted on 820927 prior to refueling outage TMI Item III D 3 4 will be completed by 830101 LINDER.F Dairyland Power Cooperative 82/10/20 EISCNHUI, B () Division of Licensing 1p 15805 227 24X Fiche 50-409, 82/10/20 8210260319
- 8210290307 Submits summary of review of SEP Topic III-3 A re effects of design basis flood on containment & turbine bldg structures Response satisfies NRC requirement for addl flooding effects into LINDER:F Dairyland Power Cooperative 82/10/22 CRUTCHFIELD, P Operating Reactors Branch 5 3pp 15853 167 24x Fiche 50-409.82/10/22, 8210290307
- B210290151 Forwards summary of outages of manual depressurization system in 1974-1980 per NRC 820929 request re TMI Action Item It & 3 17 Sys performed adequately during reporting period Sys used for testing only LINDER.F Dairyland Power Cooperative 82/10/25 CRUTCHFICLD.D Operating Reactors Branch 5 2pp 15853 151 24X Fiche 50-409, 82/10/25, 8210290151
- 8210280289 Forwards evaluation of SEP Topic IX-1. "Fuel Storage." based on 820226 safety assessment rept t 820831 addl info Fuel storage facilities acceptable Evaluation will be basic input to integrated safety assessment CRUTCHFIELD. D. Operating Reactors Branch 5 82/10/26 LINDER./ Dairyland Pouer Cooperative 7pp 15837 033 24X Fishe 50-409, 82/10/26, 8210280289
- Q Inspection reports, (E Bulletins & correspondence
- 8210040184 Forwards IC Investigation Rept 50-409/82-09 on 820615 17 No noncompliance noted MINO.J A Division of Emergency Preparedness & Operational Support 82/09/09 LINDER.F W Dairyland Power Cooperative 2pp 15582 001 24X Fiche 50-409.82/09/09.8210040184
- --8210040185 IE Investigation Rept 50-409/82-09 on 820615-17 No noncompliance noted Major areas inspected procedures & records & personnel interviews re health physics technicians listed in 820308 emergency plan. Revision 1 PHILLIP. 6 A. PAGLIARO, J. A. HARNICK. R. F. Region 3. Office of Director 82/09/02 27pp 13582 003 24X Fiche 50-409.82/09/03, 8210040184
- 8210130400 Forwards IC Insp Rept 50-407/82-14 on 820807-13 & notice of violation KEPPLER, J G Region 3, Office of Director 82/07/24 LINDER, F H Dairyland Power Cooperative 2pp 15682 072 24X Fiche 50-407, 82/09/24, 8210130400
- --9210130403 Notice of violation from insp on 820809~13 KEPPLER, J O Region 3, Office of Director 82/09/24 2pp 15682 074 24X Fiche 50-409,82/09/24,82/0130400
- --B210130408 IE Insp Rept 50-409/B2-14 on B20807-13 Noncompliance noted radiation levels in excess of DOT regulations, failure to meet burial sites acceptance critoria & uncontrolled release of radioactive liquide
  PAULIR A Division of Engineering & Technical Programs
  OREOERIL R Region 3, Office of Director 82/07/20 Spp
  15682-076 24X Fiche 50-409, B2/09/24, B210130400
- ---B210130416 Discusses apparent violation of 10CFR49 by util re radvasts shipment containing radioactive low-specific activity on 920730 Readings from util & Chem Nuclear Sys, Inc instruments show apparent discrepancy

  SHAFER,P W Dairyland Power Cooperative 82/08/19 OREGER,L R
  Division of Project & Resident Programs 12pp 15692 084 24X
  Fiche 50-409,82/09/24,8210130400
- 8210150497 Forwards IE Insp Rept 50-409/82-12 on 820701-0831 No noncompliance noted 8TREETER.J.F Division of Emergency Preparedness & Operational Support 82/09/28 LINDER.F.W Dairyland Power Cooperative 2pp 15721 280 24X Fiche 50-409.82/09/28,8210150497

- --8210150502 IE Insp Rept 50-409/82-12 on 820701-0831 No noncompliance noted Major areas inspected operational safety verification. monthly maint 5 surveillance observation, LER followup 5 fire protection/prevention annual insp granch, M W Division of Emergency Preparedness 5 Operational Support WALKER, R D Region 3, Office of Director 82/09/2170 15721 282 24% Fiche 50-407.82/09/28,8210150497
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds" Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000, 82/10/06, 8208190233
- 8210130211 Confirms conversation between J Taylor & R Walker rescheduling mgt meetings for 821019 at facility to discuss systematic assessment of licenses performance Second meeting uill failow to discuss regulatory improvement program SPESSARD, R L Division of Project & Resident Programs 82/10/07 LINDER, F W Bairyland Power Cooperative 1p 15674 116 24X Fiche 50-409, 82/10/07,8210130211
- 8210220174 Responds to NRC 820915 ltr re IE Emergency Preparedness Insp. Rept 50-409782-ii on 820803 Corrective actions Tech Spec change to emergency operating facility data acquisition sysmill be installed & operating during Oct 1982 LINDER: F Dairyland Power Cooperative 82/10/11 HIND. J A Division of Emergency Preparedness & Operational Support 9pp 15777 295 24X Fichs 50-409,82/10/11.8210220176
- 8210190638 Ack receipt of 820910 ltr informing NRC of ateps taken to correct violations noted in IE Insp Rept 50-409/82-07 SPEBSARD, R L Division of Project & Resident Programs 82/10/13 LINDER, F W Dairyland Power Cooperative 1p 15740 049 24X Fiche, 50-409, 82/10/13,8210190638
- --8210190454 Responds to NRC 820812 ltr reviolations noted in IE Insp Rept 50-409/82-07 Corrective actions Tech Spec limits for primary systactivity & chemistry entered onto water chemical & radiochemical analyses rept LINDER, F. Dairyland Power Cooperative 82/09/10 KEPPLER, J. G. Region 3, Office of Director Spp. 15740-050 24X Fiche 50-409, 82/10/13,8210190658
- 820819023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl DEYQUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- 8210190433 Confirms J Taylor & R Walker conversation re scheduling of two mpt meetings Meetings will be held 821105 at LaCrosse, Wi to discuss systematic assessment of licensee performance & regulatory improvement program SPE6BARD, R L Division of Project & Resident Programs 82/10/15 LINDER, F W Dairyland Power Cooperative ip 15741 165 24X Fiche 50-409, 82/10/19,8210190433
- 8210210336 Forwards evaluation of SEP Topic III-3 C, "Inservice Insp of Mater Control Structures," based on Licensee 820127 safety assessment Insp program does not conform w/intent of Reg Ouide 1 127 & should be modified CRUTCHFIELD.D Operating Reactors Branch 5 82/10/15 LINDER, F Dairyland Power Cooperative 9pp 15765 054 24X Fiche 50-409, 82/10/15, 8210210336
- 8210250106 Confirms convarsation between J Taylor & R Walker rorescheduling two mgt meetings Meetings will be held 821109 to discuss systematic assessment of licenses performance & regulatory improvement program
  SPEBSARD, R L Division of Project & Resident Programs 82/10/18.
  LINDER: F. W Dairyland Power Cooperative 1p 15787 073 24X Fiche 50-407, 82/10/18, 8210250106
- 8210290127 Forwards IE Bafeguards Insp Rept 50-409/82-16 on 820920-24 & notice of violation Details & notice of violation withheld (ref 100FR73 21) MILLER.J.R Division of Engineering & Technical Programs 82/10/26 LINDER.F W Dairyland Power Cooperative 2pp 15853,355, 24% Fichs.50-409,82/10/26,8210270129
- --8210290137 IE Bafeguards Insp Rept 50-407/82-14 on 820920-24 Nancompliance noted security equipment not alarm equipped & not tested properly Details withheld (ref 10GFR73\_21) PIRTLE,0 L., QREED,J R. Region 3. Office of Director 82/10/20 2pp 15853:357. 24X Fiche.50-409.82/10/26.8210290129

- S Reportable occurrences, LERs & related correspondence
- 82(0050353 PNO-III-82-091A on 820926, plant returned to svc following removal of blockage in emergency high pressure core spray sys lines Blockage caused by silt entering sys through interconnection w/svc water sys Silt removed WALKER, R. JORDAN, M. Region 3, Office of Director 82/09/29 ip 15608 255 24% Fichs 50-407, 82/09/27, 28/20050353
- 8210190448 Forwards LER 82-017/03L-0 Detailed event analysis submitted LINDER, F. Dairyland Power Cooperative 82/10/11 KEPPLER, J. G. Ragion 3, Office of Director 2pp 15740 170 24X Fiche 50-409, 82/10/11, 8210170448
- --8210190454 LER 82-017/03L-0 on B20926, during Mode 4, high pressure svc water containment isolation valve closed Caused by air leak due to loose fitting on valve operator air supply line Air supply line fitting tightened V valve reopened GDDMAN, L S Dairyland Power Cooperative 82/10/11 Region 3, Office of Director Ip 15740 172 24X Fache 50-409, 82/10/11, 8210190448

DOCKET 50-410 NINE MILE POINT NUCLEAR STATION. UNIT 2

- H General correspondence
- 8210210322 Requests changes to NRC correspondence distribution list TB Conner replaces LM Trasten & CD Hobelman JN Keib should be added to list MANGAN.C V Niegara Mohawk Power Corp 82/09/10 DIRCKS,W J Diffice of the Executive Director for Operations Ip 15764 222 24X Fiche 50-410,82/09/10.8210210332
- Q Inspection reports. IE Bulletins & correspondence
- 8210040170 Advises that util response to IE Bulletin 80~14 will be submitted by 830131 instead of 820930 MAKNO, 8 F Niagara Mohauk Power Corp 82/09/23 HAYNES, R C Region 1. Office of Director 1p 15582 314 24X Fiche 50~410,82/09/23,8210040170
- 8208190233 IR Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000, 82/10/06, 8208190233
- 8210270415 Notification of 821020 enforcement conference in Region 1 ofc w/wbi) to discuss GA insp BAUNACKH NRC - NO Detailed Affiliation Given 62/10/13 DIRCKS.W J Office of the Executive Director for Operations STELLO.V Regional Operations & Generic Requirements DEYOUNG.R C Director's Office. Office of Inspection and Enforcement ip 15833 283 24X Fiche 50-410,82/10/13,8210270415
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants" Syc list encl
  DEYGUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York
  115pp 19810 125 24X Fiche 50-000, 82/10/14,8208190239
- 8 Reportable occurrences, LERs & related correspondence
- 8210040071 Final deficiency rept re control bldg termination cabinet support sills Initially reported on 820615 Welded stude to be replaced by drilled-through anchor botts bied directly to base concrete Work will be completed by 820930 MANNO.5 F Niagara Hohawk Power Corp 82/07/23 STARQSTECKI.R Division of Project & Resident Programs 2pp 15581 276 24X Fiche: 50-410, 82/09/23, 8210040071
- 8210040190 Final deficiency rept re Rosemount Model 1152 transmitters w/gutput Codes A & D Transmitters do not use A or D amplifier boards Deficiency per 10CFR50 55s not valid Reportable per Part 21 by GE HANNO.5 F Niagara Mohauk Power Corp 82/07/23 STAROSTECKI.R Division of Project & Resident Programs 2pp 15583 189 24X Fiche 50-410.82/09/23.8210040190
- 8210180129 Interim deficiency rept re ASME III Class 1 joints welded w/ASME Class 2 k 3 welding procedures Contrary to 820831 Itr, deficiency deemed reportable per 10CFR50 55(e) MANNO.S.F Niagara Mohawk Power Corp 82/10/06 STAROSTECKI, R Division of Project & Resident Programs 1p 15497 069 24X Fiche 50-410, 82/10/06, 8210150129

11

- 8210250378 Interim deficiency rept re insufficient environ &/or seismic qualification documentation of listed control room equipment Initially reported on 820921 Final rept will be submitted by 821231 MARNO, S.F. Niagara Mohauk Power Corp. 82/10/15 STAROSTECKI, R. Division of Project & Resident Programs. 2pp. 15790-139 24X Fiche 50-410, 82/10/15, 8210250378
- DICKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 6210120031 Summary of 820831 meeting w/util in Bethesda.MD recontents of CL application % to introduce project mgt personnel Application trequested deferral of FSAR Chapter 18 until finalization of NUREG-0800 DOCLITICE.E L Licensing Branch 1 82/09/10 Licensing Branch 1 3pp 15689 197 24X Fiche 50-412.82/09/10.8210120031
- Q Inspection reports. IE Bulletins & correspondence
- 8210050211 Forwards [E Insp Rept 50-412/62-10 on 820809-13 No noncompliance noted MARTIN.T? Division of Engineering & Technical Programs 82/09/17 MODLEVER.E J Duquesne (ight Co 2pp 15615 089 24X Fiche 50-412.822/09/17.8210060211
- --B210060215 tE Insp Rept 50-412/82-(0 on 820807-13 No noncompliance noted Hajor areas inspected records re reactor pressure vessel storage 5 maint at site, vessel lift & transportation 5 final rigging 6 installation VARELA.A A. DURR.JP Region 1 Office of Director 82/09/11 6pp 15615 091 24X Fiche 50-412-82/09/17-8210060211
- 8208(90203 IE Info Notice 80-35. Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Syc list enc! COB6.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000,82/10/06.8208(90233
- 52/8190208 IE Bulletin 92-03, "Stress Corrosion Cracking in Thick-Hall-Large-Diameter: Stainless Steel Recirculation Sys Piping at BMR Plants" Svc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 82/60/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- S Reportable occurrences, LERs & related correspondence
- 8210070155 Final Significant Deficiency Rept 82-05 re misapplication of torquing equipment on emergency diesel generators shaft spider assemblies Retorquing of all fasteners to vendors specified value of 5.000 ft lb has been performed MIDILEVER.E J. Duquesne Light Co. 82/09/24 HAYNES.R C. Region 1, Office of Director 2pp. 15627-069 24X Fiche 50-412,82/09/24, 8210070155
- 6210070233 Interim deficiency rapt re Westinghouse solid state protection sys Initially reported on 620830 Vendor reviewing on-line test circuitry design Next rept will be submitted by 630520 HOCLEVER, E. J. Duquesne Light Co. 62/09/29 HAYNFS, R.C. Region 1 Office of Director. 3pp. 15634 303 23X Fiche 50-412, 82/09/29, 8210070233
- 8210280143 Interim Significant Deficiency Rept 82-06 re sheared pinion teys in Linitorque notar operators supplied by Westinghouse Initially reported on 820901 Keys replaced Westinghouse will provide data for completing corrective action MCLLEVER.E J Duquesne Light Co 82/10/07 HAYNES.R Region [, Office of Director App 15797 085 24X Fiche 50-412,82/10/07,
- 8210260135 Interim Significant Deficiency Rept 82-02 re gossible inaccuracy in two RCS wide-range pressure transmitters. Initially reported on 820512 New Mestinghouse (info being evaluated flext rept expected by 830228 WOOLEVER, E. J. Duquesne Light Co. 92/10/18 HAYNES, R. Region 1, Office of Director App. 15799 079 24X Fiche 50-412,82/10/18, 2010/24/135

- DOCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 821001000B Responds to FOIA request for 19 categories of documents rancelear reactor events & safety problems Forwards documents listed in App A FELTON. J M Division of Rules and Records 82/06/28 UDELL, R A Critical Mass Energy Project 15pp 15727 005 24X Fichs 50-000, 82/06/28, 8210010008
- --BOOSOSO265 Discusses add1 required info to better define potential far cracking in reactor vessel noticles MDDXAN.V S Assistant Director for Materials & Qualifications Engineering 80/05/05 TEDESCOR L Assistant Director for Licensing 2pp 15727 176 24X Fiche 50-000,82/06/28,8210010008
- 8210050264 Forwards summary of 820406-07 meeting in Bethesda, HD & 820419-22 meeting in Charlotte, NC w/Mechanical Engineering Branch, Westinghouse & BNML relitems in NRC 820129 ltr W/sight oversize drawings Aperture cards are in PDR TUCKER. H B Dute Power Co 82/09/27 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E. G. Licensing Branch 4 343pp 15606 060 24% Fiche 50-413.82/09/27,8210050264
- 8210070092 Forwards minutes of meeting held during wk of 820419
  w/Mestinghouse & Mechanical Engineering Branch discussing
  resolution of FSAR Item 109 re fuel damping values Minutes
  withheld (ref 10CFR2 790)
  TUCKER.H B Duke Power Go 82/09/28 DENTON,H R Office of
  Nuclear Reactor Regulation, Director ABENSAM,E G Licensing Branch
  4 2pp 15628 079 24X Fiche 50-413,82/09/28,8210070092
- 92100503H4 Forwards revised FSAR pages reflecting organizational changes & changes to Chapter 13 Changes will be included in Revision 7 to FSAR TUCKER.H B Duke Power Co 82/09/29 DENTON.H R Office of Nuclear Reactor Regulation. Director ADENSAM.E G Licensing Branch 4 28pp 15408 201 24X Fiche 50-413.82/09/29, 82100503H4
- G2i0190071 Notification of B2i006 meeting w/util in Charlotte,NC to discuss matts design General Design Criterion 51 JACDOURK N Licensing Branch 4 B2/09/29 ADENSAM.E & Licensing Branch 4 Spp 15761 095 24X Fiche 50~413,02/09/29,021019607
- 8210050130 Provides fifth quarterly update of projected const completion date Plant 90% complete as of 820718 Fuel load scheduled for Dct 1984 TUCKER. H B Duke Power Co 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation. Director ADENSAM, E G Licensing Branck 4 App 19605 045 24X Fiche 50-413, 82/09/30.8210090130
- 6210060311 Informs that review of plant operations relative to void formation in vessel head during transients completed Assessment of facility procedures in training program per General Ltr 81-21 enci
  TVCKER: H B Duke Power Co 82/09/30 DENTON, H R Office of Nuclear Resolutor Regulation, Director ADCMSAME G Licensing Branch 4 App 15619 190 24X Fiche 50-413, 82/09/30, 8210060311
- 8210150094 Application for Amend 2B to CPPR-116 & CPPR-117, consisting of Revision 6 to FBAR & Revision 1 to license application TUCKER-H B Duke Power Co 82/10/12 DENTON-H R Office of Nuclear Reactor Regulation. Director ADENSAM, E O Licensing Branch 4 22pp 19699 001 24X Fiche 50-410-82/10/12, 8210150094
- 8210220026 Summary of 820907-09 site visit & meetings w/util re Instrumentation & Control Sys Branch concerns & open items Rasponses to open items will be provided by end of Oct 1982 Summary & status of concerns & open items encl JABBDUR, K N Licensing Branch 4 82/10/15 Licensing Branch 4 9pp 15786 292 24X Fiche 50-413.82/10/15.8210220026
- 8210260201 Revises WO Parker 820701 ltr re schedule for submission of info needed to resolve concerns identified in DO Eisenhut 801222 ltr & NUREO-0612 Info requested in Bections 2 2 k 2 4 of Encl 2 to be submitted by 821124 TUCKER: H B Dute Pawer Co 82/10/21 DENTON, H R Office of Nuclear Resolven Regulation, Director ADENBAME O Licensing Branch 4 1p. 15804 271 24X Fiche 50-413,82/10/21.8210260201
- D NRC Draft/Final Environmental Statements, supple & correspondence
- B21004032R Comments on historic & archeologic impacts, water qualityentrainment, thermal discharge & post-operational monitoring discussions in DES BLANCHARD, B. Interior, Dept of BR/09/30 ADENSAM, E.Q. Licensing Branch 4 Spp. 15586 195 24X Fiche 50-413, B2/09/30, B210040322

ľ

- 3210130117 Advises that DES is rated LO-1 Normal operation of facility will not have significant impact on environ No addl info
- MOORE, S. N. Environmental Protection Agency 82/10/06 JUBBBUR. K. N. Division of Licensing 2pp 15673 007 24% Fiche 50-413, 82/10/06. 82/01/30/17
- 3210130487 Forwards comments on DES (NUREG-0921) re operation of facilities
- facilities LGCHSTET.H A Pennsylvania State Univ 82/10/06 Division of Licensing 7pp 15682 140 24X Fiche 50-413.82/10/06.8210130487
- 210130506 Comments on DES List of water users in downstream order to be contained in FES.encl TURNER, L E South Carolina, State of 82/10/07 JABBOUR, K N Division of Licensing 3pp 19682 253 24X Fiche 50-413,82/10/07,
- 210250102 Forwards comments on DES.per 10CFR51 TUCKER.H B Duke Power Co 82/10/07 DENTON.H R Office of Nuclear Reactor Regulation, Director EISENHUT.D Ø Licensing Branch 4 14pp 15791 f91 24X Fiche 50-413.82/10/07.8210250102
- 210180106 Advises that review of DES for facility has been completed Clearance valid for 1 yr CROMER.D L South Carolina, State of 82/10/00 Office of Nuclear Reactor Regulation, Director 1p 15719 318 24X Fiche 50-413,82/10/08.8210180106
- 210180169 Comments on DES (NUREO-0921) & public health & safety impacts of proposed plant operation VILLFORTH, J C Food & Drug Administration 82/10/12 JABBDUR, K N Division of Licensing 2pp 15719 166 24X Fiche 50-413,82/10/12,8210180169
- PIOZEO150 Requests encl comments on DES be transmitted to appropriate NRC ofc DES summary of cost/benefit in Table & I deficient RILEY. J L Carolina Environmental Study Oroup 82/10/22 JASBOUR. K N Division of Licensing 3pp 15797 015 24X Fiche 50-413, 82/10/22, 8210260150
- NRC Safety Evaluation Report (SER), suppls & correspondence
- 10280065 Forwards responses to none (tems in EG Adensam 820609 ltr reauxiliary feedwater system draft SER.Section 7 1 3 1
  TUCKER.H B Duke Power Co 82/10/19 DENTON.H R Office of
  Nuclear Reactor Regulation, Director ADENSAME C Licensing Branch
  4 9pp 15837 263 24X Fishe 50-413.82/10/19.8210280065
- Security, medical, emergency & fire protection plans
- 09170053 Forwards Revision 3 to security plan Revision withheld (ref 100FR73 21) TUCKER, H B Duke Power Co 82/08/18 DENTON, H R Diffice of Nuclear Reactor Regulation, Director ADEMBAH, E 0 Licensing Branch 4 2pp 14910 093 24% Fiche 50-413, 82/08/18, 8209170053
- 10190611 Responds to 810723 request for schedule for installation of public notification sys at facilities Final design of sys & schedule for installation not finalized Info submittal anticipated by 821201

  TUCKER, H B Duke Power Co 82/10/08 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E G Licensing Branch 1, NENTON, F Federal Emergency Management Agency 2pp, 15737 221

  24X Fiche 50-413,82/10/08,8210190611
- Adjudicatory correspondence
- 0050202 Response opposing Palmetto Alliance & Carolina Environ Study Proup 820922 supplemental petitions to intervene GCGARRY.J M. Duke Power Co MCGARRY.J M Dehevoise & Liberman 82/10/04 Atomic Safety and Licensing Board Panel 71pp 5602 279 24X Fiche 50-413,82/10/04,8210050202
- #21005020B Response to Charlotte-Mecklenberg Environ Coalition 820919 revised Contention 4 Contention acceptable Notice of appearance & Centificate of 8vc encl MCGARRY, J M Duke Power Co MCGARRY, J M Debeyoise & Liberman 82/10/04 Abomic Bafety and Licensing Board Panel 4pp. 15602 350 24X Fiche 50-413.82/10/04.8210050202
- 0060991 Statement of position on DES contentions Objects to all almetto Alliance/Carolina Environ Study Group contentions xcept Contention 4 as specified Gertificate of Svc encl. OHNBON, 0 E Hearing Branch 4 B2/10/04 Atomic Safety and icensing Board Panel 26pp 15613 264. 24X Fiche, 50-413, 82/10/04, 210060191.

- 82100B0081 Notion to compel util to respond to Palmetto Alliance 820903 second set of interrogatories & requests to produce Certificate of Svc enil QUILD.R Palmetto Alliance QUILD.R Quild. R 82/10/04 Atomic Safety and Licensing Board Panel Spp 15640 199 24X Fiche 50-413.82/10/04.82100B0081
- 8210180182 Order extending time until 821112 for Commission to act to review ALAB-687 CHILK: S J Office of the Secretary of the Commission 82/10/14 Commissioners [p 15719 to4 24X Fiche 50~413.82/10/14. B210180182
- 8210200071 Provides response to ASLB questions at 821007-08 second special probability conference Questions relate to risks from McGuire facility & scope of evacuation costs listed in DES Table 5 ti
  JOHNSON, 6 E Hearing Branch 4 82/10/18 KELLEY, J L , FOSTER, R F , CALLIHAN, D Atomic Safety and Licensing Board Panel 2pp 15757 192 24% Fiche 50-413,82/10/18,8210200071
- 62t0210187 Motion for order to protect NRC from answering Palmetto Alliance Interrogatorias 1 & 36 on Contention 8 & Interrogatory 1 on Contention 27 Requests are for large amount of matt w/d regard to relevance JOHNSON 0 E Hearing Branch 4 82/10/19 Atomic Safety and Licensing Board Panel 3pp 15765 159 24% Fiche 50-413-82/10/19, 8210210187
- --8210210197 Responses to second set of interrogatories & requests to produce re Palmetto Alliance Contentions 8 & 27 Prof qualifications, NUREG/CR-2644 & Certificate of Svc encl JOHNSON, G E. Hearing Branch 4 82/10/19 Palmetto Alliance 134pp 15765 162 24X Fiche 50-413,82/10/19,8210210187
- 8210250125 Responses to Palmetto Alliance 920927 third set of interrogatories & requests to produce Related correspondence CARR, A V Duke Power Co 82/10/17 Palmetto Alliance 62pp 15787 243 24X Fiche 50-413.82/10/17.8210250125
- 8210250282 Motion for protective order relieving applicants from requirement to respond to Palmetto Alliance 820727 third set of interrogatories & requests to produce Certificate of Svc encl Related correspondence
  CARR, A V Duke Power Co 82/10/19 Atomic Safety and Licensing Board Panel 4pp 15791 078 24% Fiche 50-413,82/10/19.8210250288
- 8210250370 Forwards EIA re spent fuel storage of Oconee spent fuel at McGurre Unit 1 spent fuel pool,dtd Det 1978 Copies also sent to intervenors W/o enit UOHNSON,O E Hearing Branch 4 82/10/21 KELLEY,J L . FOSTER,R F . CALLIHAN,O Atomic Safety and Licensing Goard Panel 1p 15790 188 24X Fiche 50-413,82/10/21.82(0250370
- 8210260415 Answer opposing Palmetto Alliance 821004 motion to compail answers to interrogatories ASLB should issue order denying motion as lacking merit Motion devoid of supporting arguments Certificate of Svc encl CARR, A V Duke Power Co 82/10/22 Atomic Safety and Licensing Board Panel 20pp 15806 HS 24X Fiche 50-413, 82/10/22, 8210240415
- 8210270002 Answers ASLB question to Palmetto Alliance/Caroline Environ Study Group Contention 10 DEG totaled risks to public of accidents from each unit JOHNSON, 0 E Hearing Branch 4 B2/10/25 KELLEY, J. L., FOSTER, R.F., CALLIMAN, D. Atomic Safety and Licensing Board Panel 10 15817 011 24X Fische 50-413,82/10/25,8210270002
- B210270010 Advises that NRC does not intend to file response to Palmetto Alliance 821004 mution to compel discovery from applicants NRC responded to requests on 821017
  JOHNSON, 0 E Hearing Branch 4 B2/10/25 KELLEY, J L , FOSTER.R F , CALLIHAN, D Atomic Safety and Licensing Board Panel ip 15822 340 24x Fiche 50-413,82/10/25,82/0270010
- H General correspondence
- 8210130046 Responds to 820912 ltr request that NRC continue to send copies of correspondence to util on HcGuira Since McGuira proceedings complete & documents in LPDR.request denied.

  ADENSAM, E. Ø. Licensing Branch 4 82/09/28 RILEY. J. Carolina Environmental 86udy 0roup ip 15696 284 24X
  Fiche 50-000, 82/09/28, 8210130046

- V Utility Final Safety Analysis Report (FSAR) & amends
- G2ID150094 Application for Amend 28 to CPPR-116 & CPPR-117, consisting or Revision 6 to FSAR & Revision 1 to license application TUCKER.H B Duke Power Co 82/10/12 DENTON.H R Office of Nuclear Reactor Regulation. Director ADENSAM.E G Licensing Branch 4 22pp 15699 001 24x Fisch e 50-413.82/10/12.8210150094
- --8210150101 Revision 6 to FSAR

  4 Duke Pouer Co 82/10/12 761pp 15699 023 24X
  Fire 50-413, 82/10/12, 8210150094
- Q Inspection reports, IE Bulletins & correspondence
- 6210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events % safety problems Forwards documents listed in App A Downwents in App B completely withheld (ref FOIA Exemption 5)
  FELTON J M Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project 9pp 15665 027 24X
  Fishe 50-000, 82/07/12, 8210080015
  - 8210080136 Systematic assessment of licensee performance notes re vacility evaluation for Sept 1977-Aug 1980 \* NRC - No Detailed Affiliation Given 80/08/31 5pp 15668 057 24x Fiche 50-000, 82/07/12.821008015
- 5210010106 Forwards 1E Insp. Repts 50-413/82-22 & 50-414/82-20 on 820824-27 No noncompliance noted DANCE. M C Division of Project & Resident Programs 82/09/13 TUCKER. N R Duke Power Co 2pp 15567 174 24X Fiche 50-413, 82/09/13 8210010106
- --8210010110 IE insp Repts 50-413/82-22 & 50-414/82-20 on 820824-27 No noncompliance noted Major areas inspected independent inspeciforthreview of quality records for containment structures & supports & insertice review of program CCLEV.J L. BLAKE.J J. Division of Engineering & Technical Programs 82/09/09 10pp 15567 176 24X Fiche 50-413,82/09/13,8210010106
- B21001013: Ack receipt of B20907 thr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/82-18 & 50-414/82-16 & EHIS.R C Division of Project & Resident Programs 82/09/22 TUCKER.H B Duke Power Co ip 15565-351 24X Fiche 50-413.82/09/22.8210010131
- --8210010134 Responds to NRC 820809 ltm re violations noted in IE Insp. Repts 50-413/82-18 & 50-414/82-16 Corrective actions matis personnel training unil be completed by 820915 & paint storage barshouse will be upgraded by 821015 TUCKER.H & Duke Power Co. 82/09/07 O'REILLY, J.P. Region 2. Giffice of Director. 4pp. 15565-352 24X Fiche 50-413,82/09/22,81001013/
- --8210010138 Forwards IE Insp Repts 50-413/82-18 & 50-414/82-16 on B20712-16 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/08/09 TUCKER.H B Duke Power Co 2pp 10565 356 24X Fiche 50-413, 82/09/22, 8210010131
- --8210010141 Notice of violation from insp on 820712-16 \* Division of Project & Resident Programs 82/08/09 2pp 15965 358 24% Fichs 50-443, 82/09/22, 8210010131

- --8210220471 IE Insp Repts 90-413/82-24 & 50-414/82-22 on 820826-0910 N noncompliance noted Major areas inspected review of nonconforming items & following of IE circulars VANDOGRN,D K., BRYANT, J.C. Division of Project & Resident Programs 82/09/28 3pp 15779 If8 24X Fiche 50-413, 92/09/29, 8210220467
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 660p 1576/250 244 Fiche 50-000,82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thici-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Svc list encl DEYDUNO, RC Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 165pp 15810 125 24X Fiche 50-000,82/10/14,8208190238
- S Reportable occurrences, LERs & related correspondence
- 8210080208 Significant Deficiency Rept SD 413-414/B2-18 re radiogreshion came and performed on flux core welding filler matl ordered to SFA 5 20 Initially reported on 820903 Vendor committed to radiograph all matls Action to be completed by 830301 TUCKER.H B Duke Power Co B2/10/01 O/REILLY.J P Region 2, Office of Director 3pp 15640 086 24X Fiche 50-413,82/10/01. 8210080208
- 8210270119 Significant Deficiency Rept 9D 413/82-17 re linear indications identified on Kerotest valve body 90-551 on 820819 Initially reported on 820909 Valve returned to manufacturer Final rept will be submitted by 821108 TUCKER.H B Duke Power Co 82/10/08 D'RETLLY, J.P. Region 2. Office of Director 2pp 15854 024 24% Fiche 50-413.82/10/08.8210290119
- 8210290354 Significant Deficiency Rept SD 413-414/82-20 re inappropriate governor drive matl coupling supplied for diesel generator Initially reported on 820708 Manufacturer recommends replacement w/neoprene matl TUCKER, H B Duke Power Co 82/10/08 O'REILLY, J P Region 2, Defice of Director 3pp 15853 040 24X Fiche 50-413,82/10/08,6210290254
- 8210290250 Significant Deficiency Rept 413-414/82-11 re-potential failure to activate safeguards sys due to possible failure of switch contacts shunting proving lamp Revision to solid state protection sys will be made by Hestinghouse TUCKER.H B Duke Power Co 82/10/20 GRELLLY, JP Region 2. Orfice of Director 3pp 15834-096 24X Fiche 50-413.82/10/20
- T Hearing transcripts on non-antitrust matters
- 8210130207 Transcript of 821007 prehearing conference in Charlotte, MC Pp 380-567

  \* Atomic Safety and Licensing Board Panel 82/10/07 188pp 15673 272 24X Piche 50-413,82/10/07,8210130207
- 8210130238 Transcript of 821008 prehearing conference in Charlotte, NC Pp 548-455

  \* Atomic Safety and Licensing Board Panel 82/10/08, 88pp 15675 124 24X Fiche 50-413, 82/10/08, 8210130238
- V Operator Examinations

Ł

8210260065 Bummary of 820909 meeting w/util in Cornelius, NC rs cold license exam schedulo HILBON, B.A. Division of Engineering & Technical Programs JABBOUR, K.N. Licensing Branch 4 82/10/01 Division of Engineering & Technical Programs 21pp 15810 340 24X Fiche 50-413, 82/10/01. 8210260065

- DDCKET 50-414 CATAMBA NUCLEAR STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 8210010008 Responds to FDIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/06/28 UDELL.R A Critical Mass Energy Project 15pp 15727 008 24X Fiche 50-000.82/06/28.8210010008
- --8008050265 Discusses add1 required info to better define potential for cracking in reactor vessel nozzles NGDNAN,V S Assistant Director for Materials & Qualifications Engineering 80/05/05 TEDESCO.R L Assistant Director for Licensing 2pp 15727 176 24X Fiche 50-000,82/06/28,8210010000
- 8210050264 Forwards summary of 820406-07 meeting in Bethesda, MD & 820419-22 meeting in Charlotte, NC w/Mechanical Engineering Branch, Westinghouse & BNML relitems in NRC 820129 itr W/eight oversize drawings Aperture cards are in PDR 7UCKER, H B Dute Power Co 82/09/27 DENTON, H R Office of Nuclear Reactor Regulation. Director ADENSAME G Licensing Branch 4 343pp 15606 060 24% Fiche 50-413, 82/09/27, 8210050264
- 8210070092 Forwards minutes of meeting held during wk of 820419 u/Kestinghouse & Mechanical Engineering Branch discussing resolution of FBAR Item 109 re fuel damping values Minutes withheld (ref 10CFR2 790) TUCKER.H B Duke Power Co 82/09/28 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENBAM.E Q Licensing Branch 2pp 15528 079 24X Fiche 50-413.82/09/28,8210070092
- 6210050384 Forwards revised FSAR pages reflecting organizational changes to changes to Chapter 13 Changes will be included in Revision 7 to FSAR TUCKER.H B Duke Power Co. 82/09/29 DENION.H R. Office of Nuclear Reactor Regulation. Director ADENSAM.E G Licensing Branch 4 28pp 15408 281 24X Fiche 50-413.82/09/29.8210050384
- B2:0190071 Notification of B2:006 meeting w/util in Charlotte.NC to discuss matts design General Design Criterion 51 JABBOUR,K N Licensing Branch 4 B2/09/29 ADENSAM,E G Licensing Branch 4 3pp 15761 095 24X Fiche 50~413.82/09/29,82:0190071
- BR16060311 Informs that review of plant operations relative to void formation in vessel head during transients completed Assessment of facility procedures in training program per Ceneric Ltr BI-21 and UNIVER. If S Duke Power Co. BR2709730 DENTON. HR Office of NUCLER Reactor Regulation. Director ADENBAM. E. G. Licensing Branch 4 App. 15619 170 24X Fichs 50-413.82/09/30.8210060311
- 8210150094 Application for Amend 28 to CPPR-116 & CPPR-117, consisting of Revision 6 to FSAR & Revision 1 to license application FUCKER. H B Dute Power Co 82/10/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 22pp 15699 001 24X Fichs 50~413,82/10/12,8210150094
- 8210220026 Summary of B20907-09 site visit & meetings w/util re Instrumentation & Control Sys Branch concerns & open items Responses to open items will be provided by end of Oct 1982 Summery & status of concerns & open items encl JAUBDUR.K N Licensing Branch 4 82/10/15 Licensing Branch 4 9pp 15786 292 24X Fiche SO-413.82/10/15.8210220026
- 8210260201 Revises WO Parker 820701 ltr re schedule for submission of info needed to resolve concerns identified in DG Elsenhut 801222 ltr & NUREQ-0612 Info requested in Bections 2 2 & 2 4 of Encl 2 to be submitted by 821124
  TUCKER. H B Duke Power Co 82/10/21 DENTON. H R Office of Nuclear Reactor Regulation, Director ADENSAM. E G Licensing Branch 4 ip 15804 271 24X Fiche 50-413, 82/10/21. 6210260201
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8210040322 Comments on historic & archeologic impacts,water quality, entrainment: thermal discharge & post-operational monitoring discussions in DES BLANCHARD, B Interior. Dept of 82/09/30 ADENSAM, E Q Licensing Branch 4 3pp 15586 195 24X Fiche 50-413,82/09/30,8210040322
- B210130117 Advises that DES is rated LO~1. Normal operation of facility will not have significant impact on environ No addl info needed MOGRE.S N. Environmental Protection Agency 82/10/06 JUBBOUR.K N Division of Licensing 2pp 15673 007 24X Fiche 50~413,82/10/04. B210130117

- 8210130487 Forwards comments on DES (NUREC-0921) re operation of facilities LOCHSTET.W A Pennsylvania State Univ 82/10/06 Division of Licensing 7pp 19682 140 24% Fiche 50-413,82/10/06,821013048/
- 8210130504 Comments on DES list of water users in downstream order, to be contained in FES, enc!
  TURNER, L. E. South Carolina, State of 82/10/07 JABBOUR, K. N.
  DIVISION of Licensing 3pp 15682 253 24X Fiche 50-413,82/10/07,8210130504
- 8210250102 Forwards comments on DEG.per LOCFR51 TUCKER,H B Duke Power Co 82/10/07 DENTON,H R Office of Nuclear Reactor Regulation. Director Eigenkut.D G Licensing Branch 4 14pp 15791 171 24X Fiche 50-413.82/10/07.8210250102
- 8210180106 Advises that review of DES for facility has been completed Clearance valid for 1 yr CROMER.D.L. South Carolina. State of 82/10/08 Office of Nuclear Reactor Regulation, Director tp 15717 318 24X Fiche 50-413,82/10/08,8210180106
- 8210180167 Comments on DES (NUREO-0921) & public health & safety impacts of proposed plant operation VILLEDRTH, J C Food & Drug Administration 82/10/12 JABBOUR, K N Division of Licensing 2pp 15719 166 24X Fiche 50-413.82/10/12, 8210180169
- 8210260150 Requests entl comments on DES be transmitted to appropriate NRC ofc DES summary of cost/benefit in Table 6 1 deficient RILEY, J. L. Carolina Environmental Study Group 82/10/22
  JABBOUR, N. Division of Licensing 3pp 15/99 015 24X
  Eicha 50-413, 82/10/22, 8210280150
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8210280065 Forwards responses to nine 1 tems in EG Adenson 820609 1tr re auxiliary feedwater sys.per draft SER. Section 7 1 3 1 TUCKER. H B Duke Power Co 82/10/19 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 9pp 13837 263 24X Fiche 50-413, 82/10/19, 8210280365
- F Security, medical, emergency & fire protection plans
- B209170053 Forwards Revision 3 to security plan Revision withheld (ref 10CFR73 21) TUCKER, H B Duke Power Co 82/08/18 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 14910 095 24X Fiche 50-413.82/08/18.8209179053
- 8210190611 Responds to 810723 request for schedule for installation of public notification sys at facilities Final design of sys & schedule for installation not finalized Info submittal anticipated by 821201 rucker, H B Duke Power Co 82/10/08 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E Q Licensing Branch 4 NEWTON, F Federal Emergency Management Agency 2pp 15737 221 24X Fiche 50-413, 82/10/08, 8210190611
- O Adjudicatory correspondence
- 8210050202 Response opposing Palmetto Alliance & Carolina Envi Group 820922 supplemental patitions to intervene MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise 82/10/04 Atomic Safety and Licensing Board Panel 15602 279 24% Fiche 50-413,82/10/04.8210050202
- --8210050208 Response to Charlotte-Mecklenberg Environ (
  revised Contention 4 Contention acceptable Notice of 
  appearance & Certificate of Svc enc!
  MCGARRY, J M Duke Power Co MCGARRY, J M Debevoir
  82/10/04 Atomic Befety and Licensing Board Panel
  15402 350 24X Fishe 50-413, 82/10/04,8210050202
- 8210060191 Statement of position on DES contentions Objet Palmetto Alliance/Carolina Environ Study Group content except Contention 4 as specified Certificate of Svc er JOHNSON: 0 E. Hearing Branch 4 82/10/04 Atomic E. Licensing Board Panel 26pp 15613 264 24X Fiche t 8210060191
- 82100800B1 Motion to compel util to respond to Palmetto 820903 second set of interrogatories & requests to pro Ceptificate of Bvc encl GUILD.R. Palmetto Alliance QUILD.R. Guild, R. 82, Atomic Bafety and Licensing Board Panel 5pp 15640 Fiche. 50-413,82/10/04,82100800B1

#### JOUNETED HEIMO

- 8210180182 Order extending time until 821112 for Commission to act to review ALAB-687
  CHILKS J Office of the Secretary of the Commission 82/10/14
  Commissioners ip 15719 134 24X Fiche 50-413.82/10/14, pp.10180182
- 8210200071 Provides response to ASLB questions at 821007-08 second special prehearing conference Questions relate to risks from McQuire facility & scope of evacuation costs listed in DES Table 5 II
  JOHNSON G E Hearing Branch 4 82/10/18 KELLEY, J L , FOSTER, R F , CALLIHAN, D Atomic Safety and Licensing Board Panel 2pp 15757 192 24X Fiche 50-413.82/10/18.8210200071
- 8210210187 Motion for order to protect NRC from answering Palmetto Alliance Interrogatories ( % 36 on Contention 8 & Interrogatory 1 on Contention 27 Requests are for large amount of natl u/o regard to relevance JOHNSON 0 E Hearing Branch 4 82/10/19 Atomic Safety and Licensing Board Panet 3pp 15765 159 24X Fiche 50-413.82/10/19, 8210210187
- --B21021019/ Responses to second set of interrogatorses & requests to produce re Palmetto Alliance Contentions 8 & 27 Profqualifications, NUREG/CR-2644 & Certificate of Svc encl JOHNSON, 6 E. Hearing Branch 4 82/10/19 Palmetto Alliance 134pp 15745 142 24% Fiche 50-413,82/10/19,8210210187
- 8210250125 Pesponses to Palmetto Alliance 820927 third set of interragatories & requests to produce Related correspondence CARRA V Duke Power Co 82/10/19 Palmetto Alliance 62pp 15787 243 24X Fiche 50-413.82/10/19,8210250625
- 8210250282 Motion for protective order relieving applicants from requirement to respond to Palmetto Alljance 820927 third set of interrogalories 5 requests to produce Certificate of Svc encl Related correspondence CARRA V Duke Power Co 92/10/19 Atomic Safety and Licensing Board Panel 4pp 15791 078 24x Fiche 50-413,82/10/19,8210250282
- 9210250370 Forwards EIA re spent fuel storage of Oconee spent fuel at McGuire Unit I spent fuel pool, dtd Dec 1978 Copies also sent to intervenors W/o enci JOHNSON, G E Hearing Branch 4 82/10/21 KELLEY, J L , FOSTER, R F , CALLIHAN, D Atomic Safety and Licensing Board Panel Ip 15790 188 24X Fichs 50-413.82/10/21,8210250370
- 8210260415 Answer opposing Polmetto Alliance 821004 motion to compel answers to interrogatories ASLB should issue order denying motion as lacking menit Motion devoid of Supporting arguments Certificate of Svc encl CARR.A V Duke Power Cu 82/10/22 Atomic Safety and Licensing Board Panel 20pp 15806 115 24x Fiche 50-413,82/10/22.
- 8210270002 Answers ASLB question re Palmetto Alliance/Carolina Environ Study Group Contention II DES totaled risks to public of accidents from each unit JOHNSON, GE Hearing Branch 4 82/10/25 KELLEY, J.C., FOSTER, R.F., CALLIHAN, D. Atomic Safety and Licensing Board Panel 1p 158(7-011 24X Fiche 50-413, 92/10/25, 8210270002
- 8210270010 Advises that NRC does not intend to file response to Palmetto Atliance 821004 motion to compel discovery from applicants NRC responded to requests on 821019

  JOHNSON, G E Hearing Branch 4 82/10/25 KELLEY, J L , FOSTER, R F , CALLIHAN, D Atomic Safety and Licensing Board Panel 1p

  15822 340 24X Fiche 50-413,82/10/25,8210270010

at NRC continue to send e Since McGuire equest denied B RILEY. J L Carolina 24X

- K Utility Final Safety Analysis Report (FSAR) & amends
- 8210150094 Application for Amend 29 to CPPR-116 & CPPR-117, consisting of Revision 6 to FBAR & Revision 1 to license application TUCKER, H B Dute Power Co 82/10/12 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E 9 Licensing Branch 4 22pp 15699 001 24X Fiche 50-413,82/10/12,8210150094
- --8210150101 Revision 6 to FSAR

   Duke Power Co 82/10/12 761pp 15499 023 24X

  Fiche 50-413,82/10/12.8210150094

### O Inspection reports, IE Bulletins & correspondence

- 8210080015 Addi response to FOIA request for 19 categories of info to nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
  FELTON, J M Division of Rules and Records 82/07/12 4DELL, R A Critical Mass Energy Project 9pp 15665 027 24X
  Fiche 50-000, 82/07/12, 8210080015
- --8210080156 Systematic assessment of licensee performance notes re facility evaluation for Sept 1979-Aug 1980 • NRC - No Detailed Affiliation Given 80/08/31 5pp (5568 057 24X Fiche 50-000, 82/07/12,8210080015
- 8210010106 Forwards IE Insp Repts 50-413/82-22 & 50-414/82-20 on 820824-27 No noncompliance noted DANCE:H C Division of Project & Resident Programs 82/09/13 TUCKER:H R Duke Power Co 2pp 15567 194 24X Fiche 50-413, 82/09/13
- --8210010110 IE Insp Repts 50-413/82-22 & 50-414/82-20 on 820824-27 M; noncompliance noted Major areas inspected independent insp effort, review of quality records for containment structures & supports & inservice review of program COLEY, J. L. BLAKE, J. Division of Engineering & Technical Programs 82/09/09 (Opp 15567 194 24X Fiche 50-413,82/09/13 8210010106
- 9210010131 Ack receipt of 920907 Itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/82-18 & 50-414/82-16

  LEMES.R C Division of Project & Resident Programs 82/09/22 TUCKER.H B Dute Power Co ip 15565 351 24X
  Fiche 50-413.82/09/22.8210010131
- --8210010134 Responds to NRC 820809 ltr re violations noted in It Insp. Repts 50-413/82-18 & 50-414/82-14 Corrective actions matts personnel training will be completed by 820915 & paint storage warehouse will be upgraded by 821015 TUCKER.H II Duke Power Co 82/09/07 O'REILLY.J P Region 2. Office of Director 4pp 15565 392 24% Fiche 50-413.82/09/22.
- --8210010138 Forwards IE Insp Repts 50-413/82-18 & 50-414/82-16 to 820712-16 & notice of violation LEWIS.R C Division of Project & Resident Programs 82/08/09 TUCKER.H B Duke Power Co 2pp 15565 356 24X Fiche 50-413.82/09/22.8210010131
- --8210010141 Notice of violation from insp on 820712-16 \* Division of Project & Resident Programs 82/08/09 15565 358 24/ Fiche 50-413,82/09/22,8210010131
- --8210010143 IE Insp Repts 50-413/82-18 & 90-414/82-16 on 820712-16 Noncompliance noted failure to initiate nonconforming team item repts re coatings storage temps & failure to conduct civil work activities surveillances WRIGHT, R W DEBBAGE, A O . UPRIGHT, C M Division of Engineering t Technical Programs 82/08/06 11pp 15965 360 24% Fiche 50-413.82/09/22.8210010131
- 8210150068 Ack receipt of IE Insp Repts 50-413/82-20 & 50-414/82-18
  No proprietary info
  TUCKER, H B Duke Pawer Co 82/09/24 O'REILLY, J P Region 2,
  Office of Director 1p 15696 348 24X Fiche 50-413.82/09/24,
  8210150068
- 8210220467 Forwards IE Insp Repts 50-413/82-24 & 50-414/82-22 on 820826-0910 No noncompliance noted DANCE: H C. Division of Project & Resident Progrems 82/09/29 TUCKER: H D Dave Power Co 2pp 15779 116 24X Fiche 50-413, 82/09/29, 8210220467
- 8208190233 IE 1nfo Notice 80-35, Buppl 1, "Leaking & Dislodged 1-12) Implant Seeds " Svc list enc!.
  COBB.L I. Division of Fuel Facilities, Materials & Bafeguards 82/10/06 Consolidated Sdison Co of New York 66pp 15761 2% 24X Fiche: 50-000: 82/10/06. 8208190233
- 8210220134 Ack receipt of IE Insp Repts 50-413/82-22 & 50-414/82-20 % proprietary info TUCKER, H B Duke Power Co 82/10/08 O'REILLY, J P Region 2. Office of Director 1p 15778 114 24X Fiche. 50-413.82/10/09. 82/0220134

- 8208190238 IE Bulletin 82-03. "Stress Corresion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl BEYDUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000.82/10/14.8208190238
- 5 Reportable occurrences, LERs & related correspondence
- 8210080208 Significant Deficiency Rept SD 413-414/82-18 re radiographic exams not performed on flux core welding filler matl property to SFA 5 20 Initially reported on 820903 Vendor committed to radiograph all matls Action to be completed by 830301 TUCKER, H B Duke Power Co 82/10/01 O'REILLY, J P Region 2, Office of Director 3pp 15640 086 24% Fiche 50-413,82/10/01. 8210080208
- 8210290354 Significant Deficiency Rept SD 413-414/82-20 re inappropriate governor drive matt coupling supplied for diesal generator Initially reported on 820908 Manufacturer recommends replacement w/neoprene matt TUCKER, H B Duke Fower Co 82/10/09 D'REILLY, J P Region 2. Office of Director 3pp 15853 040 24X Fiche 50-413,82/10/08, 8210290354
- 8210290250 Significant Doficiency Rept 413-414/82-11 re potential failure to activate safeguards sys due to possible failure of switch contacts, shunting proving lamp Revision to solid state protection sys will be made by Westinghouse TUCKER, H B Duke Power Co 82/10/20 O'REILLY, J P Region P, Office of Director 3pp 15854-096 24X Fiche 50-413,82/10/20,82/020250
- T Hearing transcripts on non-antitrust matters
- 8210130207 Transcript of 821007 prehearing conference in Charlotte.NC Pp 380-567 \* Atomic Safety and Licensing Board Panel 82/10/07 188pp
- \* Atomic Safety and Licensing Doard Panel 82/10/07 188pp 15673 272 24X Fiche 50-413, 82/10/07, 8210130207
- B21013023B Transcript of B2100B prehearing conference in Charlotte.NC Pp 56B-655 \* Atomic Safety and Licensing Board Panel B2/10/0B 88pp 15675 124 24X Fiche 50-413, B2/10/0B 821013023B
- V Operator Examinations
- 8210260065 Bummary of 820909 meeting w/util in Cornelius,NC re cold license stam schedule WILBON,B A Division of Engineering & Technical Programs JABBOUR,K N Licensing Branch 4 82/10/01 Division of Engineering & Technical Programs 21pp 15810 340 24X Fiche 50-413, 82/10/01, 8210260065
- DOCKET 50-416 ORAND QULF NUCLEAR STATION, UNIT 1

  E NRC Sefety Evaluation Report (SER), supple & correspondence
- B210190566 Advises of completion of thermocouple qualification testing per SER Suppl 3 Thermocouples considered qualified for seismic bydrodynamic loads including variable pool swell Final test rept will be reviewed upon receipt DALE.L F Mississippi Power & Light Co 82/10/14 DENTON.H R Office of Nuclear Reaction Repulation, Director 2pp 15736 133 24X Fiche 50-416.82/10/14,8210190566
- 8210200064 Forwards comments & status of util review of DL & SER Info provided to assist in generation of fourth suppl to SER & full power OL DALE, L.F. Mississippi Power & Light Co. 82/10/14 DENYON, H.R. Office of Nuclear Reactor Regulation, Director 54pp 15756 159 24X Fiche: 50-416, 82/10/14, 82/02/00064
- 82i0200005 Forwards outline of in situ test for HPCS standby svc water pump flow induced vibration Test will be performed prior to startup following first refueling outage Commitment to conduct test resolves EER Suppl 2. Section 3 io concerns DALG/L F Mississippi Power & Light Co 62/10/18 DENYON, H R Office of Nuclear Reactor Regulation, Director 7p 15754 341 24X Fiche. 50-416.82/10/18.8210200005
- B210200030 Forwards evaluation of valve disc pin overstressing, addressing concerns & closing supplemental BER 2, Section 22 2 (Issue II E 4.2). "Purge Valve Operability"

  DALGL F Mississippi Power & Light Co 82/10/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 15737 194 24X Fichs 30-416.82/10/18,8210200030

- 8210200073 Forwards info re monitoring trend analysis program per commitment to summarize vibration monitoring analysis program for deep draft pump reliability per SER Section 1 10 (13) DALE, L.F. Mississippi Power & Light Cu. 82/10/18 DENTON, H.R. Office of Nuclear Reactor Regulation. Director 2pp. 15754 133 24X Fiche 50-416,82/10/18,8210200073
- B210220425 Forwards add1 info is qualification of hydraulic control units affected by variable pool swell loads Test response spectra-required response spectra comparisons should be sufficient to close concern in SER Suppl 3. Section 3. 10 DALELL F. Mississippi Power & Light Co. B2/10/19 DENTON, H. R. Diffice of Nuclear Reactor Regulation. Director 7pp 15779 153 24X Fishe 50-416, 82/10/19. B210220425
- F Security, medical, emergency & fire protection olans
- 82(0150013 Responds to noncompliance re emergency accountability noted in IE Insp Rept 50-416/82-27 Interpretion of "onsite" questionable Other utils make same distinction of site boundary being same as protected area DALE, L.F. Mississippi Power & Light Co. 82/07/19 0'REILLY. J ('Region 2, Office of Director 2pp. 15698 346 24X Fiche 50-416.82/07/19,8210150013
- 8210070040 Releases public version of corrections to emergency action level table FELTON, J M Division of Rules and Records 82/09/17 Document Management Branch 1p 15646 341 24% Fiche 50-416.82/09/17, 8210070040
- --8210070044 Forwards public version of corrections to Table 4-1 re emergency action levels; in response to NRC questions on Revision 6 to emergency plan Encl changes will be (incorporated into plan by 821031 DALE, LF Mississippi Power & Light Co 82/09/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15646 343 24X Fiche 50-416,82/09/17,8210070040
- --B210070048 Public version of corrected Table 4-1 re emergency action levels Initial & final notification forms encl \* Mississippi Power & Light Co B2/09/09 App 15646 345 P4X Fiche 50-416.82/09/17.8210070040
- 8210010234 Forwards Revision 5 to physical security plan Revision withheld (ref 10CFR2 790) MCGAUGHY, J P. Hississippi Power & Light Co. 82/07/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp. 15574-060 24X Fiche 50-416, 82/09/22, 8210010234
- 6210010023 Requests delay in implementation of emergency response facility Facility will be structurally complete by 821001 commitment date, but several important sys will not yet be installed Schedule should be developed between NRC & util DALE, L.F. Mississippi Power & Light Co. 82/09/29 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 15565-141-24X Fishs 50-416,82/09/29,8210010023
- O Adjudicatory correspondence
- 8210040115 Order granting State of I time to respond to ASLB 820831 ori applicant arguments due 821011 No will be granted LAURENSONJ A Atomic Safety and LOUISIANA State of 3pp 1598 8210040115
- 8210150462 Brief supporting State or participate as interested state Or untimely petition Certificate of S LINDSEY, I D Louisiana, State of Licensing Board Panel 31pp 157 8210150462
- 8210210373 Memorandum & order denyir intervention ABLB unable to consic in proceeding Commission retained to grant full power OL LAURENSON J A : BRIGHT: O . HARBC Board Panel 82/10/20 Louisia 24X Fiche 50-416.82/10/20.82102100

- D Advisory Committee on Reactor Safeguards reports & correspondence
- 8208290018 Summarizes 268th ACRS meeting on 820812-14 in Washington.DC refull power QLs for Grand Gulf I & Watts Bar I & II. systematic evaluation & integrated reliability assessment of Ginna & control room habitability SHEWMON P ACRS Advisory Committee on Reactor Safeguards 82/08/06 PALLADING.N J Commissioners 3pp 15649 233 24X Fiche 50-000.82/08/26.8208270018
- 8210270380 Summary of ACRS Grand Gulf Subcommittee 820811 meeting in Mashington.DC re OL review \* ACRS - Advisory Committee on Reactor Safeguards 82/09/09 ACRS - Advisory Committee on Reactor Safeguards 16pp 15834 302 24% Fiche 50-416.82/09/09.8210270380
- P. Operating license stage documents & correspondence
- 6210130024 Forwards Amend 3 to License NPF-13, safety evaluation & notice of issuance & availability Amend grants add1 one-time Tech Spec exceptions for Phase I operations & changes to Tech Specs re valves & stroke times EISEMHUT, D G Division of Licensing 62/09/20 MCGAUGHY, J P Mississippi Power & Light Co 3pp 15692 312 24X Fiche 50-416, 82/09/20, 8210130024
- --8210130027 Amend 3 to License NPF-13 granting addlone-time Tech Specexceptions for Phase I operation & changes to Tech Specs re valves & stroke times
  EISENHUT.D G Division of Licensing 82/09/20 16pp 15692 315
  24% Fiche 50-416.82/09/20.8210130024
- --821013003B Safety evaluation supporting Amend 3 to License NPF-13 4 Office of Nuclear Reactor Regulation, Director 62/09/16 3pp 15592 326 24% fiche 50-416.82/09/20.8210130024
- --8210130043 Notice of issuance % availability of Amend 3 to License NPF-13
  SCHWENCER.A Licensing Branch 2 82/09/20 3pp 15492 329 249
  Fiche 50-416.82/09/20.8210130024
- 8210220032 Advises that postponement of associated startup test acceptable Recirculation flow control test under cold plant conditions should be deleted SCHMENGER.A Licensing Branch 2 82709/28 MCGAUGHY, J.P. Mississippi Power & Light Co. 2pp. 15786-283 24X Fiche 30-416.82/09/28.8210220032
- 8210040053 Advises of delay in response to Humphrey concerns recontainment issues pending 821001 conference discussion u/gE on local encroachments. Action Plans 1-4 Commitment based on 820792 telcon u/Containment Sys Branch DALE-L F Mississippi Power & Light Co 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 1558( 307 24X Fiche 50-416, 82/09/30, 8210040053
- B210040264 Discusses independent design review per License Condition 2 C(43) Design verification program to provide addition assurance that design & const activities meet 10CFR50, App B requirements will be performed by Cygna Energy Svcs DALE, L.F. Mississiphi Power & Light Co. 82/09/30 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp. 15595-001, 24K Fichs 50-416, 82/09/30, 8210040264
- 8210040353 Forwards responses to 820826 request for add1 info re Items 1-8,including current status & submittal schedule for outstanding items IF Plunkett prof qualifications enc! DALE.C F Mississippi Power & Light Co 82/09/30 DENTON.H R Diffice of Nuclear Reactor Regulation. Director 8pp 13593 348 24% Fiche 50-416.82/09/30,8210040353
- 8210060295 Responds to request for add1 info to HPCS svc water pump Add1 testing or mod not required Suggests meeting w/Equipment Qualification Branch to discuss evaluation results on 821008 in Bethesda, MD DALE, L.F. Mississippi Power & Light Co. 82/10/04 DENTON, H.R. Office of Nuclear Reactor Regulation. Director 4pp 15619 105 24% Fiche 50-416, 82/10/04, 8210060295
- 8210260264 Advises that util will reissus plant emergency operating procedures in accordance w/INPO writer guide & Revision 2 of BWR owners group emergency planning guidelines Revised procedures to be submitted by 821029

  PALE: L F Mississippi Fower & Light Co 82/10/12 DENTON, H R Office of Nuclear Resolutor Regulation. Director 2pp 15803 031 24X Fiche 50-416,82/10/12,8210260264

- B210190496 Forwards addl info per License Condition 2 C (5) re PMP effects on Facility Specific fixes will be implemented on schedule consistent w/57 power Fixes will consist of sealing doors & modifying pump house floor penetrations
  DALE: L F Mississippi Power & Light Co B2/10/14 DENTON, H R
  Office of Nuclear Reactor Regulation. Director 2pp 15740 196
  24X Fishe 50-416,82/10/14,8210190494
- B210190921 Provides info in response to Human Factors Engineering Branch 820913 informal request ro meeting human performance environ conditions in plant remote shutdown panel area DALE.L F Mississippi Power & Light Co B2/10/14 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 19751 236 24X Fichs 50-416.82/10/14.8210190921
- B210210217 Bubmits add1 info re design & testing of automatic depressuritation sys air sys, including response to NUREG-0737. Item II K 3 28, air sys testing & air sys makeup provisions Revision to FSAR Subsection 18 i 30 12 enc1 DALE.L F Mississippi Power & Light Co 82/10/18 DENION, H R Office of Nuclear Reactor Regulation, Director 3pp 15766 340 24X Fichs 50-416, 82/10/18, 8210210217
- B210260412 Requests that License Condition 2 C (44)(i)(a) be revised to require submittal re automatic depressurization sys logic mods by 821215 Previous submittal date of B21029 erroneously requested due to revised BMR owners group schedule DALELL F Mississippi Power & Light Co 82/10/21 DENTON.H 8 Office of Nuclear Reactor Regulation, Director 2pp 15803 10/24X Fishe 50-416.82/10/21.8210260412
- 8210270277 Forwards add1 info re containment design in response to J Humphrey questions Status rept per util 820715 ltr & GE proprietary info encl Proprietary info withheld Affidavit & 11 oversize drawings encl Aperture cards are in PDR DALE.L F Mississippi Power & Light Co 82/10/22 DENTON.H & Office of Nuclear Reactor Regulation. Director 82pp 15882:198 244 Fiche 50-416.82/10/22,8210270277
- 8210280135 Provides addl responses to NRC concerns re adequacy of onsite communication sys in areas exhibiting high ambient noise levels, use of 2-way radio sys & work stations requiring communications w/control room or shutdown panel DALE.L F Mississippi Power & Light Co 82/10/26 DENTON-H R Office of Nuclear Reactor Regulation, Director 3pp 15837 130 24X Fiche 50-416,82/10/26,8210280135
- B210290102 Outlines commitments made during 821025 telcon re design k testing of automatic depressurization air sys Integrated leak test on sys will be performed every 16 months Justification for interim operation listed DALEIL F Mississippi Power & Light Co 82/10/26 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 15854 001 24X Fiche 50-416.82/10/26,8210290102
- Q Inspection reports. IE Bulletins & correspondence
- 8210150013 Responds to noncompliance re emergency accountability noted in IE Insp Rept 50-416/82-27 Interpretion of "onsite" questionable Other utils make same distinction of site boundary being same as protected area DALE(LF Mississippi Power & Light Co 82/07/19 O'REILLY, J Region 2. Office of Director 2pp 15698 346 24% Fiche 50-416(82/07/19,82101500t3
- 6210010442 Forwards IE Insp. Repts 50-416/82-61 & 50-417/82-13 on B20817-20 No noncompliance noted VERRELLI, D. M. Division of Project & Resident Programs B2/09/03 STAMPLEY, N. L. Mississippi Power & Light Co. 2pp. 15570-175 247 Fichs 50-416, 82/09/703, 8210010442
- --8210010447 IE Insp Repts 50-416/82-61 & 50-417/82-13 on 820817-20 M noncompliance noted Major areas inspected const deficiency repts for Unit 1 & observation of safety-related piping work activities at Unit 2 BLAKE.J. J Division of Engineering & Technical Programs 82/09/02 4pp 15570 177 24X Fiche 50-416,82/09/03,8210010442
- 8210010148 Forwards IE Insp Rept 50-416/82-63 on 820815-18 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 82/09/07 STAMPLEY,N L Mississippi Power & Light Co 2pp 15570 354 241 Fiche 50-416, 82/09/07,8210010148
- --82(001015) IE Insp Rept 50-416/82-63 on 820815-18 No nancompliante noted Major areas inspected open vessel criticality & associated tests
  BURNETT: P T , VOOT-LOHELLI, R , JAPE, F Division of Engineering & Technical Programs 62/09/03 4pp. 15970 356, 24X Fiche 50-416,82/09/07,8210010148

i 1

- 150005 Ack receipt of 820831,0907 & 20 ltrs informing NRC of steps ten to correct violations noted in IE Insp Rept 416/82-55
- Division of Project & Resident Programs 82/09/24 MPLEY, N. L. Mississippi Power & Light Co. ip 15696 314 he 50-416, 82/09/24, 8210150005

iche 50-416, 82/09/24, 8210150005

- O150011 Suppls 820831 response to NRC 820730 ltr re violations noted n IE Insp Rept 50-416/82-55 Corrective actions Anubar nstallations will be identified as temporary alterations & laced under temporary alteration propram ICGAUGHY, J P Hississippi Power & Light Co 82/09/20 PREILLY, J P Region 20 Office of Director 2pp 15696 315 24X
- 0190019 Supple 820831 response to NRC 820730 ltm re violations noted OISOOIY Supple B20831 response to NRC B20730 for re violent IE Insp Rept 50-416/82-55 Corrective actions plant dministrative procedure will be revised to clarify emporary alteration program & delete use of chit log sys COAUGHY, J.P. Mississippi Power & Light Co. 62/09/07 REILLY, J.P. Region 2, Office of Director Spp. 15696 iche 50-416.82/09/24.8210150005
- 15696 317 24X
- D150024 Responds to NRC B20730 ltr re violations noted in IC Insp ept 50-416/82-55 Corrective actions IOCFR50 59 evaluations erformed for temporary alterations & temporary alteration rocedure revised
- COAUGHY, J P Mississippi Power & Light Co 82/08/31
  'REILLY, J P Region 2, Office of Director 2pp 15
  liche 50-416.82/09/24.8210150005 15676 320 24X
- )150027 Forwards IC Insp Rept 50-416/82-55 on 020616-0716 & notice violation
- WishR C Division of Project & Resident Programs 82/07/36
  "AMPLEY.N L Mississippi Power & Light Co 2pp 15496 322
  cha 50~416.82/09/24.8210150005 92/07/30
- 1150028 Notice of violation from insp on 820614-0716 Division of Project & Resident Programs 82/07/30 1594:124 24X Fiche 50-416, 82/09/24,8210150005 200
- 150032 IE Insp Rept 50-416/82-55 on 820616-0716 Noncompliance ted failure to perform safety evaluation for temporary terations to facility & failure to follow writte
- 0grams 10150005
- 0384 Ack receipt of 820907 ltr informing NRC of steps taken to ect violations noted in IE Insp Rept 50-416/82-55
  5.R C Division of Project & Resident Programs 82/09/24
  \*\*PLEY, N. Hississippi Power & Light Co ip 15704 068 24X
  \*\*\* 50-416.82/09/24.8210150384
- 0233 IE Info Notice 80-35. Suppl 1. "Leaking & Distodged 1-125 ent Seeds " Syc list encl L I Division of Fuel Facilities, Materials & Safeguards 0704 Consolidated Edison Co of New York 66pp Tiche 50-000,82/10/06.8208190233
- 1238 IE Bulletin B2-03, "Btress Corrosion Cracking in Thick-Large-Diameter Stainless Steel Recirculation Sys 1g at BMR Plants "Svc list encl NO.R C Director's Office, Office of Inspection and cament 82/10/14 Consolidated Edison Co of New York 15810 125 24X Fiche 50-000.82/10/14.8208190238
- 132 Forwards responses to Instrumentation & Control Bys Branch 4 questions re util evaluation of IE Info Notice 79-R2, iffication of Control Bys\* & control sys failures Info C review available in NREG-0831
  L.F. Mississippi Power & Light Co. 82/10/25 DENTON, H.R. L.F. Mississippi Power & Light Co. 82/10/25 DENTON:H R e of Nuclear Reactor Regulation, Director 10pp 15837 120 icha.50-416.82/10/25.8210280132
- odic operating reports & related correspondence
- 104 Forwards monthly operating rept for Bept 1782 OHY, J.P. Mississippi Power & Light Go. 82/10/14 DEYOUNO, R C ctor's Office, Office of Inspection and Enforcement 2pp 309 24X Fiche 30-416.82/10/14/8210180104
- 30109 Monthly operating rept for Sept 1982 4ARDSON, J.D. Mississippi Power & Light Co. it 19 311. 24X Fiche, 50-416, 82/10/14, 8210180104 82/10/15. App

- S Reportable occurrences, LERs & related correspondence
- 82:00:0008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents nuclear reactor translation of Rules and Records B2/ FELTON J M Division of Rules and Records B2/ Section Mass Energy Project 15pp 15727 005 Critical Mass Energy Project 1 Fiche 50-000, 82/04/28, 8210018008
- --8204210287 Forwards deficiency rept re failure of control rod drive hydraulic sys scram pilot valves Problems w/ws'tage of reactor protectson sys power supplies adequately addressed CHRAMAL.M Director's Office 82/03/31 MICHELSON.C Director's Office 2pp 66018 170 24X Fiche 50-000.82/04/28.
- 8210080015 Add1 response to FOIA request for 19 categories of infolio nuclear reactor events 5 safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) Folia Exemption 5; FELTON, J.M. Division or Rules and Records 82/07/1; Critical Mass Energy Project 9pp 15865 027 24x Fiche 50-000,82/07/12,8210080015 82/07/12
- --B206110186 Forwards review V evaluation of BWR scram pilot valve failures due to low voltage Aug 1981 event at facility reviewed Applicability of event to operating BWRs described MICHELSON, C Director's Office B2/06/01 DENTON, H R Office of Nuclear Reactor Regulation, Director DEYOUNG, R C Director's Office, Office of Inspection and Enforcement Spp 15666 137 Office, Office of Inspection and Enforcement 24% Fiche 50-000, 82/07/12, 8210080015
- 8210010243 Forwards LER 82-055/03L-0 MCGAUGHY, J P Mississippi Power & Light Co B2/09/27 O'REILLY, J P Region 2. Office of Director ip 15568 286 Fiche 50-416, 82/09/27, 8210010243
- --8210010248 LER 82-055/03L-0 during 820829-0908, discharge basin flow trip channel inoperable Caused by approved alteration of trip circuitry to discharge glycof-contaminated water w/o normal dilution Trip circuitry restored after discharge SPARKS, G L. Mississipp: Power & Light Co. 82/09/27 Region d. Office of Director 2pp 15568 287 24x Fiche 50-416.82/09/2/. 8210010243
- 8210050193 Forwards LER 82-047/03L-0 STAMPLEY, N L Mississippi Power & Light Co O'REILLY, J P Region 2. Office of Director Fiche 50-416, 82/09/28, 8210050193 02/09/28 15609 253 1 p
- --8210050203 LER 82-047/03L-0 on 820830 reactor vessel & head flance temps not monitored consistently Caused by mechanical group personnel failing to adhere to procedure Procedure under revision SPARKS, G.L. Mississippi Power & Light Co. 82/09/28 Region C Office of Director. 2pp. 19609-254 24x Fiche 50-416,82/09/20. Region 2, 8210050193
- 8210040201 Forwards LER 82-062/03L-0 MCGAUGHY. J P Mississippi Power & Light Co O'REILLY, J P Region 2, Office of Director Fiche 50-416, 82/09/29, 8210060201 82/09/29 15614 016 10

- 8210080120 Forwards LER 82-071/03L-0 MCGAUGHV, JP Mississippi Power & Light Co 82/10/04 G'REILLY JP Region 2. Office of Director 1p 15640 127 24Y Fichs 50-416.82/10/04.8210080120
- 6210080127 LER 82-071/03L-0 on 820903, smoke detectors in fire xones 2-4 alarmed w/no fire of funes present On 820929, detectors alarmed again No cause stated Detectors cleaned BrRD-R Mississippi Power & Light Co 82/10/04 Region 2, Office of Director Ip 15640 128 24X Fiche 50-416.82/10/04, 82/1080120
- 8210080277 Forwards LER 82-069/03L-0 MCGAUGHY, J P Mississippi Power / Light Co 92/10/04 O'REILLY, J P. Region 2, Office of Director 1p 15638 298 24X Fiche 56-416, 82/10/04, 8210080277
- -8210089281 LER 62 069/03L-0 on 820903, supervisory alarm for fire door separating RHR A piping room & east passageway alarmed & would not clear Caused by out-of-adjustment door microswitch Switch adjusted & tested to assure operability ALBERT, J h. Mississippi Power & Light Co. 82/10/04 Region 2, Office of Director. 1p. 15638 299 24X Fiche 50-416,82/10/04, 82(10/8027)
- 8210080282 Forwards LER 82-063/031-0 MCFAUGHY, J P Mississippi Pawer & Light Co 82/10/04 O'REILLY, J P Region 2. Office of Director 1p 15638 199 24X Fiche 50-416 82/10/04,82(0080282
- -821000287 LER 82-063/03L-0 on 820902.various fire rated cable penetrations discovered not scaled in several field termination cabinets located in control room Penetrations removed to allow cable removing WALKER.K.L. Mississippi Power & Light Co. 82/10/04 Region 2, Ortice or Director Ip. 15638-200. 24X Fichs 50-416,82/10/04,82/10/808282
- 021008018a Forwards LER 82-0/0/031-0 MCGAUGHY, J.P. Mississippi Power & Light Co. 82/10/05 O REILLY, J.P. Region 2: Orfice of Director 1p. 13640 177 247 Fishe 50-416, 82/10/05, 82/10/8098
- -8210080192 LER 82-070/03L-0 on 820907.13 & 16. smoke detector P65 rong 2-01 sensed smoke in standby svc water pumphouse Caused by smoke blown from nearby burn pit liben wind changed directions, alarm cleared Detector cleaned DIFFEREMT, P M Mississippi Power & Light Co 82/10/05 Region 2. Office of Director 1p 15640 178 24X Fithe 50-416.82/10/05.8210080196
- 82:0080284 Forwards LER 82-066/03L-0 MCGAUGH1, J P Mississippi Power & Light Co 82/10/05 O'REILLY, J P Region 2, Office of Director ip 15638 318 24X Fiche 50-416,82/10/05,8210080284
- -8210080289 LER 82-966/03L-0 on 820909, smoke detector ione covering hallway area elevation 93-ft auxiliary blig & HPCS pump room alarmed & would not clear Caused by dust accumulation on ionitation smoke detectors Detectors cleaned 8YRD, R Mississippi Power & Light Co 62/10/05 Region 2, Office of Director ip 15638 319 24X Fiche 50-416,82/10/05,8210080284
- 8210080295 Forwards LER 82-065/03L-0 MCGAUGHY, J P Mississippi Power & Light Co 82/10/05 O'REILLY, J P Region P. Office of Director ip 15638 323 24x 50-446.62/10/05.8210080295

- --8210220162 LER 82-064/03L-0 on 820914, two independent chlorine detection sys inoperable Caused by chlorine gas detector failing due to clogging of internal flow paths Detector cleaned, repaired & returned to svc
  SPARKS, G L. Mississippi Power & Light Co. 82/10/08 Region 2, Office of Director 2pp 15778 081 24x Fiche 50-416,82/10/08,8210220158
- 8210220181 Forward: LER 82-068/03L-0 ICC64U6HY.J P Mississippi Power V Light Co 82/10/08 O'REILLY.J P Region 2, Office of Director ip 15776 254 Fichs 50-416, 82/10/08, 8210220181
- --8210220191 LER 82-068/03L-0 on 820909, reactor pressure vessel flaige head flange temp not monitored periodically per Toch Speca Caused by operator error Required parameters verifying acceptable value read & recorded SPARKS, 6 L. Hississippi fower & Light Co. 82/10/08 Region &, Office of Director 2pp. 15776-255. 24X Fiche 50-416, 82/10/08. 82/10220181
- 8210220259 Forwards LER 067/0%.-0 MCGAUGHY.J P Mississippi Power & Light Go 62/10/08 0/REILLY.J P Region 2. Office of Director 1p 15775 130 24x Fiche 50-416, 82/10/08, 8210220259
- "-8210220262 LER 82-067/03L-0 on 820910, smake detectors in zone covery: auxiliary bldg corridor area alarmed & would not reset Caused by accumulation of dust on contration smake detector combined which sensitivity setting Detector cloaned PACE.D L Mississippi Power & Light Co 82/10/08 Region 2, Office of Director ip 15775 (39 24x Fiche 50-416,82/10/08, 821022059
- Q210220458 Forwards LER 02-073/03L-0 MC0AU0HY, J P Mississipp: Power & Light Co 82/10/08 O'REILLY, J P Region 2. Office of Director 1p 15779 125 24x Fichs 50-416, 02/10/08, 0210220458
- ~-8210220462 LER 82-073/03L-0 on 820909, smoke detectors alarmed w/no for present Caused by paint fumes resulting from maint painting activities in area Booke detectors cleaned BYRD, R Mississippi Power & Light Co 82/10/08 Region 2, Office of Director 19 15779 126 24X Fiche 50-416,82/10/08, 82/10/08.
- @210220045 Forwards LER 92~077/03L-0 MCGAUGHY, J.P. Mississippi Power & Light Co. 62/10/11 B'REILLY, J.P. Region 2. Diffice of Director ip 15778 195 24K Fiche 50-414, 82/10/11, 0210220065
- ~~8210220067 LER 82-079/03L-0 on 820710, discovered temp monitoring of specific safety-related areas not conducted every 12-h Data recorded once every 24-h from 820824-0911 Caused by inadvertent emission from operating log procedure HHITE, A J Mississippi Power & Light Co 82/10/11 Region al. Office of Director ip 15778 194 24X Fiche 50-414, 82/10/11, 8210320065
- 8210190417 Forwards LER 82-077/01T-0 MCGAUCHY. JP Mississippi Power & Light Co 82/10/12 D'REILLY. JP Region 2. Office of Director 1p 15741 014 24x Fisha 50-416, 82/10/13, 8210190417
- --8210190424 LER 82-077/01T-0 on 920930, two penetrations found not sealed from auxiliary bldg to control bldg Penetrations for electrical conduit not sealed during const Penetration sealed DIFFERENT, P M Mississippi Power & Light Co 82/10/13 Region 2, 0ffice of Director 2pp 15741 015 24x Fiche 30-416. 82/10/13,8210190417
- 8210190561 Forwards LER B2-075/99X-0 MCGAUGHY, J.P. Mississippi Power & Light Co. 82/10/13 O'REILLY, J.P. Region 2. Office of Director. 1p. 15735 020 24X Fichs. 50-416. 82/10/13. 8210190561.
- --8210190567 LER 62-075/79X-0 on 820915, steam tunnel fire door In220 discovered open w/no fire watch stationed during preparation for non-nuclear heatup Caused by need for tunnel maint Hourly fire watch established Door closed following maint CHENAULT. W H Mississippi Power & Light Co. 82/10/13 Region 2, 0ffice of Director ip 15735, 021 24X Fiche 50-416.82/10/13 8210190561

- 8210220131 Forwards LER 82-080/017-0 MC0AU0HY, J P Mississipp: Power & Light Co 82/10/18 U'REILLY, J P Region 2, Office of Director 1p 15778 115 24X Fichs 50-416, 82/10/18, 8210220131
- --8210220190 LER 82-080/017-0 on 821004, during cold shutdown insp on Div 2 standby diesel generator, capscrew to rear crankcase cover of engine block found defective Caused by fatigue during engine operation Capscrews replaced CHENAULT, W H Mississippi Power & 1.1ght Co 82/10/18 Region 2, Office of Director 2pp 15778 116 24X Fiche 50-416, 82/10/18, 8210220131
- 6210220269 Forwards LER B2-086/O3L-0 MCOAU0HY, J P Hississipp; Power & Light Co 82/10/18 G'REILLY, J P Region 2. Office of Director 1p 15776 200 24X Fiche 50-416, 82/10/18, 8210220269
- --8210220274 LER 82-086/03L-0 on 820916, fire detection Zone 2-6 trouble 1(ght alarmed & would not clear Caused by improperly seated smoke detector allowing open circuit Detector reseated, tested & returned to svc
  BYRD, R Mississippi Power & Light Co 82/10/18 Region 2, Office of Director 1p 15776 201 24X Fiche 50-416, 82/10/18, 82/10220269
- 8210220278 Forwards LER 82-083/03L-0 MCGAUGHY.J P Mississippi Power & Light Co 82/10/18 O'REULLY.J P Region 2. Office of Director 1p 15775 047 24X Fiche 50-416.82/10/18.8210270278
- --8210220282 LER 82-083/03L-0 on 820918, during cold shutdown, nine fire berrier penetrations were broken in auxiliary & control bldgs Caused by addi electrical conduit being routed due to implementation of Design Change 82-3594
  ALBERT, J M Mississippi Power & Light Co 82/10/18 Region 2, Office of Director ip 15775 048 24X Fiche 50-416, 82/10/18, 8210220278
- 8210280284 Forwards LER 82-081/03L-0 MCGAUGHY.J P Mississippi Power & Light Ca 82/10/18 O'REILLY.J P Region 2. Office of Director 1p 15775 045 24X Fichs 50-416, 82/10/18, 8210220284
- --B210220289 LER 82-081/03L-0 on 920916, containment ventilation menitoring sys effluent flour atomonitor failed to give proper indication Passibly caused by clugged flow sensor Haint work order issued to remove inspect & clean sensor CHENAULT, H Mississippi Power & Light Co 82/10/18 Region 2, Office of Director ip 15775 046 24X Fiche 50-416,82/10/18,82/19202884
- 8210220428 Forwards LER 82-085/03L-0 MCGAUOHY. JP Missilsalppi Power & Light Co 82/10/18 O'REILLY. JP Region 2, Office of Director in 15779 162 24X Fiche 50-416, 82/10/18, 0210220428
- --B210220431 LER 82-085/03L-0 on B20916, three secondary containment panetrations opened for cable routing per planned maint activity Fire watch established Penetrations sealed BYRD, R Mississippi Power & Light Co B2/10/18 Region 2, Office of Director Ip 13779 163 24X Fiche 50-416,82/10/18, B2/102428
- 8210260445 Interim Deficiency Rept 3 re corroded terminal boards on pressure flow & level transmitters Initially reported on 820421 Corroded transmitters being analyzed by independent 1ab Final rept will be sent by 821215 MCOAUGHY. J P Mississippi Power & Light Co 82/10/18 07KEILLY. J P Region 2. Office of Director 2pp 15805 248 24 Fichs 50-416.62/10/18.8210240445
- 6210260513 Final deficiency rept to extensive internal corrosion of Dikkers safety relief valva actuators Initially reported on B20521 Actuators clamed-refurbished tested & returned to original design condition Also reported per Part 21 MCGAUGHY-JP Mississipgi Power & Light Co 82/10/18 0'REILLY-JP Region 2. Office of Director 5pp 15805 128 24X Fiche 30-416, 82/10/19, 8210260513
- 8210290050 Forwards LER 82-074/03L-0 MCGAUGHY.J P. Mississippi Power & Light Co 82/10/R3 O'REILLY.J P. Region 2. Office of Director 1p 15894 020 24X Fiche 50-416.82/10/23.8210270050
- --B210290055 LER 82-074/OSL-0 on B20923 review revealed only one ECCB operational during B20722 fuel load Caused by personnel & procedural error resulting in operators not being fully aware of ECCS status Equipment problems corrected BYRD.R W Mississippi Power & Light Co B2/10/23 Region 2, Diffice of Director 3pp 15854 O21 24X Fiche 50-416,82/10/23,8210290050,

- 8210270124 Forwards LER 82-076/03L-0 MCGAUGHY. J P Mississippi Power & Light Cn 82/10/23 O'REILLY, J P Region C, Office of Director 1p 15854 018 24) Fiche 50-416.821/10/23.8210270124
- --8210570135 LER 82-079/03L-0 on 820923, small detectors in Zones 2-06. 2-07.2-17 & 2-20 of auxiliary bldg alarmed & would not clear No smoke or fire present Alarms deactivated Caused by dust accumulation Detectors cleaned ALBERT. J M Mississippi Fower & Light Co 82/10/23 Region & Office of Director ip 15854 019 24X Fiche 50-416.82/10/23 8210290124
- --8210270345 LER 82-088/03L-0 on 820923 discovered that Surveillance Procedure 06-EL-1E31-M-1002 allowed for bench test of drywell equipment drain sump jump running timers but did not specify in-sys testing Procedure revised BYRDR Mississippi Power Light Co 82/10/23 Region 2. Office of Director 2pp 15853 032 24X Fiche 50-416.82/10/23. R210203030
- B210290073 Forwards LER 82-082/03L-0 MCGAUOHY, J P Mississippi Power & Light Cu 62/10/25 O'REILLY, J P Region 2, Office of Director 1P 15852 147 24X Fiche 50-4(6,82/10/25,8210290073
- --9210290081 LER 82-082/03L-0 on 820925. Channels CDD of control room vent radiation monitors were outside required Tech Spec tolerences Caused by monitors being out of callor Channels recallor CMENAULT.W H Mississippi Power & Light Co. 82/10/25 Region 2, Office of Director lp. 15853 148 24X Fiche 50-416, 82/10/25, 8210290073
- B210270311 Forwards LER 82-089/03L-0 MCGAUGHY, J P Mississippi Power & Light Co 82/10/25 O'REILLY, J P Region 2, Office of Director 1p 15853 110 24X Fichs 50-416,82/10/25,8210290311
- --8210290332 LER 82-087/03L-0 on 820925 LPCS failed Surveillance lest 06-0P-1621-M-0001 due to failure of LPCS min flow valve (EZI-F011) Caused by tailure of valve to cycle Motor replaced, tested & sys returned to svc on 820930 WHITE.A J Mississippi Power & Light Co 82/10/25 Region 2, Office of Director 1p 15853 111 24X Fishe 50-416.82/10/25, 8210290311
- 8210290348 Forwards LER 82-090/99X-0 MCGAUCHYJ P Mississippi Power & Light Co 82/10/25 G'REILLY, J P Region 2. Office of Director 1p 15853 024 24X Fiche 50-416,82/10/25,8210290348
- --B210270351 LER B2-090/97X-O on B20920, five penetration room fire door alarm doors found inoperable, voiding ability to monitor door position Cause unknown Hourly fire watch established Alarms retested & returned to operability ALBERT, J M Mississippi Power & Light Co 82/10/25 Region 2, Office of Director ip 15853 025 24% Fiche 50-416.82/10/25, 8210270348
- DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8210040053 Advises of delay in response to Humphrey concerns recontainment issues pending 621001 conference discussion w/GE on local encroachments. Action Plans 1-4 Commitment based on 820929 telcon w/Containment Sys Branch
  DALE, L.F. Mississippi Power & Light Co. 82/09/30 DENTON, H.R.
  Office of Nuclear Reactor Regulation. Director ig 15581 307 2
  Fiche 50-416.82/09/30.8210040053
- 8210D40353 Forwards responses to 820826 request for add1 info re
  Items i-G.including current status & submittal schedule
  for outstanding items TF Plunkett prof qualifications
  encl
  DALE,L F Mississippi Power & Light Co 82/09/30 DENTON, H R
  Office of Nuclear Reactor Regulation, Director 8pp 15593 348
  24X Fiche 50-416,82/09/30,8210040353
- 8210060275 Responds to request for add1 info re HPCS svc water pump Add1 testing or mod not required Suggests meeting w/Equipment Qualification Branch to discuss evaluation results on 821008 in Bethesda, MD DALE, L F Hississippi Power & Light Co 82/10/04 DENTON, H. R Office of Nuclear Reactor Regulation, Director 4pp 15519 305 24X Fiche, 50-416, 82/10/04, 8210060295

- 82(0210217 Submits adding one design & testing of automatic depressuritation sys air sys.including response to MUREG-0737, Item II & 3 28. air sys testing & air sys makeup provisions Revision to FSAR Subsection 18 1 30 12 encl DALE.L F Mississippi Power & Light Co 82/10/18 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 15766 340 24X Fiche 50-416.82/10/18.8210210217
- S210270277 Forwards add1 info re containment design, in response to J Humphrey questions Status rept per usil 820715 ltr & OE proprietary info encl Proprietary info withheld Affidavit & II oversize drawings encl Aperture cards are in PPS BALELE F. Mississipps Power & Light Co. 82/10/22 DENTON, H & Office of Nuclear Reactor Regulation, Director. 82pp. 15852 198 244 Fiche 50-416,82/10/22,8210270277
- 8210280135 Provides add1 responses to NRC conterns re adequaty of onsite communication sys in areas exhibiting high ambient noise levels, use of 2-way radio sys & work stations requiring communications w/control room or shutdown panel DALE.L F Mississippi Power & Light Co 82/10/26 DENTON, H R Orfice of Nuclear Reactor Regulation. Director 3pp 15837 130 24X Fichs 50-416.82/10/26.8210280135
- B210290102 Outlines commitments made during B21025 teleon re design & testing of automatic depressorilation air sys Integrated leak test on sys will be performed every 18 months Justification for interim operation listed DALE.L. F. Mississippi Power & Light Co. B2/10/26 DENYON, H.P. Office of Nuclear Reactor Regulation, Director 2pp. 15854 OD1 24X Fiche 50-416,82/10/26 8210290102
- E NRC Safety Evaluation Report (SER), supply & correspondence
- B210190566 Advises of completion of the smocouple qualification testing per SER Suppl 3 Thermocouples considered qualified for seismic & hydrodynamic loads including variable pool swell Final test rept will be reviewed upon receipt DALELL F. Mississippi Power & Light Co. 82/10/14 DENTON-H R Office of Nuclear Reactor Regulation. Director 2pp 15736 LSS 24X Fiche 50-416.82/10/14,8210190566
- 8210200005 Forwards outline of in situ test for HPCS standby svc water gume flow induced vibration Test will be performed prior to startup following first refueling outage Commitment to conduct test resolves SER Suppl 2.8ection 3 10 concerns DALE:L F Mississippi Pawer & Light Co 82/10/18 DENTON, H R Office of Nuclear Reactor Regulatation, Director 7p 15754 341 E4X Fishe 50~416, 82/10/18, 8210200005
- 8210200030 Forwards swaluation of valve disc pin overstressing, addressing concerns & closing supplemental SER 2. Section 22 2 (issue il E 4 2), "Purge valve Operability "DALE.L F Mississippi Power & Light to B2/10/18 DENTON, H 8 Office of Nuclear Reactor Regulation, Director 7pp 15757 [94 24X Fishs 50-416, 62/10/18, 82/10/00030
- 6210200073 Forwards info re monitoring trend analysis program per commitment to summarise vibration monitoring analysis program for deep draft pump reliability per BFR Section 1 10 (13) DALELL F. Mississippi Power & Light Co. 92/10/19 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 15754 132 24X Fishe 30-416.82/10/18.82/020073
- 8210220425 Forwards add3 info ne qualification of hydraulic control units affected by variable pool swell loads Test response spectra-required response spectra comparisons should be sufficient to close concern in 8ER Suppl 3, Section 3 10 DALE-L F Mississippi Power & Light Co 82/10/19 DENTON-H R Office of Nuclear Reactor Regulation, Director 7pp (5779-103-24X Fiche 50-416-82/10/19,8210220425
- F Security, medical, emergency & fire protection plans

- --8210070044 Forwards public version of corrections to Table 4-] remergency action levels in response to NRC questions on Revision 6 to emergency plan Encl changes will be incorporated into plan by 821031

  DALE, L. F. Mississippi Power & Light Co. 82/09/09 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 18646-343-24X Fiche 50-416,82/09/17.8210070040
- --BRIGO70048 Public version of corrected Table 4-1 re emergency actics levels Initial & final notification forms encl # Mississippi Power & Light Co 82/09/09 app 15646 145 \_4) Fiche 50-416,82/09/17,8210070040
- B210010234 Forwards Revision 5 to physical security plan Revision withheld (ref 10CFR2 790)
  MCGAUGHY, J.P. Mississippi Power & Light Co. B2/09/22 DENTON, H. R. Office of Nuclear Reactor Repulation, Director 2pp. 18574 060
  244 Fichs 50-416, B2/09/22, B210010234

## G Adjudicatory correspondence

- 8210040115 Order granting State of LA 820921 motion for extension of time to respond to ASL3 820831 order LA response to NRC & applicant arguments due 821011 No further extension of time will be granted LAURENSON. J A Atomic Safety and Licensing Board Panel 82/09/30 Liguisiana, State of 3pp 15581 186 24X Fiche 50-416, 82/09/30 8210040115
- 82:0150462 Brief supporting State of LA Jul 1982 petition to participate as interested state Good cause shown for untimely petition Certificate of Svc encl LINDSEY, ID Louisiana, State of 82/10/11 Atomic Bafety and Licensing Board Panel Sipp 15703 073 24X Fichs 50-416,82/10/16 82:0150462
- 8210210393 Memorandum & order denying State of LA 820726 petition for intervention ASLB unable to consider challenges to Table 8-3 in proceeding Commission retained jurisdiction over decision to grant full power OL LAUKENBON, J A , BRIGHT-0 O , HARBOUR, J Atomic Bafety and Licensing Board Panel 82/10/20 Louisiana, State of 17pp 18763 184 24% Fiche 50-416, 82/10/20, 8210810393
- Q Inspection reports, IE Bulletins & correspondence
- 8210150013 Responds to noncompliance re emergency accountablility noted in IE Imap Rept 50-416/82-27 Interpretion of "onsite" questionable Other utils make same distinction of sits boundary being same as protected area DALE.L.F. Mississippi Fower & Light Co 82/07/19 O'REILLY.J.P. Region 2, Office of Director 2pp 13698 346 24X Fiche 50-416, 82/07/19, 8210150013
- 8210010442 Forwards IE Insp Repts 50-416/82-61 & 50-417/82-13 on 820817-20 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/09/03 8TAMPLEY, N L Mississippi Power & Light Co 2pp 15570 175 24
- --B210010447 IE Insp Repts 50-416/B2-61 & 50-417/B2-13 on 820817-20 % noncompliance noted Major areas inspected const deficiency repts for Unit 1 & observation of safety-related piping worl activities at Unit 2 BLAME, J J Division of Engineering & Technical Programs 82/09/02 4pp 15570 177 24X Fiche 50-416, 82/09/03, 821001642
- 8208170233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Bands " Svc list and, COBB.L I. Division of Fuel Facilities, Materials & Bafeguards 82/10/04 Consolidated Edison Co of New York. 66pp. 15761 253
- 8208190238 IE Bulletin 82-03, "Stress Carrosion Cracking in Thist-Hall, Large-Diameter: Stainless Steel, Recirculation Sys Piping at BMR Plants " Syc list and DEYOUND, R. C. Director's Office, Office of Inspection and Enforcement. 82/10/14 Consolidated Edison Co. of New York 115pg 15810.125 24X Fichs 50-000.82/10/14.8208190238
- 8210280132 Forwards responses to Instrumentation & Control Bys Branch 820714 questions re util evaluation of IE Info Notice 79-22. "Qualification of Control Sys Reliures Info re NRC review evasiable in MUREO-0831 DALE, L.F. Mississippi Power & Light Co. 82/10/25 DENTON.H 8 Office of Nuclear Reactor Regulation. Director 10pp 15937 130 24% Fichs: 50-415, 82/10/25, 8210280132

- S Reportable occurrences, LERs & related correspondence
- B2100B0223 Interim deficiency rept re unqualified Bettis air actuators on Henry Pratt valves (initially reported on B11029 Scope expanded to include other actuators Subjinot reportable per 100FR50 55(e) Final rept expected by 830331 MCOAUGHY, J.P. Mississippi Pawer & Light Co. 82/10/01 0'REILLY, J.P. Region 2, Office of Director. 4pp. 15638-049 24X Fiche 50-416,82/10/01.8210080223
- 82(0290193 Final Deficiency Rept PRD-82/36 re cadwell rebar splice testing Initially reported on 820920 Spec Change Notice ! issued requiring splice testing of each bar size All splices reviewed MCGAUOHY, J.P. Mississippi Power & Light Co. 82/10/20 O'REILLY, J.F. Region 2, Office of Director. Spp. 15854 004 22 Fiche 50-417.82/10/20.8210290193
- BOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3
- A Application/construction stage documents 2 correspondence
- 8210080105 Informs that bolt math discussed in util 820817 ltr mig & tasted to math spec requirements of SA-540. Grade 823, Class 2. in response to D Bellers request for add1 info Expeditious approval of ASHE Code Case N-310~1 requested CGUNSIL.41 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/09/28 GRANT.J Licensing Branch 1 ip 15440 274 24% fiche 50-423,82/09/28,8210080105
- 3210130331 Discusses revision of administrative procedures to incorporate revised working hour guidelines & provisions for authorizing deviations per 820208 & 0615 requests, TMI Item I A I 3, "Shift Manning" & Generic Ltr 82-12 CDUNS[L.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) CAONETTALJP Connecticut Yankee Abomic Power Co CAONETTALJP Connecticut Yankee Abomic Power Co CAONETTALJP Northeast Utilities 82/10/01 EISENHUT, D G Division of Licensing 3pp 15679 127 24X Fiche 50-000.82/10/01, 8210130331
- I Inspection reports, IE Bulletins & correspondence
- 208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Beeds " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguards 92/10/06 Consolidated Edison Co of New York 66pp 15761 256 24% Fishe 50-000.82/10/06.8208190233
- 210210241 Forwards IE Insp Rept 50-423/82-11 on 820802-31 & 0901-10 & notice of violation 
  STARDSTECKI.R Division of Project & Resident Programs 82/10/04 
  COUNSIL-W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 15766 247 24x Fiche 50-423,82/10/06,8210210241
- -8210210248 Notice of violation from lnsp on 820802-31 & 0901-10 \* Region i, Office of Director 82/10/06 ip 15766 247 24X fiche 50-423,82/10/06,8210210241
- -82(0210261 IE Insp Rept 50-423/82-11 on 820802-31 & 0901-10

  Noncompliance noted failure to follow design specs when storing electrical cables & follow requirements of document control procedure for use of const drawings

  MATTIA-J C. ELBASSER, T Division of Project & Resident Programs 82/10/04 9pp 15766 250 24X Fiche 50-423,82/10/06.8210210241
- 208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list encl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York LISPP 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- Reportable occurrences, LERs & related correspondence
- \*10210340 Interim deficiency rept re failure of pinion gear shear keys in Limitorque Model 880 (SD-25) Initially reported on 820804. Vitil currently awaiting info from vendor Next rept espected by 821115 (SD-25) (S
- 10190555 Final deficiency rept re design & const of metal shavings in containment recirculation pump motor initially reported on B20331 Event not considered reportable significant deficiency per 10GFR90 55e CGUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) CGUNSIL,W G Northeast Utilities B2/10/08 HAVNES,R C Region j, Office of Director 2pp 15734 124 24X Fichs SO-423, 82/10/08,8210190555

- B210250329 Interim deficiency lept re clacking of control rod guide tube support pins Initially reported on 800405 Westinghouse evaluating problem Next rept will be provided by 821116 CDUNSIL.W G. OPEKA.J F. Northeast Nuclear Energy Co. (subs. nf. Northeast Utilities). OPEKA.J F. Northeast Utilities. 82/10/12 HAYNESR C. Region 1, Orfice of Director. 1p. 15790-328-24% Fiche 50-423, 82/10/12, 8210250329
- 8210250290 Final deficiency rept re missing Westinghouse design thermal sleeves in 2-inch chemical b vol control sys (SD-24)
  Initially reported on 820712 Affected thermal sleeves will be eliminated
  GUMBILW G. OPEKA.J F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) OPEKA.J F. Northeast Utilities 82/10/13 HAYKES.R C. Region L. Office of Director. 2pp. 15791 160 2/4X
  Fiche 50-423,82/10/13,8210250290
- DOCKET 50-424 ALVIN W VOCTCE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 82100B0312 Summary of 820831 meeting w/util in Bethosda,MD re requirements of Reg Guide I 8B. "Collection, Storage & Maint of Nuclear Pawer Plant OA Records "Applicant concerned that tornado criteria not uell defined GRANT.J M Licensing Branch | 82/09/17 Licensing Branch 3pp 15643 338 24% Fiche 50-424.82/09/17,8210080312
- 8210120341 Forwards request for addl info re QA controls for field change notices Response due by 821020 yOUNOBLOOD B J Licensing Branch 1 82/09/20 DUTTUM D E Georgi Pauer Co épp 15591 053 24X Fiche 50-424.82/09/20.8210120341
- 8210080314 Summary of 820714 meeting w/utils & Bechtel Civil & Minerals, Inc in Bethesda, MD re Millett Fault Study Final rept will be submitted by mid-Oct ORANT, JM Licensing Branch 1 82/07/23 Licensing Branch 5pp 15663 353 24X Fiche 50-424,82/07/23,8210080314
- 8210070168 Informs that FSAR will be submitted by 830701 instead of 830701 Environ rept. security plan t antitrust info scheduled for 830701
  DUTTON D Georgia Power Co 82/10/01 EISENMUT, D G Division of Licensing 1p 15627
- 8210150362 Forwards "Studies of Postulated Militett Fault," Vols 1 & i', in response to USOS Open File Rept 82-156, which postulates existence of fault near facility Postulated Fault not capable
  DUTTON, D Georgia Power Co 82/10/15 EISENHUT, D 9 Division of Licensing 2pp 15711 011 24X Fiche 50-424,82/10/15,8210150362
- --8210150373 "Studies of Postulated Millett Fault." Vols ( & 2 Tharty oversize figures encl Apprture cards are available in PDR \* Bechtel Corp 82/10/31 807pp 15711 013 24X Fiche 50-424,82/10/15.8210150362
- 8210270246 Responds to NRC 820920 request for add1 info re controls for field change notices Field change notice program will not result in marginally acceptable design DUTTEN, D E Georgia Power Co 82/10/15 EISENRUT, D G Division of Licensing 13pp 15829 208 24X Fichs 50~424.82/10/15,8210270246
- O Inspection reports, IE Bulletins & correspondence
- 9210010182 Forwards IE Insp Repts 50-424/82-21 & 50-425/82-21 on 820817-20 No noncompliance noted DANCE:H C Division of Project & Resident Programs 82/09/09 KELLY:R J Georgia Power Co 2pp 15567 306 24X Fiche 50-424:82/07/09.8210010182
- --8210010187 IE Insp Repts 50-424/82-21 % 50-425/82-21 on 820817-20 No noncompliance noted Major areas inspected licensee action on previous insp items, storage & preventive maint of electrical & instrumentation equipment & IE circular followup RUFF.A 8 . CONLON.T E Division of Engineering & Technical Programs 82/09/08 4pp 15547 308 24X Fiche 50-424.82/09/09, 8210010182
- 8210150096 Forwards IE Insp Repts 50-424/82-19 & 50-425/82-19 on 820711-0810 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/09/15 KELLY.R J Georgia Power Co 2pp 15701 185 24X Fichs 50-424,82/09/15,8210150096

- --8210150103 IE Insp Repts 50-424/82-19 % 50-425/82-19 on 820711-0810 No noncompliance noted Major areas inspected primary containment fabrication, equipment handling & protection, structural steel installation ? steam generator mod SAUNDERS. W F BROWNLEE, V L Division of Project & Resident Programs 82/09/09 5pp 15701 187 24% Fiche 50-424-82/09/15, 8210150096
- 5210220159 Forwards IE Insp Repts 50-424/82-22 & 50-425/82-22 on 820911-0910 No noncompliance noted DANCE H C Division of Project / Resident Programs 82/09/29 KELLY:R J Georgia Power Co 2pp 15778 083 24X Fiche 50-424, 82/09/29, 8210220155
- --B210220159 IE Insp Repts 50-424/82-22 % 50-425/82-22 on 620811-0910 No noncompliance noted Major areas inspected primary containment fabrication, rebar welding, concrete placement & stean generator mode SAMOERS.W F. BROWNLEE, V.L. Division of Project % Resident Programs 82/09/29 Spp 15778-085 24% Fiche 50-424,82/09/29, 6210220155
- 9208190237 IE Info Notice 80-35. Suppl 1. "Leaking % Dislodged 1-125 Implant Seeds " Svr list enc! COBC L I Division of Evel Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 ab0 24% Fiche 50-000.82/10/06/8208190233
- SEUB190230 IE Bulletin 82-03. 'Stress Coirosion Cracking in Thick-Walli Large-Diameter Stainless Steel-Recirculation Sys
  Piping at BMR Plants "Svc list encl
  EFYGUNG.R C Director's Office. Office of Inspection and
  Enforcement 82/10/14 Consolidated Edison Co of New York
  115pp 15810 125 24x Fiche 50-000.82/10/14.8208190238
- 8210420204 Ack receipt of 820928 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-424/82-20 A 50-425/82 20 DANCE,H C Division of Project & Resident Programs 82/10/15 WELLY,R J Georgia Power Co 1p 15776 339 24% Fiche 50-424,82/10/15 82:02/20204
- -8210220208 Responds to NRC 820827 itr reviolations noted in IE Insp. Repts 50-424/82-20 5 50 425/82-20 Corrective actions contractor Procedure V-18 revised to address transition between different wall thicknesses FOSTER.D.O. Georgia Power Co. 82/09/20 DANCE.H.C. Region 2 Orfice of Director. 2pp. 15776-340 24X Fiche 50-424,82/10/10.6210220204
- F210220211 Forwards IE Insp. Repts 80-424/82-20 % 50-425/82-20 on B20809-13 % notice of violation DANCE, IC Division of Project & Resident Programs 82/08/27 KELLY, R.J. Georgia Power Co. 2pp. 15776-342 24X Fiche 50-424/82/10/15 B210220204
- --8210220213 Notice or Fiolation from Insp on 820809-13 4 Region 2, Giffice of Director 82/08/27 2pp 15776 344 24X Fiche 50-424 82/10/15.8210220204
- S. Reportable occurrences, LERs & related correspondence
- 8210220078 Interim deficiency rept re control cable length/sizing Initially reported on 820722 Deficiency determined reportable under 1005850 55(a) Final rept expected by 821022 FOSTER, D. Ø. Georgia Power Co. 82/10/08 GIREILLY, J.P. Region 2 Office of Director 1p 15778 184 24X Fiche 50-424, 82/10/08.
- 62:019062: PNO-11-92-112 area media interest occurred following licenses 82:015 issuance of news release re geological sourcey rept stating that no active earthquake fault exists in victinity of const site CLARK.K M. GittleAND J.T. Region 2 Office of Director 82/10/15 2pp 15737 217 247 Fiche 50-424.82/10/15.82:0190621

- DOCKET 50-425 ALVIN W VOGTLE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8210080312 Summary of 820831 meeting w/util in Bethosda, MD re requirements of Reg Guide 188, "Collection, Storage & Maint or Nuclear Power Plant GA Records "Applicant concerned that tornado criteria not well defined GRART, J.M. Licensing Branch 1 82/09/17 Licensing Branch 1 3pg 13663 338 24% Fiche 50-424, 82/09/17,8210080312
- 821012034; Forwards request for add1 info re QA controls for field change notices Response due by 821020
  YQUNGSLOOD.B J Licensing Branch 1 82/09/20 DUTTON,D E Oporgia
  Power Co App 15641 053 24X Fiche 50-424,82/09/20,821012034;
- 8210080314 Summary of 820914 meeting w/utils & Bechtel Civil & Minerals, Inc. in Bethesda, MD re Millett Fault Study Final rept will be submitted by mid-Oct OCRANT, J M Licensing Branch I 82/09/23 Licensing Branch I 5pp 15663 353 24% Fiche 50-424,82/09/23,8210080314
- 8210070169 Informs that FSAR will be submitted by 830701 instead of 830901 Environ rept, security plan & antitrust info scheduled for 830901 option, to general power to 82/10/01 EISENHUT, D G Division of Licensing 1p 13627 008 24X Fiche 50-424.82/10/01.8210070168
- E210150362 Forwards "Studies of Postulated Millett Fault," Vols 1 & 2, in response to USGS Open File Rept 62-156, which postulates eristence of fault near facility Postulated fault not capable
  DUTION, D. Opengia Power Co. 82/10/15 EISENHUT. D. O. Division of Licensing 2pp 15711 011 24X Fiche 50-424, 82/10/15, 8210150363
- --8210150373 "Studies of Postulated Millett Fault," Vols 1 & 2 Thirty oversize figures enc? Aperture cards are available in PDR \* Bechtel Corp 82/10/31 809pp 15711 013 24X Fiche 50-424,82/10/15,8210150362
- 0210270246 Responds to NRC 020920 request for add1 info re controls for field change notices field change notice program will not result in marginally acceptable design DUTTON, D.E. Georgia Power Co. 02710/15 EISENHUT, D.O. Division of Licensing 13pp 15029 230 24% Fiche 50-424, 82/10/15, 8210270246
- 3 Inspection reports, IE Bulletins 8 correspondence
- E210010182 Forwards IC Insp Repts 50-424/82-21 & 50-425/82-21 on 820817-20 No nancompliance noted DANCE.H C Division of Project & Resident Programs 82/09/09 KELLY,R J Georgia Power Co 2pp 15567 306 24X Fichs 50-424, 82/09/09, 8210010182
- --8210010187 IE Insp Repts 50-424/82-21 & 30-425/82-21 on 820817-20 Manoncompliance noted Major areas inspected licensee action on previous insp items, storage & preventive maint of electrical & instrumentation equipment & IE circular followup RUFF, A B , CONLON, Y E Division of Engineering & Technical Programs 82/09/08 4pp 15567 308 24X Fiche 50-424,82/09/09,8210010182
- 8210150096 Forwards IE Insp Repts 50-424/82-19 & 50-425/82-19 on 820711-0810 No noncompliance noted DANCE N C Division of Project & Resident Programs 82/09/15 KELLYR J Georgia Power Co 2pp 15701 185 24X Fiche 30-424.82/09/15.8210150096
- --8210150103 IE Inep Repts 50-424/82-19 & 50-425/82-19 on 820711-0010 % noncompliance noted Major areas inspected primary containment feath tation, equipment handling & protection, structural steel installation & steam generator mod SAUNDERS, W F . BROWNLEE, V L Division of Project & Resident Programs 82/07/09 5pp 15701 187 24X Fiche 50-424,82/07/15,8210150096
- 8210220155 Forwards | E | Imap Repts 50~424/82-22 & 50~425/82-22 on 820811-0910 No noncompliance noted | Resident Programs | 82/09/29 | KELLYR J Georgia Power Co 2pp 15778-083 24X | Fiche 50-424,82/09/29,8210220155
- --B210220159 IE Insp Repts 50-424/82-22 t 50-425/82-22 on 820811-0910 % noncompliance noted Major greas inspected primary conteinment fabrication, rebar welding, concrete placement & steam generator mods SANDERS, N. F., BROWNLEE, V. L. Division of Project & Resident Programs 82/09/29 Spp 15778 085 24X Fiche 50-424,82/09/29,8210220155

'OBI90233 IE Info Notice 80-35, Suppl 1, "Leaking & Pislodged I-125 Implant Seeds " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fichs 50-000.82/10/06.8208190233

DBJ90238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall.Large-Diameter, Stainless Steel, Recirculation Bys
Piping at BWR Plants " Svc list encl
DEYQUNOR C pirector's Office of Inspection and
Enforcement 82/10/14 Consultdated Edison Co of New York 

10220204 Ack receipt of 820928 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-424/82-20 % 50-425/82-20

50-423762-20 DAMCE, H.C. Division of Project & Resident Programs KELLY, R. J. Georgia Power Co. 1p. 15776 339 24X Ficho 50-424, 82/10/15, 8210220204

8210220208 Responds to NRC 820827 ltr re violations noted in IE Insp. Repts 50-424/82-20 to 50-425/82-20 Corrective actions contractor Procedure X-IB revised to address transition between different wall thicknesses FOSTER.D Clearly Region 2, FOSTER.D Clearly Regio FOSTER.D D Georgia Power Co 82/09/28 DANCE, H C Region 2, Office of Director 2pp 15776 340 24X Fiche 50-424,82/10/15,8210220204

3210220211 Forwards IE Insp Repts 50-424/82-20 & 50-425/82-20 un B20807-13 to notice of violation
DANCE, N C Division of Project & Resident Programs
KELLY, R J Georgia Power Co 2po 1577A 342 344 82/08/27 KELLY, R J Georgia Power Co 2pp Fiche \$0-424, 82/10/15, 8210220204

3210220213 Notice of violation from insp on 820809-19 • Region 2, Office or Director 82/08/27 2pp 15776 344 24X Fiche 50-424,82/10/15,8210220204

1210220218 IF Inso Rents 50-424/82-20 & 50-425/82-20 on 820809-13 Noncompliance noted visual insp procedure inadequate for piping butt welds & failure to follow procedure for removal of arc strikes COLEY, J L . BLAKE, J 62/08/26 App 15 .J Division of Engineering & Technical Programs 15776-346 - 24X Fiche 50-424,82/10/15,8210220204

Reportable occurrences: LERs & related correspondence

O22007B Interim deficiency rept re control cable length/sixing nitially reported on 620922 Deficiency determined aportable under IOC/R50 55(e) final rept expected by OSTER, D. O. Georgia Power Co. 82/10/08 O'REILLY, J. P. Region frice of Director ip. 15778 184 24% Fiche 50-424.82/10/08, Banton D.

210220078

019062: PNO-II-82-112 area media interest occurred following DIPOSE PROFILE area media interest occurred following icensee 821015 issuance of news release re geological urvey rept stating that no active earthquake fault exists a vicinity of const site LARK.K M . GILLILAND.J T Region 2, Office of Director 82/10/15 pp 15737 217 24X Fiche 50-424.82/10/15.8210190421

4ET 50-434 SURRY POWER STATION, UNIT 3 Reportable occurrences, LERs & related correspondence

0290267 Part 21 deficiency rept re potential galling problem between tem & bonnet of 1 25-inch & larger A105 carbon steel & item to butter by 1 20-lich & larger Alvo Caroon Steel & 162-F22 valves supplied feb 1781-Aug 1782 Valves should be riviced & stem &/or bornet replaced \*\*ABELLE.1. D Conval, Inc. 82/10/11 HAYNES.R C Region 1, Office \*\*Director\*\* 17pp 15884 232 24X Fichs 50-000.82/10/11.

LET 50-435 SURRY POWER STATION, UNIT 4 teportable occurrences. LERs & related correspondence

1270267 Part 21 deficiency rept re potential galling problem between em & bonnet of 1 25-inch & larger A103 carbon steel & 62-f22 valves supplied Feb 1781-Aug 1782 Valves should be rviced & stem 5/or bonnet replaced ABELLE, L D Conval, Inc 62/10/11 HAYNES, R C Region 1, Office Director 17pp 19854 232 24% Fiche 50-000, 82/10/11, 198854 23

DOCKET STN-50-437 FLOATING NUCLEAR PLANT

G Adjudicatory correspondence

6210150404 Order extending time until 821022 for Commission to art to review ALAB-666 & ALAB-689 CHILK.S J. Office of the Secretary of the Cummission 82/10/12 Commissioners 1p 19704-024 24X Fiche 50-437.82/10/12.

8210260460 Order extending time until B2H112 for Commission to act to review ALAB-686 & ALAB-689 CHILKS SU Office of the Secretary of the Commission 82/10/22 Commissionurs to 15807 224 24x fiche 50-437,82/10/22.

Q Inspection reports, IE Bulletims \* correspondence

8208190233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged I 12% Englines Seeds "Svc list encl Implant Seeds "Svc list encl CDBR.L I Division of Fuel Facilities, Materials & Safeguards B2/10/06 Consolidated Edison Co of New York 66pp 15761 297 24/ Fiche 50-000,82/10/06,8208/90233

8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Wall Large Timester Statistics Steering at BWR Plants "Size list encl DEYQUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 19810 125 24% Fiche 50-000, 82/10/14,8208190238

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1 A Application/construction stage documents & correspondence

6210280013 Responds to FOIA request for all internal, non-public EDUACOULD RESponds to IUIA request for all internal non-public documents. Flemos, evaluation repts & other mail dealing u/nuclear plant operations forwards documents listed in App A FELTON, J M Division of Rules and Records 82/09/17 MCINNIb.D News & Observer 5pp 15860 065 24% Fiche 50-000.82/09/17, 8210280013

--B2102B0100 Notifies that on 820224.C Alderson advised that rept sent re possible willful violation of reporting requirements & falsification of GA & guard qualification records at facilities
RESNER.H E Office of Inspector & Auditor 82/03/01 Office
Inspector & Auditor 1p 15861 039 24X Fiche 50-000,82/09/1/. Office of 6210280013

8210070348 Forwards responses to NRC 820903 questions on facilities, "Bellefonte Site," "Rept on Old Bellefonte Historical Site in Northern AL" & "Archaeological Survey of Scottsboro - Lim Rock 161 kV Transmission Line & Fort Payne "MILLS,L M Tennessee Valley Authority 82/10/04 ADENSAM. ELicensing Branch 4 32pp 15564 001 24X Fiche 50-438,82/10/04,82/10070348

--8210070355 "Bellefonte Site " FUTATO.E M Alabama, Univ of, 1 JA 300 77/6 15664 032 24% Fiche 50-438,82/10/04/8210070348 77/09/30 2A80a

--8210070358 HP--+ on Did Patternaha Ht-1-NANCE C R 15667

--e210

- n Inspection reports. IE Bulletins & correspondence
- 6210220180 Forwards IE Insp Repts 50-438/82-17 5 50 439/82-17 on B20507-10 5 notice of violation LONG.F.L. Division of Project 5 Resident Programs B2/05/28 PARRIS.H.C. Tennessee Valley Authority 2pp 15776 246 24X Fiche 50-438 82/05/28, 8210220180
- 8210220193 Notice of violation from inspin 820607-10 a Division of Project 3, Resident Programs 82/06/28 15776 248 244 Fiche 50-438, 82/06/28 8210220190
- --8210220189 [E Insp Repts 50-438/82-17 % 50-439/82-17 on 820607-10 Nenconbliance noted space heaters not energized on diesel generator IRT-EMB-001G-8 / discrepancies between cable bend radia 7 vertical cable tray fittings identified HUNT-11 D MERRIMENTHER.N . CONLON, T E Division of Engineering & Technical Programs 62/06/25 5pp 15776 249 24X Fiche 50-438.82/06/28.8210220180
- EC10010037 Advises of upcoming constrinsprto be conducted during GR0920-1001 & 1011-15 Areas to be inspected fisted on encl present visit to be held on G20830 to obtain preliminary into LEMIS.R C Division of Project & Resident Programs 62/08/31 PARRIS.H G Tennessee Valley Authority 3pp 15545 163 24% Fiche 50-438.62/08/31, 6210010037
- 6210010421 Ack receipt of 820907 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/82-12 & 50-439/82-10 Bersson of Project & Resident Programs 82/09/17 PARRIS.H G Tennessee Valley Authority Ip 15569 351 24X Fiche 50-438.82/09/17.8210010421
- --8210010427 Forwards revised response to NRC 820521 ltr re violations noted in IE Insp Repts 50:436/82-12 Corrective actions 9A program 3 procedure to require GC insp before fitup of piping components revised MILLS.L M Tennessee Valley Authority 62/09/07 O'REJLLY.JP Region 2 Office of Director 3pp 15569 352 24X Fiche 50 438.82/09/17.8210010421
- 8210150149 Forwards IF Insp Repts 50-438/82-27 & 50-439/82-27 on 820830-0903 No noncompliance noted VERRELLID M Division of Project & Resident Programs 82/09/21 PARRIS, H G Tennessee Valley Authority 2pp 15697 282 24% Fiche 50-438,82/09/21,8210150149
- 8210150164 IE Insp Repts 50-433/82-27 & 50-439/82-27 on 820830-0903 No noncompliance noted Major areas inspected structural concrete \* licensee action on previously identified items HARRIS.JR CONLON IE Division of Engineering & Technical Programs 82/09/17 4pp 15697 284 24X Fiche 50-438/82/09/21, 8210150149
- B210010191 Ack receipt of B20913 ltr informing NRC of steps taken to correct violations noted in JE Insp Repts 50-438/82-18 & 50-439/82-18 Developed to the VERRELLI.D M Division of Project & Resident Programs 82/09/22 FARRIS.H O Tennessee Valley Authority ip 15568 078 24% Fiche 50-438.82709/22.8210010191
- -8210010197 Responds to NRC 820726 ltr re violations noted in IL Insp Repts 50-438/82-18 % 50-439/82-16 Corrective actions QC investigation ropts initiated for each discrepant item KAMMER.D 8 Tennessee Valley Authority 82/09/13 0'REILLY, J.P. Region 2. Office of Director 3pp 15568 079 24X Fiche 50-438.82/09/22.8210010191
- --8210060200 Forwards IE Insp Repts 50-438/82-18 & 50-439/82-18 on 820608-11 & notice of violation W/o notice of violation VERRELLID M Division of Project & Resident Programs 82/07/26 PARRIS-M O Tennessee Valley Authority 2pp 15548 082 24X Fiche 50-438.82/09/22.8210010191
- 8210150171 Ack receipt of 920909 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/82-22 & 50-439/82-22 LEHIS:R C Division of Project & Resident Programs 82/09/23 PARRIS:H G Tennessee Valley Authority 1p 15707 184 24X Fiche 50-438.82/09/23-821015017

- --8210150181 Responds to NRC 820812 Itr reviolations noted in It Insp.
  Repts 50-438/82-22 & 50-439/82-22 Corrective actions hold
  placed on further installation of shielded power cable in
  cable tray sys Investigation continuing
  MILLS, L. M. Tennessee Valley Authority 82/09/09 O'REILLY, J.P.
  Region 2, Office of Director 2pp 15707 185 24X
  Fiche 50-438, 82/09/23, 8210150171
- --8210150189 Forwards IE Insp Repts 50-438/82-22 & 50-439/82-22 on 8207\3-16 & notice of riolation LEWIS,R C Division of Project & Resident Programs 82/08/12 PARRIS.H O Tennessee Valley Authority 2pp 15707 187 24x Fiche 50-438, 82/09/23, 8210150171
- --8210150175 Notice of violation from insp on 820713-16 + Division of Project & Resident Programs 82/08/12 lp 15707 189 24X Fiche 50-438,82/09/23,821015017(
- ~-8210150207 IE Insp Repts 50-438/82-22 & 50-439/82-22 on 820713-14 Noncompliance noted discrepancies between cable bend radii & vertical cable tray fittings GIBBONS.T S., CONLON.T E. Division of Engineering & Technical Programs 82/08/11 3pp 15707 190 24x Fiche 50-438.82/09/23, 8210150171
- 8208190233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl CD88.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000.82/10/06.8208190233
- 8210220387 Acx receipt of 820210 ltr re violations noted (n IE Supplemental Investigation Repts 50-439/81-26 & 50-439/81-26 on 820707-08 Violation against provisions of Energy Reorganization Act withdrawn O'REILLY, J.P. Region 2. Office of Director 82/10/12 PARRIS, H. & Tennessee Valley Authority 2pp 15780 259 24X Fiche 50-438, 82/10/12, 8210220387
- --8210220405 IE Supplemental Investigation Repts 50-438/81-26 & 50-439/81-26 on 820707-08 No noncompliance noted Major areas investigated reaponse to Section 210 of Energy Reorganization Act of 1974 URYC, B. MURPHY.D D. ALDERSON.C E. Region 2. Office of Director 82/09/21 3pp 15780 261 24X Fiche 50-438.82/10/12,8210220397
- --8210220422 Responds to NRC 820111 ltr re violations noted in IE.
  Investigation Repts 50-438/81-26 t 50-437/81-26 Denies that
  employee terminated in violation of Energy Reorganization
  Act 8C procedure revised correcting second violation
  MILLS,L H Tennessee Valley Authority 82/02/10 0'REILLY,J P
  Region 2, Office of Director 5pp 13780 264 24X
  Fiche 50-438/82/10/12/8210220387
- --0210220432 Forwards four exhibits inadvertantly omitted from 820111 ltr transmitting IE Investigation Repts 50-438/81-26 & 50-439/81-26 ALDERSON.C E Region 2: Atlanta, Office of the Director (81/03/01) 82/01/19 PARRIS.H C Tennesses Valley Authority 6pp 15780 269 24X Fiche 50-438, 82/10/12: 8210220387
- --8210220446 IE Investigation Repts 50-438/81-26 & 50-439/81-26 on 810831-1001 Noncompliance noted employee discharged in violation of Energy Reorganization Act of 1974 & GC not performed in accordance w/Procedure GAP-17 i VORSE, J Y , ALDERSON C E Region 2, Atlanta, Office of the Director (81/03/01) 81/12/08 24pp i5780 275 24X Fiche 50-438,82/10/12,8210220387
- 6208170236 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Dlameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl
  DEYOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York
  115pp (9810 125 24X Fiche 50-000, 82/10/14, 8208170238
- 8210220237 Ack receipt of 820812 & 0924 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-439/82-22 & 50-439/82-22 LEMIS.R C Division of Project & Resident Programs 82/10/15 PARRIS.H C Tennessee Valley Authority, ip 15776 206 24X Fiche 50-438, 82/10/15.8210220237
- --B210220271 Responds to NRC 820812 ltr re violations noted in IE Insp.
  Repts 50-438/82-22 & 50-439/82-22 Revises 820909 ltr re
  date full compliance expected Compliance will be achieved by
  821220
  MILLS, L. M. Tennessee Valley Authority 82/09/24 D'REILLY, J. P.
  Region 2: Office of Director 2pp 15776 207 24X
  Fiche 50-438, 82/10/15, 8210220237

- S Reportable occurrences, LERs & related correspondence
- \$210010011 Third Interim Deficiency Repts 50-438/81-77 & 50-439/81-76 re allowable stresses for pipe support design Initially reported on 811207 Deficiency details being evaluated Next rept by 821217
  MILLS.L M Tennessee Valley Authority 82/09/20 O'REILLY, J P Region 2. Office of Director 2pp 15565 148 24X
  Fiche 50-438/82/09/20,8210010011
- 8210080222 Second interim deficiency rept re B&W design of RCS supports 5 restraints Initially reported on 820618 Helds & shear bars at interface points potentially undersized Investigation continuing Next rept expected by 821220 HILLS, L M Tennessee Valley Authority 82/09/24 0'REILLY, J P Region 2. Office of Director 2007 15638 081 24X Fiche 50-438.82/09/24,8210080222
- 6210080247 Third & final deficiency repts re resolution of unanticipated vibratory loading concerns Initially reported on 311228 Program developed to insure piping sys operate within design parameters Next rept provided by 821217 MILLS, L.M. Tennessee Valley Authority 82/09/24 0'REILLY, J.P. Region 2. Office of Director 3pp 15438 104 24X Fiche 50-000,82/09/24,8210080247
- 82:10080272 Seventh interim deficiency rept re imprecise specs in util procurement document resulting in improper seismic qualification of 82H equipment in local instrument panels initially reported on 801:25 Util awaiting 82W input MILLS, L M Tennessee Valley Authority 82/09/24 O'REILLY, J P Region 2. Office of Director 2pp 15638 306 24X Fiche 50-438.82/09/24,8210080272
- 3210050115 Fifth interim deficiency rept re failure of boits & nuts to meet ASTM requirements (initially reported on 810924 Engineering interpretation/recommendation awaited Also reported per Part 21 Next rept expected by 830110 MILLS, L.M. Tennessee Valley Authority 82/09/27 O'REILLY, J.P. Region 2, Office of Director 2pp 15601 349 24X Fiche 50-438,82/09/27.8210050115
- 3210050117 Supplemental deficiency rept re Lambda power module failures Initially reported on 801218 Addl discrepancies identified w/power supplies Corrective action will be completed by 830301 Also reported per Part 21 MILLS.L.M. Tennessee Valley Authority 82/09/27 O'REILLY, J.P. Region 2. Office of Director ip 15601 351 24X Fiche 50-438,82/09/27.8210050119
- 210050074 Fourth interim deficiency rept re seismically unqualified auxiliary bldg fuel handling zone ventilation fans Initially reported on 810506 Contract awarded to provide qualified coils in fans Next rept by 830222 MILLS.L M Tennessee Valley Authority 82/07/28 0'REILLY, J P Region 2. Office of Director 2pp 15604 234 24X Fishe 50-438,82/07/28,8210050074
- 210050247 Final deficiency rept re use of insoluble give for purge dams in stainless attel piping Initially reported on 820322 dive residue left in piping six will not cause safety problems Glue will dissolve MILLS.L M Tennessee Valley Authority 82/09/28 O'REILLY.J P Region 2. Office of Director 5pp 15607 076 24X Fiche 50-438.82/09/28.82/090247
- 210050273 First interin deficiency rept re six sheared motor ginion teys in Linitorque Model SB-0-25 motor operators Initially reported on 820830 Valves w/motor operators being Labulated Next rept will be submitted by 821122 MILLS.L M Tennesseo Valley Authority 62/09/28 O'REILLY. J P Region 2. Office of Director 2pp 15609 070 24X Fiche 50-000.62/09/28.6210050293
- '10050407 First interin deficiency rept re design problems w/steam generators Initially reported on 820830 B&M proposed preliminary design change to inject warm feedwater into header Mext rept by 621127 Also reportable per Part 21 MILLS.L H Tennessee Valley Authority 82/09/28 O'REILLY. J P flegion 2. Office of Director 1p 15603 004 24X Fachs 50-438, 82/09/28,8210050407
- '10060274 Seventh interim deficiency rept re discrepancies in IfT Grinnel weld depositions initially reported on 800905 ITT Grinnel revision of affected hanger detail sheets near completion Also reported per Part 21 Next rept by 830315 MILLS.L M Tennessee Valley Authority 82/09/29 D'REILLY, J PRegion 2, Office of Director 2pp 13621 178 24X Fiche 50-438, 82/09/29.8210060274

- 8210080307 Third interim deficiency rept re defective weldalets on NAVCO spool pieces installed in DHR sys & makeup & purification sys piping Initially reported on 820224 Next rept due on 830208 Also reported per Part 21 MILLS.L M Tennessee Valley Authority 82/10/01 0'REILLY.J P Region 2, Office of Director 2pp 15638 119 24X Fiche 50-438.82/10/01,8210080307
- 8210080140 First interim deficiency rept to corrosion in high pressure fire protection sys [nitially reported on 820703 Corrosion analysis in progress to determine potential deficiencies in safety-related areas Next rept expected by 830831 MILLS.L M Tennessee Valley Authority 82/10/04 0'REILLY.J P Region 2. Office of Director 2pp 15640 142 24X Fiche 50-000.82/10/04.8210080160
- 8210080278 Fourth interim deficiency mept me Viking flow control valves in fire protection sys indically meported on 811124 Engineering Change Notice 1584 initiated implementing affected drawing mevisions Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 82/10/04 O'REILLY, J P Region 2. Office of Director 2pp 15638 294 24X Fiche 50-438,82/10/04,8210080278
- 8210130407 Fourth interim deficiency mept nonconservative FSAR analysis for loss of normal feedwater event Initially reported on 810316 ASME code limits will be exceeded following loss of feedwater Also reported per Part 21 MILLS.L M Tennesses Valley Authority 82/10/05 O'REILLY. J P Region 2. Office of Director 2pp 15681 008 24X Fiche 50-438.82/10/05.8210130407
- 8210220071 Final deficiency rept re attachment of pipe supports to 6-inch strip plates initially reported on 811231 Field mode for unacceptable supports scheduled for completion by 831001 MILLS.L M Tennessee Valley Authority 82/10/07 O'REILLY.JP Region 2, Office of Director 2pp 15778 189 24X Fiche 50-438.82/10/07,8210220071
- 8210220350 First interim deficiency rept re diesel generator bldg coblotray support welds made as fillet welds instead of grove welds insteally reported on 820708 Supports being reworked Process spec revised Next rept to be submitted by 830124 MILLS.t. M. Tennessee Valley Authority 82/10/08 O'REILLY. J.P. Region 2. Office of Director 2pp 15776 279 24X Fiche 50-438.82/10/08.8210220350
- 8210190528 Final deticioncy rept re overpressurization of makeup & purification piping & valves Initially reported on 820928 Valves visually examined for signs of distress & site personnel retrained re hydrostatic sys test procedures MILLS.L.M. Tennessee Valley Authority 82/10/12 O'REILLY, J.P. Region 2. Office of Director Jpp 15751 316 24X Fiche 50-438.82/10/12,8210190528
- 8210270328 Second interim deficiency rept re use of nonconservative calculational method to evaluate General Const Spec Q-32 spacing violations initially reported on 820528 Next rept will be sent by 830528 MILLS.L M Tennessee Valley Authority 82/J0/12 O'REILLY.J P Region 2. Office of Director 2pp 15853 064 24X Fiche 50-000, 82/10/12, 8210270328

- 8210200322 First interin deficiency rept re generic deficiencies in solid state control sys % basic control room switch modules supplied by Consolidated Controls Corp Initially reported on 820916 Next rept by 830519 Also reported per Part 21 MILLS:L M Tennessee Valley Authority 82/10/18 O'REILLY, J P Region 2. Office of Director 2pp 15799 342 24X Fiche 50-438.82/10/18 8210260322
- 6210260251 Final deficiency rept re work releases allowing const to cut reinforcing steel to install anchor bolts for pipe supports (initially reported on 820727 Personnel instructed to review fesign drawings more carefully MILLS.L.M. Tennessee Valley Authority 82/10/19 0'REILLY, J.P. Region 2 Ofrice of Director 2pp 15799-350 24X Fiche 50-436.82/10/19.8210260251
- FE10260105 Third interim deficiency rept re governor lube oil conlar Initially reported on 820303 Supplier has provided drawing procedure to relocate cooler below governor Vendor working to identify cause Also reportable per Part 21 MILLS.L. H. Tennessee Valley Authority 82/10/20 O'REILLY, J.P. Region 2. Office of Director 2pp 15799 120 24X Fiche 50-438, 82/10/20, 8210260105
- 6210260107 Second interim deficiency rept re failed valve control unit Initially reported on 820727 Vendor has not responded w/recommended disposition Nerl rept will contain additinfore vendor reply Also reportable per Part 21 MILS LM Tennessee Valley Authority 82/10/20 0'REI(LY, J P Region 2 Office of Director 2pp 15799 117 24X Fiche 50-438, 82/10/20, 8210260107
- 2010290274 Final rept for Deficiencies B & E & seventh interim rept for Dericiencies A & D re control of procurement activities initially reported on 810316 Final corrective actions noted Next rept expected by 830468 MILLS.L H Tennessee Valley Authority 82/10/21 O'REILLY, J P Region 2. Office of Director 4pp 15853 143 24X Fiche 50-000 82/10/21, 8210290274
- 8210290248 Revised final deficiency rept re structural tubing exceeding AMS allowables Initially reported on BioBi3 Design drawings which dictate configuration of 86 cable tray supports altered to ensure seismic qualification MILLS, L.H. Tennessee Valley Authority 82/10/22 0'REILLY, J.P. Region 2. Office of Director 3pp 15853 122 24X Fiche 50-438, 82/10/22, 8210290248
- BOOKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- FEIO280013 Responds to FQIA request for all internal non-public documents, means, evaluation repts & other matl dealing w/ nuclear plant operations forwards documents listed in App A FELTON, J M Division of Rules and Records 82/09/17 MCINNIS, D Mews & Observer 5pp 15860 065 24% Fiche 50-000,82/09/17. 8210280013
- --B210280100 Notifies that on 820224. C Alderson advised that rept sent re possible willful violation of reporting requirements & ralsification of GA & guard qualification records at facilities RESNER.ME Office or Inspector & Auditor 82/03/D1 Office of Inspector & Auditor 82/03/D1 Office of Inspector & Auditor 1p 15861 039 24% Fiche 50-000.82/09/1/,
- 52:10070348 Forwards responses to NRC 820703 questions on facilities,
  "Bellefonts Site." "Rept on Old Bellefonts Historical Site
  in Northern AL" & "Archaeological Survey of Scottsboro Lim
  Rock 161 kV Transmission Line & Fort Payne "
  MILLS, L M Tennessee Valley Authority 82/10/04 ADENSAM, E
  Licensing Branch 4 32pp 15864 ODI 24X Fiche 50-438, 82/10/04,
  8210070348

- F Security, medical, emergency & fire protection plans
- 8210260189 Confirms that evacuation time estimate study reviewed by both local & Th state authorities Population density & distribution info provided by Th Dept of Civil Defense based on 1980 census
  MILLS.L. M Tennessee Valley Authority 82/10/20 ADENSAM.F. G. Licensing Branch 4 2pp 18799 030 24X Ficha 50-000,82/10/20.8210260189
- O inspection reports, IE Builetins % correspondence
- 821020180 Forwards IE Insp Repts 50-438/82-17 & 50 4397/32-17 on 820407-10 & notice of violation LONO, F. L. Division of Project & Resident Programs 82/04/28 PARRIS.H D Tennessee Valley Authority 2pp 157/6 246 24% Fiche 50-438,82/04/28,0210220180
- --8210220189 IE Insp Repts 50-438/82-17 to 50-439/82-17 on 82080/-10 Moncompliance noted space heaters not energised on diesel generator IRT-ENB-0010-8 to iscrepancies between cable bend radio & vertical cable tray fittings identified HUNT-M D. MERRIMEATHER.N. CONLON-T E Division of Engineering & Technical Programs 82/06/25 Spp 15776 249 24x Fichs 50-438, 82/06/25 8210220180
- 8210010039 Advises of upcoming const inspite be conducted during 820920-1001 & 1011-15 Areas to be inspected listed on encl Preinspivisit to be hold on 820830 to obtain preliminary into LEMIS.R C Division of Project & Resident Programs 02/08/31 PARRIS.H 0 Tennessee Valley Authority 3pp 15365 147 24% Fiche 50-438.82/08/31.8210010037
- 8210010421 Ack receipt of 820707 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-438/82-12 & 50-439/82-12 VERRELT, DM Division of Project & Resident Programs 02/09/1/PARRIS, NG Tennessee Valley Authority ip 19567 391 24x Fiche 50-438, 82/07/17, 8210010421
- 8210150149 Forwards IC Insp Repts 50-438/82-27 & 50 439/82-27 on 820830-0903 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/09/21 PARRIS, H O Tennessee Valley Authority, 2pp 15697 202 24x Fiche 50-438, 82/09/21, 8210150149
- ~-8210150164 IE Insp Repts 50-438/82 27 & 50-439/82-27 on 890810 0903 h; noncompliance noted Major areas inspected structural concrete & licensee action on previously identified items HARRIB.J R. CONLON.T E Division of Engineering & Technical Programs 82/09/17 4pp 15697 284 24X Fiche 50-438 82/03/21.
- G210010191 Ack receipt of 620913 ltr informing NRC of steps taken to correct violations noted in IC Insp Repts 50-436/62-10 & 50-439/82-10 & VERRELLI, D M Division of Project & Resident Programs 62/09/22 PARRIS, H Q Tennessee Valley Authority ip 18560 078 24x Fichs 50-438, 62/09/22, 6210010191
- --8210010197 Responds to NRC 820726 ltr re violations noted in IE Insp.
  Repts 50-438/82-18 t 50-439/82-16 Corrective actions 0C
  investigation repts initiated for each discrepant item
  KAMMER, D S Tennessee Valley Authority 82/09/13 0'/REILLY, J.P.
  Region 2, Office of Director 3pp 15568 079 24X
  Fiche 50-438,82/09/22,8210010191
- --8210010200 Forwards IE Inap Repts 50-438/82-18 & 50-439/82-18 on 820608-11 & notice of violation M/o notice of violation VerRetLi, D M Division of Project & Resident Programs 02/07/24 PARRIS, H O Tennessee Valley Authority 2pp 15560-082 24x Fiche 50-438,82/09/22,8210010171
- ---8210010203 IE Insp Repts 50-438/82-18 t 50-439/82-18 on 820608-11 Noncompliance noted failure to follow procedure for hangar insps YORK, J W , ECONDMOB, N Division of Engineering & Technical Programs 82/07/23 6pp 15568 084, 24X Fiche 50-438.82/09/22.
- 82(015017) Ack receipt of 820909 itr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-439/82-22 & 50-439/82-22 & LEWIS.R C Division of Project & Resident Programs 82/09/23 PARRIS.H Q Tennessee Valley Authority 1p, 19707 184, 24x Fiche 50-438, 82/09/23, 82(015017)

- --0210150181 Responds to NRC 820812 ltr re violations noted in <sup>1</sup>E Insp Repts 50-438/82-22 & 50-439/82-22 Corrective actions hold placed on further installation of shielded power cable in cable tray sys Investigation continuing HILLS.L M Tennessee Valley Authority 82/09/09 O'REILLY, J.P. Region 2, Office of Director 2pp 15707 185 24X Fiche 50-438,82/09/23,8210150171
- --8210150189 Forwards IE Insp Repts 50-438/82-22 & 50-439/82-22 on 820713-16 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/08/12 PARRIS.H G Tennessee Valley Authority 2pp 15707 187 24X Fiche 50-438,82/09/23-8210150171
- --8210150195 Notice of violation from insp on 820713-14 4 Division of Project & Resident Programs 82/08/12 is 15707 189 24% Fiche 50-438, 82/09/23, 8210150171
- --8210150207 IE Insp Repts 50-438/82-22 & 50-439/82-22 on 820713-16 Noncompliance noted discrepancies between cable bend radii & vertical cable tray fittings OIBBUNS,TS , CONLOW,TE Division of Engineering & Technical Programs 82/08/11 3pp 15707 170 24X Fiche 50-438/82/09/23, 8210150171
- 8208190233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.t I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000,82/10/06,8208190233
- 8210220387 Ack receipt of 820210 ltr re violations noted in IE Supplemental Investigation Repts 50-438/81-26 & 50-439/81-26 on 820707-08 Violation against provisions of Energy Reorganization Act withdrawn O'REILLY, J P Region 2. Office of Director 82/10/12 PARRIS, H & Tennessee Valley Authority 2pp 15780 259 24X Fiche 50-438, 82/10/12,8210220387
- --8210220406 IE Supplemental Investigation Repts 50-439/81-26 & 50-439/81-26 on 820707-08 No noncompliance noted Major areas investigated response to Section 210 of Energy Reorganization Act of 1974
  URYC, B. MURPHY, D. D. ALDERSON, C. E. Region 2, Office of Director 82/09/21 3pp 15780 261 24X Fiche 50-408.82/10/12,8210220387
- --0210220422 Responds to NRC B20111 ltr re violations noted in IE.
  Investigation Repts 50-438/81-26 & 50-439/81-26 Denies that
  employee terminated in violation of Energy Reorganization
  Act &C procedure revised correcting second violation
  HILLS.L.M. Tennessee Valley Authority, 82/02/10 D'REILLY, J.P.
  Region 2. Office of Director Spp 19780 264 24X
  Fiche 50-438, 82/10/12, 8210220387
- --B210220432 Forwards four exhibits inedvertantly omitted from 820111 itr transmitting IE Investigation Repts 50-438/81-26 & 50-439/81-26 & ALDERSON.C E Region 2. Atlanta. Office of the Director (81/03/01) 62/01/17 PARRIS, H O Tennesse Valley Authority opp 15780 267 24% Fiche 50-438,82/10/12,8210220387
- ~-8210220446 IE Investigation Repts 50-438/81-26 & 50-439/81-26 on 810831+1001. Noncompliance noted employes discharged in violation of Energy Reorganization Act of 1974 & GC not performed in accordance w/Procedure QAP-17 1 VORSE.J Y , ALDERSON.C E Region 2, Atlanta: Office of the Director (81/03/01) 81/12/08 24pp 15780 275 24X Fiche 50-438,82/10/12,8210220387
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hall, Large-Diameter, Stainless Steel, Recirculation Sys Figing at BMR Plants "Svc list encl DEYOUNDER C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York (15pp. 15810-125 24X Fichs 50-000, 82/10/14, 8208190238
- 8210220237 Ack receipt of 920812 & 0924 ltrs informing NRC of steps taken to correct violations noted in IE Imap Repts 50-439/92-22 & 50-439/92-22 LEMIS,R C Division of Project & Resident Programs 82/10/15 PARRIS,H O Tempssee Valley Authority Lp. 15776 206 24X Fichs 50-438,82/10/15.8210220237
- --B210220271 Responds to NRC B20B12 ltr re violations noted in IE Insp. Repts 50-438/82-22 t 50-439/82-22 Revises B20709 ltr re date full compliance expected. Compliance will be achieved by B21220 MILLS.L.M. Tennessee Valley Authority B2/09/24 0'REILLY, J.P. Region 2. Office of Director 2pp 15776 207. 24X Fichs 50-438, B2/10/15, 8210220237

- S Reportable occurrences. LERs & related correspondence
- 8210010011 Third Interim Deficiency Repts 50-438/81-77 & 50-439/81-76 re allowable stresses for pipe support design Initially reported on 811207 Deficiency details being evaluated Next rept by 821217 MILLS.L M Tennessee Valley Authority 82/09/20 G'REILLY. J P Region 2. Office of Director 2pp 15565 148 24% Fiche 50-438,82/09/20,8210010011
- 8210080222 Second Interim deficiency rept re 1844 design of RCS supports b restraints Instially reported on 820618 Wolds b shear bars at interface points potentially undersized Investigation continuing Next rept expected by 821220 MILLS-L M Tennessee Valley Authority 82/07/24 0'REILLY-J P Region 2, Office of Director 2pp 15638 081 24X Fiche 50-438.82/09/24,8210080222
- 8210080247 Third & final deficiency repts re resolution of unanticipated vibratory loading concerns Initially reported on 811228 Program developed to insure piping say operate outher design parameters Next rept provided by 8212(7 MILLE: L N Tennessee Valley Authority 82/09/24 0'REILLY, J P Region 2. Office of Director 3pp 15638 104 24x Fiche 50-000,82/09/24,8210080247
- 8210080272 Seventh interim deficiency rept to imprecise specs in utili procurement document resulting in improper 4eismic qualification of 85M equipment in local instrument panels instially reported on 801125 Util awaiting 85M input MILLS.L.M. Tennesse Valley Authority 82/09/24 0'REILLY.J.P. Region 2, 0ffice of Director 2,0p 15638 306 24% Fiche 50-438,82/09/24,821080292
- 8210050115 Fifth interin deficiency mept re failure of bolts & nots to met ASTM requirements Initially reported on 810724
  Engineering interpretation/recommendation awaited Also reported per Part 21 Next rept expected by 830110
  MILLS,L M Tennesses Valley Authority 82/09/27 O'REILLY, J P Region 2, Office of Director 2pp 15601 349 24X
  Fiche 50-438,62/09/27,8210050115
- 8210050119 Supplemental deficiency rept re Lambda power module failures Initially reported on 801218 Addl discrepancies identified w/power supplies Corrective action will be completed by 830301 Also reported per Part 21 MILLS.L M Tennessee Valley Authority 82,09727 D'REILLY, J P Region 2. Office of Director ip 15601 351 24X Fiche 50-438,82/09/27,8210050119
- 8210050094 Fourth interim deficiency rept re-seismically unqualified auxiliary bldg fuel handling ione ventilation fans Initially reported on 810506 Contract awarded to provide qualified coils in fans Next rept by 630222
  MILLS.L M Tennessee Valley Authority 82/09/28 D'REILLY, J P Region 2. Office of Director 2ps 15604 234 24X
  Fiche 50-438.82/09/28.8210050094
- 8210050249 Final deficiency rept re use of insoluble glue for purge dams in stainless steel piping Initially reported on 820322 Glue residue left in piping sys will not cause safety problems Glue will dissolve MILLS, L.M. Tennessee Valley Authority 82/09/28 0'REILLY, J.P. Region 2, Office of Director 5pp 15609 076 24X Fiche 50-438,82/09/28,8210050249

---

## DUCKETED HEIVIO

- E210080140 First interim deficiency rept re corrosion in high pressure five protection say Initially reported on 820903 Corrosion analysis in progress to determine potential deficiencies in safety-related areas Next rept espected by 830531 MILLSIL M Tennessee Valley Authority 82/10/04 D/REILLY J P Pegion 2. Office of Director 2pp 15540 142 24X Fiche 50-000, 82/10/04, 8210080160
- 8210080278 Fourth interim deficiency rept to Viking flow control valves in fire protection sys Initially reported on 811124 Engineering Change Notice 1504 initiated implementing arfected drawing revisions Also reportable per Part 21 MILLS.L. M. Tennessee Valley Authority 82/10/04 0'REILLY.J.P. Region 2. Office of Director 2pp 15638 296 24X Fiche 50-438.02/10/04.8210080278
- 82(0130407 Fourth interim dericiency rept nonconservative FRAR analysis for loss of normal feedwater event initially reported on 810316 ASME code limits will be exceeded following loss of feedwater Also reported per Part 21 MILLSIL M. Tennessee Valley Authority 82/10/05 0'REILLY J.P. Region 2. Office of Director 2pp. 15681-008-24X Fiche 50-438,82/10/05.8210130407
- 9210220071 Final deficiency rept re attachment of pipe supports to whinch strip plates initially reported on 811231 Field mods for unacceptable supports scheduled for completion by 831001 MILLS.L M. Tennesser Valley Authority 82/10/07 O'REILLY.J.P. Region 2, Office of Director 2pp 15778 189 24X Fiche 50-438.82/10/07.8210220071
- 8210220350 First interim deficiency rept re diesel generator bldg cable tray support welds made as fillel welds instead of grove welds. Initially reported on 820508 Supports being reworked Process spec revised Mext rept to be submitted by 830124 MILLS.L. M. Tennessee Valley Authority 82/10/08 0'REILLY.J.P. Region 2. Office of Director 20p 15776 273 24X Fiche 50-438 82/10/08.8210220350
- 9210290328 Second interim deficiency rept re use of monconservative calculational method to evaluate Oeneral Const Spec G-32 spacing violations Initially reported on 820528 Next rept will be sent by 830528 MILLS.L M Tennessee Valley Authority 82/10/12 O'REILLY, J P Region 2. Office of Director 2pp 15853 064 24X Fiche 50-000.82/10/12.8210290328
- S. 10290059 Sixth interim deficiency rept re piping potential safety concern Initially reported on 801121 B&W analyses completed sicept for in-core piping Next rept by 830523 Also reported per Part 21 MILLS.L M Tennessee Valley Authority 82/10/14 O'REILLY, J P Region 2. Office of Director 2pp 15854 024 24X Fiche 50-438.82/t0/14.8210290059
- 8210290236 Third interin deficiency rept re-potentially overstressed embedded plates initially reported on 820412 investigation continuing & const activities deferred until sufficient infogathered to determine completion of project MILLS.L.M. Tennessee Valley Authority 82/10/14 O'REILLY, J.P. Region 2. Office of Director 2pp 15853 229 24X Fiche 50-000.82/10/14.8210290236
- 8210290324 Third interio deficiency rept re Bresser safety valve. Model 31709NA, suffering unacceptable internal damage during steam test initially reported on 810709 EPRI & 084M repts evaluated Also reportable per Part 21 MILLS, & M. Tennessee Valley Authority 82/10/14 O'REILLY, J.P. Region 2. Office of Director 2pp 15853 101 24X Fiche 50-438, 82/10/14, 8210290324
- 8210250320 First interim deficiency rept re addition of locking devices to handwheel operated values initially reported on 820916 Const activities deferred Analyses of locking devices continuing Next rept will be sent by 820910 MILLS.L M Tennessee Valley Authority 82/10/18 O'REILLY, J.P. Region 2. Office of Director 2pp 15802 359 24X Fiche 50-000.82/10/18.8210260320
- 8210250322 First interim deficiency rept re generic deficiencies in solid state control sys & basic control room switch modules supplied by Consolidated Controls Corp Initially reported on 820716 Next rept by 830519 Also reported per Part 21 MILLS.L M Tennessee Valley Authority 82/10/18 O'REILLY.J P Region 2. Office of Director 2pp 15799 342 24X Fiche 50-438.82/10/18.8210260322
- 8210260251 Final deficiency rept rework releases allowing const to cut reinforcing steel to install anchor builts for pipe supports. Initially reported on 820727 Personnel instructed to review design drawings more carefully.

  MILLS.L. M. Tennessee Valley Authority. 82/10/19. 0/REILLY, J.P. Region 2. Office of Director. 2pp. 15799-350. 24X. Fiche 50-438.82/10/19.8210260251

- 8210260105 Third interim deficiency rept re governor lube all color initially reported on 820308 Supplier has provided drawing by procedure to relocate cooler below governor Vendor working to identify cause Also reportable per Part 2! MILLS.L.M. Tennessee Valley Authority. 82/10/20. 0'REILLY.J.P. Region 2. Office of Director. 2pp. 15797-120. 24X Fiche 50~438,82/10/20.8210260105
- 6210290274 Final rept for Deficiencies B & E & seventh interim rept for Deficiencies A & D re control of procurement activities Initially reported on 81001A Final corrective actions noted Nert rept expected by 830428 MILLS, L M Tennessee Valley Authority 62/10/21 D'REJLLY, J P Region 2, Dffice of Director 4pp 15853 143 24X Fichs 50-000, 82/10/21, 8210270274
- 82)029024B Revised final deficiency ropt re structural tubing eleting AMS allowables Initially reported on BiOBIS Design drawings which dictate configuration of 86 cable tray supports altered to ensure seismic qualification MILLS.L K Tennessee Valley Authority 82/10/22 O'REILLY, J P. Region 2. Defice of Director 3pp 15853 122 24X Fiche 50-438, 82/10/22, 82:029024B
- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

  A Application/construction stage documents & correspondence
- 8210130010 Requests submittal of add1 fee for 820721 application for extension of const completion dates BIGGS.R License Fee Management Branch 82/09/27 DAVIDSDR.D R Cleveland Electric Illuminating Co 1p 15492 332 24X Fiche 50~440.82/09/27,8210130010
- 8210130177 Advises that response to NRC 820904 ltr re degraded cere hydrogen control will be provided by 821201 DAVIDSON.D R Cleveland Electric Illuminating Co. 82/07/27 SCHWENGER,A Licensing Branch 2 ip 19473 019 24X Fiche 90-440,82/09/29,8210130179
- 6210170326 Forwards slide presentation from 820813 meeting re-safety relief hydrodynamic loads Position similar to criteria outlined in NURGE-0763 Encls withheld (ref 10CFR2 790) DAVIDSON.D R Cleveland Electric Illuminating Co 82/10/08 SCHNENCER,A Licensing Dranch 2 2pp 15742 059 24X Fiche 50-440, 82/10/08.2210170326
- 8210260419 Forwards NEDF-22203, "Reactor Internals Vibration Predictions," dtd Aug 1982 Rept contains proprietary infore internals vibration program & peak amplitude predictions per engineering analysis Rept withheld (ref 10CFR2 790) DAVIDBON, D.R. Cleveland Electric Illuminating Co. 82/10/08 SCHMENCER, A. Licensing Branch 2 ip 15806-114 24X Fiche 50-440,82/10/08.8210260419
- 6210190619 Confirms 621006 telcon re preoperational testing program
  Util not required to continue sending preliminary
  preoperational test procedures Current status of procedures
  & implementation will be forwarded monthly
  LITLE.W 8 Division of Engineering & Technical Programs 87/10/15
  H[CKS],0 R Cleveland Electric Illuminating Co ip 15737 223
  24% Fiche 50-440.82/10/15,8210190619
- 8210210079 Forwards proprietary util 821008 ) to & attachments resistive relief valve hydrosymamic loads, inadvertently omitted from original submittal Nonproprietary info to be provided by 821105

  DAVIDBON D R Cleveland Electric Illuminating Co 82/10/15

  SCHHENCER: A Licensing Branch 2 ip 15762 235 24X

  Fiche 50-440, 82/10/15;8210210079
- 8210270073 Notification of 821107 meeting w/util,C-E & GAI in Bilbell MD to discuss pool dynamic load criteria application to plant apecific design STEFANO. J Licensing Branch 2 82/10/19 SCHWENCER. A Licensing Branch 2 3pp 15836 276 24X Fiche 50-440.82/10/19.8210278073
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8210260235 Comments on FES for facility Applicant aware of effluent limits No addl adverse environ impacts within EPA field of expertise anticipated BACKLEY.B T Environmental Protection Agency 82/10/19 SCHHENGER.A Licensing Branch 2. 1p 15799 354 24X Fiche 50-440.82/10/19.8210260235,

MRC Safety Evaluation Report (SER), supply & correspondence

2:0150233 Forwards response to SER Confirmmatory lssue 16 re beltline weld matts Info revises response to Questions 123 1,123 2 & 123 3 & should resolve issue of matl surveillance capsules DAYIDSON, D R Cleveland Electric Illuminating Co 82/09/22 SCHKENCER.A Licensing Branch 2 42pp 15706 010 24X Fiche 50-440,82/09/22.82(0150233

- 210130173 Advises that responses to MRC 820908 ltr re SCR Outstanding Issue 21 concerning reanalysis of transients & accidents & development of emergency operating procedures will be provided by 821027
  DAVIDSON, D. R. Cleveland Electric Illuminating Go. 82/09/28
  SCHMENCER, A. Licensing Branch 2 p. 15473-044 24X
  Fiche 50-440, 82/09/28, 8210130173
- 210190333 Responds to SER Confirmatory Items 32 & 45 re accident monitoring instrumentation & location of plant area radiation monitoring instrumentation Items also address TMI Items II F 1 3. II F 1 4. II F 1 5 & II F 1 6 DAVIDSON, D R Cleveland Electric Illuminating Co 82/10/14 SCHLENCER, A Licensing Branch 2 3pp 15742 120 24X Fiche 50-440. 82/10/14.8210190333
- 210170683 Forwards response to SER Confirmatory Issues 28,30 & 33 re instrumentation & control Three oversize drawings encl Aperture cardé are available in PDR DAVIDSON, D.R. Cleveland Electric Illuminating Co. 82/10/14 SCHMENCER.A. Licensing Branch 2 &pp. 15751 013 24x Fiche 50-440, 82/10/14.8210170683

Security, medical, emergency & fire protection plans

'07180055 FOIA request for all documents since 1979 re drug or alcohol abuse by persons at facilities
SANICKI,S G News-Herald Willoughby, OH 82/08/30 FELTON, J M Division of Rules and Records 1p 1975B 359 24X
Fiche 50-440, 62/08/30, 8207180055

- 10190199 Responds to FOIA request for all documents since 1979 redrug or alcohol abuse by persons at facilities Forwards documents identified during 820913 telcon FELTON. J M Division of Rules and Records, 82/09/15 SAHICKI. S G Rews-Herald Willoughby, OH 1p 15758 260 24X Fiche 50-440. 82/09/15. 8210190199
- 8210170204 Provides info re drug & alcohol abuse, fire support deficiencies, theft & forced entry observed at facilities
  Author name deleted
  \* Affiliation Unknown 82/09/15 NRC No Detailed Affiliation Given 2pp 15758 361 24X Fiche 50-440.82/09/15.8210170179
- 8210190209 Ack receipt of 1tr expressing concerns re security administration at facility NRC does not impose security requirements on licensee prior to onsite receipt of reactor fuel Contacting util suggested Info partially deleted PHILLIP, G A Region 3. Chicago. Office of the Director (81/03/01) 81/07/16 Affiliation Unknown ip 19758 363 24% Fiche 50-440,88/09/15,8210190199
- i0(9001) Notification of 821006 meeting w/util in Bethesda MD to discuss responses to NRC questions re emergency plan & status of plan finalization STEFAND. J Licensing Branch 2 82/09/23 SCHWENCER, A Licensin Branch 2 Jpp 15760 318 24X Fiche 50-440,82/09/23,8210190011
- 10260572 Releases public version of revised emergency plan FELTON.J M Division of Rules and Records 82/10/08 Document Management Branch 1p 15832 026 24X Fiche 50-440,82/10/08. 8210260572
- B210260575 Forwards public version of Revision O to emergency plan DAVIDBON, D. R. Commonwealth Edison Co. B2/09/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15832 027 24X Ficha 50-440, 82/10/08, B210260572
- 3210240579 Public version of Revision O to emergency plan + Commonwealth Eduson Co 82/07/22 29/pp 15832 029 24x Fiche 30-440,82/10/08.8210240572

## Adjudicatory correspondence

10970075 Forwards responses to interrogatories from SUnflower Alliance requiring FEMA reply KRIMM.R W Faderal Emergency Management Agency 82/09/09 RRIMES.B K Division of Emergency Preparedness 35pp 15428 127 24X Fichs 50-440.82/09/09.8210070075

- 8210010335 Reply to applicant 820721 motion to amend ASLB 820716 memorandum & order re scheduling Moving filing date of testimony will prejudice intervenors Applicant suggestion to delay hearing until 830222 should be granted HIATT.5 L. Ohio Citizens for Responsible Energy 82/07/27 Atomic Safety and Licensing Board Panel 1p 15569 163 24X Fiche 50-440, 82/07/27, 8210010335
- 8210010366 Seventh set of interrogatories Certificate of Svc enci Related correspondence HIATT, & L. Dhio Citizens for Responsible Energy 82/09/27 Office of the Executive Legal Director 8pp 15573 095 24X Fiche 50-440,82/09/27,8210010366
- 92100103/7 Reply opposing applicant 920913 motion to rescind ABLD B10804 procedural order requiring interveners to respond to NRC & applicant answers to late filed contentions Certificate of Svc encl HIATT,6 L Ohio Citizens for Responsible Energy 82/09/27 Atomic Safety and Licensing Board Panel 5pp 15573 054 24X Fiche 50-440,82/09/27,8210010377
- 8210010386 Requests article from Nuclear News noted in ASLB 820916 memorandum & order be provided to all parties since magazine unavailable in public & univ libraries HIATT'S L. Ohio Citizens for Responsible Energy 82/09/27 BLOCH, P. B. KLINE, J. R. SHON, F. J. Atomic Safety and Licensing Board Panel 1p 15569 212 24X Fiche 50-440,82/09/27,8210010386
- 8210010416 Sixth set of interrogaturies Certificate of Svc encl Related correspondence
  HIATT'S L. Dhio Citizens for Responsible Energy 82/09/27
  Cleveland Electric filtuminating Co tOpp 15572 193 24X
  Fiche 50-440.82/09/27.8210010416
- 8210010250 Response apposing applicant motion to revise procedures for late filed contentions No prejudice demonstrated Proof of Svc encl WILT.D D Sunflower Alliance HILT.D D Hilt, D D 82/09/28 Atomic Safety and Licensing Board Panel 2pp 15568 262 24X Fiche 50~440,02/09/28,8210010250
- 8210010323 Motion for 5-day extension to file motion to compel discovery against NRC Addl time necessary due to other business & personal illness Proof of Svc encl WILT-D D Sunflower Alliance WILT-D D Wilt, D D 82/09/20 Atomic Safety and Licensing Board Panel Ip 15569 192 24X Fiche 50-440 82/09/28 82/0010323
- 8210010345 Answer to fourth set of interrogatories Certificate of Svc encl MILLMORE,R L. Cleveland Electric [lluminating Co. MILLMORE,R L. Shaw, Pittman, Potts & Troubridge 82/09/28 Ohio Citizens for Responsible Energy 17pp 15574 001 24% Fiche 50-440,82/09/28, 8210010345
- 6210010457 Forwards RF Zucker & RA Pender original affidavits to be substituted for photocopies in applicant 820728 answer to OH Citizens for Responsible Energy fourth set of interrogatories Related correspondence HILLMORE.R L Shaw, Pittman, Potts & Trowbridge WILLMORE.R L Cleveland Electric Illuminating Co 82/07/29 Docketing & Services Branch 3pp 15572 311 24X Fiche 50-440,82/07/29,8210010457
- 8210040019 Notice of withdrawal of appearance in proceeding LEWIS, S. H. Hearing Dranch 2 82/09/29 3pp 15581 262 24X Fiche 50-440.82/09/29,8210040019
- B210040019 Certifies svc of NRC response to Sunflower Alliance motion seeying admission of late contention on shift rotation & GE Johnson notice of appearance on B20930 JOHNSON, 0 E Hearing Branch 4 82/09/30 2pp 15581 348 24X Fiche 50-440, 82/09/30, 8210040015
- 8210040017 Response apposing Sunflower Alliance 820910 motion seeking admission of late contention on shift rotation Contention beyond Commission regulatory requirements, lacks basis & nexus & is unitmely JOHNSON, 9 E. Hearing Branch 4 82/09/30 Atomic Safety and Licensing Board Panel Bpp 15581 297 24X Fiche 50-440.82/09/30, 8210040017
- 8210040023 Notice of appearance in proceeding JOHN50N, G E Hearing Branch 4 82/09/30 ip 15581 256 24X Fichs. 50~440, 82/09/30, 8210040023
- 8210050173 Third set of interrogatories re Issue 3 & requests for production of documents Proof of Svc encl Related correspondence WILT.D D Sunflower Alliance WILT.D D Wilt, D D 82/09/30 NRC No Detailed Affiliation Oliven 7pp 15604 138 24X Fiche 50-440.82/09/30,8210050173

- 8210050228 Fourth request for production of documents re Contention L. envoyment roughest for production of documents re Con-issue 1 on emergency evacuation planning Proof of Svc enci Related correspondence WILTO D Sunflower Alliance WILTOD Wilt, DD 82/ Office of the Esecutive Birector for Operations 2pp 15 24/ Fiche 50-440,82/09/30,8210050228 WILT. D.D. Wilt. D.D. 02/07/30
  - 15610 351
- 8210050242 Requests extension of discovery time on Contention 1 lesses not ready for hearing as final emergency plans not yet in place Plans must be reviewed prior to hearing Proof of Svc WILT.D D Sunflower Alliance WILT.D D Wilt, D D 82/09/30 Atomic Safety and Licensing Board Panel 2pp 15610 334 24X Fichy 50-440, 82/09/30, 8210050242
- 5210050252 Third set of interrogatories w/requests for production of JOUGNEY INITE set of interrogatories w/requests for productivily occuments re Issue 3 on adequacy of applicant OA program Proof of Svc encl Related correspondence WILT.D D Sufflower Alliance WILT.D D Wilt, D D 82/09/30 Cleveland Electric Illuminating Co 12pp 15610 294 24X Fiche 50~440, 82/09/30, 8210050252
- 82(0050255 Third set of interrogatories & request for production of documents re Issues 1,3 & 11 on offsite emergency evacuation plans OA & local economic benefits, respectively Certificate of Svc encl HILLPORE R L Cleveland Electric Illuminating Co WillMore, R L Shaw, Pittman, Potts & Trowbridge 82/09/30 Sunflower Alliance 12pp 15609 199 24x Fiche 50-440-82/09/30-8210050255
- 62(005)374 Response in opposition to Sunflower Alliance. Inc 820910 motion to compel applicant answer to second set of interrogatories Applicants will respond shortly Certificate of Sic encl SILBERO, J.E. Cleveland Electric Illuminating Co. SILBERO, J.E. Shaw, Pittman, Potts & Troubridge 82/09/30 Atomic Safety and Licensing Board Panel 20pp 15608 256 24X Fiche 50-440, 82/09/30, 8210050374
- 8210050207 Seventh set of interrogatories directed to applicant & eighth set of interrogatories directed to MRC pursuant to ASLB 810728 Memorandum & Order LBP-81-24 Certificate of Svc enci Related correspondence ent Artabas Correspondence HIATT, S.L. Ohio Citizens for Responsible Energy 82/09/30 Cleveland Electric Illuminating Co. 5pp 15614 157 24X Fiche 50-440, 82/09/30, 8210060207 82/09/30
- 83100500A9 Response supporting applicant 820913 mation to revise ALUCOUMAY RESponse supporting applicant B20913 motion to revise procedures for late filed contentions Allowing intervenors to raise new matter in reply constitutes amend to contentions Certificate of SVC encl
  CUTCHIN.J M. Hearing Dranch 4. 82/10/04. Atomic Safety and Licensing Board Panel. Bpp. 15603 (88. 24): Fiche 50-440, 82/10/04, 82(0050069
- 9210150192 Requests clarification of docket numbers for Harris & Petry plants Mizup may be causing prejudice to intervenors since documents go to incorrect LPDR HIAIT.S L Ohio Citizens for Responsible Energy 82/10/04 Docketing & Services Branch ip 15707 240 24X Fiche 50-000.82/10/04,8210150192
- 8210040303 Response apposing CM Citizens for Responsible Energy 820920 motion to compel discovery of NRC 5 Util ASLB chairman comments did not allow intervenors to breaden contention or CUTCHIN. J H Rearing Branch 4 82/10/05 Atomic Safety and Licensing Board Panel 6pp 15617 017 24X Fiche 50-440, 82/10/05, 8210060303 scope of discovery

- 8210150161 Confirms 821005 telcon re time for filing util response to 210150161 Confirms \$21005 teleon re time for filing util respond Citizens for Responsible Energy motion to compel answers to Sunflower second set of interrogatories Answer to be filed by \$21012 Svc list encl Related correspondence SILBERG. J E Shaw. Pittman. Potts & Troubridge SILBERG. J Cleveland Electric Illuminating Co \$2710706 HIATT. S Of Citizens for Responsible Energy 2pp 15697 067 24% Fiche 50-440, 82/10704, 8210150161
- 8210120337 Memorandum & order denying Sunflower Alliance Inc 820930 request for extension of time for discovery on Issue i Info has been made available BLOCHP B Atomic Safety and Licensing Board Panel 82/10/08 Sunflower Alliance ip 13652 183 24X Fiche 50-440,82/10/08, 2010,0037 8210120337
- 6210130327 Hemorandum & order denging OH Citizens for Responsible Energy 820907 motion to sever proceedings No reason provided for ASLB to reconsider 810909 ruling on identical motion by Synflower Alliance BLOCH, P B Atomic Safety and Licensing Board Panel 82/10/00 Ohio Citizens for Responsible Energy ip 15478 283 24X Fiche 50-440, 82/10/08, 8210130329
- 8210130333 Memorandum & order admitting Contention 12 re inadequate consideration of economic consequences of accidents Preponderance of considerations favors admission of contention KLINE, J.R., SHON, F.J. Atomic Bafety and Licensing Board Panel B2/10/08 Ohio Citizens for Responsible Energy 5pp 15682 059 24X Fiche 50-440.82/10/08.8210130333
- 8210150228 Confirms conversations w/OH Citizens for Responsible Energy 210150228 Confirms conversations W/DH Citizens for Responsible Energy

  \*\*X\*\* Judge\*\* Black The extension of time for util to respond to
  OH Citizens for Responsible Energy B20920 motion to compel
  discovery on NRC & util Response due 821018 M/svc list
  SILBERO.J E Shaw, Pittman, Potts & Trowbridge SILBERG.J E
  Cleveland Electric Jiluminating Co 82/10/08 BLOCH.PB ,
  KLINE.J R , SHON.F J Atomic 84fety and Licensing Board Panel 49;
  15706 COB 24% Fiche 50-440.82/10/08.8210150228
- 8210150467 Answer to sixth set of interrogatories Certificate of Bu WILLMORE.R L. Gleveland Electric Illuminating Co. WillMore.R L. Shaw. Pittman, Potts & Trowbridge 82/10/12 Ohio Citizens for Responsible Energy 10pp 15703 050 24X Fiche 50-440,82/10/12
- 8210180211 Reply apposing NRC & applicant responses to OH Citizens for Responsible Energy mation for leave to file Contentions 21-26 Good cause, specificity & basis requirements met 21-20 Good coser specificate of Sev encl
  HiATT.8 L Ohio Citizens for Responsible Energy 82/10/12
  Atomic Safety and Licensing Board Panel 14pp 15718 110 24X
  Fiche 50-440 82/10/12,8210180211
- 8210150175 Advises that documents requested by Sunflower Alliance fourth request directed to Executive Director for Operations available in PDR CUTCHIN, J M Hearing Branch 4 82/10/13 WILT, D D Wilt, D D WILT, D D Sunflower Alliance ip 15707 189 24X Fiche 50-440, 82/10/13, 8210150175
- 8210150275 Advises that NRC will not voluntarily respond to any discovery advises that ARC will not voluntarily respond to any discovery requests in Sunflower Alliance third set of interregatories & requests for documents, except Request 19 Remainder of discovery broader than Issue 3 CUTCHIN.J M Hearing Branch 4 82/10/13 HILT.D D Wilt, DO WILT, DD Sunflower Alliance 3pp 15705.001 24X Fiche 50-440, 82/10/13, 8210150275
- 8210180155 Advises of correction to util response to Interrogatory 68 of OH Citiens for Responsible Energy sixth set of interrogatories Conclusion of response remains unchanged Interrogatories Conclusion of response remains distinguished Related correspondence
  WILLMORE, R.L. Bhaw, Pittman, Potts & Trombridge WILLMO
  Cleveland Electric Illuminating Co. 92/10/14 HIATT.8
  Citizens for Responsible Energy ip 15719 269 24X
  Fiche 50-440. 82/10/14, 8210180155
- 8210190377 Answers to 820907 fifth set of interrogatories Prof qualifications & Centificate of Byt encl
  JOHNSON O E Operations & Administrative Division 82/10/15
  Ohio Cititens for Responsible Energy 15pp 19740 300 24%
  Fichs 50-440-82/10/15,8210190377
- 8210190475 Answer opposing Sunflower Alliance 820928 motion to extentime to file motion to compel discovery against NRC No basis for unlimited request provided Certificate of Svc encl CUTCHIN-J M Hearing Branch 4 82/10/15 Atomic Safety and Licensing Board Panel, 4pp 15740 241 24x Fiche 50-440-82/10/15 0010190475

- 8210210351 Objects to issuance of ASLB 821008 memorandum & order receivest to extend discovery on Issue 1 Order issued ASLB should request responses from all parties on expedited schedule W/Certificate of Svc Related correspondence HIATT.S L. Ohio Cititens for Responsible Energy 82/10/15 BLOCH.P B . KLINE, J R . SHON, F J. Atomic Safety and Licensing Bourd Panel ip 15764 010 24X Fiche 50-440, 82/10/15, 8210210351
- --821021035B Seventh discovery progress rept.pursuant to ASLB 810709 memorandum & order.LBP-81-35 Interrogatories submitted to applicant & NRC re Issues 4.5.6.7.8 & 7 Discovery re Issue 9 forthcoming HIATT.S L Dhio Citizens for Responsible Energy 82/10/15 2pp 15764 011 24X Fiche 50-440, 82/10/15.8210210351
- --0210210365 Motion to extend discovery on Issue 9 to 821101 to permit review of documents referenced in applicant responses to 820830 interrygatories & followup discovery Certificate of 8vc encl Related correspondence
  HIATT.5 L. Onio Citizens for Responsible Energy 82/10/15
  Atomic Safety and Licensing Board Panel 3pp 15764 013 24X
  Fiche 50-440,82/10/15,8210210351
- 8210210284 Answer opposing DH Citizens for Responsible Energy 820920 motion to compel discovery on NRC & util Interrogatories not relevant to & beyond scope of Issue & Certificate of Svc encl Related correspondence
  STLBERG. J E Gleveland Electric filuminating Co GILBERG. J E Shaw, Pittman, Potts & Trombridge 82/10/18 Atomic Safety and Licensing Board Panel 3App 15765 099 24X Fiche 50-440,82/10/18, 6210210264
- 3210210339 Amended answer to Interrogatory 13 of Sunflawer Alliance second set of interrogatories Certificate of Svc encl Related correspondence SILBERO, J E Cleveland Electric Illuminating Co SILBERO, J E Shaw, Pittman, Potts & Troubridge 82/10/18 Sunflawer Alliance Spp 15763 177 24X Fiche 50-440.82/10/18.8210210353
- 3210220481 Requests attachment to NRC 780203 Itr to GE be provided to allow progress on Issue 4 Document needed before intervenor can decide if updates to interrogatories necessary Related correspondence HiATTLE C Ohio Citizens for Responsible Energy 82/10/18 BILBERG, J Shaw, Pittman, Potts & Troubridge 611.0ERG, J Clevelant Electric Illuminating Co ip 15779 078 24X Fiche 50-440, 82/10/16.8210220481
- 3210210476 Memorandum & order denying Sunflower Alliance 820910 motion to compel applicant to answer second set of interrogatories If util agrees to stipulation on obtassium indide subcontention. Interrogatory 56 need not be answered BLOCH.P B . KLINE.J R . SHON.F J Atomic 8afety and Licensing Board Panel 82/10/17 Cleveland Electric Illuminating Co 6pp 15762 265 24X Fiche 50-440.82/10/19.8210210476
- 1210220305 Answer to 820930 seventh set of interrogatories Certificate of Syc enc!
  WILLMORE, R.L. Cleveland Electric Illuminating Co. WILLMORE, R.L. Shaw, Pittman, Potts & Trombridge 82/10/19 Ohio Citizens for Responsible Energy 13pp 13776-053 24X Fiche 50-440,82/10/19,8210220305
- 0210220309 Seventh discovery progress rept Certificate of Svc encl HILLMORE:R L Cleveland Electric Illuminating Co WILLMORE;R L Shaw, Pittman, Potts & Troubridge 82/10/19 4pp 15776 049 24 Fiche 50-440:82/10/19.8210220309
- |210220396 Hotion for leave to file answer to OH Citizens for Responsible Energy (OCRE) 821012 reply to util & NRC answers to OCRE motion for leave to file Contentions 21-24 WILLMORE,R L Cleveland Electric Illuminating Co WILLMORE,R L Shaw. Pittman, Potts & Trowbridge 82/10/19 Atomic Safety and Licensing Board Panel 2pp 15777 312 24X Fiche 50-440,82/10/19,8210220396
- "B210220405 Answer to OH Citizens for Responsible Energy 821012 reply to NRC & applicant response to Citizens motion to file Contentions 21 through 26 Citizens did not meet burden of proof for admission of new contentions W/Certificate of Svc WILLHORE, R L. Cleveland Electric Illuminating Co WILLHORE, R L. Shaw, Pittman, Potts & Trowbridge 82/10/19 Atomic Bafety and Licensing Board Penel 15pp 15777 314 24X Fichs 50-440, 82/10/19, 8210220396
- 1210250331 Reply brief supporting motion to submit addition ton Good cause for late filing demonstrated Applicant shift rotation plans may not be incorporating circadian principles WILT.D.D. Bunflower Alliance. WILT.D.D. Wilt, D.D. 82/10/19 Atomic Safety and Licensing Board Panel 3pp 15770.325 24X Fiche, 50-440, 82/10/19, 8210250331

- 8210250299 Answer to OH Citizens for Responsible Energy 821015 motion to extend discovery on Issue 9 repolymer degradation No justification exists for extending discovery cutoff date Certificate of Svc encl SILBEROJJE Cleveland Electric Illuminating Co SILBERO, J E Shaw, Pittmen, Potts & Trowbridge 82/10/20 Atomic Safety and Licensing Board Panel Spp 15790 195 24X Fiche 50-440, 82/10/20, 82(0250299
- 8210250322 Supplemental answers to Sunflower Alliance. Inc second set of interrogatories Certificate of Svc encl
  SILBERO. J E Cleveland Electric Illuminating Co SILBERG. J E. Shaw. Pittman. Potts 2. Trowbridge 82/10/20 Sunflower Alliance 17pp 15790 226 24X Fiche 50-440.82/10/20.8210250322
- 8210250365 Advises that NRC will not voluntarily respond to CH Catarantor Responsible Energy seventh set of anterrogatories except for interrogatories listed Requests irrelevant & will not lead to discovery of admissible evidence CUTCHIN.JM Hearing Branch 4 82/10/22 HIATT. 5 L Ohio Citizenfor Responsible Energy 2pp 15790 175 24X Fiche 50-440.82/10/2/, 8210250365
- B210260033 Answers to B20830 fourth set of documents Certificate of Sve encl MRIOHT,N A Hearing Branch 2 82/10/22 Ohio Citizens for Responsible Energy 12pp 15799 124 24X Fiche 50-440,82/10/소간. B210280033
- 821028021A Responds to 821018 ltr resvo of documents to parties Telcons could expedite matters in future Svo list encl Related correspondence SILBERG, J.E. Shaw, Pittman, Potts & Trombridge 82/10/22 HIATT, B.L. Ohio Citizens for Responsible Energy 9pp 15837 356 24X Fiche 30-440,82/10/22,8210280216
- 8210280231 Update to response to Interrogatory 4-2 of CH Citizens for Responsible Energy 820928 fourth set of interrogatories Related Correspondence MILLMORE, R L. Shau, Pittman, Potts & Trowbridge WILLMORE, R L. Cleveland Electric Illuminating Co. 82/10/22 HIATT, S. Chiecotters for Responsible Energy 1p. 15837-081 24X Fiche 30-440, 82/10/22, 8210280231
- 8210260383 Answers to listed interrogatories of 820927 seventh set of interrogatories NRC will not voluntarily answer remaining interrogatories Certificate of Svc encl
  CUICHIN.J H Hearing Branch 4 82/10/25 Ohio Citizens for Responsible Energy Tipp 15803 348 24X Fiche 50-440, 82/10/25, 8210260383
- 8210260395 Discovery rept for previous two months per ASLB 810909 memorandum & order CUTCHIN, J M Hearing Brench 4 62/10/25 BLOCK, P D , SHON, F J , KLINE, J R Atomic Safety and Licensing Board Panel 1p 15803 34, 24X Fiche 50-440, 82/10/25, 8210260395
- 8210280246 Forwards RB Coffey original affidavit to be included in applicant 821020 supplemental answers to Sunflower Alliance second set of interrogatories Related correspondence HILLMORE.R L. Shaw. Pittman. Potts & Troubridge WILLMORE.R L. Cleveland Electric Illuminating Co. 82/10/25 Docketing & Services Branch 2pp 15837-094 24X Fiche 50-440.82/10/25. 8210280246
- 8210290287 Requests encl RF Zucker & RV Tanney original affidavits he substituted for photocopies in applicant 821019 answers to OH Citizens for Responsible Energy seventh set of interrogatories WILLMORE, R. L. Shaw, Pittman, Potts & Trowbridge WILLMORE, R. L. Cieveland Electric Illuminating Co 82/10/26 Docketing & 8ervices Branch 3pp 15894 069 24X Fiche 50-440.82/10/26.8210290287.
- 8210280346 Answer apposing OH Citizens for Responsible Energy 821015 motion to extend time for discovery on Issue 9 No Justification for extension provided Certificate of 8vc encl CUTCHIN, J H Hearing Branch 4 82/10/27 Atomic Safety and Licensing Board Panel, 5pp 19838 301 24X Fiche 50-440,82/10/27, 8210280346
- K Utility Final Bafety Analysis Report (FSAR) & amonds
- 8210040146 Forwards Amend 9 to FBAR Certificate of Svc encl. DAVIDSON D R Cleveland Electric Illuminating Co 82/09/20 DENTON H R Office of Nuclear Reactor Regulation, Director 3pp 15584-251 24X Fiche. 50-440, 82/09/20, 8210040146
- --8210040150 Amend 9 to FBAR 4 Cleveland Electric Illuminating Co 82/09/30 573pp 15894 254. 24% Fiche 50-440,82/09/30.8210040144

#### M Antitrust correspondence

- 6210120268 Confirms 821007 telcon & forwards NRC 820809 ltr to City of Cleveland, Div of Light & Power 820708 & 10 responses VOGLER.B H Hearing Branch 2 82/10/08 LANSDALE.J Squire, Sanders & Dempsey 1p 15652 318 24X Fiche 50-440.82/f0/08.82/10/0268
- u Inspection reports. IE Bulletins & correspondence
- B210060305 Forwards IE insp Repts 50-440/B2-11 & 50-441/82-10 on B20931-0902 No noncompliance noted LITTLE:US Division of Engineering & Technical Programs B2/09/22 DAVIDSON:0 R Cleveland Electric Illuminating Co 2pp 15619 195 24X Fiche 50-440 B2/09/22.8210060305
- --8210060308 IE [nsp Repts 50-440/82-11 & 50-441/82-10 on 820831-0902 Nu moncompliance noted Major areas inspected preservice insperocedures & work activities, previous insp findings & IE Bulletin 80-08 activities UARD, K D, DANZELSON, D M Region 3. Office of Director 82/09/14 566 15419 197 24% fiche 50-440.62/09/22.8210060305
- 8210190763 Forwards IE Investigation Repts 50-440/81-19 & 50-441/81-19 on 611027-820319 & notice of violation REPPLER, J O Region 3. Office of Director 82/09/27 DAVIDSON, D R Cleveland Electric Illuminating Co 3pp 15736 318 24% Fische 50-440, 82/09/27, 8210190763
- --8210190771 Notice of violation from investigation on 811027-820319 KEPPLER, J O Region 3. Office of Director 82/09/24 9pp 15736 321 24X Fiche 50-440,82/09/27,8210190763
- --8210190787 IE Investigation Repts 50-440/81-19 % 50-441/81-19 on 811027-820319 Noncompliance noted Gould. Int Drawings E-35-51-958 E231 & E231 inadequately reviewed & instructions not incorporated into cable pulling procedures well.c H NAIDU.K R , BRAWND.C D Region J. Diffice of Director 82/09/22 95pp 15736 330 24X Fiche 50-440.62/09/27,8310190/63
- 6208[90233] IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged 1-125 Implant Seeds." Soc list encl COBB.L J. Division of Fue) Facilities. Materials & Safeguards 82/19/06. Consolidated Edison Co. of New York. 66pp. 19761 250 24% Fiche 50-000 82/10/06.8208190233
- BBOB190238 IE Bulletin 82-03. "Stress Carrasion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BWR Plants "Svc list ent) DEYOUNGER C Director's Giffice, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fichs 50-000,82/10/14,8208190238
- G210260333 Ack recript of 821008 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/82-09 % 50-441/82-09 MARELIUS.C E Division of Project & Resident Programs 82/10/21 DAVIDSON, D R Cleveland Electric Illuminating Co ip 15803 191 24X Fithe 50-440/82/10/21/8210240333
- --9210260337 Responds to NRC 820910 ltr re violations noted in IE Insp Repts 50-440/82-09 & 50-441/82-08 Corrective actions Kaiser Engineer Procedure GAP-22 revised to require annual evaluation Detailed hardware insp performed 820728 DAVIDSON.D R Cleveland Electric Illuminating Co 82/10/08 NORELIUS.C E Division of Project & Resident Programs opp 15803 192 24X Fiche 50-440,82/10/21.8210260333
- S Reportable occurrences. LERs & related correspondence
- 8210050132 Final deficiency rept to nonconforming Transamerica Dalava) standby diesel generator ASPE Section III.Class 3.piping welds initially reported on 880329 Weld insp & required repair/rework will be completed by 830401 DAVID50N.D R Cleveland Electric Illuminating Co 82/09/24 KEPPLER.J C Region 3. Office of Director 2pp 15605-047 24X Fiche 50-440.82/09/24.8210050132
- 8210130364 Third interim deficiency rept re rejection of previously accepted containment vessel radiographs Initially reported on 820405 All potentially rejectable radiographs submitted to Martford Steam Boiler (nep Co for review BAVIDSUM, D R Cleveland Electric Illuminating Co 82/09/30 KEPPLER.J G Region 3. Office of Director 2pp 15681 149 24X Fiche 50-440.82/09/30.8210130364

- DUCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- B210130010 Requests submittal of add1 fee for B20721 application for extension of const completion dates. DIGOS:R License Fee Management Branch Cleveland Electric Illuminating Co ip 15692 332 24X Fichs 50-440. B2/09/27. B210130010
- B210130179 Advises that response to ARC B20906 ltr re degraded core hydrogen control will be provided by B21201 DAVIDSON, D.R. Cleveland Electric Illuminating Co. 82/09/29 SCHMENGER.A Licensing Branch 2 lp 15673 019 24X Fiche 50-440.82/09/29.8210130179
- B210190326 Forwards slide presentation from B20813 meeting re-safety relief hydrodynamic loads Position similar to criteria outlined in NUREO-0763 Encls withheld (ref 10CFR2 790) DAVIDBON, D.R. Cleveland Electric Illuminating Co. 92/10/08 SCHMENCER.A. Licensing Branch 2 2pp 15742-059 24X Fiche 50-440.82/10/08.8210190326
- 8210260419 Forwards NEDE-22203, "Reactor Internals Vibration Predictions," dtd Aug 1982 Rept contains proprietary infore internals vibration program & peak amplitude predictions per engineering analysis Rept withheld (ref 10CFR2 790) DAVIDSON,D R Cleveland Electric Illuminating Co 82/10/08 SCHWENCER,A Licensing Branch 2 1p 15806 114 24X Fichs 50-440,82/10/08.6210260419
- 6210190519 Confirms 821096 telcon repreoperational testing program
  Util not required to continue sending proliminary
  preoperational test procedures Current status of procedures
  & implementation will be forwarded monthly
  LITLE, W.S. Division of Engineering & Technical Programs 62/10/15
  HICKE, G.R. Cleveland Electric Illuminating Co. Ip. 1971/ 201
  24% Fiche 50-440.82/10/15.8210190619
- B210210079 Forwards proprietary util B2100B ltr & attachments re sate; relief valve hydrodynamic loads, inadvertently omitted from original submittal Nonproprietary info to be provided by B21005

  DAVIDSON, D R Cleveland Ciectric Illuminating Co 82/10/15
  BCHHENCER, A Licensing Branch 2 ip 15762 235 24X
  Fiche 50-440, B2/10/15, B210210079
- 8210270073 Notification of 821109 meeting w/util.C-E & OAI in Betheids MD to discuss pool dynamic load criteria application to plant specific design STEFAND.J Licensing Branch 2 82/10/19 SCHWENCER.A licensing Branch 2 3pp 15836 296 24X Fiche 50-440.82/10/19.82102700/3
- D NRC Draft/Final Environmental Statements, supply & correspondence
- 8210260235 Comments on FES for facility Applicant aware of offluent limits No add1 adverse environ impacts within EPA field of expertise anticipated BACKLEY.B T Environmental Protection Agency 82/10/19 SCHWENGER.A Licensing Branch 2 ip 15/79/354 24X Fiche 50-440.82/10/19.8210260235
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8210150233 Forwards response to SER Confirmnatory Issue 16 re beiting weld matts Info revises response to Questions 123 i, 123 2 t 123 3 should resolve issue of matt surveillance capsules DAVIDSON.D R Cleveland Electric Illuminating Co 82/09/22 SCHMENCER-A Licensing Branch 2 42pp 15706 010 24X Fiche 50-440, 82/09/22, 8210150233
- 8210130173 Advises that responses to NRC B20908 ltr re SER [lutstanding Issue 21 concerning reanalysis of transients & accidents & development of emergency operating procedures will be provided by 821029
  DAVIDBON, D.R. Cieveland Electric Illuminating Co. B2/09/20 SCHMENGER, A. Licensing Branch 2 Jp. 19673 044 24X
  Fiche 50-440, 82/09/28, 8210130173
- 8210190333 Responds to SER Confirmatory Items 32 & 45 re accident monitoring instrumentation & location of plant area radiation monitoring instrumentation Items also address TNI Items II F 1 3, II F 1 4, II F 1 5 & II F 1 6
  DAVIDBON, D.R. Cleveland Electric Illuminating Co B2/10/14
  SCHHENCER, A Licensing Branch 2 3pp 15742 120 24X
  Fiche 50-440, 82/10/14, 8210190333

- 8210190683 Forwards response to SER Confirmatory Issues 28,30 & 43 re instrumentation & control Three oversize drawings encl Aperture cards are available in PDR DAVIDSON,D R Cleveland Electric Illuminating Co 82/10/14 SCHMENCER.A Licensing Branch 2 App 15751 013 24% Fiche 50-440,82/10/14,8210190683
- F Security, medical, emergency & fire protection plans
- 8207180055 FOIA request for all documents since 1979 ie drug or alcohol abuse by persons at facilities SAMICKI.S O News-Herald Willoughby, CH 82/08/30 FELTON, J M Division of Rules and Records ip 15758 359 24X Fiche 50-440.82/08/30,8207180055
- B210190199 Responds to FOIA request for all documents since 1979 redrug or alcohol abuse by persons at facilities Forwards documents identified during 820913 telcon FELTON.J M Division of Rules and Records 82/09/15 SAWICKI,S GREWS-Herald Willoughby, OH 1p 15758 260 24X Fiche 50-440,82/09/15,8210190199
- --B210170204 Provides info re drug & alcohol abuse, fire support deficiencies, the ft & forced entry observed at facilities Author name deleted # Affiliation Unknown B2/07/15 NRC No Detailed Affiliation Given 2pp 1575B 361 24X Fiche 50-440, 82/07/15, 8210170179
- --8210190209 Ack receipt of ltr expressing concerns re security administration at facility NRC does not impose security requirements on licensee prior to unsite receipt of leactor fuel Contacting util suggested Info partially deleted PHILLIF.0 A Region 3. Chicago, Office of the Director (81/03/01) 81/07/16 Affiliation Unknown in 15758 363 24x Fiche 50-440,82/09/15.8210190199
- 8210190011 Notification of 821006 meeting w/util in Bethesda.MD to discuss responses to NRC questions re umergency plan & status of plan finalization STEFANG.J Licensing Branch 2 82/09/23 SCHWENCER.A Licensing Branch 2 3pp 15760 318 24X Fiche 50-440,02/09/23,8210190011
- 8210240572 Releases public version of revised emergency plan FELTON, J.M. Division of Rules and Records 82/10/08 Document Management Branch Ip 15832 024 24X Fiche 50-440, 82/10/08, 8210260572
- ---8210260575 Forwards public version of Revision O to emergency plan DAVIDBOND R Commonwealth Edison Co 82/09/22 DENTON H R Offics of Nuclear Reactor Regulation, Director 2pp 19832 02/ 24X Fiche 30-440, 02/10/08.8210260572
- --B2(0240577 Public version of Revision O to emergency plan 4 Commonwealth Edison Co 82/09/22 291pp 15832 027 24X Fiche 50-440,82/10/08,8210260572

# O Adjudicatory correspondence

- 8210070075 Forwards responses to interrogatories from Sunflower Alliance requiring FEMA reply KRIMM.R W Federal Emergency Management Agency 82/07/09 GRIMES.B K Division of Emergency Preparadness 35pp 15628 12/ 24X Fiche 50-440.82/09/09.8210070075
- 8210010335 Reply to applicant 820921 motion to amend ASL8 820916 memorandum & order re-scheduling Moving filing date of testimony will prejudice intervenors Applicant suggestion to delay hearing until 830222 should be granted MIATT-8 L Ohio Citizens for Responsible Energy 82/09/27 Atomic 8afety and Licensing Board Panel ip 15569-163 24X Fichs 80-440, 82/09/27, 8210010335
- 8210010366 Beventh set of interrogatories Cartificate of Svc encl Related correspondence HIATT, S.L. Ohio Citizens for Responsible Energy 82/09/27 Office of the Executive Legal Director. 8pp 15573 095 24X Fiche 50-440,82/09/27,8210010366
- 8210010377 Reply opposing applicant 820913 motion to rescind ASLB BIO804 procedurel order requiring intervenors to respond to MRC & applicant answers to late filed contentions. Certificate of Bvc encl HIATT, S.L. Ohio Citizens for Responsible Energy 82/09/27 Atomic Befety and Licensing Board Panel, 5pp 15573 054, 24X Fiche 50-440, 82/09/27, 8210010377

- 8210010388 Requests article from Nuclear News noted in ASLB 820916 memorandum & order be provided to all parties since magazine unavailable in public & univ libraries HIATT.S L Obio Citiens for Responsible Energy 82/09/27 BLOCH.P B . KLINE, J R . SHON, J J Atomic Safety and Licensing Bourd Panel 1p 15569 212 24X Fiche 50-440,82/09/2/.8210010386
- 8210010416 Sixth set of interrogatories Certificate of Svc encl Heluted correspondence HIATT'S L. Dhio Citizens for Responsible Energy 82/09/27 Cleveland Electric Illuminating Co 10pp 15572 193 24X Fiche 50-440,82/09/27,8210010416
- B210010250 Response opposing applicant motion to revise procedures for late filed contentions No prejudice demonstrated Proof of Svc encl HILT.D D Sunflower Alliance HILT.D D Hilt. D D 82/09/28 Atomic Safety and Licensing Board Panel 2pp 15568 262 249 Fiche 50-440.82/09/28.821010250
- 8210010323 Motion for 5-day extension to file motion to compel discovery against NRC Addi time necessary due to other business & personal illness Proof of Svc enc; WLLT, D.D. Sunflower Alliance WILT, D.D. Wilt, D.D. 82/09/34 Atomic Safety and Licensing Board Panel 1p 15569 172 24x Fiche 50-440.82/09/28,8210010323
- 8210010345 Answer to fourth set of interrogetories Certificate of Svc encl WILLMORE.R L. Cleveland Electric Illuminating Co. WILLMORE.R I Shaw, Pittman, Potts & Trowbridge 82/09/28 Ohio Citizens for Responsible Energy 17pp 15574 001 24X Fichs 50-440.82/09/28 8210010345
- 9210010457 Forwards RF Zucker & RA Pender original affidavits to be substituted for photocopies in applicant 820928 answer to OH Citizens for Responsible Energy fourth set of interrogatories Related correspondence HILLMORE.R L. Shaw, Pittman, Potts & Troubridge WILLMORE.R L. Cleveland Electric Illuminating Co 82/09/29 Docketing & Services Branch 3pp 15572 311 24% Fiche 50-440.82/09/29. 8210010437
- 8210040019 Notice of withdrawal of appearance in proceeding LEWIS S H Hearing Dranch 2 82/09/29 3pp 15581 262 24X Fiche 50-440,82/09/29,8210040019
- 9210040015 Certifies svc of NRC response to Sunflower Alliance motion seeking admission of lete contention on shift rotation & GE Johnson notice of appearance on 820730 JOHNSON OF Hearing Branch 4 82/07/30 2pp 15581 348 247 Fiche 50~440 82/07/30, 8210040015
- 8210040017 Response opposing Sunflower Alliance 820910 motion seeking admission of late contention on shift rotation Contention beyond Commission regulatory requirements, lacks basis & nexus & is untimety
  JOHNSON.0 E Hearing Branch 4 82/09/30 Atomic Safety and
  Licensing Board Panel 8pp 15581 297 24X Fiche 50-440,82/09/JD,8210040017
- 8210040023 Notice of appearance in proceeding JOHNSON.GE Hearing Branch 4 82/09/30 1p 15581 256 Fiche 50-440.82/09/30.8210040023
- B210050173 Third set of interrogatories re Issue 3 & requests production of documents Proof of Svc encl Related correspondence
  WILT.D D Sunflower Alliance WILT.D D Wilt. D D 82/0
  NRC No Detailed Affiliation Civen 7pp 15604 138 24X
  Fiche 30-440.82/09/30.8210050173
- 8210050228 Fourth request for production of documents re Contilsue 1 on emergency evacuation planning Proof of Svc enclingles decrease, soundence WILT, D D Sunflower Alliance WILT, D D Wilt, D D 82/0 Office of the Executive Director for Operations 2pp 154 24X Fichs 50-440,82/09/30,8210050228
- 8210050242 Requests extension of discovery time on Contention not ready for hearing as final emergency plans not yet in place Plans must be reviewed prior to hearing Proof of Svc encl Related correspondence
  WILT, D.D. Sunflower Alliance WILT, D.D. Wilt, D.D. 82/0'
  Atomic Safety and Licensing Board Panel 2pp 15610 334
  Fiche, 30-440, 82/07/30, 8210030242
- 8210050252 Third set of interrogatories w/requests for product documents re Issue 3 on adequary of applicant 6A program Proof of Svc encl Related correspondence WILT.D.D Sunflower Alliance WILT.D.D Wilt. D.D 82/05 Cleveland Electric Illuminating Go 12pp 19610 294 24X Fiche: 50-440, 82/09/30, 8210050252

- 0210050255 Third set of interrogetories & request for production of documents re Issues 1.3 % (I on offsite emergency evacuation plans.0A / local economic benefits.respectively Certificate of Svt encl WILLMORE.R L Cleveland Electric III)uminating Co WILLMORE.R t Shaw, Pittman, Potts & Trowbridge 02/09/30 Sunflower Alliance 12pp 15609 199 24y Fiche 50-440.82/09/30 8210050255
- 8210050374 Response in opposition to Sunflower Alliance. Inc. 820910 motion to compel applicant answer to second set of interrogatories Applicants will respond shortly Certificate or Svc encl
  SILBERG. J E. Cleveland Electric Illuminating Co. SILBERG. J E. Shaw, Pittman, Potts & Troubridge 82/09/30 Atomic Safety and Licensing Board Panel. 20pp. 15608-256. 24x Fiche 50-440.82/09/30. 8210050374
- 8210060207 Seventh set of interrogatories directed to applicant % eighth set of interrogatories directed to NRC.pursuant to ASLB 810728 Hemorandum / Order.LBP 81-24 Certificate of Svc encl Related correspondence (KATT.S L. Ohto Citizens for Responsible Energy 82/09/30 Cleveland Electric Filominating Co. 5pp. 15614-157 24x Fiche 50-440, 82/09/30.8210060207
- 8210050069 Response supporting applicant 820913 motion to levise procedures for late filed contentions Allowing intervenors to raise new matter in reply constitutes amend to contentions Certificate of Svc encl COTCHIN.J M Hearing Branch 4 82/10/04 Atomic Safety and Licensing Board Panel 8pp 15603 188 24% Fiche 50-440.82/10/04.821050069
- B210150192 Requests clarification of docket numbers for Harris & Peiry plants Mirry may be causing prejudice to intervenors since documents go to incorrect LPDR HiATT.S L. Ohio Citizens for Responsible Energy 82/10/04 Docketing & Services Branch 1p 24X Fiche 50-000.82/10/04. 02:0450192
- 8210060303 Response opposing OH Citizens for Responsible Energy 820920 motion to compel discovery of NRC A util ASLB chairman comments did not allow intervenors to broaden contention or scope of discovery CUTCHIN.J M Hearing Branch 4 82/10/05 Atomic Sarety and Licensing Board Panel App 15619 017 24X Fiche 50-440-82/10/05, 82/10/06,0303
- --6210060321 Response to applicant 820921 motion to amend schedule set forth in ASLB 820916 order NRC does not object to extending period between filing of testimony & commencement of hearing Certificate of Svc enc! CUTCHIN.J H. Hearing Branch 4 82/10/05 Atomic Safety and Licensing Board Panel Spp. 15619 023 24X Fiche 50-440. 82/10/05 8210060303
- 6210070405 Answer apposing Sunflower Alliance 820430 application to lift 820930 discovery cutchf date for Issue : Intervenor has had over 1 L2 yes to file discovery No good cause shown Certificate of Svc enc] Related correspondence WILLMORE, R L Cleveland Electric Illuminating Co WILLMORE, R L Shaw, Pittman, Potts & Troubridge 82/10/05 Atomic Safety and Licensing Board Panel 6pp 15633 307 24% Fiche 50-440,82/10/05, 2010/2005
- 8210070137 Memorandum & order denying util 820913 motion to revise procedures for late-filed contentions If intervenor introduces new math in reply, applicants will be allowed to respond 8LOCH P B KLINE, J R SHON, F J Atomic Safety and Licensing Board Panel 82/10/06 Cleveland Electric Illuminating Ch 4pp 19627 GLA 247 Fichs 50-440, 82/10/06, 82/10/2013

- 8210130327 Memorandum & order denying OH Citizens for Responsible Energy 820707 motion to sever proceedings No reason provided for ASLB to reconsider 810907 ruling on identical motion by Sunflower Alliance BLOCH.P B Atoms: Safety and Licensing Board Panel 82/10/01 Chia Citizens for Responsible Energy Ip 15678 283 24X Fiche 50-440, 82/10/08.8210130327
- 8210130333 Memorandum & order admitting Contention 12 re inadequale consideration of economic consequences of accidents Preponderance of considerations favors admission of contention BLOCH P B . KLINE, J R . SHON, F J . Atomic Safety and Licensing you
- contention
  BLOCK,P B : KLINE, J R : SHON,F J Atomic Safety and Licensing Bond
  Panel 82/10/08 Ohio Citizens for Responsible Energy 5pp
  15682 059 24X Fiche 50-440,82/10/08,8210130333
- 6210150228 Confirms conversations w/OH Citizens for Responsible tress, budge Bloch re extension of time for util to respond to OH Citizens for Responsible Energy 620920 motion to compel discovery on NRC & util Response due 821018 W/svc list SILBERO, J E Shau. Pittman. Patts & Troubridge SILBERO, J C Cleveland Electric Illuminating Co 82/10/08 BLOCH.P D . KLINE.J R . SHON.F J Atomic 88fety and Licensing Board Panel 19, 15706 008 24% Fiche 50-440.82/10/08.82/10/5028
- 8210150467 Answer to sixth set of interrogatories Ceitificate of but encl MILLMORE,R L. Cleveland Electric Illuminating Go. WilLMORE,R t. Shaw. Pittman. Potts & Trombridge 82/10/12 Ohio Citizeni fur Responsible Energy 10pp 15703 050 24X Fiche 50~440.62/10/12 8210150447
- 8210180211 Reply opposing NRC & applicant responses to GH Citizens for Responsible Energy motion for leave to file Contentions 21-26 Good cause, specificity & basis requirements met Certificate of Svc encl
  HIATTIS L. Ohio Citizens for Responsible Energy 82/10/L4
  Atomic Safety and Licensing Board Panel 14pp 15718 110 21x
  Fiche 50-440,82/10/12,8210180211
- 8210150175 Advises that documents requested by Bunflower Alliance fourth request directed to Executive Director for Operations available in PDR CUTCHIN.J M Hearing Branch 4 82/10/13 WILT.D D Wilt. By WILT.D D Sunflower Alliance ip 15707 183 24X Fiche 50-440.82/10/13.8210150175
- 8210158275 Advises that NRC will not voluntarily respond to any discovery requests in Sunflower Alliance third set of interrogatories & requests for documents, except Request 19 Remainder of discovery broader than Issue 3 CUTCHIR.J M. Hearing Branch 4 82/10/13 WILT.D D. Wilt. U.E. WILT.D D. Sunflower Alliance 3pp 15705 001 24x Fiche 50-440.82/10/13.8210150275
- 0210180185 Advises of correction to util response to Interrogatory of OH Citizens for Responsible Energy sixth set of interrogatories Conclusion of response remains unchanged Related correspondence WILLMORE, R. I. Shaw, Pittman, Potts & Trowbridge WILLMORE, R. I. Cleveland Electric Illuminating Co. 82/10/14 HIATT, 8 Ohio Citizens for Responsible Energy ip 15719-269 24X Fiche 50-440,82/10/14,8210180185.
- 8210190377 Answers to B20907 fifth set of interrogatories Prof qualifications & Cartificate of Svc encl JOHNSON, O E Operations & Administrative Division 82/10/15 Ohio Citizens for Responsible Energy 15pp 15740 300 44X Fiche 50-440, 82/10/15, 8210190377
- 8210190475 Answer opposing Sunflower Alliance 620926 motion to sit time to file motion to compel discovery against NRC No basis for unlimited request provided Cortificate of Svc encl CUICHIN.J M Hearing Branch 4 82/10/15 Atomic Safety and Licensing Board Panel App 15740 241 24X Fiche 50-440,02/10 8210190475,
- 82/02/0351 Objects to issuance of ASLB 82/008 memorandum & order request to extend discovery on Issue I Order issued ASLB should request responses from all parties on expedited schedule W/Gertificate of Svc Related correspondence HARTI, S. L. Ohio Citizens for Responsible Energy 82/j0/15 8LOCH, P.B. KLINE, J.R., SHON, F.J. Atomic 82/t0/15,82/02/10/15 Panel ip 15764 010 24% Fiche, 50-440,82/10/15,82/02/10/15
- --B210210358 Seventh discovery progress rept; pursuant to ASLS BLOY memorandum & order\_LBP-81-35 Interrogatories submitted to applicant & NRC re Issues 4,5.47,8 & 9 Discovery re Issue 9 forthcoming HATT,8 L Ohio Cit(rens for Responsible Energy 13764 011 24X Fiche 30-440,82/10/15,8210210351

- --8210210366 Motion to extend discovery on Issue 9 to 821101 to permit review of documents referenced in applicant responses to 820830 interrogatories & followup discovery Certificate of Svc encl Related correspondence HIAFT. S.L. Ohio Citizens for Responsible Energy 82/10/15 Atomic Safety and Licensing Board Panel 3pp 15764-013 24X Fiche 50-440,82/10/15.8210210351
- 8210210284 Answer opposing CH Citizens for Responsible Energy 820920 notion to compel discovery on NRC & util Interrogatories not relevant to & beyond scope of Issue & Certificate of Svc encl Related correspondence SILBERG. J E Cleveland Electric Filuminating Co SILBERG. J E Shaw, Pittman, Potts & Troubridge 82/10/18 Atomic Safety and Licensing Board Panel 36pp 15765 079 24X Fiche 50-440,82/10/18,82102/0284
- 8210210353 Amended answer to Interrogatory 13 of Sunflower Alliance second set of interrogatories Certificate of Svc encl Related correspondence
  SILBERO. J E Cleveland Electric Illuminating Co SILBERO. J E Shaw. Pittman, Potts & Troubridge 82/10/18 Sunflower Alliance Spp 15763 177 24X Fiche 50-440:82/10/18.8210210353
- 6210220481 Requests attachment to IRC 780203 ltr to GE be provided to allow progress on Issue 4 Document needed before intervenor can decide if updates to interrogatories necessary Related correspondence HIATLS L. Onto Citizens for Responsible Energy 82/10/18 SILBERG, J. Shaw, Pittman, Potts & Trowbridge SILBERG, J. Cleveland Electric Jiluminating Co. 1p. 15779-078-24X Fiche 50-440, 82/10/18,821020481
- B210210476 Memorandum & order denying Sunflower Alliance 820910 motion to compel applicant to answer second set of interrogatories if util agrees to stipulation on potassium indide subcontention. Interrogatory 36 need not be answered BLOCH P B . KLINE, J R . SHON.F J Atomic Safety and Licensing Bourd Panel 82/10/19 Cleveland Electric Illuminating Co App 15762 R65 24X Fiche 50-440,82/10/19.8210210476
- B210220305 Answer to 820930 seventh set of interrogatories Certificate or Syc encl
  WILLMORF, R L Cleveland Electric Illuminating Co WILLMORF, R L
  Shaw, Pittman, Potts & Trowbridge 82/10/19 Ohio Citizens for Responsible Energy 13pp 15776 053 24X Fiche 50-440,82/10/19,8210220305
- 82[0220309 Seventh discovery progress rept Certificate of Svc entl HILLMORE, R L Cleveland Electric Illuminating Co WILLMORE, R L Shaw, Pittman, Potts & Trowbridge 82/10/19 4pp 15776 049 ,4X Fiche 50-440, 82/10/19, 8210
- 8210220374 Motion for leave to file answer to OH Citizens for Responsible Energy (OCRE) 821012 reply to util & NRC answers to OCRE motion for leave to file Contentions 21-26 WILLMORE.R L Cleveland Electric Illuminating Co MILLMORE.R L Shaw Pittman, Potts & Trowbridge 82/10/19 Atomic Safety and Licensing Board Panel 2pp 15777 312 24X Fiche 50-440,82/10/19,82/10/20374
- --B210220405 Answer to OH Citizens for Responsible Energy 821012 reply to NRC & applicant response to Citizens motion to file Contentions 21 through 26 Citizens did not meet burden of proof for admission of new contentions W/Certificate of Svc WILLMORE, R. Cleveland Electric Illuminating Co. WILLMORE, R. E. Shaw, Pittman, Potts & Troubridge 82/10/19 Atomic Safety and Licensing Board Panel 15pp 15777 314 24X Fiche 50-440,82/10/19.8210220396
- 8210250331 Reply brief supporting motion to submit addl contention Good cause for late filing demonstrated Applicant shift rotation plans may not be incorporating circadian principles WILT.D D Sunflower Alliance. WILT.D D Wilt. D D 82/10/19 Atomic Safety and Licensing Board Panel 3pp 15790 325 24X Fiche 50-440.82/10/19.8210250331
- 8210250299 Answer to OH Citizens for Responsible Energy 821015 motion to extend discovery on Issue 9 re polymer degradation No justification exists for extending discovery cutoff date Certificate of 8vc and SILBERG, J E. Cleveland Electric Illuminating Co. SILBERG, J E. Shaw. Pittman. Patts & Trowbridge 82/10/20 Atomic 8afety and Licensing Board Panel. Spp. 18790 195 24X Fithe 50-440,82/10/20,8210250279
- 9210250322 Supplemental answers to Sunflower Alliance. Inc second set of interrogatories Certificate of Svc encl
  SILBERG, J E Cleveland Electric Illuminating Co SILBERG, J E Shaw, Pittman, Potts & Trowbridge 82/10/20 Sunflower Alliance 17pp 15790 226 24% Fiche. 50-440, 82/10/20, 8210250322

- 8210250365 Advises that NRC will not voluntarily respond to DH Citizen for Responsible Energy seventh set of interrogatories except for interrogatories listed Requests irrelevant & will not lead to discovery of admissible evidence CUTCHIN.J M. Hearing Branch 4. 82/10/22 HIATT S.C. Dhio Citz/Cnf for Responsible Energy 2pp 15790 L75 24X Fiche 50-440.82/10/22, 8210250365
- 8210260033 Answers to 820830 fourth set of documents Certificate of Sylenci enci WRIGHT, N.A. Hearing Branch 2 82/10/22 Chio Citizens for Responsible Energy 12pp 15779-124 24X Fiche 50-440, 82/10/22,
- 8210280216 Responds to 821018 ltr re svc of documents to parties Telcons could expedite matters in future Svc list encl Related correspondence SILBERG-JE Shaw Pittman, Potts 3 Trawbridge 82/10/22 HIATT-S L Glo Citizens for Responsible Energy 9pp 15837 J36 24X Fiche 50-440,82/10/22,8210280216
- 8210280231 Update to response to Interrogatory 4 2 of QH Citizen, for Responsible Energy 820928 fourth set of interrogatories Related correspondence WILLMORE.R L Shaw, Pittman, Potts A Troubridge WILLMORE.R L Cleveland Electric Illuminating Co 82/10/22 HIATT.S Ohio Citizens for Responsible Energy ip 15837 081 24x Fiche 50-440, 82/10/22, 8210280231
- 8210240389 Answers to listed interrogatories of 820927 seventh set of interrogatories NRC will not voluntarily answer remaining interrogatories Certificate of Svc encl CUTCHIN.J M. Hearing Branch 4 82/10/25 Ohio Citizens for Responsible Energy (11pp. 15803-348 24X Fiche 50-440,82/10/25,821026333
- 8210260395 Discovery rept for previous two months per ASLB 810907 memorandum t order CUTCHIN, J M Mearing Branch 4 82/10/25 BLCKH, P.B. SHON, I.J. KLINE, J.R. Atomic Safety and Licensing Board Panel (p. 1580J.)43 24X Fiche 50-440,82/10/25,8210260395
- 8210280246 Forwards RB Coffey original affidavit to be included in applicant 821020 supplemental answers to Sunflower Alliance second set of interrogatories Related correspondence WILLMORE, R L. Shaw, Pittman, Potts 5 Trowbridge WILLMORE, R C. Cleveland Electric Illuminating Co. 82/10/25 Docksting & Services Branch 2pp. 19837-054 24X Fiche 50-440,82/10/25, 8210280246
- B210290287 Requests end RF Zucker & RV Tanney original affidavits he substituted for photocopies in applicant 821019 answers to OH Citizens for Responsible Energy seventh set of interrogatories
  MILLMORE: R L Show: Pittman. Polts & Trowbridge MILLMORE: R t Cleveland Electric Illuminating Co 82/10/26 Docketing & Services Branch 3pp 15854-069 24X Fiche 50-440,82/10/26.
- 8210280346 Answer opposing CH Citizens for Responsible Energy 821016 motion to extend time for discovery on Issue 9 No justification for extension provided Certificate of Svc enc!

  CUTCHIN, J M Hearing Branch 4 82/10/27 Atomic Safety Licensing Board 7 8210280346

- 4 Inspection reports IE Bulletins & correspondence
- 82100A0305 Forwards IE Imsp Repts 50 440782-11 % 50-441782-10 on 820831-0902 No noncompliance noted LITHE.W 5 Division of Engineering % Technical Programs 8270972, DAVIDSON D R Cleveland Electric [1] Unminating Co 2pp 15619 195 24X Fichs 50-440.82707722,8:100860305
- 8210060308 IE Insp Repts 50-440/82-11 % 50-441/82-10 on 820831-0902 Nu noncompliance noted Major areas anspected preservice insp procedures? untry activities, previous insp findings & IE Bulletin 80 08 activities
   HARD. N. D. MANIELSON. D. H. Region 3 Office of Director 82/09/14 5pp 15619 197 244 Fiche 50-440 82/09/22.8210060305
- 8210170763 Forwards If Investigation Repts 50-444781-17 A 50-441761 IV on 811027-920319 & notice of violation REPPLER J & Region 3. Office on Director 82.09/27 DAVIDSON.UR Clevelard Electric Illuminating C6 3pp 15736 318 24X Fince 50-440 82-076.27 & 210190762
- --8210190771 Notice of violation from investigation on 811027-820319 AEPPLER, J.G. Region 3 Office of Director 82 09/24 9pp 15735 321 24x Fiche 50-440 82/09/27,8210190763
- -82101707AT IE (investigation Repts 50-440/81-19 & 50-441/81-19 on 611027-820019 Noncompliance noted Gould. Inc Drawings E-35-51 998 E231 % E231 inadequately reviewed & instructions not incorporated into cable pulling procedures NEH.C H. NAIDU & R. BRAUND.C D. Region 3, Office of Directo 52/09/22 45pp 15738 130 24% Fiche 50-440.82/09/27, 8210190763
- 문급08190233 IE Info Autice St. 35, buppl 1, Leaking \* Dislodged I-I/O Implant Seeds " Svc list enr! COBS.L I Division of Fuel Facilities, Materials & Safeguards E2710708 Consolidated Edison Co of New York copp 15761 교기인 교사 Fithe 50-000 원교 10708 6208190233
- 9208190236 IE Builetin 8±-03 Stress Currosion Cracking in Thick-MalliLarge-Diameter Statiless Steel Recirculation Sys Piping at BMR Plants "Svt list encl DEYOUNG R C Director's Office Office of Inspection and Emportment 82/10/14 Consolidated Edison Co of New York 115pp 1501C 125 24 Fiche 50 000-82/10/14.8208190238
- 8210240333 Ack receipt of 6\_1008 itr informing NAC of steps taken to carrect violations noted in IE lisp Repts 50 440/62-09 t 50-441/62-08 MCRELIUS, C.E. Division of Project? Resident Programs 02/10/21 DAVIDSON D.R. Cleveland file-tric Tiluminating Co. 1p 15803 192 244 Fiche 50-446 82 in 21/8210220333
- -8210260337 Responds to NRC 820710 Its sevalations noted in IE insp. Repts 50-440/82-09 3 50-441.82-38 Corrective actions Maiser Enginest Procedure GAP 12 revised to require annual evaluation Detailed hardware insp.performed 820728 PAVID50N D.R. Claveland Electric [lluminating Co. 82/10/08] 3 OREL IUS. C.F. Division of Project 1 Resident Programs 6pp. 15803-192 24X Fiche 50-440, 82/10/21, 8210260333
- 5 Reportable occurrences. LFRs & related correspondence
- 5210056132 Final deficiency rept is nonconforming Transamerica Bolazat standby diesel generator ASME Section III. Class 3. piping welds Initially reported on 820327 Weld insp & required repair/rework will be completed by 830401 BAY1050N-D R Cleveland Electric Illuminating Co 82/09/24 MEFFLER. J G Region 3. Derice of Director 2pp 15605 047 247 Fiche 50 440.82/09.24.8210050132
- 8210130364 Third interin deficiency rept re rejection of previously accepted containment vessel radiographs Initially reported on 820405 All potentially rejectable radiographs submitted to Hartford Steam Boiler Insp Co for review DAVIBSCH.D R Cleveland Electric Illuminating Co 82/09/30 KEPFLER.J G Region 3. Office of Director 2pp 15681 169 24X Fiche 50-440, 82/09/30.8210130364
- DOCKET 50-449 SEABROOK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8210120617 Notification of 820924 meeting w/applicant in Seabrook,NH to inspect onsite radiological monitoring sys as part of GL sarety review MHEELER, L. Licensing Branch 3 82/09/17 KERRIGAN, J D Licensing Branch 3 3pp 15672 235 24X Fichs 50-443,82/09/17,8210120617

- 8210070160 Forwards draft results of analysis of associated circuits addressing question raised at 820910 meeting Once concurrence received response will be issued as amend to FSAR. Closing out Open Item 26
  BAXTER: F Yankee Atomic Electric Co 82/09/20 SRINIVASAN. M Power Systems Branch 12pp 15645 049 24% Fiche 50-443,02/09/20
  8210070160
- 8210180378 Requests assignment of reviewers for Bechtel work packages All three packages should be ready for NRR review by 821004
  Task Interface Agreement TIA 82-55 w/Region 4 encl
  KERRIGAN, J D Licensing Branch 3 62/09/20 LEAR, 6 Hydrologic & Geotechnical Engineering Branch 80SNAK, R Mechanical Engineering Branch SCHAUER, F Structural Engineering Granch 2pp 15/45, I... 24X Fiche 50-443, 82/09/20, 8210180378
- 8210010465 Forwards "Response to NRC Generic Request for Addl Info He NUREG-0612.Control of Heavy Loads" DEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIS.J Publis Service Co of New Hampshire 82/09/24 KERRIGAN.J D Licentin, Branch 3 1p 15572 017 24X Fiche 50-443.82/09/24.8210010445
- --8210010470 "Response to NRC Generic Request for Addl Infa Re NURCO-0612 Control of Heavy Loads" Public Service Co of New Hampshire 82/09/30 \$34pp 15572 018 24X Fiche 50-443, 82/09/24, 8210010465
- 8210040112 Forwards response to NRC generic request for addl info re NUREO-0612, "Control of Heavy Loads" #/a encl DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Publid Bervice Co of New Hampshire 82/09/24 KERRIGAN, J B Litemaina Dranch 3 ip 13581 143 24X Fiche 50-443.82/09/24,8210040112
- 8210040193 Forwards responses to Hydrologic & Geotechnical Engineering
  Branch 820727 Series 240 requests for addl info.Guestions
  240 38,240 39 & 240 41 Response to Question 240 40
  rothcoming
  DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIG, J Public
  Service Co of New Hampshire 82/09/30 KERRIGAN, J B Licensing
  Branch 3 14pp 15583 168 24X Fiche 50-443,82/09/30,(2)10040191
- 8210050199 Responds to Mechanical Engineering Branch 920618 request for addl info Response includes "Prying Effect on Concrete Espansion Anchor Bolts Due to Pipe Support Base Plate Flexibility" Draft responses submitted 820728 DEVINCENTIS, J. Public Service Co. of New Hampshire 8207930 KERRIGAN, J. 8 licensing Branch 3 3p 15609.085 24X Fiche 50-443,82/09/30,8210050149
- --8210050206 "Prying Effect on Concrete Expansion Anchor Bolts Due to Pipe Support Base Plate Flexibility " OALUNIC.B. MCKENNA.M. RIGAMONTI.G United Engineers & Constructors, Inc (subs of Raytheon Co.) 79/07/20 @Opp 15609
- 9210050373 Requests add1 info re analysis proving any challenges in Class IE circuits from associated circuits do not prevent sare shutdown of plant info re NUREG-0737. Item II E 4 2. Position 6 on containment isolation valves required KERRIOAN. J. Licensing Branch 3 82/10/01 TALLMAN.W.C. Public Service Co. of New Hampshire 9pp 15608 324 24X Fiche 50-443, 82/10/01.8210050393
- 8210070105 Forwards revised response to Question 440 136 re Reacteri,: Branch 820727 request for addition concerning steam generator tube rupture
  BEVINCENTIS.J Vankes Atomic Electric Co DEVINCENTIS.J Public Service Co of New Hampshire 82/10/05 KERRIGAN.J B Literair, Branch 3 4pp 15428 074 24X Fiche 50-443.82/10/05.82(0070105)
- 6210130436 Forwards revised responses to Mechanical Engineering Dract 820301 & 05 Requests for Addl Info 210 3-210 69.originally submitted in util 820421.30 & 0510 ltrs.per 020511-13 meeting Responses will be incorporated into FSAR Amend 47 DEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIS.J Public Service Co of New Hampshire 82/10/06 KERRIGAN.J B Licensing Branch 3 124pp 15681 199 24X Fiche 50-443.82/10/06.8210130436
- B2:0:50510 Forwards revised FBAR Section 6.2.2 providing justifaction for excluding inert cover gas on sedium hydroxide storage tank info will be incorporated in Amend 48 to OL application
  DEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIS.J Public Service Co of New Hampshire 82/10/07 KERRIGAN.J Licensing Branch 3 4pp 15714 IB9 24X Fiche 50-443.82/10/07.8210150510
- 8210180001 Forwards notes from 820914 & 15 Instrumentation & Controls
  Sys Branch review meetings.per NRC 820216 & 0323 requests
  Notes also include items discussed at 820323-25,0512 & 13 &
  0715 & 16 meetings & NUREG-0737 action items
  DEVINCENTIS.J Yankse Atomic Electric Co DEVINCENTIS.J Public
  Service Co of New Hampshire 82/10/14 KERRIGAN.J Licensing
  Branch 3 95pp 15720 031 24X Fiche 50-443,82/10/14,8210180001

j,

ş.

Part Line

12

```
250307 Requests advanced notification of scheduled NRC meetings re
23030/ Requests advanced notification of scheduled NRC meeting cilities to enable ample time for Atty General Off to range for staff attendance NDER.E T New Hampshire, State of 82/10/18 WHEELER.L L gensing Beach 3 10 15790 069 24X Fiche 50-443,82/10/18,10250307
```

270006 Forwards request for info re unsite audit for seismic & namic qualification review & pump & valve operability mpletion of encl forms requested within 3 wks Specific ter of audit to be unutally agreed to by NRC & applicant RRIGAN, J D Licensing Branch 3 82/10/21 TALLMAN, W C Public Truce Co of New Hampshire 25pp 15816 348 24X che 50-443,82/10/21.8210270006

280119 Forwards response to Power Sys Branch & Equipment alification Branch 821001 Request for Add1 Info 430 149 re alwsis on associated circuits,per 820910 & 1020-21 etings w/NRC VINCENTIS,J Yankee Atomic Electric Co DEVINCENTIS,J Public rvice Co of New Hanpshire 82/10/26 MIRAQLIA,F J Licensing anch 3 10pp 19837 136 24X Fiche 50-443,82/10/26,8210280119

RC Draft/Final Environmental Statements, suppls & correspondence

120029 Forwards comments from State of NH to be included in NRC

peoper runwards comments from State of NH to be included in NRC 0730 ltr re facilities DEG M/o encl RAGLIA.F J Licensing Branch 3 82/08/24 TALLMAN.W C Public runce Co of New Hampshire ip 15689 196 24X che 50-443.82/08/24

ecurity, medical, emergency & five protection plans

120128 Summary of 820720 meeting w/utils & United Engineers &

neutroctors in BethesdamD re associated circuits
esentation outline % details of preliminary review &
esentation outline % details of preliminary review &
elysis of associated circuits FSAR tange encl
DX.J Power Systems Branch 82/09/24 SRINIVASAN.M Power
stems Branch 100pp 15692 050 24X Fiche 50~443,82/09/24,
10120128

djudicatory correspondence

D60194 Forwards Seacoast Anti-Pollution League objection to & tion for reconsideration of ASLD 820913 order & motion to retify objections to ASLAB retify objections to ASLAB retify objections to ASLAB RACKUS.R A Seacoast Anti-Pollution CKUS.R A Backus.R A BACKUS.R A Seacoast Anti-Pollution ague 82/09/30 HOYT.H F. LUEBKE.E A . HARBOUR.J Atomic Safety of Licensing Board Panel 2pp 15614 220 24X

10060206 Objection to & motion for reconsideration of ASLB 820913 order & motion to certify objections to ABLAB Contention Suppl 4 should be admitted BACKUS,R A Seacoast Anti-Pollution League BACKUS,R A Buckus, R A 82/09/30 Atomic Safety and Licensing Board Panel /pp 13614 222 24X Fiche 50-443,82/09/30.8210060194

10060214 Affidavit of P Brown Hearings underway before appropriato state agencies re New England Electric Transmission Corp & Neu England Power Pool applications for const of transmission lines BROWN.P Seacoast Anti-Pollution League 82/07/30 Bpp 13614 287 24X Fichs 50-443,82/07/30.8210060174

O50262 Grder allowing parties to file reply to New England alition on Nuclear Pollution objections & motion & State NH motion for reconsideration of ASLB 820913 memorandum & der Reply due by 821019 YT.H F Atomic Bafety and Licensing Board Panel 82/10/01 2pp 610 284 24X Fiche 50-443,82/10/01,8210050262

200026 First set of interrogatories & request for documents on intentions 1 A 2.1 B 1.1 B 2 & 1 C RDAN,W 5 , CURRAN,D New England Coalition on Nuclear Pollution RDAN,W 5 Harmon & Weiss 82/10/13 Public Service Co of New Mpshire 14pp 15755 033 24X Fiche 50-443,82/10/13,8210200026

10200035 First set of interrogatories & request for documents on Contentions I A 2.1 B I.1 B 2 & I C.
JGRDAN, W S , CURRAN, D New England Coelition on Nuclear Pollution
JGRDAN, W S Harmon & Weiss 82/10/13. Office of the Executive
Legal Director 12pp 15755 047 24X Fiche 50-443,82/10/13. B510200034

10200042 First set of interrogetories & request for documents on Contentions II B 1, II B 3, II B 4 & II B.5
JORDAN W B , CURRAN, D New England Coalition on Nuclear Poliution
JORDAN W S Harmon & Weiss 82/10/13 Public Service Co of
New Hampshire Bpp 15755 059. 24X Fiche 50-443,82/10/13.

--8210200049 First set of interrogatories & request for documents on Contentions II B 1. [[ B 3.1] B 4 & [] B 5 Certificate of DORDAN, N.S., CURRAN, D. New England Coalition on Nuclear Pollution JORDAN, N.S. Harmon & Weiss 82/10/13 Office of the Eincutiv, Legal Director 9pp 15755-067 24X Fiche 50-440, 82/10/13, 8210200026

8210270153 Response opposing New England Coalition on Nuclear Power objections to prehearing conference memorandum & order & motion to certify objections to ASLAB Issues in objections already considered Certificate of Svc encl GAD.R K. Public Service Co. of New Hampshire. GAD.R K. Roper & Gray. 82/10/26. Atomic Safety and Licensing Board Panel. Supp. 15829-327. 24X Ficho. 50-443.82/10/26,8210270153

8210270166 Response opposing State of Not objection 5 motion for reconsideration of ASLB 820913 order No errors committed in ruling on NH contentions ASLB should not certify rulings since certification not requested Certificate of Svc encl GAD.R K Public Service Co of New Hampshire GAD.R K Popc. \* Gray 82/10/26 Atomic Safety and Licensing Doard Panel Ppp. 15830 t17 24X Fiche 50-443,82/10/26,8210270166

### H General correspondence

B210120270 Requests that DR Lewis be added to svc list TAYLOR, J. Atomic Safety and Licensing Board Panel B2/10/08 Public Service Co. of New Hampshire (p. 15652-317 24X Fiche 50-443, 82/10/08, 8210120270

G. Inspection reports: IE Bulletins & correspondence

8210070392 Forwards IC Insp Repts 50-443/82-09 t 50-444/82-09 on 820824-27 No nancompliance noted MARTIN T Division of Engineering t Technical Programs 82/09/2,2 TALLMAILW C Public Service Co of New Hampshire 2pp 156,33 331 24X Fiche 50-443,82/09/22,8210070392

--8210070400 IE Insp Repts 50-443/82-07 t 50-444/82 09 on 820824 2/ No noncompliance noted Major areas inspected procedures & work activities re concrete const of reactor containment bldg done, structural welding within containment bldg & QA review VARELAAAA. DURR. J.P. Region 1. Office of Director 82/09/29 7pp 18633 333 24x Fiche 50-443, 82/09/22-8210070329

8208290124 FOIA request for IE Insp Rept 50-443/82-06 % locfR50 BACHAND, D Affiliation Unknown 82/09/28 CARR, J NRC - No Detailed Affiliation Given 1p 15758 351 24X Fiche 50-443,82/09/28,8208290124

8210190035 Responds to FOIA request for IE Insp Rept 50-443/82-06 A 10CFR50 Forwards documents W/o encl FELTON, J K Division of Rules and Records 82/10/04 BACHAND, D Affiliation Unknown 1p 15758 352 24X Fiche 50-443,82/10/04. 8210190035

8208190233 IE Info Notice 80-35. Suppl 1. "Leaking & Disladged I-12": Implant Seeds " Svc list enc! COBBL I Division of Fuel Facilities. Materials % Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000.02/10/06.0208190233

8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-AVAIVO238 IE BUIJEth 82-03, "Stress Corresion tracking in Init."
Wall.Large-Diameter. Stainless Steel, Recirculation Sys
Piping at BWR Plants " Svc list enc!
DEYDUNG, R C Director's Office, Office of Inspection and
Enforcement 82/10/14 Consolidated Edison Co of New York
LISPP 15810 125 24X Fiche 50-000.82/10/14.8208190238

#### S Reportable occurrences, LERs & related correspondence

8210190126 Corrected version of final deficiency rept re misapplication of torquing equipment by Beloit Power Sys Instially reported on 820820 Corrective procedure provided by vendor will preclude potential problems

DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 82/09/20 STAROBTECKI, R. Division of Project & Resident Programs 2pp [5742 132 24X]

Ficher 50-443, 82/09/20, 8210190126

82(0190136 Corrected version of final deficiency rept re Robertshaw Controls thermostatic valves Initially reported on 820820 Corrective actions described by vendor will practude Carrective actions describes by Venbor Will precide potential problems
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 02/09/20 STARDSTECKI.R Division of Project & Resident Programs 3pp 15742 227 24X
Fiche 50-443,82/09/20.8210190136

- 8210190363 Final deficiency rept re-cracked welds in containment annular steel end connections Initially reported on 820910 Metallurgical investigation performed welding & installation procedure revised & cracked connections replaced DEVINCENTIS. J. Venkes Atonic Electric Co. DEVINCENTIS J. Public Service Co. of New Manpshire 82/10/12 STAROSTECKI.R. Division of Project & Resident Programs 3pp. 15740-321 24x
  Fiche 50-443,82/10/12,8210190363
- 5210260330 Interim deficiency rept re sheared pinion keys in Limitorque Model SB-0-25 motor operators Initially reported on 820902 Caused by use of inappropriate key math Limitorque & Hestinghouse confining investigation DEVINCENTIS J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Manpshire 82/10/18 STAROSTECKI, R Division of Project & Resident Programs 200 15802 340 24% Fiche 50-443,82/10/18,8210240330
- 6210260149 Interim deficiency rept re power surges in solid state protection sys which may disable protection circuit initially reported an 820805 item reportable based on 820806 Westinghouse Iter Final rept expected by 820115 DEVINCENTIS. J. Yankee Atomic Electric Co. DEVINCENTIS. J. Public Service Co. of New Harpshire 62/10/19 STAROSTECK! R. Division of Project & Resident Programs ip 15799 018 24% Fiche 50~443,82/10/19.6210260149
- PAUKET 50-444 SEABROOF NUCLEAR STATION. UNIT 2
- A Application/construction stage documents  $\hbar$  correspondence
- E210120617 Notification of 820924 meeting w/applicant in Seabrook.NH to inspect onsite radiological monitoring sys as part of QL sarety review WHEELER. U. Licensing Branch 3 82/09/17 KERRIGAN J.D. Licensing Branch 3 392/09/17 KERRIGAN J.D. Licensing Branch 3 3pp 15672 235 24X Fiche 50-443,82/09/17,8210120617
- B210070160 Forwards drart results of analysis of associated circuits addressing question raised at B20910 meeting Once concurrence received response will be issued as amend to FSAR. closing out Open Item 26 BAXTER: F Yankee Atomic Electric Co. 82/09/20 SRINIVASAN, M Power Systems Branch 12pp 15645-049 24X Fiche 50-443.82/09/20, B210070160
- 6210180378 Requests assignment of reviewers for Bechtel work packages. All three packages should be ready for NRR review by 821004. Task Interface Agreement TIA 82-75 w/Region 4 enc.]
  MERRIGAN. J. D. Licensing Branch 3 62/09/20 LEAR. O. Mydrologic & Geotechnical Engineering Branch 805NAV. R. Mechanical Engineering Branch SCHAUER, F. Structural Engineering Branch 2pp 15/49 200-24% Fiche 50-443, 82/09/20, 8210180378
- 8210010455 Forwards "Response to NRC Generic Request for Addl Info Re NAREO-0612-Control of Heavy Loads" DEVINCENTIS.J Vankee Atomic Electric Co DEVINCENTIS.J Public Service Co of New Hampshire 82/09/24 MERRIGAN.J B Licensing Branch 3 lp 15572 017 24% Fiche 50-443.82/09/24.8210010465
- --8210010470 "Response to NRC Generic Request for Addi Info Re NUREG-0612 Control or heavy Loads" + Public Service Co of New Hampshire 82/09/30 134pp 15572 018 24X Fiche 50-443.82/09/24.8210010465
- 8210040112 Forwards response to NRC generic request for add1 info re NUMBEG-0612. "Control of Heavy Loads" W/o encl DEVINCENTIS, J Public DEVINCENTIS, J Public Service Co of New Hampshire 82/09/24 KERRIGAN J B Licensing Branch J Ip 15581 143 24X Fiche 50-443.82/09/24.8210040112
- E210040193 Forwards responses to Hydrologic & Geotechnical Engineering Branch 820727 Series 240 requests for addl info. Questions 240 39 & 240 requests for addl info. Questions 240 39 & 240 41 Response to Ovestion 240 AO forthcoming DEVINCENTIS. J. Public Service Co of New Hampshire B2/09/30 KERRIGAN. J 8 Licensing Branch 3 14pp 15583 168 24X Fiche 50-443.82/09/30.8210040193
- 6210050199 Responds to Mechanical Engineering Branch 820618 request for add info Response includes "Prying Effect on Concrete Eipansion Anchor Bolts Due to Pipe Support Base Flate Flexibility" Draft responses submitted 820728 DEVINCENTIS, J Public Service Co of New Hampshire 82/09/30 KERRIGAN. J B Licensing Branch 3 3p 15609 085 24X Fiche 50-443.82/09/30,8210050199
- ---B21005D206 "Prying Effect on Concrete Expansion Anchor Bolts Due to Pipe Support Base Plate Flexibility " GALUNIC.B . MCXENNA.M . RIGAMONTIO United Engineers & Constructors, Inc (subs of Raytheon Co ) 79/07/20 88pp 15607 088 24% Fiche 50-443,82/09/30,8210050199

- 8210050393 Requests add1 info re analysis proving any challenges to class IE circuits from associated circuits do not prevent safe shutdown of plant Info re NUREG-0737, Item II E 4 2, Position A on containment isolation valves required KERRIGAN, J. Licensing Branch 3 82/10/01 TALLMAN, N.C. Public Service Co. of New Hampshire 9pp. 15608 324 24X Fiche 50-443, 82/10/01, 8210050393
- 8210070105 Forwards revised response to Guestion 440 136 re Beacter 6 Branch 820727 request for add) info concerning steam generator tube rupture DEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Harpshire 82/10/05 KERRIGAN, J B (ictnessing Branch 3 4pp 15628 074 24X Fiche 50-443, 82/10/05 02:007015
- 8210130436 Forwards revised responses to Mechanical Engineering Brail 820301 & 05 Requests for Addi Info 210 3-210 49, originally submitted in util 820421, 30 t 0510 ltrs.per 820511-13 meeting Responses will be incorporated into FSAR Amend 4/ DEVINCENTIS. J Yanker Atomic Electric Co DEVINCENTIS. J Public Service Co of New Hampshire 82/00/06 MERRIGAN.J D (Lensir) Granch 3 126pp 15681 193 24X Fiche 50-443,82/10/06.02101.N4/0
- 82]0190510 Forwards revised FSAR Section & 2 2 providing justificals: for excluding inert cover gas on sodium hydroxide storage tank info will be incorporated in Amend 48 to 0L application
  DEVINCENTIS. J. Yankee Atomic Electric Go. DEVINCENTIS. J. Public Service Co. of New Hampshire. 82/10/07 KERRIGAN, J. Licensing Branch 3 4pp. 15714-189. 24X Fiche 50-443.82/10/07, B2(1050516)
- 8210180001 Forwards notes from 820914 & 15 Instrumentation & Cantrols
  Sys Branch review meetings, per NRC 820216 & 0323 requests
  Notes also include items discussed at 820323-25,0512 & 13 &
  0715 & 14 meetings & NUREO-0737 action items
  DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Publis
  Service Co of New Hampshire 82/10/14 & RERRIGAN. J Licensing
  Branch 3 93pp 18720 031 24X Fiche 50-443,82/10/14.8210180031
- 8210280307 Requests advanced notification of scheduled NRC meetings refactities to enable ample time for Atty General Ofc to arrange for staff attendance
  KINDER.E.T. New Hampshire, State of 82/10/18 WHEELER, ( )
  Licensing Branch 3 1p 15790 069 24X Fichs 50-443, 82/10/10, 8210250307
- 8210270006 Forwards request for info re onsite audit for selamic & dynamic qualification review & pump & valve operability Completion of encl forms requested within 3 wks Specific date of audit to be mutually agreed to by NRC & applicant KERRIGAN, J D Licensing Branch 3 82/10/21 TALLMAN, H C Public Service Co of New Hampshire 25pp 15816 348 24X Fiche 50-443,82/10/21.8210270006
- 8210280117 Forwards response to Power Sys Branch & Equipment Qualification Branch 821001 Request for Add 1 Info 430 149 rs analysis on associated circuits, per 820910 & 1020-21 meetings w/NRC BEVINCENTIB. J Yanker Atomic Electric Co DEVINCENTIB, J Public Service Co of New Hampshire 82/10/26 MIRAGLIA,F J & 114003102 Branch 3 10pp 15837 130 24X Fiche 50-443.82/10/26.82102/0617
- D NRC Draft/Final Environmental Statements: supple & correspondence
- 8210120029 Forwards comments from State of NH to be included in AML 820730 itr re facilities DES W/o encl MIRAGLIA:F J Licensing Branch 3 82/08/24 TALLMAN, W C Fublic Service Co of New Hampshire ip 15689 196 24X Fiche 50-443, 82/08/24, 8210120029
- F Security, medical, emergency & fire protection plans
- 821012012B Summary of 82072O meeting w/utils & United Engineers & Constructors in Dethesda.ND re associated circuits Presentation outline & details of preliminary review & analysis of associated circuits FARR change encl KNOX.J Fower Systems Branch 82/09/24 SRINIVASAN.H Power Systems Branch 82/09/24 SRINIVASAN.H Power Systems Branch 100pp 15692 050 24X Fiche 50-443,82/09/24.8210120128
- G Adjudicatory correspondence
- 8210060194 Forwards Seacoast Anti-Pollution League objection to k motion for reconsideration of ASLB 820913 order & motion to certify objections to ASLAB 820818 erg of the seacoast Anti-Pollution BACKUS, R A Backus, R A BACKUS, R A Seacoast Anti-Pollution League 82/09/30 HOYT, H F, LUEBKE, E A., HARBOUR, J Atomic Safetr and Licensing Soard Panel 2pp 15614 220 24% Fiche 50-443, 82/09/30, 8210060194

- --8210060206 Bb jection to & motion for reconsideration of ASLB 820913 order & motion to certify objections to ASLAB Contention Suppl 4 should be admitted BACKUS.R A Seacoast Anti-Pollution League BACKUS.R A Bockus.R A 82/09/30 Atomic Safety and Licensing Board Panel 7pp 15514 222 24% Fiche 50-443,82/09/30.8210060194
- --B210060214 Affidavit of P Brown Hearings underway before appropriate state agencies re New England Electric Transmission Corp. Likew England Power Poul applications for const of transmission lines
  BROWN, P Seacoast Anti-Pollution League 82/09/30 Bpp
  [5514 227 24K Fiche 50-443, 82/09/30, 8210060194
- 8210050262 Order allowing parties to file reply to New England Coalition on Nuclear Pollution objections & motion & State of NH motion for reconsideration of ASLB 820913 memorandum & order Reply due by 821019 HOYF.H F Atomic Safety and Licensing Board Panel 82/10/01 2pp 156f0 284 24X Fiche 50-443,82/10/01.8210050262
- 8210200026 First set of interrogatories & request for documents on Contentions I A 2, I B 1, I B 2 & I C JORDAN, W S , CURRAN, D New England Coalition on Nuclear Pollution JORDAN, W S Harmon & Weiss B2/10/13 Public Service Co of New Hampshire 14pp 15755 033 24X Fiche 50~443,82/10/13,8210200026
- --8210200035 First set of interrogatories & request for documents on Contentions I A 2, I B 1. I B 2 & I C
  JORDAN, W S , CURRAND New England Coalition on Nuclear Pollution
  JORDAN, W S Harnon & Weiss B2/10/13 Office of the Executive
  Legal Director 12pp 15755 047 24X Fiche 50-443, 82/10/13.
  8210200026
- --8210200042 First set of interrogatories & request for documents on Contentions II B 1.II B 3.II R 4 & II B 5
  JORDAN, W S , CURRAN, D New England Coalition on Nuclear Pollution
  JORDAN, W S Harmon & Weiss 82/10/13 Public Service Co of
  New Hampshire 8pp 15755 059 24X Fiche 50-443,82/10/13,82/10/200024
- --B210200049 First set of interrogatories & request for documents on Contentions II B 1.11 B 3.11 B 4 & II B 5 Certificate of Svc enct
  JORDAIS, W S . CURRAN, D New England Coalition on Nuclear Pollution
  JORDANS, W S . Harmon & Weiss B2/10/13 Office of the Executive
  Legal Director 9pp 15755 067 24X Fiche 50-443, 82/10/13, 8210208026
- 8210270153 Response opposing New England Coalition on Nuclear Power objections to prehearing conference memorandum & order & motion to certify edjections to ASLAB Issues in objections already considered Certificate of Svc encl
  GAD.R K Public Service Co of New Hampshire GAD.R K Roper & Gray 82/10/26 Atomic Sefety and Licensing Board Panel 63pp 19829 327 24X Fichs 50-443,82/10/26,8210270153
- 6210270166 Response opposing State of NH objection & motion for reconsideration of ASLB 820913 order No errors committed in ruling on NM contentions ASLB should not certify rulings since certification not requested Certificate of Svc encl QAD, R K Public Bervice Co of New Hampshire GAD, R K Ropeu & Gray 82/10/26 Atomic Safety and Licensing Doard Panel 22pt 15830 117 24X Fiche 50~443,82/10/26,8210270166
- H General correspondence
- 8210120270 Requests that DR Lewis be added to svc list TAYLOR. J. Atomic 84fety and Licensing Board Panel 82/10/08 Public Service Co of New Hampshire ip 15652 317 24X Fiche 50-443, 82/10/08.8210120270
- G inspection reports, IE Bulletins & correspondence
- 8210070392 Forwards IE Insp Repts 50-443/82-09 & 50-444/82-09 on 820824-27 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs B2/09/22 TALLMAN.W C Public Service Co of New Hampshire 2pp 15433 331 24x Fichs 50-443.82/09/22 8210070392
- --8210070400 IE Insp Repts 50-443/82-09 & 50-444/82-09 on 820824-2/ No noncompliance noted Major areas inspected procedures & work activities re concrete const of reactor containment bldg dome, structural welding within containment bldg & 6A review VARELA, A A . DURR. J.P. Region 1. Office of Director 82/09/20 7pp 15633 333 24X Fiche: 50-443-82/09/22.8210070392
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds." Svc list encl. COBB.L 1. Division of Fuel Facilities, Materials & Safeguards 82/10/06 Comsolidated Edison Co of New York 66pp 15761 250 24X Fishe 50-000, 82/10/06, 8208190233

- 8208190238 IE Dulletin B2-03, "Stress Corresion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list enc! DEYGUNO, R C Director's Office. Diffice of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, D2/10/14, B208190228
- S Reportable occurrences. LERs & related correspondence
- 6210190126 Corrected version of final deficiency rept re misapplication of torquing equipment by Beloit Power Sys Initially reported on 820820 Corrective procedure provided by vendor will preclude potential problems
  DEVINCENTIS, J Yantee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/09/20 STARDSTECKI. R Division of Project & Resident Programs 2pp 15742 132 24X
  Fiche 50-443,82/09/20.8210190126
- 8210190136 Corrected version of final deficiency rept re Robertshaw Controls thermostatic valves initially reported on 820820 Corrective actions described by vendor will preclude potential problems
  DEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIS.J Public Service Co of New Hampshire 82/09/20 STARDSTECKI.R Division of Praject & Resident Programs 3pp 15742 227 24X
  Fiche 50-443.82/09/20.8210190136
- 8210190363 Final deficiency rept re cracked welds in containment annular steel and connections Initially reported on 820910 Motallurgical investigation performed welding & installation procedure revised & cracked connections replaced DEVINCENTIS. J Yanker Atomic Electric Co DEVINCENTIS. J Public Service Co of New Hampshire 82/10/12 STARDSTECKI.R Division of Project & Resident Programs 3pp 15740 321 24% Fiche 50-443.82/10/12.8210190363
- 8210240330 Interim deficiency rept re sheared pinson keys in Limitorque Model 58-0-25 motor operators Initially reported on 820902 Caused by use of inappropriate key matl Limitorque & Westinghouse continuing investigation DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hompshire 82/10/18 STAROSTECKI.R Division of Project & Resident Programs 2pp 15802 340 24X Fiche 50-443, 82/10/18, 8210260330
- 8210260149 Interim deficiency rept re power surges in solid state protection sys which may disable protection circuit Initially reparted on 820805 Item reportable based on 820806 Westinghouse Itr Final rept expected by 830115 DEVINCENTIS. J Public Service Co of New Hampshire 82/10/19 STAROSTECKI.R Division of Project & Resident Programs ip 15799 018 24X Fiche 50-443, 82/10/19, 8210260149
- DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA JUNIT 1
- A Application/construction stage documents & correspondence
- B210220513 Notification of B20913 meeting w/util in Bethesda,MD to discuss procedures generation package CLIFFORD.J W Procedures & Yest Review Branch 82/08/27 ZIEMANN,D L Procedures & Test Review Branch 2pp 15786 089 24x Fiche 50-445, B2/08/27, B210220513
- 8210210025 Summary of 820625 meeting w/util & Gibbs & Hill in Bethesda, MB re equipment qualification BURWELL.8 B Licensing Branch 1 82/09/30 Licensing Branch 1 17pp 15782 180 24% Fichs 50-445.82/09/30.8210210025
- F Security, medical, emergency & fire protection plans
- 8210040020 Releases public version of applicant motions & affidavits & State of TX emergency mgt plan FELTON, JH Division of Rules and Records 82/09/21 Document Management Branch 1p 15577 293 24X Fiche 50-445.82/09/21.8210040020
- --8210040042 Public version of State of TX emergency mgt plan.including Hood County, Somervell County & City of Olen Rose, TX emergency operations plans CLEMENTS, W D . ADAMS, J B . LANSFORD, R A Teras. State of 82/05/24 801pp 15878 269 24X Fiche 50-445,82/09/21,8210040020
- 8210070109 Forwards "Evaluation of Hood & Sommervell Counties & State of TX Radiological Emergency Plans for Comanche Peak Steam Electric Station " Offsite protection adequate Joint exercise planned for early 1983 THOMASIL IT Federal Emergency Management Agency 82/09/29 DIRCKS.W Office of the Executive Director for Operations Ip 19628 165 24X Fiche 50-445.82/09/29,8210070109

- --8210070112 "Evaluation of Hood & Sommervell Counties & State of FX Radiological Emergency Plans For Comanche Peak Steam Electric Station "
  Federal Emergency Management Agency 82/09/29 57pp 15628 166 24X Fiche 50-445,82/09/29.8210070109
- 6210130976 Forwards response to license condition on physical security program approval & pages to FBAR security plan Response & plan withheld (ref 100FR2 790 % 100FR73 21)
  GARY,R J Teras Utilities Generating Co 82/10/08 YDUNGBLOOD,B J
  Licensing Branch 1 1p 15679 060 29X Fiche 50-445.82/10/08,
  8286130576
- 6210180006 Forwards Amend 35 to FSAR consisting of Revision 5 to emergency plan GARYR J Texas Utilities Generating Co 82/10/12 DENTON, H R Diffice of Nuclear Reactor Regulation, Director 2pp 15720 1.26 24X Fiche 50-445,82/10/12.8210180006
- --821018000B Amend 35 to FSAR consisting of Revision 5 to emergency plan JONES,R A Texas Utilities Generating Co 82/10/12 199pp 15720 128 24X Fiche 50-445,82/10/12,8210180006
- B210280259 Forwards FEMA interim finding on plant offsite emergency preparedness, consisting of FEMA memo to NRC & attachments ROTHSCHILD.M V Hearing Branch | 82/10/27 MILLER.M E . COLF.R . MCCOLLOIS.K A Atomic Safety and Licensing Board Panel 59pp L5838 147 24X Fiche 50-445 82/10/27.8210280259
- G Adjudicatory correspondence
- G210040020 Releases public version of applicant motions % affidavits & State of TX emergency mgt plan FELTUN.J M Division of Rules and Records B2/09/21 Document Management Branch 1p 15577 293 24X Ficho 50-445.B2/09/21, B210040020
- B210040024 Public version of applicant motion for summary disposition
  of intervenor Citizens Assoc for Sound Energy Contention 22
  re emergency planning
  SANFORD, J C Texas Utilities Generating Co SANFORD, J C
  Debevoise & Liberman 82/08/23 Atomic Safety and Licensing
  Board Panel 16pp 15577 294 24X Fishe 50-445,82/09/21,
  B210040020
- --2210040026 Public version of statement of matl facts not genuinely at issue re emergency planning \* Teras Utilities Generating Co 82/08/23 Atomic Safety and Licensing Board Panel 5pp 15577 310 24% Fiche 50-445, 82/09/21
- --8210040030 Public version of affidavit of RA Jones re intervenor Citizens Assoc for Sound Energy Contention 22 concerning energency planning JONES.R A Texas Utilities Generating Co. 82/08/20 lipp 15577 315 24X Fiche 50-445, 82/09/21, 8210040020
- --B210040033 Public version of BT Lancaster affidavit re intervenor Citizens Assoc for Sound Energy Contention 22 concerning energency plan exercises & drills LANCASTER.B T Tesas Utilities Generating Co B2/0B/20 7pp 15577 324 24X Fiche 50-445, B2/09/21, B210040020
- --8210040037 Public version of affidavit of RE Linnemann re intervenor Cititens Assoc For Sound Energy Contention 22 conterning sycs of medical personnel for radiation emergencies U/resumes, notice of appearance & Certificate of Syc LINNEMANN, RE Texas Utilities Generating Co LINNEMANN, RE Radiation Hanagement Corp 82/08/20 21pp 15577 333 24X Fiche 50-445.82/09/21.8210040020
- --8210040042 Public version of State of TX emergency mgt plan,including Mood County, Somervell County & City of Olen Rose, TX emergency operations plans CLEMENTS, W D . ADAMS, J B . LANSFORD, R A Texas, State of 82/05/24 801pp 15578 267 24X Fiche 50-445,82/09/21,8210040020
- 82t0040089 Order denying NRC 820824 request for reconsideration of ASIM B20804 order to show cause re NRC failurs to disclose identity of informants Ltr-designated individuals 8 K must be identified MILLERIME Atomic Safety and Licensing Board Panel 82/09/30 Office of the Executive Logal Director 14pp 15586 001 24X Fiche 50-445, 82/09/30, 8210040089

- 8210130299 Brief on status of record re findings needed for docision, per ASLB 820922 memorandum & order ABLB should close record on all issues.order prompt submittal of proposed findings & issue decision Certificate of Svc enci REYNOLDS.N S . HORIN.W A Teras Utilities Generating Co REYNOLDS.N S . Debsooise & Liberman 82/10/08 35pp 19678 205 24X Fiche 50-445.82/10/08.8210130299
- 82(01501B3 Forwards exceptions to ASLB 820930 order denying reconsideration, filed per 10CFR2 782(a) Motion seeking stay of effectiveness of order to be filed on 82(012 M/o enc! TURK, S E Hearing Branch 1 82/10/08 SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 2pp 15707 178 24X Fiche 50-445, 82/10/08, 82(0150183
- 8210150366 Exceptions to ASLB B20930 order denying reconsideration of ASLB B20804 order to show cause why sanctions should not be imposed on NRC for failure to disclose informants Certificate of Svc encl TURK, S E Hearing Branch 1 82/10/08 Atomic Safety and Licensing Appeal Panel 7pp 19704 307 24X Fiche 50-445,82/10-6210150346
- 6210150224 Response to ASLB 820922 memorandum & order for brisfs on necessary documents & info to close evidentiary record Certificate of Svc encl ELLIS. J. Citizens Association for Sound Energy 82/10/09 6(Ipp 19705-286 24X Fiche 50-445,82/10/09,8210150224
- B210130292 Responds to ASLB 820922 memorandum & order re record stat ASLB should close record on Contention 22 & Contention 5 w/exception of portions on issues of Board Notification 62-90 & Malsh/Doyle allegations M/Cortificate of Svc ROTHSCHILD.M U . MIZUNO.0 B Hearing Branch 1 82/10/11 3ipp 15678 102 24X Fiche 50-445.62/10/11.6210130292
- 8210150124 Application for stay of effectiveness of ASLB 620930 ordinarying reconsideration ruling that NRC did not show good cause for failure to comply w/orders to disclose informants 3 ordering disclosure Certificate of Svc encl
  TURK S E Hearing Branch 1 82/10/12 Atomic Safety and Licensing Appeal Panel 13pp 15698 001 24X Fiche 30-449, 82/10/12, 8210150124
- B2:0150464 Notice of ASLAB constitution AS Rosenthal, chairman & MR Johnson & TS Moore, members SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 82/10/. ip 15703 105 24X Fishe 50-445,82/10/12,8210150464
- 8210250104 Response to ASLB directive re Citizens Assoc for Dound Energy exhibits Requests listed documents from Assoc Exhibits 1900-449 be accepted into evidence Certificate of Svc encl Related correspondence ELLIS.J Citizens Association for Sound Energy 82/10/10 5/1pp 15792 089 24% Fiche 50-445,82/10/18,8210250104
- 8210280355 Motion for reconsideration of ASLB ruling relatehments
  J Dowle deposition/testimony Clean copies of drawings will
  be provided, but intervenor should be allowed to ref
  documents Certificate of Svc encl Related correspondence
  ELLIS. J Citizens Association for Sound Energy 82/10/23 At
  Safety and Licensing Board Panel 8pp 15839 001 24X
  Fiche. 30-445, 82/10/23, 8210280355
- 8210280259 Forwards FEMA interim finding on plant offsite emergenty graparedness consisting of FEMA memo to NRC & attachments ROTHSCHILD, M U Hearing Branch i 82/10/27 MILLER, M L . CDif, MCCOLLOM, K A Atomic Safety and Licensing Board Panel. 59pp i5808.147 24X Fiche 50-445,82/10/27,8210280259
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8210180006 Forwards Amend 35 to FBAR consisting of Revision 5 to emergency plan GARY, R.J. Texas Utilities Generating Co. 82/10/12 DENTON, H & Office of Nuclear Reactor Regulation, Director 2pp 13720 1. A 24X Fiche 50-445
- --8210180008 Amend 35 to FSAR consisting of Revision 5 to smergency JONES.R A Texas Utilities Generating Co 82/10/12 199pp 15720 128 24X Fiche 50-445,82/10/12.8210180006
- Q Inspection reports. IE Bulletins & correspondence
- 8210070364 Forwards IE Insp Rept 50-445/82-20 on 820801-31 No noncompliance noted MADSEN/O L. Division of Resident, Reactor Project & Engineering Programs 82/09/22 OARY, R. J. Texas Utilities Generating Co 15634 040 24X Fiche 50-445, 82/09/22, 8210070364

- --8210070369 IE Insp Rept 50-445/82-20 on 820801-31 No moncompliance noted Major areas inspected preoperation test review procedure.plant tour & status KELLEY. D. L., WESTERNAN. T. F. Division of Resident, Reactor Project & Engineering Programs 82/09/17 Spp 15634 042 24X Fiche 50-445.82/09/22.8210070364
- 6210190816 Forwards IE Insp Rept 50-445/82-14 on 820803-20 No noncompliance noted MADEEN, G. L. Division of Resident, Reactor Project & Engineering Programs 82/09/27 GARY, R. J. Texas Utilities Generating Co. 2, 15736 139 24X Fiche 50-445,82/09/29,8210190816
- --8210190920 IE Insp Rept 50-445/82-14 on B20803-20 No noncompliance noted Major areas inspected pipe whip restraints & licensee method of QC insp of skewed wolds STEWART, R C . TAYLOR.R O . WESTERMAN, T F Division of Resident, Reactor Project & Engineering Programs 82/09/28 App 15736 141 24X Fiche 50-445,82/09/29,8210190816
- G210190772 Forwards IE lnsp Repts 50-445/B2-18 & 50-446/B2-09 on B20907-10 No noncompliance noted MADBEN, G L Division of Resident, Reactor Project & Engineering Programs B2/10/01 OARY, R J Texas Utilities Generating Co 2pj 15737 128 24X Fiche 50-445,82/10/01,8210190772
- --8210190776 IE Insp Repts 50-445/82-18 & 50-446/82-09 on 820907-10 No noncompliance noted Major areas inspected const activities. including site tour observation of welding eram of safety-related piping & welding on main control panels GILBERT.L D . TOM.INSON.D P . MESTERMAN.T F Division of Resident, Reactor Project & Engineering Programs 92/09/29 ip 15737 130 24X Fiche 50-445,82/10/01,8210190772
- 9209190233 IF Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Fac: lities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York & App 157&1 200 24X Fiche 50-000, 82/10/06, 8208190233
- 8208190238 IE Bulletin 92-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation SysPiping at BMR Plants " Svc list encl
  DEYOUNG, RC Director's Office, Office of Inspection and
  Enforcement 82/10/14 Consolidated Edison Co of New York
  115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208170238
- S Reportable occurrences. LERs & related correspondence
- 821004031B Interim deficiency rept re-conduit supports Initially reported on 820822 Evaluation continuing Completion anticipates by 821082

  OARY.R J Texas Utilities Generating Co. 82/09/20 MADSEN, 8 L. Bivision of Resident, Reactor Project & Engineering Programs 1, 15386-167 24% Fiche 50-445.82/09/20.8210040318
- 8210260375 Deficiency rept re overtorquing of safety-relief Valves Initially reported on 820910 Evaluation in progress & will be completed by 821130 OARY.R J Texas Utilities Generating Co 82/10/Q6 MADSEN.G L Division of Resident, Reactor Project & Engineering Programs | Ip 15803 362 24X Fiche 50-445.82/10/06/8210260375
- 821025033B Interim deficiency rept re defective Limitorque pinion kege Initially reported on 820818 Matter not reportable per 10CPR50 55(e) based on investigation QARY.R J Texas Utilities Generating Co 82/10/12 MADSEN, G L Bivision of Resident, Reactor Project & Engineering Programs In 15790 331 24X Fichs 80-445.82/10/12.821025033B
- 8210250346 Interim deficiency rept re linear indications identified in diesel generator auxiliary skid Initially reported on 820707 Evaluation continuing Next rept expected by 821217 GARV.R J Texas Utilities Generating Co 92/10/14 MADSEN, 0 L Division of Resident, Reactor Project & Engineering Programs Ip 15790 336 24X Fiche 50-445.82/10/14.8210250346.
- BOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA . UNIT 2
- A Application/construction stage documents & correspondence
- S210220513 Notification of 820913 meeting w/util in Bethesda, MD to discuss procedures generation package CLIFFORD, J W Procedures & Test Review Branch 82/08/27 ZIEMANN, D L Procedures & Test Review Branch 2pp 15786 089 24X Fichs. 50-445, 82/08/27, 8210220513
- 8210210025 Summary of 820625 meeting w/util & Gibbs & Hill in Bethesda, MB Te equipment qualification. BURMELL.6 B. Licensing Breach 1 82/09/30 Licensing Breach 1 17pp 15782 180 24X Fiche.30-445,82/09/30,8210210025.

- F. Security, medical, emergency & fire protection plans
- 8210040020 Releases public version of applicant motions & affidavith & State of TX emergency mgt plan FELTON. J H Division of Rules and Records 82/09/21 Document Management Branch [p 15577 293 24% Fiche 50-445.82/09/21, 8210040020
- --B210040042 Public version of State of TX emergency mgt plan, ancluding Hood County, Somervell County & City of Glen Rose, TX emergency operations plans CLEMENTS, M.D., ADAMS, J.B., LANSFORD, R.A. Texas, State of B2/05/24 801pp 15578 269 24X Fiche 50-445,82/09/21,8210040020
- B210070109 Forwards "Evaluation of Hood & Sommervell Counties & State of TX Radiological Emergency Plans for Comanche Peak Steam Electric Station " Offsite protection adoquate Joint exercise planned for early 1983
  THOMAS, L M Federal Emergency Management Agency 82/09/29
  DIRCKS, W Office of the Executive Director for Operations 1p 15628 165 24% Fiche 50-445, 62/09/29, 8210070109
- --B210070112 "Evaluation of Hood & Sommervell Counties & State of IX Radiological Emergency Plans for Comanche Peak Steam Electric Station" \* Federal Emergency Management Agency 82/09/29 57pp 13628 166 24x Fiche 50-445,82/09/29,8210070109
- B210130576 Forwards response to license condition on physical security program approval & pages to FSAR security plan Response & plan withheld (ref 10CFR2 790 & 10CFR73 21)

  OARY, R. J. Teras Utilities Generating Co. B2/10/08 YQUNGBLQDD: B. J. Licensing Branch 1 ip 15679 060 24X Fiche 50-445, 82/10/08.
- B210180006 Forwards Amend 35 to FSAR consisting of Revision 5 to emergency plan GARY, R. J. Tezas Utilities Generating Co. 82/10/12 DENTON, H. R. Office of Nuclear Reactor Regulation. Director 2pp. 15720-126 24X Fiche 50-445,82/10/12,8210180006
- --8210180008 Amend 35 to FSAR consisting of Revision 5 to emergency plan JONES R A Texas Utilities Generaling Co 82/10/12 199pp 15720 128 24X Fiche 50-445, 82/10/12/8210180006
- 8210280259 Forwards FEMA interim Pinding on plant offsite emergency preparedness, consisting of FEMA memo to NRC & attachments ROTHSCHILD, M U Hearing Branch 1 82/10/27 MILLER, M E Atumic Safety and Licensing Board Panel 59pp 15838 147 24X Fiche 50-445, 82/10/27, 8210280259
- G Adjudicatory correspondence
- 8210040020 Releases public version of applicant motions & affidavity & State of TX emergency mgt plan FELTON.J M Division of Rules and Records 82/09/21 Document Management Branch 1p 15577 293 24X Fiche 50-445.82/09/21.8210040020
- --8210040024 Public version of applicant motion for summary disposition of intervenor Citizens Assoc for Sound Energy Contention 22 re emergency planning SANFORD. J C Texas Utilities Generating Co SANFORD. J C Debevoise & Liberman 82/08/23 Atomic Safety and Licensing Board Panel 16pp 15577 274 24X Fiche 50-445,82/09/21,8210040020
- --B210040026 Public version of statement of matl facts not genuinely at issue re emergency planning

  \* Texas Utilities Generating Co B2/08/23 Atomic Befety and
  Licensing Board Panel 5pp 15577 310 24X Fiche 50-445,
  B2/09/21.8210040020
- --8210040030 Public version of affidavit of RA Jones re intervenor Citizens Assoc for Sound Energy Contention 22 concerning emergency planning JONES.R A Texas Utilities Generating Co. 82/08/20 | Tipp 15977:315 24X Fiche 50-445,82/09/21.8216040620
- --8210040033 Public version of BT Lancaster affidavit re intervenor Citizens Assoc for Sound Energy Contention 22 concerning emergency plan exercises & drills LANCASTER.B T Texas Utilities Generating Co 82/08/20 7pp 15577 326 24X Fiche 50-445, 82/09/21, 8210040020

- --8210040037 Public version of affidavit of RE Linnemann reintervenor Citizens Assoc for Sound Energy Contention 22 concerning syes of medical personnel for radiation emergencies W/resumes, notice or appearance & Certificate of Sye Linnemann, R E Totas Utilities Generating Co. Linnemann, R E Radiation Management Corp. 82/08/20. 21pp. 15577-333. 24% Fiche 50-445,82/09/21.8210040020
- 8210040089 Order denying NRC 820824 request for reconsideration of ASLN 820804 order to show cause to NRC failure to disclose identity of informants Ltr-designated individuals 8 K must be identified MILLER. ME Atomic Safety and Licensing Board Panel 82/09/30 Office of the Executive Legal Director 14pp 1558) 001 24X Fichs 50-445, 82/09/30, 8210040089
- 8210130299 Brief on status of record re findings needed for decision, per ASLD 820922 memorandum & order ASLB should close record on all issues, order prompt submittal of proposed findings & issue decision Certificate of Svc enci RENOUDS.N S . HORIN.W A Teras Utilities Generating Co REVICLOS.N S . Debevoise & Liberman 82/10/08 35pp 15678 205 24x Fiche 50-445.82/10/08.8210130299
- 8210150183 Forwards exceptions to ASLB 820930 order denying reconsideration, filed per 10CFR2 762(a) Motion seeking stay of effectiveness of order to be filed on 821012 W/o encl TURKIS E Hearing Branch 1 82/10/08 SHOEMAKER, C. J. Atomis Sarety and Licensing Appeal Panel 2pp 15707 178 24X Fiche 50-445, 82/10/08, 8210150183
- 8210150346 Exceptions to ASLB 820930 order denying reconsideration of ASLB 820804 order to show cause why sanctions should not be imposed on NRC for failure to disclose informants. Certificate of Svc encl 100K, S E Hearing Branch 1 82/10/08 Atomic Safety and Licensing Appeal Panel 7pp 15704 307 24X Fiche 50-445,82/10/08,6210150346
- 8210150224 Response to ASLB 820922 memorandum & order for briefs on necessary documents & info to close evidentiary record Certificate of Svc enc! ELLIS. J Citizens Association for Sound Energy 82/10/09 60pp 15705 286 24X Fiche 50-445.82/10/09.8210150224
- 8210130272 Responds to ASLB 820722 memorandum & order re record status ASLB should close record on Contention 22 & Contention 5 w/exception of portions on issues of Board Notification 82-90 & Walsh/Doyle allegations W/Certificate of Syc 80THSCHILD.M V , MIZUND.G 5 Hearing Branch 1 82/10/11 33pp 15678 102 24% Fiche 50-445,82/10/11.8210130292
- 8210150124 Application for stay of effectiveness of ASLB 820930 order denying reconsideration, ruling that NRC did not show good cause for failure to comply w/order» to disclose informants & ordering disclosure Certificate of Svc encl
  TURK, S E Hearing Branch 1 82/10/12 Atomic Safety and Licensing Appeal Panel 13pp 15698 Out 24x Fiche 50-445, 82/10/12,8210150124
- 8210150464 Notice of ASLAB constitution AS Rosenthal, chairman & MR Johnson & TS Moure, members SHOEHAKER, C. J. Atomic Safety and Licensing Appeal Panel 82/10/12 to 15703 105 24X Fiche 50-445.82/10/12.8210150464
  - SLB directive re Citizens Assoc for Sound
    \* "jated documents from Assoc
    ted into evidence Gertificate of
    dence
    ton for Sound Energy 82/10/18 55pp
- v page deposition/testimony Clean copies of drawings will be provided but intervenor should be allowed to ref documents Certificate of Svc encl Related correspondence ELLIS, J. Citizens Association for Sound Energy 82/10/23 Atomic Safety and Licensing Beard Panel 8pp 15839 001 24x Fiche 50-445.82/10/23.8210280355
- 8210280259 Forwards FEMA interim finding on plant offsite emergency preparedness, consisting of FEMA memo to NRC & attachments ROTHSCHILDIN U Hearing Branch 1 82/10/27 MILLER, M E . COLE, N . MCCGLON, K A Atomic Safety and Licensing Board Panel 39pp 15838 147 24% Fiche 50-445.82/10/27.8210280259
- K Utility Fina! Bafety Analysis Report (FSAR) & amends

1

8210180006 Forwards Amend 35 to FBAR consisting of Revision 5 to emergency plan GARY.R J Texas Utilities Generating Co 82/10/12 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 15720 126, 24X Fichs 50-445, 82/10/12, 8210180006

- --8210180008 Amend 35 to FSAR condisting of Revision 5 to energer() JUNES, R Terms Utilities Generating Co 82/10/12 19/pp 15720 128 24X Fiche 50-445, 82/10/12, 8210180006
- a inspection reports. IE Bulletins & correspondence
- 8210190772 Forwards IE (nsp. Repts. 50-445/82-18 & 50-446/82 07 gm 820907-10 No noncompliance noted MADSEN.G L Division of Resident, Reactor Project & Engineering Programs 82/10/01 GARV.R J Texas Utilities Generating Co vi
- --B210190776 IE Insp Repts 50-445/B2-18 & 50-446/B2-09 on g2000/15 to noncompliance noted Major areas inspected const activities including site bour observation of welding exam of safety-related piping & welding on main control panels of LBERTIL D., TOMLINSON, D.P., WESTERMAN, T.F. Division of Relification of Relific
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Divilodged 1-ff? Implant Seeds " Svc list encl CO86.L I Division of Fuel Facilities, Natorials & Safeguerds 82/10/06 Consolidated Edison Co of New York 6660 15/64 47 24% Fiche 50-000, 82/10/06, 8208190233
- 8208170238 IE Bulistin 82~03, "Stress Corrosion Cracking in Thirl-Wall, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BWR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 11550 15810 125 248 Fichs 50-000, 82/10/14 20208190210
- S Reportable occurrences. LERs & related correspondence
- B21004031B Interim deficiency rept to conduit supports Initially reported on B20825 Evaluation continuing Completion anticipated by B21032 GARY.R J Texas Utilities Cenerating Co. B2/09/20 MADIAN. Ut. Bivision of Resident. Reactor Project & Engineering Program 1, 15565-167 24X Fiche 50-445.82/09/20.8210040318
- 8210240375 Deficiency rept no overtorquing of safety-relief calver Initially reported on 820910 Evaluation in progress & uit1 be completed by 821130 OARY:R J Texas Utilities Generating Co 82/10/06 HADM. G I Division of Resident. Reactor Project & Engineering Programs I 15803 362 24X Fiche 50-445,82/10/06.8210260375
- 82(0250338 Interim deficiency rept re defective Limitorque pinium keys Initially reported on 820818 Matter not reportable per 10CFR50 55(e) based on investigation OARY.R J Texas Utilities Generating Co 82/10/12 HABBIN G 1
- 8210250346 Interim deficiency rept re linear indications identified in diesel generator auxiliary skid Initially reported on 820709 Evaluation continuing Next rept expected by 821217 CARY, R. J. Texas Utilities Generating Co. 82/10/14 MADNEN Q L. Division of Resident, Reactor Project & Engineering Programs 15790 336 24X Fichs 50-445,82/10/14,8210250346

#### DOCKET STN-50-447 GESSAR-238

- A Application/construction stage documents & correspondence
- 8207120147 Forwards NEDG-21471-01: "Analytical Model for Estingth Drag Forces on Rigid Submerged Structures Caused by LOCA & Safety Relief Valve Ramshead Air Discharges, Suppl for X-Quencher Air Discharges "
  BUCHHOLZ, R H General Electric Co 80/06/18 PARR, D D L14 mming Branch 3 1p 13808-001 24X Fiche 50-447, 80/06/18, 8207120142
- --8207120283 "Analytical Model for Estimating Drag Forces of Rigid Submerged Structures Caused by LOCA & Safety Relief Valve Ramshead Air Discharges, Suppl for X-Guencher Air Discharges " LASHER, LE , TOWNSEND, HE , ROSERS, A E General Electric Co NEDD-21471-01 801 79/10/31 11pp 13808 002 24X Ficht 50-447,80/06/18,8207120147
- 8210040380 Notification of 820923 meeting w/OE in Bathesda, MD for Technical Update Meeting 4 on 0688AR-II probabilistic ries assessment LYNCH. N D Licensing Branch 2 82/09/17 THOMAS, C O Standardization & Special Projects Branch 4pp 15597 207 28x Fiche 50-447, 82/09/17, 8210040380.

- 8210050398 Forwards Amend 7 to application for final design acceptance review of OESBAR-238, correcting typographical errors & clarifying discrepancies in portions of Chapters 1.3.4.6 & 15
  VILLAR General Electric Co 82/09/23 EISENHUT.D @ Division of Cicensing 1p 15777 001 24X Fishe 50-447.82/09/23, 8210050398
- --8210050408 Amend to application for final design acceptance review of OESSAR-238, correcting typographical errors & clarifying discrepancies in portions of Chapters 1.3,4.6 & 15 VILLA: R Openeral Electric Co. 82/07/23 4pp 15777 002 24X Fiche 50-447,82/09/23,8210050398
- --8210220174 Amend 7 to GESSAR II \* General Electric Co 82/09/23 259pp 15777 004 24X Fiche 50-447,82/09/23,8210050398
- 8210050328 Submits GE understanding of major agreements & ground rules re NRC review of GESBAR II. in response to NRC request at 820915 meeting Concurrence requested SHERHOOD. 9 General Electric Co 82/10/01 EISENHUT. D 9 Division of Licensing 2pp 15610 252 24X Fiche 50-447.82/10/01.8210050328
- 8210220468 Notification of 821015 meeting w/util to discuss inclusion of external events in probabilistic risk assessment review LYNCH.M D Licensing Branch 2 82/10/07 THOMAS, C Standardization & Special Projects Branch 3pp 19786 204 24X Fiche 50-447, 82/10/07, 8210220468
- 8210220463 Notification of 821015 meeting w/wtil to discuss major issues identified in probabilistic risk assessment & impact on review schedule Lynch, M D Licensing Branch 2 82/10/08 THOMAS.C Standardization & Special Projects Branch 3pp 15786-207 24X Fiche 50-447, 82/10/08, 8210220463
- 021027004A Forwards Amend 8 to DESSAR II, responding to NRC 811203 acceptance review ltr re geotechnical, radiation sources & failure mode & effects analysis & committing applicant to address NRC acceptance criteria SHERMOOD, 0 G General Electric Co 82/10/18 EISENHUT, D 9 Division of Licensing 2pp 15814 001 24X Fiche 50-447,82/10/18, pp. 1021027004A
- --B210270051 Amend 8 to 238 GEBBAR II application for review responding to NRC 811231 questions re geotechnical radiation sources & failure mode & effects analysis & committing applicant to address NRC acceptance criteria VILLAIR General Electric Co 82/10/18 345pp 15816 003 24% Fiche 50-447.82/10/18.8210270046
- K Utility Final Bafety Analysis Report (FSAR) & amends
- B21005039B Forwards Amend 7 to application for final design acceptance review of OESBAR-23B, correcting typographical errors & clarifying discrepancies in portions of Chapters 1, 3, 4, 6 & 15
  VILLA, R. General Electric Co. 82/09/23 E186NHUT, D. Q. Division of Licensing ip 15777 OOI 24X Fiche 50~447, 82/09/23, 8210050398
- --0210220174 Amend 7 to GEBSAR II # General Clactric Co 62/07/23 259pp 15777 006 24X Fiche 50-447,82/09/23,8210050378
- DOCKET STN-50-454 BYRON STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8210010271 Forwards five oversizes P&IDs referred to in util 820909 ltr to NRC re waterhammer prevention. Aperture cards are available in PDR TRAPHLT R Commonwealth Edison Co 82/09/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15573 122 24X Fiche 50-000, 82/09/22, 8210010271
- 8210080313 Bummary of 820708 & 07 meetings w/utils, Sargent & Lundy, Aprojet Energy Conversion Co & Rockford League of Women Voters in Chicago.IL & at plant site re vol reduction sys Guestions re Topical Rept AECC-2-P encl KIPER, K.L. Licansing Branch 1 82/09/23 Licensing Branch 1 12pp 15663 341 24X Fiche 80-454.82/09/23,8210080313
- 8210050123 Submits final quarterly rept re const completion date Unit 1 const & testing schedule still keyed to fuel loading on 830831 DELOECROE.L.O Commonwealth Edison Co. 82/09/27 DENTON.H R Defice of Nuclear Reactor Regulation, Director. 1p 15605 170 24X Fiche 30~434,82/09/27.8210030123

- 8210280429 Forwards addit question re vol control sys, in response to applicant answer to NRC Question 9321 43 Response requested within 30 days
  YOUNOBLOOD, II J Licensing Branch 1 92/10/04 DELCEGREE, LO Commonwealth Edison Co 3pp 15960 042 24X Fishe 50-000.82/10/04 8210280629
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" GOLDEN.J C Commonwealth Edison Co 82/10/06 CASE.E G Offsice of Nuclear Reactor Regulation, Director 2pp 15805 137 24x Fiche 50-000, 82/10/06.8210260526
- --8210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual "
  • Commonwealth Edison Co 82/09/30 83pp 15805 139 24x Fiche 50-000, 82/10/06.8210260526
- 8210/280420 Forwards request for addlinfore venting of high points in RCS.method of depressurization to cold shutdoun & depressurization following steam generator tube rupture events Response requested within 30 days YOUNOBLOOD, B J Licensing Branch | 82/10/07 DELGEORGE, L O Commonwealth Edison Co. 4pp. 15060 009 24x Fiche 50-000.82/10/07, 2010/280420
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8210010202 Submits add1 info re reactor coolant pump locked rotor by shaft break transients at facilities Info closes
  Confirmatory Issue 34 of Byron 5ER
  TRAMM.TR Commonwealth Edison Co. 82/09/22 DENTON.HR Office
  of Nuclear Reactor Regulation, Director 4pp 15568 073 24X
  Fiche 50-000 82/09/22 8210010202
- 8210250108 Forwards revised FSAR info re protection against possible turbine missiles Revisions to turbine missile analysis rept encl Info closes out SER Outstanding Item 2

  TRAMM.T R Commonwealth Edison Co 82/10/19 DENTON.H R Office of Nuclear Reactor Regulation, Director 15pp 15789 296 24X Fiche 50-000, 82/10/19, 8210250108
- F Security, medical, emergency & fire protection plans
- B210270363 Forwards list of deviations from Chemical Engineering Branch Technical Position 9 5 i re fire protection program Deviations listed include lighting & communication & hydrogen line routing Justification of deviations requested YOUNOBLOOD, B J Licensing Branch 1 82/10/05 DELGEORGE. L C Commonwealth Edison Co 7pp 15865 240 24% Fiche 50-000 B2/10/05, B210270363
- 8210130376 Advises that installation of offsite dose calculation syprogram fully operational tracking model & operational A model will be delayed until 821231 to complete prime computer installation SWARTZ,E D Commonwealth Edison Co 82/10/06 DENTON,M R Dffice of Nuclear Reactor Regulation, Director 2pp 15682 098 24X Fishe 50-000,82/10/06,8210130376
- 8210130370 Forwards Revision 7 to modified amended security plan Revision withheld (ref 10CFR2 790 & 10CFR73 21) DELOEDROEL D Commonwealth Edison Co 82/10/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 15680 323 24X Fiche 30-454,82/10/08,8210130370
- B210290047 Releases public version of revisions to Quad Cities, Zion & Dresdem emergency plan annexes & revised generating station emergency plan telephone directory FELTON. J M Division of Rules and Records 82/10/08 Document Management Branch 1p | 15877 313 24X Fiche 50-000, 82/10/08, 8210290047
- --B210290060 Forwards public version of Revision 3 to Quad Cities & Zion wergency plan annexs. Revision 2 to Dresden emergency plan annex. Revision 0 to Byron emergency plan annex & revised generating station emergency plan telephone directory MOGRE, R D Commonwealth Edison Co B2/07/30 DENTON.H R NRC No Detailed Affiliation Given 5pp 15877 314 24X Fichs 50-000,82/10/08.8210290047
- --8210290077 Public version of Revision 3 to Quad Cities & Zion emergency plan annexes. Revision 2 to Dresden emergency plan annex & Revision 0 to Hyron emergency plan annex & Commonwealth Edison Co 82/06/30 325pp 15877 319 24X Fiche 50-000,82/10/08,8210290047
- --821029008B Public version of revised generating station emergency plan telephone directory QALLE, D.P. Commonwealth Edison Co. 82/08/12 43pp 15878 218 24% Fiche. 50-000, 82/10/08, 8210290047

02:10220359 Provides info re organization & performance of depts responsible for radiation protection activities.per 820702 cornstment Training coordinator assigned in Apr 1982 to rormschent (Falning Coordinator assigner in manner the Health physics training programs TRAMM. TR Commonwealth Edison Co. 82/10/14 or Nuclear Reactor Regulation. Director 7pp Tiche 50-000. 82/10/14 8210220358 |rams | 82/10/14 DENTON, H. R. OFFICE 15776 207

### G Adjudicatory correspondence

- 6210050391 Motion for clarification of portions of ASLB 620910 memorandum to order ruling on motions for summary disposition of certain contentions Certificate of Svc encl Related of certain contentions occurrences
  correspondence
  BIELAMSKI, A P Commonwealth Edison Co BIELAMSKI, A P Isham,
  Lincoln & Beale B2/09/28 Atomic Safety and Licensing Board
  Panel 6pp 1560B 225 24x Fiche 50-454, 82/09/28, 8210050391
- 8°100a0182 Confirms 820928 telcon.in which NRC withdrew Interrogatories 77~1 & 77~2 based on withdrawn Contention 70 Answers to 77-[ 6 77-2 based on ulthdrawn Lontention /9 Answers to remaining interrogatories due by B21015 RAWSON R J Hearing Branch 4 82/10/04 ROSE, B Cherry M M /Cherry Flynn & Kanter ROSE, B League of Homen Voters of Roctford, IL 1p 15614 120 24x Fiche 50-454,82/10/04,8210060182
- A210070127 Motion for leave to file answers to util amended second round of interrogatories E day late

  ROSE.3 League of Women Voters of Rockford, IL ROSE.B Cherry, M

  M /Cherry Flynn & Kanter 82/10/05 Atomic Safety and Licensing

  Board Panel 2pp 15627 084 24X Fiche 50-455,82/10/05,8210070127
- -8210070129 Answers to amended second round of interrogatories Certificate of Svc encl RGSE.B League of Homen Voters of Rockford, IL ROSE, B Cherry, M M /Cherry, Flynn & Konter 82/10/05 Commonwealth Editon Co 344pp 15627 086 24x Fiche 50-454,82/10/05,8210070127
- 8210130373 Response opposing Detail Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 820923 motion to Energy Stanissippi Alliance For Environ 820743 motion to reconsider stammary disposition of Contention 1 on 04/00 New info would not change decision W/Certificate of Svc MILLER.M I Commonwealth Edison Co MILLER.M I Isham, Lincoln & Beate 92/10/08 Abomic Safety and Licensing Board Panel Lipp 15680 247 24X Fiche 50-454.82/10/08.8210130373
- tell0130095 Response supporting applicant 820928 motion for clarification of portion of ASLB 820910 memorandum % order denging NRC & applicant motions for summary disposition Litigable issues should be delineated M/Certificate of Svc GULDBERO, S C Hearing Branch 4 82/10/12 Atomic Safety and Licensing Board Panel Spp [5673-110 24X Fiche 50-454.82/t0/l2, 8210130095
- 8210150087 Response opposing Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 820923 motion for reconsideration of susmary disposition of Contention [th] Introduction of new facts not allowed W/Certificate of Svc GULOBERG, S.C. Hearing Branch 4 82/10/12 Atomic Safety and Licensing Board Panel 14pp 15701 200 24X Fiche 50-454,82/10/12,8210150087
- 5210150383 Memorandum & order ruling on applicant disclosure obligations Applicant 820827 motion requesting mod of ASLB 820726 memorandum & order denied Relevant or new info must
  ovided, per Commission precedents
  Atomic Safety and Licensing Board Panel 82/10/12
  6dison Co 7op 15704 058 24X Fiche 50-454,

- --8210180146 Affidavit of LA Bowen Util does not intend to install 17: sensors on feedwater bypass sys piping Existence of conflant feedwater flow procludes water hammer event similar to event at Krsko event at Mrsko BONEN, L A Commonwealth Edison Co 92/10/05 34pp 19719 : 4 24% Fiche 50-454,82/10/14,8210180142
- 8210180166 Confirming order canceling 821014 prohearing confirence Jan Rockford, IL Discovery gragiess discussed during 921014 talcon
  - talcon MARGULIES, M B Atomic Safety and Licensing Board Page ( 02/10/15 in 15719 168 24% Fiche 50-454,82/10/15,8210180166
- 8210180170 Order granting Rockford League of Women Voters motion # cicisor/o under granting Rockford League of Women Voters motion & leave to file instanter answers to util amended second round of interregatories 1 day late
  HAROULIES,N B Atomic Safety and Licensing Board Panel 82/10/1\*
  League of Women Voters of Rockford/IL 19 15749 165 248 Fiche 50-454, B2/10/15, B210180170
- 8210210274 Answers to first set of interrogatories, pursuant to A'+5 821020 memorandum & order Verification & Proof of Syc encl Related correspondence League of Women Voters of Rockford, IL JOHNSON B League of Homen Voters of Rockford, IL 192/19/15 Drfice of the Executive Legal Director 48pp 157(6 170 14x fiche 50-454, 82/10/15,8210210274
- 82(02)0278 Reply to amended first request for production of doct\*;-|| Proof of Svc encl Related correspondence Proof or Sec enci Kelatea correspondence
  ROSE, B. League of Homen Voters of Rockford, IL ROSE, D. (herry "
  M./Cherry, Flynn & Kanter 82/10/15 Office of the flecutise
  Legal Director 3pp 15745 150 24X Fiche 50-454, 82/10/15. 0210210270
- 8210210384 First interrogatories & request for documents Proof of S. ROSE/B League of Homen Voters of Rockford, IL ROYE, D Charty M H /Cherry, Flynn & Kanter B2/10/15 Commonwealth Egison C. 22pp 15764 016 24% Fiche 50-454.82/10/15.8210210104
- 6210210346 Motion for leave to file reply to new matters resert by applicant & NRC in response to Alliance motion to applicant & NRC in response to Alliance motion to reconsider disposition of Contention 1 re 64 & 6C
  CASSEL.D W DeKalb Area Alliance for Responsible Introgue CASSELL.D W Simissippi Alliance for the Environment (4M+)
  82/10/18 Atomic Safety and Licensing Board Panel to 19764 210 24X Fiche 50-454,82/10/18.8210210346
- --8210210347 Reply to new matters raised by applicant & NR( in resp.\*\*.
  to Alliance motion to reconsider summary disposition of
  Contention i re QA & QC Disposition should be denied since
  issues of matl fact exist Certificate of Svc encl
  CASSEL, D W DeKalb Area Alliance for Responsible Energy
  CASSEL, D W Sinnissippi Alliance for the Environment (6M £)
  82/10/18 Atomic Safety and Licensing Doard Panel 5pp
  15764 211 24X Fiche 50-454, 82/10/18, 82/10210346
- 8210250071 Corrects two typographical errors & minor missistement in Rockford Leagus of Homen Voters answers to NRC amended first set of interrogatories ROSE, B. ROSE, B. Cherry, M. M. /Cherry, Flynn & Kenter 8J/10/23 Docketing & Services Branch 1p 15787 047 24X Fiche 50-454, 82/10/20, 8210250071
- 8210260380 Forwards author 821022 ltr to NRC transmitting first set si 210260360 Portuards author Deloze for the Communication interrogatories ROSE, B Cherry, M M /Cherry, Flynn & Kanter ROSE, B Women Voters of Rockford, IL 02/10/22 MARQULIES, M D Safety and Licensing Board Panel 1p 15804 205 24) Fiche 50-454, 82/10/22, 8210260380 ROSE, B. League of
- --8210260384 Forwards proposed interrogatories & motion for production of documents RUBELB Cherry, M. M. /Cherry, Flunn & Kanter ROSE.B League et ; Women Voters of Rockford, IL 82/10/22 GULDBERO, S.C. Hearts; Branch 4 jp 15804 206 24X Fiche 50-454,82/10/22,82102803800 .
- --8210260392 Proposed first set of interrogatories Proposed motion for elocoustic proposed in the set of interrogatories from production of documents by NRC & Proof of Syc encl. 
  \* League of Momen Voters of Rockford IL 82/10/22 
  the Executive Legal Director 26pp 15804 207 24 
  Fiche 50-454,82/10/22,8210260380 24X
- 8210270216 Notice of ASLB reconstitution IW Smith.chairmen t AD Callihan & RF Cols.members LAZO,R M Atomic Safety and Licensing Board Panel 92/10/25 =11 51823 006 24X Fiche 50-454,82/10/25,8210270216
- 8210290305 Answers to NRC amended first set of interrogatories 210290305 Ansuges to NRC amended First set of in Certificate of SVc encl ROSE.B League of Women Voters of Rockford, IL of the Elecutive Legal Director 15pp 15855 ( Fiche 50-454, 82/10/25, 8210290305 Office -82/10/25 15855 021

- 8210270273 Forwards original B Johnson verification for Rockford League of Homen Voters answers to NRC amended first set of interrogatories on Contentions 39 & 109 Related correspondence ROSE, B Cherry, M M /Cherry, Flynn & Kanter ROSE, B League of Women Voters of Rockford. IL 82/10/26 Docketing & Services Branch 2pp 15854 075 24% Fiche 50-454,82/10/26,8210270293
- 8210280347 Response opposing Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 821018 motion for leave to submit reply to NRC & util responses to intervenor 820923 motion for reconsideration W/Certificates of Svc GOLDBERG, S.C. Hearing Branch 4 82/10/27 Atomic Safety and Licensing Board Panel 5pp 15838 351 24X Fiche 50-454,82/10/27,8210280347
- B210290105 Ack receipt of Rockford League of Women Voters proposed interrogatories to NRC & motion For production of documents NRC will shortly advise League of which interrogatories will be answered GOLDBERG. S C Hearing Branch 4 82/10/28 ROSE, B Cherry, M M /Cherry, Flynn & Kanter ROSE, B League of Women Voters of Rockford, NL 1p 15854 003 24X Fiche 50-454, 82/10/28, 8210290105

### H General correspondence

- 8210070176 Responds to 820929 ltr requesting NUREQ-0782 & QMN1-20 NUREQ can be ordered from NRC Div of Technical Info & Document Control BMI rept available from NTIB GOLDBERG, S C Hearing Branch 4 82/10/06 VON ZELLEN, B Northern Illinois Univ 1p 15634 262 24% Fiche 50-454,82/10/06,8210070176
- x Utility Final Safety Analysis Report (FSAR) & amends
- 8210040060 Forwards affidavit stating that distribution of FSAR Amend 39 has been made in accordance w/Encl 1 of NRC 781020 ltr TRAMM.T R Commonwealth Edison Co. 62/09/23 DENTON, H.R. Office or Nuclear Reactor Regulation. Director 2pp 15583 191 24X Fiche 50-000.82/09/23.8210040060

#### M Antitrust correspondence

- 8210070180 Forwards, for review & comment, draft OL antitrust review finding of no significant change W/o encl VOOLER, B H Hearing Branch 2 82/10/06 CUTLER, M Justice, Dept of 1p 15634 277 24% Fiche 50-454, 82/10/06, 8210070180
- O Inspection reports, IE Bulletins & correspondence
- 9208190233 IE Info Notice 80-35, Buppl 1, "Leaking & Dislodged J-125 Implant Seeds " Syc list encl CO38.L I Division of Fuel Facilities: Materials & Safeguards 82/60/06 Consolidated Edison Co of New York 66pp 15761 200 24X Fiche 50-000:82/10/04:8208190233
- 8208170238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants" Svc list encl
  DEYDUNO.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208170238
- 8210260387 Confirms 821026 meeting at Region 3 oft to discuss util response to IE Insp Repts 50-454/82-05 & 50-459/82-04 SPESSARD. R L Division of Project & Resident Programs 62/10/19 REED. C Gommonwealth Edison Co ip 15803 105 24X Fiche 50-454,82/10/19,8210260387
- B210260307 Ack receipt of B21014 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-454/82-14
  NORELIUS.C E Division of Engineering & Technical Programs
  B2/10/22 REED,C Commonwealth Edison Co ip 15797 321 24X
  Ficha 50-454/82/10/22/8210260307
- --821026030B Responds to NRC 820913 ltr re violations noted in IE Insp Rept 50-494/82-14 Corrective actions piping contractor initiated revision to 8IP 4 000 to include mod to hardware removal/alteration rept form DELOEDROE.L O Commonwealth Edison Co 82/10/14 KEPPLER.J 0 Region J. Office of Director 6pp 15799 322 24X Fiche 50-454,82/10/22.8210260307

- DOCKET STN-50-455 BYRON STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8210010271 Forwards five oversized P&IDs referred to in util 820909 lft to MRC re waterhammer prevention Aperture cards are available in PDR
  IRAMM.I R Commonwealth Edison Co 82/09/22 DENION.H R Uffice of Nuclear Reactor Regulation, Director 2pp 15573 122 247 Fiche 50-000.82/09/28/21001027:
- 8210080313 Summary of 820708 & 07 meetings w/utils.Sargent & Lundy.
  Aerojet Energy Conversion Co & Rockford League of Women
  Voters in Chicago. IL & at pland site re vol reduction sys
  Guestions re Topical Rep+ AECC-2-P encl
  KIPER.K L Licensing Branch | 82/09/23 Licensing Branch |
  12pp | 15663 341 | 24X Fiche 50-454.82/09/23.8210080313
- 8210280429 Forwards add1 question re vol control sys, in response to applicant answer to NRC Question Q321 43 Response requested within 30 days YOUNDBLOOD, B J Licensing Branch 1 82/10/04 DELGEORGE, L I) Commonwealth Edison Co 3pp 15860 042 24% Fiche 50-000, B2/10/04, 8210390439
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" GOLDEN, J C Commonwealth Edison Co 82/10/06 CASE, E G Offici of Nuclear Reactor Regulation, Director 2pp 15805 137 24X Fiche 50-000, 82/10/06, 8210260526
- --B210260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" \* Commonwealth Edison Co B2/09/30 B3pp 15805 139 249
- 9210280420 Forwards request for add1 info re venting of high points in RCS, method of depressurization to cold shutdown 2 depressurization following steam generator tube repture events Response requested within 30 days YDUNBBLOOD, B J Licensing Branch 1 82/10/07 DELOEORGE, L C Commonwealth Edison Co 4pp 15840 009 24X Fiche 50-000, 82/10/07, B210280420
- E NRC Safety Evaluation Report (SER), supply & correspondence
- B210010202 Submits add1 info re reactor coolant pump locked rotor & shaft break transients at facilities Info closes Confirmatory Issue 34 of Byron SER TRAMM. TR Commonwealth Edison Co 82/09/22 DENTON. HR Office of Nuclear Reactor Regulation. Director 4pp 15568 073 24X Fiche 50-000.82/09/22.8210010202
- 8210250108 Forwards revised FSAR info re protection against possible turbine missiles Revisions to turbine missile analysis rept encl Info closes out 85R Outstanding Item 2
  TRAMM.T R Commonwealth Edison Co 82/10/19 DENTON, HR Office of Nuclear Reactor Regulation, Director 15pp 15789 296 24X Fiche 50-000.82/10/19.8210250108
- F Security, medical, emergency & fire protection plans

- --8210290060 Forwards public version of Revision 3 to Quad Cities & Zinnemergency plan anneres. Revision 2 to Dresden emergency plan anner. Revision 0 to Byron emergency plan anner. Revised generating station emergency plan telephone directory MODRE.R D. Commonwealth Edison Co. 82/07/30 DENTON.H R. NRC No. Detailed Affiliation Given. Sop. 15877 314 24% Fiche 50-000.82/10/08.8210290047
- --8210290077 Public version of Revision 3 to Quad Cities & Zion emergency plan anneres. Revision 2 to Dresden emergency plan annex 5 Revision 0 to Byron emergency plan anner \* Commonwealth Edison Co. 82/06/30 325pp 15877 319 24X Fiche 50-000, 82/10/08.8210290047
- --8210290088 Public version of revised generating station emergency plantelephone directory
  GALLE,D P. Commonwealth Edison Co. 82/08/12 43pp. 15878 218
  244 Fiche 50-000,82/10/08/8210290047
- 8210220358 Provides info re organization & performance of depts responsible for radiation protection activities, per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs TRAMS, I R Commonwealth Edison Co. 82/10/14 DENTON, H R. Office of Nuctear Reactor Regulation. Director 9pp 15776-297 24X Fiche 50-000 82/10/14,8210220358

#### G Adjudicatory correspondence

- 8210050371 Motion for clarification of portions of ASLB 820910 memorandum & order ruling on motions for summary disposition of certain contentions Certificate of S/c encl Related correspondence
  BIELAWSKI.A P Commonwealth Edison Co BIELAWSKI.A P Isham, Lincoln & Beale B2/09/29 Atomic Safety and Licensing Board Panel App 19408 225 24% Fiche 50-454.82/09/28.8210050391
- 8210050182 Confirms 820928 telcon.in which NRC withdrow Interrogatories 77-1 & 77-2 based on withdrawn Contention 70 Answers to remaining interrogatories due by 821015 RANSON.R J Hearing Branch 4 82/10/04 ROBE.B Cherry. M M /Cherry, Flynn & Kanter ROSE.B League of Women Voters of Rockford.lt. 1p 15614 120 24% Fiche 50-454.82/10/04.8210060182
- 8210070127 Motion for leave to file answers to util amended second round of interrogatories 1 day late ROSE, D. League of Women Voters of Rockford, IL. ROSE, D. Cherry, M. M. /Cherry, Flynn & Kanter 82/10/05 Atomic Safety and Licensing Board Panel 2pp 15627 084 24% Fiche 50-454,82/10/05.8210070127
- --B210070129 Answers to amended second round of interrogatories Certificate of Svc enci ROSE.B League of Homen Voters of Rockford.JL ROSE,B Cherry, M M /Cherry, Flynn & Kanter 82/10/05 Commonwealth Edison Co 344pp 15627 086 24X Fiche 50-454.82/10/05,8210070127
- 8210130373 Response opposing Datalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 820923 motion to or reconsider summary disposition of Contention 1 on GA/QC New info would not change decision W/Certificate of Syc MILLER.M I Commonwealth Edison Co MILLER.M I Isham, Lincoln & Beale 82/10/08 Atomic Safety and Licensing Doard Panel 13pp 15680 247 24% Fiche 50-454,82/10/08,6210130373
- 8210130095 Response supporting applicant 820928 motion for clarification of portion of ASLB 820910 memorandum & order denging NRC & applicant motions for summary disposition Litigable issues should be defineated M/Certificate of Syc GDLDBERG.S C Hearing Branch 4 82/10/12 Atomic Safety and Licensing Board Panel 5pp 15673 110 24X Fichs 50-454,82/10/12,8210130095
- 8210150087 Response opposing Dekalb Area Alliance for Responsible Enerou/Sinnissippi Alliance for Environ 820923 motion for ition of summary disposition of Contention 1(h) new facts not allowed W/Certificate of Syc saring Branch 4 20070778 Atomic Eafety and ix Fichs 50-454,82/10/10.

- 8210150170 Confirms 821012 & 13 telcons Ref to specific answers to ctil interrogatories may be suitable response to NRC interrogatories General ref unresponsive NRC does not object to extension to answer listed interrogatories RANSON.R J Hearing Branch 4 82/10/13 ROBE.B Cherry M M //Cherry. Flynn & Kanter ROBE.B League of Homen Voters of Rockford.IL. ip 15707 261 24X Fiche 50-454,82/10/13.8210170170
- 9210180151 Forwards original verification of Rockford League of Woses Voters answers to util amended second round of interrogatories Related correspondence ROSE.B Cherry, H M /Cherry, Flynn & Kanter 82/10/13 Docketing & Services Branch 2pp 15719 267 24% Fiche 50-454.82/10/13.8210180151
- 8210180142 Forwards LA Bowen 821005 affidavit per ASLB 821012 memorandum % order ruling on disclosure obligation Info provided re DeKalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Energy Contention 9a GALLO.J (Sham, Lincoln & Beale GALLO.J Commonwealth Edison Ca 82/10/14 MARGULIES.M B. CALLIHAN.A D Atomic Safety and Licensin, Board Panel COLE.R F Atomic Safety and Licensing Appeal Panel 2pp 15719 230 24X Fiche 50-454.82/10/14.8210180142
- -B210180146 Affidavit of LA Bowen Util does not intend to initall 44% sensors on feedwater bypass sys piping Existence of constant feedwater flow precludes water hammer event similar to event at Krsko BONEN.1 A Commonwealth Edison Co 82/10/05 34pp 15719 23.24 Fiche 30-454.82/10/14.8210180142
- 8210180166 Confirming order canceling 821014 prehearing conference is Rockford, IL Discovery progress discussed during 821014 telcon MARGULIES, M B Atomic Safety and Licensing Board Panel 82/10/15 Ip 15719 168 24X Fiche 50-454,82/10/15,8210180166
- 8210180170 Order granting Rockford League of Women Voters motion for leave to file instanter answers to util amended second round of interrogatories I day late MARQUILES.M B Atomic Safety and Licensing Board Panel 02/10/15 League of Homen Voters of Rockford. IL ip 19719 165 24x
- Fiche 50-454, 82/10/15, 82/0180170

  8210210274 Answers to first set of interrogatories, pursuant to Ala D
- 8210210274 Answers to first set of interrogatories, pursuant to AAP 821020 memorandum & order Verification & Proof of Svc encl Related correspondence
  JOHNSON, B League of Women Voters of Rockford, IL 82/10/15
  Office of the Executive Legal Director 4Bpp 15766 130 24%
  Fiche 50-454, 82/10/15, 8210210274
- 8210210278 Reply to amended first request for production of documents Proof of Svc encl Related correspondence ROSE.B League of Women Voters of Rockford, IL ROSE.D Cherry. M / Cherry. Flynn & Kanter 82/10/15 Defice of the Elective Legal Director 3pp 15765 150 24X Fiche 80-454.82/10/15, 8210210278
- 8210210384 First interragatories & request for documents Proof of Lyc encl Related correspondence ROSE, B League of Women Voters of Rockford, IL ROSE, B Charry, M M /Cherry, Flynn & Kanter 82/10/15 Commonwealth Edison Co 22pp 13764 016 24x Fiche 50-454,82/10/15,8210210384
- 8210210346 Motion for leave to file reply to new matters raised by applicant & NRC in response to Alliance motion to reconsider disposition of Contention i re QA & QC CASSEL, D W DeKalb Area Alliance for Responsible Energy CASSELL, D W Sinnissippi Alliance for the Environment (BAFE) 82/10/18 Atomic Safety and Licensing Board Panel 15764 210, 24X Fiche 50-454,82/10/18,8210210346
- --B210210347 Reply to new matters raised by applicant & NRC in response to Alliance motion to reconsider summary disposition of Contention i re GA & GC Disposition should be denied since issues of math fact exist Certificate of Byc encl CASSEL,D W DeKalb Area Alliance for Responsible Energy CASSEL,D W Sinnissippi Alliance for the Environment (BAFE) B2/10/18 Atomic Safety and Licensing Board Panel 5pp 13764 211 24X Fiche 30-454, 82/10/18, 8210210346

1 1

- 8210250071 Corrects two typographical errors & minor misstatement in Rockford League of Women Voters answers to NRC amended first set of interrogatories ROSE, B. ROBE, B. Cherry, M. M. /Cherry, Flynn & Kanter 62/10/20 Docteting & Services Branch ip 15787-047 24X Fiche 50-454, 82/10/20, 8210250071
- B210260380 Forwards author 821022 ltr to NRC transmitting first set of interrogatories
  RDSE. 8 Cherry, M M /Cherry, Flynn & Kanter RDSE, D. Leasue of Homen Voters of Rockford, IL 82/10/22 MARGULIES, M B Atomic Safety and Licensing Board Panel 19 15804:205 24X Fiche 50-454, 82/10/22, 8210260380

- -- 8210260384 Forwards proposed interrogatories & motion for graduction af daruments
  - of documents ROSE, B. Cherry, M. M./Cherry, Flynn & Kanter ROSE, B. League n Homen Voters of Rockford, IL. 82/10/22 GCLDBERG, B.C. Hearing Branch 4 ip. 19804-206 24% Fiche 50-454,82/10/22,8210260300
- --B210260392 Proposed first set of interrogatories Proposed motion for production of documents by NRC & Proof of Svc encl 4 League of Momen Voters of Rockford.IL B2/50/22 Office of the Executive Legal Director 26pp 15804 207 24X Fiche 50-454,82/10/22.8210260380
- 3210270216 Notice of ASLB reconstitution IW Smith chairman & AD Callihan & RF Cole members LAZO.R M Atomic Safety and Licensing Buard Panel 02/10/25 15823 006 24X Fiche 50-454.82/10/25.8210270216
- ED10290305 Answers to NRC amended first set of interrogatories Certificate of 3cc enci RDSE.B League of Komen Voters of Rockford, IL 82, of the Executive Legal Director 15pp 15855 021 Fishe 50-454.82/10/25.8210290305 82/10/25 Office
- 8210290293 Forwards original B Johnson verification for Rockford Leanur of Women Voters answers to NRC amended first set of interrogatories on Contentions 39 & 109 Related arrespondence correspondence ROSE, B. Cherry, M. M./Cherry, Flynn & Kanter ROSE, B. League Women Voters of Rockfold, IL. 82/10/26 Docketing & Services Branch 2pp 15854 075 24X Fiche 50-454,82/10/26,8210290293 to sunsol
- B210260347 Response opposing Dekalb Area Alliance for Responsible ELUZUUSAY Response apposing Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 821018 motion for leave to submit reply to MRC & Util responses to intervenor 820923 motion for reconsideration W/Certificates of 8vc GOLDBERG.S C Hearing Branch 4 82/10/27 Atomic Safety and Licensing Board Panel 5pp 19838 351 24X Fiche 50-454,82/10/27,8210280347
- ⊕210290105 Ack receipt of Rockford League of Women Voters proposed interrogatories to NRC & motion for production of documents NRC will shortly advise League of which interrogatories will the answered GOLDBERG.S C Hearing Branch 4 82/10/28 ROSE.B Cherry. N M //Cherry, Flynn & Kanter ROSE.B League of Women Voters of Rockford, IL Ip 15854 003 24% Fiche 50-454.82/10/28.8210290105
- H Gameral correspondence
- £210070176 Responds to 820929 ltr requesting NUREQ-0782 & OMNI-20 NUMEGO can be ordered from NRC Div of Technical Info & Dacument Control BMI rept available from NIIS

  OCCUMENT CONTROL BMI rept available from NIIS

  OCLOBERGO S C Hearing Branch 4 BZ/10/06 VON ZELLEN.B Northern

  Illinois Univ 1p 15634 262 24% Fiche 50-454, 8Z/10/06, P210070174
- M. Utility Final Bafety Analysis Report (FSAR) & amends
- 2210040060 Forwards affidayit stating that distribution of FSAR Amend 37 has been made in eccordance w/Encl 1 of NRC 781020 ltr TRAMM-TR Commonwealth Edison Co 82/09/23 DENTON. HR Office of Nuclear Reactor Regulation, Director 2pp 15583 191 24X Fiche 50-000.82/09/23,8210040040
- II Antitrust correspondence
- 9210070180 Forwards, for review & comment, draft OL antitrust review funding of no significant change H/O encl VOQLER, B H Hearing Branch 2 82/10/06 CUTLER, M Justice, Dept of Ip 15634 297 24X Fiche 50-454,82/10/06, 8210070180
- O Inspection reports, IE Bulletins & correspondence
- 8208190233 IE Info Notice 80~35, Suppl 1, "Leaking & Dislodged 1-12b Implant Seeds " Svc list encl. COBB.L.! Division of Fuel Facilities, Materials & Safeguards 82/10/04 Consolidated Editson Co of New York 46pp 15761 250 24X Fiche 50-000,82/10/06,8208190233
- B208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Syc list encl BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000, 82/10/14, 8208190238

- 8210260387 Confirms 821026 meeting at Region 3 ofc to discuss util response to IE Insp Repts 50-454/82-05 & 50-455/82-04 SPESSARD.R L. Division of Project & Resident Programs 62/10/19 REED.C Commonwealth Edison Co. 1p 15803 105 24X Fiche 50-454,82/10/19,8210260387 82710710
- DOCKET STN-50-456 BRAIDWOOD STATION. UNIT 1
- A Application/construction stage documents & correspondence
- 8210010202 Submits additinfore reactor coolant pump locked rotor & shart break transients at facilities Info closes
  Confirmatory Issue 34 of Byron SER
  TRAMM. T. R. Commonwealth Edison Co. 82/09/22 DENTON-H.R. Office 82/09/22 DENTON.HR NF Lar 4pp 15568 073 24X TRAMM, T.R. Commonwealth Edison Co. 62. of Nuclear Reactor Regulation, Director Fiche 50-000, 82/09/22, 8210010202 DEFICE
- 8210010271 Forwards five oversized P&IDs referred to in util 82040\* 210010271 Forwards five oversized P&IDs referred to in uti) E that to NRC me waterhammer prevention Aperture cards are available in PDR TRAMM, T.R. Commonwealth Edison Co. 82/09/22 DENTON, H.R. of Nuclear Reactor Regulation. Director 2pp 19573 122 Fiche 50-000, 82/09/22, 8210010271
- 8210050073 Application for amend to CPPR-132 & CPPR-133 revising completion dates to 870430 & 880430 respectively DELGEBROE. D. Commonwealth Edison Co. 82707/30 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 15603 1624% Fiche 50-456.82707/30.8210050073
- --8210050077 EIA supporting request for extension of dates for completion of const of units, extending Unit 1 to 870430 & Unit 2 to 880430 Commonwealth Edison Co 82/09/30 2pp 15603 183 24X Fiche 50-454, 82/09/30, 8210050073
- B210280429 Forwards addit question relvol control sys.in response to applicant answer to NRC Question Q321 43 Response requested within 30 days
  YOUNGELOOD, D. J. Licensing Branch 1 82/10/04 DELGEORGE, L. O. Commonwealth Edison Co. 3pp. 15840 042 24X Fiche 50-000, 82/10/07 15860 042 24X Fighe 50-000,82/10/04.
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual GOLDEN, J C Commonwealth Edison Co 82/10/06 CASE. Nuclear Reactor Regulation, Director 2pp 15805 137 Fiche 50-000, 82/10/06, 8210260526 GOLDEN, J C CASE, E G Office of **~**24¥
- --8910260542 Revision 3 of Chapter 9 of "Offsite Dose Calculation Manual" Commonwealth Edison Co 82/09/30 83pp 19805 139 24X Fiche 50-000, 82/10/04, 8210260526
- 8210280420 Forwards request for add) info re venting of high points in RCB, method of depressurization to cold shutdown & depressurization following steam generator tube repture events Response requested within 30 days
  YOUNOBLOOD, B J Licensing Branch 1 82/10/07 DELGEORGE, L O Commonwealth Edison Co 4pp 15860 009 24% Fishe 50-000, 82/10/0/, and 2010/00/20 8210280420
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8210250108 Forwards revised FSAR info re protection against possible turbine missiles Revisions to turbine missile analysis rept encl Info closes out SER Outstanding Item 2 TRAMM, TR Commonwealth Edison Co 82/10/19 DENTON, HR Office of Nuclear Reactor Regulation, Director 15pp 15789 296 24X Fiche 50-000, 82/10/19,8210250108 Office
- F Security, medical, emergency & fire protection plans
- 8210290363 Forwards list of deviations from Chemical Engineering Branch Technical Position 9 5 1 re fire protection program Deviations listed include lighting & communication & hydrogen line routing Justification of deviations requested YOUNOBLOOD, B J Licensing Branch : 82/10/05 DELGEDROE, L O Commonwealth Edison Co 7pp 15865 240 24% Fiche 50-000, 82/10/05, 8211090742 8210270363
- 8210130376 Advises that installation of offsite dose calculation sys Program fully operational tracking model & operational A-model will be delayed until 821231 to complete prime computer installation SWARTZ.E D Commonwealth Edison Co 82/10/06 DENTON,H R of Nuclear Reactor Regulation, Director 2pp 15682.098 Fiche 50-000, 82/10/06,8210130376 DENTON, H R Office

5210220358 Provides info re organization & performance of depts responsible for radiation protection activities.per 820702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs TRAMM.T R Commonwealth Edison Co 82/10/14 DENTON.H R Office of Nuclear Reactor Regulation, Director 9pp 15776 287 24X Fiche 50-000.82/10/14.8210220358

### G Adjudicatory correspondence

- 8210050259 Order directing all parties to file complete status repts w/ASLB Repts should contain present status of application, documents filed by NRC or util const plans & future projections & basis for scheduling projections MILLER.M E Atomic Safety and Licensing Board Panel 82/10/01 Commonwealth Edison Co 1p 15610 290 24X Fiche 50-455.82/10/01, 021002589
- 8210250211 Status rept on plants in response to ASLB 821001 order
  Unit 1 scheduled for fuel load on 850430 & Unit 2 on 860430
  Dates unil be confirmed or revised in Jan 1983 Certificate
  of Svc encl
  MILLER.M J Commonwealth Edison Co MILLER.M J Isham, Lincoln &
  Beale 82/10/19 5pp (5788-242 24X Fiche 50-456, 82/10/19,
  8210250211
- 8210220453 Response to ALSB 821001 order to file status rept on plant Schedule for issuance of NRC documents & considerations to be used in developing prehearing & hearing schedule listed Notice of appearance & Certificate of Svc encl HASSELL, D.F. Hearing Branch 1 82/10/20 13pp 15778 325 24X Fiche 50-456,82/10/20,8210220453

## K Utility Final Safety Analysis Report (FSAR) & amends

- 8210040060 Forwards affidavit stating that distribution of FSAR Amend 39 has been made in accordance w/Encl 1 of NRC 761020 ltr TRAMM, T R Commonwealth Edison Co 82/09/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15583 191 24X Fiche 50-000.82/09/23.82t0040060
- O Inspection reports, IE Bulletins & correspondence
- 8210040230 Ack receipt of 820817 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/82-01 & 50-457/82-01 Denies request to withdraw Violation I Concurs that Violation 2 does not constitute noncompliance NREELUS.C E Division of Engineering & Technical Programs 82/09/27 REED.C Commonwealth Edison Co 2pp 15586 114 24% Fichs 50-456. 82/09/27, 8210040230
- --8210040246 Responds to NRC 820707 ltr re violations noted in 1E Insp Repts 50-456/82-01 & 50-457/82-01 Disputes Violations 1 & 2 Post-tensioning sequence adequately controlled Corrective action re Comstock nonconformance repts taken DELGEORGE, L. O. Commonwealth Edison Co. 82/08/17 KEPPLER, J. G. Region 3, Office of Director 9pp. 15586 116 24X Fiche 50-456, 82/09/27, 8210040230
- 8208190233 [E Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implent Seeds " Svc list encl CDBB.L 1 Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fiche 50-000.82/10/06.8208190233
- 8208170238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter. Stainless Steel. Recirculation Sys Piping at BMR Plants " Sve list encl DEYDUNG.R C Director's Office. Difice of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 80-000,82/10/14,2208170238

## 's & related correspondence

re breakdown of GA procedures
ifety-related mechanical
'02 All affected
rent Procedure GCP-B22
B2/10/08 KEPPLER,J O Region
'1 24X Fichs 50-456,82/10/08,

069 sufaty-

8910h 0/13.

- DOCKET STN-50~457 BRAIDWOOD STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8210010202 Submits addlinfore reactor coolant pump locked rotor k shaft break transients at facilities Info closes Confirmatory Issue 34 of Buron SER TRAMM. TR Commonwealth Edison Co 82/09/22 DENTON. HR Office of Nuclear Reactor Regulation. Director 4pp 15568 073 241 Fiche 50-000. 82/09/22. 8210010202
- 8210010271 Forwards five oversized P&IDs referred to in util D2090/ 1: to NRC re waterhammer prevention Aperture cards are available in PDR
  TRAMM.T R Commonwealth Edison Co 82/09/22 DENTON-H 8 Office of Nuclear Reactor Regulation, Director 2pp 15573 122 24x
  Fiche 50-000, 82/09/22, 8210010271
- B210050073 Application for amend to CPPR-132 & CPPR-133, revising completion dates to 870430 & 880430, respectively DELOEDROE, LO Commonwealth Edison Co 82/07/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 1960i H4 24X Fiche 50-454, 82/07/30, 8210050073
- ---8210050077 EIA supporting request for extension of dates for complete of const of units extending Unit 1 to 970430 & Unit 2 to 880430 

  \*\* Commonwealth Edison Co 82/09/30 2pp 15603 183 24x Fichs 50-456,82/09/30.8210050073
- 8210280429 Forwards add1 question re vol control sys.in response to applicant answer to NRC Question Q321 43 Response requested within 30 days YOUNOBLODD. B J Licensing Branch 1 82/10/04 DELQEURGE. L C Commonwealth Edison Co 3pp 15860 042 24X Fiche 30-808.82/10/04
- 8210260526 Forwards Revision 3 of Chapter 9 of "Offsito Dose Calculation Manual" GGLDEN.J C Commonwealth Edison Co 82/10/06 CASE,C Q (Iffice to Nuclear Reactor Regulation, Director 2pp 15805 137 24x Fiche 50-000.82/10/06.8210260526
- ~~8210260542 Revision 3 of Chapter 7 of "Offsite Dose Calculation Manual" • Commonwealth Edison Co 82/09/30 83pp 15805 139 #4r Fiche 50-000,82/10/06.8210260326
- 8210280420 Forwards request for add1 info re venting of high points is a RCS, method of depressurization to cold shutdown & depressurization following steam generator tube rupture avents Response requested within 30 days YOUNGBLOOD, B J Licensing Branch | B2/10/07 DELCENGL | D Commonwealth Edison Co 4pp | 15860 009 | 24% Fiche 30-000, 82/10:00 | S210280420
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8210250108 Forwards revised FBAR info re protection against possible turbine missiles Revisions to turbine missile analysis rept enc! Info closes out SER Outstanding Item 2
  IRAMM, T R Commonwealth Edison Co. 82/10/19 DENTEN. H R Office of Nuclear Reactor Regulation, Director 15pp 15787 276 24x
  Fiche 50-000, 82/10/19,8210250108
- F Security, medical, emergency & fire protection plans
- 8210290363 Forwards list of deviations from Chemical Engineering Branch Technical Position 9 5 in e fire protection program Deviations listed include lighting & communication & hydrogen line routing Justification of deviations requested YOUNOBLOOD, B J Licensing Branch 1 82/10/05 DECEMBRIG. D Commonwealth Edison Co 7pp 15865 240 24% Fiche 50-000,82/10/05
- 8210130376 Advises that installation of offsite dose calculation symprogram fully operational tracking model & operational A-model will be delayed until 821231 to complete prime computer installation
  SWARTZ, E. D. Commonwealth Edison Co. 82/10/06 DENTON, N.R. Office of Nuclear Reactor Regulation, Director 2pp 15682 698 24%
  Fiche 50-000, 82/10/06.8210130376
- 8210220358 Provides info re organization & performance of depty responsible for radiation protection activities, per B20702 commitment Training coordinator assigned in Apr 1982 to improve health physics training programs
  TRAMM, T R Commonwealth Edison Co 82/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp 15776 287 248
  Fiche 50-000, 82/10/14, 8210220358

## DOCKETED ITEMS

### Adjudicatory correspondence

- \$210050259 Order directing all parties to file complete status repts U/ASLB Repts should contain present status of application, documents filed by NRC or util, const plans & future projections & basis for scheduling projections

  MILLER, H E Atomic Safety and Licensing Board Panel 82/10/01

  Commonwealth Edison Co 1p 15610 290 24X Fiche 50-456,82/10/01,82(0050259
- 8210250211 Status rept on plants in response to ASLB 821001 order
  Unit 1 scheduled for fuel load on 850430 & Unit 2 on 860430
  Dates will be confirmed or revised in Jan 1983 Certificate
  of Svc enci
  HILLER, N J Commonwealth Edison Co MILLER, M J Isham, Lincoln &
  8\*al\* 82/10/19 Spp 15788 242 24X Fiche 50-456, 82/10/19,
  8210250211
- 8210220453 Response to ALSB 821001 order to file status rept on plant Schedule for issuance of NRC documents & considerations to be used in developing prehearing bearing schedule listed Notice of appearance & Certificate of Svc encl HASSELL.D F Hearing Dranch 1 82/10/20 13pp 15778 325 24y Fiche 50-456,82/10/20,8210220453
- M. Utility Final Safety Analysis Report (FSAR) & amends
- E210040060 Forwards affidavit stating that distribution of FSAR Amend 39 has been made in accordance w/Encl 1 of NRC 781020 ltr RAMM.T R Commonwealth Edison Co. 82/09/23 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 24X Fichs 50-000,82/09/23,8210040060
- O Inspection reports, IE Bulletins & correspondence
- 8210040230 Ack receipt of 820817 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/82-01 & 50-457/82-01 Denies request to withdraw Violation I Concurs that Violation 2 does not constitute noncompliance NORELIUG, C E Division of Engineering & Technical Programs 82/09/27 RED, C Commonwealth Edison Co 2pp 15586 114 24X Fiche 50-456/82/09/27/8210040230
- --9210040246 Responds to NRC 820707 ltr re violations noted in IE. Insp. Repts 50~456/82-01 & 50~457/82-01 Disputes Violations 1 & 2 Post-tensioning sequence adequately controlled Corrective action re Comstock nonconformance repts taken DELOGOROG. L. Q. Commonwealth Edison Co. 82/08/17 KEPPLER, J. G. Region 3, Office of Director 7pp 15586 116 24X Fichs 50~456, 82/09/27, 8210040830
- 0208190233 IE lnfo Notice 80-35, Suppl 1, "Leaking & Dislodged I-125-Implant Speds " Syc list encl GOBB, L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06,8208190233
- #200190238 IE Bullstin B2-03. "Stress Corresion Cracking in Thick-Wall. Large-Diameter: Stainless Steel. Recirculation Sys Piping at BMR Plants " Svc list encl DEYGUNO.R C Director's Office. Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15B10 125 24X Fiche 50-000.82/10/14/8208190238
- S. Reportable occurrences. LERs & related correspondence
- 8210040249 Deficiency Rept 82-06 re containment post-tensioning bushing thread failure Initially reported on 820820 Caused by undersize major thread diameter of bushing Thread measurements will be verified before stressing TRAMN-T R Commonwealth Edison Co 82/09/23 KEPPLER. J 0 Region 3. Office of Director 2pp 15581 358 24X Fiche 50-487.82/09/23. 8210040247
- #210190299 Interim deficiency rept re breakdown of QA procedures concerning control of erection of safety-related mechanical equipment Initially reported on 820902 All affected equipment will be rechecked using current Procedure GCP-B22 IRAMM. TR Commonwealth Edison Co 82/10/08 KEPPLER, J Q Region 3. Office of Director 7pp 15742 161 24X Fiche 50-456,82/10/08. 8210190299
- B210190662 Interim deficiency rept re untimely reinsp of 3,067 safety-related pipe hanger welds Initially reported on B20908 Contractor will inspect hanger supports installed before June 1981 prior to fuel load IRAMM.T R Commonwealth Edison Co 82/10/13 KEPPLER, J O Region 3. Office of Director 2pp 15739 092 24X Fiche 50-456,82/10/13,8210190662

- DOCKET 50-458 RIVER BEND STATION, UNIT 1
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8210040215 Forwards Amend 6 to FSAR.consisting of "Failure Modes & Effects Analysis" Certificate of Svc encl CAMILL.W J Gulf States Utilities Co 82/09/27 EISENHUT.D G Division of Licensing 4pp 15587 263 24X Fiche 50-458,82/09/27,8210040215
- --8210040220 Amend 6 to FSAR \* Gulf States Utilities Co 82/09/30 480pp 15587 267 e/4% Fich 50-458.82/09/27,8210040215
- Q Inspection reports. IE Bulletins & correspondence
- 8210050387 Forwards IE Insp Rept 50-458/82-10 on 820823-27 No noncompliance noted MADSEN.G L. Division of Resident. Reactor Project & Engineering Programs 82/09/20 CAHILL.W J. Gulf States Utilities Co. 2014/15603-008 24X Fiche 50-458.82/09/20.8210050387
- --8210050399 IE Insp Rept 50-458/82-10 on 820823-27 No noncompliance noted Major areas inspected previous insp findings, site tour, observation of work & review of records for welding & nondestructive exam of safety-related piping OILBERT.L D., CROSSMAN, N.A., HUNNICUTT, D.M. Division of Resident, Reactor Project & Engineering Programs 82/09/14 4pp 15603 010 24X Fiche 50-458, 82/09/20, 8210050387
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking % Dislodged ! L.", Implant Seeds " Svc list encl COBB.L ! Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 27:0 24X Fiche 50-000, 82/10/06, 8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recurvulation Sys-Piping at BMR Plants" Svc list encl DEYGUNO, R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- S Reportable occurrences. LERs & related correspondence
- B210050201 Interim Deficiency Rept DR-71 re GA program inconsistencies in mfg of personnel air locks Initially reported on 820827 Investigation not yet complete Next rept expected by 830115 BOOKER, J E Gulf States Utilities Co 82/09/27 COLLINS. J T Region 4. Office of Director ip 19609-294 24X Fiche 50-450, 82/09/27, 8210050201
- 8210050350 Interim deficiency rept re defective math used in complimed drive element of Transamerica Delaval standby dieset/generators Initially reported on 820827 Final rept will be provided by 821027 Also reported per Part 21 800KER. J E Gulf States Utilities Co 82/09/27 COLLING. J T Region 4. Office of Director ip 15608 254 24X Fichs 50-458,82/09/27,8210050350
- 8210050219 Final deficiency rept re indications found on shop radiographs of containment penetration believes Initially reported on 820603 Investigation determined no reportable deficiency exists
  800KER.J E Oulf States Utilities Co 82/09/29 COLLINS.J T Region 4. Office of Director 1p 15611 245 24X
  Fiche 50-458.82/09/29.8210050219
- 8210050317 Interim deficiency rept re improper installation (torquing) & insp of drilled-in expansion-type anchors Initially reported on 820830 Investigation continuing Final status rept will be provided by 821115
  BOOKER, J E Gulf States Utilities Co 82/09/29 COLLING, J T Region 4, Office of Director ip 15401 357 24X
  Fiche 50-458, 82/09/29, 8210050317.
- 8210130516 Interim deficiency rept re unsatisfactory insp performed by former field GC inspector initially reported on 820327 Re-evaluation of insp continuing Next rept to be provided by 821027 BOOKER, J E Gulf States Utilities Co 82/09/30 COLLING, J T Region 4. Office of Director 1p 15683 107 24X Fiche 50-458,82/09/30,8210130516
- 8210130182 Interim Deficiency Rept 73 re improperly installed spring nots in 9E supplied power generation control complex termination cabinets Initially reported on 820902 Investigation continuing Next rept expected by 830121 BODKER, J E Gulf States Utilities Co 82/10/05 COLLINS, J T Region 4, Office of Director ip 19473 012 24X Fiche 50-458, 82/10/05, 8210130182

- 8210190518 Final deficiency rept re weld surface imperfections in Graver shop weld for containment personnel airlock Initially reported on 820702 Imperfections do not affect safe plant operation Beficiency not reportable per 10CFR050 55e BOOKER.J E Gulf States Utilities Co. 82/10/06 COLLINS,J T Region 4. Office of Director ip 15751 243 24X Fiche 30-458,82/10/06,8210190518
- B210190367 Interin Deficiency Rept DR-65 re cracking & spalling of surface concrete around penetrations Initially reported on B20806 Investigation continuing Next rept will be provided by B21203

  DCGVER.J E Guif States Utilities Co B2/10/07 COLLINS.J F Region 4. Dffice of Director ip 15742 101 24X

  Fiche 50-458. B2/10/07. B210190367
- 8210190529 Interim Deficiency Rept FR~74 re incorrect installation of 1.4-inch drilled in expansion type anchor bolts used to support emergency lighting battery unit Initially reported on 920830 investigation incomplete Final rept due by 830128 800KER, J E Gulf States Utilities Co 92/10/08 COLLING, J F Region 4. Office of Director ip 15740 034 24X Fiche 50-458, 82/10/08, 82/10/06.
- B21020003/ Interim Deficiency Rept DR-39 re insufficient beam end gaps between drywells 8 primary shield walls initially reported on 820302 Deficiency determined reportable per 100FR50 55(e) Nost rept expected by 821109 BOOMER J E Ouif States Utilities Co 82/10/08 COLLINS.J T Region 4 Office of Director 1p 15756 326 24% Fichs 50-458.82/10/08.92/0200037
- U2:10250118 Final Deficiency Rept DR-63 ie use of improper stud mail in valve fabrication Initially reported on 820629 Studs being replaced w/special natl Condition not reportable per 10CFR50 55:e) BOOKER.J E Gulf States Utilities Co 82/10/12 COLLING.J P Region 4. Office of Director ip 15787 018 24X Fiche 50-458 82/10/12.8210250118
- B210260272 Final Deficiency Rept DR-A6 re improperly retained rod end bushings that may disengage from Bergen Paterson shubber & sway strut assemblies. Initially reported on 820426 Generic part number changed on 87 drawings for riser clamps BODKER, J.E. Gulf States Utilities Co. 82/10/14 COLLINS, J.f. Region 4, Office of Director. 3pp. 15801-355. 24X Fiche 50~458, 82/10/14, 8210260292
- 6210260286 Interim Deliciency Rept DR-75 re error found in GHOSH computer program used in reactor blig hydrodynamic analysis initially reported on 920721 Investigation to determine significance of error continuing Next rept by 930114 BOOKER, J. F. Gulf States Utilities Co. 92/10/15 COLLINS, J. Region 4, Office of Director ip. 15803-217 24X Fichs 50-458, 82/10/15, 8910260286
- COCKET 50-459 RIVER BEND STATEON, UNIT 2
- k Utility Final Safety Analysis Report (FSAR) & amends
- 6210040215 Forwards Amend & to FSAR.consisting of "Failure Modes & Effects Analysis" Certificate of Byc encl CAMTLL.W J Gulf States Utilities Co 82/09/27 EISENHUT.D & Division of Licensing App 15587 263 24X Fiche 50-458.82/09/27, 6210040215
- --8210040220 Amend & to FSAR

  " Gulf States Utilities Co 82/09/30 480pp 15587 267 24X
  Fiche 50-488,82/09/27,8210040215
- G Inspection reports. IE Bulletins & correspondence

- DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

  A Application/construction stage documents & correspondence
- 8210220511 Forwards WPPSS 820825 & 0909 & CPC 820812 )trs re D&H owners group 820720 meeting w/NRC re resolution of NUREO-0737. Item II K 3 30 on small break LOCA methods Appropriate action should be taken ADENSAM. E 0 Licensing Branch 4 82/10/04 SMERON, D H Reall: Systems Branch 1p 15786 091 24X Fiche 50-000, 82/10/09 8210220511
- 8210290446 Staff requirements memo re 821007 affirmation/discussion a vote on extension of const completion dates for WPPSB, purging of classified math in ALAB-653 & emergency preparedness & rists associated w/fuel loading CHILK, B. J. Diffice of the Secretary of the Commission 82/10/68 Dffice of the Secretary of the Commission 2pp 15863 189 .44 Fiche 50-000.82/10/08.8210290446
- G Adjudicatory correspondence
- 8210040016 Response to Coalition for Safe Power 820710 request for hearing & petition to intervene Current petition does not satisfy requirements Contention must be submitted W/notice or appearance & Certificate of Svc YOUNG, M. A. Hearing Branch 4 82/09/30 Atomic Safety and Licensing Board Panel 12pp 15581 316 24X Fiche 50-466.62/6/11 8210060016
- 8210130336 Order CLI-82-29, referring Coalition for Safe Power petit, , for hearing to ASLB ASLB chairman should appoint ASLB to determine whether 10CFR2 714 requirements met & to conduct required hearing Miseparate views of Commissioner Ollinsky CHILK.8 J Office of the Secretary of the Commission Dailo 210 21pp 15681 350 24X Fiche 50-397, 82/10/08.8210130336
- 8210150480 Memorandum & order granting Coalition for Safe Power les to amend petition to intervene per order, within 15 days after svc Util complete answer to original & amended petition due within 10 days after amended petition served SMITH, I W Atomic Safety and Licensing Board Panel 12/16/1; Coalition for Safe Power Top 15703 001 24X Fiche 50-460, 82/10/13, 8210150480
- 8210200056 Notice of ASLB constitution H Grossman, chairman & Et (141) b LW Little, members COTTER, B P Atomic Safety and Licensing Board Panel 82/10/14 2pp 15755 027 24% Fiche 50~377.82/10/14.8210200056
- 82:0180147 Lists changes to be made in Commission 02:1009 Order. CLI-82-29 STUCKY, S W Docketing & Services Branch 82/10/15 Uffice of the Executive Legal Director 1p 19719 266 24% Fiche 99 397. 82/10/15.8210180147
- 821027018! Notice of ASLB reconstitution H Grossman, chairman & G Bright & J Harbour members LAZO.R M Atomic Safety and Litensing Board Panel 82/10/25 // 15629 315 24X Fiche 50-460, 82/10/25, 8210270181
- 8210270315 Notice of ASLB reconstitution H Grossman.chairman b GG Bright & J Harbour.members LAZO.R M Atomic Safety and Licensing Board Panel BR/10/パラートタ 15853 078 24X Fiche 50-397.82/10/25.8210890315
- Q Inspection reports: IC Bulletins & correspondence
- 821007037B Ack receipt of 820909 ltr informing NRC of steps taken to correct violations noted in insp on 820501-2B STERNBERG, D M Division of Resident, Reactor Project & Engineeric Programs 82/10/04 ROOT, R W Mashington Public Power Supply System 1p 15634 017 24X Fiche 50-440, 82/10/04, 9210070378
- ~-8210070387 Responds to NRC 820624 ltr re violations noted in Herry 820801~28 Corrective actions subcontractor procedures for installation of electrical penetration assemblies submitted & approved by engineer ROOTLR N Washington Public Power Bupply System 82/09/09 815HOPLT W Division of Resident Reactor Project & Engineering Programs App 15634 018 24X Fiche 50~460.82/10/04.82100/013
- 8208190233 IE Info Notice 80~35, Suppl 1, "Leaking & Dislodged 1 1: Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 2\*3 244 Fiche 50~000.82/10/06.8208190233

- B210130415 Ack receipt of B20707 & 30 ltrs informing NRC of steps taken to correct violations noted in IE imap on B20401-30
  STERNBERG.D M Division of Resident, Reactor Project & Engineering Programs B2/10/06 ROOT.R W Washington Public Power Supply System ip 15681 317 24X Fiche 50~460.82/10/06.8210130415
- --8210130425 Updates response to NRC 820608 ltr re violations noted in IE insp on 820401-30 Corrective actions local grinding to expose weld rook performed on four welds Cause of undersized welds due to improperly prepared weld bevels ROOT.R W. Hashington Public Power Supply System 82/09/30 STERNBERG.D M. Division of Resident, Reactor Project & Engineering Programs Spp. 15481-320 24X Fiche 50-460.82/10/06.82101J0415
- --8210130432 Responds to NRC 820608 ltr re violations noted in lk inspon 820401-30 Corrective actions local grinding conducted to expose weld root 5 base metal surfaces Partial penetration butt weld undersized RCOT.R W Washington Public Power Supply System 82/09/09 BISHOP.T W Division of Resident. Reactor Project & Engineering Programs 7pp 15681 325 24% Fiche 50-460-82/10/06,820190415
- 3208170238 IE Bulletin 82-03, "Stress Corrasion Gracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Syc list encl BEYDUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000,82/10/14,8208190238
- 3210280185 Ack receipt or 821012 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-460/82-08 STERNSERG,D M Division of Resident, Reactor Project & Engineering Programs 82/10/22 RG0Tr W Washington Public Power Supply Bystem 1p 15837 006 24X Fiche 50-460,82/10/22,8210280185
- --B210280190 Responds to NRC 820607 itr re violations noted in it insp Rept 50-460/82-08 Corrective actions const package sys initiated to track work operations in field & craft personnel instructed to perform work per package sys ROOT.R W Hashington Public Power Supply System 62/10/12 STERNBERG.D M Division of Resident, Reactor Project & Engineering Programs 4pp 15837 007 24X Fiche 50-460,82/10/22,8210280185
- 3210280286 Ack receipt of 821012 itr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-460/82-07 STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 82/10/22 R00T.R W Washington Public Power Supply System 1p 15845 194 24X Fiche 50-460, 82/10/22,8210280286
- --8210280277 Responds to NRC B20B04 ltr re violations noted in II Insp
  Rept 50-460/B2-07 Corrective actions GCRFI sys deleted &
  insp repts will be written when question as to validity/
  accuracy of requirements of item occurs
  ROUT, R W Washington Public Power Supply System 82/10/12
  STERNDERO, D M Division of Resident, Reactor Project & Engineering
  Programs 3pp 1845 175 24x Fiche 50-460,82/10/22,8210280286
- S Reportable occurrences, LERs & related correspondence
- B21007033B Interim deficiency rept re emergency diesel generator governor lube oil cooler initially reported on B20126 Lube oil cooler will be moved to elevation below oil level per Transamerica Delaval instructions & drawings ROOT, R W Hashington Public Power Supply System B2/09/15 STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 2pp 15634 071 24X Fiche 50-460,82/09/15,8210070338
- 8210070297 Interim deficiency rept re unsuitability of isoprene math used in governor drive coupling elements Initially reported on 820819 Field change notice issued to implement changeout of element math to heoprene Also reported per Part 21 8001.8 W Washington Public Power Supply System 82/09/20 STERNBERG, D M Division of Resident. Reactor Project & Engineering Programs 2pp 15634 178 24X Fiche 50-440.82/09/20.8210070897
- 8210070311 Interim deficiency rept re use of lumped mass loads in performance of pipe stress analysis Initially reported on 820305 Parametric studies may resolve trivial mass changes interim status repts will be provided on semiannual basis ROOT.R H Mashington Public Power Supply Bystem 82/09/20 STERNBERO.D M Division of Resident, Reactor Project & Engineering Frograms 3pp. 15434 145 24X Fiche 50-460,82/09/20,8210070311

- DOCKET 50-461 CLINTON POWER STATION, UNIT 1

  A Application/construction stage documents & correspondence
- B209290072 Forwards 581 oversize electrical, instrumentation & control drawings, identified in Table ( 7-1 of FSAR Aperture cards are available in PDR WULLER, G E Illinois Power Co B2/09/20 THOMAS, C G Standardization & Special Projects Dranch ip 15540-196 24X Fiche 50-461, B2/09/20, B209290072
- B210050460 Requests add1 info to 820722 submittal on meteorological measurements sysidata acquisition & assessment scheme for emergency plan & Bil016 submittal on hydrogen ignition sys Schedule for responding to questions requested within 2 wks THOMAS.C O Standardization & Special Projects Branch 92/09/2/ MULLER.C [Flinois Power Co 7pp 15626-250 24X Fiche 50~461.82/09/22.8210050460
- 8210040104 Responds to 820326 request for add1 info re hydrodynamic water hammer analysis of control rad drive sys MULLER, G E Illinois Power Co 82/09/24 7HOMAS.C O Standardization & Special Projects Branch 3pp 15580 35! .'47 Fiche 50-461, 82/09/24, 8210040104
- 8210040070 Disapproves 820920 request for concurrence re-partial lift of Stop Work Order Old-re-electrical conduct installation Matrix of commitments & completion status for each item required SPESSARD, R.L. Division of Project & Resident Programs 82/09/27 OERSINER, W.C. Illinois Power Co. 2pp 15581 278 24% Fiche 50-461.82/09/27,8210040070
- B210130490 Advises that response to Questions 810 57.810 58 & 810 59 of NRC 820922 litrine degraded core hydrogen control & emergency plan dose assessment reporting sys will be provided via FEAR amend by 821130

  MULLER.G E Illinois Power Co 82/10/08 THOMAS.C O Standardization & Special Projects Branch ip 15682 169 247

  Fiche 50-461.82/10/08.8210130490
- 8210130325 Provides quarterly update re const schedule Fuel loading & commercial operation projected for Jan & Aug 1984, respectively KOCH.L J Illinois Power Co 82/10/11 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 15678 281 24X Fiche 50-461,82/10/11,8210130325
- 8210150357 Provides schedule for submitting add1 info for NRC review of hydrogen ignition sys/in response to NRC 820922 questions re degraded core hydrogen control & emergency plan dose assessment rept sys Questions will be addressed by 830101 MULER, G E Illinois Power Co 82/10/11 THOMAS, C O Standardization & Special Projects Branch ip 15704 317 200 Fiche 50-461, 82/10/11, 8210150357
- 8210280340 Responds to 820902 questions re ECCS NRC review of util 1970 on Humphrey concerns will be reported in SER suppl No further concern over Nuo Sheng Contention 10 Portions of ARRS transcript end CODDARD.R J Hearing Branch 3 82/10/15 WILLMAN.P L 111:no State of 24pp 15038 327 24X Fiche 50-461.82/10/15.82102803
- 8210260204 Confirms 821006 discussion w/util & LL? Iimited resumption of work, per 820901 confirmat ltr Concurrence assumes that listed changes wil implemented prior to conducting nondestructi KEPFLER, J Q Region 3, Office of Directo lilinois Power Co 821026--
- 8210280213 Provides initial response to 820901 confirmatory action its recourse of action in progress to assure that facility will be constructed in accordance w/FSAR Viewgraph of facility project update encl HALL, D.P. Illinois Power Co. 82/10/20 KEPPLER, J.G. Region 3, Office of Director. 43pp. 15838-258 24X Fiche 50-461,82/10/20,8210280213
- 8210280089 Forwards operability analyses to demonstrate capability of containment vent/purge butterfly isolation valves to function as designed into resolves TMI Action Item II E 4 2(4) & SER Outstanding Issue 100 MULLER, 0 E Illinois Power Co 82/10/22 THOMAS, C O Standardization & Special Projects Dranch 369pp 15843 088 24X Fiche 50-461, 82/10/22, 8210280089

- E NRC Bafety Evaluation Report (SER), supply & correspondence
- 8210050278 Requests incorporation of Licensing Review Group II program re channel box deflection concern into future suppl to SER, superseding SER Section 4 2 3 13 info
  WULLER G E Illinois Power Co 82/09/28 THOMAS, C 0
  Standardization & Special Projects Branch 2pp 15611 187 24X
- B2100502B9 Confirms commitment to revise emergency operating procedures to address common vessel ref level for fuel zone level meter Info should close out SER Confirmatory Itom 39 WULLER, G E Illinois Pouer Co B2/09/28 THOMAS.C O Standardization & Special Projects Branch 1p 15609 084 24X Fiche 50-461. B2/09/28. B2100502B9.
- 8210050281 Forwards Sargent & Lundy analysis of feedwater check valves Analysis indicates that feedwater check valve will withstand worst case loadings w/o losing pressure boundary integrify info should close out SER issue HULLER. © E Illinois Power Co 82/09/30 THOMAS. C O Standardization & Special Projects Branch 7pp 15409 179 24X Fiche 50-461. 82/09/30, 8210050281
- 8210280089 Forwards operability analyses to demonstrate capability of containment vent/purge butterfly isolation valves to function as designed Info resolves FMI Action Item II E 4 2(6) & SER Clutstanding Issue IOa HULLER, G E Illinois Power Co 82/10/22 THOMAS, C O Standardization & Special Prajects Branch 369pp 15843 088 24X Fiche 50-461, 82/10/22, 8210280089
- F Security, medical, emergency & fire protection plans
- 8210050460 Requests add1 info re 820722 submittal on meteorological measurements sys.data acquisition & assessment scheme for emergency plan & 816016 submittal on hydrogen ignition sys Schedvie for responding to questions requested within 2 wks THOMAS, C O Standardization & Special Projects Branch 82/09/22 MULLER, O Illinois Power Co 7pp 15626 250 24% Fiche 50-461, 82/09/22, 8210050460
- 8210130470 Forwards Revision 4 to physical security plan Revision withheld (ref 10CFR2 7901 KOCH, J. 1111nots Pawer Co 82/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 15682 160 24X Fiche 50-461, 82/09/30, 8210130470
- 8210130490 Advises that response to Questions 810 57,810 58 & 810 59 of NRC 820922 ltr re degraded core hydrogen control & emergency plan dose assessment reporting sys will be provided via FSAR amend by 821130 HULLER.O E Illinois Power Co 82/10/08 THOMAS.C O Standardization & Special Projects Branch ip 15682.169 24X Fiche 50-461, 82/10/08,8210130490
- B210150357 Provides schedule for submitting additinfo for NRC review of hydrogen ignition sys, in response to NRC B20922 questions re degraded core hydrogen control & emergency plan dose assessment rept sys Questions will be addressed by B30101 WULER, O E Illinois Power Co B2/10/11 THOMAS, C O Btandardization & Special Projects Branch ip 15704 317 24X Fiche 50-461, B2/10/11, B210150357

.

- Q Inspection reports, IE Bulletins & correspondence
- B210130547 Forwards IE Investigation Rept 50~461/82-02 on 820105 03.0 KEPPLER, J O Region 3, Office of Director 82/08/04 GERSTMEA, #1 111inois Power Co 2pp 15683 307 24X Fiche 50-461, 82/08/04, 8210130547
- --8210130557 IE Investigation Rept 50-461/82-02 on 820105-0303 Flyst violations noted in GA program for safety-related electrical work 9C personnel not granted sufficient freedom to perform duties PHILLIP.0 A , FOSTER.J E , LOVE, R B , Region 3, Office of Direct 82/06/07 53pp 15683 309 24X Fiche 50-461.82/08/04, 8210130547
- 8210040270 Confirms 820924 verbal approval re limited work resumptiff on 820927 per confirmatory action ltr Scope of work limited to insplof remedial work associated w/nonsafety-related setsmic electrical trays in Setsmic Category I bldgs NORELIUS, C.E. Division of Engineering & Technical Programs 82/09/28 GERSTNER, W.C. Illinois Power Co. 1p. 15594-360 247 Fiche 50-461.82/09/28, 9210040270
- 8210070336 EN-82-032 on 821006, notice of violation & proposed imposition of civil penalty to be issued to licenses Action based on numerous violations in electrical area & licenses failure to exercise control over contractor FLACK.E., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 82/10/04 ip 15634-084 24% Fiche 50-461,62/10/04 82/10/0336
- 8210130451 Discusses IE insp on 820105-0303 & forwards notice of violation & notice of proposed imposition of civil penalty KEPPLER.J & Region 3. Office of Director 82/10/05 GERSTMER MC Illinois Power Co 2pp 15681 332 24X Fiche 50-461,82/10/05. 8210130451
- --B210130459 Notice of violation & notice of proposed imposition of a genalty in amount of \$40,000 Noncompilance noted failure to exercise adequate oversight & control of principal contractor for assuring execution of GA program KEPPLERIJ O Region 3, Office of Director B2/10/03 13pp 13681 334 24% Fiche 50-441.82/10/05.8210130451
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Distodged 1-125 Implant Seeds " Svc list encl COBB.L | Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 2'0 24X Fich 50-000, 82/10/06, 82081908333
- 8210130181 Forwards revised Pages 3,11,12 & 14 to 820223 "Clinton Power Station Preservice Insp Program" 
  WULLER: 6 E Illinois Power Co 82/10/06 THOMAS, C 0 
  Standardisation & Special Projects Branch ip 15673 013 Rev 
  Fichs. 50-461: 82/10/06.8210130181
- --B210130184 Revised Pages 3,11,12 & 14 to "Clinton Power Stateon Preservice Insp Program" \* Illinois Power Co 82/10/06 Spp 13673 014 24% Fiche 50-461,02/10/06.8210130181
- 8210130240 Submits confirmatory action ltr per 820930 meeting No further work will be allowed until completion of NRC approvel of overinsp program plan BPESBARD, R L Division of Project & Resident Programs 82/10/05 OERSTNER, W C Illinois Power Co 2pp 15675 124 24x Fiche 30-461, 82/10/06, 8210130240
- B210250224 Forwards IE Insp Rept 50-461/82-08 on 820601-0731 No noncompliance noted KNOP:R C Division of Project & Resident Programs 82/10/06 GERBYNER:W. C Illinois Power Co 2pp 15788 349 24X Fiche' 50-461, 82/10/06.8210250224
- --8210250232 IE Insp Rept 50-461/82-08 on 920601-0731 No nencomplishing noted Major areas inspected const activities, including mail laydown & storage areas, pipe & structural welding, program control & numerous stop work recovery activities LIVERMORE, H H , HAYES, D W Division of Project & Resident Programs 82/09/30 App 15788 351 24X Fiche 50-461.82/10/pg 8210250224.
- 8210280170 Forwards IE Mgt Meeting Rept 50-461/82-17 on 820930 Mg noncompliance noted KEPPLER.J.O Region 3. Office of Director 82/10/13 GERSTNER w: Illinois Power Co 2pp 15845 048 24X Fiche 50-461.82/10/12 8210280170

- --8210280174 IE ligt Meeting Rept 50-461/82-17 on B20730 No noncompliance noted Major areas discussed status of stop work recovery & overinsp programs, master mgt plan & recommendations from audit Related viewgraphs enc!

  KEPPLER.J G , HAYES,D W Division of Project & Resident Programs MNDP.R C Division of Project \* Resident Programs B2/10/13 42pp 15845 050 24x Fishe 50-461.82/10/13,8210280170
- --8210280174 IE Mgt Meeting Rept 50-461/82-17 on 820930 No noncompliance noted Major areas discussed status of stop work recovery & overinsp programs master mgt plan & recommendations from audit Related viewgraphs enci

  KEPPLER, J G Region 3, Office of Director SPESSARD, R L

  Division of Project & Resident Programs 82/10/13 42pp
  15845 050 24X Fiche 50-461, 82/10/13, 8210280170
- 2208190236 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Hallitarge-Diameter. Stainless Steel. Recirculation Sys Piping at DWR Plants "Svc list encl DEYQUNG. R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- 8210280050 Forwards full payment for 821005 notice of proposed imposition of cavil penalties re violations noted in IE Investigation Rept 50-461/82-02 GERSTNER. W.C. Illinois Power Co. 82/10/21 Director's Office, Office of Inspection and Enforcement App. 15837-252 24X Fiche 50-461.82/10/21.8210280050
- 5 Reportable occurrences, LERs & related correspondence
- 6210190350 Interim Deficiency Rept 82-08 re lack of distribution control for instrument data sheet Initially reported on 820902 Condition could result in errors in documentation & instrument requirements Document control tightened MALL, D.P. Illinois Power Co. 62/10/01 KEPPLER, J.G. Region 3, Office of Director. 4pp. 15742-091 24X Fiche 50-461,82/10/01, 82/0190350
- 82:0190354 Final Deficiency Rept 82-06 ie loss of structural steel inspreyends Initially reported on 820625 Measures taken to document destroyed drawings brevise 8C requirements 6685THER.W C Illinois Power Co 82/10/01 KEPPLER, J G Region ), Office or Director 3pp 15742 104 24X Fiche 50-461.82/10/01, 8210190354
- 8210190416 Interam Deficiency Rept 82-09 is small bore/instrumentation piping support design calculations Initially reported on 820902 Review of all calculations to determine extent of errors underway Next rept due in 90 days HALLID P Illinois Power Co 82/10/01 KEPPLER. J 8 Region 3. Grice of Director 3pp 15740 353 24X Fiche 50-461.82/10/01. 62:0190416
- 6210190633 PND-111-82-108 on 621005.util announced hiring of 5&W Engineering to augment const mgt plogram & assess site const organization Majority of safety-related work stopped since June 1982, tending upgrading of GA program LIVERMORE, H. HAYES, D. KNUP, R. Region 3. Office of Director 02/10/06 pp 15737-359 24X Fiche 50-461.62/10/06.8210190633
- 8210280160 Interim Part 21 Ropt 82-07 re breakdown in const GA program insp & carrective action procedures Initially reported on 820708 Stop work action issued until investigation complete Results expected in 90 days HALL D P Illinois Power Co 82/10/19 KEPPLER. J G Region 3. Office of Director 5pp 15837 210 24X Fiche 50-461,82/10/19. Re10280160

DOCKET 50-462 CLINTON POWER STATION, UNIT 2

- @ Inspection reports, IE Bulletins & correspondence
- 8208190203 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeds " Syc list encl COBB.t. I Division of Fuel Facalities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24x Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corresion Cracking in Thick-Hall-Large-Diameter: Stainless Steel, Recirculation Sys Piping at BWR Plants " Syc list encl BEYQUMG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238

DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1

- G Adjudicatory correspondence
- B210070120 Motion for termination of proceedings Util decided to cance) plant Certificate of Svc encl
  NEWMAN.J R Houston Lighting & Power Co NEWMAN.J R
  Lowenstein.Newman.Reis.Azelrad & Toll 82/10/06 Atomic Safety and Licensing Board Panel 3pp 15627 061 24x
  Fiche 50-466.82/10/06.8210070120
- 8210070147 Withdrawal of application for CP NEUMAN, J R Houston Lighting & Power Co NEUMAN, J R Lowenstein, Neuman, Reis, Azelfrad & Toll 82/10/06 1p 15627 075 24K Fiche 50-466, 82/10/06, 8210070147
- 8210190390 Response to util 821006 motion for termination of proceeding NRC does not object to motion Certificate of Svc encl
  BLACK.R L Hearing Branch 3 82/10/15 Atomic Safety and Licensing Board Panel 3pp 15740 348 24X Fiche 50-466.82/10/15, 8210180390
- G Inspection reports, IE Bulletins & correspondence
- 8208170233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-12', Implant Seeds " Svc list ent! COBB.L I Division of Free! Facilities, Materials & Safeguards 82/10/06 Consulidated Edison Co of New York 66pp 15761 250 244 Face 50-000, 82/10/06, 8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys
  Piping at BWR Plants "Svc list encl
  DEYOUNG, R C Director's Office, Office of Inspection and
  Enforcement 82/10/14 Consolidated Edison Co of New York
  115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238

DOCKET STN-50-470 CESSAR SYSTEM BO

- B Utility Preliminary Safety Analysis Report, amends
- B2102B0202 Withdraws App C to CESSAR-F supporting operation of Sys 80 NBSB at reduced power level w/two pumps from NRC review Partial loop operation not required for issuance of final design approval SCHERER.A E Combustion Engineering, Inc B2/10/25 THOMAS.C Standardization & Special Projects Branch 1p 15837 049 24X Fiche 50-470.82/10/25.8210280202
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8210150306 Forwards proprietary & nonproprietary "Statistical Combination of Uncertainties, Part II" & "Statistical Combination of Uncertainties, Part III," re SER Confirmatory Item 7 Proprietary versions withheld (ref 100FR2 790) SCHERER, A E Combustion Engineering, Inc 82/10/08 EISENHUT, D & Division of Licensing 6pp 19715 173 24X Fiche 50-470,82/10/08,8210150306
- --8210130313 "Statistical Combination of Uncertainties, Part II, Uncertainty Analysis of Limiting Safety Sys Settings for C-E Sys 80 NBSB "

  \* Combustion Engineering, Inc 82/09/30 30pp 15715 175 Fichs 50-470, 82/10/08, 8210150304

DOOKE 125 11 2011

- --B210220253 "Comparison of Finite Element & Lumped Mass Seismic Analysis Methods for Selected SNUPPS Bldgs: Revision 1 Standardized Nuclear Unit Power Plant System 82/06/18 24pp 15775 327 24X Fiche 50-000.82/10/18.8210220252
- 8210260274 Submits plant-specific rept re NUREG-0737. Item II D 1.
  "Relief & Safety Valve Testing " Acceptable operability of
  SNUPPS safety valves demonstrated Evaluation of safety &
  relief valve discharge piping & support expected by 821231
  PETRICK.N A Standardized Nuclear Unit Power Plant System
  82/10/20 DENTON.H Office of Nuclear Reactor Regulation, Director
  3pp 15803 026 24% Fiche 50-000.82/10/20.8210260274
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8210040373 Forwards Suppl 1 to SER (NUREG-0881) W/o encl YOUNGBLOOD, B J Licensing Branch 1 62/07/07 KOESTER, G L Kansac Oas & Electric Co 3pp 15597 200 24X Fiche 50-482,82/09/07, 8210040373
- F Security, medical, emergency & fire protection plans
- B210210272 Notification of 821019 meeting w/utils & SNUPPS organization in Bethesda, MD to discuss matters re fire protection for alternate shutdown panel EDISON.6 E , HOPKINS.J D Licensing Branch 1 62/09/27 YOUNGBLOOD, B J Licensing Branch 1 4pp 15774 341 24X Fiche 30-000, 82/09/27,8210210272
- G Adjudicatory correspondence
- 8210200050 Notice of ASLB reconstitution JA Laurenson.chairman & GC Anderson & HC Parton.members COTTER.B P Atomic Safety and Licensing Board Panel 82/10/14 2pp 15757 224 24X Fiche 50-482.82/10/14.8210200050
- H General correspondence
- 8210120197 Informs of mgt organization changes FSAR will be revised to reflect changes MOESTER: 8 L. Kansas Cas & Electric Co. 82/10/06 DENTON,H R Office of Nuclear Reactor Regulation, Director Spp. 15651-232 24/ Fiche 50-482.82/10/06.8210120197
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 8210080260 Forwards Revision 10 to FSAR, including FSAR changes transmitted by 820706,13 & 0827 ltrs PETRICK,N A Standardized Nuclear Unit Power Plant System 82/09/20 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 15638 333 24X Fiche 50-000,82/09/30,8210080260
- --8210080264 Revision IO to FSAR
  4 Standardized Nuclear Unit Power Plant System 82/09/30 409pp
  15638 335 24X Fiche 50-000.82/09/30.8210080260
- Q Inspection reports. IE Bulletins & correspondence
- B210190596 Forwards IE Insp Rept S0-482/82-11 on 820701-0831 No noncompliance noted SciDLE W C Division of Resident, Reactor Project & Engineering Programs 82/09/22 KOESTER, 0 L Kansas Cas & Electric Co 2pp 15739.039 24% Fichs 50-482.82/09/22.82019/90596
- ~~8210190608 IE Insp Rept 50~482/82-11 on 820701-0831 No noncompliance noted. Major areas inspected follows on previous insp findings, records review for post-tensionsng sys installation & raceways & power cable installation activities VANDEL, T E , NORTON, J F , HUNNICUTT, D M Division of Resident, Reactor Project & Engineering Programs 82/09/20 12pp 15739 341 24X Fiche 50~482,82/09/22,8210190596
- 8208190233 IE Info Notice 80-35. Suppl ir "Leaking & Dislodged I-125 Implant Seeds " Syc list encl CDBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fichs 50-000,82/10/06.8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYGUNO.R.C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238

- 8210280225 Advises that IE Insp Rept 50-482/81-18 has been canceled Rept will not be issued SEIDLE.W C Division of Resident, Reactor Project & Engineering Programs 82/10/25 KDESTER.G L Kansas Gas & Electric Co ip 15837 086 24X Fiche 50-482.82/10/25.8210280225
- S Reportable occurrences, LERs & related correspondence
- 8210040364 Interim deficiency rept re potential defect in diesel generator thermostatic valve units AE awaiting receipt of additectnical info from vendor to finalize rework plan Rept on status of insp by 830120 Also reported por Part 21 KOESTER.G L. Kansas Gas & Electric Go. 82/07/23 SEIDLE.W C. Division of Resident, Reactor Project & Engliseering Program. Ip 15589-027 24X Fiche 50-482,82/09/23,8210040364
- DOCKET STN-50-483 CALLAWAY PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- B210040370 Informs that util proposed exception to Reg Ouide ( 146 or qualifications of GA audit personnel unacceptable Util should provide clear commitment to Reg Guide ( 146 by B21005 YOUNOBLOOD, B J Licensing Branch ( 82/09/03 SCHNEILDF Union Electric Co 3pp 15597 197 24X Fishe 50-483, B2/09/07, B2/004b173
- 8210210309 Notification of 821020 meeting w/utils & SNUPPS in Daithersburg, MD to discuss electrical power sys EDISON.0 E. HOPKINS.J B. Licensing Branch I 82/09/27 VOUNDBEOOD.B J. Licensing Branch I 4pp 15782-074 24X Fiche 50-000, 82/09/27, 8210210309
- B210050299 Responds to 820903 ltr re commitments to Reg Guide [ 144, ge Revision 2 of FSAR site addendum Commitment will be revised, w/o stated clarification, in next revision to FGAR addendum SCHNELL.DF Union Electric Co B2/09/20 YGUNBBLGDD, B J Licensing Branch 1 4pp 15609 072 24X Fiche 50-483,82/09/49,8210050299
- 8210220252 Forwards Revision 1 to "Comparison of Finite Element & Lumped Mass Seismic Analysis Methods for Bolected SNUPPS Bldgs " PETRICK.N A Standardized Nuclear Unit Power Plant System
  - PETRICK: N A Standardized Nuclear Unit Power Plant System 92/10/18 DENTON H R Office of Nuclear Reactor Regulation, Director Ip 19779-326 24X Fiche 50-000 02/10/16 021022020
- --8210220293 "Comparison of Finite Element & Lumped Mass Seismic Analymethods for Selected SNUPPB Bldgs:" Revision I

  4 Standardized Nuclear Unit Power Plant System 82/06/18 44pp
  15775 327 24% Fiche 50-000,82/10/18,8210220252
- 8210260274 Submits plant-specific rept re NUREG-0707, Item II D I.
  "Relief & Safety Valve Testing " Acceptable operability of
  SNUFPS safety valves demonstrated Evaluation of safety 6
  relief valve discharge piping & support expected by 021231
  PETRICK,N A Standardized Nuclear Unit Power Plant Gystem
  B2/10/20 DENTON,H Office of Nuclear Reactor Regulation, Directo,
  3pp 15803 026 24X Fiche 50-000,82/10/20,8210260274
- F Security, medical, emergency & fire protection plans
- 8210070152 Advises that no radiological emergency response plan or std operating procedure has been developed or accepted by Montgomery or Gasconade Counties, MO, as reported in RW Krimm 820817 memo REED, J 9 Affiliation Unknown 82/09/23 GRIMER, B Division of Emergency Preparedness KRIMM, R W Federal Emergency Management Agency 3pp 15627 071 24X Fiche 50-483,82/09/23,82100/0157
- 8210210272 Notification of 821017 meeting w/utils & SNUPPS organisation in Bethesda MD to discuss matters re fire protection for alternate shutdown panel EDISON.9 E . HOPKINS. J B Licensing Branch 1 82/09/27 VOUNGBLOOD.B J Licensing Branch 1 4pp 15774 341 24X Fiche 50-000.82409/27.8210210272
- Q Adjudicatory correspondence
- 8210060197 Final particularization of J Reed amended Contentions 1.2 3 Certificate of Svc encl
  3 Certificate of Svc encl
  REED. J G Reed. J G 82/10/O1. Atomic Safety and Licensing boar,
  Panel 42pp 15614 176 24X Fiche 50-483,82/10/O1.8210060197

#### DOCKETED ITEMS

- Balo:20202 Forwards revised schedule stipulated at 820908 prehearing conference reflecting 2-uk extension for discovery of undisputed contentions Original interrogatories no longer appropriate Svc list encl Related correspondence DATER, TA Shaw Pittman, Potts & Trowbridge BAXTER, TA Union Electric Co 82/10/06 CLFASON.J.P. BRIGHT.0 D. KLINE, J.F. Atomic Safety and Licensing Board Panel 4pp 15652 293 24X Fiche 50-483, 82/10/06,8210120262
- 8210210365 Objections to JG Reed 821001 particularization of Contentions II & I2 Contention II seeks greater specificity re energency planning for re-entry & recovery than specified by regulations Certificate of Svc enci DAXTER.I A Union Electric Co BAXTER.I A Shaw, Pittman, Potts & Traubridge 62/10/18 Atomic Safety and Licensing Board Panel 24pp 15763 216 24% Fiche 50-483.82/10/18.8210210365
- Fallousulaŭ Forwards reviseo interrogatories & requests of JO Reed for production of documents Responses due B21113 & objections due B21027, per stipulated schedule Requests replace util E20715 interrogatories & requests Certificate of Svc enci BAYTER. TA Shaw. Pittman. Potts & Trowbridge BAYTER. TA Union Electric Co B2/10/20 REED. J C Reed. J G 4pp 15788 308 24X Fiche 50-483. 82/10/20. 8210250248
- -8210250253 Revised interrogatories / requests for production of documents BAKTER.I A Union Electric Co BAYTER.T A Shaw, Pittman, Potts / Troubridge 82/10/20 REED.J G Reed. J G 25pp 15798 312 24% Fiche 50-483.82/10/20,8210250248
- EZICZ70157 Response to J Reed 821001 final particularization of amended Contentions 1,2 \* 3 Objects to admission of Contentions 7 11,12 \* 14 % portions of 3,19 & 15 Certificate of Sic encl
  PERLISER G Hearing Branch 3 82/10/25 Atomic Sofety and Licensing Board Panel 16pp 15830 028 24X Fiche 50-483.82/10/25, 8210270157
- Utility Final Safety Analysis Report (FSAR) & amends
- E210030260 Forwards Revision 10 to FSAR, including FSAR changes transmitted by 820706.13 % 0827 Itrs nit Power Plant System 82/09/30 DENIGN.H R Office of Nuclear Unit Power Plant System Director 2pp 15630 33.1 24% Fiche 50-000.82/09/30.8210080260
- 8210080266 Revision 10 to FSAR + Standardized Nuclear Unit Power Plant System 82/09/30 409pp 15638 335 24; Fiche 50-000,82/09/30,8210080260
- a inspection reports. If Bulletins & correspondence
- B210130514 Forwards IE Insp Rept 50-483/B2-10 on B20801-31 & notice of violation SPESSARD, R L. Division of Project & Resident Programs 82/09/16 SCHWELL, D F. Union Clectric Co. 2pp. 15682 241 24X Fiche 50-483, 62/09/16, 8210130514
- 8210130523 Notice of violation from insp on 820801-31 SPESSARD, R. L. Division of Project & Resident Programs 82/09/16 2pp 15682 243 24X Fiche 50-483,82/09/16,8210130514
- --8210133529 IE Insp Rept 50-483/82-10 on 820801-31 Noncompliance noted failure to follow cable installation procedures & failure to identify monconforming electrical penetrations NEISLER.J H , KONKLIN.J E Division of Project & Resident Programs 82/09/16 7pp 15682 245 24% Fiche 50-483,82/09/16,8210130514
- 8210130484 Ack receipt of 820723 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-06
  SPESSARD R L Division of Project & Resident Programs 82/10/05
  SCHNELL, D F Union Electric Co Ip 13684 196 24X
  Fiche 50-483,82/10/05.8210130484
- --8210:30555 Responds to NRC 820825 ltr re violations noted in IE Insp Rept 50-483/82-06 Corrective actions review of all completed work assistgnments for non-Q non-scheduled raceway within Seismic II/I boundaries in process SCHNELL D F Union Electric Co 82/09/23 SPE88ARD, R L Division of Project & Resident Programs 2pp 15684 197 24X Fiche 50-483,82/10/05.8210/30484
- 8203190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implemt Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fichs 50-000,82/10/06,8208190233

- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall.Large-Diameter.Stainless Steel.Recirculation Sys
  Piping at BMR Plants " Svc list encl
  DEYCUNO,R C Director's Office. Office of Inspection and
  Enforcement 82/10/14 Consolidated Edison Co of New York
  [15pp 15810 125 24X Fiche 50-000.82/10/14.8208190238
- S Reportable occurrences, LERs & related correspondence
- 8207180037 FOIA request for insp % enforcement records re accidents of F Lawson & H Dillon at facility. Union Electric Co CP & other NRC safety manuals or mattls 160E. V M 190e, V M 82/08/12 KEPPLER, J O Region 3, Office of Director 1p 15626 243 24X Fiche 50-483,82/08/12,8207180037
- 8210050512 Responds to FOIA request for insp & enforcement records ro accidents of F Lawson & H Dillon at facility. Union Electric CP & other NRC safety maths or manuals Forwards two documents Renaining records available in FDR FELTON. J H Division of Rules and Records 82/09/21 IGGE. M V Igoe. V M 2pp 15528 244 224 Fische 50-000. 82/09/21, B21005051.2
- ---82:0050518 Region 3 daily rept for 780807 + Region 3. Chicago. Office of the Director 78/08/07 1p 15626 246 24X Fiche 50-000, 82/09/21.8210050512
- -6210050522 PNO-111-78-062 on 780804, two workers seriously injured whin hit by support girder for polar crane rail GSHA notified SCHWEIBINZ, E.R., HAYES, D.W., HEISHMAN, R.F., Region G., Chicago, Office of the Director 78/08/04 lp 15626-247 24X Fiche 50-000,82/09/21,8210050512
- DOCKET STN-50-485 STERLING POWER NUCLEAR PROJECT, UNIT 1
- @ Inspection reports. IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged I-125 Implant Seeds " Svc list encl CDBG.L.] Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York & App. 15761 250 24% Fiche 50-000, 82/10/06, 8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recurculation Sys Piping at BMR Plants " Sve list encl DEYOUNG, R C Director's Office. Office of Inspection and Entercement 82/10/14 Consolidated Edison Co of New York 115pp 19810 125 24X Fiche 50-000.82/10/14.8208190238
- DOCKET STN-50-488 PERKINS NUCLEAR STATION, UNIT 1
- O Inspection reports. IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1. "Leaking & Dislodged 1-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/04 Consolidated Edison Co of New York 66pp 15761 250 244 Fiche 50-000, 82/10/06, 8208190233
- B208190238 IE Bulletin 82-03. "Btress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUND, R C Director's Office. Office of Inspection and Enforcement B2/10/14 Consolidated Edison Ca of New York 1155p 15810 125 24% Fiche 50-000, 82/10/14-8208170238
- DOCKET STN-50-489 PERKINS NUCLEAR STATION, UNIT 2

  O Inspection reports, IE Bulletins & correspondence
- B20B190233 IE lnfo Notice 80-35. Suppl i, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards B2/10/06 Consolidated Edison Co of New York 64pp 15741 250 24X Fiche 50-000,82/10/06.8208190233
- 8208190238 IE Bullstin 82-03, "Stress Carrosion Cracting in Thick-Wall. Large-Diameter. Stainless Steel. Recirculation Sys Piping at BMR Plants " Svc list encl DEYGUNG.R C Director's Diffice. Office of Inspection and Enforcement 92/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000. 82/10/14. 8208190238

DOCKET STN-50-490 PERKINS NUCLEAR STATION, UNIT 3

- O Inspection reports, IE Bulletins & correspondence
- B20B190233 lE Info Notice 80-35, Suppl I. "Leaking & Dislodged I-125 Implant Seeds " Svr list encl C088.L I Division of Fuel Facilities, Materials & Safeguards B2/10/04 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000, B2/10/06.8208190233
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick— Hall-Large-Diameter. Stainless Steel. Recirculation Sys Piping at BMR Plants " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238

DOCKET STK-50-491 CHEROKEE NUCLEAR STATION, UNIT 1

- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-12"; Implant Seeds " Svc list encl COBB.L I Division of Foel Facilities, Materials & Bafeguards 82/10/06 Consolidated Edison Co of New York 65pp 15761 850 24% Fiche 50-000,82/10/06,8208190233
- 820B190238 JE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hall-Large-Diameter, Stainless Steel, Recirculation Sys Piging at BMR Plants " Svc list encl DEYOUNG, R C Director's Defice, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fichs 50-000,82/10/14,8208190238

OGCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

- G208190233 IE Info Notice 80-35, Suppl i, "Leaking & Dislodged 1-12h implant Seeds " Svc list encl CD8.L I Division of Fuel Facilities, Materials & Safeguards 62/10/06 Consolidated Edison Co of New York 66pp 15761 250 24% Fichs 50-000.82/10/06.6208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BUR Plants " Svc list encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238

DOCKET STN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3

G Inspection reports. IE Builetins & correspondence

- 8203190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-128 implant Seeds " Svc list encl CORB, L 1 Division of Fuel Facalities, Materials & Safequards 82/10/06 Consol(dated Edison Co of New York 66pp 15761 250 24X Fache 50-000,82/10/06,8208190233
- 8208190238 IE Dulletin 82-03. "Stress Corresion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " SVc list encl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238

DOCKET STN-50-498 SOUTH TEXAS PROJECT. UNIT 1

- A Application/construction stage documents & correspondence
- 8210250358 Requests latest revision to Form NRC-3, "Notice to Employees," per amend of 10CFR19, 30, 40, 50, 60, 70, 72 & 150 to provide employee protection against discrimination as consequence of reporting info to NRC OPREA, G W Houston Lighting & Power Co. 82/08/09 COLLINS, J T Region 4, Office of Director 2pp 15790 341 24X Fiche 50-498, 82/08/09, 8210250358
- 8210250263 Bubmits updated schedulas for const activities to be restarted during remainder of 1982,per util 820514 ltr W/ two oversire charts Aperture cards are evaliable in PDR OPREA.0 W Houston Lighting & Power Co 82/08/30 COLLINS.J T. Region 4. Defice of Director. Bpp. 15791:029. 24X Fiche 50-498.82/08/30.8210250263

- B210040422 Forwards Task Interface Agreement 82-44; complete wiffington for Quadrex Rept re Brown & Root design of project MAR input needs to be generated during Bept 1982; in order for Region 4 to issue final rept in Oct 1982
  HERAOLIAF & Licensing Branch 3 62/08/31 MULHAN & ALL
  EVALUATION Branch PARR: 0 D Auxiliary Systems Branch BERLINGER. C. Core Performance Branch 2pp (1997) 23/ 24/ Fiche 50-498; 82/08/31:0210040422
- 8210250259 Advises that add) safety-related const activity to be restarted in 1982 has been identified since util 620010 [FF] Updated schedule for const activities to be restarted during 1982 enc) Whome oversite chart Aperture card as an PPN OPREA.O W Houston Lighting & Power Co. 62709720 [fig. 5] Fig. 5] Fishe 50-498.82/09/20.8210250259
- B210200075 Forwards info requested at 820722 meeting hospital 1' geobechnical info on essential cooling water pipelines soil profiles boundaries of four low density barifit areas to contaminated backfill GOLDRERG, J. H. Houston Lighting & Power Co. 83/11/12 min. AP. 17 Assistant Director for Licensing 84op 157% 211 '41 Fiche 50-498.82/10/12.8210200075
- 8210200052 Forwards responses to Questions 24t 1 through #41 6 17s to expedite geotechnical review Info will be insurpressed into FBAR amend GOLDBERG, J.H. Housen Lighting & Power Co. 112/10/411 JagsAs-31 Assistant Director for Licensing 77pp 19791 010 741 Fiche 50-498, 82/10/18, 8210200052
- 8210220239 Forwards Revision 0 to "Control Room Design Revise Pett Plan" GLOBERO, J H. Houston Lighting & Power Co. (12/10/m) Fitch Pt. Assistant Director for Licensing 3pp 15775 191 24s Fitch S0-498, 821022031
- ---B210220241 Revision O to "Control Room Design Review Program Plat + Houston Lighting & Power Co | B2/10/11 | 129pp | 157/5 144 Fiche 50-498, 82/10/20, 8210220239
- Q Adjudicatory correspondence
- 8210050241 Proposed opinion, findings of fact, conclusions of law & s in form of partial initial decision Certificate of two eret OUTIERRES, J.M. Hearing Branch 3 82/10/04 21/pp 1550/ 905 . Fichs 50-476, 82/10/04 8210050241
- 8210180172 Memorandum & Order LBP-92-91 granting Cittiens Cunterest About Nuclear Power motion to adopt Citiens for Equitable Utils contentions re Contention 4 & denying motion re Contentions 3-8 American Bridge contentions of Isalessed BECHNOFFER C Atomic Safety and Licensing Board Panel Caffell Citiens Concerned About Nuclear Power, Inc. 17pp 15719 1643 J. Fiche 50-490,82/10/15.8210180172
- 8210210363 Forwards applicant reply to Citizens Concerned Abaul Main Power Inc & NRC proposed findings of Fact & conclusions of Law NEWMAN, J.R. Lowenstein, Newman, Reis, Azelrad & Yoll Parker J. R. Houston Lighting & Power Co. 82/10/18 BCCHMEFILE, C. LANG, J. C. HILL, E.E. Atomic Bafety and Licensing Board Panel & P. 19F&F2, 24X Fishe 50-498, 82/10/18, 8210210363
- --B210210368 Reply to Citizens Concerned About Nuclear Power Inc a warproposed findings of fact & conclusions of law Certificate of Byc encl
  # Houston Lighting & Power Co # Lowenstein Newman Reis Alsin & Toll B2/10/18 Atomic Bafety and Licensing Sears Farst 97pp 15763 241 24% Fichs 50-498.82/10/18.0210210786
- G Inspection reports, IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of the sinuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld first FOIA Exemption 3)
  FELTON, J. H. Division of Rules and Records 82/07/12 UDGLL. R A Critical Mass Energy Project 9pp 15645 027 24%
  Fiche 50-000, 82/07/12, 8210080015
- --B2100B0163 By stematic Assessment of licensee performance mother ry facility evaluation for Aug 1979-Jul 1980 M NRC - No Detailed Affiliation Olven B0/07/31 13sp 13668 079 24X Fiche 50-000.82/07/12,82100B0015
- 8210190419 Forwards IE Insp Repts 50-498/82-14 & 50-499/82-14 to 620823-27 No noncompliance noted.

  MADEN, 6 L Division of Resident, Reactor Project & Engintering Programs 82/09/28 OPREA, 6, W Houston Lighting & Power Ce 28 15741 001 24% Fichs 50-498,82/09/28,8210190413

#### DOCKEIED HEMS

- -82:0190419 IE Insp Repts 50-498/82-14 & 50-499/82-14 on 820823-27 No noncompliance noted Major areas inspected GA program re design engineering procurement & const CROSSMAN.W A . HILL.W H . BOARDMAN.J R Division of Resident, Reactor Project & Engineering Programs 82/09/24 [Ipp 1574] 003 24X Fiche 50-498.82/09/28.82:10190413
- G20B190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBD.L I Division of Fuel Facilities, Materials & Safeguards B2/10/06 Consolidated Edison Co of New York 66pp 19761 250 24x Fiche 50-000: 82/10/06: 8208190233
- G208190236 IE Bulletin B2-03, 'Stress Corrosion Cracking in Thick-Wall, Carge-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York LISPP 15810 125 24X Fiche 50-000.82/10/14.82081970238
- 8210220122 Ack receipt of 820909 ltr informing NRC of staps taken to correct violations noted in IE Insp Rept 50-498/82-02 MABSEN, G L Division of Resident, Reactor Project & Engineering Programs 82/10/14 0 0986A.G W Houston Lighting & Power Co Ip 15777 332 24X Fiche 50-498.82/10/14.8210220122
- --8210220125 Responds to NRC 820811 ltr re violations noted in IE Insp Repts 50-498/82-02 & 50-499/82-02 Corrective actions deficiency reporting procedures revised & employees retrained CREEA G W Houston Lighting & Power Co 82/09/09 COLLINS, J T Region 4, Office of Director App 15777 333 24X Fichs 50-498.82/10/14.8210220122
- 5 Apportable occurrences, LERs & related correspondence
- B210250112 Supplemental deficiency rept re beam to column connection design in containment bldg.per NRC lequest Info expected by B21217 Oroum & Root, inc reanalysis received in Aug & submitted to Bechtel for review CPREA.C W Houston Lighting & Power Co 82/08/19 COLLINS.J T Region 4. Office of Director Rpp 15/87 022 24% Fiche 50-498.82/08/19.8210250112
- 8210050327 Final deficiency rept re possible exceeding of design pressure loading of isolation valve cubicle auxiliary feedwater pump compartment walls in event of feedwater bypass line break Initially reported on 820901 OPREA.O W Houston Lighting & Power Co 82/09/29 COLLINS, J T Region 4. Office of Director 4pp 15610 254 24X Fiche 50-498, 82/09/29, 8210030329
- 32:0250249 Fifth interim deficiency rept re vendor fabricated structural steel Initially imported on BIOLOS Bechtel will assure that surveitlance insp of 100% of all welded matl was or will be performed prior to shipment Next rept by 830509 OPREA.O W Houston Lighting & Power Co B2/10/15 COLLINS.J 1 Region 4. Office of Director 3pp 19788 339 24x Fiche 50-498.82/10/15.8210250249
- 8210260452 Final deficiency rept re HVAC design Instially reported un 810508 Chillers added to existing auxiliary bldg chillers, mixing boxes deleted,make-up air balanced & electrical penetration exhaust sys down-graded CPREA.0 W Houston Lighting & Power Co 82/10/20 COLLING, J T Region 4. Office of Director 14pp 15807 106 24X Fiche 50-498, 82/10/20,8210260452
- DOCKET STN-50-499 BOUTH TEXAS PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- #21025035B Requests latest revision to Form NRC-3, "Notice to Employees." per amend of 10CFR19, 30, 40, 50, 60, 70, 72 & 150 to provide employee protection against discrimination as consequence of reporting info to NRC OPREA G W Houston Lighting & Power Co 82/08/09 COLLINS, J T Region 4. Office of Director 2pp 15790 341 24X Fichs 50-498, 82/08/09, 821025035B
- 8210230263 Submits updated schedules for const activities to be restarted during remainder of 1982, per util 820514 ltr W/tuo oversite charts Aperture cards are available in PDR OFFREA.O W Houston Lighting & Power Co 82/08/30 CULLINS, J T Region 4, Office of Director 8pp 15771 027 24X Fiche 50-498, 82/08/30, 8210250263

- 82:10040422 Forwards Task Interface Agreement 82-44, complete w/review plan for Quadres Rept re Brown & Root design of project NRR input needs to be generated during Sept 1982, in order for Region 4 to issue final rept in Oct 1982 MIRAGLIA, F J Licensing Branch 3 82/08/31 HULMAN, L G Accident Evaluation Branch PARR, O D Auxiliary Systems Branch BERLINGER, C Core Performance Branch 2pp 15597 237 24X Fiche 50-498, 82/08/31, 8210040422
- 9210250259 Advises that addisafety-related constactivity to be restarted in 1982 has been identified since util 820800 ltr Updated schedule for constactivities to be restarted during 1982 encl M/one oversize chart Aperture Card is in PDR OPREA 0 W Houston Lighting & Power Co 82/09/20 COLLINS J T Region 4. Office of Director 9pp 15791 019 24X Fiche 50-498.82/09/20.8210250259
- 8210200075 Forwards info requested at 820722 meeting Submittal includes geotechnical info on essential cooling water pipelines soil profiles boundaries of four low density backfill areas & contaminated backfill GOLDBERG. J. H. Houston Lighting & Power Co. 82/10/12 NOVAK.T. M. Assistant Director for Licensing 84pp 15756 231 24X Fishe 50-498.82/10/12.8210200075
- 8210200052 Forwards responses to Questions 241 1 through 241 6, in order to expedite gentechnical review Info will be incorporated into FSAR amend GOLDEERG. J H Houston Lighting & Power Co 82/10/18 NOVAK, T M Assistant Director for Licensing 77pp 15753 010 24X Fiche 50-498.82/10/18.8210200052
- 8210220239 Forwards Revision O to "Control Room Design Review Program Plan" GOLDBERG, J H Houston Lighting & Power Co 82/10/20 NOVAK, F M Assistant Director for Licensing 3pp 15775 193 24X Fiche 50-498, 82/10/20, 8210220239
- --8210220241 Revision 0 to "Control Room Design Review Program Flan" + Houston Lighting & Power Co 82/10/11 129pp 15775 196 24X Fiche 50-496 82/10/20,8210220237
- G Adjudicatory correspondence
- 8210050241 Proposed opinion, findings of fact, conclusions of law & order in form of partial initial decision Certificate of Svc encl OUTLERREZ. J M Hearing Branch 3 82/10/04 217pp 15607 306 24X Fiche 50-498.82/10/04.8210050241
- 8210180172 Memorandum & Order LBP-82-91 granting Citizens Concerned About Nuclear Power motion to adopt Citizens for Equitable Utils contentions re Contention 4 & denying motion re Contentions 5-B American Orige contentions dismissed BECH-WOEFER, C. Atomic Safety and Licensing Board Panel 82/10/15 Citizens Concerned About Nuclear Power, Inc. 17pp. 15719 148 24% Fiche 50-498, 82/10/15, 8210180172
- 8210210363 Forwards applicant reply to Citizens Concerned About Nuclear Power, Inc & NRC proposed findings of fact & conclusions of law NEWHAN, J R Lowenstein, Newman, Reis, Axelrad & Toll NEWHAN, J R Houston Liphting & Power Co 82/10/18 BECHHOEFER, C, LAMB, J C, HILL, E Atomic Safety and Licensing Board Panel ip 15763 240 24% Fiche 50-498,82/10/18,8210210363
- ---8210210368 Reply to Citizens Concerned About Nuclear Power, Inc & NRC proposed findings of fact & conclusions of law Cortificate of Syc encl
- Q Inspection reports, IE Bulletins & correspondence
- 8210080015 Add1 response to FDIA request for 19 categori nuclear reactor events & safety problems Forwards doculisted in App A Documents in App B completely withheld FOIA Exemption 5)
  FELTON, J M Division of Rules and Records, 82/07/12 Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000, 82/07/12,8210080015
- --B2[Q080163 Systematic assessment of licensee performan facility evaluation for Aug 1979-Jul 1980 + NRC No Detailed Affiliation Given 80/07/31. 15668 079 24% Fiche 50-000. 82/07/12.B210080015
- 8210190413 Forwards IE Insp Repts 50-498/82-14 & 50-499/8 820823-27. No noncompliance noted MADBEN. 9 L Division of Resident, Reactor Project & El Programs 82/09/28. OPREA. 9 W Houston Lighting & Pt 15741 001. 24X Fiche 50-498,82/09/28.8210190413

- --B210190419 IE Insp Repts 50-498/82-14 & 50-499/82-14 on B20823-2/ No noncompliance noted Major areas inspected GA program re design, engineering procurement & const CROSSMAN,W A . HILL,W K . BOARDMAN,J R Division of Resident, Reactor Project & Engineering Programs B2/09/24 11pp 15741 003 24% Fiche 50-498,82/09/28,8210190413
- B208190233 IE Info Notice 80-35, Suppl I, "Leaking & Dislodged I-12% implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards B2/10/06 Consolidated Edison Co of New York 65pp 15761 250 244 Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Sys Piging at BNR Plants "Svz list encl DEYOUNG-R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000-82/10/14.8208190238
- 8210220122 Ack receipt of 820907 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-498/82-02 MADSEN.O L Division of Resident, Reactor Project & Engineering Programs 82/10/14 QPREA.C W Houston Lighting & Power Co ip 15777 332 24X Fiche \$0-498.82/10/14.8210220122
- ~-8210220125 Responds to NRC 820811 ltr reviolations noted in IE Insp Repts 50-478/82-02 & 50-499/82-02 Corrective actions defitiency reporting procedures revised & employees retrained ORREA: G W Houston Lighting & Power Co 82/09/09 Chilling, J C Region A. Office of Director App 15777 333 24X Fiche 50-498.82/10/14,8210220122
- S Reportable occurrences, LERs & related correspondence
- 8210250112 Supplemental deficiency rept re beam to column connection design in containment bldg.per NRC request Info expected by B21217 Brown & Root, Inc reamalysis received in Aug & submitted to Bechtel for review OPREA.0 W Howston Lighting & Power Co 82/08/19 COLLING, J T Region 4, Dffice of Director 2pp 15787 022 24% Fiche 50-498.82/08/19.8210250112
- B210050327 Final deficiency rept re possible exceeding of design pressure loading of isolation valve cubicle auxiliary feedwater pump compartment walls in event of feedwater bypass line break initially reported on B20901 OPREA:0 W Houston Lighting & Power Co B2/09/29 COLLINS, J T Region 4, Office of Director 4pp 15640 254 24X Fiche 50-498, 82/09/27, 8210050029
- 6210250247 Fifth interim deficiency rept re vendor fabricated structural steel Initially reported on 8:0108 Bechtel will assure that surveillance insp of 100% of all welded mati was or will be performed prior to shipment Next rept by 830507 OPREA:Q W Houston Lighting & Power Co 82/10/15 COLLINS, J T Region 4. Office of Director 3pp 15788.339 24% Fiche 50-498.82/10/15.8210250249
- 8210260452 Final deficiency rept re HVAC design Initially reported on B10508, Chillers added to existing auxiliary bldg chillers, mixing boxes deleted, make-up air balanced & electrical penetration exhaust sys down-ganded OPREA-O W Houston Lighting & Power Co 82/10/20 COLLING, J T Region 4, Office of Director 14pp 15807 106 24% Fiche 50-498, 82/10/20, 8210260452
- DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3
- A Application/construction stage documents & correspondence
- 8210180214 Summary of B20831-0702 caseload forecast panel site visit w/util in Satsop. MA re info to use as input to OL review scheduling progress & projected fuel load date. WHEELER, L. Litensing Branch 3 82/09/17 Licensing Branch 3 2pp 15744 113 24X Fichs 50-508,82/09/17.8210180214
- --8209210550 Notification of 820831 & 0901-02 meetings w/util in Sattop, WA to review const progress in order to obtain info for use as input to OL review scheduling process Related matt encl MHEELER.L Licenting Branch 3 82/08/20. MRRAQIA:F Licenting Branch 3 105pp. 14746:117 24X Fichs.50-508.82/09/17. 8210180214
- S210120197 Advises that fuel load date scheduled for Dec 1785, per NRC request Schedules do not preclude achieving fuel load 6 months earlier. Planning details provided basis for discussions w/NRC Caseload Forecast Panel on 820831-0902. BOUCHEY. O D Washington Public Power Supply System 82/10/01 EISENHUT. D. O Division of Licensing 1p. 15651 229 24% Fiche 50-508. 82/10/01.8210120197

- 8210280416 Approves use of ASME Code Case N-249-2, in response to 820921 request Scape of approval limited to use of code case for strap & rivet matts in ITT-Grinnel Figures 215 for stiff clamps
  KERRIGAN, J. D. Licensing Branch 3 82/10/08 FERGUSON, R. L. Washington Public Power Supply System 2pp 15859 358 24X
  Fiche \$0-508, 82/10/08, 82/102804(6
- 8210270012 Forwards responses to FSAR questions transmitted w/NRL B20820 ltr Responses to questions re environ rept will be sant under separate rover BOUCHEY, G D Washington Public Power Bupply System 82/10/2. KERRIGAN, J D Licensing Branch 3 300pp 15815 001 24x Fiche 50-508, 82/10/22, 8210270012
- H General correspondence
- 8210010020 Advises that EPA (Region X) deleted from distribution ii I for FSAR & general info amends EPA informed util that FSAR, energency preparedness plan.fire protection plan & general info not required COUCHEY, G D Washington Public Power Supply System 82/07/2, EISENHUT, D O Division of Licensing 2pp 15565 150 -4X Fiche 50-508. 82/09/22, 8210010020
- K Utility Final Safety Analysis Report (FSAR) & amends
- B210120194 Forwards Amend 1 to FBAR.updating design description torrecting typographical errors
  BOUCHEY.G D Washington Public Power Supply System (\$2/10/06 KERRIGAN.J D Licensing Branch 3 3pp 15657 137 24x
  Fiche 50-508
- --8210120200 Amend 1 to FSAR

  # Washington Public Power Supply System 82/10/31 216/pp
  15657 140 24X Fiche 50-508,82/10/06,8210120194
- G Inspection reports, IE Bulletins & correspondence
- 8210060155 Forwards 1E Insp Repts 50-508/82-17 & 50 509/02 0/ bn 820801-31 & notice of violation StERNBERG, D M Division of Resident, Reactor Project & Inginering Programs 82/09/24 LEDDICK, R S Washington Public Cower tupply System 2pp 15614 056 24X Fiche 50-508.82/09/24.0210000175
- --82(0060157 Notice of violation from insp on 820801-31 20005.R T Division of Resident, Reactor Project & Inginesting Programs 82/09/24 ip 15614 058 24X Fichs 50 508, 82/07/1
- --8210060163 IE insp Repts 50-508/82-17 & 50-509/82-07 on H/0H01 Noncompliance noted on 820810, nonsafety-related Q decking attached to containment bldg safety-related structural attached to containment bldg safety-related structural attached to containment bldg safety-related structural attached to 295-ft level using nonqualified procedure
  ALBERT, W G , DODDS, R T Division of Resident, Reactor Project a Engineering Programs 82/09/22 9pp 15614 QS9 24x
  Fiche 50-508,82/09/24,8210060155
- 8210070158 Ack receipt of 820528 itr informing NRC of steps talen to correct violations noted in IE Insp. Repts 50-508/82-06 & 50-509/82-03
  STERNBERG.D M Division of Resident, Reactor Project & Ingenery, p. Programs 82/10/04 LEDDICK, R. S. Mashington Public Power Investignation of Resident Public Pu
- --8210070161 Responds to NRC 820426 ltr re violations noted in if 1 in Repts 50-508/82-06 5 50-509/82-03 Corrective actions two shutdown cooling Mss placed in care & maint program to insure monthly monitoring of maint on nitrogen purge LEDDICK, R S Washington Public Power Supply System 62/05/-ct BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 4pp 15627 065 24X Fiche 50-508,82/10/04.0210303118
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Bislodged I lea Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safegueria 82/10/06 Consolidated Edison Co of New York 64pp 13761 pto 24X Fiche 50-000-82/10/06.8208190233
- B209170239 JE Bulletin 82-03; "Stress Corrosion Cracking in Thick MalirLarge-Diameter: Stainless Steel, Recirculation Sye Piping at BWR Plants "Sye list encl DEYGUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 13810 125 24X Ficha 50-000,82/10/14,8208190238

- DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5
- a inspection reports. IE Bulletins & correspondence
- 6210060155 Forwards IE Insp Repts 50-508/82-17 % 50-509/82-07 on 820801-31 % notice of violation STERNBERG, D.M. Division of Resident, Reactor Project & Engineering
- STERNOERG, D.H. Division of Resident, Reactor Project & Engineering Programs 62/09/24 LEDDICK, R.S. Washington Public Power Supply System 2pp 13614 056 24% Fiche 30-808.82/09/24.8210060155
- -8210040163 IC Insp Repts 50-508/82-17 & 50-509/82-07 on 820801-31 Noncompliance noted on 820810, nonsafety-related 0 decking attached to containment bldy safety-related structural steel at 395-ft level using nonqualified procedure ALBERT.W G . DOUDES.R T Division of Resident. Reactor Project & Engineering Programs 82/09/22 9pp 15614 059 24X Fichs 50-508,82/09/24,8210060155
- 9210070159 Ack receipt of 820528 ltm informing NRC of steps taken to correct violations noted in IE Insp Repts 50-508/82-06 & 50-509/82-03 SIFINUSERG.D M Division of Resident, Reactor Project & Engineering Programs 82/10/04 LEDDICK,R & Washington Public Power Supply System ip 19627 064 24X (iche 50-508,82/10/04,8210070158
- -02100/0161 Responds to NRC 820426 ltr re violations noted in IE Insp Rept. 90-500/82-06 & 50-509/82-03 Corrective actions two shutdown cooling HXs placed in care & maint program to insure monthly monitoring of maint on nitrogen purge LLDBICK.R S Nashington Public Power Supply System 82/05/28 BISHBP,T W Division of Resident, Reactor Project & Engineering Programs 4pp 85627-065 24X Fishe 50-508,82/10/04,8210070198
- DULKET 50-51 I WPPGS MUCLEAR PROJECT, UNIT 4
- g inspection reports. IE Bulletins & correspondence
- 62100707/B Ack receipt of 820707 ltr informing NRC of steps taken to correct violations noted in insp on 820501-28 SFERMECRO.D M Division of Resident. Reactor Project & Engineering Programs 82/10/04 ROOT.R W Washington Public Power Supply System 1p 15634 017 24k Ficho 50-460.82/10/04.8210070378
- 0210070397 Responds to NRC 020624 lfr re violations noted in IC insp on 020001-20 Corrective actions subcontractor procedures for installation of electrical penetration assemblies submitted & approved by engineer ROOT. R W Hashington Public Power Supply System 82/07/09 BIGHOP.T W Division of Resident, Reactor Project & Engineering Programs 4pp 15634 OIB 24X Fiche 50-460,82/10/04,8210070378
- 8210130415 Ack receipt of 820707 & 30 ltrs informing NRC of steps taken to correct Violations noted in IC insp on 820401-30 STERNBERO, D M Division of Rosident, Reactor Project & Engineering Programs 82/10/06 R00T.R W Mashington Public Power Supply System 1p 15691 319 24% Fiche 50~460,82/10/06,8210130415
- --9210133425 Updates response to NRC B20608 Itr re violations noted in IE insp on 820401-30 Corrective actions local grinding to expose weld root performed on four wolds Cause of undersized welds due to improperly prepared weld bevels ROOT, R W. Mashington Public Power Supply System. 82/07/30 STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 5pp. 15681-320 24X Fichs 50-460.82/10/06.8210130415
- 87]0130402 Responds to NRC 820608 ltr re violations noted in IE inspon 820401-30 Corrective actions local grinding conducted to spose well root & base metal surfaces Partial penetration butt weld undersized RODT.R W Hashington Public Power Supply System 82/07/09 BISHOP.T W Division of Resident. Reactor Project & Engineering Programs 7pp 15681 325 24X Fiche 50~460,82/10/06.8210130415
- S Reportable occurrences, LERs & related correspondence
- 6210070338 Interim deficiency rept re emergency dissel generator governor lube oil cooler initially reported on 820126 Lube oil cooler will be moved to elevation below oil level per Transamerica Delaval instructions & drawings RODs R W Hashing ton Public Power Supply System 82/09/15 SYERNDERO, D M Division of Resident, Reactor Project & Engineering Programs 2pp 15634 071 24X Fiche, 50-440, 82/09/15, 8210070338
- 8210070297 Interim deficiency rept re unsuitability of isoprene method in governor drive coupling elements Initially reported on H20H19 Field change notice issued to implement changeout of element math to neoprene Also reported per Part 21 ROOTLR W Washington Public Power Supply System 62/09/20 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 15634 178 24X Fiche 50-460,82/09/20,8210070297

- 8210070311 Interim deficiency rept re use of lumped mass loads in performance of pipe stress analysis Initially reported on 820305 Parametric studies may resolve trivial mass changes Interim status repts will be provided on semiannual basis ROOT, R W Washington Public Power Supply System 82/09/20 STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 3pp 15634 145 24X Fiche 50-460.82/09/20.8210070311
- DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1
- G Adjudicatory correspondence
- 8210150476 Memorandum & order directing applicants to rept details of status of applications for CPs to ASLB within 30 days of svc of order SMITH.I W Atomic Safety and Licensing Board Panel 82/10/13 Portland General Electric Co ip 15703 047 24x Fiche 50-514.82/10/13.8210150476
- G Inspection reports, IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fiche 50-000,82/10/06.8208190233
- 820B19023B IE Bulletin 82-03. "Stress Corrosion Crecking in Thick-Hall.Large-Diameter.Stainless Steel.Recirculation Sys Piping at BMR Plants " Syc list encl DEYOUNG.R C Director's Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 80-000.82/10/14.820819023B
- DOCKET 50-515 PEBBLE SPRINGS MUCLEAR PLANT. UNIT 2
- Q Adjudicatory correspondence
- 8210150476 Memorandum & order directing applicants to rept details of status of applications for CPs to ASLB within 30 days of svc of order SMITH, I W Atomic Safety and Licensing Board Panel 82/10/13 Portland General Electric Co 1p 15703 047 24X Fiche 50-514, 92/10/13.8210150474
- Q Inspection reports, IE Bulletins & correspondence
- 9208190233 IE Info Notice 80-35, Suppl 1. "Leating & Dislodged I-125 Implant Seeds " Syc list enc! COBB.L I Division of Fuel Facilities, Materials & Safeguards B2/10/06 Consolidated Edison Co of New York 66pp 13761 250 24X Fiche 50-000,82/10/06.8208190233
- 820B19023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall. Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115po 15810-125 24X Piche 50-000, 82/10/14, 820B19023B
- DOCKET STN-50-510 HARTSVILLE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence

- 8210010411 Ack receipt of 820913 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-518/82 08 & 50-520/82-08
  VERRELLI, D. M. Division of Project & Resident Programs 82/09/22 PARRIS. H. G. Tennessee Valley Authority 1p 15572 181 24% Fiche 50-518.82/09/22.8210010411
- --B210010420 Forwards response to NRC B20812 ltr re violations noted in IE Insp Repts 50-518/82-08 & 50-520/82-08 Corrective actions GC investigation rept written to prevent use of protective coatings & PVC conduit covered & stored KAMMER.D S Tennessee Valley Authority 82/09/13 O'REILLY.J P Region 2. Office of Director 3pp 15572 182 24X Fiche 50-518,62/09/22.8210010411
- --8210010426 Forwards IE Insp Repts 50-518/82-08 & 50-520/82-08 on 820720-23 & notice of violation VERRELLID M Division of Project & Resident Programs 82/08/12 PARRIS.H G Tennessee Valley Authority 2pp 15572 185 24X Fichs 50-518, 82/09/22: 8210010411
- --9210010431 Notice of violation from insp on 920720-23 • Division of Project & Resident Programs 82/08/12 ip 15572 187 24X Fiche 50-518,82/09/22,8210010411
- --8210010433 IE Insp Repts 50-518/82-08 & 50-520/82-08 on 820720-23
  Nencompliance noted failure to fullow procedures on storage
  & preventive maint of safety-related matls
  MERRIWEATHER, N . CONLON, T E Division of Engineering & Technical
  Programs 82/08/11 Spp 15572 188 24X Fiche 50-518.82/09/22,
  9210010411
- 8208190233 IE Info Notice 80-35, Suppl 1. "Leaking & Dislodged I-125 Implant Seeds " Swc list enci CD89.L I Division of Fuel Facilities. Materials & Safequards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24x Fiche 50-000.82/10/05.82081970233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall.Large-Diameter, Stainless Steel, Recirculation Sys Piping at SWR Plants " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 80-000, 82/10/14.8208190238
- S Reportable occurrences. LERs & related correspondence
- 8210080247 Third & final deficiency repts to resolution of unanticipated vibratory loading concerns Initially reported on Bili228 Program developed to insure piping sys operate within design parameters Next rept provided by 821217 MILLS, L M Tennessee Valley Authority 82/09/24 0'REILLY, J P Region 2, Office of Director 3pp 15638 104 24% Fiche 50~000,82/09/24,8210080247
- 8210050293 First interim deficiency rept re six sheared motor pinion keys in Limitorque Model 88-0-25 motor operators initially reported on 820830 Valves w/motor operators being tabulated Next rept will be submitted by 821122
  HILLGL M Tennessee Valley Authority 82/09/28 G'REILLY, J.P. Region 2. Office of Director 2pp 15609 070 24X
  Fiche 50-000, 82/09/28, 8210050293
- 9210270328 Second interim deficiency rept re use of nonconservative calculational method to evaluate General Const Spec G-32 spacing violations Initially reported on 620528 Next rept will be sent by 830528 MRLLG,L H Tennessee Valley Authority 82/10/12 G'REILLY, J P Region 2. Office of Director 2pp 15853 064 24% C'-he-50-000, 82/10/12, 8210270328

- 8210260320 First interim deficiency rept re addition of locking device to handwheel operated valves Initially reported on 820916 Const activities deferred Analyses of locking devices continuing Neit rept will be sent by 820310 MILLS.L H Tennessee Valley Authority 82/10/18 0'REILLY.J# Region 2. Office of Director 2pp 15802 359 24X Fichs 50-000.82/10/18.8210260320
- 8210290274 Final rept for Deficiencies B & E & seventh interim rept of Deficiencies A & D re control of procurement activities. Initially reported on 810316 Final corrective actions noted Next rept expected by 830428 MILLS, L M Tennessee Valley Authority 82/10/21 O'REILLY, J.P. Region 2, Office of Director 4pp 15853 143 24% Fiche 50-000, 82/10/21, 8210290274
- DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8210040430 Informs of decision to refund fees remitted w/801()31 application to delete certain requirements from primary water quality monitoring Fees should not be charged in cases where licensee has effective NPDES permit MILLER.H.O. License Fee Management Branch 82/09/21 PANNIEN & Tennessee Valley Authority 1p 15597 263 24X Fiche 50-000.82/09/21.8210040430
- Q Inspection reports. IE Bulletins & correspondence
- 8210150318 Forwards IE Insp Repts 50-518/82-11.50-519/82-1(), 50-520/82-11 & 50-521/82-09 on 820816-18.25 & 0910 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs (52/09/50) PARRIS, M 0 Tennessee Valley Authority 2pp 19705-256, 24x Fiche 50-518.82/09/20.8210150318
- --8210150334 IE Insp Repts 50-518/82-11.50-519/82-10.50 520/82 II to 50-521/82-09 on 820816-18.25 to 0910 No nuncompliance inited Major ereas inspected open items.independent inspective (A-1 & A-2) to 3.50 - 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Distriged 1 p. Implant Seeds " Svt list encl CDSR.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 13/61,000 24% Fiche 50-000.82/10/06.8208190233
- 8208170238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick Wall, Large-Diamster. Stainless Steel, Recirculation Sys Piping at BHR Plants " Syc list enci DEYOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp. 15810 125 24% Fiche 50-000. 82/10/14.8208170236
- S Reportable occurrences. LERs & related correspondence
- 8210290187 Interim deficiency rept re deferral of const activities Initially reported on 820623 Commitments made in rept. audit findings & response to violations deferred until restart of design & const MILLS/L M Tennessee Valley Authority 82/10/14 0'REILLY, J P Region 2, Office of Director in 15853 312 24% Fiche 50-000.82/10/14.8210290187
- DOCKET STN-50-520 HARTSVILLE MUCLEAR PLANT, UNIT 3
- A Application/construction stage documents & correspondence
- 8210040430 Informs of decision to refund fees remitted w/801031 application to delete certain requirements from primary water quality monitoring Fees should not be charged in cases where licensee has effective NPDES permit MILLER.W O License Fee Management Branch 82/07/21 PARRITH I Tennessee Velley Authority ip 15597 263 24X Fiche, 50-000, 82/09/21, 8210040430
- Q Inspection reports, IE Bulletins & correspondence
- 8210150318 Forwards IE Insp Repts 50-518/82-11, 50-519/82-10, 50-520/82-11 & 50-521/82-07 on 820816-18,25 & 0910 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 62/09/20 PARRIS, H G Tennessee Velley Authority 2pp 15705 256 24x Fiche 50-518, 82/09/20, 8210150318

# DOCKETED ITEMS

- --82:0150334 IE Insp Repts 50-518/82-11.50-519/82-10.50-520/82-11 & 50-521/82-09 on 820816-18.25 & 0910 No noncompliance noted Major areas inspected open items, independent insp effort (A-1 & A-2) & site deferral preparation (A-1 & A-2) SCHAPMER. J F. CANTRELL. F S Division of Project & Resident Programs 82/09/20 4pp 15705 258 24X Fiche 50-518.82/09/20, 8210150318
- 8210010411 AC) receipt of 820713 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-518/82-08 & 50-520/82-08 VERRELLI.D M Division of Project & Resident Programs 82/09/22 PARRIS.H G Tennessee Valley Authority Ip 15572 181 24X Fiche 50-518, 82/09/22, 8210010411
- --B210010420 Forwards response to NRC 820812 ltr re violations noted in IE Insp Repts 50-518/82-08 & 50-520/82-08 Corrective actions QC investigation rept written to prevent use of protective coatings & PVC conduit covered & stored MAMMER, D S Tennessee Valley Authority 82/09/13 0'REILLY, J P Region 2, Office of Director 3pp 15572 182 24X Fiche 50-518,82/09/22,8210010411
- --9210010426 Forwards IE lnsp Repts 50-518/82-08 & 50-520/82-08 on B20720-23 & nutice of violation VERRELLI,D M Division of Project & Resident Programs 82/08/12 PARRIS,H G Tennessee Valley Authority 2pp 15572 185 24X Fiche 50-518,82/09/22 8210010411
- --8210010431 Notice of violation from Insp on 820720-23 # Division of Project & Resident Programs 82/08/12 ip 15572 187 24X Fiche 50-518, 82/09/22,8210010411
- --B210010433 IE Insp Repts 50-518/82-08 & 50-520/82-08 on 620720-23 Noncompliance noted failure to follow procedures on storage 1 preventive maint of safety-related matis MERRIMEATHER, N. CONLON, T.E. Division of Engineering & Technical Programs 82/08/11 5pp 15572 188 24% Fiche 50-518,82/09/22, 8210010411
- 0208190233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged I 125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York Adap 15761 2:10 24x Fiche 50-000:82/10/06.8208190233
- 0208190238 lE Bulletin 82~03, "Stress Corrosion Cracking in Thick-Mall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list enci BEYOUNG.R C Director's Office, Office of Inspection and Entercement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000,82/10/14,8208190238
- 3 Reportable occurrences, LERs & related correspondence
- 9210080247 Third b final deficiency repts re resolution of unanticipated vibratory loading concerns initially reported on 911228 Program developed to insure piping sys operate within design parameters Next rept provided by 821217 MILLS.L M Tennessee Valley Authority 82/09/24 0'REILLY, J P Region 2. Office of Director 3pp 15638 104 24X Fiche 50-000, 82/09/24, 8210080247
- 2210050293 First interim deficiency rept re six sheared motor pinion keys in Limitorque Model SB-0-25 motor operators limitially reported on 820830 Valves w/motor operators being tabulated Next rept will be submitted by 821122 MILLS.L M Tennessee Valley Authority 82/09/28 0'REILLY, J P Ragion 2. Office of Director 2pp 15609 070 24X Fiche 50-000.82/09/28.8210050293
- B21029032B Second interim deficiency rept re use of nonconservative calculational method to evaluate General Const Spec G-32 spacing violations initially reported on 82052B Next rept will be sent by 83052B MILLG.L M Tennessee Valley Authority B2/10/12 O'REILLY, J P Region 2. Office of Director 2pp 15853 064 24X Fiche 50-000, 62/10/12, 921029032B
- 9210290187 Interim deficiency rept to deferral of const activities
  Initially reported on 820623 Commitments made in rept.audit
  findings & response to violations deferred until restart of
  design & const
  HILLS.L M Tennessee Valley Authority 82/10/14 O'REILLY, J P
  Region 2, Office of Director ip 15853 312 24X
  Fiche 50-000.82/10/14.8210290187

- 8210290236 Third interim deficiency rept re potentially overstressed embedded plates Initially reported on 820412 Investigation continuing & const activities deferred until sufficient info gathered to determine completion of project MILS.L M Tennessee Valley Authority 82/10/14 D'REILLY, J P Region 2. Office of Director 2pp 15853 227 24X Fiche 50-000, 82/10/14, 8210290236
- 821026032D First interim deficiency rept re addition of locking devices to handwheel operated valves Initially reported on 820916
  Const activities deferred Analyses of locking devices continuing Next rept will be sent by 820310
  MILLS.L M Tennessee Valley Authority 82/10/18 O'RETLLY, J P Region 2, Office of Director 2pp 15802 359 24X
  Fiche 50-000, 82/10/18, 8210260320
- 8210290274 Final rept for Deficiencies 8 & E & seventh interim rept for Deficiencies A & D Te control of procurement activities Initially reported on 810316 Final corrective actions noted Next rept expected by 830428 MILLS.L M Tennessee Valley Authority 82/10/21 O'REILLY. J P Region 2. Office of Director 4pp 15853 143 24X Fiche 50-000.82/10/21,8210290274
- DOCKET BIN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4

  A Application/construction stage documents & correspondence
- B210040430 Informs of decision to refund fees remitted w/B01031 application to delete certain requirements from primary water quality monitoring fees should not be charged in cases where licensee has effective NPDES permit MILLER.W O License Fee Management Branch B2/09/21 PARRIS.H G Tennessee Valley Authority 1p 15597 263 24X Fiche 50-518, 82/09/21, 8210040430
- G Inspection reports, IE Bulletins & correspondence
- 82:015031B Forwards IE Insp Repts 50-518/82-11.50-519/82-10, 50-520/82-11 & 50-521/82-09 on 820816-18.25 & 0910 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/09/20 PARTIS,H 0 Tennessee Valley Authority 2pp 24X Fiche 50-518.82/09/20.821015031B
- --8210150334 IE Insp Repts 50-518/82-11, 50-519/82-10, 50-520/82-11 & 50-521/82-09 on 820816-18, 15 & 0910 No noncompliance noted Major areas inspected open items, independent insp effort (A-1 & A-2) & site deferral preparation (A-1 & A-2) & Site
- 9208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York AApp 15761 280 24X Fiche 50-000,82/10/06,8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall Large-Diameter, Stainless Steel Recirculation Sys Piping at BNR Plants "Svc list encl BEYOUNG.R C Director's Office. Office of Inspection and Enrorcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125. 24% Fiche 50-000, 82/10/14,8208190238
- S Reportable occurrences, LERs & related correspondence
- 8210290187 Interim deficiency rept re deferral of const activities Initially reported on 820623 Commitments made in rept, audit findings & response to violations deferred until restart of design & const MILLS.L M Tennessee Valley Authority 82/10/14 0'REILLY.JP Region 2, Office of Director to 15853 312, 24% Fiche 50-000, 82/10/14.8210290187
- DOCKET 50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8210270158 Summary of 820721 meeting w/applicants in Bethesda.MD re program to investigate May Junction monocline MOON.C W Licensing Branch 4. 82/10/05 Licensing Branch 4 4pp 15876-224. 224 Fiche 50-522,82/10/05.8210270158

- 8 Utility Preliminary Safety Analysis Report. amends
- 8210210337 Forwards Amend 27 to PSAR

  MYERS,R V Puget Sound Power & Light Co 82/10/08 Dffice of
  Nuclear Reactor Regulation, Director 3pp 15764 311 24X

  Fiche 50-522,82/10/08.8210210337
- --8210210399 Amend 27 to PSAR + Poget Sound Power & Light Co 82/10/08 101pp 15764 314 24% Fichs 50-522,82/10/08.8210210337
- 8210260430 Forwards Affidavit of Svc certifying distribution of PSAR Amend 27 to listed persons on 821020 THOMSEN.F T Perkins, Cole. Stone. Olsen & Hilliams 82/10/22 Office of Nuclear Reactor Regulation. Director 3pp 15806 033 24X Fiche 50-522.82/10/22.8210260430
- C Utility Environmental Report (ER), amends & correspondence
- 8210070189 Forwards Amend 7 to application for site certification/environ rept Amend revises info re need-for-power, alternative energy sources, socioeconomics & exclusion area boundary Verification & distribution list encl MYERS, R V Puget Sound Power & Light Co 82/09/16 Office of Nuclear Reactor Regulation, Director 6pg 15634 348 24% Fiche 50-522, 82/09/16, 8210070189
- --8210070193 Amend 7 to application for site certification/environ rept
  \* Puget Sound Power & Light Co 82/09/16 230pp 15634 354
  24x Fiche 50-522,82/09/16.8210070189
- 8210010382 Forwards Affidavit of Svc for Amené é to application for site certification/environ rept THOMSEN,F T. Perkins, Coie, Stone, Olsen & Hilliams 82/09/27 Office of Nuclear Reactor Regulation, Director 3pp 15574 293 24X Fiche 50-525, 82/09/27, 8210010382
- 8210130190 Forwards Affidavit of Svc for Amend 7 to application for site certification/environ rept
  THOMSEN, T Perkins, Coie, Stone, Olsen & Williams 82/10/07
  Office of Nuclear Reactor Regulation, Director 3pp 15674 104
  24X Fiche 50-522,82/10/07.8210130190
- G Adjudicatory correspondence
- 8210050389 Responds to util 820917 first set of interrugatories Certificate of Svc encl Related correspondence BELL,N Coalition for Safe Power 82/09/28 Puget Sound Power & Light Co 4pp 15608 231 24X Fiche 50-522, 82/09/28, 8210050389
- 8210050169 Supplement to petition to intervene. Consisting of contentions & bases for contentions HOVIS, J B Hovis, R L 82/09/29 Atomic Safety and Licensing Board Panel 62pp 15605 052 24X Fiche 30-522, 82/09/29, 8210050169
  - 10050171 Applicant response to Coalition for Bafe Power 820910 first set of interrogatories Cartificate of Byc encl.Related correspondence
    THOMBEN.F T Puget Sound Power & Light Co THOMBEN.F T Perkins,
    Coie. Stone. Olsen & Williams 82/09/29, Coalition for Safe
    Power 34pp 15604 145 24X Fiche 50~522, 88/09/29, 8210050171
    - of interrogatories Certificate of Syc

Federation THATCHER.T.L. Oregon T.L. Thatcher, T.L. 82/10/04. Pp. 15643 268 24X

> bal Fish Commission Indom & order Ise appeal in

THOMSEN, FT Puget Sound Power & Light Co
Coie, Stone, Olsen & Williams 92/10/06
Licensing Appeal Panel 3pp 15680 320
24X Fiche 50-522, 82/10/06,
92/10/30/367

HOLDO498 Response to 820917 first set of interrogatories THOMSEN.F.T Puget Sound Power & Light Co THOMSEN.F.T Perkins, Coie. Stone. Olsen & Williams 82/10/06 Natural Resources Defense Council. 8pp 15683 089 24% Fiche: 50-522;82/10/06.8210130498

Mi0120271 Notice of appearance in proceeding Certificate of Svc encl DEMEY.L S Hearing Branch 3 82/10/08 3pp 15652 314 24X Fiche 50-522,82/10/08,8210120271

- 8210120288 Brief supporting Columbia River Inter-Tribal Fish Commission 820923 appeal of ASLB 820908 memorandum & order denying Columbia petition to intervene Columbia has met injury in fact test Certificate of Svc encl DEWEY.L S Hearing Branch 3 82/10/08 Atomic Safety and Licensing Appeal Panel 20pp 15453 058 24X Fishe 50-522, 82/10/08, 8210120288
- 8210200045 Response to Vakima Indian Nation 820930 supply to pelilian to intervene containing list of contentions Objects to Contentions 4-10 Certificate of Svc encl.

  HIGHERM, F.T. Puget Sound Power & Light Co. THOMSEN, F.T. Perklip.

  Cois. Stone. Clien & Williams 82/10/14 Atomic Safety and Licensing Board Panel 16pp 15756-026 24X Fiche 50 522.
- 8210190373 Notice of withdrawal of appearance in proceeding Certifical of Svc encl
  65 Svc encl
  81ACK.R L. Hearing Branch 3 82/10/15 3pp 1574t 2[1 14x
  Fiche 50-522.82/10/15.8210190373
- B21020005B Response to B20910 first set of production requests
  Certificate of Svc encl Related correspondence
  FRANTZ, S.P. Puget Sound Power & Light Co. FRANTZ, S.P.
  Lowenstein, Neuman, Reis, Aselrad & Toll B2/10/15 Coalition for
  Safe Power 82pp 15753 093 24X Fiche 50-522, 82/10/15, 8210/25050
- 8210220429 Response to Yakima Indian Nation 820930 supplito petition to intervene, setting forth contentions Contentions 1.2.3 to 6 should be admitted & consolidated w/similar contentions Certificate of Svc encl
  DEMEYL 8 Hearing Branch 3 82/10/20 Atomic Bafety and Licensing Board Panel 21pp 15780 190 24X Fichs 50-522,82/10/2010/20498
- H General correspondence
- 8210220434 Requests all parties be informed of Natl Wildlife (edicat & OR Environ Council correct address THATCHER.T L National Wildlife Federation 82/10/19 () #ffire the Secretary of the Commission 1p 15778 269 24X Fiche 50-522, 82/10/19, 8210220434
- G Inspection reports, IE Bulletins & correspondence
- 8208170233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged t La Implant Seeds " Svt list encl
  COSB.L I Division of Fuel Facilities, Materials & Bafeguards
  82/10/06 Consolidated Edison Co of New York Adopt 17/61 a
  24X Fichs 50-000,82/10/06,8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Third Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl BEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fichs 50-000.82/10/14/82001902/30
- DOCKET 50-523 SKAOLT NUCLEAR POWER PROJECT, UNIT 2

  A Application/construction stage documents & correspondence
- 821029015B Summary of 820921 meeting w/applicants in Bethesds.Htl r. program to investigate May Junction monacline HOON.C W Licensing Branch 4 82/10/05 Licensing Branch 4 4pp 15874 224 24X Fichs 50-522.82/10/05.821029015B
- B Utility Preliminary Safety Analysis Report, amends
- 9210210337 Forwards Amend 27 to PBAR
  MYERS,R V Puget Sound Power & Light Co 82/10/08 (Iffice &
  Nuclear Reactor Regulation, Director 3pp 15744 31) 24x
  Fiche 50-522,82/10/08,8210210337
- ~-8210210339 Amend 27 to PSAR 4 Puget Sound Power & Light Co 82/10/08 101pg 15764 134 24X Fiche 50-522,82/10/08,8210210337
- 8210260430 Forwards Affidavit of Svc certifying distribution of Pr Amend 27 to listed persons on 821020 THUMSEN,F T Perkins, Cole, Stone, Olsen & Williams 82/10/22 Office of Nuclear Reactor Regulation, Director 3pp 13806 Op 24X Piche, 50-522, 82/10/22, 8210260430

- Utility Environmental Report (ER), amenda & correspondence
- 10070189 Forwards Amend 7 to application for site certification/environ rept Amend revises info re need-for-power, alternative energy sources, socioeconomics & exclusion area boundary Verification & distribution list encl MYERG, R V Puget Sound Power & Light Co 82/09/16 Office of Nuclear Reactor Regulation, Director 6pp 15634-348 24% Fichs 50-522, 82/09/16, 8210070189
- -8210070193 Amend 7 to application for site certification/environ rept 4 Puget Sound Power & Light Co 82/09/16 250pp 15634 354 24x Fiche 50-522,82/09/16.8210070189
- 2100;03B2 Forwards Affidavit of Svc for Amend 6 to application for site certification/environ rept.

  14MMSENF T Pervins, Coie, Stone, Olsen & Williams B2/09/27

  Orrice of Nuclear Reactor Regulation, Director 3pp 15574 293

  24/ Fiche 50-522,82/09/27,82100103B2
- 3210130190 Forwards Affidavit of Svc for Amend 7 to application for site certification/environ rept
  THOMSEN F T Perkins, Cole, Stone, Olsen & Williams 82/10/07
  Office of Nuclear Reactor Regulation, Director 3pp 15474 104
  24x Fiche 50-522,82/10/07.8210130190
- s Adjudicatory correspondence
- 8\_10050389 Responds to util B20917 first set of interiogatories Certificate of Svc encl Related correspondence BEL1.N Coalition for Safe Power B2/09/28 Puget Sound Power & Light Co 4pp 15608 231 24% Fiche 50-522,82/09/28,8210050389
- 6210090169 Supplement to petition to intervene consisting of contentions A bases for contentions MOVIS, J B. Yakima Indian Nation HoVIS, J B. Hovis, R L. 82/09/25 Atomic Safety and Lirensing Board Panel 62pp 15605-052 24X Fiche 50-522,82/09/29,8210050169
- GZ10050171 Applicant response to Coalition for Safe Power B20910 first set of interrogatories Certificate of Svc entl Related correspondence
  THOMSEN.F T Puget Sound Power & Light Co. THOMSEN.F T Perking,
  Coie. Stone. Olsen & Williams GZ/09/29 Coalition for Safe
  Power 34pp 15604 145 24y Fiche 50-522 BZ/09/29, BZ10050171
- 8210080073 Response to first set of interrogatorium Certificate of Sve encl HATCHER, T.L. National Wildlife Federation THATCHER, T.L. Oregon Environmental Council THATCHER, T.L. Thatcher, T.L. 82/10/04 Pupet Sound Power & Light Co. 9pp. 15443 268 24X Fiche 50-522, 82/10/04, 8210080073
- 8210130498 Response to 820917 first set of interrogatories THOMSEN.F T Puget Sound Power & Light Co THOMSEN.F T Perkins, Cole. Stone. Clsen & Hilliams 82/10/06 Natural Resources Defense Council Bpp 15683 089 24% Fiche 50-522, 82/10/04. 8210130498
- B210120271 Notice of appearance in proceeding Certificate of Svc encl DEUBY.L S Hearing Branch 3 82/10/08 3pp 15652 314 24X Fiche 50-522.82/10/08.8210120271
- \$210120288 Brief supporting Columbia River Inter-Tribal Fish Commission 820923 appeal of ASLB 820908 memorandum & order denying Columbia petition to intervene Columbia has mot injury in fact test Certificate of Svc enc. DENEY.L 8 Hearing Branch 3 82/10/08 Atomic Safety and Licensing Appeal Panel 20pp 15453 058 24X Fiche 50-522, 62/10/08, 8210120288
- 8210200045 Response to Yakima Indian Nation 820730 suppl to petition to intervene, containing list of contentions Objects to Contentions 4-10 Centificate of Svc encil WHOMSEN, FT Puget Sound Power & Light Co. THOMSEN, FT Perkins, Coix, Stone, Clsen & Williams 82/10/14 Atomic Safety and Licensing Board Panel 14pp 15756-026 24X Fiche 50-522, 82/10/14, 8210200045

- 8210190373 Notice of withdrawal of appearance in proceeding Certificate of Svc encl BLACK,R L Hearing Branch 3 82/10/15 3pp 15741 211 24X Fiche 50~522.82/10/15.8210190373
- 8210200058 Response to 820910 first set of production requests
  Certificate of Svc enc! Related correspondence
  FRANTZ.S P Puget Sound Power & Light Co FRANTZ.S P
  Cowenstern.Nowman, Reis. Axeirad & Toll 82/10/15 Coalition for
  Safe Power 82pp 15753 093 24X Ficha 50-522, 82/10/15, 8210200058
- 8210220429 Response to Yakima Indian Nation 820930 supplito petition to intervene setting forth contentions Contentions 1.2.3 & 6 should be admitted & consolidated w/similar contentions Certificate of 5vc encl
  DEWEY.L 8 Hearing Branch 3 82/10/20 Atomic Safety and
  Licensing Board Panel 21pp 15780 190 24X Fiche 50-522.82/10/20,
  8210220429
- H General correspondence
- BR10220434 Requests all parties be informed of Natl Wildlife Federation & OR Environ Council correct address
  THATCHER.T L. National Wildlife Federation 82/10/19 Office of the Secretary of the Commission 1p 15778 269 24X
  Fiche 50-522, 82/10/19, 8210220434
- O Inspection reports. IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Syc list enc! COBB,L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York & App 15761 250 24% Fiche 50-000,82/10/06,8208190233.
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainiess Steel, Recirculation SysPiping at BWR Plants "Syc list encl
  DEYOUNG, R C Director's Office, Defice of Inspection and
  Enforcement 82/10/14 Consolidated Edison Co of New York
  115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 8210180308 Notifies that commitment re accuracy of calibr stds per Amend 9 Page 17 2-56 not acceptable Justification should be provided or 2nd & 3rd paragraphs should be revised MIRAOLIA.F J Licensing Branch 3 82/09/17 VAN BRUNT.E E Arisona Public Service Co 2pp. 15746 355 24X Fiche 50-528,82/09/17.82101803DB
- --- 8209210413 Discusses branch position on Amend 9 to FBAR re revised commitment regarding accuracy of calibr stds Justification must be provided or commitment must be revised in order to be acceptable HAABB, WP Quality Assurance Branch 82/08/31 MIRAGLIA, F. J Licensing Branch 3 2pp 15746 357 24% Fiche 50-528,82/09/17,8210180308
- 8210120025 Discusses organizational arrangement for technical support of facility operation Updated arrangement should be provided by 821115
  KERRIGAN-J D Licensing Branch 3 82/09/23 VAN BRUNT, E E Ariona Public Service Co 2pp 15689.187 24X
  Fithe 50-528,82/09/23.8210120025
- 8210180243 Forwards draft final nonradiological protection plan Comments requested KERRIOAN,J D Licensing Branch 3 82/09/23 VAN BRUNT,E E Florida Power & Light Co 2pp 15746 243, 24X Fiche 50-528,82/09/23,8210180243
- --8210180248 Draft final nonradiological environ protection plan 4 Licensing Branch 3 82709/23 13pp 15746 245 24X Fiche 50-528,82709/23,8210180243
- 8210210026 Forwards request for add1 info to complete review of "Probabilistic Risk Assessment of Tornado Missile Damage to Station UMS" Bachtel Staty 13-MS-10B KERRIGAN.J D Licensing Branch 3 82/09/29. VAN BRUNT, E Ariona Public Bervice Co 4pp 15782 197 24X Fiche, 50-528, 82/09/29, 8210210026
- B210060245 Forwards Revision i to "Pump & Valve Inservice Testing Program.Palo Verde Nuclear Generating Station " VAN BRUNT,E C Arizona Public Service Co 82/10/01 NQVAK.T Division of Licensing 2pp. 15620 243 24% Fiche 50-528,82/10/01,8210060245

- --8210060247 "Pump & Valve Inservice Testing Program, Palo Verde Nuclean Generating Station," Revision 1 \* Arizona Public Service Co 82/08/17 179pp 15620 245 24X Fiche 50-528, 82/10/01-8210060245
- 8210150163 Forwards application to amend CPPR-141.CPPR-142 & CPPR-143, extending const completion date for Unit 1 to 830831 VAN BRUNT, E E Arizona Public Service Co 81/10/12 Office of Nuclear Reactor Regulation, Director 3pp 15706 351 24X Fishe 50-528.82/10/12.8210150163
- --B210150176 Application to amend CPPR-141.CPPR-142 & CPPR-143, extending const completion date for Unit 1 to 830831 VAN DRUMF.E E Arizona Public Service Co B2/10/12 7pp 15704 354 24X Fiche 50-528.82/10/12.8210150163
- B210190717 Requests NRC review results of PWR design analyses to approve renoval of pape whip restraints Meeting w/NRC to discuss request & facilitate exchange of info & questions suggested VAN BRUNT, E.E. Arizma Public Service Co. 82/10/14 NGVAK, T. Assistant Director for Licensing 2pp 15/38 211 24X Fiche 30-528, 82/10/14, 8210190717
- B210190463 Forwards responses to Auxiliary Sys Branch 820929 request for add1 info re probabilistic risk assessment of tornado missile damage to UHS VAN BRUNT, E E Arizona Public Service Co 82/10/15 NOVAK, T H Assistant Director for Licensing 9pp 15740 289 24X Fiche 50-523, 82/10/15, 8210190463
- B210280057 Advises that util will provide comments on draft environ protection plan by 821129

  VAN BRUNT, E E Arijona Public Service Co 82/10/21 NOVAK, T M Assistant Director for Licensing 1p 15837 261 24X Fiche 50-528, 82/10/21, 8210280057
- 8210280139 Advises that util will respond by 821129 to NRC 820929 ltree schedule for resolution of remaining outstanding & confirmatory issues

  VAN BRUNT, E.E. Ariona Public Service Co. 82/19/21 OVAK, T.H. Assistant Director for Licensing (p. 15837-133, 24% Fiche 50-528, 82/10/21, 8210280139
- 8210280199 Forwards Proof of Svc for 821012 application to amend CPPR-141.CPPR-142 & CPPR-143
  VAN BRUNT, E E Arizona Public Service Co 82/10/21 Office of Nuclear Reactor Regulation, Director 3pp 15837 001 24X
  Fiche 50-528
- 82102702:1 Forwards proposed amended pages to FBAR Section 6.2 b, providing Type C testing of valves associated w/Containment Penetrations 44,67 % 77 using air Affidavit encl VAN BRUNT, E E Ariona Public Service Co 82/10/22 NDVAK, T H Assistant Director for Licensing 17pp 15829 318 24X Fiche 30-528,82/10/28,8210270211
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8210210500 Forwards SER. Suppl 3 re OL application W/o encl KERRIGAN.J D Licensing Branch 3 82/09/23 VAN BRUNT.E E Artiona Public Service Cu Jpp 15782 263 24x Fiche 50-528. 82/09/23. 8210210300

ETY EVALUATION REPORT RELATED TO THE OPERATION OF PALO R GENERATING STATION, UNITS 1, 2, AND 3 Docket GO-529, And 50-530 (Arijona Public Service

Regulation, Director NUREG-0857 803

in 13 1 2 3 concerning

0/04 NOVAK.T H 50-528,82/10/04,

octocovers insures or easign mode incorporated into listed drawings to provide two devices in series for adequate primary & backup protection of circuits Mode close SER confirmatory item discussed in Section B 4.3

VAN BRUNT.E E Arizona Public Bervice Co B2/10/25 NOVAK.T M Assistant Director for Licensing. 2pp 15838 356 24X

Fiche 50-528,82/10/25,8210280274

- G Adjudicatory correspondence
- 82:10130417 Notice of corrections to Joint Applicants reply to Pt. Hourihan proposed findings of fact & conclusions of law BISCHOFF, C A Joint Applicants Palo Verde BISCHOFF, C A Bischoff C A 82/10/05 2pp 15680 224 24X Fiche 50-528,82/10/05,
- ---B210130486 Corrected pages to Joint Applicants reply to PL Hourshin proposed findings of fact & conclusions of law Certificate of Svc encl

  # Joint Applicants-Palo Verde B2/10/05 15pp 15680 226 ,4g
- 8210150247 Forwards Suppl 3 to SER W/o encl DEWEY.L S Hearing Branch 3 82/10/13 LAZO.R M . COLE.R C . CALLIHAN, D Atomic Safety and Licensing Board Fanel 1p 15704 357 24% Fichs 50-528.82/10/13.8210150247
- B210150497 Memorandum of law supporting West Valley Agricultural Protection Council Inc petition to intervene Substantial new info only recently discovered Certificate of Svc encl BERLIN.K Affiliation Unknown BERLIN.K Affiliation Unknown B2/10/13 Atomic Safety and Licensing Board Panel 24pp 15712 209 24x Fiche 50-528,82/10/13.B210150499
- --B210150512 Petition of West Valley Agricultural Protection Council. (1) to intervene, request for preparation of supplemental or revised EIA & request for reopening retord Certificate of Svc enc!

  BERLIN,K Affiliation Unknown BERLIN,K Affiliation Unknown 82/10/13 Atomic Safety and Licensing Board Panel 300pp 15713 233 24% Fiche 50-528.82/10/13.8210150499
- 8210150474 Notices of appearance in proceeding Certificate of Svi Birtl BERLIN.K., GERWIN.E.F., LASOTA.J. Affiliation Unknown 82/10/14 App. 15703 043 24X Fichs 50-528,82/10/14,82/0150474
- B210270171 Motion for 2-wk extension of time to answer West Valley
  Agricultural Protection Council. Inc B21013 petition to
  intervene Complete petition not received Certificate of Syc
  enci
  BISCHOFF, C. A. Jaint Applicants-Paid Verde BISCHOFF, C. A. Bischute
  C. A. B2/10/22 Atomic Safety and Licensing Board Panel hpp
  15822 349 24% Fiche 50-528.82/10/22.8210270171
- 8210290297 Response of West Valley Agricultural Protection Countil to Joint Applicants 821022 motion for extension of time to answer Council patition to intervene Ten-day extension should be granted Cartificate of Svc encl
  BERLIN.K Affiliation Unknown 82/10/26 Atomic Safety and Licensing Board Panel Opp (5853 160 24X Fiche 50-528,02/10/26, 82109/297
- 8210280262 Brder granting Joint Applicants 821022 motion for extension of time to answer Mest Valley Agricultural Protection Council, Inc B21014 petition to intervene Joint Applicants have 2 wks after svc of complete petition to file answer LAZO,R M Atomic Bafety and Licensing Board Panel 82/10/27 Joint Applicants-Pale Verde 2pp 15837 310 24X Fichs 50-928,82/10/27,8210280242

#### M Antitrust correspondence

- 8210040292 Forwards page inadvertently omitted from first response to requirements contained in Reg Quide 7 3
  VAN BRONTLE E Arizona Public Service Co 82/09/28 Office of Nuclear Reactor Regulation. Director Rpp 15587 138 24X
  Fichs 50-528.82/09/28.8210040292
- --B210040305 Forwards Bait River Project Agricultural Improvement & Fe District & AZ Public SVc Co revised responses to requirements contained in Reg Quide 9 3 Corrected copy VAN BRUNT.6 E Aritona Public Service Co 82/05/10 Office of Noclear Reactor Regulation: Director 9pp 15587,140 24X Fiche 50-528,82/09/28.8210040292
- G Inspection reports. IE Bulletins & correspondence
- 9210090155 Responds to NRC 811119 ltr re violations noted in IE Inap Rept 50-528/81-12 on 810817-21 Corrective actions procedure for piping sys final inap, WPP/QCI No 2023, deleted & included in other procedures VAN BRUNTLE E Arizona Public Service Co 82/06/16 BISHOP.T W Division of Resident, Reactor Project & Engineering Programs Spp 13640-139, 24x Fichs 50-528,82/06/16.8210080155

i

1

11

- 210060341 Forwards IE Insp Rept 50-528/82-23 on 820823-0917 No noncompliance noted STERIBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/09/23 ANDOGNINI, G C Arizona Public Service Co 2pp 15619 046 24x Fiche 50-528,82/09/23,8210060341
- -8210060345 [F Insp Rept 50:528/82-23 on B20823-0917 No noncompliance noted Hajor areas inspected startup testing, document control, maint, startup GA & sign releases & organization FIGRELLI. G. JOHNSTON, G. YOUNG, T. Division of Resident, Reactur Project & Engineering Programs 82/09/22 Spp 15619 048 44% Fiche 50-528, 82/09/23, 8210060341
- 8210060413 Forwards Relief Request B for exemption from preservice exam requirements, supplementing 820406 relief requests VAN BRUNT. E Arizona Public Service Co 82/10/01 NOVAK, T N Assistant Director for Licensing 3pp 15615 007 24X Fiche 50-528.82/10/01.8210060413
- 8210070210 Provides corrected supplemental response to IE Bulletin BI-02. "Failure of Gate Type Valves to Close Against Differential Pressure" No Westinghouse Flectro Motor Div gate valves used in plant design Twenty-five manhours used VAN BRUNT.E E Arizona Public Service Co 82/10/01 ENGELKEN.R H Region 5. Office of Director 2pp 15634 264 24X Fiche 50-528.82/10/01.8210070210
- 6200170233 IE Info Notice 80-35. Suppl 1: "Leaking & Dislodged 1-125 Implant Seeds " Svc tist encl COBB L I Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolidated Edisjn Co of New York 66pp 15761 2/0 24% Fiche 50-000 82/10/06 8208190233
- 9210100443 Commits to performing guide tube surveillance inspian representative bundles or first reload per NUREO-0852, Section 4 2 3 1 VAN DRUNT. E.E. Arizona Public Service Co. 82/10/06 NOVAK. 1 Assistant Director for Licensing 2pp 15682 013 24X Fiche 50-528.82/10/06.8210130443
- 6210220394 Corrected copy of commitment to perform guide tube wear surveillance this described in NUREG-0832 Section 4 2 3 1, per NUREG-0857 Section 4 2 5 requirement Commitment will be incorporated into neit FSAR amend VAN BRUNT.E E Alizona Public Service Co 82/10/06 NDVAR, [Assistant Director for Licensing 2pp 15779 203 24X Fiche 50-528,82/10/06,8210220394
- 8210250351 Forwards IE Insp. Repts 50-528/82-25,50-529/82-09 & 50-530/82-10 on 820830-0903 % notice of violation STERNBERG, D. M. Division of Resident, Feactor Project & Engineering Programs 82/10/08 VAN BRUNT, F.E. Aftona Public Service Co 200 15790 026 84X Fiche 50-528-82/10/08,8210250351
- --8210250361 Notice of violation from insp on 820830-0903 YOUNG T Division of Resident, Reactor Project & Engineering Programs 82/10/08 2pp 15790 028 24X Fiche 50-528.82/10/08, 8210250351
- --8210250375 IE Insp Repts 50-528/82 25.50-529/82-09 & 50-539/82-10 on 820830-0903 Noncompliance noted 29 inches of weld metal found missing from control room panels & defective instrument repts not prepared ECKMARBI, J H, HERNANDEZ, G, YOUNG, T Division of Resident. Reactor Project & Engineering Programs 82/10/07 App 15790 030 24x Fiche 50-528 82/10/04, 8210250351
- 8210289368 Forwards IE Insp Repts 30-528/82-24,50-529/82-10 & 50-539/82-11 on 820713-0903 No noncompliance noted STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/10/13 VAN BRUNT, E E Arizona Public Service Co 2pp 15345 155 24X Fichs 50-528/82/10/13/8210280368
- ~-B210280372 IE Insp. Repts 50-528/82-26.50-529/82-10 & 50-530/82-11 on 820713 0903 No honcompliance noted Major areas inspected const activities associated w/grouting of Lemporary underground piping & containment post-tensioning VORDERORUEGGEN, YOUNG, T. Division of Resident, Reactor Project & Engineering Programs 82/10/07 12pp 15845 157 24X Fiche 50-528,82/10/13,8210280368
- 8208190238 IE Bulletin 82-03. "Stress Corrosion Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BNR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238

# R Periodic operating reports & related correspondence

- B210120264 Forwards biweekly status rept of independent GA evaluation of Palo Verde Nuclear Generating Stations Units 1,2 & 3 for period 820711-24
  SIMON,W A Torrey Pines Technology B2/10/04 TURLEY.K L Arijuna Public Service Co 15pp 15652 278 24X Fiche 50-528,82/10/04.
  B210120264
- 8210220198 Forwards "Independent QA Evaluation of Palo Verde Nuclear Cenerating Stations Units 1.2 & 3." Blueekly Status Rept 7 for period ending 821008 SIMON, WA Torrey Pines Technology 82/10/18 TURLEY, W. Arizon, Public Service Co. 1p. 19776 211 24X Fiche 50-528,82/10/18, 8210220198
- --B210220244 "Independent GA Evaluation of Palo Verde Nuclear Generating Stations Units 1.2 & 3." Biweekly Status Rept 7 for period ending 82100B + Torrey Pines Technology 82/10/18 14pp 15776 212 24X Fiche 50-528,82/10/18,8210220198
- S Reportable occurrences, LERs & related correspondence
- 8210070321 Final deficiency rept re mounting failures of C-E supplied valve position indicating switches Initially reported on 820525 Nonconformance Rept SE-0487/0542 dispositioned to rework broken brackets Not reportable per IOCFR50 55(e) VAN DRUNT.E E Aritona Public Service Co 82/09/09 STERNBERG.D M Division of Resident, Reactor Project & Engineering Programs App 15634 117 24X Fiche 50-528,82/09/09,8210070321
- 8210070213 Interim Deficiency Rept DER 82-44 re ITT-Darton pressure transmitters failing to meet required overpressure range Initially reported on 820824 C-E issuing purchase order suppl to obtain correct transmitters Next rept by 821118 VAN BRUNT.E E Arizona Public Service Co 82/09/15 STERNBERG.D M Division of Resident, Reactor Project & Engineering Programs 3pp 15634 258 24X Fiche 50-528,82/09/15,8210070213
- B210070227 Requests add1 time to submit Final Deficiency Rept DER B2-9 re thermowells in diese! generator lube oil sys by Cooper Energy not procured to AGME code Initially reported on B20316 Info should be finalized by B21116 VAN BRUNT.E E Arizona Public Service Co B2/09/15 STERNBERG.D M Division of Resident. Reactor Project & Engineering Programs 2pp 15634 281 24X Fiche 50~528,82/09/15.8210070229
- B210070320 Final deficiency rept re weld procedure not prequalified by Ametek-Strain for reactor hat leg pipe stops Initially reported on 800514 Review of documentation revealed no further deviations Item not reportable per 10CFR90 55(e) VAN BRUNT.E E Arisona Public Service Co B2/09/15 STERNBERO.D M Division of Resident, Reactor Project & Engineering Programs Spp 15624 114 24X Fiche 50-528,82/09/15,8210070320
- 8210070337 Interim Deficiency Rept DER 82-45 re unqualified motor operators installed w/C-E/Borg-Harner safety injection sys valves Initially reported on 820326 Motor operators returned to mfg for mod Next rept expected by 821117
  VAN BRUNTLE E Arizona Public Service Co 82/07/15 STERNBERG, D el Division of Resident, Reactor Project & Engineering Programs Upp 13634 068 24X Fiche 50-928,82/09/15,82/0070339
- 8210070374 Final Deficiency Rept DER 82-18 re Westinghouse pump motors Initially reported on 820423 Motors found w/deteriorating epoxy coatings & metal particles in lube oil C-E determined incident not reportable per 10CFR50 35s VAN BRUNT.E E Arizona Public Service Co 82/09/16 STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 5pp 15634 022 24X Fiche 50-528,82/09/16.8210070374
- 8210070384 Final deficiency rept re steam generators loose internal nuts & couplings Nonconformance repts will be dispositioned to repair defects to conform w/C-E drawing requirements Unit 2 & 3 will be inspected for similar defects VAN BRUNT.E E Arizona Public Service Co BZ/09/21 STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs App 15634 055 24X Fiche 50-528,82/09/21,8210070354
- 8210130187 Interim deficiency rept re Dragon Valve Co instrument line check valves seized open by welding heat Initially reported on 820701 Corrective action plan under review Next rept will be provided by 821206
  VAN BRUNT.E E. Arizona Public Service Co 82/09/30 STERNBERG.D M Division of Resident, Reactor Project & Engineering Programs 3pp 13674 131 24X Fiche, 50-528, 82/09/30, 8210130187

- 8210250100 Interim Deficiency Rept BER 82-50 re-potential damage of flexible conduit couplings between auxiliary & control bldgs during seismic event Initially reported on 820910 Bechtel establishing min acceptance criteria Final rept by 821230 VAN BRUNTIE Arizona Public Service to 82/10/08 STERNBERO, DM Division of Resident, Reactor Project & Engineering Programs Sept. 113 282 Fiche 50-528,89-10/08 B210250100. 15787 111, 24X Fiche 50-528,82/10/09,8210250100
- 8210250305 Final Deficiency Rept DER 82-47 re stoom generator 2 pipe support welded to sway struts instead of attached by approved brackets Initially reported on 820905 Beam attachments replaced w/sway strut rear end brackets VAN BRURT, E E Arizona Public Service Co 62/10/08 STERNBERG, D Division of Resident, Reactor Project & Engineering Programs Spp 15790 094 24X Fiche 50-528,82/10/08.8210250305 STERNBERG, D H
- 8210250326 Interim Deficiency Rept DER 82-51 re Pullman-Kellogg pape lining failure in essential cooling water sys Initially reported on 820910 Condition Under evaluation Final cept expected by 821202 WAND BRUNTLE E Arisona Public Service Go 82/10/08 STERNBLE Division of Resident Reactor Project & Engineering Programs 15790 322 24% Fiche 50-528,82/10/08.8210250326 VAN BRUNT, E E 82/10/08 STERNDERG, D M

8210260275 Final Deficiency Rept DER 82-19 re Class IF GE motor control ctr burned out due to damage during testing Noncomformance SE-0567 dispositioned to replace damaged components Test procedures revised providing spec warning re damage VAN BRUNT, E Artiona Public Service Co. 82/10/14 STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 4pp. 15003-222 24% Fiche 50-528,82/10/14.8210260275

SOCKET STN-50-529 PALO VERDE MICLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

- 8210180308 Notifies that commitment re accuracy of calibr stds per Amend 9 Page 17 2-86 not acceptable Justification should be provided or 2nd & 3rd paragraphs should be revised MIRAOLIA.F J Licensing Branch 3 62/09/17 VAN BRUNT.E E Afilona Public Service Go 2pp 15746 395 24X Fiche 50-528, 82/09/17, 8210180308
- ~-8209210413 Discusses branch position on Amend 9 to FSAR re revised commitment regarding accuracy of calibr stds Justification must be provided or cummitment must be revised in order to be acceptable HAASS,WP Guality Assurance Granch 82/08/31 MIRAGLIA.P J Licensing Branch 3 2pp 15746-357 24% Fiche 50-528,82/09/1/, HAASB, N.P.
- 8210120025 Discusses organisational arrangement for technical support of facility operation Updated arrangement should be provided by 821115 KERRIGAN. J B Licensing Branch 3 82/09/23 VAN BRUNT, E E Arizona Public Bervice Co 2pp 15689 187 24X
  Fiche 50-528, 82/09/23, 8210120025
- 8210(80243 Forwards draft final nonradiological protection plan Comments requested

  KERRIGAN, J D Licensing Branch 3 82/09/23 VAN BRUNT, E E

  Florida Power & Light Co 2pp 15746 243 24X

  Fiche, 30-588, 92/09/23, 8210180243
- --B210180248 Draft final honrodiciogical environ protection plan \* Licensing Branch 3, 82/09/23 13pp 15746 245 24X Fiche 50-528,82/09/23,8210180243

"" for addl info to complete review of ant of Tornado Missile Damage to -NB-108 3 82/09/29, VAN BRUNT, E E 15782 197 24X

- 6210060245 Forwards Revision i to "Pump & Valve Inservice Testing Program.Palo Verde Nuclear Generating Station " VAN SRUNT, E E Artrona Public Service Co 82/10/01 NOVAK, T Division of Licensing 2pp 15620 243 24X Fichs 50-528.82/10/01.
- --- 9210060247 "Pump & Valve Inservice Testing Program, Palo Verde Nuclear Generating Station " Seuteton |

15620 245 24%

-142 & CPPR-143,

Office of 24X

- -8210150176 Application to amend CPPR-141.CPPR-142 & CPPR-143, eiterdica const completion date for Unit I to 830831 VAN BRUNT, E.E. Arizona Public Service Co. 82/10/12 7pp 24X Fiche 50-528, 82/10/12, 8210150163
- 8210190717 Requests NRC review results of PWR design analyses to approve removal of pipe whip restraints Meeting w/NRC to discuss request & facilitate exchange of info & questions Suggested

  VAN DRUNT, E E Artiona Public Service Co B2/10/14 NOVAK, 1 H
  Assistant Director for Licensing 2pp 15738 211 24x
  Fiche 50-528, 82/10/14.8210190717
- 8210190463 Forwards responses to Auxiliary Sys Branch 820929 request for add info re probabilistic risk assessment of tornado missile demage to UHS

  VAN DRUNTLE E Arizona Public Service Co 82/10/15 NOVAK, Fil
  Assistant Director for Licensing 9pp 15740 2B9 24x

  Fiche 50~528 82/10/15,82i0190463
- 82(0280057 Advises that util will provide comments on draft environ protection plan by 821129 VAN BRUNTLE E Artiona Public Service Co 82/10/21 NOVAK, Y M Assistant Director for Licensing 1p 15837 261 24X Fiche 50-528.82/10/21.8210280057
- 8210280139 Advises that util will respond by 821129 to NRC 820929 ling reschedule for resolution of remaining outstanding & confirmatory issues
  VAN BRUNT.E E Arizona Public Service Co 82/10/21 {
  Assistant Director for Licensing ip 15837 133 24X
  Fiche 50-528.82/10/21.8210280139 DVAK, T H
- B2102B0199 Forwards Proof of Svc for B21012 application to amend CPPR-141.CPPR-142 CPPR-143 VAN BRUNT, E.E. Arizona Public Service Co. B2/10/21 ... Office Nuclear Reactor Regulations Director. 3pp. 15837 001 ... 24X Fiche 50-528, 82/10/21, 8210280199
- 8210270211 Forwards proposed amended pages to FSAR Section 6.2 6.
  providing Type C testing of valves associated w/Containment
  Penetrations 44.67 & 77 using air Affidavit encl
  VAN BRUNT.E E Arizona Public Service Co 62/10/22 NGVAH.(H Assistant Director for Licensing 17pp 15829-318 24X Fiche 50-528. 82/10/22. 8210270211
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8210210500 Forwards SER.Suppl 3 re OL application W/o encl KERRIGAN,J D Licensing Branch 3 82/09/23 VAN BRUNT,E E Arizona Public Service Co 3pp 15782 263 24X Fiche 50-528,82/09/23,8210210500
- 8210060006 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF PALO TIOUGOUUGA BAFELT EVALUATIUM REPURT RELATED TO THE DPERATIC VERDE NUCLEAR GENERATING STATION UNITS 1.2, AND 3 Docket Nos 50~528.50-529, And 50-530 (Apricons Public Service Company et al ) # Office of Nuclear Reactor Regulation, Director NUREQ-085/ SO3 82/09/30 38pp Available at NRC \$4.75 15636 268 24X Fiche 50-528, 82/09/30, 8210060006
- 8210190315 Advises that position re SER, Section 13 1 2 3 concerning operations superintendent not filled Resume will be forwarded to NRC when position is occupied VAN BRUNT, E E Arizona Public Service Co 82/10/04 NOVAK, T H Division of Licensing 2pp 15742 146 24% Fiche 50-528-82/10/18210190315
- 8210280274 informs of design mods incorporated into listed drawings provide two devices in series for adequate primary & backup protection of circuits Mods close SER confirmatory item discussed in Section 8 4 3

  VAN BRUNT, E. E. Arizona Public Service Co 82/10/25 NOVAK, T M Assistant Director for Licensing 2pp 15838 356 24X

  Fichs 50-528, 82/10/25, 8210280274
- Q Adjudicatory correspondence
- 8210130417 Notice of corrections to Joint Applicants reply to Pt. Hourthan proposed findings of fact & conclusions of law BISCHOFF, C.A. Joint Applicants-Palo Verde BISCHOFF, C.A. Bit C.A. 82/10/05, 2pp 15680 224 24X Fiche 50-528,82/10/05. Bitt
- --8210130486 Corrected pages to Joint Applicants reply to PL Hours proposed findings of fact & conclusions of law Certificate of Byc and 4 Joint Applicants-Palo Verde 82/10/05 15pp 15480 22& Fiche. 50-528, 82/10/05, 8210130417

- 5210150247 forwards Suppl 3 to SER W/o encl DENEYLL S Hearing Branch 3 82/10/13 LAZO,R M . COLE.R F . CALLIHAN D Atomic Safety and Licensing Board Panel ip 15704 337 24% Fithe 50-528,82/10/13.8210150247
- B210150499 Memorandum of law supporting West Valley Agricultural Protection Council. Inc petition to intervene Substantial new info only recently discovered Certificate of Svc encl 3EALIN. K Affiliation Unknown BERLIN.K Affiliation Unknown B2/10/13 Atomic Safety and Licensing Board Panel 24pp 15713 209 24x Fiche 50-528,82/10/13.8210150499
- -8210150512 Petition of West Valley Agricultural Protection Council, Inc to intervene, request for preparation of supplemental or revised EIA & request for reopening record Certificate of Svt entl BERLINA Affiliation Unknown BERLINAK Affiliation Unknown

BERLIN, A Affiliation Unknown BERLIN, K Affiliation Unknown BERLIN

- BERLIN. K. OERMIN.E F. LASUTA. J. Affiliation Unknown 4pp 15703 043 24X Fiche 50-528.82/10/14/8210150474
- 8210270171 Motion for 2-wk extension of time to answer West Valley Agricultural Protection Council/Inc 821013 position to intervene Complete patition not received Certificate of Sycencl

BISCHOFF, C.A. Joint Applicants-Palo Verde BISCHOFF, C.A. Bischoff, C.A. 82/10/22 Atomic Safety and Licensing Board Panel 5pp 15822 349 R4x Fiche 50-528,82/10/22.8210270171

- 8210290277 Response of West Valley Agricultural Protection Council to Joint Applicants 821022 motion for extension of time to answer Council petition to intervene Tenday extension should be granted Certificate of Sec encl EERLIN.K. Affiliation Unknown 82/10/26 Atomic Safety and Licensing Board Panel App 15853 160 24% Fiche 50-528.82/10/26, 8210270270277
- 8210280262 Order granting Joint Applicants 821022 motion for extension of time to answer Hest Valley Agricultural Protection Council Inc 821014 petition to intervene Joint Applicants have 2 was after sec of complete petition to file answer 1A20.8 H Atomic Safety and Licensing Board Panel 82/10/27 Joint Applicants-Palo Verde 2pp 15837 310 24% Fiche 50-528.82/10/27,8210280262

#### M Antitrust correspondence

- 8210040292 Forwards page inadvertently omitted from first response to requirements contained in Reg Quide 9 3 VAN BRUNT,E E Arizona Public Service Co 82/09/28 Office of Nuclear Reactor Regulation, Director 2pp 15587 138 24X Fiche 50-528, 82/09/28, 8210040292
- --8210040305 Forwards Salt River Project Agricultural Improvement & Power Bistrict & AZ Public Svc Co revised responses to requirements contained in Reg Guide 9 3 Corrected copy VAN BRUNT.E E Arizona Public Bervice Co 82/05/10 Office ut Ruclear Reactor Regulation, Director 9pp 15587 140 24X Fiche 50-528,82/09/28,8210040292
- O Inspection reports: IE Bulletins & correspondence
- 521007021Q Provides corrected supplemental response to IE Bulletin B1-02. "Failure of Gate Type Valves to Close Against Differential Pressure" No Hestinghouse Electro Motor Div gate valves used in plant design Tuenty-five Manhours used VAN BRUNT, E. Arizona Public Service Co. 62/10/01 ENGELKEN, R. H. Region 5. Office of Director 2pp 15634 264 24X Fiche 50-528, 82/10/01, 8210070210
- 8208190833 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged I-125 Inplant Seeds " Svc list encl COBS-L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24/ Fiche 50-000,82/10/06,8208190233
- 9210250351 Forwards IE Insp Repts 50-528/82-25,50-529/82-09 & 50-530/82-10 on 820830-0903 & notice of violation STERNBERO, DM Division of Resident, Reactor Project & Engineering Programs 82/10/08 VAN BRUNT, E E Arizona Public Service Co 2pp 15790 026 24X Fiche 50-528,82/10/08,8210250351
- --821025036f Notice of violation from insp on 920830-0903 YOUNG:T Division of Resident, Reactor Project & Engineering Programs, 82/10/08 2pp 15790 028 24X Fiche 50-528,82/10/08, 8210250351

- --8210250375 IE Insp Repts 50-528/82-25.50-529/82-09 & 50-530/82-10 on 820830-0903 Noncompliance noted 27 inches of weld metal found missing from control room panels & defective instrument repts not prepared ECKHCARDT. J H. HERNANDEZ, G. YOUNG, T. Division of Resident, Reactor Project & Engineering Programs 82/10/07 App 15790 030 24X Fiche 50-528, 82/10/08, 8210250351
- 8210280348 Forwards IE insp Repts 50-528/82-24.50-529/82-10 & 50-530/82-11 on 820713-0903 No noncompliance nated STERNBERG, D M Division of Resident. Reactor Project & Engineering Programs, 82/10/13 VAN BRUNT, E Arizona Public Service Co 2pp 15845 155 24X Fiche 50-528,82/10/13.8210280368
- --8210280372 IE Insp Repts 50-528/82-26,50-529/82-10 & 50-530/82-11 on 820713-0703 No noncompliance noted Major areas inspected const activities associated w/gouting of temporary underground piging & containment post-tensioning VORDERBRUEOGEN, YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/10/07 12pp 15845 157 24X Fiche 50-528,82/10/13,8210280368
- B20B190238 IE Bulletin B2-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Flants " Svc list encl DEYOUNO, R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15B10 125 24X Fiche 50-000,82/10/14,8208190238
- R Periodic operating reports & related correspondence
- 8210120264 Forwards biweekly status rept of independent OA evaluation of Palo Verde Nuclear Oenerating Stations Units 1,2 & 3 for period 820911-24 SIMON-W A Torrey Pines Technology 82/10/04 TURLEY, K.L. Arizona Public Service Co. 15pp. 15452-278 24X Fiche 50-528,82/10/04,8210120244
- 8210220198 Forwards "Independent DA Evaluation of Palo Verde Nuclear Generating Stations Units 1.2 & 3." Biweekly Status Rept 7 for period ending 821008 SIMDMAN A Torrey Pines Technology 82/10/18 TURLEY.K L Arizona Public Service Co 1p 15776 2(1 24X Fiche 50-528,82/10/18, 8210220198
- --8210220244 "Independent OA Evaluation of Palo Verda Nuclear Generating Stations Units 1.2 & 3." Biweekly Status Rept 7 for period ending 821008 \* Torrey Pines Technology 82/10/18 14pp 15776 212 24X Fiche 50-528.82/10/18.8210/20198
- S Reportable occurrences. LERs & related correspondence
- B210070391 Interim Deficiency Rept DER B2-43 re improperly crimped termination lugs on Comsip main control panels Initially reported on B20B13 Extensive investigation & evaluation underway Final rept expected by B21212
  VAN BRUNT.E E Arizona Public Service Co 82/09/09 STERNBERO.D M Division of Resident, Reactor Project & Engineering Programs 3pp 18663 343 24x Fichs 50-929, 82/09/09, 8210070391
- 8210070229 Requests add1 time to submit Final Deficiency Rept DER 82-9 re thermowells in diesel generator lube oil sys by Cooper Energy not procured to ASME code Initially reported on 820314 Info should be finalized by 821114 VAN BRUNT.E E Arizona Public Service Co 82/07/15 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 15634 281 24X Fithe 50-528,82/09/15,8210070229
- 8210070320 Final deficiency rept re weld procedure not prequalified by Amatek-Straza for reactor hot leg pipe stops Initially reported on 820514 Review of documentation revealed on further deviations I tem not reportable per iOCFRSO SSI(s) VAN BRUNTLE E Arizone Public Service Co 82/09/15 SIERNBERG, D M Division of Resident, Reactor Project & Engineering Programs Upp 15634 114 24X Fiche 50-526.82/09/15.8210070320
- 8210070339 Interim Deficiency Rept DER 82-45 re unqualified motor operators installed w/C-E/Borg-Marner safety injection sys valves Initially reported on 820826 Motor operators returned to mfg for mod Next rept expected by 82/117

  VAN BRUNTLE E Arizona Public Service Co 82/09/15, SYERNBERG,) N Division of Resident, Reactor Project & Engineering Programs 3pp 15634 068 24X Fiche 50-528,82/09/15,8210070339
- 8210130495 Final deficiency rept re low pressure safety injection & containment spray pump casing hold-down bolts under-torqued Condition determined not regortable per IOCFRSS 55(e) VAN BRUNT, E E Arizona Public Service Co 82/09/29 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs. 4pp 15682 165 24X Fiche 50-529,82/09/29,8210130495

- 8210130544 Revised interim deficiency rept re Pullman pipe for main feedwater lines w/multiple linear indications or leminations Final rept will be submitted by 821123 VAN DRUNT,E E Arizona Public Service Co 82/09/30 STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs App 15492 283 24% Fichs 50-529,82/09/30,8210130544
- DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8210180308 Notifies that commitment re accuracy of calibr stds per Amend 9 Page 17 2-56 not acceptable Justification should be provided or 2nd & 3rd paragraphs should be revised MIRAGLIA,F J Licensing Branch 3 82/09/17 VAN BRUNT,E E Arizona Public Service Co 2pp 15746 355 24X Fiche 50-528.82/09/17,8210180308
- --8209210413 Discusses branch position on Amend 9 to FSAR re revised eutelutes discusses premier possision on Ameno y to PMAK me r commitment regarding accuracy of callibr stds Justification must be provided or commitment must be revised in order to be acceptable HAASS. W.P. Quality Assurance Branch 82/08/31 MIRAGLIA.F.J. Licensing Branch 3 2pp 15746 357 24X Fiche 50-528,82/09/17.
- 82:0120025 Discusses organizational arrangement for technical support of facility operation Updated arrangement should be provided by 821115 KERRIGAN.J D. Licensing Branch 3 82/09/23 VAN BRUNT.E.E. Articona Public Service Co. 2pg. 15689 187 24X Fiche 50-528, 82/09/23, 8210120025
- 9210190243 Forwards draft final nonradiological protection plan Comments requested KERRIGAN, J D Licensing Branch 3 82/09/23 VAN BRUNT, E E Florida Power & Light Co 2pp 15746 243 24X Fiche 50-528, 82/09/23, 8210180243
- ---82(0180248 Draft final nonradiological environ protection plan + Licensing Branch 3 B2/09/23 13pp 15746 245 24X Fichs 50-528, 82/09/23, 8210180243
- 8210210026 Forwards request for addl info to complete review of Probabilistic Risk Assessment of Tornado Hissile Damage to Station UHS." Bechtel Study 13-NS-108 KERRIGAN, J D Licensing Branch 3 B2/09/29 VAN BRUNT, E E Arizona Public Service Co 4pp 15782 197 24X Fiche 50-528, B2/09/29, B210210026
- ctubor240 Forwards Revision i to "Pump & Valve Inservice Testing Program,Palo Verde Nuclear Generating Station " VAN BRUNT.E E Artrona Public Service Co 82/10/01 NOVAK,T Division of Licensing 2pp 15620 243 24% Fiche 50-528.82/10/01. 8210060245 8210060245 Forwards Revision 1 to "Pump & Valve Inservice Testing
- --B210050247 "Pump & Valve Inservice Testing Program, Palo Verde Nuclear Generating Station." Revision 1 \* Arizona Public Service Co 62/08/17 179pp 15620 245 Fiche 50-528,82/10/01 8210060245

- 8210280057 Advises that util will provide comments on draft environ protection plan by 821129 VAN BRUNT, E.E. Arizona Public Service Co. 82/10/21 NOVAK, I N Assistant Director for Licensing ip 15837 241 Fiche 50-528, 82/10/21, 8210280057
- 8210280139 Advises that util will respond by 821129 to NAC 820929 It: re schedule for resolution of remaining outstanding & confirmatory issues

  VAN BRUNT, E E Arizona Public Bervice Co B2/10/2:
  Assistant Director for Licensing 1p 15837 133
  Fichs 50-528, 82/10/21, 8210260139 82/10/21 37 133 24X DVAK, F R
- 8210280199 Forwards Proof of Svc for 821012 application to amend CPPR-141, CPPR-142 & CPPR-143

  VAN BRUNT, E. E. Arizona Public Service Co. B2/10/21

  Nuclear Reactor Regulation, Director. Jpp. 15837 001

  Fiche 50-528, 82/10/21, 8210280199 Office of
- 8210270211 Forwards proposed amended pages to FSAR Section & 2 &. providing Type C testing of valves associated w/Containment Penetrations 44.67 & 77 using air Affidavit encl VAN BRUNT, E.E. Arizona Public Service Co. 82/10/22 NGVAI Assistant Director for Licensing 17pp 15829 318 24X NOVAK, 7 II Fiche 50-528, 82/10/22, 8210270211
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8210210500 Forwards 9ER, Suppl 3 to 0L application W/o entl KERRICAN, J D. Licensing Branch 3 82/09/23 VAN BRUNT. Artizona Public Servica Co. 3pp 15782 263 24X Fiche 50-528, 82/09/23, 8210210500 VAN DRUNT, E E
- 8210060006 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF PAIG VERDE NUCLEAR GENERATING STATION. UNITS 1.2. AND 3 Docket Nos 50-528,50-529, And 50-530 (Arizona Public Service Company.et al 1 \*\* Office of Nuclear Reactor Regulation, Director NUR 82/09/30 38pp Available at NRC \$4 75 15636 268 Fiche 50-528,82/09/30,8210060006 NUREO-0057 501
- evolves advises that position re SER, Section 13 1 2 3 concerning operations superintendent not filled Resume will be forwarded to NRC when position is occupied VAN BRUNT, E E Artiona Public Service Co 82/10/04 NGVAK, T II Division of Licensing 2pp 15742 144 24X Fiche 50~520.62/10/04, 82/0190315 8210190315 Advises that position re SER, Section 13 1 2 3 concerning
- 8210280274 Informs of design mods incorporated into listed drawings to provide two devices in series for adequate primary b backup protection of circuits Mode close SER confirmatory item discussed in Section B 4 3 officiated in Section 8 4 3 VAN BRUNT, E E Ariiona Public Service Co B2/10/25 NC Assistant Director for Licensing 2pp 15838 356 24% Fiche 50-528,82/10/25,8210280274
- G Adjudicatory correspondence
- 8210130417 Notice of corrections to Joint Applicants reply to Pl Hourthan proposed findings of fact & conclusions of law BISCHOFF, C A Joint Applicants-Palo Verde BISCHOFF, C A B C A 82/10/05 2pp 15680 224 24X Fiche 50-528, 82/10/05. 8210130417
- --8210130486 Corrected pages to Joint Applicants reply to Pt Hourihan proposed findings of fact & conclusions of law Certificate of Syc entl
  - 4 Joint Applicants-Palo Verde 82/10/05 15pp 15680 226 24; Fiche 50-528,82/10/05,8210130417
- 8210150247 Forwards Suppl 3 to SER W/o encl DENEY, L S Hearing Branch 3 82/10/13 LAZO,R M . COLE,R F . CALLIHAN, D Atomic Safety and Licensing Board Panel Lp 15704 357 24% Fiche 50-528,82/10/13,8210150247
- 8210150499 Memorandum of law supporting West Valley Agricultural Protection Council, Inc. petition to intervene Bubstantial new info only recently discovered Certificate of Svc encl
  BERLIN, K Affiliation Unknown, BERLIN, K Affiliation Unknown BERLIN, K Affiliation Unknown BERLIN, C Affiliation Unknown BERLIN, Affiliation Unknown
- --8210150512 Petition of West Valley Agricultural Protection Council,: to intervene, request for preparation of supplemental or revised EIA & request for reopening record Certificate of Syc encl BERLIN, K Affiliation Unknown BERLIN, K Affiliati B2/10/13 Atomic Safety and Licensing Board Panel 18713 233 24X Fichs 50-529,82/10/13.8210150499 BERLIN, K 82/10/13 Affiliation Unknown 300pp

## DOCKETED ILEMS

- 6210150474 Notices of appearance in proceeding Certificate of Svc enc) BERLIN.K., GERMIN.E.F., LASOTA, J. Affiliation Unknown 82/10/14 4pp 15703 G43 24X Fiche 50-528,82/10/14,8210150474
- 8210270171 Motion for 2-wk extension of time to answer West Valley Agricultural Protection Council, Inc 821013 petition to intervene Complete petition not received Certificate of Sycenci BISCHOFF, C A Joint Applicants-Palo Verde BISCHOFF, C A B2/10/22 Atomic Safety and Licensing Board Panel Syp 13822 347 24X Fiche 50-528 82/10/22,82102/0171
- 9210290297 Response of Hest Valley Agricultural Protection Council to Joint Applicants 821022 motion for extension of time to answer Council petition to intervene Ten-day extension should be granted Certificate of Suc encil BERLINIX Affiliation Unknown 82/10/26 Atomic Safety and Licensing Board Panel 6pp 15853 160 24X Fiche 50-528,82/10/26,87/0290297
- 8210280262 Order granting Joint Applicants 821022 motion for extension or time to answer West Valley Agricultural Protection Countil Int 821014 petition to intervene Joint Applicants have 2 wks after svr of complete petition to file answer LAZO.R M Atomic Safety and Licensing Board Panel 82/10/27 Joint Applicants-Paio Verde 2pp 15837 310 24X Fiche 50-528.82/10/27.8210280262
- M. Antitrust correspondence
- GRICO40292 Forwards page inadvertently omitted from first response to requirements contained in Reg Ouide 9-3
  VAN BRUNTLE E Arizona Public Service Co 82/09/28 Office of Nuclear Reactor Regulation, Director 2pp 15587-138 24X
  Fiche 50-528.82/09/28.8210040292
- --0210040305 Forwards Salf Rive: Project Agricultural Improvement & Power District & AZ Public Svc Co revised responses to requirements contained in Reg Guide 9 3 Corrected copy VAN BRUNT.E E Arizona Public Service Co 82/05/10 Office of Huclear Reactor Regulation. Disector 9pp 1558/140 24X Fiche 50-528, 82/09/28, 8210040292
- @ Inspection reports, IE Bulletins % correspondence
- 6216070210 Provides corrected supplemental response to 1E Bulletin BI-G2. "Failure of Gate Type Valves to Close Against Differential Pressure." No Westinghouse Electro Motor Div gate valves used in plant design Twenty-five Manhours used VAN BRUNT, E.E. Arizona Public Service Co. 82/10/01 ENGELKEN R II Region 5. 0ffice of Director. 2pp. 15634-264. 24X Fiche 50-528.82/10/01.8210070210
- 8208170233 IE Info Notice 80-35, Suppl I, "Leaking & Dislodged I-12; Implant Seeds ' Svc list encl C088.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 2hD 24/
- 8210250351 Forwards IE Insp Repts 50-528/82-25.50-529/82-09 & 50-530/82-10 on 820830-0903 & notice of violation SERN/BERG. D M Division of Resident, Reactor Project & Engineering Programs 82/10/08 VAN SRNNT, E C Artiona Public Service Co 2pp 15790 026 24% Fiche 50-528.82/10/08.8R10250351
- --E2(0250375 IE Insp Repts 50-528/82-25,50-529/82-09 % 50-530/82-10 un 820830-0903 Moncampliance noted 29 inches of weld metal found missing from control raom panels & defective instrument repts not prepared ECKMARDI, H . HERNANDEZ, G . YOUNG, T Division of Resident. Reactor Project & Engineering Programs 82/10/07 App 15790 030 24% Fiche 50-528,82/10/08,8210250351
- 8210280368 Forwards IE Insp Repts 50-528/82-26.50-529/82-10 & 50-530/92-(1 on 820713-0903 No noncompliance noted STERNBERG.D M Division of Resident, Reactor Project & Engineering Programs 82/10/13 VAN BRUNT, E E Arizona Public Service Co 2pp 15845 155 24X Fishe 50-528-82/10/13-8210280368
- --8210280372 IE insp Repts 50-528/82-26.50-527/82-10 & 50-530/82-11 un 820713-0903 No noncompliance noted Major areas inspected const activities associated w/grouting of temporary underground piping 5 containment post-tensioning VORDERBRUEGGEN, YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/10/07 12pp 15848 137 24X Fiche 50-528.82/10/13.8210280368

- 820819023B IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list enct DEYOUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000, 82/10/14,8208190238
- R Periodic Operating reports & related correspondence
- 8210120264 Forwards biweekly status rept of independent QA evaluation of Palo Verde Nuclear Generating Stations Units 1.2 & 3 for period 820911-24
  SIMON W A Torrey Pines Technology 82/10/04 TURLEY, K L Arizona Public Service Co 15pp 15652 278 24X Fiche 50-528,82/10/04,8210100264
- 8210220198 Forwards "Independent GA Evaluation of Palo Verde Nuclear Generating Stations Units 1.2 & 3." Biweekly Status Rept 7 for period ending 821008 SIMON,N A Torrey Pines Technology 82/10/18 TURLEY,N L Arizon, Public Service Co 1p 15776 211 24X Fiche 50-528,82/10/18.
- --B210220244 "Independent QA Evaluation of Palo Verde Nuclear Generating Stations Units 1.2 & 3." Biweekly Status Rept 7 for period ending 82100B \* Torrey Pines Technology 82/10/18 14pp 15776 212 24X Fichs 50-528,82/10/18,821022019B
- S Reportable occurrences. LERs & related correspondence
- 8210070219 Interim Defictency Rept DER 82-44 re ITE-Goold load ctrs w/improperly crimped ampere termination lugs Initially reported on 820813 Bechtel pursuing matter w/Goold Brown Boveri to determine disposition Next rept by 821207 VAN BRUNT.E E Arizona Public Service Co 82/09/09 SIERNBERG.D M Division of Resident, Reactor Project & Engineering Programs 2pp 15637 163 24X Fiche 50-530.82/09/09.8210070219
- 8210070227 Requests add1 time to submit Final Deficiency Rept DER 82~9 re thermowells in diosel generator Tube oil sys by Cooper Energy not procured to ASME code Instituting reported on 820316 Info should be finalized by 821116 VAN BRUNT, E. E. Arizona Public Service Co. 82/07/15 STERNBERG, D. M. Division of Resident. Reactor Project & Engineering Programs 2pp 15634 281 24X Fiche 50-528 82/07/15 8210070229
- 6210070320 Final deficiency sept re weld procedure not prequalified by Ametek-Straza for reactor hot leg pipe stops initially reported on 820814 Review of documentation revealed no further deviations item not reportable per 100FRSD 55(e) VAN DRUNT, E E Arziona Public Service Co 82/09/15 STERNBERG, D N Division of Resident, Reactor Project & Engineering Programs 3pp 15634 114 24X Fiche 50-528,82/09/15,8210070320
- 8210070339 Interim Deficiency Rept DER 82-45 re Unqualified motor operators installed w/C-E/Dorg-Warner safety injection systalves Initially reported on 820826 Motor operators returned to mfg for mod Next rept expected by 821117

  VAN BRUNT, E E Arizona Public Service Co 82/09/15 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs Opp 15634 048 24X Fiche 50-528,82/09/15,8210070339
- 8210130446 Final Deficiency Rept DER 81-55 re const svc water line leak under auxiliary bidg Initially reported on 820108 Foundation of auxiliary bidg not adversely affected Ali temporary air, water & gas lines near Category I bidgs taken out of svc VAN BRUNT, E E Aritona Public Bervice Co. 82/07/29 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs App 15682 015 24X Fiche 50-530.82/07/29.8210130446
- B210130491 Interim deficiency rept to Pullman 24-inch pipe spools winternal surface indications violating min wall thickness Initially reported on 820831, Bechtel Engineering investigating cause Final rept will be submitted by 821119 VAN BRUNT, E E Arizona Public Service Co 82/09/30 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 15682 115 24X Fiche 50-530,82/09/30,8210130491
- B210]30544 Revised interim deficiency rept to Pullman pipe for main feedwater lines w/multiple linear indications or laminations final rept will be submitted by B21123 VAN ORUNT, E E Arizona Public Service Co B2/09/30 STERNBERO.D M Division of Resident, Reactor Project & Engineering Programs App 15482,283 24% Fiche 50-529,82/09/30.8210130544

#### DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

- A Application/construction stage documents & correspondence
- 8210120103 Addl response to FDIA request for nine categories of records generated by present NRC Commissioners, primarily Chairman Palladino & Commissioner Roberts & White House Forwards App B documents

  FELTON, J H Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project 3pp 15490 117 24X

  Fiche 50-000, 82/07/12, 8210120103
- --8210120140 Agrees w/recommendation that Commission adopt modified DDF schedule circulated at 811216 meeting Forwards changes to schedule for Commission review of Section 50 12 request for CRBR ROBERTS, T M Commissioners 81/12/21 PALLADING, N, GILINSKY, V, BRADFORD, J Commissioners 2pp 15690 133 24X Fiche 50-000,82/07/12.8210120103
- --9210120143 Db jects to action outlined in Commissioner Gilinsky 811221 memo re CRBR licensing exemption ROBERTS, T H Commissioners 81/12/22 PALLADINO,N, GILINSKY,V, BRADFORD,J Commissioners 2pp 15690 135 24% Fiche 50-000,82/07/12,8210120103
- 8210070029 Partial response to FDIA request for documents re CRBR E15 & all comments, evaluations & documents from BNML re EIS
  Forwards documents listed in App A
  FELTON.J M Division of Rules and Records 82/07/16 WEISS,E R
  Harmon & Weiss 8pp 15648 004 24X Fiche 50-537,82/07/16.
  R210070029
- --B210070039 Forward: updated schedule for CRER environ review HURT, D. NRC No Detailed Affiliation Given 82/04/29 MULLEN, S. GASKIN, C. JUNES, B. NRC No Detailed Affiliation Given 2pp 15648 014 24% Fiche 50-537, 82/07/16, 8210070029
- --B2(0070070 Discusses lead ofc responsibilities for CRBR fuel cycle environ review Overall schedule should be established for NMSS for inclusion ufexecutive operating plan DAVIS, J G NRC No Detailed Affiliation Given B2/02/12 CUNNINGHAM, R E NRC NO Detailed Affiliation Given 2pp 15648 028 24X Fishe 50-537, 82/07/16.8210070029
- --B210070071 Advises that continued delay of DDE environ input will result in schedule compression for CRBR fuel cycle environ review DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director B2/02/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 15448 030 24X Fiche 50-537, 82/07/14, 8210070029
- --8210070084 Requests contentions for CRBR licensing which have implications in areas of fuel cycle, safeguards & waste mpt discussed during 810906 meeting LONENGERG, H. Office of Nuclear Material Safety & Safeguards, Director 81/10/09 CHECK.P. S. Clinch River Breeder Reactor Program Office 3pp 15648 033 24% Fiche 50-537, 82/07/16, 8210070029
- --8210070089 Ack receipt of 811020 memo re CP review schedule Severe problems in meeting deadlines anticipated due to time constraints & personnel limits LOWENBERG.H Office of Nuclear Material Safety & Safeguards, Director 81/10/23 CHECK.P 5 Clinch River Breeder Reactor Program Office 2pp 15548 036 24% Fiche 50-537.82/07/16.8210070029

review of CP application activities, in response to inte schedule dates impossible "structure of internat

> led Affiliation Given 81/11/02 filiation Given 2pp 15648 03B

- --82[0070103 Advises that R Browning will be contact for D<sub>1V</sub> of Waste Mgt & T Johnson & R Boyle will provide technical review for low level & high level waste matters re CRBR fuel cycle review MARTIN. J B NRC No Detailed Affiliation Given 82/02/10 CUMMINGHAM. R NRC No Detailed Affiliation Given Ip 15448 047 24X Fiche 50-537.82/07/16.8210070029
- --8210070118 Provides info re resources allocated to CRBR as of 82031 in response to 820511 request BROWN.R S Program Support Branch 82/05/12 WINNINGHAM, J Resource Analysis Branch 1p 15648 052 24X Fiche 50-537, 82/07/16
- ---B210070151 Provides guidance to standardize resumes of starf member consultants who may participate in environ review hearings.

  J Boe educational & prof qualifications encl.

  LOMENBERO.H Office of Nuclear Material Safety & Safeguards. Director B2/03/26 BROWNING.R E Division of Wart Management Dutter. B2/03/26 BROWNING.R E MACRONALD.( I Transportation Branch 2pp 15448 194 24% Fiche 50-537.
- --8210070157 Discusses resource utilization for CRBR fuel cycle invireview Projected expenditures for remainder of FY82 provided LONENBERG.H Office of Nuclear Material Safety & Safeguards, Director 82/07/02 DAVIS.J G Office of Nuclear Material Safety & Safeguards, Director 2pp 15648 198 24X Fiche 50-537,82/07/16.8210070027
- ---92)0070163 Provides highlights for wk ending 820618 re CRBR full a environ review Minor corrections to FES update submitted to CRBR program ofc.
  LINEMBERG, H. Office of Nuclear Material Safety & Safeguards, Director 82/06/24 DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director Ip 15648 200 24X Fiche 50-537, 82/07/16, 8210070029
- --8210070179 Provides highlight items for CRBR fuel cycle environ it for uk ending 820604 Discovery items requiring input received on 820604 CUNNINGHAM. R. E. Division of Fuel Cycle & Material Safety 82706709 DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director 1p 15448 232 24X Fiche 50-537.02/07/178210070029
- --8210070182 Provides highlight items to CROR fuel cycle environ test for uk ending 820521 Callection & resolution of NRC comments scheduled for 820601 CUNNINOHAM.R E Office of Nuclear Material Safety & Sareguards. Director 82/05/27 DAVIS.J G Office of Nuclear Material Safety & Saf
- --8210070222 Provides highlight items re CRBR fuel cycle envirous rov for uk ending 820423 Final version of GRIGEN 2 Code received from ORNL LOHEMBERO: H Office of Nuclear Material Safety & Safeguards: Director 82/04/29 CUNNINOHAM.R Office of Nucle. Material Safety & Safeguards. Director in 19648 248 24X Fiche 50-537, 82/07/14.8210070029
- ---8210070225 Submits schedule for CRBR fuel cucle environ review LOWENBERG, H. Office of Nuclear Material Safety & Safeguards, Director 82/04/27 ROUSE, L. C. Advanced Fuel & type Fuel Licensing Branch MACDONALD, C. E. Transportation Branch DUBE, R. J. Division of Safeguards 2pp 18448 250 24X Fiche 50-537, 82/07/14, 8210070027
- --8210070251 Forwards revised ORIGEN 2 outputs for CRBR
  LOWENBERO.H Office of Nuclear Material Safety &
  Safeguards.Director 82/04/23 ROUSE.L C Advanced Fuel & lip
  Fuel Licensing Branch MACDONALD.C E Transportation Branch
  PAGE.R G Uranium Fuel Licensing Branch ip 15448 252 24x
  Fiche 50-537.82/07/16.8210070029
- --8210070253 Forwards revised ORIGEN 2 output for CRDR Averaging procedures altered for agreement between flows & physical mass
  CROFF.A O Clas Ridge National Laboratory 82/04/20 LCHENNER
  Office of Nuclear Material Safety & Safeguards, Director 13pp
  13648 253 24% Fiche 30-537.82/07/16.8210070029
- --8210070256 Forwards backup calculations for Table D 4, CRBR fuel c suppl Related info encl HILL.O F Battelle Memorial Institute, Pacific Northwest Laboratory 82/06/09 LOWENBERG; H Office of Nuclear Materia Bafety & Safegurds, Director Bopp 15648 266 24X Fiche 50-537, 82/07/16, 8210070029

- --Bigo70259 Provides highlights no CRBR fuel cycle environ review for ut ending 820416 Revised ORIGEN 2 Code prepared by ORNL LONENGERO, H. Office of Nuclear Material Safety v. Safeguards, Director 82/04/22 DAVIS, J. G. Office of Nuclear Material Safety v. Safeguards, Director ip 15648-352 24X Fiche 50-537,82/07/16,8210070029
- --8210370226 Clarifies responsibility for dose assessment calculation for CRSR activities LONENBERG H Office of Nuclear Material Safety & Sareguards, Director 82/04/12 COMMELT J Radiological Assessment Branch MILLS.W A Human Factors Engineering Branch ROUSE L C Advanced Fuel & Spent Fuel Licensing Branch | Ip 15549 087 24/ Fiche 50-537,82/07/16,8210070029
- --E210079273 Provides clarification of DQE Amend XIII submittals per 820323 telcon Full Pu ' () throughputs used as basis for radioactive release (all ulations for conservative estimation of erriumets
  (i) FIDERC, H. Office of Auclear Material Safety \*
  Sareguards, Director 82/03/25 ROUSE/L C Advanced Fuel & Spent Fuel Licensing Branch (MACDONALD, C E Transportation Branch Direct J Division of Safeguards ip 15449 089 24X
  Fiche 50-537, 82/07/16, 8210070029
- --ZIOG702/6 Notification of 8204(4-15 meeting w/BNWL in Bathesda, ND to discuss contract under fin B-247/ Discussion will include preliminary source term data i initial ORIGEN 2 data LOWENGERG H Office or Nuclear Material Safety A garegoards, Director fin B-217/ 82/03/25 ROUSE, L.C. Advanced Fuel 'Spent Fuel Licensing Blanch MACDONALD, C.E. Transportation Branch DUBER J. Division of Sareguards ip 15649-090 AX Fiche 50-537,82/07/16 8P10070029
- --P2100703P2 Advises that proposal submitted by BNWL meets objectives of statement of work for review & assessment of CRDR environ impact ichsculers. H. Office of Nuclear Material Safety & Safeguards Director fin 8-2477 82/03/19 GRESHAM, J. Division of Fuel Cycle & Material Safety ip 19649-092 24X Fiche 30-537,82/07/16,82/10070029
- -8210070285 Provides quidance for designation of specialists for environ review proveeding that of exports followed by individual statement of qualitrations must be propared (DUEDBFRG.) Office on Nuclear Material Safety & Sareguards Director 82/03/19 BROWNING.R & Division of Waste Management DUKE.R / Division of Safeguards MACDDNALD.C & Transportation 81 anch 2pp 15649 093 24% Fiche 50-537, 82/07/16 82100700/9
- --B210370.93 Submits schedule of meetings w/technical assistance contractor & DDF or LMBR environ review LONEMBERG.H Difice or Nuclear Material Safety '. Safeguards Director BC/02/23 ROUSE.L C Advanced Fuel & Spint Fuel Licensing Branch MACDONALD.C T Transportation Branch DUSE.R J Division of Safeguards 1p 15649 100 24X Fiche 50-53',82/07/16.8210070029
- --E210070298 Confirms 82022, meeting w/DOF to review 820219 draft input to CRBR fuel cyclo review LOLENBERG.B Office of Nuclear Material Safety & Sareguards, Director 82/02/23 ROUBE.L C Advanced Fuel & Sprint Fuel Licensing Branch MACDONALD.C E Transportation Branch BUBE.R J Division of Safeguards ip 15649 101 24% Fiche 50-537,82/07/16.8210070029
- ~-B210070701 Provides broad assessment of CRBR fuel cycle environ effects Amend XII fairly represents 50-yr dose commitments from fuel fabrication & reprocessing ROUSE.i. C. Advanced Fuel L Spent Fuel Licensing Branch B2/02/0b LOMENBERG. H. Office of Nuclear Material Safety & Safeguards, Director 1p 15649 102 24X Fiche 50-537,82/07/16. B210070027
- --8210070306 Provides results of review of DDE draft Amend XIII to CHIR fuel cycle environ review Addi info needed re data used as basis for DQE determination of environ impact AYEN, JE KRC - No Detailed Affiliation Given 82/02/20 LOHENBERG: H NRC - No Detailed Affiliation Given 2pp 15649 LO3 24X Fiche 50-537,82/07/16.8210070029
- --8210070310 Forwards resumes of JE Ayer & AT Clark for CRBR fuel cycli environ review ROJSE, C Advanced Fuel & Spent Fuel Licensing Branch 82/03/31 LOMENBERG. H Office of Nuclear Material Safety & Safeguards. Director Spp 15649 105 24X Fiche 50-537.82/07/16. 8210070029
- 6207110033 FOIA request for documents by Science Applications. Inc for CRSR project including FES. site suitability rept & SER WEISS. ER Harmon & Weiss 02/07/26 FELTON. J M Division of Rules and Records 1p 15597 264 24X Fiche 50~537. B2/07/26. B20710033

- 8208270699 Summary of 820723 meeting w/util.DQE & Project Mgt Corp in Bethesda.MD re review of CRRR probabilistic risk assessment in areas of success criteria for shutdown heat removal sys, logic & event trees & fault trees STARK.R M Clinch River Breeder Reactor Program Office 82/08/13 Clinch River Breeder Reactor Program Office 4pp 14683 045 74y Fiche 50~537.82/08/13.8208270699
- B210040343 Responds to FOLA request for all documents re work performed by Science Applications, Inc for CRBR project Forwards documents listed in App A FELTON, J M Division of Rules and Records B2/08/20 WEISE.E R Harmon & Weiss 2pp 15597 265 24x Fiche 50-537,82/08/20,82/08/40343
- --8210040346 Forwards draft itr repts for CRDR Tasks 1-A,(~D & probabilistic risk assessment review plan Comments requested JOHNSON.8 Science Applications, Inc. NRC-03-82-096 82/05/26 SILVER, H. NRC No Detailed Affiliation Given 4pp (5597 26/24X Fiche 50-537,82/08/20,8210040343
- --8210040349 A6vises that answers to NRDC interrogatories for CRBR review will be completed per 820609 tetron Plan & schedule submitted JOHNSON, B Science Applications. Inc. NRC-03-82-096 82/06/10 SILVER, MRC No Detailed Affiliation Given 2pp 15597 271 24% Fiche 50-537, 82/08/20.8210040343
- --B210040350 Confirms action item re risk reduction per 820609 telcon Info re diversity of CRBR heat transport sys encl LINER, R T Science Applications. Inc NRC-03-B2-096 82/06/ii IRC - No Detailed Affiliation Given 2pp 15597 273 24 X Fiche 50-537.82/08/20.8210040343
- --8210040351 Forwards comments on applicant 820618 proposed probabilistic risk assessment plan Items addressed include content, resource allocations to phenomenological tasks JOHNSON, B. Science Applications. Inc. NRC-03-82-096 82/07/07 SPANO, A. NRC No. Detailed Affiliation Civen. 3pp. 15597-275 24% Fiche 50-537,82/08/20,8210040343
- --8210040355 Forwards questions for applicant re frequency of simultaneous loss of three main cooling loops, discussed during 820715 meeting tiper.

  (INER.R., ATEFI, B. Science Applications, Fac. NRC-03-82-096 82/07/16 SWIFT, J. NRC No Detailed Affiliation Given Rep 1597 278 24X Fiche 50-537,82/08/20.8210040343
- 8210060442 Responds to FDIA request for input to Chapter 7 & App J of FES & suppl to CRBR Documents listed in App A available in PDR App B documents completely withheld advice & opinions (ref FDIA Exemption 5) FELTON.J M Division of Rules and Records 82/08/24 WEISS.L R Harmon & Weiss App 15636 040 24% Fiche 50-537.82/08/24. 8210060442
- --B210060451 Forwards list of transients within 10 miles of CRBR per 820217 request FERRELL.C NRC - No Detailed Affiliation Given 82/02/17 THADAMI.M NRC - No Detailed Affiliation Given 3pp 15636 12/ 24X Fiche 80-537.82/08/24.8210060442
- --8210060453 Submits representative meteorological data for input into CRAC computer code for CRBR site SFICKLER. I Accident Evaluation Branch 82/04/13 PASEDAG, W Accident Evaluation Branch 19 15434 130 24X Fiche 50-537,82/08/24,8210060442
- --8210060455 Forwards site description of CRIR per 820513 request FERRELL,C NRC No Detailed Affiliation Given 82/05/13 THADAMI,M NRC No Detailed Affiliation Oiven 19pp 15436 134 24X Fiche 80-837.82/08/24,8210060442
- --8203190016 Forwards draft statement of work for technical assistance contract re-probabilistic assessment & reliability program for comment by 820305 Detailed breakdown of FY82.FY83 & FY84 time required for wach subtask forthcoming THADANI.A Reliability & Risk Assessment Branch 82/03/03 SPET8.T NRC No Detailed Affiliation Given 13pp 15636 152 24X Fiche 50-537.82/08/24.8210060442
- B2101501B6 Forwards response to NRC 820407.0514 & 0607 ltrs re request for add1 info Responses to Questions C5 421 26.43.51 & 53 & C8 760 162.164 & 176 will be incorporated into future FBAR amend LONGENECKER, J. Energy, Dept of, Clinch River Breeder Reactor Plant 82/08/24 CHECK, P. S. Clinch River Breeder Reactor Program Office 39pp 15707 195 24X Fiche 50~537,82/08/24,8210150186

- 8208290086 FOIA request for rept to EPA. "Pu & Human Tissues re Smoking. Age: Residence Near Rocky Flats & Eastern CO " JOHNSON: C Affiliation Unknown 82/07/01 Office of Administration ip 15636 207 24X Fiche 50-537.82/09/01. 8208290086
- 8210050454 Summary of B20915 meeting w/applicants in Bethesda. MD re review of thermal margin beyond design basis & seismic margin beyond design basis issues BECKER, R.A. Clinch River Breeder Reactor Program Office 82/09/20 Clinch River Breeder Reactor Program Office 4pp 15636-221 249 Fiche 50-537.82/09/20.8210060454
- 8210050477 Comments on CRBR probabilistic risk assessment program plan submitted in 820621 ltr Plan responsive to NUREG-0718, Item III B 8 requirements Details encl CHECK.P S Clinch River Breeder Reactor Program Office 82/09/23 LONGENECKER, J Energy. Bept of, Clinch River Breeder Reactor Plant opp 15626 257 24X Fiche 50-537,82/09/23,8210050477
- 8210120445 Notification of 821006-08 meetings ω/DDE.Project Mgt (σrμ & TVA in Bethesda.MD to discuss direct heat Temoval sys STARK.R M Clinch River Breeder Reactor Program Office 82/09/2/CHECK.P S Clinch River Breeder Reactor Program Office 3pp 15671 183 24x Fiche 50-537,92/09/27-8210120445
- 8210040251 Confirms that microfiche containing CACECO input/output for extreme sodium-concrete penetration case & explanatory info has been delivered to CRBR program of CLONGENECKER. J. Energy, Dept. of 82/09/28 CHECKLP S. Clinib River Breeder Reactor Program Office ip 15581-357 24X Fiche 50-537-82/09/28.8210040251
- 8210040304 Forwards TN Historical Commission 820708 ltr to TVA concurring that archelogical & historical field survey is not warranted prior to transmission line tower const LONGENECKER.J Energy. Dept of. Clinch River Breeder Reactor Plant 82/09/28 CHECK.P & Clinch River Breeder Reactor Program Office 2pp 15587 149 24X Fiche 50-537.82/09/28.8210040304
- 8210130069 Notification of 821005 meeting w/80E.Project Mgt Corp & IVA in Bethesda.MD to discuss working structural & seismic review STARK.R M Clinck River Breeder Reactor Program Office 82/09/28
  - STARK.R M Clinck River Breeder Reactor Program Office 82/09/28 CHECK.P S Clinck River Breeder Reactor Program Office 3pp 15495-264 24% Fiche 50-327,82/09/28,8210130069
- B210040t67 Forwards Itr rept in support of CRBR thermal margins beyond design base instrumentation development per DDE 820514 submittal refeture info for review of CRBR LONGENECKER, J. Energy, Dept of, Clinch River Breeder Reactor Plant B2/09/29 CHECK, P.S. Clinch River Breeder Reactor Program Office 11pp 15582 034 24X Fiche 50-537, B2/09/29, B210040167
- 8210060426 Responds to FOIA request for rept to EPA, "Pu & Human Tissues re Smoking, Age. Residence Near Rocky Flats & Eastern CO" & related documents No info available Forwards request to EPA for response FELTON, J M Davision of Rules and Records 82/09/29 JOHNSON, C J Affiliation Unknown ip 15636 208 24% Fiche 50-537, 82/09/29, 8210060426
- 8210060217 Forwards responses to Questions CS 421 27,30,31,34 & 58 re ESF, instrumentation & control drawings for safety-related sys & adequacy of reactor vessel level gauges: per 820409 request Responses will be incorporated in future FSAR amend LONGENECKER. J Energy Dept of, Clinch River Breeder Reactor Plant 82/10/04 CHECK, P.S. Clinch Rayer Breeder Reactor Program Office.

- 8210130311 Summarizes 820928 meeting w/NRC for CRBR leak detection sylfor primary coolant boundary Test results encl LONGEMECKER. J. Energy, Dept of 82/10/07 CHECK.P.S. (linch River Breeder Reactor Program Office 1p 15678 135 24X Fishe 50-537, 82/10/07, 8210130311
- --8210130315 "Liquid Metal to Gas Leak Detection Instruments" HATLIN, E. WITHERSPOON, J. JOHNSON, J. L. Rockwell International Corp. 82/10/07 15pp 15678-136 24X Fiche 50-547,88/10/47, 9210130311
- 8210220023 Notification of 821019 meeting w/DDC, Project Mgt ("orp & IV. in Rethesda, MD to review control room design STARK, R M. Clinch River Breeder Reactor Program Office (R2/10/17) CHECK, P.S. Clinch River Breeder Reactor Program Office ipp 15786-304 24x Fiche 50-537, 82/10/14, 8210220023
- B210210022 Forwards summary of B20717 ASME Code comparison working meeting w/CRDR project of LLASL Mestinghouse # MLLCO in Bethesda.MD to resolve concerns to utilization of 1974 ASME Code for design of containment vessel LDNGENECKER.J Energy Dept of B2/10/15 CHECK.P 5 (1104 h River Breeder Reactor Program Office 14pp 15745 198 /4X Fiche 50-537, 82/10/15, 8210210022
- B210210273 Forwards summary of CRUR/NRC hypothetical core disturble accident energetics 820921 meeting me plenum fission gas compartion, role of structures in energetic termination to fuel removal & energetic potential LONGEMECKER. J. Energy, Dept. of B2/10/15 CHECK.P.5 (limin River Breeder Reactor Program Office 5lpp 15766-1711 P4x Fiche 50-537, 82/10/15, 8210210273
- B210260302 Forwards add1 info resulting from Mechanical Engineering Branch 820908-09 meetings A response to Items 17.19.32.8.69 Responses to Items 3.4.34.49.51 & 54 will be provided by 821025 LONGENECKER, J. Energy. Dopt or 82/10/20 CHECK P. Limith River Breeder Reactor Program Office 6pp 16092 297 .48 Fichs 50-537,82/10/20.9210260302
- 8210260168 Summarizes 821019 control room philosophy exchange meeting Viewgraphs encl LONGCNECKER, J. Energy, Dept or 82/10/21 CHECK,P () (1111/2) River Breeder Reactor Program Office 38pp 15004 27/1 24x Fiche 50-537,88/10/21,8210260168
- 8210260401 Forwards summary of Decay Heat Removal Theimal Hydianiss's 821020 meeting w/MRC re-resolution of items concerning CRBR project LONGENECKER. J Energy, Dept of 82/10/21 CHCCK.F is (items River Breeder Reactor Program Office Spp 13805 Pd.) 44 Fithe 50-537, 82/10/21.8210260401
- 8210380496 Notification of B21028-29 meetings w/util.pol & Prinje to a Corp in DethesdorMD to discuss matls & mechanical issues, including lest before break & leak detection STARK.R M Clinch River Breeder Reactor Program Office (DECK.P S Clinch River Breeder Reactor Program Office (July 1586) 052 24X Fiche 50-537.82/10/22,8210280493
- B Utility Preliminary Safety Analysis Report, amends
- 8209300353 Forwards Amend 71 to PSAR Amend includes responses to requests for add informerisions to Chapter 7.
  "Instrumentation & Controls," Sections 17E & 17I & other updates & revisions Certificate of Svc encl LGNGENECKER. J Energy Dept of, Clinch River Oresder Reactor Program Health 4pp 15560 197 24X Fiche 50-537.62/09/30.8209300353
- ---8209300355 Amend 71 to PBAR

  4 Clinch River Dreader Reactor Program Office 82/09/KD \$4.1, 1556 201 24X Fichs 50-537,82/09/30.8209300353
- 8210130246 Forwards Certificate of Bvc confirming distribution of the 71 to PSAR LONGENECKER, J. Energy, Dept of B2/10/07 DENTON, H. R. Million Nuclear Reactor Regulation, Director 2pp 15676-010 24x Fishe 50-537, 82/10/07, 8210130246
- C Utility Environmental Report (ER), amends & correspondence
- 8210070029 Partial response to FOIA request for documents re CRER & all comments, evaluations & documents from BNML re EIB Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/07/16 WEISN.8 \*\* Harmon & Weiss 8pp. 15648 004 24% Fichs 50-537.82/07/16. 8210070027

- -8210070128 Forwards drart Amend XIII to CRBR environ rept, consisting of rinor editorial changes
  LONEMBERG H Office of Nuclear Material Safety & Safeguards, Director 82/02/24 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch MACDOMALD C E Transportation Branch DUBE, R J Division of Safeguards 48pp 15648 136 24X
  Fiche 50-537,82/07/16,8210070029
- --B21007019; Forwards add) input to Amend XIII to CABR environ rept to socioecononic impact W/o encl LUMEMBERG.H. Diffice of Nuclear Material Safety & Sarequards, Director 82,04/26 ROUSE.L. C., MACDOHALD.C. E., DUBE R. J. NRC. NO Detailed Aftiliation Given 2pp 15648 184 Par Fiche 50-537.82/07/16 8210070029
- --B210070134 Requests raviaw of DDE revised environ rept. Section 5 / 1 refuel cyclo Revision includes detailed explanation of method used to calculate doses from transportation W/o encis LOKEMDERG.H Diffice or Nuclear Material Safety & Sarequards. Director B2/03/15 ROUSE.L C Advanced Fuel & Sport Fuel Licensing Branch MACDDNALD.C E Transportation Branch BJDE.R J Division of Safeguards 2pp 15648 196 24X Fiche 50-537.82/07/16.8210070029
  - 8210070138 Dutlines revised Amend XIII to fuel cycle environ rept
    Updated version contains supplemental safeguards infoestimated costs & modified Kr-85 disposal scheme
    LOKENDERO. M. Office or Nuclear Material Safety %
    Fareywards Director B2/03/23 Advanced fuel & Spent Fuel
    Licensing Branch MACDONALD.CE
    LIBER J Division of Safeguards
    Fiche 50-53/ 82/07/16 8210070029
- --8210070142 Requests review of Amend X(V) containing revised environ ript Section 5.7 ) refuel cycle W/o encl LONEMBERG.H Office of Nuclear Material Safety & Sareguards. Director 82/05/04 ROUSE, L C Advanced Fuel & Spirit Fuel Licensing Branch MACOONALD.C E Transportation Branch DUBE.R J Division of Sareguards ip 15648 190 24X Fiche 50-537 82/07/16 8210070029
- 621CO70146 Requests review of Amend XIV.including Section 3 8 % 5 / j
  to environ rept Comments affecting final vorsions of Apps
  D & E & Sections 7 2.7 3.5 7 2 6 % 5 7 2 7 should be
  transmit(ed by 820o16
  LOWENGERG, H. Office or Nuclear Material Safety &
  Safeguards Director 82/06/09 CLARK, A T : AYER, J : LONG, J. NRC
   No. Defailed Afficiation Olymn. Ip. 1564B 191 24X
  Fiche 50-537 82/07/16.8210070029
- --G210070170 Advises that DOE has been notified of omissions, prrors & inconsistencies found in Amend XIV to environ rept 10kEMBERG.H Office of Nuclear Material Bafeth & Safeguards, Director B2/06/16 CHFCK,P S Clinch River Breeder Reactor Program Office 2pp 15648 229 24X Fiche 50-537 82/07/16.8210070029
- --B2100701/4 Provides highlight items to CRBR fuel cycle environ review for uk ending 820611 Amend XIV to environ rept under review (OKENBERC H Office or Nuclear Material Safety & Safeguards, Director B2/06/16 DAVIG.J O Office of Nuclear Material Safety & Safeguards, Director ip 15648 234 24X Fiche 50-537 82/07/16/8210070029
- --E21007019% Discusses status & changes to Amend XIV to environ rept.
  per 820514 telcon w/DDE Rept will be modified to cover
  protection for rail shipments
  LOWERIBERG, B. Office or Nuclear Material Safety &
  Saseguards, Director 82/05/14 ROUSE, L. C. Advanced Fuel & Spunt
  Fuel Licensing Branch MACDONALD, C. E. Transportation Branch
  PAGE, R. G. Unanium Fuel Licensing Branch 2pp (5648-238 PAX
  Fische 50-537,82/07/16.8210070029
- --8210070200 Forwards socioeconomic impact portion of environ rept for inclusion w/Amend XIV LOWENDERG/H Office of Nuclear Material Safety & Safeguards, Director 82/05/07 ROUGE, L C Advanced Fuel & Sprnt Fuel Licensing Branch MACDONALD, C E Transportation Branch PAGE, R J Wranium Fuel Licensing Branch 3pp 15648 240 24X Fishe 50-537, 82/07/16,8210070029
- --B210070206 Advises that DDE failed to meet schedule of milestone for safeguards info & revised CRBR environ rept New target date scheduled for 820511
  LONENBERG, H. Division of Fuel Cycle & Material Bafety 82/05/05
  DAVIS.J. G. Office of Nuclear Material Bafety & Safeguards. Director ip 15648-246 24X Fiche 50-537, 82/07/16. 8210070029

- ~8210070260 Forwards revision to Amend XIII to environ rept.provided by DDE on 820415
  LOWENBERG.H Office of Nuclear Material Safety & Sareguards.Director 82/04/20 ROUSE.L C Advanced Fuel & Spirit Fuel Licensing Branch MACDONALD.C E Transportation Branch DUBE.R J Division of Safeguards 86pp 15648 393 24X Fiche 50-537,82/07/16.8210070027
- ~-8210070262 Provides highlights of CRBR fuel cycle environ review for wk ending 820413 DGE plans to submit draft Amend XIII to environ rept during which 820419 LONENBERG.H Office of Nuclear Material Safety & Safeguards. Director 82/04/13 DAVIS.J O Office of Nuclear Material Safety & Face of Nuclear Material Safety & Safeguards. Director 2pp 15649 077 24X Fiche 50-537, 82/07/16, 8210070029
- --B210070280 Discusses radiological dose assessment for licensing of CRDR DDE will submit environ rept on fuel cycle used to fabricate, reprocess, transport & safeguard fuel LOWENBERO, H Office of Nuclear Material Safety & Safeguards, Director B2/03/19 CONGEL.F J Radiological Assessment Branch 1p 15649 091 24X Fiche 50-537, B2/07/16, B2/03/039
- --8210070291 Forwards corrected pages to Amend XIII package of CRBR environ rept
  LOENBERG.H. Office of Nuclear Naterial Safety &
  Safeguards.Director 82/03/16 RDUSE.L.C. Advanced Fuel & Spent
  Fuel Licensing Branch MACDDNALD.C E. Transportation Branch
  DUBE.R.J. Division of Safeguards. Spp. 15449-095 244
  Fichs 50-537.82/07/16.8210070029
- D NRC Draft/Final Environmental Statements, supply & correspondence
- 8210070029 Partial response to FOIA request for documents re CRBR EIS & all comments, evaluations & documents from BNML re EIS
  Forwards documents listed in App A
  FELTON.J M Division of Rules and Records 82/07/14 WEISB.E R
  Harmon & Weiss Bpp 15648 004 24% Fiche 50-537,82/07/16.
  8210070029
- --8210070037 Provides info re revision to CRBR fuel cycle environ revails schedule FES contributions due 820614 Review responsibilities identified EVANS.1. J NRC No Detailed Affiliation Given 82/03/23 MCCORKLE.G., SHERR.T., ERICKSON.B. NRC No Detailed Affiliation Given 2pp 15648 012 24% Fishe 50-837.62/07/16,8210070029
- --8210070043 Discusses plans for 820408-09 meeting w/BNWL in Silver Spring, MD to discuss CRBR environ review Draft updates of EIS sections on transportation & fuel fabrication will be provided HURT, D. NRC No Detailed Affiliation Given 82/03/22 DUBE, BNRC No Detailed Affiliation Given 19 19648 Q16 24X Fiche 50-537, 82/07/16,8210070029
- --B210070047 Discusses plans for B20512 & 13 meeting w/DNML re draft update of safeguards portion of E18 HURT.D NRC No Detailed Affiliation Given B2/04/21 GABKIN,C : MULLEN,B : BAKER,P NRC No Detailed Affiliation Given Ip 15448 017 R4X Fiche 50-537,82/07/14.8210070029
- --8210070050 Advises that BNWL contractors will be available on 820407-QU to discuss CRBR environ review Transportation section of El<sup>o</sup> will be reviewed on 820407 HURT, D NRC No Detailed Affiliation Given 82/03/31 D NRC No Detailed Affiliation Given 19 15648 018 24X Fiche 50-537,82/07/16.8210070029

- --82(0070067 Advises that work task sheet will serve for basis of plan supporting environ review effort Safeguards portion of DDE environ rept should be reviewed to determine if sufficient into has been included for confirmatory review BURNETT, R. F. Division of Safeguards BE2/02/17 LOWENBERG, H. Office of Nuclear Material Safety & Safeguards, Director 2pp 15648 026 24X Fiche 50-537, 82/07/16,82:0070029
- --8210070084 Requests that BNM\_ handle all safeguards-related arras of EIS & interrogatory updates except those concerning threats to clandestime fission explosives in response to B20303 memo MCCORKLE. O NRC No Detailed Affiliation Given B2/03/04 EVANS. D MRC No Detailed Affiliation Given 1p 15648 032 24X Fiche 50-537.82/07/16.8210070029
- --B210070101 Advises that B20305 deadline for draft suppl to E1S cannot be net due to delay in receipt of info from DDE LOWENDERO.H Office of Nuclear Material Safety & Safeguards, Director B2/01/13 CHECK.P Clinich River Breeder Reactor Program Office 2pp 15448 043 24X Fiche 50-537,82/07/14,8210070029
- --B210070119 Forwards safeguards portion of FEB update.including Section 7 3 & App E LOWENBERG.H Defice of Nuclear Material Safety & Safeguards.Director B2/06/09 CHECK.P S Clinich River Breeder Reactor Program Office 20p 15648 093 24X Fiche 50-537.82/07/16.8210070029
- --B210070123 Forwards updated responses to comments on 1976 DES,
  NUREQ-0137 re safeguards & fuel cycle info re radwaste
  shipments, disposal site & licensed burial site included
  LOWENBERG, H. Office of Nuclear Material Safety &
  Bafeguards, Director 82/06/15 LEECH.P. Clinch River Breeder
  Reactor Program Office 15pp 15648 073 24X
  Fiche 50-537, B2/07/16, B210070029
- --8210070126 Forwards update to FES, including App D. "Environ Effects of CRBR Fuel Cycle & Transportation of Radioactive Matle" & Section 5 7 2 7. "Fuel Cycle Impacts "
  LOMENBERG H Office of Nuclear Material Safety & Safeguards. Director 82/06/19 CHECK.P S Clinch River Breeder Reactor Program Office 50pp 15648 088 24X
  Fiche 50-537, 82/07/16, 8210070029
- --8210070163 Provides highlights for wk ending 820619 re CRBR feel cycle environ review Minor corrections to FES update submitted to CRBR program ofc LOWENBERG, H Office of Nuclear Material Safety & Safeguards, Director 82/06/24 DAVIS, J 0 Dffice of Nuclear Material Safety & Safeguards, Director 1 p 15648 200 24X Fiche 50-537, 82/07/16, 8210076029
- --8210070166 Forwards replacement pages for fuel cycle portion of LRBM FES update Pages correct minor errors LOMENDERG.H Office of Nuclear Material Safety & Safeguards, Director B2/06/21 CHECK.P S Clinch River Greeder Reactor Program Office 28pp 15648 201 24X Fiche 50-537, 82/07/16, 8210070029
- --8210070186 Provides highlight items re CRBR fuel cycle environ review for wk ending 820514 Draft fuel cycle portion of EIS in progress LONENBERO.H Office of Nuclear Material Safety & Safeguards, Director 82/05/20 DAVIS, J 0 Office of Nuclear Material Safety & Begguards Director 1p 15648 235 24% Fiche 50-637, 82/07/14.6210070029

- --8210070223 Notifies that BNWL will be available to review (484 | 1 , on 8205;2 LDMENDERG, H. Office of Nuclear Material Safety & Safeguards, Director 82/04/26 ROUSE, L.C. Advanced fuel inglining Free Licensing Branch MACDUNALD, C.E. Transportation Brauch PAGE, R.G. Uranium Fuel Licensing Branch to 1564H 249 4: Fiche 50-537,82/07/16,8210070029
- --B210070313 Submits responses to Contention 6. Interrogatorine 15 ////
  61.62.63 & 64 on CRUR hearing re EIS update
  AYER, J E., CLARK, A T. Advanced Fuel & Spent Fuel Ficensing UsaB2/06/09 LOWENDERG, H. Office of Nuclear Material Figfely /
  Safeguards, Director App. 15649 110 24X Fishe 50 517 H/2012/F
  8210070029
- --B210070315 Discusses potential need for add1 funding for (1914 11), update project NELSON, I Battelle Memorial Institute, Pacific Northwest Laboratory B2/06/24 LCMENBERG.H Office of Nuclear Material Safety & Safeguards, Director 2pp 15649 114 24X Fiche 50-537, 82/07/16,8210070029
- --8210070318 "CRBR EIS Update," monthly progress rept for Hay I'm, NELSON, I C Battelle Memorial Institute, Pacific Northwest Laboratory 82/06/17 LONENBERG, H Office of Nuclear Material Safety & Safeguards, Director 3pp 15649 116 24x Fiche 50-537, 82/07/16-8210070029
- --8210070923 Forwards final draft submittal of CRBR EIS update professors 5 7 2 6.5 7 2 7.7 2 5 7 3 M/o encl
  NELSON-I C Battelle Memorial Institute, Pacific Northwest
  Laboratory 92/05/21 (OMENBERG.H Office of Nortean Haterial
  Safety & Safeguards.Director in 15649 119 .44X
  Fiche 50-537.82/07/16.8210070029
- ~-8210070327 Confirms changes to final CRBR E18 draft update per intelecon w/NRC safeguards staff
  NELSON.1 Battelle Memorial Institute. Pacific Northwest
  Laboratory 82/05/18 LOWENDERO.H Office of Nullear Males, all
  Sarety & Safeguards.Director 1p 15649 120 24x
  Fiche 50-537,82/07/16.8210070029
- --8210070332 "CROR EIS Update," monthly progress rept for Apr 17d . NELSON, I C Battelle Memorial Institute, Pacific Northwest Laboratory 82/05/17 LOWENBERGH Office of Northur Paleite. Safety & Safeguards, Director 3pp 15649 121 (44x Fiche 50-537, 82/07/16, 8210070029
- --8210070335 Forwards second draft of CRBR EIS update including 'et 5 7 2 6. "Transportation of Radioactive Matl," Section 5 8 2 7 "Fuel Cycle Impacts" & Section 7 3. "Safeguards Considerations " W/o encl NELSON. I C Battolle Memorial Institute. Pacific Nothwest Laboratory 82/05/07 LOWENBERG.H Office of Notlear Mats. 8 a Safeguards, Director ip 15649 124 24% Fiche 50-537.82/07/16.8210070029
- --8210070347 "CRBR EIS Update." monthly progres rept for Mai 14cr NELSON. I C Batteile Memorial Institute. Pacific Northwest Laboratory 82/04/12 LOMENDERO.H Office of Noticer Males 4 a Safety & Safegyards. Director 3pp 15449 125 44x Fiche 50-537.82/07/16.8210070029
- --B210070445 Forwards back-up notes & refs for fuel cycle part) , update Related info encl NELSON. I Battelle Memorial Institute, Pacific Northwest Laboratory 82/06/24 LOMENBERG.H Office of Nuclear Males of Safety & Safeguards. Director 57pp 15649 120 24x Fiche 50-537, 82/07/16, 8210070029
- 8207110034 FDIA request for input to Chapter 7 & App J of \$45 b 1 to GRBR MEISS, ER Harmon & Weiss 82/07/26 FELTON, J N 1920 stun . Rules and Records ip 15636 039 24X Fiche 50-537. 1924 1944 8207110034
- B210060442 Responds to FOIA request for input to Chapter / h App | FEE & suppl to CRBR Documents listed in App A available | n PDR App B documents completely withheld advice & opinions (ref FOIA Exemption 3)
  FELTON, J M Division of Rules and Records B2/08/24 WARM Harmon & Weiss App 15636 040 24% Fiche 50-537, B2/08/44 B210060442
- --8201150176 Forwards Accident Evaluation Branch input to 11% set for Pacifity Section 7 requires suppl to address NRC 8000018 statement of interim policy Info presented in Sections V J & 11 7 requires no update
  KREOER: W E Assistant Director for Radiation Protection 81/12/18 CHECK,P S Clinch River Breeder Reactor Program 34 Spp 15636 044 24% Fichs 50-537,82/00/24,8210060444

- --8206080467 Forwards Accident Evaluation Branch input to final environ statement update re Class 9 accidents MDUSTDIAR W Assistant Director for Radiation Protection 82/05/28 CHECK.P.S Clinch River Breeder Reactor Program Office 9pp 15636-049 24% Fiche 50-537.82/08/24,8210060442
- --E207(4013B Forwards Accident Evaluation Branch revised evaluation of four classes of come disruptive accident included as App J to proposed FES addendum.per B Morris verbal request Calculated risks of accidents not different from LMR risks HOUSTON, R W Assistant Director for Radiation Protection B2/07/01 CHECK.P S Clinck Riser Oreeder Reactor Program Uffice 420p 156:36 05B 24X Fiche 50-537,82/08/24,8210060442
- --8210060447 Draft input to Class 9 accident analysis for CRBR FfB RAMBLE,E Science Applications, Inc. 82/06/30 NRC - No Detailed Affiliation Given 20pp 15636 100 24X Fishe 50-537.82/08/24.8210060442
- --B202240446 Forwards population data input for DES Section 5 9 4 9 2 for yr 2010.per request REGAN, W H Siting Analysis Blanch 82/02/10 HULMAN, L G Accident Evaluation Branch 3pp 15636 124 24X Fiche 50-537, 82/08/24, 8210060442
- --8201150007 Provides description of aspects of liquid pathway for update of accident analysis section of FE5 suppl Liquid pathway consequences small due to absence of large water stores LEAR.O Hydrologic & Ocotechhical Engineering Branch 01/12/22 MOUSTON.R W Accident Evaluation Branch 2pp 15636 132 24X Fiche 50-537,82/08/24.8210060442
- --8203050073 Confirms tentative schedule for roview of CRBR program probabilistic risk assessment study to be included in FES suppl HULMAN, L G Accident Evaluation Branch 82/02/17 THADANI, A Reliability & Risk Assessment Branch 1p 15636 165 24X Fiche 50-537 82/08/24,8210060442
- --B210060458 Forwards comments on draft math for FES update per 820501 request Section 7 2 should include brief discussion on U herafluoride Related info encil CMECK,PS Clinch River Breedel Reactor Program Office 82/05/28 LOKEMERG,H NRC No Detailed Affiliation Given 14pp 15636 166 24X Fiche 50-597, 82/08/24,8210060442
- --8204290408 Forwards marked up Table 7 2 of FES Revisions reflect differences in current site atmospheric dispersion values from reg guide values used for original FES calculations HOUSTON, R W. Assistant Director for Radiation Protection 82/04/07 CHECKLP S Clinch River Breeder Reactor Program Uffice 2pp 15636 189 24x fiche 50-537.82/08/24,8210060442
- --2203220512 Advises that schedule for review of probabilistic risk assessment proposed in 820217 memo no longer applicable Input to review will be provided upon request HULMANL Q Accident Evaluation Branch 82/03/09 THADANIA Reliability & Risk Assessment Branch 1p 15636 192 24X Fiche 50-537.82/08/24.8210060442
- EC10080053 Ack receipt of 870908 ltr commenting on draft suppl to lts Comments will be considered in FES CHECK,PS Clinch River Breeder Reactor Program Office 82/09/23 CHONO,L R Affiliation Unknown ip 15669 319 24X Fiche 50-537, 82/09/23, 8210080053
- --8210080055 Comments on draft suppl to FEG re decommissioning of CHUR CHONG.L R Affiliation Unknown 82/09/08 NRC ~ No Detailed Affiliation Given 2pp 15669 320 24% Fiche 50-537,82/09/23. 8210080053
- F Security, medical, emergency & fire protection plans
- 8210070027 Partial response to FOIA request for documents re CRBN E15 & all comments, evaluations & documents from BNML re EIS
  Focuards documents listed in App A
  FELTON, J M Division of Rules and Records 82/07/16 WEISS.t. R
  Harmon & Weiss Spp 15648 004 24X Fiche 50-537, 82/07/16, 8210070027
- --8210070047 Discusses plans for 820512 & 13 meeting w/BNWL re draft update of safeguards portion of EIS HURT,D NRC - No Debailed Affiliation Olven 82/04/21 OASKIN.C : MULLEN,S : BAKER,P NRC - No Detailed Affiliation Given 1p 15648 017 24X Fiche 50-507.82/07/16,8210070029
- --8210070064 Provides update of EIS review Document requires updated math on reactor safeguards Interrogatories may be issued to clarify or constrain issues
  EVANS.L J NRC No Detailed Affiliation Given 82/03/01
  MCCORKLE.G NRC No Detailed Affiliation Given 2pp 1564B 024
  24X Fiche 50-537.82/07/16.8210070029

- --8210070067 Advises that work task sheet will serve for basis of plan supporting environ review effort Safeguards portion of DBE environ rept should be reviewed to determine if sufficient info has been included for confirmatory review BURNETF.R F Division of Safeguards 82/02/17 LOWENDERO.H Office of Nuclear Material Safesty & Safeguards. Director 2pp 19648 026 24X Fiche 50-537, 82/07/16,8210070029
- --8210070084 Requests that BNM. handle all safeguards-related areas of EIS & interrogatory Updates except those concerning threats & clandestine fission explosives, in response to 820303 memo HCCORKLE, 0 NRC - No Detailed Affiliation Given 82/03/04 EVANS.B NRC - No Detailed Affiliation Given 1p 15648 032 24% Fiche 50-537,82/07/16,8210070029
- -8210070086 Requests contentions for CRBR licensing which have implications in areas of fuel cycle, safeguards & waste most discussed during 810906 meeting LQHENBERG, H Office of Nuclear Material Safety & Safeguards, Director 81/10/09 CHECK, P S Clinch River Breeds: Reactor Frogram Office 3pp 15448 033 24X Fiche 50-537, 82/07/16, 8210070029
- --B210070119 Forwards safeguards portion of FES update, including Section 7 3 & App E LCHENBERG,H Office of Nuclear Material Safety & Safeguards, Director 82/06/09 CHECK,P S Clinch River Breeder Reactor Program Office 20pp 19648 053 24X Fiche 50-537,82/07/16.8210070029
- --8210070123 Forwards updated responses to comments on 1976 DES, NUREG-0109 re safeguards & fuel cycle Info re radwaste shipments, disposal site & licensed burial site included LOWENBERG.H Office of Nuclear Material Safety & Safeguards, Director 82/06/15 LEECH.P Clinch River Breeder Reactor Program Office 19pp 15648 073 24X Fiche 50-537,82/07/16,8210070029
- --8210070138 Dutlines revised Amend XIII to fuel cycle environ rept Updated version contains supplemental safeguards info, estimated costs & modified Kr-85 disposal scheme LOWENBERQ.H Office of Nuclear Material Safety & Gafeguards. Director 82/03/23 Advanced Fuel & Spent Fuel Licensing Branch MACDONALD.C E Transportation Branch DUBE.R J Division of Safeguards 2pp 15648 188 24X Fiche 50-537.82/07/16, 8210070029
- --8210070148 Forwards updated list of staff members & contractor personnel who may be called to testify on fuel cycle or safeguards issues at CRUR hearings LOWENSERG.H Office of Nuclear Material Safety & Safeguards, Director 82/05/06 TREBY.S A Office of the Executive Legal Director 2pp 19648 192 24X Fichs 50-537,82/07/16,8210070029
- ~-8210070154 Submits list of staff members & Contractors who may provide testimony on CRBR fuel cycle safeguards LUMENBERG.H Defrice of Nuclear Material Safety & Safeguards, Director 82/03/16 JDNES,8 NRC ~ No Detailed Affillation Oliven 2pp 15648 196 24X Fiche 50-537,82/07/16. 8210070029
- --8210070206 Advises that DDE failed to meet schedule of milestone for safeguards info & revised CRBR environ rept New target date scheduled for 820516 LOMENGERO, H. Division of Fuel Cycle & Material Safety 82/05/05 DAVIS.J 0 Office of Nuclear Material Safety & Safeguards Director in 15648 244 Fiche 50-537.82/07/16.8210070029
- --B210070264 Forwards add) info re add1 safeguards cost info for CMBR fuel cycle environ review
  LOMENBERG.H Office of Nuclear Material Safety &
  Safeguards, Director 82/03/26 ROUSE,L C Advanced Fuel & Sprnt
  Fuel Licensing Branch MACDUNALD.C E Transportation Branch
  DUBER J Division of Safeguards ip 15649 079 24X
  Fiche 50-537,82/07/16.8210070029
- --B210070269 Provides weekly rept on CRBR fuel cycle environ review activities for whending B203RS DEC submitted supplemental info re draft Amend XIII concerning request for safeguards costs

  LOHENBERO, H. Office of Nuclear Material Bafety & Safeguards, Director B2/03/31 CUNNINGHAM.R Division of Fuel Cycle & Material Safety in 15449 088 24X Fiche 30-837, B2/07/16.8210070027

### Q Adjudicatory correspondence

- 8210120103 Addi response to FDIA request for nine categories of records generated by present NRC Commissioners, primarily Chairman Palladino & Commissioner Roberts & White House Forwards App B documents FELTON, J M Division of Rules and Records 82/07/12 UDELL, R A Critical Mass Energy Project 3pp 15690 117 24% Fiche 50-000, 92/07/12, 8210820103
- --8210120123 Forwards memorandum & order re Council of NC objection to util request for exemption to perform certain site preparation work Memorandum addresses exemption question & sets out history of Commission regulation. Section 50-12 ROBERTS, T. M. Commissioners 81/12/09 FALLADING, N., OILLINSKY, V., BRADFORD, J. Commissioners 81 15670-124 24X Fiche 50-000, 82/07/12, 8210120103
- 8208290094 FDIA request for CRAC & CRAC 2 analyses for facilities CURRAN.D Harmon & Woiss 82/09/10 Office of Administration 1p 15686 239 24% Fiche 50-000.82/09/10.8208290094
- 8210010064 Motion for summary disposition of NRDC & Sierra Club Contentions 6 & 7a(1) No factual issues requiring adjudication exist & dismissal of contentions warranted as matter of law Matl facts as to which there is no issue encl JONES.B W . SWANSON.D T Hearing Branch 1 82/09/29 Atomic Safety and Licensing Board Panel 12pp 15565 274 24X Fiche 50-537.82/09/29.8210010064
- --8210010082 Affidavit of P Leech on Contention 7(a)(1) Concern re CREEC achieving objectives of LNFBR program impact statement & suppl supersaded by theing changes given in suppl Prof qualifications & Certificate of Svc encl LEECH. P Clinch River Breeder Reactor Program Office 82/09/38 5pp 15585 290 24X Fiche 50-537. 82/09/29. 8280010064
- 8210050184 Corrected notification of pending litigation, including omitted sentence from 820924 notice Certificate of Svc encl EDOAR, O L Project Management Corp BEROHOLZ, W E Energy, Dept of EDOAR, O L Edgar, O L 82/09/27 24pp 15504 00; 24x Fiche 50-537, 82/09/29,8210050184
- B210050582 Responds to FOIA request for CRAC & CRAC 2 analyses for facilities No analyses sits for Shoreham Nuclear Flant Analyses for CRBR furnished under FOIA B2-344 FELTON, J M Division of Rules and Records 82/09/29 CURRAN, D Harmon & Weiss 1p 15626 240 24X Fiche 50-000, 82/09/29, 8210050582
- B210060183 Angwers to twenty-seventh set of interrogatories Certificate of Svc encl
  EWANSON, D.T., JONES, B.W., MIZUNG, G.S., Hearing Branch 1 82/10/01
  Natural Resources Defense Council 176pp 15613 001 24X
  Fichs 50-537.
- B210060185 Siith set of interrogatories Certificate of Svc encl EDGAR, O. L. Project Management Corp. BEROHOLZ, W. E. Energy, Dept of EDGAR, O. L. Edgar, O. C. 82/10/04, Natural Resources Defense Council 14pp 15613 198 24X Fiche 50-537, 82/10/04, 8210060185
- 82:10040195 Proposed findings of fact on Contentions 1,2 & 3 re site suitability FINAMORE, B A , TOUSLEY, D R Natural Resources Defense Counci! TOUSLEY, D R 61erra Club 82/10/04 77pp 156:13 273 24X Fiche 50-537, 82/10/04, 8210060195
- 8210060200 Second set of admissions & seventh set of interrogatories, per ASLB 820831 scheduling order Certificate of Svc encl EDQAR.Q L. Project Management Corp BERGHOLZ,W E Energy, Dept of ED0AR.G L. Edger, G L. 82/10/04 Natural Resources Defense Council App 15614 170 24X Fiche 50-537.82/10/04.8210060200
- 8210070192 Informs that time provided for Commission to act to review ALAB-658 expired Commission declined review Decision became final agency action on 821004 CHILK, B. J. Office of the Secretary of the Commission 82/10/05. Office of the Executive Legal Director ip 15637, 155 24% Fiche: 50-537, 82/10/05, 8210070192

- B210120302 Confirms 821005-06 discussions listing NRC personne) to be deposed on various contentions on 821012-13 FINAMORE, B A Natural Resources Defense Council 82/10/0/SHANSON.D Hearing Branch 1 3pp 15653 03B 24X Fiche 50-537.82/10/07.8210120302
- 8210120327 Withdrawal of 821004 proposed findings of fact on Contentions 1, 2 & 3 re site suitability Intervenors failed to note ASLB 820831 withdrawal of request for filing proposed findings Certificate of Svc enci FIXAMORE, B A , WEISS, E R Natural Resources Defense Council WEISS, E R Sierra Ciub 82/10/07 5pp 15653 028 24X Fiche 50-537, 82/10/07, 8210120327
- 8210130435 Notice of pending litigation Certificate of Svc enri EDGAR.G L. Project Management Corp. BERCHDLZ.W E. Energy, Dipt of 82/10/07 7pp 19681 171 24X Fiche 50-937.82/10/07. 8210130435
- B210130268 Confirms 821007 discussion listing add1 NRC personnel to be available for deposition re Contentions 5(a) & 7(b) on B21013 FINAMORE, B A. Natural Resources Defense Council \* Finamore & A B2/10/08 JONES, B Hearing Branch 1 2pp 15678 290 24x Fiche 50-537, B2/10/08, B210130268
- 8210130343 Answer supporting NRC 820929 motion for summary disposition of intervenor Contentions 6(a) & (b) & 7(a)(1) No genuing issue of matl fact exists Certificate of Svc encl Related correspondence
  DERCHOLIN E Energy, Dept of EDGAR, G t. Project Management Corp 82/10/12 Atomic Safety and Licensing Board Panel Upp 15682 038 24% Fiche 50-537.82/10/12.8210130343
- 8210200080 Confirms 821005 & 06 telcons NRDC will have no witnesses for LMA-1 hearings other than TB Cochnan NRC considers failure to update discovery to be affirmative statement that previous responses still correct SMANSON.D T Hearing Branch | 82/10/15 FINAMORE B A Naturel Resources Defense Council 3pp 15753 001 24X Fiche 50-537.82/10/15.821020080
- 8210200047 Answer to 820917 third request for production of documents Certificate of 8vc encl
  SMANSON, D.T. Hearing Branch ( 82/10/18 Natural Nesconces)
  Defense Council App. 15755-088-24X Fiche 50-537, 02/10/10.
  8210200047
- 8210200082 Supplemental responses to discovery requests Prof qualifications & Certificate of Svc encl HIBDITTS: H W Joint Applicants-Clinch River Broeder Renttor 82/10/18 Natural Resources Defense Council 27pp 15/52 | 11:2
- 8210210357 Response to 821004 sixth set of interrogatories Related correspondence FINAMORE, BA. WEISS, ER Natural Resources Defense Countri WEISS, ER Sierra Club 82/10/18 Atomic Safety and (intersity Board Panel 26pp 15763 346 24X Fiche 50-537, 82/10/10.
- 8210210453 Response to applicant 821004 seventh set of interrogaturaes & second set of admissions Related correspondence FINAMORE, B.A., WEISS, E.R. Natural Resources Defense Council FINAMORE, B.A. Sierra Club 82/10/18 Joint Applicants Clanch River Breeder Reactor 8pp 15763-065 24X Fiche 50 537,82/10/18 8210210453
- B210210232 Answer to NRC motion for summary disposition of MADC/'ive-ra Club contentions Motion should be granted for Contentions 6.6 (b) (2). (3) & (4) & (5) (2) & denied for Contentions 6.6 (b) (1). (3) & (4) & 7(a)(1) No math facts at issue Related correspondence TOUSELEY, DR FINAMORE, BA Natural Resources Defense Council FINAMORE, BA Bierra Club B2/10/19 Atomic Gafety and Literia.

  Board Panel 17pp 15766 264 24X Fiche 50-537.82/10/19.
- --8210210240 Affidavit of TD Cockran re environ analyses for fuel tyti & timing objective Prof qualifications & Certificate of Byc encl Related correspondence COCKRAN.T B Natural Resources Defense Council 82/10/19 13gs 13764 281 24X Fiche 50-537.82/10/19.8210210232

} 1

8210220268 Motion for qualification of TB Cochran as expert interrogator, allowing Cochran to cross-examine on Contentions 1, 2, 3, 4, 5(b), 6, 7(a), 7(b), 8 & 11, excluding Contentions 1(b), 3(a) & 11(a) FINAMORE, B A , TOUSLEY, D R Natural Resources Defense Causcit TOUBLEY, D R Bierra Club B2/10/20 5pp 15775 051 24X Fichs 50-537, 82/10/20, 8210220265

- -- P210220276 Arfidavit of ER Weiss UCS scientist R Pollard allowed to net KINGENERAL METERS OF METER OUR SCIENTIST M POLIAND as expert witness for UCS t as cross-examiner of other witnesses during TMI restart hearing
  - Ultresses during interestant hearing NEISS.ER Natural Resources Defense Council WEISS.ER United Concerned Scientists WEISS.E.R. Harmon & Weiss. 82/10/20 2pp 15775 056 24% Fiche 50-537.82/10/20.8210220268
  - 8210220279 Affidavit of TB Cochran listing qualifications to be considered as expert interrogator COCHRAN, F B Natural Resources Defense Council 82/10/20 5pp 15775 058 24X Fiche 50-537 82/10/20.8210220268
- -8210220283 Arfidevit of TB Cochian clarifying testimony at 820826-2/ hearings Shock wave production not required for nuclear explosion to occur

  (CCCHRAN T | Natural Resources Defense Council 82/10/20 Jpp

  15775 063 24% Fiche 50-537,82/10/20 8210220268
- 821022028B Request to derer cross examination of C Johnson until 821213-17 portion of LWA-1 hearings Johnson will not be in US during B21116-19 portion of hearings in US during B21116-19 portion of hearings in US during B2116-19 portion of hearings in EISS.E R FINAMORE.B A Natural Resources Defense Council WEISS.E R Sierra Club #2/10/20 Atomic Safety and Licensing Board Panel 3pp 15775 066 24% Fiche 50-537.82/10/20. 8210220248
- --8210220295 Mation to regulate conduct of cross-examination Util & NRC should cross-examine witheases first Util & NRC used cross-examination for rehabilitation Certificate of Svc encii TOUSLEY, D.R., FINAMDRE, B.A. Natural Resources Defense Councii TOUSLEY, D.R. Sierra Club B2/10/20 Atomic Safety and Licensing Board Panel 7pp 15775 069 24X Fiche 50-537. 52/10/20, 82/1020269
- 6210250353 Forwards NRC signed & notarrized affidavits re answers to NADO A Sierra Club 821001 twenty-seventh set of interrogator)es MANASON,D T Hearing Branch 1 B2/10/20 FINAMORC,R , WEISG,F R Natural Resources Defense Council 21pp 15790 343 24X Fiche 50-537, 82/10/20 8210750393
- 6210260397 Supplemental response to second set of admissions & seventh set of interrogatories
  FINAMORE B A MEISSE R Natural Resources Defense Council
  FINAMORE B A Sierra Club B2/10/21 Joint Applicants-Clinch
  Fiver Breeder Reactor 4pp 19803 331 24X Fiche 50-537,82/10/21, 0210260397
- -8210260404 Statement of qualification for intervenor expert witnesser TB Cachran & C Johnson Prof qualifications & Certificate of Sic enc.] FIMAMORE, B.A., WEISE, E.R. Natural Resources Dofense Council FIMAMORE, B.A. Sietra Club. B2/10/21 Bpp. 15803 335 24 Fichs 50-537, 82/10/21, 8210260397
- 8210270015 Forwards documents to be placed in PDR Documents respond to KIUKAUUIS FORWARDS documents to be placed in PDR Documents respon NRDC & Sierra Club 820917 third request for production of documents & Sierra Club 27th set of interrogatories SWEEREY.M F Office of the Executive Legal Director 82/10/22 SCOTT.S Document Management Branch 4pp 15818 092 24X Fiche 50 000, 82/19/22.8210270015
- --8210270020 "Greater Commitment Needed to Solve Continuing Problems at IMI." rept to Congress
  General Accounting Office EMB-81-104 81/08/24 122pp
  15818 076 24X Fiche 50 000.82/10/22.8210270015
- --8210270023 "INEL as Site for Large LMFBR" a Idaho, State of 81/01/31 95pp 15818 218 24X \* Idaho, State of 81/01/31 9 Fiche 50-537,82/10/22,8210270015
- --8210270035 "AIRDOS Computer Code for Estimating Population & Individual Dosos Resulting From Atmospheric Releases of Radionuclides From Nuclear Facilities " MORE, R E Dak Ridge National Laboratory ORNL-TM-4687 /5/01/31 80pp 15819 317 24X Fiche 50-537.82/10/22,8210270015
- --8210270041 "ALLDOS Computer Program for Calculation of Radiation Doses From Airborne % Waterborne Raleases " STRENDE.D L. NAPIER.D A., PELOGUIN,R A Battelle Memorial Institute, Pacific Northwest Laboratory PNL-3524 80/10/31 152pp 15820 034 24% Fiche 50-537,82/10/22,8210270015
- --8210270052 "CONCEPT 5 User Manual " πρ.μι -5470 79 /01/31 HUDSON, C. R. Dak Ridge National Laboratory DRNL-5470 191pp 15820 186 24X Fiche 50-537,82/10/22,8210270015

- --8210270056 Advises that listed mods made to CONTAC & CONCEPT computer codes to improve usefulness & accuracy of CONCEPT code HUDSON.C R Dak Ridge National Laboratory 81/07/02 BDWER5.H 1 Oak Ridge National Laboratory 2pp 15821 017 24X Fiche 50-537.82/10/22.8210270015
- --9210270040 "Energy Economic Data Base (EEDB) Program, " Phase 4 final rept & fourth update rept & Youren update ALLEN,R E United Engineers & Constructors, Inc (subs of Raytheon Co ) UE&C-ANL-810930 81/09/30 421pp 13821 019 24X Fiche 50~537.82/10/22.8210270015
- --8210270044 Computer runs for 400 MW,800 MW & 1.200 MW PMRs + NRC + No Detailed Affiliation Given 82/04/03 24pp 15822 080 24X Fiche 50-537,82/10/22,8210270015
- -8210270068 Provides info re verification of reasonableness of applicant cost estimates for CRBR Applicant cost estimate may be low cost estimates for CMBM Applicant cost estimate may be low due to low excalation rate & imadequate to contingency allowance for design & regulatory evolution BOMERS.H I Dak Ridge National Laboratory FIN 0-0741 82/06/15 TOALSTON.A Antitrust & Economic analysis Branch (Utility Finance) 7<sub>bp</sub> (5822 097 24X Fiche 50-537.82/10/22.8210270015 82/06/15
- --B210270069 Computer printout for 1.000-yr dose ECKERMAN, K F NRC No Detailed Affiliation Given 75. 28pp 15822 104 24% Fiche 50-537.82/10/22,8210270015
- 82:026036: Corrected Page 4 to applicant 82:018 supplemental responses to NRDC & Sierra Club discovery requests Certificate of Svc
  - EDOAR, Q L Project Management Corp B2/10/25 Natural Res Defense Council Spp 15799 358 24X Fiche 50-537,82/10/25. B210240361
- 8210270178 Order ruling on NRC 820927 motion for summary disposition Contentions 6(a) & d(b)(2) dismissed but Contention 7(a)(1) retained Portlans of Contentions 6(b)(3) & d(b)(4) delated LINENBERGER. G. MILLER. M. E. Atomic Safety and Licensing Board Panel 82/10/26 Office of the Executive Legal Director lopp 19820-025 24x fiche 50-537,02/10/26.8210270178
- Q Inspection reports. IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35. Suppl 1, "Leaking & Dislodged I-125 Implant Seeds " Svc list ent! COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York & Aco 15741 256 82/10/06 Consolidated Edison Co of New York 24% Fiche 50-000, 82/10/06, 8208170233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Mail.Large-Diameter: Statuless Steel.Recirculation Sys
  Piping at BWR Plants "Syc list encl
  DEYOUNO,R C Director's Office, Office of Inspection and
  Enforcement 82/10/14 Consolidated Edison Co of New York
  115pp 15810 125 24% Fiche 50-000,82/10/14,8208170238
- T Hearing transcripts on non-antitrust matters
- 8210040257 Transcript of ACRS CRBR Working Group on Sys Integration 820930 meeting (n Mashington, DC Pp 1-242 Viewgraphs enc) \* ACRS Advisory Committee on Reactor Safeguards 82/09/30 359pp 15594 001 24X Fichs 50-537, 82/09/30, 8210040257
- 8210280133 Transcript of ACRS CRBR Thermal Hydraulic Working Group 821026 meeting in Washington, DC Pp 1-278 Eupporting documentation encl \*\* ACRS - Advisory Committee on Reactor Safeguards 82/1456pg 15839 307 24% Fiche 50-537,82/10/26,8210880133
- 8210290184 Transcript of ACR6 Subcommittee on CRBR 821027 meeting in Washington.DC Pp 1-233 Supporting documentation encl \* ACR6 Advisory Committee on Reactor Safeguards 82/10/27 308pp 15855 048 24X Fiche 50-537,82/10/27,8210290184
- DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION: UNIT 1
- A Application/construction stage documents & correspondence
- 8210120348 Forwards NUREG-0885, "Steam Generator Tube Experience," per telephone request W/o enci VOUNDBLOOD, B. J Licensing Branch 1 82/09/13 PILALIS, L Public Service Co of Indiana: Inc 1p 15690 300 24X Fiche 50-546.82/09/13,8210120348

- 8210210023 Summary of 820917 meeting w/util, Bechtel & Sargent & Lundy in Bethesda, MD re SRP conformance review required by 100FRSO 35 DODLITILE, E.L. Licensing Branch & 82/09/27 Licensing Branch & 5pp 15782 203 24X Fiche 50-546.82/09/27,8210210023
- 8210290008 Provides info on procedures for tendering OL application, FSAR & environ rept Two copies of FSAR should be sent directly to E080, who will perform acceptance review NRC will perform acceptance review NRC will perform acceptance review of environ rept YOUNOBLOOD B J Licensing Branch 1 82/10/06 SHIELDS, S W Publis Service Co of Indiana. Inc App 15877 073 24X Fiche 50-546, 82/10/06, 8210290008
- Q Inspection reports, IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents itsted in App A Documents in App B completely withheld (ref FOIA Exemption 5)
  FELTON.J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24X
  Fiche 50-000.82/07/12.8210060015
- --8210080157 Systematic assessment of licenser performance notes re facility evaluation for Jul 1977-June 1980 \* NRC - No Detailed Affiliation Given 80/06/30 9pp 15668 062 24X Fiche 50-000, 82/07/12:8210080015
- 8210130221 Forwards IE Insp Repts 50-546/82-15 & 50-547/82-15 on 820827-28 No moncompliance noted KNOP.R C Division of Project & Resident Programs 82/09/21 SHIELDS.B W Public Service Co of Indiana, Inc 2pp 15674 145 24% Fichs 50-546,82/09/21,8210130221
- --9210130222 IE Insp Repts 50-546/82-15 & 50-547/82-15 on 820827-28 Nu noncompliance nuted Major areas inspected Unit 1 reactor vessel installation activities & 10CFR21 reportable items PELKE.P R. KONKLIN.J E. Division of Project & Resident Programs 82/09/20 Spp 15674 147 24X Fichs 50-546,82/09/21,8210130221
- 8208190233 IE Info Notice 80-35, Suppl 1. "Leaking & Dislodged I-12b Implant Seads " Svc list enc! COBB.L I Division of Fuel Facilities. Materials & Safeguards 62/10/06 Consolidated Edison Co of New York AApp 15761 250 24X Fiche 50-000,82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys
  Piping at BMR Plants " Svc list encl
  DEYQUNO, R C Director's Office, Office of Inspection and
  Enforcement 82/10/14 Consolidated Edison Co of New York
  115pp 15810 125 24% Fiche 50-000, 82/10/14,8208190238
- S Reportable occurrences, LERs & related correspondence
- 8210250130 Interim deficiency rapt re incorrect fabrication of several pieces of structured steel initially reported on 820610 Procedures established to inspect for deficiencies & to repair remaining steel Next rept expected by 830210 SMECDS.S W Public Service Co of Indiana. Inc 82/10/15 KEPPLER.J G Region 3. Office of Director 2pp 15787-016 24X Fiche 50-546, 82/10/15,8210250130
- DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8210120348 Forwards NUREC-0886. "Steam Generator Tube Experience," per telephone request W/o encl VOUNOBLOOD.B J Licensing Branch i 82/09/13 PILALIS.L Public Service Co of Indiana. Inc 1p 15870-300 24X Fiche 50-546.82/09/13.8210120348
- B210210023 Summary of B20917 meeting w/util.Bechtel & Sargent & Lundy in Bethesda.MD re SRP conformance review required by 10CFR50 35 BCGLIYTLE.E L Licensing Branch 1. B2/09/27 Licensing Branch 1 5pp 15782 203 24X Fiche 50-546.B2/09/27.B210210023
- 8210270008 Provides info on procedures for tendering OL application, FSAR & environ rept Two copies of FSAR should be sent directly to EG&O, who will perform acceptance review NRC will perform acceptance review of environ rept YOUNGBLOOD. B. J. Licensing Breanch 1. 82/10/06 SHIELDS, S. M. Public Bervice Co. of Indiana. Inc. 6pp. 15877-073 24X Fiche 50~546, 82/10/06, 8210250008

- G Inspection reports. IE Bulletins & correspondence
- 8210080015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 82/07/12 UDCLL.(f A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000.82/07/12.8210080015
- --8210080159 Systematic assessment of licensee performance notes re racility evaluation for Jul 1979-June 1980 4 NRC - No Detailed Affiliation Given 80/06/30 9pp 15668 062 24X Fiche 90-000,82/07/12.8210080015
- 8210130221 Forwards IE Insp Repts 50-546/82-15 & 50-547/82-15 on 820827-28 No noncompliance noted KNOP.R C Division of Project & Resident Programs 82/09/21 SHIELDS.S W Public Service Co of Indiana, Inc. 2pp 176/4 14J 24X Fiche 50-546,82/09/21.8210130221
- ---8210130222 IE Insp Repts 50-546/82-15 & 50-547/82-15 on 820927 .ii N noncompliance noted Major areas inspected Unit I reactor vessel installation activities & 10CFR21 reportable items PELKE, P R . KONKLIN, J E Division of Project & Resident Programs 82/09/20 Spp 15674 147 24X Fiche 50-546,82/09/21,0210130-31
- 8208190233 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged 1 to Implant Seeds " Svc list encl COBB.L I Division of Fuel Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15/61 200 24X Fiche 50-000:82/10/06.8208190233
- 8208190238 IE Builetin 82-03, "Stress Corrosion Cracking in Thick Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24X Fichs 50-000-82/10/14,82081902JB
- 5 Reportable occurrences, LERs & related correspondence
- 8210250130 Interim deficiency rept re incorrect fabrication of several pieces of structured steel Initially reported on 820610 Procedures established to inspect for deficiencies & to repair remaining steel Next rept expected by 830210 SHIELDS,S W Public Service Co of Indiana. Inc 82/10/15 KEPPLER,J G Region 3. Office of Director 2pp 13787 016 .4x Fiche 50-546, 82/10/15,8210250130
- DOCKET STN-50-553 PHIPPS BEND NUCLEAR STATION, UNIT 1
- Q Inspection reports, IE Bulletins & correspondence
- 820B190233 IE Info Notice 80-35, Suppl i. "Leaking & Dislodged I lar-Implant Seeds " Svc list enci COBB.L I Division of Fuel Facilities. Materials & Bafequards 82/10/06 Consolidated Edison Co of New York 66pp 19761 at 40 24X Fiche 50-000.82/10/06.8208190233
- 8208190238 IE Bulletin 82-03, "Btress Corresion Cracking in Thick Wall, Large-Diameter, Stainless Steel, Recirculation By: Piping at BMR Plants " Svc list encl DEYDUND, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New Yorl 115pp 15810 125 24X Fiche 50-000, 82/10/14, 8208190238
- DOCKET SYN-50-554 PHIPPS BEND NUCLEAR STATION, UNIT 2

  O Inspection reports, IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1, "Leaking & Dislodged 1 km, Implant Beeds " Svc list enc! COBB,L I Division of Fuel Facilities, Materials & Bafeguards B2/10/06 Consolidated Edison Co of New York 66pp 1974도 알았
- 8208190238 IE Bulletin 82-03, "Btress Corrosion Cracking in Thack-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Syc list and DEYDUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/14, Consolidated Edison Co of New York 115pp 15810 125 24X Fiche 50-000.82/10/14,8208190238

~~··~

### DOCKET STR-50-556 BLACK FOX STATION, UNIT 1

- A Application/construction stage documents & correspondence
- B210330595 Informs that implementation of erosion control plan will adequately stabilize soil in areas found to be eroding during site visit in May MOVAK.TM Assistant Director for Licensing B2/09/24 WEST.J I Public Service Co of Otlahoma 2pp 15692 341 24X Fishe 50-556 82/09/24.8210130595
- 1) Inspection reports. IE Bulletins & correspondence
- 8208190233 IE Info Notice 80-35, Suppl 1. "Leaking & Dislodged I-125 Implant Seeds " Syc list encl COBB. L. I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24/ Fiche 50-000/82/10/06/8208190233
- 5208190238 IE Bulletin B2-03, "Stress Corrosion Cracking in Thick-Hall, Large-Diameter Stainlies Steel, Recirculation Sys Piping at BHR Plants " Svc list encl BYGUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fichs 50-000.82/10/14,6208190238
- DOCKET BIN-50-\$57 BLACK FOX STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B210130595 Informs that implementation of erosion control plan will adequately stability soil in areas found to be eroding during site visit in May MOVAK.T M. Assistant Director for Licensing 82/09/24 WESF.J B Public Service Co of Otlahoma 2pp 19692 341 24X Fiche 50-556.82/09/24.8210130595
- a Inspection reports, IF Bulletins & correspondence
- 520B/90203 IE Info Notice BO-35, Suppl 1, "Leaking & Dislodged I-125 Implant Geeds " Svc list encl CDBB, L | Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 247 Fiche 50-000.02/10/06.8208190823
- 62v8190238 IE Dulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter Stainless Bleel, Recirculation Sys Piping at BMR Plants " Svc list encl DEYOUND.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York IJSpp 15810 125 24% Fiche 50-000.82/10/14.0200170238
- DOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1

  4 [Aspection reports, IE Bulletins & correspondence
- 5208190203 IE Info Notice 80-35. Suppl 1. "Leaking & Dislodged 1-125 [mplant Seeds " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 18761 2', 24x Fiche 50-000.82/10/06.8208190233
- 820B190238 IE Builetin 82-03, "Stress Corrosion Cracking in Thick-Hall, Large-Diameter, Stainless Steel, Recirculation Systeps at DNR Plants " Svc list encl
  DEYOUNG.R C Director's Office, Office of Inspection and Conforcement B2/10/14 Consolidated Edison Co of New York
  115pp 19810 125 24X Fichs 50-000, 82/10/14, 820B190238
- S Reportable occurrences, LERs & related correspondence
- 82(0050247 Third & final deficiency repts re resolution of unanticipated vibratary loading concerns Initially reported on Bit228 Program developed to insure piping sys operate within design parameters Next rept provided by 821217 MILLS.L.H. Tennessee Valley Authority 82/09/24 O'REILLY, J.P. Region 2. Office of Director 3pp 15638 104 24X Fiche 50-000, 82/09/24, 8210080247
- \$210050285 First interin deficiency rept re failure to consider seismic & inertial loadings on ladders, platforms & walkways Initially reported on 820826 Const activities deferred until decision re const completion reached HILLS.L M Tennessee Valley Authority 82/09/27 O'REILLY, J P Region 2, Office of Director 2pp 15611 176 24X Fiche 50-566,82/09/27,8210050285

- 8210050273 First interim deficiency rept re six sheared motor pinion keys in Limitorque Model SB-0-25 motor operators Initially reported on 820830 Valves w/motor operators being tabulated Next rept will be submitted by 821122 MILLS.L. H. Tennessee Valley Authority 82/09/28 O'REILLY, J. P. Region 2, Office of Director 2pp 15609 070 24X Fiche 50-000, 82/09/28, 8210050293
- 8210270328 Second interim deficienty rept re use of nonconservative calculational method to evaluate General Const Spec 9-32 spacing violations [nitially reported on 820528 Next rept will be sent by 830528 MILLS.L.M. Tennessee Valley Authority 82/10/12 O'REILLY.J.P. Region 2. Office of Director 2pp 15853 064 24X Fiche 50-000.62/10/12,8210270328
- 8210290187 Interim deficiency rept re deferral of const activities Initially reported on 820623 Commitments made in rept. audit findings & response to violations deferred until restart of design & const MILLS.L M Tennessee Valley Authority 82/10/14 0'REILLY, J P Region 2, Office of Director ip 15853 312 24X Fiche 50-000.82/10/14,8210290187
- 8210290236 Third interim deficiency rept re potentially overstressed embedded plates Initially reported on 820412 Investigation continuing & const activaties deferred until sufficient info gathered to determine completion of project MILLS.L M Tennessee Valley Authority 82/10/14 0'REILLY, J P Region 2, Office of Director 2pp 15853 229 24% Fiche \$50-000,821/0/14,8210290236
- 8210260320 First interim deficiency rept re addition of locking devices to handwheel operated valves Initially reported an 820916 Const activities deferred Analyses of locking devices continuing Next rept will be sent by 820310 MILS.L.M. Tennesses Valley Authority 82710/18 O'REILLY, J.P. Region 2. Office of Director 2pp 15802 359 24X Fiche 50-000.82/10/18,8210260320
- 8210290274 Final rept for Deficiencies B & E & seventh interim rept for Deficiencies A & D re control of procurement activities Initially reported on 810316 Final corrective actions noted Next rept expected by 830428 MILLS.L M Tennessee Valley Authority 82/10/21 O'REILLY, J P Region 2, Office of Director 4pp 19853 143 24X Fiche 50-000, 82/10/21, 8210290274
- DOCKET STN-50-547 YELLOW CREEK NUCLEAR PLANT, UNIT 2

  Q Inspection reports. IE Bulletins & correspondence
- 8208190233 IE lnfo Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Beeds " Syc list enc! COBD.L ! Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24
- 8208190238 IE Builetin 82-03. "Stress Corrosion Cracking in Thick-Wall.Large-Diameter.Stainless Stock Recirculation Sys Piping at BMR Plants "Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000.82/10/14.8208190238
- 9 Reportable occurrences. LERs & related correspondence
- 8210080247 Third & final deficiency repts re resolution of unanticipated vibratory loading concerns Initially reported on Bil228 Program developed to insure piping sys operate within design parameters Next rept provided by 821217 MILLS.L M Tennessee Valley Authority 82/09/24 D'REILLY. J'Region 2, Office of Director Spp 15638 104 24X Fiche 50-000.82/09/24.8210080247
- 8210050285 First interim deficiency rept re failure to consider & inertial loadings on ladders, platforms & walkways Initially reported on 820826 Const activities deferred until decision re const completion reached MILLS.L M Tennessee Valley Authority 82/09/27 O'REILLY. Region 2. Office of Director 2pp 15611 176 24X Fiche 50-566.82/09/27.8210050285
- 8210050293 First interim deficiency rept re six sheared motor pi keys in Limitorque Model 88-0-25 motor operators Initially reported on 820830 Valves w/motor operators being tabulated Next rept will be submitted by 821122 MILLS,L M Tennessee Valley Authority 82/09/28 0'REILLY, Region 2. 8ffice of Director 2pp 15609.070 24X Fiche 50-000.82/09/28.8210050273

- 8210290328 Second interim deficiency rept re use of nonconservative calculational method to svaluate General Const Spec 0-32 spacing violations initially reported on 820528 Nest rept be sent by 830528 MILLS.L M Tennesses Valley Authority 82/10/12 D'REI(LY.J P Region 2. Office of Director 2pp [5853 064 24X Fiche 50-000.82/10/12,8210290328
- 8210270187 interim deficiency rept re deferral of const activities Initially reported on 820623 Commitments made in reptraudit findings & response to violations deferred until restart of design & const MILLS.L M Tennessee Valley Authority 82/10/14 0'REJLLY. J P Region 2. Office of Director ip 15853 312 24X Fiche 50-000. 82/10/14.8210270187
- 8210290236 Third interim deficiency rept re potentially overstressed embedded plates Initially reported on 820412 Investigation continuing & const activities deferred until sufficient info gathered to determine completion of project MILLS, L.M. Tennessee Valley Authority 82/10/14 0'REILLY, J.P. Region 2. Office of Director 2pp 15853 227 24X Fiche 50-000.82/10/14.8210290236
- 8210260320 First interim deficiency rept to addition of locking devices to handwheel operated valves Institully reported on 820916 Const activities deferred Analyses of locking devices continuing Next rept will be sent by 820310 MILLS.L. M. Tennessee Valley Authority 82/10/18 O'REILLY. J.P. Region 2. Office of Director 2pp 19802 359 24X Fichs 50-000.82/10/18.8210260320
- 82:0290274 Final rapt for Deficiencies B & E & seventh interim rapt for Deficiencies A & D re control of procurement activities initially reported on 810316 Final corrective actions noted Next rapt expected by 830428 HILLS.L H Tennessee Valley Authority 82/10/21 O'REILLY, J P Region 2. Office of Director 4pp 15853 143 24X Fiche 50-000.82/10/21.8210290274

#### DOCKET STN-50-584 GIBBSAR, GIBBS & HILL

- A Application/construction stage documents & correspondence
- 8210270124 Forwards QA program, Topical Rept OIBBAR 17-A, Amend A KEDDIS, N N Qibbs & Hill. Inc. (subs of Dravo Corp.) 82/10/25 HAAGS, W P Quality Assurance Branch 1p 15827 115 24X Fiche 50-584, 82/10/25, 8210270124
- --8210270129 Amend 6 to GA program Topical Report OIBSAR 17-A \* Oibbs & Hill, Inc. (subs. of Dravo Corp.) OIBSAR-17-A AO6 82/08/31 115pp 15827 116 24X Fiche, 50-584, 82/10/25, 8210270124

## DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DUCKET 70-0007 ICN PHARMACEUTICALS, INC , IRVINE, CA

- 8210060225 Ferwards IE Insp Rept 70-0007/82-01 on 820505-0605 No noncompliance noted KINNEMAN, J D Division of Engineering & Technical Programs, 82/09/30 BAIETTI, A L ICN Pharmaceuticals, Inc., ICN-C&R Development 2pp 15620 049
- --8210060227 IE Insp Rept 70-0007/82-01 on 820505-0605 No noncompliance ' "acility decontamination surveyed & site closed out cense 37-00345-03 terminated M, KINNEMAN J D. Division of Engineering & Technical 92/08/02 10pp 15620.050

CA

--- CALIMOA D D

for

- --8210060356 IE Safeguards Insp Rept 70-0025/82-08 on 820913-16 No noncompliance noted Major areas inspected measurement control program & independent insp safeguards effort Details withheld (ref 10CFR2 790)

  NELSON.0 B Division of Radiological Safety & Safeguards Program 82/09/27 ip 15615 193
- DOCKET 70-0027 BABCOCK & WILCOX CO , LYNCHBURG, VA
- 8210270232 Forwards mods to B&W upgrade physical security plan.made during implementation Mods withheld (ref 10CFR2 790) KELLY.J W Babcotk & Wilcor Co 82/06/10 EVANS, L J Fuel Facility Safeguards Licensing Branch 2pp 19886 070
- 8210010353 Forwards IE Safeguards Insp Rept 70-0027/82-19 on 820993-2 No noncompliance noted GIBSON.AF Division of Engineering & Technical Programs 82/49/1 ECKERT, J P Babcock & Wilcox Co 2pp 15369 233
- --8210010361 IE Safeguards Insp Rept 70-0027/82-19 on 620623-26 No noncompliance noted Major areas inspected MC 65206B measurement control & statistics Details withheld (ref 10CFR2 790) SARADOS,J W, MCALPINE,E J Division of Engineering & Technola? Programs 82/09/10 ip 15569 235
- 8210150229 Forwards IE Insp Rept 70-0027/82-20 on 820830-0901 No noncompliance noted GIBBONAF Division of Engineering & Technical Programs 827/99/1 ECKERT.J P Babcock & Wilcox Co 2pp 15701 356
- --8210150239 IE Insp Rept 70-0027/82-20 on B20830-0901 No noncomplia:
  noted Major areas inspected review of lab QC program,
  radiochemistry procedures & records & liquid & gaseous
  sampling & accountability
  EVANS.C D. MCNTGOMERY.D M Division of Emergency Preparednoss:
  Operational Support 82/09/16 4pp 15701358
- 8210220497 Forwards page changes to radiological contingency plan to clarify procedure for notifying NRC state & locality of declared state emergency Provisions for assessing offsite radiological impact of radiological emergency also revised KELLY.J W Babcock & Wilcox Co 92/09/29 PAGE.R O Uranium Fu Licensing Branch 4pp 15786-317
- B210210341 Forwards IE Safeguards Insp Rept 70-0027/B2-25 on 820927-1001 No noncompliance noted 01BSDN.AF Division of Engineering & Technical Programs 92/10/ECKERT, J.P. Babcock & Wilcox Co. 2pp. 15764-307
- --8210210342 IE Safeguards Insp Rept 70-0027/82-25 on 820927-1001 21: noncompliance noted Mayor areas inspected security plan & implementing procedures: records & repts; lucks, keys & detection aids Details withheld (ref 100FR73 21) 0000E.R W : MCGUIRE.D R Division of Engineering & Technical Programs 82/10/14 1p 15744 309
- DOCKET 70-0033 TEXAS INSTRUMENTS, INC , ATTLEBORO, MA
- B210070239 Forwards IE Insp Rept 70-0033/B2-04 on B20901-03 No noncompliance noted STAROSTECKI, R Division of Project & Resident Programs B2/09/2: ODET2.W K Texas Instruments, Inc. 2pp 15637 146
- --8210070240 IE Insp Rept 70-0033/82-04 on 820901-03 No noncompliant noted Major areas inspected review of operations closeout surveys:environ programs & licensee/licensing meeting ROTH: J. KEIMIO, R. Division of Project & Resident Programs SHUN: C. Office of Nuclear Material Safety & Safeguards, Director 82/09/21 4pp 15637 146
- 9210290238 Forwards IE Insp Rept 70-0033/82-03 on 820831-0902 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/10 OGETZ.W H Texas Instruments, Inc 2pp 15853 198
- --B210290241 IE Insp Rept 70-0033/82-03 on B20831-0902 No noncomptinated Major areas inspected licenses closeout survey rept.
  Independent measurements in general mfg area, chemical & metallographic labs & roof exhausts

  JOHANSEN, J., LADUN, R., KINNEMAN, J. D. Division of Engineering & Technical Programs 82/10/12 lipp, 15853 200.

- COLVET 70-0096 COMBUSTION ENGINEERING, INC., WINDSOR, CT
- 8\_10210583 Provides schedule for review of license renewal application.
  Contents & recommendations on application.notification of scheduled imsp & action required to meet schedule requested CRGW.H T Uranium Evel Licensing Branch 8\_2/10/01 MILLER.J R Division of Engineering & Technical Programs 2pp 15782-360
- 8210180316 Requests transfer of C-E fee funds from deferred revenue to catls revenue account per review of amend to License ENM-33 MILLER. U.O. License fee Management Branch 82/10/06 MANION. W.E. Finantial Operations Branch 1p 15746-017
- DOCKET 70-0135 DADCOCK \* WILCOX CO . APOLLO, PA
- EC10130303 Ack receipt of 820728 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 70-0135/82-07 & 70-0364/82-06 SIRROSTECKI, # Division of Project & Resident Programs 82/10/04 CARLSON, R V Babcock & Wilcox Co 1p 15678 181
- --921013030B Responds to NRC 820901 ltr re violations noted in IC Insp. Repts 70-0135/82-07 & 70-0364/82-06 Corrective actions ammonium diuranate drying belt encl adjusted & more effectively designed reflector installed AUSTIFIAM A Babcock & Milcox Co 82/09/28 STAROSTECKI, R Division of Project & Resident Programs 2pp 15678 182
- DOCKET 70-0143 NUCLEAR FUEL SERVICES. INC., ERWIN, IN
- 8210270235 Application for amend to License SNM-124 to allow use of rinishing onlit for tinishing highly enriched U in Bldg 110 MICHEL C J Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.) 82/04/14 WIXON W Division of Fuel Cycle & Material Bafety 20p 18974 073
- e210200571 Forwards Revision B to physical safeguards plan incorporating personnel search to detect 3 g unshielded U. enriched to 90% U-235, to allow wider range of flexibility Revision withheld (ref 10CRT93 21) MICHEL.C J Nuclear fuel Services, Inc. (subs of Gotty Oil Co.) 82706701 EVANS.L J Fuel Facility Safeguards Licensing Branch 10 15814 358
- 8210150061 Confirms 820721 commitment to submit groundwater nanitoring program to NMSS by 821015 MANSER,N C Nuclear Fuel Sorvices, Inc (subs of Getty Oil Cn ) 82/07/27 (IBBON.A.F Division of Engineering & Technical Programs 1p 15701 264
- 8210010164 Ack receipt of IC Insp Rept 70-0143/82-28 No proprietary into MANSER, W.C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Cu.) 82/08/30 (DISSON, A.F. Division of Engineering & Technical Programs 1a 15968-090
- 9219260569 Forwards Page 3-2 to application for renewal of Certificate of Compliance 5492 for Model RNG-181-[ inadvertantly omitted from original MICHEL C J Nuclear Fuel Services. Inc (subs of Getty Oil Co) 92/09/30 MACDONALD. C E Transportation Branch Ip 15814 355
- --8210260569 Page 3-2 to application for renewal of Certificate of Compliance 5492 for Model RMG-181-1 MACDONALD.C & Transportation Branch 82/08/25 ip 15814 396
- 8210010162 Concurs w/decision to terminate use of environ impingers in conjunction u/environ samples based on review of 820527 results of environ impinger air measurements for Jan-Mar 1982 GISSON A F Division of Engineering & Technical Programs 82/09/03 MAVSER.W C Nuclear Fuel Services, Inc (subs of Getty Dil Co) ip 15567 273
- 8210010344 Forwards IE Insp Rept 70-0143/82-32 on 820823-27 No noncompliance noted GIBSONA F Division of Engineering & Technical Programs 82/09/10 MANEER, N C Nuclear Fuel Services, Inc (subs of Getty Oil Co ) 2pp 15567
- --8210010371 IE Insp Rept 70-0143/82-32 on 820823-27 No noncompliance noted Hajor areas inspected facility operations, storage & internal control & records & repts Details withheld (ref 100FR2 790)

  100D.0 A , MCALPINE. J Division of Enganeering & Technical Programs 82/09/10 ip 15569 238

- 8210150197 Forwards IE Safeguards Insp Rept 70-0143/82-33 on 820806-0903 No noncompliance noted GIBSON.A F Division of Engineering & Technical Programs 82/09/14 MANSER.W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 15715 273
- --82i0150204 IE Safeguards finsp Rept 70-0143/82-33 on 820806-0903 No nancompliance moted Major areas inspected licensee action on previous inspectoromoroutine events & facility operation Details withheld (ref 10CFR2 770) LEE.TD , MCALPINE,E J Division of Engineering & Technical Programs 62/09/14 App 15715 275
- 8210040048 Ack receipt of check in payment of civil penalty proposed on 820809 Corrective action discussed in 820903 ltr will be examined during future insp. AXELRAD. J A Director's Office, Office of Inspection and Enforcement 82/09/21 MANEER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co ) 2pp 15977 288
- 8210010052 Denies 820127 % 0507 requests that IE Insp Rept 70-0143/81-04 not be placed in PDR 0/REILLY.J P Region 2. Diffice of Director 82/07/22 MANSER.W C Nuclear Fuel Services, Inc. (subs. of Oetty Oil Co.) ip
- 82(00)0313 Forwards IE Safeguards Insp Rept 70-0143/82-34 on 820907-10 No noncompliance noted OIBSON.A F Division of Engineering & Technical Programs 82/09/22 MANSER.N C Nuclear Fuel Services, Inc (subs of Getty Oil Co ) 200 15568 283
- --8210010317 IE Safeguards Insp Rept 70-0143/82-34 on 820907-10 No noncompliance noted Major areas inspected shipping & receiving of SNM Details withheld (ref 10CFR2 790) JONES, D. W. RICHARDS, B. L. HCALPINE, E. J. Division of Engineering & Technical Programs 82/09/22 ip 15568 285
- B210150473 Ack receipt of check for \$2,500 sent in payment of civil penalty proposed on 820809 Corrective action specified in 820903 ltr will be examined at future imap AXELRAD.J A Enforcement Staff 82/09/22 MANBER.W C Nuclear Fuel Services, Inc (subs of Oetty Oil Co ) 2pp 15714 172
- --8210150477 Responds to NRC 820809 ltr re violations noted in IE Insp. Rept 70-0149/82-23 Corrective actions withheld (ref. 100FR2 790) Payment of civil penalty encl.

  MANSER, N.C. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.)

  B2/09/03 Director's Office, Office of Inspection and Enforcement 1p 19714 174
- 8210040085 Order establishing addl extensions of time Parties may submit questions to be posed in oral session by 821109 Oral session will be held between 821215-830115 CHILK, S. J. Office of the Secretary of the Commission 82/10/01 2pp 15581 039
- 8210080179 PND-11-82-10A on 821003, explosion occurred in calciner area of scrap recovery bldg.causing two to three times max airborne radioactivity release Caused by introduction of volatile math to calciner (small furnace) WRAY, JR. O 1880N, A.F. Region 2, Office of Director 82/10/04 2pp 15640 165

82

- --B210(50376 Forwards IE Safeguards Insp Rept 70-0143/82-29 on 820802-06 & notice of violation Details & notice of violation uithheld (ref 10CR73 21)
  GLSHINSKI.J A Division of Engineering & Technical Programs 82/08/25 MANSER.W C Nuclear Fuel Services, Inc (subs of Getty Gil Co ) 2pp 15704 273
- --8210150380 IE Safeguards Insp Rept 70-0143/82-29 on 820802-06 Nonconpliance noted failure to review & audit safeguards contingency plan Details withheld (ref lockr73 21) PERNY,C D., TILLMAN.A., McGUIRE.D R. Division of Engineering & Technical Programs 82/08/24 2pp 15704-275
- B210130383 Motion for Commission to direct DDE to make available to NRDC, under suitable protections, classified info covered by enci FOIA request Deadline for filling testimony should be suspended Certificate of Svc enci WEISS.ER Natural Resources Defense Council WEISS.ER Harmon & Weiss 82/10/08 Commissioners 12pp 15680 324
- B210130281 Advises that organization will appear at hearing but will not present direct oral testimony Comments provided on Issues A.B & C MISDRENER.J M Gil.Chemical & Atomic Workers Intl B2/10/12 CHILK.S J Office of the Secretary of the Commission 3pp 15578 278
- 8210150472 Order denying NRDC 821012 motion to suspend deadline for filing testimany until NRDC FOIA requests resolved Motion would be unnecessary if NRDC had filed FOIA request on more timely basis Commissioner Ahearne separate views encl CHILK.S J Office of the Secretary of the Commission 82/10/14 Natural Resources Defense Council 3pp 15703 040
- 6210180103 Submittal of R Burnett 820930 testimony representing consolidated testimony of all NRC ofts FORMER R L Regulations Division 82/10/14 2pp 15718 025
- --8210180107 Testimony of R Burnett Present safeguards program adequate to protect public health & safety License should be revoked if amend not sustained W/Certificate of Bvc BURNETT.R F Division of Safeguards 82/09/20 30pp 15718 02/
- 8210200001 Forwards memorandum of law re license amend process & TB Cochran testimony Testimony & Exhibit 28 withheld SCHERR. S J Natural Resources Defense Council 82/10/15 STUCKY.S H Docketing & Services Branch (p 1575
- --8210200004 Memorandum of law on license amend process Amend unlawfully substitutes "reasonably achievable" std in place of lagislatively ordained std of protection of public health & safety Certificate of Svc encl Exhibit 20 withheld HEISS ER Natural Resources Defense Council 82/10/15 Commissioners 240pp 15755 105
- 8210200057 Response opposing NRDC motion for Commission to direct production of documents FOIA process cannot be used as substitute for discovery Commission has no authority to order production of DDE documents Certificate of Svc encl LEIKEN.L., BERGHOLZ, W.E. Energy, Dept of 82/10/18 Commissioners 8pp 15756-048
- 8210250060 Forwards Page 50 of written testimony filed w/Commission on 821015 LEIKEN.L Energy, Dept of 82/10/21 CHILK,S J Office of the Secretary of the Commission ip 19787 090
- ---8210250041 Page 50 of testimony filed the option on #21015, inadvertently omitted Certificate of Svc encl tenengy, Dept of #2/10/21 3pp 15787 091
- DOCKET 70-0223 CALIFORNIA, UNIV OF, LOS ANGELES, CA
- 8210290023 Partial response to FOIA request for documents re UCLA Lab & research reactors Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/09/00 HIRSCH.D Government Accountability Project 2pp. 15864 195
- --B21029004B Discusses insp of activities authorized under License R-71 & SNM-974 on 780520 No honcompliance noted Major areas inspected control of SNM & selective exams of procedures & personnel interviews SNM-974 or Procedures & Personnel interviews ENMELKEN, R H Region 5, San Francisco. Diffice of the Director 75/06/10 BROWN, N V California, Univ of Lus Angeles 1p 15864 262 24x Fiche 50-142,82/09/03.8210290023

## DOCKET 70-0278 DOW CHEMICAL CO . MIDLAND, MI

- 8210180028 Responds to FOIA request for seven categolies of documents re Dow Chemical Co & incineration of low level radwaste Request for fee waiver granted Forwards listed documents FELTON.J.B. Division of Rules and Records 82/08/20 Willight A. Afriliation Unknown 2pt
- --82(0180424 Provides info re use of Dow Chemical Co radiation profitt; manual.per AEC 58(219 ltr Requests info on licensing of irradiated U BEAMER,W H Dow Chemical Co 58/12/24 JOHNSON,L. Atoms: train. Commission 2pp 15748 331
- DOCKET 70-0364 BABCOCK & WILCOX CO , APOLLO, PA
- 8210280452 Forwards corrected Page 8 of Amend 17 to ticense 4.6 414 issued 820831 License Condition 36 C should reflect conditions contained in Amend 12 issued 810225 ROUSEL C Advanced Fuel & Spent Fuel Licensing Branch 187007 of AUSTIN.M A Babcock & Wilcox Co 1p 15859 011
- --8210280453 Corrected Page 8 to Amend 17 to License GNM-414.revision 24 C License Condition 34 C ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch (12) (1) 1 1p 15859 012
- 8210070307 Forwards IE Insp Rept 70-0364/82-05 on 82072まと notice にいいる institution MARTINIT T Division of Engineering & Technical Programs (Indアンチン) CARLSON R V Babcock & Wilcox Co 2pp 15634 により
- --8210070312 Notice of violation from insp un 02072;

  # Division of Engineering & Technical Programs G2/07/24 \*\*F
- --8210070316 IE Insp Rept 70-0364/82-05 on 920723 Noncompliants rolls excessive dose rate at external surface of vehicle & failure to label package correctly CLEMONS.P E. GREENMAN.E Q Division of Engineering & Technics #1 Programs 82/09/21 7pp 15634 127
- 8210130303 Ack receipt of 820928 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/82 0/ to 70-0364/82-06 STARGSTECKI,R Division of Project & Resident Programs (62/10/25 CARLSON,R V Babcock & Wilcor Co. ip 15670 101
- --9210130308 Responds to NRC 820901 ltr re violations noted in 11 hily Repts 70-0135/82-07 & 70-0364/82-06 Corrective actions ammonium discremants drying belt encl adjusted & more effectively designed reflector installed AUSTIN.M A. Babcock & Wilcox Co. 82/09/28 STARGETICKL. It Division of Project & Resident Programs. 2pp. 196/4 187
- DOCKET 70-0371 UNC NAVAL PRODUCTS: INC . UNCASVILLE, CT
- 8210040392 Issues Amend 18 to License SNM-368, authorizing new starage shelves & new fuel handling criteria for raw fuel storage room, in response to 820510 application & 820604,8709 & 0812 suppls
  PAGE,R 9 Uranium Fuel Licensing Branch 82/09/07 XIRK, H & United Nuclear Corp 2pp 15597 214
- --B210040377 Safety evaluation supporting Amend 18 to License 'NM's Arb BIDINGER, G. H. CROW, W.T. Uranium Fuel Licensing Branch (AA's Lill 2pp 15597-216
- 8210250016 Forwards revised fundamental nuclear matl control progress W/o enci COLLOPY,Y J United Nuclear Corp 82/09/07 EVANS,L J fuel Facility Safeguards Licensing Branch ip 15808 259
- 8210220168 Forwards IE Safeguards Insp Rept 70-0371/82-10 on 826916-19 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/10/10 AMY.0 D United Nuclear Corp 2pp 15778 055
- --8210220172 IE Safeguards Insp Rept 70-0371/82-10 on 820816-19 P4noncompliance noted Major areas inspected security plan & implementing procedures lighting & review of open items Details withheld (ref 100FR73 21) SMITH.0 C , QODY,A T. Division of Engineering & Technical Programs. 82/10/07 ip 15778 057

- 8210220177 Forwards IE Safeguards Insp Rept 70-0371/82-09 on 820809-13 No noncompliance nuted MARTIM T T Division of Engineering & Yechnical Programs 82/10/14 AMY.C O United Nuclear Corp 2pp 15777-304
- --0210220179 IE Safeguards Insp Rept 70-0371/82-09 on 820809-13 No noncompliance noted Major areas inspected measurement control program Details withheld (ref 10CFR2 790) ZIBULSKY, H. GDDY, A.T. Division of Engineering & Technical Programs 62/10/07 1p 15777 304
- DOCKET 70-0398 COMMERCE, DEPT OF, WASHINGTON, DC
- 921CO60138 Ark receipt of 820917 ltr informing NRC of steps taken to correct violations noted in IE lusp Repts 70-0398/82-03 & 30-03918/82-03 MARTIN. T T Division of Engineering & Technical Programs 82/09/30 PEVEYL E Commerce Dept of National Bureau of Standards 1p 1544-304
- --8210060147 Responds to NRC 820908 ltr re violations noted in IL libp Repts 70-0398/82-03 & 30-03718/82-03 Corrective actions instructions issued re Spec /A container reuse & labeling & posting of containers for Cf-252 source PEVEY.LE Commerce.Dept of National Bureau of Standards 82/097/17 MARTIN.T T Division of Engineering & Technical Programs 2pp 19614 305
- DOCKET 70-0416 COLORADO STATE UNIV , FT COLLING, CO
- 6210220004 IE Insp findings & Licensee Ack dtd 620921 of License SCH-380 Insp findings no violations observed SPITBERG.D D Region 4. Office of Director 82/09/21 13pp
- DOJKET 70-0633 PAN AMERICAN WORLD AIRWAYS, INC , PATRICK AFD, FL
- 8210010116 IE Insp Findings & Licensee Ack dtd 820901-02 of License ENM-575 Insp findings no nancompliance noted FRAMALIKA | Region 2. Office of Director 82/09/02 ip 15567 219
- COURET 70-0667 UNION CARBIDE CORP . TUXEDOS NY
- Ga10270067 Forwards integrated site wide emergency preparedness plan Agreement it's encl HUZICKA. H G Union Carbide Corp 82/09/03 CUNNINGHAM. R E Division of Fuel Cycle & Material Safety ip 15836 128
- --8210270070 Nuclear facility emergency plan + Union Carbide Corp 82/09/03 85pp 15836 129
- B210220260 Forwards II Sareguards Insp Rept 70-0687/82-06 on 82090/-10
  No noncomptiance nuted
  MARIIN I Division of Engineering & Technical Programs 82/10/19
  MCGUVERN, J. J. Union Carbide Corp. 2pp 15776 325
- --0210220264 IE Safeguards Insp Rept 70-0687/82-06 on 820907-10 No noncompliance noted Major areas inspected nuclear maticontrol & accounting, including measurement & statistical controls Details withheld (ref 100FR2 790) 218ULSKY, H., RATTALA D., CODY. A T. Division of Engineering & Technical Programs 82/10/07 ip 19774-327
- DOCKET 70-0753 WHEATON COLLEGE, WHEATON, IL
- 62[6220343] Memorandum & order directing OE to file rept on intention to submit applications to renew OL & SNM license, within 15 days of sic of order FRYELJH Atomic Safety and Licensing Board Panel 82/10/21 General Electric Co 3pp 19776 265 24x Fiche 50-070,82/10/21, 8210220343
- DOCKET 70-0754 GENERAL ELECTRIC CO . PLEABANTON: CA
- 8210080302 Forwards IE Insp Hepts 70-0754/82-03 on 820812 & 70-0754/82-04 on 820910 & 14 Excessive Pu contamination levels found in Advanced Fuels Lab Bldg 102 basement, front Lab & sodium room areas in 820812 insp BCA:H E Division of Radiological Safety & Bafeguards Program 82/10/05 ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 2pp 15638 008

- --8210080311 IE Insp Rept 70-0754/82-04 on 820910 & 14 Major areas inspected walls, floors, pipelines & fixture Pu contamination levels in Advanced Fuels Lab Bldg 102 Surfaces within guidelines for release of area for unrestricted use RIEDLINGER, B A, PANG.J F., ZURAKONSKI.P R Division of Radiological Safety & Safeguards Program 82/09/28 19pp 15498 072
- 82:0190473 Forwards IE Insp Rept 70-0754/82-04 on 820910 % 14 No noncompliance noted 800K.H E Division of Radiological Safety & Bafeguards Program 82/10/05 DARMITZEL, R W General Electric Co 2pp 15740 220
- 8210200087 Notice of ASLB reconstitution JH Frye, chairman & H Foreman & OA Linenberger, members
  COTTER, B P Atomic Safety and Licensing Board Panel 82/10/14
  2pp 15753 176 24X Fiche 50-070,82/10/14,8210200087
- DOCKET 70-0820 UNITED NUCLEAR CORP . WOOD RIVER JCT . RI
- 82)0270218 Forwards well results Sr-90(pCi/L), Apr 1980-Mar 1782 MELGESON, K.A. United Nuclear Corp. 82/06/17 CROW. W.T. NRC - Nu Detailed Affiliation Given 2pp 15896-041
- 8210250012 Forwards corrected copy of fertilizer analysis performed & reported on 800718 Analysis consistent w/n-ture of crushed apatite fertilizer

  #ELOESDN.X A United Nuclear Corp 82/06/22 CRDW.H T Uranium Fuel Licensing Branch 2pp 15808 [8]
- 8210270206 Forwards corrected copy of Controls for Environ Pollution.
  Inc 800718 Fertilizer analysis, per 820911 request Fluoride
  concentration analysis consistent w/nature of crushed
  apatite fertilizer
  - apatite fertilizer HELDESDN.KA United Nuclear Corp 82/06/22 CROW.W.F. Uranzum Fuel Licensing Branch 2pp 15836 031
- 8210200104 Forwards "Water Solubility Test Performed on Soll." used by analytical vendor HELGESON, KA United Nuclear Corp. 82/08/18 CROW, W.T. NRC Nu Detailed Affiliation Given . Ip. 15767-307
- --B310200106 "Water Bolubility Test Performed on Soil," for United Nuclear Corp.Woodriver Junction.RI MUELLER.J J Controls for Environmental Pollution. Inc. B2/07/ NRC - No Detailed Affiliation Given 9pp 15767 308
- 8210250014 Forwards response to NRC comments on licensee 820412 detailed soil decontamination plan Revised plan will not be presented but comments will be incorporated into plan GREGG R J United Nuclear Corp 82/08/31 CROW.W T NRC No Detailed Affiliation Given 6pp 15808 253
- 821026010B Forwards response to NRC comments on 820412 detailed suil decontemination plan Conduit to river will be surveyed per required criteria Site characterization survey will be forwarded under separate cover GREGOR J United Nuclear Corp 82/08/31 CROW, W T NRC No Detailed Affiliation Given 6pp 15808 353
- 8210270213 Forwards response to NRC Comments 1-13 on 820412 "Detailed Soil Decontamination Plan " Revisions will be incorporated into final survey rept GREGO,R J United Nuclear Corp 82/08/31 CRDW.W T NRC No Detailed Affiliation Given 6pp 15836 035
- 8210260038 Forwards site characterization survey w/addendum re dose commitment data for Lagoon A area soil sample analyses HELCESON.K A United Nuclear Corp 82/09/02 CROW,W T NRC - No Detailed Affiliation Given ip 15809 001
- --B210260041 Exposure tables for Dec 1981

  \* Controls for Environmental Pollution, Inc. 81/12/31 41pp.
- --B210260049 "Macadam & Soil Statistical Analysis & Evaluation of Analytical Data for Decommissioning of Woodriver Junction Facility" "Controls for Environmental Pollution, Inc. 81/07/14 443pp.
- 8210270173 Provides info on & justification for two imperative actions to be taken as preventive maint re roof over main processing bldg & ofc areas & steelwork in process area QREGO, R. J. United Nuclear Corp. 82/09/07 GROW, W.T. NRC No Detailed Affiliation Given 3pp. 15835-329

1 1

- B210290211 Requests detailed survey rept for maint to be performed on roor & steelworks, including map showing grid sizes & locations & survey results for each grid Time should be scheduled so Region 1 can conduct survey prior to painting CROW.H T Uranium Fuel Licensing Branch 82/09/28 GREGO.R J United Nuclear Corp ip 15876-257
- DOCKET 70-0824 BABCOCK & WILCOX CO . LYNCHBURG, VA
- 8210220231 Responds to MRC itrire violations noted in IE Insp Rept 70-0824/82-04 Corrective actions cutting & welding permit form revised W/o encl OLSENIA F Dabcock & Hilcox Co 82/08/18 TROUP.G L Region 2, Office of Director 1p 15775 130
- 82(0150130 Forwards tE Insp Rept 70-0824/82-05 on 820901-03 No noncompliance noted 01880N.A F Division of Engineering & Technical Programs 82/09/16 ENGELDER, T C Babcock & Wilcox Co 2pp 15698-318
- --8210150136 IE Insp Rept 70-0824/82-05 on 820901-03 No noncompliance noted Major areas inspected external & internal radiation control, contamination surveys & source leak testing XAMLE-J B. MRTZGER, J R. BARR, K. Division of Engineering & Technical Programs 82/09/15 4pp 15698 320
- 9210010388 Forwards IE Safeguards Insp Rept 70-0624/82-06 on 920909 & 17 No noncompliance noted 10 Components of Engineering & Technical Programs 10 Components of Engineering & Technical Programs 10 Components of ENGELDER. T C Babcock & Hilcox Co 2pp 15572 289
- --B210010378 IE Safeguards Insp Rept 70-0874/82-06 on 820909 & 1/ Nu noncompliance noted Major areas inspected MC-85206 measurement control program (scrap/waste) Rept details withheld (ref 100FR2 790) CLAY, E. L. MCALPINE. E. J. Division of Engineering & Technical Programs 82/09/22 1p 15372 29(
- 8210210194 Forwards IE Safeguards Insp Rests 50-013/82-03 & 70-0824/82-10 on 820930-1001 No noncompliance noted 01880N:A F Division of Engineering & Technical Programs 82/10/15 ENGELOER: T C Babcock & Wilcox Co 2pp 15765 304 24X Fiche: \$0-013,82/10/15,8210210194
- --B210210206 IE Safeguards Insp Repts 50-013/82-03 & 70-0824/82-10 on 820730-1001 No noncompliance noted Major areas inspected physical protection of low enriched SNM Details withheld (ref 10CFR2 770)
  OGODE, R. MCGUIRE, D.R. Division of Engineering & Technical Programs 82/10/15 ip 15765-306 24X Fiche 50-013,82/10/15,82/0210/19
- DOCKET 70-1100 COMBUSTION ENGINEERING, INC . WINDSOR, CT
- 8210220440 Forwards typical American Nuclear Insurers insp rept. BHEERAN.R E Combustion Engineering, Inc. 92/09/16, NRC - No Detailed Affiliation Olven Spp. 15786-214
- 8210060365 Forwards IE Safeguards Insp Rept 70-1100/82-07 on 820824-27 No noncompliance noted MARTIKE, T. Devision of Engineering & Technical Programs 62/09/28 LICHTENBERGER Combustion Engineering, Inc. 2pp 15615,188
- ---8210060370 IE Safeguards Insp Rapt 70-1100/82-07 on 820824-22, No noncompliance noted Hajar areas inspected facility organization, operation & mgt of matls control sys Details withheld (ref 100FR2, 790) DELLA RATTA, A.; GOPY, A.T. Division of Engineering & Technical ms. 82/09/21 19 18415.190
  - ceipt of 820910 ltr informing NRC of steps taken to one noted in IE Insp Rept 70-1100/82-06.

    Project & Resident Programs. 82/09/29 oring. Inc. ip 13883 100
    - s violations noted in IE Imap adjustable windows for chemistry labs set at
    - inc 82/09/10 Resident Programs 2pp.

- DOCKET 70-1113 GENERAL ELECTRIC CO . WILMINGTON, NO
- 8210220518 Advises that groundwater monitoring program will be implemented before 82:101
  MAKILD C North Carolina, State of 82/09/15 CROH, W.T. Urina: \*
  Recovery Licensing Branch 1p 15786 085
- 8210150064 Forwards IE Safeguards Insp Rept 70-1113/82-10 on (\$20/07-12 No noncompliance noted Glegon, A.F. Division of Engineering & Technical Programs 8://G9:21 LONG, J.A. General Electric Co. 2pp. 15715-270
- --B210150067 IE Safeguards Insp Rept 70-1113/82-18 on 020/0/-10 to noncompliance noted Major areas inspected measurement control program & followup of previous insp findings Details withheld (ref 10CR2 770)
  BATES, J W. BABADDS, J W. MCALPINE, E. J. Division of Engineering | Technical Programs. B2/09/24 ip 15718 271
- 8210270425 Notification of contract execution. Hod 2 to "flA No of SM License SNM-1097" Contractor Science Applications, Isia FLEENOR.C M. Administrative Contracts Branch FIN B 7337 1 82/097/30 DAVIS.J., LDYSEN.P. Office of Nuclear Malerial Systems I Bafeguards, Director 1p 15833 357
- --8210270428 Mod 2.deobligating unexpended balance of contract funds issuance of no cost settlement after termination, to 'fla re OE SMM License SMM-1097' ARCHER, C.D. Science Applications, Inc. HAGAN, T.F. Technismit Assistance Contracts Branch FIN 8-7337-1 192/09/30 Jpp 1983 338
- 8210210514 Forwards draft litense conditions re effluent & prosent nonradiological monitoring requirements Conditions (include stack monitoring of fluoride release & groundwater monitoring on nonradiological parameters (CROW.W T. Uranium Recovery Litensing Branch B2/10/01) WAKILD (North Carolina, State of App. 15782-201
- 9210220205 Ack receipt of IE Insp Rept 70-1113/92-20 on Ha0/11 13 N proprietary info VAUOHAN, C M General Electric Co 92/10/12 GIBBENA J DEVES of Engineering & Technical Programs 1p 15/76 373
- 8210220420 Ack receipt of 820914 ltr informing NRC of steps taken to correct violations noted in IC Insp Rept 70-1113/III JA OLSHINSKI, JA Division of Engineering & Technical Progress 82/10/12 LONG, JA General Electric Co
- --8210320427 Responds to NRC 820820 ltr reviolations noted in It Rept 70-1113/82-16 Corrective actions meetings between supervisors & radiation technicians conducted & new survey equipment ordered AVAUMAN.C M General Electric Co 82/09/14 (DLSMN6n). F A Division of Engineering & Technical Programs (Spp. 15/46) 215
- --8210220430 Forwards IE Insp Rept 70-1113/82-16 on 820/86 to & videtion OLBRINBRIJ A Division of Engineering & Technical Programs 82/08/20 LONG, J A General Electric Co Spp 15/80 215
- --B210220437 Notice of violation from insp on 820726 30 t OBJ 1-Q‡
  # Division of Engineering & Technical Programs 8708740
- --B210220442 IE Insp Rept 70-1113/B2-16 on B20726-30 & ORB ) C& Noncompliance noted contamination limits exceeded for release of mati to restricted area HOBEY, C M . BARR, K P Division of Engineering & Tachmical Programs B2/08/19 10pp 13780 218
- 8210220308 Ack receipt of 820930 ltr informing NRC of steps tatal correct violation noted in IR Insp Rept 70-1132/82-17 GRIBON.AF Division of Engineering & Technical Programs Ballong, J.A. General Electric Co ip 18778 304
- --B210220320 Responds to NRC B20902 ltr reviolation noted in RE Rept 70-1113/82-17 Corrective actions withheld cref 10CFR2 790)
  VAUDMAN.C M General Electric Co B2/09/30 DL6HINGK! J a Division of Engineering & Technical Programs ip 157/8 36
- DOCKET 70-1149 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH. PA
- 8210150433 Advises that portion of few for Amend 7 to License 5J will be refunded HILLER, H.O. License Few Henegement Branch 82/10/07 MARDI. Westinghouse Electric Corp. 1p. 15715.360.

### SUCKET 70-1151 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA

- E216010189 Ack receipt of IE Safeguards Insp Rept 70-1151/82-16 on 820815-19 No proprietary info FOSTER, H Westinghouse Electric Corp 82/09/10 O'REILLY, J P Region 2, Office of Director ip 15567 312
- 321u270434 Amend 11 to License SNM-1107, authorizing disposal of moth containing trace quantities of enriched U as of 820818 PACE, R.G. Uranium Recovery Licensing Branch 82/10/12 NORDI. A J. Wastinghouse Electric Corp. jp. 15833-281
- --8210270436 Safety evaluation supporting Amend 11 to License SMM-()O/ redisposal of trace quantities of enriched U BIDINGER, G. H. CROW, W. T. Uranium Recovery Licensing Branch 82/10/12 1p 15833-282

# DOCKET 70-1201 BABCOCK \* WILCOX CO , LYNCHBURG, VA

- e210010121 Forwards IE Insp Rept 70-1201/82-13 on 920830-0901 No noncompliance noted OIBSON: A F Division of Engineering & Technical Programs 92/09/10 ALTO, R A Babcock & Wilcox Co 2pp 15567 220
- 8210010127 IE Insp Rept 70-1201/82-13 on 820830-0901 No honcompliance noted Major areas inspected health physics procedures, external & internal radiation controls; instrument rallbr, contanguation surveys leak testing & reduction work permits KAHLE, J B, BARH, k P. Division of Engineering & Technical Programs 82/09/10 bpp 15567-222
- B210150215 Forwards IC Insp Rept 70-1201/82-14 on B20901-02 No noncompliance noted G1850N A F Division of Engineering & Technical Programs | 62/09/17 ALTOLR A Babtock & Wilcol Co | 2pp | 15721 316
- -8210150217 IE Insp Rept /0·1201/82 14 on 820901-02 No noncompliance noted Major areas inspected review of lab GC program & radiochemistry procedures & records EVANS.C D. MONTGOMER', D.M. Division of Emergency Preparedness & Operational Support 82/09/15 7pp 15721 218
- B210210216 Forwards IE Safeguards Insp Rept 70-1201/82-1/ on 820929-30 No noncompliance noted G1380N A F Division of Engineering & Technical Programs 82/10/15 ALTO.P A Babcock & Wilcox Co 2pp 15765-301
- --8210210223 IE Safeguards Insp Rept 70 1201/82-1/ on 820929-90 No noncompliance noted Major areas inspected general requirements for physical protection of low enriched SW Details withheld (ref (OCFR73 21) GODDE R W MCGUIRL D R Division of Engineering & Technical Programs 84/10/15 ip 15765 303

### DOCKET 70-1257 EXXON NUCLEAR CO . INC . RICHLAND, WA

- 6210220025 Advises of issuance of Amend 7 to Liconse BNM-1227, authorizing sever discharge of process liquids & changing environ monitoring requirements PAGE:R G Uranium Fuel Licensing Granch 82/09/27 MALODY, C W Eiron Nuclear Co., Inc. (subs. of Exxon Corp.) 2pp. 15786-301
- --8210220028 Safety evaluation supporting Amend 7 to License SNM-1217 deleting License Conditions 15-17 & revising Section 3 reliquid effluent & monitoring controls SIBINGER, O H . CROW, W T Uranium Fuel Licensing Branch 82/09/29 lp 15786-301
- 8210260389 Forwards (E Sateguards Insp Rept 70-1257/82-10 on 820920-24 No honcompliance noted MORDERHAUGIL R Division of Radiological Safety & Safeguards Program 82/10/18 NILSON,R Exton Nuclear Co , Inc (subs of Eiron Corp ) 2pp 15803 322
- BBIOR60402 RE Safeguards Insp Rept 70-1257/82-10 on B20920-24 No nancompliance noted (fajor areas inspected followup actions for flosing out notice of deviation records k rept audits & independent insp Details withheld (ref 10CFR2 790) WIEDER, A V . NORDERHAUG. R. Division of Radiological Safety & Safeguards Program 82/10/18 ip 15803 326

1

### DOCKET 70-1510 NUCLEAR ASSURANCE CORP . ATLANTA, GA

- 8207110023 FOIA request for correspondence between Nuclear Assurance Corp & NRC re 1982 irradiated fuel shipments between Chaik River, Ontario & Savannah River, NC RESNIKOFF, M. Council on Economic Priorities 82/06/23 Division or Rules and Records ip 15849 109
- 8210050430 Responds to FDIA request for correspondence between Nuclear Assurance Corp & NRC re 1982 (readlated fuel shipments between Ontario & NC Forwards App A documents App B documents withheld (ref FDIA Exemption 3) FELTON, J M Division of Rules and Records 82/08/17 RESNIKOFF, M Council on Economic Priorities 3pp 15626 172
- --B204200405 Forwards decontrolled version of route for transport of spent fuel route requested in Bilil3 ltm Submittal meets IOCFR73 37 requirements for shipment & is approved SHERR.T S Material Transfer Safeguards Licensing Branch B2/04/02 DANESE.F L Nuclear Assurante Corp 14pp 15626 20/
- --B210050444 Requests revision to route from Alexandria Bay, NY to Savannah River, NC, approved by NRC on B20402 Route change nacessary in Byracuse, NY DANESE, Ft L Nuclear Assurance Corp B2/05/25 Division of Safeguards ip 15026-221
- --8210050451 Forwards "Spent Fue) Route Survey, Syracuse, NY Dypass," approving detour around const per 820555 request SHERR.T S Office of Nuclear Material Safety & Safeguards, Director 82/06/03 DANESC, F L Nuclear Assurance Corp bp 15426 222
- --8210050456 "Spent Fuel Route Survey, Syracuse, NY Bypass " SHERR, 7 S Office of Nuclear Material Safety & Safeguards, Director 82/06/30 2pp 15626 223
- 8210270423 Addi response to FOIA request for correspondence between Nuclear Assurance Corp & NRC re 1982 fuel shipments Forwards documents listed in App A App 8 documents partially withheld (ref FOIA Exemption 3) FELTON, J M Division of Rules and Records 82/09/23 RESNIKOFF, M Council on Economic Priorities 3pp 15849 110
- --8210270427 Confirms 820616 telcon re indefinite delay of six apent fuel shipments from AECL Chalk River facility to DOE Bavannah River facility DANEGE.FL Nuclear Assurance Corp 62/06/16 GODY, A Region 1, Office of Director 1p 15849 (1)
- --8210270429 Confirms 820816 teleon re route approval for reactor fuel shipments between AECL Chalk River facility & DOE Savannah River facility Eight shipments planned w/possible increase to 11

  DANESE.F L Nuclear Assurance Corp 82/08/17 HILLMAN.C
  Division of Safeguards 2pp 15849 114
- --8204200408 Forwards decontrolled version of route for transport of spent fuel route requested in Billi3 ltr Submittal meets 10CFR73 37 requirements for shipment & is approved Info partially withheld (ref FDIA Exemption 3) SHERR.15 Material Transfer Safeguards Licensing Branch 82/04/13 DANESE.F.L. Nuclear Assurance Corp. 24pp. 19849 116
- --B204220144 Advises that Bill13 request for spont fuel route meets
  10CFR73 37 requirements & is approved Data re initial
  arrangements w/law enforcement agencies & approved route
  encl Safeguards info withheld (ref FOIA Exemption 3)
  BHERR: 18 Material Transfer Safeguards Licensing Branch
  82/04/14 DANESE: F.L. Nuclear Assurance Corp. 32pp. 15849 130
- --8210270437 Notifies of plans for series of spent fuel shipments from AECL Chalk River facility to DOE Bavannah River facility Schedule and DANESE, F. L. Nuclear Assurance Corp. 82/06/03. GDDY, A. Region 1, Office of Director. 2pp. 15847-171
- --8210270438 Forwards schedule for add1 spent fuel shipments
  DANESE.FL Auclear Assurance Corp 82/08/13 900Y,A Region 1.
  Office of Director 2pp 15849.173

# DOCKET 70-1621 DUQUESNE LIGHT CO , PITTSBURGH, PA

8210060020 Forwards Endorsements 59 % 51 to NELIA Policy NF-226 & MAELU Policy MF-87, respectively BARNETT, J E Conover & Associates, Inc. Insurance. 82/09/30 DINITZ, I Antitrust & Economic analysis Branch (Utility Finance) 3pp 15615 010

### DOCKET 76-1739 TRI-STATE MOTOR TRANSIT CO . JOPLIN, MO

- 8210150605 Forwards route overview re planned theck call frequency for shipment of strategic quantity of SNM W/o encl RUTEHKROBER: E. Tri-State Motor Transit Co. (subs. of Georgia Pacific Corp.) 82/09/01 HILLMAN.C. NRC - No Detailed Affiliation Given Ip. 15716-334
- ~-B210150609 Submits review of 820901 application for mat1s safeguard amend HILLMAN, C.R. Division of Safeguards 82/09/16 MILLER, W.D. License Fee Management Branch 1p 15716-335
- DOCKET 70-2116 LAWRENCE GENERAL HOSP , LAWRENCE, MA
- 8210210437 Ack receipt of 820924 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-01878/82-01 & 70-2136/82-01 Division of Engineering & Technical Programs 89/10/14 NOYES.A W Lawrence General Hosp Lawrence MA 1p 15762 396
- --8210210448 Responds to NRC 820826 ltr re violations noted in IE Insp Repts 30-01878/82-01 & 70-2116/82-01 Corrective actions personnel will be monitored following I-131 therapy & elution & preparation area will be surveyed on daily basis NDYES:A W Lawrence General Hosp Lawrence:MA 82/09/24 Region 1: Office of Director 2pp 15762 257
- DOCKET 70-2650 ST JOHN'S MERCY MEDICAL CTR , ST LOUIS, MO
- 8210250190 Discusses IE insp of Licenses 24 00794-03 & SNM-1792 on 820927 No soncompliance noted Major areas inspected radiation safety, procedures & representative records, observations, independent measurements & interviews HIEDEMAN, D G Division of Project & Resident Programs 82/10/13 FARRELL. J T St Johns Mercy Medical Hosp St Louis, MO Ip
- DOCKET 70-2748 SCIOTO MEMORIAL HOSP , PORTSMOUTH, OH
- 6907070319 Ack receipt of 920621 ltr informing NRC of steps taken to correct violations noted in IE insp of Licenses 34-15938-01, 34-15939-02 & BNM-1768
  SRENIAMEKI.D J Division of Engineering & Technical Programs 92/06/30 CASS,K Scioto Memorial Hosp Portsmouth, OH ip 13734-170
- --8207070324 Responds to NRC 820512 ltr re violations noted in IE insp of Licenses 34-15938-01, 34-15938-02 & SNN-1788 Corrective actions implemented procedure to survey doses & sites of injections outside of hosp EMMERT, R M Scioto Memorial Hosp Portsmouth, DH 82/06/21 SRENIAWSKI, D J Division of Engineering & Technical Programs 2pp. 13734-171

# DOCKET 70-2789 MISSOURT, UNIV OF, COLUMBIA, MO

- 8210080293 Discusses IE insp of Licenses 24-00513-35 & SNM-1799 on 820915 & forwards notice of violation MIEDEMAN.D Q Region 3, Office of Director 82/10/05 TOLAN.J Missouri, Univ of, Columbia 2pp 15638 311
- --8210080297 Notice of violation from insp on 820915 Noncompliance noted madiation monitor not functional in battery mode WIEDEMAND O Region 3. Office of Director 82/09/29 ip 15638-313
- DOCKET 70-2792 LOWER BUCKS HOSP . BRISTOL, PA
- 8210080306 IE Insp Findings & Licenses Ack dtd 820916 of Licenses SNM-1800 & 37-06572-02 Insp findings no noncompliance noted \* Region 1. Office of Director 82/09/16 ip 15638 123
- DOCKET 70-2873 PUERTO RICO, UNIV OF, MAYAGUEZ, PR
- 8210010231 IR Imap Findings & Licensee Ack dtd 820701 of License BNM-1836 Imap findings no violations observed BROWN, R A Region 2, Office of Director 82/09/01 1p. 1556B 247

- DOCKET 70-2942 HARPER-GRACE HOSPS , DETROIT, MI
- B210050204 Ack receipt of B20922 litr informing NRC of steps taken to correct violations noted in IE insp of Licenses 21-04127-02. 21-04127-08 & SMM-1881 SREMIAHMENT D J Region 3. Office of Director B2/10/01 (ARM) 1.5 Happer-Grace Hosps DetroitMI ip 15609 048
- --8210050213 Responds to NRC 820908 ltr re violations noted in 11 irap of Licenses 21-04127-06 & 21-04127-08 Corrective actions timer acturacy determination made & included in spot checks CARALIG.G P. Harper-Grace Hosps Detroit, MI 82/09/22 SRENIAWSKI, D. J. Region 3. Office of Director Ip 156/9-014
- DOCKET 70-2944 DUKE POWER CO , CHARLOTTE, NO
- 9210150617 Application to renew License SNM-1885, requesting license extension to 831231
  TUCKER: H B Duke Power Co 82/09/07 DAVIS. J G Office of Nacle
  Material Sefety & Safeguards: Director CUNNINGHAM. R L PIV281ER &
  Fuel Cycle & Material Safety | Ip 15716 099
- 6210290383 Issues Amend I to License SNM-1805, changing liters expiration date to 831231 or upon conversion of CPPR-84 to DL.
  PAGE,R G. Uranium Recovery Licensing Branch 62/10/1, This H. Duke Power Co. 2pp. 15865-264
- --8210290392 Reviews 620907 application for Amend 1 to liceuse 'fad I requesting expiration date be extended to 831211 Citebsion should be granted KETZLACION . CROWN T Uranium Retovery Liceusing Branch 82/10/12 Uranium Recovery Liceusing Branch 1p 15865 .'Ar
- DOCKET 70-2946 LOUISIANA POWER & LIGHT CO . NEW ORLLAND IA
- 8210260003 Forwards Revision I to physical protection plan for type SNM-1886 Revision consists of changes made to plan based on agreements reached during 820624 telton Revision withheld (ref. 10CFR2 790)
  WULLER.O E Illinois Power Co. 82/06/28 BURNLIT.R.I. livision Safeguards ip 15814-251
- B207150432 Forwards updated pages to SNM application is personnel changes
  MAURINIL V Louisiana Power & Light Co 82/07/2 (filter of Nuclear Material Safety & Safeguards, Director in 14090-1/2
- --8209150436 Updated pages to SNM license application \* Louisiana Power & Light Co 82/07/23 10pp 14890 149
- --B209150438 Application to extend 6NM license until Waterford in received MAURINIC V Louisians Power & Light Co 62/01/04 (Millice Nuclear Material Bafety & Safeguards, Director 2pp 141/44 1
- DOCKET 70-2949 ARIZONA PUBLIC BERVICE CO , PHOENIX, AZ
- 8210260563 Forwards Palo Verde Nuclear Generating Stateon physics security plan Amend 2 in support of 810817 application for SNM licents Amend withheld (ref 10CFR2 790) ANDONINIO C Arizona Public Service Co 82/08/111 (1884 Nuclear Material Safety & Safeguards, Director 1p 19814 148)
- DOCKET 70-2955 EDLOW INTERNATIONAL CO . WASHINGTON, DL
- B210210537 Forwards responses to B20520 request for addition of application for SNM license SRAMA A Ediow International Co B2/06/21 SERINI. 8 (10.4). Fuel Licensing Branch Bpp 15782 220
- --8210210543 Application for license to store U hexafluoride en SK max EDUN,J Ediow International Co 82/03/11 PAGERQ the Fuel Licensing Branch 34ph 15782 228
- DOCKET 70-2957 FLORIDA POWER & LIGHT CO . MIAMI, FL
- B2102B0415 Forwards License BNM~1902,Amend 7 to Indemnity Agra; B-74 & safety evaluation PAGE,R 0. Uranium Retovery Licensing Branch - 82/10/14 (兵庫 Florida Power & Light Co - 2pp - 15859 339

#### DUCKETED CLEARLY

- --8210283417 License SNM-1902 for FL Power & Light Co.authorizing receipt.passession.insp & storage of U-235.Pu-238.239.240 & 241.U-235.Cs-137.Pu-238.239 & Am-241 PAGE.R G Uranium Recovery Licensing Branch 82/10/14 3pp 15859 341
- --8210283421 Safety evaluation re review of 820319 license application t suppls for maths license Application acceptable SERINLS L , CROW. W T Uranium Recovery Licensing Branch 82/10/14 13pp 19859 344
- DOCKET 70-2968 CLEVELAND ELECTRIC ILLUMINATING CO . CLEVELAND, DIS
- 6310260009 Forwards application for SM1 license for storage only of unirradiated reactor fuel 7 associated radioactive matl DAVIDSON DR Cleveland Electric Illuminating Co 82/08/30 BAVIS.J G Office of Nuclear Material Safety & Safeguards, Director ip 15814 252
- ~-8210260011 Application for SMM license for storage only of unirradiated reactor fuel b associated radioactive mat[ DAVIDSON D R Cleveland Electric Illuminating Co 82/08/30 52pp 15814 253

# PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0030 GENERAL ATOMIC CO

8210270187 Supple 820623 request for NRC comment re acquisition by GA Technologies. Inc of licenses held by GA Co GA Tuchnologies. Inc adopts GA GA program lopical Rept GA-Al3010A, Amend & AGMEN.M M GA Technologies. Inc Venneral Atomic Co 82/08/30 Urfice of Nuclear Reactor Regulation, Director 1p 15835-27')

DOCKET 71-0481 MONROE X-RAY CO . INC

- 0210010005 Forwards OA program for pending license, in accordance U/requirements of 1001871
  HEAD, T. G. Monroe X Ray Co., Inc. 82/07/09 MACDONALD, C. E. Transportation Brench. 1p. 15577-221
- --0210010024 GA program for pending litense in accordance w/requirements of 10CFR71
  4 Monroe x-Ray Co . Inc 82/07/09 3pp 15577 222
- BOCKET 71-5908 MODEL DOT-6M TYPE B. BABCOCK & WILCOX CO
- 0210120331 Forwards Revision 9 to Certificate of Compliance 5908 for Model DDT-6M Type 3 MACDDNALD,C E. Transportation Branch 82/09/13 AUSTIN.M. Babluck % Wilcox Co. 3pp. 19689-279
- --B210120384 Certificate of Compliance 5908.Revision 9, for Model DDT-6M Type 8 HACDONALD.C E Transportation Branch 82/09/13 App 15489 P84
- DOCKET 71-5926 MODEL GE-100, GENERAL ELECTRIC CO
- B210150348 Submits revised certification drawings for GE Model 100.per 020716 its Notes consistent w/Model 700 drawings Cask weights listed on drawings should be used to correct weight on Certificate of Compliance 5926 CURNINGHAM.0 E General Electric Co 02/09/07 MACDQNALD.C C Transportation Branch 10pp 15715 343
- DOCKET 71-5939 MODEL GE-1500, GENERAL ELECTRIC CO
- 8210270057 Forwards revised certification drawings for GE Model 1500 per 820722 itr Changes listed Three aperture cards available in PDR CUNNINGHAM G General Electric Co 82/09/08 MACDONALD C E Transportation Branch 8pp 15836 113
- DOCKET 71-6115 MODEL R1010-0032, ENERGY, DEPT OF
- 8210280343 Forwards Revision 1 to Certificate of Compliance 6115 for Model R1010-0032 MACDONALD.C E Transportation Branch 82/09/21 BAVER,R H Energy, Dept of ip 15839 193

- --810280245 Certificate of Compliance 6115.Revision 1.for Model R1D10-0032 MACDDNALD.C E Transportation Branch 82/09/21 3pp 15859 194
- DOCKET 71-6346 MODEL FSV-L. GENERAL ATOMIC CO
- 8210250122 Requests registration as user of Model FSV-1 MATHIB:C J Boston Edison Co B2/09/22 MACDONALD:C E Transportation Branch 1p 15798 361
- 8210280322 Forwards Revision 6 to Certificate of Compliance 6346 for Model FSV-1 MACDONALD.C E Transportation Branch 82/10/01 MDWRY,W R GA Technologies, Inc./General Atomic Co 1p 15859 046
- --8210280326 Certificate of Compliance 6346, Revision 6, for Model FSV-1 MACDONALD, C.E. Transportation Branch 82/10/01 4pp 15859 04/
- 82(0150653 Notification of registration as user of Model FSV-1 in response to 820922 request MACDGMALD,C E Transportation Branch 82/10/13 MATHIS,C J Boston Edison Co. 1p 15715-308
- DOCKET 71-6947 MODEL FSV-3. GENERAL ATOMIC CO
- B210120146 Forwards Revision 4 to Certificate of Compliance 6347 for Model FSV-3 MACDONALD,C E Transportation Branch B2/10/01 MOWRY,W R CA Technologies, Inc /General Atomic Co 2pp 15492 171
- --8210120150 Certificate of Compliance 4347 Revision 4 for Model FSV-3 MACDONALD C E Transportation Branch 82/10/01 4pp 15492 173
- DOCKET 71-6574 MODEL HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP
- 8210270439 Requests registration as user of Models GE-1600, CNS-1600, CNS-6-80-2, CNS-8-1600, CNS-14-175H, CNS-21-300, HN-600, HN-200 & HN-100, Series S. 1, 2 & 3

  MAURIN, L. V. Louisiana Power & Light Co. 82/07/07 DAVIS, J. 0

  Office of Nuclear Material Safety & Safeguards, Director ip. 19863–187
- DOCKET 71-6601 MODEL CNS 8-120, CHEM-NUCLEAR BYSTEMS, INC
- 821G28038B Responds to 82072/ ltr re cause of defects in cask lid buits of CN8-B-120 shipping cask Preliminary investigations determined defects caused during bolt mfg PDPPE.L. K Chem-Nuclear Systems. Inc. 82/08/25 MACDONALD, C F Transportation Dranch 3pp 15859 259
- 8210290938 Requests registration as user of Models CE-1600, CNS-1600, CNS-6-80-2, CNS-8-120, CNS-14-195H, CNS-21-300, HN-600, HN-200 & HN-100, Series S.1,2 & 3 MAURIN, L V Louisiana Power & Light Co 82/09/07 DAVIS, J Q Dfrice of Nuclear Material Safety & Safeguards, Director ip 15863 187
- DOCKET 71-6639 MODEL MH-1A, ARMY, DEPT OF
- 8210270074 Forwards "SAR for Packaging of TRIGA & MTR Irradiated Fuel Assemblies in MK-iA Spent Fuel Shipping Cask" PRICHARDIR P Energy, Dept of 92/07/07 MACDONALD.C E Transportation Branch 4pp 15848 107
- --8210270079 Certificate of Compliance 4639. For Model MH-1A ROEDER, J. R. Energy, Dept. of 82/06/18 2pp 19848 113
- --8210270085 "SAR for Packing of TRIOA & MTR Irradiated Fuel Assemblies in MH-1A Spent Fuel Shipping Cask " Fourteen oversize drawings encl Aperture cards available in PDR \* Ridihalgh, Eggers & Associates 82/05/31 354pp 15848 115
- DOCKET 71-6677 MODEL LP-12, ENERGY, DEPT OF
- 8210280334 Forwards Revision 3 to Certificate of Compliance &677 for Model LP-12 MACDONALD, C E Transportation Branch, 82/09/17 STETSON, N Energy, Dept of, 1p 15859 129

- --8210280337 Certificate of Compliance 6677, Revision 3, for Model LP-12 MACDOUALD, C. E. Transportation Branch 82/09/17 Spp. 15859-130
- DOCKET 71-6678 MODEL LP-50, ENERGY, DEPT OF
- 8210280338 Forwards Revision 3 to Certificate of Compliance 4678 for Model LP-50 MACDONALD.C E Transportation Branch 82/09/17 STETSON.N Energy, Dept of 1p 15859 133
- --8210280342 Certificate of Compliance 6678 Revision 3 for Model LP-50 MACDQNALD, C E Transportation Branch 82/09/17 3pp 15859 134
- DOCKET 71-6698 MODEL NFS-4, NUCLEAR FUEL SERVICES, INC
- 8210290155 Forwards pages inadvertently omitted from 820720 responses to NRC ltr W/o encl
  JOHNSON, C R Nuclear Assurance Corp 82/09/02 MACDONALD, C E
  Transportation Branch 1p 15876-223
- DOCKET 71-6703 HODEL RG-1. GENERAL ATOMIC CO
- 8210120180 Forwards Revision 3 to Certificate of Compliance 670\$ for Model RG-1
  MACDIMALD,C E Transportation Branch 82/10/01 MOWRY,W E GA Technologies. Inc /General Atomic Co 2pp 19692 211
- --8210120192 Certificate of Compliance 6703 Revision 3 for Model AU-1 MACDONALD C E Transportation Branch 82/10/01 3pp 15692 21.1
- DOCKET 71-6745 MODEL FSV-2, GENERAL ATOMIC CO
- 8210280329 Forwards Revision 3 to Certificate of Compliance 6745 for Model FSV-2 MACDONALD, C.E. Transportation Branch 82/10/0[ MOWRY, W.R. GA Technologies, Inc. /General Atomic Co. ip. 15859 125
- --0210280333 Certificate of Compliance 6745 Revision 3 for Model FSV-2 HACDUNALD, C & Transportation Branch 82/10/01 3pp 15889 126
- DOCKET 71-9001 MODEL IF-300, GENERAL ELECTRIC CO
- B210120198 Forwards Revision 14 to Certificate of Compliance 9001 for Model IF-300 MRCDDNALD.C E Transportation Branch 82/09/30 DAWSON,D M General Electric Co 2pp 15692 187
- --8210120166 Certificate of Compliance 9001.Revision 14.for Hodel IF-300 MACDDNALB.C E Transportation Branch 82/09/30 Spp 15692 189
- DOCKET 71-9010 MODEL, NLI-1/2, NL INDUSTRIES, INC
- 8210280448 Requests revision to maint mahual covering NLI-1/2 spent fuel shipping casks to further define maint schedule JOHNSON C R Nuclear Assurance Corp 82/09/09 MACDONALD C E tation Branch is 15859 121
  - wards Revision 8 to Certificate of Compliance 9010 for ation Branch 82/09/24 JOHNSON: C R
    - · 9010.Revision 8. for Model NL1-1/2 nch R2/09/24 App 15490 184
- 82:0150428 Advises that licensing action for amend of Certificate of Compliance 90:10 terminated on 820826 No addl fees required MILLER, W O License Fee Management Branch 82/10/07. JQHNSON, C R Nuclear Assurance Corp Ip 15715 388
- DUCKET 71-9034 HODEL TRIGA-1, DENERAL ATOMIC CO
- 8210120169 Forwards Revision 4 to Certificate of Compliance 9034 for Model TRIOA-1 MACDONALD.C E Transportation Branch 92/10/01 MOHRY, H E GA Technologies, Inc /General Atomic Co 2pp 15692 197

- --E210120174 Certificate of Compliance 9034, Revision 4, for Hodel TRIC4-; MACDONALD, C E Transportation Branch 82/10/01 3pp 15692 19-
- DOCKET 71-9037 MODEL TRIGA-2, GENERAL ATOMIC CO
- 8210120339 Forwards Revision 4 to Certificate of Compliance 903) for Model TRIGA-2 MACDONALD.C E Transportation Branch 82/10/01 MOWRY.W R LA Technologies. Inc /General Atomic Co 2pp 15690 177
- ~-8210120340 Certificate of Compliance 9037 Revision 4.for Model TRICA MACDONALD.C E Transportation Branch 82/10/01 3pp 156/00 17y
- DOCKET 71-9044 MODEL GE-1600, GENERAL ELECTRIC CO
- 821029043B Requests registration as user of Models GE-1600, CNG-1600. CNG-6-80-2. CNS-6-120. CNS-6-
- 8210280382 Requests registration as user of Model GE-1600 BORRT,F J Public Service Co of Coloradn 82/09/08 MACDUNALU,C E Transportation Branch 2pp 15859 257
- B210150691 Notification of registration as user of Mode) QC-1600 in response to B2090B request MACDONALD,C E Transportation Branch B2/10/13 BDRST,f J Put Service (o of Colorado Ip 15715 319
- DOCKET 71-9057 MODEL. FPD-100, GENERAL ATOMIC CO
- 9210280311 Forwards Revision 3 to Certificate of Compliance 905/ Fe. Model FPD-100 MACDONALD,C E. Transportation Branch 82/10/01 MOURLY,R R. GA. Technologies, Inc./General Atomic Co. lp. 15859-042
- --8210280316 Certificate of Compliance 9057, Revision 3, for Hadel Fir MACDONALD, C E Transportation Branch 82/10/01 3ep 15174
- BOCKET 71-9079 MODEL HN-100, SERIES 2 & 2A, HITTMAN NUCLEAR
- 8210260023 Requests registration as user of Model (Mr100 Berigs ,' a SCOTT, D.J. Communwealth Edison Co. 82/08/03 MACDONALD.(' I Transportation Branch | 16 | 15808-360
- 821029043B Requests registration as user of Models OE-1600.CNP (cd; CNS-6-80-2:CNS-8-120).CNS-14-193H.CNS-21-300.HN-600.HR-200.L NN-100.Series S. 1, 2 & 3 MANRIN.L V Louisiana Power & Light Co 82/09/07 DAVIB. J G Office of Nuclear Material Safety & Safeguards.Director to 15863 187
- DOCKET 71-9080 MODEL 9080, HITTMAN NUCLEAR & DEVELOPMENT COMP
- 821029043B Requests registration as user of Models QE-1600.CM3-14. CMS-6-80-2.CMS-8-120.CMS-14-173H.CMS-21-300.HM-600.HM-200 & HN-100.Series S. 1.2 & 3 MAURIN.L V Louisiana Power & Light Co 82/09/07 DAVIS., J Q Office of Nuclear Material Safety & Safeguards.Director ip 15863 87
- DOCKET 71-9081 MODEL CN8-1500, CHEM-NUCLEAR SYSTEMS, INC
- 8210290438 Requests registration as user of Models GE-1600, CNS-14 CNS-6-80-2, CNS-6-120, CNS-14-175H, CNS-21-300, HN-600, HN-200 & HN-100, Beries S, 1, 2 & 3 MAURIN: L V Louisiana Power & Light Co 82/09/07 DAVIS. J Q Office of Nuclear Material Safety & Safeguards, Director 1p 15863 187
- DOCKET 71-9086 MODEL, HN-100, SERIES 1, HITTMAN NUCLEAR & DAV C
- B21027043B Requests registration as user of Models GE-1600, CNB-1 CNB-6-80-2; CNB-8-120, CNB-14-175H, CNB-21-300, HN-600, HN-200 & HN-100, Beries S.1,2 & 3 HAURIN. L.V. Louisiane Power & Light Co B2/09/07 DAVIS, Jr. Office of Nuclear Material Bafety & Safeguards, Director Lp. 18863 187

- GOCKET /1-9089 MODEL HN-1008, HITTHAN NUCLEAR & DEVELOP CORP
- 8/1029043B Requests registration as user of Models GE-1600 CNS-160b, CNS-6-80-2, CNS-8-120, CNS-14-175H, CNS-21-300, HN-600, HN-200 & HI-100, Serves S. 1, 2 3 3 MAWRIN, L. V. Louistana Power / Light Co. 82/09/07 DAVIS, J. G. Biffice of Nuclear Material Bafety & Safeguards, Director. Ip 19863 187
- COLMET /1-9091 HODEL JOA / BOB, GULF NUCLEAR CO
- 820679438 Requests registration as user of Models GF-1600, CNS-1600, CNS-160
- DOCHEF 71 9094 MODEL CN3 11 195-H, CHEM-NUKLEAR SYSTEMS. INC
- 8210/38637 Proquests registration as user of Model CHS 14-195-H HILLER.R 1 Sacramento Municipal Utility District 80/12/24 HACDEMALD.C E. Transportation Branch tp 15808 352
- MICHET 71-9096 MODEL (NS 21 300, CHEH NUCLEAR SYSTEMS, INC
- 8710290476 Requests registration as user of Models GL-1600, CNS-1600, FRE-6-60-2, CNS-6-120, CNS-14-195H, CNS-21-300, HN-600, HN-200-2, RAP-150, Series S. U. 2-2-3 Hower & Light Le B2/09/07 DAVIS, J G MARRIN U Louisiana Hower & Light Le B2/09/07 DAVIS, J G Price of Neclear Material Safety 2 Sateguards, Director 1p 1506-1-107
- BOLFET AT 96 HE MIDEL OLD BONG -2 & ZA, UNION CARBIDE CORP
- --Batto-BOSSY Curtificate of Compilance YOYB, Revision S. for Models OCC-ACHC-2 & UCC-ACHC-2A MACDDHALD, C.C. Transportation Branch B2/09/16 3pp 15899 201
- DOCKET 71 9118 MODEL CAPA 80-2. CHEM NUCLEAR SYSTEMS. INC.
- 6210270438 Requests requestration as used of Models OF-1600, CNS-1600, CNS-1600, CNS-6 80-2 CNS-8-1200-CNS-14 199H, CNS-21-300, HN-600, HN-200 & HY-100, Gentes State 7 1 HAURIN, L.V. Louistana Power & Light Co. 82/09/07 DAVIS, J. G. Office of Nuclear Material Safety & Gafeguards, Director. 1p. 1586-3 182/

- DOCKET 71-9150 MODEL PAT-2, ENERGY, DEPT DF
- --8210070410 "Operational Conditions for Pu Air Transportable Packaues PAT-1 & PAT-2 " # Edlow International Co 82/04/22 33pp 15637 233
- --B2100704|3 "Analysis of Crush Environ for Light Weight Fransportable Accident Resistant Containers" MCCLURE, J. D. Sandia Laboratories SANDB0-0763 81/12/31 29µp 15637 272
- DOCKET 71-9151 MODEL HN-100, SERIES 3, HITTMAN NUCLEAR & DEV (GRP
- 8210290438 Requests registration as user of Models GE-1600 CN5-1800. CNS-6-80-2. CNS-8-120. (NS-14-1930. CNS-21-300. HN-600. HN-200 % HN-100. Series S.). 2 & J HAU-100. Series S.). 2 & J HAU-100. HN-600. HN-200 % HAU-100. The Constant Power & Light Co 82/09/07 DAVIS. J G Office of Nuclear Material Safety & Safeguards. Director Ip 19863 187
- 8210150687 Notification of registration as user of Madel HN-100 Series 3 (n response to 820714 request MACDONALD.C E Transportation Branch 82/10/13 MARSHALL.J R Artansas Power & Light Co ip 15715 318
- DOCKET 71-9167 MODEL TYPE B, AMERSHAM CORP
- 8210080225 Application for certificate of compliance to use Type B keg design containers for storage & shipping of up to 25 Ci Amersham mfg Am-241 & beryllium approved special form sources BAGBY. A Amersham Carp 82/08/25 MACDONALD. C NRC No Detailed Affiliation Given 2pp 15663 141
- --8210080232 Forwards payment to replace incorrect funds accidentally included in 820825 application for certificate of compliance to use Type 8 keg design containers for storage & shipping of up to 25 Ci Amerisham mfg Am-241 & beryllium BAOBYL A Amerisham Corp 82/08/26 WEISS.D License fee Management Branch 2pp 15663 142
- --82100B0237 "SAR Keg Design Containers Type B Package " • Amersham Corp 82/08/25 75pp 15463 145
- DOCKET 71-9964 MODEL LP-12-1, ENERGY, DEPT OF
- 8210120349 Forwards Revision 2 to Certificate of Compliance 9964 for Model LP-12-1 MACDONALD.C E Transportation Branch 82/09/24 STETSON, N Energy, Dept of 1p 15690 172
- --8210120352 Certificate of Compliance 9964. Revision 2. for Model LP-12-1 MACDONALD, C & Transportation Branch 82/09/24 4pp 15690 173

# NONDOCKETED ITEMS

#### COMMISSION MEETING RECORDS LOCKE

- 8210050435 Unofficial transcript of 820910 public meeting w/ACRS in Weshington, DC Pp 1-52

  4 Commissioners 82/09/10 55pp 15622 164
- 8210060070 Transcript of B20918 affirmation/discussion session in Washington DC Pp 1-3 \* Commissioners B2/09/18 7pp 13636 237
- 9210080327 Staff requirements memo informing that Commission was briefed on ORNL rept. "Potential Precursors to Savere Core Demage" on 920721 Qamage" on 820721 CHILK.S J Office of the Secretary of the Commission M820721A 82/07/22 DIRCKS, W J Office of the Executive Director for Operations 1p 15663 292
- 8210120581 Transcript of 820918 public meeting in Washington.DC re FEMA briefing on offsite appraisals program Pp 1~63 Viewgraphs encl. Commissioners 82/09/18 87pp 15489 232
- 8210120599 Staff requirements memo re FEMA 820917 briefing on offsite appraisals program for commercial nuclear power plants FEMA should provide NRC w/info re availability of emergency plans snotes provide NRC of the Recretary of the Commission, M8209178 CHILK.S J Office of the Becretary of the Commission, M8209178 82/09/24 BICKWIT, L Office of the Executive Director for Operations DIRKS,W J Office of the General Countei in
- 0210220507 Unofficial transcript of 821007 briefing by Regulatory Reform Tesk Force re legislative proposals in Washington, DC
- Commissioners 82/10/07 75pp 15786 129
- 8210280402 Addi response to FOIA request for SECY-82-232 & SECY-82-202 Documents listed in App A available in PDR FELTON.J K Division of Rules and Records 82/09/30 BUCKLES.R Affiliation Unknown 2pp 15859 10i
- --8210190198 Staff requirements memo re B20701 affirmation session concerning SECY 82-202 on amend to IOCFR140 9, "Financial Protection Requirements & Indemnity Agreements " Ubjections to publication of apps as reg guides due by B20719 CHILK, B J Office of the Secretary of the Commission MB2070: B2/070706 DRCKB, W J Office of the Executive Director for Operations 2pp 15837 106 MB20701
- 8210270393 Transcript of 820929 public meeting on SECY-82-352 rs GA in Washington, DC Pp 1-85 Marked-up SECY-82-352 encl PALLADINO, N , OILINGKY, V , AHEARNE, J , Commissioners 82/09/29 146pp 15865 268
- 8210290400 Unofficial transcript of B20930 public affirmation/ discussion & vote in Washington: DC Pp 1-3 4 Commissioners 82/09/30 App 15866 329

#### ACRS. ADVISORY COMMITTEE ON REACTOR BAFEGUARDS

- 8207180066 Forwards edited version of draft on pressurized thermal shock w/substantive changes proposed KOUTS,H Brockhaven National Laboratory KOUTS.H Brockhaven National Laboratory KOUTS.H ACRS - Advisory Committee on Reactor Safeguards 82/08/10 IONE.E ACRS - Advisory Committee on Reactor Safeguards 82pp 15852-012. ACRS - Advisoru
- 8207180080 Comments on util group position per 820630 request ATMS issue remains unregolved because of difference between NRC estimate of ATMS risk & risk preferred by industry DAVIS.PR ACRS Advisory Committee on Reactor Safeguards. 82/08/24. ROEHNERT,P ACRS Advisory Committee on Reactor Safeguards. 82/08/24. ROEHNERT,P ACRS Advisory Committee on Reactor Safeguards. 3pp. 13832 043.

- 8208270011 Comments on ACRS Subcommittee on Human Factors 82090/ meeting Planned research program lacks in basic generic research SALVENDY.O ACRS - Advisory Committee on Reactor Safeguards SALVENDY.O Purdue Univ 82/09/09 FISCHER.D ACRS - Advisory Committee on Reactor Safeguards 4pp 13852 034
- 8208290012 Comments on ACRS Bubcommittee on Human Factors Safety AUMAYOUR Comments on AUMS Budgemmittee on Human Factors Safety integrated program plan Approx levels of effort to areas & at major units within areas need to be clearly shown BUCK.J R Iowa, Univ of BUCK.J R ACRS ~ Advisory Committee on Reactor Safeguards 82/09/13 WARD.D ACRS - Advisory Committee on Reactor Safeguards 3pp 15852 009
- 8208290017 Summarizes 269th ACRS meeting on 820909-11 in Washington. DC OBEYOOT / Summarises 2040 ACRS meeting on BEOSUS-11 in washing programmer on BEOSUS-11 in washing for transport-testing requirements for diesel generators & integrated human factors program plan
  SHEHMON, P. ACRE. - Advisory Committee on Reactor Safeguards
  SL-0278 82/09/21 PALLADINO, N. J. Commissioners Spp. 1 15449 236
- 8208290019 Forwards comments on util group response to NRC proposal for raducing ATHS sequences Meeting planned for 821001 MUELLER.C J Argonne National Laboratory MUELLER,C J ACRS ~ Advisory Committee on Reactor Safeguards 82/07/14 BOEHMERT.P ACRS ~ Advisory Committee on Reactor Safeguards 8pp 15852 001
- 8208290026 Outlines two approaches for evaluating seismic margins available to accomplish safe shutdown following earthquake of greater severity & lower liklihood than SSE Assessment of margins in terms of risk singularity recommended ZUDANS, Z Franklin Institute/Franklin Research Center ZUD ZUDANS, Z ACRS - Advisory Committee on Reactor Safeguards 62/09/24 SAVID. ACRS - Advisory Committee on Reactor Safeguards 6pp 15851 386
- 8210010464 Transcript of ACRS Subcommittee on Reactor Operations 820929 meeting in Washington, DC Pp 1-268 Supporting documentation
  - ACRS Advisory Committee on Reactor Safeguards 82/09/29 370pp 15571 008
- B210040080 Transcript of ACRS Metal Components Working Group 620930 meeting in Hashington, DC Pp 1-268 Eupporting documentation ent 1 \* ACRS - Advisory Committee on Reactor Safeguards 82/09/30 344pp 15583 195
- 8210050435 Unofficial transcript of 820910 public meeting w/ACRS in Washington.DC Pp 1-52 → Commissioners 82/09/10 55pp 15622 164
- 8210120149 Transcript of 270th ACRS general meeting on 821007 in Washington DC Pp 1-267 Viewgraphs and \*\*
  \* ACRS Advisory Committee on Reactor Bafeguards 82/10/07 416pp 19656-083
- 8210130157 Yranscript of ACR8 270th general meeting on 821008 in Mashington DC Pp 268-399 Supplemental info encl # ACR8 Advisory Committee on Reactor Safeguards 82/10/08 194pp 13697-087
- 8210210324 Ack receipt of 820914 views on BECY-82-001A, "Proposed Commission Policy Statement on Severe Accidents & Related Views on Nuclear Regulation." DIRCKS H J Office of the Executive Director for Operations 82/09/27 SHEWMON, P ACRB - Advisory Committee on Reactor Safeguards App 15774-315.
- 8210260119 Transcript of ACRS Subcommittee on ATMS 821022 meeting in Washington, DC Pp 1-332 Supporting documentation encl \* ACRS - Advisory Committee on Reactor Safeguards. 82/10/22. 404pp. 15800:001

- 82:02702:0 Transcript of ACRS Subcommittee on Extreme External Phenomena 82:022 meeting in Santa Monico.CA Pp 352-703 ACRS ~ Advisory Committee on Reactor Sefeguards 82/10/22 350pp 15826 034 82/10/22
- 8210270217 Transcript of ACRS Subcommittee on Extreme External Phenomena 821021 meeting in Santa Monsca.CA Pp 1-351 + ACRS > Advisory Committee on Reactor Safeguards 82/10/21 354pp 15825 040
- 8210270371 Summary of ACRS Subcommittee on Reactor Radiological Effects 820720 meeting in Washington.DC re methods for reducing radiation exposure exposure instories at PMRs & status of RUREC-0761. "Radiation Protection Plans for Licenses."

  \* ACRS Advisory Committee on Reactor Safeguards 82/09/87 ACRS Advisory Committee on Reactor Safeguards 17pp 18835 006
- 6210270375 Summary of ACRS Subcommittee on Reactor Radiological Effects 2 Site Evaluation 820623 joint meeting in Washington, DC restatus of registen to 10CFR20. "Stds for Protection Against Radiation"

  \* ACRS Advisory Committee on Reactor Safeguards 82/08/23
  ACRS Advisory Committee on Reactor Safeguards 19pp 15835 237
- 8210270378 Summary of ACRS Subcommittee on Safety Research Program 820707 meeting in Hashington, DC re research program & budget for FYB4-85
- ACRS Advisory Committee on Reactor Safeguards ACRS - Advisory Committee on Reactor Safeguards 19pp 15835 256
- 8210270385 Summary of ACRS Subcommittees on Reactor Radiological Effects & Site Evaluation 820609 joint meeting in Washington, DC re proposed FY84-85 research programs & budget \* ACRS - Advisory Committee on Reactor Safeguards 82/08/09 ACRS - Advisory Committee on Reactor Safeguards 14pp 15833 343 budget
- 8210270404 Summary of ACRS Subcommittee on Waste Mgt 820608 meeting in Washington, DC to review "DDE Public Draft of Natl Plan in Magnington, DC to review "DUE rublic Draft of Nati Flan For Siting High Level Waste Repositories & Environ Assessment Review " 4 ACRS - Advisory Committee on Reactor Safeguards 82/08/09 ACRS - Advisory Committee on Reactor Safeguards 17pp 15833 251
- 8210270420 Summary of ACRS Subcommittee on Safety Research Program 820602 meeting in Washington DC re research program & budget tor FY84-85
  - for Fideria \* ACRB Advisory Committee on Reactor Bafeguards B2/07/23 ACRS Advisory Committee on Reactor Safeguards 20pp 15833 312
- 8210270424 Summary of ACRS Subcommittee on Human Factors 820706 meeting in Mashington,DC re FY84-85 research program & budget & comments on long range research plan a ACRS Advisory Committee on Reactor Safeguards 82/07/13 ACRS Advisory Committee on Reactor Safeguards 37pp 15834 263
- 82:0280044 Summary of ACRS Ad Hoc Ketal Components Subgroup 8205;1-12 meetings in Washington DC repressurised thermal shock problem
  - problem \* AGRS Advisory Committee on Reactor Safeguards | 02/07/27 AGRS Advisory Committee on Reactor Safeguards | 19pp | 15862 336
- B2102B0059 Transcript of ACRS Subcommittee on SEP 821026 meeting in Washington, DC Pp 1-292 Supporting documentation encl # ACRS Advisory Committee on Reactor Safeguards 82/10/26 433pp 15841 043
- 8210270011 Transcript of ACRS Subcommittee on SEP 821027 hearing in Hashington, DC Pg 293-509 Supporting documentation encl \* ACRS Advisory Committee on Reactor Safeguards 82/10/27 33500 15955 354

mic Safety Margins Research Program Review ter presentation provided good involved w/correlating sarthquake Assignments
HAXWELL, J. C ACRS - Advisory
/02/14 DMRENT, T D ACRS ands 7pp 15877 306

> | establishment of joint proposed mods Hodnations

> MARTINEZ.FP Spain ip

- --8206060015 Requests joint program to resolve approval of mode to Westinghouse Model D-3 steam generators & followup evaluation during operating conditions MARTINEZ, F.P. Spain 82/05/27 PALLADING.N I Co-MARTINEZ:F P Spain 82/05/27 PALLADING:N J Commissioners 2pp 15624 050
- 8206200091 Responds to 820629 inquiry re discussions between NRC & LOS on requirements for site characterization of patential high level waste repositories No negotiations to relax requirements have taken place PALLADINO, N J Commissioners 82/07/29 MATHESON. S M Utah. Stat of 4pp 19624 052
- --8206270016 Requests verification as to occurrence of informal negotiations w/DGE to relax waste repository requirements of MATHESON, S M Utah, State of 82/09/29 PALLADINO.N J Commissioners 2pp 15684 056
- 8206200097 Responds to 820602 itr proposing extension of current preliminary design approvals for nuclear power plant designs until reactivation under new quidelines Standardization of designs is vital component to viable program PALLADIND,N J Commissioners 82/07/29 WALSKE,C Atomic Industrial Forum 2pp 15512 302
- --8204060013 Requests that NRC develop & implement new guidelines Fe preliminary design approval extensions & take action to extend administrative approvals that have expired until activation of new guidelines
  WALSKE,C Atomic Industrial Forum 82/06/02 PALLADING,N J Commissioners 2pp 15512 303
- --8209270379 Discusses extension of applicability period for previous issued preliminary design approvals Resources already expended should be preserved & standardization program used effectively TMI-related safety issues must be addressed QIBBS.D C Atomic Industrial Forum 81/05/28 DRCKS,W J Office of the Executive Director for Operations 2pp 155
- 6206270053 Forwards Science Mgt Corp/DRNL interim rept. "Fresibilit Licensing Nuclear Util Managers & Officers " Licensing requirements should not be established for managers & santor officers W/o encl PALLADINO N J C Commissioners FIN 8-0764-1 82/10/04 O'NEILL, TP House of Rep . Speaker of the House 6pp 13074::
- --8210270003 Forwards summary of selected US govt agency licensing progrems & Science Mgt Corp/ORNL. "Feasibility of Licensing Nuclear Util Managers & Officers " Licensing requirements whould not be established for managers & senior officers PALLADING. N J Commissioners FIN 8-0764-1 82/10/04 BUSH Senate: President of the Senate
- --8210290006 "Feasibility of Licensing Nuclear Util Managers & Ofe PERSENSKY, J. J. Division of Human Factors Safety SELBY D . BARTINE D E 81/12/17
- 8206270089 Accepts invitation to serve as chairman of 1980 combin federal campaign, w/PO Norry as vice-chairman PALLADINO, N J Commissioners 82/09/16 LEWIB, D Transportation, Dept of ip 15722, 251
- 82:0150659 Requests opportunity for members of public to comment following full-scale joint exercises involving licenses, state & local agencies AHEARNE, JF Commissioners 82/09/14 GIUFFRIDA, L O Feder, Emergency Management Agency 2pp 15716 348 GIUFFRIDA, LO Feder.
- 8210270423 Public version of weekly info rept for uk ending 8205 REHM.T.A Office of the Executive Director for Operations 82/09/30 49pp, 15863 190
- CONTRACT NRC CONTRACTS AND MODIFICATIONS
- 82:0040001 Notification of contract execution "LA Offshore Radiological License Survey," awarded to LA Dept of Natural MCNULTY:A Purchasing Section FIN 8-8703 NRC-05-82-252. 82/07/23 BLAMA.J. YACKO.C Program Support Branch 1p. 15577-246
- --B210040002 Contract "LA Offshore Radiological License Buryage to LA Dept of Natural Resources.

  SHONDAUX,F.P. Louisiana, State of SMITH,P A Administration of Contracts Branch. IN B-6703 NRC-05-82-252 82/09/20

- 82]CO40003 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Phoenix,AZ
  - Public Library

    LITTLE, H Purchasing Section NRC-10-82-697 82/09/22

    FELTON, J N . EQUOER, J Division of Rules and Records i
- --8210040004 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Phoenix, AZ Public Library COLLEY, J A Phoenix: AZ SMITH.P A Administrative Contracts Branch NRC-10-82-697 82/09/22 7pp 15577 253
- 8210940410 Notification of contract execution. Mod 5 to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2" Contractor Science Applications, Inc FLYNX, M. Technical Assistance Contracts Branch NRC~03-B2-096 82/09/15 EISENNUT. D 0 . SILVER, H. Division of Licensing ip 15597 202
- ~-B210040412 Mod 5, incorporating award fee earned for period Mar-May 1982.to "Technical Assistance in Support of NRC Reactor Litensing Actions Program 2" 4 Stience Applications, Inc. HAGAN, T.F. Technical Assistance Contracts Branch NRC-03-82-096 82/09/15 2pp
- \$210050561 Notification of contract execution. Mod 3 to "Unsaturated 210050501 Notification of contract execution, Mod 3 to "Unsaturated Flow & Transport Through Fractured Rock re High Level Waste Repositories " Contractor Univ of AZ WACO85:A Research Contracts Branch FIN B-7291 NRC-04-81-224 82/39/20 BAY80N.W. NICHOLSON.T J Office of Nuclear Regulatory Research, Director 1p 15626 234 Office of Nuclear Regulatory
- --821005050B Mod 3 changing reporting requirements to "Unsaturated Flow & Transport Through Fractured Rock re High Level Waste Repositories" CARR.S E Arizona: Univ of GUBTAVE.R P Research Contracts Branch FIN 8-7291 NRC-04-81-224 82/09/20 4pp 15626 235
- B210030516 Notification of contract execution. Mod & to "Memphis Area Regional Beismic Network" Contractor Memphis State Univ JACOBS, A Research Contracts Branch FIN B-6276 NRC-04-7B-200 82/09/13 FOREMAND. W. MURPHY. A Office of Nuclear Regulatory Research Director ip 15626 354
- --8210050521 Ltr contract.NRC-04-78-200, "Momphis Area Regional Beismic Metwork." Mod 6.increasing amount of funds Receipt ack by TO Carperter on 820830 GUSTAVE.R.P Research Contracts Branch FIN B-6276 NRC-04-78-200 82/08/19 TRENKIN 8 Memphis State Univ. 1p
- 8210050525 Notification of contract execution. Mod 3 to "NBS Calibr Heasurement Assurance Program to Support NRC Third Pilot Study Test of Personnal Dasimetry Processors " Contractor
- GUSTAVE:R P Research Contracts Branch. FIN 8-7103 NRC-01-80-82/09/14 FOREHAND,W, DERVIS,N Office of Nuclear Regulatory Research, Director is 15626-356 NRC-01-80-023
- --8210050530 Mod 3.extending period of performance to 830731 at no addl cost, to "NSS Calibr Measurement Assurance Program to Support NRC Third Pilot Study Test of Personnel Dosimetry Processors "
  BREVE, D B Commerce, Dept of, National Bureau of Standards
  OUSTAVE, R P Research Contracts Based Contracts
  - OUSTAVE.R P Research Contracts Branch. FIN B-7103 WRC-01-80-023 62/09/14. (p. 15626 357
- 02:10060420 Notification of contract execution "Const & Calibr of Br-90 Irradiator for Multiple Dosimeter Irradiations," awarded to FIN 8-8285 NRC-04-82-024
- univ 47 m. HAGEY, H. Research Contracts Branch. FIN B-8285 NRC-04-82-024 82/09/20 FÜREHAND, W., DENNIB, N. Office of Nuclear Regulatory Research, Director 19 13636 243
- --8210050424 Contract: "Const & Calibr of Sr-90 Irradiator for Multiple Dosineter Irradiations," awarded to Univ of MI HATTHERS C W Michigan, Univ of MORTON, K V Research Contracts Branch FIN 8-8285 NRC-04-82-024 82/09/20. 9pp 15636:244
- 8210070017 Notification of contract execution. "Reviewing Hydrologic Investigations of Baselt Wasta Isolation Project (BHJP), Project B." awarded to Golden Associates Inc MILEBLE B Technical Assistance Contracts Branch FIN 8-7373-2 NRC-02-82-045. 82/07/20. DAVIS.J., JOHNSON.R Office of Nuclear Material Bafety & Bafeguards, Director. 1p 15646: 304
- --8210070021 Contract: "Reviewing Hydrologic Investigations of Basalt Waste Isolation Project (BHIP), Project B. " awarded to Colder Associates, Inc. Volum Associates, Inc.
  WEBT.L J Golder Associates, MATTIA.H. J Technical Assistance
  Contracts Branch FIN 8-7373-2 NRC-02-82-045 82/07/20, 36pp

- 8210070153 Notification of contract execution.Mod 3 to "Fuel Cycle Analysis Spain " Contractor Nuclear Assurance Corp MCNULTY.A Administrative Contracts Brench FIN B-7374-2 NRC-02-62-048 82/09/13 BROWN, R S . THOMAS, B H Program Support Branch 1p 15445-004
- --8210070186 Med 3.deobligating funds to "Fuel Cycle Analysis Spain "
  SMITH.R L Nuclear Assurance Corp REBELLO. J E Division of
  Contracts FIN 8-7374-2 NRC-02-82-048 82/08/13 ip
- 8210070456 Notification of contract execution "ADP Planning Assistance." awarded to Dept of Air Force MILES.E B Technical Assistance Contracts Branch FIR B-8810 NRC-33-82-321 82/09/17 FROST.A Office of Resource Management. Director 19 13644 325
- --8210070459 Contract "ADP Planning Assistance," awarded to Dept of Air FORCE RUPP, W.A. AIF Force, Dept of MATTIA, P FIN D-8810 NRC-33-82-321 82/09/17 MATTIA,M J Division of Contracts 12/09/17 15pp 19444 326
- 8210080004 Notification of contract execution. Mod 3 to "Resolution of Shipper-Receiver Differences" Contractor PNL MOLLETT.8 Research Contracts Branch FIN II-8103 NRC-01~81-012-0 82/09/21 Farenanch Research Director 1p 15669 351
- --8210080009 Mod 3, adding no-cost extension from B20723 to 0823 to.
  "Resolution of Shipper-Receiver Differences"

  HAVERFIELD: A J Battelle Memorial Institute, Pacific Northwest
  Laboratory QUSTAVER P Research Contracts Branch FIN 8-8103

  NRC-01-81-012-0 82/09/21 ip 13669 352 1p 13669 352
- 8210080012 Notification of contract execution, Mod 4 to "Seismicity & Earthquake Hazard Research in Northern A." Contractor Oeological Survey of AL. Univ of AL.
  HOLLETT, S. Research Contracts Branch FIN 8-6674 NRC-04-80-220
  82/09/21 BATSON.W. MURPHY, A. Office of Nuclear Regulatory Research, Director ip 13669-353
- --8210080022 Mod 4, adding funding for equipment purchases for use under previously approved scope to: "Seismicity & Earthquake Hatard Research in Northern AL "
  MANCINI,E A Alabama Univ of. GUSTAVE,R Research Contracts
  Branch FIN B-6674 NRC-04-80-220 82/09/21 1p 15669 354
- 8210120321 Notification of contract execution, Mod 8 to "Development & Implementation of Flow Analysis Sys Based on Synthetic Aperture Ultrasonic Imaging Technique" Contractor SHRI MOLLETT. 8 Research Contracts Branch FIN 8-5605 NRC-09-77-145 82/09/15 FOREHAND, W. NUSCARA, J Gffice of Nuclear Regulatory Research, Director in 18672 218
- ---B210120330 Mod 8, extending period of performance to 830930 & increasing funding, to "Development & implementation of Flow Analysis Based on Synthetic Aperture Ultransonic Imaging Technique." Technique." SPRENCELLJ F Bouthwest Resparch Institute GURTAVE,R Research Contracts Dranch FIN 8-3605. NRC-04-77-145 15692 219
- 8210120308 Notification of contract execution. Mod 2 to "Habash Valley Seismic Profile " Contractor Purdue Research Foundation WOLLETT.8 Research Contracts Branch FIN 8-7223 NRC-04-80-224 82/07/22 BATBON.W , ZURFLEUH.E Office of Nuclear Regulatory Research, Director ip 15691 051
- ---9210120342 Mpd 2.extending period of performance to 830907.to "Wabesh Valley Beismic Profile"

  GREENKORN, R A Purdue Research Foundation GUSTAVE, R P. Research Contracts Branch FIN 8-7223 NRC-04-80-224 82/09/22 ip
- 82:10:20347 Notification of contract execution "Reviewing Hydrogeologic Investigations of NV Test Site (NTS)-Project D. awarded to GeoTrans, Inc WIQOING.E Technical Assistance Contracts Branch FIN 8-7377-2 NRC-02-82-047 82/09/29. DAVIS.J., VERMA.T Defice of Nuclear Material Bafety & Safeguards, Director ip 15691 061 FIN 8-7377-2
- ~-8210120350 Contract "Reviewing Hydrogeologic Investigations of NV Test Site (NTB) ~Project D." awarded to GeoTrans.Inc. HERCER.J W Geotrans. Inc. MATTIA:M J Division of Contracts FIN 8-7377~2 NRC-02-82-047 82/09/29, 37pp 15691.062

FLYNN, M. Technical Assistance Contracts Branch FIN B-8622 NRC-03-82-131 82/09/29 EISENHUT, D. G. BILVER, H. Division of Licensing ip 15690.340

- --8210120357 Mod 2.redefining tasks.extending delivery date of draft technical evaluation rept & increasing contract amount to, "Value-Impact Analysis of Recommendations re Steam Generator Tube Degradations & Rupture Events"

  FINDLEY.D E Science Applications, Inc. HAGAN, T F Division of Contracts FIN 8-8622 NRC-03-82-131 82/09/28 2pp (15690-341
- B210120361 Notification of contract elecution Mod 3 to "Economic Assistance in Connection w/Antitrust Hearings" Contractor JM Kuhlman MCLEAREN.T Technical Assistance Contracts Branch FlN 8-5494 NRC-03-75-097 82/10/05 DENTON.H R Office of Nuclear Reactor Regulation. Director ip 15690 247
- --B21012D362 Mod 3.deobligating funds, to "Economic Assistance in Connection w/Antitrust Hearings"

  KUHLMAN,J M Kuihman, J M FIN B-5494 NRC-03-75-097 B2/10/05

  10 15690 248
- 8210120363 Notification of contract execution.Mod 7 to "Study of Paleoiols Stratigraphy in New Madrid Area of MS Embayment "Contractor Univ of KY Research Foundation SILVIS.R M Research Contracts Branch FIN 8-8972 NRC-04-76-321 82/09702 BATSON.W. STEUER.W. Office of Nuclear Regulatory Research, Director 1p 15490 245
- --8210120364 Ltr Contract NRC-04-76-321.Mod 7.deobligating funds.to
  "Study of Paleozoic Stratigraphy in New Madrid Area of
  MS Embayment "
  GUSTAVE.R P Research Contracts Branch NRC-04-76-321 82/06/08
  GARTER.R Kentucky, Univ of 1p 15690 246
- 92(0120365 Notafication of contract elecution "Purchase of BSAM-100 Assay Neters for Region 2," awarded to IRT Corp EDOSHORTH,P J Administrative Contracts Branch NRC-29-82-721 82/09/16 STOHR,J P MONTGOMERY,D M Division of Emergency Preparedness & Operational Support 1p 15690 222
- --8210120366 Contract "Purchase of BSAM-100 Assay Meters for Region 2,"
  avaried to IRT Corp
  \* IRT Corp MATTEA, M J Administrative Contracts Branch
  NRC-29-82-721 82/09/16 22pp 15690 223
- B210120391 Notification of contract execution "Reviewing Hydrogeologic Investigations of NV Test Site (NTB)-Project C." awarded to William-Robinette & Associates, Inc WIODINS. E Technical Assostance Contracts Branch FIN 8-7377-2 NRC-02-82-046 B2709/30 DAVIS, J. VERMA, T. Office of Nuclear Material Safety & Safeguards. Director ip 15689-242
- --B210120401 Contract "Reviewing Hydrogeologic Investigations of NV Test Site (NTS)-project C," awarded to Williams-Robinette Associates, Inc WILLIAMS, R E Williams-Robinette & Associates, Inc MATTIA, N J Technical Assistance Contracts Brench FIN B-7077-2 NRC-02-82-046 B2/09730 36pp 15689 243.
  - i of contract execution. "Haint & Operation of Rooms (LPDRs)." awarded to Appling
  - itive Contracts Branch NRC-10-82-714 SOUDER, J. Division of Rules and Records
    - of Local Public Document Rooms ibrary, GA 4 Administrative Contracts on 15AR9 225

- 8210120427 Notification of grant execution Mod 2 to "Aerospace-Electric Power Workshop Conference on Commercial Nuclear Power " Grantee American Inst of Aeronautics & Astronautics MCDERMOTT, D. Research Contracts Branch FIN G-1005 NRCG-04-81-002 82/09/29 RIB.L. Office of Nuclear Regulatory Research, Director ip 15671 159
- --B210120432 Mod 2.extending no-cost period of performance to B21231.t "Aerospace-Electric Power Workshop Conference on Commercial Nuclear Power" BRUCE.W R American Institute of Aeronautics & Astronautics MORTON.K V Research Contracts Branch FIN G-1005 NRCO-04-B1-002 B2/09/29 1p 13671 160
- B210120436 Notification of contract execution "Bioassaye Using Resource Ionization Spectroscopy," awarded to Atom Griences, Inc.
  HAGEY: H. Research Contracts Branch FIN B-8122 NRC-04-82-021
  B2/09/27 FOREHAND, H. NREL, R. Office of Nuclear Regulatory Research, Director Ip 15671 167
- --8210120440 Contract "Bloassays Using Resource Indication Spectroscopy," awarded to Atom Sciences, Inc GCHMITT,H W. Atom Sciences, Inc. MORTON,K V. Research Contract Branch FIN B-8122 NRC-04-82-021 82/09/27 15pp 13671 [68
- S210120454 Notification of contract execution, Mod 1 to "Reviewing Hydrologic Investigations of Basalt Waste Isolation Project (BMTP), Project B "Contractor Oolder Associates.Inc FLEENOR.C Technical Assistance Contracts Branch FIN 8-7373-2 NRC-02-82-045 82/09/22 DAVIS.J., VERMA, T R Office of Nuclear Material Safety & Safeguards, Director ip 15671 207
- --8210120458 Mod 1.increasing funds.to "Reviewing Hydrologic Investigations of Basalt Haste Isolation Project (BWIP). Project B " WEST.L J Golder Associates HAGAN.T F Technical Assistance Contracts Branch FIN 8-7373-2 NRC-02-82-045 82/09/22 2ps
- 8210120467 Notification of contract execution. Hod 4 to "US Army Corpi of Engineers Geotechnical Assistance " Contractor US Army Corps of Engineers FLEENGR.C Tachnical Assistance Contracts Branch NRC-02-01-036-82/09/24 DAVIS.J. PRESTHOLT, P Office of Nuclear Material Bafe! & Bafeguards. Director ip 15672-001
- --B210120471 Mod 4, revising reporting requirements, extending period performance to B30930 & changing project officer, to "UB Army Corps of Engineers Geotechnical Assistance"

  KAVANAUGHJP F. Army Dept of Corps of Engineers HAGAN, T F
  Technical Assistance Contracts Branch NRC-02-81-036 B2/09/24
  3pp 19672 002
- 8210120483 Notification of grant execution "Horkshop on Strong-Grow Motion Simulation & Engineering Applications." awarded to Earthquake Engineering Research Inst MCDERMOTT, D. Research Contracts Branch FIN G-1038 NRC-0-04-82-007 82/09/29, BATRON, W., MURPHY. A. Office of Nutle Regulatory Research, Director ip 15672 053
- --8210120488 Grant: "Morkshop on Strong-Oround Motion Simulation & Engineering Applications," awarded to Earthquake Engineering Research Inst. SCHOLL-R E Serthquake Engineering Research Institute, MORTON, K V Research Contracts Branch. FIN G-1038 NRC-0-04-82-007 82/09/29 2pp 19672 054.
- 82(0120490 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)" awarded to Joseph Mann Library LITLE: M Administrative Contracts Branch NRC-10-82-707, 82/09/27, FELTON, J M , SQUDER, J Division of Rules and Records ip 15672 056
- --8210120494 Contract "Maint & Operation of Local Public Documents Rooms (LPDRs)" awarded to Joseph Hann Library HEITKEMPER, E M. Two Rivers, MI SHITH, P. A. Administrative Contracts Branch NRC-10-82-707. 82/09/27 9pp 13672 057
- 8210120497 Notification of contract execution. Task Order 25. "Techn Assistance to Support NRC IE Personnel in Investigations of Incidents." awarded to Parameter. Inc MOLLETT. 8. Research Contracts Branch FIN 8-1302. NRC-03-82-24. B2/09/10. BLAMA. J. LAUDAN. W. Director's Office Office of Inspection and Enforcement. ip 13672-072.
- --8210120308 Ltr Contract NRC-05-B2-249, Task Order 23, "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents," awarded to Parameter, Inc QUSTAVE, R P Research Contracts Branch. FIN B-1302 NRC-05-B2-249. 82/09/07. LOFY, R A Parameter, Inc 2pp 15472,073.

- E210120510 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Exeter,NH blic Library FUBING LANGUAGE CONTRACTS Branch NRC-10-82-712 LITTLE, M Administrative Contracts Branch NRC-10-82-712 BZ/09/20 FELTON, J M , SQUDER, J Division of Rules and Records
- --82(0120517 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Exeter.NH Public Library QUETTUM.P Exeter.NH SHITH.P A. Administrative Contracts Branch NRC-10-82-712 82/09/30 7pp 15672 082
- 8330120534 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Ocean County Library, NJ LITTLE, M Administrative Contracts Branch NRC-10-82-713 B2/09/30 FELTON, R R . BOUDER, J Division of Rules and Records
- -- 8210120541 Contract "Maint & Operation of Local Public Document Ploy2034 Contract Rooms (LPDRs)," awarded to Ocean County Library, NJ NUDIXI.J J Ocean County, NJ SMITH,P A Administrative Contracts Branch NRC-10-82-713 82/09/30 7pp 15672 R07
- 5210120540 Notification of contract esecution. Mod 7 to "Peer Review of High Level Maste Site Suitability Criteria " Contractor TRM.

inc MCLEAREN,Y Technical Assistance Contracts Branch FIN B-613/~3 MRC-02-77-143 82/09/27 DAVIS,J 9 Office of Nuclear Material Safety & Safeguards, Director 1p 15672 217

- --B210120550 Hod 7, incorporating final indirect rates for FY77 & FY78, to \*Feet Review of High Level Waste Site Suitability Criteria " MCDDNNELLE J TRH INC HAGAN.T F Division of Contracts FIN B-6137-3 NRC-02-77-143 82/09/27 ip 15672 218
- @210120549 Notification of contract execution "Maint & Operation of 210120549 Notification of contract execution "Maint & Operation " Local Public Document Rooms (LPDRs)," awarded to San Clements, CA Public Library LITTLE, H Administrative Contracts Branch NRC-10-82-708 82/09/30 FELTON, J M , BOUDER, J Division of Rules and Records
- --8210120556 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Ban Clemente, CA Public Library SHITH,E M San Clemente, CA GMITH,P A Administrative Contracts Branch NRC-10-82-708 82/09/30 7pp 15672 227
- 82(0120407 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)" awarded to Kowawnee, WI Public Library LITTLE.M Administrative Contracts Branch NRC-10-82-674 82/09/27 FELTON, J M , BOUDER, J Division of Rules and Records 15694 199
- --82(0)20613 Contract "Maint & Operation of Local Public Document Rooms (LPORs)" awarded to Kewawnee, HI Public Library GROSSHUESCH, B Kewaunse County, WI SMITH,P, A Administrative Contracts Branch NRC-10-82-674 82/07/27 7pp 13684 200
- E21013000B Notification of grant execution, Mod 2 to "Study of Faulting in & Near Surface & Underground Mines of Southwestern IN "

on a new survey of the state of

- --8210130014 Hod 2, incorporating renewal proposal, extending period of performance to B30930 & increasing funding to "Study of Faulting in & Near Surface & Underground Mines of Southwestern HULMOLLAND, J. D. Indiana Univ MORYON, K. V. Research Contracts Branch FIN 9-1019 NRC-9-04-81-017 82/09/22 1p 15692:334
- 6210130052 Notification of contract execution. "Expart Opinion During Meetings of NRC Advanced Reactor Subcommittee of ACRB Concerning LMFBRs." awarded to Rockwell Intl. TOWNBEND.B L Administrative Contracts Branch FIN 8-1557 TOWNSEND, B L Administrative Contracts Spanch FIN 8-1557 NRC-11-82-433 82/09/23. OASKE, M. C., BOEHNERT, P. A. ACRS - Advisory Committee on Reactor Safeguards. 1p 15696 277.
- -- 8210130054 Contract "Expert Opinion During Meetings of NRC Advanced Reserve Subcommittee of ACRB Concerning LMFBRs," awarded to Rockwell Intl. AGENBON,R A Rockwell International Corp R AGENISTRATIVE Contracts Branch FIN 8-1557 82/09/23, 4pp. 15496:278 RESELLO, J. E. NRC-11-82-433

- 8210130058 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)" awarded to Southporth Brunswick NC County Library LiTrLe: M Administrative Contracts Branch NRC-10-82-702 62/09/28 FELTON. J H , SOUDER, J Division of Rules and Records 15692 274
- --8210130061 Contract "Meint & Operation of Local Public Document Hours (LPDRs)," awarded to Southport-Brunswick NC County Library HARPER, M T Southport, NC SMITH, P Administrative Contracts Branch NRC-10-82-702 82/09/28 9pp 15492 275
- B2(0130071 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Sometvell County Public Library on Square

  LiTTLE, M Administrative Contracts Branch NRC-10-82-686

  82/09/28 FELTON.J M . SQUDER, J Division of Rules and Records

  1p 15696 883
- --8210130074 Contract "Haint & Operation of Local Public Document Noums (LPDRs)," awarded to Somervell County Public Library on Equare
  WHITHORTH,F Somervell County,TK SMITH,PA Ada
  Contracts Branch NRC-10-82-686 82/09/28 9op
- 82(0130587 Notification of contract execution Task Orders 21,22,23 & 24,4c "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents," awarded to Parameter, Inc. HOLLETT, S. Research Contracts Branch FIN 8-1302 MRC-05-82-249 82/09/02 BLANA, J. 1AUDAN, W. Director's Office, Office of Inspection and Enforcement ip 15492 338
- --8210130592 Ltr contract executing Task Orders 21, 22, 23 & 24, to "Technical Assistance to Support NRC JE Personnel in Investigation of Incidents " GUSTAVE.R P. Research Contracts Branch FIN B-1302 NRC-09-82-249 82/08/31 LOFTY,R A Pavameter. Inc. 2pp 14402 230
- 8210150328 Notification of contract execution, Mod 11 to "Study of Seismicity & Tectonics in New England "Contractor Boston College Lollege JACOBS, A. Research Contracts Branch FIN A-4084 NRC-04-74 B2/09/23 BATBON, H. MURPHY, A. Office of Nuclear Regulatury Research, Director 1p 15715 337 NRC~04~74~236
- --8210150350 Mad il.increasing funding. to "Study of Seismicity & Tectonics in New England " BHITH JR Boston State College QUSTAVE, R F Research Cuntracts Branch Fin A-4056 NRC-04-74-238 82/09/23 5pp 15715 338
- 8210180327 Notification of contract execution:Mod 22 to "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions " Contractor Franklin Inst FLYNN:M Technical Assistance Contracts Branch FIN 8-6590 NRC-03-79-118 82/09/20 EISENHUT.D 9 BAJWA:B Division of Licensing 1p 15746 GO3
- --B210180302 Mod 22.obligating funds, to "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions" RTOVERJR Franklin Institute/Franklin Research Center HAGAN, TF Division of Contracts FIN 8-6590 NRC-03-79-118 82/09/28 Spp 13744 004

8210180329 Not & Re E New Tinc. BAZIN, JP Administrative Conviger BAZIN, JP Administrative Conviger BESAW, W J. SKOCZLAB, J. BCOTT, B B2/09/30 BESAW, W J. SKOCZLAB, J. BCOTT, B Information & Document Control ip 15745: Division of Technical 15745:339

- -8210180348 Contract. "Microfiche Verification & Ratrofit," awarded to Labat-Anderson:Int Labat-IV J Labat-Anderson; Inc HILL:D Small Business Administration, NRC-10-82-425 82/09/30 23pp 15745 15745 342
- 82(0)80357 Notification of contract execution: Mod 9 to "Seismotectonic Study of New England & Adjacent Areas " Contractor Boston College. College.

  JACOBB: A Research Contracts Branch FIN 8-5961 NRC-04-76-291
  BATBON W , MURPHY, A Office of Nuclear Regulatory
  Research, Director 19 15745.302

- --8210180362 Mod 9, funding FYB2 action to "Seismotectoric Study of New England & Adjacent Areas " SMITH.J R Boston College QUSTAVE, R P Division of Contracts FIN 8-5961 NRC-04-76-291 82/09/23 Bpp 15745 303
- 8210180365 Notification of contract elecution "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Calvert County, MD Library LITTLE: M Administrative Contracts Branch NRC-10-82-704 82/09/29 FELTON, J M , SQUDER, J Division of Rules and Records to 15745 21:
- 82(0180384 Notification of contract execution, Mod 23 to, "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions" Contractor Franklin Inst FLYNN, M. Technical Assistance Contracts Branch Fin 8-6590 NRC-03-79-118 82/09/30 EISENHUT, D., BAUHA'S Division of Licensing Ip 15745 321
- --8210180390 Mod 23, obligating funds, extending performance period to 830331 & assigning new project manager, to "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions"

  ZUDARG, Z Franklin Institute/Franklin Research Center MATTIA.H J Division of Contracts FIN 8-6590 NRC-03-79-118 82/09/30 3pp 15745 382
- 8210180395 Notification of contract elecution "Maint & Operation of Local Public Document Rooms (LPDRs)" awarded to Lawson McGhee Public Library LITTLE, M. Administrative Contracts Branch NRC-10-82-701 82/09/28 FELTON. J. M., SCUDER, J. Division of Rules and Records (p. 15745-290)
- --8210:8040: Contract "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Lawson HcObee Public Library BARTOLINI.R P Knozville, TN SMITH, PA Administrative Contracts Branch NRC-10-82-701 82/09/28 7pp 15745 291
- 8210180411 Notification of contract execution. "Maint & Operation of Local Public Sprument Rubes (LPDRs)," awarded to Emporta State Univ LITTLE: M Administrative Contracts Branch NRC-10-82-687-82/09/28 FELTON, J K . SQUDER, J Division of Rules and Records
- --8210180416 Contract "Maint & Ogeration of Local Public Document Ruoms (LPDRs)," awarded to Emporta State Univ VISSER, J E Emporia State Univ SHITH, P A Division of Contracts NRC-10-82-687 82/09/28 8pp 15745 326
- 8210190001 Notification of grant elecution "Chapman Conference on Fault Behavior & Earthquake Generation Process," awarded to American Geophysical Union (HOBERMIFF, D.K. Research Contracts Branch FIN 0-1039 NRC-G-04-82-008 82/09/29 BATSDN, W., MURPHY, A.J. Office of Nuclear Regulatory Research, Dispector ip 15760 174
- --B210190002 Grant "Chapman Conference on Fault Behavior & Earthquake
  Process," awarded to American Geophysical Union
  American Geophysical Union MURPHY, A J Research
  1ch FIN 0-1039 NRC-0-04-82-008 82/09/29 2pp

- 82(019001B Notification of contract execution, Mod 7 to "Technica) Assistance in Bupport of Reactor Licensing Actions Program 2 "Contractor Science Applications, Inc FLYNN, H Technical Assistance Contracts Branch FIR B-8609 NRC-03-82-096 92/09/30 EISENHUT, D, SILVER, H Division of Licensing ip 15760 342
- --8210190025 Hod 7, providing incremental funding, to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2" & Ectence Applications, Inc. HADAN, T.F. Technical Assistance Contracts Branch FIN 8-8609 NRC-03-82-096 92/09/30 2pp
- B210190030 Notification of contract execution, Mod & to "Technica) Assistance in Support of NRC Reactor Licensing Actions Program 2 " Contractor Science Applications Inc FLYNN, M Technical Assistance Contracts Branch FIN B-BA09 NRC-03-92-096 82/09/28 EISENRUT, D G & SILVER, H Assistant Director for Licensing lp 13761 031
- --8210170037 Mod 6, substituting members of performance evaluation bosis & providing incremental funding to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2" FINDLEY, DE Science Applications. Inc HAGAN, T.F. Tachnical Assistance Contracts Branch FIN 8-8609 NRC-03-82-096 82/09/28 2pp 15761 032
- 8210190057 Notification of contract execution "Tornado Hindspeed Documentation," awarded to Univ of Chicago HAGEV,H. Research Contracts Branch FIN B-8108 NRC-04-82-004 82/09/22 BATBEN,W. ORENIER,B. ABBEV,R. Office of Nuclear Regulatory Research, Director ip 15761 049
- --8210190063 Contract "Tornado Windspeed Documentation," awarded to Univ of Chicago SIOAL,D S Chicago Univ of MORTON,K V Research Contracts Branch FIN 8-8108 NRC-04-82-004 82/09/22 10pp 15745 053
- B210190076 Notification of contract execution, Mod 2 to "Degraded Piping Program" Contractor BMI WOLLETT, B Research Contracts Branch FIN 8-7027 NBC-04-81-178 B2/09/24 FOREMAND 8, STROSNIDER, J Office of Nuclear Regulators Research, Director 1p iS761 098
- --B2i0190087 Mod 2.increasing funding 5 extending period of perforased to 830531.to "Degraded Piping Program"

  \* Battelle Mamorial Institute, Columbus Laboratories
  QUSTAVE, R. P. Research Contracts Branch NRC-04-81-178 82/09/N
  3pp 15761 099
- 8210190102 Notification of contract execution. Mod 1 to "Hydrological Engineering Coastal Review of Operating Factors (I) " Contractor DDD. FIELDS, J.A. Technical Assistance Contracts Branch FIN 9-DDDA NRC-03-81-132. 82/09/30 VOLLMER, R.H., LEAR, G. Division of Engineering ip 13761 223
- --8210190105 Mod 1.deobligating balance of FY81 travel funds & obligating FY82 travel funds to "Hydrological Engineering Coastal Review of Operating Factors (I)"

  \* Army, Dept of FIN B-8006 NRC-03-81-132 82/09/30 2pp 15761 224
- 82:0190132 Notification of contract execution.Mod 9 to "Utilication of BMR & PMR 8 imulator Activities " Contractor TVA JACO88.A Research Contracts Branch NRC-05-76-357 82/09/23 BLAHA, J., FOX.E Program Support Branch 1p. 15761 237
- --8210190141 Mod 7, increasing funding to "Utilization of BUR & PAR Simulator Activities." JUHNSON.R.A Tennessee Valley Authority GUBTAVE.R P Researc Contracts Branch NRC-05-76-357 82/09/23 ip 15761 238
- B210190149 Notification of contract execution. Mod 4 to "On-Call & Scheduled Monthly Preventive Haint on ECLIPBE 8/230 Computer Sys "Contractor Computer Sys Bupport Corp EMITH.P A. Division of Contracts FIN 8-1671 NRC-1D-80-706 82/04/30 DDRIE, W M . JOHNBON, C Office of Administration 19 13761 244
- --8210190154 Mod 4, deobligating balance remaining, to "On-Call & Scarl Monthly Preventive Maint on ECLIPSE S/230 Computer Sys ROST.L.E. Computer Systems Support Corp. BMITH.P.A. Division Contracts FIN 8-1671 NRC-10-80-706 82/09/30 bp 1574121
- 8210190162 Notification of contract execution. Mod 1 to "Partitions" Contractor, Aspects, Inc SMITH-P.A. Division of Contracts, NRC-10-82-401 82/09/30 FETROM: 0 Division of Facilities & Operations ip 15844 138

- ~-8210190167 Hod 1, deobligating balance remaining, to "Partitions " LEO.F A Aspects. Inc SMITH.P A Division of Contracts MRC-10-82-401 82/09/30 ip 15758 048
- 821G190172 Notification of contract execution "Near Ground Tornado Mind Fields:" awarded to TX Tech Univ PAGEY.H Research Contracts Branch FIN 8-8099 NRC-04-82-002 82/09/21 BATSDN.W - ABBEY.R Office of Nuclear Regulatory Research, Director 1p 13758 049
- --8210190177 Contract "Near Ground Tornado Wind Fields," awarded to TX Tech Univ JONES.J K Texas Tech Univ MORTON, K V Research Contracts B-B099 NRC-04-82-002 82/09/21 12pp 15758 050
- 8210190179 Notification of contract execution "Presentation of General & Refresher Courses in Nondestructive Exam," awarded to Roctuell Intl Corp HAGEY.H Research Contracts Branch FIN 8-1303 NRC-05-82-246 82/09/21 FOX.E Program Support Branch ip 15739 114
- --B2101901B2 Contract "Presentation of General & Refresher Courses in Nondestructive Exam," awarded to Rockwell Intl Corp JOHNSON,R A Rockwell International Corp MORTON, K V Contracts Branch FIN B-1300 NRC-05-B2-246 82/09/21 3pp
- 8210190210 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)" awarded to Charlevoix, MI Public Library LITTLE, M Administrative Contracts Branch, NRC-10-02-699 B2/09/30 FELTON, J M : BOUDER, J Division of Rules and Records ip 13759 141
- --8210190215 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)" awarded to Charlevoix MI Public Library WALLICK: HE Charlevoix MI REBELLO. JE Administrative Contracts Branch NRC-10-82-699 82/09/30 9pp 15758 142
- 8210190219 Notification of contract execution "Radio Frequency Surveillance Receiver & Accessories," awarded to Micro-Tel Corp. COLEMAN, R Administrative Contracts Brench NRC-10-82-682 B2/09/30 BRADY, R, FINGER, R Division of Security ip 19789 151
- 8210190230 Notification of contract execution, Mod 1 to "Reviewing Hydrogeologic Investigations of MV Test Site (NTS) Project D." Contractor Geotrans, Inc H1001NB.E Technical Assistance Contracts Branch FJN A-7377-2 NC-02-82-047 82/09/30 DAVIS.J., VERMA, T. Diffice of Nuclear Miterial Safety & Bafeguards, Director. 1p 18758 177
- --8210190339 Hod i.correcting accounting & appropriation data.to
  "Reviawing Hydrogeologic Investigations of NV Tast Site
  (MTS) Project D"

  a Geotrans, Inc. MATTIA.M J Technical Assistance Contracts
  Branch FIN B-7377-2 NRC-02-82-047, 82/09/30 jp 15758 J78
- 8210210036 Notification of grant execution, Mod 2 to "Development of Kethodology for Systematic Probabilistic Risk Assessment of Nuclear Power Plants." Orantee, IEEE HODERMOTT, D. Research Contracts Branch FIN 0-1007 NGC-0-04-81-005 82/08/30 BATSON.N., JOHNSON, C. Office of Nuclear Regulatory Research, Director 1p. 18773, 271
- --8210210038 Med 2, providing add1 funds, to "Development of Methodology for Systematic Probabilistic Risk Assessment of Nuclear Power Plants."

  # Institute of Electrical & Electronic Engineers HORTON, K V, Research Contracts Branch FIN G-1007, NRC-G-04-Bi-005 82/08/30, ip 15773 272
- 8210210061 Notification of contract execution. Mod 7 to "Sealing Rock Hasses " Contractor. Univ of AZ JACOBS. A Research Contracts Brench FIN 8-6627 NRC-04-78-271 82/09/28 BATSON, W., DOYLELL Office of Nuclear Regulatory Research, Director 1p. 18774:123.
- --8210210066 Mod 7, adding govt property, to "Sealing Rock Masses "
  CARRISE Arizona, Univ of, QUSTAVE, R P Research Contracts
  Branch. Fin 8-6627. NRC-04-78-271 82/09/28. 1p 15774 124

- 8210210147 Notification of contract execution. Mod 1 to "Maint & Operation of Local Public Document Rooms (LPDR) "Contractor Richland. MR Public Litrary LITTLE, M Administrative Contracts Branch NRC-10-82-706 82/09/29 FELTON.J M . SOUDER.J Division of Rules and Records in 15774 299
- --8210210161 Mod 1,increasing monetary value of contract,to "Maint & Operation of Local Public Document Rooms (LPDR) " \* Richland, HA. SMITHIP A Administrative Contracts Branch NRC-10-82-706 82/09/29 ip 15774 300
- 6210210174 Notification of grant execution "Evaluation of Denefits of Response Time In Situ Testing of Neutron Bensors Used in Nuclear Power Reactor Protection Sys "Awarded to OH State Univ Research Foundation MCDERMOTTID Research Contracts Branch FIN G-1044 NRC-0-04-82-011 82/09/20 HINTZE.A Diffice of Nuclear Regulatory Research, Director 1p 15772 361
- --8210210178 Grant "Evaluation of Benefits of Response Time In 51th Testing of Neutron Sensors Used in Nuclear Power Reactor Protection Sys." SLOAN,K W. Ohio State Univ. MORTON,K V. Research Contracts Branch FIN G-1044 NRC-0-04-82-011 82/09/20 2pp 15772 362
- 8210210438 Notification of contract execution "Facilities Documentation to Update Project." awarded to SBA Subcontractor Bryant & Bryant EDGEWORTH: P Administrative Contracts Branch NRC~10-82-420 B2/09/28 CORLEY. J H. FISHER. L Division of Facilities & Operations ip 15773 273
- --8210210444 Contract "Facilities Documentation & Update Project."

  awarded to SBA & Bryant & Bryant (subcontractor)

  BRYANT,R E Bryant & Bryant AlA DENNISTON, S F Small Business

  Administration MATTIA, M J Administrative Contracts Branch

  NRC-10-82-420 82/09/28 21pp 15773 274
- 8210210502 Notification of contract execution "Maint & Operation of Local Public Document Rooms (LFDRs)," awarded to Richland, WA Public Library LITTLE. H Administrative Contracts Branch NRC-10-82-704 82/09/29 FELTON, J H , BOUDER, J Division of Rules and Records to 18782 273
- --8210210805 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Richland, MA Public Library ROBERTS, D E Richland, MA. SMITH. P A Administrative Contracts Branch NRC-10-82-706 82/09/29. 9pp 15782 274
- 8210210564 Notification of contract execution "Transient Prototypical Steam Generator (MB-2) Research Testing Program," awarded to Westinghouse & EPRI BARBDEN,L. Research Contracte Branch FIN B-8252 NRC-04-82-020 82/09/30 DATBON,H, HOPENFELD,J Office of Nuclear Regulatory Research, Director 2pp 15784 283
- --B210210570 Ltr Contract NRC-04-B2-020, "Transient Prototypical Steam Generator (MB-2) Research Testing Program "Accepted by BB Rytkonen on 820927 & J Moore on 820924 HORTON: K V Research Contracts Branch FIN 8-8252 NRC-04-82-020 82/09/28 FEROUSON: K L Westinghouse Electric Corp. RYTKONEN: B D Electric Power Research Institute 11pp 13784, 285

- 3210260237 Notification of grant execution "Thermal-Hydraulic Transient Behavior of Coolant in Simulated Reactor Loop," awarded to Univ of hD MCDERMOTT, D.K. Research Contracts Granch FIN G-1043 NRC-0-03-02-013 02/09/27 YOUNG, M. Office of Nuclear Regulatory Research, Director 1p 15830 145
- --8210260240 Grant "Thermal-Hydraulic Transient Dehavior of Coolant (n Simulated Reactor Loop," awarded to Univ of MD GASHMAN,D C Maryland, Univ of MORTON,K V Research Contracts Branch FIN 0-1043 NRC-0-04-82-013 82/09/27 2pp 15830 146
- 8210260278 Notification of contract elecution, Mod 11 to "Technical Assistance to Support NRC IE Personnel in Investigation of Incidents" Contractor Parameter Inc WOLLETT, 5 Research Contracts Branch FIN 8-1013 NRC-05-80-251 82/09/24 BLAHA, J. L. LOFY, R. A. Program Support Branch in 15830 148
- --8210260280 Mod 11.increasing calling & changing billing ofc & address for submission of invoices, to "Technical Assistance to Support NRC IE Personnel in Investigation of Incidents" LOFY, R A Parameter inc OUSTAVE, R Research Contracts Branch FIN 2-1013 NRC-05-80-251 82/09/24 ip 15830 149
- 8210260282 Notification of contract execution, Mod 4 to "Presentation of CE BUR/6 Design & Operation Courses " Contractor GE JACOBS, A Research Contracts Branch FIN B-1224 NRC-05-80-282 82/09/29 BLAHA.J. PIERCE.R Program Support Branch ip 15830 150
- --B210260284 Mod 4, changing order re-price & funding action, to "Presentation of OE BWR/6 Design & Operation Courses "AVERITY, D D General Electric Co OUSTAVE, R P Division of Contracts FIN B-1224 NRC-05-80-282 92/09/29 2pp
- B210260516 Notification of contrast execution "Maint & Operation of Local Public Document Rooms (LPDRs)." awarded to Chattanooga-Hamilton County TN Bicentennial Library LITTLE.M Administrative Contracts Branch NRC-10-82-703 B2/09/28 FELTON.J M . SQUDER, J Division of Rules and Records 19 15830 158
- --8210260320 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Chattanooga-Hamilton County TN Bicentennial Library ARNOLD: K Chattanooga: TN BMITH:P A Administrative Contracts Branch NRC-10-82-703 82/09/28 9pp 15830 159
- 8210260525 Notification of contract ejecution "Maint & Operation of Local Public Document Rooms (LPDRs)," awarded to Lacrosse HF Public Library LITTLE, K Administrative Contracts Branch NRC-10-82-685 B2/09/28 FELTON, J M , BOUDER, J Division of Rules and Records 1p 15830 179
- --8210260530 Contract "Maint & Operation of Local Public Document Rooms (LPDRs)," Awarded to Lacrosee WI Public Library HHITE, J W LaCrosse, HI SMITH, P A Administrative Contracts Branch NRC-10-82-685 B2/09/28 Fee 15830 180

- 8210270199 Natification of contract execution "Maint & Operation of Local Public Document Rooms (LPDRs)," swarded to State Library of PA BAZNUJP Administrative Contracts Branch NRC-10-82-674 B2/09/28 FELTONUJM , SOUDER, J Division of Rules and Records to 15836 001
- --8210270203 Contract "Haint & Operation of Local Public Document Act (LPDRs)," awarded to State Library of PA SHELKROT.E L Pennsylvania, State of MATTIA.H J Division of Contracts NRC-10-82-696 82/09/28 149p 15836 002
- 8210270207 Notification of contract execution "Availability of Modification of contract execution "Availability of Modification Accidents," awarded to SBA Subcontractor Androllis Research Corp MiggINS, E. Tychnical Assistance Contracts Branch FIN 19-7616. NRC-03-82-128 82/09/27 MATTSON.R.J. WOHL.M. Division of Lytts. Integration (post 811005) 1p 15836 016
- --0210270221 Contract "Availability of Medical Treatment to Hintelts Early Fatalities Post-Bavere Reactor Accidents," awarded to SBA Subcontractor Andrulis Research Corp ANDRULIE,M M. Andrulis Research Corp DENNIBTON, 8 F. 8mg j.t. Business Administration FIN 8-8616 NRC-03-82-128 02/09/29 2pp 15836 017
- ---S210270223 Contract "Availability of Medical Treatment to Manager?"
  Early Fatalities Post-Severe Reactor Accidents, "Awarded to
  SBA Bubcontractor Andrulis Research Corp
  DENNISTON,S F Small Business Administration \* Andrulis
  Research Corp HATTIAN J Division of Contracts IN B 8616
  NRC-03-82-128 82/09/29 12pp 15836-019
- 8210270226 Notification of contract execution "Fire Protection Profile Review Case Work Plant 1." awarded to Qaga-Babcock & Associates Wiggins, E. Technical Assistance Contracts Branch FIN B (6)20 NRC-03-B2-11B 82/09/28 VOLLMER:R. H. Division of Engineering NOLAN, F. Chemical Engineering Branch 1p 15836-046
- 8210270393 Notification of contract execution, Mod 3 to "Invisor Monitoring Program W/State of NC " Contractor State of NC WGLEETT, B Research Contracts Branch FIN B-1237 NRC 05 Hb 263 82/10/12 COBB, L 1, COHENL, V Director's Office, Office of Inspection and Enforcement ip 15833 340
- --8210270395 Mod 3.changing name of NRC billing ofc & address for submission of invoices to "Environ Monitoring Program W/State of NC"

  What of NC"

  What Caroline, State of, GUSTAVE, RP Research Contracts
  Branch FIN 8-1239 NRC-05-80-283 82/10/12 ip 158144 855
- 8210270399 Notification of contract execution, Mod 7 to "Hemphis Area Regional Seismic Network " Contractor Memphis State Univ JACOBB, A Research Contracts Branch FIN B-6276 NMC 04 7th 22m 82/09/13 BATSON W MORPHY, A Office of Nuclear Regulatory Research, Director 1p. 15832 356

- --B210270419 Mod 3, deabligating unexpended balance of contract funds by issuance of no cost settlement after termination, to "Environ Assessment of Reffinate Study Disposal at Kerr-McGem Sequagah Facility, Gore, OK "

  ARCHER, C D Science Applications, Inc HAGAN, T F Technical Assistance Contracts Branch FIN B-7314 NRC-02-81-045 B2/09/30 2p 15833 285
- 8210280206 Notification of contract execution "Use of PA Fish & Hildlife Data Base Sys in Environ Analyses for Nuclear Power Plant Lichasing," awarded to PA Game Commission HOYLEIA Administrative Contracts Branch FIN 8-8812 MRC-25-82-323 82/09/30 BASSETT.H S , JOHNSON, C Division of Data Automation & Management Information ip 15858 355
- --B210280235 Contract "Use of PA Fish & Wildlife Data Date Bys in Environ Analyses for Nuclear Power Plant Litensing," swarded to PA Came Commission SMITH, P Pennsylvania: State of SITLINGER, J I Administrative Contracts Branch FIN 8-8812 NRC-25-82-323 82/09/30 Spp 15858 356
- 8210280299 Notification of contract execution.Mod 2 to "Environ Assessments & EIS for Low Level Waste Disposal Facilities" Contractor Envirosphere Co. FLEENOR, C M Technical Assistance Contracts Branch NRC-02-02-02-09 82/10/05 DAVIS, J. PANOBURN, Q Office of Nuclear Haterial Safety & Safeguards, Director 1p 15059-036
- --8210280306 Mod 2, extending period of agreement to 830929 & incorporating administrative changes re billing, to "Environ Agreements & EIS for Low Level Waste Disposal Facilities " # Envirosphere Co HAGAN.TF Division of Contracts NRC-02-89-026-09 82/10/05 2pp 15859 037
- 8210280310 Notification of contract execution Mod 2 to "Environ Assessments & EIS for Low Level Waste Disposal Facilities" Contractor Engineering-Science, Inc ELECNOR, C M Technical Assistance Contracta Branch RRC-02-82-026-08 82/10/05 DAVIS, J, PANOBURN, O Office of Nuclear Material Safety & Safeguards, Director ip 15859 039
- --B2i0280319 Mod 2. extending period of agreement to B90929 & incorporating administrative changes re billing, to "Environ Assessments & E18 for Low Level Waste Disposal Facilities " & Engineering Science HA9AN TF Division of Contracts NRC-02-B2-026-0B 82/10/05 2pp 15859 040
- 8210280327 Notification of contract execution, Hod 2 to "Environ Assessments & EIB for Low Level Maste Disposal Pacilities" Contractor Waste Hpt Group, Inc FLEENOR, C M Technical Assistance Contracts Branch NRC-02-82-026-06 82/10/05 DAVIS, J , PANGBURN, Q Office of Nuclear Material Safety & Safeguards, Director 1p 15859 122
- --9210280331 Mod 2, extending period of agreement to 830929 & incorporating administrative changes re billing, to "Environ Assessments & E18 for Low Level Waste Disposal Facilities " & Maste Management Group. Inc HAQAN, T F Division of Contracts NRC-02-82-024-04, 82/10/03 Rpp 15859 123
- 8210280354 Notification of contract execution, Mod 2 to "Environ Assessments & EIB for Low Level Waste Disposal Facilities" Contractor Kaman Tempo FLEENOR, CM Technical Assistance Contracts Branch NRC-02-82-026-05 82/10/05. DAVIB.J. PANOBURN, Q Office of Nuclear Material Safety & Safeguards, Director 1p 15839-197
- --8210280335 Mod 2.extending period of agreement to 830929 & interparating administrative changes re billing, to "Environ Assessments & EIS for Low Level Waste Disposal Facilities " \* Kawan Tempo HAGAN.T.F. Division of Contracts NRC-02-82-026-05 82/10/05. 2pp 15859 178
- 8210280370 Notification of contract execution "Monitoring Use of Equipment Purchased by NRC Under Contract NRC-04-74-187." awarded to GARD. Inc MCDERMOTT, D Research Contracts Branch NRC-04-82-023, 82/10/07 BATSON, W. MUSGARA, U. Office of Nuclear Regulatory Research, Director ip 15857-228.
- --8210280374 Contract "Monitoring Use of Equipment Purchased by NRC Under Contract NRC-04-74-187." awarded to OARD, Inc SAIGH/P A Gard, Inc MORTON, K. V Research Contracts Branch, NRC-04-82-023 82/10/07. 7pp. 15857 229
- 8210280384 Notification of contract execution, Mod 1 to "Establish Collaborative Program Batusen State & Commission to Provide Independent Measurements of Radioactivity in Effluents & Environ " Contractor CT Dept of Environ Protection SICVIS,R M. Administrative Contracts Brench. NRC-05-73-011. 82/10/15 COBB-L.1. ROSE.H Director's Office of Inspection and Enforcement. 1p 13859:236

- --8210280397 Mod 1, dechligating funds, to "Establish Collaborative Program Between State & Commission to Provide Independent Measurements of Redicativity in Effluents & Environ Around Selected Commissioned Licensed Activities "
  HEUBNER, A.T. Connecticut, State of GUSTAVE, R.P. Research Contracts Branch NRC-05-73-011 82/10/15 ip 15859-237
- 8210270104 Notification of contract execution, Mod 1, to "Use of PA Fish & Wildlife Date Base Sys in Environ Analyses for Nuclear Power Plant Licensing " Contractor Commonwealth of PA HOVLE, A Administrative Contracts Branch FIN B-8912 NRG-25-82-323 82/10/18 BASBETT, HS, JOHNSON, C Division of Data Automation & Management Information 1p 15866-336
- --8210290131 Mod 1, adding statement that data base training will be conducted at game commission. Harrisburg & deleting Reporting Requirement 2, to "Use of PA Fish & Wildlife Data Base Bys in Environ Analyses for Nuclear Power Plant Licensing" REBELLO, J E Pennsylvania, State of \* Administrative Contrarts Branch FIN B-8812 NRC-25-82-323 82/10/18 1p 15866 337
- 8210290396 Notification of contract execution "Safety Aspects of Industrial Radiography Course," awarded to Gamma Industries COLEMAN R Administrative Contracts Branch NRC-05-82-251 82/09/28 BLAHA, J. L. HASSELBERG, R. Program Support Branch 19866 054
- --8210290398 Contract "Bafety Aspects of Industrial Radiography Course." awarded to Gamma Industries \* Nuclear Bystem SKITH.P A Administrative Contracts Branch NRC-05-82-251 82/09/28 28pp 15866 055
- 821029042D Natification of contract execution, Mod 3 to "Hydrologic Engineering Consulting Svcs for Site Bafety Reviews" Contractor Haria Engineering Co HCLEREN, T Technical Assistance Contracts Branch FIN B-1123 NRC-03-74-308 B2/10/09 DENTON, HR Office of Nuclear Reactor Regulation, Director ip 15863 239
- --B210290422 Mod 3.deobligating unliquidated balance of contract funds, to "Hydrologic Engineering Consulting Sycs for Site Safety Reviews"

  4 Harra Engineering Co HAQAN.T F Division of Contracts FIN B-1123 NRC-03-76-308 B2/10/08 ip 15843 240

# FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES

- 8204060002 Appeals denial of FOIA request for segregable portions of draft NUREO-GB44. "Resolution of Unresolved Bafety Issues A-3.A-4 & A-5 Re Bisam Generator Tube Integrity UDELLIR A Critical Mass Energy Project 82/06/04 DIRCKS.W J Office of the Executive Director for Operations 2pp 15668 333
- 9207050075 FOIA request for seven categories of documents re Dow Chemical Co & incineration of low level radwaste HILBON, A K Affiliation Unknown 82/07/01 MALLETY Region 3, Office of Director ip 15748 COL
- 8207110026 FOIA request for documents re St Joseph Hosp in 'NM & I-128 seed incident DAVISL S. Richards. Brandt, Miller & Nelson 82/07/1 NUSSBAUMERD A Assistant Director for State Agreement Ip 15894 00!

- B207180060 F01A request for documents re NRC shutdown plan mentioned in weekly info rept for wk ending 910828 & SECY 81-600 & SECY 81-600A
  - CONNOR.L Doc-Search Associates 82/08/31 Records 1p 15758 311 Division of Rules and
- 8207180051 FOIA request for documents re pre-implementation review of NUREO-0737. Item II F 2 CONNOR. L. Doc-Search Associates 82/09/01 Division of Rules at Records Ip 15667 076 Division of Rules and
- 8207180064 FOIA request for "Initial Guidance for Performance of Sys Interaction Analysis at Selected LURs" & "Initial Guidance on Diagraph-Matrix Analysis for Sys Interaction Studies at Selected LARS "
  FABRIZIO, R F Boston Edison Co 92/08/30 Division of Rules and

15859 117 Records 1p

- 8208290088 FOIA request for SECY 82-419 re use of nonplant-specific 2082Y008B FULL request for SELY B2-14 re use of nonplantas simulators for initial replacement & requalification exams for licensed reactor operators & senior operators ARMSTRONG,X A Debevoise & Liberman 62/08/29 FELTON,J Division of Rules and Records tp 15760 177 PRZOBZZO FELTON J M
- 820829089 FOIA request for records to disposal of radwasto & chemical & medical wastes at St Albans Hosp in Obsens.NY FREEDERG, Vouth News 82/09/07 Division of Rules and Records ip 15774 313
- B20B290098 FOIA request for all declassified matl on Manhattan Project CHAIXEN, J.A. Affiliation Unknown B2/09/10 Division of Hules and Records ip 15636 205
- 8208270105 FOIA request for info re each NRC licensee in States of PA. PREDLAND.D R Affiliation Unknown 82/09/15 Administration 1p 15646 006
- 820829010B FOIA request for RFP RS-OIE-82-251 "Safety Aspects of goardino ruim request for APP AS-01E-82-201 " Industrial Radiography Course" & related info WILLIAMS D.T. Affiliation Unknown 82/10/01 Contracts ip 15877 071
- 8209180056 FOIA request for lists of names & addresses of all NRC Dicenses in ME.VT.MA.OH.CT & WV & appropriate afcs in Agreement States of NH.RI.NY & MD PARKINSON.T W Interstate Nuclear Services 02/07/29 FELTON. 82/07/27 FELTON, J Davision of Rules and Records ip 15843 310
- 8209150057 f01A request for NRC Annual Rept to Congress for 1981 SCHULKE.S Affiliation Unknown 82/09/25 FELTON.J.M Division of Rules and Records ip 15758 309
- 8209290168 Responds to FOIA request for documents prepared by NRC staff & consultants on 10CFR50, App B re GA audits of testing racilities conducted within past tO yrs by NRC Related documents listed FELTON, J.M. Division of Rules and Records 82/08/26 PHILIPS, M.H. Debevoise & Liberman Rep. 15564-002
- --8209290236 Forwards GA Program Insp Rept 99900905/82-01 on 811229-30 No noncompliance noted HEISHMAN, R F Reactor Construction Branch 82/05/26 Washington Public Power Supply System 29p 15564 060

- -- B005270B22 Discusses shortcomings in NUREG-0572, "Review of LERs (1974-1978) 18707 000
- --8006300104 Forwards BL Cohen B00324 ltr & study re design adequacy of refueling water storage tank Requests views FRALEY, R F ACRB Advisory Committee on Reactor Sefeguards 80/04/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 15727 104
- --8010240413 Submits evaluation of NUREO-0667. "Transient Response of Bl Designed Reactors " Recommends related studies be combined & specified Priority 2 items implemented by expanding an existing task in TMI action plan MATTBONR Division of Safety Technology 80/08/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 43pp 15727 199
- --B010240496 Forwards analysis & recommendations re plants w/o seismimi qualified auxiliary feedwater sys Concludes that shutdown of non-seismically qualified sys would not significantly reduce risk & proposes that more detailed study be initiated MATTBOLM R Division of Safety Technology 80/08/08 EISENNUT.D O Division of Licensing 19pp 15727 241
- --8103030076 Forwards revision to evaluation of automatic air header de on BNRs transmitted in 801208 memo Revision restructures analysis supporting proposed change to BWR scram discharge

ERNSY, M L Assistant Director for Technology Review 80/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 15727 307

- ---8103050756 Forwards as part of NUREO--0651 review.cost benefit amakya of radiation detectors on main steam lines to provide added diagnostic capability for PWR operator during steam generator tube rupture
  LOBEL,R., VANDERHOLEN,H Safety Program Evaluation Branch
  BO/12/15 BAER,R Safety Program Evaluation Branch
  10pp
- --8103060088 Comments on proposed change to STS re battery sys per LLO1 OSD6008B Comments on proposed change to 818 re eattery sys not request for review Operating plants using battery sys not covered by 878 should submit for approval equivalent surveillance program Proposed ST6 & 801230 memo encl ERNST.M L Assistant Director for Technology Review (il) SCHROEDER: Assistant Director for Generic Projects in 017017011
- --Bi03240272 Forwards summary of Bi012B operating reactor events wert Next meeting scheduled Bi0204 LAINA9.0 C Assistant Director for Bafety Assessment Bi/O///(A EIBENHUT, D 0 Division of Licensing App 13728,000
- --8103310127 Bummary of 810226 operating reactor events meeting me ex which occurred since last meeting Next meeting scheduled for Biogil for Blod:: LAINAB.G C Assistant Director for Bafety Assessment EIBENHUT.D.G Division of Licensing App. 1572B 255
- ---B104240059 Discusses reactor coolant pump seal failure, in response 800612 memo Issue will be considered potential unresolved safety issue Potential failure during station blackout may be taken up under Task Action Plan A-44 MURLEY.T E Division of Safety Technology, 81/03/27 EISENHUT.D 0 Division of Licensing 13pp 15728 336
- --- B104290103 Discusses IE daily rept for B10406 re alternate office to OAZYOTOS DISCUSSES IE CALLY rept for GLOVOUS PE ATTENDED OF SECTION TO THE PLAN WERE PERCENT OF SECTION TO THE PROPERTY OF SECTION OF SAFETY SYS CHIRAMALM Director's Office, 81/04/21 Director's Offi
- --8105110396 Forwards findings & recommendations for J Elin 910 tts ; re requirements of preferred or offsite power sys ABHE, F. Director's Office: 81/04/29 MICHELBON.C Director ... 0ffice 4pp 19729 070
- --BiOAiOO3A2 Comments on problem of flow blockage of cooling water by asiatic clams (ref IE Bulletin 81-03). Problem considered by asiatic clams (ref in Bulletin 01-03. From a consister potentially serious common mode failure, Quidance for proposed stepwise investigation provided BARR, R. L. Barety Program Evaluation Branch IEB-81-03 BirD MURLEY.T.E Division of Safety Technology 3pp 15729 166
- --B107070220 Discusses Ofc of Nuclear Regulatory Research comments supporting conclusions of Mar 1981 oft rept re safely concerns associated w/pigs breaks in PWR scram ays Shortcomings of analysis listed ORNSTEIN H L. Director's Office CF Director's Office 3pp 15729.205 CF-354 81/06/11 HICHEL MA

### NONDOCKETED HEIVIS

- --BL07090355 Forwards Nuclear Safety Analysis Ctr/INPO rept, "Significant Event Evaluation & Info Network" & background info re review of sresning & preliminary evaluation program for comment HICHRLSON, C. Director's Office CF-337 81/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 15pp 15729 222
- --B1671603B6 Provides info as discussed at ACRS B10507 meeting re-control sys failures that could cause or accelerate nuclear power facility accidents Comments from plant sys unit encl ASME.F Director's Office AEOD/Eii4 B1/06/24 MICMELBON, C Director's Office Spp 15729 251
- ~~BIOBOGOC41 Discusses prioritization of new requirements for PWR feedwater line cracks Remedial measures development should be responsibility of industry w/approval of design changes responsibility of NRR ERNST. N L Bafety Program Evaluation Branch 81/06/30 MURLEY. T E Division of Bafety Technology 26pp 15729 290
- --310B180604 Discusses review of LERs re setpoint drift occurrences for Barton Model 288 instrument Provides recommendations for MRR ASHE,F Director's Office 81/07/20 MICHELSON,C Director's Office 2pp 15730-054
  - 3108240273 Forwards marked-up draft Commission paper re integrated operational experience reporting sys for concurrence Draft advance notice of proposed rulemaking & Congressional litrs and
  - ent. MJCHELSON.C. Director's Office 81/07/15 DENTON.H R Office of Nuclear Reactor Regulation, Director 14pp 15730 007
  - BIO8270056 Forwards concurrence on NUREO-0803, "Generic Safety Evaluation re Integrity of BWR Scram Gys Piping " Any significant changes will be provided for consideration HICHELSON, C Director's Office 81/07/30 EISENHUT.D O Division of Licensing 3pp 15730 083
  - 8109100077 Advises that review of proposed draft supplied IE Bulletin 81-02, "Failure of Gate Type Valves to Close Against Differential Pressure," yielded no substantive comments HELTERIES, C. J. Director's Defice IED-01-02 81/08/06 JORDAN, E. L. Division of Resident & Regional Reactor Inspection 1s 18730 106
  - 8109220915 Recommends memo be prepared requesting Off of Nuclear Regulatory Research to initiate preparation of proposed rule thange on high priority basis for Gomeral Design Criteria 4 MCRLEY, TE Division of Easiety Technology 81/08/26 VOLLMER, R H Division of Engineering 2pp 15731 031
  - -8107240007 Comments on NUREG/CR-1659 Vol 2, "Reactor Bafety Study Mathodology Application Program Quante 3 PWR Power Plant "DENNING, R L Director's Office 81/09/15 Director's Office 2pp 45589\*237
  - -Bi09250504 Comments on proposed IE circular re borque switch jumpers for safeguards syc motors More appropriate title could be "Torque Bwitch Jumpers for Bafeguards Byc Valve Motor Control Circuits" Marked-up circular encl HICHCEBONG Director's Office BI/08/28 JORDAN, E L Director's Office 4pp 15730-142
  - -Bii0010072 Comments on J Austin 810306 note re purge & vent valve assembly operability during expected accident conditions & potential problems should valve closure be delayed BROWNE J Director's Office 4pp 15730 273
  - --8110190928 Discusses 810625 memo re approach to sys interactions in LMS: No comments were developed which would need to be assimilated into interfa guidance Author ofc will offer assistance w/use of sequence coding & search procedure HICHELBON, C Director's Office. 81/09/02 MURLEY, T E Division of Safety Technology ip 15780 202
  - --Rii0890933 Forwards background statement & discussion of process & policies established for Ofc of Analysis & Evaluation of Berational Data repts. Future repts sent for paer review will be complete & include conclusions & recommendations HICHLEON, C Director's Office 81/09/02. DAVIB.J O Office of Nuclear Material Safety & Rafeguards, Director, 3pp 15730 199
  - --8i10220004 Forwards summary of activities re PWR primary sys voids.
    Initiated by Ofc for Analysis & Evaluation of Operational
    Data
    BIRCKB.W J Office of the Executive Director for Operations
    86/09/30 PALLADINO:N Commissioners 2pp 15730; 290.

- --Bii1030201 Responds to inquiry into status of BWR scram discharge volpips break safety concerns NUREO-0803 contains guidance for resolving outstanding issues on plant by plant basis RUBIN,S D Director's Office 81/10/02 LEWIS,M I Affiliation Unknown ip 15730 336
- --Billo60130 Forwards draft proposed rule & reg guide to new LER sys.for review Comments should indicate whether improved sys will meet needs for operational safety data MICHELSON,C Director's Office 81/10/06 DENTON,H R Office of Nuclear Reactor Regulation, Director 24pp 15730 337
- --Billi6030B Responds to Bi0B2B memo re draft rept, "Compressed Air & Backup Nitrogen Sys in Nuclear Power Plants " Forwards comments re areas where addl work is suggested prior to final publication HELTEMES, C J Director's Office Bi/10/07 ERNST, M L Assistant Director for Technology Review 3pp 15730 361
- --BiiiiBOOOi Recommends comprehensive assessment of plant operating conditions to determine specific predetermined time related sequences of occurrence to emergency buses SRP should be revised re design features
  ABHE.F Director's Office Bi/10/16 MICHELSON.C Director's Office 4pp 15731 049 24% Fiche 50-000.62/06/28.82100100008
- --8111240712 Requests Div of Sys Integration review SER section on leak rate & leak rate detection criteria Conclusions should be limited to subj plants but general comments would be appreciated HURLEY.TE Division of Safety Technology 81/10/09 MATEON.R J Division of Systems Integration (post 811005) 3pp
- --Bii2020725 Comments on draft CRNL Bi0930 rept, "Evaluation of Events Involving Byc Water Sys in Nuclear Power Plants," per Bil020 request Beveral recommendations made w/o sufficient Justification to ment serious consideration MICHELSON.C Director's Office Bi/11/10 MINNERS,# Safety Program Evaluation Branch Ip 1573; 117
- --Bil2030585 Provides info re better means of coordinating & reducing duplication in acreening LERs & evaluation efforts Supporting info encl ERNBT.M L Division of Safety Technology 81/11/09 HELTEMES.C J Director's Office Spp 15731 107
- --Bil2100374 Forwards summary of NRR.NMSB & IE actions resulting from Ofc of Analysis of Evaluation & Operational Data activities, in response to recommendations contained in case studies & engineering evaluations
  LANNINO, W Director's Office 81/11/12 MICHELSON, C Director's Office 4pp 19731 iiB
- ~8112210166 Recommends that proposed LER rule including existing & proposed reporting requirements & coordination plan be sent to Commission for consideration Stello, V. Regional Operations & Generic Requirements 81/11/24 DIRCKB, W. J. Office of the Executive Director for Operations 1, 1272 005.
- --8112210193 Requests assistance of Ofc of Nuclear Regulatory Research to complete editorial & administrative activities necessary to issue encl draft reg guide HICHELBONG Director's Office 81/11/17 HINGOUE, R B Office of Nuclear Regulatory Research, Director ip 15731 202,
- --B201060003 Comments on NRC svaluation of MCAP-9558 & MCAP-9787, re excluding asymmetric blowdown loads in plant design based on lask-before-break acceptance criteria Safety evaluation using subj basis will require regulation changes ERNBT.H L. Assistant Director for Technology Review B1/ JCHNSTON.W V Assistant Director for Materials & Qualif Engineering 21pp. 15731 315
- ---B201130322 Provides background info re FIN B--0445, "Analy Reliability Data From Nuclear Power Plants " Review of B11113 in-plant data program (FIN B-0445) progress revi meeting enci DENNINGR L Director's Office FIN B-0445 81/12/02 MICHELSON, C Director's Office Spp 15731:336
- --8201150003 Forwards Chairmen Palladino & Aksarne 811110 & Commission briefing on NRC program for reactor operatio experience evaluation.
  HELTEMES, C. J. Director's Office, 81/11/25 BERNERO, R Nuclear Regulatory Research, Director 1p. 15731 309.

į

1 ,

1,

- --8201150004 Responds to 811105 memo re functions of Ofc for Analysis & Evaluation of Operational Data Commission briefing should cover NRC program for reactor operational experience evaluation PALLADINO, N. J. Commissioners 81/11/10 AHEARNE, J. Commissioners 1p 13731-310
- --B201150005 Suggests Commission be briefed on current & projected distribution of Ofc of Analysis & Evaluation of Operational Data resources thru FY84 AHEARIELU Commissioners 81/11/05 PALLADING N J Commissioners 4pp 15731 311
- --8201190040 Forwards INPO 811110 ltr commenting on draft proposed rule to modify & codify existing LER reporting requirements Comment I should be considered during review of reporting requirements MICHELSON C Director's Office 81/12/11 DEYOUNG, R C Director's Office of Inspection and Enforcement 1p 15732 015
- --820119004! Comments on draft rule.10CFR50 73 re LER sys Rule would significantly reduce number of LERs filed Only significant events would be reported ZEBROSKI.E L Institute of Nuclear Power Operations B-B1-0.306 B1/11/10 MICHELSON.C Director's Office 60pp 15732 016
- --8201190296 Concurs w/procedures for developing NRC research program, in response to NRC 811112 memo Requests that all research projects collection, storage analysis or evaluation of operational safety data be sent for review & concurrence MICHELSON. C Director's Office 81/11/24 BASETT, HS Office of Management and Program Analysis 1p 15731 246
- --8201270037 Endorses Committee to Review Generic Requirements recommendation that appropriate ofts coordinate outline of reporting requirements interrelated widraft proposed LER rule Identifies documents he reporting requirements DIRCKS,W J. Office of the Executive Director for Operations 81/12/08 DAVIS,J G. Office of Nuclear Material Safety & Safeguards, Director 2pp. 15732 003
- 8202020441 "Evaluation of Events Involving Svc Water Sys in Nuclear Power Plants," draft HARIED.J A Clark Ridge National Laboratory FIN B-0755 B2/01/31 47pp 15732 107
- --8202030092 Forwards proposed Commission paper requesting approval of proposed rule which would modify & codify existing LER sys MICHELSON, C. Director's Office 81/12/30 DIRCKS, W. J. Office of the Executive Director for Operations | Ip 15732-104
- --B203120016 Discusses repetitive failures of emergency feedwater flow value as reported in LERs due to valve operator hydraulic problems LERs encl
  IMBRO.E V Director's Office AEOD/E211 B2/02/24 MICHELSON.C
  Director's Office 76pp 15732 308 24X Fiche 50-000.B2/06/78,
  B210010008
- --8203160383 ORNL/NSIC-208
  "Evaluation of Events Involving Unplanned Boron Dilutions in Nuclear Power Plants"
  MAGEN.E W Clak Ridge National Laboratory FIN 8-0755 82/03/31
  Office of Nuclear Reactor Regulation, Director 37pp 15733 017
- --B203170060 Requests that review be conducted on missile protection of safety-related sys at plants to assure adequate protection analyse homerator rotor retaining rings as missiles Director's Office AEOD/E207 82/02/23 Director's Office 15pp 15745 054

~204

t Removal Sys in

0755 **02/**03/31 101pp

> ator t

> > r I

- --B2040B0171 Forwards "Recommendations for Improving NRC Incident
  Response Technical Assessment Capability "Recommendations
  consistent w/NRC B20104 1tr re NUREO-0845 List of
  recommendations enci
  MINNERS.W Safety Program Evaluation Branch B2/03/04
  DENYON,H R Office of Nuclear Reactor Regulation, Director
  DEYOUND.R C Director's Office. Office of Inspection and
  Enforcement 3pp 15733 274
- ---B2040B0260 "Recommendations for Improving NRC Incident Response Technical Assessment Capability " CONGEL.F Office of Nuclear Reactor Regulation. Director B2/02/2B 77pp 15733 297
- --8204270464 Submits engineering evaluation re-potential for air binerg or degraded performance of BWR RHR sys pumps during LOCA recirculation phase Air bubble generation will not adversely affect RHR pump performance Oas release calculations end RUBIN-S Director's Office AEOD/E218 82/03/31 MICHEL 60M.C Director's Office Bpp 15745 103
- --B205070377 Advises that proposed circular, "Contamination of Air Serving Safety-Related Equipment," reviewed Fallowup to It Notice BI-38 or IE bulletin should be sent requesting info assessment of plant air supply sys CRNSTEIN.H L Director's Office AEOD/E219 82/04/01 MICHELSON.C Director's Office 2pp 15745 263
- --8210010061 Forwards review of B&W itr rept on effect of fuel rod bowing on DNBR Proposed method acceptable for licensing calculations GRIMES D K Division of Operating Reactors 79/07/25 VARGA & Assistant Director for Light Water Reactors 6pp 1932 D.O.
- --8210010065 Notification of ACRS LER Subcommittee 800422 meeting in Mashington, DC Schedule & background info encl BATES, A ACRS - Advisory Committee on Reactor Safeguards 80/04/14 MOELLER, D. MATHIS, W. CATTON, I ACRS - Advisory Committee on Reactor Safeguards 3pp 19727 078
- --8210010067 Outlines INPO & Ofc for Analysis & Evaluation of Operation Data 800311 & 20 reviews of nuclear plant operating data Related info encl YOUNG, 0 O ACRS Advisory Committee on Reactor Safeguards 80/03/26 ACRS Advisory Committee on Reactor Gafeguards App 15727 081
- --0210010068 "Status Rept.Ofc for Analysis & Evaluation of Uperational Data"
  MICHELSON, C Director's Office 80/03/20 10pp 15/4/ 08/
- --8210010073 Advises that ACRS 800422 meeting w/LER Bubcommitter & FAPT will include discussion of status organization & planned activities of Ofc for Analysis & Evaluation of Operational Data & NRC program for collection of data MICHELBON, C Director's Office 80/03/21 BERNERO, R Probabilistic Analysis Btaff (Pre 801117) CARTER, T F Division of Fuel Cycle & Material Safety EISENHUT, D O Division of Operating Reactors 2pp 15727 101
- --8210010074 Confirms telcon re 800422 presentation on INPO w/AIR'S telegraphic subcommittee Member requested to make presentation on status of organization & plans for future activities re use & evaluation of operational data from nuclear plants BATES. A ACRS Advisory Committee on Reactor Safeguards 80/04/14 LAVALLEE.W Electric Power Research Institute to 15727 103
- --8210010089 Discusses failures of HPCI & RCIC sys subsequent to /fr/& event culminating in 790627 loss of both sys BOEHNERT, P ACRS Advisory Committee on Reactor Sefaguards 79/09/06 KERR, W ACRS Advisory Committee on Reactor Sefaguards 2pp 15727 142 24X Fiche 50-0000, 82/06/28.
- --8210010119 Discusses problems w/LER data reporting & recording sys-Form is not designed for subsequent use of data for statistical analyses Draft notes encl HDELLER.D M Harvard Univ 80/07/01 BATES, A L. ACRS -- Advisor Committee on Reactor Safeguards 8pp 15727-146
- --9210010161 Discusses potential problem re sequoyah reactor pressur; norsle-supplementing 800222 memo Underclad cracks found by use of ultrasonic equipment, Addl Items of recent origin discussed Related info encl
  DENTON: H R Office of Nuclear Reactor Regulation, Director 80/02/28 AHEARNE. J Commissioners 9pp 15727 178 24% Fichs 50-000, 82/04/28, 8210010008

- --B21C010169 Discusses evaluation of applicability of proposed new requirement of Class IE station batteries Div of Licensing should retain responsibility for further exploration of matter in course of licensing reviews MATISON.R J Division of Systems Safety 80/02/28 EISENHUT.D G Division of Licensing 2pp 15727 187
- --B210010172 Forwards comments on NRC LER sys W/o and BATES.A NRC - No Detailed Affiliation Given B0/07/22 MICHELSON.C Director's Office HALLER.N Office of Management and Program Analysis ip 15727 189
- --B210040368 Discusses NRC procedures for reviewing LERs, in response to request during 245th ACRS meeting on B00904-04 Reporting requirements require reviston to eliminate unneeded matl BATES. A ACRS Advisory Committee on Reactor Safeguards 80/09/23 ACRS Advisory Committee on Reactor Safeguards 3pp 15727 266
- --R210040371 Responds to B00523 request re action by Ofc for Analysis & Evaluation of Operational Data on two specific LERs Ofc currently working on more significant safety areas BATES. A NRC No Detailed Affiliation Given B0/07/23 BENDER.M NRC No Detailed Affiliation Given 1p 15727 271
- --8210040379 Submits review of IE insps of operating PWRs related to followup actions identified in NUREC-0138 Sensitivity analyses recommended BUTLER, W B Plant Systems Branch 77/12/28 EISENHUT, D G Division of Operating Reactors 12pp 15727 285
- --B2100403B: Netification of ACRS LER Bubcommittee 801120 meeting in Mashington: DC to discuss progress toward improving NRC use of operational data BATES. A NRC - No Detailed Affiliation Given 80/11/10 MATHIS, W. LAMROSKI: S. RAY, J. NRC - No Detailed Affiliation Given 1p 15727 304
- --B2100403B3 Notification of ACRS LER Subcommittee 801120 meeting in Hashington DC Schedule encl BATES.A NRC - No Detailed Affiliation Given B0/11/10 HIGHELSON.C Director's Office 2pp 15727 305
- --8210040376 Submits evaluation of recommendations contained in NURLG-O651. "Evaluation of Steam Generator Tube Rupture Events " Licensees should investigate other techniques to more rapidly determine damage BAER, R L Safety Program Evaluation Branch 81/02/17 MURLEY, T Division of Safety Technology 26pp 19788-007
- --B210040411 Summary of B10311 operating reactor events meeting Assignment of followup review responsibility discussed Related info encl LAIMAS.0 C Assistant Director for Bafety Assessment 81/03/13 ETSENHULD Q Division of Licensing 5pp 15728 263
- --8210040416 Summary of 810318 operating reactor events meeting LAINAS.O C. Assistant Director for Bafety Assessment 81/03/24 EISENHUT.D G Division of Licensing 4pp 15728 328
- --8210040421 Summary of 810325 operating reactor events meeting LAINAS.Q C Assistant Director for Bafety Assessment B1/03/26 EISENHUT.D Q Division of Licensing App 19728 332
- --8210050006 Forwards draft rept, "Potential for Water Hammer During Restart of RHR Pumps for BHR Nuclear Plants " HUANO,Y 8 Director's Office 81/03/31 MICHELSON.C Director's Office ip 15729 008
- ~-8210050007 "Potential for Nater Hammer During Restart of RHR Pumps for BHR Nuclear Plants" NUANGJ Director's Office 81/03/31 14pp 15729 009
- ~-B210050010 Forwards preliminary rept, "Initial Consideration of Potential for Water Hammer in Bteam Condensing Mode of RHR Sys Operation for BMR Nuclear Plants" HUNNOY B Director's Office. B1/03/31 MICHELSON.C Director's Office ip 15729 023.
- --8210050011 "Initial Consideration of Potential for Water Hammer in Steam Condensing Mode of RHR Bys Operation for BWR Nuclear Plants" HUNNO,J Director's Office 81/03/31, 11pp 15729 024
- --8210050021 Summary of 910408 operating reactor events meeting LAHAB.0 C. Assistant Director for Safety Assessment 81/04/15 EIBENHUT,D Q. Division of Licensing 4pp 15729 035 24 X Fichs 50-000:82/04/28.8210010008

- --B210050031 Speech entitled "Assessment of Operational Safety Data in NRC" presented at 810427-29 Fourth Symposium on Training of Nuclear Facility Personnel in Gatlinburg, TN HICHELSON, C. HELTEMES, C.J. Director's Office 81/04/27 44pp 15729 046
- ~-0210050035 Summary of 010422 operating reactor events meeting Related info encl LAINAS.Q C Assistant Director for Safety Assessment 01/04/29 EISENHUT.D Q Division of Licensing 10pp 15729 074
- ~-8210050038 "Power Reactor Events, Jan-Feb 1981," Vol 3, Number 2 MASSARO, S A Director's Office 81/05/31 16pp 15729 084
- --8210050064 Summary of 910506 operating reactor events meeting LAINAS.G C Assistant Director for Safety Assessment B1/05/1/2
  E[SENHUT.D G Division of Licensing 9pp 15729 151
- --8210050075 Summary of 810513 operating reactor events meeting LAINAS,O C Assistant Director for Safety Assessment 81/05/18 EISENHUT.D G Assistant Director for Licensing 6pp 15729 860
- --8210050082 Forwards IE Bulletin Bi-O3, "Flow Biockage of Cooling Water to Safety Sys Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel)," for issuance on BiO410 SNIEZEM, Jf Division of Resident & Regional Reactor Inspection Si/O4/OB GRIER,D H Region i, Philadelphia, Office of the Director (81/O3/O1) O'REILLY, J P Region 2, Atlanta, Office of the Director (81/O3/O1) KEPPLER,J G Region 3, Chicago, Office of the Director (81/O3/O1)
- --82(0050087 Summary of 810520 operating reactor events meeting LAINAS, G C Assistant Director for Safety Assessment 81/05/2/ EISENHUT, D G Division of Licensing 7pp 15729 189
- --B210050093 Bummary of 810603 operating reactor events meeting LAINAS,0 C Assistant Director for Bafety Assessment 81/06/09 EISENHUT.D 0 Division of Licensing 7pp 15729 196 24X Fich & 50-000,82/06/28.8210010008
- --B210050116 Forwards comments & questions re GE response to Ofc for Analysis & Evaluation of Operational Data safety concerns w/ pipe breaks in BMR scram sys, in response to D Eisenhut 810603 request MICHELBONG Director's Office 81/06/14 DENTON-N R Office of Nuclear Reactor Regulation, Director 2pp 15729 203
- --B210050124 Bummary of B10410 operating reactor dvents meeting LAINAB.0 C Assistant Director for Safety Assessment 81/06/1/ EISENHUT.D O Division of Licensing 5pp 19727 217 24X Fiche 50-000, B2/06/28. B210010008
- --8210050135 Summary of 810617 operating reactor events meeting LAINAB.0 C Assistant Director for Safety Assessment 81704/23 EISENHUT D 0 Division of Licensing 4pp 15729 244 247 Fichs 50-000.82/06/28.8210010008
- --8210050155 Forwards summary of NUREG/CR-1682, "Electrical ref Insulators in Reactor Accident Environ." Used as ref in Ofc of Nuclear Regulatory Research comments on safety concerns re pipe breaks in BMR scram sys EL-ZEFTAHY. M Director's Office 81/06/26 Director's Office 5pp. 15727 285
- --8210050164 Summary of 810708 operating reactor events meeting Noxt meeting scheduled on 810715 LAINAS,0 C Assistant Director for Safety Assessment B1/0//13 E18ENBUT,D Q Division of Licensing Spg 15727 355 247 Ficha 50-000,82/04/28,8210010008
- --8210050181 Discusses plans for managing NRPDS per 810708 telcon Data & repts from data base will continue to be made available to NRC Mesting scheduled on 810721
  HILKINSON.E P Institute of Nuclear Power Operations 81/07/09
  DIRCKS.W J Office of the Executive Director for Operations 5pp
- --8210050190 Summary of Bi0723 operating reactor events meeting Next meeting scheduled for B10805 LAINAB.0 C Assistant Director for Safety Assessment B1/07/29 E18ENUT,D 0 Division of Licensing Spp 15730 075 24X Fichs 50-000,82/06/28,8210010008
- --8210050200 "Power Reactor Events, Mar-Apr 1981, " Vol 3, Number 3 MASBARO, 8 A Director's Défice 81/08/31 18pp 15730 086
- --8210050209 "Operational Safety Data Review," Chapter 0515 4 Director's Office. 81/08/12 8pp 15730 107

- --8210050212 Summary of 810806 operating reactor events meeting Related info enc. Next meeting scheduled for 820812 LAINAS, 0 C. Assistant Director for Safety Assessment Bi/08/10 EISENHUT: 0 Division of Licensing 16pp 15730 115 24X Fiche 50-000.82/06/28.8210010008
- --8210050217 Summary of B10819 operating reactor events meeting Status of followop review responsibility assignments enti LAINAS.OC Assistant Director for Safety Assessment 81/08/24 EISEMIUT.D O Division of Licensing 5pp 19730-123 24X Ficha 50-000.82/06/28.8210010008
- --B210050403 Forwards draft rept entitled "Characteristics of LEH Reporting Sys " RVDER,C ACRS - Advisory Committee on Reactor Safeguards 81/08/31 ACRS - Advisory Committee on Reactor Safeguards ip 15730 146
- --8210050407 Draft rept entitled "Characteristics of LER Reporting Sys" RYDER, C.P. ABBOTT. E.C., MCCRELESS, T.O. ACRS -- Advisory Committee on Reactor Safeguards 81/08/28 43pp 15730 147
- --B210050424 Advises that SECY B1-494 will be discussed at B10707 subcommittee meeting on evaluation of LERs QUITTECHREIBER ACRS Advisory Committee on Reactor Safeguards B1/07/02 MATHIS W, WARD, D, MOELLER, D, ACRS Advisory Committee on Reactor Safeguards 2pp 15730-203
- --8210050426 Provides presentation schedule for 810909 subcommittee meeting for evaluation of LERs QUITTSCHREIBER ACRS - Advisory Committee on Reactor Safeguards 81/09/02 MICHELSDN.C Birector's Office 3pp 15730 227
- --8210050434 Comments on LER Subcommittee 810909 meeting Ofc for Analysis & Evaluation of Operational Data could benefit from analytical models used in other fields & other stages of data analysis RYDER, C. ACRS Advisory Committee on Reactor Safeguards 81/09/11 MATHIS, W.M. ACRS Advisory Committee on Reactor Safeguards 2pp 19730 238
- --8210050436 Discusses methods for preventing recurrence of LERs Attention should be given to math suppliers & architect engineers as LER originators MOELLER, D.W. ACRS - Advisory Committee on Reactor Safeguards 81/09/06 MATHIB.W. ACRS - Advisory Committee on Reactor Safeguards ip 15730-240
- --B2100\$Q473 Forwards draft proposed rule re integrated operational experience reporting for comment MICHELSON, C. Director's Qffice 81/09/IB ROSSIN, D. Affiliation Unitown 7pp 15730 231
- --B210050478 Forwards SECY-B1-505 re systematic assessment of licensed performance, first rept on licensee assessments W/o encl contains facility ratings for operating power reactor licensees & CP holders

  MAJDR.R ACRS Advisory Committee on Reactor Safeguards
  81/09/21 ACRS Advisory Committee on Reactor Safeguards ip 15730 241

name of 810916 operating events meeting List of

ector for Safety Assessment 81/09/21 Licensing 9pp 18730 263

> Zudans comments on LER sys tee on Reactor Bafeguards Advisory Committee on Reactor

- --B210050496 Comments on LER reporting sys LER cover sheets contain misleading info re facility in question LERs should not be grouped in packets w/o appropriate sub, heading MDELLER,D W ACRB Advisory Committee on Reactor Safeguards 81/09/19 MAJOR,R ACRS Advisory Committee on Reactor Safeguards 19 15730 278
- --8210050500 "Power Reactor Events May June 1981," Vol 3, Number 4 MASSARO.S A , RIZZO, J Birector's Office 81/10/31. 14pp
- --B210050514 Topical rapt evaluations of Revision 2 to WCAP-955B,
  "Machanistic Fracture Evaluation of Reactor Coolant
  Pipe " & WCAP-9787, "Tensil & Toughness Properties of
  Primary Piping Weld Metal for Use in "
  \* NRC No Datailed Affiliation Given 82/04/28 24pp.
  15731 005

- --8210050520 Summary of 811007 operating reactor events meeting Status of previous assignments end LAINAS.9 C Assistant Director for Safety Assessment 81/10/13 EISENHUT.0 0 Division of Licensing 9pp 15731 033 24x Fiche 50-000,82/06/28,8210010008
- --8210050533 Summary of 811021 operating reactor events meeting list of attendees, events discussed & assignments encl LAINAS, 0 C. Assistant Director for Safety Assessment 81/10/29 EISENBUT, D. Q. Division of Licensing 6pp 15731 053 24% Fiche 80-000, 82/06/28.8210010008
- --8210050939 Discusses proposed rule dealing w/LER sys Features will include compatibility of sys w/10CFR50 72
  MAUGR.R ACRS Advisory Committee on Reactor Safeguards 81/11/02 MATHIS.W M ACRS Advisory Committee on Reactor Safeguards 19 19731 091
- --B210050542 Forwards info re selection of LERs worthy of AD rept gtatus MDELLER, D W ACRS - Advisory Committee on Reactor Bafeguards 81/10/24 MAJOR.R ACRS - Advisory Committee on Reactor Bafeguards 2pp 15731 092
- --8210060001 Summary of 811028 operating reactor events meeting first of attendees; events discussed & review assignments encl LAINAS, O C Assistant Director for Sefety Assessment BI/11/0 J ETERNHUT, D Q Division of Licensing 5pp 15731 074,
- ~-8210060005 Revised draft rept, "Compressed Air & Backup Nitrogen Sys Nuclear Power Plants" HAGEN,E W Clak Ridge National Laboratory. FIN 8-0795 W-7405-ENG-26 81/11/19 NRC - No Detailed Affiliation Given BOpp 1579\$ 122
- ~~B2100±000B Forwards background mat! for B1120B reactor operations subcommittee meeting on proposed rule & reg guide ro LER rulemaking MAJOR.R ACRS Advisory Committee on Reactor Safeguards B1/11/19 MATHIB.W M ACRS Advisory Committee on Reactor Safeguards ip 15791 205
- ~-8210050009 Draft Reg Guide i XXX.Revision 3, "LER Sys " \* NRC - No Detailed Affiliation Given 81/11/16 22pp 18731 215
- --8210060026 Discusses Zudans comments re ACRS LER subcommittes the Court meeting Change in connectivity function of sequence coding proposed Fundamental change involved MAJOR, R ACRB Advisory Committee on Reactor Safeguards B1/11/20 MATHIS W M ACRS Advisory Committee on Reactor Safeguards is 19731.237
- --B210060042 Bummary of B11112 operating reactor events meeting titt ; attendees, events discussed & review assignments encl
  LAINAB, G C Assistant Director for Safety Assessment B1/11/2; EIBENRUT.D G Division of Licensing 6pp 18731 240
- --8210060068 Discusses 811107 ltr re LERs & AD repts per 86CY 01 328 BECY 81-602 Meeting to discuss proposed LER rule scheduled for 811208. MAJOR.R. ACRS - Advisory Committee on Reactor Safeguards 81/11/24 MOELLER, D. W ACRS - Advisory Committee on Reactor Safeguards. 2pp 15731 247
- --8210060079 Requests info renotification of ACRB concerning propagation of significant avents per BECY 81-598
  MDELLER.D W. ACRS Advisory Committee on Reactor Bafeguards, 81/11/07. MAJOR.R ACRB Advisory Committee on Reactor Bafeguards ip. 18731 249
- --B2100600B4 "Background Reading for Discussion of Program & Methods Screening & Analysis of Operational Info at NRC," presented to IAEA Advisory Group on B11123-27. MICHELBON: C Director's Office 81/11/23 25pp 13731 284
- --8210060100 Summary of 811202 operating reactor events mesting 4 and attendees, events discussed & status of previous essignments entl.

  LAINAB.G C Assistant Director for Safety Assessment BI/12/Q.

  EISENHUI.D O. Division of Licensing. Spp 15731 345
- --8210060363 Summary of 811216 operating reactor events meeting that attenders; events discussed & status of masignments encl. LAXNAS.O C. Assistant Director for Safety Assessment #1/12/20 EISENHUT D. Q. Division of Licensing. 10pp 15732 081
- --8210060369 "Power Reactor Events, Jul-Aug 1981," Vol 3, Number 5
  MASSARD, 8 A., RIZZD, J. Director's Office. 82/01/31 14pp

### NONDOCKETED ITEMS

- --B230Cc0381 Discusses Zudans input re sequence coding & search sys, per 810930 memo implementation of approach would require major revision to sys HELLEMES.C J Director's Office 81/10/22 MAJOR, R ACRS --ASVisory Committee on Reactor Safeguards ip 15731 239
- --8210050427 Forwards comments re potential consequences of load drop in LMRs.providing understanding & background of scope of current regulatory review for accidents EL-ZEFTAMY. H Director's Office AEOD/E205 82/02/16 Director's Office 13pp 19732 281
- --8210060449 Responds to request for review of LERs on steam generator leaks Distribution of problems from 1976 to 1981 provided RYDER.C.P ACRS - Advisory Committee on Reactor Safeguards 82/03/05 MATHIB.W ACRS - Advisory Committee on Reactor Safeguards 3pp 15745 026
- --8210060452 Comments on "Learning Function in Nuclear Reactor Operation & Implications for Siting Policy " Analysis does not support finding that adding reactors to existing sites enhanced learning MACEVOY. J A ACRE Advisory Committee on Reactor Bafeguards 82/03/15 COTTRELL.W D Oak Ridge National Laboratory 5pp. 15475-045
- "-B21007000B Responds to B20324 request for assessment of reactor coolant year study General rept on all mechanisms of bolting degeneration in progress Visual insp of reactor coolant sys bolts recommended HWAVER, B H Division of Safety Technology B2/04/05 EISCHAUT, D O Division of Licensing 5pp 15745 265
- E210040357 "Should Addi Independent Power Source Be Required for CHR Sys " ATEF18 B, LINER, R, HUOHES, A Science Applications, Inc MSC-03-82-096 82/07/15 10pp 15597 280
- 8210940350 Responds to FGIA request for BECY-B2-72B & BECY-B2-72C returdinated program for steam generators Documents available in PR FELTON, J M Division of Rules and Records 82/09/27 FORTING, K C Lowenstein, Neuman, Reis, Axelrad & Toll ip 15597 291
- --8204200390 SECY-82-0728
  Responds to Chairman 820301 request for short-term actions reperformance of steam generators Comprehensive water chemistry criteria for steam generators should be implemented to the Executive Director for Operations 82/04/03 2pp. 15597 292
- --8205270507 SECY-82-072C
  Advise: Commission of results of 820428 meeting w/industry re-proposed coordinated program for steam generators. Proposal in SECY-82-72A re-formal structural organization such as policy group & steering committee rejected DIRCKS. W. J. Office of the Executive Director for Operations 62/05/17 3pp 15557 294
- --3205270526 Advises of legal difficulties re coordinated steam generator research program proposed in BECY-82-72A Reconsideration of grogram organization suggested in light of Federal Advisory Committee Act
  HALSCH.H 9 Office of the General Counsel 82/05/05 AHEARNE, J
  Commissioners, 4pp. 15597 297
- 8210040365 Responds to appeal re denial of FOIA request for four affidavits concerning allegations of improper const practices at facility Forwards requested info. Page 4 of E Orave affidavit withheld (ref FOIA Exemption 7).

  DIRCKE, H J. Office of the Executive Director for Operations.
  82/09/24. STEPTOE, P P. Isham, Lincoln & Beale. 29p. 18597 303.
- 8210950430 Responds to FOIA request for correspondence between Nuclear Assurance Corp & NRC re 1982 irradiated fuel shipments tetween Ontario & NC.Forwards App A documents.App B decuments withheld (ref FOIA Exemption 3).
  FRITONLUM Division of Rules and Records 82/08/17. REBNIKOFF, M Council on Economic Priorities 3pp. 15626 172
- --8201050245 Requests approval of alternate routes for planned irradiated fuel shipments from Chalk River Nuclear Labs to DDE Savenneh River facility, Date of arrival deleted, DANERE, F.L. Nuclear Assurance Corp. 19955. 81/11/13. Division of Safeguards Spp. 15626; 201
- --8210050439 Provides add1 info re initial shipment of irradiated fuel per 811110 ltr.Shipment will arrive at destination on 811121. DAMESE:F.L. Nuclear Assurance Corp FLD/81/81/ETS. 81/11/17 Division of Emergency Prepar

- --B210050467 Advises of plans for series of spent fuel shipments frum Chalk River to DDE Savennah River Plant BANESE, FL Nuclear Assurance Corp FLD/82/84/ETS 82/07/02 GDDY, A Region 1. Office of Director 1p 15626 232
- --8210050471 Corrects 920702 prenotification of planned series of irradiated reactor fuel shipments from Chalk Rivor to Savannah River Plant Port of entry is Berby Line, Vf DANESE, F L. Nuclear Assurance Corp. FLD/82/86/ETS 82/07/07 GDDY.A. Region 1. Office of Director 1p 15626-233
- B210090512 Responds to FOIA request for insp & enforcement records is accidents of F Lawson & H Dillon at facility. Union Electric CP & other NRC safety matts or manuals Forwards two documents Remaining records available in PDR FELYON, J M Division of Rules and Records 82/09/21 IGDE, M V Igoe. V M 2gp 15626 244 24x Fiche 50-000, 82/09/21, 8210050512
- --8210050518 Region 3 daily rept for 780807

  \* Region 3. Chicago. Office of the Director 78/08/07 1p 15626 246 24X Fiche. 50-000. 82/09/21.8210050512
- ~-B210050522 PND-III-78-062 on 780804, two workers seriously injured when hit by support girder for polar crans rail OSHA notifies BCHWEIBINZ.E R. Region 3. Chicago, Office of the Director 78708704 ip 15826 247 24X Fiche S0-000, 82/09/21, 8210050512
- 8210050562 Responds to FOIA request for SECY-75-588, 588A, 588B, SECY-R-74-64, SECY-81-600A & SECY-81-622A Document review in progress FELTON, J. M. Division of Rules and Records 82/09/17 CONNOR.L. Doc-Search Associates 1p 15626 242
- 8210060403 FOIA request for itrs from Dhmart Corp & TX Nuclear justifying aroprietary claims re FOIA 82-A-12 COLLINS.P L Research Counsel of Mashington 82/09/03 DIRCKS.W J Office of the Executive Director for Operations ip 15636 235
- 8210060406 Responds to FOIA request for lirs from Ohmart Corp & IX Nuclear justifying proprietary claims re FOIA 82-A-12 Forwards documents. FELTON J M Division of Rules and Records 82/09/22 COLLINS, P L Research Coursel of Washington ip 15636 236
- --8210060411 Responds to 820630 request for info re FGIA 82-263 All info contained in general license rept considered proprietary Any rept dtd earlier than Apr 1976 may be released w/o significant competitive harm HENDRICKIN 0 Texas Nuclear Div (subs of Ramsay Eng Co ) 82/07/09 FELYON, J. M. Division of Rules and Records Rep 18636 238
- --8210060415 Responds to 820630 ltr re Ohmart Corp quarterly repts listing devices distributed to general licenses Repts are always treated as confidential Disclosure would harm competitive position CODK.H L. Ohmart Corp. 82/07/13 FELTON.J M. Division of Rules and Records, 2pp. 15636-240.
- 8210060419 Responds to FOIA request for SECY-82-728 & SECY-82-72C recordinated program for steam generators Document review in progress.
  FELTON, J M Division of Rules and Records.
  ESELTON, J M Division of Rules and Records.
  Lowerstein Neumann Reim Assirad & Toli ip 15636 255
- 8210060429 Forwards CJ Johnson FOIA request for rept to EPA. "Pu & Human Tissues Re Smoking. Age. Residence Near Rocky Flats & Eastern CO " Response requested. FELTON, J M Division of Rules and Records B2/09/27 OREEN. J. B Environmental Protection Agency (p. 18634-209)
- 8210060434 Responds to FOIA request for all declassified matl on Manhattan Project NRC has no documents subj to request FELTON, J M Division of Rules and Records 82/09/15 CHAIKEN, J A Affiliation Unknown. ip 15636.206
- B210060442 Responds to FOIA request for input to Chapter 7 & App J of FEB & suppl to CRBR. Documents listed in App A available in PDR App B documents completely withheld advice & opinions (ref FOIA Exemption 5) FELTON, J H Division of Rules and Records, B2/08/24 WEISS, E R Harmon & Weiss 4pp. 15536 040.
- 8210070007 Responds to FDIA request for eight categories of retords re steam generators & steam turbines App A documents provided in R Udell FDIA Request Bi-313, Forwards documents listed in App B FELTON, J. H. Division of Rules and Records 82/08/10, LONG, D. J. Hinthrop, Stimson, Putnam & Roberts. 9pp 15645-063 24X Ficher 50-000, 82/08/10, 8210070007.

- --7812200285 Summarizes steam generator tube leak on 780920 & 1hsp Leak rate reached 560 gpd at 5 00 AM, caused by two tubes w/cracks located w/in thickness of tube sheet & one tube w/leaky plug General cause plant conversion to AVT NOONAM, V S Engineering Branch (Pre 791030) 78/12/12 GRIMES, B K Assistant Director for Engineers & Projects (Pre 790625) 2pp 15645 244 24X Fiche 50~000.82/08/10,8210070007
- --7909280105 Discusses steam generator tube leak & inservice insp Steam generator caused by deep crevice cracking of three tubes within tube sheet Hot leg tube tests indicated 52 tubes w/ deep crevice tracking in ercess of 50% plugging limit NODNAN, V S. Engineering Branch (Pre 791030) 79708/17 FISEINHUT, D G. Division of Operating Reactors 3pp 15645-254-24% Fiche 50-000, 82/09/10,8210070007
- --8201210107 Advises that utils should be informed that impact of tube plugging should be evaluated for all SAR Chapter (5 events 2 results of svaluation submitted when requesting approval of new steam generator tube plugging limit POVAK.T M Assistant Director for Operating Reactors 81/12/29 Assistant Director for Operating Reactors 2pp 15445 281
- --8203190034 Forwards State of IL Poliution Control Board 820127 it: & delineates areas of responsibility re response LARNAS.G C Assistant Director for Safety Assessment 82/02/09 JUHNSTON.H V Assistant Director for Materials & Qualifications Engineering Ip 15645 124
- ---8203260003 Recommends that STS limits for coolant activity & sampling requirements be incorporated into remaining operating plant. Tech Specs w/other substantive change requests fodine dose problems can be avoided by limiting coolant MOUSTON, R W. Assistant Director for Radiation Protection 82/03/04 NOVAK, I Assistant Director for Operating Reactors 2pp. 15645-285
- --B210070135 Bevil rept input re Ginna 820125 steam generator tube rupture event NRC 16th monthly status rept to Congress re TMT-1 restart encl # NRC - No Detailed Affiliation Given 82/03/11 3pp 15645 128 24X Fiche 50-000
- --82:0070196 Distusses intervice inspiprograms for PMR steam generator tubing to monitor conditions of tubing in all PMR operating plants Licensees w/o steam generator tube surveillance program should be required to suppl Tech Specs SCHROEDER: F. Division of Technical Review (MRR-1975 only) 75/04/21 G[MRDUSDEA Division of Reactor Licensing (NRR-1975 only) 3pp 15645-207
- --8210070198 Recommended Tach Specs 3 4 5 & 4 4 5 re steam generator tubing surveillance

  \* Division of Technical Review (NRR-1975 only) 75/04/21 20pp 15645 210
- --8210070205 Submits summary of findings & comments Te facility stram generator tube leak incident & inspiresults contained in Annual Operating Rept 1976 Recommends that licensee be requested to submit inspirogram for next scheduled inspisHAO.L C Engineering Branch (Pre 791030) 77/07/25 EISENBUT. B Division of Deprating Reactors Ppp 15645 235 24X Fichs 50-000, 82/08/10, 8210070007
- ---8210070235 Agrees w/801028 memo suggestions All assistant directors in Dis of Licensing requested to follow same approach EISENHUT.D Q Division of Licensing 80/11/07 MARTIN.J D Division of Waste Management ip 15445-290
- 8210070029 Partial response to FOIA request for documents re CRBR EIS & all comments, evaluations & documents from BNWL re EIS Forwards documents listed in App A FELTEN, J M Division of Rules and Records 82/07/16 WEISS, E R Harmon & Weiss 8pp 15648 004
- --B210070123 Forwards updated responses to comments on 1976 DES.

  NUREG-0137 Te safeguards & fuel cycle Info Te raduaste
  shipments.disposal sits & licensed burial site included
  LOMENBERG.H Office of Nuclear Material Safety &
  Safeguards. Director CRUR 82-49 82/06/15 LEECH.P Clinch
  River Breeder Reactor Program Office 15pp 15648 073

- --B210070421 Notifies that no physical security concerns exist re expert of low enriched U to Japan under export license application KENN-1894 SHERR.TS Material Control & Accountability Development Branch 81/12/17 DEVINC.JB Assistant Director for Export/Import & International Safeguards 1p 15647 007
- --8210070426 Recommends that NMSB provide representative to join State Dept entourage to Canada on 820112-14 to exchange technical info on application of IAEA safeguards to on-load reactors WIRFS, NRC - No Detailed Affiliation Given B2/01/07 CHAPELL.D NRC - No Detailed Affiliation Given 1p 15647 000
- --8210070428 Forwards summary of Interagency Steering Group 820106
  meeting w/Ofc of Intl Programs & NMSS re action plan
  activities. US program for technical assistance & resource
  allocation to IAEA
  DIRCKS, W. J. Office of the Executive Director for Operations
  82/01/19 PALLADING, N., GILINSKY, V., BRADFORD, J. Commissioners
  App. 15547-009
- ---8210070431 Requests that summary of Interagency Steering Group D20165 meeting be forwarded to Commission No major decisions reached SHEAJ R Office of International Programs, Director 62/01/19 DIRCKS,WJ Office of the Executive Director for Operations 19
- --8210070434 Notifies that no physical protection toncerns exist reexport of highly enriched U to Japan Update on status of negotiations requested SHERR.T S Haterial Transfer Bafeguards Licensing Branch 82/02/09 DEVINE, J B Assistant Director for Export/Import & International Safeguards 1p 15647-015
- --8210070436 Notifies that no physical protection concerns exist 18 applications to export low enriched U to Japan under Licenses XBNM-1723, 1925, 1928 & 1876
  SHERR.T 8 Material Transfer Safeguards Licensing Branch 82/02/25 PETERSONMR Assistant Director for Export/Import & International Safeguards ip 15447-016
- --8210070441 Forwards response to 811125 & 30 ltrs re IACA safeguards MAC receives little specific info concerning intl safeguards Classified info received through briefings PALLADING, N J Commissioners 82/03/02 OTTINGER, R L House of Rep , Energy & Commerce 12pp 15647-017
- --B210070445 Forwards Intl Bafeguards & foreign physical security review for comment & inclusion in draft Commission paper re proposed export of highly enriched U to West Germany & Buitzerland Burnetter B1/03/08 BHEA. J.R. Diffier of International Programs, Director 2pp 15647 036
- ---8210070447 Notifies that no physical protection concerns exist reapplications to expert low enriched U to Japan, Inforequested restatus of facility attachment to Fukushima I. Unit 4

  SHERR.T S Material Transfer Safeguards Licensing Branch 82/03/11 PETERSON.HR Assistant Director for Export/Import & International Safeguards 1p 15647 038
- --8210070448 Speech entitled. "Nuclear Common Sense," presented at O⊇O, AIF fuel cycle conference KENNEDY,R T President of US & Executive Offices 82/03/2≥. 13pp 15647 039
- --8210070451 Forwards trip rept of B20315-26 visit to Vienna Austría foworking consultants session on IAEA safeguards effectiveness assessments
  BRACH, E W Office of International Programs, Director 02/04/08
  GREEN, L Brookhaven National Laboratory 6pp 15647 052
- --8210070454 Forwards transcript of Subcommittees on Intl Brourity & Scientific Affairs & Intl Economic Policy & Trade Committee on Foreign Affairs 820318 hearing re IAEA safeguards Edited comments requested by 820402 KAMMERER, C Office of Congressional Affairs 82/03/30 PALLADIND, N, GILINSKY, V, AHEARNE, J Commissioners & 15447 057
- ---82:0070458 Transcript of Subcommittees on Intl Security & Scientific Affairs & Intl Economic Policy & Trade & Committee on Foreign Affairs 820318 hearing in Washington DC re IACA safeguards improvements 4 House of Rep 82/03/18 110pp 15647 058

# NONDOCKETED ITEMS

- -~8210070464 Discusses plan established for fulfilling Ofc of Executive Director for Operations request for info re NRC efforts to improve IAEA safeguards Accuracy of info reported by states to IAEA needs major improvement WIRF3.L NRC No Detailed Affiliation Given 82/05/06 BURNETT, 8 NRC No Detailed Affiliation Given 4pp 15647 171
- --B210070467 Forwards draft IAEA guidelines for nuclear facility design, incorporating design features to facilitate implementation of intl safeguards Comments requested by B20521
  SHERR.T S flaterial Transfer Safeguards Licensing Branch B2705707 ERICKBON.R A Power Reactor Safeguards Licensing Branch COHEN.K Defice of International Programs, Director 44pp 13647 175
- --B21007046B Forwards memo for Commission providing summary of sign(ficant NRC & Executive Branch efforts to improve IAEA safeguards H/o enc! SHEA.J R Office of International Programs, Director 82/05/21 DIRCKS,W J Office of the Executive Director for Operations 1, 15447 223
- ~-8210070471 Forwards draft Commission paper re application for license to export highly enriched U to France Comments & License conditions specified in Encl 2 should be included in License BURNETT, H F Division of Bafeguards 82/05/25 SHEA, J R Office of International Programs, Director 3pp 15647 224
- --B210070473 Comments on DDE analysis re retransfer of spent fuel assemblies from Japan to United Kingdom & France for reprocessing Advanced notification required if fuel shipment enters US territorial waters SHERRITS Haterial Transfer Safeguards Licensing Branch B2706/03 ZIMMERMANJ V Assistant Director for Export/Import & International Safeguards 2pp 15647 227
- --8210070475 Summarizes 820607-08 meeting w/IAEA in Dethesda, MD re lAEA safeguards agreement Problems associated w/US reporting of nuclear matl info to IAEA discussed SHERR. TS Division of Safeguards 82/06/09 DAVIS, J G Uffice of Nuclear Material Safety & Safeguards Director 2pp 15647 229
- --3210070478 Discusses corrective actions re reporting transactions & inventories for US facilities selected by IAEA Bys to provide correction data to IAEA in acceptable format should be developed SHERR.IS Haterial Transfer Safeguards Licensing Branch 82/05/18 DGYLE.G J Union Carbide Corp 2pp 15447 231
- --8210070480 Forwards intl safeguards & foreign physical security review sections for inclusion in Commission paper re retransfer of low enriched U feel assemblies from Federal Republic of Garany to Peru SHERRITS Material Transfer Safeguerds Licensing Granch 82706/16 ZIMMERMANJU Assistant Director for Export/Import & International Safeguards 2pp 15647 233
- ~ 821070482 Submits summary of activities to support interagency efforts to strengthen IAEA safeguards during first half of CYB2
  BURNETTURE Division of Safeguards B2/07/13 DAVES, J Q
  Office of Nuclear Material Safety & Safeguards, Director 29sp
  15647 235
- --92(0070484 Notifies that no physical protection concerns found reapplication for license to export single reload of low enriched U to Japan
  SHERR.T S Material Transfer Safeguards Licensing Branch
  82/06/23 ZIMMERMAN.J V Assistant Director for Export/Import & International Bafeguards ip 13647 263
- --82100704B5 Forwards list of priorities activities for FY83 per f Hourks 820824 memo, CDHEN.K D Assistant Director for Export/Import & International 846gwards 82/07/10 Assistant Director for Export/Import & International Safeguards 3pp 15647 264
- --82:0070486 Notifies that no special physical protection or inth safesuerds concerns identified re Amend 1 to application to sijort low enriched U to Malaysia SHERRIS Haterial Transfer Bareguards Licensing Branch 82/06/28 ZIMMERHAN.J V Assistant Director for Export/Import & International Safeguards ip. 15647-267.
- --8210070498 Speech entitled "Nuclear Safeguards Challenges & Realities," prespited at 22nd annual meeting of Inst of Nuclear Hatis ligt KRATZER, H B International Energy Associates, Ltd 82/09/10 27pp 15447 268

- --8210070489 Notification of 820908-10 consultant meeting to discuss draft guidelines for design features to facilitate intl safeguards Draft guidelines enc!

  SANDERS, K. E. Office of Nuclear Material Safety & Safeguards, Director 82/06/29 HOUCK, F. NRC No Detailed Affiliation Given SHERR, T. Office of Nuclear Material Safety & Safeguards, Director COMEN, K. Office of International Programs, Director 68pp 15647-297
- 8210070417 Responds to FOIA request for info re each NRC licensee in States of PA.DE & NJ Forwards three computer printouts furnishing names & addresses of licensees Info re licensee this featurity officers not maintained FELTON.J M Division of Rules and Records 82/09/29 FREDLAND.D R Affiliation Unknown 1p 15446 007
- --B210070423 Computer printouts listing names & addresses of NRC licensees in States of NJ.DE & PA

  # NRC No Detailed Affiliation Civen B2/09/24 210pp 15446 008
- 8210080010 Addl FDIA request re minor additions & deletions to B20403 request for 19 categories of info on nuclear reactor events & safety problems
  UBELLIR A Critical Mass Energy Project 82/06/11 FELTON, J
  Division of Rules and Records ip 15665 022
- 8210080015 Add1 response to FDIA request for 19 categories of inip to nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5) feLTON.J M Division of Rules and Records 82/07/12 UDELL.R A Critical Mass Energy Project 9pp 15665 027 24% fiche 50-000,82/07/12,8210080015
- --8011060346 Discusses licensee responses to NRC request to commit to interim position re Generic Item B-24 venting & purging containments while at full power Plants meet interim position & existing TAGs should be closed but REEVEG.E A Operating Reactors Branch I BO/08/25 Operating Reactors Branch I BO/08/25 Operating Reactors Branch I BO/08/25
- --Bi04080309 Std order for DOE work "Program for Cost Estimation for Proposed Safaty Requirements," issued to 1D Operations Ofc Statement of work encl GRENIER, D.L. Office of Nuclear Reactor Regulation, Director | IN A-6452-1 20-Bi-165 81/03/12 App 13665 183
- ---Bi052B0476 Requests that regions confirm licensee submittal of rept for satisfactory implementation of Item 4 of IE Bulletin 79-26.

  Revision 1

  JORDAN, E. Division of Resident & Regional Reactor Inspection
  IEB-79-26 Bi/05/18 GRIER, B. H. Region 1, Philadelphia, Office of the Director (Bi/03/01) SEYFRIT, W. Region 4, Dallas, Dffice of the Director (Bi/03/01) ENGELKEN, B. H. Region 5, San Francisco, Office of the Director (Bi/03/01) 1p 13668 130 241X
  Fiche 50-000, 98/07/12, 8210080015
- --BI06220159 Supports efforts in resolving purge valve leakage & operability issues Incorporation of leak testing position into Tech Speca should assure leakage integrity of containment BAER, R L Reactor Engineering Branch 81/06/09 BUTLER, H R Containment Systems Branch 2pp 15668, 153
- ~-8106220168 Forwards proposed [E bulletin identifying potential safety concern rs leakage of reactor bidg purge valves O'REILLY-U P. Region 2. Atlanta: Office of the Director (81/03/01) [EC-77-11 Bi/03/20 SNIEZEK, J Director's Office 5pp 18669 167
- --Bi07170126 Comments on proposed IE bulletin re leakage of reactor bidg purge valves Issuance not marited for reasons indicated Generic Issuaes B-20 & B-24 provide assumance of increased surveillance testing & reduced excessive leakage SNIEZEK, J H Director's Office IEC-77-11 81/07/01 078EILLY, J P Region 2, Atlanta, Office of the Director (81/03/01) 2pp 15668,151
- --8108210025 Forwards draft suppl to IE Bulletin 81-02, "Failure of Oale Type Valves to Close Against Differential Pressure," for review & comment JORDAN, E. L. Director's Office 81/07/23 GRIER, B. H. Region 1, Philadelphia, Office of the Director (81/03/01) GREILLY, J. P. Region 2, Atlanta, Office of the Director (81/03/01) KEPPLER, J. G. Region 3, Chicago, Office of the Director (81/03/01) 28pp 18668 181

- 1203040536 Comments on Bii218 corrections to facility assessment equivious comments un official corrections to rectify asset contained in NURGO-DB34 re hearings & discussion of systematic assessment of license performance Revision to systematic assessment of license performance Revision to RUMBC inappropriate Issue rlosed MOSELEY, N.C. Systematic Assessment of Licensee Performance Review Group B2/01/04 WESSMAN, R.H. NRC. - No Detailed Affiliation Given Ip 1568 256 24X Fishe 50-000.82/07/12.8210080015
- 203040538 Forwards performance element summary for Jul 1979-June 1980 in response to ABLB request for testimony on systematic assessment of license performance in general & facility
- assessment or license performance in general & facility assessment in particular WESSMAN,R H Director's Office Office of Inspection and Enforcement 81/12/18 MOSELEY,N C Systematic Assessment of Licensee Performance Review Group 2pp 15648 254 24X Fiche SG-000,82/07/12.8210080015
- 1204120487 Discusses problems w/water in fuel oil tank Case does not OALOUND DIscusses problems by Macel The Total Care Care Care The Nave generic implications
  TREMAN, N.K. Director's Office 82/04/06 MICHELSON, C
  Director's Office Spp 15645 036 24% Fiche 50-000, 82/07/12, 82100B0015
- 205190428 Forwards engineering evaluation rept. "Inadvertent Loss of Reactor Coolant Events at Sequoyah Muclear Plant, Units 1 & 2 " Rept contains recommendations which should be incorporated in ongoing Task Interface Agreement 81-15 LANNING, U.D. Director's Office 82/05/11 MICHELSON, C. Director's Office 19 15646 095 24X Fiche 50-000, 82/07/12, 8210080015
- 205190441 "Inadvertent Loss of Reactor Coolant Events at Bequoyah Nuclear Plant, Units 1 ½ 2:" engineering evaluation rept LANNING.N D Director's Office 1EB-80-12 02/05/31 23pp 15666-076 24X Fiche 50-6000, 82/07/12, 8210080015
- 205Q80490 Forwards diesel generator interim reliability program for operating plants 5 proposed Tech Specs
  MANAUER.S H Division of Safety Technology 82/09/06
  EISENHUT.D G Division of Licensing MATTSON.R J Division of Systems Integration (post 811005) THOMPSON.H L Division of Human Factors Safety 49p 15666 031
- 205280497 "Dieset Generator Interim Reliability Program for Operating # Division of Safety Technology 82/05/06 22pp 15666 037
- 205280502 Proposed Tech Specs re electrical power sys \* Division of Safety Technology 82/05/06 lipp 15666 059
- 206040401 Forwards procedures for screening operational data, particularly LERs received after 820501 Submittal replaces procedures issued by 810427 & 820315 memos MICHELSON, C Olrector's Office 82/04/23 Director's Office Director's Office
- 206070105 Operating Reactor Event Memo B2-01 re B10B10 reactor scram w/water hammer event Study of Unresolved Bafety Issue A-1 shows no other water hammer events in BWR isolation condensers EIGENHUT D Q Division of Licensing OREM-82-002 82/05/25 VOLLMER, R M Division of Engineering 7pp 15645 150 24X Fiche 50-000, 82/07/12, 8210080015
- 1210000054 Forwards "Cost of Upgrading Capability to Isolate LPWR Majn Fredwater Sys in Event of Breaks Inside Containment," final rept.in response to statement of work in TE Murley 810616 1tr re INEL technical assistance to NRR SAFFELL BF E080, Inc. FIN A-6452 SAFF-195-82 82/04/14 SOLECKI, J E Energy Dept of, Idaho Operations Office ip 15665 167
  - Upgrading Capability to Isolate LPMR Main Feedwater teaks Inside Containment." final rept, per for DDE Work Order 20-81-165, "Program for Proposed Safety Requirements" A-6452 RGB-2-B2 82/03/19 15pp

- --8210080106 Oral presentation of "New Trends in Evaluation & Implementation of Safety-Related Operating Experience " MICHELSON, C. NRC No Detailed Affiliation Olven 1AEA-CN-39/2 2A 82/07/12, 13pp 15667 278
- ~-8210080187 Forwards draft IE bulletin on channel independence in Etta 21008018/ Forwards draft le bullatin on channel independence le actuation sys for DMS clearance Specific items listed in Part II of app to draft NRC Manual Chapter 0213 discussed Expedited review & OMB clearance requested JORNAN, EL Director's Office 81/05/28 SCOTT, 8 Document Management Branch 7pp 19648 144
- --8210080196 Forwards IE Circulars 80-15 & 81-10.Generic Lir 81 31 & 1
  Info Notice 79-13, in response to 810630 request re issuance
  of IE bulletins concerning steam voids & events at foreign or domestic BWR or comestic BBN STELLG.V Director's Office, Office of Inspection and Unfort##\*\*\*\* OL-81-21 81/07/27 LEMIS.M I Lewis, M 20p 15569 [14]
- --8210080197 NRC operations ctr usage chart re events at facilities NRC No Detailed Affiliation Oliven 82/07/12 tp 19//01/12 24X Fiche 50-000,82/07/12,8210080015
- --8210080202 Forwards questions on licensee performance rating protos for use in preparing for systematic assessment of licences performance briefing Draft responses dtd 810904 encl \* NRC - No Detailed Affiliation Given 81/08/28 | NRC Detailed Affiliation Given 18pp 18668-222
- --8210080206 Forwards SJ Chilk B10923 staff requirements memo re 🖽 🖰 briefing on systematic assessment of litensee performance rept Excerpts of 810922 briefing transcript re Commission guidance encl
  ALLISON.D P NRC - No Detailed Affiliation Given 81/10/01
  MDSELEY.N C NRC - No Detailed Affiliation Given 9pp
- --B210080207 Forwards Commission guidance for future conduct of like assessment process per systematic assessment of licenses performance program Commission should be advised of progress CHILK, S J CHILK, S J Office of the Secretary of the Commission (IMFJ' 4) 81/10/20 DIRCKS, W J Office of the Executive Director for Operations 4pp 15668 250 Operations
- --8210080213 Forwards revised description of responsibilities & for of Div of Engineering & GA
  JORDAN, E Division of Engineering & Quality Assurance 112713,
  SNIEZEK, J. NRC No Detailed Affiliation Olven 4pp 175646.
- --8210080215 Forwards revised IE organizational charts & funrissing statements for review & comment Roorganizations of 82():04 & 25 will be incorporated in NUREO-0325 Educitive incorporates in NVREG-0325
  BLAHAJ J. Brogram Support Branch 82/04/29 (.18 B) NNAN p
  Enforcement Staff FORTUNA, R Director's Office, Office of P
  Inspection and Enforcement COBB. L I Division of Puel
  Facilities, Materials > Safeguards 7pp 15468 261
- --B210080216 Forwards draft IE Manual Chapter 0101 re If present all functions Comments requested by B20624 Chapter will be included in Jul quarterly issue of changes to IE manual BRACH, B Director's Office, Office of Inspection and Engles B2706/10 CDBs.L. ORIMES, B. JORDAN, E NRC No Usiasies Affiliation O(ven 17pp 15668 272
- --8210080217 Forwards new IE organization chart.functional states new organizational units & list of proposed personnel assignments within new organization, per NJ Palladino [[11]—1] memo Functional atatements for reactor sys speciallests sir 3 DEYQUNO.R C Director's Office Office of Inspection and Enforcement 81/12/14 Director's Office, Office of Ethaga and Enforcement 32pp 15648 289
- B210080020 Responds to FDIA request for documents to preimplement review of NUREG-0737, Item III F 2 Forwards documents listed in App A FELTON. J M Division of Rules and Records B2/07/16 (\*\*\*\*\*) \*\*\* Doc-Search Associates 2pp 15669 097
- ---BioB270547 Requests add1 info through C-E owners group to Real junction thermocouple reactor yeasel level measurement set info should be submitted by Bio901 RUBENBTEIN. LB Assistant Director for Care & Containance C Bi/07/09 LAINAS.0 C Assistant Director for flafety as the 15667.103
- --Bi0B19000B Forwards LS Rubenstein 810709 memos requesting from C-E & Hestinghouse owners groups re reactor vassel level measurement sys. TMI Action Plan Item II F 2 3 LAINAB.Q. Assistant Director for Bafety Assessment Bridy. 15469 CRUTCHFIELD.D Operating Reactors Branch 5

.....

- --8109110478 Requests that licensee provide plant-specific submittal re installation of Hostinghouse reactor vessel level Instrument PHILLIPS:L E Core Performance Branch 81/08/13 SHEA.J Generation Reactors Branch 5 200 65569 300
- \_\_gj092804B4 Requests that project managers transmit encl sample ltr ru Westinghouse reactor væssel jevel instrumentation sys for monitoring inadequatë core cooling.TMI Item II F 2 3 to licenseem for plants listed CRUTCHFIELD.O Deretting Reactors Branch 5 81/09/14 VARGA.S A Operating Reactors Branch 1 5pp 15469 110
- --B210080032 Provides guidance for Commission Bi1223 briefing on PWR vessel level indicators per BECV-BI-582 Info requested re vendor contacts & appropriate order of briefing REMM.T A Office of the Executive Director for Operations B1/12/23 MAFTBON.R J Division of Systems Integration (post B11003) 2pp 15469 234
- --8210080074 Advises of Commission approval re delay in implementation schedule for NURCO-0737. Item II F 2. "Add I Instrumentation for Detection of Inadequate Core Cooling "SECY-81-528A withdrawn (AINAS. O C Assistant Director for Safety Assessment 82/02/10 EXEMENTUT, D O Division of Liferning 2pp 15669 236
- 8210080038 WCAP-7870 Sicerpt from "Neutron Shielding Pads" + Hestinghouse Electric Corp 72/05/31 4pp 15669 242
- --9208250412 Responds to 820327 memo re broken care barrel assembly thermal shield boits at Ocones i & applicability to other StW plants NRR review described in enci Task Interface Agreement Bi-19 did 811026, should be completed by 820901 LIECKINUT, D Q Division of Licensing 82/07/19 OLGHINSKI, J A Division of Engineering & Technical Programs ip 15669 284
- 10000058 Responds to appeal re denial of FOIA request for sagregable portions of draft NUREG-0844, "Resolution of Unresolved Safety Issues A-3.A-4 & A-5 Re Steam Generator Tube Integrity." Request deniad (ref FOIA Exemption 5) DINCMS.H J Office of the Executive Director for Operations 62/07/19, UDELL.R A Critical Mass Energy Project 2pp 18660 331
- IOIRODIS Partial response to FOIA request for documents re St Joseph Hosp in Albuquerque.NH & 1-125 seed incident Forwards documents listed in App A FELTON.J H Division of Rules and Records 82/08/20 DAVIES.L & Richards, Srandt, Miller & Nelson 3pp 15691 173
- QOID:180362 PNA-B0-039 on B01201, Btate of NM informed NRC of overexposures of patients receiving I-125 seed therapy for treatment of prostate cancer Gausedby computer dose conversion factor error Btate request hosp rept
- -8210120018 Discusses PNA-BO-039 re overexposures of patients receiving 1-129 seed therapy for prostate cancer at St Joseph Hosp.
  Albuquerque, NM Computer program error cited as contributing factor
  LUBENAU. J O NRC No Detailed Affiliation Given 80/12/02
  REHMIT NRC No Detailed Affiliation Given ip 15691 178
- -B210120021 Confirms D01220 telcon w/LW Huppert re misadministration of 5-125 seeds used in prostate cancer therapy Definitive rept will be provided by B10202 Related info enci TOPP-A A New Mexico. State of 80/12/31 KOEBEL,C St Joseph Hosp Albuquerque, NM 14pp 15491,180
- -B210120023 Requests assistance in independent technical review of encl rept from St Joseph Hosp re misadministration of 1-125 seed implant Ltr delineating info required & article from Albuquerque Journal encl H/o enci. MDLFF, T A New Hestico, State of. 81/02/03 NUSBHAUMER, D A Assistant Director for State Agreements Programs ip 15691 192
- --8210120027 Forwards rept to St Joseph Hosp, Albuquerque, NM remisedministration of I-125 seed implant Event attributed to personnel error & lack of communication between computer plan developers & users Comments requested by 810227 NUSBBAUMER, D.A. Assistant Director for State Agreements Programs 82/02/23 HIQQINBOTHAM, L. Radiological Safety Branch. CUNNINGHAM, R.E. Advanced Fuel & Spent Fuel Licensing Branch ip 1849 193

- --8210120030 Advises that hosp rept re misadministration of I-125 seed implant therapy raises more questions than answers Related info encl
  HIGOINBOTHAM, L Radiological Safety Branch 82/08/20
  NUSSBAUMBER, D. A. Assistant Director for State Agreements Programs 11pp 15691 194
- --82(0)(2005) Discusses review of hosp rept re misadministration of I-125 seed implant therapy Rept does adequate job of defining magnitude of misadministration Contributing causes unclear Related info encl HILLER.V. L. Licensing Hanagement Branch 81/03/09 NUSSBAUMER, D. A. Assistant Director for State Agreements Programs 82pp 15691 206
- --8210120057 Forwards WR Hender review of selected matis remisadministration of 1-125 seeds at St Joseph Mosp Albuquerque M/o enc!
  NUSSBAUMER, D.A. Assistant Director for State Agreements Programs 81/03/25 HIOGENBOTHAM.L. Radiological Safety Branch
  MILLER: V.L. Licensing Management Branch 1p 15491 289
- --8210120062 Forwards rept re investigation of St Joseph Hosp I-125 serd incident Related info encl TOPPA A New Herico. State of 81/11/13 NUSSBAUMER, D A Assistant Director for State Agreements Programs 12pp 15801 200
- --B210120066 Statement of St Joseph Hosp president re treatment of 18 prostate cancer patients by 1-126 seed implantation Related info encl
  KOEBELIC St Joseph Hosp Albuquerque, NM 80/12/18 68pp 15691 303
- --8210120068 "Radiation Dose Evaluation of I-125 Implants at St Joseph Hosp " ANDERSON,L L. Affiliation Unknown 81/08/18 30pp 15692 008
- --82(0120075 Forwards State of NM rept re investigation of incident involving overexposure of patients treated w/l-125 seeds AO rept will be included in nest quarterly rept W/o encl NUSSBAUMER. D. A. Assistant Director for State Agreements Programs BI/11/24 CUNNINOMAM. R. E. Advanced Fuel & Spent Fuel Licensing Branch 1p. 15492 040
- 8210120090 Addi response to FOIA request for 19 categories of documents Forwards "Symmery of Events Discussed At Operating Reactors Events Meeting During 1981," "Most Significant Events of 1981," & "Less Significant Events of 1981 "
  FELTON. J Division of Rules and Records 82/07/26 UDELL.R A Critical Mass Energy Project 5pp 15692 041
- 8210120112 Advises that questions re T Hoffett 810817 memo on efforts to expedite licensing of new nuclear power plants should be answered by Chairman ROBERTS, T M Commissioners 81/08/25 HALLER, N Commissioners Ip 15890
- --B20506055B Expresses concern that 780209 NRC Manual Chapter NRC-0502, NRC incident resportant to the horadates TMI-2 accident, remains effection should; ROBERTS, T M

1

1 1

100 1

> I, 1 The second

1.1 -b

7.11

雪貨 البال

14)

4

Вİ

-1

- --8210120170 Comments on SECY 82-74 re proposed rulemaking, 100FR50 55a, "Codes & Stds " First full sentence on Page 7 of Enci 1 is misstatement of fact Requests B Dircks response ROBERTS,T M Commissioners 82/03/04 CHILK,S Office of the Secretary of the Commission ip 15690 154
- --8204010046 Comments on Commissioner Roberts statement in SECY-82-74 on 20401.0046 Comments on Commissioner Roberts statement in Settings.
  Page 7 of Enci I re estimated costs applicant companies
  intur when applying for ASME approval Statement applies only
  to ASME charges made to company applying for N stamp
  RINIOGUE.R B Office of Nuclear Regulatory Research, Director
  82/03/18 DIRCKS.H J Office of the Executive Director for
  Operations Ip 15690 455
- --8210120176 Forwards Ofc of Nuclear Regulatory Research memo explananing concerns re proposed rulemaking. "Godes & Stds " Section of rule in question not intended to upgrade or downgrade basic quality of product DIRCKS, M J Office of the Executive Director for Operations 82/03/24 ROBERTS, T M Commissioners ip 15490-156
- --B210120181 Requests that P Paris G Irwin & D Cooper, experts in fracture mechanics field, be invited to Commission 820504 briefing re pressurized thermal shock ROBERTG, T.M. Commissioners E Commissioners Ip 15690 159 82/04/21 PALLADIND.N
- --8210120176 Recommends approva) of SECY 81-570 proposed amend to IOUFR30.App E mad to emergency preparedness regulations ZECH, Q NRC No Detailed Affiliation Given B1/11/25 RGBERTS.T H Commissioners ip 15590 161
- --8210120202 Requests meeting during neit visit to Washington.DC to discuss subj of recent lir to NY Times ROBERTS.T M Commissioners 82/04/16 PARIS.P C Affiliation Unknown 1p 15690 162
- 7903090181 In accordance w/790118 application, Mati/Syproduct License 21~08362-12 for Dow Corning Corp is amended to read Cs-137 sealed sources for use in Dhmart Model SR-1 source holders for density & level measurements

  BASSIM, N Radioisotopes Licensing Branch (Pre 790501) 79/02/15 ĺΩ
- --8001080054 Mat1/Byproduct License 21-08362-12 for Dow Corning Corp is renewed per 790622 application Amend 5 authorizes Cs-137 for source holders for density measurement COUPER.J W Licensing Management Branch 79/11/07 3pp
- --8006050154 Mati/Dyproduct Lirense 21-08362-07 for Dow Corning Corp 16 amended per 800227 ktr Amend 9 changes Condition I4 as described in 800227 ltr PETTIJOMN 5 L Region 3, Chicago, Office of the Director 80/03/17 Ιø
- ~-8006050188 Matl/Byproduct License 21~08362-12 for Dow Corning Corp is amended per 800229 Itr Amend 6 changes Conditions 15 & 18 t allows use of incensed matt by J Banderson, J Laicht, D Goff & others PETTIJOHN, S.L. Region 3. Chicago, Office of the Director 80/03/17 ip 15748 094
- --B006170030 Matl/Byproduct License 21-08362-08 for Daw Corning Corp. is amended in its entirety per 770109 application Amend 10 authorizes use of C-16, tritium, P-32, I-125, I-131 & S-35 for biological tracer studies in plants JONES, J A Licensing Management Branch 80/05/06 200
- ---800B070143 Mat1/Byproduct License 21-08362-12 for Dow Corning Corp is amended per 800328 ltr Amend 7 authorizes users of of licensed mat1 PETTINGHN, 8 L Licensing Management Branch 80/06/26 1p
- --8101270870 Mat1/Buproduct License 21-08362-12 for Dow Corning Corp is amended per 801014 It Amend authorizes J Sanderson, J Esicht. B Goff, A Shovan D Wingert et al to use or supervise use of licensed mat! PETTIJOHN, S L Region 3. Chicago, Office of the Director 80/11/20 ip 15748 096
- ---8102280195 Mat1/Byproduct License 21-08362-12 for Dow Corning Corp is amended per 801014 ltr Amend 8 changes reading of Condition 12 re users of licensed matl (corrected copy), COPPER, J W Region 3, Chicago, Office of the Director 81/02/02 15748 097
- --8103160338 Mat1/Buppoduct License 21-08362-05 for Dow Corning Corp is amended per 801014 ltr Amend 14 changes Conditions 12 & 16 GUINN, P.R Licensing Management Branch 81/02/11 ip

- ---BIO3160346 Mat1/Byproduct License 21-08362-13 for Dow Corning Coff #6 amended per B01022 ltr Amend 3 changes Condition 12 & 14 re users, possession & use of licensed mat1 GUINN,P R Licensing Management Branch 81/02/17 ip 15748 107
- --8104170703 Mat1/Byproduct License 21-08362-05 for Dow Corning Coff \*1 amended per Amend 14 changes reading of Conditions 12 & 16 re use of licensed matl (corrected copy) GUINN,P R Licensing Management Branch 81/03/23 ip
- --8210180030 Mati/Byproduct License 21-08362-01 for Dow Corning Coff-authorizing possession & use of 10 Ci tritium.100 mCi C-14 k 100 mCi Cl-36 in any form for lab chemical research BRINKMAN,R E Atomic Energy Commission 62/04/26 ip 1574B 004
- -8210180032 Amend 1 to Met1/Buproduct License 21-08362-01, adding 100 cci 8-35 in any form for lab chemical research per 670311 application
  BRINKMAN.R E Atomic Energy Commission 63/03/20 jp 15748 005
- --8210180034 Amend 2 to Matl/Byproduct License 21-08362-01, priending expiration date to 660430, per 640127 application BRINAMAN, R E Atomic Energy Commission 64/02/24 1p 15748 006
- ~-BRI0180036 Amend 3 to Matl/Hyproduct License 21-08362-0), increasing max amount of C-14 in any form per 640507 application BRINKMAN R E Atomic Energy Commission 64/06/04 ip 15748 007
- --82:0180038 Amend 4 to Hatl/Byproduct License 21-08362-01.changing license in entirety per 660308 application Amend authorities possession of britismsC-14 & CI-36 in any form for lab chemical research & activation analysis
  BRINKHAN.R E Atomic Energy Commission 66/03/21 day 15748 008
- 15748 010
- --B210180041 Amend 6 to Met1/Byproduct License 21-00362-01, changing expiration date to 780430 & amending Condition 12 re years of byproduct mati, per 730201 itr BRINKMAN, R E Atonic Energy Commission, Directorate of License 73/02/14 1p 15748 011
- --8210180042 Amend 7 to Matl/Byproduct License 21-08342 Oi.changin. Condition 14 repossession & use of byproduct mati described in Items 6.7 & 8.per 740529 Ite Atomic Energy Commission, Directorate of Licensing 74/1045 15748 012
- --8210180043 Amend B to Matl/Byproduct License 21~08362 01, thangar Conditions 12 & 14 re possession & use of byproduct mail. per 750304 application # Licensing Management Branch 75/06/26 in 15/40 des Licensing Management Branch 75/06/26 ip 15/48 Q1.4
- -- 8210180046 Amend 9 to Mati/Byproduct License 21-08362 Olichampar license in entirety per 780328 application Amend authorises possession of tritium C-14.C1-36.8-35 & any byproduct met. w/Atomic Numbers 3-83 inclusive in any form COMBS,F C Radioisotopes Licensing Branch Radioisotopes Licensing Branch (Pre 790501) 2pp 15748 014
- --B210180049 Mat1/Byproduct License 21-08362-05 for Dow Corning C Alothough mariyopproduct literas at homosoft for bost correst as chark authorizing possession of Br-90 sealed sources as chark sources in Victorsen remote area monitoring sys HOMELL, D. B. Atomic Energy Commission 66/09/02 2pp 1574
- --8210180051 Amend 1 to Matl/Bygroduct License 21-08362-03-add byg BNL MK-1 strip sources, per 660907 to 22 ltrs CHURCHILL, BW Atomic Energy Commission 66/09/27 lp
- --B210180054 Amend 2 to Mati/Byproduct License 21-08362-05.Fe=1 Subitams 6.B.7.8 & B. Sto authorize possession of 25.000 c. s Co-60 8N. NA-1 strip sources, per telegram received 64121/6 CHURCHILL, S.W. Atomic Energy Commission 66/12/29 1p 15748.019
- --8210180037 Amend 3 to Matl/Byproduct License 21-08362-05.cham sitesses in entirety. Amend authorizes Co-60 BML MK-L strip sources for use in hat cell for irradiation of matts & Br. Qc CHURCHILL. 8 W Atomic Energy Commission 67/01/30 3pp

- --2210)80058 Amend 4 to Moti/Byproduct License 21-08362-05, deleting Condition 16.per 670405 ltr CHRCHILL, 9 W Atomic Energy Commission 67/04/27 lp
- --P210180061 Amend 5 to Matl/Byproduct License 21-08362-05, changing Substems 7 A & 8 A to read 35.000 Ci sealed sources (BNL MA-1 strip sources or Neutron Products Inc Catalog IP1-12CC5 clad wire).per 710609.0709 & 0820 ltrs MALARO.J C Atomic Energy Commission 71/08/30 lp 15748 024
- --8210160064 Amend & to Mati/Byproduct License 21-08362-05, changing license in entirety per 711227 application Amend authorizes Co-60 sealed sources for use in hot cell for irradiation of eatls & ST-90 sealed sources as check sources (HENDRIE, O H. Atomic Energy Commission 72/01/25 3pp 15748 025
- --BZIO180066 Amend 7 to Mat1/Byproduct License 21-08362-05, changing Conditions 12 & 15 re user & possession & use of byproduct nat1-per 740527 ltr
  DAVIS.F C Atomic Energy Commission, Directorate of Licensing 74/07/23 ip 15748 028
- --8210180072 Amend 8 to Mat)/Byproduct License 21-08362-05, changing Conditions 12 to 15 recuser to possession to use of byproduct asti-per 741121 to 750623 ltrs
  SWPE-M W Licensing Management Branch 75/07/22 1p 15748 029
- --B210180075 Amend 9 to Mat1/Byproduct License 21-08362-05.changing Condition 12 re user of lirensed mat1.per 750818 ltr CDLLINS.D M Licensing Management Branch 75/10/09 lp 15748 030
- --8210180076 Amend 10 to Matl/Byproduct License 21-08362-05, changing Condition 12 re user of licensed matl.per 761112 application BASSIN. N Radioisotopes Licensing Branch (Pre 790501) 77/01/17 ip 15748 031
- --B210180080 Amend ii to Matl/Nyproduct License 21-08362-05, changing license in entirety per 761222 application Amend authorizes Co-60 sealed sources for use in hot cell for irradiation of eatls & Sr-90 sealed sources as check sources ASSINAN Ratioisotopes Licensing Branch (Pre 790501) 77/05/06 3pp 15748 032
- -- \$21018081 Amend 12 to Matl/Byproduct License 21-08362-05, changing Condition is repasses ion & use of licensed matl.per 771212 application BASBIN.N Radioisotopes Licensing Branch (Pre 770301) 78/08/13 to 15748 035
- --8210180085 Amend 13 to Matl/Byproduct License 21-08362-05, adding Co-60 saled sources for use in Traceriab Model DC-1 dosimeter calibrators for dosimeter calibrators 780307 application COMBS.F C Radioisotopes Licensing Branch (Pre 790501) 78/04/20 19 15748 036
- --8210180089 Amend 15 to Mati/Duproduct License 21-08362-05, changing license in entirety per 811228 application Amend authorites 8r-90 & Co-60 sealed sources as check sources in Victorean area monitoring sys & as dosimeter calibrators GUNN,P R Licensing Management Branch 82/04/19 3pp
- ~82(0180092 Corrected Amend 15 to Matl/Byproduct License 2:-08362-05, changing license in entirety per 8:1228 application Amend authorizes Br-90 & Co-60 sealed sources as check sources in Victorien area monitoring sys & as dosimeter calibrators QUINLPR Licensing Management Branch 82/05/04 3pp 15748 042
- --8210180076 Mat1/Byproduct License 21-08362-07 for Dow Corning Curpauthorizing tritium as foils in F & M Model 2-2837 detector cell for use w/gas chromatography unit for sample analysis BRINKMAN.R. E. Atomic Energy Commission 67/10/12 2pp. 19748 045
- --8210180098 Amend 1 to Matl/Byproduct License 21-08342-07, changing Consistion 12 re user of byproduct matl.per 681224 ltr. + Atemic Energy Commission 69/01/10 ip 15748 047
- --B210180102 Amend 2 to Mati/Byproduct License 21-08362-07, changing license in entirety per 691113 ltr Amend authorizes tritium as foils in F & H Model 2-2837 detector cell for use w/gas chromatography unit for sample analysis.
  BRINKHAN, R E Atomic Energy Commission. 69/11/21. 2pp 13748 0an

- ---8210180105 Amend 3 to Matl/Byproduct License 21-08362-07, changing Condition 14 re possession & use of byproduct matl/per 700312 ltr
  BRINKMAN R & Atomic Energy Commission 70/03/23 ip 15748 050
- --8210180108 Amend 4 to Matl/Ryproduct License 21-08362-07.changing expiration date to 771031 & amending Condition 12 re user of byproduct matt, per 720912 application
  BRINKHAN-R E Atomic Energy Commission 72/10/12 ip
  15748 051
- --8210180111 Amend 5 to Matl/Byproduct License 21-08362-07, changing Condition 14 re possession & use of byproduct matl, per 740529 ltr
  - \* Atomic Energy Commission, Directorate of Licensing 74/06/20 16 15748 052
- --8210180113 Amend & to Matl/Byproduct License 21-08362-07,changing Condition 14 re possession & use of licensed matl.per 761203 application 4 Radioisotopes Licensing Branch (Pre 790501) 77/01/10 lp
- --B2101B0115 Amend 7 to Matl/Byproduct License 21-08362-07, changing Conditions (2 & 14 re user & possession & use of licensed math,per 751222 application

  \* Radioisotopes Licensing Branch (Pre 790901) 77/03/04 ip 15748 054
- --B210180116 Amend 8 to Matl/Syproduct License 21-08362-07.changing license in entirety per 770928 application Amend authorizes tritium as US Radium Lab Model 508-1 foils in Howlett-Packard Model 2-2837 detector cell JONES, J A Radioisotopes Licensing Branch (Pre 790501) 78/04/10 2pp 15748 055
- --8210180118 Mat1/Byproduct License 21-08362-08 for Dow Corning Corpartherizing C-14, tritium & P-32 in any form for use in biological tracer studies on animals & microorganisms BUCHANANIC R Atomic Energy Commission 69/01/09 2pp 15748-058
- --8210180121 Amend 1 to Mat1/Ryproduct License 21-08362-08, changing license in entirety per 681113 ltr Amend authorizes C-14, tritium & P-32 in any form for use in biological tracer studies on animals & microorganisms
  BRINKHAN, R C Atomic Energy Commission 69/11/21 ip 15/48 060
- --B210180125 Amend 2 to Met1/Byproduct Litense 21-08362-08, changing Condition 13 re possession & use of byproduct mat1.per 700312 itr BRINKMAN.R E Atomic Energy Commission 70/03/20 lp 15748 OA1
- --8210180127 Amend 3 to Mat1/Dyproduct License 21-08362-08, adding I-125 & I-131 in any form for use in biological tracer studies on animals, plants & microorganisms, per 720814 ltr
  DRINKMAN.R E Atomic Energy Commission 72/09/25 1p
  15748 062
- --B2101B0130 Amend 4 to Matl/Buproduct License 21-0B362-0B, changing expiration data to 790131 & amending Condition 12 ra user of Syproduct matiser 731206 application BRINKMAN, R E Atomic Energy Commission, Directorate of Licensing 74/01/04 lp 1574B 063
- --82i0180132 Amend 5 to Matl/Dyproduct License 21-08362-08, adding 8-35 in any form for use in biological tracer studies on animals, plants & microorganisms, per 740306 ltr # Atomic Energy Commission. Directorata of Licensing 74/03/20 ip
- --B210180135 Amend 5 to Matl/Byproduct License 21-08362-08, changing Condition 13 re possession & use of byproduct matl.per 740329 ltr \* Atomic Energy Commission, Directorate of Licensing 74/06/20 fp 15748 065
- --8210180139 Amend 7 to Matl/Byproduct License 21-08362-08, changing Condition 13 re possession & use of licensed matl.per 761203 application.

  \* Radioisotopes Licensing Branch (Pre 790501). 77/01/10 | lp
- --B210180140 Amend B to Matl/Byproduct License 21-08362-08, changing Conditions 12 & 13 re user & posession & use of licensed matl.per 761227 application BASBINN Radioisotopes Licensing Branch (Pre 790501) 77/03/02 ip 15748 067.

- --B210180145 Amend 9 to Matt/Byproduct License 21-08362-08, changing Subitems 8 A & B B to read 150 mCi & 50 mCi, respectively & amending Condition 13 re possession & use of licensed matt, per 780403 ltr HR10HT.E G Radiossotopes Licensing Branch (Pre 790501) 78/08/10 1p 15748 068
- --8210180150 Mati/Byproduct License 21-08362-09 for Dow Corning Corp. authorizing Ni-63 as folls in detector cells (Hewlett-Packard 2-6195) for use in gas chromatography unit for sample analysis
  BRINMAN, R & Atomic Energy Commission 69/03/14 3pp 15748 071
- --9210180152 Amend 1 to Matl/Byproduct License 21-08362-09, adding tritium as sitanium tritide foils in detector cells for use in gas chromatograph for chemical analysis, per 700707 application

  BRINKMAN, R E Atomic Energy Commission 70/07/22 1p 15748 074
- --8210180157 Amend 2 to Matl/Byproduct Literse 21-08362-09, adding Ni-63 as folls in detector cells (Hewlett-Packard 19713A) for use in Hewlett-Packard gas Chromatography unit for sample analysis.per 730329 ltr
  BRINKMAN.R E Atomic Energy Commission 73/05/02 1p
- --8210180159 Amend 3 to Mat1/Byproduct Liters# 21-08362-09, changing expiration date to 79031 & amending Condition 12 re user of byproduct mat1, per 740227 application 

  \* Atomic Energy Commission, Directorate of Licensing 74/04/01 in 15749 076
- --8210180164 Amend 4 to Mati/Dyproduct License 21-08362-09, changing Condition 14 re possession & use of byproduct mati, per 740529 ltr \* Atomic Energy Commission, Directorate of Licensing 74/06/20
  - Atomic Energy Commission, Directorate of Licensing 74/06/20
     15748 077
- ~~8210180168 Amend 5 to Matl/Ryproduct License 21-08362-09.changing license in entirety per 790288 application Amend authorizes Ni-63 & tritium as foil source for use in gas chromtography units for sample analysis COPPER.J W Licensing Hanagement Branch 79/03/14 4pp 19748 078
- --8210180171 Matl/Buproduct License R1-08362-12 for Dow Corning Corp. authorizing Cs-137 sealed source for use in Dhmart Model RD-4 density gauge \* Atomic Energy Commission. Directorate of Licensing 74/07/16 App 15748 082
- --B210180173 Amend 1 to Matl/Byproduct License 21-08362-12, adding Cs-137 sealed source for use in source holder for measurement of gips fluid density, per 750729 ltr

  4 Radioisotopes Licensing Branch (Pre 790501) 74/05/28 2pp
- --B210180176 Amend 2 to Matl/Byproduct License 21-08062-12.changing Conditions 12.14 D.15 & 16 re user of licensed matl, performance of tests for leskage/contamination & maint, repair & radiation survey.per 761223 ltr
  BELL.J M Radioisotopes Licensing Branch (Pre 790501) 77/07/29 2pp 66383 193
- --B210180178 Amend 3 to Mat1/Byproduct License 21-08362-12, changing Bubitems B & C of Items 6.7 & B & adding Cs-127 sealed sources for use in source holders for measurement of pipe density & level.per 770727 & 1206 ltms Radioisotopes Licensing Branch (Pre 770501) 77/12/20 ip-15748 039
- --8210180194 Matl/Byproduct License 21-08362-13 for Dow Corning Corp. authorizing Co-60 sealed sources for use in two irradiation reaction vessels for irradiation of matls to produce
  - (Pre 790501) 77/03/22 3pp

- --B210180213 Amend 4 to Matl/Byproduct License 21-08362-13, changing Items 6:7,8 & 9 to read Co-60 sealed sources for use in three irradiation reaction vessels for irradiation of matls to produce chemical synthesis.per B1031 itr QUINN.P & Licensing Management Branch 81/04/21 ip
- --BR10180215 Responds to AEC 411220 ltr re violations noted in Insp of License 21-00265-01 on 610307-10 Corrective actions amend to license requested to permit use of two addl Co-60 sealed sources & tags fastened to each source holder BEAHER, H.H. Dow Chemical Co. 40367 62/01/02 PRICE, E. Atomic Energy Commission Rep. 15748-109
- --8210180219 Corrects 610109 ltr requesting increase in quantity of Cs-137 on License 21-00265-01 Limit of Cs-137 scaled sources requested to be increased to 6,000 mCl foo sealed sources containing 1,500 mCl each of Cs-137 will be ordered BEAMER.W H Dow Chemical Co 31801 61/01/12 ROGERS.L R Atomic Energy Commission ip 15748 iii
- --B2101B0222 Requests that limit of Cs-137 sealed sources on License 21-00265-01 be increased to 3:000 mci Sealed source containing 1,500 mci Cs-137 will be installed as part of liquid level controller instrument BEAMER.W H. Dow Chemical Co. 3:B07 61/01/09 ROGERB.L R Atomic Energy Commission ip 15748 112
- --8210180229 Inquires about possibility of amending License 2[-00065-i to increase 1 Ci per yr limit for disposal of tritiated water into effluent sewage stream KEAMER.W H Dow Chemical Co 58/12/24 BOWYER.J E Atomic Energy Commission ip 15748 113
- --0210180234 Describes relationship of Bechtel Corp to Bow Chemical (
  (DCC) as agent in purchase of four radioactive Cs-137
  sources, per AEC 580616 request Bources will be in physical
  possession of DCC before & after installation
  BEAMER! HH Dow Chemical Co 58/06/24 BOWYER, J E Atomic
  Energy Commission ip 15748 114
- --8210180239 Application for renewal of Matl/Byproduct Licenses 21-00265-06, 21-00265-02, 21-00265-04, 21-00265-07, SNM-1253, STB-527 & R-108 authorizing any byproduct matl between Atomic Numbers 3 & 83, tritium, Po-210 & Am-241 HOYLE:N R Dow Chemical Co 38682 73/06/25 2pp
- --8210180247 Forwards application for renewal of Matl/Bygroduct Lice 21-00265-06 List of plant locations including three plants not authorized under current license & description of byproduct matl used in lower animals encl H/o application HOYLE.H R Dow Chemical Co 38652 73/06/18 CUNNINGHAM.R & Atomic Energy Commission 3pp 15748 117
- --8210180251 Forwards application for renewal of Matl/Byproduct 1.1c1 21-00265-01 & 21-00265-02 Sample of isotope data card & revisions to radiation protection manual enci BEAMER, W H Dow Chemical Co. 28079 60/07/21 MASON, J R. Atomic Energy Commission 5pp 15748 120
- --8210180297 Application for renewal of Mati/Byproduct Licenses 21-00265-01 & 21-00265-02 authorizing use of Elements 3 through 83 in any form tritium sealed source for R&D Saaled source inventory entl BEAMER.W H Dow Chemical Co. 25079 60/07/21 5pp 13748 |
- --B210180260 Ack receipt of 600113 Amend B to Matl/Dyproduct Licent 21-00265-01 adding authorization for use of Pm-147 sources at Bay City plant. Daw Chemical Co will possess beta ray instrument ordered by Bachtel BEAMER, H H Dow Chemical Co 60/01/29 BRINKMAN-R E Atomi-Energy Commission 19 15748:130
- --8210180262 Application for math/byproduct license authorizing E1 i to 84 inclusive in any form for use in chemical & agricultural R&D. tracer problems & as sealed sources in instruments. Std for control of radiation hazards encl BEAMER. W M Dow Chamical Co 56/04/03 20pp 15748-131
- ~-8210180266 Forwards application for renewal of Matl/Byproduct & i 21-00265-06 BEAMER, W. H. Dow Chemical Co 66/06/10 Atomic Energy Commission. 1p 15749 151
- ~-8210180270 Amend if to Mat1/Byproduct License 21-00265-03, chang Condition if re user of byproduct mat1 & adding Condition 13 to require compliance w/locke20.chapter i. "Stds for Protection Against Radiation," per 590105 ltr + Atomic Energy Commission 59/01/29 ip. 15748 155

ITVITE CONTINUE TO A STATE OF THE PARTY OF T

- --8210180275 Mati/Bygroduct License 21-00265-03 for Dow Chemical Co. authorizing Co-60 as aluminum clad slugs in steinless steel rods per Dow Chemical Drawing NDI-3492 for use in gamma rous per now chemical prawing NDI-3492 fo irradiator to initiate chemical reactions a Atomic Energy Commission 57/09/10 1 n
- --8210180277 Matl/Byproduct License 21-00265-02 for Dow Chemical Co. riusbuz// nati/byproduc witense ex-dukeb-uz for Dow Chemic author(ing Co-60 as cylindrical sealed source & aluminum clad siugs in copper rods per 560706 ltr for use in radiation chemistry studies a Atomic Energy Commission 56/09/21 2pp 15748 157
- ~-82101802B2 Amend 1 to Matl/Byproduct License 21-00265~02, adding Co-60 sealed sources for use in high level radiation chemistry research.per 370115 application
   Atomic Energy Commission 57/02/25 ip 15748 159
- --B2[0]B02B4 Amend 2 to Matl/Byproduct License 21-002A5-02, changing Conditions if & 12 re user of byproduct matl & compliance w/IOCFR2O.Chapter 1, "Stds for Protection Against Radiation" respectively, per 990105 ltr MASON, J R Atomic Energy Commission 59/01/29 lp 15748 160
- --B230180267 Amend 3 to Mat1/Byproduct License 21-00265-02, changing license in entirety per 610711 application Amend authorizes Co-60 as BNL cylindrical source & aluminum clad cobalt slugs for use in irradiator & hot cell for experimental studies MASON, J R Atomic Energy Commission 61/07/19 2pp 15748 16 1574R 161
- -- P210180270 Amend 4 to Mat1/Byproduct License 21-00265-02, changing PIGEORYO Amena a to natr/Buproous Litemse at-ouses-Os/shanging litemse in entirety per 620831 itr Amend authorizes Co-80 as cylindrical source in aluminum & as aluminum clad slugs in stainless steel for use in irradiator & hot cell BELL-J M Atomic Energy Commission 62/07/24 2pp 18748 163
- --B210180295 Amend 5 to Matl/Dyproduct License 21-00265-02, changing license in entirety per 620925 ltr Amend authorizes Co-60 as cylindrical source in aluminum & as aluminum clad slugs in stainless steel for use in irradiation & hot cell BELLJ M Atomic Energy Commission 62/11/09 3pp 15748 16
- --8210180278 Amend & to Matl/Suproduct License 21-00265-02, changing Conditions 13 & 14 re possession & use of byproduct matl & written instructions concerning operating procedures for cobalt radiation sources & facilities, per 621219 ltr BELL-J H Atomic Energy Commission 63/01/28 lp 15748 168
- --B210180301 Amend 7 to Hatl/Byproduct License 21-00265-02, adding Cendition 19 authorizing disposal of 100 mCi Co-60 by autid, per 621219 ltr BELL.v H Atomic Energy Commission 63/02/28 lp 15748 id
- --8210180304 Amend B to Mat1/Byproduct License 21-00265-02, adding 330 Ci erolbushe Amen B to narrybyproduct License 21-00263-026 add: Co-60 as BNL cylindrical source in aluminum for use in fraduator device & revising Subitems 9B & Conditions 13 & 14 rs possession of byproduct math.per 630418 & 0317 ltms BUCHANAN.C R Atomic Energy Commission 63/06/23 2pp 15748 170
- --8210180307 Amend 9 to Matl/Dyproduct License 21-00265-02, deleting Bubitems C of Items 6.7.8 & 9 & Condition 18, per 660125 ltr HOHELL, D B. Atomic Energy Commission. 66/02/17 ip 15748 172
- --8210180310 Amend 10 to Mat1/Buproduct License 21-00265-02, extending espiration date to 710930 deleting Subitems 6A, 7A, 8A & 9A & revising Subitems 7B, per 660705 application 9046ELL, 0 B Atomic Energy Commission. 66/09/01 ip 15748, 173
  - 210180312 Amend 11 to Matl/Byproduct License 21-00265-02, adding Condition 20 to permit transfer of byproduct matl to new irradiation facility.per 661017 ltr CHURCHILL B W. Atomic Energy Commission 66/11/02. Ip 1574B 174
  - 210180315 Amend 12 to Matl/Byproduct License 21-00265-02, changing license in entirety Amend authorizes Co-60 as aluminum clad slugs in stainless steel & as cylindrical source in aluminum for use in hot cell & irradiation device CKRCHILL-B.W. Atomic Energy Commission 67/01/25 3pp 15748 175
  - 5210180318 Amend 13 to Mat1/Byproduct License 21-00265-02, revising Bulitems 6 A7 A & B. A to read 15,000 Ci Cu-60 as aluminum clad slugs in stainless steel & adding Ca-137 as doubly sacapsulated stainless steel sources, per 670126 ltr. CHNRCHTLL/B W Atomic Energy Commission 67/02/15 ip. 19780 1579 13748 178

- -- 8210180319 Amend 14 to Mati/Buproduct License 21-00265-02, deleting Condition 17.per 670313 ltr BUCHANAN.C R Atomic Energy Commission 67/03/30 15748 179
- --8210180324 Amend 15 to Matl/Byproduct License 21-00265-02, revising Bubitem 9 A to authorize use of byproduct matl in hot cell or rediation reactor for irradiation of various matls, per 650415 tr BUCHANANC R Atomic Energy Commission 69/04/23 (p. 1574B 180
- --BR10180326 Amend 16 to Hatl/Buproduct License 21-00265-02, revising Condition 12 authorsising 48 Hoyle to use &/or supervise use of byproduct matl.per 700615 ltr MALARD, J.C. Atomic Energy Commission 70/07/06 1p 15748 181
- ---9210180328 Amend 17 to Matl/Byproduct License 21-00265-02, changing license in entirety per 710726 application Amend authorizes Co-60 as aluminum tlad silugs in stainless steel & Cs-137 as doubly encapsulated stainless steel sources MALARO, J C Atomác Energy Commission 71/08/16 3pp 15748 182
- --8210180333 Amend 18 to Matl/Byproduct License 21-00265-02.revising Condition 16 re possession & use of byproduct matl.per 711119 ltr HENDRIE: O W Atomic Energy Commission 71/12/21 ip 15748 JB5
- --8210180335 Amend 19 to Mat1/Byproduct License 21-00265-02, revising Condition 16 re-possession & use of licensed mat1-per College Colleg 15748 186
- --8210180337 Amend 20 to Matl/Byproduct License 21-00265-02, revising Condition 16 re possession & use of licensed matl.per 760909 ltr BASSIN:N Radioisotopes Licensing Branch (Pre 790501) 76/11/24 lp 15748 187
- --B210180340 Ameng 2 to Mat1/Byproduct License 21-00245-04.changing license in entirety per 651210 application Amend authorizes Co-60 sealed sources for use in industrial radiography by open-air handling techniques MILLER, W.O. Atomic Energy Commission 65/12/29 2pp 15748 188
- --8210180341 Amend 13 to Matl/Byproduct License 21-00265-04, adding Co-60 sealed source for use in Tech Ops Model 525 exposure device for industrial radiography & adding Conditions 14, C. 15 & 14, per 660729 ltr
  HILLER. H O Atomic Energy Commission 46/09/27 2pp 15748 190
- --B210180343 Amend 4 to Matl/Byproduct License 21-00265-04, changing license in entirety per 681227 application Amend authorizes Co-60 sealed sources for use in Tech Ops Model 525 exposure devices for industrial radiography
  MALARO.J C Atomic Energy Commission 69/01/17 4pp 13748 192
- --9210180344 Amend 5 to Mat1/Byproduct License 21-00265-04, changing Item 9, A & Condition 16 re-possession & use of byproduct mat1 BASSIN, N Atomic Energy Commission 72/05/19 1p 15748 196
- --8210180346 Amend & to Matl/Byproduct License 21-00265-04, changing license in antiraty per 731227 application Amend authorizes Co-60 sealed sources for use in Tech Ops Model 525 expasure devices & Model 416 source changers Licensing Management Branch 75/09/10 2 RERNER E P 15748 197

- --8210180353 Requests documents indicating disposal of all licensed math possessed under License 21-00265-04.per 770707 telcon in response to licensee 770627 request for bermination of incense Note of 770707 telcon encl JONES.J A Radjoisotopes Licensing Branch (Pre 770501) 77/09/13 WILLIAMS.P R Dow Chemical Co 2pp 15748 203
- --- 8210180354 Requests termination of Matl/Byproduct License 21-00265-04 Five Co-60 source used for industrial radiography disposed of via Nuclear Engineering Co at Sheffield. IL MILLAMS, P R Dow Chemical Co 88259 77/06/27 Redio Licensing Branch (Pre 790501) tp 15748 205 Radioisotopes
- --8210180358 Requests termination of Matl/Byproduct License 21-00265-04 Industrial radiographic source (2 J C: Co-60) shipped to Shaffield, IL by Nuclear Engineering Co for disposal Shipping racord encl THOMAS, B.R. Dow Chemical Co. 89463 77/08/25 JONES, J Radioisotopes Licensing Branch (Pre. 790501) 2pp. 15748 15748 204
- --8210180360 Mat1/Byproduct License 21-00265-06 for Dow Chemical Co. authorizing any byproduct mail between Atomic Numbers 3 & 83 inclusive w/listed exceptions in any form for use in R&D lab tracer studies Atomic Energy Commission 64/08/14 3pp 15748 208
- --8210180363 Amend 1 to Matl/Byproduct License 21-00265-06, increasing max amount of Kr-85 from 10 Ci to 25 Ci & revising Condition 11 re use of instruments, devices & gauges containing sealed sources, per 650414 ltr
  BRINKMAN R E Atomic Energy Commission 65/04/28 ip 15748 211
- --8210180366 Amend 2 to Matl/Byproduct Eleense 21-00265-06, adding Pe-210 as static eliminators & revising Condition 11 re use of instruments. devices & gauges containing sealed sources.per Atomic Energy Commission 45/08/18 1p 15748 212
- --8210180367 Amend 3 to Mati/Byproduct ticense 21-00265-06,adding Po-210 in any form for use in R&D, per 651006 ltr + Atomic Energy Commission 65/10/29 ip 15748 213
- --8210180370 Amend 4 to Matl/Byproduct License 21-00265-06, revising Condition 11 re use of instruments, devices & gauges containing sealed sources.per 660214 ltr
  BUCHANANC R Atomic Energy Commission 66/02/24 lp 15748 214
- --8210180372 Amend 5 to Hat1/Byproduct License 21-00265-06.changing license in entirety per 660610 ltr Amend authorizes any byproduct mat1 between Atomic Numbers 3 % 83 inclusive. tritium & Po-210 in any form for use in R&D BRINKMAN.R E Atomic Energy Commission 66/06/29 App 16748-315 15748 215
- --8210180373 Amend & to Mati/Byproduct License 21-00265-06, revising Condition 16 re possession & use of byproduct matl.per 660722 1tr BRINKMAN, R E Atomic Energy Commission 66/08/08 15748 219
- --B210180374 Amend 7 to Matl/Ryproduct License 21-00265-06, adding Am-241 & 80-239 in any form for use in analytical chemistry tracer experiments, per 661216 ltm
  - Atomic Energy Commission 67/01/03 ip 15748 220
- --8210180375 Amend 8 to Matl/Byproduct License 21-00265-06, adding Po-210 sealed source for use in storage & testing of instruments & revising Condition 16 re possession & use of byproduct matl. per 670525 telegram BUCHANAN.C R Atomic Energy Commission 67/06/01 ip 15748 221
- ---8210180376 Amend 7 to Mati/Byproduct License 21-00265-06, changing Subitem 8 F to read 10 Ci.per telegram received 670608 \* Atomic Energy Commission 67/06/15 ip 15748-222
- --8210180377 Amend 10 to Matl/Byproduct License 21-00265-06, changing license in entirety per 680627 application Amend authorizes any byproduct matl between Atomic Numbers 3 & 83 inclusive, 5 tritium, Po-210, Am-241 & Pu-297 in any form BRINKMAN.R E Atomic Energy Commission, 68/07/16 4pp 15748 223
- --8210180379 Amend 11 to Matl/Byproduct License 21-00265-06, changing Subitem 8 8 to read 60 Ci.per 681223 ltr \* Atomic Energy Commission 69/01/10 1p 15748, 227

- --8210180380 Amend 12 to Mat1/Byproduct License 21-00265-06 changing Subitem B A to limit radionuclide to 1 Ci except for Kr-85, Cs-137,Co-60, 6r-90 & C-14.per 700115 ltr BRINKMAN.R E Atomic Energy Commission 70/01/26 1p 15748 228
- --8210180381 Amend 13 to Matl/Byproduct License 21-00265-06.changing Condition 12 re user of byproduct matl.per 700615 ltr \* Atomic Energy Commission, 70/06/25 tp 15748 229
- --8210)80383 Amend 14 to Mati/Byproduct License 21-00265-05, changing Condition 10 re use of byproduct matl.per telegram received BRINKMAN, R E Atomic Energy Commission 71/03/25 1p 1574B 230
- --8210180386 Amend 15 to Matl/Byproduct License 21-00265-06, adding Am-24 sealed sources for use in developments standardization & testing of instruments devices & gauges per 710809 ltr BRINKHAN R E Atomic Energy Commission 71/08/20 ip 15748 231
- -- 9210180387 Amend 16 to Matl/Byproduct License 21-00269-06, changing Subitem 8 0 to read 11 Ci.per 711118 ltr BRINMAN.R E Atomic Energy Commission 71/11/30 ip 15748 232
- --8210180391 Amend 17 to Mati/Byproduct License 21-00265-06, changing Substem B Q to read 15 Ci.per 720107 ltr BRINXMAN.R E Atomic Energy Commission 72/01/19 1p 15748 233
- --8210180394 Amend 18 to Matl/Byproduct License 21-00265-06, changing Subitem 9 0 re use of licensed matl, per 720509 ltr BRINKMANLR E Atomic Energy Commission 72/05/24 1p
- --B210180397 Amend 19 to Matl/Byproduct License 21-90265-06, changing Subitem 8 0 to read 25 Ci.per 720721 1tr BRINMAN.R C Atomic Energy Commission 72/08/03 1p 15748 235
- --B210180399 Amend 20 to Matl/Byproduct License 21-00265-06, changing Subitem 8 A to limit radionuclide to 1 Ci w/exceptions of Kr-85, Ce-137, Co-60, Sr-90 & C-14 & deleting Bubitems 6 C.7 E. 8 E & 9 E. per 730222 ltr BRINKMAN, R E Atomic Energy Commission. Directorate of Licensing 73/03/08 lp 15748 236
- ~~8210180402 Amend 21 to Mat1/Byproduct License 21~00265~04, changing Subitem 8 0 to read 40 Ci.per 730301 ltr BRINKMAN:R E Atomic Energy Commission, Directorate of Licensing 73/03/27 1p 15748 237
- ~-8210180406 Amend 22 to Matl/Byproduct License 21~00265~06, changing license in entirety per 730625 application Amend authorites any byproduct matl between Atomic Numbers 3 & 83. tritium. Po-210 & Am-241 in any form & Po-210 & Am-241 sealed source BRINKMAN.R & Atomic Energy Commission. Directorate of Licensia 73/07/31 App 15748 238
- ~-8210180409 Amend 23 to Hatl/Byproduct License 21~00265-0A.ch.ang.ing Subitom B B to read 100 Ci.per telegram received 730906 BRINKNAN.R E Atomic Energy Commission, Directorate of Licenser 73/09/26 ip 15748-242
- --B2101B0410 Amend 24 to Mat1/Byproduct License 21-00265-06, changing Subitsm B F to read 75 Ci,per 740401 ltr Atomic Energy Commission, Directorate of Licensing 74/04/1 15748 243 1 p
- --8210180413 Amend 25 to Math/Sygroduct License 21-00265-06.changin Conditions 10 & 16 re possession & use of byproduct math, per 740827 telegram \* Atomic Energy Commission, Directorate of Licensing 74/09/0
  - 15748 244
- --B2101B0417 Amend 26 to Matl/Byproduct License 21-00265-06.adding sealed sources for use in process control instrumente & Eberline Model 1000 calibrator.per 750103 ltr
  BELLJ M Licensing Management Branch 75/03/20 ip 15-748
- ---8210180421 Amend 27 to Matl/Byproduct License 21-00265-06.rsvize Bubitems 8. A, B F, P A, P 8 & P C re amount of redictoclide & use of licensed matl.per 750407 ltr \* Licensing Management Branch 75/07/11 1p 15748 24&

- --8210(80422 Amend 28 to Matl/Byproduct License 21-00265-05, revising Substems 9 A.B & C re use of licensed mati, per 750714 application BASSIN.N Licensing Management Branch 75/09/04 1p 1574B 247
- 8210180423 Amend 27 to Matl/Byproduct License 21-00245-01, revising Condition 16 re possession & use of licensed matl.per 740315

  1tr
  a Radioisotopes Licensing Branch (Pre 790501) 76/05/19 19
- 8210180425 Amend 3D to Mat1/Byproduct License 21-00265-06, revising Condition 10 re use of Fe-55 & Am-241 sealed sources, per 760706 application a Radioisotopes Licensing Branch (Fre 790501) 76/08/26 1p
- -821018042A Amend 31 to Matl/Byproduct License 21-00265-04, revising Conditions 10 & 16 re possession & use of licensed matl.per 780709.17 & 1019 ltrs BASSIN.N Radioisotopes Licensing Branch (Pre 790501) 76/11/30 to 15748 250
- --8210180427 Forwards up-to-date list of radiation detection instruments, per Item 15 of 660403 application for renewal of Matl/
  Byproduct License 21-00265-06
  BEAHER,H H Dow Chemical Co 66/07/22 BRINKMAN,R & Atomic Energy Commission. 2pp 15748 333
- --8210180428 Revised "Radiation Protection Manual" a Dow Chemical Co 73/01/31 159pp 15748 337
- --B210180429 Amend 32 to Mati/Byproduct License 21-00265-06, changing Subitem 8 A to limit radionuclide to 1 Ci w/exceptions of Ke-85.Cs-137, Co-60, Sr-90, C-14.mixed fission products & Ni-63 & revising Condition 16.per 761102 ltr BASSIM, N Radioisotopes Licensing Branch (Pre 790501) 77/04/11 jp 15748 251
- --B210180430 Application for amend to Matl/Byproduct License 21-00265-06. (creating dosing of rats & mice to 1,500 uCi C-14 or tritium per animal & 10,000 uCi per animal for monkeys forwards revised "Radiation Protection Manual" LANGER. F. Dow Chemical Co 2344 77/07/07 URIGHT, E. Radioisotopes Licensing Branch (Pre 790301) ip 15748 336
- --8210180431 Advises that use of polonium/beryllium neutron source for testing instruments under Matl/Byproduct License 21-00265-06 will cases after reactor OL becomes effective, per licensee 670511 & 16 ltrs.
  BEMER.N H Dow Chemical Co 67/05/25 HADDICAN, W Atomic Energy Commission Ip 15748 335
- --g2i0l90432 Amend 33 to Matl/Byproduct License 21-00265-06, changing Condition 11 re use of licensed matl.per 770404 ltr s Radioisotopes Licensing Branch (Pre 790501) 77/04/25 ip 15748 282
- --8210180434 Application for renewal of Matl/Byproduct Licanse 21-00265-06: authorizing any byproduct matla w/Atomic Numbers 1-83,Po-210 & Am-241 in any form for use in RRD LANDER:R R Dow Chamical Go 95118 78/06/14 60pp 15748 261
- --8210180436 Corrected Amend 39 to Matl/Byproduct License 21-00265-06, changing Condition 17 re possession & use of licensed matl & affing Condition 18 re disposal of licensed matl, per 801029 ltr HALETT, B 8 Licensing Management Branch 81/09/03 ip
- tilliggoar Aidl response to FOIA request for tape recordings of interviews w/F Oitz on 810225 & 0604 Forwards emitted transcript pages. W/o encl.
  FRITOM JH Division of Rules and Records 82/10/04 HICKEY, J. P. Shew, Fittman, Potts & Trombridge, ip 15758 353

- 8210190079 Partial response to FOIA request for documents re NRC shakdown plan mentioned in weekly info rept for wk ending 810831 & SECY 81-600 & SECY 81-600A Forwards draft Manual Chapter 1302
  FELTON.J M Division of Rules and Records 82/10/01 CONNOR.L Doc-Search Associates Ip 15758 312
- --82(0050573 Forwards draft Manual Chapter 1302, "Shutdown Plan Contingency Plan for Periods of Lapsed Appropriations," for review & comment BARRY.L W Office of Resource Management, Director 82/09/03 NRC No Detailed Affiliation Given 37pp 15758 313
- 8210190094 Responds to FOIA request for NRC Annual Rept to Congress for 1981 Formards document W/o encl FELTON, J M Division of Rules and Records 82/10/06 SCHULKE, S Affiliation Unknown ip 15758 310
- 8210190112 Partial response to FDIA request for five categories of documents re SEP Forwards documents listed in App A App B lists documents available in FDR FELTON. J M Division of Rules and Records 82/10/06 GALLD. J Isham, Lincoln & Beale 3pp 15758 191
- --8210190115 Responds to request for advice on applicability of general design criteria & 10CFR100. App A to older licensed facilities Sids of general design criteria must be used for assessing safety of all facilities SCINTO. J. Hearings Division 82/03/10 LAINAS. 9 Assistant Ofrector for Safety Assessment 4pp 15758 196
- --8210190121 Discusses legal questions concerning re-review program
  Backfitting recommendations premature, pending re-review for
  particular case
  SCINTO.JF Hearings Division 76/09/03 QDLLER.K R Division
  of Operating Reactors 3pp 15758 200
- --8210190124 Responds to BOO116 request for legal opinion re applicability of siting requirements of IOGFR100 to operating plants App A elements should be used in seismic adequacy Judgments for all reactors BC(NTG, Jf Hearings Division 82/10/06 VOLLMER, R Division of Engineering 2pp 15758 203
- --B002080095 Requests consultation re operating reactors legal obligation to fulfill code requirements re seismic & geologic considerations of proposed sites VOLMERR H Assistant Director for Sistems & Projects 60/01/16 CHRISTENDURY, E Hearings Division 2pp 15758 205
- 8210190144 Responds to FOIA request for SECY 82-232 re use of nonplant-specific simulators for initial replacement & requalification exams for licensed reactor operators & senior operators FELTON. If Division of Rules and Records 82/09/30 ARMSTRONG.K A Debevoise & Liberman 2pp 15760 178
- n=8206180042 SECY-82-232

  Recommends requirements of simulator licensing exam be constitued for power reactors w/plant-specific simulator Oral exam per 100FR58.23 should be administered where facility has no plant-specific simulator DIRCKB.W J Office of the Executive Director for Operations 82/06/07 14pp 16002 236
- --8210190159 Advices that Commission has approved reconting the specific DIRCKE
- 8210190189 Responds to J Hickey FOIA request for names & plant locations of all US facilities licensed to possess 100,000 or more GI Co-60 FELTON, J N Division of Rules and Records , 82/09/08 BUFFALD, V Gobe Laboratories
- --B210190191 "Co-A0 Irradiations w/Possession Limits of 100.000 Ci or Orester"

  W. NRC No Detailed Affiliation Given 82/09/08 2pp 13788.337.
- 821021007) Responds to FGIA request for retords re disposal of radwaste & chemical & medical wastes at St Albans Hosp in Gueens, NY NRC has no documents subj to raquest FELTON, J M. Division of Rules and Records. 82/09/30 FREEDBERG-L. Youth News 1p. 13774-314.

- 8210270083 Add1 response to FOIA request for eight categories of LERs Forwards documents listed in App A App B documents withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/09/20 ARNOLD, J Miami Herald 4pp 15836 221
- --8204300098 SECY-82-142 Requests approval of draft Rept to Congress on AO (NUREO-0090) for Oct-Dec 1981 DIRCKS, W J Office of the Executive Director for Operations 82/04/02 40pp 15836-225
- ~-8208020047 Responds to 820603 memo re proposed AD Incident involving pressure transients during shutdown does not constitute AD Finding based upon analysis showing integrity of pressure vessel not impaired & fatigue life not affected MINOQUE.R B Office of Nuclear Regulatory Research, Director 82/06/22 MICHELSON.C Director's Office 3pp 15806 282
- 8210280019 Responds to 750819 memo re QA Program Insp Rept 99900084/75-01 Info in rept does not establish reasonable basis for determining violation of criminal statutes Referral to DOJ inappropriate MCTIERNAN.T J. Office of Inspector & Auditor 75/10/01 DAVIS.J G Office of Inspection & Enforcement, Office of the Director App 15860 070
- --8210280110 DRNL/NSIC-it2 DRFT
  "Pressure Vessel Thermal Shock at US PWRs Events &
  Precursors.1963 to Mud-1981," draft interim rept Related
  into encl
  pHUNG.D.C. Oak Ridge National Laboratory FIN 8-0435 82/05/19
  Office of Nuclear Regulatory Research. Director 218pp
- --8210280321 "Extremity Doses & Compliance w/Monitoring Regulations at Nuclear Power Plant " HUGGINS,T North Carolina, Univ of 62/06/30 lipp 15961 303
- 8210280374 Responds to FOIA request for "Initial Quidance for Performance of Sys Interaction Analysis at Belected LHRs" & "Initial Quidance on Diagraph-Natrix Analysis for Sys Interaction "Forwards repts W/o enci FELTON.J M Division of Rules and Records 82/09/14 FAORIZIO.R F Boston Fdison Co Ip 19859 118
- 8210280402 Add) response to FOIA request for SECY-82-202 & SECY-82-202 Documents listed in App A available in PDR FELTON.J K Division of Rules and Records 82/09/30 DUCKLES.R Affiliation Unknown 2pp 15859 101
- --8210280406 Commissioner Absance Affirmation response sheet re SECY-82-202 amend to 10CFR140, "Financial Protection Requirements & Indomnity Agreements " Comments encl AHEARNE, J. NRC - No Detailed Affiliation Given 82/06/16 3pp 19859 103
- --B210190198 Staff requirements memo re 820701 affirmation session concerning SECY 82-202 on amend to 100FR140 9, "Financial Protection Requirements & Indemnity Agreements " Objections to publication of apps as reg guides due by 820719 CHILK, B.J. Office of the Secretary of the Commission M820703 82/07/06 DIRCKS, W.J. Office of the Executive Director for Operations 2pp 15859 106
- 8210290020 Responds to FOIA request for RFP R8-01E-82-25; "Safety Aspects of Industrial Radiography Course" & related info Forwards document W/o encl FELTON.V M Division of Rules and Records 82/10/01 WILLIAMS, D T Affiliation Unknown 1p 15877 072
- 8210290027 "Anner i, Cost Benefit Analysis of Proposed Rule 73 47 of 10CFR73 " List of commentors encl \* NRC ~ No Detailed Affiliation Given 82/09/03 57pp 15864 197
- --8210290032 Discusses impact of proposed safeguards upgrade rule on nonpower reactors Paper requesting exclusion of nonpower reactors from rule will be initiated MILLER.J R Standardization & Special Projects Branch 82/09/03 SYELLO.V Division of Operating Reactors 4pp 15864 255
- --8210290083 "Licensees-SNM of Moderate Strategic Bignificance (Category II)"

  \* NRC No Detailed Affiliation Given 78/12/05 3pp
- --8210290058 "Category II Nonpower Reactor Licenses Holdings as of Jan 1979 " 4 NRC - No Detailed Affiliation Given 82/09/03 2pp 18864 270

- --8210290061 Responds to Commission request for rept on safeguards self-protection criterion impact of safeguards upgrade rule on 23 affected nonpower reactors would be severe Financial expense would force many reactors out of operation DENTON, H.R. Office of Nuclear Reactor Regulation, Director 79706/20 HENDRIE, J. GILINSKY, V. KENNEDY, P. Commissioners 5pp. 15865-065
- --8210290065 Comments on new Commission paper to upgrade rule Nonpower reactors should be exempt from rule Legal backup needed in event of public meeting HILLER, JR Assistant Director for Reactor Safeguards 77/06/28 BURNETT,R Division of Safeguards 2pp 15865 070
- --8210270067 "Dose Rate Due to Irradiated Fuel "

  \* NRC No Detailed Affiliation Given 81/04/14 Spp 15845 088
- 8210270085 Responds to FOIA request for lists of names & addresses of all NRC licensees in ME.VT.MA.DH.CT & MV & appropriate ofcs in Agreement States of NH.RI.NY & MD Forwards requested lists
  FELTON.J M Division of Rules and Records 82/10/15
  PARKINSON.T W Interstate Nuclear Services 1p 15863 311
- --8210290090 Lists of active licenses for States of MA,VT.ME,CT,OH & W. & Agreement States as of 820910

  4 NRC No Detailed Affiliation Given 82/10/07 240pp

### GEN TEC 18 GENERIC TECHNICAL ISSUES

- 8206060002 Appeals denial of FOIA request for segregable portions of draft NUREO-0844, "Resolution of Unresolved Safety Issues A-3.4-4 & A-5 Re Steam Generator Tube Integrity UDELL, R A Critical Mass Energy Project \$2706704 DIRCKS, W J Office of the Executive Director for Operations 200 15668 333
- 8207190066 Forwards edited version of draft on pressurized thermal shock w/substantive changes proposed KOUTS,H Brookhaven National Laboratory KOUTS,H ACRS Advisor, Committee on Reactor Bafeguards 82/08/10 IONE,E ACRS Advisor Committee on Reactor Safeguards 22pp 15852 012
- 8209280426 Discusses status of pressurized thermal shock short term recommendations ACRS Working Oraup on Metal Components meeting scheduled for 820930 to continue discussion Forwards draft "NRC Staff Evaluation of Pressurized Thermal Shock "DIRCKS.H J Office of the Executive Director for Operations 82/09/20 PALLADINO,N. GILINSKY.V., AHEARNE,J F Commissioners 2pp 15670-033
- --8210120335 "NRC Staff Evaluation of Pressurized Thermal Shock." drg rept Apps encl - Office of the Executive Director for Operations 82/09/13 393pp 13670 035
- 82:0010286 Concurs that NUREG-0744. "Resolution of Reactor Vessel Matls Toughness Eafety Issue," need not be reviewed by CROR STELLO, V. Regional Operations & Generic Requirements 82/09/30 DENTON, H.R. Office of Nuclear Reactor Regulation, Director, Ip 15573 881
- 8210080015 Add1 response to FOIA request for 19 categories of info r nuclear reactor events & safety problems. Forwards documents listed in App & Documents in App B completely withheld (ref FOIA Exemption 5)
  FELTON, J M Division of Rules and Records 82/07/12 UDELL. H A Critical Mass Energy Project 9pp 15665 027 · 24X
  Fiche 50-000, 82/07/12, 8210080015
- --8011060346 Discusses licensee responses to NRC request to commit interim position re Generic Item 8-24 venting & purging containments while at full power Plants meet interim position & existing TACs should be closed out REEVES E A Operating Reactors Branch 1, 80/08/25, Operating Reactors Branch 1 10pp 15668 155
- ---8106220159 Supports efforts in resolving purge valve leakage & operability issues Incorporation of leak testing position into Tech Specs should assure leakage integrity of containment BAER.R. Reactor Engineering Branch. 81/06/09 BUTLER, W. & Containment Systems Branch. 2pp 1566B 153

### NONDOCKETED ITEMS

- --8107170126 Comments on proposed IE bulletin re leakage of reactor bldg
  purge valves Issuance not menited for reasons indicated
  Centric Issues B-20 & B-24 provide assurance of increased
  surveillance testing & reduced excessive leakage
  SNIEZEK, J H Director's Office IEC-77-11 B1/07/01
  O-REILLY, J P Region 2, Atlanta, Office of the Director
  (B1/03/01) Zpp 15668 151
- --8210080097 "Cost of Upgrading Capability to Isolate LPWR Main Feedwater Sys in Event of Breaks Inside Containment," final rept.per statement of work for DOE Work Order 20-81-165, "Program for Cast Estimation for Proposed Safety Requirements "
  BEARDEN,R O EO&O, Inc FIN A-6452 ROB-2-82 82/03/17 15pp 15A55 169
- --BIO6220157 Supports offorts in resolving purge valve leakage & operability issues incorporation of leak testing position into Tech Specs should assure leakage integrity of containment BAER:R L Reactor Engineering Branch 81/06/07 BUTLER.W R Containment Systems Branch 2pp 15668 153
- --8107170126 Comments on proposed IE bulletin re leakage of reactor bldg purge valves Issuance not merited for reasons indicated Generic Issues B-20 & B-24 provide assurance of increased torve()lance testing & reduced excessive leakage SNIEZEKJ H Director's Office IEC-77-11 B1/07/01 O'REILLY, J.P. Region 2, Atlanta, Office of the Director (81/03/01) 2pp 15668 151
- 8210080021 Summary of 253rd ACRS meeting on 810507 re control sys failures that could cause or exacerbate nuclear power plant accidents per Task Action Plan A-47
  ASMER Reactor Operations Analysis Branch AEOD/E114 81/06/24
- P2100B005B Responds to appeal re denial of FOIA request for segregable portions of draft NURGO-0844, "Resolution of Unresolved Safety Issues A-3,A-4 & A-5 Re Steam Generator Tube Integrity " Request denied (ref FOIA Exemption 5) DIRCKS,N J Diffice of the Executive Director for Operations 82/07/19 UDELL,R A Gritical Mass Energy Project 2pp 15669 331
- E21008015B Forwards "Potential for Water Hammer During Restart of RHR Pumps for BMR Nuclear Plants " HUANNY S Director's Office, AEOD/E105 01/03/31 MICHELSDN.C Director's Office Ip 15663 255
  - 9210080165 "Potential for Water Hammer During Restart of RHR Pumps for ELR Nuclear Plants" HAMAD. Director's Office AEOD/E105 01/03/31 14pp 13663 256
  - (10080169 Forwards "Initial Consideration of Potential for Water Reaser in Steam Condensing Mode of RMR Sys Operation for SWR Plants " HUMBAY 8 Director's Office AEOD/E106 81/03/31 MICHELSON.C Director's Office ip 15463 271
  - -8210080172 "Initial Consideration of Potential for Water Hammer in Stem Condensing Mode of RHR Sys Operation for BWR Nuclear Plants" MUNROJ Director's Office AEOD/E106 B1/03/31 ilpp 15663 372
  - 210080294 Forwards "Review of Emergency Response Quidelines Re Pressurized Thermal Shock " KINGSLEV.O D Westinghouse Operating Plants Owners Group XINGSLEV.O D Alabama Power Co 00-72 82/06/22 DENTON.H R Offics of Nuclear Reactor Regulation. Director 1p. 15638 208
  - --E2100B0297 "Review of Emergency Response Quidelines Re Pressurized Thermal Shock " + Westinghouse Electric Corp 82/04/30 Bapp 19638 209
  - P210150552 WUREQ/CR-2791

    NETHROGLODY FOR EVALUATION OF INSULATION DEBRIG EFFECTB

    Containment Emergency Gump Performance, Unresolved Sefety

    Issus A-43

    WESKILJ KOLBE, R Sandia Laboratories FIN A-1276 SAND82-7067

    B2/09/20, Division of Bafety Technology 27ipp Available at

    NC 48 00 15725.005
  - 82/0180002 Requests attendance at CROR Meeting 29 on 82/028 in Bittenda.HD to discuss cost/benefit info for alternatives for resolving pressurized thermal shock issue SELD.V. Committee to Review Generic Requirements 82/10/14 EISBNUT.D Q. Division of Licensing JORDAN.E L. Division of Engineering & Guality Assurance. CUNNINGHAM.R E. Diffice of Nuclear Naterial Safety & Bafeguards.Director. 1p 15718.024

- 8210250156 Notification of CRCR 821110 25th meeting in Bethesda, MD to discuss proposed revision to 100FR20 on stds for protection against radiation, proposed amend to 100FR50 re radiation protection programs & Unresolved Safety Issue A~43
  STELLO, V Regional Operations & Generic Requirements 82/10/22
  EISENHUT.D 0 Defice of Nuclear Reactor Regulation. Director URBBAN, E. L. Director's Office, Office of Inspection and Enforcement Cunntinopham, R. Office of Nuclear Haterial Safety & Safeguards, Director ip 15788 288
- 8210280044 Summary of ACRS Ad Hoc Metal Components Subgroup 820511-12 meetings in Washington DC re-pressurized thermal shock problem \* ACRS - Advisory Committee on Reactor Safeguards 82/07/27 ACRS - Advisory Committee on Reactor Safeguards 19ap 15862 336
- 8210290118 Forwards, for info, draft rept & apps on pressurized thermal shock Completed rept will form basis of Commission decision due 821030 W/o encl
  LAINAS, C.C. Assistant Director for Operating Reactors 82/09/29
  ROCHINO.L. Babcock & Wilcox Operating Plants Duners Group
  ROCHING.L. Oeneral Public Utilities GPU Service Corp 2pp
  15884 358
- 8210290450 Forwards for info draft rept & apps on pressurized thermal shock Completed rept will form basis of Commission paper due 821030 M/o encl
  LAINAGO € Assistant Director for Operating Reactors 82/09/28
  HI001NS.P Atomic Industrial Forum 2pp 15863 181
- B210290453 Forwards, for info,draft rept & apps on pressurized thermal shock Completed rept will form basis of Commission paper due B21030 M/o encl
  LAINAS, O C Assistant Director for Operating Reactors B2/09/28 BASKIN, K C-E Operating Plants Owners Group 2pp 15863 185
- 8210290458 Forwards, for info.draft rept & apps on pressurized thermal shock Completed rept will form basis of Commission paper due 821030 H/o encl
  LAINAS, O C Assistant Director for Operating Reactors 82/09/28
  KINGSLEY, O Westinghouse Operating Plants Duners Group KINGSLEY, O
  Alabama Power Co 2pp 15863 183

### INSPECTION AND ENFORCEMENT

- 8208190233 lE Info Notice 80-35, Suppl 1, "Leaking & Disladged I-125 Implent Seeds" Svc list encl CDB.L I Division of Fue) Facilities. Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 250 24X Fichs 50-000.82/10/06.8208190233
- 8208190238 lE Bulletin 82-03, "Atress Corrosion Cracking in Thick-Hall/Large-Diameter.Stainless Steel.Recirculation Sys Piping at BNR Plants "Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/14 Consolidated Edison Co of New York 115pp 15810 125 24% Fiche 50-000.82/10/14.8208190238
- 8210040130 PNO-III-82-102 on 820926, lead container marked radioactive mat1 found on Cleveland OH street Wipe survey showed container to be free of radioactive contamination Container reportedly mislabeled to discourage theft from auto LASUK. 8 R. 8 BRENIAHSKI.D J. Region 3. Office of Director 82/09 ip 15581 212
- 8210040337 PNO-111-82-100 on 820924, stop work order issued for preparatory remedial soils identified problems w/cert( per confirmatory action ltr QARDNER.R Region 3. Offic. v. .....
- 8210050224 PNO-II-R2-105 on 820925,100 mC: Cs-137 mine logging source discovered missing Search of mine premises datected slightly elevated radiation level in one area of coal car POTER, J. 91880N.A Region 2. Office of Director 82/09/30 App 15611.024
- 8210030314 PNO-III-82-104 on 820903.40 42 mCi Ir-172 seeds removed from patient on 820605 determined to be missing Search continuing Wissistance of two NRC inspectors MATSON, E R . BRENIAMSKI, D J. Region 3, Office of Director 82/09/29 2p 15602 360
- 82:0070265 PNO-TMI-82-020 on 82:005, game poacher apprehended on util property & turned over to state police & Game Commission No vital areas threatened Security increased Licensee will issue press release.
  WIEBE, J. Region 1, Office of Director. 82/10/06 ip.

- 92(0150496 EN-82-026A on 820722.order to show cause & order suspending license effective immediately issued to Midstate Testing Lab Action based on licensee apparent abandonment of radiographic facility & licensed mati BROCKETT, X. AXELRAD, Director's Office. Office of Inspection and Enforcement 82/10/14 2pp 15/14 188
- B210150507 PND-111~82-109 on 821007, US Army infinity aloning collimator containing 10 Ci gaseous tritium discovered missing Theft suspected State of IL local police & defense contract administration notified DBERO.C T. WIEDEMAN, D.G. Region 3: Office of Director B2/10/12 Ip 19713-208
- 8210190673 PNO-111-82-110 on 821011. Troiler soil density & moisture gauge w/Ct-137 & Am-241 scaled sources reported stolen from const site in Ashland-MI Significant inadvertent eiposure unlikely since warming labels attached OBERG.C T , MiEDEMAN.D G Region 3. Office of Director 82/10/13 19 18737 283
- 8210250055 PND-V-82-043 on 821016 unusual event declared when grass fire started in 500 kV switchward On 821017, three 500 kV circuits tripped resulting in loss of all offsite power Second unusual event declared STERNBERG, D M Region 5. Offsice of Director 82/10/16 ip 15787 100
- 8210260471 PNO-III-82-113 on 820917.Victoreen Hodel 848-8 calibrator containing 112 mCi of Cs-137 shipped w/o proper warning labels or shipping papers Calibrator discovered in storage on 820924 & read 12 millirem/hour Caused by gersonnel error SRENIAMSKI,D J . MILLER,J R Region 3. Office of Director 82/10/19 1p 15807 229
- 8210260493 PND-1-82-047 on 821022, kinetic expansion conducted on eight rows of tubes in B once—through steam generator Expansion involves controlled detonation within tube Some media attention expected CONTER Region 1, Office of Director 82/10/22 ip 15806-232
- 9210280072 EN-82-030A on 921026, decision re 820827 order to show cause & order modifying License 41-17870-01 issued Since licensees took adequate corrective actions on violations: license will not be revoked Order to modify License further forthcoming FLACK, E. AXELRAD. J Director's Office. Office of Inspection and Enforcement 82/10/26 19 15837 146
- 8210280073 EN-82-031A order issued rescinding 820903 order to show cause & order temporarily suspending license of Orion Chemical Co Licensee 820924 response describing corrective actions acceptable AXELRABJ Director's Office, Office of Inspection and Enforcement 82/10/24 ip 15837 664
- 40SC PURT TO INDOUMENT ROOM MISCELL AMERICA

- 8210070476 Forwards findings & recommendations re 810115 memo on requirements offsite power sys design criteria ASHE,F Director's Offsice AEDA/E110 81/04/27 MICHELSON.C Director's Offsice 4pp 15637 358
- 8210070481 Recommends actions to be taken to lower rate of occurrences of inoperability of instrumentation due to extreme cold weather Suppl to IE Builletin 79-24 directing changes to Tech Specs should be issued HICHELSON.C Director's Office AEOD/E112 BI/06/13 DENTON.H R Office of Nuclear Reactor Regulation. Director STELLO,V Director's Office. Office of Inspection and Enforcement Spp 1944 350
- 8210080057 Summarizes findings of LER review to determine patterns of setpoint drift occurrences for Barton Model 288 instrument for 1975-80 Changes to procedures for BARS w/o analog safety sensor sys recommended ASHE.F Director's Office AEOD/Eli8 81/07/20 MICHELSON.C Director's Office 2pp 15667 324
- B210120073 Compares reactor coolant pump events contained in LERs, NRRDs, RECON & plant records Search indicates little confidence can be placed in single reporting tys, but such sys should be developed BROWN, E. J. Director's Office AEOD/E003 B0/06/19 MICHELEON. C. Director's Office 11pp 15689 172
- 8210120370 Discusses IE Bulletin 80-21, "Integrity of Polymer Coating for Surfaces Inside Containment " Coating developed by Con-Chem, Inc could fail when subjected to DBA conditions, releasing debris through sump screen MICHELSON.C Director's Office AEOD/E011 80/08/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 15690-1/0
- 8210120372 "Burvey of Valve Operator-Related Events Occurring During 1978,1979 & 1980 "
  BROWN, E. J. ASHE, F.S. Director's Office AEOD/C203 82/05/31
  S8pp
- 82(0)30545 Forwards abstract & summary cover sheet for paper re testing of 1/4-inch expansion anchors in repaired concrets Review requested for consideration of paper as candidate for presentation at Aug 1903 SHMRT-7 conference TOONI.C S Public Service Co of Indiana. Inc 82/10/07 WILLIAMS.M Office of Nuclear Reactor Regulation. Director 3pp 15682 207
- 8210150090 Forwards statement of consideration of biomedical wasts disposal published in FR when NRC adopted 10CFRQO 306 Adoption of regulation does not pose unreasonable radiological risk to public health & safety W/o encl BURNS.8 O Regional Operations & Enforcement Division 82/10/07 SCHEUERNANN,X KS Processing Co., Inc. 19 13701 197
- 8210260554 Forwards Engineering Planning & Mgt, Inc analysis of NAC sponsored fire tests evaluating 20-ft separation criteria.

  NGTLEY-D P Electrical Engineering Branch 82/09/29 KNIGHTON. Q W
  Research & Standards Chordination Granch 67pp 15830 193
- B210280431 Submits NRC findings re Phibro-Salomon, Inc application for proposed import of 300,000 tons U from Australia, South Africa & other countries Proposal conforms w/std provisions MODRE, R N Office of International Programs. Director 8209926 Office of International Programs. Director p 15860-053
- NUREO NUREO REPORTS AND RELATED CORRESPONDENCE
- 8206060002 Appeals denial of FOIA request for segregable portions of dract NURGO-0844. "Resolution of Unresolved Bafety Issues A-3.A-4 & A-3 Re Steam Generator Tube Integrity UDELLAR A Critical Mass Energy Project 82/05/04 DIRCKS, H J. Office of the Executive Director for Operations 2pp 15668 333
- B207180061 FOIA request for documents re-pre-implementation review of NUREO-0737. Item II F 2.
  CONNOR.L Doc-Bearch Associates 82/09/01 Division of Rules (Records, 1p 15669 096
- 8207290410 NUREG/CR-2229 VO2 BWR LARGE BREAK BIMULATION TESTS-BWR BLOWDOWN/EMEROENCY CORE COOLING PROGRAM Volume 2-Appendices I-N LEF,L S. General Electric Co FIN 9-3014 GEAP-24962~2, \$2707/ Division of Accident Evaluation 552pp, Available at NTIB 413 00 14126 COI.

- 8:18290017 Summarizes 269th ACRS meeting on 820909-il in Washington. DC to proposed safety goals: radjoactive math packaging for transport; testing requirements for diesel generators & integrated human factors program plan
  SHEMBON: P ACRS Advisory Committee on Reactor Safeguards
  SL-0278 82/09/21 PALLADINO. N J Commissioners 3pp 15649 236
- B209280307 MUREO/BR-0024
  MORKING BAFELY IN GAMMA RADIOGRAPHY A TRAINING MANUAL FOR
  INCLUSE IA PERBODY, C A Office of Nuclear Regulatory Research,
  Director 82/09/30 168pp
- E210010008 Responds to FOIA request for 19 categories of documents renuclear reactor events & safety problems Forwards documents listed in App A FELTON-J H Division of Rules and Records. B2/06/28 UDELL.R A Critical Mass Energy Project 15pp 18727 ODS 24% Ficht 50-000-82/06/28.8210010008
- -- 9210040379 Submits review of IE insps of operating PWRs related to followsp actions identified in NUREO-0138 Bensitivity analyses recommended SUTLER: H B Plant Bystems Branch 77/12/28 EISEN: NUY, D O Quiston of Operating Reactors 12pp 15727 285
- --E21004839A Submits evaluation of recommendations contained in NURLG-0651. "Evaluation of Steam Generator Tube Rupture Events" Licenses should investigate other techniques to more rapidly determine damage AMERIC Safety Program Evaluation Branch 81/02/17 MURLEY.T Division of Bafety Technology 26pp 15728 007
- --S010240413 Submits evaluation of NUREO-0667, "Transient Response of B&W Designed Reactors" Recommends related atudies he combined is specified Priority 2 items implemented by expanding an existing task in TMI action plan PATSON.R Division of Bafety Technology 80/08/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 43pp 15727 199
- --Bitt03020t Responds to inquiry into status of BHR scram discharge vol pipe break safety concerns NUREO-0803 contains guidance for resolving outstanding issues on plant by plant basis RUBIN-5 D Director's Office 81/10/02 LEWIS, M I Applilation Unknown 1p 15730-336
- --8108270056 Forwards concurrence on NUREG-0803, "Generic Safety Evaluation re Integrity of BHR Scram Bys Piping " Any significant changes will be provided for consideration MICHELSON.C Director's Office 81/07/30 EISENHUT, D 9 Division of Licensing 3sp 19730 083
- -Silio30201 Responds to inquiry into status of DWR scram discharge volsign breat safety concerns NUREG-0803 contains guidance for resolving outstanding issues on plant by plant basis RUBIKS D Director's Office 81/10/02 LEWIS, M J. Affiliation Uninown ip 19730-336
- -8105110396 Forwards findings & recommendations for J Elin 810115 memo re requirements of preferred or offsite power sys ASRE f Director's Office 81/04/29 MICHELEON C Director's Office 4pp 15729 070
- -8109240007 Comments on NUREO/CR-1659 Vol 2: "Reactor Safety Study Methodology Application Program Ocones 3 PWR Power Plant "DEWINDER L Director's Office 81/09/15 Director's Office 31/09/15
- EXIOIO223 Comments on proposed rule IOCFRBO is mandatory property instance for decontamination of nuclear reactors & MARIO-0091; "Muclear Property Insurance Status & Outlook " System rule WRK.F.B. Mississippi Power & Light Co. 47FR27371 041 82/09/24 Office of the Secretary of the Commission in 15568 019
- 8210010286 Concurs that NUREO-0744, "Resolution of Reactor Vessel Natt Toughness Safety Issue," need not be reviewed by CAPA STELLO, V Regional Operations & Qameric Requirements 62/09/30 text06/HR Office of Nuclear Reactor Regulation, Director ip 15573-191

- 8210010307 Package of three comments opposing proposed rule (OCFR50 re mandatory property insurance for decontamination of nuclear reactors (OFRER, C.M. Historian Public Service Corp. WITHERS, B.D. Pacific Qas & Electric Co. KELLY, A.B. American Nuclear Insurers 47FR27371 82/09/28 CHILK, S.J. Office of the Secretary of the Commission 19pp 15548 289
- 8210010381 Package of four comments on proposed rule 10CFR50.

  "Mandatory Property Insurance for Decontamination of Nuclear Reactors" Supports rule

  HYATT.JM Louisiana Power & Light Co DELLSY.H M Communusalth Edison Co ROBERTSON.C O Houston Lighting & Power Co 47FR27371

  82/09/24 Decision & Services Branch 22pp 15573 059
- 8210040311 Forwards Revision 4 to SCP-01-A. "RADCAL Gamma Thermometers as Local Power Measuring Devices for Use in Cores of PMRs."

  per NUREO-0390

  MARINO. P Scandpower. Inc 82/09/29 BERNARD. H Standardization b Special Projects Branch 1p 15586 198
- 82:0050360 NUREO/CR-2792
  AN ASSESSMENT OF RESIDUAL HEAT REMOVAL AND CONTAINMENT SPRAY
  PUMP PERFORMANCE UNDER AIR AND DEBRIS INVESTING CONDITIONS
  KAMATH-P S , TANTILLO,T J , SWIFT.W C Creare, Inc FIN A-1237
  BZ/09/30 Division of Bafety Technology 110pp Available at
  NRC 45 50 15525-010
- 8210050368 NUREO/CR-2905
  RAMAN SCATTERING TEMPERATURE MEASUREMENTS FOR WATER VAPOR
  IN NON-EQUILIBRIUM DISPERSED THO-PHASE FLOH
  AMASTASIA.C M., NETI.S., SMITH, W.R. Lehigh Univ. FIN B-6794
  B2/09/30 Division of Accident Evaluation 204pp Available at
  NRC \$7.00 15624.061
- 8210050388 NUREC/CR-2761
  RESULTS OF VORTEX SUPPRESSOR TESTS, SINGLE QUILET SUMP TESTS,
  AND MISCELLANEOUS SENSITIVITY TESTS
  PADMANABHAN.M Alden Research Laboratory # Sandia Laboratories
  FIR A-1227 SAND82-7065 82/07/30 Office of Nuclear Reactor
  Regulation, Pirector 115pp Available at NRC 46 50 15425 170
- 8210050397 NUREO/CR-2606
  ANALYSES OF 1/15 SCALE CREARE BYPASS TRANSIENT EXPERIMENTS
  KMETYKL N . BUXTONL D . CCLE, R K Sandia Caboratories FIN
  A-1115 SANDBJ-1932 92/09/30 Division of Systems Integration
  (post B11005) 4ipp Available at NRC \$9 00 15425 329
- B210050412 NUREO/CR-2920
  BEHAVIOR OF REIMPORCED CONCRETE SLABS SUBJECTED TO COMBINED PUNCHINO SHEAR AND BIAVIAL TENSION
  JAULY C., WHITE, R. N., DEROELY, P. Cornell Univ. 82/09/30
  Division of Engineering Technology 103pp Available at NRC \$5.50 15624.266
- 0210050418 NUREO/CR-2754
  CRITICAL REVIEW OF STUDIES ON ATMOSPHENIC DISPERSION IN
  COASTAL REGIONS
  SMEARER, D.L. KALEEL, R.J. TRC Environmental Consultants, Inc. \*
  Pattelle Hemorial Institute, Pacific Northwest Laboratory FIN
  B-2384 PNL-4292 02/09/30 Division of Health, String &
  Environment 399p Available at NRC \$4.75 13625 237
- 6210050426 NUREO/CR-2897
  CALCULATIONS OF HYPROGEN DETONATIONS IN NUCLEAR CONTAINMENTS
  BY RANDOM CHOIGE METHOD
  DELICHATBIDS, M. GENADRY, M. G. FARDIS, M. N. Massachusetts Institute
  of Technology FIN 8-7085 82/09/20 Division of Engineering
  Technology 215pp Available at NRC 97 50 15612 117
- 8210050431 NUREC-0858
  COMPARISON BETHERN FIELD DATA AND ULTIMATE HEAT SINK COOLING
  FOND AND BERKY PUND MODELS
  CODELL, R B Division of Engineering 82/09/30 67pp Available at
  NRC #5 00 18586 108
- 0210060004 NUREO/CR-1369 ROI
  PROCEDURES EVALUATION CHECKLIST FOR MAINTENANCE, TEST AND
  CALIBRATION PROCEDURES USED IN NUCLEAR FDWER PLANTS
  SRUNE, R. L. HEINSTEIN, M. HPT. Inc. \* Bandia Laboratorias FIN
  B-3098 BANDAO-7034 82/09/30 Division of Reacter Programs
  25pp Available at NRC \$3.50 15636,308
- 8210060417 NUREO/CR-2250 ERR
  Errate, Changing Report Number of NUREO/CR-2260 To
  NUREO/CR-2620 To.AN ANALYSIS OF PROPOSED INLET FLOW BLOCKAGE
  EXPERIMENTS USINO MAYU-46
  4 EG&G. Inc EGO-2181 82/06/30 Office of Nuclear Regulatory
  Research, Director 1p 15836 242

- B210070007 Responds to FDIA request for eight categories of records re steam generators & steam turbines App A documents provided in R Udell FOIA Request B1-313 Forwards documents listed in App B FELTON.J M Division of Rules and Records 82/08/10 LONG.D J Winthrop. Stimson, Putnam & Roberts 9pp 15645 063 24X Fiche 50-000.B2/08/10.8210070007
- --8203260003 Recommends that STS limits for coolant activity & sampling requirements be incorporated into remaining operating plant. Tech Specs w/other substantive change requests lodine dose problems can be avoided by limiting coolant. HOUSTON, R.W. Assistant Director for Radiation Protection. 82/03/04 NOVAK, T. Assistant Director for Operating Reactors. 2pp. 15445-285
- 8210070029 Partial response to FDIA request for documents re CRBR EIS & all comments evaluations & documents from BNML re EIS Forwards documents listed in App A FELTON. J. N. Division of Rules and Records 82/07/14 WEISB.E R Harmon & Weiss 8pp 15448 004
- --8210070123 Forwards updated responses to comments on 1976 DES.
  NUREG-0137 re safeguards & fue! cycle info re radwaste
  shipments.disposal site & licensed burial site included
  LOMENDERGO.H Office of Nuclear Material Safety &
  Safeguards.Director CRBR 82-69 82/06/15 LEECH, P Clinch
  River Breeder Reactor Program Office 15pp 15648 073
- 8210090015 Add1 response to FOIA request for 19 categories of info re nuclear reactor events & safety problems Forwards documents listed in App A Documents in App B completely withheld (ref FOIA Exemption 5)
  FELTON-J-M Division of Rules and Records 82/07/12 UDELL-R A Critical Mass Energy Project 9pp 15665 027 24X Fiche 50-000-82/07/12-8210080015
- ~-92:0080057 "Cost of Upgrading Capability to Isolate LPWR Main Feedwater 8ys in Event of Breaks Inside Containment," final rept.per statement of work for DUE Mork Order 20-81-165. "Program for Cost Estimation for Proposed Safety Regulrements." BEARDEN.R G E06G. Inc FIN A-6452 RCB-2-82 82/03/19 15pp 15645 168
- --B2100B0215 Forwards revised IE organizational charty & functional statements for review & comment Reorganizations of B20104 & 25 will be incorporated in NUREO-0325 BLAHA-J L. Program Support Branch B2/04/29 LIEBERMAN, J Enforcement Staff FORTUNA, R. Director's Office. Diffice of Inspection and Enforcement COBB, L. I. Division of Fuel Facilities. Materials & Bafeguards 7pp 15668 261
- --8203040536 Comments on B(i218 corrections to facility assessment contained in NOREG-0834 re hearings & discussion of systematic assessment of license performance Revision to NOREO inappropriate Issue closed MOSELEY.N C Systematic Assessment of Licensee Performance Review Group 82/01/04 WESSMAN.R H NRC NO Detailed Affiliation Given ip 15668 256 24X Fishe 50-000.82/07/12,8210080015
- --- 8203040538 Forwards performance element summary for Jul 1979-June 1980 in response to ABLB request for testimony on systematic assessment of license performance in general & facility assessment in particular MESSMAN.R H Director's Office Office of Inspection and Enforcement 81/12/18 MUSELEY,N C Systematic Assessment of Licensee Performance Review Oroup 2pp 19669 254 24X Fiche 50-000,82/07/12.8210080015
- 8210080020 Responds to FOIA request for documents re preimplementation of NUREG-0737, Item III F 2 Forwards documents listed

and Records 82/09/16 CONNOR.L

·ntation

10

able

- B210120092 NUREO/CR-2873 VO2
  NUCLEAR FUEL CYCLE RISK ASSESSMENT DEBCRIPTIONS DF
  REPRESENTATIVE NON-REACTOR FACILITIES Sections 15-19
  SCHNEIDER, K. J. BICKFORD, W. E., DALING, P. M. Battelle Memorial
  Institute, Pacific Northwest Laboratory FIN B-2402 PNL-4306,
  B2/09/30 Division of Risk Analysis 361pp Available at NRC
  49 00 15589 328
- B210120102 NUREO/CR-2B73 V01
  NUCLEAR FUEL CYCLE RISK ASSESSMENT DESCRIPTIONS OF
  REPRESENTATIVE NON-REACTOR FACILITIES Sections 1-14
  SCHNEIDER, K J. BICKFORD, W E. DALINO, P M Battelle Memorial
  Institute. Packfic Northwest Laboratory PIN B-2402 PNL-430,
  B2709/30 Division of Risk Analysis 376pp Available at NAC,
  \$9 50 15686 313
- 8210120116 NUREG-074B VOZ NOB OPERATINO REACTORS LICENSING ACTIONS SUMMARY Data As Df August 31.1982 (Grange Book) \* Management Information Branch 82/09/30 355pp 15685 j[y
- 8210120119 NUREG-0580 VI1 NO9
  REQULATORY LICENSING STATUS SUMMARY REPORT Data As Of
  September 15, 1982 (Blue Book)
  \* Management Information Branch 82/09/30 43pp 15689 004
- 8210120125 NUREO/CR-2820
  RESOLUTION OF SHIPPER-RECEIVER DIFFERENCES
  JOHNSTON. J W. BROWNS: R J . STEMART.K B Battelle Memorial
  Institute, Pacific Northwest Laboratory FIN B-8103 82/09/10
  Division of Facility Operations 117pp Available at NRC 47 %0
- 8210130381 Comments on proposed rule 10CFR50 re mandatory property insurance for decontamination of nuclear reactors (NUREO-0891) Imposition of blanket coverage requirement passa restrictive economic hardship on smaller plants TAYLOR.J W Dairyland Power Cooperative 47FR27371 042 62/09/17.3 Office of the Secretary of the Commission 2pp 19681 001
- 8210130539 Forwards util comments on proposed rule 10CFR30 re mandator property insurance for decontamination of nuclear reactors (NUREG-0891)
  FLYNN 8 F Carolina Power & Light Co 47FR27371 044 92/09/29 WOOD, R 8 Office of State Programs, Director Ip 15692 26:1
- --B210130550 Comments on proposed rule 10CFR50 re mandatory pruperty insurance for decontamination of nuclear reactory (MUREO-QB91) Present requirements re property insurance adequate to assure sufficient funds for decontamination BARHAM.C D. Carolina Power & Light Co. 47FR2731 044 122/49249 CHILK, B.J. Office of the Secretary of the Commission 122p
- 8210130554 Comments on proposed rule 10CFRSD re-mandatory property insurance for decontamination of nuclear reactors (NUREO-OBS))
  MITTLIR L Public Service Electric & Gas Co of New Jersey 47FR27371 043 82709/24 CHILKIS J Docketing & Services Brazish App 15584 00
- G210150547 NURE9-0750 V15 NO5 NUCLEAR RECOLLATORY COMMISSION ISSUANCES May 1982, \* Division of Technical Information & Document Control 1927()5 \* \$1 275pp. 15722 OO1
- 8210150548 NUREG/CR-2404
  ANALYZING SAFEQUARDS ALARMS AND RESPONSE DECISIONS
  AL-AYATAR A JUDD, B R MCCORD, R K Laurence Livermore Labourge to fin A-0115 UCRL-53034. 82/09/30. Division of Facility Operations 115pp Available at NRC, 85 00 15726 133
- 8210190849 NUREO/CR-2831 A TEST OF THE CONTROLLABLE UNIT APPROACH (CUA) CONCEPT IN A LOW-ENRICHMENT URANIUM FUEL-FABRICATOR FACILITY FUSTER, K W Hound Laboratory/Monsanto FIN A-1075 NLM 2457 82/10/31 Safeguards Branch 108pp 15724-061
- 8210150550 NUREO/CR-2889
  A YECHNICAL TEST DESCRIPTION OF THE NRC LONG-TERM WHOLE RGD
  AND CRUD PERFORMANCE TEST
  EINZINGER, R E., FISH.R L
  Laboratory, FIN B-2435
  Engineering Technology, 77pp Available at NRC \$5.00 IS Full
- 8210150552 NUREG/CR-2791

  METHODOLOGY FOR EVALUATION OF INSULATION DEBRIS EFFECTH
  Containment Emergency Sump Performance, Unresolved Barety
  Issue A-43

  WYSICKI, J. KOLBE, R. Sandia Laboratories FIN A-1296 SAND FAUL
  B2/09/30 Division of Barety Technology. 271pp Available
  NRC. \$8.00 15725 005

```
Elicitossi (NREG/CP-p030
Si79CSIUM ON UNBATURATED FLOM AND THANSPORT MODELING
Si79CSIUM ON UNBATURATED FLOM AND THANSPORT MODELING
Si79CSIUM ON UNBATURATED FLOM AND THANSPORT MODELING
ANDIDLE M. OKE.0 W. NELSON,R W. Battelle Memorial Institute.
ANDIDLE M. OKE.0 W. NELSON,R W. Battelle Memorial Institute.
ANDIDLE M. OKE.0 W. NELSON R. D. OKE.0 P. OKE.0
```

.3150360 NUREO/CR-0/67 V20
LOFT EXPERIMENTAL HEASUREMENTS UNCERTAINTY ANALYSES VOLUME
LOFT EXPERIMENTAL HEASUREMENT USING PULSED NEUTRON
ATTIVATION
LAESAND 0 , TAYLOR, D J EGG, Inc FIN A-6043 EGG-2037 VRO
LAESAND 0 , TAYLOR, D J EGG, Inc FIN A-6043 EGG-2037 VRO
LAESAND 0 Division of Accident Evaluation 32pp 15747 296

710150564 MAREO/CR-2874 VO1
MICH-TEMPERATURE GAB-CODLED REACTOR BAFETY STUDIES FOR THE
MICH-TEMPERATURE GAB-CODLED REACTOR BAFETY STUDIES FOR THE
MICHISTON OF ACCIDENT EVALUATION Quarterly Progress Report,
January I-Harch 31: 1788
JAL-S J, CLAPP.N E., CLEVELAND, J C Dak Ridge National Laboratory
314L-S J, CLAPP.N E., CLEVELAND, J C Dak Ridge National Laboratory
FIN 8-0122 ORNL/TM-8443/V1 82/09/30 Division of Accident
FIN 8-0122 ORNL/TM-8443/V1 82/09/30 Division of Accident
Fivaluation 19pp 15716 113

EXIOLADAY AUREO/CR-2163
OTSFERSED FILM FLOW BOILLING OF HIGH PRESSURE WATER IN A ROD
PINDLE
HERRISD 0 , MERLING.C D , YODER,O L Oak Ridge National Laboratory
FIN B-0125 ORNL/TM-7864 GR/09/30 Division of Accident
Exitation 88pp 15716-246

E::3150549 MAREO/CR-2719
FMUATION OF INSERVICE INSPECTIONS OF GREASED PROSTRESSING
FENOME CONSIDER A Ridge National Laboratory FIN A-9044
COUNNLY B 82/09/30 Division of Engineering Tethnology
Fig. 15716 169

\$3:61:0075 MURED/CR-2730 MIRROSEN BURN SURVIVAL PRELIMINARY THERMAL MODEL AND YEST FEBLTS ROADON-W W. RATZEL, A.C., KEMPKA, S.N. Sandia Laboratories FIN A-1270 SAND82-1180 82/09/30 Division of Accident Evaluation 31p 15716 132

EI015074 NUREO/CR-2898
MINFORCED CONGRETE CONTAINMENT SAFETY UNDER HYDROGEN
EDUISION LOADING
FMOISH N , NACAR, A , DELICHATSIGS, M
THINDLEY FIN B-7085 82/09/30 Division of Engineering
Technology 222pp Available at NRC 47 50 15722 252

LINESSY ARRES/CR-2000 VOI NB LICESCE EVENT REPORT (LER) COMPILATION For Month Of Alight 1982 • Oil Ridge National Laboratory FIN B-1583 ORNL/NSIC-200 82/8/20 Director's Office 180pp 15723.113

ROWNER MREGOR-2922 (GMM)SON OF GUICK PREDICTIONS WITH RESULTS OF SELECTED REGIT AEROSOL BEHAVIOR EXPERIMENTS (GMM)H, BOHUMACHER, P. M. OIESEKE, J. A. Battelle Mamorial Initiaty, Columbus Laboratories FIN A-4063, BMI-R097 82/09/30 Office of Nuclear Regulatory Research, Director 37pp 15726-324

Engroups Responds to 820805 itr re unresolved issues from 820615 ltr is falsquate requirements developed per TMI Item I.D i knipment of responsibility for human factors within NRC & cases of operator integrity addressed CONSMIR Diffice of Nuclear Reactor Regulation, Director 8209/46 BHESHY, E.J. Affiliation Unknown 29pp 15758 207.

~200100008 Informs that response to 820615 ltr incomplete in areas of ioun factor evaluation of ADs & ability of operator to act attended.
SECHY, E.J. Affiliation Unknown 82/08/05 PALLADING, N.J. Confessioners, 8pp. 15788-234

RO1001001A NURFO/CR-0909 Plog10014 NUREGYCK-gyes
NAPPC UBER'S MANUAL
JORDAN, H., BCHUMACHER, P.M., GIESEKE, J.A. Battelle Memorial
Inseltote, Columbus Laboratories FIN A-4063 BMI-2100 82/09/30
Office of Nuclear Regulatory Research, Director 53pp Available
at NRC \$4.75 15784 324 B21021002A NUREG-0940 VOI NOI-2 ENFORCEMENT ACTIONS SIGNIFICANT ACTIONS RESULVED Quarterly Progress Report, January-June 1982

\* Director's Office Office of Inspection and Enforcement
82/07/30 250pp Available at NRC \$7.50 15781 187 8210210037 NURE0/CR-2673 ALUZIOUS/ NUREO/CH-26/3
EVALUATION OF THERMAL DEVICES FOR DETECTING IN-VESSEL
COOLANT LEVELB IN PURS
HARDY, J E , DAVIS:C E , TURNAGE,K Ø Dak Ridge National Laboratory
FIN 8-0401 CRNL/TH-8306 82/09/30 Division of Accident
Evaluation 73pp 19773 295 9210210039 NUREGYCR-2409 210210039 NUREG/CR-2609 THERMAL-HYDRAULIC TEST FACILITY BUNDLE 3 IN-CORE INSTRUMENTATION AND OPERATING HISTORY DTT.L V Dak Ridge National Laboratory FIN D-0125 ORNL/NUMEG 75 B2/09/30 Division of Accident Evaluation 104pp 15774 906 8210210046 NUREO/CR-2914
CORRELATION DE LIGHTE BEDS FOR FAULT IDENTIFICATION IN THE
HIBSISSIPPI EMBAYMENT AREA OF HESTERN KENTUCKY
COBS.J C. WILLIAMS.D A Kentucky. State of FIN 8-5972 82/09/30
Division of Nealth. Biting & Environment 36pp Available at
NRC \$4.50 15786-012 9210210051 NUREO/CR-2909 riozioosi Runco/ch-zyou PALEO7010 GeOLgov Of The New Madrid Area SCHMALD, ff R Illinois, State of \* Illinois, Univ of, Urbana-Champaign FfN D-6291 B2/09/30 Division of Health. Siting & Environment 69pp Available at NRC 45 OD 15785 L 9210210054 MIREOZCR~2444 VOI RIO210034 NUREO/CR-2444 VO1
PHR FLECHT BEAGET 21-ROD DUNDLE FLOW BLOCKAGE TASK DATA
AND ANALYSIS REPORT.NRC/EPRI/WESTINGHOUSE REPORT NO 11
LOFTUS,H J. + MOCHREITER L E. LEE,N Westinghouse Electric Coip
FIN 9-4204 EPRI NP-2014 82/09/30 Division of Accident
Eyaluation 560pp 15783 001 8210210329 Forwards proposed proprietary Revision 3 to Topical Rept EDR-1(P)-A. "Edgress Nuclear Bafety-Related Extra-Bafety & Monitoring (X-8AM) Cranes "Rept withheld (ref 10CFR2 770) CLARK.C W Edgress Inc 82/10/08 THOMAS.C Standardization & Special Projects Branch 2pp 19765 296 0210220047 Proposes to submit by end of CY82, evaluation of ACRS 020818 recommendations to control room Rabitability & NRC plans for implementing design improvements
DIRCKS, M. Diffice of the Elecutive Director for Operations
82/09/17 SHCLMON, P. B. ACRS - Advisory Committee on Reactor
Beforerate 3pp 19785 219 -821022004B Comments on ACRS 820818 ltr re control room habitabylity
Response should address burden of new requirements on
licensess, limited NRC budget & overall contribution to total 0000HIH.E.F. Technical Support Branch 82/08/24 MATTSON.R J Division of Bystems Integration (post 811005) 3pp 1878A 222

- 8210220154 NUREG/CR-2444 VO2 PHR FLECHT SEASET 21-ROD BUNDLE FLOW BLOCKAGE TASK DATA AND ANALYSIS REPORT, NRC/EPRI/WESTINGHOUSE REPORT NO 11 LOFTUS,M J. HOCHRELITER,L E., LEE,M Westinghouse Electric Corp EPRI/M-2014 82/09/30 Division of Accident Evaluation YUAp; Available at NRC 115 00 15796 128
- 8210220353 Comments on proposed rule 10CFR50 re mandatory property inturance for decontamination of huclear reactors (NUREC-0891) Insurance problems should remain responsibility of utils 5 NRC should not impose mandates DIXDN-0 W South Carolina Electric & Gas Co 47FR27371 046 82/10/11 CHILK-S J Office of the Socretary of the Commission 2pp 15776 271
- 8210250030 Forwards NUREO/CR-2927, "Nuclear Power Plant Electrical Cable Damageab) lity Experiments " Potential problem recable failures at temps less than min temps required for LOCA atmosphere should be brought to attetion of ASLB NOTLEY, D.P. Electrical Engineering Branch 82/09/30 KNIGHTDN, C. W. Research & Standards Coordination Branch 1p 15808 271
- --8210250033 Forwards NUREC/CR-292/, "Nuclear Power Plant Electrical Cable Damageability Esperiments" LUKENS, L. t. Sandia Laboratories 82/09/20 NOTLEY, D.P. Electrical Engineering Branch 41pp 15808 272
- 8210260206 NUREG/CR-2710
  MASS FLOW MEASUREMENTS UNDER PWR REFLOOD CONDITIONS IN A
  DOWNCOMER AND AT A CORE BARREL VENT VALVE LOCATION
  MARDY, J. E. Clar Ridge National Laboratory FIN 8-0413
  ORNL/TM-8331 82/09/30 Division of Accident Evaluation 46pp
  15831 001
- 8210260211 NUREG/CR-2877
  INVESTIGATION OF CABLE DETERIORATION IN THE CONTAINMENT
  BUILDING OF THE SAVANNAM RIVER NUCLEAR REACTOR
  GILLEN'N T , CLOUGH R W , JONES, L H Sandia Laboratories FIN
  A-1051 SANDB1-2613 82/09/30 Division of Engineering
  Technology 42pp 15831 048
- 8210260215 "TMT Action Plan Tracking Sys." 820630 issue KNNGM Office of Resource Management. Director 82/06/30 159p 15831 227
- 8204300098 SECY-82-142
  Requests approval of draft Rept to Congress on AD
  (NUREC-0090) for Oct-Dec 1981
  DIRCKS, M J Office of the Executive Director for Operations
  62/04/02 40pp (5836-225
- 8210270106 Forwards request for QMB review & supporting statement re NUREC-0906. "Guidance for implementation of SRP Rule." per IOCPRSO 34(g) amend NURRY.P G Office of Administration 82/10/20 SCURRY.N Office or Management & Budget ip 15832 320
- 8210270322 SECY-82-407
  Advises of issues remaining from 820108 meeting reinstrumentation for detection of inadequate core cooling in FWRs Requests action on update recommendations for implementation of NUREG-0737. Item II F 2
  BIRCKS: W. J. Office of the Elecutive Director for Operations 82/10/07 12pp 15851 323
- 8210270331 NUREG-0267 R01
  PRINCIPLES AND PRACTICES FOR KEEPING OCCUPATIONAL RADIATION
  EXPOSURES AT MEDICAL INSTITUTIONS AS LOW AS REASONABLY
  ACHIEVABLE
  BRODSKY, A Div(sion of Facility Operations 82/10/31 90pp
  Available at NRC #5 50 15648 022
- B210270338 NUREO/ER-2799
  A PARAMETRIC STUDY OF CONTAINMENT SMERGENCY SUMP
  PERFORMANCE RESULTS OF VERTICAL DUTLET SUMP TESTS
  KREIN.M S. MESTER.M J. STROM.P.O. Sandis Laboratories FIN
  A-1276 SANDB2-7062 82/10/31 Division of Engineering
  Technology 113pp Availably at MRC \$5.50 15847.271
- 8210270371 Summary of ACRS Subcommittee on Seactor Radiological Efforts 820720 meeting in Hashington: DC re-mathods for reducing radiation exposure exposure histories at PMRs 4 status of NUREO-0761. "Radiation Protection Plans for Licensees" \* ACRS Advisory Committee on Reactor Safeguards. 82/09/17 ACRS Advisory Committee on Reactor Safeguards 17pp 15835-004

- ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS
- S208190233 IE Into Notice 80-35, Suppl 1, "Leaking & Dislodged 1-125 Implant Seeda " Svc Fist encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/10/06 Consolidated Edison Co of New York 66pp 15761 (250 24X Fiche 50-000, 82/10/06, 8208190233
- B20B19023B IE Builetin B2-03, "Stress Corrosion Cracking in Thick-Wall.Large-Diameter.Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list end:
  DEYOUND, R C Director's Office, Office of Inspection and Enforcement B2/10/14 Consolidated Edison Co of New York 115pp 15810 [25 24% Fiche 50-000,82/10/14.8208]9023B
- 8104080307 Std order for DDE work "Program for Cost Estimation for Proposed Safety Requirements." issued to ID Operations Dfc Statement of work encl GRENIER. B L Office of Nuclear Reactor Regulation, Director J.J. A-6452-1 20-81-163 81/03/12 6pp 15465 183
- ~-8210080054 Forwards "Cost of Upgrading Capability to Isolate (PHR Main Feedwater Bys in Event of Breaks Inside Containment," final rept in response to statement of work in TE Murley 810616 libr re INEL technical assistance to NRR SAFFELL.B F EO&G. Inc FIN A-6452 SAFF-155-82 82/04/14 SOLECKI.J E Energy. Dept of Idaho Operations Office 1p 15565 167
- 8210120378 Forwards request for OMB review & supporting statement reporting & recordkeeping requirements of 10CFR73 concerning physical protection of plants & matls NORRY,P of Office of Administration 82/10/08 SCURRY,N Diffice of Management & Budget ip 13672 223
- 8210120388 Forwards request for QMB review & supporting statement refinal amend to 10CFR71 12 concerning general license for shipment in packages approved for use by another person NORRY, 9 Office of Administration 82/10/06 SCURRY, N Office of Management & Budget 1p. 19692 242
- B210120402 Responds to approval request for info collection re-100FR150 Request approved through 850630 under OMB Number 3150-0032; per Paperwork Reduction Act. SCURRY.N Office of Management & Budget OMB 3150-0032 (12/07/12 SCOTT.S Document Management Branch 2pp 15692 250
- B210120404 Responds to approval request for info collection ry domps1; licensing of source math.10CFR40 Request approved through 830930 under GMB Number 3190-0020, per Paperwork Reduction Act SCHRRY.N Office of Management & Budget OMB 3150-0020 NP/494.\*L SCOTT.8 Document Management Branch Zpp 15672-252
- 8210120981 Transcript of 820918 public meeting in Washington.BC re-FEMA briefing on offsite appraisals program Pp 1-63 Visugraphs encl
- Visugraphs encl + Commissioners 82/09/18 87pp 15685 232
- 8210120599 Staff requirements memo re FEMA 820917 briefing on offeste appraisals program for commercial nuclear power plants FLMA should provide NRC w/info re availability of emergency plans & public broadcasts in foreign language CHILK.8 J Office of the Secretary of the Commission HD2091/F 82/09/24. BICKHIT.L Office of the Executive Director for Operations DIRKS.W J Office of the General Counsel Ip 15672 349
- 8210150236 Forwards 10CFR2 206:10CFR2 202: supplementary mail accompanying issuance of original rule in 1974:1977 amend to FR notice re 10CFR2 206 procedures
  BURNES, B. Regional Departions & Enforcement Division 82/07/14
- 8210220072 Informs that proposed rule on radiological protection activities coordination plan will be reviewed within next few months for congruence w/NRC/INPO umbrella memorandum of agreement re plant evaluations
  DIRCKS.H J Office of the Executive Director for Operations
  82/09/20 WILKINSON.E P Institute of Nuclear Power Operationa
  2pp 15786-245.
- ~-BROBO10019 Informs of acceptability of encl draft App 3. "Cumrated Plan for NRC/INPO Radiological Protection Activities," to NRC/INPO unbrella memorandum of agreement re plant evaluations
  HILKINBON W.P. Institute of Nuclear Power Operations. BRACHERS, DIRCKS, W.J. Office of the Executive Director for Operations.

#### NUNDUCKETED HEIVIS

- E10280531 Forwards requests for OMB review & supporting statement re groposed revisions to 100FR30, 40 & 70 specifying licensee responsibility for nuclear matis & procedures for termination of specific licenses works, PO Office of Administration 82/10/22 SCURRY, N Office of Hangement & Budget 1p 15914 333
- EZID260544 Forwards request for OMB review & Congressional infocallection request re economic & worker safety aspects of problem concerning steam generator tube integrity (generic lit) MCARAP Office of Administration 82/10/22 SCURRY,N Office of Management & Budget in 15814-325
- ETIO270106 Forwards request for DMB review & supporting statement re NABEO-0906. "Guidance for Implementation of SRP Rule." per LOCFR50 34(9) amend MCRNY-P O Office of Administration B2/10/20 SCURRY, N Office of Management & Budget ip 15832 320
- E210270116 Responds to approval request for info collection re
  100FR35 27 concerning records of teletherapy image &
  servicing Request approved through B30630 under GMS Number
  3150-0010, per Paperwork Reduction Act
  500FRY, Office of Management & Budget DMS 3150-0010 B2/10/0B
  500FT, S Document Management Branch 2pp. 19832 342
- E210270119 Responds to approval request for info collection re Mark 1 containment program Request approved through 851031 under C3 Number 3150-0091 per Paperwork Reduction Act SURBY.N Office of Management & Budget DMB 3150-0091 B2/10/09 0015 Document Management Branch 2pp 15832 344
- BRIGG70301 Forwards comments on Aug 1982 draft FEMA planning guidance for preparation of federal radiological emergency response ylansiper BRO920 memo NRC needs to continue to work w/FEMA in defining role as cognizant federal agency (ENTON-18 R Office of Nuclear Reactor Regulation, Director 82/10/15 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement App 15836-330
- --B210270304 Requests comments on planning guidance for preparation of fairly radiological response plan by 821015 Results of review will be provided for consideration & comment BEVOUND. R C Director's Office. Office of Inspection and Enforcement 82/09/20 DENTON. R Office of Nuclear Reactor Regulation. Director MAYNES. R C Region 1. Office of Director O'REILLY. J P Region 2. Office of Director 1p 15836 336
  - M0270450 Forwards, for info, draft rept & apps on pressurized thermal that Completed rept will form basis of Commission paper (we 821030 H/o and LAIMS). C Assistant Director for Operating Reactors 02/09/28 + M02108.P Atomic Industrial Forum 2pp 13863 181

### R PROPOSED RULE

- 1207140040 Transcript of 920615 public meeting re-certification of ridiographers (Region 5) in Oakland, CA Pp 1-99 Exhibits and
- Commissioners 82/06/15 121pp. 13847, 206
- E2:0010185 Comments on proposed rule 10CFR80 re fitness for duty Rule sould be altered to require that any individual solutions in jured by licensee application of rule be afforded adequate opportunity to rebut info MACKRON, RF Affiliation Unknown 47FR39780 024. 82/09/24 Deteting & Services Branch 13pp 15568 030
- MIMIO190 Comments on proposed rule 10CFR50 re fitness for duty of sotter power plant personnel Opposes rule COMDOT D H Affiliation Unknown 47FR33980 025 82/09/2/ Cotteting & Services Branch 1p 15568 020
- MIMOID218 Comments on proposed rule 10CFR50 re fitness for duty elautear power plant personnel Opposes rule SMINAJE American Nuclear Society 47FR33980 026 82/09/27 Withing & Services Branch 2pp 15568 028.
- RICO10223 Comments on proposed rule JOCFR50 re mandatory property invance for decontamination of nuclear reactors & NREF-0891, "Nuclear Property Insurance Status & Dutlook " Spaces rule.

  TORKE B Mississippi Power & Light Co. 47FR27371 041, 82/09/24 Office of the Secretary of the Commission ip 15568 019

- 8210010226 Pactage of two comments opposing proposed rule 10CFR 90 rumandatory property insurance for decontamination of nuclear reactors
  SANDERS, W.L. Alabama Power Co. GODDMAN, L. Affiliation Unknown.
  47FR27371 82709/27 CHILK, S.J. Office of the Secretary of the Commission 7pp 15568 021
- B210010230 Package of three comments on proposed rule 10CFR50 relicensed operator staffing at nuclear power units COUNSIL.W 0 Connecticut Yanke Atomic Power Co COUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Otilities) COUNSIL.W 0 On theast Utilities 47FRB135 82/09/29 Docketing & Barvices Branch 13pp 15568 248
- 8210010232 Package of three comments opposing proposed rule 100FR50 rulicensed operator staffing at nuclear power units offESLERIC U Misconsin Public Service Corp. SMITH.J.E. American Nuclear Society SMITH.J.E. Duke Power Co. 47FR38135 02/09/29 Docketing & Services Oranch. Lipp. 15574-062
- 9210010273 Comments on proposed rule IOCFR50 re licensed operator staffing at nuclear gower units Requirement to have two senior reactor operators on shift should be reconsidered & implementation date delayed for 1 yr HOUGHTON.T C. MMC. Inc. 47FR38135 008 82/09/27 CHILK.6 J Office of the Secretary of the Commission 14pp 15569 197
- --8207050005 Informs that vendor has been working closely w/utils & NH(
  in developing personnel requirements for operators of
  nuclear power plants NRC should issue regulations or
  guidance & not dictate means of meeting requirements
  KNUTH.D F HMC, Inc 82/07/13 PALLADIND,N Commissioners
  7pp 15567 202
- 8210010302 Comments on proposed rule 10CFR50 re mandatory property insurance for decontamination of nuclear reactors Supports rule SPENCER.M D. Texas Utilities Generating Co. 47FR27371 035 82/09/22 Office of the Secretary of the Commission. 2pp 15558 308
- 8210010307 Package of three comments opposing proposed rule 1061850) ro mandatory property insurance for decontamination of nuclear reactors
  OIESLER.C W Wisconsin Public Service Corp. WITHERS, D.D. Pacifis Gas & Electric Co. KELLY-A B. American Nuclear Insurers
  47FR27371 82/09/28 Cflitx, S.J. Office of the Secretary of the Commission 19pp. 15568-289
- 8210010310 Comments on proposed rule 100FR50 re staffing at nuclear power plants Deposes rule LEMIS.M I Lewis.M 47FR38135 004 82/09/10 Defice of the Bacretary of the Commission ip 19568 264
- 82:00:0322 Comments on proposed rule IOCFR50 re licensed operator staffing at nuclear power units Comment period should be extended 6 months during which time NRC should introduce addl evidence to justify proposed rule POPEO.D J. Washington Legal Foundation 47FR38135 007 82/09/2/Docksting & Bervices Branch 5pp 19574 035
- 8210010374 Package of two comments opposing proposed rule 100FR90.
  "Mandatory Property Insurance for Decontamination of Nuclear
  Reactors "
  PARKYN, J D Affiliation Unknown SOUCY, A R Yankes Atomic Electric
  Co 47F827371 S2/09/24 Docketing & Bervices Branch 5pp
  15573 090
- 8210010381 Package of four comments on proposed rule 10CFR50,
  "Mandatory Property Insurance for Decontamination of Nuclear
  Reactors " Supports rule
  WYATT-J H Louisiana Power & Light Co DELLSY.H K Commonwealth
  Edison Co. ROBERTBON.C O Houston Lighting & Power Co 47FR273/1
  82/09/24 Bocketing & Bervices Branch 22pp 15573 059
- 8210120147 Responds to 820830 ltr expressing concern re final version of 100FR61. "Licensing Requirements for Land Disposal of Redwaste." De minimis issue for managing low level radwaste will be addressed within next few yrs HARTIN. J. B. Division of Haste Hanagement 82/09/21 HARRIS. B. J. Health Physics Society 2pp 15692 177
- 8210120173 Forwards minutes of 820729 briefing on 10CFR60 W/o enci BELL: M J High Level Weste Technical Development Branch 82/08/31 BOHLINGER: H Louisians, State of LIEBGLD-W C Affiliation Unknown CAHIL-F C Environmental Protection Agency App 15692, 205

- 8210130270 Package of three comments supporting proposed rule 1008830, "Applicability of License Conditions & Tech Specs in Emergency "
  CLAYTON,F L. Alabama Power Co. MULLER, G.E. Illinois Power Co. PARKYN, J.D. Affiliation Unknown 478835996 82/10/04 CHILK, S.J. Gerice of the Secretary of the Commission. Spp. 15679 004
- 8210130277 Package of two comments opposing proposed rule 10CFR50 rule tithess for duty of personnel w/unescorted access to protected areas
  0'TGDLE.J D Consolidated Edison Co of New York PDFE0.D J
  Washington Legal Foundation 47FR33980 82/10/05 CMILK.9 J
  Office of the Secretary of the Commission 11pp 15678 355
- 62(0130282 Package of three comments on proposed rule 10CFR50 refitness for duty of personnel w/unescorted access to protected areas

  JENSIUH Detroit Edison Co. GIESLER, C. W. Wisconsin Public Service Corp. KEARREY, J. J. Edison Electric Institute 47FR33980

  82/10/04 CHILK, S. J. Office of the Secretary of the Commission 14pp. 15678-264
- 8210130331 Comments on proposed rule 10CFRS0 re mandatory property insurance for decontamination of nuclear reactors (MUNEG-0893) Imposition of blanket coverage requirement poses restrictive economic hardship on smaller plants TAYLOR.J N Dairyland Power Cooperative 47FR27371 042 92/09/23 Office of the Secretary of the Commission 2pp 15681 001
- 8210130391 Comments on proposed rule 10CFR50 refitness for duty of personnel w/unescorted access to protected area Existing program adequate Transferring authority to federal level will not improve effort LUNGWALLIAE Baltimore Gas & Electric Co. 47FR33980 027 82/09/30 CH1LX,S J. Office of the Secretary of the Commission 2pp. 15681 004
- 8210130376 Comments on proposed rule 10CFR50 re fitness for duty of personnel D/unescorted access to protected areas Great latitude for implementation would provide better end product than rule that defies compliance Opposes rule ANDGONINI.0 C Arisona Public Service Ca 47FR33980 028 82/09/2/Docketing & Services Oranch 4pp 1568: 028
- 8210130399 Package of 10 comments opposing proposed rule 10CFR50 refitness for duty of personnel w/unescorted access to protected areas KNUTH,0 F KMC, Inc. UHRIG,R & Florida Power & Light Co. COUNSIL,W G. Northeast Utilities. 47FR33980 82/10/04 CHILK,5 J. Office of the Secretary of the Commission. 33pp. 15681 128
- 8210130402 Comments on proposed rule 10CFR5D, "Licensed Operator Staffing at Noclear Power Units " Requirement to have senior reactor operator domiciled to control room would not contribute to overall plant safety DELOCORCE, L D Commonwealth Edison Co 47FR38135 Q17 82/09/27 Docketing & Services Branch 1p 15682 064
- 8210130433 Comments on proposed rule 10CFR50 "Licensed Operator Staffing at Nuclear Power Units" Need for proposed rule has not been adequately established HELFRICHIR E Vaniee Atomic Electric Co. 47FR38135 021 82/09/27 Docketing & Services Branch. 4pp. 15682 055
- 8210130521 Package of two comments on proposed rule 10CFR50, "Lacenced Operator Staffing at Nuclear Power Plants" MILLS.L M Tennessee Valley Authority VANDEWALLE.D J Consumers Power Co 47FR38135 82/10/04 Bocketing & Services Branch 6pb 15692 355

ents on proposed rule 1905RSO, "Applicability of License" Each Specs in Emergency " Supports rule efense, Dept of, Defense Nuclear Agency 47FR35996 006 ach 500 15683 001

- 8210130554 Comments on proposed rule IOCFR50 re mandatory property insurance for decontamination of nuclear reactors (NUREG-0891)
  MITTL.R L Public Service Electric & Gas Co of New Jersey 47FR27371 043 82/09/24 CHILK.S J Docketing & Services Branch 6pp 15694 001
- 8210130584 Comments on proposed rule 10CFR50. "Licensed Operator Staffing at Nuclear Power Units" Kin staffing table should be modified to indicate two-operator requirement for two-units one-control room plant FAY.C W. Wisconsin Electric Power Co. 47FR38135 018 B2/09/27 CRILK.S J. Diffice of the Secretary of the Commission 2pp 15679 088
- 8210130594 Comments on proposed rule 10CFR50, "Licensed Operator Staffing at Nuclear Power Units" Due to difficulties in obtaining qualified personnel effective date for rule should be extended to 840101

  THORPE.J R Oeneral Public Utilities GPU Service Corp 47FR58135
  016 82/09/28 CHIEK, SJ Office of the Secretary of the Commission ip 15679 116
- 8210130599 Package of two comments opposing proposed rule 10CFR50 "Licensed Operator Staffing at Nuclear Power Units" TUCKER.H B Duke Power Co MATTIMOE, J J Sacramento Municipal Utility District 47 FR38135 82/09/30 Docketing & Services Branch Spp 15479-050
- 8210220226 Comments on proposed rule 10CFR34 providing third party certification of radiographers Measure would be excellent step in direction of safety LOW-R L. Associated Technologies, Inc. 47FR19152-090 82/05/11 JONES, J. A. Office of the Secretary of the Commission 1p 15776-209
- 8210220246 Comments re proposed rule 10CFR34 providing for third party radiographic certification Opposes rule THOMPSON,V J Vester J Thompson, Jr., Inc. 47FR19152 081 82/05/21 GODWIN.A V Alabama, State of 1p. 15776 199
- B210220256 Comments on proposed rule 10CFR34 providing for certification of radiographers Supports rule
  SACKETTM H Affiliation Unknown 47FR19152 087 82/06/00
  JONES J A Office of Nuclear Regulatory Research, Director 3pp
- B210220285 Package of two comments opposing proposed rule 100FR90 rule fitness for duty COLLING.R M Bechtel Corp FLYNN,S F Carolina Power & Light Co 47FR33980 B2/10/07 Docketing & Services Branch 8pp 19775 076
- 8210220301 Comments on proposed rule 10CFR50 allowing waiver of Tech Specs during emergency situation if necessary to protect health & safety of public Supports rule WITHERS: B D Portland General Electric Co 47FR35974 011 82/10/05 Docketing & Services Branch 1p 15776 104
- 82(0220306 Comments on proposed rule 10CFR50 or applicability of license conditions & Tech Specs in emergency Applauds rule for providing leeway to protect health & safety of public Deplores need for rule which should be self-evident 0003MANLE S Affiliation Unknown 47FR35996 010 82/10/07 Docketing & Services Branch 2pp 15776 179
- 8210220316 Package of five comments on proposed rule 10CFR34 providing for third party radiographic certification
  HAMILTON.JF Oklahoma Steel Castings Co MODES, H C Universal Technical Testing Laboratories. Inc MCINNIS.E L Jacksonville Shipyards, Inc 47FR19152 82/10/08 JONES.JA Office of Nuclear Regulatory Research, Director 17pp 15776 128
- 8210220321 Package of two comments on proposed rule 10CFR34 providing for certification of radiographers.
  HICKLICH,R M. Rockwell International Corp. BRADLEY,F J. New York.
  State of 47FR19152 82/10/08 JONES.J A. Office of Nuclear Regulatory Research. Director. 7pp. 15776 170
- 8210220326 Package of two comments on proposed rule 10CFR30 re licensed operator staffing at nuclear power plants
  HITTLER L Public Service Electric & Qas Co of New Jersey PRATT.C M Power Authority of the State of New York 47FR38135 B2/10/07 CHILK.B.J Office of the Secretary of the Commission 2pp 13776 045
- 8210220333 Comments on proposed rule 10CFR50 re licensed operator staffing Rule lacks true applicability to criteria of YMI lessons learned & ignores complexity, range of different fac[littles & human factor issue of size of control room PAHKYN, J D. Affiliation Unknown 47FR38135 025 82/09/26 Docketing & Services Branch 2pp 15776 181

- 82IOIR0334 Package of three comments on proposed rule 10CFR50 ru (lives) for outy of personnel w/unescorted access to
- | Consumers Power Condition | Consumers Power Condition | Condition | Consumers Power Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Condition | Cond
- FILDP20339 Comments on proposed rule 10CFR50 re licensed operator shaffing Shared control room w/identical layout & controls for each unit of multi-unit stations proposed EAVIDSON, D. R. Cleveland Electric Illuminating Co. 47FR3B135 022 E2/07/25 Docketing & Services Branch ip 15776 028
- \$210226342 Forwards comments on proposed rule 10CFR34 W/o encl FAULICK.L R Pipe Fabrication Institute 47FR19152 086 82/09/09 CMCS.J A Office of Nuclear Regulatory Research, Director Ip 13724 151
- E215220333 Comments on proposed rule 10CFR50 re mandatary property insurance for decontamination of nuclear reactors (NAFCS-0891) Insurance problems should remain responsibility of utils & NRC should not impose mandates 11VNH3 W South Carolina Electric & Oas Co. 47FR27371 046 827[07]1 CHILK-S J. Office of the Secretary of the Commission Co. 15776 271
- 210220359 Comments on proposed rule 10CFR50 re fitness for duty of systemet u/unescorted access to protected areas Most practical approach would be issuance of general policy statement rather than rule saturent rather than rule has resulted by Public Service Co of Colorado 47FR33980 056 8210704 CHIEKS J Office of the Secretary of the Commission by 15776 257
- 62:0220366 Comments on proposed rule 10CFR50 re fitness for duty of personnel diffusered access to protected areas Rule not receivery (URIS:N H pennsylvania Power & Light Co 47FR33980 057 p2/10/07 HOYLE:J C Office of the Secretary of the Commission 2st 15779 199
- E210220372 Package of four comments on proposed rule 10GFR50 re fitness for lute of parsonnel w/unescorted access to protected
- ETHANDS D H Yankee Atomic Electric Co THORPE. J R Queeral Public Countries OPU Service Corp QARY.R J Texas Utilities Concreting Co 47FR33780 B2/10/12 Docketing & Services Branch 1 Gpp (1378 338)
- Exion20373 Comments on proposed rule 10CFR50 rs fitness for duty of streamst w/unescorted access to protected areas Opposes sale [EMSRG1.R H Virginia Electric & Power Co 47FR33980 063 82/10/08 Docketing & Services Branch 2pp 19779 182
- E210220376 Comments on proposed rule 10CFR50 re fitness for duty of intended w/unescorted access to protected areas Current seques practiced throughout industry adequate w/o use of the blood tests agorgangle out of States Utilities Co. 47FR33980 062 82/10/04 Quitting & Bervices Branch 3pp 15779 179
- 2:022379 Comments on proposed rule 10CFR60 re technical criteria for geologic repusitories for high level raduasts Overly retrictive & specific performance elds not necessary settled. If American Nuclear Society 46FR35280, 82/10/03 DIGEST J Office of the Executive Director for Operations 3p 1579 171
- 22/02/03/03 Pactage of three comments on proposed rule 10CFRBO re
  filters for duty of personnel w/unescorted access to
  feteteted areas
  PRINCES, N.S. Debevoise & Liberman DELGEORGE, L.O. Commonwealth
  Efficiency MAIER, J.E. Rochester Gas & Electric Corp. 47F/3/3/9/00
  EMINONS CHILL, S. J. Office of the Becretary of the Commission
  27s 15/779 391
- ©1020095 Package of three comments on proposed rule 10CFR5D refitness for duty of personnel w/unescorted access to provide access to provide access to provide access to provide access to access to access to access to access the formation of the following access to the following access to access to access to access to access the following access to access the following access to access to access the following access to access the following access to access the following access to access the following access to access the following access to access the following access to access the following access to access the following access to access the following access to access the following access to access to access the following access to access the following access to access to access the following access to access to access to access to access to access to access the following access to access to access to access to access to access to access to access to access the access to access to access to access to access to access the a

- 8210220403 Package of two comments on proposed rule 10CFR50 re applicability of license conditions & Tech Specs in emergency KOESTER.0 L. Kansas Oas & Electric Co. FUENTE.E.S. Mississippi. State of 47FR3596 82/10/13 Docketing & Gervices Branch 2pp 15779 164
- B210220409 Petition for exemption from schedular requirements of proposed rule 100FR50 re hydrogen control UTLEV,E E Carolina Power & Light Co 45FR65466 B2/10/11 CHILK,S J Office of the Secretary of the Commission 4pp 15779 207
- 8210290234 Package of four tomments supporting proposed rule 10C/R50 re applicability of license conditions & Tech Specs in emergency situations \*\*

  \*\* LeBoeuf, Lamb, Leiby & MacRae GIESLER, C.W. Wisconsin Public Service Corp. FJSMER. C.R. GA Technologies. Inc. /General Atomic Co. 47FR35996 82/10/21 CHILK, S.J. Dffice of the Secretary of the Commission. 8pp. 15893-267
- 8210290237 Comments on proposed rule 100FR50 re applicability of license conditions & Tech Specs in emergency situations Rule vague & unquantified BRADDURY,R & Stone & Webster Engineering Corp. 47FR35996-026 82/10/18 Docketing & Services Branch 2pp. 15853-179
- 8210290239 Package of two comments opposing proposed rule (OCFRbC refitness for duty of phraomnel w/unescorted access to protected areas SHIELDS-S W Public Service Co of Indiana. Inc. MUSDLF, D
- SHIELDS:S W Public Service Co of Indiana, Inc. MUSCLF, D Northern States Power Co. 47FR33980 82/10/18 CHILK, S J. Office of the Secretary of the Commission 11pp 15853 239
- 8210270240 Package of six comments supporting proposed rule 1007R50 re applicability of license conditions & Tach Epacs (n emergency situations ZUMMO.J. LORIG.P. Utility Workers Union of America MARSHALL.JR Arkansas Power & Light Co. 47FR35976 82/10/18 CHILK,S.J. Office of the Secretary of the Commission 13pp. 19853 182
- 8210290242 Comments on proposed rule 10CFR30 re fitness for duty of personnel u/unescorted access to protected areas Utils already have related programs 87ALAY.R Atomic Industrial Forum 47FR33980 070 82/10/22 Docketing & Services Branch 2pp 15863 265
- 8210290244 Comments on proposed rule 100FR50 re applicability of license conditions & Tech Specs in energency situations Opposes rule EDDLEMAN, W. Affiliation Unknown 4/FR35976 021 82/10/14 Office of the Secretary of the Commission 3pp 15853 254
- 6210290245 Package of two comments supporting proposed rule 1907R50 re applicability of license conditions & Tech Specs in emergency situations
  DIXON Q W South Carolina Electric # Qas Co DELGEORGE. L O
  Commonwealth Edison Co 47FR35996 82/10/19 CHILM. B J Diffice of the Secretary of the Commission 5pp 15054 086
- 8210290249 Comments on proposed rule (OCFRSO, "Licensed Operator Staffing at Nuclear Power Units" Rule underestimates difficulty involved in selecting training & licensing personnel MUSOLF.D Northern States Power Co 47FR30135 026 82/10/06 Docksting & Services Branch 2pp 15854 099
- 8210290253 Comments on proposed rule 10CFR50. "Licensed Operator Staffing at Nuclear Power Units " Deposes rule SZALAY, A Atomic Industrial Forum 47FR38135 027 82/10/22 Docketing & Services Branch tp 15854 090
- 8210270255 Comments on proposed rule 10CFR50 re reduction in vol of Tech Specs for nuclear power reactors Supports rule HONEY: J American Muclear Insurers 47FR13369 031 82/10/14 Docketing & Services Branch & pp. 15853 114
- 82/0290259 Comments on proposed rule 10CFR5D re applicability of license conditions & Tech Specs in emergency situations Bupports rule, BAUSER: N.A. Lowenstein: Newman: Reis: Axelrad & Toll 47FR3599& 014 82/10/15 Bocteting & Gervices Branch 2pp 15853:12&
- 8210290263 Package of two comments supporting proposed rule 10CFR50 re applicability of license conditions & Tech Specs in emergency situations EDWARDS.O W Yankee Atomic Electric Co BOOKER. J E Oulf States Utilities Co 47FR95976 82/10/20 Docketing & Services Branch 3pp 15854 091

8210290265 Comments on proposed rule 10CFR50 re actions that depart from license conditions or Tech Specs in emergency Supports

MILLS,L M Tennessee Valley Authority 47FR35996 031 82/10/2 Drive of the Secretary of the Commission 1p 15854 045

8210290267 Package of two comments opposing proposed rule 100FR50 re fitness for duty of personnel w/unescorted access to protected areas

Protected ateas

KUBINAK,R A Long Island Lighting Co SANDY,W Affiliation

Unknown 47FR33980 62/10/21 Docketing & Services Branch Spp. 19854 078

8210290273 Package of two comments opposing proposed rule 10CFR50 refitness for duty of personnel w/unescorted access to protected areas
NIXON ON South Carolina Electric & Gas Co. GUCHA-L. T. Georgi

projected areas DIXON.O H South Carolina Electric & Gas Co. GUCWA-L T. Georgia Power Co. 47FR339BO 82/10/19 CHILK.S J. Office of the Secretary of the Commission. Spp. 15934-054

## PRM PETITION FOR RULEMAKING

6210130257 Comments on petition for rulemaking PRM-50-33 re reduction in frequency of emergency planning exercises Supports petition & concept of biennial secretises Supports MOPHOOD, CA Drange County, CA 47FR29252 035 82/09/30 Office of the Secretary of the Commission Ip 15675 336

82(0)30280 Comments on petition for rulemaking FRM-50-32 re protection against affects of electromagnetic pulse Petition should be denied CAGMETTA, J.P. Atomic Industrial Forum 47FR27371 021 82/10/04 Docketing & Bervices Branch 2pp 15678 350

8910220294 Comments on petition for rulemaking PRM-50-328 reelectromagnetic pulse in nuclear power plants Requests that 10CFRSO be amended to require provision for design features for protection against attacks & destructive acts MARSHALL, W H Mapleton Intervenors ISSUANCES OM 82/08/31 Office of the Secretary of the Commission 2pp 15776 066

8210220386 Comments on petition for rulemaking PRM-50-33 re emargency preparedness Supports concept of reducing frequency of emergency exercise involving state & local govt GUCMA-L Georgia Power Co. 4762925 036 82/10/04 Docketing & Services Branch 1p. 15779 170

#### PROJ PROJECTS - PREDOCKET LICENSING

8210120360 Forwards comments on "Topical SAR for Castor Cast Type ISF81 (Dry Storage) " Tosts & analysis results do not address site parameters Only generic design info applicable ROUSE; L. C. Advanced fuel & Spent Fuel Licensing Branch 82/09/29 ROUSE; L. C. Advanced fuel & Spent Fuel Licensing Branch 82/09/29 ROUSE; C. Ogesellschaft für Nukleur-Service mbH 47pp

8210250356 Comments on 820921 proposed order concerning preservation of documents Util should not be allowed to terminate proceeding Parties should provide list of files designated "central files " Certificate of Svc enc! MCDIARMID.R C Northern California Pawer Agency, California, State of, BLAIR.B S Anaheim, CA BLAIR.B S Riverside, CA ISSUANCES A 82/10/21 [Opp 15790 141]

9210270175 Notice of ASLB reconstitution JA Laurenson, chairman LAZO,R if Atomic Safety and Licensing Soard Panel ISSUANCES A 62/10/25 ip 15922 354

#### MONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

itro) rod guide tube lants:

214 80/03/14

tube support pins rating

11 EIBENRUT, D

82(0120236 Part 21 rept re emergency standby diesel generator set Defect exists in one power piston installed in Cylinder Location 71 in engine 7188 Piston will be replaced by Apr 1783, prior to stantup STOLBA.F B Cooper Energy Services PT21 82-698-000 82/09/30 Director's Office, Office of Inspection and Enforcement 19 (5845) 104

8210130447 Part 21 rept re sheared pinion keys in Limitorque Model 98-0-25 motor operators Sheared keys apperently resulted from use of inappropriate matis Utils advised to watch for indications of failed pinion keys RAME, E.P. Westinghouse Electric Corp. NS-EPR-2637 B2/09/29 BEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 2pp 15682 028

8210250132 Part 21 rept re preliminary exam of EPRI safety & relief valve test program indicating that Dresser safety valves could chatter reducing capability to relieve pressure Listed plants should determine ring settings
TAYLOR.J H Babcock & Milcox Co PT21 B2-718-000 B2/10/15 DEYUUNG.R C Director's Office Office of Inspection and Enforcement 3pp 15787 019

QA999 QUALITY ASSURANCE INSPECTIONS

920929016B Responds to FOIA request for documents prepared by NRC staff & consultants on 100FR50.App B re GA audits of testing facilities conducted within past 10 yrs by NRC Related documents listed security of Rules and Records 82/08/26 PHILIPS, H II Bebevois & Liberman 2pp 15564 002

--8207270236 Forwards GA Program Insp Rept 79700705/82-01 on 811227-30 No noncompliance noted HEISHMAN R F Reactor Construction Branch 82/05/26 BBUCHEY: O D Washington Public Power Supply System 2pp 15544 Q40

--8209270240 GA Program Insp Rept 99900705/82-01 on 811229-30 No noncompilance noted Major areas inspected test set-up of Weidmuller terminal block post-LOCA test program, post-test insp test specimens & test plan AGEE.J R , BENNETT.A B Reactor Construction Branch CRAFT.C M Bandia Laboratories 82/09/18 5pp 15564 062

B21004014B Ack receipt of 820827 itr informing NRC of steps taken to correct monconformance noted in GA Program Insp Rept 9990083782-01 POTAPDVS,U Division of Vendor & Technical Programs 82/09/27 MOYER,D J Pacific Pumps Div 1p 15382 350

--8210040155 Responds to NRC ltr re nonconformance noted in GA Program
Insp Rept 9990063/82-01 Corrective actions visual insp
procedure added providing approved written procedure after
mfg operations, welding & cleaning
HOYER: D J Pacific Pumps Div 82/08/27 POTAPOVS, U Division o
Vendor & Technical Programs 2pp 15582,351

8210040171 Ack receipt of 820908 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900503/82-02

POTAPOVS, U Division of Vendor & Technical Programs 82/09/27 HENDRICKSON, T Burns & Ros Co 1p 18582 308

---B210040173 Responds to NRC 820806 itr re nonconformance noted in QA Program Insp Rept 99900303/82-02 Corrective actions, special audit will be performed to verify that each corporate operation manual is up-to-date HENDRICKSON. T. Burns & Roc Co 82/09/08, PDTAPDV8, U Division of Vendor & Technical Programs Spp 15582 306

8210040192 Ack receipt of 820823 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900404/82-01 PDTAPOV8.U Division of Vendor & Technical Programs 82/09/27 SLEMBER.R J Hestinghouse Electric Corp. 19 15583 184

--B210040176 Responds to NRC 820811 ltr rs nonconformance noted in 0 Program Insp Rept 97900404/82-01. Corrective actions, GA program revised in 1981 to require that purchase order or purchase order change se issued to vendor RLEMBER: R J. Hestinghouse Electric Corp PI&DA-82-21;5 82/08/23 POTAPOVS, U Division of Vendor & Technical Programs 2pp 15583 185

8210040333 Ack receipt of 820904 & 15 ltrs informing NRC of steps to correct nonconformance noted in GA Program Inap Rept 99900712/82-01
POTAPOR, U Division of Vendor & Technical Programs, 82/09/R7, CAPRAL A Systems Control, Inc. ip. 15586-180

- --2210040335 Revises B20904 response to NRC B20804 ltr re nonconformance nated in GA Program Insp Rept 99900712/82-01 Corrective actions GA manual will be revised & new procedure developed to address control of drawings CAPRA. A Systems Control Inc B2/09/15 PATAPAYS, U Division of Vendor & Technical Programs 2pp 15584 181
- --2210040340 Responds to NRC 820806 ltm re nonconformance noted in OA Program Insp Rept 99900712/82-01 Corrective actions OA excusi will be revised procedures followed in transmitting frautings instructions developed for control of drawings CAPRAL A Systems Control. Inc 82/09/04 POTAPOVS. U Division of Vendor & Tachnical Programs 2pp 15586 183
- 5310050188 Act receipt of 820630 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept eag00533/83-01 FOTAF005.U Division of Vendor & Technical Programs 82/10/01 TAILEY.F C Teledune Engineering Services ip 15611 189
- --E210350191 Responds to NRC 820611 ltr re-nonconformance noted in GA Program InSp Rept 97900513/82-01 Corrective actions dual storage of records design activities re-containment tonus beforedynamic analyses provided in accordance w/oA manual E21LEV.F.C. Teledyne Engineering Services A773-82/01, 82/06/3( PCTAPEVS,U Division of Vendor & Technical Programs 7pp 15611 190
- E210050195 Act receipt of 820910 ltr informing NRC of steps taken to carrect nonconformance noted in GA Program Inap Rept 9950033/82-01 POINDUS NOTED TO Vendor & Technical Programs 82/10/01 PUPPEL ND Westinghouse Electric Corp 1p 15609 173
- 8210030284 Ack receipt of 820128 & 811006 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp. Fest 99700334/81-02. Two nonconformances, Itams C & D. closed tok k require no further action 90128988. Division of Vendor & Technical Programs 82/10/01 MATHEMS.C Transamerica Delayal. Inc. ip 15611-163
- --9210030287 Ack receipt of 820128 & 811006 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rest 99900334/81-02 Questions re validity of nonconformance. Items C & D. re snviron qualification of motors unacceptable potapuls. U Division of Vondor & Technical Programs 82/05/06 MATRESS. Transamerica Delaval. Inc. 2pp 15611 164
- --8210050270 Responds to NRC B20114 ltr re nonconformance noted in BA program Insp Rept 9790036/181-02 Requests reconsideration of anconformance Items C & D Hotor name plats & motor test rest indicate motors are environmentally qualified.

  BUER, R E Transmentica Delaval, Inc B2/01/28 POTAPDVS, U Vendor Inspection Branch Zpp 15611 166
- --B2100502P2 Ack receipt of 811006 ltr re nonconformance noted in QA frogram insp Rept 97900334/81-02 Addl info required in order to consider request for re-evaluation purpovist. Vendor Inspection Branch 88/01/14 MATHEMS. C Transmerica Delaval. Inc. 2pp 13611 148.
- --8210050275 Responds to NRC 810718 ltr re-nonconformance noted in 6A Frogram Insp Rapt 99900334/81-02 Corrective actions drawing a showing installation of oil plug revised, Requests reconsideration of Items B.C & D 80088, RE Transamerica Delaval, Inc 81/10/04 POTAPOVE, U Vandor Inspection Branch 6pp 19611-170
- 8210120202 Forwards OA Program Insp Rept 99900522/82-02 on 820712-15 60 noncompliance noted FOTAPDYS-U Division of Vendor & Technical Programs 82/09/15 STATION C D Bachtel Corp 3pp 15452 130
- --B2j0120233 GA Program Insp Rept 99900522/82-02 on 820712-15 No conceptionce noted, Major areas inspected: procedures & representative records re hydrodynamic load analysis, interviews w/personnel & observations by inspectors, 605fELLO, J. R., HALE, C. J. Division of Vendor & Technical Programs 82/09/08 lipp 15652 133.
- 82(0)20280 Ack receipt of 820525 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rapt 9760302/81-02.
  FORMOUS-U Division of Vendor & Technical Programs 82/10/06 FRIENDAN, N.A. Western Piping & Engineering Co., Inc. ip. 1943-052

- --8210120285 Forwards ASME Ltr indicating status of inquiry re nonconformance noted in GA Program Insp Rept 99900302/81-02 HAYTACK,R K. Western Piping & Engineering Co., Inc. 82/08/23 POTAPOVS,U. Division of Vendor & Technical Programs 2pp 15553-053
- --8210120293 Responds to NRC 820504 ltr re nancanformance noted in UA Program Insp Rept 99900302/81-02 Categorically denses allegations of nonconformance re design of component supports FRIEDMAN.K A Hestern Piping & Engineering Co., Inc. 82/05/25 POTAPOVS.U Division of Vendor & Technical Programs 3pp 18653-055
- 8210120301 Ack receipt of 820623 & Q901 itrs informing NRC of steps taken to correct nonconformance noted in QA Program (nsp Rept 9700400/79-04 POTAPOVS.U Division of Vendor & Technical Programs 82/10/05 GUILBERT.D & Babcock & Hilcox Co 1p 15653 Q41
- --B210120304 Responds to NRC 620811 ltr re nanconformance noted in UA Frogram Insp Rept 99900400/79-04 Corrective actions input ref for old calculations winew effectivities varified OULLBERT DE Babook & Milcor Co 82/09/01 POTAPRUS, U Division of Vendor & Technical Programs 2pg 15453 042
- --B210120309 Ack receipt of B20623 lir informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900400/79-04 Request verification of input lef for revised calculations POTAPOVS.U Division of Vendor & Technical Programs B2/08/11 GUILBERT.D E Dabcock & Hillor Co ip 15653-044
- --8210120313 Forwards rept re nonconformance noted in GA Program Insp 99900400/79-04 Corrective actions treatment of new & revised calculations defined for source ref gilot program QUILDERT.D E Babcock & Wilcox Co 82/06/23 PUTAPOVS.U Division of Vendor & Technical Programs 5pp 15653 045
- 8210120311 Forwards OA Program lnsp Rept 99900780/82-01 on 820712-16 & notice of violation & monconformance POTAMOVS, U. Division of Vendor & Technical Programs 82/09/19 STEVENSON, J. G. Magnetrol International. Inc. 2pp 15452-059
- --82/0120312 Notice of violation from insp on 820712-16
  # Division of Vendor & Technical Programs 82/09/15 ip 15652.061
- ~~82;0120317 Notice of nonconformance from the pon B2D712~16 # Sivision of Vendor & Technical Programs 82/09/15 ip 15852:062.
- --BR10120319 GA Program Insp Rept 99900780/BB-01 on 820712-16
  Noncompliance noted Part 21 procedures not adopted for
  evaluating defects pertaining to Class IE items & IEEE Std
  dA program not established for mfg of Class IE items
  PARKER.L B , BARNES, I Division of Vendor & Technical Programs
  82/08/30 Spp. 15652 063
- 8210150513 Ack receipt of 820713 & 0914 line re nonconformances noted in GA Program Insp Rept 9970289782-01 POTAFOVS. V Division of Vendor & Technical Programs 82/10/08 DV8ROW.A L Borg-Warmer Corp 1p 15714 212
- ~-8210150517 Responds to NRC 820831 ltm re nonconformances noted in QA Program Insp Rept 99900289/82-01 Corrective actions systematic check of drawings made No evidence of similar error found MILINAZZO.P.L. Borg-Werner Corp. 0-82-084/PLM 82/09/14 POTAPOV8.U. Division of Vendor & Technical Programs 3pp 15714 213
- --8210150521 Act receipt of 820713 itr re honconformances in Program Thep Rept 99700289/82-01 Response unacceptable. Required design incomplete Revised response expected within 25 days of itr receipt POTAPOVS. U Division of Vendor & Technical Programs PUSROW.A L Sorg-Harner Corp Ip 15714 216
- --82(0150526 Responds to NRC ltr re nonconformances noted Insp Rept 99900289/82-01 Corrective actions disagress; revealed nonconformance Systematic check of remaining drewings found no similar error HJLINAZZG,P L. Barg-Marner Corp Q-82-043/PLM 82/0 POTAPOVS.U. Division of Vendor & Technical Programs 15/14:217.

- 8210150502 Ack receipt or 811123,820111 & 0723 ltrs in response to 0A Program Insp Rept 97900759/81-01 Efforts to account for 10 missing or unaccounted for defective springs of the print of tending governors w/defective springs continuing POTAPOVS,U Division of Vendor & Technical Programs 82/10/08 SUNDSTEDITURE Monday of Governor Co 1p 15713 147
- --82j0150536 Forwards ltr sent to customers re exemption from 10CFR21 6 posting regulations, per NRC 820506 ltr & in response to GA Program Insp Rept 97900759/81-01 List of customers encl ZWEG, A Hoodward Governor co 82/07/23 POTAPOUS, U Division of Vendor & Technical Programs App 15713 150
- --8210150540 Ack receipt of Bili23 & 820111 ltrs in response to GA Program Insp Rept 99900759/81-01 lnfo re corrective action measures required within 25 days PDTAPPOWS.U Division of Vendor & Technical Programs 82/05/06 SUNDSTEDT.J E Hoodward Governor Co ip 18713 186
- --8210(30544 Supplemental response to violations noted in GA Program
  Insp Rept 99900759/81-01 Corrective actions second complete
  investigation results search conducted to verify original
  results Ltrs to customers encl
  VEITCH, J L Hoodward Governor Co 82/01/11 POTAPOVS,U Vendor
  Inspection Branch Slpp 15713-157
- 8210190369 Ack receipt of 820930 ltm informing NRC of steps taken to correct nunconformances noted in QA Program Insp Rept 99900769/82-02 POTAPOVS.U Division of Vendor & Technical Programs 82/10/14 MESS.L R Pacific Air Products Co tp 15741 133
- --B210190372 Responds to NRC B20823 ltr re nonconformances noted in GA Program Insp Rept 99900769/82-02 Corrective actions calibr date labels on micrometers calipers & Porta-Lab replaced & GC insp implemented to inspect/replace labels Audits encl HESS.L R . CONLON.E T Parific Air Products Co 82/09/30 POTAPBUS.U Division of Vendor & Technical Programs 20pp 15741 174
- 82(0190725 Forwards QA Program Insp Rept 99900902/82-06 on 82052b-26, 0603-05 & 29-0701 No noncompliance noted POTAPOVS,U Division of Vendor & Technical Programs 82/10/01 SHITH E W Hyle Laboratories 3pp 15/37 114
- --8210190761 QA Program insp Rept 99900902/82-06 on 820525-26,0603-05 & 29-0701 No noncompliance noted Major areas inspected first 24-h of LOCA/HELB environ qualification tests for Foxboro N-E 10 & Rosemount 1193 Series D pressure transmitters FHILLIPS H S . JOHNSON A R Division of Vendor & Technical Programs 82/09/20 11pp 15737 117
- 82(0190756 Forward: QA Program Insp Rept 99900907/82-02 on 620621-22 No noncompliance noted POTAPOUS V Division of Vendor & Technical Programs 82/09/27 EDELSTEIN, A National Testing Systems 3pp 15737 105
- --8210190766 GA Program Insp Rept 99900907/82-02 on 820621-22 No noncompliance noted Major areas inspected followup insp of all spations made against employee & initial testing of Dorg Marner modulating electrohydraulic valve operator AGEE. J. R. PHILLIPS.H. S. Region 4. Office of Director 82/09/23 App. 15737 108
- 8210220407 Responds to 820803 itr re Woodward Obvernor Co failure to adapt appropriate procedures, per 100FR21 21(a) & failure to post procedures, per 100FR21 & Dedication of governors falls on procuring party, per 100FR21 POTAPOVS.U Division of Vendor & Technical Programs 82/10/05 HORIARTY, J Colt Industries, Inc. 1p 15778 297
- ~-8210220417 Discusses Woodward Governor Co failure to comply w/10CFR21 6 posting requirement No further action will be taken unless advised by NRC MORIARTY.J M Colt Industries Inc 82/08/03 PDTAPDVB, U Division of Vendor & Technical Programs 3pp 15778 298
- 8210250121 Ack receipt of 820923 ltr informing NRC of steps taken to correct nonconformance noted GA Program Insp Rept 99900005/82-01
  POTAPOVS, U Division of Vendor & Technical Programs 82/10/20
  JACOBI, W N Westinghouse Electric Corp 1p 15787 038
- --8210250128 Responds to NRC 820902 ltr re nonconformance noted in QA Program Insp Rept 97900003/82-01 Corrective actions QC instruction revised to include instruction to area supervisors & procedure placed in assigned book RUSSO, H L Westinghouse Electric Corp 82/09/23 PDTAPOVS, U Division of Vendor & Technical Programs 3pp 15787 039

- 9210250135 Ack receipt of 820924 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 9900294/82-01
  POTAPQVS,U Division of Vendor & Technical Programs 82/10/20
  HOGUER,D L Westinghouse Electric Corp 1p 15787 007
- --8210250141 Responds to NRC 820817 ltr re nonconformance noted in &A Program Insp Rept 999029482-01 Corrective actions ltr sent to district sales ofcs requesting copy of customer purchase order for any nuclear safety-related orders MCKECVER.R F. Westinghouse Electric Corp 82/09/24 POTAPOVS, U Division of Vendor & Technical Programs 3pp 13787 008
- 8210260126 Forwards QA Program Insp Rept 99900400/82-03 on 820817-18 g notice of nonconformance POTAPDG.U Division of Vendor & Technical Programs 82/10/05 GUILBERT,D G Babcock & Hilcox Co 2pp 15799 057
- --8210240127 Notice of nonconformance from insp on 820817-18 # Division of Vendor & Technical Programs 82/10/05 2pp 15797 039
- --B210260131 GA Program Insp Rept 99700400/B2-03 on B20817-18 Noncompliance noted error identified in hybrid computer program POWER TRACK not processed per Procedure NP8-0903-13 HALE: C J Division of Vendor & Technical Programs B2/09/27 7pp 15799 041
- 8210260494 Forwards QA Program Insp Rept 99900003/82-02 on 820824-27 & notice of nonconformance POTAPOVS,U Division of Vendor & Technical Programs 82/10/12 LONG, J A General Electric Co 2pp 15805 114
- ~-8210760496 Notice of nonconformance from insp un 820824-27

  \* Division of Vendor & Technical Programs 82/10/12 2pp
  15805 118
- ~-821026055B QA Program insp Rept 99700003/82-02 on 820824-27 Noncompliance noted all purchase order requirements not verified, purchased butk chemicals not always examined upon delivery & hardness tester not callbr every 3 months MCMEILL.4 M , BARNESI I Division of Vendor & Technical Programs 82/10/05 Bpp 15805 120

#### RECOD REGULATORY GUIDES

- B210060009 Draft Reg Guide 1 XXX, Revision 3, "LER Sys"
  + NRC No Detailed Affiliation Given 81/11/16 22pp 15731 215
- 8210050017 Forwards proposed response to Ballot N13 on proposed AND1 Std N721.per draft Reg Guide OP 713-4, "Internal Dosimetry 55ds for Tritium." for concurrence COOL.W Occupational Health Standards Brench 79/03/16 URODSKY.A NRC - No Detailed Affiliation Olven 4pp 15612 332
- ---8210050020 Forwards "Guidelines for Bioassay Requirements for Tritium" to assist in development of licensing program, per draft Reg Guide OP 713-4 ALEXANDER, R. E. Occupational Health Standards Branch, (after 740734 see 850H) 77/10/27 SINGER, B. Radioisotopes Licensing Branch (Pre 790501) ip 15612 335
- --8210050024 Concurs w/NMSS position on proposed ANSI Btd, N721, "Internal Dosimetry Btds for Tritium" per draft Reg Guide GP 713-4 Considerable empirical data available to develop reg guide similar to branch position used by NMSS BRODSKY.A NRC No Detailed Affiliation Given 79/01/31 COOL.W Occupational Health Standards Branch 2pp 15612 344
- --8210050030 Forwards Environ Evaluation Branch comments on proposed ANG Std N721. "Internal Dosinstry Stds for Tritium" per draft Reg Ouide OP 713-4 Std suitable for implementation as reg guide DENTON-H R Office of Nuclear Reactor Regulation, Director 79/01/29 MINDOUE/R Office of Standards Development, Director 4pp 13612-346
- --B210050034 Comments on proposed ANSI Std N721. "Internal Dosimetry Sti for Tritium." per draft Reg Guide OF 713-4 Document Unacceptable as reg guide in present form because prof background required for comprehension CUNNINGHAM, R E Division of Fuel Cycle & Material Bafety 79/0/23 OCLERK K Division of Siting, Health & Bafeguards Standards 3pp 15612 350

- --E210050042 Requests technical review of encl proposed ANSI Std N721, \*Internal Dosimetry Stds for Tritium" per draft Reg Guide OP 713-4 Recommendations for action on Ltr Ballot Ni3 requested by 77017 M/o encl

  COLLERK R Division of Siting, Health & Safeguards Standards 78/12/27 DAVIS, J G Office of Inspection & Enforcement. Office of the Director DENTON.H R Office of Nuclear Reactor Regulation, Director DIRCKS,W J Office of Nuclear Material Safety & Safeguards, Director 2pp 15612 354
- Endardil2 Reg Guide 2 B.Revision 2. "Preparation of Environ Repts for U Milbs " • Office of Nuclear Regulatory Research, Director 82/10/31 49pp 15163-318
- EMIC2003R0 Forwards proprietary & nonproprietary responses to Revision 1 to Res Guide 1 92. "Combining Model Responses & Spatial Corponents in Seismic Response Analysis" to assist in fuel assistly analysis response withheld (ref 100FR2 790) AR-E-F P Westinghouse Electric Corp NS-EPR-2658 82/09/17 EERLINGER.C . NEYER.R O Core Performance Branch 2pp 15803 045
- --E210260351 Submits application for withholding proprietary response to Revision I to Reg Guide 1 92, "Combining Model Responses & Epatial Components in Seismic Response Analysis " Affidavit & nonproprietary response encl YIESEMANIR A Westinghouse Electric Corp AW-82-55 82/09/17 BEPLINDER, C H Core Performance Branch 9pp 15803 047
- 52.0290247 Comments on draft Reg Guide QP 722-4, "Qualification for Pai:ation Safety Officer in Large-Scale Non-Fuel-Cycle Biglonuclide Program " Small hosp will be at disadvantage if Jude is adopted ALLEN.J J St Lukes Hosp Milwaukee, WI 82/09/28 BELL.J M NRC to Disalted Affiliation Oliven 2pp 15854 088

1%20251 Comments on draft Reg Ouide OP 722-4, "Qualification for Palistion Safety Officer in Large-Scale Non-Fuel-Cycle Palistide Program " Guide should be more specific re programs requiring expertise CCO-6.8 R Forbes Health Sys , East Suburban Health Center Notational Palisting & Services Branch | 19 1553 125

# RESEARCH AND TECHNICAL ASSISTANCE REPORTS

- © 0000504 "Quick Look Rept on Test of Intermediate Vessel V-8A-Tearing Blavier of Lou Upper-Shelf Hatl" BRANK H., BOLT, B.E., MERKLE, J.O. Oak Ridge National Laboratory FN 8-0197 ORNL/887-4 82/08/25 Division of Engineering Technology 20pp 13426 334
- E:10060425 "Quarterly Mgt Rept ORNL Programs for NRC Ofc of Nuclear Segistory Research." third quarter ICHS.A L , BAYLOR.V B , HOMAN.F J Oak Ridge National Laboratory R2/99/01 Office of Nuclear Regulatory Research. Director 72pp 1555-308
- KIMMO149 "SSC Development, Validation & Application, " & "Generic Inlance of Plant Modeling," monthly highlights for Aug 1982 497, J 0 Brookhaven National Laboratory FIN A-3015 82/09/08 UNIS.8 T Severe Accident Assessment Branch 8pp 15437-348
- K 08032 "Actual Emission/Flaw Relationships for Inservice Mailtoing of Nuclear Pressure Vessels," monthly progress rightfor Aug 1982 3,71,8 H . HUTTON,P H Battelle Memorial Institute, Pacific Mailteast Laboratory FIN 8-2088 82/09/22 MUSCARA,J Materials "glasering Branch 8pp 15668 323.
- H20118 "Reactor Expert Sys for Diagnosis & Treatment of Nuclear Hiter Accidents," presented to Natl Conference on Hifs(sal Intelligence, B20818-20 BEOW, R. E0&G. Inc. EGG-M-09782 B2/08/20 Offfice of Nuclear Hulatory Research, Director 7pp. 15687 156
- 0100124 "Multimethods Approach to Bafety Parameter Display Valvation" AWS.H.W., BLACKMAN,H.B., GERTMAN,D.I. EQ&G, Inc. EQQ-M-11782 R31905 NRC - No Detailed Affiliation Given 7pp 15672 255

- B210120367 "Bource Terms of Radionuclides in Shallow Land Burtal Sites " PIETRZAK.R F , DAYAL.R Brookhaven National Laboratory BNL-NUREG-31834 82/10/05 NRC - No Detailed Affiliation Given 9pp 15690 213
- 8210120368 "Approximate Tolerance Intervals, Based on Max Likelihood Estimates"

  ATMODD.C L EGAG, Inc. EGG-M-11692 82/10/05 NRC No Detailed Affiliation Given 2200 15690 191
- 9210120390 "Stress Corrosian Cracking of PMR Steam Generator Tubing," monthly highlights for Aug 1982 VAN ROUYEN.D Broothaven National Laboratory FIN A-3208 82/09/17 TAGODA:A Office of Nuclear Regulatory Research. Director 5pp 15691 103
- 8210120397 "Safety Parameter Display Sys Progress Statement "
  MEYERLO R EQ&O, Inc HARMON D L Combustion Engineering, Inc
  LONOLA B Electric Power Research Institute EQQ-M-04382
  B2210709 NRC No Detailed Affiliation Given 13pp 15691 124
- 8210120400 "LWR Debris from Severe In-Pile Transient Tests " HODBINS.R R . CDOK.B A . MASON.R E EO&G. Inc 82/10/05 NRC -No Detailed Application Given 6pp 1549: 137
- 82(0120428 "Investigation of Accident Induced Flow & Matl Transport in Nuclear Facilities," progress rept for Aug 1982 MARTIN,R A , OREGORY,M S Los Alamos Scientific Laboratory FIN A-7029 Q-6-507 (R673) 82/09/28 BERNSTEIN,S Transportation & Materials Risk Granch App 15671 161
- S210120430 "Polynomial Regression for Tektronix 4052 Computer" BHATIA.P E0269 Inc FIN A-6043 E90-LGF1-5937 82/09/30 LANDRY.R P Experimental Programs Granch 92p 155/1 067
- 8210120453 "Rept of Foreign Travel of AP Malinauskas to England. Austria & Cermany." foreign trip rept MALINAUSKAS.A Oak Ridge National Laboratory FIN B-0127 ORNL/FIR-1365 82/09/07 MINDOUE.R B Office of Nuclear Regulatory Research. Director 2pp 15671 187
- 8210120455 "Btress Corrosion Cracking Galvanic Corrosion & Selectave Leaching Test Requirements for TiCode-12 High Level Waste Containers," draft rept BISKIND, B Brookhaven National Laboratory FIN A-3167 BNL-NUREO-31755 82/08/31 Office of Nuclear Material Safety & Bafeguards, Director 43pp 15671 210
- 8210120459 "Crevice Corrosion Data Requirements for TiCode-12 High Lavel Maste Containers," draft rept LEE,B B Brookhaven National Laboratory FIN A-3164 BNL-NUREO-31775 82/08/31 Office of Nuclear Material Safety & Safeguards, Director 26pp 15671 253
- 82(0)20460 "Mechanical Failure Mode Data Requirements for TiCode-12 High Level Maste Container Sys." draft rept SOD.P. BREWSTER, C. SCHWEITZER, D. O. Brookhaven National Laboratory FIN A-3164 BML-MUREO-31774 82/08/31 Dffice of Nuclear Material Safety & Safeguards.Director 1799 15671 279
- 8210120400 One-Corresponding to the State of the State of the State of the State of the State of the State of the State of the State of the State of State o
- 8210120630 "HTOR Bafety Program," monthly highlights for Aug 1982 SABTRE.C Brookhaven National Laboratory FIN A-3016 82/09/14 FOULDB.Q Diffics of Nuclear Requistory Research, Director 4pp 15672, 360.
- B210120649 "Thermal-Hydraulic LMFBR & LWR Bafety Experiments,"
  monthly highlights for Aug 1982
  OINEBERG, T., ORECNE, Q.A. Brookhaven National Laboratory FIN
  A-3024 82/08/31 CURTIS, R.T. Severe Accident Assessment Branch
- 8210120453 "Rept of Foreign Travel of TS Kress to Neeting of CSNI Group of Experts on Nuclear Aerosols in Parts/France re Aerosol Release & Transport Program," foreign trip rept. KRESS/T S Oak Ridge Mational Laboratory FIN 3-0121 ORNL/FTR-1371 82/09/15 BILBERG/M Division of Accident Evaluation 8pp 15672 279

- 8210120554 "TRAC-BD1 Turbine Model for Code Development & Improvements" informal technical rept (LES.M M E866, Inc. FIN A-6052 EGG-CDD-6029 B2/09/30 ODAR:F Office of Nuclear Regulatory Research, Director 47pp 15672 287
- 8210120657 "Advanced Display Concepts in Nuclear Control Rooms " CLARK.M I , BANKS.W W . BLACKMAN.H S EG&G. Inc 82/10/05 Office of Nuclear Regulatory Research. Director 11pp 15672 335
- 8210150409 Speech entitled. "Swaling Criteria & Assessment of Semiscale Mod-3 Scaling for Small Break Loss-of-Coolant Translents." presented at NRC/ANS 820914-15 meeting on Basic Thermal Hydraulic Mechanisms in LWR Analysis in Bethesda, MD LARSON, T K , ANDERSON, J L , SHIMECK, D & EQ&G, Inc EGG-M-21082 82/09/15 47pp 15716 OOI
- 8210150412 Speech entitled, "Power Burst Facility Severe Fuel Damage Test Program," presented at 820928-1001 Intl Topical Meeting on Irradiation Technology MCCARDELL,R K , MACDONALD,R & EG&G. Inc EGG-M-06682 82/10/01 19pp 15716 049
- 82:0150415 Speech entitled, "Monitoring PNA Reactor Vessel Liquid Level W/SPND During LOCAs," presented at ANG 820722-24 meeting on Advances in Reactor Physics & Core Thermal Hydraulica ADANS, J P EGGO, Inc. EGG-N-14082 82/09/24 15pg 15716 068
- B210150428 "Natural Circulation in Experimental Facility Scaled from PWR" LOOMIS G C EG&G, Inc SDDA, K Japan Atomic Energy Research Inst B2/10/12 NRC No Detailed Affiliation Given App 15714 OBA
- 8210150611 "Dest Estimate Prediction for LOFT Experiment Series L6-8C," interim rept CONDIE.K 0 EG&G. Inc FIN A-6048 EGG-LOFT-5982 82/08/31 MCPHERSON.G D Integral Systems Section 48pp 15717 017
- 8210150625 "LOFT Experiment Operating Spec.LOFT Anticipated Transient Series L6 Nuclear Experiment L6-6," interim rept Document Revision Requests L-4953 & L-4954 enc.]
  SILVERHAN. B EG&O. Inc FIN A-6048 EGG-LOFT-5733 82/07/21 MCPHERSON. O D Office of Nuclear Regulatory Research. Director 43pp 15717 118
- 8210150631 "Eram of Health Effects Associated W/Unit Radionuclide Releases to Surface Environ " HELTON: J Arizona State Univ \* Sandia Laboratories FIN A-1165 SAND82-1895 81/12/31 Division of Waste Management 85pp 15717 177
- 8210180497 "ORNL Programs for Ofc of Nuclear Regulatory Research," Jul 1982 monthly highlights LOTTS,A L , BAYLOR,V B , HOMAN,F J Dak Ridge National Laboratory 82/09/25 Office of Nuclear Regulatory Research, Director 96pp 15746 019
- 8210200102 "Fiber Optic Void Fraction Measurement Sys for Steam Generator in LOFT" SNYDERS C EQ&G. Inc FIN A-6043 EQG-LOFT-5999 82/09/30 LANDRY.R R Division of Accident Evaluation 20pp 15767 283
- 8210270421 "Accident Aerosol Characterization," quarterly rept for Jul-Bept 1982 ONCZARSKI,P C Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2287 62/10/13 BERNSTEIN,S Transportation & Materials Risk Branch lipp 15833 332
  - 'Preliminary Two-Phase Instrumentation Evaluation," status
    - 3 R EG&O, Inc. FIN A-6376 EGG-1D-6040 82/09/30 N Instrumentation & Control Branch 23pp 15859 013

or Aug 1982," interim rept 26-LOFT-4039 82/09/30 72pp 15832 299 8210290397 "Network Flow & Transport/Distributed Velocity Methods, Self-Teaching Curriculum" FINLEY,N C Sandia Laboratories LONGSINE,D E Divewood Corp CAMPBELL,JE INTERA Environmental Consultants,Inc FIN A-1158 SANDB1-0826 81/08/31 Division of Waste Management 245pp 15866 083

### REVIEW GRP NRC RESEARCH REVIEW GROUPS

- B2100;0286 Concurs that NUREG-0744; "Resolution of Reactor Vesse)
  Matis Toughness Safety Issue," need not be reviewed by
  CNCR
  STELLD, V Regional Operations & Generic Requirements 82/09/30
  DENION HR Office of Nuclear Reactor Regulation, Director 1p
  15573 181
- 8210040314 Summary of CROR Meeting IP on 820915 re cost/benefit study of design requirements for inadequate core cooling instrumentation & open technical issues from CROR Meeting if on 820324
  STELLO.V Regional Operations & Generic Requirements 82/09/22
  DIRCKS.W J Office of the Executive Director for Operations 6pp 155503 124
- 6210080109 Notification of 821008 CRGR Meeting 22 in Bethesda, MD to consider proposed bulletin re stress corrosion cracking as Category I requirement under provision of III-D of CROR charter Attendance should be limited to senior staff STELLO, V Regional Operations & Generic Requirements 82/10/07 EISENHUT, D G Division of Licensing JORDAN, E L Director's Office Office of Inspection and Enforcement CUNNINGHAM, R Office of Notice of Staff St
- 8210(20049 Forwards response to 820819 memo re standby shutdown racilities Postulated SBE toold cause failure of condenser circulating sys Util seismic criteria permits auxiliary syc water sys backup
  DENTON: HR Office of Nuclear Reactor Regulation. Director
  82/09/23 STELLO, V Regional Operations & Generic Requirements
  4pp 19689 207
- --8210120053 Requests briefing re standby shutdown facility design requirement changes, focusing on integration of NRC bacifit efforts Briefing requested at 820908 CRGR meeting STELLO.V Regional Operations & Generic Requirements 82/08/19 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pg 15889 218
- 82(0)20216 Forwards summary rept of CROR activities for 820828-1001 SCHWINK, W Regional Operations & Generic Requirements 82/10/09 Regional Operations & Generic Requirements 6pp 19692 144
- 9210120326 Forwards 820713 ltr documenting 820623 meeting between Licensing Review Group 1 & NRR BOYDA 8 KMC, Inc. 82/10/06 THOMAB,C O Standardization & Special Projects Branch Ip. 15652 333
- --8210120331 Forwards summary of 820623 meeting w/Licensing Review Group I Tech Spec Group & NRR in Bethesda.MD STS issues, proposed mods & justification encl BOVD, R S KMC, Inc. 82/07/13 TEDESCO, R L Assistant Director for Licensing 52pp 15652 334
- 821015013B Summary of CRGR Meeting 20 on 820921 re proposed resolution of reactor coolant pump trip issue & BWR pipe cracking issue STELLO. V Committee to Review Generic Requirements 82/10/05 DIRCKS.W J Office of the Executive Director for Operations App 15498-310
- 8210180002 Requests attendance at CRGR Meeting 23 on 821028 in Sethesds, MD to discuss cost/benefit info for alternatives for resolving pressurized thermal shock issue STELLO, V Committee to Review Generic Requirements 82/10/14 EISENHUT, D O Division of Licensing JORDAN, E L Division of Engineering & Quality Assurance CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director ip 15718 024
- B210170Q06 Notifies of CROR Meeting 20 on 820921 to discuss proposed resolution of reactor coglant pump trip issue & proposed bulletin to address BHR pipe cracking STELLD, V. Regional Operations & Gameric Requirements 82/09/20 EISENHUT.D G. Office of Nuclear Reactor Regulation, Director. JORDAN, E. L. Director's Office, Office of Inspection and Enforcement MAUSSHARDT.D B. Office of Nuclear Material Bafety & Bafeguards, Director

- EXILITIONS Designates R Purple as NRR co-chair of Safety/Safeguards fitted Committee Comprehensive re-svaluation of sifety/safeguards program should consider human factors elegants (Principle of Nuclear Reactor Regulation, Director Principle Office of Nuclear Material Safety & Safeguards, Director 4pp 19741 115
- -Rill90095 Responds to encil Commission 820816 memo & forwards draft Safety/Safeguards Review Committee charter, describing proposed committee responsibilities EFFETTR F Division of Safeguards 82/07/14 STELLO,V Pigsonal Operations & Generic Requirements DENTON:HR Office of N.clear Reactor Regulation, Director MINDGUC,R Office of N.clear Regulatory Research, Director 2pp 15761 119
- 11:FOLIS Responds to B20805 itr re unresolved issues from 820415 itr re inadequate requirements developed per TMI Item I D I suspension of responsibility for human factors within NRC & crept of operator integrity addressed (ENTON-HE Office of Nuclear Reactor Regulation, Director 82:09716 SHEEHY,E J Affiliation Unknown 29pp 15758 207
- 511.7063] Forwards long-range CROR agenda for Oct 1982-Sept 1983 Mods for signal items not reflecting current status should be for tensideration to B20616 CROR charter requested for tensideration re B20616 CROR charter requested STELLO.V. Committee to Review Generic Requirements B2/10/18 EDMITA, MINDOUS,R B NRC No Detailed Affiliation Given CMINN.H R Office of Nuclear Reactor Regulation, Director 12pp 17740 013
- EL-220131 Notifies of CROR meeting on 821103 in Bethesda. HD Requests the firstors limit attendance to senior staff needed to address agenda items STBLOV Regional Operations & Generic Requirements 82/10/20 STEARMIT.D 0 Division of Licensing 2pp 15787 114
- Ex20156 Notification of CRCR 821110 20th meeting in Bethesde, MD to instruct proposed revision to 10CFR20 on stds for protection applied radiation, proposed amend to 10CFR20 re radiation tradiation, proposed amend to 10CFR20 re radiation with the proposed amend to 10CFR20 re radiation from the control of
- E.M70199 Summary of CROR 22nd meeting on 821008 re proposed IE Littin. "Stress Corrosion Cracking in Thick-Wall Large Flates Stainless Steel Recirculation Sys Piping at BWR Flates to recolant pump criteria for PWRs FELD.V Regional Operations & Generic Requirements IEB-79-05C E210720 DIRCKS.W J Office of the Executive Director for Cylotion App 15822 957.
- E::::0034B Comments on summary of CROR Meeting 21 on 821006 to proposed princing criteria for vessel ref temp NDT Figure provides Inglithinal crack extension frequencies for mean surface ratur than computed mean plus 2 sigma SIMTO. F NRC No Detailed Affiliation Given 82/10/26 ELLO. Regional Operations & Generic Requirements 1p 1937-043
  - 51020051 Summary of CROR Meeting 21 on 821004 in Bethesda, MD List of attendes and grade. Operations & Generic Requirements 82/10/20 Mt(S,W ) Office of the Executive Director for Operations App 1889 044

### ET POSITION PAPERS BEFORE THE COMMISSION

Z52045 SECY-82-186
Milits Consisting of current status of makeup notals
midits Consisting to B&W plants Problem under evaluation
Didentis have established task group to oversee followup
stills Group will mest w/NRC in early May 1982
SECS-07 Office of the Executive Director for Operations
82755/07 Opp 15397,082.

W20012 SECY-82-267
Guiders postporing work on comprehensive fire protection
firs for nuclear power plants. Recommends Commission redirect
still to prepare comprehensive fire protection rule for new
solin power plants by June 1984.
BURGEN J Office of the Executive Director for Operations
BURGEN J Office of the Executive Director for Operations

8210040360 Responds to FDIA request for SECY-82-728 & SECY-82-72C re coordinated program for steam generators Documents available in PDR FELTONIJ M Division of Rules and Records 82/09/27 FORTINO.K C Lowenstein.Newman.Ress.Aselrad & Toll 1p 15597 291

--B204200090 SECY-82-072B
Responds to Chairman 820301 request for short-term actions reperformance of steam generators Comprehensive water chemistry criteria for steam generators should be implemented
DIRCKS,W J Office of the Elecutive Director for Operations 82/04/05 2pp 15597 892

--8205270507 SECY-82-0720
Advises Commission of results of 820428 meeting w/snowstry re-proposed coordinated program for steam generators Proposal in SECY-82-72A re-formal structural organization such as policy group & steering commistee rejected DIRCKS,W J Office of the Erecutive Director for Operations 82/05/17 3pp 19597 294

B210190144 Responds to FDIA request for SECY B2-232 re use of nonplant-specific simulators for initial replacement & requalification seems for licensed reactor operators & senior operators & senior operators FELTON. J M Division of Rules and Records B2/09/30 ARMSTRONG.K A Debayolse & Liberman 2pp 15760-178

--8206180042 SECV-82-232
Recommends requirements of simulator licensing exam be continued for power reactors w/plant-specific simulator Oral exam per 10CFR55 23 should be administered where facility has no plant-specific simulator DIRCKS-W J Office of the Executive Director for Operations 82/06/07 14pp 16002 236

8210220534 SECY-82-399
Informs Commission of status of "Nuclear Standardization Act of 1982" & proposed plan for 1983 legislative proposals TQURTELLOTTE, J. Regulatory Reform Task Force 82/09/30 28pp 15786 049

82102700B3 Add1 response to FOIA request for eight categories of LERs Forwards documents listed in App A App B documents withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 82/09/20 ARNOLD.J Miami Herald 4pp 15836 221

--8204300098 BECY-82-142
Requests approval of draft Rept to Congress on AD
(NUREO-0090) for Det-Dec 1981
DIRCKB.W J Office of the Executive Director for Operations
82/04/02 40pp 15836 225

8210270322 SECY-82-407
Advises of issues remaining from 820108 maeting reinstrumentation for detection of inadequate core cooling in PWRs Requests action in update recommendations for implementation of RURE9-0737. Item EI F 2 DIRCKB, W. Office of the Executive Director for Operations 82/10/07 12pp 19851 323

B210290393 Transcript of B20929 public meeting on SECY-B2-352 re GA in Weshington.DC.Pp 1-85 Marked-up SECY-B2-352 encl PALLADING.N. OILINSKY.V. AHEARNE.J Commissioners B2/09/29 146pp 15865 268

#### STATE PROD STATE PROGRAMS

82:00:100:14 Comments on state actions outlined in 82:04:17 & 09 ltrs re NRC recommendations on State of KY radiation control program Program adequate to protect public health & safety NRC should be kept informed of staff augmentation O'REILLY.J P Region 2. Office of Director 82:08/13 STUMBD.W & Kentucky. State of Rpp. 15565 160

821001004B Forwards rept of NRC 1982 review of State of TN radiation control program for agreement matis Program adequate to protect public health & safety Physicists should receive specific radiation safety control training.

HODDRUFF,R.L. Region 2. Office of Director. 82/09/13
FOWINKLE.E W Tennesses, State of 106pp 15565 010

821001010D Responds to 820409 itm re NRC review of State of KV radiation control program NRC comments re review of selected license files encil Licensing comments minor. Rept not yet completed.

SWOODRUFF,R L. Region 2. Office of Director. 82/OB/13 HUGHES. D. Kentucky. State of 12pp 15565. 243

- 8210010154 Forwards rept % evaluation of State of MS radiation control program for 800426-810911 Program adequate to protect public health & safety MDDDRUFF,R L Region 2, Office of Director 82/09/08 COSB.A B Mississippi. State of 72pp 15568 140
- 8210010358 Forwards "Rept & Evaluation of GA Radiation Control Program for Period Jul 15,1980 to Nov 25,1981." twelfth regulatory review program MOGDRUFF,R L Region 2, Office of Director 82/09/10 LEDBETIER,J G Georgia, State of 1p 15574 160
- --8210010363 "Rept & Evaluation of GA Radiation Control Program for Paried Jul 15.1980 to Nov 25.1981." twelfth regulatory review program + MRC - No Detailed Affiliation Given 82/09/10 129pp
- 8210120015 Partial response to FOIA request for documents re St Joseph Hosp in Albuquerque, NM & I-125 seed incident Forwards documents listed in App A FELTON, JM Division of Rules and Records 82/08/20 DAVIES, L S Richards, Brandt, Miller & Nelson 3pp 15691 173
- --8012180362 PNA-80-037 on 801201. State of NM informed NRC of oversiposures of patients receiving 1-125 seed therapy for treatment of prostate cancer Causedby computer dose conversion factor error State request hosp rept LUBEMAN, J O Office of State Programs. Director 80/12/02 ip 15591 176
- --8210120023 Requests assistance in independent technical review of encl rept from St Joseph Hosp re misadministration of I-125 seed implant Ltr delineating info required & article from Albuquerque Journal enct Wo encl WOLFF-IT A New Mexico. State of 81/02/03 NWSSHAUMER, D.A. Assistant Director for State Agreements Programs 1p 15691 192
- --B210120027 Forwards rept to St Joseph Hosp, Albuquerque, NM remissedministration of I-125 seed implant Event attributed to personnel error & lack of communication between computer plan developers & users Comments requested by 810227 NUSSBAUMER, D. A. Assistant Director for State Agreements Programs 82/02/23 HIQQINBOTHAM, L. Radiological Bafety Branch CUNNINGHAM, R. E. Advanced Fuel & Spent Fuel Licensing Branch Jp. 15591 193
- --8210120057 Forwards WR Hondee review of selected matls re misadministration of I-125 seeds at St Joseph Hosp, Albuquerque W/o encil NUSSBAUMER, D.A. Assistant Director for State Agreements Programs 81/03/25 HIGGENBUTHAM, L. Radiological Safety Branch MILLER, V.C. Licensing Management Granch ip 15691 289
- --8210120075 Forwards State of NM rept re investigation of incident involving overexposure of patients treated w/I-125 seeds AD rept will be included in next quarterly rept W/o encl NUSSBAUMER. D. A. Assistant Director for State Agreements Programs 81/11/24 CUNNINGHAM.R. E. Advanced Fuel & Spent Fuel Licensing Branch 1p 19692 040
- 82:0130152 Discusses insp of Western Industrial X-Ray at Hunters Point Naval Shippard on 820922 Two violations of BOT regulations, 49CFR172, re placarding of transportation vehicle observed State of CA consideration of enforcement action requested BOOK, H E Division of Radiological Safety & Safeguards Program 82/10/08 HUNEY, D California, State of 2p 15673 000
- 8210190530 Forwards results of insp of Model Ce-30 gauge mfg by Industrial Gauging & Control CAMPBELL,M A Region 1. Office of Director 82/10/12 CORCORAH,R G Maryland, State of 1p 15751 250
- --8210190533 Responds to 820805 request for insp of general licensee cility to obtain info re C-Frame type gauge mfg by dustrial Gauging & Control ENIAMBKI, D J Region 3. Office of Director 82/09/20
- 8210270393 Notification of contract execution, Mod 3 to "Environ Monitoring Program w/State of NC" Contractor State of NC HOLLETTS Research Contracts Branch FIN 8-1239 NRC-03-80-129 SECTION 19 CONTRACTOR OF THE PROGRAM OF THE PROGR

- --8210270395 Mod 3, changing name of NRC billing ofc & address for submission of invoices to "Environ Monitoring Program u/State of NC " # North Carolina, State of GUSTAVE,R P Research Contracts Branch FIN B-1239 NRC-05-80-283 82/10/12 ip 15833 361
- 82:0280386 Notification of contract execution, Mod 1 to "Establish Collaborative Program Between State & Commission to Provide Independent Measurements of Radioactivity in Effluents & Environ " Contractor CT Dept of Environ Protection SILVIS.R H Administrative Contracts Branch NRC-05-73-011 82/10/15 COBP.L I. ROSG.H Director's Office. Office of Inspection and Enforcement 10 15859 236
- --8210280397 Mod 1.deobligating funds, to "Establish Collaborative Program Between State & Commission to Provide Independent Measurements of Radioactivity in Effluents & Environ Around Selected Commissioned Licensed Activities " HEURNER.A T Connecticut, State of GUSTAVE, R P Research Contracts Branch NRC-05-73-011 82/10/15 1p 15859 237
- 8210290085 Responds to FDIA request for lists of names & addresses of all NRC licensess in ME.VT.MA.QH.CT & MV & appropriate ofcs in Agreement States of NH.RI.NY & MD Forwards requested lists
  FELTON, J M Daylsion of Rules and Records 82/10/15
  PARKINSON, T W Interstate Nuclear Services 1p 15863 311
- --B210290090 Lists of active licenses for States of MA.VT.ME.CT.OH & WV & Agreement States as of 820910 4 NRC - No Detailed Affiliation Given 82/10/07 240pp 18863 312
- TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE
- 8207070009 Forwards response to NRC B20923 questions on BAW-10143P, "Statistical Core Dasign Applied to Babcock 205 Core," including proprietary response to Guestion 20 & microfiche records of computer runs associated w/listed questions TAYLOR.J H Babcock & Wilcox CO 82/08/25 BEROGREN.J B Standardization & Special Projects Branch 23pp 14754 037
- B210010008 Responds to FOIA request for 19 categories of documents re nuclear reactor events & safety problems Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/06/28 UDELL, R A Critical Mass Energy Project 15pp 15727 005 24X Fiche 50-000,82/06/28.8210010008
- --8210050514 Topical rept evaluations of Revision 2 to WCAP-9558.
  "Mechanistic Fracture Evaluation of Reactor Coolant
  Pips "& WCAP-9787." Tensil & Toughness Properties of
  Primary Piping Weld Metal for Use in "
  \* NRC No Detailed Affiliation Given 82/06/28 26pp
  15731-005
- 8210010217 Forwards "Mark I Dwners Group Response to Humphrey Containment Concerns," per 820715 request SHERMODD, G Q General Electric Co MFN 138-82 82/09/24 EIBENHUT, D Q Division of Licensing 2pp 15567 351
- ~~8210010224 NSEO-88-0982

  "Mark I Owners Group Response to Humphrey Containment
  Concerns "
  BILLIO,P F , ROGERS,A E General Electric Co T23-00452
  82/09/30 28pg 19547 353
- 8210010351 Forwards proprietary NEDE-82232, "Shutdown of Reactor Power w/Boron Injection" Rept withheld GRAVES.C C Reactor Systems Branch 82/09/16 DIAMOND.D Brookhaven National Laboratory, 1p 15573,124
- 8210040229 Forwards XN-NF-507(P), "Exxon Nuclear Co Betpoint Methodology for C-E Reactors Statistical Setpoint Methodology, Suppl 1 " Rept withheld (ref 10CFR2 790) UMSLEY, G F Exion Nuclear Co, Inc. (subs of Exxon Corp.) CFO 077 82 82709/29 THOMAS, C O Standardization & Special Projects Branch 4pp 15595 338
- 8210040275 Forwards complaint & amended complaint re law suit filed by ML Williams per BF Williams death allegedly caused by radiation exposure during employment from 1958 to Oct 1980 HARWARD. E American Nuclear Insurers. 82/09/13 SALTZMAN. J Assistant Director for State & Licensee Relations 14pp 15587 135
- 8210040311 Forwards Revision 4 to SCP-D1-A, "RADCAL Gamma Thermometers as Local Power Measuring Devices for Use in Cores of PWRs."

  per NUREO-0390

  MARINO.U.P. Beandpower.Inc 82/09/29, BERNARD.H Standardization ;

  & Special Projects Branch ip 13584-198.

- --22:C040319 SCP-01-A R04

  Revision 4 to "RADCAL Gamma Thermometers as Local Fuel

  Power Heasuring Devices for Use in Cores of PHRs "

  Power Heasuring 12:02:28 291pp 15586 200
- FILOC40323 Forwards nonproprietary & proprietary versions of Suppl 3 to Figural Rapt CEN-185, "Heated Junction Thermocouple Phase III Test Rept " Proprietary version withheld Itel 10CFP2 790)

  REKINLY P C-E Operating Plants Cuners Group BASKIN,K P C-E Operating Plants Gr
- --:216040329 CEN-185-NP Anproprietary version of Suppl 3 to Topical Rept CEN-185, \*Masted Junction Thermocouple Phase III Test Rept " \* (ambustion Engineering, Inc. 82/09/30 77pp 15611 313
- EI:D040394 Forwards request for add1 info re NNI-81-6(P), "Waste Sileification & Parkaging Sys"
  THEMAS.C D Standardization & Special Projects Branch 82/09/08
  ESSEMBALM R Newport News Industrial Corp (subs of Newport News
- -:10350053 Requests meeting w/NRC to present status of BHR owners group research program on gipe cracking Most favorable date is E21015 Proposed agenda encl.
  ARMELLEF BHR Dukers Group HARWELL, E F Tennessee Valley Atherity 82/09/29 VOLLMER, R H Division of Engineering 3pp 1503.185
- El.::50104 Forwards revised organization chart for Div of Nuclear Power as described in TVA-TR75-1A. "GA Program Description for Issign. Const & Operation of TVA Nuclear Plants "Issign. Const & Operation of TVA Nuclear Plants "Issign. Universely Valley Authority 82/09/29 HAABB. W P. F. Slity Assurance Branch ip 15605 159
- i. US0152 Forwards Steam Generator owners group comments on draft steam generator generic requirements discussed during 820729 resting SMMIDI.A D Steam Generator Owners Group SCHMIDI.A D Florida SMMIDI.A D 82/09/30 EISENHUT.D 0 Division of Licensing logs 15603 244
- 1.0560255 Forwards proprietary & nonproprietary versions of AECC-2-NP ip Reduction Sys.Amend 1." in response to NRC 91110 & 820428 requests for addl info Proprietary version sittled iref 10CFR2 7901 (ARIBAR Aerojet Energy Conversion Co (subs of General Tire & 1.1hr Co | 8100 2871 RG RR 92/10/01 THOMAS, C Standardization is 5; still Projects Branch 1p 15615 109
- -- C210060257 Affidevit of SP Ferreiro requesting withholding of AECG-2-P, faduate Vol Reduction Sys, " from public disclosure tref IOCFR2. 790).
  FERREIRA B P Aerojet Energy Conversion Co (subs of General Yire Enther Co ) 82/09/29 App 15615 111
- -E210050259 AECC-2-NP AOI
  h.sproprietary version "Radwaste Vol Reduction Sys.Amend 1 "
  + Aerojet Energy Conversion Co (subs of General Tire & Rubber
  to 1 82/10/01 72pp 15415 115
- E:0860345 Forwards BAH-10153P, "Extended-Burnup Evaluation, "Rept will truled to support util customer OL applications for fuel lattle average burnups up to 45,000 mWd/mtU Rept withheld life IOCFR2 790).
  TAMOR, J. H. Babcock & Wilcox Co. 82/09/30. BERGOREN, J. 8 Stenfardication & Special Projects Branch. 8pp. 15615-100
- EIIO70074 Advises that proprietary WCAP-9863(P), "Rod Bank Worth Jesurksents Utiliting Bank Exchange," contains info of Intern to NRC Resolution of concern needed to proceed Winter NRC viewpoint withheld TOMASCO Standardization & Special Projects Branch 82/09/06 SAMEEP Mestinghouse Electric Corp. ip 15628-081
- :DODGIO Forwards request for addl info re XN-NF-82-25(P), "Generic Milesical Design Erxon 17x17 Fuel Assembly " Requests date for planned submitted of info Proprietary questions situated Property ( ) Standardization & Special Projects Brench B2/09/13, DSEEV, C.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) ip. 1851 073
- 20000038 MCAP-7870 Littris from "Neutron Shielding Pads " : Mistinghouse Electric Corp. 72/05/31 4pp 15669 242

- 8210080158 Forwards "Potential for Mater Hammer During Restart of RHR Pumps for BHR Nuclear Plants " HUANG.Y S Director's Office AEOD/E105 81/03/31 MICHELSON.C Director's Office ip 15663 255
- --8210080165 "Potential for Water Hammer During Restart of RHR Pumps for BHR Nuclear Plants " HUANO. Director's Office AEOD/E105 81/03/31 14pp 13663 256
- 8210080169 Forwards "Initial Consideration of Potential for Hater Hammer in Steam Condensing Mode of RHR Sys Operation for EHR Plants " HUAND, Y S Director's Office AEOD/E106 81/03/31 MICHELSON.C Director's Office Ip 15663 271
- --8210080172 "Initial Consideration of Potential for Hater Hammer in Steam Condensing Mode of RHR Sys Operation for BWR Nuclear Plants " HUANG.J Director's Office AEOD/E106 81/03/31 11pp 136483 272
- 82)0080229 Forwards proprietary response to EGMO questions/comments re seismic aspects of equipment qualification program & "Beismic Analysis of Safety Injection Motors for Byron Nuclear Stations 1 & 2 & Brasidwood Nuclear Stations 1 & 2 " RAHE,E P Westinghouse Electric Corp NB-EPR-2667 82/10/05 ROSZTOCZY,Z Equipment Qualification Branch 1p 15438-007
- 8210080262 Forwards slide presentation w/summary of 820917 meeting in Bathasda-MD re Intergranutar Stress Corrosion Cracking Progress Rept 8 Encl withheld (ref 100CR2 790) ORIDLEY,R L General Electric Co MFN-141-82 82/09/30 JBHNSTON, W V Assistant Director for Materials & Gualifications Engineering 6pp 15638 COI
- 8210080267 Recommends GE &/or affected BWR licensees be requested to submit & commit to schedule for replacement of all hold down beams w/lmproved design Potential for water hammer type loads on jet gump integrity should be evaluated MICHELSON,C Director's Office AEOD/EOO2 80/05/23 DENTON,H R DFfice of Nuclear Reactor Regulation, Director 4pp 15647 270
- 8210080274 Forwards "Review of Emergency Response Guidelines Re Pressurized Thermal Shock" KINOSLEY.O D Westinghouse Operating Plants Owners Group KINOSLEY.O D Alabama Power Co 00-72 82/06/22 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 15638 208
- --8210080297 "Review of Emergency Response Guidelines Re Pressurized Thermal Bhock"

  \* Waskinghouse Electric Corp 82/06/30 86pp 15638 209
- 8210150173 Forwards nonproprietary "Combined Seismic-LOCA Mechanical Evaluation for Exxon Nuclear 15:15 Reload Fuel for Westinghouse PMRs" OHBLEY, 0 F Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) QFO 082 82 82/10/08 THOMAS. CO. Standardization & Special Projects Branch ip 15706.364
- --B210150182 XN-NF-76-47(NP)(A)
  Nonproprietary "Combined Beismic-LOCA Mechanical Evaluation for Exxon Nuclear 15x15 Reload Fuel for Westinghouse PWRs "
  # Exxon Nuclear Co . Inc (subs of Exxon Corp ) 82/10/04
  176pp 15707 001
- 8210150416 Forwards proprietary responses to NRC 820908 request for aid1 info, Quastions 1-5 re NEDE-23785-1(P), "GESTR-LOCA & SAFER Models for Evaluation of LOCA" Responses withheld (ref 10CFR2 799)

  GUJRK-J F Oemeral Electric Co MFN-144-92 82/10/07 THOMAS, C O Standarfization & Special Projects Branch 19 19715 283
- 8210150445 Summarizes 820802 meeting w/MRC re planned dynamic testing of BMR 4/5 HPCI turbing Mode to original HPCI seismic qualification test extremely conservative Viewgraphs encl QUIRK.J F General Electric Co MFN-146-82 82/10/07 JOHNSTON.W.V Assistant Director for Materials & Qualifications Engineering 8pp. 15703 156
- 8210150461 Forwards slide presentation used at 820929 meeting w/NRC to discuss OE environ qualification program as defined in NEDE-24326-P Info withheld OURK, J.F. Ganeral Electric Co. MFN-145-B2 82/10/07 JOHNSTON, W.Y. Division of Engineering 2pp 15715-279
- B210150511 Forwards XN-NF-80-19(P), "Exxon Nuclear Methodology for BMRs Application of ENC Methodology to BMR Reloads," Vol 4 Rept withheld (ref 10CFR2 790) CHANDLER, J.C. Exxon Nuclear Co., Inc. (subs of Exxon Corp.) JCC.098.82 82/10/13 THOMAS.C.O. Standardization & Special Projects Branch Ip. 15715.162

- 6210150656 Notification of 821005 branch meeting in Bethesda.MD to discuss STS for rod position indication TAM,P S Operating Reactors Branch I 82/09/28 VARGA,S A Operating Reactors Branch I fp 15715-310
- B210150681 Discusses review of Licensing Topical Rept XN-NF--77-57
  "Exton Nuclear Power Distribution Control for PMR Phase II "
  Rept acceptable for referencing in Westinghouse-designed
  reactor reload license applications
  THOMAS.C. G. Standardization & Special Projects Branch B2/09/24
  OMSLEY, G. F. Exton Nuclear Co., Inc. (subs. of Exton Corp.) 2pp
- B210180023 Forwards request for additinfo needed to review Topical Rept CENPD-266(P). "ROCS & DIT Computer Code for Nuclear Design " THOMAS.C O Standardisation & Special Projects Oranch B2/09/15 SCHERER, A E Combustion Engineering. Inc. 4pp 15721 265
- B210180050 Forwards NEDE-24632, "Mark I Containment Program Cumulative Distribution Functions for Typical Dynamic Responses of Mark I Torus & Attached Piping Bys." per NRC B20909 request Rept withheld PFEFFERLEN.H C General Electric Co MFN-147-B2 B2/10/07 VASSALUO, B Operating Reactors Branch 2 9pp 15720 016
- B2(0190607 Submits add1 info per B2(014 discussion w/G Laines re review of Dresser safety valve performance observed in EPRI safety & relief valve test program Valves consistently achieved rated steam flow RAHELE P Westinghouse Electric Corp NS-EPR-2669 B2/10/15 EISENHUT, D G Division of Licensing Jpp 15739-354
- 8210190755 Forwards comments on NRC proposed steam generator requirements, distributed at 820727 meeting w/NRC & industry representatives in Dethesda.MD MILLS.L.M Tennessee Valley Authority 82/10/13 DENTON.H R Office of Nuclear Reactor Regulation. Director 4pp 18737 100
- B210190810 Forwards proprietary slide presentation entitled, "GE BUR Fuel Performance" from NRC/GE 820708 meeting in San Jose, CA Slides not properly labeled proprietary Slides withheld (ref 10CFR2 790) CHARNLEY, J S General Electric Co JSC-017-82 82/10/12 BERLINER, C H Core Performance Granch 1p 15736 317
- 0210200113 Notification of 821015 meeting w/BMR owners group & EPRI in BethesdarMD to discuss status of research on pipe cracking in BMRs & questions raised at 820927 meeting w/BWR licensees CLARK.D Operating Reactors Branch 2 82/10/13 VASSALLO.D B Operating Reactors Branch 2 3pp 15767 320
- 8210210329 Forwards proposed proprietary Revision 3 to Topical Rept EDR-1(P)-A. "Ederers Nuclear Safety-Related Extra-Safety & Monitoring (X-SAM) Cranes " Rept withheld (ref 10CFR2 790) CLARK,C W Ederer. Inc. 82/10/98 TH
- G210220152 Notifies of organization re restructuring within Water Reactor Div effective 820927 & forwards clarification of GA program plan GA plan in WCAP-8370 is accurate description of GA program controls GAUTET Westinghouse Electric Corp. NS-EPR-2666 82/10/14 Guality Assurance Branch 13pp 15778 093

- B210260072 Notification of B20930 meeting w/8&W in Bethesda, MD to discuss status of work re generic accident source term considerations
  HOUSTON.R W Assistant Director for Radiation Protection 82/09/21
  BENTON.H R , CASE, E , MINOQUE, R , NRC No Detailed Affiliation Given ip 15808-359
- 8210260305 Requests review of Instrumentation & Control Sys Branch proposed requirement for addirector trip breaker circuit tests in near-term Westinghouse plants TVA recommended procedures represent potential threat to safety RAME, EP Westinghouse Electric Corp NS-EPR-2660 82/IO/18 SPEIS, TP Division of Systems Integration (post 811005) 2pp 15805 231
- --8206300370 Ack receipt of 820427 ltr providing position on testing of shunt trip circuits of reactor trip breakers in Westinghouse plants Instrumentation & Control Sys Branch does not concur w/vendor position Evaluation enc! ROSA,F Instrumentation & Control Systems Branch 82/06/18 RAHE,EP Westinghouse Electric Corp 6pp 15805 233
- 8210260340 Forwards proprietary & nonproprietary responses to Revision i to Reg Guide 1 92, "Combining Model Responses & Spatial Components in Seismic Response Analysis" to assist in fuel assembly analysis Response withheld (ref 10CFR2 790) RAHELE P Westinghouse Electric Corp NS-EPR-2659 82/09/17 DERLINGER.C. MEYER.R O Core Performance Branch 2pp 15803 045
- --8210260351 Bubmits application for withholding proprietary response to Revision 1 to Reg Ouide 1 92, "Combining Modal Responses & Spatial Components in Seismic Response Analysis " Affidavit & nonproprietary response enci
- 9210270092 Forwards proprietary "Exxon Nuclear Power Distribution Control for PWRs - Phase II." Suppl 2 & Addendem 1 to Suppl 2 Encl withheld (ref 100FRZ 790) OWSLEY, 0 F Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) GFO 097 82 82/10/21 THOMAS, CO. Standardization & Special Projects Branch 1p 15829 317
- 8210270164 Forwards nonproprietary & proprietary "Generic Mechanical Design for Exxon Nuclear Jet Pump BHR Reload Fuel: "per NRC 820826 request Proprietary rept withheld (ref 100FR2 790) CHANDLER.J C Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) JCC 094 82 82/09/29 THOMAS.C O Standardization & Special Projects Branch ip 15824 236
- --8210270169 XN-NF-81-21(NF)(A)
  Nonproprietary "Generic Mechanical Design for Exxon Nuclear
  Jat Pump BHR Reload Fuel "
  \* Exxon Nuclear Co. Inc (subs of Exxon Corp.) 82/09/22
  115pp 13824 238
- 9210270214 Forwards proprietary revision to "RODEX2 Fuel Rod Thermal—Mechanical Response Evaluation Model " Revision modifies RODEX2 code based on benchmarking of model to enlarge data base Rept withheld (ref 10CFR2, 790) CHSLEY, 0 F Exxon Nuclear Co. Inc. (subs. of Exxon Corp.) GFO 088 82 82/10/22 THOMAS, C.O. Standardization & Special Projects Branch. ip. 15822-347
- 8210280433 Forwards review of Westinghouse safety parameter display sys, in response to 820504 request Verification & validation program generally acceptable Outstanding concerns must be resolved before review completion CRUTCHFIELD,D Operating Reactors Branch 5 LS05-82-10-005 82/10/05 RAHE, E P Westinghouse Electric Corp 7pp 15860 056
- 8210290118 Forwards for info draft rept & apps on pressurized thermal shock Completed rept will form basis of Commission decision due 821030 W/o encl
  LAINAS C Assistant Director for Operating Reactors 82/09/28 ROCHING L Babcock & Wilcox Operating Plants Owners Group ROCHING L General Public Utilities GPU Service Corp 2pp 15866 398
- --B210290144 GA-A13010A A07 Amend 7 to GA program \* 9A Technologies, Inc /General Atomic Co. GA-LTR-11 B2/10/Q1 7ipp 15854 3ii.

- E210290288 Confirms 821020 telcon re new fatigue curve (Figure 2-11b) aided to NEDE-24011-P-A-4 Curve illustrates stress/cycle relationships used in fatigue evaluations & serves as basis for fatigue analysis of approved PBx8R fuel design HARRLEY.J S Ogneral Electric Co HFN-154-B2 B2/10/25 EERGGREN.J S NRC No Detailed Affiliation Given ip 15854 07/
  - 10270453 Forwards, for info.draft rept & apps on pressurized thermal shock Completed rept will form basis of Commission paper due
  - BICOS M/o onel
    -AINAS.G C Assistant Director for Operating Reactors 82/09/
    BASKIN.K C-E Operating Plants Owners Group 2pp 15863 185
  - 10270458 Forwards, for info, draft rept & apps on pressurized thermal shock Completed rept will form basis of Commission paper ius 621030 W/a encl
  - for Beyond Wid and 1 A]NAS.G C Assistant Director for Operating Reactors 82/09/28 HNSEEY,D Westinghouse Operating Plants Owners Group KINGSEEY Alabama Power Co 2pp 15863-183

# STE HOT NUCLEAR WASTE MANAGEMENT

- iol20131 Summary of 820903 meeting w/DDE.BNL & DuPont re environ issetiated & draft finding of no significant impact re use if borosilicate glass in defense waste processing facility latendence list encl.

  ELL.H J High Level Waste Licensing Management Branch 82/09/IHigh Level Waste Licensing Management Branch 3pp 15692 154
- 3pp 15492 154
- |0120138 Requests copies of papers presented at Bozeman Montain Neting of Rocky Mountain Section of Geological Boc of Lagrica, dealing w/geologic aspects of Basalt Waste Isolation
- MICHTR J High Level Waste Technical Development Branch 12/08/31 SQUIRES, D Energy, Dept of 1p 15692 169
- .0120147 Responds to B20830 ltr expressing concern re final version of 16CFR61, "Licensing Requirements for Land Disposal of Redwiste" De minimus issue for managing low level radwaste all be addressed within next few yrs GRINJB Division of Waste Management 82/09/21 HARRIS, S.J. Hall Physics Society 2pp 18672 177
- |0120173 Forwards minutes of B20729 briefing on iOCFR40 W/o encl |ELL,N J High Level Waste Technical Development Branch | B2/08/31 |ORL|N6ER.L H Louisiana. Blate of LIEBOLD.W C Affiliation | Intown | CAMIL.P C Environmental Protection Agency | App Introven |5692 205
- .0120173 Notification of 820709 meeting w/Basalt Waste Isolation reject coordinators in Silver Spring MD for site issue malysis treatment & systematic review & comparison of site
- issues

  R[GHT.R J High Level Waste Technical Development Branch

  2/2/09/31 BELL.M J. BOYLE.R., COCK.R High Level Waste Lirensing

  tangement Branch 2pp 15692 209
- 10120322 Forwards draft DDE/NWTS-33(3), "NWTS Program Criteria for 10120322 Forwards grart DUE/RWIE-33(3). "RMIB Program Criteria for sinsi Geologic Disposal of Nuclear Wastes Repository Performance & Development Criteria." Comments on repository lesign features requested by 821006 W/o enci 30mEnR High Level Waste Licensing Management Branch. 82/09/21 RECUES. J.T. High Level Waste Technical Development Branch. 1p
- | O|20324 Forwards draft DOE/NWTS-S3(3), "NWTS Program Criteria for their declogic Disposal of Nuclear Wastes Repository \*\*rforsance & Development Criteria " Comments on GA stds \*\*rqusted by 82(005 W/o snc) | OYLERR High Level Waste Licensing Management Branch 100K.AF High Level Waste Licensing Management Branch 10 15670 351. 62/09/21
- 101203R5 Forwards "Corrosion of Cast Iron & Low Carbon Steel Nuclear Mete Containers in Basalt Repository " Draft rept will be RIGHT R J High Level Waste Technical Development of ip REO High Level Waste Technical Development Branch
- 1210120327 "Corrosion of Cast Iron & Low Carbon Steel Nuclear Waste Containers in Basalt Repository," draft rept MALLEE NRC No Detailed Affiliation Given 82/08/26 44pp 15590 354
- 012035; Forwards second "Draft Technical Position on Radionuclide per & Bolobility Determinations "
  USIUS-P 8 High Level Waste Technical Development Branch
  2709/30 MILLER, H J High Level Waste Technical Development ranch ip 15690 301

- --8210120353 "Draft Technical Position on Radionuclide Spec & Solubility Piorecologia (Prary Established Processing State of Processing Sta
- 8210120355 Trip rept of 820507 internal desimetry symposium in Marriaburg.PA
  Harriaburg.PA
  FEHRINGER.D J High Level Waste Licensing Management Branch
  82/09/10 KNAPP.M R High Level Waste Licensing Management Branch
- 8210120356 Trip rept of 820830-0903 visit to Denver,CO & Los Alamos,NM to attend fourth annual DDE low level waste mgt program participants info meeting HAMKINS,EF, STARMER,RJ Low Level Waste Licensing Branch 82/09/21 SCARANO,RA Low Level Waste Licensing Branch 4pg 15490 347
- 8210120358 Proposes lead responsibilities for Basalt Waste Isolation Project WRICHT:R J High Level Waste Technical Development Branch High Level Waste Technical Development Branch 15690 298
- 8210120359 Requests list of documents referenced in SCR for Basult Maste Isolation Project
  WRIGHT:R J High Level Waste Technical Development Branch
  B2/09/21 BDYLE:R: COOK.R: OREEVES.J Division of Waste
  Management 3pp 15690 275
- 9910120375 Requests review & comments on encl DDE/NWTS-33(3), "NWTS Program Criteria for Mined Geologic Disposal of Nuclear Wastes Repository Performance & Development Criteria " W/o enci BELL.N J High Level Waste Licensing Management Branch BE ARGENAULT.F Division of Health. Siting & Environment 1p 82/09/21
- 8210120377 Forwards preliminary geological hydrological & geotechnical evaluation of Coke Oven Site Montrose County. CO Meeting planned for early Sept to discuss comments JACOBI.W Colorado State of 82/08/20 SMITHLED Low Level Waste Licensing Branch ip 15699/330
- --821012038& Preliminary geological, hydrological & geotechnical evaluation of Coke Site. Montrose County, Co ROBABCO, P. V., HEATH, R. A. Fox Consulting Engineers & Geologists 82/07/31 147pp 15859 331
- 821012044B Forwards draft DOB/NWTS-33(3), "NWTS Program Criteria for AIDLEMAND FORWARDS GRAFT DUBLEMING—JULIA, FRAME PROGRAM CRITE Mined Geologic Disposal of Nuclean Wastes Repository Performance & Development Criteria "Radiological safety & dosimetry comments requested by S2:006 M/o encl BOYLE.R R High Level Waste Licensing Management Branch KNAPP.M R High Level Waste Licensing Management Branch 82/09/21 1 n
- 8210120854 Comments on Jul 1982 monthly rept for Edgemont cleanup action program No changes to costs or final delivery of contracted products authorized FLORY, G.A. Uranium Recovery Licensing Branch FIN 8~2217 82/09/14 HOGMAN, N.A. Battelle Hemorial Institute, Pacific Northwest Laboratory 2pp 15684-216
- 8210120574 Forwards comments on draft remedial action concept paper for Office of the Company 82/09/20. 15695 229
- 8210120648 Trip rept of 820830-31 visit to Edgement.8D to evaluate progress on remedial action program
  FLORY.C A. Uranium Recovery Licensing Branch FIN 8-2217
  82/09/15 BMITH.R D. Uranium Recovery Licensing Branch Rep 13694-235
- 8210220037 Forwards NRC temments on final draft remedial action concept paper for Durango.CO inactive U mil) tailings site Comments can be easily resolved.

  SCARAMOR A Upratium Recovery Licensing Branch 82/09/09
  CAMPBELLER H Energy, Dept of 3pp 15786-278
- 8210250025 UHTRA-DOE/ALD-34 DRF Draft "Remedial Action Concept Paper for U Hill Tailings Site at Shiprock.NM "

  \* Navajo Nation CAMPBELL.R.H Energy, Dapt of 20482
  82/08/31 27pp 15778 314
- 8210240084 Forwards "Certificate of Mater Analysis, May 1982" CAIN: J Cotter Corp 20591 82/05/09 HAZLE: A J Colora of. 2pp. 15814 153.

1

--8210260071 "Certificate of Water Analysis.May 1982 " Five oversize listings encl Aperture cards available in PDR MCDDMELL, J., CURREY.M., HERRERA.D. Cotter Corp. 05-82 82/07/12 Spp. 15844 155

## APORTLIC EXPORT AND IMPORT LICENSES

- 8210040382 Ltr of assurance re export of 330 32 kg V-235, contained in 11,590 kg V, to Japan SHIRAKANA.T Japan 82/09/02 GRIFFIN.J A Energy, Dept of 1p 15597 211
- 8210040395 Ltr of assurance re export of 26B kg U-235.contained in 10,936 kg U, to Japan SHIRAKANA.T Japan 82/09/02 GRIFFIN.J A Energy, Dept of 1p 15997 212
- 8210040387 Ltr of assurance re export of 340 28 kg U-235, contained in 10.470 kg U. to Japan SHIRAKAWA.T Japan S2/09/02 GRIFFIN.J A Energy, Bept of ip
- 8210040403 Erecutive Branch position re Mitsubishi Intl Corp application to export 575 kg U-235 contained in 29,698 kg U, to Japan Ltr of assurance enci License should be granted DEVINELJ B. State, Dept of, Mureau of Oceans & Internati Environ & Scientific Affairs 82/09/10 SHEAJ R Office of International Programs, Director 2pp 15597 230
- 8201060245 Requests approval of alternate routes for planned irradiated fuel shipments from Chalk River Nuclear Labs to DDE Savannah River facility Date of arrival deleted DANESC.F L Nuclear Assurance Corp 19955 81/11/13 Division of Safeguards 3pp 15626 201
- ~-8210050467 Advises of plans for series of spent fuel shipments from Chalk River to DOE Savannah River Plant DANESE,F L. Nuclear Assurance Corp FLD/02/B4/ETS 82/07/02 GDDY,A Region L. Office of Director 1p 13626 232
- --821005047t Corrects 820702 prenotification of planned series of irradiated reactor fuel shipments from Chalk River to Savannah River Plant Port of entry is Derby Line, VI DANESE, F L Nuclear Assurance Corp FLD/82/86/ETS 82/07/07 GODY, A Region 1, Office of Director 1p 15626 233
- S210060007 Amend 5 to GE export license changing licensee & consignee addresses & adding 3 addit consignees PETERSON M R Assistant Director for Export/Import & International Safeguards UBM-073-82 82/08/31 jp 15636 267
- 8210060471 Ltr of assurance re-application to export 319 20 kg U-235, contained in 11.200 kg U-to Japan SHIRAKAMA.T Japan 82/09/02 GRIFFIN.J A Energy, Dept of ip 15636 219
- 8210070411 Add) response to FOIA request for documents re IAEA nuclear math safeguards program Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/09/10 OREENBERO.E V Tuttle & Taylor 3pp 19847
- ~-8210070486 Notifies that no special physical protection or intlessed safeguards concerns identified re Amend ( to application to export low enriched U to Malaysia SHERR,T S Material Transfer Safeguards Licensing Branch 82/06/28 ZIMMERMAN.J V Assistant Director for Export/Import & tonal Safequards ip 15647-267

urity concerns exist

w enriched U

n. - -

- --8210070421 Notifies that no physical security concerns erist re eigert of low enriched U to Japan under export license application XSNM-1896 SHERR.T S Haterial Control & Accountability Development Dranch B1/12/17 DEVINE, J B Assistant Director for Export/Import & International Safeguards (p 19647 007
- --8210070436 Notifies that no physical protection concerns erist re applications to export low enriched U to Japan under Licenses XBNN-1923, 1928 & 1894 SHERR.TS Haterial Transfer Safeguards Licensing Branch 82/02/25 PETERSDN.H R Assistant Director for Export/Import & International Safeguards 1p 13647 016
- --B210070434 Notifies that no physical protection concerns guist re export of highly enriched U to Japan Update on status of negotiations requested SHERR.T S Haterial Transfer Safeguards Licensing Branch B2/02/09 D2VINE.J B Assistant Director for Export/Import & International Safeguards 1p 15647-015
- --8210070436 Notifies that no physical protection concerns silst reapplications to export low enriched U to Japan under Licenses XSMH-1923,1925,1928 & 1896
  SHERR.T S Material Transfer Safeguards Licensing Dranch
  82/02/25 PETERSON M R Assistant Director for Export/Leport & International Safeguards 1p 15647 016
- ---8210070471 Forwards draft Commission paper re application for license to export highly enriched U to Franco Comments & license conditions specified in Encl 2 should be included in license BURNETT, R F Division of Safeguards 82/05/25 6HEA, J. R. Office of International Programs, Director 3pp 18647-224
- --8210070436 Notifies that no physical protection concerns exist reapplications to export low enriched U to Japan under Licenses XSM-1923, 1928 & 1896
  BHERR.T S Material Transfer Safeguards Licensing Branch
  82/02/25 PETERSON,M R Assistant Director for Export/Import & International Safeguards 1p 15647 016
- --B210070447 Notifies that no physical protection concerns exist rapplications to export low enriched U to Japan Info requested re status of facility attachment to Fukushima I. Unit 4
  SHERR.TS Haterial Transfer Safeguards Licensing Branch 82/03/11 PETERBONN R Assistant Director for Export/Japuri & International Safeguards ip 15647 038
- ---9210070484 Notifies that no physical protection concerns found reapplication for license to export single reload of low enriched U to Japan
  SHERRI'S Material Transfer Safeguards Licensing Branch
  82/06/23 ZIMMERMAN-J V Assistant Director for Export/Import & International Safeguards ip 13647 263
- 82:0070433 License for Transnuclear, Inc to import 17,000 kg U.enriched to 1 04 U-235, as U hexefluoride, from France Zimmerman, J V Assistant Director for Export/Import & International Safeguards 82/09/24 ip 15637 336
- 8210070439 License for Exxon Nuclear Co.Inc to import 93,020 kg U.
  enriched to 4 3X U-235.contained in fuel rods or assemblies.
  from Taiwan
  IMMERMAN.J V Assistant Director for Export/Import & International
  Safeguards 82/09/26 ip 15637 344
- 8210070443 License for Phibro-Balamon, Inc to import 500,000 tg U, including normal U & U enriched to 5 0% U-235, in any form except U contained in irradiation fuels, from any country ZIMMERMAN, U V Assistant Director for Export/Import & International Safeguards 82/09/26 1p 15637 347
- 8210070452 Application for license to import 21,702 kg U.containing 418 49 kg U-235 & 21,346 kg U.containing 544 232 kg U-235. from West Germany HANNETI.8 A Transnuclear, Inc TNF 418. 82/09/28 MOORE, N Office of International Programs, Director 2pp 15637 356
- 82:10080003 Forwards application for license to export 500,000 Ci tritium gas to United Kingdom SHANI A Ediow International Co. 82/09/10 HEMBY.E Assistant Director for Export/Import & International Bafeguards 1p 19568 353.
- --B2100B0005 Application for license to export 500,000 Ci tritium gau to United Kingdom SHAMA A Ediow International Co BRD-1(82) 82/09/10 |p 15668 354

- E210090033 Forwards application for license to export 400 kg cassiterite, enriched to 0 4% to United Kingdom vas RIPER 0 0 AMAX. Inc B2/09/09 HEMBY, E NRC No Detailed Affiliation Given ip 15669 001
  - -8210080035 Application for license to export 400 kg cassiterite, +nriched to 0 4%, to United Kingdom DISTLER.W F AMAX. Inc SN-EXP 82/09/10 1p 15669 002
- 210080037 Forwards application for license to export 86 861 m(.)
  Cf-252 as cermet wire to France
  HAWEITLE A Transnuclear, Inc. 82/09/08 MODRE,N Office of
  International Programs, Director 1p 15669 003
- -8210080040 Application for license to export 86 861 mC: Cf-252 as termst wire to France
  HANETT, B A Transnuclear, (no (TNP 414) 82/09/08 ip
- --B210080042 Advises that CEA will fabricate Cf-252 & send entire source to Institut Gustave Roussy de Villejuif, in response to questions on 820908 application for license to export 86 861 mCi Cf-252 as cermet wire to France MANETIS A Transmuclear. Inc. 82/09/15 HEMBY. E Director's Office Office of Inspection and Enforcement 2pp 19649 005
- 921008005 Corrected license for Edlow Intl Co to import 30,000 kg U.smriched to 3 5% U-235. from France ZINSERNAN.J V Assistant Director for Export/Import & International Safeguards 82/09/15 ip 15663 330
- B210080071 Application for license to import 5,000,000 kg U.containing 250,000 kg U-235 SWMA Edlow International Co 82/09/17 Assistant Director for Esport/Import & International Badeguards ip 15669 363
- 0210000108 Application for license to import 21,000 kg U.containing 210 by U-235.from the Netherlands HANRETT.B A Transnuclear, Inc 82/09/20 MODRRE,N Office of International Programs, Director 2pp 15649-360
- 8210080113 Application to amend export license, submitting addl info ru Intersediate consignees WIEDD, B D General Electric Co DDW-083-82 82/09/07 WRIGHT, B L NRC - No Detailed Affiliation Olven 1p 15669 362
- 8210080il9 Executive Branch position re Carpanter Technology Corpapilication to export Zircalog tubing to Norway License should be granted DEVING. JB State, Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs 82/09/17 SHEA. JR Office of International Programs, Director 2pp 13663 283
- 8210090126 Erecutive Branch position re KMS Fusion, Inc application to riport 300 Ci tritium in hollow glass pellets to United Xingdon License should be granted DEVINE, J.B. State, Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs, 82/09/10, SHEA, J.R. Office of International Programs, Director ip 15663 318
- 8210080130 Application for license to import 27,280 kg U.containing 872 % ig U-235, from West Germany HAMMETTA A Transnuclear, Inc 82/09/13 MODRE, N Office of International Programs. Director 3pp 18663,243
- 8210080133 Application for license to import 27,000 kg U.containing 324 kg U-235, from the Netherlands HAWRETT, B A Transnuciear, Inc 82/07/20, HOORE, N Office of International Programs, Director 2pp. 15663 246
- 8210360135 Application to amend export license submitting addl info re interestiate consignees NILSON, B. O. General Electric Co. BDW-083-82 B2/09/07 MRIGHT, B.L. MRC - No Detailed Affiliation Given. Ip. 15663:248
- 8210080138 License for Mitsui & Co (USA), Inc to export 33,000 lb licealog-4 tube shells to Japan IMMERMAN, J V Assistant Director for Export/Import & International Staguerds 136261, 82/07/20, lp. 15663.249.
- 8210080143 License for Mestinghouse to export 15 kg depleted U oxide: in fire of sintered pellets, to Canada IMMERNAN, J V. Assistant Director for Export/Import & International Safeguards ILB-174 82/09/22 ip 15663.250

- 8210080149 License for Westinghouse to export 1.808 microgram Cf-252, contained in eight cermet sealed sources & 480 mg Np-237, contained in 24 radiation surveillance capsules, to South Korea
  ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards ILS-187 82/09/22 2pp 15463 251
- 8210080153 License for Wastinghouse to export three ionization chambers & three gamma chambers to West Germany ZIMMERHAN.J V Assistant Director for Export/Import & International Safeguards ZE 10478 82/09/22 ip 15663 253
- 8210080157 License for Exxon Nuclear Co.Inc to export fuel rod hardware & cage assemblies to France ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 82/09/22 ip 15663 254
- 8210080162 Amend I to Transnuclear, Inc export license, increasing quantity of U-235 from 91 434 kg.contained in 98 kg U, to 94 513 kg.contained in 101 3 kg U
  74 513 kg.contained in 101 3 kg U
  71MMERMAN,J V Assistant Director for Export/Import & International Bafeguards 81-269/01 82/09/21 1p 15663 270
- 8210080319 Forwards application for license to esport four Zirca)oy-4 alloy fuel channels to Republic of China WDZNIAK.D R Carpenter Technology Corp 2-909-028 B2/09/09 HEMBY.E Assistant Director for Export/Import & International Safeguards ip 13643 358
- --8210080320 Application for license to export four Zircaloy-4 alloy fuel channels to Republic of China \* Carpenter Technology Corp 82/09/09 2pp 15663 359
- 8210080321 Forwards application to export 15 kg depleted U oxide to Canada
  HERSCHIN H Westinghouse Electric Corp. ILS-194 82/09/15
  ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 1p. 15663-361
- --8210080323 Application for license to export 15 kg depleted U axade, in form of sintered pellets, to Canada
  HERSCH.M H Westinghouse Electric Corp 82/09/15 lp 15663 362
- B210080324 Application for license to export 12 guide thimble tubes to Japan \* C. Itoh & Co (America), Inc M-004 B2/09/16 Ip 15663 288
- B2100B0327 Forwards application for license to export 9.500 kg individual rare earth compounds or mixtures & concentrates to various countries BARNUM.E C Molycorp. Inc 82/09/16 HEMBY.E Assistant Director for Export/Import & International Safeguards 2pp 15663 289
- --B2100B0331 Application for license to export 9.500 kg individual rare warth compounds or mixtures & concentrates to various countries Elements consist primarily of certum landbonum, headynium & praseodynium, WARHOL-W N MOJycorp, Inc. B2/09/i6 1p 15663 29:
- 8210080334 License for Luigi Serra. Inc. to export 18,400 springs to Italy
  ZIMMERHAN. J V Assistant Director for Export/Import & International Bafeguards 828-536 82/09/22 ip 13563 329
- 8210080337 Application for license to export 4,050 ft zirconium Orade II seamless tubing to Canada TUPPER.K F. Cabot Corp 1-6730(01-28043 82/09/15 ip 15663;328
- 82:0080343 License for Edlaw Intl Co to export 0 01 micros 0 17 microgram Pu-239 to Philippines ZIMMERMAN.J V Assistant Director for Export/Import & Bafeguards PNPC-1 82/09/20 2pp 13663 321
- 8210080345 Advises of issuance of license to Wastinghouse kg depleted U to Canada w/o 15 day waiting period since matt to be shipped on 820924

  ZIMMEMAN, J V Assistant Director for Export/Import & Bafeguards 82/09/22 Assistant Director for Export International Bafeguards. 1p 15663 320
- 8210080349 Requests Executive Branch position re Intl Coapplication for license to export 500,000 Ci bulk tritium gas to United Kingdom ZIMMERMAN, J. V. Assistant Director for Export/Import & Bafeguards 82/09/22 STOIBER, C. R. State, Dept of, D. & Internati Environ & Scientific Affairs ip 15663

- 8210120117 License for KMS Fusion. Inc to export 300 C1 tritium, contained in microshell hollow glass pellets, to United / Assistant Director for Export/Import & International KMSF-882-RO 82/09/22 ip 15689 157 ZIMMERMAN, J V Safequards
- 8210120503 Application for Dicense to import 26 kg low enriched U
- docade pellets from Japan CROSBLE.K L IRT Corp 82/10/01 MODRE.N NRC No Detailed Affiliation Given 1p 85672 075
- 8210120511 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
  71MMERNAN, J V Assistant Director for Export/Import 5 International
  Safeguards 82/09/30 GRIFFIN.J A Energy, Dept of 1p
- 8210120519 License for Transnuclear. Inc to import 31,000 kg U.enricked to 1 10% U-235 as U hexafluoride. from France ZIMMERMAN. J V Assistant Director for Export/Import & International Safeguards 82/09/24 1p 15672 095
- 8210130049 License for Transnuctear, Inc to export 1 464 kg U-235, contained in 3 223 kg U & 1 264 kg U-235 contained in 6 329 kg U. to Japan ZIMMERMAN, S R Assa Assistant Director for Export/Import & International JK 405)82-097 82/09/28 2pp 15694 361 Safequards (NUK 405)82-097
- 9210130055 License for Pechiney Ugine Kuhlmann Development, Inc to export 6 547 kg U-225.contained in 7 O[B kg U. to Greece ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 7/2/82 92/09/24 2pp 15694 275
- 8210130059 License for Mitsu; & Co (USA), Inc to export 237 1& Tircalogy 2 barrier tube shells to Japan
  ZIMMERMAN.J V Assistant Director for Export/Import % International
  Safaguards 136249 82/09/26 2pp 15694 358
- 8210130062 License for Isotope Products Labs to export 0 0125 mg Cm=244 to Gatar ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards W/O 9898 82/09/24 1p 15694 357
- 8210130066 License for Carpenter Technology Corp to export 24 piecer of Zircaloy tubing to Norway
  ZIMMERMAN.J V Assistant Director for Eiport/Import & International
  Safeguards CARTECH-SPD 150 82/09/24 ip 15696 267
- 8210130070 Amend & to GE export license, extending expiration date to 880101.changing intermediate consigners & increasing quantity of matt for export to 3.055 kg U-235.contained in quantity of mati for export to 3,055 kg U-235.contained in 126.595 kg U. to Italy ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards BDW-074-82 92/09/24 ip 15696-263
- 8210130072 Application for license to export equivalent of 5 kg deuterium to Malaysia \* Sigma Chemical Co D-97 B2/09/23 ip 15696.252
  - oplication for license to export 2 mg Cf-252, contained in orce. Model GEN-CF123, doubly encapsulated, to

- 8210220517 Application for license to export 7 54 kg thorium, contained in 10 kg Thorium fluoride in granular form, to Lichtenstein (Switzerland) COLTON, E Cerac, Inc 82/09/24 Ip 15786 084
- 8210260083 License for Instrumentation Research Technology Corp to import 26 kg U. enriched to 4% U-235, as U oxide pellets, from Japan Japan ZIMMERMAN,J V Office of International Programs, Director 82/10/01 1p 15814 324
- 6210260523 Notifies that Westinghouse 821007 application to export riozable assemblies that westinghouse Baloov application to export cable assemblies to Belgium has been approved w/o 15-day waiting period Equipment roady for immediate shipment
  ZIMMERNAN.J V Assistant Director for Export/Import & International
  Safeguards B2/10/14 Assistant Director for Export/Import & International Safeguards 1p 15830 178
- 8210260541 Notifies that Westinghouse 821107 application to export one compensated conjustion chamber to Belgium has been approved w/o normal 15-day waiting period Equipment ready for immediate shipment Safeguards 82/10/14 Assistant Director for Export/Import & International Safeguards 82/10/14 Assistant Director for Export/Import & International Safeguards 1p 15830 355
- 8210260570 Application to amend export license extending expiration date to 851231 Oeneral Electric Co ODW-089-82 82/10/05 International Proorams, Director ip 15014 WILSON, B D HEMBY, E. O. Office of International Programs, Director 15814 357
- 8210260573 License for Sigma Chemical Co to export 5 0 kg deuterium oside to Malaysia ZIMMERMANJ V Assistant Director for Export/Import & International Safeguards D-97 82/10/13 1p 19814 359
- 9210260574 Amend 1 to GE export license, extending expiration date to 851931 ZIMMERNAN.J V Assistant Director for Export/Import & International Safeguards BDH-089~82 B2/10/14 ip 15814 360
- 8210260578 Amend 3 to GE Co. Inc export license, extending expiration date to 891231 & changing end use statement
  ZIMMERMAN.J V Assistant Director for Export/Import & International
  Safeguards KKL-8DW 81008 82/10/13 ip 15830 141
- 8210240580 Amend 1 to GE export license, extending expiration date to B41231 ZIMMERMAN,J V Assistant Director for Export/Import & International Bafeguards BD4-79201 82/10/13 ip 15830-142 Safequards
- 8210270001 Amend 1 to Sandvik Special Metals Corp export license. increasing quantity of matl from (2.800 to 20.000 lb & increasing value of export
  Indianal Standard St
- 8210270003 Amend 1 to GA Co export license, extending expiration date to 851101 ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards IEL-4015 82/10/13 1p 15836-079
- 8210270005 Amend 6 to Transnuclear Inc export license extending expiration date to 880301

  ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards RBU-33180-120/0 82/10/13 1p 15836 080
- 8210270007 Application for Amend 1 to export license increasing value of equipment to be shipped to Japan
  TSUKUDA.T Mitsui & Co (U S A ).Inc (Subs of Mitsui & Co .Ltd )
  82/10/12 WRIGHT.D L Office of International Programs. Director 15836,081
- 8210270011 Application for license to export 24,840 lb Zircalow tres to Germany AERNI, B L Teledyne Wah Chang Albany 2326(JFM) B2/10/OB 1p 15836 082
- 8210270014 Application for license to export compensated ionization chamber: Model WL23084: to Japan POCHAL: W.F. Westinghouse Elec-Westinghouse Electric Corp ZE 60252 82/10/04 15836 083
- 8210270017 Application for license to export compensated ionization chamber Model ML23774, to Belgium POCKALNF Westinghouse Electric Corp ZE20561 82/10/07 in Westinghouse Electric Corp ZE20561 82/10/07 15836 084

- 8210270021 Application for license to export 12 6 kg U as metal to Canada 5MAN, A Edlow International Co AECL-1(82) 82/10/13 ip 15836-085
- 821027007& Application for license to export 4,850 lb Zircaloy trex to Hett Germany AERNI,B L. Teledyne Wah Chang Albany 2420 (JFM) 82/10/14 lp 15836 299
- 8210270094 Application to amend export litense changing quantity to be exported to 50 g U-235 contained in 500 g U & 500 g Th-232 MARCHAL. J European Communities Commission of 82/09/27 GRIFFIN J A Energy, Dept of 1p 15836 218
- 8210270099 License for Separative Work Unit Corp to import 2,000,000 lb natural U in any form & 300,000 kg U.enriched to 5% U-235 in any form from any country ElfmentAhi J V Office of International Programs, Director 62/10/04 lp 15836 219
- 9210270103 Advises that proposed import of 26 kg U. enriched to 4% U-23. constitutes no undue risk to public health, safety or environ
- environ MORR.R N Office of International Programs, Director 82/10/04 Office of International Programs, Director ip 19836-220
- 9210270109 Advises that license to import 26 kg U dioxide pellets, enriched to 4%, from Japan issued w/o 15-day waiting period since math urgently needed for testing INMERHANLY V Assistant Director for Export/Import & International Safeguards 82/10/04 Assistant Director for Export/Import & International Safeguards 1 p 15832 340
- E210270114 Advises that proposed import of 27.280 kg Usenriched to 3.27 U-235 constitutes no undus risk to public health, safety or environ MORER PL Office of International Programs, Director 82/10/05
- MODRE: R N Office of International Programs, Director 92/10/05 Diffice of International Programs, Director 1p 15832 341
- 8210270122 Advises that II cense to Import 27,280 kg low enriched V in fara of V herafluoride from Wost Germany issued prior to elpiration of 30-day period stated in FR (IMMERHAN. J V Assistant Director for Export/Import & International Safequards 82/10/05 Assistant Director for Export/Import & International Safequards Ip 19832 347
- 8210270127 Advises that license to export 238 lb Zircaloy-2 barrier tube shells to Japan issued w/o 15-day waiting period since tubing ready for immediate shipment & urgently required by customer INPERMAN, J V Assistant Director for Export/Import & International Safeguards 82/09/26 Assistant Director for Export/Import & International Safeguards ip 15802 346
- \$210270147 Application for license to import 19.500 kg U.enriched to 9.8% U-235.from France HWMETT.B A Trensnuclear, Inc 92/09/30 MODRE.N Office of International Programs. Director 2pp 15834-342
- 8210270149 Forwards application for export license for minor nuclear signst Ltr of assurance required IMMERMAN, J V Assistant Director for Export/Import & International Safeguards 92/10/05 GRIFFIN. J A Energy, Dept of 1p 15834-344
- --8210270152 Application to amend import license, increasing amount of U from 10 to 15 kg
  OLSENIR W National Nuclear Corp. 82/09/29 WRIGHT, B L
  Assistant Director for Export/Import & International Safeguards
  19 15834-345.
- 8210270155 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl | INMERHAN, J V Assistant Director for Export/Import & International Safeguards 82/10/06 ORIFFIN, J A Energy, Dept. of ip 15935 077
- 8210270158 Ltr of assurance re export of SNM to Switzerland FISCH.C Switzerland 82/09/28 GRIFFIN.J A Energy. Dept of 3pp 15834.346
- 8210270163 Application to amend export license, increasing quantity to he jaported from 12.800 to 20.000 ib.
  WENIER.L. Bandvik Spacial Metals Corp. B2/10/04 HEMBY.E NRC No Detailed Affiliation Given ip 15834 349
- 82:027016B Requests examption from 30-day FR notice requirement for import bicense Hatl must be exported immediately HASETT.B A Transmuclear, Inc. TNF-415 82/09/23, MODRE, N Office of International Programs, Director. 1p 18834-350

- 8210270194 Application for license to export 5 kg deuterium mide liquid over 2-yr period to Malaysia 4 Sigma Chemical Co D-98 82/09/30 lp 15835 348
- 8210270201 Amend 3 to GA Co export license extending expiration date to 651001 & increasing quantity of mail authorized for export to 50 g U-235, contained in 500 g U & 500 g #h-232, to Hest Oermany ZIHMERMAN, J V Assistant Director for Export/Import & International Safeguards [EL-954 82/10/06 ip 15936 033
- 82:0270233 License for Transnuclear.Inc to export 86 861 mC: Cf-252.as cement wire to France ZIMMERHAN,J V Assistant Director for Export/Import & International Safeguards (TNP-414) 82/10/05 ip 15836 072
- 8210270238 License for Carpenter Technology Corp to export four Zircaloy-4 alloy fuel channels to Taswan ZiMMERMAN.J V Assistant Director for Export/Import & International Bafeguards CARTECH 2-909-0 82/10/05 tp 15836-075
- B210270243 Informs that Amend 5 to License X8NM-1686 may be issued Nu matt changed circumstances since issuance of License X8NM-1840 MODRE, R N Assistant Director for Export/Import & International Safeguards B2/10/06 Assistant Director for Export/Import & International Safeguards 1p 15836 076
- 8210270281 Application for license to export 10 kg thorium oxide powder to Italy COLTON.E Cerac, Inc. 82/10/06 HEMBY, E. NRC No Detailed Affiliation Given bp. 15836-304
- B210270282 Amend 1 to Mitsui Air Intl. Inc export license, increasing value of equipment for export to Japan ZiMMERNAN, J V Assistant Director for Export/Import & International Safeguards 82/10/14 lp 15836 305
- B210270283 Application to amend export license, extending expiration date to 841231
  WILSON, B D General Electric Co BDU-088-82 82/10/05 1p
  15838-306
- 8210270284 License for Westinghouse to export one compensated ionization chamber. Model WL23774, to Belgium IMMERHAN, J V Assistant Director for Export/Import & International Safeguards ZE-20561 82/10/14 ip 15836 307
- 9210270285 License for Westinghouse to export one triax cable assembly, Model ML-24058 & one coax cable assembly, Model WL-24060 to Belgium ZIMMERNAN, J. V. Assistant Director for Export/Import & International Safeguards ZE-20567 82/10/14 ip 15836-308
- 8210270286 License for Natl Nuclear Corp to export 2 0 milligrams CF-232, contained in one neutron source, to United Kingdom ZIMMERNAN, J V Assistant Director for Export/Import & International Befeguards BNFL-C-578 82/10/14 ip 15836 300
- 8210270287 License for CERAC, Inc. to export 7 54 kg thoroum, contained in 10 kg thoroum fluoride to Suitzerland ZIMMERRAN, J V. Assistant Director for Export/Import & International Safeguards TLX-6725 82/10/13 2pp 15836
- B210270290 Litense for Molycorp. Ir to Australia Austria, Belgium C Greece, Ireland, Italy, Japan, Lus Norway, Sweden, United Kingdom ZIMHERNAN, J V Assistant Di Safeguards 82/10/08 ip
- B210270313 Requests Executive ... application for license to export small amounts of thorium contained in rare earth products W/o encl
  ZIMMERHAN, J V Assistant Director for Export/Import & International Safeguards 82/10/13 STDIBER C R Scate, Dept of, Bureau of Oceans & Internati, Environ & Scientific Affairs 2pp 15836 339
- B210270391 Application for license to export 4.850 lb Zircaloy trex to West Oermany AERNI.B L Teledyne Hah Chang Albany. 2419 (TFM) B2/10/14 ip 15833 362
- B210270431 License for AMAX.Inc to export 190 kg natural U.contained in 35 metric tons tin concentrate & 180 kg natural thorium. to United Kingdom ZIMMERMAN.J V Assistant Director for Export/Import & International Bafeguards SN-EXP 82/10/05 tp 15833 250

- 8210270446 License for Cabot Corp to export 4.050 ft zirconzum Grade 11 seamless tubing of various outside diameters & lengths to Canada IIMMERMAN, J V Assistant Director for Export/Import & International 1-6930 82/10/05 1p 15833 280 Safequards
- 8210270448 Forwards application for license to export 11,279 kg U. enriched to 3 95% U-235, to Japan HATTORI-H Missui & Co. (U.S. A.), Inc. (Subs. of Missui & Co., £td.) Assistant Director for Export/Import & International Sareguards 1p 15832 361
- --8210270452 Application for license to export 11,279 kg U, enriched to 3 956 U-235 to Japan MONDEN.T Mitsou t Co (U S A ).Inc (Subs of Mitsou & Co (Ltd ) MBK-2F1-R2-(8) 82/09/27 lp (5832-362
- 8210280030 Application for license to export 0 0000125 mg Cm-244 JAMRISKA D Isotope Products Laboratories 4/0 9975 82/09/20 15863 003
- 8210280032 Application for license to export 355 Zircaloy-4 guide thinble tubes to Japan BANGERTER,D H Sandvik Special Metals Corp. SSM-2927 82/09/27 Ip. 15862 362
- 6210280035 License for GA Co to export (1 kg U-235, contained in 55 4 kg (1) to Bangladesh
  ZIM ERMAN. J V Assistant Director for Export/Import & International
  Safeguards IEL 1163 82/10/05 2pp 15863 001
- 8210280038 License for Tiansnuclear, Inc to import 27,280 kg U.enriched 22 U-235, from Hest Germany
  ZIMMERMAN, J V Assistant Director for Export/Import & International
  Sareguards 82/10/05 lp 15862 361
- 8210280040 License for C Itah & Ca,Ltd to export 12 guide thimble tubas to Japan Zimmerman, J V Assistant Director for Export/Import & International Sakeouards M-004 82/10/05 to 1982 360 Satequards M-004 82/10/05
- 6210280043 Application for license to export 2,490 Zircaloy-4 guide ELUCATION APPLICATION FOR ILCONSE to export 2.490 Zircalou-thinble tubes 605 Zircalou-4 instrument tubes & 720 double thimble tubes to Japan End use statement encl BANCERTER.D H Sandvik Special Metals Corp SSM-2893-290 82/09/27 Jpp 15862 35 SSM-2693-2900
- 8210280092 Application for license to export 2,002 mC; Cf-252 as cernet wire to France HANNETT,D A Transnuclear, Inc (TNP 421) 82/10/04 2pp 15962 355
- 8210280056 Forwards applications for licenses to export 15 038 kg U, enriched to 93 3% U-235 to Denmark & 2,002 mCs CF-252,as carmet wire Application for U-235 only encl HANNETT.B A Transnuclear, Inc. 82/10/04 MOORE,N Office of International Programs. Director ip 15862 (20
  - -- ---- Application for license to export 15 038 kg U.enriched to 5. to Denmark End use statement encl
    1 Transpuctear, Inc. NUK-420 82/10/04 300

- 8210280862 Application to amend export license extending expiration date 3 yrs weve J v:\* MDWRY.W R GA Technologies. Inc /General Atomic Co IEL-40:5 82/09/30 ZIMMERMAN.J Assistant Director for Export/Import & International Gafeguard: 1p 15862 233
- 8210280064 Application to amend export license increasing quantity to 15 g U-235, contained in 330 g U
  MARCHAL, J European Communities, Commission of
  GRIFFIN, J A Energy, Dept of 1p 15862 234
- 8210280088 Application to amend export license, increasing quantity to IO g U-235, contained in 220 g total U MARCHAL, J European Communities, Commission of GRIFFIN, J A Energy, Dept of Ip 15862 235
- 8210280403 Application for license to export 5 kg depterium diide to India

  + Sigma Chemical Co D-100 82/10/12 App 15859 319
- 8210280409 Amend 1 to Westinghouse export license, increasing quantity of metl authorized for export to 10 g U-235, contained 220 g U, to Belgium ZIMMERMAN, J V V Assistant Director for Export/Import & International ILS-150 82/10/05 ip 15859 331 Safequares
- 9210280414 Amend 5 to Transnuclear, Inc export license, increasing elucative in mmeno o to framenuclear inc export license increasing quantity of mat authorized for export to 6.738 665 up. 1986 to 9.00 up. 2005 contained in 181.131 620 kg U. to Switzerland ZIMMERNAPL V Assistant Director for Export/Import & International Safeguards RBU 331 80-120/ 82/10/12 ip 15859 357
- 8210280418 Amend 1 to Westinghouse export license, increasing quantity of mat1 authorized for export to 10 g U-235, contained in 220 g U, to France V Assistant Director for Export/Import & International ILS-150 82/10/06 ip 1989 360 ZIMMERMAN, J V
- 8210280422 Amend I to Westinghouse export license, increasing quantity of matl authorized for export to 15 g U-235 contained in 330 g U.to United Kingdom Zirhmernan, J V Assistant Director for Export/Import & International

Safequards

- Safaguards 1L6-150 82/10/06 ip 15860 013
- 8210280435 Ltr of assurance re application to export 1 464 kg U-235, contained in 3 223 kg U & 1 264 kg U-235, contained in Contained at Sees by Contained 15860 063
- 8210290367 Requests assistance in expediting issuance of export license Addl valves must be shipped to reactor site ARNDT, Q E Borg-Harner Corp CQA/82/494 82/10/13 HEMBY, E Assistant Director for Export/Import & International Safeguards 15865 247
- --8210270372 Application for license to export carbon & stainless steel valves, various globes, gates & supporting drawings & data to ARNDT.G E Borg-Warner Corp A-55127 82/10/13 1p 15865 248

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS, These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AU FNOR	ACCESSION NUMBER	SUBJECT CATEGORY
M MATOPTAN M MATOPTAN M MATOPTAN A CALOPTAN A SECTION	8210050192 8210210359 8210260400 8210130162* 8210050409*	50-289 0 50-289 0 50-289 0 50-296 6 F01A	ALLAN, J M ALLEN, J J ALLEN, R E ALLISON, D P AMAKO, V	821022041   8210290247 8210270060* 8210080206* 821008020	50-271 G REGGD 50-537 G FOLA 50-322 H	ATKINSON, S. A. ATWOOD, C. L. AULUCK, R. AULUCK, R. AUSTIN, O.	8210120463 6210120368 6210270072 8210270227 8210270227	RES RES 50-397 A 50-397 A 50-295 P
ABELSON, H ABELSON, H ABETAKKE, D. L ACHERHAN, H. C ADMERHAN, H. C	8210180311 8210290167 8210010361 8210150597 8210210254	50-3\$2 A 50-3\$2 A PR 40-8743 40-6659	AMES, K ANASTABIA, C M ANDERSON, J L ANDERSON, L L ANDERSON, M T	8210270041* 8210090368 8210150407 8210120068* 8210130566*	50-205 P NUREG RES FOIA 50-306 Q	AUSTIN, M A AUTERIND, L AUTIO, H A AUTIO, H A AUTIO, H A	8210130308* 8210180091* 8210130230 8210130230 8210130519	70-135 50-286 R 50-29 S 50-29 S
E PARAJA D LEMAJA D LEMAJA D J. MASHEJA D J. MASHEJA	8210040042* 8210150415 8210190528 8210070016 8210130046	50-445 0 RES PR 50-404 A 50-369 H	ANDERSON, P ANDERSON, P ANDERSON, R L ANDERSON, T M ANDERSON, T M	8210040125 8210250120 8210210037 8005070094 8005070099#	50-266 0 50-266 0 Nureo PT21 PT21	AUTIO, H A AUTIO, H A AUTIO, H A AUTIO, H A	8210260106 8210260109 8210260165 8210260428 8210280085	50-29
acensam.e g Adensam.e g Adensam.e g Adensam.e g Acensam.e g	8210180254 8210180267 8210180418 8210190110 8210220511	50-369 F 50-329 A 50-404 A 50-327 P 50-329 A	ANDOGNINI.G C ANDOGNINI.G C ANDRULIB,M N ANG,W P APPEL,R R	8210130394 8210260563 8210270221* 8210150170* 8210280032	PR 70-2949 CONTRACT 50-324 Q 40-878]	AVERITT, D D AXELRAD, J AXELRAD, J AXELRAD, J AXELRAD, J	8210260284* 8210010170 8210070336 8210150267 8210170285	CONTRACT 50-325 Q 50-461 Q 50-271 Q 50-269 Q
Acensame o Aceper u Aceper u Aceper u Aceper u Aceper u Aceper u	8210280407 8210040218 8210210378 8210279011 8210279074	50-369 P 50-289 Q 50-289 Q XPORTLIC XPORTLIC	APPELIR R APPLEGATEIT W ARAGONIJ J ARCHERIC D ARCHERIC D	8210280412 8209270271* 8210150571 8210270413* 8210270419*	40-8728 50-358 H NUREQ 50-367 X CONTRACT	AXELRAD, J AXELRAD, J AXELRAD, J AXELRAD, J AXELRAD, J	6210150368 6210150496 6210260072 6210260073 6210260163	90-315 0 16E 16E 16E 90-318 8
reant. B l Ajarnal R Ajee, J r Agee, J r Ajeem, H m	B210270391 B206230020# B209290240# B210190766# B210270187	XPORTLIC 50-245 P FOIA QA999 71-30	ARCHER.C D ARCHITZEL.R E ARCHITZEL.R E ARMSTRONO.K A ARNOT.O E	8210270428# 8210150235* 8210170714* 8208270088 8210270387	70-1113 50-317 0 50-317 0 FOIA XPORTLIC	AXELRAD, J AXELRAD, J A AXELRAD, J A AXELRAD, J A AXELRAD, J A	8210280221 8210040047 8210040048 821010597 8210150473	50-272 Q 50-321 Q 70-143 50-344 Q 70-143
AHEARNE, J NHEARNE, J NHEARNE, J NHEARNE, J F NHENG, P	8201150005* 8210280404* 8210290393 8210150459 8210040190	FOIA FOIA 10CFR COMMISSION 50-307 G	ARNOT, Q E ARNOLD, E M ARNOLD, K ARNOLD, M L ARNOLD, R C	8210270372* 8210150553 8210240520* 8210270370 8210060342	XPORTLIC NUREQ CONTRACT 40-8153 50-287 P	AXELRAD, J A AXELBON, N AXELBON, N C AXELBON, N L AXELBON, N L	8210190232 8210080251 6210040185* 6210040354* 8210080204*	20-509 0
L-GENB.P *101*OFF.B *101*OFF.B *C-A/AT.R A ALBERT.J H	8210280227 8210150206* 8210150206* 8210150548 821008028[*	50-307 0 50-322 T 50-322 T NUREG 50-416 8	ARNOLDIR C ARNOLDIR C ARSENAVLTIF J ASHBAUGHIC E ASHBAUGHIC E	8210130279 8210290204 8210050039* 8210290043* 8210290051*	50-320 P 50-287 P REGGD 50-142 F 50-142 F	AKELSON, W L AKELSON, W L AYER, J E AYER, J E DACHAND, D	8210150495*	
ALBERT, J H ALBERT, J H ALBERT, J H ALBERT, J O ALBERT, H H	8210220282* 8210270135* 8210270351* 8210060163* 8210010137*	50-416 8 50-416 8 50-416 8 50-508 9 50-324 0	ASHE, F ASHE, F ASHE, F ASHE, F ASHE, F	8105110396* 8107160386* 8103180604* 8111180001* 6111270314*	FO(A FO(A FO(A 50-338 8 50-275 8	BACHMANN, R O BACHMANN, R G BACHMANN, R G BACKLEY, B T BACKUB, R A		
ALDEN, II H ALDEN, II M ALDERSON, C E ALDERSON, C E ALDERSON, C E	8210150282 8210220174* 8210010111* 8210220404* 8210220432*	50-277 P 50-277 R 50-400 G 50-438 Q 50-438 Q	ASHE, F ASHE, F ASHE, F ASHE, F ASHE, F	8210050023* 8210070429 8210070432 8210070474 8210070476	50-278	BACKUS,R A BACKUS,R A BACKUS,R A BACKU,J L BAER,R L		
ALDERSON, C E ALEMANDER, R E ALEAN, J H ALEAN, J H ALEAN, J H	8210220446* 8210050020* 8210170580 8210210136 8210220182	50-438 Q RECOD 50-244 Q 50-209 Q 50-219 Q	ASHE.F ASHE.F SHE.F STEFI.B ATEFI.B	8210080021 8210080059 8210120372 8210040355* 8210040357*	GEN TEC 18 MISC MISC SO-537 A FDIA	DAER,R L BAER,R L BAER,R L BAER,R L BAGBY,L A		

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUJHÜR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	GUBJECT CATEGO»,
BAGBY, L A BAILEY, F C BAIR G G BAIR G G BAISDEN, L	8210080232* 8210050191* 8210250093* 8210250175* 8210210564	71-9167 GA999 50-344 S 50-344 S CONTRACT	BASSIN, N BASSIN, N BASSIN, N BASSIN, N BASSIN, N	8210180344* 8210180347* 8210180349* 8210180351* 8210180352*	FOIA FOIA FOIA FOIA FOIA	BEAMER.W H BEAMER.W H BEAMER.W H BEAMER.W H BEAMER.W H	8210180257* 8210180260* 8210180262* 8210180266* 8210180424*	FOIA FOIA FOIA FOIA 70-278
GAISDENL BAXER, C E DAYER, C E BAYER, C E GAKER, C E	8210210576 8210220516 8210250006 8210250034 8210260017	CONTRACT 40-9681 40-8681 40-8681 40-8681	BASSIN.N BASSIN.N BASSIN.N BASSO.L F BASSO.L F	8210180422* 8210180425* 8210180429* 8210250095* 8210250160*	F01A F01A F01A 50-318 S 50-317 S	BEAMER, W H BEAMER, W H BEARDEN, R G BEARDEN, R O BECHHOEFER, C	821018042/* 8210180431* 8210080057* 8210080064* 8210060229	FOIA FOIA FOIA 50-317 P 50-329 G
EAZER,C E BAKER,C E CAMER,C E BALL,B J BALLARD,R L	8210260022 8210270209 8210270435 8210150564 8111240071*	40-8681 40-8681 40-8681 NUREG 50-266 P	BASTIAN B E BATES.A BATES.A BATES.A BATES.A	8210070358* 8210010045* 8210010074* 8210010172* 8210040368*	50-430 A FOIA FOIA FOIA FOIA	BECHHOEFER, C BECHHOEFER, C BECHHOEFER, C BECHHOEFER, C BECHHOEFER, C	8210130304 8210130421 8210180172 8210210270 8210220322	50-329 ¢ 50-329 ¢ 50-493 ¢ 50-329 ¢
BALLARD R L BANGART.R BANGERTER.D H BANGERTER.D H BANGER R R	8202120129* 7912280014* 8210280032 8210280043 8210120124	50-266 P 50-324 P XPORTLIC XPORTLIC RES	BATES,A BATES,A BATES,A BATES,J W BAUER,E G	8210040371# 8210040381* 8210040383* 8210150067* 8210200063*	FOIA FOIA FOIA 70-1113 50-277 P	BECKIG P BECKERIR A BECKHAMIJ T BECKHAMIJ T BECKHAMIJ T	8210130476 8210040454 8210010022* 8210060231 8210060275	50~151 S 50-537 A 50-321 G 50-366 P 50-366 P
BARKAS, W W BARBER G BARHAM, C D BARKES, C BARKES, I	8210120657 8210150285 8210130550 * 8208£90097 8210120319 *	RES 50-269 G PR 50-148 H GA999	BAUER, E G BAUER, T L BAUM, S L BAUM, S L BAUNACK, W	8210220007* 8210050174 8210250265 8210250265 8210270415	50-27B P 50-192 P 50-247 G 50-247 G 50-410 G	BECKHAM, J T BECKMAM, J T BELMAN, T P BELANGER, J L BELANT, J L	8210120047 8210190329 8210040205# 8210050110# 8210040162#	50-366 P 50-321 P 50-315 S 50-305 G 50-305 S
LARIJES, I BARNETT, J E BARIJUM, E C BARON, J S BARON, J S	8210260558* 8210060020 8210080327 8210150265* 8210150265*	GA999 70-1621 XPORTLIC 50-322 T 50-322 T	BAUNACK, W H BAUSER, M A BAYTER, F BAXTER, J A GAXTER, J A	8210270173* 8210270257 8210070160 8210120262 8210120262	50-244 Q PR 50-443 A 50-483 Q 50-483 G	BELISLE, Q A BELISLE, O A BELL, J M BELL, J M BELL, J M	8210150052* 8210150256* 8210160176* 8210160290* 8210160295*	50-324 G 50-327 G FOIA FOIA FOIA
BARON, J S BARON, J S BARP, K CARR, K BARP K P	8210150290* 8210150290* 8210150136* 8210220341* 8210010122*	50-322 T 50-322 T 70-824 50-160 G 50-83 O	BAKTER, T A BAKTER, T A BAKTER, T A BAKTER, T A BAKTER, T A	8210200009 8210200009 8210200013* 8210200013* 8210210365	50-400 Q 50-400 G 50-400 G 50-400 G 50-483 G	BELL.J M BELL.J M BELL.J M BELL.M J BELL.M J	8210180298* 8210180301* 8210180417* 8210120191 8210120173	FOIA FOIA FOIA WASTE HOT PR
DARR,K P BARR,K P BARR K P BARR K P BARR,X P	8210010127* 8210010137* 8210150086* 8210150356* 8210220356*	70-1201 50-324 Q 50-348 Q 50-335 Q 50-280 Q	BAKTER, TA BAKTER, TA BAKTER, TA BAKTER, TA BAKTER, TA	8210210365 8210250248 8210250248 8210250253* 8210250253*	50-483	BELL.M J BELL.N BELLAMY.R BELLAMY.R BELLAMY.F P	8210120375 8210050369 8210050537 8210070265 8210190757*	WASTE HOT 50~502 0 50~020 P 50~289 S 50~J15 S
DAPR.K P BARR.K P BARR.K P BARRETT.D J BARRETT.L	8210220401* 8210220442* 8210220485* 8206230020*	50-259 Q 70-1113 50-327 Q 50-245 P 50-247 P	BAKTER,T A BAKTER,T A BAYLOR,V B BAYLOR,V B BAYNARD,P Y	8210280360 8210280360 8210060425 8210180407 8210060198	50-289 0 50-289 0 RES RES 50-302 P	BEMIS, P R DENDER, M BENDER, P C BENNECHE, P E BENNETT, A B	8210010436* 8210040374* 8210120132* 8210080237 8209290240*	50-369 0 50-320 5 50-400 0 50-82 P FOIA
BARRETT, L H BARRETT, L H BARRETT, L H BARRETT, L H BARRETT, L H	8009100100 8009100104 8210070043 8210070150 8210190012	90-247 P 50-247 P 50-320 R 50-320 R 50-320 R	DAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY	6210060263 8210150216 8210190681 8210190691 8210210421	50-302 P 50-302 P 50-302 P 50-302 P	BENSINGER, P D BENTON, J W BENTON, J W BERGHOLZ, N E BERGHOLZ, N E	8210130379 8210210189* 8210210189* 8210080184 8210060185	PA 50-382 0 50-382 0 50-337 0 50-537 0
BAPRETT,L H BARRETT,L H BARROWS,J BARRY,L W BARTH,C A	8210190052 8210190127 8210260202 8210050573* 8210200062	50-320 P 50-320 R 50-309 H FDIA 50-400 G	BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY	8210220207 8210220375 8210260010# 8210260310# 8210260377#	50-302 P PR 50-302 F 50-302 Q 50-302 Q	BERGHOLZ, W E BERGHOLZ, W E BERGHOLZ, W E BERGHOLZ, W E DERLIN, K	8210060200 8210130343 8210130435 8210200057 8210150474	50 537 Q 50-537 Q 50-537 Q 70-143 50-528 Q
BARTHIC A BARTINE,D E BARTLETT.J BARTOLINI,R P	8210270087 8210270006* 8210150135 8210180401*	50-255 G COMMISSION 50-220 B CONTRACT 50-206 P	BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY	8210260422 8210260436 8210260454 8210260497 8210270186	50-302 P 50-302 P 50-302 P 50-302 P 50-302 S	BERLIN, K BERLIN, K DERLIN, K BERLIN, K BERLIN, K	8210150499 8210150499 8210150512* 8210150512* 8210290297	50-528
	23 17 32 32	TOPREP TOPREP 50-361 P 50-206 P 50-363 A	P P, GRANARD BAYNE, J P BAYNE, J P BAYNE, J P BAYNE, J P	8210290312 8210040213* 8210040317 8210050079 8210050083	50-302 8 50-286 F 90-333 Q 50-286 F 50-333 F	BERNABEI, L BERNABEI, L DERNABEI, L BERNABEI, L BERNHOFT, S L	8210150449 8210150449 8210150457* 8210150457* 8210040159*	30-358 9 30-358 9 30-358 9 50-305 \$
	)4 '6 14 14 )0	50-361 P 50-206 P 50-206 P 50-361 P 50-361 P	H C 'BNAVB C 'BNAVB C 'BNAVB C 'BNAVB C 'BNAVB	6210040181 6210120233 6210150031 6210170411 6210170713	50-286 P 50-247 P 50-286 P 50-333 Q 50-286 H	BERNHOFT, 8 L BETTENHAUSEN, L BETTENHAUSEN, L BETTENHAUSEN, L BETTENHAUSEN, L	8210190356* 8210070283* 8210070330* 8210210097* 8210210162*	50-305 s 50-293 q 50-277 q 50-354 q 50-272 q
	75 19 18 13	50-206 F 50-206 P 50-206 P 50-206 P 50-206 P	BAYNE, J P BAYNE, J P BAYNE, J P BAYNE, J P	8210190728 8210190738 8210200028 8210200039* 8210200074	50-284 P 50-284 F 50-333 P 50-333 P 50-333 P	BETTENHAUBEN, L BETTENHAUBEN, L BHATIA, P BIBB, H E BICKFORD, W E	8210270132* 8210270354* 8210120430 8210220303* 8210120072	50-322 G 50-322 G REB 50-335 G NUREO
	15# 11# 8# 10# 11#	50-289 Q FOIA FOIA FOIA	BAYNE, J P BAYNE, J P BAYNE, J P BAZIN, J P BAZIN, J P	8210210459 8210210470* 8210280070 8210180329 8210270199	50-286 P 50-286 P 50-286 P CONTRACT CONTRACT	BICKFORD, W E BICKWIT, L BICKWIT, L BIDINGER, G H BIDINGER, G H	8210120102 8210120256 8210120314 8210040397# 8210220028*	NUREO 50-289 0 50-289 0 70-371 70-1257
	0+ '7* 0* 5* 7*	FOIA FOIA FOIA FOIA	BEAMER, W H BEAMER, W H BEAMER, W H BEAMER, W H	8210180215* 8210180217* 8210180222* 8210180234* 6210180251*	FOIA FOIA FOIA FOIA FOIA	BIDINGER, O H BIELAWSKI, A P BIELAWSKI, A P, BILLIG, P F BILLS, J M	8210270436* 8210050391 8210050391 8210010224* 8210060390*	70-115k 50-454 e 50-454 e TOPREP 50-317 \$

ACCESSION   CALLED											•
1.       1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.       1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.       1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.       1.       1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.     1.       1.	яонт <u>и</u>			_	AU THOR		CATEGORY	_	AUTHOR	NUMBER	CATEGORY
	BINGSELDBL SIECHOFF.C A BISCHOFF.C A	8210260411* 8210130417 8210130417	50-295 50~528 50~528	5 G G	BLOCH, P B BLOCH, P B BLOCH, P B	8210210476 8210220242 8210220338	50-155 G 50-440 G 50-266 G 50-155 G	) } }	BOUCHEY, O D BOUCHEY, O D BOUCHEY, O D	8210050154 8210050348 8210060223 8210060319	50+397 E 50-397 A 50+397 A 50-397 E
1-9-1-1	BISHOP.L L BISHOP.L L	8210070132 8210070132 8210070136	50-329 50-329 50-329	G G	BLODGETT, T H BLODGETT, T H	8210150431 8210260114 8210260466	50-387 R 50-387 A 50-389 R	₹ 4 ₹	BONCHEA'O D BONCHEA'O D	8210080095 8210120194 8210120197	50-397 K 50-508 K 50-508 A
	BISHOP.L L BISHOP.L L	8216200054 8216200061 8216200061	50-329 50-329 50-329	G G G	BLUMBERO, N BLUMBERO, N BOARDMAN, J R	0210210213* 0210210236* 0210170419*	50-244 ( 50-334 ( 50-498 (	Ω Ω	BOUCHEY, G D BOUCHEY, G D	8210130575 8210190574 8210190646	50-397 F 50-397 E 50-397 G
1	BISHOP, T W BISHOP, T W BISHOP, T W	8210060109 8210060133 8210060264	50-362 50-275 50-206	Q Q	DOEHNERT, P BOEHNERT, P BOEKNERT, P	9210010083* 9210010089* 9210010095*	50-321 5 50-366 5 50-366 5	5 5	BOUCHEY, G D BOUCHEY, G D	9210210045 9210210049 9210210148	50-397 K 50-397 E 50-397 €
110-07   1	\$1940P, T W B1940P, T W B1940P, T W	8210080212 8210190250 8210190478	50-206 50-361 50-361	0 5 0	BOMBERGER, C BOOK, H E BOOK, H E	8210040131* 8210040134	50-346	Q.	BOUCHEY, O D BOWERING, D	8210270012 8210180146* 8210290006*	50-508 A 50-454 G COMMISSION
LLY, R. L. 8210150234 50-232 0 BODK. H. E. 821015036- 80-22 0 BOYLE, R. R. 8210120324 MASTE HOT LLY, R. L. 821015036- 80-22 0 BODK. H. E. 82101203017 BODK. R. R. 821012034 MASTE HOT LLY, R. L. 821015036- 80-22 0 BODK. H. E. 8210203014 S0-297 0 BING. R. R. 821012034 MASTE HOT LLY, R. L. 821015036- 80-22 0 BODK. H. E. 8210203041 S0-297 0 BING. R. R. 8210203041 BODK. R. R. 8210203041 BODK. R. R. 8210203041 BODK. R. R. 8210203041 BODK. R.	21640P.T H 31640P.T H 8166EFF.P	8210280324 8210280330* 8210210213*	50-275 50-275 50-244	0 0 0	BOOK'H E BOOK'H E BOOK'H E	8210130152 8210190450 8210190473	State Pro 50-361 70-754	ā	BOYD, R S BOYER, R E	8210120324 8210120331# 8210050290#	REVIEW GRP REVIEW GRP GA999
LLCF, R   G210194024   90-322   0   GOSK   H   O	ELACKUR L ELACKUR L	8210150324* 8210150337* 8210150351*	50-322 50-322 50-322	G G G	000K'H E 000K'H E 000K'H E	8210190636* 8210250173 8210250178*	50-27 50-362 50-362	0 0 G	BOYLE, R R BOYLE, R R BRACK, B	6210120324 8210120448 8210060216*	WASTE MGT WASTE MGT FOIA
LLF/F, R	ELACKAR L ELACKAR L ELACKAR L	8210150402* 8210150410* 9210150422*	50-322 50-322 50-322	0 0 0	BOOKER, J E BOOKER, J E	8210190605 8210050201 8210050219	50~312 50~458 50~458	0 5 5	DRADBURY,R D DRADFORD,L DRADFORD,L	8210290237 8210050176 8210050237	PR 50-269 0 50-289 6
St.P.F.   S.	ELACKIR L ELACKIR L ELACKIR L	8210190370 8210190373 8210190381	50-312 50-522 50-312	0 0 0	BOOKER, J E BOOKER, J E	8210130182 8210130516 821017036/	50-45B 50-45B 50-45B	8 5 5	BRADLEY, E J BRADLEY, E J BRADLEY, E J	8207070201 8207170149 8210060296	50-278 P 50-352 F 50-277 J
ELAR, B S	SLACKUS SLACKMANUH S SLACKMANUH S	0210240285 8210120124 8210120457	50-382 RES REB		BOOKER, J E BOOKER, J E	8210200037 8210220376 8210250118	50-458 PR 50-458	s s	BRADLEY,E J BRADLEY,E J BRADLEY,E J	8210200046 8210200049* 8210220006	50-277 P 50-277 P 50-278 P
ELWE E L 821080094 50-287 0 BORDENICK, ID 821029059** 50-322 0 BRANDE, CD 8210490787 50-247 Q BLUE E L 8210180078 50-289 0 BORDENICK, B M 8210040011 50-322 0 BRANDE, CD 8210190780** 50-284 F BLUE E L 8210180075 50-289 0 BORDENICK, B M 821004003 90-322 0 BREHEN, P J 8210140760** 50-234 F BLUE E L 821020033 50-289 0 BORDENICK, B M 821004003 90-322 0 BREHEN, P J 82101400608 50-234 F BLUE E L 821020033 50-289 0 BORDENICK, B M 8210200034 50-322 0 BRENER, L 8210240860 50-322 0 BRENER, L 8210240803 50-289 0 BORDENICK, B M 8210200034 50-322 0 BRENER, L 8210240803 50-322 0 BRENER, L 8210240803 50-289 0 BORDENICK, B M 8210200034 50-322 0 BRENER, L 8210240803 50-322 0 BRENER, L 8210240803 50-322 0 BRENER, L 8210240803 50-322 0 BRENER, L 8210240803 50-322 0 BRENER, L 8210240803 50-322 0 BRENER, L 8210240803 50-322 0 BRENER, L 8210240460 50-329 0 BORDENICK, B M 8210280234 50-322 0 BRENER, L 8210240460 50-329 0 BORDENICK, B M 8210380371 50-155 0 BRENER, L 821040460 50-329 0 BORDENICK, B M 8210380371 50-155 0 BRENER, L 821040460 50-329 0 BORDENICK, B M 8210380371 50-155 F BLUE, J 8210010110* 50-413 0 BORDENICK, B M 8210803037 50-358 S BORDENICK, B M 821080303 50-389 0 BORDENICK, B M 821080303 50-389 S BORDENICK, B M 821080303	ELAIR.B S Elair.B S Plair.B S	8210250356 8210250356 8210250356	PROJ PROJ PROJ	G	BOOKER, J E DOOS, A BOOS, A	8210240504 8210240504 8210240504	PR 50-329 50-329	T T	BRADLEY, F J BRANCH, M W BRANDENBURG, D	8210230321 8210150502* 8210250081	PR 50-407 G 50-247 G
S.A.G.E L 021020033 50-287 0 BORDENICK, B M B210200034 50-322 0 BRENNER, L 8210210383 1.A.G. J 8210150708 50-324 0 BORDENICK, B M 8210280209 50-322 0 BRENNER, L 821022032 1.A.G. J 82101504046 50-259 0 BORDENICK, B M 8210280209 50-322 0 BRENNER, L 821022032 1.A.G. J 821020031 50-424 0 BORDINE, T C 8210130471* 50-155 0 BREN, H L 821022032 1.A.G. J 8210100091* 50-424 0 BORDINE, T C 8210150505 50-155 F 821021001010* 50-413 0 BORDINE, T C 8210150505 50-155 F 8210101010* 50-413 0 BORDINE, T C 82101505037 50-155 F 8210101010* 50-413 0 BORDINE, T C 821050337 50-155 F 8210101012* 50-267 0 BORDINE, T C 821050337 50-358 K 82101001039* 90-389 0 BORDINE, T C 821050337 50-358 K 82101001031* 50-338 0 BORDINE, T C 8210050337 50-358 K 8210100303* 90-389 0 BORDINE, T C 8210050337 50-358 K 82101001031* 50-338 0 BORDINE, T C 8210050337 50-358 K 82101001031* 50-338 0 BORDINE, T C 8210050337 50-358 K 821010033* 50-324 0 BORDINE, T C 8210050338 50-358 K 821010031* 50-324 0 BORDINE, T C 8210150357 50-358 S R R R R R R R R R R R R R R R R R R	elwe, e l Blwe, e l Blwe, e l	8210080094 8210080094 8210130275	50-287 50-287 50-289	0 G G	BORDENICK, D BORDENICK, D M BORDENICK, D M	8210250057* 8210040011 8210040063	50-322 50-322	Q G Q	BRANDENBURG.B BRAUND.C D BREHENY.P J	8210290271 8210190787* 8210190760*	50-247 G 50-440 G
BLAKE, J B210010110+ 50-247 0 BDRDINE, T C B210250371 50-155 F BLAKE, J B210010305+ 50-367 0 BDRGMANN, E A B210050332 50-358 K BLAKE, J B210010314+ 50-338 0 BDRGMANN, E A B210050332 50-358 K BLAKE, J B210010314+ 50-338 0 BDRGMANN, E A B210040271 50-958 S  BLAKE, J B210150043+ 50-324 0 BDRGMANN, E A B210040355 50-358 E BLAKE, J B210150043+ 50-324 0 BDRGMANN, E A B21010372 50-358 E BLAKE, J B210150123+ 50-324 0 BDRGMANN, E A B21010372 50-358 E BLAKE, J B210150123+ 50-324 0 BDRGMANN, E A B210150372 50-358 E BLAKE, J B210150123+ 50-324 0 BDRGMANN, E A B210150387 50-358 K BLAKE, J B2101404322 50-413 D BDRGMANN, E A B210150387 50-358 K BLAKE, J B210040183+ 50-322 T BDRGMANN, E A B210260279 50-358 E BLAKE, H H B210150257+ 50-322 T BDRGMANN, E A B21026048 50-358 E BLAKE, H H B210150257+ 50-322 T BDRGMANN, E A B210270281+ 50-358 Q BLAKE, H H B210150257+ 50-322 T BDRGMANN, E A B210270281+ 50-358 Q BLAKE, H H B210150257+ 50-322 T BDRGMANN, E A B210270281+ 50-358 Q BLAKE, H H B210150257+ 50-322 T BDRGMANN, E A B210270281+ 50-358 Q BLAKE, H H B210150257+ 50-322 T BDRGMANN, E A B210270285+ 50-358 Q BLAKE, H H B210150257+ 50-322 T BDRGMANN, E A B210270285+ 50-358 Q BLAKE, H H B210150257+ 50-322 T BDRGMANN, E A B210270285+ 50-358 Q BLAKE, H B B210120337 50-440 Q BDRGMANN, E A B2102702870+ 50-368 Q BLOW, P B B210120337 50-440 Q BDRGMANN, E A B2102702870+ 50-368 Q BLOW, P B B210120337 50-440 Q BDRGMANN, E A B2102702870+ 50-368 Q BLOW, P B B210120337 50-440 Q BDRGMANN, E A B2102702870+ 50-368 Q BLOW, P B B210120337 50-440 Q BDRGMANN, E A B2102702870+ 50-368 Q BLOW, P B B210120337 50-440 Q BDRGMANN, E A B210010025 50-308 H BLOW, P B B210120337 50-440 Q BDRGMANN, E A B210010025 50-308 H BLOW, P B B210120337 50-440 Q BDRGMANN, E A B210010025 50-308 H	e.ake.e l I.ake.j Ilake.j	8210200033 8210150170* 8210150404*	50-287 50-324 50-259	0 Q Q	BORDENICK.B M BORDENICK.B M BORDENICK.B M	8210200034 8210280209 8210280234	50~322 50~322 50~322	0 0	DRENNER, L DRENNER, L DREWSTER, C	8210220332 8210210383	
BLAKE, J	BLAKE, J J BLAKE, J J SLAKE, J J	8210010110* 8210010124* 8210010305*	50-413 50-267 50-369	Q Q Q	BORDINE, T C BORGMANN, E A BORGMANN, E A	8210250371 8210050137 8210050332	50-155 50-359 50-358	F 8 K			
#LAUER, H H 8210150250* 50-322 T BORGMANN, E A 8210240488 50-358 E  \$LAUER, H H 8210150250* 50-322 T BORGMANN, E A 8210240281* 50-358 G  \$LAUER, H H 8210150257* 50-322 T BORGMANN, E A 8210240285* 50-358 G  \$LAUER, H H 8210150257* 50-322 T BORGMANN, E A 8210240285* 50-358 G  \$LOCH, P B 8210050751 50-266 G BORGMANN, E A 8210240285* 50-358 G  \$LOCH, P B 8210120337 50-440 G BORGMANN, E A 8210280382 71-9044  \$LOCH, P B 8210120337 50-440 G BORGMANN, H 8210140236* 50-304 B  \$LOCH, P B 8210130329 50-440 G BORGMEN, G B 8210010020 50-508 H  \$LOCH, P B 8210130333 50-440 G BORGMEN, G B 8210040255 50-397 A	BLAKE, J J BLAKE, J J BLAKE, J J	8210150063* 8210150114* 8210150123*	50-324 50-324 50-369	Q Q Q	BOROMANN, E A BOROMANN, E A BOROMANN, E A	8210040358 8210130372 8210150387	50-358 50-358 50-358	6 8 K			
BICCH,P B B210120337 50-440 Q BCHYSIAK,H B210190399* 50-346 B BICCH,P B B210130329 50-440 Q BCHCHEY,O D B210010020 50-50B H BICCH,P B B210130303 50-440 Q BCHCHEY,O D B210040255 50-397 A	RLAUER, H M BLAUER, H M BLAUER, H M	6210150204* 6210150250* 8210150257*	50-322 50-322 50-322	T T T	Borgmann, e a Borgmann, e a Borgmann, e a	8210250498 8210270281* 8210270285*	50-398 50-358 50 <b>-</b> 358	E 0 0			
	BLOCH, P B BLOCH, P B BLOCH, P B	8210120337 8210130329 8210130333	50-440 50-440 50-440	0	BOUCHEY, O D BOUCHEY, O D	8210170359* 8210010020 8210040255	50-346 50-508 50-397	Ĥ A			

# FERSUNAL AUTHUR INDEX

AU THOR	ALLES ION ROGNUM	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEB910N NUMBER	5 3 <del>4</del> - Cate, -
BRINAMAN, REBRINAMAN, REBRINAMAN, REBRINAMAN, REBRINAMAN RE	8210180152+ 8210180157+ 8210180343+ 8210180372+ 821018037J+	FOIA FOIA	BUCK, J R BUCK, J R BUCKLES, J BURDOIN, J F BURGER, C	8208270012 8208270012 8210040313 8210060141# 8210010206#	ACRS ACRS 50-315 J 50-275 Q 50-325 Q	GAREY, J J CAREY, J J CARLSON, J D CARR, A V CARR, A V	8210270267 8210270268* 8210280303* 8210250125 8210250282	50 334 50 3.4 ( 50-215 50 413 (
GRINAMAN, R.E. GRINAMAN, R.E. SRINAMAN, R.E. SRINAMAN, R.E. BRIMAMAN, R.E.	8210180377+ 8210180380+ 8210180383+ 8210180387+	FOIA FOIA FOIA	BURGER, C BURGER, C BURGER, C BURGER, C W BURGER, C W	B210220173* 8210220503* 8210220504* 8210010205* 8210010397*	50-324 Q 50-324 Q 50-261 Q 50-324 Q 50-400 Q	CARR, A V CARR, S E CARR, S E CARRICO, J B CARRICO, J B	8210240415 82100505000 8210210064 8210220066 8210220092#	20 411 COV +4.1 COV +2.1 40 E1; 40 E1;
BRIMAMAN R E BRIMAMAN R E BRINAMAN R E BRIMAMAN R E BRIMAMAN R E	8210180391* 8210180394* 8210180399* 8210180402*	FOIA FOIA FOIA FOIA FOIA	BURGER, C W BURGER, C W BURGER, C W BURGER, F J BURGESS, B L	8210190300 8210190659 8210220163* 8210130193* 8210190750*	50-324 S 50-324 S 50-490 G 50-271 R 50-329 G	CARTER,R E CARTER,R S CARTER,R S CARTER,S CARTER,S	8210180014 8210130160 8210130163+ 8210290321+ 82100604224	50 82   1 50 184   1 50 184   50 457 50 457
OFINAMAN, RE OFINAMAN RE OFICATION BRODE, RH OFIODSKY, A	62(#160406* 6210(60409* 8210)50496 62(#060354* 82(#060026*	FOIA FOIA 18E 50-261 F REGGD	BURKE.D J BURKE.E M BURNETT.P T BURNETT.P T BURNETT.P T	8210010245* 8210260504 8210010151* 8210010176* 8210010472*	50-280 0 50-329 T 50-416 0 50-261 0 50-395 0	CARTWRIGHT, W CARTWRIGHT, W CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R	8207230301 8207230301+ 8210010140 8210010145+ 6210010163	50-0 3 1 50-3/3 1 50-3/3 1 50-3/4 1
BRODSKY, A BRONS, J C BRONS, J C BROOKS, D BROOKS, E	8210270331 8210180088 8210180088 8210120353*	NUREG 50-286 F 50-286 R WASTE MGT 50-348 Q	BURNETT, P T BURNETT, R F BURNETT, R F BURNETT, R F BURNETT, R F	8210150143* 8210070047* 8210070445* 8210070471* 8210070482*	50-269 G 50-537 D FOIA FOIA FOIA	CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R	8210010136 8210010341 8210010319 8210010160	10 3m ( 50 Jm ( 50 Jm 50 Jm 50 Jm
BROOMS, E H GROOMS, W GROUN, C H BROWN, E J BROUN, E J	6210010432* 8210210200* 8210150384* 8110010072* 8111040084*	50-259 0 50-271 P 50-243 0 F81A 50-313 S	BURNETT,R F BURNETT,R F BURNETTE,R D BURNS,R A BURNS,S	8210180107* 8210170075* 8210080258* 8210170435* 8210150236	70-143 REVIEW GRP 50-267 P 50-333 Q ORG	CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R	8210080182 8210080165 ± 8210190264 8210190270 ± 8210190129	50 43 1 50-03 8 50-03 1 50-03 1
BROWN, E J BROWN E J BROWN, E J BROWN, E J	6207/50106+ 6210070104 6210070111 6210120093 6210120372	50 261 P 50-313 S 50-348 S MISC MISC	BURNS.S C BURSEY.B BURSTEIN.S BURWELL,S B BUSCH.S L	8210150090 8210150458 8210050055 8210210025 8210070099*	MISC 50-395 0 50-246 P 50-445 A 50-29 P	CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R	921019033/+ 8210220227 92102202J4+ 8210220415 6210220421+	50 3 3 4 5 50 3 3 7 1 50 3 4 1 50 3 4 1 50 3 3 1 1
BUGMY O D BUGMY O D BUGMY O D BUGMY O D	621070363 6210220123 6210220161 6210220464 6210280160	40-4622 40-1162 40-2259 40-4622 40-7580	BUSCH, S. L. NUSH, N. BUSS, R. D. BUTLER, H. B. BUTTER, L. D.	8210120300* 6210120425* 8210130390* 8210040379* 8210050397	50-213 P CONTRACT 50-254 R FOIA NUREG	CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R	921022044 [ 82102204501 8210240201 8210240287+ 8210240290	50 34 50-14 [ 50-04] [ 50 33] [ 50-2 ] [
BROWN H H BROWN H H BROWN H H BROWN H H	8210050180 8210050180 8210050189 8210050189 8210250097	50-275 0 50-275 0 50-322 0 50-322 0 50-275 P	BYRD, R BYRD, R BYRD, R BYRD, R BYRD, R	8210080127* 8210080287* 8210080298* 8210220274* 8210220431*	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S	CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R	82 (0260293# 8210260346 8210260360# 8210290337 8210290347#	50 3 d 54 50 3 l 6 50 3 l 1 50 3 d 1
BROWN, P BROWN, R BROWN, R BROWN, R BROWN, R C	8210290097 8210040214# 8210010231 8210070281 8210220171#	50-275 P 50-443 Q 70-2873 40-8745 40-2259	BYRD, R BYRD, R BYRD, R W CAGNCTTA, J P CAGNETTA, J P	8210220462* 8210270345* 8210270055* 8210130280 8210130331	50-416 S 50-416 S 50-416 B PRM 50-213 P	CARUSO, R CARUSO, R CARUSO, R CARUSO, R GARUSO, R	8210070085 8210070169 8210120207 8210120245 8210120272	50 29 F 50 29 F 50-29 F 50-29 F
BROWN, R C BROWNLEE, V L BROWNLEE, V L BROWNLEE, V L	8210010450* 8210010031* 8210010031*	50-537 A 50-537 A 50-321 Q 50-321 Q 50-325 Q	CAGNETTA, J P CAGNETTA, J P CAMILL, W J CAIN, C L CAIN, C L	8210130331 8210130331 8210040215 8210070374* 8210220070*	50-213 P 50-213 P 50-258 K 40-6622 40-8111	CARUSO,R CARVER,A M CABE,E O CASEY,B J CASHMAN,D C	821021012J 82100101151 82102603391 8210190720+ 8210260240+	COMINACE   20 Sel   20 Sev   20 Sev   20 Sev
BROWNLEE, V L BROWNLEE, V L BROWNLEE, V L BROWNLEE, V L BROWNS, R J	8210150103* 8210190271 8210220159* 8210220232* 8210120125	50-424 G 50-302 S 50-424 G 50-348 G NUREO	CAIN, C L CAIN, J CALDWELL, R A CALL, V B CAMPBELL, D	8210220128* 8210240084 8210240301* 8210270288* 8210170040*	40-1162 Waste Mgt 50-278	CASSEL, D W CASSEL, D W CASSEL, D W CASSEL, D W CATCHPOLE, G J	9210210346 9210210346 9210210347* 9210210347* 9210260377	50 454 6 3 50 454 6 7 50 454 6 7 50 454 6 7 40 6745
BRUCE, W R BRUNE, R L BRUNNER, E BRUNNER, E BRUNNER, J E	8210120432* 8210060004 8210010007 8210220255 8210050246	CONTRACT NUREQ 50-220 8 50-333 8 50-329 0	CAMPBELL, G CAMPBELL, J E CAMPBELL, M A CAMPBELL, R H CANTER, H	8210290066# 8210290399 8210190530 8210250025 8210250138	50-259 S RES State Prog WASTE MOT 50-912 S	CAUDLE, R E CAVANAUGH, W CAVANAUGH, W CAVANAUGH, W CHAJKEN, J A	8210070409 8210040107 8210250159 8210260180* 8208290078	71-7150 50 313 / 50 368 / 50 313   FOIA
T V.VAVAR D V.VANNOND D V.VANNOND D V.VAVAR D V.VAVAR	8210040193 8210180212 6210220381 8210050504 8210240084	50-329 G 50-329 G 50-329 G RES 40-8452	CANTER: H L CANTRELL: F 8 CANTRELL: F 8 CANTWELL: P E CAPHTON: D L	6210060334* 8210150032* 8210150334* 8210160175* 8210210056*	50-312 Q 50-416 Q 50-518 Q 50-304 B 50-209 Q	CHAN, T L CHANDLER, J C CHANDLER, J C CHANDLER, J C CHANDLER, L J	8210060393 8210120230 8210150511 8210270164 8210040009	50-015 4 50-016 1 10PPEP 10FFEP 50-041 1
BRYAN, V J BRYANT, J C BRYANT, J C BRYANT, J C	8210280446 6210010166* 8210010436* 8210010474* 82100170447	40-6452 50-269 0 50-369 0 50-269 0 50-287 8	CAPHTON, D L CAPHTON, D L CAPHTON, D L CAPRA, L A CAPRA, L A	82 0210213* 82 0210236* 82 0290072* 82 0040335* 82 0040340*	50-244 Q 50-334 Q 50-289 Q QA999 QA999	CHANDLER, L J CHANDLER, L J CHAPLIN, B D CHARNLEY, J B CHARNLEY, J B	8210180075 8210220240 8210150289* 8210170818 8210250074*	50-361 6 50-361 8 50-320 8 50-320 8 50-320 8
BRYANT, J C BRYANT, R E BUCHANAN, C R BUCHANAN, C R BUCHANAN, C R	8210220471* 8210210444* 6210180116* 8210180319*	50-413 0 CGNTRACT FOIA FOIA FOIA	CARALIE, O P. CAREY, J J CAREY, J J CAREY, J J CAREY, J J	8210050213* 8210010013 8210050165 8210060076 8210130561	70-2942 50-334 F 50-334 P 50-334 R 50-334 P	CHARNLEY, J 8 CHARTERINA, J CHABE, J, CHABE, J, W CHAUDHARY, 8 K	8210270288 8210070181+ 82102205031 8210150032+ 8210270210+	10PREP 50-219 1 50-324 i 50-418 i 50-052 i
BUCHANAN.CR BUCHANAN.CR BUCHANAN.CR BUCHHEIT.RD BUCHHOLZ.RH	8210180324* 8210180370* 8210180375* 8210190420* 8207120147	FOIA FOIA FOIA 50~333 G 50~447 A	CAREY, J J CAREY, J J CAREY, J J CAREY, J J CAREY, J J	8210150018* 8210150312 8210190747 8210220184 8210240458	50-334 Q 50-334 P 50-334 P 50-334 Q 50-334 F	CHECK.P 8 CHECK.P 8 CHECK.P 8 CHECK.P 8 CHECK.P 8	8002140204+ 8003310179+ 8004100193+ 8010210783 8011200025	50-265 P 50-265 P 50-265 T 50-247 P

RDHTUA	NUMBER (	SUBJECT CATEGORY		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	• ••	AUTHOR	ACCESSION NUMBER	CATEGORY
HECKLP S HECKLP S HECKLP S HECKLP S HERLY C	8203040474* F0 8210050477 50 8210060458* 50 8210080053 50	31A 0-537 A 0-537 D 0-537 D UREG		CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W	8210080084 8210080070 8210080070 8210180051* 8210180054*	50-382 50-382 50-382 FOIA FOIA	G G G	CLAYTON, F L CLAYTON, F L CLEMENTS, W D CLEMONS, P CLEMONS, P E	8210280282 8210290289 8210040042* 8210220255 8210070316*	50-364 P 50-364 B 50-445 G 50-333 S 70-364
MEN'S J MEN'S J HEMAULT, N H HEMAULT, N H HEMAULT, N H	B107270196* 5 B210190967* 5 B210220150* 5	0-266 0 0-266 0 0-416 5 0-416 5 0-416 5		CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W	6210180057* 6210180058* 6210180312* 6210180315* 6210180310*	FOIA FOIA FOIA FOIA FOIA		CLEVELAND, J C CLIFFORD, J W CLINE, W E CLOUGH, R W CLOUGH, R W	8210150564 8210220513 8210150401* 8107270176* 8107270182*	NUREG 50-445 A 50-261 G 50-266 G 50-266 G
MENAULTIN H MENAULTIN H MENGUN H MIANOLIN J MIANOLIN J	B210290081* 5 B210270208* 5 B210180141 5	0-416 S 0-416 S 0-338 P 0-400 S 0-400 S		CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W	8210260406 8210280253 8210280253 8210280387 8210280387	50-266 50-266 50-266 50-382 50-382	G G G	CLOUGH, R W CLOUGH, R W CLOUGH, R W CLOUGH, R W	8107270185* 8107270188* 8107270191* 8107270194* 8107270198*	50-266 0 50-266 0 50-266 0 50-266 0 50-266 0
MIFK'S 1 MIFK'S 1 MIFK'S 1 MIFK'S 1	8210040102 5 8210040108 5 8210060189 5	70-143 50-275 G 50-247 G 50-133 G		CILIMBERO,R L CILIMBERO,R L CILIMBERO,R L CILLIS,M CILLIS,M	8210040415 8210050538 8210250340 8210260131# 8210250178#	50-315 50-315 50-315 50-228 50-362	<del>የ</del> የ ዐ ዐ	CLOUGH, R W CLOUGH, R W COALHELL, I N COBB, J C COBB, L I	8107270199* 8210260211 8210040231 8210210046 8208190237	50-266 0 NUREO 50 264 J NUREO 50-3 0
HITH'S A HITH'S A HITH'S A	8210070183 8210070192 8210080207*	50-275 0 50-201 0 50-537 6 F01A 100FR		Clpolla, A J Clapp.n E Clark, A T Clark.c W Clark.d	8210150600 8210150564 8210070313* 8210210329 8210200113	40-3392 NUREG 50-537 TOPREP TOPREP	D	COCHRAN, T B COCHRAN, T B COCHRAN, T B CODELL, R CODELL, R	8210210240# 8210220279# 8210220283# 8007280312 8210050431	50-53/ G 50-537 G 50-537 G 50-247 P NUREG
HITK'S A HITK'S A HITK'S A HITK'S A	8210120599 8210130075 8210130087#	50-275 0 100FR 50-289 T 50-289 T 50-395 T		CLARK,K M CLARK,L GLARK,M T GLARK,N E GLARK,P R	8210170621 8210170334 8210120657 8210080276 8210210280	50~424 50-20 RES 50-395 50-219	5 F P	COHEN, I COHEN, K D COHN, B M COLARULLI, P F COLARULLI, P F	8210290107* 8210070485* 8210270230* 8210250272 8210250272	50-220 G FOIA CONTRACT 50-247 H 50-247 H
HITM'S A MITM'S A MITM'S A MITM'S A	8210130106* 8210130327 8210130336 8210150193	50~395 T 50~275 0 50~397 0 50~133 0 50~437 0		CLARK, R A CLARK, R A CLARK, R A CLARK, R A CLARK, R A	8110270050* 8207210514 8210010018 8210040044* 8210040443	50-266 50-309 50-317 50-335 30-309	የ የ የ	COLBURNIT O COLBURNIT G COLBURNIT O COLEIR K COLEIS	8110300460* 8210270274 8210270426 8210050377 8210260232	50-266 P 50-266 P 50-266 P NUREG 50-322 I
HILKE J HILKE J HILKE J HILKE J	8210190472 8210180180 8210180182	70~143 50~269 50~413 FOIA 50~269	;	CLARK, R A CLARK, R A CLARK, R A CLARK, R A CLARK, R A	8210040414 8210040420# 8210040427* 8210050484 8210050507*	50-266 50-266 50-266 50-317 50-309	Р Р Р	COLE, S COLEMAN, J M COLEMAN, J M COLEMAN, J M COLEMAN, J M	8210260239# 8210260367 8210260367 8210260373 8210260373	50-322 T 50-338 G 50-338 G 50-338 G
HITKER OF HITKER OF HITKER OF HITKER OF	B210210422 B210210427 B210210428 B210210493 B210210508	50-287	) 	CLARKIR A CLARKIR A CLARKIR A CLARKIR A CLARKIR A	8210050507# 8210070012 8210070057# 8210070060# 8210070117#	50-309 50-344 50-309 50-309 50-317	ե 6 2 6	COLEMAN, R COLEMAN, R COLEY, J L COLEY, J L COLEY, J L	8210170217 8210270376 8210010110* 8210150114* 8210220218*	CONTRACT CONTRACT 50-413 G 50-324 G 50-424 G
41.FK/8 7 41.FK/8 7 41.FK/8 7 41.FK/8 7	8210220249 8210220416 8210220473 8210230010 8210230040	50-275 50-382 50-387	P T Q P Q	CLARK, R A CLARK, R A CLARK, R A CLARK, R A CLARK, R A	8210070130* 8210120134 8210180599 8210190008 8210210587	50-317 50-317 50-213 50-313 50-336	ያ ር ያ የ	COLLEY, JA COLLINS, D M COLLINS, J T COLLINS, J T COLLINS, J T	8210040004# 8210180075# 7811200399# 7905290357* 7908130654#	CONTRACT FOIA 50-325 S 50-324 P 50-261 P
HILK'S A HILK'S A HILK'S A HILK'S A HILK'S A	8210260468 8210270161 0210270170 8210280265 8210270446	50-327 50-320 50-289	0 0 0 0	CLARKIR A CLARKIR A CLARKIR A CLARKIR A CLARKIR A	8210220020 8210230050* 8210230267 8210260551 8210270297*	50-336 50-335 50-307 50-335 50-266	P P P	COLFINS'N CORTINS'N L CORTINS'N L CORTINS'N L	8210280030 8210280024* 8210280027* 8210280042*	8tate Frog 50-324 P 50-324 P 50-241 P
HAMAL IS GENALL	8103050787* 8104270103* 8107080417* 8112010310* 8201050061*	50~366	የ 8 8 8 8	CLARK.R A CLARK.R A CLARK.R A CLARK.R A CLARK.R A	8210270303* 8210280210 8210270038 8210270042 8210270413	50-266 50-344 50-285 50-338 50-344	₽ ₽ ₽ <b>Q</b>	COLLINS, M COLLINS, P COLLINS, P L COLLINS, R M CC		
Firanal, M Firanal, M Firanal, M Firanal, M	8201170538* 8203170060* 8204210287* 8210080027* 8210070115	50-346 FDIA 50-416 50-348 50-346	8 8 8	CLARK, R A CLARK, R A CLARK, R A CLARK, R A CLARK, R A	B210270416* B210270421* B210270428* B210270431* B210270441*	50-338 50-317 50-264	<u> </u>			
ERANAL M ERANAL M ERANAL M ERANAL M ERANAL M	8210070122 8210070442 8210070440 8210070470 8210080018	50-327 50-324 50-346 50-346 50-336	8 8 8	CLARK, R. A CLARK, R. Q CLAV, E. L. CLAYTON, F. L.	9210290444 9210290041 9210010460 9210010399 9210010129	:				
IRAMAL, M IRAMAL, M IRAMAL, M IRAMAL, M IRAMAL, M	8210080067 8210120155 8210120171 8210120369 8210220519	50-339 50-293 50-321 50-272 50-333	8 8 8	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8210010195 8210050066 8210050087 821013027 821013052					
DNG.L A RIBBOTIMOS.N RIBTIMAN.J N RIBTIMAN.J N RIBTOFFER.O	8210080055# 8011060568# 8210150279 8210150279 8210050311#	50-537 50-254 50-322 50-322 50-331	D 8 6 0	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F. L CLAYTON, F. L	821015007 8210150331 8210190404 8210190724 821019074					
RESTOPHER, W. RESTOPHER, W. RESTILL B. RESTILL B. RESTILL B. RESTILL B. RESTILL B. RESTILL B.	8210130174* 8210290057* 8210070124 8210070124 8210080084	50-282 50-382 50-382 50-382	8 6 9	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F. L CLAYTON, F. L	821025007( 8210260416 821026043, 821026045/ 8210280136					

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUD FCT CATEGORI
FORMER E L GREEN E L OK ER T B OREER T B OREER T B	8210640043 8210250048 8210050197 8210050197 8210050326	50-335 P 50-335 P 50-352 O 50-352 G 50-352 A	CORRADO, J COSTELLD, J R COTTER, B P	8210260076 8210120353* 8210120233* 8210200050 8210200056	50-142 G WASTE MGT GA979 50-482 G 50-397 G	CRANE, PA CREED, JR CREED, JR CRESWELL, JS	8210260359 8210270276 8210050110* 8210050311* 8210120380	50-133 F 50-275 # 50-325 f 50-328 f 50-327 f
COMPERT B CERNERT B COMPERT B COMPERT B COMPERT B	8210050382 6210050392 8210070402 9210970402 8210200046	50-352 G 50-352 G 50-358 G 50-358 G 50-352 G	CONNEIL, N G CONNEIL, N G	8210200087 8209300324 8210010207 8210010207 8210010207	50-70 G 50-213 P 50-213 P 50-213 P 50-213 P	CREWS, J L CREWS, J L CREWS, J L CRISCIONE, J L CROCKER, H W	8210010042 8210010285 8210190731 8210010385* 8210150059*	50 205 } MISC 50 344 L 50 -335 \$ 50 022 }
COMMERT B COMMORT L COMMORT L COMMORT L COMMORT B	8210200066 8207180058 8207180060 8207180061 8210270180	50-352 G FOIA FOIA FOIA 40-8502	COUNSIL, W G COUNSIL, W G COUNSIL, W G COUNSIL, W G COUNSIL, W G	8510010315 8510010315 8510010530 8510010530	PR PR PR 50-213 P 50-213 P	CROCKER, H W CROFF, A G CROMER, D L CROSBLE, % L GROSSMAN, W A	8216210142• 821007025 1• 8210180105 821012050 3 8210056379•	50-337   50-537   50-413   5 xr0411   5 xr04111   5
CONTE R CONTERR CONTISSERT S COOK.B A CNOK H L	8210150091* 8210260483 8210130399 8210120400 8210160415*	50-289 Q 50-289 S PR RES FOIA		8210010312 8210040120 8210040120 8210050090 8210050090	50~213 P 50~245 F 50~245 F 50~336 P 50~336 P	CROSSMAN, W A CROSSMAN, W A CROUSE, R P CROUSE, R P CROUSE, R P	8210190419+ 8210190452+ 8210050235 9210050236+ 8210050304	50 478 1 50 302 1 50 345 4 50 345 1
1 00% 1 M 2 00% 1 M 2 00% 1 M 2 00% 1 M	0210120243* 8207070419 8207070422* 8210010278 8210010437	50-333 R 50-329 K 50-329 K 50-329 E 50-329 A	CONVEIT'M C CONVEIT'M C CONVEIT'M C	8210050118 8210050118 8210050177 8210050177 8210050179	50-245 P 50-245 P 50-245 P 50-245 P 50-336 P	CROUSE.R P CROUSE.R P CROUSE.R P CROUSE.R P CROUSE.R P	8210090310 8210090313* 8210050333 8210040314 8210080280*	50 345 F 50 345 F 50 345 F 50 345 F
COC+ U N COC+ U N COC+ U N COC+ U N COC+ U N	8210050143 8210080115 8210120274 82101300054 8210130264	50-329 S 50-329 R 50-329 A 50-329 F 50-329 F	COUNSIL, W G COUNSIL, W G COUNSIL, W G	8210050179 8210050374 8210060048 8210060048 8210060094	50-336 P 50-213 Q 50-245 P 50-245 P 50-245 P	CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P	8210180174 8210170303 8210170623 8210210458 8210220013	50-346 P 50 341 N 50 845 F 50-346 P 50 346 P
сайк у и саск у и саак.у и саак.у и саак.у и	8210130266* 8210190520 8210210294 8210260121 8210260195*	50-329 K 50-329 E 50-329 A 50-329 S 50-329 O	COUNSIL, W G	8210040074 8210040233 8210040233 8210040237 8210040237	50-245 P 50-245 Q 50-245 Q 50-336 P 50-336 P	CROUSE.R P CROW.W T CROW.W T CROW.W T	8210260260 8210040397* 8210210514 8210210593 8210220028*	90 345 # 70 371 70-(11) 70 35 70-1-37
1994 7 M 1994 7 M 1994 7 M 1994 9 M	8210280076 8210290163* 6210290228 8210290229* 8210290380*	50-329 6 50-329 0 50-329 A 50-329 A	COUNSIL, H G COUNSIL, H G	8210070356* 8210070356* 8210080105 8210130331 8210130331	50-245 0 50-245 0 50-423 A 50-213 P 50-213 P	CROW.W T CROW.W T CROW.W T CROW.W T CROWLEY.B R	8210270436+ 8210280421+ 8210270211 8210270792+ 8210010124+	70 1151 70 1957 70 123 70 2744 90-217 1
000/R J 000/E N 000/EY, M J 000/EY, M J 000/EY, M J	821019u750 8210050017 8210060017 8210060047 8210068074	50-329 Q REGGD 50-278 S 50-277 S 50-277 S	CONNEIL H 6 CONNEIL H 6 COUNEIL H 6	8210130331 8210130379 8210170555 8210170555 8210170663	50-213 P PR 50-423 S 50-423 S 50-213 P	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8109280484 × 82100100a3 82100400a2 82100400a7 8210040099	50 214 F 50 214 F 50 407 F FOIA
Г М. (ЗИОВО Г М. (ЗИОВО Г М. (ЗИОВО Г М. (З (ВО)	8210040083* 8210040177 8210040353 8210070177 8210130224	50-277 S 50-277 S 50-277 S 50-277 S 50-278 S	COUNTIL, W G COUNTIL, W G COUNTIL, W G	8210210340 8210210340 8210250290 8210250290 8210250329	50-423 S 50-423 S 50-423 S 50-423 S 50-423 S	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	821004013+ 82100402+1 82100402+5+ 8210090059 8210090045	50 24 F 50 244 F 50 244 F 50 497 F
COONEY, M U COONEY, M U COONEY, M U COONEY, M U COONEY, M U	8210150154 8210150179* 6210150400 8210230190 8210240112	50-277 5 50-277 5 50-277 5 50-277 5 50-277 5	d consirin e consirin e consirin e	8210250329 8210260194 8210260194 8210260414 8210260414	50-403 S 50-245 P 50-245 P 50-245 P 50-245 P	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	82100500/2 8210070010 8210070404 8210120296 8210130088	00 ±35 F 30 213 F 50 213 F 50 200 F
COONEY M J COOPER, J W COOPER, J W COOPER, J W LUDPER, W E	9210240329 9001020054* 8102280195* 8210180148* 9210080191	50-277 F FOIA FOIA FOIA 50~275 F	COUNSIL.W G COUNSIL.W G	8210260459 8210260459 8210260519 8210260519 8210270200	50-245 P 50-245 P 50-245 P 50-245 P 50-213 P	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8210130093 8210130205 8210130375 8210180059 8210180065	50 245 F 50 213 F 50-407 F 50-237 F 50-206 F
COOPER W E COOPER, W E COOPER, W E COOPER, W E COOPER, W E	8210080193* 8210080272 8210190583 8210190584 8210250147	50-275 f 50-275 f	P COWSIL.W 6 P COWSIL.C P COW.H T	8210270200 8210270200 8210060374 8210070275* 8210170244*	50-213 P 50-213 P 50-219 S 50-219 Q 50-261 S	CRUTCHFIELD, D GRUTCHFIELD, D GRUTCHFIELD, D GRUTCHFIELD, D CRUTCHFIELD, D	8210180070 8210180073* 8210180074 8210180077* 8210180082	50-205 A 50-205 P 50-244 I 50-244 A 50-244 P
COOPER.W E COOPER.W E COOPER.W E COOPER.W E	8210250197 8210250240 8210250291 8210280211 8210280277	50-275 f 50-275 j	R CBA.H T P COX.H T P COY.H T R CRAFT.C M P CRAIG.J	8210220247* 8210270078* 8210270339* 8207270240* 8210150247	50-261 8 50-261 8 50-261 8 FOIA 50-271 Q	CRUTCHFIELD, D GRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8210180087* 8210180094* 8210180110 8210180112 8210180149	59-244   50-244   50-244   50-244
CODPER, W E COPELAND, V G COPELAND, V G COPELAND, V G	8210290319 8210130448 8210130448 8210130457* 8210130457*	50-155 ( 50-155 ( 50-155 (	R CRAIO.J G CRAIO.J G CRANE.P A O CRANE.P A G CRANE.P A	8210150388 8210280143 8210010198 8210010404 8210010413*	50-315 Q 50-312 P 50-133 F 50-275 P 50-275 P	CRUTCHFIELD. D GRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D	8210180153# 8210180161# 8210180183 8210180187	50-244 # 50-244 # 50-244 # 50-403 # 50-29 #
COPPER.W E CORDARO.M CORDARO.M CORDARO.M C CORDARO.M C	8210250318 8210150204* 8210150250* 8210150223* 8210150257*	50-322 50-322 50-322	P GRANE, P A T GRANE, P A T GRANE, P A T GRANE, P A T GRANE, P A T GRANE, P A	8210050122 8210050144 8210120278 8210130272 8210150151	50-275 P 50-275 P 50-275 P 50-275 P 50-275 R	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8210170680 8210200015 8210200016 8210200025 8210200031	50-237 # 50-409 # 50-409 # 50-409 #
CORDARD, H C CORE, H R CORLEY, W G CORLEY, W G CORMIER, W H	8210150290* 8210090303* 8210260527 8210260527 8210260527	50-285 50-327 50-327	T CRANE, P A S CRANE, P A T CRANE, P A T CRANE, P A G CRANE, P A	8210150389 8210210044* 8210220371 8210220395 8210250192	50-275 F 50-275 F 50-275 P PR 50-133 R	CRUTCHFIELD, B CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D, CRUTCHFIELD, D	8210200038 8210200041 8210200040 8210200070 8210210224	50-109 # 50-155 # 50-219 # 50-219 # 50-213 #

яснтиц	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR	ACCESSION NUMBER	SUBJE( CATEG			ACCESSION	SUBJEC	: <b>T</b>
OTCHFIELD. D HOTCHFIELD. D HOTCHFIELD. D HOTCHFIELD. D	8210210246 8210210336 8210210545 8210210552* 8210210555*	50-29	P Q P P	CUTCHIN, J M D'ANGELO, A J DAHLMAN, L C DALE, L F DALE, L F	8210290100 8210190678* 8210130566* 8210010023 8210040053	50-287 50-397 50-396 50-416 50-416	0 0 0 0 F	AUTHOR  DANESE, F L	NUMBER 8210050471* 8210270427* 8210270427* 8210270437* 8210270438*	FOIA 70-1510 70-1510 70-1510	IRY
OTCHFIELD: D OTCHFIELD: D OTCHFIELD: D OTCHFIELD: D	8210220105 8210220233 8210220272 6210220368 8210220449	50-244 50-155 50-409 50-155 50-409	P 0 P P	DALE.L.F DALE.L.F DALE.L.F DALE.L.F DALE.L.F	8210040264 8210040353 8210060295 8210070044* 8210150013	50-416 50-416 50-416 50-416 50-416	Р Р Р С	DANIELSON.D H DAVIDSON.D R DAVIDSON.D R DAVIDSON.D R DAVIDSON.D R	82100403084 8210040144 8210050132 8210130173 8210130179	50-440 50-440 50-440 50-440 50-440	0 K S E A
UTCHFIELD. D UTCHFIELD. D UTCHFIELD. D UTCHFIELD. D	6210250071 8210250124 8210250203 8210250213 8210250310	50-245 50-237 50-155 50-155	P P P	DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	8210190496 8210190521 8210190566 8210200005 8210200030	50-416 50-416 50-416 50-416 50-416	E E E E	DAVIDSON, D R DAVIDSON, D R DAVIDSON, D R DAVIDSON, D R DAVIDSON, D R	8210130344 8210150233 8210170326 8210170313 8210170463	50-440 50-440 50-440 50-440 50-440	8 A E
JTCHFIELD, D JTCHFIELD, D JTCHFIELD, D JTCHFIELD, D JTCHFIELD, D	8210250323 8210250327* 8210250337* 8210250363 8210260182	50-155 50-155 50-155 50-213 50-219	ь ь ь	DALE.L F DALE.L F DALE.L F DALE.L F DALE.L F	8210200064 8210200073 8210210217 8210220334 8210220425	50-416 50-416 50-416 PR 50-4[6	E 6 6 6	DAVIDEDN.D R DAVIDEDN.D R DAVIDEDN.D R DAVIDEDN.D R DAVIDEDN.D R	8210210079 8210220339 8210220372 8210240009 82102400011*	50~440 PR PR 70~2968 70~2968	A
, TL PFIELD, D , TC PFIELD, D , TC PFIELD, D , TC PFIELD, D , TC PFIELD, D	8210260185* 8210260191* 821026029 8210260296 8210270004	50-219 50-206 50-237 50-219	Р Р Р	DALE,L F DALE,L F DALE,L F DALE,L F DALE,L F	8210260264 8210260412 8210270277 8210280132 8210280135	50-416 50-416 50-416 50-416 50-416	P P G P	DAVIDSON, D R DAVIDSON, D R DAVIDSON, D R DAVIS, C E DAVIS, F C	8210260337* 8210260419 9210260575* 8210210037 8210180066*	50-440 50-440 50-440 NUREG FUIA	t V O
TCHFIELD.D TCHFIELD.D TCHFIELD.D TCHFIELD.D TCHFIELD.D	8210270202 8210270265 8210270270 8210280287 8210280433	50-219 50-155 50-155 50-409 TOPREP	P P P	DALE, L. F. DALENO, P. M. DALING, P. M. DALTON, C. DALTROFF, S.	8210290102 8210120092 8210120102 8210220357* 8207090208*	50-416 NUREG NUREG 50-387 50-278	л Н Р	DAVIS, J O DAVIS, J O DAVIS, J O DAVIS, L S	8210070070* 8210070071* 8210120135 8210120187 8207110026	50-537 50-537 27-47 40-2061 FULA	A
TOMFIELD, D TOMFIELD, D TOMFIELD, D TOMFIELD, D HINGHAM Q E	9210290169 8210290175* 9210290183* 9210290316 8210150348	50-206 50-206 50-206 71-5926	b b	DALTROFF,S L DALTROFF,S L DALTROFF,S L DALTROFF,S L DALTROFF,S L	8210130296* 8210150049 8210210297 8210210330 8210280196	50-277 50-277 50-277 50-277 50-277	0 0 P P	DAVIS.H J DAVIS.P R DAVIS.P R DAVIS.P R DAVIS.P R	8210010245* 8207180080 8207180080 8207180085 8207180085	50-352 ACRS ACRS ACRS	0
ILINGHAM, O E VINGHAM, R E VINGHAM, R E VINGHAM, R E	8210250110 8210270037 8210050034* 8210070073* 8210070179*	50-70 71-5739 REGGD 50-537 50-537	P A A	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8106220165* 8210010088* 8210010106 8210010113 8210010117	50-261 50-335 50-413 50-321 50-269	P Q Q Q	DAVIS.R DAVIS.S H DAVIS.S H DAVIS.S H DAVIS.S H	8210220316 8210170276* 8210270280* 8210280200*	PR 50-317 50-317 50-310 50-317	9 9 6 9
INCHARL R E INCHARL R E IAN D IAN D IAN D	8210070182* 6210280434 8208270074 8210200026 8210200026	50-537 40-2061 50-322 50-443 50-443	A G G	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8210010142 8210010155 8210010158 8210010162 8210010204	50-335 50-335 50-269 50-424 50-348	0 0 0 0	DAVIS, W DAYAL, R DE AGAZIO, A W DE AGAZIO, A W DEAN, W	8210210034 8210120367 821012035 8210290378 8210290378	50-259 RES 50-344 50-344	14 6 6
AM D AM D AM D AM D AM O AM O	8210200035* 6210200035* 8210200042* 8210200042* 8210200047*	50-443 50-443 50-443 50-443 50-443	0	DANCE.H C DANCE.H C DANCE.H C DANCE.H C DANCE.H C	8210010213 8210010221 8210010235 8210010245* 8210010300	50-389 50-336 50-321 50-280 50-338	0 0 0 0	DEARIEN, J A DEBBAGE, A G DEBBAGE, A G DEGROOT, D M	8210290017 8210010143# 8210150315# 8210220145* 8210010190	RES 90-413 50-390	0 0
18' W M 18' W M 18' W M EA' W	8210200049* 8210260091* 8210010268 8210010417 8210040052	50-443 WASTE MG 50-388 50-387 50-387	9 8 F E	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8210010301 8210010309 8210010316 8210010380 8210010424	50-389 50-321 50-250 50-404 50-369	0 0 0 0	DELGEORGE, L O DELGEGRGE, L O DELGEGRGE, L O DELGEGRGE, L O DELGEORGE, L	8210040246# 8210050056# 8210050073 8210050123 8210040268#	50~456 50~373 50~456 50~454	0 0 A A
18' N N 18' N N 18' N N 18' N N	8210050325 8210050370 8210060179 8210080083 8210130122	50-387 50-387 50-387 50-387 50-387	Р Р Р	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8210010451 8210010466 8210010467 8210080227 8210150014	50-369 50-395 50-395 50-321 50-369	0 0 0 0	DELGEGRGE.L G DELGEGRGE.L G DELGEGRGE.L G DELGEGRGE.L G DELGEGRGE.L G	8210130370 8210130402 8210220383 82102603084 8210280125+	50-454 PR PR 50-454	F
15. N W 16. N W 18. N W 18. N W	0210130341 8210170277 8210210020 8210210137 8210220102	50-387 50-387 50-387 50-387 50-387	2 2 3 5 5	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8210150053 8210150078* 8210150076 8210150076	50-370 50-348 50-348 50-424 50-369	0 0 0 0	DELGEORGE, L. O DELICHATSIGG, M DELICHATSIGS, M DELLA RATTA, A DELLA RATTA, A	8210270245 8210050428 8210150574 8210060370* 8210210238*	PR NUREG NUREG 70-1100	Q.
8. M W 8. M W 8. M W 8. M W 8. M W	8210220175 8210220366 8210250256 8210250264* 8210250367	50-387 PR 50-387 50-387 50-387	9 9 9	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8210150131 8210150187 8210150253 8210150262 8210150345	50-269 50-338 50-269 50-389 50-335	0 0 0 0	DELLSY, H M DELGNG, S R DEN (SON, E DEN (SON, E DEN (SON, E	8210010381 8210270251 8210080078 8210080080* 8210250221	PR RECCD 50-275 50-275	k h
9. N H 8. N H 8. N H 8. N H 9. N H	8210250373* 8210240270* 8210240364 8210240379* 8210270318	50-387 50-387 50-387 50-387 50-387	Р О Р Р	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8210190683 8210220158 8210220204 8210220211* 8210220229	50-257 50-424 50-424 50-424 50-348	5 G G G	Denison, e Denison, e Denning, r Denning, r Denniston, s F	8210270184 8210270188* 8109240007* 8201130322* 8210210444*	50-275	P P
IKJ K IKJ K IKJ K IKJ K	8210050069 8210060321* 8210150175 8210150275	50-440 50-440 50-440 50-440 50-440	0 0 0	DANCE.H C DANCE.H C DANCE.H C DANCE.H C DANCE.H C	8210220280 821022029!* 8210220331 8210220454	50-335 50-335 50-370 50-280 50-338	Q Q Q Q	DENNISTON, 8 F DENNISTON, 8 F DENTE, T J DENTON, H R DENTON, H R	8210270221x 6210270223x 8210250181 8107010140x 8210010147	CONTRACT CONTRACT TOPREP 50-261	P P
a. 3 k k. 3 k ge 3 k ge 3 k	8210190475 8210250365 8210260383 8210260395 8210260346	50-440 50-440 50-440 50-440 50-440	0000	DANCE, H C DANEBE, F L. DANEBE, F L DANEBE, F L. DANEBE, F. L	82102R0467 8201060245* 8210050439* 8210050446* 8210050467*	50-413 FOIA FOIA 70-1510 FOIA	Q	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8210010161* 8210050030* 8210060473 8210080350 8210120049		9 P

PENTI N	ASUESSIO 4 NUMBER	SUBJE		AUTHOR	ACCESSION NUMBER	SUBJE	ORY	AUTHOR	ACCE 49 ICH NUNDE R	ն "1 Га
SÉ ATO A HI R	821016-083	50-244	Р	DIETZ. C R	8210010298	50~324	5			- '
TEATLE H R	0210190092	REVIEW		DIETZ, C R	8210010399	* 50-324	a	DI YOM O W	8210100156	51.4
อสุนที่ถึงหล	8210190118	REVIEW	GRP	DIETZ, C R	8210010473	50-324	5	DIXONO H	6510130327	: 1
LENTE I H R	6210270075	50-251	5	DIETZ.C R	8210060320	50-324	ទ	DIXON O N	0210190505	
EENTC / H R	8210270331	ORG		DIETZ, C R	8510080181	50-325	9	DIKON'O M	E21019051.j	\$2.5
								D1 (ON¹ □ M	8210190557	2.7
EENTOU H &	82:02900614			DIETZ.C R	8210080220	50-325	5			
CF TCIHP	8210290449	50-275	G	DIETZ, C R	8210080221	50-324	s	DIKON, D N	8510550 140	<b>\$</b> ~5₁
DEMTON H R	B210270451		G	DIETZ.C R	8210130477	50-325	8	M O'NDXIG	6510770143	FP
LEVICK H B	82102904544	50-275	G	DIETZ, C R	8210130489	50-325	5	DIXON O M	0210320470	217
Emuster R W	0210260592 <b>+</b>	50-201	G	DIETZ. C R	821015001 <b>6</b> *	50-324	G.	DIXON, O M	8210350110	: 3
								H O'NDAIG	0210260140	\$ 5 mg
CEVINCENTIS J	0210010465	50-443	Ą	DIETZ, C R	8210150023*		G	Divan a o		
CEVINJENTIS J	8216016445	50-443	Ą	DIETZ, C R	8210150038#		G	DIYON, O W	8310700134	• •
CEVINCENTIS J	8210040112 8210040112	50-443 50-443	Ą	DIETZ, C R	8210150041	50-324	5	DIXON, O W	8210260172	4,54
ESUMMENTIS, J	6210040112	50-443	Ą	DIETZ, C R	8210150045#		Q	M G W100	D210JV0J45	PA
110 (11.511)13/3	6210040143	50-443	A	DIETZ.C R	8210150106#	50-324	G	DIXON, O W	0510590571	PR
DEMINICENTIS U	B210040193	50-443	A	DIETZ, C R	8210150291	50-324		DE CONTO W	02102902414	1131,
DEVINCENTIS J	8210050199	50-443	Ä	DIETZ, C R	B210150295*	50-324	5	DEKONLO W	0111 / 1/04 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
DEVINCENTIS J	8210050199	50-443	Ä	DIETZ, C R	8210190666	50-325	Q.	DODDS, R	0210270115	35 3
DEVINCENTIS, J	8210070105	50-443	Ä	DIETZ, C R	8210190748	50-323	5 S	DODDS, R T	0210190569	3
CEMINCENTIS J	8210070105	50-443	Ä	DIETZ, C R	8210190754	50-324	8 8	DODDS, R T	6210060157* 6210060157*	52.51
			,,		0210170734	00-324	8	DODDS, R T	02101707A&	20 23 50 23
DEVINCENTIS >	6210130436	50-443	A	DIETZ, C R	B210220492*	50-324	0		THE POLICE THE	7
DEVINCENTIS U	8210130436	50-443	A	DIETZ, C R	8210260254	50-325	8	DODDS, R T	B210190556*	** 34
DEVINCENTIS D	8210150510	50-443	Α	DIETZ, C R	8210260269	50-321	5	DODDB, R T	8210193570	2 - 3
DEMINUENTIS J	82101505(0	50-443	Α	DIETZ, C R	8210260294	50-325	g	DODDS, R T	0210190733	30.30
CEVINCENTIE J	8210180001	50-443	A	DIETZ, C R	8210260344	50-325	8	DODDS, R T	0210190741	
FELGA CENTAGE .						0.0 0.00	.,	DOERFLEIN, L. T	8210210115.	50 04 ; 50 3
DEVINGENTIS U DEVINGENTIS, U	BZ10180001	50-443	A	DIETZ, C R	8210290079	50~324	6			
DEVINCENTIS. J	8210190126	50-443	S	DIETZ, C R	8210290243	50-324	6	DOMER, J A	8210190105	21.1
CEVINCENTIS, J	8210190126	50-443	5	DIETZ, C R	8210290325	50-325	6	DOOLITILE, E. L.	02101200 11	50 41
CEVINCENTIS J	8210190136 8210190136	50~443	S	DIETZ, C R	8210290336	50-324	ŝ	DOOLITTLE, E L	0210210021	5 7 54
	0510140139	50-443	5	DIETZ, C R	8210270346	50-325	6	DOROGHON, J	8210090176	27.71
DEVINCENTIS, J	8210190363	50-443	8					DORSEY, J A	02100/0194	9 15
DEVINCENTIS J	8210190363	50-443	S	DIFFERENT, P M	8210060203*	50-416	B			1
DEVINCENTIS J	8210260149	50-443	S	DIFFERENT,P M DIFFERENT,P M	8510080145*	50-416	8	DORSEY, J A	0210070199	1 - 1
CEVINCENTIS, J	9210260149	50-443	5	DIGGS, R	#P210190424#	50~416	8	DOUGAN, J R	821019096Y	1, 5, 5
DEVINCENTIS J	8210240330	50-443	s	DIGGS, R M	8210130010	50-440	A	DOVOHERTY, J B	8210260748	1. 4
			_	51465H, H	8210040049	50-346	P	DOUGHERTY, J II	0510540425	4
DEVINCENTIS J	6510590330	50-443	s	DIOGS,R M	8210050589		_	DRAKE, J H	0210290QA)	\$ 1×14}
CEVINCENTIS, J	8210280119	50~443	A	DIGGS, R M	0210070033	50-250	P	DRAPER, D M	****	1
PEVINCENTIS. J EEVINE J B	8510580115	50-443	Α	DIGOS, R M	8210130050	50-266 50-331	Q.	DUBRY, N E	02100400/5=	5, 11
CEVINE, J B	6210040403	XPORTL I C		DIGGS, R M	8210270298	20-331	P	DVDALE	8510500171*	
erine, o b	8210080119	XFORTLIC		DIGNAN, T O	8210130314	50-200	P	DUDA, L E	8210150045	A
CEMINE, J B	6210080126	VEGOW				30-304	Q	DUFFY, O	0210120102 0210240441•	61 + 13 80 <sup>11</sup> 1
DEVINE, T	8210040375+	XPORTLIC	_	DIGNAN, T G	8210130314	50-309	Q		ORTORGUNATE	5. 1
CEVINE, T	8210150457*	50-373 50-358	Q.	DIIANNI, D C	8210120589	20-565	ř	DUNEAP, J H	6210060049+	90.00
CEVINE, T	8210150457*	50-35B	Q.	DIMASCIO, N J	B210150188*	50-322	r r	DUNLAP, J M	0210290207*	
CEVINE, T	8210210391	50-35g	G G	DIMASCID, N J	8210150240*	50-322	÷	DUNLOP, P	8210140445	13.31
		30-338	G.	DIMASCIO, N J	0210150290*	90-322	ŕ	DUINE, L. A	0210210041	3333
CEVINE, T	8210210371	50~35B	Q	Blocks			•	DUROIN, W W	6210130207+	
DEVINE, T	8210210400#	50-358	ŏ	DIRCKS, W J Dircks, W J	8110220004*	FOIA			W-14 10 DE 177 1	
DEVINE, T	8210210400*	50-358	ŏ	DIRCKS, W J	8201150180#	50~206	8	DURR, J P	8210060215+	10 10
DEMANDEL, E P	8210210053*	50~280	Ë	DIRCKS, W J	B201270037*	FOIA		DURR, J P	0210070400+	15 111
DENEY, L S	6210120271	50-522	G	DIRCKS, H J	8203110374+	FOIA		DURR, J P	05105100071	3 . 112
DEWEY, L S			-	TOTAL NATIONAL DE	8204200390*	FOIA		DURR, J. P.	0210210264	
DEWEY, L S	8210120288	50-522	G	DIRCKS, W J	930400000			DURR. J P	8510550500+	22.01
DENEY L B	8210150247	50~528	G	DIRCKS, W J	8204300078* 8205040550*	FOIA		DITTOL 0		
DEYGUNG, R C	8208190238 8208190238	50-522	o	DIRCKS, W J	8205270507#	FOIA		DUTTON, D	0210070140	20 4.4 1
ē	6508140538	50-3	Q	DIRCKS, W J	8205280495	FOIA		DUTTON, D	0210150362	\$2.44
				DIRCKS, W J	B206180042*	SECY		DUTTON, D.E.	8210270246	20 4.4 1
						FOIA		DYNEB, R R DYNEB, R R	02101502271	52 %;
								MINERIA W	82101502233	F 55

# LINGUIME MUTHOR HINDEY

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	, 
EDLOW, J EDWARDS, D L EDWARDS, D W EDWARDS, D W ETCHERHOLZ, H	8210210543* 8210240079 8210220372 8210220372 8210290243 8210150017*	70-2955 40-3453 PR PR 50-293		EVANS,L J EVANS,L J EVERETT,R J EVERETT,R J EVERETT,R J	B210070058* B210070064* B210070394* B210220128* B210220171*	50-537 50-537 40~6622 40-1162 40-2259	D D	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8210180028 8210190013 8210190019 8210190020 8210190035	50-321 50-322	P F A C Q
EICHLER, T V EINZIMGER, R E EISENHUT, D G EISENHUT, D G EISENHUT, D G	8210150557 8210150550 8007010658 8007070448 8103170719#	50-247	p p	FABRIZIO,R F FABRIZIO,R F FALCONER, D FALCONER, D FARDIS, M N	8207160064 8210160039 8210010166* 8210010474* 8210050428	F01A 50-318 50-269 50-269 Nureg	a a a	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8210190036 8210190042 8210190066 8210190047 8210190079	50-315 50-321 50-348 FOIA FOIA	F F
EISEMHUT, D C EISEMHUT, D C EISEMHUT, D C EISEMHUT, D C	8111300367* 8204290048* 8206070106* 8208250412* 8210010212	50-270 50-245 FOIA	9 A <del>S</del> P	FARDIS, M N FASANO, A FASANO, A FAN, R E FAY, C U	8210150574 8210150071* 8210150232* 8210150365 8107270156	NUREO 50-287 50-287 50-188 50-266	ช ช ส ช	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8210190074 8210190097 8210190112 8210190144 8210190158	FOIA 50-367 FOIA FOIA 50-397	f F
EIGENRUT, D G EIGENRUT, D G EIGENRUT, D G EIGERRUT, D G EIGENRUT, D G	8210010215* 8210050495* 8210060433* 8210070217* 8210070235*	50-289 50-272	P F P	FAYIC W FAYIC W FAYIC W FAYIC W FAYIC W	8210040119 8210050005 8210050054 8210050222 8210050256	50-246 50-266 50-266 50-266 50-266	F P F P Q	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	F310910158 9710910158 9810910158 9810910199 9810910158	50-219 50-250 FG1A 50-440 50-275	н г г
EISENHUT, D 0 EISENHUT, D 0 EISENHUT, D 0 EISENHUT, D 0	8210120505 8210120590* 8210130024 8210130029* 8210150519	50-278 50-416 50-416	F P P P	FAY, C W FAY, C W FAY, C W FAY, C W FAY, C W	8210050272 8210060325 8210060333* 8210130586 8210150150	50-245 50-301 50-301 PR 50-265	f S S R	Felton. J M Felton. J M Felton. J M Felton. J M	8210210050 8210210071 8210210073 8210210544 8210260008	50-240 FOTA 50-267 50-317 50-302	F F I
TISENHUT.D G TISENHUT.D G TISENHUT.D G TISENHUT.D G	8210250148 8210260521* 8210260532 8210260021* 8210260423	50-272 50-382 50-324	P F A P F	FAY.C W FAY.C W FAY.C W FAY.C W FAY.C W	8210150158× 6210150430 6210150471 6210160047 6210190264	50-266 50-266 50-266 50-266 50-266	R P F Q P	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	6210240122 6210260572 6210270083 6210270132 6210270256	50-314 50-440 50-251 50-369 50-266	F S F
ISENHUT.D G ISENHUT.D G ISENHUT.F T L-ZEFTAHY.M L-ZEFTAHY.M	8210280425* 8210270203 8210040122* 8207120140* 8210050155*	50-286 50-387	r o s P	FAY, C W FAY, C W FAY, C W FAY, C W FAY, C W	8210190519 8210250258 8210250242* 8210250344 8210250352*	50~266 50~266 50~266 50~266 50~266	P 5 5 8 8	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8210270429 8210270426 8210280013 8210280016 8210280033	70-1510 50-271 50-261 50-369 50-322	F P T
L-ZEFTAWY, M LASSER, T C LORED, D T LORED, D T LIN. J O	8210040427* 8210210174* 8210250277* 8210280078* 8210170478*	F01A 50-245 50-346 50-346 50-397	9 8 9	FAY.C N FAY.C U FAY.C W FAY.C N FEHRINGER.D J	B210260476 B210270259* B210280295 B210280294 B210120355	50-266 50-266 50-266 50-266 Waste M	Р F Р Р	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	0210260045 0210260056 6210260106 6210260117 6210260134	50 409 50-255 50-313 50-275 50-271	F F F
LL1S.J LLIS.J LLIS.T S LLIS.T S	8210150224 8210250104 8210260355 8210200003 8210200003	50-445 50-445 50-445 50-322 50-322	G G O	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8210060088 8210120090 8209150434 8209210425 8209290125	50-334 FOIA 50-247 50-251 50-10	R F F	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8210280140 8210280361 8210280378 8210280389 8210280394	50-3 50-254 50-315 50-149 FOIA	i t i
EROD, 8 A LEASSER, T LEASSER, T LEASSER, T LSASSER, T C	8210220303* 8210190017* 8210210241* 8210220521 8210270174*	50-335 50-373 50-423 50-273 50-213	0 0 0	FELTON. J M FELTON. J M FELTON. J M FELTON. J M FELTON. J M	8209290148 8210010008 8210040020 8210040343 8210040340	FDIA 50-311 50-445 50-537 FOIA	Р С А	FELTON.J M FELTON.J M FELTON.J M FELTON.J M FELTON.J M	8210280399 8210280402 8210280419 8210280442 8210290020	50-315 FOIA 50-275 50-275 FOIA	r F
MMERT, R M MGEL, R E MGELKEN, R H MGELKEN, R H MGELKEN, R H	8207070324* 8207090224* 8210010267 8210250392* 8210290048*	70-2748 50-278 50-342 50-275 50-142	P Q P G	Felton, J M Felton, J M Felton, J M Felton, J M Felton, J M	8210050013 8210050430 8210050512 8210050559 8210050562	50-309 70-1510 50-483 50-333 FOIA	F 8 F	FELTON, J M FELTON, J M FELTON, J M FENSTERMACHER FERNANDEZ, W	8210290023 8210290047 8210290085 8009250234 8210190077*	50-142 50-10 FOIA 50-247 50-233	F F F F
MOLERL R MOLERT, B R MIHIBLE, E B MILINNA, R B	8210290414 8210280272 8210150200 8210150200 8210010284*	50-338 RES 50-170 50-170 50-329	Р Н Е	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8210050582 8210060404 8210060419 8210060423 8210060426	50-322 FOIA FOIA 50-358 50-537	C H A	FERREIRA, 6 P FERRELL, C FERRELL, C FERTNER, K FICOLER, P D	8210060257# 821006045[# 8210060455# 8210060477# 8210010077	TOPREP 50-537 50-537 50-213 50-219	ሉ ሉ ቦ
RIKSON, K T RIKSON, K T RIKSON, K T RIKSON, K T RIKST, M L	8210260232 8210260232 8210260239* 82102602374*	50-322 50-322 50-322 50-322 FOIA	T T T	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8210060429* 8210060434 8210060437 8210060442 8210070003	FD1A FD1A 50-149 50-537 50-346	H D F	FIEDLER, P D FIEDLER, P D FIEDLER, P D FIEDLER, P D FIEDLER, P D	8210070178 8210070238 8210130167 8210130357 8210130098	30-219 50-219 50-219 50-219 50-219	5 5 5 5
RNST, M & RNST, M & RNST, M & RNST, M & URY, L &	810306008B* 8108030041* 8112030565* 8201060003* 8210050007	FOIA FOIA FOIA FOIA 50-241	Р	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	#210070007 #210070027 #210070040 #210070411 #210070417	50-244 50-537 50-416 FOIA FOIA	P D F	FIEDLER, P D FIEDLER, P D FIEDLER, P D FIEDLER, P D FIEDLER, P D	8210190398* 8210190704 8210220187* 8210250092 8210250136	50-219 50-219 50-219 50-219 50-219	0 P 0 P
384°F M 184°F M 184°F M 184°F M	8210050342 8210060013 8210190709 8210260244 8210260323	50-324 50-241 50-241 50-324 50-324	Р Р Р Р	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8210080015 8210080020 8210080029 8210080036 8210080129	50-281 FDIA 50-245 50-249 50-315	P	FIEDLER, P D FIEDLER, P D FIEDLER, P D FIELDS, C FIELDS, C	82 0250 87 82 0250285 82 0250254 82 0220443* 82 0290286*	50-219 50-219 50-219 50-395 50-395	р О Р S
JRY, L H JRY, L H JRY, L H JANS, C A JANS, C D	8210260405 8210260475 8210260508 8210010176* 8210010118*	50-324 50-261 50-261 50-313 50-321	р Р Р	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	6210120015 6210120103 6210120392 6210120545 6210120643	FOIA 50-3 50-331 50-231 50-241	F	FIELDS.C FIELDS.J A FIELDB.W W FINAMORE.D FINAMORE.D A	8210290338* 8210190102 8210190720* 8210220288* 8210060195	CONTRAC 50-261	т Р О
/ANS, C, D /ANS, C D /ANS, C D /ANS, L J /ANS, L J	8210150217* 8210150237* 8210150263* 8210070037* 8210070056*	50~249 50~537	G D D	FELTON, J M FELTON, J M. FELTON, J M FELTON, J M FELTON, J M	6210130004 6210130105 6210150594 6210150621 6210160014	50-315 50-244	}	FINAMORE B A FINAMORE B A FINAMORE B A FINAMORE B A FINAMORE B A	8210210232 82102102327 8210130246 8210130232	50-537 50-537 50-537 50-537	0000

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FINAMORE, B A FINAMORE, B A FINAMORE, B A FINAMORE, B A FINAMORE B A	8210210232 8210210357 8210210357 8210210453 8210210453	50-537 0 50-537 0 50-537 0 50-537 0 50-537 0	Frahm, R Frahm, R Frahm, R Frahm, R Frahm, R	8210130358* 8210150065* 8210150093* 8210150118* 8210150140*	50-311 S 50-311 S 50-311 S 50-311 S 50-311 S	GARCIA, P J GARCIA, P J GARCIA, P J GARCIA, R GARDNER, R	8210210021 8210210525* 8210220475 8210040255 8210040337	40-3453 40-3453 40-1162 10PREP 50-329 S
FINAMORE, B A FINAMORE, B A FINAMORE, B A FINAMORE, B A FINAMORE, B A	8210220268 8210220286* 8210220295* 8210260397 8210260397	50-537 G 50-537 G 50-537 G 50-537 G 50-537 G	Frahm, R Frahm, R Frahm, R Frahm, R Frahm, R	8210150320* 8210150339* 8210210144* 8210250057* 8210250389*	50-311	GARDNER,R N GARDNER,R N GARNER,L GARNER,L W GARNER,L W	9210050154* 8210190750* 8210010206* 8210010205* 8210010415*	50-329 Q 50-329 Q 50-325 Q 50-324 Q 50-324 Q
FIMAMORE, B A FIMAMORE, B A FINCKE, J R FINDLEY, D E FINDLEY, D E	8210260404+ 8210260404+ 8210280339 8210120357+ 8210170037+	50-537 G 50-537 G RES CONTRACT CONTRACT	Frahm, R Frahm, R Frahm, R Frahm, R Frahm, R	8210280128* 8210280154* 8210290218* 8210290314* 8210290361*	50-311	GARNER, L W GARNER, L W GARTITY, J H GARRITY, J H GARRITY, J H	8210220173* 8210220503* 8210010230 8210040074 8210040077	50-324 Q 50-324 Q PR 50-309 P 50-309 P
FINALL A E FINLATION, F C FINLET, N C FIORAVANTE, H FIORE, R A	8210210097* 8210260246* 8210290399 8210120139* 8210260352*	50-354 0 50-322 T RES 50-317 F 40-8610	FRALEY, R F FRANCIS, E FRANCIS, E FRANFLIN, L FRANTZ, S P	8006300104* 8210130607 8210270054 8210010116 8210200058	FOIA 40-299 40-2259 70-633 50-522 G	QARRITY, J H GARRITY, J H GARRITY, J H GARRITY, J H GARRITY, J H	8210040217 8210060302 8210150398 8210220203 8210220212	50-309 P 50-309 Q 50-309 P 50-309 P
ilore.r a Fibreili.o Fisch.c Fischer.l Fish.r l	8210260352* 8210040345* 8210270158 8210150500* 8210150550	40-8610 50-528 0 XPORTLIC 50-263 P NUREG	Frantz, S. P. Fredland, D. R. Fredrickson, P. Fredrickson, P. Freedberg, L.	8210200058 8208290105 8210010350* 8210150254* 8208290089	50-522 G FOIA 50-324 G 50-327 G FOIA	GARRITY, J H GARRITY, J H GARRITY, J H GARRITY, J H GARRITY, J H	8210250078 8210260144 8210260327 8210260420 8210270008	50-309 P 50-309 G 50-309 E 50-309 P 50-309 G
FISHER, C R FISHER, C R FISHER, L FITZPATRICK, B FLACK, E	8210290141 8210290234 82101505094 8210040145* 8210070336	TOPREP PR 50-263 P 50-247 S 50-461 0	FRENCH, L D FRENCH, L D FRIEDMAN, K A FRIEDMAN, P FRIEND, H B	8210(30531* 8210260167* 8210(20293* 8210(50272* 0210(90470	50-29 S 50-29 S QA979 50-322 T 50-275 P	GARRITY, J H GARRITY, J H GARY, R J GARY, R J GARY, R J	8210260087 8210280161 8210290343 8210040318 8210130576	50-309 F 50-309 P 50-209 S 50-445 S 50-445 F
FLACK, E FI BENOR, C FLEEHOR, C FI BENOR, C FLEEHOR, C	8210280072 8210120454 8210120467 8210190180 8210270416	ILE CONTRACT CONTRACT 50-320 F CONTRACT	FRIEND, H B FRIEND, H B FRYE, J H FRYE, J H FUENTE, E 5	8210270351 8210270351 8210220343 8210250223 8210250223	50-275 P 50-275 P 50-70 G 50-142 G PR	GARY,R J GARY,R J GARY,R J GARY,R J GARY,R J	8210180004 8210220372 8210250338 8210250346 8210260375	50-445 P PR 50-445 S 50-445 S
FLEENGR, C M FLEEHOR, C M FLEEHOR, C M FLEEHOR, C M FLEEHOR, C M	8210120411 8210270411 8210270425 8210280299 8210280310	27-39 50-387 X 70-1113 CONTRACT CONTRACT	FUHRMAN, O R FULFORD, P J FULLER, C FULLER, C FULLWOOD, R R	8210190730 8210210306* 8210050337* 8210190543* 8210120092	50-317 S 50-329 A 50-267 S 50-267 S NUREG	GEE.O N GEFFEN.C A GEFFEN.C A GENADRY.M D GERDEMAN.F W	8210150553 8210120092 8210120102 8210050428 8210260019	Hureg Nureg Nureg Nureg 40-8648
FLEENOR,C H FLEENOR,C M FLEISHER,Z S FLEISHER,Z S FLEISHER,Z S	8210280327 8210280354 8210180203 8210200019 8210210390	CONTRACT CONTRACT 50-247 G 50-247 G 50-247 G	FULCHOODER R FURGALED T FULATOEE M GADER K GADER K	8210120104 8210180571 8210070355# 8210130314 8210130314	NUREG NUREG 50-43B A 50-307 G 50-309 G	GERETY, H F GERGELY, P GERNER, L F GERSTNER, W C GERSTNER, W C	8210150147 8210050412 0210280364* 8210190354 8210280050	50-289 J NUREQ 50-254 F 50-461 5 50-462 Q
HEIGHER, Z G HEMING, T E HEESENER, S A FLIPPO, T A FLORY, C A	8210210397# 821012053& 8209290225# 8210170349# 8210120554	50-247 G 40-0771 50-10 F 50-205 G WASTE MGT	GAD.R K GAD.R K GAD.R K GAD.R K GALLE.D P	8210270153 8210270153 8210270166 8210270166 8210270088*	50-443	GERTMAN, D I GERWIN, E F GIANELLI, J GIANELLI, J GIANELLI, J	8210120124 8210150474 8(12010310* 8210070416 82100800(8	RE9 50-528 G 50-034 S 50-024 S 50-036 S
FLGRY, C A FLORY, C A FLYNN, M FLYNN, M FLYNN, M	9210120604 8210120648 8210040410 8210120354 8210180327	40-8452 Waste Mot Contract Contract Contract	GALLO, J GALLO, J GALLO, J GALLO, J GALLO, J	8207180052 8207180052 8210010408 8210010408 8210010446	FDIA FDIA 50-155 G 50-155 G 50-185 G	GIBBONB, T S GIBBB, D C GIBBON, A GIBBON, A F GIBBON, A F	8210150207# 8209270379* 8210050224 8210010121 8210010162	50-438 3 COMMISSION 18E 70-1201 70-143
FLYNN, M FLYNN, M FLYNN, M FLYNN, M FLYNN, S F	8210180584 8210190018 8210190030 8210190005 8210130539	CONTRACT CONTRACT CONTRACT CONTRACT PR	GALLO, J GALLO, J GALLO, J GALLO, J GALLO, J	8210010446 8210050232 8210050232 8210050356 8210050356	50-155	01960N, A F 01980H, A F 01980N, A F 01960N, A F 01960N, A F	8210010313 8210010353 8210010364 8210010388 8210080179	70-143 70-27 70-143 70-124 70-143
FLYIN,S F FLYIN,S F FOGARTY,D J FOLEY,T FOLEY,T	8210150305 8210220285 8210080211* 8210070216* 8210210307*	50-400 G PR 50-204 Q 50-284 Q 50-247 Q	GALLO, J GALLO, J GALLO, J GALLO, J	8210040204 8210040204 8210120457* 8210120457* 8210150300	50-155	GIBSON, A F GIBSON, A F GIBSON, A F GIBSON, A F GIBSON, A F	8210150064 8210150130 8210150197 8210150215 8210150229	70-1113 70-824 70-143 70-1201 70-27
FOLSOM, R D FOLSOM, R D FONKER, R L FORD, E W FORD, E W	8210220074* 8210220077* 8210180103 8210130319* 8210130530*	40-8111 40-8111 70-143 50-302 5 50-302 8	GALLO, J GALLO, J GALLO, J GALLO, J	8210150300 8210150470 8210150470 8210180142 8210180142	50-155 G 50-155 G 50-155 G 50-454 G 50-484 O	GIBSON, A F GIBSON, A F GIBSON, A F GIBSON, A F GIBSON, A F	8210150361 8210150403 8210210174 8210210216 8210210341	70-143 70-143 50-13 Q 70-1201 70-27
FORTUNA,R A FOSTER,D O FOSTER,D O FOSTER,H FOSTER,J E	8210280047* 8210220078 8210220208* 8210010189 8210130557*	50-324 P 50-424 B 50-424 Q 70-1151 50-461 Q	GALLO, J GALLO, J GALLO, J GALLO, J	8210180206 8210180206 8210180242 8210180242 8210200027	50-155 0 50-155 0 50-155 0 50-155 G 50-155 G	GIBSON, A F GIESEKE, J A GIESEKER, J GIESEKER, J GIESLER. C W	8210220308 8210150592 8210210014 8210260118* 8210010179	70-1113 NUMEO NUMEO 50-373 \$ 50-305 P
FOSTER, K W FRAHM, R FRAHM, R FRAHM, R FRAHM, R	8210150547 8210070231* 8210070252* 8210070258* 8210070314*	NUREO 50-311 S 50-311 S 50-311 S 50-272 S	GALLO,J GALLO,R GALLO,R M GALLO,R M GALLO,R M	8210200029 8210070361* 8210070393* 8210150274* 8210290157*	50-155 Q 50-309 Q 50-271 Q 50-271 Q 50-29 Q	GIESLER.C W GIESLER.C W GIESLER.C W GIESLER.C W GIESLER.C W	8210010232 8210010307 8210040154 8210050263 8210060312	PR 50-305 8 50-305 Y 50-305 P
FRAHM, R FRAHM, R FRAHM, R FRAHM, R FRAHM, R	8210070377* 8210070398* 8210130170* 8210130227* 8210130345*	50-311 S 50-272 S 50-311 S 50-311 S 50-311 S	GALUNIC, B GAMMILL, W P GAMMILL, W P GARCIA, E M GARCIA, P J	8210050206* 8104290774* 8201120280* 8210190636* 8210120628	50-443 A 50-324 P 50-324 P 50-324 P 50-27 G 40-6659	GIESLER, C W GIESLER, C W GIESLER, C, W GIESLER, C, W GIESLER, C W	8210130581 8210130582 8210130582 8210130581	50-305 # 50-305 # PA 50-305 F 50-305 F

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGOR	Y	AUTHOR	ACCESSION NUMBER	SUDJECT CATEGOR		AUTHOR	ACCESSIDN NUMBER	SUBJECT CATEODRY
SIEELER, CH SIEELER, CH SIEELER, CH SIEELER, CH SIEELER, CH SIEELER, CH	8210170353 8210170487 8210260260 8210270234 8210270144*	50-305 50-305 50-305 PR 50-349	8 8 5	GRAY, E H GRAY, E H GRAY, J R GREED, J R GREEN, H J	8210210125* 8210210264* 8210220445 8210290137* 8209300170	50-354 50-220 50-289 50-409 50-259	0 0 0 0 5	GUIMN, P. R. GUIMN, P. R. GUIDEMOND, U. G. GULKAIJ, P.	8210180089* 8210180092* 8210180213* 8210250114* 8107270178*	FDIA FOIA FOIA 50-373 0 50-266 0
· (r 1/15K4, v · (r 1/15K4, v · (r 2 E b 1, r · (r 2 E	0210050399* 8210190776# 8210120654 0210220351 6210220363	50-450 50-445 RES 50-367 50-275	а н н	ORECHIH J ORECHIH J GRECHIH J GRECHIH J GRECHIH J	8210010108 9210060219 8210060265 8210060409 9210060414	50-327 50-327 50-276 50-259 50-259	ន <b>ខ</b> ន ន ន	GULKAN. P GULKAN. P GULKAN. P GUPPY, J G GUSTAVE, R	8107270182* 8107270185* 8107270194* 8210070449 8210080022*	50-246 Q 50-266 Q RES CONTRACT
TLLEINN T LITEN D H LITEN'D H LITEN'D H	B210270332* B210270373 B210040363 B210210534* B210260211	50-209 1 OCFR 40-0601 40 -0601 NUREQ	o	U H M31R0 U H M31R0 U H M 13R0 U H M 13R0 U H M11R0	8210130157 8210130165 8210130172 8210110317 8210130429	50-296 50-259 50-259 50-327 50-259	ម ទ ទ ទ	GUSTAVE,R GUSTAVE,R GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P	821 0240280 <b>4</b> 821 0240559 821 0050508 <b>4</b> 821 0050521 <b>4</b> 821 0050525	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
ALLILAND, J T INSBERO, T ATRAND, E H IFARD, E H C-ETTUM, P	8210190621 8210120649 8210010076# 8210150406# 8210120517#	90-424 REB 50-335 50-259 CONTRACT	B Q Q	ORLENTH O OBEENTH O OBEENTH O OBEENTH O OBEENTH O	8210130442 8210130565 8210130572 8210130572 8210190712	50-327 50-259 50-326 50-327 50-327	5 5 5 5	GUSTAVE, R P GUSTAVE, R P GUSTAVE, R P GUSTAVE, R P GUSTAVE, R P	8210050530 * 8210080007* 8210120330 * 8210120342* 8210120364*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
LEASON J P LEASON J P LEASON J P LEASON J P LOVER M 8	6210090254 6210150092 6210150141 6210200069 6210170106#	50-247 50-247 50-247 50-247 50-369	0 0 0	C H-M-1300 C H-M-1300 C H-M-1300 C H-M-1310	8210260212 8210220058 8210220058 8210260212	50-259 90-328 50-327 50-328 50-259	5 6 6 6 6 6 6	GUSTAVE, R P GUSTAVE, R P GUSTAVE, R P GUSTAVE, R P GUSTAVE, R P	8210120422# 8210120508# 8210130592# 8210150350# 8210160362#	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
ACYER, MIS CODARD, RIJ CODARD, RIJ CODARD, RIJ CODARD, RIJ	8210270144# 8210040081 8210040083# 8210150167 8210250301	50-369 50-155 50-155 90-155 50-155	F G G G	L HW13BD C HW13BD C HW13BD U HW3BB U HW3BB	8210260349 8210260381 8210260417 8210290054 8210290062	50~240 50~259 50~260 50~259 50~259	ន ទ ទ ទ ទ	GUSTAVE, R P GUSTAVE, R P GUSTAVE, R P GUSTAVE, R P GUSTAVE, R P	8210180419* 8210170004* 8210170087* 8210170141* 8210210046*	50-201 P CONTRACT CONTRACT CONTRACT CONTRACT
CSDARD,R J CSY, A T CSY, A T CSY, A T CSY, A T	8210280340 8210040049* 8210660370* 8210130449* 82102388	50 461 50-29 70-1100 XPORILIC 50-271	a a	C H 443 390 C H 443 390 C H 447 490 C H 447 490 C H 444 4300	821029021 8210290277 8210290317 8210290317	50-328 50-276 50 327 50-259 50 259	6 6 6 6	GUSTAVE, R P GUSTAVE, R P GUSTAVE, R P GUSTAVE, R P GUSTAVE, R P	8210210584 8210260284* 8210270033* 8210270395* 8210270402*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
001.A I CD1.A I GD1.A I GD1.A I GD1.A I	8210210321# 8210220172# 8210220179# 8210220244# 8210290107#	50 309 70 371 70 371 70 697 50 220	a a	GREI HOLATT, D GREENBLATT, D GREENBLATT, D GREENBLATT, D GREENE, Q. A	8210210308 8210210308 8210210419 8210210419 8210120649	50-400 50-400 50-400 50-400 REU	G G G	GUSTAVF,R P GUSTAVE,R P GUTTERREZ.J M GUTTERREZ.J M GUTTERREZ.J M	8210270407* 8210280397* 8210050241 8210080089 8210150134	CONTRACT CONTRACT 50~498 G 50-309 G 50-307 G
ODY, A T OLCEERO, J H OLCEERO, J H OLCEERO, J H OLCEERO, 8 C	8210270207# 8210200092 8210200075 8210270247 8210070176	50 087 50 498 50 498 50-498 50-498	0 A A H	GREENKORN, R. A GREENMAN, E. GREENMAN, E. O. ORLENMAN, E. O. OREENMAN, E. O.	B210120342* B210220255 B210060127* B2100703D6* B210070316*	€ 0NTRACT 50 -0J3 50~317 50~278 70 -764	G Q Q	GUTTERREZ.J M HAASS.M P HACKETT.D B HAFTZ.A HAGAN.T F	8210150460 8207210413* 8010070320* 8210150535* 8210040412*	50-309 Q 50-520 A 50-305 P 50-287 P CONTRACT
CLDSERQ. 8 C COLDSERG. 8 C CLDSERG. 8 C GLDSERG. 8 C COLDEN. V C	8210130095 8210150087 8210280347 8210280347 8210270105 8210260526	50 454 50 -454 50 -454 50 -454 50 -10	9 9 9 9	GRECHMAN, E O ORELIMAN, E O GREENMAN, E O OREGER, E R GREGER, E, R	0210070345* 0210210451* 0210270344* 0210050112* 0210050205*	50~219 50~272 50~322 50~295 50~266	0 0 0 0	HAGAN, T F HAGAN, T F HAGAN, T F HAGAN, T F	8210120357* 8210120419* 8210120423* 8210120458* 8210120471*	CONTRACT 27-39 50-369 M CONTRACT CONTRACT
OLL.ST OLLERKA OLLERKA OLLERKA OLLERKA	8210220149 8210050042* 8210070172* 8210070185* 8210070187*	NURLO REGOD 50~269 50~266 50~266	Ö P P	GREGERIL R GREGERIL R GREGGIR J GREGGIR J GREGGIR J	8210030 180* 8210130400* 8210280014 8210260108 8210260173	50-186 50-409 70-820 70-820 70-820	a a	HAGAN, T F HAGAN, T F HAGAN, T F HAGAN, T F HAGAN, T F	8210120550* 8210180332* 8210190025* 8210190037* 8210270413*	CONTRACT CONTRACT CONTRACT CONTRACT 50-307 X
OTIZALEZA ODDE: R ODDE: R ODDE: R W ODDE: R W	B210120640x B210210206x B210260515x B210210223x B210210342x	50-341 50-13 50-335 70-1201 70-27	A G	GREOGER J GREGORY, H B GRENIER, B L GREVE, F GRIDLEY, R L	0210270213 0210120428 8104080307* 8207140494* 8210080262	70 820 RES FOIA 90-373 TOPREP	C	HAGARL T F	8210270419×	
CCCHOPE.A C CODIE.J 8 CCCCHAILL CCCMAILL CCCMAILL 8	8210080075 8210260501 8210010226 8210010232 8210190454*	27-09 50-074 PR PR 50-109	o 8	ORIMLB. B K OROBE. J GROBE. J GROESCH. O L	8210010061* 8210060384* 8210260467 8210060393* 8210050366	FOIA 50-073 50-254 50-015 50-082	Q S Q			
ODOMANIL S ODOMINIE F OULD. J P PADAIK D RAESSERIK L	8210220304 8210220048* 8210260504 8210080168* 8210040114	PR NUREQ 50-029 50-034 50-004	t P	GROESCH, O.L. GROESCH, O.L. GROESHULBCH, B. GROSSMAN, H. GROSSMAN, H.	8210050372# 8210050376# 8210120613# 8210150217 8210250229	50~392 50~392 CONTRACT 50~395 50~395	0 0 0			
Jagsser, X i. Jagsser, K i. Pagsser, K i. Pagsser, K i. Pagsser, K i.	8210060262 8210150405 8210160167 8210190483 8210190689	50-304 50-295 50-304 50-295 50-295	8 8 8	QROTERHUIB, H QROTERHUIB, H QUADAONO, V QUCHA, L T QUCHA, L T	8210050546* 8210120621 8210270376* 8210050330 8210220287*	50-315 50-250 40-8824 50-321 50-321	<u>የ</u> የ			
FAESSERIK L PAESSERIK L RAESSERIK L RAMTIJ H RANTIJ H	021020219 02102020128 02102020128 02102020128 02102020119	50-304 50-275 50-275 50-424 50-424	8 8	QUCHA, L T QUCHA, L T QUCHA, L T QUILBERT, D E QUILBERT, D E	8210220290 8210220386 8210290273 8210120304* 8210120315*	50~366 PRM PR QA999 QA999				
DANT. W B DANES.C C RANES.R H DANES.R H DANES.R H	8210050380* 8210010351 8210150122 8210270245 8210280071	50-184 TOPREP 50-213 50-213 50-213	8 8 8	GUILD.R GUILD.R GUINN.P R GUINN.P R GUINN.P R	8210080081 8210080081 8103160338* 8103160366* 8104170703*	90-413 50-413 FOIA FOIA FOIA				

#### EUSCHAF ACTUON INDEV

AUTHOR	ACCESSION NUMBER	CATEGOR		AUTHOR	ACCESSION NUMBER	SUBJEC Y CATEGOR	Y	AUTHOR	ACCESSION NUMBER	SIIS E I
HALL.D P	8210280213	50-461	Α	HEIDER, L H	8210130353	50-29	Р	HIDALOD, P. A	0400000	
HALL, E E	8210120329*	WASTE MO	Т	HEIDER, L H	8210170484	50-29	ρ	HIETALA, J	8107270174	5U-1*5
HALLER,N M	8005270820*	FOIA		HEIDER, L H	8210220157*	50-29	G .	HIETALA, J	8210260297	50 JY
MAMAWI.J N	8210150290*	50-322	٢	HEIDER, L H	8210280094	50-29	P	HIGGINBOTHAM, L	8210240321*	50-37
HAMILTON J F	8510550317	PR		HEINZ, E L	8210270182*	40-8577		HILF, C L	8210120030± 8210250074±	F0[4 50~2*3
HAMILTON P P	8210050214	50-244	P	HEESHMAN, R F	B209290236*	FOIA		HILL, D	8210180338•	
HAMMER, S	9210190293*	50-263	S	HEESHMAN, R F	8209290240*	FOIA	_	HILL, D	8210180338	ርርጓሞት "
HANAUER, 8 H	9205280470*	FOIA		HEISHMAN, R F	8210050522*	50-483	5	HILL, K L	8210040376	CENTRA" 30 331
HANAUER, 5 H	9210070008+	FOIA		HEITKEKPER, E M	8210120496*	CONTRACT		HILL, K L	8210130137+	ונג, טק גער פפ
A L.NODDMAH	8210130310	50-302	8	HEITHER, K L	8210040423	50-309	P	HILL, K.	621013039B+	ונק ספ ניק ספ
HANCOCK, J A	8210130520	50-302	8	HEITNER, K L	8210070054	50-309	P	HILL.K L	82101305904	80.3%
HANCOCK, J A	8210220052 8210070452	50-302	S	HETTNER, K L	8210290160	50-309	P	HILL, K L	B5105205914	53.3
HANNETT B A		XPORTLIC		HE I TNER, K L	8210270165	50-309	Р	HILL, K L	8210250300	30-31
HANNETT, B A HANNETT, B A	8210080037 8210080040*	XPORTLIC XPORTLIC		HELFRICH R E	8210130433	PR COA		HILL, K L	8210250387	50 31
HINNETTID W	0% 1000004 0x	XFOR IL10		HELGESON, K A	8210200104	70-B20		HILL, OF	9210070256	30 317
HANNETT, B A	9210080042*	XPORTLIC		HELGESON, K. A	8210250012	70-820		HILL,U H		
A GITTENNAH	8210080108	XPORTLIC		HELGESON: K A	6210260038	70-820		HILLMAN, C R	8210190419	50 113
HANNETT, B A	8210080130	XPORTLIC		HELGESON, K A	8210270206	70-820		MIND, J A	B210150609•	70 174
HANNETT, IF A	8510080133	STATEMENT		HELGESON, K. A	8210270218	70-820		HIND, J A	8210040184	20 4.7
HANNETT, B A	8210270147	XPORTLIC		HELLER, J K	8210190449*	50-255	Q.	A LIGNIH	8210080201 8210190652	50-31 50 31
HANNETT, B A	8210270168	XPORTLIC		HELLER, R	8210010047*	50-311	5	HIND, J A		
HANNETT, B A	6210260052	XPORTLIC		HELLER.R	8210010123	116-08	8	A L.dnih	9210190753	30-24
HANNETT, B A	8510380029	XEGRILIC		HELLER.R	8210010128*	50-311	ន	HIND, J A	9210250296	50~31)
HANNETT, B A	8210280057*	XPORTLIC	_	HELLER, R	8210010150*	50-311	S	HINRICHS, O	8210260374 8210250149•	50 7-1
HARBOUR, J	8210010254	50~329	G	HELLER, R	8210010172	50-272	ន	HOBBINS, R R	8210(20400	50-247 Res
- ANDORAN	0210210393	50-416	G	HELLER, R	8210010239*	50-311	8	HOCH, J B	0010400100	
ARDING, M R	B210010115*	50-327	5	HELLER, R	8210010355*	50~311	5	HOCHREITER, L E	9210150159* 9210210054	50-2-5
ARDING, M R	8510090551*	50-327	8	HELLER, R	8210010390*	50-272	8	HOCHREITER, L E	B210220154	ALF(S
ARDING, M R	8210130452*	50-327	6	HELLER, R	8210010412*	50~311	8	HODGDON, A P	8210040087	AUFER En out
HARDING, M R	8210130579*	50-328	8	HELLER, R	8210010423*	50-311	8	HODGDON, A P	8210030000	50-317 50-317
ARDING, M R	8210170386*		8	HELLER, R	8210010461*	50-311	8	HODGDON, A.P.	8210200040	
ARDING, M R	6510550045*		5	HELLER, R	8210070248*	50~311	8	HODGDON, A P	8210280207	10 352
ARDING, M. R	8210220085*		8	HELLER, R	8210070359*	50-311	8	HODGE S A	8210210034	50 312 50-251
ARDING IS R	8210260196#		8	HELLER, R	8210070375*	50-272	5	HOFFMAN, D P	9210150146	50-255
ARDING, M R	8210270094*	50-326	s	HELLER, R	8210150066*	50-272	8	HOFFMAN, J C	8210130148	50-297
ARDING, H R	8210290279*		8	HELLER, R	8210150075*	50-272	8	HOLLAND, P	82101302014	
KARDY, JE KARDY, JE	8210210037 8210260206	NUREO		HELLER, R	8210150121*	50-272	8	HULLAND, P	8210230276*	50 247 1 96-247 1
A L DANA	820202044 <b>1</b> *	NUREG		HELLER, R	8210150155*	50-272	6	HOLLAND, P	8210230276	30.57,
IARIED, JA	8203250320*	FOIA		HELTENES C J	8109100077*	FOIA		HOLMES-RAY, P	6210010327	50 321 1
MULTED! O M	9503520350*	FOIA		HELTENES.C J	8111140308*	FOIA		HOLT, J	8210200010	50 247 1
ARMON, D. L.	8210120397	RES		HELTEMES, C J	8112210538*	50-304	8	HOKAN, F J	8210060425	RES
IARPER, M T IARRINGTON, R M	8210130061*	CONTRACT		HELTEKES, C J	6201150003*	FOIA		HOMAN, F J	8210180407	MES RES
	8210150564	NUREQ		HELTENES C J	#1E0080031	FOIA		HONEY, J	8210290255	PR NES
IARRINGTON.W D	6204160222* 8210060080		3	HELTEMES, C J	#18E0A001SB	FOIA		HOPKINS, J B	8210210272	50 to 1
WWW.TIAG.LOUV.M. D.	9510090090	50-293 1	•	HELTEMES, C J	8210070422	50-275	S	HUBRING'' B	0810510878	30 to 1

#### TOO NATE AND LICH THINEY

AU FHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MANG. Y S MANG. Y S MANG. Y S MANG. Y S	8210080165* 8210080172* 8210050006* 8210050010* 8210080158	GEN TEC IS GEN TEC IS FOIA FOIA GEN TEC IS	IMBRO, E V IMBRO, E V IPPOLITO, T IPPOLITO, T A IPPOLITO, T A	8210130045 8210190009 8210070139* 8204070250* 8209210383*	50-336 8 50-368 5 50-27 0 50-244 P 50-237 P	JOHNSON, B D JOHNSON, B D JOHNSON, B D JOHNSON, B D JOHNSON, B D	8210060213 8210120078 8210130144 8210130184 8210170604	50-255 B 50-255 P 50-255 B 50-255 B 50-255 B
VIANG, Y S WIGHECK, H G JUCHTON, R L WIDEOIN C R WIGEOIN C R	82:0080169 8210190419* 820:200462* 82:0270052* 82:0270056*	GEN TEC 19 50-498 Q 50-241 P 50-537 G 50-537 G	PPOLITO,T A IPPOLITO,T A IRBY,B J IRBY,B J IRBY,B J	8210070121* 8210080002* 8209300175* 8210130438* 8210130569*	50-244 P 50-237 P 50-289 S 50-259 S 50-259 S	JOHNSON, 8 D JOHNSON, 8 D JOHNSON, 8 D	8210190620 8210190639 8210220186 8210260183* 8210260107	50-255 8 50-255 9 50-255 P 50-255 0 50-255 F
NUSON, S D NUFFMAN, G N NUFFMAN, G N NUGGINS T NUGHFS, A	8210070350# 8210010159# 8210220461# 8210280321# 8210040357#	50-220 Q 50-335 Q 50-338 Q FOIA FOIA	IRBY.B J IRWIN,D P ISABELLE.L D ISHII.M ISLEY.T	8210290232* 8210200036 8210290267 8210150556 8210190261*	50-294 8 50-322 0 50-247 5 NUREG 50-346 8	JOHNSON, B D JOHNSON, C JOHNSON, C E JOHNSON, C R	8210260276 8208290084 8210190452* 8210280448 8210290155	50-255 P 50-537 A 50-382 Q 71-9010 71-4498
PUCHES, P G NOFILL, H D NOFILL H D NOFILL, H D NOFILL, H D	8210220056* 8210050113 8210050196 8210060228 8210070372	50-302 S 50-289 P 50-289 P 50-289 F 50-289 P	JABBOUR, K N JABBOUR, K N JABBOUR, K N JACK, R A JACKIW, I	8210190071 8210220026 8210260065 8210260582* 8210190694*	50-413 A 50-413 A 50-413 V 50-201 G 50-373 Q	JOHNSON, D F JOHNSON, O E JOHNSON, O E JOHNSON, O E JOHNSON, O E	8210010225* 6210040121* 6210040015 8210040017 6210040023	50-338 Q 50-304 S 50-440 Q 50-440 Q 50-440 Q
OWICE, H D CRICE, H D EWICE, H D OWICE, H D OWICE, H D	8210080043 8210080308 8210130206 8210130210* 8210130248	50-287 P 50-289 P 50-289 P 50-289 P 50-289 P	JACKIW, I N JACKIW, I N JACKIW, I N JACKSON, L H JACKSON, L H	8210060335* 8210170601* 8210170626* 8210010350* 8210150132*	50-10 b 50-373 0 50-295 0 50-324 0 50-324 0	JOHILOON, O E JOHNSON, O E JOHNSON, O E JOHNSON O E JOHNSON, O E	8210060191 8210190377 8210200071 8210210187 8210210197*	50-413 0 50-440 0 50-413 0 50-413 0 50-413 0
SPICE.H D CPICE.H D CPICE.H D CPICE.H D	8210130515 8210130546 8210150202 8210250097* 8210260499	50~287 S 50~287 P 50~287 Q 50~217 P 50~289 R	JACKSON.L H JACOBE.W JACOBE.A JACOBE.A JACOBE.A	8210220307* 8210120379 8210050501 8210050516 8210150328	50-321 Q WASTE MGT CONTRACT CONTRACT CONTRACT	2 0,408/400 3 0,408/400 4 0,408/400 5 0,408/400 4 1,408/400 1 1,408/400	8210250370 8210270002 8210270010 8210150017* 8210260232	50-413 G 50-413 G 50-413 G 50-293 G 50-322 T
OLMAN, E G ULMAN, E G ULMAN, E G ULIMER, M M UNIMICUIT, D M	8203050073* 8203220512* 8210290405 8210190362* 8210050399*	50-537 D 50-537 D 50-245 P 50-331 Q 50-458 Q	Jacobs, a Jacobs, a Jacobs, a Jacobs, a Jacobs, a	8210180357 8210180414 8210190003 8210190132 8210210041	CONTRACT 50-201 P CONTRACT CONTRACT CONTRACT	L ,NOBNHOU A R ,NOBNHOU A R ,NOBNHOU A R ,NOBNHOU O W ,NOBNHOU O	8210130315* 8210130054* 8210170141* 8210170182* 8210240474	50-537 A CONTRACT CONTRACT CONTRACT 50-368 S
CHRICOTT, D. M. UNRICOTT, D. M. REMICOTT, D. M. CHRICOTT, D. M. CHRICOTT, D. M.	8210190349* 8210190452* 8210190516* 8210190539* 8210190608*	50-285 Q 50-382 Q 50-313 Q 50-285 Q 50-482 Q	JACOBE, A JACOBE, A JACOBE, H R JACOBE, J L JACOBE, R H	8210250282 8210270399 8210260230* 8210010434* 8210120043	CONTRACT CONTRACT 50-72 R 40-1202 50-289 P	O MOTENHOU W U MOTENHOU V U MOTENHOU V W MOTENHOU V W MOTENHOU	8210060345* 8210120125 8202170310* 8203110403* 8205280532*	50-520 0 NUREQ 50-244 P 50-244 P 50-207 0
ULNICUTT, B. M. UNSTAD, A. A. UNSTAD, A. A. UNSTAD, A. A. UNSTAD, A. A.	8210190776* 8210130533* 8210150390* 8210190745* 8210250183*	50-445 0 50-282 S 50-282 S 50-306 S 50-282 S	JACOBS.R H JAFFE.D JAFFE.D H JAFFE.D H JAFFE.D H	8210270162 8210120139* 8210070106 8210070125* 8210200108	50-289 P 50-317 F 50-317 P 50-317 P 50-317 P	JOHNSTON, II V JONES, B W JONES, B W JONES, C R	8205280533* 8210010064 8210040097 8210060183 8210260217	50-207 P 50-537 Q 50-275 Q 50-537 Q 50-298 Q
UNSTABLA A UNST.M D UNTLM D UNTER D UNTER,R S	8210250376* 8210010462* 8210220189* 8210170627 8210010362	50-282 8 50-390 0 50-438 0 50-358 5 50-315 F	Januska, a o Januska, a o Januska, d Januska, a o	8210270412 8210120466 8210280030 8210040208* 8210150543*	50-317 P RES XPORTLIC 50-331 Q 50-10 Q	JONES, D. L. JONES, D. W. JONES, J. A. JONES, J. A. JONES, J. A.	8210270009* 8210010317* 8006170030* 8210010028 8210180116*	50-309 Q 70-143 FOIA 50-261 H FOIA
UNTER.R S UNTER.R S UNTER.R S UNTER.R S UNTER.R S	8210050138 8210050159 8210050211 8210050349 8210060296*	50-315 P 50-315 P 50-316 P 50-315 P 50-315 Q	Jape. F Jape. F Jape. F Jape. F Jape. F	8210010151* 8210010176* 8210010208* 8210010240* 8210010432*	50-416 0 50-261 0 50-348 0 50-321 0 50-257 0	JONES, J A JONES, J K JONES, L L JONES, L H JONES, R A	8210180353* 8210190177* 8210150084* 8210260211 8210040030*	FOIA CONTRACT 50-249 8 NUREQ 50-445 0
UNTER.R S UNTER.R S UNTER.R S UNTER.R S URREY.K C	8210190676 8210220393 8210220478 8210250228 8210180371*	50~315 R 50~315 P 50~315 P 50~315 P CONTROL	JAPE, F JAPE, F JAPE, F JAPE, F JAPE, F	8210010459* 8210010472* 8210150062* 8210150143* 8210150269*	50-369 Q 50-395 Q 50-370 Q 50-269 Q 50-389 Q	Jones, R Jones, S Jones, S Jones, B Jones, W C	8210180008* 8210120527 8210120528 8210210527 8209170051	50-445 X 40-8102 40-6639 40-6639 50-285 F
URT.D URT.D URT.D URT.D URT.D	8210070039* 8210070043* 8210070047* 8210070050* 8210070053*	50-537 A 50-537 D 50-537 D 50-837 D 50-537 D	Jape, f Jape, f Jau, W C Jeikins, o R Jenkins, g R	8210220147* 8210220337* 8210050412 8210010157* 8210150021*	50-324 Q 50-370 Q NUREQ 50-335 Q 50-369 Q	nokep'h c nokep'h c nokep'h c nokep'h c	8210040186 8210050247 8210050301 8210060196 8210070333*	50-285 8 50-285 P 50-285 8 50-285 P 50-285 Q
JSEBY.D E JSEBY.D E JSEBY.D E JTTON.J W JTTON.P H	8210170294* 8210270273* 8210280267* 8210070133 8210080322	50-317 8 50-317 8 50-317 9 50-259 T RES	JENKINS, OR JENKINS, OR JENKINS, OR JENKINS, RT JENS, WH	8210150025* 8210150401* 8210220461* 8210130558* 8210130282	50-349 Q 50-241 Q 50-338 Q 50-317 S PR	JONES. W C JONES. W C JORDAN. E JORDAN. E JORDAN. E	8210130570 8210190734 8210200077 8210080213* 8101050528	50-285 S 50-285 R 50-285 P FOIA 50-247 P
MATONIS, A SHATONIS, A SOE, V. M MBRD, E MBRD, E	8210190447 8210190653 8207180037 8106100203* 8107300168*	50-287 S 50-267 S 50-483 S 50-313 P 50-324 B	JUHANSEN, J JOHANBEN, J JOHANBEN, J JENBEN, W L JENBEN, W L	8210270078# 8210260345# 8210290241# 8210010428# 8210060227#	50-289 0 40-8410 70-33 40-1202 70-7	JORDAN, E. L. JORDAN, E. L. JORDAN, E. L. JORDAN, E. L. JORDAN, H.	8105040420* 8105280476* 8108210025* 8210080187* 8210180592	50-352 0 50-263 0 FOIA FOIA NUMEG
1880. E 1880. E 1880. E 1880. E 1380. E V	8112010310* 8210070416 8210080018 8210080028 8203120016*	50-336 S 50-324 S 50-336 S 50-368 S 50-368 S	H A, MORNHOL JOHNSON, A H JOHNSON, A R JOHNSON, A R JOHNSON, B	8210010459* 8210150062* 8210220337* 8210190761* 8210040346*	50-369 Q 50-370 Q 50-370 Q GA979 50-537 A	Jordan, H Jordan, M Jordan, M Jordan, M Jordan, W 8	8210210014 8210050182 8210050353 8210150538* 8210200024	NUREQ 50-263 8 50-407 8 50-10 0 50-443 9
18RO.E V 18RO.E V 18RO.E V 18RO.E V 18RO.E V	8203290028* 8203290031* 8210060430* 8210070425 8210080017	50-293 P 50-293 P 50-336 S 50-335 S 50-317 S	JOHNBON, B JOHNBON, B JOHNBON, B JOHNBON, B D JOHNBON, B D	8210040349* 8210040351* 8210210274 8210050265 8210050302	50-537 A 50-537 A 50-454 Q 50-255 P 50-255 P	JORDAN, W S JORDAN, W S JORDAN, W S JORDAN, W S JORDAN, W S	8210200026 8210200035* 8210200035* 8210200042* 8210200042*	50-443 Q 50-443 Q 50-443 Q 50-443 Q
l								

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION	
JORDAN, W S JORDAN, W S JORGENSEN, B L JORGENSEN, B L JUDD, B R	8210200049+ 8210200049+ 8210190449+ 8210190707+ 8210150548	50-443 0 50-443 G 50-255 Q 50-255 Q NUREQ	KEISER, H W	8210040088 8210040118 8210130352 8210130363 8210130377	50-387 S 50-387 S 50-387 S 50-387 S	KERRIGAN, J D KERRIGAN, J D KERRIGAN, J D KERRIGAN, J D KERRIGAN, J D	9210180243 8210180253 8210180253 821019054 8210210028	50-337 50-441 50-357
JULIAN, C JULIAN, C JULIAN, C JULIAN, C JULIAN, C	9210010206* 9210010225* 9210010346* 8210220329* 8210190376	50-338 Q 50-250 Q 50-250 Q 50-251 S		8210210285 8210210433 8210210440 8210250347 8210250357	50-387 5 50-387 S 50-387 S	KERRIGAN, J D KERRIGAN, J D KERRIGAN, J D KERRIGAN, J D KERRIGAN, J D	8210210026 8210210317 8210210500 8210270006 8210270324	50-389 50-382 50-529
JULIAN.C A JUNGE.M A JUNGE.M A JUNGE.M A JUSTUS,P S	8210220303* 8210040069* 8210040219* 8210130578* 8210120351	50-318 S 50-318 S 50-317 S WASTE MOT	KEISER, H W KEISER, H W KEISER, H W KEISER, H W KÉITH, H N	8210250369 8210250381 8210260509 8210260215 8210040332	50-387 S 50-387 S 50-387 S	KERRIGAN, J D KERRIGAN, J D KESSLER, J KETZLACH, N KEY, N J	8210270339 8210280416 8210200019 8210290392 8210130557	50-3 <sub>9</sub> 50-5 50-24 • 70-29
KACICH,R M KACICH,R M KADAMBI,N P KADAMBI,N P KADAMBI,N P KADAMBI,N P	8210130326 8210130326 8210150647 8210210258 8210210312	50~10 P 50~10 P 50~400 A 50~400 A	KEITH,H N KELLER,H T KELLEY,D L KELLEY,J L KELLEY,J L	8210040292 8210270208 8210070369 8210050247 8210060184	• 50~33B P	KIEL, R L KINDER, E T KING, M KINGSLEY, O D KINGSLEY, O D	9210260561 9210250307 9210260215 9210080294 9210080294	
KAHLE,J B KAHLE,J B KAISER,G D KAISER,W T	6210270222# 621010127# 8210150136# 8210210306# 8210170427#	\$0-275 8 70-1201 70~824 50-327 A 50-282 P	KELLY, A B KELLY, J A F KELLY, J J KELLY, J J KELLY, J H	8210010307 8210010178: 8210260301: 8210360145 8210220497		D U MAMENNIA D U MAMENNIA D U MAMENNIA D U MAMENNIA D U MAMENNIA	8210010418 8210060225 8210060227 8210260341 8210260345	40 12 70-7 70-7 40-84.
KALEEL.R J KALIVIANAKIS,N KALIVIANAKIS,N KALIVIANAKIS,N	8210050418 8210040375 8210120551* 8210130172 8210130251	NUREG 50-254 9 50-254 F 50-254 9 50-254 9	KELLY, J W KELMERS, A D KEMPER, J S KEMPER, J S KEMPER, J S	8210270232 8210150564 8210040224 8210040362 8210220374*	70-27 NUREG 50-352 Q 50-352 A 50-352 Q	KINNEMAN J D KINNEMAN J M KINNEY, W W KINTNEM, L L KIPER, K L	821027024[* 8210010426* 8210270304* 8210120026 8210080313	70-33 40-12
KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N	8210130324 8210130386 8210130413 8210130466 8210130501	50-254 S 50-254 R 50-254 S 50-254 S 50-254 S	KEMPKA, S N KENNEDY, R J KENNEDY, R T KENNEDY, R T KENNEDY, R T	821015057; 8210130138 8210010079* 8210010105* 8210070448*		KIRK, G B KIRSCH, D F KIRSCH, D F KIRSCH, D F KIRSCH, D F	8210270074* 8210060124* 8210060267* 8210170250 8210170501*	50-324 50-342 50-351 50-351 50-361
KALIVIANAKIS, N KALIVIANAKIS, N KALMAN, K KAMATH, P KAMMER, D S	8210190658 6210250148 8210040344 8210050360 8210010135*	50-254 8 50-254 8 40-8697 NUREG 50-327 0	KENYON, T J KENYON, B D KENYON, B D KENYON, B D	8210070216* 8210060391 8210080142 8210080146* 8210210417	50-286 Q 50-387 P 50-387 P 50-387 P 50-387 P	KIRSCH, D F KIRSHEN, A H KISTER, H KISTER, H KISTER, H	8210280303* 8210060244 8210010007 8210060046* 8210070216*	50 275 50-265 50-260 50-247 50-286
KAMMER, D S KAMMER, D S KAMMER, D S KAMMER, D S KAMMER, D S	9210010197* 9210010420* 8210250236 8210250244 8210260148	50-438 0 50-518 0 50-259 F 50-250 F 50-327 P	KENYON, B D KENYON, B D KENYON, T J KEPPLER, J G KEPPLER, J Q	8210260350 8210290230 8210190084 8011060565* 8209160503	50-387 P 50-387 P 50-390 A 50-254 S 50-295 P	KISTER, H KISTER, H B KISTER, H B KISTER, H B KLEINSORGE, W P	8210210307 • 8210076350 • 8210210115 • 8210270173 • 821001009 [ •	50-247 50-223 50-223 50-246 50-423
KAMMER, D S KAMMERER, C KANE, R S KANE, W F KANE, W F	8210260228 8210070454* 8210050341 8210080309 8210270136*	50-327 P FOIA 50-199 P 50-395 P 50-387 P	KEPPLER,J Q KEPPLER,J Q KEPPLER,J Q KEPPLER,J Q KEPPLER,J Q	8209270242 8210050105 8210050107* 8210050186 8210050194*	50-358 H 50-295 Q 50-295 Q 50-266 Q 50-266 Q	KLINE, J R KLINE, J R KLINE, J R KLINE, J R KMETYK, L N	8210050251 8210070137 8210130333 8210210476 8210050397	50-245 50-445 50-445 50-446
KANEN.A C KANGA.B K KANGA.B K KANGA.B K KANGA.B K	8210240232 8210040200 8210070220 8210070224 8210070345	50-322 T 50-320 P 50-320 P 50-320 R 50-320 P	KEPPLER,J O KEPPLER,J O KEPPLER,J O KEPPLER,J O KEPPLER,J O	8210060253 8210080174 8210130186 8210130400 8210130403*	50-315 Q 50-315 P 50-341 Q 50-409 Q 50-409 Q	KNIGHT, J P KNOLL, F J KNOP, R KNOP, R C KNOP, R C	8204290455+ 8210290202 8210190437 8210130221 8210250224	NUMEQ 50-264 50-264 50-461 50-546
KANGA, B K KANGA, B K KANGA, B K KANGA, B K	9210130583 8210150043 8210150085 8210170570 8210200012	50-320 P 50-320 P 50-320 P 50-320 P 50-320 P	KEPPLER, J 0 KEPPLER, J 0 KEPPLER, J 0 KEPPLER, J 0 KEPPLER, J 0	8210130451 8210130459* 8210130547 8210150487 8210170532	50~461 Q 50~461 Q 50~461 Q 50~254 Q	KNOP, R C KNOX, J KNOTH, D F KNOTH, D F KOCH, L J	8210280174# 8210120128 8207050005# 8210130399	50-441 50-441 98 98
KANGA, B K KAPLAN, C KATAOKA, I KAUCHER, J E KAUCHER, J E	8210240236* 8210180138 8210150554 8208190178* 8208190290*	50-320 0 50-247 0 NUREO 50-213 P 50-302 P	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8210190635 8210190699 8210190763 8210190771* 8210250312	50-358 Q 50-255 Q 50-440 Q 50-440 Q 50-395 F	KOCH.L J KOCH.L J KOEBEL.C KOESTER.O L KOESTER.G L	8210130325 8210130470 8210120046* 8210120199	50-451 50-451 50-451 FOJA 50-482
KAVANAUDH, P F KAY, D KAY, D L KAY, J KAY, J A	8210120471* 8210190744* 8210190346* 8210130401 8210150363	CONTRACT 50-373 8 50-373 8 50-27 0 50-27 P	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8210250320 8210260179 8210260198 8210260204 8210260371	50-243 P 50-255 P 50-243 F 50-441 A 50-409 F	KOESTER.O L KOESTER.O L KOLBE.R KOLTAY.P KOLTAY.P	8210130399 8210220403 8210130592 8210040046* 8210210307*	50-492 PR PR NUREG 50-247
KAYANABIN C KEAHER, W H KEARNEY, J KECKEISEN, T	8210250097* 8210180229* 821027054 8210130282 8210260353*	50-219 P FOIA 40-2259 PR 50-260 S	KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J G KEPPLER, P	8210280170 8210280174* 8210280174* 8210270330 8210250035	50-461 Q 50-461 Q 50-461 Q 50-358 A	KOMOSKY, G KONG, Y H KONKLIN, J E KONKLIN, J E	8210210160* 821028020[* 8210130222* 8210130529* 8210290080*	50-247   50-336   50-277   50-545   50-483   60-281   60-
KEDDIB, N N KEIMIG KEIMIG, R KEIMIG, R	8210270124 8210130405 8210270366 8210220447 8210240483	80-584 A 50-387 8 80-277 8 50-334 6 50-289 8	KERCH, H W KERR, V B KERR IGAN, J KERR IGAN, J KERR IGAN, J	8210290093* 8210050446 8210010829* 8210050393 8210130371	50-322 Q 50-320 P 50-361 P 50-443 A 50-361 P	KOON, A R KORNEGAY, P C KOT, C A KOUTS, H KOUTS, H	8210220346* 8210150564 8210150537 8207180066	50-341   50-395   KUREG NUREG ACRE
KEIMIG.R R KEIMIG.R R KEISER,H W. KEISER.H W KEISER.H W	8210270304* 8210010177 8210010228	70-33 50-184 q 50-387 8 50-387 8 50-387 8	Kerr Igan, J Kerr Igan, J Kerr Igan, J Kerr Igan, J. D Kerr Igan, J. D	8210130573* 8210210035 8210010037 8210120025 8210180237	50-361 P 50-400 A 50-400 F 50-528 A 50-387 E	KOVACK, T S KRATZER, M B KRAUSE, D KREGER, W E KREGER, W, E	8207180066 8210280364* 8210070488* 8210040203* 8108270422* 8111090062*	ACRS 50-254 / FOIA 50-315 1 50-261 1 50-266 1

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PREGER N E	B112020885*	50-324 P	LATHAS, G C	8210210553*	50-346 P	LEASBURG, R H	8210120258	50-280 P
PEGER WE	8112300287*	50~324 P	LAINAS, O C	8210290118	TOPREP	LEASBURG R H	8210120265	50~280 P
≥REGER.WE	#201150176*	50-537 D	LATHAS, G C	8210290450	ORG	LEASBURG, R H	8210120297	50-280 P
•ದ ೯೮೭೪, ಟ ೬	9201200656*	50-241 P	LAINAS, G C	8210290453	TOPREP	LEASBURG, R H	8210130112*	50-338 F
FEEIN II S	82102/0338	NUREG	LAINAS, G C	821 0290458	TOPREP	LEASBURG R H	8210130427	50-280 G
FFEST T S	8210120453	RES	LAIRD, R C	8210040163*	50-220 P	LEASBURG, R H	8210190321	50~339 P
PEUS R E	8210130284	50-341 F	LAMP, M S	8210040313*	50-316 8	LEASBURG R H	6210200043	50-280 P
## TEGER, R W	8210080093	50-206 P	LANCASTER B T	8210040033 <b>*</b>	50~445 G	LEASBURG R H	8210220011	50-338 P
FRIEGER, RW	8210260214 8210260272	50-206 P 50-206 P	LANDGRAF, L C	8210010287	50-341 K	LEASBURG, R H	8210220170	50-280 P
PREGER. R W	REIDERDE	30-200 F	LANDGRAF, L C	8510010589	50-341 K	LEASBURG R H	8210220178	50-280 P
MATICALS N	6210070075	50-440 0	LANDIS, K D	8210190376	50-251 5	LEASBURG, R H	8210220200	90-33B G
*elled B N	8210130161	50-289 F 50-289 F	LANDSMAN, R B	B210050154*	50-329 Q	LEASBURG, R H	8210220373	PR
NETHA H	8210130320 8210130430	50-287 F	LANDSMAN, R D	8210190750*	50~329 G	LEASBURG, R H	8210250208	50-338 F
FRIMM R W	8210220147*	50-324 0	LANGER, R R LANGER, R R	#004304 #4460410198	FOIA FOIA	LEASBURG R H	8210260133	50-338 P
FRUS H E			LANGER, R. A.	95101904244	PUIM	LEASBURG, R H	8210270160	50-338 P
PUBLINAK R A	8210290249	PR 50-387 5	LANIK, O	8011060561	50-254 8	LEASBURG, R H	8210270204	50-338 P
HICZYNEKI, L A	8210010402* 8210040088*	50-387 S	LANIK, Ø LANIK, Ø	8210040082* 8210070438	50-296 S 50-219 S	LEASBURG R H	8210270256	50-338 P
POCTYNSPI, L A	8210120342*	CONTRACT	LANIK, O F	8110230085*	50-219 S	LEASGURG R H	8510580130	50-280 P
PURSUMAN, J. M PURSUMAN, J. M	8210120423*	M PBE-08	LANNING, H	8112100374*	FOIA	LEASBURG R H	9510580599	50-280 P 50-278 P
ALLERGINATION OF						LEASER, J D	8207090224*	50-278 P
PURITA P. N	8210080322	RES	LANHING, H	8202120236*	50-272 B	LECLAIR, D E	8210170004*	CONTRACT
とびまされた 出いれ ア	8510510351*	50-309 0	LANNING, W D	8012290110	50-302 8	LEDDICK, R S	9210070161*	50~508 Q
T HENBERT'S M	0210130578*	50-317 S CONTRACT	LANNING, H D	8107160079*	90-240 S	LEE, BS	8210120459	RES
L V TABAL	8210260129# 8210260129#	50~334 F	FANNING'M D	#460000118 #205030617	50-313 B 50-247 S	LEE.L S	8207290410	NUREG
ACE: W.J	De l'Ordora 7*	30324	CHRISTIAN D	65020309174	30-24/ 5	TEE'N	8210210054	NUREO
LACEY, R.S.	B210040045	50-334 S	LANNING, H D	8205030619*	50-247 S	LEE, N	8210220154	NUREG
LACEY, W S	B210190185	50-334 S	L'ANHING! H. D.	8205190428*	50-327 S	LEE-D R	8210250083	50-267 F
LACEY. H S	62(0150199	50-334 S 50-334 S	LAMITING, H D	8205190441*	50~327 S	LEE OR	8210270104	50-267 P
L-CENH S	8210150201* 8210170274	50-334 S 50-334 S	FWHING H D	8209150106# 8210070104	50-261 P 50-313 B	LEE O R	B210270113#	50~267 P
tacerall S	9810170274	30-354 8	CUMHINGS M. D.	8510070104	20-212 0	LEE, T D	6210150204*	70-143
LACELLUS	B2101702B2*	50~334 S	LAMMING, IJ D	8210070490	50-260 S	LEECH. P	8210010082*	50-537 Q
CACES W S	8510510009	50-334 S	LANNING, H D	8510150150	50-334 P	LEIGH.D N	B210010440*	40-1202
ынд <b>е</b> ⊱ И 8	8210210065	50~334 S	LARRING, W. D.	8210120182	50-275 6	LE LKEN, L	8210200057	70-143
LACIETIUS	8210260163 8210260203	50-334 B 50-334 S	CANPHER, L C	8210050383	50-322 0	LETREN L	8210250040	70~143
LACEY. (1 S	8510500303	30-334 5	LANPHER, L C	8210050383	50-322 G	LEMPGES, T E	8210010165*	50-220 0
LAÇ€n.H 5	8210240478	50-334 S	LANPHER . L. C	8510500039	50-322 ¢	LEMPGES.T E	8210010287*	50-220 4
LACEY H 5	8210260487*	50-334 S 50-334 S	LAMPHER, L C	B210200076	50~322 G	LEMPOES, T E	8210040182	50-220 P
LHCEY.H S	8210280271 8210280280	50~334 S 50~334 S	LANPHER L C	8210200076	50-322 0	LEMPGES, T E	8210050148	50~220 F
LHCEY M 5	8210280307	50-334 S	LANPHER, L C LANPHER, L C	8210200083*	50-322 G 50-322 G	LEMPGES T E	851009050B*	50-220 0
LACEY. IF S	951050000	10-354 2	LARPHENIL	85105000974	20-755 G	LEMPGES.T E	8210060284	50-220 S
LACUMI R	8210290241*	70-33	LANPHER, L C	8210200089*	50-322 G	LEMPGES, T E	8210130347	50-220 R
LAIGART, M H	BZ10250383	50-219 F 50-317 B	LANPHER, L C	8210200089*	50~322 G	LEMPGES. T E	8210260184*	50~220 G
LAG I EMSKI, J. 5	8210040144* 8210130465*	50-317 S 50-317 S	LANSFORD R A	8210040042*	50-445 0 50-282 0	LEMPGES, T E	8210280144	5 <i>0</i> -220 P
LHU LENSKI J S	82102702694	50-317 B	LARSON.C E LARSON.C E	8210150255* 8210150435*	50-282 G	LENTINE, F Q	8210050207	50~295 F
LAGIENSKI, J S	95105705074	20-317 6	EMEDRIA' P E	0210170407×	טעיירעק ע	LENTINE, F 0	8210050270	50-295 P
LASTEMBRI, J B	8210270273*	50-317 6	LARSON, T K	8210150409	RES	LENTINE, F Q	8210080111	50-275 P
LAGIENSKI, J S	8210280141×	50-318 8	LASHER, C. E	8207120253*	50-447 A	LENTINE, F O	8210220399	50-295 P
IAINAS, C	8011120579	FOIA 50-247 P	LASOTA, J LASSAHN, O D	8210150474 8210150540	30~528 0 NUREG	LEG, F A	8210190167*	CONTRACT
laifias. G C Laifias. G C	8103120107*	50-321 S	LASSAM, G D	8210280339	RES	LESSY, R P	8210050075 8210190370	27-39 50~312 9
THILLMS A P	Ofociento\*		Chaanilly V	0284A00437	1754	LESSY, R P	0210170370	50~312 0
LA DIANG G C	B103240292*	FOIA	LASUA.S R	9210040130	18E	LEVINE J H	B210050346	50-368 8
LA (IPZ-+B) Q C	0103310127*	FOIA 50-302 5	LATHAM, S D	8210150309*	50-322 0	LEWIS, D F	8210130505¥	50-329 T
LATITUDE O C	8106150555* 8203170034*	50-302 5 F01A	LATHAN, SB LATHAN, SB	9210150337* 9210150351*	50-322 G 50-322 G	LEWIS D F	8210130505* 8210260442	50~329 T 50-397 A
LAINAS, G C LAINAS, G C	B210040411*	FOIA	LATHAM, S B	8210150365#	50-322 6	LEWIS, H D LEWIS, H I	6210200448	au-da/ A
CONTINUES OF A						erentant II 4		

#### LEUSONAL AO LUOK INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SLD E CATE,-
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8210150027# 9210150034# 8210150036 8210150040# 8210150048#	50-416 G 50-324 G 50-324 G 50-324 G 50-324 G	LINNEMANN, R E EINVILLE, J C LIPINSKI, D R LIPINSKI, R LIPPOLD, W J	8210190178* 8210210115* 82102101964 8210190601* 8210260299	50-322 T 50-333 Q 50-245 Q 50-373 Q 50-318 P	LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H	8210010079+ 8210070086+ 8210070095+ 8210070095+ 8210070098+	50-531 . 50-531 . 50-541 . 50-541 .
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8210150100 8210150113* 8210150171 8210150189* 8210150225	50-324 Q 50-324 Q 50-438 Q 50-438 Q 50-327 Q	LITERSKI,L A LITTLE,B H LITTLE,M LITTLE,M LITTLE,M	8209290225* 8210250080* 8210040003 8210120414 8210120490	50-10 F 50-341 G CONTRACT CONTRACT CONTRACT	LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H	8210070101 ± 82100701194 82100701234 82100701264 8210070128	50-51", 50-51" 50-51" 50-531 "
LEWIS,R C LEWIS,R C LEWIS,R C LEWIS,R C LEWIS,R C	9210150237* 8210150260* 8210150278* 8210150384 8210150396	50-327 Q 50-390 Q 50-390 Q 50-416 Q 50-261 Q	LITTLE, M LITTLE, M LITTLE, H LITTLE, M	8210120510 8210120534 8210120549 8210120607 8210130058	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H	8210070131+ 8210070134+ 8210070139+ 8210070142+ 8210070146+	50-501
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8210220127 6210220137* 6210220237 6210220277 6210220272*	50-400 Q 50-400 Q 50-438 Q 50-321 Q 50-321 Q	LITTLE, M LITTLE, M LITTLE, M LITTLE, M LITTLE, B	8210130071 8210180365 8210180375 8210180411 8210170210	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H	8210070148+ 6210070151+ 8210070154+ 8210070157+ 8210070161+	50-501 50-501 50-501 50-501 50-501
LEWIS,R C LEWIS,R C LEWIS,R C LEWIS,R C	8210220276 8210220310* 8210220467 8210220495 8210220500*	50-250 Q 50-250 Q 50-327 Q 50-241 Q 50-261 Q	LITTLE, M LITTLE, M LITTLE, M LITTLE, M LITTLE, W S	6210210147 8210210502 8210260516 8210260525 8210060305	CONTRACT CONTRACT CONTRACT CONTRACT 50-440 @	LONENDERG, H LOWENDERG, H LONENDERG, H LONENDERG, H LONENDERG, H	8210070166* 8210070170* 9210070106* 9210070196*	50-131 50-131 50-131 50-131 50-53
LEWIS,R C LEWIS,R C LEWIS,R C LEWIS,R C	8210260309 8210260370 8210260376 8210260310* 8210270229	50-302 0 50-302 0 50-335 0 50-335 0	LITTLE, W S LITTLE, W S LITTLE, W S LITTLE, N S LITTLE, W S	8210060329 8210060379 8210130368 8210170589 8210170617	50-10 0 50-373 0 50-341 0 50-373 0 50-275 0	LOWENBERG. H LOWENBERG. H LOWENBERG. H LOWENBERG. H LOWENBERG. H	8210070195* 8210070200* 8210070206* 8210070207*	50-531 50-531 50-531 50-531
LENIS, S H LENIS, S H LEWIS, S H LIAW, C Y LICITRA, E A	8210040019 8210040021 8210040022 8205250020* 8210130053	50-440 Q 50-320 Q 50-367 Q 50-155 P 50-400 A	LITTLE, W S LITTLE, W S LITTLE, W S LIU, L LIU, L LIVERMORE, H	8210190619 8210190669 8210190682 8210130509 8210190633	50-440 A 50-266 G 50-373 G 50-331 P 50-461 S	LOUENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H	9210070222+ 8210070223+ 8210070225+ 8210070259+	50 537 50-537 50-537 50-537 50-537
LICITRA E A LIDEN, E A LIDEN, E A LIDEN E A LIEBERMAN, E	8210210320 8210180009 8210190507 8210220275 8210150188*	50-400 A 50-272 P 50-272 P 50-272 P 50-322 T	LIVERMORE, H H LIVERMORE, H H LO, T LO, T LO, T	8210130357* 8210250232* 8210050537 8205250010* 8207300222*	50-461 Q 50-461 Q 50-320 P 50-155 P 50-206 P	LOWENBERO, H LOWENBERG, H LOWENBERG, H LOWENBERG, H LOWENBERG, H	8210070260+ 82100702624 8210070264+ 8210070264+ 8210070269+	50-517 50-517 50-537 50-537 50-537
LIEBERMAN, E LIEBERMAN, E LIEBERMAN, E LIEBERMAN, E LIEBERMAN, J	821015016B* 8210150206* 8210150240* 8210150240* 8208260424	50-322 T 50-322 T 50-322 T 50-322 T 50-280 Q	LOBEL, A LOCHSTET, N A LOCKE, R F LOCKE, R F LOCKE, R F	8103050756* 8210130487 8210060220 8210250192 8210250196*	FOIA 50-413 D 50-275 G 50-133 R 50-133 R	LOWENDERO, H LOWENBERO, H LOWENBERO, H LOWENBERG, H LOWENDERG, H	6210070273 6210070276 8210070280 8210070282 8210070285	50-537 50-547 50-531 50-531
LIHOV, H LIHOV, H LIHOV, H LIN, H C	8210130253* 8210130473* 821013051[* 8210250153* 8210150557	50-254 8 50-254 8 50-254 8 50-254 8 NUREO	LOFTUS, M J LOFTUS, M J LOFY, R A LOGSDON, M J LOMBARDO, J J	8210210054 8210220154 8210260280* 8210040338 8210250284	NUREO NUREO CONTRACT 40-8502 50-217 P	LOHENDERO, H LOHENBERO, H LOWENBERO, H LOYSEN, P LUBENAU, J O	82100702914 8210070293* 8210070298* 8210120299* 8012180362*	50-537 50-537 50-537 50-257 FOLA
LINDEN, E A LINDER, F LINDER, F LINDER, F LINDER, F	8210270136 8210010389 8210040152 8210050067 8210050339	50-272 P 50-409 P 50-409 F 50-409 P 50-409 F	LONG.A B LONG.D J LONG.F J LONG.F L LONG.J W	8210120397 8207050085 8210010194* 8210220180 8210180137*	RES 50-247 P 50-324 Q 50-438 Q 50-344 S	LUBENAU, J O LUDWIG, P G LUEBKE, E A LUETT, W LUKENS, L L	8210120018+ 8210130445+ 821025023 8210250252+ 8210250033+	FOIA 50-Ja7 . 50-142 . 50-373 NURE:
LINDER, F LINDER, F LINDER, F LINDER, F LINDER, F	8210130365 8210150203 8210150446 8210150448 8210150654*	50-409 F 50-409 P 50-409 P 50-409 G	LONG.R L LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J	8210250097* 8209300353 8210040167 8210040251 8210040304	50-219 P 50-537 B 50-537 A 50-537 A 50-537 A	LUNDELL.B E LUNOVALL.A E LUNDVALL.A E LUNDVALL.A E LUNDVALL.A E	8210240059* 8210070159 8210130103* 8210130338 8210130391	40 8761 50-317 ( 50-317 ) 50-317 P
LINGER, F LINDER, F LINDER, F LINDER, F	8210220009 8210220174 8210250349 8210260319 8210280048*	80-409 J 50-409 Q 50-409 F 50-409 P 80-409 F	LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J	8210060217 8210060249 8210130246 8210130249 8210130311	50-537 A 80-537 A 50-537 B 50-537 A 50-537 A	LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUTKEHAUS, T C	9210180005 9210180124 9210190803* 9210220378 6210190577	50-317 1 50-317 1 50-317 1 50-318 / 50-302 1
LINDER, F LINDER, F LINDER, F LINDER, F LINDSEY, I D	8210280051* 8210280055* 8210290151 8210290307 8210150462	50-409 F 50-409 F 50-409 P 50-409 P 50-416 G	LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J	8210150186 8210210022 8210210273 8210260148 8210260302	50-537 A 50-537 A 50-537 A 50-537 A 50-537 A	LYNCH, M D LYNCH, M D LYNCH, M D LYNB, J E	8210040380 8210220463 8210220468 8202240397* 8203020267*	50-647 # 50-647 # 50-246 # 50-246 #
LINEHAN, J J LINEHAN, J J LINEHAN, J J LINEHAN, J J	8210040338 8210040344 8210040348 8210040365 8210120479	40-8502 40-8697 40-8793 40-8768 40-8786	LONGENECKER, J LONGSINE, D E LOGKABAUGH, A L LOGKABAUGH, A L LOGMIS, O O	8210210159* 8210210159*	50-537 A RES 50-382 G 50-382 G RES	LYONS, J E LYONS, J E LYONS, J E LYONS, J E	8203040502* 8203100593* 8203110334* 8203110337* 8210070038*	50-244 / 50-244 / 50-244 / 50-244 / 50-244 /
LINEHAN, J J LINEHAN, J J LINEHAN, J J LINENBERGER, O LINER, R	8210120591 8210120641 8210220515 8210270178 8210040355#	40-8745 40-8681 40-8714 50-537 G 50-537 A	LORENZ,R A LORIO,P LOTITO,E LOTITO,E M LOTTS,A L	8210270240 8210210457* 8210210328	50-259 F FR 50-317 R 50-317 R RES	LYONS, J E LYONS, J E LYONS, J E LYONS, J E LYONS, J E	8210070068* 8210070073* 8210070076* 8210070080* 8210070083*	50-244 / 50-244 / 50-244 / 50-244 / 50-244 /
LINER,R LINER,R T LINNEMANN,R E LINNEMANN,R E LINNEMANN,R E	8210040350* 8210040037* 8210040037*	FQIA 50-537 A 50-445 Q 50-445 Q 50-322 T	LOTTS.A L LOVE.R S LOVENDALE.P C LOVENDALE.P C LOH.R L	8210130557* 8210050205* 8210050380*	RES 50-461 G 50-266 G 50-186 G PR	LYONS, J E LYONS, J E, LYONS, P J MACDONALD, C E MACDONALD, C E	8210070087* 8210070090* 8210220491 8210120146	50-244 F 50-244 F 40-299 71-6347 71-6347

MUTHER	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT
MAIDE, IALD, C E MAIDENAID, C E MAIDENAID, C E MAIDENAID, C F MAIDENAID C E	8210120158 8210120146* 8210120169 8210120174*	71-9001 71-9001 71-9034 71-9034 71-6703	MAJOR, R MAJOR, R MAJOR, R MAJOR, R MALARO, J C	821006008* 8210060026* 8210060051* 8210080051*	FOIA FOIA FOIA 50-289 O FOIA	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8210040365 8210070277 8210070294 8210070307 8210070317	70~(100 50-293 Q 50-278 Q 70~364 50-277 Q
MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E.	8210120334 8210120336# 8210120339	71-6703 71-9010 71-9010 71-9037 71-9037	MALARO, J C MALARO, J C MALARO, J C MALARO J C MALINAUSHAS, A	8210180326* 8210180328* 8210180343* 8210220080* 8210120453	FOIA FOIA FOIA 40-8111 RES	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8210070341 8210070352 8210070392 8210130079 8210130178	50-217 0 50-245 0 50-443 0 50-317 0 50-309 0
MACEGRAP DICE MACEGRADO CIE MACEGRADO CIE MACEGRADO CIE MACEGRADO CIE MACEGRADO CIE	8210120352* 8210120381 8210120384*	71-9964 71-9964 71-5908 71-5908 71-6346	MALLETT.B S MALLETT.B S MALMROS.M H MALSCH.M G MANCINI.E A	82(0180435# 82(0180436# 82(0190743# 8205270526# 8210080022#	FOIA FOIA 50-344 G FOIA CONTRACT	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8210130441 8210190375 8210210052 8210210069 8210210091	xPORTLIC 50~219 G 50~289 G 50~352 G 50~354 G
MICODMALD C E MICODMALD C E MICOMALD C E MICOMALD C E MICOMALD C E	8210150607 8210150671 82102605694 8210280311 82102803114	71-9151 71-9044 70-143 71-905/ 71-9057	MANGAN, C V MANGAN, C V MANGAN, C V MANGAN, C V MANGAN, C V	8210010413* 8210010033 8210040117 8210040296 8210050111	50-275 P 50-220 P 50-220 P 50-220 F 50-220 P	MARTIN, T I MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8210210109 8210210146 8210210201 8210210221 8210210231	50-354
MACDONALD C E MACBONALD C E	8210280327 8210280324 8210280324 8210280334* 8210280334	71-6346 71-6346 71-6745 71-6745 71-6677	MANGAN, C V MANGAN, C V MANGAN, C V MANGAN, C V MANNO, S F	8210050240 8210050354 8210130107 8210210322 8210040071	50-220 P 50-220 P 50-220 P 50-410 H 50-410 S	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8210210255 8210210313 8210210435 8210210437 8210220168	50-220 0 50-309 0 50-272 0 70-2116 70-371
MHCDONALD C E MHCDCMALD C E MHCDCMALD C F MHCDCMALD C F MHCDCMALD C E	8210280337* 8210280338 8210280342* 6210280343 8210280345*	71-6677 71-6678 71-6678 71-6115 71-6115	MANNO, B F MANNO, S F MANNO, S F MANNO, S F MANNO, S F MANSER, W C	8210040170 8210040190 8210150129 8210250378 8210010184	50-410 G 50-410 S 50-410 S 50-410 S 70-143	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8210220177 8210220240 8210220347 8210240177 8210240334	70-371 70-487 50-352 G 50-220 G 50-333 G
MACEGRALE, C. E. MACEGRALE, C. E. MACEGRALE, C. R. E. MACEGON, J. A. MACEGON, J.	6210280357 8210280759* 8210150412 8210060452* 8210150317	71-9098 71-9098 RES Füia 50-170 G	MANSER.W C MANSER N C MANSER.W C MANSER.W C MARCHAL.J	8210150061 8210150371± 8210150408* 8210150477* 8210270094	70 -143 70 -143 70 -143 70 -143 XPORTLIC	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8210270048 8210270084 8210270103 8210270125 8210270201	50-209 0 50-322 0 50-220 0 50-322 0 50-387 0
EATHLING FACHLING FACHLING FACHLING FACHLING	8210150317 8210150395 8210150375 8210270439 8210270439	50~170 G 50~170 G 50~170 G 50~170 G 50~170 G	MARCHAL, J MARCHAL, J MARCHI, M L MARDIS, D C MARGULIES, M B	8210280064 8210280088 8210260263* 8210010049* 8210190383	XPORTLIC XPORTLIC 50-209 8 50-302 0 50-454 0	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTINEZ, F P	6210270236 6210270275 6210270341 6210270350 6206060015*	70-39 50-273 G 50-322 G 50-322 G COMMISSION
Macal 18.1 Macal 18.1 Macal 18.1 Macal 18.1 8 S Macal 18.0 F	8210280220 8210280220 82102204484 82102204488 82102204488	50-170 G 50-170 G 50-170 G 50-170 G 50-170 G 50-400 G	MARGULIES, M B MARGULIES, M B MARKT, D MARKT, D MARKT, D I	8210180166 8210180170 8210280138* 8210280138* 8210270430*	50-454 0 50-454 0 50-271 F 50-271 F 50-271 F	MASON, JR MASON, JR MASON, RE MASSARO, SA MASSARO, A	8210180284# 8210180287# 8210180400 8210050038# 8210050200#	FOIA FOIA RES FOIA FOIA
madison, A Madison, A. L Madeem, G. L Madeem, G. L Madeem, G. L Madeem, G. L	8210250114# 9210150396# 9210750224 9210070387 9210070364	50-373 0 50-269 0 50-267 0 50-458 0 50-449 9	MARKT, D. 1 MARSHALL, J. R MARSHALL, J. R MARSHALL, J. R MARSHALL, J. R	8210270430* 8210070395 8210120247* 8210120252* 8210130212	50-271 F 50-313 F 50-313 Q 50-313 Q 50-313 S	MASBARO, B A MASSARO, B A MATERS, B R MATERS, B R MATHESON, 6 M	8210050500# 8210060367# 8210130158 8210280222 8206270016#	FOIA FOIA 50-341 A 50-341 A COMMISSION
Madeen o l Madeen o l Madeen o l Madeen o l Madeen o l	8210120030 0210190413 6210190431 0210190547 6210190772	50-382	MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8210130382 8210130409 8210130513 8210130002 8210150073	50-313 8 50-359 P 50-313 S 50-313 P 50-313 F	MATHIS.C J MATHIS.C J MATHIS.C J MATHIS.C J MATHIS.C J	8210040100 8210060023 8210070245 8210070340 8210130472	50-273 B 50-273 S 50-273 S 50-273 S 50-273 S
MADSELL G L MADSELL G L MADSELL G L MADSELL G L MADSELL G L	6210190816 0210720122 6210220130 6210220404 6210260278	50-445 0 50-498 0 50-298 0 50-267 0 50-269 0	MARSHALL.J R MARSHALL.J R MARSHALL.J R MARSHALL.J R MARSHALL.J R	0210190494 0210190517 0210190545 0210220114 0210250206	50-313 P 50-313 S 50-348 S 50-313 P 50-313 P	MATHIS.C J MATHIS.C J MATHIS.C J MATHIS.C J MATLIN.E	8210170235 8210250122 8210260127 8210260146 8210130315#	50-273 \$ 71-6346 50-273 8 50-273 6 50-537 A
Padsen. G L Majer. T B Majevs. D Majnus. D Majer. J E	8210280142 8210050427* 8210280041* 8210280041* 8210280041*	50-247 Q 50-155 P 50-322 F 50-322 F 50-244 P	MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8210250292 8210260190 8210260192 8210260112* 8210290240	PR	MATLOCK,R G MATLOCK,R G MATLOCK,R G MATLOCK,R G MATLOCK,R G	8210070302* 8210070370 8210080175 8210080375 8210080304	50-397 0 50-397 8 50-397 0 50-397 8 50-397 8
Maier. J e Maier, J e Maier. J e Maier. J e Maier. J e	B2100103554 B210010444 B210040281 B210040284# B210130195	50-244 P 50-244 P 50-244 P 50-244 P 50-244 S	MARSHALL, W H MARSHALL, W H MARSHALL, W H MARSOLAIS, L D MARSTON, R R	8210070398 8210070398 8210220274 8210180190 8210150021#	50-329 0 50-329 0 50-329 0 50-271 F 50-369 0	MATLOCK,R O MATSON,E R MATTHEWS.C W MATTEA,J C MATTEA,H J	8210130217 8210080314 8210040424# 8210210261# 8210070021#	50-397 B 14E CONTRACY 50-423 G CONTRACY
Maier. J e Maier. J e Maier. J e Maier. J e Maier. J e	8210130439 8210150643* 8210190591* 8210190618* 8210190637*	50-244 0 50-244 F 50-244 0 50-244 0 50-244 0	Mareton.r R Martin.d E Martin.J Martin.J B Martin.J B	8210220461* 8210120536 8210260113* 8210010460* 8210070103*	40-8771 50-397 A 50-341 A	MATTIALH J MATTIALH J MATTIALH J MATTIALH J	8210070459* 8210120350* 8210120364* 8210120401* 8210180370*	TOARTHOO TOARTHOO TOARTHOO TOARTHOO TOARTHOO
Maier, J e Maier, J e Maier, J e Maier, J e Maier, J e	8210170647* 8210220352* 8210220360* 8210220383 8210250275	50-244 Q 50-244 Q 50-244 Q PR 50-244 P	MARTIN, J B MARTIN, R A MARTIN, T J MARTIN, T T MARTIN, T T	8210120147 8210120428 8210060326 8210010157 8210010332	50-213 Q 50-213 Q	HATTIAH J HATTIAH J HATTIAH J HATTIAH J HATTIAH J	8210190010# 8210190185# 8210190339# 8210210444# 8210270203#	50-320 F CONTRACT CONTRACT
Maier, J e Maiep, J e Majer, R Majer, R Pajer, R	B210250334 B210270217* B210050478* B210050473* B210050539*	50-244 S 50-244 0 FOIA FOIA FOIA	MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8210040258 8210040034 8210040079 8210040138 8210040211	50-322	U MARITTAN U MARITTAN U U JONITTAN U U JONITTAN U U JONITTAN	8210270223* 8210270230* 8210010057 8210050220 8210070287*	CONTRACT 50-312 F 50-312 P

AUTHOR	ACCESSION RESMUN	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESS ION NUMBER	St.
L L. JOHITTAM L L. JOHITTAM L L. JOHITTAM L L. JOHITTAM L L. JOHITTAM	8210070294* 8210070331* 8210130175 8210130599 8210190331	50-312 Q 50-312 Q 50-312 P PR 50-312 P	MCGLESKEY, K E MCGLESKEY, K E MCGLESKEY, K E MCGLESKEY, K E MCGLESKEY, K E	8210150351* 8210150365* 8210150393* 8210150402* 8210150410*	50-322 0 50-322 0 50-322 0 50-322 0 50-322 0	MCGUIRE, D R MCGUIRE, D R MCGUIRE, D R MCGUIRE, D R MCGUIRE, M F	8210210342* 8210260265* 8210260515* 8210270239* 8210210054	70-27 50-327 50-3 5 50-3.2 Nurses
L JONITTAM L L GONITTAM	8210190594 8210250045 8210250094 8210250384 8210260231	50-312 P 50-312 F 50-312 P 50-312 S 50-312 P	MCCLESKEY, K E MCCLESKEY, K E MCCLUNG, C E MCCLUNG, C E	8210150422* 8210150527* 8210250059* 8210150490 8210150490	50-382 0 50-322 0 50-322 0 50-361 0 50-361 0	MCGUIRE, M F MCGUIRE, B A MCGUREN, H J MCGUREN, H J	8210230154 8207280307 8210200055 8210200059 8210280353	NURES 50-245 50-247 50-247
L L.3ONITTAM R.MORTTAM R.MORTTAM L. R.MORTTAM J. R.MORTTAM	8210280228 8010240413* 801024049A* 8007150303 8208310034*	50-312 P FOIA FOIA 50-247 P 50-155 P	MCCLUNG, C E MCCLURE, J D MCCORD, R K MCCORKLE, O MCCRELESS, T G	8210150490 8210070413* 8210150548 8210070084* 8210050409*	50-361 G 71-9150 NUREO 50-537 D FOIA	MCINNIS.D MCINNIS.E L MCINTOSH.H D MCKEEVER.R F MCKENNA.E N	820/180044 6210220315 8210280020* 8210250141* 8010210036	50-261 PA 50-367 DAPP, 50-3
MATTOOM, R J MATTOOM, R J MATUSCHECK, R J MASURA, F MASURA, R MASURA	8210010169* 8210070032* 8210270046 8210170694* 8210180419*	FGIA 50-289 6 40-878! 50-373 0 50-201 P	MCCULLOCH, W H MCDERMOTT, D MCDERMOTT, D MCDERMOTT, D MCDERMOTT, D	8210150571 8210120427 8210120483 8210210036 8210210174	NUREO CONTRACT CONTRACT CONTRACT CONTRACT	MCKENNA, M MCLEAREN, T MCLEAREN, T MCLEAREN, T MCLENDON, G D	8210050206* 8210120361 8210120416 8210120540 8210150347	50-463 00*18401 50-367 00*15811 50-042
MAURIN.L V MAURIN.L V MAURIN.L V MAURIN.L V MAURIN.L V	8209150432 8209150438* 8209220135 8210010370 8210040078	70-2946 70-2946 50-382 A 50-382 F 50-382 S	MCDERMOTT, D MCDERMOTT, D K MCDERMOTT, D K MCDERMOTT, D K MCDIARMID, R C	8210280370 8210130008 8210190001 8210260237 8210250356	CONTRACT CONTRACT CONTRACT CONTRACT PROJ	MCLEREN, T MCMURRAY, C M MCMURRAY, C M MCMURRAY, C M MCMURRAY, C M	8210270428 8210019375 8210010375 8210150309* 8210150324*	00mlx4* 50-322 50-3-2 50-322 50-322
MAURIN.L V HAURIN.L V MAURIN.L V MAURIN.L V MAURIN.L V	8210040110 8210040168 8210040191 8210130174 8210130243	50-362 A 50-382 F 50-382 A 50-382 S 50-382 S	MCDIARMID, R C MCDONALD, C K MCDONALD, J A MCDONNELL, E J MCDOWELL, J	8210250354 8210240493* 8210150303* 8210120550* 8210260091*	PROJ 50-358 E 50-390 G Contract Haste Mgt	MCMURRAY, C M MCMURRAY, C M MCMURRAY, C M MCMURRAY, C M MCMURRAY, C M	8210150337* 8210150351* 8210150345* 8210150373* 8210150402*	50-322 50-322 50-322 50-322 50-322
MAURIN, L. V MAURIN, L. V MAURIN, L. V MAURIN, L. V MAURIN, L. V	6210130245 8210130551 8210130564 8210170345 6210170542	50-382	MCDUFFIE.M A MCDUFFIE.M A MCDUFFIE.M A MCDUFFIE.M A MCDUFFIE.M A	8210050106 8210050125 8210190512 8210200032 8210200084	50-400 A 50-400 A 50-400 A 50-400 C 50-400 C	MCHURRAY, C M MCMURRAY, C M MCMURRAY, C M MCMURRAY, C M MCMURRAY, C M	8210150410* 8210150422* 8210150527* 8210250858 8210250858	20-355 20-355 20-355 20-355
MAURIN, L V MAURIN, L V MAURIN, L V MAURIN, L V MAURIN, L V	8210250217 8210250242 8210250254 8210250341 8210250355	50-382 S 50-382 S 50-382 S 50-382 S 50-382 A	MCDUFFIE, M A MCFARLAND, C R MCFAUGHY, J P MCGARRY, J M MCGARRY, J M	8210240442 8210150315* 8210080282 8210050202 8210050202	50-400 A 50-370 Q 50-416 S 50-413 Q 50-413 Q	MCMURRAY, C M MGMURRAY, C M MCMURRAY, C M MGNEILL, C A MCNEILL, C A	8210250059+ 8210290283 8210290283 8210040324 8210060285	50-322 50-322 50-322 50-333 50-333
MAURIN, L V MAURIN, L V MAURIN, L V MAXWELL, O F MA(WELL, J C	8210260362 8210270190 8210290438 8210220163* 8210290035	50-382 F 50-382 K 71-6574 50-400 Q ACRS	M CARRAY, J M M CARRAY, J M MCAAUGHY, J P MCAAUGHY, J P MCAAUGHY, J P	8210050208* 8210050208* 8210010234 8210010243 8210040201	50-413 G 50-413 G 50-414 F 50-416 S 50-416 S	MCNEILL, C A MCNEILL, C A MCNEILL, C A MCNEILL, C A MCNEILL, C A	8210120240 8210150263* 8210190069 8210200018 8210260170	50-311 50-333 50-333 50-333 50-333
MAKHELL.J C MAY.E L MAYER,L O MAYER,L O MAYER,R L	8210270035 8210130225* 8210150174 8210150381 8107270146*	ACRS 50-27 S 50-263 S 50-282 S 50-284 O	HCGANGHY, J P MCGANGHY, J P MCGANGHY, J P MCGANGHY, J P MCGANGHY, J P MCGANGHY, J P	8210040224 8210080120 8210080184 8210080223 8210080277	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S	MCNEILL,C A MCNEILL,C A MCNEILL,C A MCNEILL,H M MCNIVEN,H D	8210240304 8210240338* 8210240378 8210240558* 8107270144*	50-333 50-333 50-333 0A979 50-265
MAYES,R L MAYES,R L MAYES,R L MAYES,R L MAYES,R L	8107270169* 8107270174* 8107270178* 8107270182* 8107270185*	50-264 0 50-266 0 50-266 0 50-266 0 50-266 0	MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P	9210080284 9210080295 9210150011* 9210150019* 9210150024*	50-416 5 50-416 5 50-416 Q 50-416 Q 50-416 Q	MCNIVEN, H D MCNULTY, A MCNULTY, A MCTIERNAN, T J MEDFORD, M D	8107270174* 8210040001 8210070153 8210280019* 8210260450	50-266 CONTRA CONTRA FOLA 50-206
Mayes, R L Mayes, R L Mayes, R L Mayes, R L. Mayes, R L.	8107270188* 8107270191* 8107270194* 8107270194* 8107270198*	50-244 0 50-246 0 50-264 0 50-266 0 50-266 0	P C.YHOUADOM P C.YHOUADOM MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P	8210180104 8210190417 8210190561 8210220065 8210220131	50-416 R 50-416 S 50-416 S 50-416 S	MEDLOCK, R L MEHAFFEY, R F MELKONIAN, E MENCZER, W B MENDENHALL, E E	8210150444 8210040187* 8210290309 8210040005 8210040405*	40 - 845 50 - 285 50 - 208 50 - 254 50 - 254
MAYES,R L MAZETIS,G R MCALPINE,E J MCALPINE,E J MCALPINE,E J	8107270199* 6205050480* 6210010317* 6210010361* 6210010371*	50-266	MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P	8210220158 8210220176 8210220176 8210220257	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S	MENDEZ, R MENDONCA, M MENDONCA, M MENTER, L MERCER, J W	8210040384* 8210170501* 8210280303* 8210270143 8210120350*	50-3/3 50-361 50-2/5 XPDRIL CONTRA
MCALPINE,E J MCALPINE,E J MCALPINE,E J MCBREARTY,R A MCBREARTY,R A	821010378# 8210150067# 8210150204# 8210210264# 8210270280#	70-824 70-1113 70-143 50-220 9 50-293 9	MCGAUGHY,J P MCGAUGHY,J P MCGAUGHY,J P MCGAUGHY,J P MCGAUGHY,J P	8210220278 8210220284 8210220428 8210220428 8210220458 8210260445	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S	MERKLE, J O MERRIWEATHER, N MERRIWEATHER, N MERRIWEATHER, N MERRIWEATHER, N	82:0050504 82:0010216# 82:0010384# 82:00:0433# 82:0220189#	RES 50-389 50-404 50-516 50-438
MCBRIDE,L M MCBRIDE,L H MCBRIDE,M F MCCABE MCCABE,E C	8210130349* 8210190667* 8210280250 8210060376 8210130405	50-247 R 50-247 R 50-287 Q 50-219 S 50-387 S	MCGAUGHY,J P MCGAUGHY,J P MCGAUGHY,J P MCGAUGHY,J P MCGAUGHY,J P	8210260513 8210290050 8210290073 8210290124 8210290193	50-416 S 50-416 S 50-416 S 50-416 S 50-417 B	METZGER, J R MEYER, G W MEYER, J F MEYER, J F MEYER, K A	8210150136# 8210210056# 8008130744 8009080464 8210120399#	70-821 50-281 50-247 50-3 50-331
McCabe, e c McCabe, e c McCabe, e c McCabe, e c McCabe, e c	8210150235# 8210170714# 8210270210# 8210270366 8210150202#	50-317 0 50-317 0 50-352 0 50-277 5 50-277 0	MCGAUGHY.J P MCGAUGHY.J P MCGAUGHY.J P MCGRATH.J R MCGUIRE.D R.	8210290311 8210290340 8210290348 8210120308* 8210080228*	50-416 8 50-416 8 50-416 5 50-259 0 50-321 0	MEYER, OR MICHEL, CJ MICHEL, GJ MICHEL, GJ MICHEL, GJ	8210120347 8210220345 8210260568 8210260571 8210270235	RES PR 70-14: 70-14: 70-14:
MCCARDELL, R K MCCLESKEY, K E MCCLESKEY, K E MCCLESKEY, K E MCCLESKEY, K, E,	8210150412 8210150296* 8210150309* 8210150324* 8210150337*	RES 50-322 0 50-322 0 50-322 0	MCGUIRE.D R MCGUIRE.D R MCGUIRE.D R MCGUIRE.D R MCGUIRE.D R	82102102239* 8210150380* 8210180007* 8210210206* 8210210223*	50-395 Q 70-143 50-348 Q 50-13 Q 70-1201	Michelbon, C Michelbon, C Michelbon, C Michelbon, C Michelbon, C	8009240202 8107010161* 8107090355* 8108240273* 8108270056*	50-33( 50-36) FOIA FOIA FOIA

ROHIUA	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR	ACCEBSION NUMBER	SUBJECT	
MICHELSON C	8109250504#	FOIA		MIDURA: H J	8210270216	50~272	S	YILLS/L M	8210070255	50-259	p
HICHELSON, C	*4E00B\$901B	50~312	<b>S</b>	L H ARUGIN	8210290310	50-272	S	MILLS, L M	8210070348	50-438	Α
HICKELSON, C	8110140456*	FOIA		HIDONY'H A	8210290353	50-272	S	MILLE.I. M	8210080150	50~390	ន
HICKELEOK, C	8110190933*	FOIA		WIELE W F	8210150178* 8210070017	50-322 CONTRACT	Т	WILLENE M	8510080198	50-390	8
n i i HELEON. C	8111040130*	FOIA		MILES E B	a2100/001/	CONTRACT		MILLS, L M	8510080518	50-259	P
SICHFUSON C	81111910424	50-206	G .	MILES E B	8210070456	CONTRACT		MILLELL H	82(0080219	50-259	G
HICHEL SOM C	8112020725*	LDIA		MILETI D S	8210150223*	50-322	<u>T</u>	MILLS, L M	8510080555	50~438	5
HICKELSON C	8112210193*	FOIA		MILETI D S	8210150223* 8210150517*	50-322	Ŧ	MILLS, L M	8210080247	50-390	s
MICHELEON C	9201170040* 9201170276*	F01A F01A		MILINAZZO, P. L. MILINAZZO, P. L.	821015052A*	04 <del>9</del> 99 04 <del>9</del> 99		MILLS, L H	8210080255	50-390	5
MICHELSON C	8501130536*	CHIM		MICHWESON C	\$510[30350*	GM 777		HILLSIL H	8210080278	50-478	ន
#3CHELISON C	8201200453*	50-255	S	MILLER D E	8210050112#	50-295	Q	MILLS.L M	8510080580	50~370	6
թքվիանև≲նՈՒ C	8202030072* 8202180457	FOIA HISC		WICTER'D 2	9210050236 9210050236	50-309 50-309	G G	MILLS, L. M	8210080291	90~390	8
HICHELEON, C	8203100549*	50~313	s	HILLER, D S	B210200065	50-307	Ğ	MILLS C M	8210080272	50-438	S
HITHELEON, C	8203300270#	FOIA	5	MILLER, D S	6210200065	50-309	o o	WILLS L M	8210080307	50-436 50-390	g g
MICHELSON C	@f03100C.0	•		, accent b				MILLS, L M	8210080310	30-370	a
MICHELSON C	8203310089# 8205130114#	50-311 50-293	P P	MILLER, D S	8210270303 8210270303	50-309 50-309	0	MILLS, L. M	R210120284	50~327	P
#1 JHFLEON C	6205040401*	FOLA	r.	MILLER, D S	8101500355*	50-307	ř	HILLS L H	6210130142	50~259 50~327	P
HICHELEON, C	*991010199	50-416	8	MICLER J R	0210050052	50-373	Q.	MILLS L M	8210130150 8210130247	50-327	ŝ
MICHELSON C MICHELSON C	8210010048*	FOIA	=	HILLER, J R	0210050102	50-305	ē.	MILLS.L M	0210130379	50-390	Š
UTCHETSON &								CICCO, L D	0510:00011		
~1CHELEON C	0210010073#	FOIA		NEFFER 1 B	6210050308	50-371	Q.	MILLS, L M	8210139384	90-390	В
HINHELEON, C	0210050031*	A103		MILLER J R	621005035 <i>9</i> 6210050365*	50~186 50~186	Q Q	MILLS. L. M	8210130407	50-438	ь
MICHELSON, C	8210050116* 8210050473*	101V		MILLER, J.R MILLER, J.R	B210260471	14E	ď	MILLS, L M	9210130521	PR 50~390	s
MICHEL SON, C	*1500400158	FOIA		MILLER, J R	0210290032*	FOIA		WITER'T H	8210130560 8210150181*	50-390 50-438	ø
MICHELEON C								MILLS, L M	95101301014	30-426	U
MICHELSON C	# 3E F0A00150	50 -934	5	MILLER J R	8210290065*	FOIA		MILLS, L M	9210150218	50-257	a
MICHELSON C	8210070412 8210070415	50 -312 50 -259	5 5	MILLER, J R	8210290129 8210060269*	50~409 50~206	Q Q	MILLIGIL H	8210150230*	50-390	a
MICHELSON C	0210070415	MISC	E)	MILLER, L MILLER, L K	8210200014*	50-200	R	MILLE, L M	8210150231*	50-327	G
MICHELSON C MICHELSON C	821000000154	50 244	5	MILLER, L K	8210200090*	50~277	R	MILLS,L M MILLS,L M	6210150241* 6210150251*	50-390 50-390	0
		- '						HILLEN E #			
MICHELSON, C	8210080104	50~250	ន	MILLER, M E	9210040099	50~445	o o	MILLS,L M	8210180117	50~327	P
MECHELSON C	6210080106* 8210080264	FOTA TOPREP		MILLER, M E	0210050259 0210270176	50-456 50-537	0	WILLEY F W	0210170307	50-370	8
MICHELSON C	8210080284	50-2H7	ទ	MILLER, M E MILLER, M I	6210050227*	50-329	ō	HILLEY L M	6210190357	50~370	G A
MICHELSON C MICHELSON C	8510170157	50-296	ğ	MILLER, M I	9210090229*	50~329	ğ	MILLS, L H	8210190467 8210190528	50-438 50-438	A
ALCHEL SDU'C								MILLBIL M	EL2 ( D 1 70 3 & C	110.470	ω
MICHELEON	8210120370	MISC	9	HILLER, M I	6210130373	50-454	Q	MILLS.L M	8210190755	TOPREP	
MICHELSON C	8210130077	50 334 50-266	b J	MILLER, M. I	8210130373 8210250211	50~454 50~456	G G	MILLEIL M	8210220071	50-438	8
HICHELEON C	8510550351 8510510004	90-280	1-	MILLER, M J	0210250211	30-456 30-456	ő	HILLER H	8210220098	50~390	8
MICHFICHER M MIDURALH J	0210010045	50 -311	S	MILLER, N E	6210120092	NUREC	•	MILLS.L H	8210220223 8210220223	50-257 50-390	G G
utfinewiti s		-						MILLBAL M	GRIGAEORRO	50 1170	•
HIGHPA, H.J.	8210010121	50+311	ទ	MILLER, N E	0210120102	NUREO		MILLS.L H	8210220225	50-390	F
MIEURA, H. J.	0210010144	50 -31 i 50~272	s S	MILLER, R I	6210250037 6210120055*	71 9094 FOIA		MILLB.L M	8210220271*	50-430	O
MIDONA N	8210010181 8210010237	50-272	S	HILLER, W O	8210040429	50-275	Р	WILLSOF W	8210220350	50~438	5
HIEUNA, N. J	02100103344	50 -311	S	MILLER, W O	8210040430	50-518	A	MILLS.L. M	8210220422* 8210220466*	50~438 50 • 370	G G
MIDUHA, H. J.								HILLS, L. H	05104504004	20 -370	\ <b>4</b>
HIDDAY HIJ	821001938 1 8210019407	50 -272 50 -311	6 5	MILLER, W.O.	8510150033 8510090003	50-204 50-255	р Р	MILLS, L M	8210220474*	50-327	Q
MICORA, H J	8210010407	50-311	9	MILLER,W O MILLER,W O	6210130428	71-9010	,	WILLS! L W	B210250067	50~260 50~257	b b
ндрукан Ј нарукан Ј	0210010455	50-311	ŝ	MILLER, W O	8210150432	10-8102		WILLS F. W	8210250096 8210250100	50-390	5
MIDURA H J	8210070221	50 -311	ŝ	MILLER, W O	6210150433	70-1143		MILLSIL M MILLSIL M	8210260100	50-430	S
								CILLED L II			
MIDURA H J	6210070243 6210020344	50-311	8 8	MILLER, W. O.	8210180316	70-36		MILLBIL M	0210260107	50-438	뚕
MIDURA H J	6210070246 6210070249	50-311 50-311	ត 5	MILLER, W O MILLER, W O	8210180340* 8210180341*	FOIA		WILLS L H	6210260174	50 -390	F B
L H ARUGIN	0210070254	50-311	8	MILLER, W O	8210180389	50-349	p	MILLS, L H	8210260186 8210260189	50~390 50 390	ਸ F
talbown in A	0210070305	50 -272	9	HILLIONN H H	0210070304	50-322	ន	Milleil H Milleil H	8210260167	50-370	,
ARMITTELL A.								HILLEDIG D	was a value of		

AUTHOR		CATEGOR		ACCESS IO NUMBER	N SUBJEC		AUTHOR	ACCESSION NUMBER	4 SUB FCI CATEUD
MINGR.G C MIRAGLIA.F MIRAGLIA.F J MIRAGLIA.F J	8510180308 8510150054	50-237 50-498 50-443 50-528	T MOYER, D J P MROCZKA, E J A MROCZKA, E J D MROCZKA, E J A MROCZKA, E J	821004015 821001037 821001037 821007025 821007025	6 50-336 6 50-336 0 50-245	5	MUSDLF, D MUSDLF, D MUSDLF, D MUSDLF, D MUSDLF, D		90-263 90-263 90-263 90-264
MISBREKER, J MITCHELL A D MITCHELL D G MITCHELL D G MITCHELL D G MITCHELL D G	8210210034 8210010180 8210130361 8210130371	50-259 50-397 50-387 50-387	F MRGCZKA, E J S MRGCZKA, E J S MRGCZKA, E J S MRGCZKA, E J S MRGCZKA, E J	8210070304 8210070304 8210070346 8210070346 8210130228	50-245 50-245 50-245	5 5 5 5	MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D	8210250 is 4 8210260194 8210260209 8210270262 8210270219	50 , 82 50 262 50 263 50 262
MITCHELL, D G MITCHELL, D G MITCHELL, D G	8210130389: 8210210293: 8210210434: 8210210446: 8210250377:	* 50~387 * 50~387 * 50~387	S MRDCZKA.E J HRBCZKA.E J HRBCZKA.E J HRBCZKA.E J HRBCZKA.E J MRBCZKA.E J	8210130228 8210190472 8210210155 8210210155 8210210425	50-336 50-336 50-336	8 0 8 8	MUSOLF. D MYERS. D CI MYERS. D CI MYERS. D CI MYERS. D CI	8210290249 8210010205 8210010415 821022017 }	948 ■ 50 124 ■ 90 124 ■ 50 424
MITCHELL, D G MITCHELL, D G MITTL, R L HITTL, R L MITTL, R C	8210250385* 8210280219* 8210130554 8210220326 8210060183		HROCZKA, E J HROCZKA, E J HROCZKA, E J	8210210425 8210220060 8210220060 8210220103 8210220103	50-336 50-336	5 5 5 5	MYERS, R. V MYERS, R. V NACAR, A NADIPURAM, P	821022050   8210020189 8210210312 8210130724 62101301123	50 572 50 572 NURFO
MIZUNO.0 S HODES.M C MOELLER.D W MOELLER.D W MOELLER.D W	8210130292 8210220314 82100101119* 8210040367* 8210050436*	50~366 S	MROCZKA, E J MROCZKA, E J HROCZKA, E J MROCZKA, E J MROCZKA, E J	8210220112 8210220195 8210220195 8210240432 8210240432	50-245 50-245 50-245 50-336 50-336	5555	NAIDU, K. R NAIDU, K. R NAIDU, K. R NANCE, C. R NAPIER, B. A	8210130 374x 8210130957x 8210170787x 8210070358x 8210270041x	50 J() 50 461
MDELLER, D W MOELLER, D W MOELLER, D W MOKL G MONDEN, T	8210050476* 8210050542* 8210060079* 8210280198* 8210270452*	FOIA FOIA FOIA 50-277 P XPORTLIC	MUCHA, E MUELLER, C J MUELLER, C J MUELLER, J J MULHOLLAND, J D	8202010167* 820827001 9 820827001 9 8210200106* 821013001 4*	50-219 ACRS ACRS 70-820	P	NAPUDA, O  NARAYANI, I V  NARDI, A J  NARDICI, P B  NARDICI, P B	82102900724 82101907204 82101301804 82102203274	50 259 6 50 261 8 50 22 8 50 38 8
MONTGOMERY, D ; MONTGOMERY, D ; MONTGOMERY, D ; MONTGOMERY, D ; MOON, C W	8210150219* 8210150239*	50-321 0 70-1201 70-27 50-269 0 50-522 A	MULLINS,C B MUNTZING,L M MURDOCK,E S MURDOCK,E S MURLEY,T E	8210150567 821020379 8210180415 8210180420* 8103090389*	NUREG PR 40-6622 40-6622	s	NATHAN, S. J NAVE, E NETLD, J NETLL, J H	8210080.494 × 821013089 + 8210130189 + 8210130142 × 8210130142 × 8210180128 + 8210180128 + 8210180128 + 8210180128 + 8210180128 + 8210180128 + 8210180128 + 8210180128 + 8210180128 + 8210180128 + 8210180128 + 8210180128 + 8210180128 + 8210180128 + 8210180128 + 8210180128 + 821018018018018 + 821018018018 + 821018018018 + 821018018018 + 821018018018018 + 821018018018 + 821018018018 + 821018018018 + 821018018018018018 + 821018018018018018 + 821018018018018018018018018018018018018018	70 457 5 50 451 6 50 457 4 50 257 5
MOORE, D E MOORE, D E MOORE, J MOORE, J E MOORE, R D	8210260226* 8210260255* 8210260259 8210260230 8210270060*	50-321 Q 50-327 Q 50-247 Q 50-247 G 50-10 F	MURLEY, T E MURLEY, T E MURLEY, T E MURPHY, A J MURPHY, C E	8104240059* 8109220915* 8111240912* 8210190002* 8210190342*	FOIA FOIA FOIA CONTRACT		NEILL, J K NCISLER, J II NCLSON, C C NELSON, C II NELSON, C II	82101802264 82101805294 8210880497 8210860391	50 463 s 50 463 s 50 463 s 50 469 s 70 25
MODRE,R E MODRE,R H MODRE,R N MODRE,R N MODRE,R N	8210270035* 8005270822* 8210270103 8210270114 8210270243	50-537 Q FOIA XPORTLIC XPORTLIC XPORTLIC	MURPHY, D D MURPHY, D E MURPHY, D E MURPHY, D W MURPHY, D W	8210220406* 8210040412* 8210260222* 8210290371* 8209140027*	50-438 50-259 50-259 50-259	0 8 5 5	NELSON, I NELSON, I NELSON, I NELSON, I C NELSON, I C	6210020 496# 6210070 315* 6210070 127* 6210070469# 6210070 310*	70 25 50 517 6 50 517 6 50 517 6 50 517 6
MOGRE, R N MODRE, S N MODRE, V A MORGAN, C MORGAN, C	9210280431 8210130117 8010240329 8210040235 8210040235	MISC 50-413 p 50-247 p 50-247 g 50-247 g	MURPHY, D W MURPHY, M E MURPHY, W P MURPHY, W P MURPHY, W P	9209210923* 8210190349* 8210040113 8210130189 8210130447	50-309 50-285 50-271 50-271	Р О О R	NELBON, I C NELBON, I C NELBON, I C NELBON, I C	821007032 to 02100703324 02100703155 02100703474 0210210016#	50 51/ ( 50 51/ ( 50 51/ ( 50 51/ ( 50 51/ ( 50 51/ (
Morgan, C Morgan, C Morgan, C Morgan, C Morgan, C	8210250081 8210250081 821025021 <i>6</i> 821025021 <i>6</i> 8210270271	50-247 0 50-247 0 50-247 0 50-247 0 50-247 0	MURPHY, IF P MURPHY, IF P MURRAY, B MURRAY, B MURRAY, B	8210220418* 8210270432* 8210070374* 8210120073*	50-271 50-271 40-6622 50-382	P Q F Q	NELSON, R H NELSON, R H NELSON, R L NELSON, R W NELSON, W R	8210120118 8210190903 8210760202 8210760200	50 N/3 S 50 N/3 S 50 N/5 Q
MORGAN, C MORGAN, W MORGAN, W MORIARTY, J M MORISI, A V	8210290271 8210190412* 8210250348* 8210220417* 8210050146	50-247 G 50-247 B 50-247 S 0A979 50-293 0	MURRAY, P L MURRAY, P L MURRAY, P L MURRAY, P L	621022028 (* 6210240457 6210240457 6210240445* 6210240445*	50-313 ( 50-309 ( 50-309 (	0 9 9	NERSES, V NERSES, V NERSES, V NERSES, V NERSES, V	8510186599 8510186593 8510136205* 8510136922	865, 50 Hd y 50 Td1 P 50 Hd E 50 Hd A
MORISI.A V MORISI.A V MORKEN.D J MORRILL,P J	8210250085 8210250372*	50-293 P 50-293 Q 50-293 P 50-213 P 50-275 Q	MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D	8210050323 8210050355 8210070006# 8210130124 8210130356	50-346 E 50-346 E 50-346 F 50-346 E	3 5 5	NERBES, V NERSES, V NETI, B NEUMANN, M R	821019014 8210210251 8210210251	50 763 A 50 763 A 50 763 A
MORRIS, D O MORTON, D K MORTON, K V MORTON, K V MORTON, K V	8210150567 8210120300* 8210060424* 8210120432*	NUREO 50-213 P CONTRACT CONTRACT CONTRACT	MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D	8210130404 8210180131 8210190254 8210190358	50-346 8 50-346 8 50-346 8 50-346 8	<b>;</b> ;	NEUMANN, M R NEWMAN, J R NEWMAN, J R NEWMAN, J R NEWMAN, J R	8210290043 8210070120 8210070120 8210070147 8210070147	40 0697 50 466 0 50 466 0
MORTON, K V MORTON, K V MORTON, K V MORTON, K V MORTON, K V	8210120488* (8210130014* (821019063* (8210190177* (821019017* (821019019017* (82101	CONTRACT CONTRACT CONTRACT CONTRACT	MURRAY, T D MURRAY, T D MURRAY, T D MUSOLF, D MUSOLF, D	8210250226 8210250270 8210260283 8210280078 8210010036	50-346 8 50-346 P 50-346 9 50-346 9 50-263 P		NEWMAN, J R MEWMAN, J R NICHOLAB, H H NICHOLAB, J B NICHOLAB, J B	8210210363 8210210363 8210290356# 8210120073#	50 498
MORTON, K V HORTON, K V MORTON, K V MORTON, K V MORTON, K V	8210210038* C 8210210178* C 8210210570* C 8210210581* C	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D	8210010041* 8210010060 8210040123 8210050319 8210060258	50-263 P 50-263 P 50-282 P		NIX'H C NIX'H C NIX'H C	8210010094 8210010094 8210010094	50 313 4 50-10 6 50-278 0 1 50-366 5
MORTON, K V MORTON, K V MORTON, K V MOSELEY, N C	8210260240* C 8210260561* C 8210260374* C	ONTRACT ONTRACT ONTRACT ONTRACT	MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D	8210060377 8210060380# 8210130260 8210130261	50-263 g 50-263 p 50-263 p 50-263 p		MIX,H C MIX,H C MIX,H C MIX,H C	8210060244 8210060287 8210060317 8210080234	70-365 S 70-365 S 70-365 S 70-366 S
MOURY, W.R.	OCIACOA	0-329 q Portlic	MUSOLF, D MUSOLF, D	8210130510 8210130510	50-263 p 50-304 q 50-263 p		NIX, H G, NIX, H G, NIX, H G NIX, H, G	8210130183 8210130256 8210130256	0-321 R 10-366 S 10-366 S 0-366 S

яснты <sub>н</sub>	NUMBER C	BUBJECT CATEGORY		ADHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	Y	AU THOR	ACCESSION NUMBER	SUBJECT CATEGORY	
14 H C 14 H C 14 H C 14 H C 14 H C	8210130541 50 8210190504 50 8210190595 50 8210220219 50	0-366 S 0-366 S 0-366 S 0-321 S		O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8210010016 8210010019 8210010025* 8210010035 8210010031	State Pro 50-32! 50-32! 50-257 50-251	9 9 9 9 9	GTT.L J OVERBECK.G J ONCZARSKI.P C CHSLEY.G F GWSLEY.G F	62(02(0039 62(0050068* 62(0270421 62(0040229 62(0130123	NUREG 50-409 P RES TOPREP 50-316 P	•
10 H C 10 H C 10 H C	8210290096 50 8210290206 50 8210290206 50	0-366 S 0-321 S 0-366 S 0-321 S 0-321 S		O REILLY, J P O'REILLY, J P O'REILLY, J P	9210010052 9210010102 8210010112 8210010227 9210010238*	70-143 50-400 50-324 50-348 50-280	@	ONSLEY, 0 F OWBLEY, 0 F OWBLEY, 0 F OWBLEY, 0 F	8210150033 8210150173 8210190502 8210270092 8210270214	50-316 P TOPREP 50-219 P TOPREP TOPREP	
IX H G IV H G IV H G IV H C IV H C	8210290349 5 8210290357 5 8210290373 5	2 155-0 2 155-0 3 345-0 5 155-0 4 445-0		0.4007E'7 b 0.4617TA'7 b 0.4617TA'7 b	8210010326 8210150020* 821020387 8210130559* 8210010401	50-259 50-369 50-438 50-247 50-3	0 0 0 0 P	PACE, D L PACE, P PACE, P L PACE, P L PACE, P L	8210220242* 8210130542* 8210010174* 8210040212* 8210080257*	50~416 S 50~335 S 50~335 S 50~251 S 50~250 S	3 3
12 H H H C 4V V S C 4V V S C 4V V S C 4V V S	7812200285* 5 7907280105* 5 8001300616* 5	0-8355 60-266 P 60-266 P 60-266 P 60-327 P	ı	0.100FE' A D 0.100FE' A D 0.100FE' A D 0.100FE' A D 0.100FE' A D	8210010409* 8210010425* 8210010443* 8210040141 8210040232	50-3 50-3 50-3 50-247 50-247	р Р Р 5 Т	PACE.P L PACE.P L PACE.P L PACE.P L PADMANABHAN.M	8210130462* 8210150039* 8210260117* 8210260369* 8210050388	50-335 5 50-335 5 50-250 5 50-335 5 NUREC	3
OMANAV S PREMIAUGIL R PREMIAUGIL B PELIOSIG E PELIOSIG E	8210260309 7 8210260402 7 8210040230 5	50-266 0 70-1257 70-1257 50-456 0 50-461 0	)	0.100FY D 0.100FY D 0.100FY D 0.100FY D 0.100FY D	8210060394 8210070361 8210120253 8210130277 8210130411	50-247 50-247 50-247 PR 50-247	8 6 P 8	PAGE,R G PAGE,R G PAGE,R G PAGE,R G PAGE,R G	8205240010* 8210040392 8210120646 8210220025 8210270434	40-8355 70-371 70-25 70-1257 70-1151	
PELIVA: E E PELIVA: C E PELIVA: C E PELIVA: C E	8210080281 8210190360 8210190361*	50~331 ( 50-331 (	3 3 1 1	0.100FE' 1 D 0.100FE' 1 D 0.100FE' 1 D 0.100FE' 1 D	8210130455 8210170693 8210200078 8210250145 8210260332	50-247 50-247 50-247 50-247 50-247	P G S P	PAGE,R Q PAGE,R G PAGE,R G PAGLIARD,J PAGLIARD,J A	0210260415 6210280417* 6210290383 6210080251 6210040165*		8 0
FE 105. C E -E. 105 C F -E. 105 C F -E. 105. C E -E. 105 C F	8210260176 8210260307 8210260315	50 255 50-454 50-155	0 0 0 0	O'TOOLE, J D CAKLEY, C B DAKUM, K E OBERO, C T OBERO, C T	8210280154* 8210070363* 8210270373 8210150507 8210190673	50-3 50-438 40-8824 14E 14E	F A	PAGE (ARO, J A PAJOMSKI, J E PAJOMSKI, J E PALLADINO, N PALLADINO, N J	8210080204* 8209290189* 8209290225* 8210290373 8201150004*	50-10 I	a F F
ELIUS.CF ELIUS.CF ANTEN L PROMINI J RIS.MR	8210279276 8210220447 8210210477*	50-358 50-334 50-272	a a 5 a R	DESTMANNIM J OHLDACHIR OLSENIA F OLSENIA F OLSENIR M	8210080171* 8210250192 8210040214 8210220231 8210270152*	50-358 50-133 50-13 70-824 XPORTLE	a R P	PALLADINO, N J PALLADINO, N J PALLADINO, N J PALLADINO, N J PALLADINO, N J PALLADINO, H J	8206200086 8206200091 8206200097 8206270053 8206270059	COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO	N N
A1.F O A1.P O R1.P G R1.P O A1.P G	8210120388 8210260531 8210260544	0RG 0RG 0RG 0RG 0RG		A THENTHELD A THENT A THENT A THENTHELD A	8011070227 8010240644 8010270312 8208250417* 8210150376*	50-247 50-247 50-247 50-269 70-143	<u>የ</u> የ	PALLADINO, N J PALLADINO, N J PALLADINO, N J PALLADINO, N J PALLADINO, N J PALMER, R A	8207050040* 8210070441* 8210120151* 8210270003* 8210040209*	FOIA 50-244 COMMISSIO	면 면 () () () ()
TH. 14 9 1001, J. F. 480. J. A. 4814 D. P. 484, D. P.	8210190608* 8210190281* 8210250030		Q Q T	OLSHINSKI, J A OLSHINSKI, J A OMATE, Y OMATE, Y OMATE, Y	8210220420 8210220430* 8107270188* 8107270191* 8107270196*	70-1113 70-1113 50-266 50-266 50-266	a ò a	PALMER.R A PALMER.R A PALMER.R A PALMER.R A PALMER.R A	8210040327* 8210040330* 8210040307* 8210160129* 8210190389*	50-316 50-315 50-316	8888
Ar. T Ar. T II Ar. T II Ar. T II Ar. T IS	8001090220 8006230784 8201210107* 8204790237* 8205130256	50-247 50-247 FOIA 50-289 50-269	P G P	OPEVA, J F OPEVA, J F OPEKA, J F OPEKA, J F	8210250290 8210250290 8210250329 8210250329 8210250414	50-423 50-423 50-423 50-423 50-245	8 8 8 P	PALMER, R.A. PALMER, R.A. PANG, J.F. PANGBURN, G.C. PANGBURN, G.C.	8210190404* 8210190578* 8210080311* 8210120144 8210120445		9 6
AD., T 29 GA. T 29 AP. T 29 AP. T 25	8206140329* 8210010015 8210040424 8210040426 8210050492	50-289 50-373 50-369 50-327 50-362	P P P A	OPEKA, J F OPEKA, J F OPEKA, J F OPEKA, J F	8210260414 8210260519 8210260519 8210270200 8210270200	50-245 50-245 50-245 50-213	P የ የ የ	PAPAY.L T PAPAY.L T PAPAY.L T. PAPERIELLO.C PAPERIELLO.C J	8210080214* 8210190455* 8210250227* 8210080251 8210040202	50-331 50-341 50-341 50-231	0 0 8 0
#/ L ta 	8210070042 8210070045* 8210070051* 8210070055* 8210070061*	50-373 50-373 50-373 50-373 50-373	н н н	OPREA.Q W OPREA.Q W OPREA.Q W OPREA.G W OPREA.G W	8210050327 8210220125* 8210250112 8210250247 8210250257	50-498 50-498 50-498 50-498 50-498	s g s a	Paperiello, C J Paperiello, C J Paperiello, C J Paperiello, C J Paperiello, C J	8210040204* 8210040345 8210050142 8210080146 8210080174	50-331 50-292 50-254 50-358 50-305	0 P Q
(K, T 計 (K, T 計 (K, T 計 (K, T 計 (K, T 社	8210070066* 8210070107 8210080340 8210130595 8210180331	50-373 50-329 50-389 50-554 50-390	H & A A	OPREA.G W OPREA.G W OPREA.G W ORDERS.W ORDERS.W	8210250263 8210230358 8210260452 8210010166* 8210010474*	50-498 50-498 50-498 50-269 50-269	A 8 0 0	Paperiello, C J Paperiello, C J Paperiello, C J Paris, O H Paris, O H	8210150537 8210250297* 8210260220 8210050254 8210150092	50~10 50~346 50~155 50~247 50~247	0 0 0 0
%, Т 11 %, Т 15 %, Т 15 9, А 16 117, № 1.	8210210212 8210210244 8210210498 8210210448* 8210150407	50-400 50-387 50-361 70-2116 40-2259	D P P	ORNSTEIN; H ORNSTEIN; H ORNSTEIN; H L ORNSTEIN; H L	8107180478* 6210080026 6004020420 8010230435 8107070220*	50-289 50-289 50-302 30-302 FOIA	8	Paris, o h Paris, o h Paris, o h Paris, o h Parker, l b	8210210349 8210220338 8210250223 8210270176 8210120319*	50-155 50-155 50-142 50-320 QA999	0000
BAUMER, D A BAUMER, D A BAUMER, D A LEN. J LEN. J N	B210120027* B210120057* B210120075* B210060336* B210220135	FOIA FOIA FOIA 50-312 Nureo	a	ORNSTEIN: H L ORNSTEIN: H L ORNSTEIN: H L ORNSTEIN: H L	8108130268* 8205070377* 8210050141* 8210060460* 8210080024	50~320	5 6	Parker. U 0 Parker. U 0 Parkinson, T W Parkyn. J D Parkyn. J D	9210150012* 9210150079 8209150056 9210010374 9210130270	50-369 50-269 FOIA PR PR	B G
### ### ##############################	8210550304 8210050327* 8210200021* 821020168*	50-237 50-346 50-400 50-400 FOIA	P 3 0	ORNSTEIN, H L ORNSTEIN, H L ORNSTEIN, H L ORNSTEIN, H L OSTER, J	8210080061 8210080124 8210120099 8210120406 8210060283	50-320 50-206 50-321 50-320 50-295	8 P	Parkyu, J d Parson, R M Parsons, R M Parsons, R M Parsons, R M	8210220333 8210130567 8210010360* 8210080180 8210080283	PR 50-400 50-400 50-400 50-400	8 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AU [HOR	ACCF6810N NUMBER	SIGITE CATE <sub>A</sub> SI
PARSONS, R M PARSONS, R M PARSONS, R M PARSONS, R M PARSONS, R M	8210220075 8210220132* 8210220412 8210220484 6210260398	50-400 S 50-400 0 50-400 S 50-400 S 50-400 S	PETTENGILL, H J PETTENGILL, H J PETTIJOHN, S L PETTIJOHN, S L PETTIJOHN, S L	8210210527 8210210530 8006050154* 8006050188* 8008070143*	40-4659 40-299 FOIA FOIA	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8210150540 • 8210170365 8210170725 8210170756 8210170756	0A979 0A979 0A974 0A974
PARSONS,R M PARSONS,R M PASTVA,M J PASTVA,M J PASTVA,M J	8210270258 8210270240 8210010303* 8210010475* 8210040327*	50-400 S 50-400 S 50-324 S 50-324 S 50-324 S	PETTY, J C PETTY, J C PETTY, J C PETTY, J C	8101270870* 8210270087* 8210270199* 8210270313* 8210270365*	FOIA 50-270 5 50-267 5 50-287 5 50-269 S	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTTER, J	8210250101 8210250105 8210260126 8210260494 8210750224	1 i E Davij Davij Davij
PASTVA.M J PASTVA.M J PASTVA.M J PASTVA.M J PASTVA.M J	8210080183* 8210080230* 8210130483* 8210130497* 8210150046*	50-325 S 50-324 S 50-325 S 50-325 S 50-324 S	PEVEY, L E PFAFF, S J PFEFFERLEN, H C PHILLIP, G A PHILLIP, G A	8210040147* 8210220910 8210180050 8210040185* 8210130557*	70-398 40-6659 TOPREP 50-409 G 50-461 G	POITER, J P POULK, R M POULK, R M POWERS, T B POWERS, T B	8210010072 8209160311* 8210190674* 821012009? 8210120102	MIUC 50 125 50 225 5 NUMBS NUMBS
PASTVA.M J PASTVA.M J PASTVA.M J PASTVA.M J PASTVA.M J	8210150308* 8210190759* 8210190762* 8210260266* 8210260318*	50-324 S 50-324 S 50-324 S 50-325 S 50-324 S	PHILLIPS A PHILLIPS H S PHILLIPS L E PHILLIPS K P	8210170207* 8210170741* 8210170746* 8107110478* 8210150495*	50~440 F QA979 QA999 FOIA 50~254 Q	PRATT.C M PREUSS.M PREVATTE.R PRICHARD.R P PROFFITT.N L	8210220324 82102200170 8210220074 8210220074 8210040220	FH 50 454 8 50 274 F 21 4437 50 3 3 4
PASTVA, M J PASTVA, M J PASTVA, M J PASTVA, M J PASTVA, M J	8210240368* 8210270079* 8210270246* 8210270331* 8210270342*	50-325 S 50-324 S 50-324 S 50-325 S 50-324 S	PHUNG.D L PIANKI,F J PIEHL.R H PIEHL.R H PIERRET.J A	8210280110* 8210130504* 8210180123* 8210190588* 8210280184*	F01A 70-1100 50-316 S 50-315 S 40-7580	PROFFITT, W L PROFFITT, W L PULLANI, S V PUZEY, A M PYLE, R B	821004024/4 8210040315* 8210070330* 8210140021* 8210290061	50 443 4 50 344 4 50 ,24 5 50 (84 F
PASTVA, M J PATON, M D PATROU, N PATTERSON, J P PAUL, R A	8210270352* 82100800&6 8210060271* 8210040354* 8210130408*	50~325 S 50~327 G 50~220 S 50~282 G 50~407 Q	PIETRIAKA F PIGOTT, D R PIGOTT, D R PIGOTT, D R PIGOTT, D R	8210120367 8210130309 8210130309 8210150454 8210150454	RES 50-361 0 50-361 0 50-361 0 50-361 0	PYLE.R B GUICK, D R GUICK, D R GUIGG, C GUIHN, M D	8210260429 8210150301* 8210150331* 8210210235 8210150128*	50 .50 . 50 lou 4 50 lou 4 50 .75 . 50 .11 !
PAULICK, L R PAULSON, W PAULSON, W PAULSON, W PAULSON, W A	821020342 8210040153 8210050300 8210200023 8210150298	PR 50-206 P 50-206 P 50-206 P	PIGOTT, D R PIGOTT, D R PILANT, J M PILANT, J M PILANT, J M	8210150482 8210150482 8210010058 8210130318 8210220136*	50-361 G 50-361 G 50-298 F 50-298 F 50-298 G	GUINN, M D GUIRK, J F GUIRK, J F GUIRK, J F GUITTSCHREIBER	8210280074* 8210130416 8210150445 8210150461 8210050424*	50 , 13 5 Tracke Place Tareer Folk
PAULSON, H A PAVIS. G S PAVIL. CKI, S S PAVILCKI, S S PA (SON, E	8210190671 8210250095* 8210250160* 8009040493* 8210270208*	50-204 P 50-318 8 50-317 8 50-266 P 50-338 P	PILANT, J M PILANT, J M PILANT, J M PIRTLE, G L PITCHER, D M	8210220254 8210240328 8210290323 8210290137# 8210190457#	50-298 P 50-298 Q 50-298 P 50-409 Q 50-395 P	GUITTSCHREIBER RAGONE, S RAHE, E P RAHE, E P RAHE, E P	8210050426* 8210040325* 8210080219 8210130447 8210130935*	FD3A 50 1/3 ≠ 100627 2124 50 314 ≠
PAYTON, H C PAYNE, M T PAYNE, M T PEABODY, C A PECK, L S	8210050251 8210210419 8210210419 8209280307 8210190457*	50-266 G 50-400 G 50-400 G NUREG 50-295 P	PLIME, Q PLIME, Q PLIME, Q PLIME, Q PLISCO, L R	8210080030* 8210280120* 8210280424* 8210280445* 8210290132*	50-295 F 50-295 F 50-295 F 50-295 F 50-322 Q	RAHE, E P RAHE, E P RAHE, E P RAHE, E P RAMBLE, E	8210190507 821022015,1 8210260305 8210260340 8210060447#	Tursje Tursee Tulase Tulase So ajj i
PEERY, W W PEERY, W W PEERY, N W PELIZZA, M B R	821010122* 8210150084* 8210220341* 8210180354 8210130222*	50-83	PLOBXI, T J PLUMLEE, G L PLUMCEE, K E POCALUJKA, L P POCALUJKA, L P	8210250297# 8210050239# 8210150290# 8210150290#	50-346 0 50-267 0 50-317 0 50-322 T 50-322 T	RAMPY,L W RANDAZZA,J B RANDAZZA,J B RANDAZZA,J B RANDAZZA,J B	9210290202 921060171 921010252 921010287 9210130360	50 7/4 5 50 957 8 50 N/8 8 50 N/8 8
	*450061010 510140055 510140055 6501300598 6104640011*	50-289 P 50-312 S 50-271 B 50-271 S	POCHAL, N F POCHAL, N F POHLE, J A POLLARD, R D POLLOCK, M S	8210270014 8210270017 8210220515 8210120274 8210040274*	XPORTLIC XPORTLIC 40-8714 50-289 0 50-322 0	RANKIN,W B RANY,J RATTA,A D RATZEL,A C RAUSCH,T J	82102900414 82102800634 82102802644 8210150571 8210010009	50 264 F 50 255 F 70 207 NUMBY 50 217 F
			3 'L	8210040361* 8210260141* 8210150281* 8210150281* 8210150281* 8207180077	50-322 0 50-322 0 50-322 T 50-322 T 50-3 0	RAUSCH, T J RAUSCH, T J RAUSCH, T J RAUSCH, T J RAUSCH, T J	8210080178 8210180176 8210190464 8210190565 8210190780	50 k37 \$ 50-10 # 50 247 F 50 247 F 50 244 #
PERLISAR O PERNYAC	8210270159 8210270239#	50-487 P 50-483 G 50-302 G	POPEC.L K PORTER.F W	8207180077 8210010322 8210130277 8210280388 8210120419*	50-3 D PR PR 71-6601 27-39	RAUBCH, T J RAUBCH, T J RAUBCH, T J RAUBCH, T J RAUBCH, T J	8210250069 8210250114 8210250155 8210250309 8210260485	50 m37 P 50 m54 P 50 m54 F 50 m54 F 50-m37 P
PERNY, C D PERSH, R L PESCHEL, J M PETERS, R F PETERSON, D A	9210150380* 9210180274 9210170675* 8210210556* 8210130145*	70-143 50-387 P 50-266 Q 50-346 P 50-255 R	PORTER, M R PORTER, M R POSNER, P POTAPOVS, V POTAPOVS, V	8210040270* 8210220057* 8210200019 8210040148 8210040171	50-296 8 50-259 8 50-247 0 GA999 GA999	RAWSON, R J RAWSON, R J RAWSON, R J RAWSON, R J RAY, H B	8210060182 8210120291 8210150190 8210270090 8210050008	50-454
PETERSON,M R PETRICK,N A PETRICK,N A PETRICK,N A PETRONE,C D	8210060007 8210080260 8210280252 8210260274 8210070283*	XPORTLIC 50-482 K 50-482 A 50-482 A 50-293 G	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8210040192 8210040333 8210050188 8210050195 8210050284	QA999 QA999 QA999 QA999 QA999	RAY, H B RAY, H B RAY, H D RAY, H B RAY, H B	8210050012+ 8210050014 8210050014+ 8210050024+ 8210050029+	50-341 \$ 50-341 \$ 50-341 \$ 50-341 \$
PETTENGILL, H J PETTENGILL, H J PETTENGILL, H J PETTENGILL, H J PETTENGILL, H J	8210120494 8210120514 8210120529 8210120619 8210120624*	40-8728 40-2259 40-8102 40-8781 40-8781	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8210050287* 8210050292* 8210120222 8210120280 8210120301	QA999 QA999 QA999 QA999 QA999	RAY, H B RAY, H B RAY, H B RAY, H B RAY, H B	8210050032* 8210050037* 8210050041* 8210050044* 8210050048*	50-381 \$ 50-381 \$ 50-381 \$ 50-381 \$ 50-381 \$
PETTENGILL, H J PETTENGILL, H J PETTENGILL, H J PETTENGILL, H J PETTENGILL, H J	8210120634 8210120644 8210210021 8210210315 8210210325#	40-8452 40-6622 40-3453 40-8684 40-3453	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U, POTAPOVS, U	8210120309* 8210120313 8210180513 8210180521* 8210180532	QA777 GA779 GA779 GA779 GA779	RAY, H B RAY, H B RAY, H B RAY, H B RAY, H B	8210050050* 8210050076 8210050078* 8210050101* 8210050151	50-361 S 50-361 S 50-361 S 50-361 S 50-361 S

ROHIUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	TOSUBUS YRGOSTAS
PA: H B PA: H B PA: H B PA: H B PA: H B	8210050234# 8210050261 8210050266# 8210050381 8210050390#	50-361 S 50-361 S 50-361 S 50-361 S 50-361 S	RIBEIRO, J RICCARDELLA, P RICE, D A RICHARDS, B L RICHARDS, S A	8210040183* 6210050427* 8210130235* 8210010317* 8210290132*	50-220 P 50-155 P 50-29 S 70-143 50-322 Q	ROOT, L D ROOT, L D ROOT, L E ROOT, R W ROOT, R W	8210260138 8210260461 8210170156* 8210070277 8210070311	50-331 P 50-331 F CONTRACT 50-440 S 50-440 S
FA1. H B FA1. H B FA1. H B FA1. H B	8210130267 8210130274* 8210130276 8210130285* 8210130469	50-361 S 50-361 S 50-361 S 50-361 S 50-361 S	RICHARDSON, J D RICHTER, L RICKARD, D C RIDGELY, J RIDGWAY, D A	9210180109* 9210170359* 8210260425 8210150535* 8210010435	50-416 R 50-346 8 50-170 G 50-267 P 50-382 G	ROOT, R W ROOT, R W ROOT, R W ROOT, R W ROOT, R W	8210070338 8210070387* 8210130425* 8210130432* 8210280190*	50-460 6 50-460 0 50-460 0 50-460 0
FALLE B FALLE B FALLE B FALLE B	8210130478* 8210130485* 8210130493* 8210130499 8210130508*	50-361 S 50-361 S 50-361 S 50-361 S 50-361 S	RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A	8210070197 8210070197 8210120267 8210120267 8210210266	50-382 0 50-382 6 50-264 0 50-380 0	RODT.R W ROSA.F ROSAND.R ROSASCO.P V ROSE.B	8210280297* 8204300370* 8210280221 8210120384* 8210070127	50-460 Q TOPREP 50-272 Q WASTE MGT 50-454 Q
FA: # B FA: # B FA: # B FA: # B	8210170369 8210170317* 8210170323* 8210170328* 8210170470	50-361 S 50-361 S 50-361 S 50-361 S 50-266 S	RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A	8210210266 8210210372 8210210372 8210260423 8210260423	50-382 0 50-382 0 50-382 0 50-380 0	ROSE, B ROSE, B ROSE, B ROSE, B ROSE, B	8210070127 8210070129* 8210070129* 8210180151 8210210278	50-454 G 50-454 Q 50-454 Q 50-454 G 50-454 O
601.H B 601.H B 601.H B 601.H B	8210190506* 8210250137 8210250140* 8210250207 8210250214	50-206 S 50-361 S 50-361 S 50-361 S 50-361 S	RIEDLINGER B A RIGAMONII, G RIGGLE, E I RILEY, J L RIVELLO, J	8210080311* 6210050204* 8210070241* 8210260150 8210150204*	70-754 50-443 A 50-219 S 50-413 D 50-322 T	ROSE. B ROSE. B ROSE. B ROSE. B ROSE. B	8210210278 8210210384 8210210384 8210250071 8210260380	50-454 0 50-454 0 50-454 0 50-454 0 50-454 0
8A., H B 8A. H B 8A. H B 8A. H B 8A. H B	8210250214* 8210250269 8210250280 8210250280 8210280066	50-361 5 50-361 5 50-361 6 50-206 5 50-206 5	HIZZO, J HIZZO, O HIZZO, O HIZZO, O	8210150223# 8210150250# 8210270269# 8210060369#	50-322 T 50-322 T 50-317 S FOIA FOIA	ROSE. B ROSE. B ROSE. B ROSE. B ROSE. B	8210240384* 8210240384* 8210240293 8210240293	50-454 G 50-454 G 50-454 G 50-454 G 50-454 G
BALHB BALHB BALHAR DWOCNYAR UWONCHYAR	8210280048* 8210280080 8210280084* 8210070393* 8210150274*	50-206 8 50-361 8 50-361 8 50-271 0 50-271 0	R1ZZO, P G R1ZZO, P G R1ZZO, P G R1ZZO, P G ROBERDS, J	8210280200+ 8210280284+ 8210280301+ 8210280313+ 8210190452+	50-318 S 50-318 S 50-317 S 50-317 S 50-362 Q	WOANSCHITD'A C BOLH'? BOLH'? BOSE'B BOSE'B	8210270305 8210270352 8210070240* 8210130272 8210280257	50-454
RATEOR UN READ OF READ OF READ OF READALR	82102801414 8210010328 8210010337 8210150340 8208010022	90-318 S 90-400 G 90-400 G 50-400 G M150	ROBERTS, D E ROBERTS, T K ROBERTS, T K ROBERTS, T K RODERTS, T K	8210210505* 8205060558* 8210120112* 8210120123* 8210120140*	CONTRACT FOIA FOIA 50-537 G 50-537 A	ROUSE, L C ROUSE, L C ROUSE, L C ROUSE, L C ROUSE, L C	8210070301* 8210070310* 8210120360 8210280452 8210280453*	50-537 A 50-537 A FRGJ 70-364 70-364
REAVIS: J A REDECTO J E REDECTO J E	8210190552# 8210190751# 8210070156# 8210130054# 8210180371#	R PAS-06 R PAE-06 TOARTHOO TOARTHOO TOARTHOO	ROBERTS. T M ROBERTS. T M ROBERTS. T M ROBERTS. T M ROBERTS. T M	8210120143# 8210120161# 8210120170# 8210120181# 8210120202#	50-537 A FOIA FOIA FOIA FOIA	rome, c a rome, c a rozak, s rozak, b rubenbtein, l	8210070345* 8210210491* 8210040208* 8210080171* 8011240024*	50-219 Q 50-272 Q 50-331 Q 50-358 Q 50-247 S
AFBELLO, J E AEBELLO, J E AEBEL OVSKI, T REBELEWSKI, T AEBELEWSKI, T	8210190215# 8210090131# 8210060044# 8210210307# 8210290174#	CONTRACT 50-247 0 50-247 0	ROBERTS, T M ROBERTS, T M ROBERTSON, C Q ROBERTSON, C Q ROBINSON, D	8210150469 8210230332* 8210010381 8210220334 8210170694*	50-155 0 50-287 0 PR PR 50-373 0	RUBENSTEIN L S RUBENSTEIN L S RUBENSTEIN C S RUBIN S RUBIN S D	8008219627 8007030334 8108270549* 8204270464* 8111030201*	50~247 P 50-247 P FOIA FOIA FOIA
REDAND R T REED.C REED.J G REED.J Q REED.R F	8210280149* 8210060367* 8210060197 8210070152 8210250247		ROBINSON.D L ROBINSON.S RODRIGUEZ.R J ROEDER.J R ROCERS.A E	8210190426 <b>*</b> 8208290090 8210190278 8210270079 <b>*</b> 8207120253 <b>*</b>		RUFF.A B RUFF.A B RUFK.A B RUNKLE.J RUNKLE.J B	8210010187* 8210150194* 8210220323* 8210210419 8210210348	50-424 Q 50-338 Q 50-370 Q 50-400 Q 50-400 Q
FERDY.R F FERDY.R F REEVES.E A REEVES.E A REEVES.E A	8210280157 8210280272 801(060346* 8210040038 8210280410	50-275 R 50-275 P FOIA 50-364 P 50-348 G	ROOERS, A E ROGERS, H R ROGERS, H R ROGERS, H R ROGERS, H R	8210010224* 8210060221* 8210130452* 9210130579* 8210220062*		RUSSELL, J E RUSSELL, G RUSSELL, G RUSSELL, G	9210210348 9210070459* 9210050178* 9210040044 9210220474*	80-400 Q CONTRACT 0A999 50-318 8 40-6622
REGAN, W H REWAT, T A RELATIONAL W RESTANCE W REVITO W A	8202240446* 8210080032* 8210290423 8210060335* 8210210162*	. 20-10	ROGERS.H R ROGERS.H R ROGERS.P ROGERS.P ROGERS.P	821022085* 8210270279* 8210130214* 8210130368* 8210130328*	50-327 5 50-313 5 50-313 5	RUSSELL. J E RUSSELL. J E RUSSELL. J L RUSSELL. L B RUSSELL. L B	8210250028 8210270177 8210220317* 8210040142 8210040211	40-4622 40-4622 50-160 0 50-317 8 50-318 8
ACT.GEROER.D ACTIZ.W F PETIZ W F PETIA.D A REPFA.D A	8210260113+ 8210150168 8210150272+ 8210190385 8210280240	50-322 f	ROGERS, P ROGERS, P ROGERS, P ROGERS, P ROGERS, R F	8210190526* 8210190558* 8210250298* 8210260123* 8210010031*	+ 50-368 9 + 50-368 8 + 50-368 8	RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L B	8210040216 8210060385 8210060394# 8210130461 8210130543	50-317 8 50-317 6
RESNER, E P RESNER, M E RESNINGFF, M PE   ES, L RENES, L	8210180346 8210280100 8207110023 8210080088 8210080189	* 50-250 P 70-1510 50-295 B	ROCERS.R F ROGGE.J F ROHDE.J E ROHRER.D M ROMAN.T W	8210010327 8210(90271 8210260254 8210190514 8210130350	50-302	RUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSELL, L B	8210130548 8210190290 8210250088 8210250154 8210270237	50-317 8 50-317 8 50-318 6 50-317 6 50-318 8
REYES.L REYES.L PELES.L A REYES.L A REYMOLDS.J R	8210190599 8210280171 8210190449 8210280232 8210050218	* 50-202 0 * 50-255 0 * 50-305 0	ROMINE, W D ROMS, H ROMS, H ROMSY, Y	8210170384 8210260174 8210180258 8210210184 8210210200	* 50-328 B 50-362 A 50-361 Y	RUSBELL: L B RUSBELL: L B RUSBELL: L: B RUSBELL: L B RUSBELL: L B	8210270244 8210270252 8210270265 8210270276 8210270274	90-317 8 90-317 8 90-317 8 90-317 8 90-317 8
REYNOLDS, JR REYNOLDS, US REYNOLDS, US REYNOLDS, US RHEE, S	8210050218 8210130299 8210130299 8210220383 8210050233	50-445 0 50-445 0 PR	ROONEY, V L ROOT, L D ROOT, L D ROOT, L D ROOT, L D	8210210101 8210050307 8210130544 8210130140 8210190464	50-331 9 50-331 P	RUSSELL, L. B RUSSELL, L. B RUSSELL, L. B RUSSELL, L. B RUSSELL, L. B	8210270274 8210270279 8210280134 8210280191 8210280194	50-317 B 50-317 B 50-318 B 50-318 B 50-318 B

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCLSS10N NUMBER	SUBJECT CATEGO: /
RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L B	8210280203 8210280249 8210280263 8210280279 8210280276	50-317 S 50-317 S 50-317 S 50-318 S 50-317 S	SCHULTZ.5 D SCHUMACHER.M SCHUMACHER.M C SCHUMACHER.M C SCHUMACHER.P M	8210130359 8210080171* 8210040208* 8210150543* 8210150592	PR 50-35B Q 50-331 Q 50-10 Q NUREG	Shap Iro. R Shap Iro. R Shap Iro. R Shap Iro. R Shap Iro. R	82:0150402* 82:01504;0* 82:0150422* 82:0150527* 82:0250059*	50-322
RUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSO, H L RUTENKROGER, E	8210280305 8210280318 8210280334 8210250128* 8210150405	50-317 S 50-317 S 50-318 S QA999 70-1739	SCHUMACHER, P M SCHWALB, H R SCHWEIBINZ, E SCHWEIBINZ, E R SCHWEITZER, D G	8210210014 8210210051 8210190627 8210050522* 8210120460	NUREG NUREG 50-358 S 50-483 S RES	SHARISON, S S SHAUB, E SHAUB, T SHAII, A SHAH, A	8208270099 8210270072* 8210210236* 8210080003*	50-322 ( 50-264 , 50-334 , 50-331() 50-331()
RUZICKA, W G RYDER, C RYDER, C RYDER, C P RYDER, C P	8210270067 8210050403* 8210050434* 8210050407* 8210060449*	70-687 FOIA FOIA FOIA FOIA	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8208040341 8210050479 8210050488 8210070218* 8210080068	50-373 P 50-352 A 50-322 A 50-266 P 50-397 A	SHAW, A SHAW, A SHAW, A SHAW, J T SHEA, J	8210080071 8210210537 8210270021 8210200036 8210040233	#PORTLIC 70-2955 #PORTLIC 50-322 : 50-245 F
SABADOS, J N SABADOS, J N SACKETT, M H SAFFELL, B F SAGENDORF, J F	8210010361* 8210150067* 8210220256 8210080054* 8210220149	70-27 70-1113 PR FOIA NUREG	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWINK, W	8210130043* 8210190134 8210210510 8210220032 8210120216	50-414 P 50-352 A 50-322 A 50-414 P REVIEW GRP	SHEA, J SHEA, J SHEA, J SHEA, J J SHEA, J J	6210040293 9210150362 9210250219 9210010320 9210220479	50-245 # 50-245 # 50-245 # 50-245 P 50-245 3
SAIGH, PA BALOHON, SN SALVENDY, O SALVENDY, G SANCIC, D	8210280374* 8210120316* 8208290011 8208290011 8210190435*	CONTRACT 50-259 0 ACRS ACRS 50-333 0	SCINTO, J SCINTO, J SCINTO, J F SCINTO, J F SCINTO, J F	8210050536* 8210170115* 8210170121* 8210170124* 8210280348	50-289 P FOIA FOIA FOIA REVIEW QRP	SHEA. J J SHEA. J R SHEA. J R SHEARCR. D L SHEDLOSKY, J T	8210220486 8210070431= 8210070468* 8210050418 8210210196*	50-245 P FOIA FOIA NUREG 50-245 G
SANDERS.K E SANDERS.W F SANDERS.W L SANDOUIST.G M SANDS.B P	6210070489* 6210220159* 6210010226 6210260234* 6109280175*	FOIA 50-424 0 PR 50-72 R 50-29 S	3 0.11038 U 0.11038 U 0.11038 U 0.11038	8210150032* 8210040126 8210040188 8210050227 8210130197	50-416 0 50-249 5 50-237 6 50-237 5 50-249 8	SHEEHY.E J SHEEKAN.R E SHELLEY.W J SHELLEY.W J	8207180088* 8210220440 8210270203* 8210220487 8210260543	review G= 70-1100 Contract 40-8027 40-8027
SANDS, S.P. SANDUSKY, W.F. SANDY, W. SANFORD, J.C. SANFORD, J.C.	81100500(8* 8210220149 8210290249 8210040024* 8210040024*	50-369 S NUREG PR 50-445 G 50-445 G	SCOTT, D J SCOTT, D J SCOTT, D J SCOTT, D J	8210150044 8210150097 8210180097 8210190403 8210190458	50-237 S 50-249 S 50-10 R 50-249 S 50-249 S	SHEFFELYM Y SHEFFELYM Y SHEFFELYM Y SHEFFELYM Y	8210260565 8210260576 8210270077 8210270086* 8210270242	40~8027 40~8027 40~2041 40~2041 40~8007
SANTELLA, A SARSTEN, O E SASTRE, C SATTERFIELD, R SAUNDERS, O A	8210150112* 8210260205 8210120630 8011210284 8210280046	50-219 S 50-324 S RES 50-247 P 40-8745	SCOTT.D J SCOTT.D J SCOTT.D J SCOTT.D J	8210250268 8210250283 8210250304 8210250328 8210260023	50-237 S 50-237 S 50-249 S 50-249 S 71-9079	SHELLEY, W J SHERR, T S SHERR, T S SHERR, T S SHERR, T S	8210270247+ 8210270095+ 8204200405+ 8204200408+ 8204220144+	40-8027 50-289 4 70-1510 70-1510 70-1510
SAUNDERS,W F SAWICKI,S D SCACE,S E SCARAND,R A SCARAND,R A	8210150103* 8207180055 8210010214* 8210120574 8210220036	50-424 Q 50-440 F 50-213 P WASTE MGT 40-8714	SCOTT. D J SCURRY, N SCURRY, N SCURRY, N SCURRY, N	8210270251 8210120402 8210120404 8210270116 8210270119	50-249 S ORG ORG ORG ORG	SHERR, T S SHERR, T S SHERR, T S SHERR, T S SHERR, T S	8210050451* 8210050456* 8210070418* 8210070421* 8210070434*	70-1510 70-1510 FOTA FOTA FOTA
SCARANO,R A SCHANEN,J F SCHAPKER,J F SCHEINER,C A SCHERER,A E	8210220037 8210130566* 8210150334* 8210200019 8210150306	WASTE MOT 50-305 Q 50-518 Q 50-247 Q 50-470 E	SECOR, D T SEIDLE, W C SEIDLE, W C SEIDLE, W C	8210170457* 8210010175 8210070326 8210120241 8210120246	50-395 P 50-313 0 50-285 0 50-313 0 50-313 0	SHERR, T S SHERR, T S SHERR, T S SHERR, T S SHERR, T S	8210070436* 8210070447* 8210070467* 8210070473* 8210070475*	FOIA FOIA FOIA FOIA
SCHERER, A E SCHERER, A E SCHERER, A E SCHERR, S J SCHERRER, J	8210200022 8210260202 8210270240 8210200001 82102000186*	50-36B P 50-470 B PR 70-143 50-155 Q	SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8210190347 8210190497 8210190531 8210190596 8210220110	50-285 0 50-313 0 50-285 0 50-482 0 50-285 0	SHERR, T S SHERR, T S SHERR, T S SHERRER, J	6210070478* 6210070480* 6210070484* 6210070486* 8208100269*	FOIA FOIA FOIA SO-29 P
SCHERRER, J SCHIFFMACHER, W SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D	8207190431* 8210150168 8210050152 8210050152 8210150035	50-29 Q 50-322 T TDPREP TOPREP 50-335 S	SEIDLE.W C SEIDLE.W C SEIDLE.W C	8210220270 8210220377 8210240178 8210240224 8210280225	50-313 0 50-313 0 50-313 0 50-72 R 50-482 0	SHERWOOD, O G SHERWOOD, O G SHERWOOD, O G SHEWMON, P SHEWMON, P	8210010217 8210050328 8210270046 8207180073* 8208290017	TOPREP 50-447 A 50-447 A Nureo Acres
	8210060354* 8210120440* 8210150257* 8210150265* 8210150290*	50-261 F CONTRACT 50-322 T 50-322 T 50-322 T	BELAN, J C SELBY, D SEMMEL, H SEMMEL, H	8209130461* 8209200475* 8210290006* 8210150341 8210150341	50-293 P 50-29 P COMMISSION 50-155 G 50-155 G	SHEWMON, P SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S W	8208290018 8210010230 8210250130 8210290239 8210290240	50-244
	8210280451 8210190599* 8210120092 8210120102 8210050299	40-8697 50-295 Q ' NUREQ NUREQ 50-483 A	Semmel. H Semmel. H Seniua, P Serini. B Eestak. F	8210210381 8210210381 8210250231* 8210280421* 8210280308	50-155 G 50-155 G 50-346 S 70-2957 50-275 R	SHIFFER, J D SHIM, K SHIM, K SHIMECK, D J SHIRAKAWA, T	8210290219 8210060267* 8210190715* 8210150409 8210040382	50-275
	8210130555* 8210130176* 8210120488* 8210150102* 8210180100*	50-483 G 50-254 S CONTRACT 50-249 S 50-10 R	SHAFER, P N SHAFER, W SHAFER, W D SHAFER, W D SHAFER, W D	8210130416* 8210040337 8210050154* 8210170362* 8210170750*	50-409 0 50-329 5 50-329 Q 50-331 Q 50-329 0	SHIRAKAWA, T SHIRAKAWA, T SHIRAKAWA, T SHIRAKAWA, T SHIRLEY, S J	8210040385 8210040387 8210060471 8210280435 8210080077	XPORTLIC XPORTLIC XPORTLIC XPORTLIC 50-142 C
	8210270254* 8210040221 8210050077 8210130233 8210130241	30-249 B 50-373 P 50-373 P 50-373 P 50-373 P	SHAMLA, W A SHAD, L C SMAPIRO, R SHAPIRO, R SHAPIRO, R	8210080117 8210070205* 8210150234 8210150234 8210150309*	50-263 8 50-266 P 50-322 0 50-322 0 50-322 0	SHIVELY, C SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J	8210270101 8210150464 8210200006 8210260433 8210260447	50-356 P 50-445 £ 50-289 £ 50-289 £ 50-289 £
	8210190506 6210070196* 6210130199* 8209150057 6210220369*	50-373 6 FOIA 50-244 5 FOIA 50-275 H	SHAPIRO, R SHAPIRO, R SHAPIRO, R SHAPIRO, R SHAPIRO, R	8210150324* 8210150337* 8210150351* 8210150365* 8210150393*	50-322 0 50-322 0 50-322 0 50-322 0	SHOEMAKER, C J SHON, F J SHON, F J SHON, F J SHON, F J	8210280269 8210050254 8210070137 8210130333 8210150092	50-289 0 50-247 0 50-440 0 50-440 0 50-247 0

- 15°-17'7	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WOTHER  SHOULE U   8210210349 8210210476 8210220338 8210270176 8210220128#	50-155	SMITH, II G SMITH, P SMITH, P A SMITH, P A SMITH, P A	8210040277 8210130041# 8210040002# 8210040004# 8210120425#	50-316 S CONTRACT CONTRACT CONTRACT CONTRACT	SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	8210130514 8210130523* 8210190432 8210190433 8210190568	50-493 0 90-403 0 50-202 0 50-407 0 50-295 0	
SHORD, E M SHORT R M SHREW, D B SHUTE FILTHOGAREL R	8210050162 8210190746° 8210050530° 8210070240° 8210210504	50-367 0 50-285 R CONTRACT 70-33 50-329 T	SM ( TH, P A SM ) TH, P A SM ) TH, P A SM ) TH, P A SM ) TH, P A	8210120496* 8210120517* 8210120541* 8210120613* 8210130074*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	8210190613 8210190638 8210190707* 8210250072 8210250075*	50~275
Emilie E. M. A. Emiliar OCH, M. B. STEDER, U. D. ETESER U. D. ETERFEN, D. L.	8210180072# 8210010225# 8210050148* 8210240125# 8210120320	FOIA 50-338 0 50-334 P 50-334 P 27-39	SM(1H, P A SM)TH, P A SM)TH, P A SM)TH, P A SM)TH, P A	8210180336* 8210180401* 8210180416* 8210190149 8210190156*	CONTRACT CONTRACT CONTRACT CONTRACT	SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	8210250106 8210260161 8210260387 8210280122 8210280174*	50-409 0 50-305 0 50-454 0 50-373 0 50-461 0
LIEGEL, H FILAT, D & FILDERG J E SELDERG, J E FILDERG, J E	8210180320 8210193063* 8210050374 8210050374 8210150161	50-298 F CONTRAC1 50-440 G 50-440 G 50-440 G	SMITH P A SMITH P A SMITH P A SMITH P A SMITH P A	8210190162 8210190167* 8210190223* 8210210161* 8210210506*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	SPICKLER.I SPILHAUS.A F SPITZBERG.D B SPRENCEL.J F SRENIAWSKI.D J	8210060453* 8210190002* 8210220004 8210120330* 8207070319	50~537 A CONTRACT 70-416 CONTRACT 70-2748
SILBERG.JE EILBERG.JE SILBERG.JE FILBERG.JE SILBERG.JE	8210150161 8210150228 8210150228 8210210284 8210210284	50-440 G 50-440 G 50-440 G 50-440 G 50-440 G	SM(TH,PA SMITH,PA SMITH,PA SMITH,PA SMITH,RD	8210240520* 8210260530* 8210280235* 8210270378* 8210120578	CONTRACT CONTRACT CONTRACT CONTRACT 40-8102	JENIASWAINERS L DINSWAINERS L DINSWAINERS L DINSWAINERS JENIASWAINERS	8210040130 8210050204 8210050314 8210170533* 8210260471	I&E 70-2942 I&E State Prog I&E
SILCERG. JE SILGERG. JE CILGERG. JE CILGERG. JE TILGERG. JE	8210250324 8210250274 8210210354 8210210351	50-440 G 50-440 G 50-440 G 50-440 G 50-440 G	SMITH, R D SMITH, R C SMITH, R M SMITH, S K	821021052  8210210532 8210070 56* 8210280095* 8210150377*	40-3453 40-8681 CONTRACT 50-324 P 50-263 P	STADNICK, S STAHL, D STAHL, D M STAHLE, C STAMIRIS, B	8210130232* 8210130482 8210130482 8210210542 8210205238	50-334 S 50-329 0 50-329 0 50-327 P 50-329 0
ILIERG. J E INEEPO. J E ILVERMAN S ILVIS. R M ILVIS. R M	8210250342 8210280216 8210150495 8210120363 8210270403	50-440 G 50-440 G RES CONTRACT CONTRACT	SMITH.W 0 SMITH.W 0 SMITH.W 0 SMITH.W 0	8210040073 8210040199 8210040201 8210040212 8210040321	50-315 8 50-315 8 50-314 8 50-315 P 50-316 8	STAMIRIS, D STAMPLEY, N STAMPLEY, N STAMSBERRY, W STAMSBERRY, W	8210050240 8210210370 8210050193 8210260515* 8210180007*	50-329 0 50-329 0 50-416 S 50-335 0 50-348 0
1 02.05 0 E 1 02.0 V 1 02.0 V 1 02.0 V 1 02.05 0 E	8210280384 8210190840* 8210120264 821013025# 8210150025#	CONTRACT 50-315 F 50-528 R 50-528 R 50-347 Q	SMITHOUS SMITHOUS SMITHOUS SMITHOUS SMITHOUS SMITHOUS	8210060300 8210180120 8210190266 8210190340 8210190380	50-315 8 50-316 8 50-315 8 50-315 8	STARK, R M STARK, R M STARK, R M STARK, R M STARK, R M	8208270699 8210120445 8210130969 8210220023 8210220436	50-537 A 50-537 A 50-537 A 50-537 A 50-537 A
IT DEADNE P INCLAIR, M INCLAIR, M INCLAIR, M INCEMANT R W	8210040902# 8210070140 8210070140 8210170480 8210150307#	CONTRACT 50-329 0 50-329 0 50-255 0 50-155 0	SMITH.W O SMITH.W O SMITH.W O SMITH.W R SMIEZEK.J H	8210190572 8210190727 8210190749 8210050368 8105040512#	50-315 S 50-316 S 50-315 S NUREO 50-285 P	STARKEY.R B STARKEY.R B STARKEY.R B STARKEY.R B STARKEY.R B	B210130242 B210190240 B210220265 B210220497* B210290074	50-261 R 50-261 S 50-261 S 50-241 Q 50-261 S
10×1/40x B 111,1/40ER, U 1 >1/4,4ER, P 1/4 >11,4ER, P 1/4 >12,4ER, U 1	8210120455 8210280235* 8210170132* 8210220307* 8210010469*	RES CONTRACT 50-324 G 50-321 G 50-375 O	SNICZEK, J H SNICZEK, J H SNOW. B A SNYDER, B J SNYDER, B J	8107170126* 8210050082* 8210170703 8210260535 8210270326	FOIA FOIA 50-244 8 50-320 P 50-320 P	STARKEY,R Ø STARMER,R J STARMESTECKI,R STARMESTECKI,R STARMESTECKI,R	8210270333 8210120354 8203050387 8210010274* 8210040024	50-241 8 WASTE MGT 50-317 0 50-220 0 50-247 0
FCLDS. J. L. FULMOLIT. D. J. LEHSER. R. J. LOJAN K. V. MITH. E. M.	8210080259* 8210290034* 8210040196* 8210210176* 8210120556*	50-395 Q 50-142 F GA999 CONTRACT CONTRACT	SNYDER, S.C. SODA, K. SOLLENBERGER, D. SOLLENBERGER, D. SOO, P.	8210700102 8210150421 8210120494 8210120514 8210120460	RES RES 40-8728 40-2257 RES	STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8210040150 8210040240 8210040318 8210070214 8210070239	50-273
13 TH E M 11 TH C C 11 TH C C 11 TH C C 11 TH C C 11 TH C M	0210120556* 0210040049* 0210130449* 0210220172* 0210040206	CONTRACT 50-24 0 XPORTLIC 70-371 50-286 F	SORRELL, E C SOUCY, A R SPARKS, O L SPARKS, G L	8210190016* 8210190046* 8210010374 8210010248* 8210050203*	50-321 F 50-321 F PR 50-416 S 50-416 S	STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R	8210070268 8210070337 8210070337 8210070362 8210070376	50~219 0 50~220 G 50~309 G 50~333 G 50~271 G
11TH, G H 11TH, G N 11TH, G H 11TH, G H 11TH H	8210060202 8210060306 8210080063 8210150055 8210040379	50-220 Q 50-27 Q 50-217 P 50-322 Q 50-29 P	Sparks.g L Sparks.g L Sparks.g L Specter.a Specter.b M	6210060224* 6210220142* 6210220141* 6210150646*		STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8210130271 8210130303 8210130476 8210130556 8210150001	50-277 G 70-135 70-1100 50-247 G 50-293 G
ITH E W ITH. E W ITH. E W IETH, J A IETH, J C	8210010427 8210150474 8210150480 8210130132* 8210150601	50-289 0 50-514 0 50-440 0 50-321 R 40-6622	SPEDDEN, H R SPEIS, T P SPELMA'I, H J SPELMAN, H J	8210220086* 8010280078 8011110084 8210150463 8210250315	40-8111 50-247 P 50-247 P 40-2061 40-2061	STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8210150015 8210150076 8210150083* 8210150214 8210150221	50~334 0 50~289 0 50~289 0 50~317 0 50~289 0
1114. J C 1114. J C 1114. J E 1114. J E 1134. J E	8210180420* 8210260013 8210010218 8210010232 8210010232	40~6622 40~6622 PR PR PR	SPELMAN.H J SPENCER.D SPENSER.M D SPESSARD.R SPESSARD.R	8210250315 8210040134* 8210010302 8210080088 8210080187	90-314 8 50-314 8	STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R SYAROSTECKI, R	8210150246 8210150271 8210150279 8210190702* 8210190797	50-271
17H, J K 17H, J K 17H, J K 17H, J L 17H, J L	8210190500* 8210190504* 8210190509* 8210280036* 8210280039*	50~263 P 50~263 P 50~322 F	SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	8210040070 8210050304 8210050336 8210060264 8210060357	90-461 A 90-331 Q 90-185 Q 50-373 Q 50-237 Q	STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8210210100 8210210182 8210210241 8210210300 8210210464	50-333 Q 50-245 Q 50-423 Q 50-247 Q 50-272 Q
THE J R THE J R THE E THE H C THE H J	8210150350# 8210180362# 8210270227# 8210060400# 8210150495#	• CONTRACT • 40~8632 • 50~247 8	SPESSAPD.R L SPESSARD.R L SPESSARD.R L SPESSARD.R L SPESSARD.R L	8210080190 8210130164 8210130211 8210130240 8210130484	50-237	STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8210220159 8210220344 8210220134 8210220225 8210220257*	50-29 Q 50-244 Q 50-322 Q 50-320 Q 50-387 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AU FHOR	ACCESSION NVMBER	SURGET CATED III
STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8210260483 8210290147 8210290171 8210290189 8210290208	50-287 S 50-29 0 50-244 0 50-213 0 50-352 0	STOLZ.J F STOLZ.J F STOLZ.J F STOLZ.J F STOLZ.J F	8210270342 8210270372 8210270382# 8210270387# 8210270143*	50-287 P 50-346 P 50-346 P 50-346 P 50-313 P	TARME, D N TAUBER, H TAUBER, H TAUBER, H TAUBER, H	8210270222 8210010454 8210080044 8210150322 8210180180	40-8604 50-341 a 50-341 a 50-341 a
STAROSTECKI.R STAROSTECKI.R STASEK.S STABJESKY.F M STEED.L L	8210290212 8210290300 8210250116* 8204160212 8210060096*	50-244	STOLZ, J F STOLZ, J F STOLZ, J F STONE, J C STONER, M A	8210290148* 8210290382* 8210290387* 8210040393* 8210210301*	50-313 P 50-346 P 50-346 P 50-315 Q 50-327 A	TAUBER.H TAUBER.H TAYLOR.D TAYLOR.D J TAYLOR.J	8210190&9& 8210220414 821026044&* 82101505&0 8210120270	50-34; 6 50-34; 4 50 26° 5 NUFEC 50-443 -
STEELE,R L STEELE,R L STEELE,W J STEFAND,J STEFAND,J	8210250084 8210250164 8210150089* 8210190011 8210270073	50-344 S 50-344 S 50-311 S 50-440 F 50-440 A	STOVER, J R STREETER, J STREETER, J STREETER, J STREETER, J	8210180332* 8210040178 8210080088 8210080189 8210260447	CONTRACT 50-237 S 50-295 S 50-316 S 50-254 S	TAYLOR, J H TAYLOR, J H TAYLOR, J H TAYLOR, J W TAYLOR, P A	8209090009 8210060346 8210250132 8210130381 8210130369	TOPAEP TOPAEP P T 2 1 P R 50-30+
STELLO, V STELLO, V STELLO, V STELLO, V	8210170631 8112210166* 8210010109* 8210010286 8210040314	REVIEW GRP FOIA 50-366 S REVIEW GRP REVIEW GRP	STREETER, J F STREETER, J F STREETER, J F STREETER, J F STREETER, J F	8210050253 8210050274 8210150249 8210150385 8210150497	50-346 0 50-315 Q 50-282 Q 50-263 Q 50-409 Q	TAYLOR,R G TEDESCO.R L TERC,H M TEST.R Z THADANI.A	8210170820 + 8210260481 + 8210190059 + 8210270249 + 8203170016 +	50 444 1 50 400 4 50-362 * 50 213 5 50-537 •
STELLO, V STELLO, V STELLO, V STELLO, V	8210080109 8210080196* 8210120053* 8210150138 8210180002	REVIEW ORP FOIA REVIEW ORP REVIEW ORP REVIEW ORP	STREETER, J F STREETER, J F STREETER, J F STREETER, J F STREETER, J F	8210150523 8210150530* 8210170421 8210170427* 8210170643	50-10 Q 50-10 Q 50-255 Q 50-255 Q 50-331 Q	THATCHER, T L THATCHER, T L THATCHER, T L THATCHER, T L THATCHER, T L THIES, A C	8210080073 8210080073 8210080073 8210220434 8210260331	50-522 ( 50-522 ( 50-522 : 50-522 : 50-367 (
STELLO, V STELLO, V STELLO, V STELLO, V	8210170004 8210250131 8210250154 8210270178 8210280031*	REVIEW GRP REVIEW GRP REVIEW GRP REVIEW GRP 90-336 P	STREETER, J F STREETER, J F STREETER, J F STREETER, J F STREETER, J F	8210250105 8210250109* 8210280164 8210280168* 8210280223	50-373 0 50-373 0 50-282 0 50-282 0 50-305 0	THOMA, J O THOMA, J O THOMA, J O THOMA, J O THOMAS, B R	8210040400 8210080049 8210130047 8210130063 82101803584	50-206 / 50-247 / 50-266 f 50-266 f FOIA
STELLO V STEPHENSON, C J STEPTOE, P STEPTOE, P STEPTOE, P P	8210280351* 8210130524* 8210050223 8210050223 8210050215	REVIEW GRP 50-289 S 50-329 G 50-329 G 50-329 G	STREETER, J F STREETER, J F STRENGE, D L STROM, P O STUCKY, S W	8210280226# 8210280229* 8210270041* 8210270338 8210180147	50-305 Q 50-305 Q 50-537 Q NUREG 50-397 G	THOMAS.C O THOMAS.C O THOMAS.C O THOMAS.C O THOMAS.C O	8210040394 8210050460 8210050540 8210050543* 8210070074	TOPREP 50-461 1 50-192 P 50-192 P TOPREP
STEPTOE.P P STEPTOE.P P STEPTOE.P P STEPTOE.P P STEPTOE.P P	8210050215 8210080082 8210080082 8210080079 8210080079	50-327 0 50-255 0 50-255 0 50-255 0 50-255 0	STUCKY, 8 W SUBRAMONIAN, N SUGARMAN, R J SUGARMAN, R J SUGARMAN, R J	8210250325 8210120640# 8210010244 8210010244 8210180204	50-289 G 50-341 A 50-352 G 50-352 G 50-352 G	THOMAS, C O THOMAS, C O THOMAS, C O THOMAS, C O THOMAS, C O	8210070110 8210120475 8210120480* 8210120492* 8210120115	TOPATA 50-62 A 50-62 A 50-62 I 50-142 A
STERNBERG, D M STERNBERG, D M STERNBERG, D M STERNBERG, D M STERNBERG, D M	8210010053 8210060155 8210060330 8210060341 8210070158	50~344	Sugarman, R. J. Sugarman, R. J. Sugarman, R. J. Sugarman, R. J. Sugarman, R. J.	8210180204 8210180208* 8210180208* 8210180217 8210180217	50-352	THOMAS.C O THOMAS.C O THOMAS.C O THOMAS.C O THOMAS.C O	8210150481 8210180021 8210220185 8210240504 821007027\$*	T GPAEP T GPAEP T GPAEP 50-157   50-219
STERNBERG.D M STERNBERG.D M STERNBERG.D M STERNBERG.D M STERNBERG.D M	8210070278 8210070290 8210070297 8210070319 8210070378	50-312 0 50-312 0 50-397 0 50-312 0 50-460 0	Sugarmanir J Sugarmanir J Sugarmanir J Sugarmanir J Sugarmanir J	8210180223 8210180223 8210180224 8210180224 8210180226*	50-352 0 50-352 0 50-352 0 50-352 0 50-352 0	THOMAS, L M THOMAS, L M THOMAS, R D THOMAS, R D THOMAS, R D	8210070109 8210250170 8210080311* 8210130130 8210260304	50-445 F 50-10 F 70-754 27-48 27-10
STERNREDO N M	0013550017			8210180226* 8210180253 8210180253 8210190364 8210210477*	50-352 0 50-352 0 50-352 0 50-329 K 50-272 0	THOMPSON, D THOMPSON, T R THOMPSON, T R THOMPSON, Y J THOMSEN, F T	8207180041 8210070099* 8210270288* 8210220246 8210010382	FDIA 50-27   50-155   PR 50-572 (
				8210060248* 8210270334* 8210270364* 8210270381* 8210010064	50-346 B 50-321 S 50-346 B 50-346 S 50-537 G	THOMSEN, F T THOMSEN, F T THOMSEN, F T THOMSEN, F T THOMSEN, F T	8210050171 8210050171 8210130190 8210130367 8210130367	50-522 ( 50-522 ( 50-522 ( 50-522 (
				8210060193 8210200047 8210200080 8210250383 8207140491*	50-537	THOMSEN, F T THOMSEN, F T THOMSEN, F T THOMSEN, F T THOMSEN, F T THOMSEN, F T	8210130498 8210130498 8210200045 8210200045 8210260420	50-522 F 50-522 F 50-523 F 50-523 F
				8210120105 8210130376 8210190443 8210190445 8210220335	50-237 P 50-10 F 50-275 P 50-237 P 50-237 P	THORNTON, P THORNTON, P THORNTON, P THORNTON, P THORNTON, P	8210050232 8210050232 8210050356 8210050356 8210150470	50-155 f 50-155 f 50-155 f 50-155 f 50-155 f
				8210260151 8210010284* 8210270015 8210070381* 8210050360	50-373 P 50-329 E 50-537 Q 50-309 Q NUREQ	THORNTON, P THORPE, A A THORPE, J R THORPE, J R THORSEN, E O	8210150470 8210260407# 8210130574 8210220372 8210220375	50-155 6 50-259 5 PR PR 50-247 6
				3210130294 3210180154 3210270242 3210270253 3210280204*	50-358 A 50-358 A PR PR 50-277 P	THULL, T 8 THULL, T S THULL, T S THULL, T S TIETZ, O	8210210430* 8210220108* 8210220116* 8210220201* 8210130423*	50-245 5 50-245 5 50-245 5 50-245 5 50-254 5
				)210260223* )210190444* )210080045 )210150656 )210050360	50-304 6 50-395 P 50-334 F TOPREP NUREO	TILLMAN, A TIMBON, B S TIPPS, S B TIPPS, S B TIPPS, S B	8210150360* 821021004! 8210010078* 8210050084* 8210060287*	70-143 50-201 / 50-366 \$ 50-366 \$ 50-366 \$

<sub>የ</sub> ሚዝተህ <sub>ላ</sub>	ACCESSION NUMBER	SUBJECT CATEGORY	AV THÛR	ACCESSION NUMBER	SUBJECT Category	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
TIPES B TIPES B TIPES B TIPES B	8210960324* 8210960240* 8210130185* 8210130223* 8210130258*	50-366 S 50-366 S 50-366 S 50-366 S 50-321 S	TUCKER.H B TUCKER.H B TUCKER.H B TUCKER.H B TUCKER.H B TUCKER.H B	8210010134+ 8210010282 8210010382 8210010387 8210010463+	50-413 0 50-369 0 50-269 F 50-370 0 50-269 0	UHRIG, RE UHRIG, RE UHRIG, RE UHRIG, RE UHRIG, RE UHRIG, RE	8210050416 8210050567* 8210060236 8210060276 8210060281	50-389 A 50-335 F 50-389 B 50-389 A 50-250 P
1) PFE: 8 8 F [ PFE S B F [ PFE S B F ] PFE S B	8210130414* 8210130549* 8210190511* H2101906U2** 8210220222*	50~366 S 50~366 S 50~366 S 50~366 S	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8210040107 8210040232 8210040254 8210040273* 8210050130	50-269 P 50-269 P 50-369 K 50-369 K 50-413 A	UHRIG, REUHRIG, REUHRIG, REUHRIG, REUHRIG, RE	8210060288 8210060371 8210080264 8210130090 8210130297	50-335 P 50-367 R 50-335 Q 50-387 S 50-389 E
**************************************	0210290272# 0210290106# 0210290106# 02102203084	50-321 S 50-346 5 50-321 S 50-326 S 50-321 S	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8210050264 8210050384 8210060311 8210070072 8210070092	50-413 A 50-413 A 50-413 A 50-369 F 50-413 A	UHRIG, A E UHRIG, R E UHRIG, R E UHRIG, R E UHRIG, R E	8210130289 8210130301 8210130348 8210130339 8210130534	50-389 A 50-389 A 50-389 F PR 50-389 8
「[F戸7 5 は ・[FP5 5 B ・[FP5 5 B ・[Tが 2] CはA 「ごれ 2] CはA	BE 10090329* 8010070375* 8010070327 8010070327	50-381 S 50-321 S 50-321 S 50-382 M	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8210080208 8210130157 8210130177 8210130262 8210130267	50-413 5 50-269 P 50-369 5 50-369 K 50-269 0	UHRIG,RE UHRIG,RE UHRIG,RE UHRIG,RE UHRIG,RE	8210150407 8210150439 8210150186* 8210150316 8210150348	50-250 P 50-250 P 50-250 F 50-335 P 50-389 A
OBJANEA OPPO A OTHER OP DIAMENTO P	8210150180* 8210010371* 8210130545 8210190776* 8210010257	50-263 5 70-143 MIRC 50-445 0 50-237 6	TUCKER, IF B TUCKER, IF B TUCKER, H B TUCKER, H B TUCKER, H B	8210130399 8210130467 8210130502 8210130599 8210150068	PR 50-369 P 50-287 P PR 50-413 0	UHRIG,RE UHRIG,RE UHRIG,RE UHRIG,RE UHRIG,RE	8210190351 8210190371 8210190440 8210190559 8210220090	50-250 0 50-235 F 50-250 F 50-250 P 50-251 P
CHAPITS I A CHAPITAS B A LIVERTAS B A CHAPITAS B A CHAPITAS B A	8 (16040093 8:10050275 8:10060192 8:1077031 ) 8:10 (80-58	50-31;	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8210150094 8210150269 8210150518 8210150617 8210180055	50-413 K 50-269 0 50-369 F 70-2744 50-269 P	UHRIO, RE UHRIO, RE UHRIO, RE UHRIO, RE UHRIO, RE	8210220167 8210220214 8210220286# 8210220304# 8210220451	90-387 9 50-387 0 50-335 0 50-250 0 50-335 0
CHARLE A CHARLE A CHARLE A CHARLE A CHARLE A	8.4104.00573 821049459 8210495545 8210496548 8210.20112	50~155 P 50~155 P 50~255 P 50~255 P 50~155 P	TUGMER.H B TUGMER.H B TUGMER.H B TUGMER.H B TUGMER.H B	8210180040* 8210180128 8210190103* 8210190544 8210190511	50-267 P 50-370 A 50-369 F 50-269 R 50-413 F	UHRIG, REUHRIG, REUHR	8210250313 8210250317 8210260391* 8210270253 8210280067	50-387 A 50-387 R 50-335 0 50-350 P 50-389 E
THE A A DEFENDA	HETOHOTPH HETOTOTHE HETOTOHETA HETOTOHOTA HETOTOTOTOH	50-237 5 50-10 0 FUIA 701A 50-247 0	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8210190740 8210190742 8210210191 8210210407 8210220134	50-370 F 50-369 R 50-269 P 50-269 P 50-413 Q	UHRIG, R E UHRIG, R E UHRIG, R E ULLRICH, J ULRICH, W T	8210280254 8210280271 8210270240 8210130215* 8210130272*	50-389 A 50-250 F PR 50-373 R 50-277 P
THAD TARLITE, I TENDR TELETIDR QUILLIBR	8 101903684 9210/50934 9210/509379 9210060175 9210060195	50-397 0 SECY 50-537 0 50-537 0 50-537 0	TUCKER, H B FUCKER, H B FUCKER, H B FUCKER, H B FUCKER, H B	0210250102 9210220128 9210220128 9210220201	50-369 0 50-369 0 50-369 5 50-269 0 50-413 D	UNTERMEYER UPRIGHT.C M UPRIGHT.C M UPRIGHT.C M UPRIGHT.C M UPRIGHT.C M	8210130074 8210010143* 8210010350* 8210150052* 8210150132*	XPORTLIC 50-413 0 50-324 0 50-324 0 50-324 0
COLEND R COLEND R COLEND R COLEND R COLEND R COLEND R	8510550488 8510550581 8510550581 8610550581	50-537 0 50-537 0 50-537 0 50-537 0 50-537 0	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8210250304 8210260201 8210270139* 8210280017* 8210280065	50-369 P 50-413 A 50-369 F 50-369 F 50-413 E	UPRIGHT.C M UPRIGHT.C M UPRIGHT.C M UPRIGHT.C M URBANIK.T	9210190256* 9210190315* 9210220145* 9210220307* 9210290195	50-327
CONTRACTOR OF THE CONTRACTOR O	0,10,70295# 0,107202-54 0,107202-54 0,10720257 0,2076257 0,2076257	50-537 9 50-537 0 CONTRACT	Tucker, H B Tucker, H B Tucker, H B Tucker, H B Tucker, H B	6210270045 6210270083 6210270117 6210270170 6210270250	50-370 \$ 50-270 \$ 50-413 \$ 50-269 \$ 50-413 \$	URYC, B UPYC, B UTLEY, E E UALKOVIC, M M	8210220406* 8210220316 8210220409 8210210054	50-400 G 50-438 G PR PR NUMEG
r et, T ft	6210010±02 6210010±71 6210740060 6210740249 6210190299	50 454 E 50-454 A 50 454 K 50 457 9 50-456 5	TUCKER, H B TUCKER, H B TUCKER, H B TUPPER, K F TURK, B E	8210290308 8210290354 8210290359 8210080339 8210040059	50-287 8 50-413 8 50-269 8 XPDRTLIC 50-382 0	VALKOVIC, M M VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8210220154 8210060413 8210070391 8210040292 8210040305*	NUREQ 50-529 9 50-529 8 50-529 H
FAMILY OF MENTS OF ME	#210190552 #210220354 #210270104 #210150354 #210190429	50-456 G 50-10 F 50-454 E 50-344 P * 50-282 P	TURK, SE TURK, SE TURK, SE TURK, SE TURK, SE TURK, SE	8210040061 8210040183 8210080070 8210130124 8210130183	50~382 0 50~382 0 50~382 0 50~445 0 50~445 0	VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E	8210050245 8210070210 8210070213 8210070217 8210070227	50-528 A 50-528 Q 50-528 8 50-528 8
THAN, IT K THAN, IT K THE WAY N K THAN IT B THINGS IT B	8203310094 8204120487 8205180693 8219270408 9219270408	* 50-281 8 * 50-281 8 * CONTRACT	TURK. S E TURK. S E TURK. S E TURNAGE. K G TURNER: L C	8210130564 8210210037 8210210037 8210130504	50-445 G 50-382 G 50-382 G NUREO 50-413 D	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8210070320 8210070321 8210070339 8210070354 8210070374	50-520 8 50-520 8 50-520 8 50-520 8
FETAC. H D [Male. D C . PP PP L E PP L E	8210270466 8210150235 8210060376 8210070275 821021047	50-275 0 5 50-317 0 5 50-219 8 5 50-219 0	TURNOVEST, L VDELL, R A VDELL, R A VDELL, R A VDER(TZ, R A	8210190471 8206060032 8210010036 8210080010 8210120328	FOIA FOIA FOIA	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8210080155 8210130167 8210130443 8210130444 8210130491	50-526 0 50-526 8 50-526 0 50-530 9 50-530 9
Leridoe. O F Weridoe. O F Leridoe. O F Leridoe. O F Leridoe. O F	8210210173 8210210173 8210210174 821021017 821021037	3 50-320 0 3 50-320 0 7* 50-320 0 9* 50-320 0	UDERITZ.R A UDY.A C UDY.A C UHRIG.R E UHRIG.R E	82101500B0 8210250372 8210280432 8209170062 8210010017	* 50-213 P * 50-247 P 50-250 F	VAN BRUNT, E.E. VAN BRUNT, E.E. VAN BRUNT, E.E. VAN BRUNT, E.E. VAN BRUNT, E.E.	8210130495 8210130544 8210150163 82101501763 8210170315	50-526 E
HERIDGE, G YUDA, T HERIH O HERIK B HERIK B	921021037 921027000 920917005 921001009 921001009	4 50-289 0 7 XPORTLIC 3 50-413 F 0 50-369 0	OHRIO, R E UHRIO, R E UHRIO, R E UHRIO, R E	8210010084 8210010153 8210010272 8210010321 8210050041	14 50~335 9 2 50~250 9 14 50~250 Q	VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E. VAN BRUNT,E E VAN BRUNT,E,E	8210190463 8210190717 8210820394 8210850100 8210850305	50-528 A 50-528 A 50-528 G 50-528 B 50-528 B

VAN BRUNT, E E 8210260275 50-528 S VERRELLI, D 8210180004 50-348 0 WALKER, R D 64 VAN BRUNT, E 8210270211 50-528 A VERRELLI, D 8210260245 50-327 D WALKER, R D 65 VAN BRUNT, E 821028037 50-528 A VERRELLI, D M 8210010086 50-400 Q WALKER, R D 65 VAN BRUNT, E 8210280139 50-528 A VERRELLI, D M 8210010120 50-83 D WALKER, R D 65 VAN BRUNT, E 8210280279 50-528 A VERRELLI, D M 8210010120 50-83 D WALKER, R D 65 VAN BRUNT, E 8210280279 50-528 E VERRELLI, D M 8210010132 50-324 Q WALKER, R D 65 VAN BRUNT, E 8210280279 50-528 E VERRELLI, D M 8210010132 50-324 Q WALKER, R D 65 VAN BRUNT, E 8210280279 50-528 E VERRELLI, D M 8210010132 50-324 Q WALKER, R D 65 VAN RIPER, D 65 VERRELLI, D M 8210010171 50-324 Q WALSKE, C 65 VERRELLI, D M 8210010171 50-324 Q WALSKE, C 65 VERRELLI, D M 8210010173 50-261 Q WARD, E C 65 VERRELLI, D M 8210010171 50-439 Q WARD, E C 65 VERRELLI, D M 8210010333 50-390 Q WARD, E C 65 VAN RIPER, D 65 VERRELLI, D M 8210010333 50-390 Q WARD, E C 65 VAN SYGC, C 8201030145 50-482 Q VERRELLI, D M 8210010333 50-390 Q WARD, E C 65 VAN SYGC, C 8201030145 50-482 Q VERRELLI, D M 8210010333 50-390 Q WARD, E C 65 VAN SYGC, C 8201030145 50-482 Q VERRELLI, D M 8210010334 50-390 Q WARD, E C 65 VAN SYGC, C 8201030145 50-482 Q VERRELLI, D M 8210010335 50-390 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394	ACCESSION NUMBER	BUBJE I CAREAL
VAN BRUNT, E E 8210260275 50-528 S VERRELLI, D 8210180004 50-348 0 WALKER, R D 64 VAN BRUNT, E 8210270211 50-528 A VERRELLI, D 8210260245 50-327 D WALKER, R D 65 VAN BRUNT, E 821028037 50-528 A VERRELLI, D M 8210010086 50-400 Q WALKER, R D 65 VAN BRUNT, E 8210280139 50-528 A VERRELLI, D M 8210010120 50-83 D WALKER, R D 65 VAN BRUNT, E 8210280279 50-528 A VERRELLI, D M 8210010120 50-83 D WALKER, R D 65 VAN BRUNT, E 8210280279 50-528 E VERRELLI, D M 8210010132 50-324 Q WALKER, R D 65 VAN BRUNT, E 8210280279 50-528 E VERRELLI, D M 8210010132 50-324 Q WALKER, R D 65 VAN BRUNT, E 8210280279 50-528 E VERRELLI, D M 8210010132 50-324 Q WALKER, R D 65 VAN RIPER, D 65 VERRELLI, D M 8210010171 50-324 Q WALSKE, C 65 VERRELLI, D M 8210010171 50-324 Q WALSKE, C 65 VERRELLI, D M 8210010173 50-261 Q WARD, E C 65 VERRELLI, D M 8210010171 50-439 Q WARD, E C 65 VERRELLI, D M 8210010333 50-390 Q WARD, E C 65 VAN RIPER, D 65 VERRELLI, D M 8210010333 50-390 Q WARD, E C 65 VAN SYGC, C 8201030145 50-482 Q VERRELLI, D M 8210010333 50-390 Q WARD, E C 65 VAN SYGC, C 8201030145 50-482 Q VERRELLI, D M 8210010333 50-390 Q WARD, E C 65 VAN SYGC, C 8201030145 50-482 Q VERRELLI, D M 8210010334 50-390 Q WARD, E C 65 VAN SYGC, C 8201030145 50-482 Q VERRELLI, D M 8210010335 50-390 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394 Q WARD, E C 65 VAN SYGC, C 8201030145 50-55 R VERRELLI, D M 8210010336 50-394	B210250467	50 2*4
VAN BRUNT, E E 821028027 50-528 A VERRELLI, D M 8210280245 50-327 D WALKER, R D 82 VAN BRUNT, E E 821028027 50-528 A VERRELLI, D M 8210010120 50-83 D WALKER, R D 82 VAN BRUNT, E E 8210280139 50-528 A VERRELLI, D M 8210010120 50-83 D WALKER, R D 82 VAN BRUNT, E E 8210280274 50-528 E VERRELLI, D M 8210010132 50-324 D WALKER, R D 82 VAN BRUNT, E 8210280274 50-528 E VERRELLI, D M 8210010132 50-416 D WALLICK, M E 82 VAN BRUNT, E 8210280274 50-528 E VERRELLI, D M 8210010173 50-416 D WALLICK, M E 82 VAN BRUNT, E 8210150557 NUREO VERRELLI, D M 8210010173 50-324 D WALLICK, M E 82 VAN BRUNT, E 8210150557 NUREO VERRELLI, D M 8210010173 50-261 D WARD, E C 8210180051 50-418 VERRELLI, D M 8210010173 50-261 D WARD, E C 8210180051 50-219 H VERRELLI, D M 8210010171 50-438 D WARD, E C 8210180051 50-418 D VERRELLI, D M 8210010333 50-439 D WARD, E C 821018068 50-482 D VERRELLI, D M 8210010334 50-390 D WARD, K D 82101010145 50-482 D WARD	8210150386=	50-2-3
VAN BRUNT, E B 210280037 50-528 A VERRELLI, D M 8210010120 50-83 0 WALLER, R D 8 VERRELLI, D M 8210010120 50-83 0 WALLER, R D 8 VERRELLI, D M 8210010120 50-83 0 WALLER, R D 8 VERRELLI, D M 8210010120 50-83 0 WALLER, R D 8 VERRELLI, D M 8210010120 50-83 0 WALLER, R D 8 VERRELLI, D M 8210010120 50-83 0 WALLER, R D 8 VERRELLI, D M 8210010132 50-324 0 WALLER, R D 8 VERRELLI, D M 8210010133 50-324 0 WALLER, C E 9 VERRELLI, D M 8210010133 50-324 0 WALLER, C E 9 VERRELLI, D M 8210010133 50-324 0 WARD, E C 9 VERRELLI, D M 8210010133 50-324 0 WARD, E C 9 VERRELLI, D M 8210010131 50-438 0 WARD, E C 9 VERRELLI, D M 821001033 50-338 0 WARD, E C 9 VERRELLI, D M 821001033 50-390 0 WARD, E C 9 VERRELLI, D M 821001033 50-390 0 WARD, E C 9 VERRELLI, D M 821010333 50-390 0 WARD, E C 9 VERRELLI, D M 821010333 50-390 0 WARD, E C 9 VERRELLI, D M 821010333 50-390 0 WARD, E C 9 VERRELLI, D M 821010333 50-390 0 WARD, E C 9 VERRELLI, D M 821010333 50-390 0 WARD, E C 9 VERRELLI, D M 821010333 50-390 0 WARD, E C 9 VERRELLI, D M 821010333 50-390 0 WARD, E C 9 VERRELLI, D M 821010333 50-390 0 WARD, E C 9 VERRELLI, D M 821010333 50-390 0 WARD, E C 9 VERRELLI, D M 821010333 50-390 0 WARD, E C 9 VERRELLI, D M 821010333 50-390 0 WARD, E C 9 VERRELLI, D M 821010333 50-390 0 WARD, E C 9 VERRELLI, D M 921010333 50-390 0 WARD, E C 9 VERRELLI, D M 921010333 50-390 0 WARD, E C 9 VERRELLI, D M 921010333 50-390 0 WARD, E C 9 VERRELLI, D M 921010333 50-390 0 WARD, E C 9 VERRELLI, D M 921010334 50-390 0 WARD, E C 9 VERRELLI, D M 921010334 50-390 0 WARD, E C 9 VERRELLI, D M 921010334 50-390 0 WARD, E C 9 VERRELLI, D M 921010334 50-390 0 WARD, E C 9 VERRELLI, D M 921010334 50-390 0 WARD, E C 9 VERRELLI, D M 921010334 50-390 0 WARD, E C 9 VERRELLI, D M 921010334 50-390 0 WARD, E C 9 VERRELLI, D M 921010334 50-390 0 WARD, E C 9 VERRELLI, D M 921010334 50-390 0 WARD, E C 9 VERRELLI, D M 921010334 50-390 0 WARD, E C 9 VERRELLI, D M 921010334 50-390 0 WARD, E C 9 VERRELLI, D M 921010334 50-390 0 WARD, E C 9 VERRELLI, D M 921010334 50-390 0 WARD, E C 9 VERRELLI	#200010158	50 (6)
VAN BRUIT. E 8210280139 50-528 A VERRELLI. D M 8210010120 50-83 0 WALKER, R D 8  VAI BRUIT. E 8210280199 50-528 A VERRELLI. D M 8210010132 50-324 0 WALLACE. T 8  VAN BRUIT. E 8210280274 50-528 E VERRELLI. D M 8210010148 50-414 0 WALLACE. T 8  VAN REP. J B 8210160555 NUREC VERRELLI. D M 8210010171 50-324 0 WALSKE. C 8  VAN RIPER. O 8210080033 XPORTLIC VERRELLI. D M 8210010173 50-264 0 WAMBACH. T V 8  VAN RODYEN. D 8210120370 RES VERRELLI. D M 8210010191 50-439 0 WARD. E C 8  VAN SYGC. C 8207180051 50-219 H VERRELLI. D M 8210010200* 50-439 0 WARD. E C 8  VANDELI T E 8210190408* 50-482 0 VERRELLI. D M 8210010333 50-390 0 WARD. K D 82101010145 50-382 0 VERRELLI. D M 8210010336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 8210101336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 8210101336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 8210101336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 8210101336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 8210101336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 8210101336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 8210101336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 8210101336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 8210101336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 8210101336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 8210101336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 8210101336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 8210101336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 8210101336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 8210101336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 8210101336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 82101010336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 82101010336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 82101010336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 82101010336 50-394 0 WARD. K D 82101010145* 50-55 R VERRELLI. D M 821010	0210150530*	50-10
VAIL BRUTT. E B210280197 50-528 A VERRELLI, D M 8210010132 50-324 0 WALLACE, T E VAN BRUNT. E B210280274 50-528 E VERRELLI, D M 8210010148 50-416 0 WALLACE, T E VAN BRUNT. E B210150557 NUREO VERRELLI, D M 8210010171 50-324 0 WALSKE, C E VAN ERP. D B 8210150557 NUREO VERRELLI, D M 8210010173 50-261 0 WARBACH, T VAN RIPER, D G 8210080033 XPORTLIC VERRELLI, D M 8210010173 50-261 0 WARBACH, T VAN RODYEN, D B210120370 RES VERRELLI, D M 8210010171 50-438 0 WARD, E C E VAN SYGC, C B207180051 50-219 H VERRELLI, D M 8210010200 50-438 0 WARD, E C VANDELLI, D M 821010333 50-390 0 WARD, K D E VANDEMBERG, D 82101301458 50-255 R VERRELLI, D M 821010336 50-324 0 WARD, K D E VANDEMBERG, D 82101301458 50-255 R VERRELLI, D M 821010336 50-324 0 WARD, K D E VANDEMBERG, D 82101301458 50-255 R VERRELLI, D M 821010336 50-324 0 WARD, K D E VANDEMBERG, D 82101301458 50-255 R VERRELLI, D M 821010336 50-324 0 WARD, K D E	8210250116.	50 373
VAN RRUIT. E B210280277 50-528 E VERRELLI. D H B210010148 50-416 G MALLICK, M E VAN RRUIT. E B210280277 50-528 E VERRELLI. D H B210010171 50-524 O MALSKE, C E VAN REPR. D B B210180557 NUREO VERRELLI. D H B210010173 50-526 O MARIGACH. T V VAN RRUIT. D B210120370 RES VERRELLI. D H B210010173 50-526 O MARIGACH. T V VAN RRUIT. D B210120370 RES VERRELLI. D H B210010171 50-438 O WARD. E C VAN SYGG. C B207180051 50-219 H VERRELLI. D H B210010200* 50-438 O MARD. E C VANDENGERO. D B210130145* 50-255 R VERRELLI. D H B210010336 50-390 O MARD. K D E VANDENGERO. D B210130145* 50-255 R VERRELLI. D H B210010336 50-324 O MARD. W J MARD. W J		
VAN SYOC. C 8201905051 50-219 H VERRELLI.D M 8210010332 50-324 0 WARD. E C VANDELLT E 8210190508 0 VERRELLI.D M 8210010333 50-324 0 WARD. E C E VANDELT E 8210190501 50-489 0 WARD. E C E VANDELT E 8210190608 50-489 0 WARD. E C E VANDELT E 8210190608 50-482 0 VERRELLI.D M 8210010333 50-390 0 WARD. E C E VANDENBERG. D 82101301458 50-255 R VERRELLI.D M 8210010336 50-324 0 WARD. W	8210280187	50 223
VAN RIPER, 0 G 8210080033 XPORTLIC VERRELLI.D H 8210010173 50-261 0 WAMBACH.T V 6 VAN RODYEN.D 8210120370 RES VERRELLI.D H 8210010191 50-438 0 WARD.E C 6 VAN SYGC.C 8207180051 50-219 H VERRELLI.D H 82100102000 50-438 0 WARD.E C 7 VANDENLI T E 82101904080 50-482 0 VERRELLI.D H 8210010333 50-390 0 WARD.K D 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D H 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D H 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D H 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D H 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D H 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D H 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D H 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D H 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D H 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D H 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D H 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D H 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D H 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D H 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D H 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D H 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D M 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D M 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D M 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D M 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D M 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 82101301455 50-255 R VERRELLI.D M 8210010336 50-324 0 WARD.W J 6 VANDENBERG.D 821013014	8210190215+	COMPA
VAN RODYEN, D 8210120370 RES VERRELLI, D M 821010191 50-438 0 WARD, E C E  VAN SYOC, C 8207180051 50-219 H VERRELLI, D M 9210010200* 50-438 0 WARD, E C  VAN SYOC, C 8207180051 50-482 0 VERRELLI, D M 8210010333 50-390 0 WARD, K D 82101010145* 50-255 R VERRELLI, D M 8210010336 50-324 0 WARD, W J 82101010145*	#E10090902B	COMMISSIO
VAN SYGC, C 8207180051 50-219 H VERRELLI, D M 8210010200* 50-438 0 WARD, E. C E VANDEL, T E 8210190600* 50-482 0 VERRELLI, D M 8210010333 50-390 0 MARD, K D E VANDEMBERG, D 8210130145* 50-255 R VERRELLI, D M 8210010336 50-324 0 WARD, W J E	6210120323	50 255
VAIDELL T E 82(0190608) 50-482 Q VERRELLID 11 8210010333 50-390 0 MARD. K D VANDENBERG, D 8210130145* 50-255 R VERRELLID M 8210010336 50-324 0 WARD. W J	6210060164	50-263
VANDELLT E 8210190608* 50-482 Q VERRELLID M 8210010333 50-390 O NARD, K D E VANDENBERG, D 8210130145* 50-255 R VERRELLID M 8210010336 50-324 O WARD, W J	9210250200	50-282
VANDENBERG, D 8210130145* 50-255 R VERRELLI D M 8210010336 50-324 0 WARD, W J	9210040308+	50-463
	8010150103	50-247
	810[140002*	50-224
	6210040114	50 247
VANDENALE, D. J. 82100503424 50-155 0 VERRELLI, D. M. 8210010421 50-438 0 WAREHOOURG, D. E.		4:-
AMADEM-CECI D. O. DETADOGGATE, DO 100 d	92091504404	5-0~247
THE PROPERTY OF THE PROPERTY O	8210050331	50-267
AMIDENALLY D DETOUDE SO TO T	8210130344	50-267
ANADEMACE A DETOCRACE AD 100 L	8210190537	50-247
VANGEWALLE, D J #210060237 50~155 P VERRELL[, D M #210010452 50-370 Q WAREMBOURG D £	8210140992	50~267
VANGEWALLE, D. J. 8210070013 50-155 P. VÆRRELLI, D. M. 8210150026 50-390 G. WAREMBOURG, D. W.	8210080256	50+267
	8210190306	50-767
VANDEWALLE, D. J. 8210130334 50-255 P. VERRELLI, D. H. 8210150149 50-438 Q. WAREMBOURG, D. W.	8210210081+	50-767
VANDENALLE, D J 82[0]3052; PR VERRELLI, D M 8210150162 50-324 Q WAREMBOURG, D W	8210220357	PR
VANDEWALLE, D J 8210220334 PR VERRELLI, D M 8210150209 50-390 Q WARLOL, W N	8210080331*	XPDAILI,
VANDEMALLE, D J B210260316* 50-155 Q VERRELLI.D M 8210150288 50-324 0 WARING, J P	8216646311	TOPPEP
	8210040337	50 3₹₹
	8210190627	50~358
	8210040185*	50-409
	8210050139	50-02,
VARELA, A 8210210082* 50~352 0 VERRELLI, D M 8210150399 50-259 G WARNICK, R F	8210050146*	50-327
	8510080188	50-007
	6210130557*	50-461
VARGA,S A 8210040041* 50-364 P VERRELLI,D M 8210720149 50-324 0 WARNICK,R F	8210150441	50-329
VARGA, S A 8210040417* 50-315 P VERRELLI.D M 8210220312 50-160 G MARNICK, R F E	8210190739	50-347
VARGA,S A 8210040419+ 50-315 P VERRELLI.D M 8210220315 50-390 Q WARNICK,R F	82101907874	50-440
	8210370140	50-329
	0210290154	50-327
TOTAL TO TOTAL TO THE TOTAL TO THE TOTAL TO THE TOTAL TOTAL TO THE TOTAL	8210290377	50-327
Third to the second sec	8210240377	50-261
ANIMALO II DESCRIPTION OF THE PROPERTY OF THE	ationdant.	55 463
	8210190599+	50-275
	8210200096+	50-331
	8210190185	50-320
	8210210034	50-259
VARGA,S A 8210120560* 50~315 P VILLA,R 8210050398 50~447 A WEDER,D A 8	8210280432*	50-247
VARGA,S A 8210120565* 50-315 P VILLA,R 8210050408* 50-447 A WEBER, N V	8210050427*	50-155
	8210040189#	50-237
	1800020128	50-142
VARGA, S.A. 8210130604 50-286 F VISSER. J.E. 8210180416* CONTRACT WELL, C.H.	0210270338	NUREG

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY
#E1596 E P #E1896 E P #E1896 E P #E1896 E P #E1896 E R	8210220410 8210220465 8210220465 8210260397 8210260397	50-247 G 50-287 G 50-289 G 50-289 G 50-537 G	Wiesemann, R A Wiesemann, R A Wigoins, E Wigoins E Wigoins, E	8210170508* 8210260351* 8210120347 8210120371 8210170230	50-395 P TOPREP CONTRACT CONTRACT CONTRACT	Milson, J C Milson, J C Milson, J C Milson, J C	6210040376* 8210130204 8210130206* 8210130213* 8210130213*	50-280 8 50-280 8 50-280 8 50-280 8 50-280 8
20110000000000000000000000000000000000	8210240397 8210260404# 8210260404# 8210260404# 8210260242	50-537 G 50-537 G 50-537 G 50-537 G 50-247 G	Migointon, D Wigointon, D Wigointon, D Wigointon, D	8210270207 8210270226 8210260061 8210270344 8210280405	CONTRACT CONTRACT 50-315 P 50-295 P 50-295 F	MILSON, J L WILSON, J L WILSON, J L WILSON, J L	8210130500 8210130507* 8210150054 8210150075 8210150139	50-280 8 50-280 8 50-280 9 50-280 8 50-280 9
WEIGS ER WEIGE BA WEIGE BA WEIGE BA WEIGE BA	8210280242 8210190332 8210040084 8210040127 8210190657	50-247 0 50-341 S 50-341 S 50-341 S 50-341 S	NIZTOR, D NIZTOR, D NILCOVE, M N WILCOVE, M N WILCOVE, IS N	8210210381 8210210381 8210010062 8210040018 8210040057	50-155 G 50-155 G 50-329 G 50-329 G 50-329 G	MILSON, J L MILSON, J L MILSON, J L MILSON, J L	8210150359 8210150394 8210220095 8210220097* 8210220100*	50-281 5 50-280 5 50-280 5 50-280 8 50-280 8
NELLE BA NEWLEYDA NEWLERLICH R L NEWLERLICH R L NEWLERLICH R L	6210250191 8210260382* 8210130558* 8210280267*	50-341 S 50-341 Q 50-318 S 50-317 S 50-317 S	WILCOVE, N N WILCOVE, N N WILCOVE, N N WILCOVE, N N	8210150486 8210200051 8210260364 8210260388 8210130328#	50-320 0 50-327 0 50-327 0 50-327 0 50-254 E	WILSON, J L WILSON, J L WILSON, J L WILSON, J L WILSON, J L	8210220392 8210220398* 8210220408* 8210220413* 8210220424	50-280 8 50-280 8 50-280 9 50-281 9
NEILCERLICH R L NEILCERLICH R L NEILCEALACHT F LEICHA SHIIF A NEILSEALACHT A	8210280284* 8210280313* 8210010240 8210040131* 8210190412*	50-310 5 50-317 5 50-206 5 50-220 0 50-312 0	WILKINSON, E P WILKINSON, W P WILLETT, B J WILLIAMS, C C WILLIAMS, C C	8210050181* 8208010019* 8210170569* 8210170787* 8210060384*	FOTA ORG 50-397 O 50-440 O 50-373 O	MILSON, J L WILSON, J L WILSON, J L WILSON, J L	8210220435* 8210270212 8210270215* 8210270220* 8210270224*	50-281 5 50-280 5 50-280 5 50-280 5 50-280 5
HEIN-LAMERINE A HEIN-CHARINE A HEIN-SLAMERNIE A HEIN-SELAH HEN-SELAH	8210,29044A* 8210239178* 8210280244* 8210280248* 821028024	50-27 Q 50-362 Q 50-397 Q 50-397 Q NUREG	Williams. C C Williams. C C Williams. D A Williams. D T	8210060393* 8210130374* 8210130557* 8210210046 8208290108	50-315 G 50-341 G 50-461 G NUREG FOIA	WILSON, J. L. WILSON, J. L. WILSON, J. L. WILSON, K. R.	8210290264 8210290270* 8210290276* 8210290282* 8210190687*	50-280 S 50-280 S 50-280 S 50-280 S 50-202 S
enjelah h Kenjer B J Legitah B Legitah B Legitah	6210720154 6210130126* 6203040538* 6210050221 6210050221	NUREG 50-346 S 50-329 G 50-329 G 50-329 G	u C sentiulu u C sentiulu u C sentiulu u C sentiulu u C sentiulu	8210010164 8210060209 8210080252 8210130456 8210130552	50-335 8 50-251 8 50-250 8 50-335 8 50-335 8	WILT, D D WILT, D D WILT, D D	8210200053 8210010250 8210010250 8210010323 8210010323	50-400
, "ST A E KET, A E FST : U TET: L U TET: RGW, A D	8210070250 8210070230 8210070021# 8210120458# 8210040355	50-329 G 50-329 G CONTRACT CONTRACT 40-8748	Williams, J W Williams, J W Williams, P R Williams, R E Williams, R E	8210260116 8210260357 8210180354# 8210120401# 8210120604#	50-250 S 50-235 S FDIA CONTRACT 40-8745	WILT.D D WILT.D D WILT.D D WILT.D D	8210050173 8210050173 8210050228 8210050228 8210050242	50-440 G 50-440 G 50-440 G 50-440 G 50-440 G
ESTEROTAL B STERMAN T STERMAN T SSTERMAN T SSTERMAN T	8210170479 8210770338 8210050239* 8210070369* 8210170547	40-8786 NURFG 50-267 0 50-445 0 50-267 S	WILLMORE, R. L. WILLMORE, R. L. WILLMORE, R. L. WILLMORE, R. L. WILLMORE, R. L.	8210010345 8210010345 8210010457 8210010457 8210050255	50-440 G 50-440 G 50-440 G 50-440 O 50-440 O	WILT, D D WILT, D D WILT, D D WILT, D D WILT, D D	8210050242 8210050252 8210050252 8210250331 8210250331	50-440 G 50-440 G 50-440 G 50-440 G 50-440 G
ESTERMALT F ESTERMALT F ESTERMALT F TEEMMENT IN U TTEEMMENT IN U	8210190775* 8210380149* 8210280149* 821029039 8210290299	50-445 Q 50-445 Q 50-267 Q 27-39 50-358 Q	WILLMORE, R L WILLMORE, R L WILLMORE, R L WILLMORE, R L WILLMORE, R L	8210050255 8210070405 8210070405 8210150467 8210150467	50-440 G 50-440 G 50-440 G 50-440 G 50-440 G	WINKS, R. W WINTERHOFF, D WINTERHOFF, D WINTERHOFF, D WIRFS, L	8210010284* 8210130236* 8210250163* 8210260313* 8210070426*	50-327 E 50-373 B 50-373 B 50-373 B FOIA
ITTERMINA II J IALEIL R IALEIL R GELERIL GELERIL	8210270279 8210040127* 8210250314* 8209210550* 8210180214	50-35B 0 50-247 5 50-249 8 50-508 A 50-508 A	WILLMORE, R L WILLMORE, R L WILLMORE, R L WILLMORE, R C WILLMORE, R L	8210220309 8210220305 8210180155 8310180155	50-440	WIRFS, L WITHERS, B D WITHERS, B D WITHERS, B D WITHERS, D D	8210070454* 8210010307 8210040163 8210080253* 8210130399	FDIA PR 50-344 P 50-244 Q PR
EEU.6 R. L L RTE. A J RTE. A J RTE. J W	0210120617 0210220067* 0210270332* 0210270344* 0210260530*	50-322 0	WILLMORE,R L WILLMORE,R L WILLMORE,R L WILLMORE,R L WILLMORE,R L	8210220405* 8210220394 8210220405* 8210220405*	50-440 Q 50-440 Q 50-440 Q 50-440 G 50-440 Q	WITHERB, B D WITHERBPOON, J WIZNER, D G WIZNER, D G WIZNER, D G	8210220301 8210130315# 8210170277# 8210170287# 8210170415#	PR 50-537 A 50-315 B 50-315 B 50-315 B
ite.r i ite.r b itener.h i itener.h i itney.o o	8206170006* 8219950412 8219950459* 8219270147* 8219940105*	NUREO 90~369 0 50~324 0	WILLHORE.R L WILLHORE.R L WILLHORE.R L WILLHORE.R L WILLHORE.R L	8210280231 8210280231 8210280246 8210280246 8210290287	50-440 G 50-440 G 50-440 G 50-440 G 50-440 G	WIZNER,D G WOJCHOUSKI,A V WOJNAS,E J WOLF,J F WOLF,J F	8210190735* 8210060260* 8210210142* 8210270176 8210280245	50-314 8 50-243 8 50-309 0 50-320 0 50-275 0
ithey.o G ithey.o G ithey.o G ithey.o G ithey.o G	8210060030× 8210070247× 8210070346× 8210130479× 8210170237×	90-293 8 50-293 8 50-293 8	WILLMORE, R E WILLSEY, W B WILLSEY, W B WILSON, A K WILSON, B A	8210270287 8210050320 8210150354 8207050075 8210260065	50-440 0 50-277 P 50-277 R FGIA 50-413 V	WOLF, T R WOLF, T R WOLF, T R WOLF, T R WOLF, T R	8203120103* 8206220591* 8207120140* 8209150162* 8209150164	50-331 S 50-324 P 50-324 P 50-325 P 50-324 B
TNEY. 0 0 TNEY. 0 0 TTEM. J E TWORTH F RIOM 8 0	0210280131+ 8210280150+ 9210220171+ 8210130074+ 8210080276	+ 50-293 B + 40-2259	MILSON.B D WILSON.B D WILSON.B D WILSON.B D	8210080113 821008013! 821026057( 821027028; 8210050071	XPORTL1C	MOCEE' &	82101303 <b>4</b> 6*	50~346 <b>Я</b>
HITARI, K. R. HIVER, R. P. BEL. J. DEMAN, D. G. DEMAN, D. G.	8007310117 8210210034 8210070265 8210080293 8210080297		MITZON'N T MITZON'N T MITZON'N T MITZON'N T	8210050074 8210050076 8210050081 8210050086 8210050091				
DEMAN, D O DEMAN, D O DEMAN, D O DER: A V DERISANI, A II	8210150507 8210190673 8210250190 8210250402 8210150557	70-2450 70-1257	Wilson, J L Wilson, J L Wilson, J L Wilson, J L	8210050092 8210050103 8210050109 8210060361 8210060372				

AUTHOR	ACCESSIGN NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJEC	RY	AUTHOR	ACCESS LON NUMBER	EUD EIT CATEG P
WOLLETT.S WOLLETT.S	8210130587 8210190076	CONTRACT	YATES,K R YODER, O L	8210120102 8210150567	NUREG NUREG		Z IMMERMAN, J. V. Z IMMERMAN, J. V.	0210130052 0210130056	at Della
HÖLLETT. S	8210260278		YORK, F S	8210010223	₽R		Z IMMERMAN, J. V	6210130070	
HOLLETT, S	8210270027 8210270373		YORK, J H	8210010203		0	ZIMMERMAN, J V	8510590093	) F DATEL
			TORKI U W	8210010305	<b>50−389</b>	Ω	7 IMMERMAN, J V	8210260521	¥£⊔41⊾ի
HOLLEVER.E J HOLTNER.E	8210260143		YORK, J. H	8210010314		0	ZIMMERMAN, J. V	8210260541	a Pumila 14
HOLTNER, E F	8210290107 8210210238		YOUNG, F YOUNG, G G	82101500914 82100100674		O .	Z IMMERNAN, J. V	821026057 (	KPLOTEIZ
HONG, T	8210190246		YOUND M A	8210040016	50-460	G	ZIMMERMAN, J. V. ZIMMERMAN, J. V.	BJ10260574	11 (62 LL)
WONG T	8210250019	40-299	YOUNG, II A	8510580070	50-244	Ğ	Z IMMERMAN, J. V	0510590280 0510590470	A FIELER FLED A PLUR FLED
MOOD'E C	8210210015	50-309 B	YOUNG, T	B210060336*	50-312	œ.	ZIMMERHAN, J. V		
HOOD, E C	8210260193	50-309 5	γουχο, τ	8210040345*	50-528	ā	ZIMMERMAN, J V	021027400J 021027400J	ደ፤ (ምሽር)? 4፤ ዕካቸር (ር
MODD'E C	8210260199 8210270165	50-307 S 50-307 S	YOUNG, T	821025013B	50-312	S	V L MANNAMITS	0210,7000	MP DATE (L
HUUDHEAD, C P	8210040082	50-341 G	YOUNG, T YOUNG, T	821025036(* 8210250375*		G G	ZIMHERMAN, J. V	0210270099	ED (WILL)
WGGDHEAD, C P	0740470744						ZIMMERMAN, J. V	8510570100	V(41)/
WOODPUFF.R L	8210120261 8210010048	50-142 G State Prog	YOUNG, T YOUNG, Y A	8210280372*		Q .	Z IMMERMAN, J. V	0.210.27017.2	#1100TLU
MÕODRUFF.R L	8210010100	State Prog	YOUNGBLOOD, B J	8210040349 8210040285*	40-8793 50-338	Р	Z IMMERMAN, J V	8210270127	31 111 111 K
WOODRUFF, R L	8210010154	State Prog	YOUNGBLOOD, B J	8210040307*		P	Z IMMERMAN, J. V Z IMMERMAN, J. V	0210570147	■ F & 71L J+
WBODRUFF,R L	0210010358	State Prog	AONAGBFOOD'B 7	B210040320*	50~308	P	Z IMMERMAN, J. V	921022015a 8210220101	ar earling
чоорз. н ч	8101090296#	50-247 S	AORKESFOOD' B ?	8210040370	50~483				काताल्या दि
WOOLEVER,E J	0210070155	50-412 S	ACANGBTOOD'S ?	8210040373	50-482	A E	Z IAMERIAN, J. V. Z IAMERIAN, J. V	82102707.31	A F COLLEGE
WOOLEVER.E J WOOLEVER.E J	8210070233 8210260135	50-412 S 50-412 S	AONINGBEOOD'B ?	8210040377	50-341	À	Z I HMERMAN, J V	6210270218 6210270218	a Promitity
HOOLSEY, R T	8210120519	50-412 S 40-8781	AGANGBEGGD'B 1	8210120341	50-424	A	ZIRMERMAN, J. V	02102702414 02102702414	አፋ ውብቱ ( አፋ የረሻህን
WOOLSEY,R T				8210120344	50-358	۸	ZIMMERMAN, J. V	05105205015	MELLONE DE
HOOLSEY, R T	8210120624* 8210210515	40-8781 40-8084	YOUNGBLOOD, B J	8210120348	50-546	۸	Z IMMERMAN, J. V	821027020a	
WOZNIAK, D R	8210080319	XPORTLIC	AUNOBFOOD'B 1	8210210288 8210280420	50-387	P	Z THMERMAN, J. V	0210270207	A STREET OF
ALANA B	8210070345*	50-219 G	YOUNGBLOOD, B J	8210280429	50-454 50-454	A	ZIMMERMAN, J. O.	0210370590	# F (1 1 # L E)
WRAY, J R	8210080179	70-143	YOUNGBLOOD, B J	0210270008	50-546	Ä	ZIMMERMAN, J. V. ZIMMERMAN, J. V.	0≥1027031 i 8210270431	kPijlišti ti
WRAY, J R WRAY, R	8210150358*	50-335 Q	C G.GOOJEONUOY	8210290115	50-387	P		0000000411	11,1,41,11
WRIGHT, E G	8210250210	50-275 P	AOONGBCGOD'B ?	8210290128*	50-397	P	ZIMMERMAN, J V	0210270446	REDRUGE
WRIGHT, E G	8210180145* 8210180433*	FOIA FOIA	YOUNGBLOOD, D J YUHAS, C	8210290363	50-454	į.	Z IMMERMAN, J. V Z IMMERMAN, J. V	82102690 35 82102690 36	MUSILL
WRIGHT. G	8210250114*	50-373 G	YUHAS, G P	8210010260 8210280248*	50-206 50-397	5	V L INAMILANTIZ	0210/90036	X1,146.11 1 .
WRIGHT, N A	8210040018	50-329 G			50-347	Q	Z EMMERMANI J. V	8210/00409	#Fdlw1t1
WRIGHT, N A	8210080062	50-327 G	YUNDT, C P	8210190026*	50-344	F	Z LIMERMAN, J. V	0210/00414	F. F. L. 19. 71. 1
A N.THDIRW L R.THDIRW	8210260033	50-440 G	YUNDT, C P	9210250084 8210250164	50-344 50-344	6	2 IMMERMAN, J. V	0210200410	ME COUTE   ME CENTED
WRIGHT, R J	8210120178 8210120138	WASTE MOT	ZARBIS, W A	8210250074*	50~260	ន P	Z TRMERMAN, J. V	0210280472	ri will
	0510150170	WASTE MGT	ZEBROSXI, E L	8201190041*	FOIA	•	Z IMMERMAN, R. P. Z IMMERMAN, B. R.	#21029017 b	50 244 3
WRIGHT,R J WRIGHT,R J	8210120325	WASTE MOT	ZECH, G	8210120188*	50~3			9210090315	50 124 1
WRIGHT, R J	8210120358 8210120359	WASTE MGT WASTE MGT	ZECH, Q	0210120194*	LD19	P	ZIMHERMAN, G. R	0210060349	50 261 F
WRIGHT, R W	8210010143*	50~413 g	ZIBULSYY, H	8210220179*	70-371		ZIMMERMAN, B R ZIMMERMAN, B R	0210120644	50 PM F
WRICHT, R W	8210220145*	50-400 Q	ZIBULSKY, H Zielenbach, W R	8210220264* 8210120092	70~607		7 IMMERMAN, S. R.	0210130049 8210130295	MPROPERTY OF
WUDZKI, J J	B210120541*	CONTRACT		GETOTEOUTE:	NUREG		ZIMMERMAN, B R	BB1013035.1	70 CAL #
WULLER, O E	8209290072	50-461 A	ZIELENBACH, W R ZIMMERMAN, J V	8210120102	NUREG		ZIMMERMAN, 8 R	62101300 in	
WULLER, C E WULLER, C E	8210040104	50-461 A	ZIMMERHAN, J V	8210070433 8210070439	XPORTLIC		Z LIMERMAN, S R	8210130130	50 3/4 F
WULLER, G E	8210050278 8210050281	50-461 E	ZIMMERMAN, J V	0210070443	XPORTL1C XPORTL1C		Z IMMERMAN, 6 R	0210150264	00 241 7
	GE14030201	50-461 E	ZIMMERMAN, J V	8210080045	XPORTLIC		ZIMMERNAN.S R ZIMMERMAN.S R	0210250202	50 A81 F
WULLER, G E WULLER, O E	8210050289	50-461 E	ZIMMERMAN, J V	8210080138			Trink Milyari & 10	0210280054	30 4.0 (
WULLER, O E	8210130181 8210130270	50-461 Q	ZIMMERMAN, J V	82100B013B	XPORTLIC		ZIMMERMAN, G R	0210200275	50-324 r
WULLER, G E	6210130379	PR PR	ZIMMERMAN, J V	8210080149	XPORTLIC		ZIMMERMAN, S R	8210290356	50 PAL P
WVLLER, C E	8210130490	50-461 A	ZIMMERMAN, J V ZIMMERMAN, J V	8210080153	XPORTLIC		ZIRWAB, K R ZUDANS, Z	8210150049# 8208290026	50 217 5
WULLER, G E	8210150357	E0-4/1 .	-	8210080157	XPORTL IC		ZUDANS, Z	0200290026	ACRS ACRS
WULLER, G E	6210260003	50-461 A 70-2946	ZIMMERMAN, J V Zimmerman, J V	8510080195	XPORTLIC		ZUDANS, Z		
WULLER, G E	B210280089	50-461 A	ZIMMERMAN, J V	8210080334 8210080343	XPORTLIC		ZUDANS, Z	0210100390+ 0210270390	CCM1RAC1 50 341 (
WYSOCKI, J	8210010381 8210150552	PR	ZIMMERMAN, J V	82100B0345	XPORTLIC		ZUDANS, Z	6210270396	50-341
VANDELL : :		NUREG	ZIMMERMAN, J V	8210080348	XPORTLIC XPORTLIC		ZUFELT, E ZUKOR, D	8210200024	50 131 4
YANDELL,L A	8210190539*	50-285 q	ZIMMERMAN, J V	8210120117			- voca i p	02030906694	50-354 n
YARNICK, T P	8210190429* 8210260557	50-282 р 40-8102	ZIMMERMAN, J V	8210120117	XPORTLIC XPORTLIC		ZUMMD, J	B210290240	PR
YARNICK, T P	8210270195	40-8102	ZIMMERMAN, J V	8210120517	XPORTLIC		SONNO N W	8210250245	50-72 /
YATES, K R	8510150045	NUREG	ZIMMERMAN, J V ZIMMERMAN, J V	8210130055	XPORTLIC		ZURAKOWSKI,PR ZWETZIO.O B	0210080311* 0210060141*	70-754
			······································	8210130059	XPORTLIC		ZWETZIO, O B	0210060299#	50-275 2 50-205 2
							ZWIEQ, A	82101505364	04959

6.A 82101505364 QA959

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents,"

AUTHUR AFF IL IATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFF IL JATION	ACCESSION NUMBER	SUBJECT CATEGOR	
AMAZ, Inc  ATResparch Associates, Inc  Agnodis, The	8210080033 8210080035# 8210250035 8210150557 8210150192	XPORTLIC XPORTLIC 40-8820 NUREG 50-289	<b>a</b>	Alden Research Laboratory Allied Chemical Corp American Electric Power Service Corp	8210080022* 82100 50388 82101 30287* 82101 50600 82100 70286*	CONTRACT NUREG 50-369 40-3392 50-315	E I
Aerojet Energy Conversion Co. (subs. of	8210210359 8210260400 8210060255	50-289 50-289 TOPREP	9 9	American Opophysical Union American Institute of Aeropautics & Astronautics	8210190002* 8210120432*	CONTRACT	
General Tire & Rubber Co )	8210060257* 8210060257*	TOPREP TOPREP		American Nuclear Insurers	8210010307 8210040275 8210290255	PR TOPREP PR	
Air Force, Dept of Air Force, Dept of, Radiossotope Committee	8210070459* 8210270179 8210270182*	CONTRACT 40-8577 40-8577		American Nuclear Society	8210010218 8210010232 8210220379	PR PR PR	
Alabama Power Co	8510010154 8510010154	50-348 50-348	6 8	Amerisham Corp	8210080232*	71-9167 71-9167	
	8210010139* 8210010147* 8210010195 8210010195 8210010224	50-348 50-348 50-348 50-348 FR	9 9 F F	Ansheim, CA Andrulis Research Carp Antíoch Callege of Law	8210980239* 8210250356 8210270221* 8210270223* 8210150341	71-9167 PROJ CONTRACT CONTRACT 50-155	
	8210050066 8210050069 8210060294	50-364 50-364 Toprep	b b	Appling County, OA Argonne National Laboratory	8210210381 8210120425* 8208290019	50-155 CONTRACT	G
	8210130270 8210130527	PR 50-364	P		821 -		
	8210150074* 8210150338 8210150344* 8210150373* 8210170073*	50-348 50-364 50-364 50-348 50-348	0 P F F	Arizona Public Service Co			
	8210190609 8210190614* 8210190722 8210190723*	50-348 50-348 50-348 50-348	9 8 R R				
	8210190747 8210190773*	50~364 50~364	R R		95100.40519	50-528	В
	8210250090 8210260418 8210260437 8210260453	50-364 50-364 50-364 50-348	P P P		9210070219 9210070229 9210070229 9210070229	50-530 50-528 50-528 50-528	888
	8210240453 8210260443* 8210260470* 8210260480* 8210260490*	50-348 50-348 50-348 50-348 50-348	9 8 6 8		0210070320 0210070320 0210070320 0210070321 0210070339	50-528 50-528 50-528 50-528 50-528	3 3 3 3 5
	8210280158 8210280158 8210280145* 8210280145* 8210280282	50-348 50-348 50-348 50-348 50-364	Р Р Р		8210070339 8210070339 8210070354 8210070374 8210070371	50-528 50-528 50-528 50-528 50-529	***
Jahara. Univ of.	8210290289 8210290292* 8210070355* 8210070358*	50-364 50-364 50-438 50-438	8 8 A A	•	8210080155 8210130187 8210130394 8210130443	50-528 50-528 PR 50-528	0 8 0

AUTHOR AFF IL IAYION	ACCESS ION	SUBJECT CATEGORY	AUTHOR AFF ] L ( AT	ACCESSION REMUN	SUBJECT CATEGORY
	8210130444 8210130491 8210130495 8210130544 8210130544	50-530 S 50-530 S 50-529 S 50-529 S 50-529 S	BHR Owners Group  Babcock & Hilcox Co	8210270253 8210050053 8210250181 8210250184* 8207070007	PR TOPREP TOPREP TOPREP TOPREP
	8210150163 8210150176* 8210150315 8210150463 8210150717	50-528 A 50-528 A 50-528 E 50-528 A 50-528 A		8210010284* 8210040344 8210120304* 8210120315* 8210130308*	50-329 E TOPREP GA999 GA999 70-135
	8210190717 8210220394 8210250100 8210250305 8210250326	50-528 A 50-528 B 50-528 S 50-528 S 50-528 S	Backus, R A	8210220231 8210220497 8210250132 8210270232 8210040194	70-824 70-27 PT&1 70-27 50-443 G
	8210240275 8210240543 8210270211 8210280057 8210280057	50-528 S 70-2949 50-528 A 50-528 A 50-528 A	Baitimore Cas & Electric Co	8210060194 8210060206* 8210060206* 8210040066 8210040069*	50-443 C 50-443 C 50-443 Q 50-318 4 50-318 S
	8210280057 8210280139 8210280139 8210280139 8210280199	50-528 A 50-528 A 50-528 A 50-528 A 50-528 A		8210040142 8210040144* 8210040211 8210040214 8210040219*	50-317 G 50-317 G 50-318 G 50-318 G
Arizona State Univ Arizona, Univ of	8210280199 8210280199 8210280274 8210150431 8210050508#	50-528 A 50-528 A 50-528 E RES CONTRACT		8210040224* 8210040385 8210040390* 8210040394* 8210070159	50-318 8 50-317 9 50-317 9 50-317 9
Arkansas Power & Light Co	8210210066* 8210040109 8210040111* 8210050346 8210070395	CONTRACT 50-313 P 50-313 P 50-368 S 50-313 F		8210130103* 8210130338 8210130338 8210130342* 8210130342*	50-317 Q 50-317 P 50-317 P 50-317 P
	8210070395 8210120247* 8210120252* 8210130212 8210130214*	50-313 F 50-313 Q 50-313 Q 50-313 S 50-313 S		8210130391 8210130461 8210130465* 8210130543 8210130558*	PR 50-317 5 50-317 5 50-317 5
	8210130382 8210130388* 8210130407 8210130513 8210130522*	50-313 9 50-313 8 50-348 P 50-313 8 50-313 9		8210130548 8210130578* 8210150423 8210180005 8210180039	50-317 5 50-317 6 50-317 F 50-317 F 50-318 0
	8210150002 8210150073 8210150073 8210150494 8210190517	50-313 P 50-313 F 50-313 F 90-313 P 50-313 S		8210180124 8210190290 8210190296* 8210190730 8210190803*	50-317 P 50-317 S 50-317 S 50-317 S
	8210170526* 8210170545 8210170598* 8210220114 8210250157	50-313 B 50-268 B 50-368 9 50-313 P 50-368 P		8210190803* 8210210328 8210210328 8210210457* 8210210457*	50-317 0 50-317 P 50-317 R 50-317 R
	8210250161* 8210250204 8210250292 8210250298* 8210260120	50-368 P 50-313 P 50-368 S 50-368 S 50-368 S		8210210546* 8210210546* 8210210551* 8210210531* 8210220378	50-317 F 50-317 F 50-317 F 50-317 F 50-318 P
	8210240123* 8210240180* 8210240192 8210270101 8210280112*	50-368 8 50-313 4 50-313 P 50-348 P 50-313 F		8210220385* 8210250088 8210250075* 8210250154 8210250160*	50-318 P 50-318 S 50-318 S 50-317 S 50-317 S
Armed Forces Radiobiological Research Institute	6210280112* 6210280114* 8210290240 8210260425	50-313 F 50-313 F FR 50-170 G		82;0240277 8210270237 8210270241* 8210270244 8210270248*	50-318 P 50-318 S 50-318 S 50-317 S
Army,Dept of, Headquarters Materiel Development & Readiness Command	8210270227*	40-8432 40-8632		8210270252 8210270257* 8210270266	50-317 9 50-317 9 50-317 9
Army.Dept of Army.Dept of, Corps of Engineers Aspects, Inc Associated Technologies, Inc	8210190105# 8210120471# 8210190147# 8210220226	CONTRACT CONTRACT CONTRACT PR		8210270269* 8210270272 8210270273* 8210270274	50-317 S 50-317 S 50-317 S 50-317 S
Atlas Minerals  Atom Sciences, Inc.	8210150596 8210260079 8210260080* 8210120440*	40-3453 40-3453 40-3453 CONTRACT		8210270274 8210270275* 8210270276 8210270278*	50-317 S 50-317 S 50-317 S 50-317 S
Atomic Industrial Forum	82040 400 13* 82092 70379* 82101 30280 82102 70242	COMMISSION PRM PRM PR	•	8210270279 8210270280* 8210280134 8210280141* 8210280191	50-217 9 50-317 8 50-318 9 50-318 5 50-318 S

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	t Author Affiliation	ACCE 5 G I ON NUMBER	SUBJECT CATEGOR	
	8210280194 8210280195* 8210280200* 8210280203 8210280205*	50-318 50-318 50-318 50-317 50-317	3 8 9 9		82100 50164 82100 60023 82100 60030# 82100 60080 82100 60085#	50-293 50-293 50-293 50-293 50-293	9 9 9
	8210280249 8210280255* 8210280263 8210280267* 8210280279	50-317 50-317 50-317 50-317 50-318	8 8 8 8 8 8		8210060164* 8210060160* 8210070245 8210070247* 8210070340	50-293 50-293 50-293 50-293 50-293	0 0 5 8
	8210280294 8210280294 8210280301* 8210280305 8210280313*	50-318 50-317 50-317 50-317 50-317	ន		9210070346* 8210130399 9210130472 8210130479* 8210150444	50-293 PR 50-293 50-293 50-293	8 8 8
Cattelle Memorial Institute, Columbus Laboratories	8210280318 8210280332* 8210280334 8210280341* 8210180592	50-317 50-317 50-318 50-318 NUREO	5 5 5 5 5		8210190235 8210190237* 8210190721 8210250065 8210250122	50-293 50-293 50-293 50-293 71-6346	8 0 P
sttelle Memorial Institute, Pacific Northwest Laboratory	8210190087# 8210190420# 8210190428# 8210210014 8209140027#	CONTRACT 50-333 50-333 NUREO 50-244	T G Q P	Boston State College	82102 80129 82102 80131 * 82102 80146 82102 80150 * 82101 50350 *	50-293 50-293 50-293 50-293 CONTRACT	8 8 8
Workings reports to the	8209210523* 8210050418 8210070254* 8210070315*	50~309 NUREQ 50~537 50~537	P A D	Brookhaven National Laboratory	9207180064 9210070449 9210120367 9210120390 9210120495	ACRS RES RES RES RES	
	8210070318* 8210070323* 8210070327* 8210070332* 8210070335* 8210070347*	50-537 50-537 50-537 50-537 50-537	D D D D		8210120459 8210120466 8210120466 8210120630 8210120642#	reb res reb res 50-341	A
	6210070465* 6210060009* 6210060322 6210120092 6210120102	50-537 50-537 CONTRACT REB NUREG	Р	Oryant & Bryant AlA Burns & Roe Co Bursey, D	8210120649 8210220135 8210210444* 8210240173* 8210150458	RES NUREQ CONTRACT QA999 50-395	G
	B210120125 B210150553 B210220149 B210270041* B210270421	NUREG NUREG NUREG NUREG 50~537	o	C-E Operating Plants Dumars Group C I took & Co (America), Inc Cabot Corp California, State of	8210040323 8210080324 8210080339 8210050180 8210290097		G P
ar Crenk Uransum Co chtel Corp	8210290041 ± 0210150644 6210050248 6210060241 ±	RES 50-285 40-8452 50-329 50-155	P R P	Calitornéa, Univ of, Berkeley	8107270146* 8107270149* 8107270178* 8107270178* 8107270178*	50-266 50-266	а е е е
	8210130505* 8210150373* 8210190470 8210190470 8210220287	50-329 50-424 50-275 50-275 PR	T A P P		8107270182* 8107270182* 8107270185* 8107270185* 8107270188*	50-246 50-246 50-266	0 0 0 0
uvrordyng Paychological Corp isinger, DuPont & Associates, Inc	8210260504 8210270351 8210270351 9210130399 9210130399	50-327 50-275 50-275 PR PR	P P		8107270191* 8107270194* 8107270196* 8107270198* 8107270199*	50~246 50~264 50~266	0 0 0 0 0 0
eridge, Fafrbants, & Diamond choff, C A	8210240347 8210240347 8210240373 8210240373 8210130417	50-339 50-339 50-339 50-338 50-528	0 0 0 0	California. Univ of. Los Angeles	8210150456 8210200081 8210250076 8210250043* 8210250051*	50-142 50-142 50-142	9 9 9 7
hop, L t.	8210270171 8210070132 8210070132 8210070136 8210070136	50-528 50-329 50-329 50-329 50-329	0 6 8 0	Caivert Gounty, ND Cammer & Shapiro Carolina Environmental Study Group Carolina Power & Light Co	8210180371* 8210150234 8210260150 8209140148 8209140153*	50-413 50-324	o D F
ing Computer Services, Inc. (subs. of ling Co.)  -Barner Corp	8210070140 8210260561* 8210150517* 8210150526*	50~329 CONTRACT GA999 GA999	Q		8209160299 8209160311* 8210010028 8210010183* 8210010188*	50-325 50-241 50-324	\$ H G G
on College on Edison Co	8210290367 8210290372* 8210180362* 8204160212 8204160222*	XPORTLIC XPORTLIC CONTRACT 50-293 50-293	G G		8210010248 8210010303* 6210010340* 6210010347* 6210010473	50-324 50-400 50-324	8 8 0 0 8
	82041 60225* 82071 80064 82100 40100 82100 40105*	50-273 FOIA 50-273 50-273	8 8		8210010475# 8210050009 8210050106 8210050106 8210050125	50-261 50-400 50-400	8 A A

# CUMPURATE SOURCE INDEX

AFF ILIATION	NUMBER	CATEGOR	Y	AFF IL IATION	NUMBER	CATEGOR	Y
	8210050125 8210050362 8210050362 8210050371* 8210050371*	50-400 50-324 50-324 50-324 50-324	A P P P		8210220409 8210220412 8210220412 8210220484 8210220492*	PR 50-400 50-400 50-400 50-324	5 5 7 <b>Q</b>
	8210040013 *410040014 *8210040314 8210040314	50-261 50-261 50-324 50-324 50-324	P P F F S		8210220499* 8210250202 8210260244 8210260244 8210260256	50~261 50~261 50~324 50~324 50~325	9500
	8210040323# 8210040323# 8210040327# 8210040349 8210080180	50-324 50-324 50-324 50-261 50-400	r r 9 r 9		8210260264 8210260267 8210260294 8210260318* 8210260323	50-325 50-324 50-325 50-324 50-324	5 5 5 p
	8310080350 8310080350 8310080183* 8310080180	50-400 50-325 50-325 50-325 50-324	1) 5 5 5		8210240323 8210240325* 8210240325* 8210240344 8210240348*	50-324 50-324 50-324 50-325 50-325	ម ម ម
	8210080230# 8210080283 8210120645# 8210120647# 8210130242	50-324 50-400 50-241 50-241 50-241	8 8 F R		8210260398 8210260398 8210260405 8210260405 8210260410*	50-400 50-400 50-324 50-324 50-324	999
	8210130244* 8210130295 8210130295 8210130323 8210130323	50-261 50-324 50-324 50-261 50-261	л Г Н Н		8210260410* 8210260462 8210260475 8210260482* 8210260508	50-324 50-400 50-261 50-261 50-361	P A P P
	8210130323 8210130323 8210130477 8210130463* 8210130469	50-241 50-241 50-325 50-325 50-325	11 5 8		8210260511* 8210280054 8210280275 8210280275 8210280278*	50-261 50-400 50-324 50-324 50-324	P C C C C
	8210130497* 8210130539 8210130550* 8210130567 8210150016*	50-325 PR PR 50-400 50-324	ទ ព		8210280278* 8210290074 8210290078* 8210290079 8210290099*	50-324 50-261 50-261 50-324 50-324	0000
	82101 50023* 82101 50030 82101 50038* 82101 50041 82101 50045*	50-924 50-924 50-924 50-924 50-924	Q ទ ទ ទ ខ		8210290243 8210290246* 8210290258 8210290258 8210290258	50-924 50-324 50-400 50-400 50-400	55555
	8210150046* 8210150106* 8210150198 8210150264 8210150291	50-324 50-324 50-261 50-261 50-324	8 9 P P 8		8210290325 8210290331* 8210290333 8210290336 8210290339*	50-325 50-325 50-26! 50-324 50-26!	9 4 9 8
		50-324 50-400 50-324 50-155 50-400	g 9 9	Garpenter Technology Corp	8210270342# 8210270346 8210270352# 8210270358 8210080317	50-324 50-325 50-325 50-261 XPORTL10	\$ \$ \$
		-2	8 8 8 A A	Center for Law in the Public Interest Gerac, Inc Chapel Hill Anti-Nuclear Group Effort	8210080320* 8210050218 8210220517 8210270281 8210010328	XPORTLIC 50-275 XPORTLIC XPORTLIC 50-400	C G
				Charlevoix.MI Chattanooga.TN	8210010337 8210150340 8210210419 8210190215* 8210260520*	50-400 50-400 50-400 CONTRACT CONTRACT	G G G
	##1040009	50-400	Ğ	Chem-Nuclear Bystems. Inc Cherry, M. M. /Cherry, Flynn & Kanter	8210280388 8210070127 8210070127 8210070129*	71-6601 50-454 50-454 50-454	G G
	8210200013* 8210200013* 8210200021* 8210200021* 8210200032	50-400 50-400 50-400 50-400 50-400 50-400	6 6 6 6 C		8210070129* 8210180151 8210210278 8210210278 8210210384 8210210384	50-454 50-454 50-454 50-454 50-454 50-454	00000
	B210200084 B210200084 8210200084* B210200086* 8210220075	50-400 50-400 50-400 50-400 50-400	C C C C S		8210250071 8210260380 8210260380 8210260384* 8210260384*	50-454 50-454 50-454 50-454 50-454	00000
	8210220075 8210220125 8210220265 8210220247* 8210220265	50-400 50-400 50-261 50-261 PR	8 G S S	Chicago, Univ of Christa-Maria	8210270273 8210270305 8210170063* 8210150341 9210210381	50-454 50-454 CONTRACT 50-155 50-155	0 0 0

AUTHOR AFF (LIATION	ACCESSION NUMBER	SUBJE CATEG		AUTHOR AFF 16.1 ATTON	ACCESSION	ເດຊຸບຂ	ECT
irczrnati Oas & Electric Go	8210050137 8210050332 8210050334* 8210060271 8210060309	50-258 50-258 50-258 50-258 50-258	K K S		NUMBER 8210240419 8210240419 8210280231 8210280246 8210290287	50-440 50-440 50-440 50-440	A A G G
	8210040358 8210070402 8210130294 8210130297* 8210130372	50-358 50-358 50-358 50-358 50-358	G	Coalition for Safe Power Cobe Laboratories, Inc Colorado State Univ Colorado, State of Colt Industries, Inc	8210050389 6207180039 62101502234 8210120379 82102204174	WASTE	9 G
	8210150387 8210150443 8210180154 8210260279 8210260488	50-358 50-358 50-358 50-358 50-358	8 8 8	Columbia Univ Combustion Engineering, Inc	8210290307 8210040327* 8210120397 8210130504* 8210150304	50-209 TOPREP RES	o
tizens Association for Sound Energy	8210270281 * 8210270285 * 8210270270 * 8210270277 8210150224	50-359 50-359 50-359 50-359 50-445	G G G		8210150313* 8210150319* 8210180133* 8210170004* 8210200022	50-470 50-470 50-317 CONTRAC 50-368	E E P CT
titens for Nuclear Reactor Safety, Inc	8210250104 8210280355 8210150200 8210150317 8210150395	50-445 50-445 50-170 50-170 50-170	G H G G	Commerce.Dept of National Bureau of Standards	8210220440 8210280202 8210290240 8210050530≠	70-1100 50-470 PR CONTRAC	D EE
leeland Electric [[]uminating Co	8210150395 8210220439 8210220448* 8210280220 8210010345	50-170 50-170 50-170 50-170 50-440 50-440	6 6 6 0	Commonwealth Edison Co	8210130140 8210130140 8210130143* 820929018* 820929028* 8210010009	70-378 50-184 50-10 50-10	R R F
	8210010457 8210010457 8210040146 8210040146	50-440 50-440 50-440 50-440 50-440	и 8 8 8		8210010009 8210010202 8210010202 8210010202	50-237 50-237 50-237 50-454 50-454 50-454	r r r r
	8210040150* 8210050132 8210050255 8210050255	50-440 50-440 50-440 50-440 50-440	K 6 0 0		8210010202 6210010202 6210010271 8210010271 6210010271	50-454 50-454 50-454 50-454 50-454	EAAA
	8210050374 8210070405 8210130173 8210130173	50-440 50-440 50-440 50-440	9 6 6 6		8210010271 8210010271 8210010381 8210040060 8210040060	50-454 50-454 PR 50-454	A A
	8210130179 8210130364 8210130364 8210150161 8210150228	50-440 50-440 50-440 50-440	A 60 60 60 60 60 60 60 60 60 60 60 60 60		82100 40116 82100 40121* 82100 40126 82100 40129* 82100 40131	50-454 50-304 50-304 50-249 50-249	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8
	8210150228 8210150233 8210150447 8210180155	50-440 50-440 50-440 50-440	0 0 0 0 0		8210040134* 8210040188 8210040189* 8210040218	50-373 50-373 50-237 50-237 50-295	9 8 8 9
	8210180155 8210190326 8210190324 8210190333 8210190333	50-440 50-440 50-440 50-440 50-440	0 A E E		8210040221 8210040221 8210040223+ 8210040223+ 8210040244+	50-295 50-373 50-373 50-373 50-456	ե ե
	8210190483 8210190483 8210210079 8210210284 8210210284	50-440 50-440 50-440 50-440 50-440	E A Q		8210040249 8210050056*		
	8210210353 8210210353 8210220305 8210220309	50-440 50-440 50-440 50-440 50-440	0				
	8210220309 8210220372 8210220376 8210220376	50~440 PR PR 50~440 50~440	о о				
	8210220405* 8210220405* 8210250277 8210250277 8210250322	50-440 50-440 50-440 50-440 50-440	0 0 0		8210040252* 8210040242 8210040247* 8210040248*	50-373 50-304 50-304 50-373	9 8 8
	8210250322 8210260009 8210260011* 8210260337* 8210260337*	50-440 70-2968 70-2968 50-440 50-440	0 0		8210040263 8210040347* 8210040347* 8210040395 8210040405*	50-295 50-237 50-237 50-254	J 0 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOS	
	8210080030* 8210080031* 8210080111 8210080111	50-275 50-295 50-295 50-295 50-295	Г F F P		8210190344 8210190346# 8210190403 6210190412# 8210190443	50-373 50-373 50-249 50-249 50-295	9 9 9 9
	8210080178 8210080178 8210080178 8210080178 8210080178	50-237 50-237 50-237 50-237 50-237	9 9 9		8210190445 8210190445 8210190445 8210190445 8210190445	50-237 50-237 50-237 50-237 50-237	թ թ թ
	B210080178 B210080178 B210120105 B210120105 B210120105	50~237 50~237 50~237 50~237 50~237	Q Р Р		8210190458 8210190462 8210190464 8210190468* 8210190471*	50-249 50-373 50-237 50-373 50-249	ទ ទ ទ
	8210120105 8210120551* 8210130192 8210130196* 8210130197	50-237 50-254 50-254 50-254 50-249	P F S S		8210190481* 8210190483 8210190487 8210190493* 8210190494*	50-373 50-295 50-373 50-295 50-373	5 6 5
	8210130200 8210130201* 8210130235* 8210130233 8210130233	50-373 50-249 50-373 50-373 50-373	R 3 # P P		8210190498 8210190503* 8210190509 8210190514* 8210190522	50-373 50-373 50-373 50-373 50-373	998
	8210130234 8210130236* 8210130241 8210130241 8210130251	50-373 50-373 50-373 50-373 50-254	8 P 8		8210190525* 8210190536 8210190565 8210190573* 8210190606	50-373 50-373 50-237 50-373 50-373	9 8 9 0
	6210130253* 6210130324 8210130326* 6210130370 8210130370	50-254 50-254 50-254 50-454 50-454	8 9 F		8210190624* 8210190624* 8210190658 8210190662 8210190689	50-275 50-275 50-254 50-456 50-275	9 9 9 9
	8210130373 8210130373 8210130376 8210130376 8210130376	50-454 50-454 50-10 50-10 50-10	0 6 F F		8210190700* 8210190715* 8210190737 8210190744* 8210190780	50-254 50-295 50-373 50-373 50-254	6 6 6 6
	8210130374 8210130374 8210130374 8210130374 8210130374	50-10 50-10 50-10 50-10 50-10	F F F		8210200002 8210200007* 8210200035 8210220335 8210220358	50-373 50-373 50-247 50-237 50-10	ն 0 ր
	8210130374 8210130374 8210130374 8210130374 8210130374	50-10 50-10 50-10 50-10 50-10	F F F F		8210220358 8210220358 8210220358 8210220358 8210220358	50-10 50-10 50-10 50-10 50-10	Г Г Г Г
	8210130376 8210130386 8210130386 8210130390* 8210130390*	50-10 50-254 50-254 50-254 50-254	F R R R		8210220358 8210220369 8210250069 8210250069	50-10 PR 50-245 50-237 50-237	F P P
	821 01 30402 821 01 30413 821 01 30423# 821 01 30466 821 01 30473#	PR 50-254 50-254 50-254 50-254	\$ 8 8		8210250049 8210250108 8210250108 8210250108 8210250114	50-237 50-454 50-454 50-454 50-254	Р Е Е
	8210130501 8210130511# 8210150044 8210150049# 8210150097	50-254 50-254 50-237 50-237 50-249	8 8 8		8210250124# 8210250148 8210250152 8210250153# 8210250155	50-254 50-254 50-373 50-254 50-254	բ 3 5
	8210150102* 8210150405 8210150405 8210150411* 8210150411*	50-249 50-295 50-295 50-295 50-295	8 8 8		8210250155 8210250163* 8210250169* 8210250169* 8210250211	50-254 50-373 50-254 50-254 50-456	ր 9 P Q
	8210180097 8210180097 8210180097 8210180100* 8210180100*	50-10 50-10 50-10 50-10 50-10	R R R R		8210250211 8210250248 8210250278* 8210250283 8210250294*	50-456 50-237 50-237 50-237 50-237	6 8 8
	82101 80100# 82101 80142 82101 80142 82101 80144 82101 80167	50-10 50-454 50-454 50-454 50-304	R Q Q Q B	•	8210250304 8210250309 8210250316* 8210250324 8210250324	50-249 50-254 50-249 50-247 50-247	S & & & & & & & & & & & & & & & & & & &
	82101 80175* 82101 80194 82101 90050 82101 90058* 82101 90299	50-304 50-10 50-373 50-373 50-456	9 9 9 9		8210250328 8210250348* 8210260023 8210260115 8210260118*	50-249 50-249 71-9079 50-373 50-373	9 9 9

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUDJEC CATEQO	
	8210240151 8210240151 8210240210 8210240219 8210240221*	50~373 50~373 50~373 50~304 50~373	83 83 84 64	***************************************	8210270200 8210270245 8210270249* 8210280071 8210280074*	50-213 50-213 50-213 50-213 50-213	P 9 8 8 8
	8210260223* 8210260227 8210260233 8210260238* 8210260234*	50-204 50-273 50-275 50-273 50-275	4 4 4 4	Connectácut, State of Conner & Wetterhahn	8210280397# 8210050197 8210050197 8210050326 8210050382	CONTRAC 50-352 50-352 50-352 50-352	7 0 0 0
	0210240295 8210240297* 8210240308* 8210240311 8210240313*	50-373 50-373 50-454 50-373 50-373	8 0 9	Compyer & Associates, Inc. Insurance	921 00 50382 921 00 70402 921 0200066 921 0270297 921 0060020	50-352 50-359 50-352 50-358 70-1621	G G
	8210260317 8210260321* 8210260399 8210260411* 8210260485	50-373 50-373 50-295 50-295 50-237	9 10 10 10 10	Conservation Council of North Carolina Consolidated Edison Co. of New York	821021034B 8210010401 8210010401 8210010409* 8210010409*	50-400 50-3 50-3 50-3 50-3	ե Ե Ե
	8210240524 8210240524 8210240524 8210240524	50-10 50-10 50-10 50-10	4 4		8210010414* 8210010414* 8210010425* 8210010438* 8210010443*	50-3 50-3 50-3 50-3 50-3	6 6 6 6
	8210260526 8210260526 8210260526 8210260526	50-10 50-10 50-10	9 9 9		8210010449* 8210040141 8210040145* 8210040232 8210040232	50-3 50-247 50-247 50-247 50-247	Р 9 8 Т 7
	8210240524 8210240524 8210240524 8210240524 8210240542*	50-10 50-10 50-10 50-10 50-10			8210040394 8210040400* 8210070341 8210070344* 8210120253	50-247 50-247 50-247 50-247 50-247	8 8 8
	B210260542* B210260542* B210260542* B210260542* B210260542*	50-10 50-10 50-10 50-10	स स स स		8210130277 8210130411 8210130419* 8210130455 8210130559*	PR 50-247 50-247 50-247 50-247	6 6 6
	8210260542* 8210260575* 8210260575* 8210260579* 8210260579*	50-10 50-440 50-440 50-440 50-440	p r r r		8210196693 8210250081 8210250081 8210250099 8210250145	50-247 50-247 50-247 50-247 50-247	р 0 0 8
	6210270251 6210270254* 6210260120* 6210260120* 6210260125*	50-249 50-249 50-295 50-295 50-373	6 1. 8		6210250149* 6210240332 6210260154* 6210260154* 6210260159*	50-247 50-247 50-3 50-3 50-3	8 P F F
	8210280126# 8210280126# 8210280364# 8210280364# 8210280375#	50~295 50~295 50~254 50~254 50~254	L	Consultation Coal Go Consumers Power Co	8210290271 8210040214 8207070419 8207070419 8207070422#	50-247 50-10 50-329 50-329 50-329	0 Р К К
	8210280375+ 8210280424+ 8210280424+ 8210280427+ 8210280427+	50-254 50-295 50-295 50-295 50-295	ا د د		82070 70422# 82070 70428# 82071 80052 82100 10278	50-329 50-329 FOIA 50-329	к К Е
	8210280445# 8210280445# 8210280447# 8210280447* 821029060#	50-295 50-295 50-295 50-295 50-10	1 F F F				
tech Engineering Services, Inc	8210290077* 8210290088* 8210290245 8210040178* 8210190010*	50-10 50-10 PR 50-206 Contract	F F T				
eticut Yankee Atomic Power Co	8210190156* 8209300326 8210010207 8210010207 8210010207	CONTRACT 50-213 50-213 50-213	የ የ የ የ				
	8510010315 8510010315 8510010315 8510010530 8510010510*	50-213 PR 50-213 50-213	Р Р Р				
	82100 50376 82101 30331 82101 50122 82101 50128* 82101 90663	50-513 50-513 50-513 50-513	8 8 8				

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
**************************************	8210040173 8210040204 8210040213 8210040214* 8210040222	50-329 50-155 50-255 50-255 50-155	9 9 5 F		8210280076 8210280107 8210280276 8210290163* 8210290163*	50-327 G 50-255 F 50-255 P 50-329 G 50-329 G	
	8210040237 8210070013 8210070013 8210070013 8210070014*	50-155 50-155 50-155 50-155 50-155	թ թ թ		8210270228 8210270228 8210270227# 8210270227# 8210270240	50-329 A 50-329 A 50-329 A 50-329 A	
	8210070014* 8210070018* 8210070018* 8210080082	50-155 50-155 50-155 50-255	Р Р С	Controls for Environmental Pollution,	8210290380# 8210290380# 8210200106#	50~329 0 50~329 0 70~820	
	8210080099	50-255	o		8210260041* 8210260049*	70-820 70-820	
	82100 80115 82100 80115 82100 80279 82101 20078 82101 30005*	50-329 50-329 50-155 50-255 50-329	R R O P F	Convai, Inc Cooper Energy Sørvices Cornell Univ Cotter Corp	8210290247 8210120236 8210050412 8210240086 8210240091*	50-247 B PT21 NUREO WASTE MOT WASTE MOT	
	8210130007* 8210130138 8210130145* 8210130146 8210130156*	50-329 50-255 50-255 50-255 50-255	F R S S	Council on Economic Priorities Creare, Inc Critical Mass Energy Project	8207110023 8210050360 8206060002 8210010006 8210080010	70-1510 NUREQ FOIA FOIA FOIA	
	8210130264 8210130264 8210130265 8210130265 8210130266*	50-329 50-329 50-329 50-329 50-329	К К Т Т К	D'Appolonia Consulting Engineers, Inc Dairyland Power Cooperative	8210270439* 8210010389 8210010394* 8210040152 8210050067	40-8681 50-409 P 50-409 P 50-409 P 50-409 P	
	8210130267* 8210130267* 8210130334 8210130448 8210130457*	50-329 50-329 50-255 50-155 50-155	К Р С С		8210050070* 8210050939 8210130365 8210130381 8210130416*	50-409 P 50-409 P 50-409 F PR 50-409 Q	
	8210130471* 8210130482 8210130474 8210130474 8210130505*	50-155 50-329 50-329 50-329 50-329	1 1 0 0		8210150203 6210190446 6210190446 8210190454# 8210190654#	50-409 P 50-409 P 50-409 B 50-409 B	;
	82101 30505# 82101 30521 82101 50146 82101 50152# 82101 50300	50-329 PR 50-255 50-255 50-155	T 9 9 6		8210220009 8210220176 8210250349 8210260319 8210280048#	50-409 J 50-409 G 50-409 F 50-409 F	l 1
	82101 50307* 82101 50470 82101 50533 82101 80186 82101 80191*	50-155 50-155 50-155 50-255 50-255	0 0 F 5 5		8210280051* 8210280053* 8210280055* 8210290151 8210290307	50-409 F 50-409 F 50-409 F 50-409 P	
	8210180206 8210180212 8210180242 8210190364	50-155 50-329 50-155 50-329	G G K	Dats Design Laboratories DeKalb Area Alliance for Responsible Energy	B210060348# 8210210346	50-209 P 50-454 0	
	82101 90344 82101 90459	50-329 50-155	K P		8210210344 8210210347* 8210210347*	50-454 0 50-454 0 50-454 0	
	8210170437 8210170459 8210170535 8210170546 8210170546	50-155 50-125 50-255 50-255 50-255	6 6 6	Debeydise & Liberman	8208290088 8210040024* 8210050202 8210050202 8210050208*	FGIA 50-445 0 50-413 0 50-413 0 50-413 G	!
	8210170415* 8210170420 8210170428* 8210170437	50~255 50~255 50~255 50~255		Debevoise & Plimpton Defense, Dept of, Defense Nuclear Apency	8210050208* 8210130299 8210220383 8210040179 8210130528	50-413 G 50-445 G PR 50-348 M PR	<b>)</b>
	8210170649* 8210200029 8210210294 8210210294 8210220117	50-255 50-155 50-329 50-329 50-155	G A A P	Del-Aware Unlimited, Inc.	8210010244 8210010244 8210180204 8210180204 8210180208*	50-352 0 50-352 0 50-352 0 50-352 0 50-352 0	†  - 
	8210220186 8210220334 8210220381 8210220381 821023037;	50-255 PR 50-329 50-329 50-155	6 6 7		8210180208* 8210180217 8210180217 8210180223	50-352 0 50-352 0 50-352 0 50-352 0	) 
	8210240121 8210240121 8210240183# 8210240175# 8210240175#	50-329 50-329 50-255 50-329 50-329	8 9 9		6210180223 6210180224 6210180224 8210180226* 6210180226*	50-352 0 50-352 0 50-352 0 50-352 0	· )
	8210240314* 8210240504 8210240527 8210280041* 8210280043*	50-155 50-329 50-329 50-255 50-255	Q T T F	Delaware, Univ of Detroit Edison Co	8210180253 8210180253 8210150223* 8210010289	50-352 0 50-352 0 50-322 T 50-341 K	,

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFF ILIATIO	M	ACCESSION NUMBER	SUBJECT CATEGOR	
	8210010295* 8210010297* 8210010297* 8210010456 8210040084 8210040127	50-341 50-341 50-341	K K K A S S S			8210070092 8210080208 8210120276 8210130139 8210130177	50-413 50-413 50-329 50-269 50-369	A A P B
	8210080046 8210130158 8210130282 8210130284 8210150322	50-341 pr 50-341	A A F Q			8210130180* 8210130262 8210130262 8210130263* 8210130263*	50-347 50-349 50-349 50-349 50-369	8 K K K K
	8210180188 8210190332 8210190657 8210190696 8210220414	50-341 50-341 50-341	A S B Q A			8210130290 8210130399 8210130467 8210130502 8210130599	50~269 PR 50~369 50~287 PR	Q P P
.oad Corp Swarch Associates	8210250191 8210260382* 8210280222 8210290399 8207180058	50-341 50-341 50-341 RES FOIA	B G A			8210150012* 8210150068 8210150079 8210150064* 8210150094	50-349 50-413 50-269 50-249 50-413	8 8 9
ig. JA erty. JB	8207180060 8207180061 8210070199 8210240348 8210240348	FOIA FOIA 50-352 50-338 50-338	G C			8210190094 8210150101# 8210150101# 8210150369 8210150318	50-413 50-413 50-413 50-269 50-369	К К С С Е
hemacal Co	8210260355 8210260355 8210040231 8210180199* 8210180215*	50-338 50-238 50-264 50-10 FOIA	6 G J			8210130518 8210130522* 8210130522* 8210130617 8210180055	50-369 50-369 50-369 70-2944 50-269	F F P
	8210180219# 8210180222# 8210180227# 8210180234# 8210180239#	FOIA FOIA FOIA FOIA FOIA				8210180055 8210180055 8210180060* 8210180060* 8210180060*	50-249 50-269 50-269 50-269 50-269	ե ե ե
	8210180247* 8210180251* 8210180257* 8210180260* 8210180262*	FOIA FOIA FOIA FOIA FOIA				8210180128 8210170103* 8210170103* 8210170108* 8210170544	50-370 50-369 50-369 50-369 50-269	A F F R
	8210180264* 8210180354* 8210180358* 8210180424* 8210180427*	FOIA FOIA FOIA 70-278 FOIA				8210170544 8210170544 8210170552* 8210170552* 8210170552*	50-269 50-269 50-269 50-269 50-269	A R R A
	8210180428* 8210180430* 8210180431* 8210180434* 8210290202	FOIA FOIA FOIA FOIA 50-264	8			6210190411 6210190411 6210190495 6210190495 6210190740	50-413 50-413 50-270 50-270 50-370	# F 80 80 F
wer to	8209170053 8210010090 8210010090 8210010093 8210010134*	50-413 50-367 50-367 50-370 50-413	r a a a			8210190742 8210190751# 8210210131 8210210407 8210210407	50~369 50~369 50~269 50~269 50~269	R P P
	8210010232 8210010282 8210010352 8210010387 8210010463*	PR 50-349 50-249 50-370 50-249	a F G			B210210407 B210210411* B210210411* B210210411* B210220134	50-269 50-269 50-269 50-269 50-413	ր դ 0
	8210040107 8210040232 8210040232 8210040232 8210040245#	50-269 50-269 50-269 50-269 50-269	ն 6 6 6 5			821 0220134 821 0220202 821 0220202 821 0220206 821 0220206	50-413 50-369 50-369 50-369 50-369	0 0 0
	8210040245* 8210040245* 8210040254 8210040254 8210040253*	50-269 50-269 50-369 50-369	Р Р К К			8210220318 8210220327* 8210220426 8210220426 8210220426	50-369 50-269 50-269 50-269 50-269	8 8
	8210040273 8210040279 8210040279 8210040286 8210040286	50-349 50-349 50-369 50-369	К К К К			8210250102 8210250125 8210250125 8210250282	50-413 50-413 50-413 50-413 50-413	6 0 0
	82100 50130 82100 50202 82100 50202 82100 50208 82100 50208	50-413 50-413 50-413 50-413	A G G G			8210250304 8210260201 8210260331 8210260336* 8210260415	50-349 50-413 50-369 50-369 50-413	6 4 4
	92100 50264 92100 50364 92100 60311 92100 70072 92100 70072	50-413 50-413 50-413 50-369 50-369	A A F F			8210270139* 8210270139* 8210270144* 8210280017* 8210280017*	50-369 50-369 50-369 50-369 50-369	FFFF

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8210280020* 8210280020* 8210280065 8210280065 8210280065	50-369 F 50-369 F 50-413 E 50-413 E 50-370 S			8210250372* 8210270288* 8210280292 8210280323 8210280339	50-213	
	8210290083 8210290087* 8210290119 8210290190 8210290199*	50-270 9 50-270 8 50-413 9 50-269 9 50-269 6	<b>!</b> !	ENSA, Inc Earthquake Engineering Research Institute Ebasco Services, Inc (subs of Enserch Corp )	8210280432* 8210290017 8210210594* 8210120488* 8210040072	RES CONTRACT CONTRACT	P A
	8210290250 8210290308 8210290313* 8210290354 8210290354	50-413 S 50-287 S 50-287 S 50-413 S 50-413 S	) } ;	corp /	8210040334 8210150431 8210190720# 8210260114 8210260466	50-389 50-261 50-389	ARPAR
Duquesna Light Co	8210290355 8210290365* 8210010013 8210040065 8210050165	50-249 8 50-269 9 50-334 F 50-334 8 50-334 P	<del>1</del> <del>-</del> 3	Eddleman, W	8210210308 8210210308 8210210376 8210210374 8210210419	50-400 50-400 50-400 50-400	00000
	8210050148* 8210040076 8210040081* 8210040068 8210040094*	50-334 P 50-334 R 50-334 R 50-334 R 50-334 R	? ? ?	Edelstein & Payne Ederer, Inc	8210210419 8210250068 8210210419 8210210329 8210210329	50-400 50-400 50-400 TDPREP	0 6 6
	8210070155 8210070233 8210130561 8210150018* 8210150185	50-412 S 50-412 S 50-334 P 50-334 G 50-334 S	8 P Q	Edgar, G L  Edison Electric Institute Edlow International Co	8210040185 8210040200 8210130282 8210070410* 8210080003	50~537	G
	8210150199 8210150201* 8210150208* 8210150312 8210150316*	50-334 S 50-334 S 50-334 S 50-334 P 50-334 P	\$ \$ P		8210080005* 8210080071 8210210537 8210210543* 8210270021	XPDRTLIC XPORTLIC 70-2955 70-2955 XPORTLIC	
	8210190274 8210190262* 8210190747 8210210004 8210210010*	50-334 B 50-334 F 50-334 S	9 8 9	Electric Power Research Institute Emporia State Univ Energy Fuels Nuclear, Inc	8210120397 8210180416* 8210220516 8210250006 8210250008*	RES CONTRACT 40~8591 40~8691	
	8210210065 8210210072* 8210220184 8210260125* 8210260127*	50-334 S 50-334 G 50-334 F	9 9 0 F F		8210250034 8210240017 8210240018* 8210240022 8210270209	40-8681 40-8681 40-8681 40-8681 40-8681	
	821 02 60 135 821 02 60 143 821 02 60 163 821 02 60 167 * 821 02 60 203	50-412 8 50-334 8 50-334 8	8 8 8 8	Energy, Dept of	8210270435 8210040251 8210050184 8210040185 8210040200	40-9591 50-537	A 6 0
	821 0240226* 821 0240458 821 0240478 821 0240487* 821 0270267	50-334 F 50-334 S 50-334 S	8 8 9 P		8210070409 8210130246 8210130249 8210130311 8210130343	71-9150 50-537 50-537 50-537 50-537	BAAQ
	821 0270268* 821 0270271* 821 0280271 821 0280260 821 0280307	50-334 f	P 6 6 6 8		8210130435 8210170466* 8210200057 8210210022 8210210273	50-537 50-322 70-143 50-537	Q A A A
EQ&Q, inc	8010070320* 8205250020* 8210060417 8210070079* 8210080054*	50-155 I	P P		8210250025 8210250060 8210250061* 8210260168	WASTE MOT 70-143 70-143 50-537 50-537	
	8210080057* 8210080064* 8210120118 8210120124 8210120300*	res res	P P	Energy,Dept of, Clinch River Breeder Reactor Plant	8210260401 8210270074 8210270079* 82102700353	50-537 71-6639 71-6639 50-537	A
	8210120368 8210120397 8210120400 8210120430	res res res res		nwactor right	8210040167 8210040304		A
	8210120463 8210120463 8210120654 8210120657 8210130409	RES RES RES RES		Engineering Decision Analysis Company, Inc	8210060217 8210060249 8210150186 8210070091*		A A P
	8210150412 8210150415 8210150421	RES RES		Engineering Science Entwisle, E B. Enviro Audits	8210280319* 8210150200 8210040301*		H P D
,	8210130360 8210130825 8210130825	NUREO RES RES RES		Environmental Protection Agency  Envirosphere Co  European Communities, Commission of	8210130117 8210260235 8210280306* 8210270094	SO-440 CONTRACT XPORTLIC	Ď

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGGR	ŀΥ	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
Ereter.III Erion Nuclear Co., Inc. (subs. of Erron Corp.)	8210280064 8210280088 8210120517* 8201200662*	XPORTLIC XPORTLIC CONTRACT 50-241 TOPREP	:		82101 90348 82101 90351 82101 90351 82101 90371 82101 90374*	50-287 50-250 50-250 50-335 50-335	
	8210120230 8210130123 8210150033 8210150173 8210150182*	50-316 50-316 50-316 TOPREP TOPREP	P P P	5 6 6	22101 90440 32101 90440 32101 90440 32101 90440 32101 90559	50-250 50-250 50-250 50-250 50-250	F F F F
	8210130311 8210190302 8210260357 8210260560# 8210270092	TOPREP 50-219 40-8102 40-8102 TOPREP	þ	5 E	0210190559 0210220090 0210220167 0210220214 0210220286*	50-250 50-251 50-389 50-389 50-335	P P G Q
	8210270164 8210270169* 8210270195 8210270197* 8210270214	TOPREP TOPREP 40-8102 40-8102 TOPREP		E E	3210220304= 3210220451 3210250313 3210250317 3210260116	50-250 50-335 50-387 50-387 50-250	Q A R S
Finites: Metals (subs of Fanstee),Inc ) Federa: Emergency Management Agency	8210280184* 8210070075 8210070109 8210070109 8210070112*	40-7580 50-440 50-445 50-445 50-445	<b>e</b> F F	\$ 8	8210260117* 8210260357 8210260369* 8210260391* 8210270253	50-250 50-335 50-335 50-335 50-250	S S G P
	8210070112# 8210130161 8210130320 8210130430 8210170760#	50-445 50-289 50-289 50-387 50-254	4 4 7	5 E	2210280067 9210280254 8210280291 9210280291 8210280293*	50-387 50-387 50-250 50-250 50-250	E A F F
Finamore, B A Fiore & Jaskot	8210210159* 8210250170 8210130268 8210210232 8210260352*	50-382 50-10 50-537 50-537 40-8410	0 F 0	Florida Power Corp	210280293* 3210290240 3210010049* 3210060198 3210060263	50-250 PR 50-302 50-302 50-302	F Q P P
Flemming, Anderson, McClung & Finch Florida Power & Light Co	8210150490 8209170062 8210010017 8210010084* 8210010153*	50-361 50-250 50-389 50-335 50-335	6 F A Q	5 6	210130310 0210130319* 0210130520 0210130530* 021015021&	50-302 50-302 50-302 50-302 50-302	S S S P
	8210010164 8210010174* 8210010292 8210010292 8210010321*	50-335 50-335 50-250 50-250 50-250	8 9 9	5 8	9210190677 9210190681 9210190687* 9210190691 9210210421	50-302 50-302 50-302 50-302 50-302	9 8 8 P
	8210050061 8210050152 8210050416 8210050419* 8210050567*	50-335 TOPREP 50-369 50-369 50-335	P A A F	E E	210220052 210220054* 210220207 210220395 210260010*	50-302 50-302 50-302 PR 50-302	9 9 P F
	8210060209 8210060212# 8210060236 8210060276 8210060281	50-251 50-251 50-387 50-387 50-250	8 9 8 A	\$ 8	2210260012+ 2210260310+ 2210260377+ 2210260422 2210260436	50-302 50-302 50-302 50-302 50-302	ь О Е
	8210040288 8210040288 8210040371 8210080252 8210080257*	50-335 50-335 50-389 50-250 50-250	P P R 9	E E	3210260454 3210260497 3210290186 3210290312	50-302 50-302 50-302 50-302	P 9 8
	8210080264 8210130090 8210130257 8210130289 8210130301	50-335 50-389 50-389 50-389 50-389	Q ₽ A A	Center Monroeville, PA	35101 503894 3510 540491	HASTE MO	ז,
	8210130348 8210130399 8210130454 8210130442* 8210130334	50-369 PR 50-335 50-335 50-389	F 8 8				
	8210130552 8210130562* 8210150035 8210150039* 8210150407	50-335 50-335 50-335 50-335 50-250	8 8 8 8				
	8210150407 8210150413* 8210150413* 8210150439 8210150439	50-250 50-250 50-250 50-250 50-250	6 6 6				
	8210190186* 8210190186* 8210190194* 8210190310	50-250 50-250 50-250 50-335	F F F	Friends & Family of CA Technologies, Ir			

# CONFURMIC SOUNCE INDEX

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	<u> </u>	AUHTUA ADITALII AAA	1	ACCESSION NUMBER	SUBJEC CATEGO	
GUARD	8210280062 8210270141 8210270144* 8210270234 8210150470	XPORTLIC TOPREP TOPREP PR 50-341	c			8210150202 8210170378* 8210170570 8210170577* 8210170704	50-289 50-219 50-320 50-320 50-219	
Gage-Babcock Associates, Inc Gallagher, P. K. Gallo, J. Gard, Inc General Accounting Office	8210270230* 8210150490 8210060204 8210280374* 8210270020*	CONTRACT 50-341 50-155 CONTRACT 50-537	0 0			8210200012 8210210280 8210220187* 8210220372 8210250092	50-320 50-219 50-219 PR 50-219	р Р О
General Electric Co.	8207090224 * 8207120147 8207120253 * 8207290410 8210010217	50-270 50-447 50-447 NUREQ TUPREP	P A A			8210250097 * 8210250134 8210250189 8210250285 8210250383	50-219 50-219 50-219 50-219 50-219	د د د
	8210010224# 8210050328 8210050398 8210050408# 8210080113	TOPREP 50-447 50-447 50-447 XPORTLIC	A A A			8210260236* 8210260499 8210260505* 8210280124 8210280127	50-320 50-289 50-289 50-320 50-320	0 R S S
	8210080135 8210080262 8210150348 8210150416 8210150445	XPORTLIC TOPREP 71~5924 TOPREP TOPREP		Georgie Institute of Tech Georgie Power Co	nology	8210290204 8210290234 8210290254 8210220319# 8210010022#	50-289 PR 50-219 50-160 50-321	ቦ ወ ወ
	8210150461 8210180050 8210190785* 8210190785* 8210190810	TOPREP TOPREP 50-254 50-254 TOPREP	P P			82100 10094 82100 10098* 82100 50080 82100 50084* 82100 50330	50-366 50-366 50-366 50-366 50-321	8 8 G 8 P
	8210220174* 8210220205 8210220320* 8210220427* 8210250074*	50-447 70-1113 70-1113 70-1113 50-260	P P			8210050330 8210060231 8210060246 8210060248* 8210060275	50-321 50-366 50-366 50-366 50-366	ր Մ Տ Բ
	8210250077* 8210250078* 8210250110 8210250113* 8210250177*	50-240 50-70 50-70	թ թ թ			8210060276# 8210060287 8210060287# 8210060317 8210060324#	50-356 50-366 50-366 50-366 50-366	ր 8 8 8
	8210250184* 8210260284* 8210260570 8210270046 8210270051*		A A			8210070148 8210080234 8210080240* 8210120047 8210120050*	50-424 50-366 50-366 50-366 50-366	A 9 8 9
	8210270057 8210270283 8210280198* 8210280201* 8210290288	50-277 TOPREP	ь Б			8210130129 8210130129 8210130132# 8210130132# 8210130183	50-321 50-321 50-321 50-321 50-366	R R R B
			<b>Ե</b> <b>Ե</b>			8510130529* 8510130529* 8510130529 8510130182*	50-366 50-366 50-366 50-321 50-321	9999
						8210130406 8210130414# 8210130541 8210130549# 8210150329	50-364 50-366 50-368 50-366 50-321	G 8 8
						B2101 50333* 62101 50362 92101 50362 62101 70016* 62101 70016*	50-321 50-424 50-424 50-321 50-321	P A A F
						8210190017* 8210190017* 8210190046* 8210190046* 8210190051*	50-321 50-321 50-321 50-321 50-321	ት ት ት
						8210170504 8210170511* 8210170575 8210170602* 8210220078	50-366 50-366 50-366 50-366 50-424	8 8 8 8
						8210220208* 8210220219 8210220222* 8210220287*	50~424 50~321 50~321 50~321 50~321	0 8 0
						8210220290 8210220298* 8210220384 8210220386 8210220388*	50-346 50-366 50-321 PRM 50-321	р 8

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGUR	
	8210270246 8210270246 8210270075 8210270080* 8210270096	50-424 50-424 50-366 50-366 50-321	A A S S S S		8210220268 8210220276* 8210220288* 8210220275* 8210220410	50-537 50-537 50-537 50-537 50-247	00000
	8210270106* 8210270206 8210270207* 8210270262 8210270272*	50~321 50~366 50~366 50~321 50~321	5 6 6 5 5	Harold J Spelman & Associates	8210220465 8210260397 8210260404* 8210280242 8210150463	50-289 50-537 50-537 50-247 40-2041	G G G
	8210290273 8210290324 8210290327 8210290329* 8210290334*	PR 50-321 50-321 50-321 50-321	S S S S	Harper-Grace Hosps Detroit.M! Harvard Univ Karia Engineering Co House of Rep	8210250315 8210050213* 8210010119* 8210290422* 8210070458*	40-2061 70-2942 FOIA CONTRACT FOIA	
	8210270347 8210270357 8210270359* 8210270364* 8210270373	50-321 50-366 50-321 50-366 50-321	9 9 9 9	Housing & Urban Development.Dept of Houston Lighting & Power Co	8210270066 8210010301 8210050329 8210070120 8210070147	40-8781 PR 50-478 50-466 50-466	6 9 9
trans, inc	8210290374 8210290375# 8210290381# 8210120350# 8210190339#	50-366 50-366 50-366 CONTRACT CONTRACT			8210200052 8210200052 8210200075 8210210363 8210210363	50-498 50-498 50-498 50-498 50-498	A A G G
ty Q:1 Co (Petrotomics) ps & Hill: Inc (subs of Dravo Corp ) der Associates	8210220510 8210270124 8210270129* 8210070021* 8210120458*	40-6659 50-584 50-584 CONTRACT			8210210368* 8210220239 8210220125* 821022039 8210220239	50~498 50~498 50~498 50~498 50~498	0 0 0 0 0
lds Pumps, Inc ernment Accountability Project	8210150326* 8210150330* 8210150335* 8210150449 8210150457*	50-341 50-341 50-341 50-358 50-358	G G G		6210220241* 6210220334 6210250112 6210250247 6210250259	50~498 PR 50~498 50~498 50~498	A B S A
at Lates Energy Alliance inblatt, D	8210210391 8210210400* 8210190480 8210210308 8210210308	50-358 50-358 50-255 50-400 50-400	G G G G	Hovis, R L	8210250263 8210250359 8210260452 8210260452 8210050169	50-498 50-498 50-498 50-498 50-522	A A B B
d. R 'States Utilities Co	8210210419 8210210419 8210080081 8210040215 8210040215	50-400 50-400 50-413 50-458 50-458	G G K K	Hunton & Williams  INTERA Environmental Consultants. Inc	8210120307 8210150279 8210150296* 8210200003 8210290399	50-322 50-322 50-322 50-322 RFB	G G Q
	8210040220* 6210040220* 6210050201 6210050219 6210050317	50-458 50-458 50-458 50-458 50-458	8 8 8	IRT Corp Jdaho, State of Igoe, V M Illinois Pawer Co	6210120346* 8210120503 8210270023* 6207160037 6207270072	CONTRACT XPORTLIC 50-537 50-483 50-461	
	8210050350 8210130182 8210130514 8210190367 8210190318	50-458 50-458 50-458 50-458 50-458	9 9 8		6210040104 8210050183 8210050185* 8210050278 8210050281	50-461 50-461 50-461 50-461 50-461	A K K E E
	8210190629 8210200037 8210220376 8210250118 8210260286	50-458 50-458 PR 50-458 50-458	8 6 8		8210050289 8210130181 8210130184* 8210130270 8210130325	50-461 50-461 50-461 PR 50-461	E G G
Inc ind Engineering Development indeary	8210240292 8210290243 8210040004 8210150550	50-45B PR NUREO NUREO	\$		8210130399 8210130470 8210130490 8210130357 8210170350	PR 50-461 50-461 50-461 50-461	F A B
in & Weins	8207110033 8207110034 8208290094 8210040195 8210040210 8210120274	50-537 50-337 50-322 50-537 50-289 50-289	A D O O O O		8210170354 8210170416 821026003 8210260050 8210260089	50-461 50-461 70-2946 50-461 50-461	9 8 0 A
	8210120327 8210130383 8210200026 8210200026 8210200035*	50-537 70-143 50-443 50-443 50-443	о о о	Illinois, State of Illinois, Univ of, Urbana-Champaign	8210280160 8210280213 8210210051 8210260501 8210120419*	50-461 50-461 NUREO 50-374 27-37	4
	8210200035* 8210200042* 8210200042* 8210200047* 8210200047*	50-443 50-443 50-443 50-443 50-443	G G G		8210130265 8210130265 8210130476 8210130494 8210130494	50-329 50-329 50-151 50-329 50-329	T T 81 T
	8210200054 8210200041 8210210357 8210210453	50-329 50-329 50-537 50-537	G G G	Indiana & Michigan Electric Co.	8210210051 8210010362 8210040073 8210040075# 8210040179	NUREQ 50-315 50-315 50-315 50-315	F 8 8

AUTHOR AFF IL IATION	ACCESSION NUMBER		JECT CORY	AUTHDA AFFILIATION	ACCESSI NUMBER	CATE	COAY
	8210040201 8210040203* 8210040205* 8210040209* 8210040212	50-31	5 B 5 B 6 B	Interior, Dapt of Interior, Dapt of, Fish & Wildlife Bervio International Energy Associates, Ltd Interstate Nuclear Bervices	821028000 82100403 821005021 821007040 820715005	22 50-41 14 50-24 38 FDJA	1 t
	8210040321 8210040327* 8210040330* 8210050138 8210050138	50-31 50-31 50-31 50-31 50-31	6 B 6 B 5 P	Iowa Electric Light & Power Co	821004034 821004037 821005030 821012039 821013013	76* 90~00: 07* 90~30: 19* 90~131	1 6 1 9 1 F
	82;0050159 82:0050159 82:0050140# 82:0050140# 82:00502:1	50~33 50~31 50~31 50~31 50~31	5 P 5 P		821013013 821013039 821013039 821013039	3 50-311 8* 50-311 9 50-331	1 to 1 9
	9210050276# 6210050349 6210050349 6210060256# 6210060277	50~315 50~315 50~315 50~315 50~316	) Р 5 Р 6		6210190546 6210190566 6210190566 6210190546	6 50-9 ft 50-011 0* 50-011 0 50-031	9 6 6
i	9210060300 9210060307* 9210060313* 9210070279 9210070279	50-315 50-315 50-314 50-315 50-315	8 8		821 02 00 09 0 821 02 00 09 0 821 02 50 25 1 821 02 50 26 1 821 02 50 26 9	1 00 331 57 50-371 11 - 02 1	10 11 11
: :	8210070286* 9210070286* 9210080132* 9210080132* 9210080136*	50~315 50~315 50~315 50~315 50~315	I F		6210250300 6210250364 6210250367 6210260136 62(0260461	* 50 99; 50-94; * 50 99;	ts ts te tr
8 8 8	1210080136* 1210150604* 1210150604* 1210150616* 1210150616*	50-315 50-315 50-315 50-315 50-315	न न न न	Jowa, Univ of Isham, Lincoln & Beals	0210240409 0210240495 0200290012 0207100005 0210010400	90-331	P
େ ଅ ଅ	210180120 210180123* 210180129* 210190040* 210190246	50-316 50-316 50-315 50-315	8 8 8 F 8		8210010444 8210050215 8210050221 8210050221 8210050223	50-155 50-129 50-129 50-129 50-129	000
9: 8: 8:	210190277* 210190287* 210190340 210190342* 210190380	50-315 50-315 50-315 50-315 50-315	8 8 8 8		82100 50223 82100 50229* 82100 50230 82100 50230 82100 50232	50-329 50-329 50-329 50-329 50-155	0 0 0
82 82 82 82	10190404* 210190415* 210190572 210190578*	50-315 50-315 50-315 50-315 50-315	8 8 8		921005039A 9210050391 9210000092 9210090099 9210130373	50-135 50-454 50-255 50-255	o 0000
85 85 85 85	101 90676 101 90676 101 90685* 101 90685*	50-315 50-319 50-315 50-315 50-315	8 R R R	₹ ₹ €	92101 90440 92101 90457# 92101 90462 92101 90900 92101 90970	50-155 50-155 50-155 50-159 50-159	0 0 0 0
85 85 85	10190735# 10190749 10190757#	50-314 50-316 50-315 50-315	8 8 8 9	8 6 8	2101801AR (21018020A (21018024A (210200029 210200021	50-155 50-155 50-155	0 0 0
	5		р Б Б	Isotope Products Laboratories & Acksonville Shipyards, Inc & Apen & G	210280030 210220314 210040382 210040385 210040387	XPORTLIC PA XPORTLIC XPORTLIC	4
	5 5 5 5	0-315 0-315 0-315	F F F F	Olapan Atomic Energy Research Inst Go Joint Applicants-Clinch River Breeder SI Reactor	210040471 210280425 210180421 210200082	XPORTLIC XPORTLIC XPORTLIC REA 50-537 G	9
	5 5 5	0-170 0-170 0-170	0 0 0	92 92	10130417 10130417 10130486# 10130486#	50-528 0 50-528 0 50-528 0 50-528 0	3
	56 36 66	0-170	9 9	Joint Intervenors-Waterford 62 KLD Associates, To- 82	10270171 10050218 10050366 10050378+	50-508 Q 50-275 Q 50-382 Q 50-382 Q 50-382 Q	
	50	)-219 /	P 4	KMC, Inc 82: 82: 82: 82:	10150188# 10150240# 10280041# 07050005# 0010293	50-322 T 50-322 T 50-322 F PR PR PR REVIEW OAP	

### CONFURATE SOURCE INDEX

AUTHUR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	₹٧
nam Tempo nsaw Gas & Electric Co	8210120331* 8210130399 8210280356* 8210040364 8210120199	REVIEW OF PR CONTRACT 50-482 50-482			8210150204* 8210150223* 8210150240* 8210150250* 8210150257*	50-322 50-322 50-322 50-322	T T T
nsas State Univ nnecott Copper Corp	8210130399 8210220403 8210190365 8210220074* 8210220077*	PR PR 50-188 40-8111 40-8111	R		8210150245* 8210150272* 8210150277 8210150281* 8210150270*	50-322 50-322 50-322 50-322 50-322	T T Ø T T
ntucky. State of rr-HcGes Chemical Corp (subs of srr-HcGes Corp )	8210220086* 8210210046 8210260574	40-B111 NUREQ 40-8027			8210150309# 8210150324# 8210150337# 8210150351#	50-322 50-322 50-322	Q Q Q
r-McGee Corp	8210260543 8210260548*	40~8027 40-8027			8210150345* 8210150393*	50-322 50-322	e e
	8210240565 8210270077 8210270088* 8210270242 8210270247*	40-8027 40-2061 40-2061 40-8027 40-8027			8210150402* 8210150410* 8210150422* 8210150527*	50-322 50-322 50-322 50-322	000
r-HcGee Nuclear Corp aunce County, WI ipatrick Lockhart, Hill, Christopher Phallips		40-8027 CONTRACT 50-322	g		8210200003 8210200035 8210250059* 8210260141* 8210280035*	50-322 50-322 50-322 50-322	96901
	8210050189 8210050189	50-275 50-322	G G		8210280039* 8210280041*	50-322 50-322	F
	821 00 50383 821 02 00 076 821 02 00 003* 821 02 00 089* 821 02 50 058	50-322 50-322 50-322 50-322	0 0 0 0	Los Alamos Scientific Laboratory	8210280285 8210290269 8210120428	50-322 PR RES	9
	8210290097 8210290097 8210290283	50-322 50-275 50-322	G P P G	Louise County, VA  Louisiene Power & Light Co	8210240347 8210240347 8210240373 8210240373 8209150432	50-339 50-339 50-339 50-339 70-2946	0
shen. A H cville, TN	8210180401*	50-265 CONTRACT			82091 50436* 82091 50438*	70-2946 70-2946	
ru Alliance nam. J M osse. W M-Amdørson, Inc	8210210419 8210120362* 8210120423* 8210260530* 8210180338*	50-400 CONTRACT 50-389 CONTRACT CONTRACT	. м		6207220135 6207220137* 6210010370	30-382 50-382 50-382	A F
ence General Hosp Lawrence, MA ence Livermore Laboratory	8210180348* 8210210448* 8205250010* 8206170006*	CONTRACT 70-2116 50-155 50-312	b b		8210010435 8210040078 8210040110 8210040168	PR 50-382 50-382 50-382 50-382	0 8 A F
	8207300222* 8207130461* 8207200475* 8210150548	50-204 50-293 50-29 NUREQ	р Р Р		8210040191 8210070124 8210070197 8210080086 8210080090	50-382 50-382 50-382 50-382 50-382	4000
euf, Lamb, Leiby & MacRae	8210290113* 8210010289	50-324 50-341	K		8210130174 8210130243	50~382 50~382	8
ue of Homen Vaters of Rockford, IL	8210180160 8210280250 8210290234 8210070127 8210070127	50-287 50-287 PR 50-454 50-454	0 0 0		8210130245 8210130551 8210130564 8210150347	50-382 50-382 50-382	9 9 8
	8210070129* 8210070129* 8210210274 8210210274	50-454 50-454 50-454 50-454	0000		8210190345 8210190542 8210210372 8210250217	50-362 50-362 50-362 50-382	8 6 8
	8210210278 8210210278 8210210384 8210210384	50-454 50-454 50-454 50-454	G G G G		8210250242 8210250254 8210250341 8210250355 8210240342	50-382 50-382 50-382 50-382 50-382	8 9 A
	8510570380 8510570380	50-454 50-454	G G		8210240423 8210270190	50-382 50-382	o K
	8210240384* 8210240384* 8210240392* 8210240392*	50-454 50-454 50-454 50-454	0 0 0 0		8210270193# 8210280387 8210290438	50-362 50-362 71-6574	K G
om Steel Foundry h Univ	8210270293 8210270305 8210270370 8210050348	50-454 50-454 40-8153 NUREO	G G	Louisians, State of Lowell, Univ of Lowenstein, Newman, Reis, Axelrad & Toll	8210040002* 8210150462 8210280183 8210280186* 8210070120	CONTRACT 50-414 50-223 50-223 50-466	R R R
, м	8210290304 8210010310	PR 50-289	o o		B210070147 B21020005B	50-466 50-522	0
ick Ecology Action Estand Lighting Go	8210070199 8210040274# 8210040361* 8210070384 8210120307	50-352 50-322 50-322 50-322 50-322	0 0 8 9		8210210343 8210210348* 8210210348*	50-498 50-498 50-498 50-498	0
	8210150148 8210150178# 8210150188#	20-355 20-355 20-355	T T T	MPR Associates. Inc. Maine Nuclear Referendum Committee	8210240202 8210010081* 8210010085*	PR 50-219 50-219 50-209	P P H

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEOOR	4	AUTHI AFF IL IA	ACCESSION NUMBER	SUBJECT CATEGOR	Y
Maine Yankes Atomic Pawer Co	8210010230 8210040074 8210040077 8210040217 8210050015*	PR 50-309 50-309 50-309 50-309	۶ ۱۹ ۱۹		8210050193 8210050203* 8210060201 8210060203* 8210060224	50-416 50-416 50-416 50-416 50-416	នទទទ
	8210050018* 8210040171 8210040173* 8210040302 8210130252	50-309 50-309 50-309 50-309 50-309	F P Q P		8210060226# 8210060275 8210060275 8210070044# 8210070044#	50-416 50-416 50-416 50-416 50-416	9 P F
	8210130254* 8210130283 8210130286* 8210130314 8210130360	50-309 50-309 50-309 50-309 50-309	Р Р С Р		8210070048* 8210070048* 8210080120 8210080127* 8210080186	50-416 50-416 50-416 50-416 50-416	F 5 8
	8210130349* 8210150398 8210210016 8210210018* 8210220303	50-307 50-307 50-309 50-309 50-309	P G S S P		8210080192# 8210080223 8210080277 8210080281# 8210080282	50-416 50-416 50-416 50-416 50-416	98888
	82102R0212 8210250078 8210240144 8210240173 8210240197	50-309 50-309 50-309 50-309 50-309	ម ច ម		8210080284 8210080287* 8210080289* 8210080295 8210080298*	50-416 50-416 50-416 50-416 50-416	9 9 9 9
	8210240200* 8210240208* 8210240327 8210240420 8210270008	50-309 50-309 50-309 50-309 50-309	8 8 9 9 9		8210150011* 8210150013 8210150019* 8210150024* 8210180104	50-416 50-416 50-416 50-416 50-416	0 0 0 8
	8210270009* 8210270165 8210270177* 8210280087 8210280161	50-307 50-307 50-307 50-309 50-307	0 9 8 F P		8210180109* 8210190417 8210190424* 8210190496 8210190521	50-416 50-416 50-416 50-416 50-416	6 8 8 9
Maine, State of Manhattan College Mapleton Intervenors	8210290343 8210060190 8210280227 8210080341 8210070398	50-309 50-309 50-309 50-179 50-329	8 0 0 P 0		8210190561 8210190566 8210190566 8210190567* 8210200005	50-416 50-416 50-416 50-416 50-416	8 6 8 6
Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div Marshall, W H Maryland, Univ of	8210220274 8210040313 8210070378 8210240240*	50-329 50-329 50-329 CONTRACT	G G		8210200005 8210200030 8210200030 8210200044 8210200073	50-416 50-416 50-416 50-416 50-416	E E E
Massachusetts Institute of Technology  Maywood, NJ McDonald Engineering Analysis Co , Inc	8210050428 8210150574 8210190334 8210260352* 8210150343* 8210150346*	NUREQ 50-20 40-8610 50-341 50-341	F G Q		8210200073 8210210217 8210210217 8210220065 8210220067*	50-416 50-416 50-416 50-416 50-416	E P 8
Memphis State Univ Metropolitan Edison Co	8210150352* 8210260493* 8210270402* 8210040210 8210070194	50-341 50-358 CUNTRACT 50-289 50-289	Q E		8210220131 8210220150* 8210220158 8210220162* 8210220161	50-416 50-416 50-416 50-416 50-416	8 8 8 8
	8210080094 8210130275 8210150280 8210150289# 8210200033	50~289 50~289 50~320 50~320 50~269	0 6 8 8		8210220191* 8210220194 8210220199* 8210220259 8210220262*	50-416 50-416 50-416 50-416 50-416	9 6 8 8
	8210210173 8210210179* 8210210266 8210210374 8210280360	50-320 50-320 50-320 50-287 50-289	0 0 0 0		8210220269 8210220274* 8210220278 8210220282* 8210220284	50-416 50-416 50-416 50-416 50-416	និងទាន
Mismi Valley Power Project Michigan, Univ. of	8210150449 8210150457* 8210210391 8210210400* 8210060424*	50-358 50-358 50-358 50-358 CONTRACT	0 0		8210220267* 8210220334 8210220425 8210220428 8210220431*	50-414 PR 50-414 50-414 50-416	5 £ £
Micro-Tel Corp Miller, D S. Mississippi Power & Light Co.	8210170223* 8210050236 8210200045 8210270303 8210010023	CONTRACT 50~309 50~309 50~309 50~414	0 0 F		8210220458 8210220462* 8210260264 8210260412 8210260445	50-416 50-416 50-416 50-416 50-416	8 P P 8
	8210010223 8210010234 8210010243 8210010248* 8210040053	PR 50-416 50-416 50-416 50-416	F 8 8		8210240513 8210270277 8210280132 8210280132 8210280135	50-416 50-416 50-416 50-416 50-416	8 9 9 9
	9210040053 9210040264 9210040353 9210040353	50-416 50-416 50-416 50-416	P P P		8210280135 8210270050 8210270055* 8210270073 8210270081*	50-416 50-416 50-416 50-416 50-416	P 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AFF ILIATION	ACCESSION NUMBER	BUBJECT CATEGOR'	Y 
	8210290102 8210290102 8210290124 8210290135* 8210290193	50-416 50-416 50-416 50-416 50-417	8 8 8	8 Rew Hampshire, State of New Mexico, State of	210200049#  210200049#  210250307  210120021#  210120023#	50-443 50-443 50-443 FOIA FOIA	g A
	8210290311 8210290332* 8210290340 8210290345* 8210290348	50-416 50-416 50-416 50-416 50-416	8 8 8	New York, State Univ of, Buffalo E New York, State of E	9210120052* 9210019277 9208290099 9210160419* 9210210041	FOIA 50-57 50-322 50-201 50-201	F 6 P P
ississippi. State of	8210290351* 8210220403 8210270033*	50-416 PR CONTRACT	8	New York, State of, Energy Research & E Development Administration	1210220321 1210260582*	PR 50-201	a
Itsul & Co (U S A ). Inc (Subs of Mitsus & Co . Ltd )	8210130078 8210130080*	XPORTLIC XPORTLIC		News & Observer	121018013B 1207180044 1207180055	50-247 50-261 50-440	Q P F
olycorp. Inc	8210270007 8210270448 8210270452* 8210080327 8210080331*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		E	1210010033 1210010145* 1210010267* 1210040071 1210040117	50-220 50-220 50-220 50-220 50-220	P G G B P
orae K-Ray Ca , Inc Irgan Associates	8210010005 8210010024* 8210040235 8210250081 8210250081	71-481 71-481 50-247 50-247 50-247	6 0 0	E E	0210040170 0210040182 9210040183* 9210040190 9210040296	50-410 50-220 50-220 50-410 50-220	0 P P B
	8210250214 8210250214 8210250245 8210250245 8210250272	50-247 50-247 50-247 50-247 50-247	6 6 6 7	6 6	0210040303* 0210050111 0210050148 0210050260 0210050354	50-220 50-220 50-220 50-220 50-220	ն ե ե ե
rgan. Lewis & Bocklus ung Laboratory/Monsanto rray. Plumb & Murray	8210250272 8210290271 8210240581 8210150549 8210260457	50-247 50-247 50-201 NUREG 50-309	Н С С	6 6	1210040208* 1210060284 1210060291* 1210130107 1210130347	50-220 50-220 50-220 50-220 50-220	0 8 8 9 8
Industries, Inc 3 Corp	8210240465# 8210010434# 8210010440# 8210040354# 821024036#	50-309 40-1202 40-1202 50-261 50-329	G F A	E E	0210130350* 0210150129 0210150135 0210150142* 0210210322	50-220 50-410 50-220 50-220 50-410	R 8 8 6 H
IECH (Kuclear Technology, Inc )	8210010440# 8210050427# 8210150377# 8210150500# 8210150504#	50-341 50-155 50-263 50-263 50-263	ր 19 19 19	6 E	9210250378 9210260184# 9210280121 9210280144 9210220518	50-410 50-220 50-220 50-220 70-1113	8 9 9
ional Nuclear Corp ional Wildlife Federation	8210150509* 8210130076 8210270152* 8210080073	50~263 XPORTLIC XPORTLIC 50~522	G.	North Carolina. Univ of North Shore Committee Against Nuclear & E Thermal Pollution	9210270375* 9210290321* 9210150234	CONTRACT FOIA 50~322	Q
ural Resources Defense Council	8210220434 8210040195	50-522 50-537	9	£	#210150307# #210150324#	50-322 50-322	G
	8210120327 8210130268 8210130383	50-537 50-537 50-537 70-143	G G		3210150337# 3210150351# 3210150345# 3210150393# 3210150402#	50-322 50-322 50-322 50-322	00000
	8210200001 8210200004* 8210210232 8210210240* 8210210357	70-143 70-143 50-537 50-537 50-537	9 9		3210150410* 3210150422* 9210150527* 3210250059* 9210010207	50-322 50-322 50-322 50-323	9999
	8210210453 8210220268 8210220276* 8210220279* 8210220283*	50-537 50-537 50-537 50-537 50-537	60000	Northeast Utilities) "	9210010207 9210010207 9210010214* 9210010230	50-213 50-213 50-213 PR	P P
ijo Nation	8210220288* 8210220295* 8210260397 8210260404* 8210250025	50-537 50-537 50-537 50-537 WABTE MO	G G G		9210010312 9210010312 9210010376 9210010385* 9210040120	50-213 50-213 50-334 50-334 50-245	P P S S F
asta Public Power District	8210010058 8210130318 8210220136* 8210220254 8210260217	50-298 50-298 50-298 50-298 50-298	0 6 6		8210050090 8210050118 8210050177 8210050179	50-236 50-245 50-245 50-336	P P P
	8210240328 8210270323	50-278 50-276	Q P		8210050187# 8210060048	50-334 50-245	P
England Coalition on Nuclear Jution	8210200035* 8210200036	50-443 50-443 50-443	0		8210060094 8210060233 8210060237 8210060238#	50-245 50-245 50-334 50-336	р О Р
	8210200035* 8210200042* 8210200042*	50-443 50-443 50-443	0		6210070250 6210070304 6210070356*	50-245 50-245 50-245	8

AUTHOR AFF ILEATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBUECT CATEGORY
	8210070340 8210080105 8210130228 8210130232* 8210130326	50-245 S 50-423 A 50-336 S 50-336 S 50-10 P		8210040380* 8210040386* 8210080117 8210080184 8210080184	50~263 P 50~263 P 50~263 S 50~282 F 50~282 F
	8210130331 6210130331 8210130331 8210130331 8210190472 8210190476*	50-213 P 50-213 P 50-213 P 50-334 G 50-334 G		8210130260 8210130261 8210130510 8210130533* 8210130563	50-263 P 50-263 P 50-282 S 50-282 S 50-306 Q
	8210190555 8210210155 8210210160* 8210210340 8210210425	50-423 B 50-336 B 50-336 B 50-423 B 50-245 B		8210130544* 8210150174 8210150180* 8210150255* 8210150255*	50-304 0 50-263 5 50-263 6 50-282 6 50-282 0
Northeast Utilities	8210220060 8210220064* 8210220103 8210220108* 8210220112	50-334 8 50-336 8 50-245 8 50-245 8 50-245 8		8210150344 8210150381 8210150390* 8210190289 8210190293*	50-263 P 50-282 L 50-282 S 50-263 S 50-263 E
	8210220116# 8210220195 8210220201# 8210250290 8210250329	50-245 B 50-245 S 50-245 G 50-423 S 50-423 S		8210190422 8210190439# 8210190439# 8210190479 8210190726	50-282 P 50-282 Q 50-282 Q 50-263 P 50-306 S
	8210260174 8210260414 8210260432 8210260441* 8210260459	50-245 P 50-245 P 50-336 8 50-336 9 50-245 P		8210190745* 8210250179 8210250183* 8210250200 8210250364	50-306 5 50-282 9 50-282 F 50-282 F
	6210240519 6210270200 6210270200 6210010207 6210010207	50-245 P 50-213 P 50-213 P 50-213 P 50-213 P		8210250376# 8210260154 8210260154 8210260209 8210270262	50-282 S 50-282 P 50-282 P 50-263 P 50-262 F
	6210010207 6210010230 6210010312 6210010312 6210010374	50-213 P PR 50-213 P 50-213 P 50-336 S	Nuclear Assurance Corp	8210270242 8210270237 8210270249 821020245# 8210050439*	50~282 F PR FOIA FOIA
	82100 40120 82100 50070 82100 50118 82100 50177 82100 50179	50-245 F 50-336 P 50-245 P 50-245 P 50-336 P		B210050446* B210050467* B210050471* B210070156* B210270427*	70-1510 FOIA FOIA CONTRACT 70-1510
	82100 40048 82100 40074 82100 40233 82100 40237 82100 70250	50-245 P 50-245 P 50-245 Q 50-336 P 50-245 8		8210270429* 8210270437* 8210270438* 8210280448 8210290155	70-1510 70-1510 70-1510 71-9010 71-6698
	6210070304 6210070354* 6210070340 6210130228	50-245 B 50-245 G 50-245 9 50-336 8	Nuclear Energy Service, Inc Nuclear Fuel Services, Inc (subs of Getty Oil Co )	8210040228* 8210010184 8210150061	50-352 G 70-143 70-143
	8210130331 8210130331 8210130397	50-213 P 50-213 P PR		8210150371* 8210150408* 8210150477*	70-143 70-143 70-143
	8210190555 8210210155 8210210340	50-423 S 50-336 S 50-423 S		8210220395 8210240548 8210240571 8210240581	PR 70-143 70-143 50-201 9
	8210210425 8210210430* 8210220060 8210220103 8210220195	50-245 B 50-245 B 50-336 B 50-245 B 50-245 S	Nuclear Law Center Nuclear System Dak Ridge National Laboratory	8210260582* 8210270235 8207180041 8210290398* 8202020441*	50-201 G 70-143 FOIA CONTRACT FOIA
	8210250270 8210250327 8210260174 8210260414 8210260432	50-423 8 50-423 8 50-245 P 50-245 P 50-334 8	Car Mayo Marional Casalago, 4	82031 60383# 82032 50320# 82100 50504 82100 60005# 82100 60425	FOIA FOIA REB FOIA REB
Northern California Power Agency, California,State of,	8210260459 8210260519 8210270200 8210250356	50-245 P 50-245 P 50-213 P PROJ		8210070253* 8210120453 8210120653 8210150544	50-537 A Res Res Nureo
Northern Indians Public Service Co Northern States Power Co	8210030162 8210010036 8210010041* 8210010046* 8210010040 8210040123	50-367 Q 50-263 P 50-263 P 50-263 P 50-263 P 50-282 P	•	8210150567 8210150569 8210150577 8210180407 8210210034 8210210037	NUREO NUREO NUREO RES 50-259 F NUREO
	8210050319 8210040258 8210040260* 8210040377	50-282 P 50-263 S 50-263 P		8210210039 8210260204 8210270035* 8210270052*	NUREG NUREG 50-537 G 50-537 G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	łY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC CATEGO	RY
Ccean County, NJ	8210270056* 8210270068* 8210280110* 8210290006* 8210120541*	50-537 50-537 FGIA COMMISSI CONTRACT	G O ION	Parameter, Inc Parents Concerned About Endian Point	8210240280* 8210200019 8210200019 8210220389 8210220389	CONTRAC 50-247 50-247 50-247 50-247	
Gf+sce of Management & Budget	8210120402 8210120404 8210270116 8210270119	DRG DRG DRG DRG		Pathfinder Mines Corp	8210150601 8210150607 8210150613*	40-4622 40-2259 40-2259	
Sile Petroleum. Inc	8210260577 8210270063	40-8745 40-8745			8210180415 8210180420* 8210220476*	40-6622 40-6622	
ראים Citisens for Responsible Energy	8210280046 8210280049* 8210010335 8210010335	40-8745 40-8745 50-440 50-440	G G		8210250028 8210260013 8210260014* 8210270054	40-6622 40-6622 40-6622 40-2259	
	8210010366 8210010366 8210010377 8210010377 8210010386	50-440 50-440 50-440 50-440 50-440	0 6 6 6	Pennsylvania Power & Light Co	8210290177 8210010177 8210010180* 8210010228 8210010228	40-6622 50-387 50-387 50-388 50-388	8 8 8 8
	8210010384 8210010414 8210010414 8210040207 8210150192	50-440 50-440 50-440 50-440 50-400	0 6 6 7		8210010393 6210010402* 6210010417 6210040052 6210040066	50-987 50-387 50-387 50-387 50-387	8 5 6 8
	B210180211 B210210351 B210210351 B210210358* B210210358*	50-440 50-440 50-440 50-440 50-440	0 0 0 0		82100 40088* 62100 40 116 62100 40 122* 62100 50325 62100 50370	50-387 50-387 50-387 50-387 50-387	ր 6 9
ghao State Univ Ohmant Cong	6210210366* 6210210366* 6210220461 6210210176* 6210060415*	50-440 50-440 50-440 CONTRACT FOLA	G G		82100 60 199 82100 6039 1 82100 80083 82100 80142 82100 80146*	50-387 50-387 50-387 50-387 50-387	հ ե ե
Dil.Chemical & Atomic Workers Int) Gilahoma Steel Castings Co grapa Public Power District	8210130281 8210220316 8209170051 8210040186 8210040187*	70-143 PR 50-285 50-285 50-285	ក ន ន		8210080151* 8210130122 8210130341 8210130392 8210130361*	50-387 50-387 50-387 50-387 50-387	8 5 1 6
	82100 50247 82100 50301 82100 50303* 82100 60196 82100 70333*	50-265 50-265 50-265 50-265 50-265	ម ១ ១ ០		8210130363 8210130371* 8210130377 8210130389* 8210170166*	50-387 50-387 50-387 50-387 50-387	ti 8 8 F
drange County, CA	8210130570 8210190736 8210190746* 8210200077 8210130259	50-285 50-285 50-285 50-285 PRM	8 R R P		B210190166* B210190173* B210190173* B210190297 B210210020	50-387 50-387 50-387 50-387 50-387	F F F 9
uregon Environmental Council Orrick, Herrington & Sutcliffe	82100 80073 82101 30309 82101 50454 82101 50454 82101 50482	50-522 50-361 50-361 50-361 50-361	G G G G		8210210020 8210210137 8210210137 8210210285 8210210293#	50-387 50-387 50-387 50-387 50-387	8 8 8
Pacific Air Products Co Pacific Gos & Electric Co	8210150482 8210190372* 8210010198 8210010307 8210010404	50-361 0A999 50-133 PR 50-275	6 Г Р		8210210417 8210210433 8210210436* 8210210440 8210210446*	50~387 50~387 50~387 50~387 50~387	9 8 8 8
	8210010413* 8210090122 8210050144 8210050144 8210060220	\$0-275 50-275 50-275 50-275 50-275	ը Բ Թ		8210220102 8210220175 8210220364 8210250256 8210250264*	50-387 50-387 PR 50-387 50-387	9 9 1
	6210120276 6210120263* 6210130272 8210150151 6210150157*	50-275 50-275 50-275 50-275 50-275	P P G R		8210250276* 6210250347 8210250357 8210250367 6210250369	50-387 50-387 50-387 50-387 50-387	8 8 9
	8210150389 8210210044* 8210210048* 8210220371 8210220375	50-275 50-275 50-275 50-275 PR	<b>р</b> Г Р		8219250373* 8219250360* 8219250381 8219250381	50-387 50-387 50-387 50-387 50-387	9 7 8
	8210250192 8210250196* 8210260359 8210270236 8210270240*	50-133 50-133 50-133 50-275 50-275	R R R		8210260270* 8210260350 8210260354* 8210260366 8210260379*	50-387 50-387 50-387 50-387 50-387	0 P P
Pacific Pumps Div Palmetto Alliance	8210270351 8210290219 8210290222* 8210040155* 8210080081	50-275 50-275 50-275 0A999 50-413	<b>ខ</b> ខ ស		8210240385* 8210240507 8210280215 8210280217* 8210290230	\$0-987 \$0-987 \$0-987 \$0-987 \$0-987	P 8 8

AUTHÛR AFF EL IATION	ACCESSION NUMBER	SUBJECT Category	AUTHOR AFF IL IATION	ACCESSION NUMBER	SUBJECT CATEGORY
Pennsylvanía State Univ Pennsylvanía, State of	8210270318 8210130487 8210040218 8210210378 8210270203*	50-387 F 50-413 D 50-289 G 50-289 G CONTRACT	Pollution & Environmental Problems, Inc Portland Cement Association Portland General Electric Co	6210210235 8210240527 6210040143 8210080253# 8210130399	50-295 / 50-329   50-344 / 50-344 ( PR
Perkins, Coie, Stone, Olsen & Williams	8210280235* 8210290131* 8210010382 8210050171 8210130190	CONTRACT CONTRACT 50-522 C 50-522 G 50-522 C		8210170024± 8210170026± 8210220301 8210250084 8210250093±	50-344   50-344   FR 50-344   50-344
	8210130347 8210130347 8210130498 8210130498 8210130498	50-522 G 50-522 G 50-522 G 50-522 G 50-522 G	Power Authority of the State of New York	8210250164 8210250175* 8210040213* 8210040317 8210040324	50-344 ! 50-344 ! 50-266 ! 50-333 !
Philadelphia Electric Go	8210250430 8207090201 8207090208* 8207090215* 8209170149	50-522 B 50-278 P 50-278 P 50-278 P 50-352 F		0210040332* 0210050079 0210050003 0210050005* 0210050005*	50-333 ( 50-266 ( 50-333 ( 50-333 (
	8210040224 8210040362 8210040362 8210050197 8210050197	50-352		8210060091 8210060145 8210060148* 8210060181 8210060235	50-286   50-247   50-247   50-286   50-247
	8210050320 8210050320 8210050321* 8210050321* 8210050382	50-277 P 50-277 P 50-277 P 50-277 P 50-352 G		8210040235 8210040285 8210040292* 8210120240 8210120243*	50-247 C 50-333 b 50-333 S 50-333 R 50-333 R
	8210050382 8210060017 8210060047 8210060074 8210060083*	50-352 G 50-278 S 50-277 S 50-277 S 50-277 S		8210180091* 8210180088 8210180088 8210180293*	50-247 P 50-286 P 50-333 O 50-286 R 50-286 R
	8210060177 8210060296 8210060296 8210060353 8210070177	50-277 S 50-277 J 50-277 J 50-277 S 50-277 Q		8210190069 8210190077# 8210190411 8210190435# 8210190712	50-333 S 50-333 S 50-333 G 50-333 G
	8210070188* 8210130276* 8210130276* 8210150069 8210150126	50-277 Q 50-278 S 50-277 Q 50-277 Q 50-252 A		8210190728 8210190734* 8210190738 8210200018 8210200024*	50-286 P 50-286 P 50-286 F 50-333 R 50-333 R
	8210150126 8210150133* 8210150133* 8210150154 8210150179*	50-352 A 50-352 A 50-352 A 50-277 8 50-277 9		8210200028 8210200039* 8210200074 8210210459 8210210470*	50-333 P 50-333 P 50-333 P 50-286 P 50-286 P
	8210150282 8210150292* 8210150356 8210150356 8210150368*	50-277 P 50-277 P 50-277 R 50-277 R 50-277 R	,	8210210473* 8210220326 8210250081 82102500B1 8210250216	50-285 P PR 50-247 0 50-247 0 50-247 0
	82101 50368* 82101 50397 82101 50397 82101 50400 8210200046	50-277 P 50-352 C 50-352 C 50-277 B 50-277 P		8210250216 8210250265 8210250265 8210250272 8210250272	50-247 0 50-247 0 50-247 0 50-247 H 50-247 H
	8210200044 8210200063* 8210200066 8210200068*	50-277 P 50-277 P 50-277 P 50-352 Q 50-277 P		8210260170 8210260175* 8210260306 8210260338* 8210260378	50-333 S 50-333 S 50-333 S 50-333 S
	8210200068* 8210210297 8210210297 8210210330 8210210330	50-277 P 50-277 P 50-277 P 50-277 P 50-277 P	President of US & Executive Offices	8210260386* 8210280070 821029027! 8208010022 8210070448*	50-333 S 50-286 F 50-247 O MISC FOIA
	8210220006 8210220007* 8210220170 8210220170 8210220174*	50-278 P 50-279 P 50-277 R 50-277 R 50-277 R	Project Management Corp	8210050184 8210060185 8210060200 8210130343 8210130435	50-537 0 50-537 0 50-537 0 50-537 0 50-337 0
	8210220194* 8210220374* 8210260112 8210260158 8210260329	50-277 R 50-352 G 50-277 S 50-352 A 50-277 P	Public Interest Research Group, New York	8210260361 8210130335 8210130337* 8210130337*	50-537 G 50-247 G 50-247 G 50-247 G 50-247 G
Phoenix. AZ Pipe Fabrication Institute Plateau Resources, Ltd.	8210280194 8210280204* 8210040004* 8210220342 8210240019	50-277 P 50-277 P CONTRACT PR 40-8698	Public Service Co, of Colorado	8210200019 8209150440# 8210040114 8210050331 8210050337#	50-247 0 50-257 F 50-267 P 50-267 S 50-267 S

AUTHOR AFF I LIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFF 1L IATION	ACCESSION NUMBER	SUBJEC CATEGO	
	8210040273 8210040282* 8210040284* 8210080254 8210130344	50-267 50-267 50-267 50-267 50-267	8 6 6 6		6210070314* 6210070351 6210070359* 8210070368 8210070371	50-272 50-311 50-311 50-272 50-311	១១១១១
	8210130349# 8210190306 8210190537 8210190543# 8210190655	50-267 50-267 50-267 50-267 50-267	A C C C C C		8210070375* 8210070377* 8210070380 8210070388* 8210080241	50-272 50-311 50-272 50-272 50-311	8 8 8
	8210190667* 8210190701 8210190706* 8210210081* 8210210089*	50-267 50-267 50-267 50-267 50-267	В Р Г		8210080294 8210120328 8210130164 8210130170* 8210130219	50-311 50-272 50-311 50-311 50-311	8 6 9 9
	8210220359 8210250083 8210270104 8210270113* 8210270118*	PR 50-267 50-267 50-267 50-267	F P P		8210130227* 8210130340 8210130345* 8210130351 8210130258*	50-311 50-311 50-311 50-311	8 8 8
Public Service Co of Indiana, Inc	8210280362 8210010230 8210130545 8210250130 8210270237	71-9044 PR MISC 50-546 PR	g		8210130554 8210150057 8210150058 8210150065* 8210150066*	PR 50-311 50-272 50-311 50-272	8 8 8
Public Service Co. of New Hampshire	8210290240 8210010465 8210010465 8210010470* 8210010470*	PR 50-443 50-443 50-443 50-443	A A A		8210150071 8210150075* 8210150080 8210150088 8210150089*	50-272 50-272 50-311 50-311 50-311	9 9 9
	B210040112 B210040112 B210040193 B210040193 B210050199	50-443 50-443 50-443 50-443 50-443	A A A A		8210150093* 8210150099 8210150109 8210150111 8210150118*	50-311 50-311 50-311 50-272 50-311	8 8 8
	8210050199 8210070105 8210130436 8210150510 8210180001	50-443 50-443 50-443 50-443 50-443	A A A A		8210150121* 8210150127 8210150140* 8210150148 8210150155*	50-272 50-272 50-272 50-272 50-272	8 8 9
	82101 90126 82101 90126 82101 90136 82101 90136 82101 90363	50-443 50-443 50-443 50-443 50-443	8 8 8		8210150311 8210150320* 8210150337* 8210180009 8210190507	50-311 50-311 50-311 50-272 50-272	6 8 8 8
	8210240149 8210240330 8210270153 8210270153 8210270164	50-443 50-443 50-443 50-443 50-443	9 9 0 0		8210190507 8210190515* 8210190515* 8210190644 8210190651	50-272 50-272 50-272 50-311 50-311	8 6 6
Public Service Electric & Gas Co of New Jersey	8210270166 8210280117 8210280117 8210010045	50-443 50-443 50-443 50-311	0 A A S		8210200010 8210200014* 8210200085 8210200070* 8210210134	50-311 50-311 50-272 50-272 50-272	R R R S
	82100 10123 82100 10128# 82100 10144 82100 10150# 82100 10181	50-311 50-311 50-311 50-311 50-272	9 9 8		8210210144* 8210220275 8210220326 8210250053	50-272 50-272 PR 50-311	8 8
	82100 10172* 82100 1023/ 82100 10237* 82100 10344 82100 10355*	50-272 50-311 50-311 50-311	8 8 8 8				
	82100 10383 82100 10390# 82100 10407 82100 10412# 82100 10419	50-272 50-272 50-311 50-311 50-311	8 8 8				
	82100 10423* 82100 10455 82100 10461* 82100 60326* 82100 70221	50-311 50-311 50-311 50-354 50-311	8 9 9 9				
	8210070231* 8210070243 8210070246 8210070248* 8210070249	50-311 50-311 50-311 50-311	8 8 8 8	Puget Bound Pows			
	8210070252* 8210070254 8210070258* 8210070305	50-311 50-311 50-311 50-272	8 8				

### **CORPORATE SOURCE INDEX**

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8210130367 8210130498 8210130498 8210200045 8210200058	50-522 50-322 50-522 50-522 50-522	G G G O		6210190331 8210190594 8210190598* 6210190603* 8210250037	50-312 P 50-312 P 50-312 P 50-312 P 71-9094	
Purdue Research Foundation	8210210337 8210210337 8210210339* 8210210339* 8210120342*	50-522 50-522 50-522 50-522 CDNTRACT	8 8 8		8210250065 8210250094 8210250386 8210250390# 8210260231	50-312 F 50-312 F 50-312 B 50-312 S 50-312 P	
Purdue Univ Pyle, R B	8208270011 8210250063 8210250063 8210250063 8210260427	ACRS 50-259 50-259 50-259 50-259	0 0	Safe Power for Maine San Clemente,CA Sandia Laboratories	8210280228 8210260457 8210260465# 8210120556# 8209290240#	50-3/2 P 50-309 0 50-309 0 CONTRACT FOIA	
R F Reedy, Inc	8210260429 8210260429 8210250247 8210280157 8210280272	50-259 50-259 50-275 50-275 50-275	Q Q R R P		8210050388 8210050397 8210040004 8210070413* 8210150552	NUREG NUREG NUREG 71-9150 NUREG	
Radiation Management Corp Reed, J Q Research Counsel of Washington Richards, Brandt, Miller & Nelson	8210040037* 8210150178# 8210060197 8210060403 8207110026	50-445 50-322 50-483 FOIA FOIA	G T G		8210150571 8210150631 8210250033* 8210240211 8210270338	NUREG RES NUREG NUREG NUREG	
Richland,WA, Ridihalgh, Eggers & Associates Riverside, CA Robert L Cloud Associates, Inc	8210210161* 8210210505* 8210270085* 8210250356 8210080078	CONTRACT PRATHOD PROJ PROJ 50-275		Sandvik Special Metale Corp Santa Monzca.CA	8210290399 8210270143 8210280032 8210280043 8210080077	RES XPORTLIC XPORTLIC XPORTLIC 50-142 0	
Rochester Das & Electric Gorp	8210080080* 8210250221 8210270184 8210270185* 8210010357	50-275 50-275 50-275 50-275 50-244	P R P P	Scandpower, Inc Science Applications, Inc	8210040311 8210040319* 8206210571* 8210040346* 8210040349*	TOPREP TOPREP 50-266 P 50-537 A 50-537 A	
	8210010365* 8210010367* 8210010444 8210040281 8210040284*	50-244 50-244 50-244 50-244 50-244	ե Ե Ե Ե		8210040350* 8210040351* 8210040355* 8210040357* 8210040412*	50-537 A 50-537 A 50-537 A FOIA CONTRACT	
	8210040288* 8210070030* 8210130195 8210130199* 8210130439	50-244 50-244 50-244 50-244 50-244	6 8 6 6 6		8210060447* 8210120357* 8210120422* 8210170025* 8210170037*	50-537 D CONTRACT CONTRACT CONTRACT CONTRACT	
	8210150443* 8210150648* 8210190591* 8210190618* 8210190637*	50-244 50-244 50-244 50-244 50-244	F G G	Science Management Corp	8210270413* 8210270419* 8210270428* 8210290320* 8210290006*	50-397 X CONTRACT 70-1113 50-206 V COMMISSION	
	8210190647* 8210190703 8210220352* 6210220360* 8210220383	50-244 50-244 50-244 50-244 PR	G G G	Scioto Memorial Hosp Portsmouth, OH Seaccast Anti-Pollution League	8207070324* 8210060194 8210060194 8210060204* 8210060206*	70-2748 50-443 G 50-443 G 50-443 G 50-443 G	
Rockland Citizens for Safe Energy	8210250275 8210250334 8210250343* 8210250217* 8210290217	50-244 50-244 50-244 50-244 50-247	P 8 8 9	Senate Sensible Maine Power	8210060214* 8210060214* 8208010016* 8210080236 8210200065	50-443 Q 50-443 Q 50-289 H 50-309 Q 50-309 Q	
Rockland County, NY Rockwell International Corp	8210220375 8210130054* 8210130315* 8210170182* 8210220321	50-247 CONTRACT 50-537 CONTRACT PR	A	Shaw, Pittman, Potts & Troubridge	8210290303 8210010345 8210010457 8210050255 8210050255	50-309 G 50-440 G 50-440 G 50-440 G	
Rocky Mountain Energy Co Rolf Jensen & Associates: Inc	8210180398 8210180405* 8210250043 8210190185*	40-8380 40-8380 40-9697 50-320	F		8210050374 8210050374 8210070124 8210070194	50~440 0 50~440 0 50~382 0 50~289 0	
Rondout Associates Ropes & Gray	8210130314 8210270153 8210270153 8210270164 8210270164	50-307 50-307 50-443 50-443 50-443	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		8210070197 8210070405 8210080086 8210080090 8210080094 8210120262	50-382 Q 50-440 Q 50-382 Q 50-382 Q 50-289 Q 50-483 Q	
SEP Owners Group Sacramento Municipal Utility District	8210130326 8210610057 8210650220 8210670287* 8210670294*	50-312 50-312 50-312 50-312	P F G G		8210120267 8210130275 8210150161 8210150228 8210150467	50-266 C 50-267 C 50-440 C 50-440 C 50-440 C	
	8210070331# 8210130175 8210130599 8210170278 8210170285#	50-312 50-312 PR 50-312 50-312	а Р R R		8210200013* 821020009 821020009 8210180155	50-440 @ 50-400 @ 50-400 @ 50-400 @ 50-400 @	

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	′	AUTHO AFFILIAT		ACCESSION NUMBER	SUBJECT	
	6210200021# 8210200021# 6210200033 6210210173 8210210179#	50-400 50-400 50-289 50-320 50-320	6 6 6 6			8210010348 8210050175 8210050210 8210050324 8210050324	50-395 50-395 50-395 50-395 50-395	8 P F
	8210210264 8210210284 8210210284 8210210353 8210210353	50-320 50-440 50-440 50-440 50-440	G G G G			821,0080290* 821,0080276 821,0120248 821,0180156 821,0180162*	50-375 50-375 50-375 50-375 50-375	ե ե 6
	8210210345 8210210372 8210210374 8210220305 8210220305	50-483 50-382 50-287 50-440 50-440	6 6 6 6			8210190352 8210190457# 8210190505 8210190513 8210190553	50-375 50-375 50-375 50-375 50-375	ն 6 6 6
	8210220307 8210220309 8210220394 8210220396 8210220405*	50-440 50-440 50-440 50-440 50-440	0 0 0 0			8210220340 8210220346* 8210220353 8210220438 8210220443*	50-375 50-375 PR 50-375 50-375	8 8 8
	8210220405* 8210250248 8210250253* 8210250279 8210250297	50-440 50-483 50-483 50-440 50-440	6 6 6 8			8210250330 8210250339* 8210260140 8210260139 8210260166*	50-395 50-395 50-395 50-395 50-395	р Р Р
	8210250322 8210250322 8210240404 8210240423 8210260214	50~440 50~440 50~266 50~382 50~440	0 0 0 0			8210240172 8210270245 8210270273 8210270284 8210270284*	50–395 PR PR 50–395 50–395	E E
	8210280216 8210280231 8210280231 8210280246 8210280253	50-440 50-440 50-440 50-440 50-266	G G G	South Carolina, State South Carolina, Univ		8210270335 8210270338* 8210130506 8210180106 8210170444*	50-395 50-395 50-413 50-413 50-395	8 9 9
Shoreham Opponents Coalition	8210280360 8210280387 8210290287 8210150309* 8210150324*	50-289 50-382 50-440 50-322 50-322	6 6 6	Southern California Ed	ison Ca	8210040177 8210040323 8210050008 8210050012* 8210050016	50-204 Toprep 50-361 50-361 50-361	Р 8 8
	8210150337* 8210150351* 8210150345* 8210150373* 8210150402*	50-322 50-322 50-322 50-322 50-322	6 6 6			8210050019* 8210050024* 8210050029* 8210050032* 8210050037*	50-361 50-361 50-361 50-361 50-361	8 9 8
	B210150410* B210150422* B210150527* B210200036 B210250059*	50-322 50-322 50-322 50-322 50-322	G G G			8210050041* 8210050044* 8210050048* 8210050050* 8210050096	50-361 50-361 50-361 50-361 50-361	6 6 6
Saerra Club	8210060195 8210120327 8210210232 8210210357 8210210453	50-537 50-537 50-537 50-537 50-537	0 0 0 0			8210050098* 8210050101* 8210050151 8210050234* 8210050241	146-05 146-05 146-05 146-05	8 8 8 8
	8210220248 8210220288* 8210220295* 8210240397 8210240404*	50-537 50-537 50-537 50-537 50-537	6 6 0 0					
igma Chemical Co	8210130072 8210270194 8210280403 8210250054 8210250056#	XPORTLIC XPORTLIC XPORTLIC 40-8502 40-8502	;					
inclair. M	821027004B 8210070132 8210070132 8210070136 8210070136	40-8602 50-327 50-327 50-327 50-327	0 0 0					
anissippi Alliance for the Environment SAFE:		50-329 50-329 50-329 50-454	0					
all Business Administration	8210210347* 8210210347* 8210210347* 8210180338* 8210180348* 6210210444*	50-454 50-454 50-454 CONTRAC CONTRAC CONTRAC	T					
merwell County, TX uth Carolina Electric & Gas Co	8210270221* 8210270223* 8210130074* 8210010167	CONTRAC CONTRAC CONTRAC 50-395	T T T					

1001 59925   20-36	AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOAY	
Section   Sect		8210150482 8210150482 8210190309 8210190317*	90361 9 50361 9 50361 9 50361 9		8210150337* 8210150351* 8210150365*	50~322 ( 50~322 ( 50~322 ( 50~322 (	G G G
1010 10505   50-101   7		8210190455# 8210190490 8210190506#	50-341 0 50-204 6 50-206 8		6210150410* 6210150422* 6210150527*	50-322 0 50-322 0 50-322 0	G G B
School   S		8210190560 8210190625 8210190625	50-361 P 50-204 F 50-206 F		8210200093* 8210200089* 8210250058	50-322 6 50-322 6 50-322 6	e e c
Section   Sect		8210250(40* 8210250207 8210250214	50-361 9 50-361 9 50-361 9		8210260239* 8210260242* 8210260246*	50-322 1 50-322 1 50-322 1	T T
BRIOS 00040   S0-000   P   BRIOS 00040   S0-000   S0-000   P   BRIOS 00040   S0-000   S0-0000   S0-0000   S0-0000   S0-0000   S0-0000   S0-0000   S0-0000   S0-0000   S0-000		8210250269 8210250273* 8210250280	50-361 S 50-361 S 50-206 S	Sugarmen, R J	8210010244 8210010244 8210180204	50-352 0 50-352 6 50-352 0	G U
Ballotached   So-2006   P   Solidached   So-2006   Solidached   So-2006   Solidached   So-2006   Solidached   So-2006   Solidached   So-2006   Solidached   Solidached   So-2006   Solidached   Solidached   So-2006   Solidached   Sol		9210260249 8210260272 8210260416	50-206 P 50-206 P 50-361 P		8210180208# 8210180217 8210180217	50-352 0 50-352 0 50-352 0	3
Section   Sect		8210240448 8210240450 8210240472	50-206 P 50-206 P 50-206 P		8210180224 8210180224 8210180224*	50-352 0 50-352 0 50-352 0	3
Southern California, Unit v of   S210270408   S210300173   S0-440   COMPACT   S210300173   S21030173   S0-440   COMPACT   S210300173   S0-440   COMPACT   S		8510580089* 8510580080 8510580098*	50-206 B 50-361 S 50-361 S	Sunflower Alliance	8210180253 8210010250 8210010250	50-352 6 50-440 6 50-440 6	2
St	Southpart,NC Southwest Research Institute	8210270408 8210130061* 8210120330*	50-295 0 CONTRACT CONTRACT		8210050173 8210050173 8210050228	50-440 0 50-440 0 50-440 0	}
Salos   Solos   Solo	St Joseph Hosp Albuquerque, NM St Lukes Hosp Milwaukee,WI	8210120066* 8210270247 8210050238	FOIA REGGD 50-329 G		8210050242 8210050252 8210050252	50-440 0 50-440 6 50-440 6	] }
State   Dept. of   Bureau of   Deans t   State   Dept. of   State   Dept. of   Bureau of   Deans t   State   Dept. of   St		8210050240 8210210370 8210080260	50-329 G 50-329 G 50-482 K	Systems Control, Inc	8210040335* 8210040340* 8210050418	QA999 Qa999 Nureq	ſ
State   Dept. of   Bureau of Doceans &   Size   S		8210080260 8210080266* 8210080266* 8210080266*	50-482 K 50-482 K 50-482 K 50-482 K	Target Research, Inc	8210270373 8210270376* 8210080123	40-8824 40-8824 50-275 P	
## S210080124 XPORTLIC    Steam Oenerator Owners Oroup   S210080125		8210240274	50-482 A	Felodyne Engineering Services	8210080191 8210080193* 8210190583	50-275 P 50-275 P 50-275 P	,
Steam Centerator Currers Group   S210050152   FR   S210220316   FR   S210220316   FR   S210220316   FR   S210250316   FR   S210250316   FR   S210250316   FR   S210250217   S0-275   FR   S210250217   S0-275   FR   S210250210   S0-275					8210190584	50-275 P	3
Sciol 50270+   So-322   T     Sciol 50270   So-275   P     Sciol 50270   Sciol 50270   So-275   P     Sciol 50270   Sciol 50270   So-275   P     Sciol 50270   Scio	Stearns-Roger Engineering Corp Stevenson & Associates	8210170468* 8210170468* 8210150206*	PR 50-213 P 50-322 T		8210250171* 8210250197 8210250201*	50-275 P 50-275 R 50-275 R	1
Stone & Webster, Inc.   S210270237 PR   S210280211   50-275 R   S210280212   S		8210150270* 8210170472 8210170500* 8210220346	50-522 T 50-395 P 50-395 P PR		9210250210 9210250240 9210250291	50-275 P 50-275 P 50-275 P	3
8210050189 50-322 0 Teledyne Wah Chang Albany 8210270011 XPORTLIC 8210050383 50-322 0 821027076 XPORTLIC 8210050383 50-322 0 8210270391 XPORTLIC	Stoner Associates, Inc Structural Dynamics Research Corp	8210270237 8210150281* 8210210301* 8210180143*	PR 50-322 T 50-329 A 50-358 A		8210280211 8210280212* 8210280277	50-275 A 50-275 A 50-275 P	ì
	auffolk County, NY	8210050189 8210050383	50-322 0 50-322 0	•	8210270011 8210270076 8210270391	XPORTLIC XPORTLIC	

### CORPORATE SOURCE INDEX

AUTHGR Affiliation	ACCESSION NUMBER	SUBJECT		AUTHOR AFF ILIATIO	JN	ACCESSION NUMBER	SUBJECT CATEGOR	
	820917006B 8209170101 8209300170 8209300175* 8210010011	50-327 50-259 50-259 50-259 50-259	F F B B B			8210080222 8210080217 8210080217 8210080222	50-257 50-259 50-259 50-438 50-438	6 6 8
	B210010104* B210010104* B210010104* B210010109 B210010115*	50-259 50-259 50-259 50-327 50-327	0 0 9 9			8210080247 8210080247 8210080247 8210080247 8210080247	50-390 50-390 50-390 50-390 50-390	9 8 8 8 9
	8210010135+ 8210010197+ 8210010304+ 8210010304+ 8210010304+	50-327 50-438 50-259 50-259 50-259	Q Q Q Q			8210080247 8210080255 8210080255 8210080278 8210080278	50-390 50-390 50-390 50-438 50-438	9 9 9 9
	8210010341* 8210010420* 8210010427* 8210050053 8210050042	50-390 50-518 50-438 TOPREP 50-390	G G			8210080280 8210080280 8210080291 8210080291 8210080292	50-390 50-390 50-390 50-390 50-438	5 5 5 5
	8210050062 8210050094 8210050094 8210050099 8210050104	50-390 50-438 50-438 50-390 TOPREP	ន ទ ន			8210080292 8210080307 8210080310 8210080310 8210120284	50-438 50-438 50-390 50-390 50-327	8 8 8 8
	8210050114 8210050114 8210050115 8210050115 8210050119	50-390 50-390 50-438 50-438 50-438	ន ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ			8210120289* 8210120289* 8210130142 8210130150 8210130150	50-327 50-327 50-259 50-327 50-327	<b>የ</b> የ የ
	8210050119 8210050158 8210050158 8210050216 8210050216	50-438 50-390 50-390 50-327 50-327	8 8 P P			8210130157 8210130162* 8210130165 8210130167* 8210130172	50-296 50-296 50-259 50-259 50-259	\$ 9 8
	8210050249 8210050249 8210050268 8210050271* 8210050285	50-438 50-438 50-259 50-259 50-564	8 9 P P 3			8210130176* 8210130247 8210130247 8210130317 8210130379	50~259 50~390 50~390 50~327 50~390	8 8 8
	8210050293 8210050293 8210050293 8210050293 8210050293	50-370 50-370 50-370 50-370 50-370	8 8 8 8 8 8			8210130384 8210130407 8210130429 8210130438* 8210130442	50-370 50-438 50-259 50-259 50-327	8 9 9
	82100 50316 82100 50316 82100 50344 82100 50344 82100 50407	50~390 50~390 50~390 50~390 50~438	9 0 0 8			8210130452* 8210130521 8210130540 8210130560 8210130565	50-327 PR 50-390 50-390 50-259	8 9 9
	82100 50407 82100 60205 82100 60205 82100 60219 82100 60221*	50-438 50-390 50-390 50-327 50-327	# # # # #			8210130549* 8210130572 8210130579* 8210150105 8210150181*	50-239 50-328 50-328 50-239 50-239	8 6 9 0
	82100 60265 82100 60270* 82100 60274 82100 60279 82100 60279	50-294 50-294 50-438 50-390 50-390	8 8 8 8			8210150218 8210150218 8210150230* 8210150230* 8210150231*	50-259 50-259 50-390 50-390	
	8210060280 8210060280 8210060301 8210060304* 8210060347	50-390 50-390 50-259 50-259 50-327	\$ \$ P P F			8210150241* 8210150251* 8210180117 8210180117		
	8210060352* 8210060352* 8210060409 8210060412* 8210060414	50-327 50-327 50-259 50-259 50-259	F 8 8					
	8210040422* 8210070133 8210070255 8210070255 8210070348	50-259 50-259 50-259 50-259 50-438	8 T P A					
	8210070348 8210080160 8210080160 8210080160 8210080160	50-43B 50-390 50-390 50-390 50-390	A 55 55 55 55 55 55 55 55 55 55 55 55 55					
	8210080218 8210080218 8210080218 8210080218	50-390 50-390 50-259 50-259 50-259	ե Ե					

AUTHOR AFF JLIATION	ACCESSION NUMBER	SUBJEC	)RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8210220225 8210220271* 8210220271* 6210220350 8210220422*	50~390 50~438 50~438 50~438 50~438	F G G S	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	6210290236 8210290236 8210290236 8210290236 8210290236	50-370 50-370 50-370 50-370 50-370	5 6 6 5
	8210220466* 8210220474* 8210220474* 8210250067 8210250070*	50-390 50-327 50-327 50-260 50-260	0 0 p P		8210290236 8210290248 8210290265 8210290266 8210290266	50-390 50-438 PR 50-390 50-390	5 6 9 9
	8210250096 8210250096 8210250096 8210250101* 8210250101*	50-259 50-259 50-259 50-259 50-259	<b>ե</b> Ե Ե		8210290274 8210290274 8210290274 8210290277 8210290279#	50-328 50-328 50-328 50-327 50-327	9 9 9 9
	8210250101* 6210250236 8210250236 6210250236 8210250244	50-259 50-259 50-259 50-259 50-250	4 4 4 4		8210290317 8210290321# 8210290324 8210290324 8210290328	50-259 50-259 50-438 50-438 50-390	88888
	8210250244 8210250244 8210260100 8210260100 8210260105	50-250 50-250 50-390 50-390 50-438	F ន ន		8210290328 8210290328 8210290328 8210290368 8210290371*	50-390 50-390 50-390 50-259 50-259	មាយមាលា
	8210260105 8210260107 8210260148 8210260174 8210260174	50-438 50-438 50-327 50-390 50-390	9 P F	Teton Exploration Drilling Co , Inc Texas A & M Univ Texas Nuclear Div (subs of Ramsay Eng Co)	8210280412 8210250195 8210250198* 8210060411*	40-8728 50-341 50-341 FOIA	F F
	8210240184 8210240188 8210240188 8210240187 8210240187	50-390 50-390 50-328 50-390 50-390	8 8 F F	Taxas Tech Univ Taxas Utilities Generating Co	8210190177* 8210010302 8210040024* 8210040024* 8210040026*	CONTRACT PR 50-445 50-445 50-445	9
	6210260189 6210260189 6210260189 8210260196* 6210260212	50-390 50-390 50-390 50-328 50-259	6 6 7		8210040030* 8210040030* 8210040030* 8210040033* 8210040037*	50-445 50-445 50-445 50-445 50-445 50-445	0 0 0 0 0
	8210260222# 8210260228 8210260251 8210260320 8210260320	50-259 50-327 50-438 50-390 50-390	8 8 8		8210040037* 8210040318 8210130297 8210130299 8210130576	50-445 50-445 50-445 50-445 50-445	0 5 6 6 7
	8210240320 8210240320 8210240320 8210240320	50-390 50-390 50-390 50-390 50-438	8 8 8 9		8210130576 8210180006 8210180006 8210180008# 8210180008#	50-445 50-445 50-445 50-445 50-445	F K K K
	8210260322 8210260349 8210260353* 8210260361 6210260390	50-438 50-260 50-260 50-259 50-390			8210220372 8210250338 8210250338 8210250344 8210240375	PR 50-445 50-445 50-445 50-445	8 8 8
	8210240390 8210240407* 8210240408 8210240408 8210240417	50-390 50-259 50-390 50-390 50-260	8 8 8 8 8	Texas, State of Texas, Univ of Thatcher, T L Three Hile Island Alert	8210040042* 8210050174 8210080073 8210050176 8210050237	50-445 50-192 50-522 50-289 50-289	0 P G G
	8210260446* 6210260451 8210260451 6210260208 6210270047	50-260 50-390 50-390 50-391 50-391	8 8 8 8 8	Toledo Edison Co	8210280234 8210050235 8210050258* 8210050304 8210050310	50-287 50-346 50-346 50-346 50-346	Б 0 1,
	8210290054 8210290057* 8210290059 8210290059	50-259 50-259 50-438 50-438	5 S S S S		8210050313* 8210050318* 8210050323 8210050327* 8210050333	50-346 50-346 50-346 50-346 50-346	9 8 8
	8210270066* 8210270091 8210270074* 8210270178	50-259 50-328 50-328 50-390	8 8 8		9210050358 #210050361* #210060314 #210070005* #210070006*	50-346 50-346 50-346 50-346 50-346	8 8 6 F
	8210270187 8210270187 8210270187 8210270187 8210270187	50-518 50-518 50-518 50-518	8 8 8 8 8		8210080288* 8210130124 8210130128* 8210130356 8210130366*	50-346 50-346 50-346 50-346 50-346	0 8 8
	8210290232* 8210290236 8210290236 8210290236	50-294 50-294 50-390 50-390 50-390	8 9 8 8		8210130404 8210130410* 8210180131 8210180135	50-346 50-346 50-346 50-346	8 9 9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
***************************************	8210180137* 8210170254 8210170261* 8210170303 8210170358	50-346 50-346 50-346 50-341 50-346	a a a a		8210260108 8210270173 8210270206 8210270213 8210270218	70-820 70-820 70-820 70-820 70-820
	8210190359* 8210190623 8210210458 8210210556* 8210210559*	50-346 50-346 50-346 50-346 50-346	8 P P	Universal Technical Testing Laboratories, Inc Uranium Resources, Inc Utah, State of Utah, Univ of	6210180354 6210250013 6206270016*	PR 40-8784 40-8786 COMMISSION
	8210220013 8210250224 8210250231* 8210250270 8210250279*	50-346 50-346 50-346 50-346 50-346	e 8 8 9	Utility Morkers Union of America Vermont Yankee Nuclear Power Corp	8210240230* 8210240234* 8210240240 8210040113 8210130189 8210130189	50-72 R 50-72 R FR 50-271 Q 50-271 R 50-271 R
, Parks, Seliger, Simonoff & irlan	8210240248 8210240283 8210280075 8210280076* 8207180051	50-34A 50-34A 50-34A 50-34A 50-219	H 8 8 6		8210150447 8210180190 8210190022 8210190029* 8210210204	50-271 P 50-271 F 50-271 B 50-271 S 50-271 S
ų Pines Technology	8210120264 8210150353* 6210220198 8210220198 8210220198	50-528 50-382 50-528 50-528 50-528	R A R R		8210210214* 8210220416* 8210270430* 6210270432* 8210280138*	50-271 B 50-271 G 50-271 F 50-271 F 50-271 F
inerica Delavat, inc	B210220244* B210220244* B210220244* B210050270* B210050275*	50-528 50-528 50-528 GA999 GA999	R R R	Vester J. Thompson, Jr., Inc Virginia Electric & Power Co	8210280143* 8210820246 8206160306* 8207230301 8207230303*	50-271 F PR 50-280 Q 50-339 9 50-339 S
uclear. Inc	8210070452 8210080037 8210080040* 8210080042* 8210080108	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			9209090114 6208090114 6210010103 6210010107* 6210010125	50-338 P 50-339 P 50-339 P 50-339 P 50-280 F
	8210080130 8210080133 8210270147 8210270168 8210280052	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			8210010125 8210010125 8210010140 8210010145* 8210010143	50-280 F 50-280 F 50-338 9 50-338 8
ite Motor Transit Co (subs of	8210280056 8210280059⊭ 8210150605	XPORTLIC XPORTLIC 70-1739	<b>;</b>		8510010533 8510010512* 8510010502 8510010198*	50~338 S 50~338 S 50~338 S 50~337 S
P	8210120496* 8210120286*	CONTRACT 50-275	P		6210010236*	50-339 B
ogy: Inc (Formerly Nuclear ecing! arbide Corp	8210130302 8210130304 8210130306* 8210190246	27-39 50-54 50-299	P P		8210010246* 8210010247* 8210040277 8210040277	50-338 P 50-338 P 50-338 P
	8210190256* 9210220491 9210250019 9210250021* 9210270047	40-299 40-299 40-299 40-299 70-687			8210040290* 8210040297* 8210040315* 8210040325* 8210050071	50-338 P 50-338 P 50-338 P 50-338 P 50-280 S
lectric Co	8210270070* 8210050277 8210120242 8210130555* 8210210345	70-687 50-483 50-483 50-483 50-483	A G G		8210050074* 8210050076 8210050078* 8210050081 8210050081	50-280 S 50-280 F 50-280 S 50-280 S
Concerned Scientists	8210250248 9210250253* 8210120274 8210130335 8210130335 8210130337*	50-483 50-483 50-289 50-247 50-247 50-247	0 0 0 0		8210050086* 8210050092* 8210050103 8210050105	
	8210130337* 8210220274* 8210220410 8210220465 8210280242	50-247 50-537 50-247 50-269 50-247	0 0 0			
irlines. Inc (subs of UAL)	8510550319	PR				
)ginders & Constructors, Inc )f Raytheon Co )	8210030206* 8210260205 8210270060*	50-443 50-324 50-537	A 9 0			
iclear Corp	8210200104 8210250012 8210250014 8210250016 8210250032 8210250038	70-820 70-820 70-820 70-371 40-8781 70-820				

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFF (LIATION	ACCESSION NUMBER	SUBJECT CATEGORY	<i>'</i>
	8210120297 8210120297 8210120205* 8210120305* 8210120305*	50-280 50-280 50-280 50-280	ь Б Б		8210270258 8210280130 8210280246 8210290244 8210290270*	50-938 50-280 50-280 50-280 50-280	Р Р Б Б
	8210120305* 8210120305* 8210130112* 8210130114* 8210130114*	50-280 50-280 50-338 50-338 50-338	р <b>Б</b> Б Б	Virginis, Univ of	8210290276* 8210290282* 8210290337 8210290347* 8210060686	50-280 50-280 50-338 50-338 50-62	\$ 9 9
	8210130204 8210130204 8210130208* 8210130213* 8210130216*	50-280 50-280 50-280 50-280 50-280	5 5 5 6 8	Washington Legal Foundation Washington Public Power Supply System	8210080237 8210010322 8210130277 8210010020 8210040255	50-62 PR PR 50-508 50-397	P H A
	8210130427 8210130431* 8210130500 8210130507* 8210150054	50-280 50-280 50-280 50-280 50-280	0 6 5 8		8210050124 8210050154 8210050348 8210060223 8210060319	50-397 50-397 50-397 50-397 50-397	E A A C
	8210150095 8210150139 8210150359 8210150394 8210190264	50-280 50-280 50-281 50-280 50-338	6 6 6 6		8210040445 8210070141 8210070144* 8210070161* 8210070297	50-397 50-397 50-397 50-509 50-460	F A Q G
	8210190270* 8210190321 8210190329 8210190337* 8210200043	50-338 50-339 50-338 50-338 50-280	ស ស ស ស		8210070297 8210070302* 8210070311 8210070311 8210070338	50-460 50-397 50-460 50-460 50-460	8 8 8
	8210200043 8210200048* 8210200048* 8210210053* 8210210053*	50-280 50-280 50-280 50-280 50-280	ቀ ቀ ፫ ፫		8210070370 8210070387* 8210070387* 8210080075 8210080100*	50-397 50-460 50-460 50-397 50-397	8 9 8 K K
	8210210055* 8210210055* 8210210058* 8210210058* 8210220011	50-280 50-280 50-280 50-280 50-238	ቸ F F		8210080195 8210080275 8210080304 8210120194 8210120197	50-397 50-397 50-397 50-508 50-508	0 6 6 8
	6210830100* 6210830042* 6310830042* 6310830011	50-338 50-280 50-280 50-280 50-280	P 8 8 8 8		8210120200* 8210130188 8210130194 8210130217 8210130425*	50-508 50-397 50-397 50-397 50-460	K A F 9
	8210220170 8210220178 8210220178 8210220178 8210220178	50-280 50-280 50-280 50-280 50-280	р Р Р Р		8210130432* 8210130432* 8210130675 8210190576 8210190582*	50-460 50-460 50-397 50-397 50-397	E 0 0
	8210220200 8210220227 8210220234* 8210220373 8210220372	50-936 50-938 50-938 PR 50-280	Q S S		8210190584* 8210190646 8210190708 8210190764 8210210045	50-397 50-397 50-397 50-397 50-397	E O A K
	8210220392 8210220398# 8210220408# 8210220413# 8210220415	50-280 50-280 50-280 50-280 50-339	5 5 5 5 6		8210210049 8210210148 8210210276 8210210327 8210260113*	50-397 50-397 50-397 50-397 50-397	E E A
	921 0220 421 * 821 0220 424 821 0220 435 * 821 0220 441 821 0220 450 *	50-339 50-281 50-281 50-339 50-339	8 8 8 8 8	Washington, State of Waste Management Group, Inc	8210270012 8210280170* 8210280277* 8210240442 8210280331*	50-508 50-460 50-460 50-397 CDNTRACT	A G G A
	8210250208 8210250208 8210250212* 8210240133 8210240133	50-338 50-338 50-338 50-338 50-338	F F P P	West Branch Conservation Association  West Chicago, IL	8210180203 8210200019 8210210390 8210210397* 8210250315	50-247 50-247 50-247 50-247 40-2061	0 0 0
	8210240134* 8210240134* 8210240281 8210240287* 8210240270	50-338 50-338 50-339 50-339 50-338	P ទ ន ន	Westchester County, NY Westchester Peoples Action Coalition, Inc Western Geophysical Western Piping & Engineering Co., Inc	8210250287 8210200017 8207300332* 8207300336* 8210120285*	50-247 50-247 50-213 50-213 94999	0 Р Р
	8210260293* 8210260346 8210260360* 8210270160 8210270204	50-338 90-339 50-339 50-338 800-03	8 8 8 P P	Westinghouse Electric Corp	8210120293* 8005070094 8005070099* 8210010169 8210040196*	GA999 PT21 PT21 70-1151 GA999	
	8210270212 8210270212 8210270215* 8210270220* 8210270224*	50-260 50-260 50-260 50-260 50-260	8 8 8 8		8210050198* 8210080038* 8210080229 8210080227* 8210080321	GA999 FOIA TOPREP TOPREP XPORTLIC	;

AUTHOR AFF (LIATION	ACCESSION NUMBER	SUBJECT	Υ	AUTHOR AFF I-LIATION	ACCE 8810N	CATEO	
	8210080323* 8210120250* 8210130250* 8210130420 8210130426*	XPORTL10 50-395 50-537 50-22 50-22			6210260253 6210260295 6210260295 6210260296* 6210260298*	50-266 50-266 50-266 50-266 50-266	ե ե ե
	8210130447 8210130535± 8210190429± 8210190508* 8210190607	PT21 50-364 50-282 50-395 TOPREP	р Р	Wisconsin Public Service Corp	8210290294 8210010179 8210010186* 8210010202 8210010307	50-266 50-305 50-305 PR PR	ե ե
	8210210054 8210220152 8210220154 8210250128* 8210250141*	NUREG TOPREP NUREG GA999 GA999			8210040156 8210040159* 8210040162* 8210050263 8210060312	50-305 50-305 50-305 50-305 50-305	8 8 9 P
	8210260305 8210260340 8210260351* 8210270014 8210270017	TOPREP TOPREP TOPREP XPORTLIC XPORTLIC			82100 60328 82100 70108 82101 30282 82101 30300 82101 30581	50-305 50-305 PR 50-305 50-305	0e Р Г Г
izlinghouse Operating Plants Owners Toup 	8210270208* 8210270260* 8210080274 8210120401*	50-338 50-338 TOPREP CONTRACT	p p		8210170393 8210170355* 8210170356* 8210170487 8210240260	50-305 50-305 50-305 50-305 50-305	9 9 P
lisan. R (It. D.D	8210120604# 8210200053 8210010250 8210010250 8210010323	40-8745 50-400 50-440 50-440	0000	Wisconsin's Environmental Decade Hoodward Governor Co	8210240243* 8210270234 8210040125 8210250120 8210150534*	50-305 PR 50-266 50-266 GA999	6 G
	8210010323 8210050173 8210050173 8210050228 8210050228	50-440 50-440 50-440 50-440	G G G G	Wyoming Mineral Corp Wyoming, State of	8210150544* 8210270180 8210270183* 8210130607 8210150597	0A999 40-8502 40-8502 40-299 40-0743	
	8210050242 8210050242 8210050252 8210050252 8210250331	50-440 50-440 50-440 50-440 50-440	6 6 6		9210210254 8210240084 8210240074 8210240077* 8210280444	40-6459 40-6452 40-8761 40-8761 40-8452	
inthrop, Stimson, Putnam & Roberts iscansin Electric Power Co	82070 50085 81072 70156 82072 90257 82072 90279 82100 40119	50-247 50-266 50-266 50-266 50-266	P a k k F	Yakima Indian Nation Yale Univ. Yankee Atomic Electric Co	6210280451 8210050169 8210260232 8210260239* 8210010374	40~8697 50~522 50~322 50~322 PR	G T T
	8210050005 8210050005 8210050054 8210050054 8210050055	50-244 50-244 50-246 50-246 50-246	6 6 6		8210010465 8210010465 8210040112 8210040112 8210040173	50~443 50~443 50~443 50~443 50~443	A A A A
	8210050055 8210050222 8210050221* 8210050231*	50-266 50-266 50-266 50-266	6 6 6		8210040193 8210050197 8210050199 8210050310* 8210070105	50-443 50-443 50-443 50-29 50-443	A A Q A

### **CORPORATE SOURCE INDEX**

AUTHOR AFF [LIATION	ACCESSION NUMBER	SUBJECT	łΥ	AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGOR
	8210240145 8210240147# 8210240330 8210240428 8210270430#	50-29 50-29 50-443 50-29 50-271	8 8 8	92 82	10280119 10280138*	50-29 50-443 50-271
	8210280085 8210280094	50-29 50-29	9 P		10290263 08290089	PR FOIA

### REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT	OTHER REPORT Y NUMBER
1 JA 300 1000-PLN-7200 01 R00 100-92/N7KF 11410 R01 P630 1	8210070355* 8210250097* 8210130287* 8210180143* 8210270240*	50-438 A 50-219 P 50-389 E 50-358 A 50-338 P		CRBR-ARD-0117 DEY-16-0201 R01 DNS-D1-034 EDAC 175-130 02 DRF EERC 75-15	8210130250* 8210010460* 8210180197* 8210070091* 8107270198*	50-341 50-10	A A P DOE/ET 34205-33 P Q
1159 C-21 11C152 1 12-1 2-32 210050504	8210040241* 8210170668* 8210170444* 8210280178* 8210050504	50-155 P 50-213 P 50-395 P 50-277 P RES	0020A DRF 137-0010 ORNL/861-4	EERC 75-21 EERC 76-16 EERC 76-8 EGG-1183-4168 EGG-EA-5307 ROI	8107270199* 8107270191* 8107270188* 8010070320* 8210280432*		0 0 0 P P TAC 12992
210040425 210070449 210080322 210120118 210120124	9210040425 8210070449 8210080322 9210120118 8210120124	RES RES RES RES RES	EGG-M-09782 EGG-M-11782	EGG-EA-4014 EGG-EA-4017 EGG-EA-4033 EGG-EA-4031 EMD-81-104	8210120300* 8210070099* 8210250372* 8210270288* 8210270020*	50-213 50-27 50-213 50-155 50-537	P P P Q
210120367 210120368 210120390 210120397 ?10120400	8210120367 8210120368 8210120370 8210120377 8210120400	REG REG REG REG	BNL-NUREO-31834 EGG-M-11682 EGG-M-04382	GA-A13010A A07 GA-A16764 GIBSAR-17-A A06 MBB/PDO-77-1 ME-146	8210290144* 8210080258* 8210270127* 8210040277* 8210150352*	TDPREP 50~267 50~584 50~369 50~341	QA-LTR-11 P UC-77 A K Q
110120428 110120430 110120453 110120455 110120459	8210120428 8210120430 8210120453 8210120455 8210120459	RES RES RES RES	Q-6-507 (R673) EGG-LDFT-5937 GRNL/FTR-1365 BNL-NUREG-31755 BNL-NUREG-31775	ME-229 ME-230 ME-884 MPR-733 MPR-734	8210150343* 6210150346* 8210260493* 8210010081* 8210010085*	50-341 50-341 50-358 50-219 50-219	G G E P P
10120460 10120463 10120466 1012046	8210120440 8210120463 8210120466 8210120630 8210120649	RES RES RES RES RES	BNL-NUREG-31774 BNL-NUREG-31754	NEDG-21471-01 801 NEDG-22192 NEDG-24088-1 NO4 ERR NEDG-24088-1 NO5 ERR NEDG-241464 ERR OB	8207120253* 8210190785* 8210250077* 8210250078* 8210250177*	50-447 50-254 50-260 50-260 50-254	A 79MED99R P 82MED080 P 77MED360 F 77MED360 P 79MED273
10120653 10120654 10120657 10150409 10150412	8210120653 8210120654 8210120657 8210150409 8210150412	RES RES RES RES	ORNL/FTR-1371 E00-CDD-6029 E0G-M-21082 E00-M-06482	NEDD-24934 ERR RO2 NSE-50-0582 NSEO-72-0782 NSEO-88-0982 NSP-77-001 ROO	8210280184* 8210280201* 8210280204* 8210010224* 8210150500*	TOPREP 50-277 50-277 TOPREP 50-263	P DRF-F13-00023 P DRF-F13-00023 T23-00452 P 30 1777 0100
0150415 0150426 0150625 0150625 0150631	8210150415 8210150421 8210150611 8210150625 8210150631	RES RES RES RES RES	E0G-M-14082 E0G-L0FT-5782 E0G-L0FT-5733 SAND82-1855	NSP-77-003 ROO NSP-77-007 ROO NSP-77-008 NUREG-0030 VO6 NO2 NUREG-0267 RO1	8210150509* 8210150504* 8210150377* 8210280142 8210270331	50-263 50-263 50-263 NUREO NUREO	P 30 1777 0102 P 30, 1777 0106 P 30 1777 0026
0189407 0200102 0270421 0280292 0280323	8210180407 8210200102 8210270421 8210280272 8210280323	RES RES RES RES	EGG-LOFT-5999 EGG-ID-6040 EGG-LOFT-6039	NUREO-0580 V11 NO9 NUREO-0749 V02 NO8 NUREO-0750 V15 NO5 NUREO-0793 NUREO-0822 DRFT	8210120119 8210120116 8210150547 8210210030 8210270345	NUREO NUREO NUREO 50-329 50-219	E P
0280039 0290017 0290399 -FRPE-282 -2-NP A01	6210280339 6210290017 6210290399 6210270206* 8210040259*	RES RES RES 50-336 P TOPREP	EGG-ID-6037 EGG-WRR-6019 BAND81-0826	NUREO-0846 NUREO-0847 801 NUREO-0857 803 NUREO-0858 NUREO-0928	8210050422 8210050405 8210060006 8210050431 8210050377	40-1341 50-390 50-528 Nureo 50-62	E E
-1743 -04261 -185-NP -216(B) -01-110 R00	8210010284* 8210120642* 8210040329* 8210180133* 8210050427*	50-329 E 50-341 / TOPREP 50-317 F 50-155 F	<b>.</b>	NUREG-0940 VO1 NO1-2 NUREG/BR-0024 NUREG/CP-0030 NUREG/CR-0169 V20 NUREG/CR-1369 RO1	8210210024 8207280307 8210150553 8210150560 8210040004	NUREO NUREO NUREO NUREO NUREO	PNL-8A~10325 EGG-2037 V20 SAND80-7054

### REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT		REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	
NUREG/CR-2000 V01 N8 NUREG/CR-2182 V02	8210150577 8210210034	NUREG	ORNL/NGIC-200 F ORNL/NUREG/TM-4	SAI-184-028-22 SAI-186-029-17	8206210571* 8210270320*	50-266	P V
NUREQ/CR-2183	0210150567	NUREO	ORM./TH-7864	SAND00-0783	8210070413*	71-9150	TTC~0079
NUREG/CR-2229 VO2	8207290410	NUREO	GEAP-24962-2	SCP-01-A R04	8210040319*	TOPREP	
NUREG/CR-2260 ERR	9210060417	NUREO	E00-2181	SECY-82-0728	8204200390#	FOIA	
NUREG/CR-2404 NUREG/CR-2444 VOI	8210150548 8210210054	NUREO NUREO	UCRL-53034 EPRI NP-2014	8ECY-82-072C SECY-82-142	8205270507# 8204300098#	FOIA FOIA	
NUREG/CR-2444 V02	8210220154	NUREG	EPRI NP~2014	SECY-82-186	8205280495	SECY	
NUREG/CR-2406	8210050397	NUREC	SAND81-1932	SECY-82-232	8206180042#	FOIA	
NUREG/CR-2609	8210210039	NUREG	ORNL/NUREQ-75	SECY-82-255	B206240119#		8
NURE9/CR-2673	8210210037	NUREO	ORNL/TM-8306	SECY-92-267	6204290412	SECY	_
NUREG/CR-2710	8210240204	NUREO	IEEB-MT\JKRO	SECY-82-384	8210210503		P
NUREG/CR-2719	8210150569	NUREG	ORNL/TM-8278	SECY-02-399	8210220534	SECY	
NUREO/CR-2730	8210150571	NUREO	BAN092-1150	SECY-82-407	8210270322	SECY	_
NUREG/CR-2754	8210050418	NUREO	PNL-4292	SECY-02-414	8210290214		P
NUREG/CR-2759	6210270339	NUREG	SAND82-7062	8RD-307	8205250020*		p
NUREG/CR-2761	8210050388	NUREQ	SAND82-7065	T1002745 R03	8210120283*		P
NUREQ/CR-2791	8210150552	NUREG	SAND82-7067	TER-C5257-282	8208190290*		P
NUREO/CR-2792	8210050360	NUREO		TER-C5257-294	8206190178*		P TAC 12438
NUREG/CR-2820	8210120125	NUREG		TER~C5257-317	8209160459*	50-155	P
NUREG/CR-2831	8210150549	NUREG	MLM-2957	TER-C5257-318	820B170083*	50~204	P
NUREQ/CR-2846	0210220135	NUREO	BNL/NUREO-51567	TER-C5257-403	8204230020#		P
NUREG/CR-2859	8210150557	NUREQ	ANL-CT-81-32	TER-C5257-414	8208180082*	50-155	P
NUREG/CR-2862	8210210041		P	TER-C5257-426	#920B100269	50-29	P
NUREG/CR-2873 V01	8510150105	NUREG	PNL-4306	TER-C5257-530	#4500B101ZB	50~346	P
NUREO/CR-2873 V02	8210120092	NUREO	PNL-4306	TER-C5257-542	*88100E8028	50-155	a
NUREG/CR-2874 VOI	8210150564	NUREO	ORNL/TM-8443/V1	TER-C5257-544	8207190431*		o
NUREG/CR-2877	8210260211	NUREO	SAND81-2613	TER~C5506~151	8206030064*	50~206	p
NUREQ/CR-2885	8210150554	NUREO	ANL-82-44	Ter-C5506-307	8210120640*	50-341	A
NUREG/CR-2889	8210150550	NUREQ	HEDL/THE 82-32	TER-C5504-58	8202010167*	50-219	Þ
NUREG/CR-2897	8210050428 8210150574	NUREO		UCB/EERC-77/07	8107270196#		O C
NUREG/CR-2898		NUREG		UCB/EERC-78/17	8107270174*		g .
NUREG/CR-2905	8210050368	NUREO		UCB/CERC-78/27 VO1	8107270166*		Q .
NUREG/CR-2707	8210210051	NUREO		UCB/EERC-78/28 VO2	8107270169*		Q
NUREG/CR-2714	8210210046	NURED		UCB/EERC-79/12 VQ3	8107270174*		G
NUREO/CR-2919	8210220149	NUREO	PNL-4380	UCB/EERC-79/23 VO1	8107270178*		G .
NUREG/CR-2920	8210050412	NUREG		UCB/EERC-79/24 VOQ	8107270182*		a
NUREO/CR-2922	8210150592	NUREO	BMI-2099	UCB/EERG-79/25 VO3	91072701 <b>85</b> #		G .
NURE0/CR-2923	8210210014	NUREQ	BW1-3100	UCID-18689 ROI	8207130461*		P
NUS-4146 R01	8210210306*		4	UCID-19113	8206170006#	50-315	P
NUS-4154	921006 <b>0354</b> * 9210270052*		- -	UCID-19141 DRFT	8207300222*		<u> </u>
ORNL-5470	8210270035*		9 }	UCID-19147	0209200475*		P
ORNL-TM-4697			g.	UE&C-ANL-810930	8210270060*		G COO-6411-1
ORNL/NBIC-112 DRFT	8210280110*	FOIA FOIA		UMTRA-DOE/ALO-34 DRF	8210250025	WASTE MOT	
ORNL/NSIC-208				URS/JAB 8216	8310130386*		P
ORNL/N81C-209	8203250320*	FOIA	_	VEP-FRD-33 ERR	8210120305*		Þ
P 105-4-839-008 R00	# 0800B0012B		P	HCAP-10102	8210190429*		p
PNL3524	8210270041*		9 UC-11	WGAP-10142	8210130535*	50-364	P
R543-02 V05	8210040178*		2	WCAP-7870	#8C0080038	FOIA	
RAI-C5504-196	8210050068*	50-409	p	XN-NF-76-47(NP)(A)	8210150182*	TOPREP	
				XN-NF-81-21(NP)(A)	8210270169*	TOPREP	
				Y1003501A40	8210250074*		P DRF L12-00304-1
				109 OSA10UE001Y	8207090224*		P
					•		

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

ACCESSION NUMBER

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

	~			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEGO:	
		-~		
7811200399	8510580013	82/09/17	50-325	ន
7Ø122002B5	8210070007	82/08/10	50~266	P
7903090181	8210180028	62/08/20	FOIA	
7905290357	8210280013	82/09/17	50~324	P
7908130454	8210280013	82/09/17	50-261	P
7909280105	8210070007	85/08/10	50-244	P
7912280014	8210280013	82/09/17	50-324	P
8001080054	8210180028	82/08/20	FOIA	
9002080095	6210190112	82/10/06	FØIA	
8002140204	8210010008	82/06/28	50-266	P
8003310179	8210010008	82/06/28	50-244	р
8004100193	8210010008	82/06/28	50-265	P
8004300616	8210070007	85/08/10	50-266	ė
				-
BC05070079	8005070094	80/03/14	PT21	
6005270820	8510010008	83/07/58	FOTA	
6005270822	8210010008	82/06/28	FOIA	
6006050154	8210180028	82/08/20	FOIA	
8006050188	8210180028	82/08/20	FDIA	
BQQ6170030	8210180028	82/08/20	FOIA	
B006300104	8210010008	82/06/28	FOIA	
8008300104	9510010008	62706720		
8008050265	8210010008	65/04/28	50-327	₽
8008070143	8210180028	82/08/20	FOIA	
8009040493	8210070007	82/08/10	50-266	P
				þ
8009040497	8210070007	82/08/10	50~266	-
BO 10070320	8210210375	82/09/30	50-305	P
8010210037	8210010008	82/04/28	50-327	8
8010240413	851001000B	82/06/28	FOIA	
8010240496	8210010008	82/06/28	FOIA	
8011060346	8210080015	82/07/12	FOIA	
8011060565	8011060561	80/10/20	50-254	8
8011040548	8011060561	80/10/20	50~254	8
8011120679	8210010008	82/06/28	50-247	š
				š
8011240024	8210010008	85/09/58	50-247	a
6012180362	8210120012	82/0B/20	FOIA	
8101090294	8210010008	82/06/28	50-247	8
8101140002	8210280013	82/09/17	50-324	Р
8101200322	8210290023	82/09/03	50-142	F
8101270870	8210180028	82/08/20	FOIA	
		82/08/20	FOIA	
8102280195	8210180038			
8103030076	8210010008	85\09\58	FOIA	
8103050756	8210010008	82/04/28	FOIA	
8103050987	8210010008	82/06/28	50-327	р
8103040088	8210010008	82/06/28	FOIA	
	8210010008	82/04/28	50~247	S
8103090389		82/06/28	50-321	5
B103120107	8210010008	95170148	JU-3≰I	a
8103160338	8210180028	82/08/20	FOIA	
8103160366	8210180028	82/08/20	FOIA	
B103190719	8210010008	82/06/28	50-245	3
0.00170717	8210010008	82/04/28	AlDa	
8103240292		82/06/28	FOIA	
8103310127	8210010008	02/40/58	- UIN	

	ACCESSION	NUMBER			
	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISQUED	SUBJECT	Y
	8104080309 8104170703	8210080015 8210180028	82/07/12 82/08/20	FOIA FOIA	
	8104240059	8210010008	82/06/28	FOIA	
	8104290103 8104290774	821001000B 8210280013	82/06/2B 82/09/17	50-366 50-324	8 P
	8105040420	8210080015	82/07/12	50-352	0 P
	8105040512 8105110396	8210080015	82/07/12 82/06/28	50-285 FOIA	P
	8105280476	8210080015	82/07/12	50-263	œ
	8106100203	8210010008	82/06/28	E1E-05	P
	8106100362	8210010008	92/06/28	FOIA	_
	8106150555 8106220159	8210010008 8210080015	82/06/28 82/07/12	50-302 FOIA	8
	8106220165	8210080015	92/07/12	50-261	P
	8106220168	8210080015	82/07/12	FOIA	
٠.	8107010140	8210280013	92/09/17	50-261	P
	8107010141 8107070220	8210010008 8210010008	85\09\58 85\09\58	50-368 FOIA	8
	8107070220	8210010008	83/04/58	FOIA	
	8107160079	8210010008	85/06/28	50-260	6
	8107160386	821001000B	62/06/28	FOIA	
	8107170126 8107270161	8210080015 8107270154	82/07/12 81/07/17	FOIA 50~266	Q
	8107270166	8107270156	81/07/17	50-266	ă
	8107270169	8107270154	81/07/17	50~266	q
	8107270174	B107270154	81/07/17	50-266	G
	8107270178 8107270182	8107270156 8107270156	81/07/17 81/07/17	50-266 50-266	Q.
	8107270185	8107270156	01/07/17	50-244	ä
	8107270188	B107270156	81/07/17	50-266	a
	8107270191	8107270156	01/07/17	50-266	Q
	8107270194 8107270196	8107270156 8107270156	Ø1/07/17 Ø1/07/17	50-266 50-266	Gi Gi
	8107270198	8107270156	91/07/17	50-244	œ.
	8107270199	8107270156	81/07/17	50-266	G.
	8107300168 8108030041	8210010008 8210010008	82/06/28 82/06/28	50-324 FOIA	8

ACCESSION						N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DDCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8109180478 8109220915 8109240007 8109250504 8109280036	8210010008 8210010008 8210010008 8210010008	82/06/28 82/06/28 82/06/28 82/06/28 82/06/28	50-289 FOIA FOIA FOIA 50-312		8203120103 9203160383 8203170060 8203170016 8203190034	8210010008 8210010008 8210010008 8210040442 8210070007	62/04/28 62/06/28 62/06/28 62/08/24 62/08/10	50-331 S FOIA FOIA 50-537 A	
8109280175 8109280684 8110010072 8110050018 8110190928	8210010008 8210080020 8210010008 8210010008 8210010008	82/06/28 82/09/16 82/06/28 82/06/28	50-29 FOIA FDIA 50-369 FOIA	s	8203220512 8203220514 8203250320 8203240003 8203290028	8210060442 8210280013 8210010008 8210070007 8210080015	82/08/24 82/09/17 82/06/28 82/08/10 62/07/12	50-537 D 50-261 P FOIA FOIA 50-293 P	,
8110170733 8110220004 8110230085 8110270050 8110300440	8210010008 8210010008 8210010008 8210070007 8210070007	82/06/28 82/06/28 82/06/28 82/08/10 82/08/10	FOIA FOIA 50-219 50-244 50-246	8 P	8203270031 8203300270 8203310089 8203310094 8204010046	8210080015 8210010008 8210010008 8210010008	82/07/12 82/06/28 82/06/28 82/06/28 82/06/12	50-293 P F01A 50-311 P 50-311 P F01A	
8111030201 8111040084 8111040130 8111040062 8111140308	8210010008 8210010008 8210010008 8210070007 8210010008	82/06/28 82/06/28 82/06/28 82/06/28	F01A F01A F01A 50-246 F01A	S P	8204080171 8204060220 8204120487 8204140222 8204160222	8210010008 8210010008 8210080015 8204160212 8204160212	82/06/28 82/06/28 82/07/12 82/03/19 82/03/19	F01A F01A 50-281 5 50-293 0	1
8111180001 8111191042 8111240071 8111240912 8111270314	8210010008 8210010008 8210070007 8210010008 8210010008	82/06/28 82/06/28 82/08/10 82/06/28 82/06/28	50-338 50-206 50-266 FOIA 50-295	8 6 P 8	8204200390 8204200405 8204200408 8204200438 8204200442	8210040360 8210050430 8210270423 8210080015 8210080015	82/09/27 82/08/17 82/09/23 82/07/12 82/07/12	FOIA 70~1510 70~1510 50~289 P 50~289 P	
8111300367 8112010310 8112020725 8112020852 8112020885	821001000B 821001000B 821001000B 8210280013 8210280013	82/06/28 82/06/28 82/06/28 82/09/17 82/09/17	50-206 50-336 FOIA 50-261 50-324	9 8 P	8204210289 8204220144 820427044 8204290049 8204290237	8210010008 8210270423 8210010008 8210010008 8210080015	82/06/28 82/09/23 82/06/28 82/06/28 82/07/12	50-414 S 70-1510 FOIA 50-270 A 50-289 P	
8112030585 8112100374 8112210166 8112210193 8112210538	8210010008 8210010008 8210010008 8210010008 8210010008	82/06/28 82/06/28 82/06/28 82/06/28 82/06/28	FOIA FOIA FOIA FOIA 50-304	5	8204290408 820430094 8205030617 8205030617 8205050480	8210060442 8210270083 8210080015 8210080015 8210280013	82/08/24 82/09/20 82/07/12 82/07/12 82/09/17	50-537 D FOIA 50-247 S 50-247 S 50-261 P	;
81 12300287 8201050061 8201060003 8201060245 8201120280	8210280013 8210010008 8210010008 8210050430 8210280013	82/09/17 82/06/28 82/06/28 82/08/17 82/09/17	50-324 50-324 FOIA FOIA 50-324	P S	82050&0550 82050&0558 9205070377 8205130114 8205130114	8210120103 8210120103 8210080015 8210080015	82/07/12 82/07/12 82/06/28 82/07/12 82/09/17	F01A F01A F01A 50-293 P 50-324 P	
8201130322 8201150003 8201150004 8201150005 8201150087	8210010008 8210010008 8210010008 8210010008 8210060442	82/06/28 82/06/28 82/06/28 82/06/28 82/08/24	FOIA FOIA FOIA FOIA 50-537	D	8205180673 8205190428 8205190441 8205240006 8205240010	8210080015 8210080015 8210080015 8205240003 8205240003	82/07/12 82/07/12 82/07/12 82/05/05 82/05/05	50-281 S 50-327 S 50-327 S 40-8355 40-8355	3
9201150176 9201150180 9201170040 9201170041 9201170276	6210060442 6210010008 8210010008 6210010008 6210010008	82/08/24 82/06/28 82/06/28 82/06/28 82/06/28	50-537 50-206 FOIA FOIA FOIA	5	8205250010 8205250220 8205270507 8205270524 8205270524	8210270270 8210270270 8210040340 8210040340 8210080015	82/10/19 82/10/19 82/09/27 82/09/27 82/07/12	50-155 P 50-155 P FOIA FOIA FOIA	
9201190538 9201200653 9201200658 9201200662 9201210107	8210010008 8210010008 8210280013 8210280013 8210070007	82/06/28 82/06/28 82/09/17 82/09/17 82/08/10	50-346 50-255 50-261 50-261 FOIA	8 8 P	8205280497 8205280502 8205280503 8205280503 8206030044	8210080015 8210080015 8210080015 8210080015 8210040062	82/07/12 82/07/12 82/07/12 82/07/12 82/09/27	FDIA FDIA 50-287 0 50-287 P 50-206 P	•
					8206040401 820606013 820606015 8206070106 8206070106	8210080015 8206200097 8206200086 8210080015 8210070007	82/07/12 82/07/29 82/07/19 82/07/12 82/08/10	FOIA COMMISSION COMMISSION 50-245 & 50-244 P	1
					8206080467 8206110186 8206140329 8206160306 8206170006	8210060442 8210080015 8210080015 8208260424 8210180195	82/08/24 82/07/12 82/07/12 82/07/29 82/09/20	50-537 D 50-416 S 50-289 P 50-280 Q 50-312 P	,
					8206180042 8206210571 8206220591 8206230020 8206240119	8210190144 8210040414 8210280013 8210150382 8210270083	82/09/30 82/08/31 82/09/17 82/09/30 82/09/20	FOIA 50-265 P 50-324 P 50-245 P 50-251 S	3
					8206270016 8206270655 8206270666 8206300188 8206300370	8210260071 8210070007 8210080015 8210220233 8210260305	82/07/29 82/08/10 82/07/12 82/10/12 82/10/18	COMMISSION 50-244 P 50-289 P 50-155 Q TOPREP	,
					8207050005 8207050040 8207070324 8207070422 8207070428	8210010293 8210050506 8207070317 8207070419 8207070419	82/09/27 82/09/16 82/06/30 82/06/28 82/06/28	PR 50-289 P 70-2748 50-329 K 50-329 K	

ACCESSION					ACCESSION NV				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE DAUED	SUB JECT CATEGOR		FR	INCIPAL DOUMENT	DATE ISSUED	SUBJECT CATEGOR	
8207090208 8207090215 8207090224 8207120140 8207120253	8207090201 8207090201 8207090201 8210280013 8207120147	82/07/06 82/07/06 82/07/06 82/07/17 80/06/18	50-278 50-278 50-278 50-278 50-324 50-447	PPPA	8210010095 82 8210010096 82 8210010098 82 8210010099 82	10010008 10010075 10010094 10010008	92/06/28 92/09/15 92/09/21 92/06/28	50-346 50-335 50-346 50-366 50-259	900000
8207140138 8207140491 8207140494 8207140497 8207140500	8210040346 8210040366 8210040366 8210040366 8210040366	82/08/24 82/08/24 82/08/24 82/08/24 82/08/24	50-537 50-373 50-373 50-373 50-373	0000	8210010107 82 8210010109 82 8210010110 82	10010008 10010103 10010008 10010106 10010102	82/06/28 82/09/27 82/06/28 82/09/13 82/09/13	50-366 50-339 50-366 50-413 50-400	5 9 0 0
6207180073 6207180068 6207190431 6207230303 6207300222	8210220047 8210190118 6210120272 6207230301 6210050300	82/09/17 82/09/16 82/10/04 82/07/13 82/09/21	NUREG REVIEW G 50-29 50-339 50-206	RP 0 9 9	8210010118 82 8210010119 82 8210010122 82	10010108 10010113 10010006 10010120 10010117	82/09/24 82/09/07 82/06/28 82/08/31 82/09/02	50-327 50-321 F01A 50-83 50-269	9 0 0
8208010016 8208010019 8208020047 8208100269 8208110271	8210070440 8210220072 8210270083 6210120245 8210270270	82/09/14 82/09/20 82/09/20 82/09/30 82/10/19	50-289 ORG FOIA 50-29 50-155	H P P	8210010127 82 8210010128 82 8210010134 82	10010130 10010131 10010131 10010131	82/07/03 82/07/10 82/07/16 82/09/22 82/09/20	50-324 70-1201 50-311 50-413 50-327	0 5 0
6208170063 6208180062 6208190178 6208190290 6208250412	8210050300 8210200041 8210130205 8210180035 8210080036	82/09/21 82/10/12 82/10/05 82/09/27 82/08/13	50-206 50-155 50-213 50-302 FOIA	P P P	8210010139	10010132 10010131 10010127 10010131 10010131	82/09/01 82/09/22 82/09/27 82/09/22 82/09/22	50-324 50-413 50-348 50-413 50-413	0 8 0
H206250417 B208310034 B209130461 B209140027 B209140153	8210080036 8210280013 821022015 8210220105 8209140148	82/09/13 82/09/17 62/10/08 82/10/18 82/09/08	50~269 50~155 50~293 50~244 50~324	P P P F	8210010147 82 8210010150 82. 8210010151 82.	10010140 10010127 10010144 10010148 10010142	82/09/22 82/09/27 82/09/16 82/09/07 82/09/17	50-338 50-348 50-311 50-416 50-335	5 5 6
8209150106 8209150162 8209150436 8209150438 8209150440	8210280013 8210280013 8209150432 8209150432 8209150434	82/09/17 82/09/17 82/07/23 82/07/23 82/08/25	50~261 50~325 70~2946 70~2946 50~267	P P F	8210010161 82: 8210010165 82: 8210010166 83:	10010195 10010008 10010157 10010158 10010143	82/09/08 82/06/28 82/09/24 82/09/02 82/09/22	50-335 50-327 50-220 50-269 50-336	9 9 9
8209160311 8209160459 8209200475 8209210383 8209210413	8207160277 8210250071 8210040132 8210080001 8210180308	82/08/31 82/09/30 82/09/27 82/09/14 82/09/17	50-325 50-155 50-29 50-237 50-528	S P P A	8210010172 921 8210010174 921 8210010176 821	10010008 10010009 10010164 10010173 10010175	82/06/28 82/06/28 82/07/24 82/07/08 82/07/16	FD1A FD1A 50-335 50-261 50-313	S Q
8207210523 8207210527 8207210550 8207220137 8207270271	8209210514 8209210425 8210180214 8209220135 8209270242	82/09/01 82/08/20 82/09/17 82/09/13 82/09/24	50-309 50-251 50-508 50-382 50-358	P S A A H	9210010193 92 8210010196 92 8210010197 92	10010177 10010171 10010179 10010182 10010171	82/09/22 82/09/16 82/09/27 82/09/09 82/09/16	50-397 50-324 50-305 50-424 50-324	8 9 9 0
0207270377 8207270187 8207270225 8207270236 8207270240	8206200097 8209290125 8209290125 8209290168 8209290168	82/07/27 82/09/16 82/09/16 82/08/26 82/08/26	COMMISSI 50-10 50-10 FOIA FOIA	E F F	8210010173 B2 8210010174 B2 8210010177 B2	10010181 10010170 10010171 10010171 10010171	82/07/16 82/07/15 82/07/16 82/07/22 82/07/16	50-272 50-325 50-324 50-438 50-324	8 0 0 0
8209300175 8209300332 8209300336 8209300355 8210010022	8209300170 8209300326 8209300326 8209300353 8210010019	82/09/24 82/09/22 82/09/22 82/09/30 82/09/16	50-259 50-213 50-213 50-537 50-321	5 P B	8210010205 82 8210010205 82 8210010206 82	10010191 10010191 10010171 10010170	82/07/22 82/07/22 82/07/16 82/07/15 82/08/30	50-438 50-438 50-324 50-325 50-348	0 0 0
8210010024 8210010025 8210010029 8210010031 8210010041	8210010005 8210010017 8210010017 8210010017	82/07/07 82/09/14 82/09/16 82/09/16 82/09/24	71-481 50-321 50-321 50-321 50-263	а а а Р	6210010214 82 6210010215 82 6210010216 82	10010207 10010207 10010212 10010213	82/09/22 82/09/22 82/09/17 82/08/31 82/09/22	50-213 50-213 50-361 50-389 50-39	P P Q
8210010046 8210010047 8210010049 8210010061 8210010065	8210010034 8210010045 8210010044 8210010008 8210010008	82/09/24 82/09/16 82/09/22 82/06/28 82/06/28	50-263 50-311 50-302 FOIA FOIA	P S G	8210010224 82 6210010225 82 6210010229 82	10010212 10010217 10010221 10010212 10010233	82/09/17 82/09/24 82/08/31 82/09/17 82/09/22		
8210010047 8210010048 8210010073 8210010076 8210010078	8210010008 8210010008 8210010008 8210010008 8210010075	82/04/28 82/04/28 82/04/28 82/06/28 82/09/15	FOIA FOIA FOIA FOIA 50-335	a	6210010237	08240424 10010237 10010235 08240424 08070114			
8210010079 8210010081 8210010082 8210010083 8210010084	8210010064 8210010077 8210010064 8210010008 8210010075	82/09/29 82/09/24 82/09/29 82/06/28 82/09/15	50-537 50-219 50-537 50-321 50-335	G G G	8210010248	0B09011- 1001024: 4001027: 1001027: 10010275			
8210010085 8210010089 8210010089 8210010091 8210010092	8210010077 8210010075 8210010008 8210010086 8210010075	82/09/24 82/09/15 82/06/28 82/09/13 82/09/13	50~219 50~335 50~366 50~400 50~335	P G S O O	8210010295 82 8210010297 82 8210010303 82	10010275 10010287 1001028 1001029 1001029			

### TO PRINCIPAL DOCUMENTS

ACCESSION N	UMBER				ACCE8910	N NUMBER			
	RINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	
8210010305 8: 8210010314 8: 8210010317 8: 8210010321 8:	210010301 210010316 210010316 210010309	02/09/10 82/09/03 82/09/22 02/09/13 82/09/10	50-387 50-338 70-143 50-250 50-321	0 0 0	8210040075 8210040083 8210040088 821004018 8210040111	8210040073 8210040081 8210040086 8210040100 8210040107	82/09/22 82/10/01 82/09/24 82/09/22 82/09/29	50-315 50-155 50-297 50-293 50-313	8 C 8 S P
8210010338 8 8210010340 8 8210010341 8	210010316 21001033 21001033 210010336	02/09/13 02/09/13 02/09/16 02/09/17 02/09/13	50-250 50-250 50-324 50-390 50-250	0 0 0 0	8210040121 8210040122 8210040129 8210040134 8210040134	8210040116 8210040118 8210040126 8210040131 8210040132	82/09/24 82/09/24 82/09/16 82/09/15 82/09/27	50-304 50-387 50-249 50-373 50-29	9 8 8 8
8210010355 8 8210010340 8 8210010341 8 8210010343 8	210010336 210010344 210010349 210010353 210010358	82/09/16 82/09/16 82/09/22 82/09/10 82/09/10	50-324 30-311 50-400 70-27 State Pr	_	8210040144 8210040145 8210040150 6210040155 8210040157	8210040142 8210040141 8210040146 8210040148 8210040156	82/09/24 82/09/28 82/09/30 82/09/27 82/09/24	50-317 50-247 50-440 0A999 50~305	S S K
8210010368 8 8210010369 8 8210010371 8 8210010373 8	210010357 210010349 210010357 210010364 210010349	82/09/28 82/09/22 82/09/28 82/09/10 82/09/22	50-244 50-400 50-244 70-143 50-400	P G G	8210040162 8210040173 8210040178 8210040183 8210040183	8210040156 8210040171 8210040177 8210040182 8210040184	82/09/24 62/09/27 82/09/30 82/09/27 82/09/09	50-305 GA999 50-206 50-220 50-409	S Р Г
8210010385 83 8210010390 83 8210010394 83	210010380 210010376 210010383 210010389 210010349	92/09/13 92/09/22 92/09/23 92/09/23	50-404 50-336 50-272 50-409 50-400	9 9 9	8210040187 8210040189 8210040196 8210040203 8210040204	8210040184 8210040188 8210040192 8210040199 8210040202	82/09/20 82/09/15 82/09/27 82/09/24 82/09/10	50-285 50-237 69999 50-315 50-331	ន
8210010377 82 8210010402 83 8210010405 83	210010388 210010391 210010393 210010391 210010401	82/09/22 82/09/22 82/09/22 82/09/31	70~824 50~324 50~387 50~324 50~3	0 8 0 P	8210040205 8210040208 8210040209 8210040213 8210040217	8210040199 8210040202 8210040201 8210040206 8210040211	92/09/24 92/09/10 82/09/23 92/09/27 82/09/24	50~315 50~331 50~314 50~284 50~316	9 9 8 8
8210010412 82 8210010413 83 8210010414 83	210010401	82/09/22 82/09/14 82/09/17 82/09/31 82/09/22	50-324 50-311 50-275 50-3 50-324	0 9 P 0	8210040220 8210040223 8210040226 8210040228 8210040228	8210040215 8210040221 8210040216 8210040224 8210040232	82/09/27 82/09/24 82/09/23 82/09/24 82/09/27	50-45B 50-373 50-31B 50-352 50-269	К Р С Р
8210010423 82 8210010425 82 8210010426 83	210010417 210010401 210010411	82/09/22 82/09/14 82/08/31 82/09/22 82/09/23	50-518 50-311 50-3 50-518 40-1202	0 5 P 0	8210040246 8210040265 8210040274 8210040274 8210040279	8210040230 8210040261 8210040254 8210040258 8210040254	82/09/27 82/09/28 82/10/01 82/09/27 82/10/01	50-454 50-219 50-369 50-322 50-369	0 Р К О К
8210010431 82 8210010432 82 8210010433 82	210010411 210010430 210010411	82/09/17 82/09/22 82/09/03 82/09/22 82/09/23	50-438 50-518 50-259 50-518 40-1202	Q Q Q Q	8210040284 8210040285 8210040286 8210040288 8210040289	8210040281 8210040277 8210040254 8210040281 8210040277	82/09/28 82/09/27 82/10/01 82/09/28 82/09/27	50-244 50-338 50-367 50-244 50-238	ъ К Р
8210010438 82 8210010440 82 8210010443 82	210010401 210010418 210010401	82/09/08 82/08/31 82/09/23 82/08/31 82/09/03	50-369 50-3 40-1202 50-3 50-416	0 Р О	8210040297 8210040301 8210040303 8210040305 8210040307	8210040277 8210040277 8210040296 8210040292 8210040277	82/09/27 82/09/27 82/10/01 82/09/28 82/09/27	50-338 50-338 50-220 50-528 50-338	P F H P
82	210010401 210010451 210010456	82/09/31 82/09/08 82/09/22 32/09/16	50-3 50-369 50-341 50-311 50-390	P Q A Q	\$210040315 8210040319 8210040320 8210040325 8210040327	8210040277 8210040311 8210040277 8210040277 8210040321	82/09/27 82/09/29 82/09/27 82/09/27 82/09/22	50-338 TOPREP 50-338 50-338 50-316	P P S
			50-269 50-269 50-395 50-443	0 0 A 0	8210040329 8210040330 8210040332 8210040340 8210040340	8210040323 8210040321 8210040324 8210040333 8210040333	82/09/30 82/09/22 82/09/21 82/09/27 82/09/27	TOPREP 50-314 50-333 98979 98999	<b>6</b>
				9	8210040346 8210040349 8210040350 8210040351 8210040354	8210040343 8210040343 8210040343 8210040343 8210040345	82/08/20 82/08/20 82/08/20 82/08/20 82/09/10	50-537 50-537 50-537 50-537 50-282	A A A
					8210040355 8210040357 8210040361 8210040368 8210040368	8210040343 8210040343 8210040258 8210010008 8210010008	82/08/20 82/08/20 82/09/27 82/06/28 82/06/28	50-537 FOIA 50-322 50-366 FOIA	A Q S
					8210040371 8210040374 8210040375 8210040376 8210040379	8210010008 8210010008 8210040364 8210040369 8210010008	82/06/28 82/06/28 82/08/24 82/09/24 82/06/28	FOIA 50-320 50-373 50-331 FOIA	808
					8210040381 8210040383 8210040345 8210040347 8210040411	8210010008 8210010008 8210010008 8210040372 8210010008	82/06/28 82/06/28 82/06/28 82/09/07 82/06/28	FOIA FOIA FOIA 70-371 FOIA	

ACCESSIO	N NUMBER				ACCE891	ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO		ENCL OSURE	PRINCIPAL DOCUMENT	CATE ISSUED	SUBJEC	
8210040412 8210040416 8210040417 8210040418 8210040419	8210040410 8210010008 9210040415 8210040415 8210040415	82/09/15 82/06/28 82/09/15 82/09/15 82/09/15	CONTRACT FOIA 50-315 50-315 50-315		821005020 821005020 821005021 8210050213 8210050217	8210050202 8210010008 8210010008 8210050204	82/10/04 82/06/28 82/06/28 82/10/01 82/04/28		G
8210040420 8210040421 8210040425 8210040427 8210050006	8210040414 8210010008 8210040414 8210040414 8210010008	82/06/28 82/06/28 82/08/31 82/08/31	50-266 FOIA 50-266 50-266 FOIA	P P	8210050229 8210050231 8210050231 8210050234 6210050239	8210050223 8210050222 8210050227 8210050151 8210050224	82/09/28 82/09/20 82/09/22 82/09/22 82/09/16	50-329 50-266 50-237 50-361 50-267	0 8 8
8210050007 8210050010 8210050011 8210050012 8210050015	8210010008 8210010008 8210010008 8210050008 8210050013	82/06/28 82/06/28 82/06/28 82/09/24 82/09/16	F01A F01A F01A 50-361 F0E-07	4 33	8210050258 8210050264 8210050271 8210050276 8210050287	8210 050253 8210 050261 8210 050268 8210 050274 8210 050284	82/09/24 82/09/23 82/09/21 82/09/24 82/10/01	50-344 50-34! 75-05 50-315 98999	0 8 9 0
6210050018 6210050020 6210050020 6210050023	8210050013 8210050014 8210050017 8210010008 8210010008	82/09/16 82/09/24 79/03/16 82/06/28 82/06/28	50-309 50-361 REGGD FOIA 50-278	F 55	8210050290 8210050293 8210050295 8210050303 8210050307	8210050284 8210050284 8210050284 8210050301 8210050305	82/10/01 82/10/01 82/10/01 82/10/01 82/09/24	QA999 QA999 GA999 50~285 50~331	s
8210050024 8210050026 8210050027 8210050029 8210050030	8210050014 8210050017 8210010008 8210050014 8210050017	82/09/24 79/03/16 82/06/28 82/09/24 79/03/16	50–36  Regod 50~348 50–36  Regod	s s	8210050311 8210050313 8210050318 8210050321 8210050327	9210050309 9210050310 9210050310 9210050320 9210050323	82/09/29 82/09/30 82/09/30 82/09/28 82/09/22	50-331 50-346 50-346 50-277 50-346	9 P P B
8210050031 8210050032 8210050034 8210050035 8210050037	8210010008 8210050016 8210050017 8210010008 8210050016	82/06/28 82/09/24 79/03/16 82/06/28 82/09/24	FOIA 50-361 REGGD FOIA 50-361	s	82;0050334 82;0050337 8210050342 82;0050341 82(0050365	8210050332 8210050331 8210050334 8210050355 8210050359	82/09/30 82/09/23 82/09/24 82/09/24 82/09/15	50-35B 50-267 50-195 50-346 50-166	K 6 5 6
8210050038 8210050039 8210050041 8210050042 8210050044	8210010008 8210050017 8210050016 8210050017 8210050016	92/06/28 79/03/16 92/09/24 79/03/16 92/09/24	ROIA REGOD 70-36! REGOD 50-361	8	8210050371 8210050372 8210050378 8210050390 8210050390	82100503A2 82100503A6 8210050356 8210050357 8210050381	82/09/29 82/09/29 82/09/29 82/09/15 82/09/23	50-324 50-382 50-382 50-186 50-361	P 0 0 8
8210050048 8210050050 8210050056 8210050064 8210050068	8210050016 8210050016 8210050052 8210010008 8210050065	82/09/24 82/09/24 82/09/30 82/06/28 82/09/29	50-361 50-361 50-373 FOIA 50-409	23 23 49 49	8210050399 8210050403 8210050408 8210050409 8210050419	8210050387 8210010008 8210050398 8210010006 8210050416	82/09/20 82/06/28 82/09/23	50-458 FOIA 50-447 FOIA 50-389	Q A A
8210050070 8210050074 8210050075 8210050077 8210050078	8210050067 8210050071 8210010008 6210050073 8210050071	82/09/29 82/09/27 82/09/30 82/09/27	50-409 50-280 50-304 50-454 50-280	6 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	8210050424 8210050426 8210050427 8210050434 8210050436	8210010008 8210010008 8210050425 8210010008 8210010008	85/06/58 85/06/58 85/06/58 85/06/58	FOIA FOIA 50-155 FOIA FOIA	P
8210050082 8210050084 8210050085 8210050086 8210050087	8210010008 6210050080 6210050083 6210050061 6210010008	82/06/28 82/09/23 82/10/01 82/09/27 82/06/28	F01A 50~366 50~333 50~280 F01A	S F S	8210050439 8210050446 8210050456 8210050456 8210050467	6210050430 6210050430 6210050430 6210050430 8210050430	82/08/17 82/08/17 82/08/17 82/08/17 82/08/17	FOIA 70~1510 70~1510 70~1510 FOIA	
8510020101 8510020048 8510020043 8510020045 8510020041	8210050081 8210050081 8210010008 8210050076 8210050076	82/09/27 82/09/27 82/06/28 82/09/24 82/09/24	50-280 50-280 F01A 50-361 50-361	55 55	6210050471 6210050473 6210050478 6210050481 6210050490	8210050430 8210010008 8210010008 8210010008 8210050485	82/08/17 82/06/28 82/06/28 82/06/28 82/09/20	FOIA FOIA FOIA FOIA 80-272	P
8210050116 8210050119 8210050119 8210050112	8210010008 8210050103 8210050102 8210050105	82/07/09 82/09/24 82/09/30 82/07/09 82/06/28	50~295 50~280 50~305 50~295 F01A	0 6 0	8210050493 8210050495 8210050496 8210050500 8210050503	821001000B 8210030491 821001000B 821001000B 821001000B	82/06/28 82/09/14 82/06/28 82/06/28		
8210050124 8210050135 8210050146 8210050154 8210050155	8210010008 8210010008 8210050137 8210050137 8210010008	85/04/58 85/04/55 85/04/58 85/04/58	50-3(1 FOIA 50-329 50-329 FOIA	9 0 0	8210050505 8210050508 8210050507 8210050514 8210030518	8210050497 8210050501 8210050497 6210010006 8210050512			
8210050160 8210050161 8210050164 8210050168 8210050181	8210050157 8210010008 8210010008 8210050165 8210010008	82/09/29 82/06/28 82/06/28 82/09/29 82/06/28	50-315 50-320 F01A 50-334 F01A	р 8 Р	8210050520 8210080521 8210050522 8210050528 8210050530	6210010008 6210050516 6210050512 6210050506 6210050525			
8210050185 8210050187 8210050190 8210050191 8210050194	8210050183 8210050179 8210050188 8210050188	82/09/30 82/09/24 82/06/28 82/10/01 82/09/15	50-461 50-336 FOIA QA999 50-266	K P G	8210050533 6210050534 6210050539 6210050541 6210050542	8210010008 8210050504 8210050538 8210050538			
8210050198 8210050200 8210050203 8210050205 8210050204	8210050195 8210010008 8210050193 8210050186 8210050199	82/10/01 82/04/28 82/09/28 82/09/15 82/09/30	0A999 F01A 50~416 50~246 50~443	S Q A	8210050543 8210050544 8210050546 6210050548 8210050567	B210050540 B210050538 B210050540 B210050540 B210050559			

# TO PRINCIPAL DOCUMENTS

ACCE8910	NUMBER				ACCES810N				
ENCLOBURE	PRINCIPAL DOCUMENT	DATE ISBUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISBUED	SUBJECT	
8210050573 8210060001 8210060005 8210060008 8210060009	8210190079 8210010008 8210010008 8210010008 8210010008	82/10/01 82/06/28 82/06/28 82/06/28	FOIA FOIA FOIA FOIA FOIA		8210060345 8210060348 8210060352 8210060354 8210060356	8210060341 8210060342 8210060347 8210060349 8210060351	82/07/23 82/10/01 82/10/01 82/10/04 82/09/28	50-528 50-289 50-327 50-261 70-25	0 P F
8210040014 8210040026 8210040030 8210040041 8210040042	8210040013 8210010008 8210040023 8210040024 8210010008	82/10/01 82/06/28 82/09/24 82/09/17 82/06/28	50-261 FOIA 50-293 50-247 FOIA	P S G	8210040343 8210040347 8210040369 8210040370 8210040372	8210010008 8210060359 8210010008 8210060365 8210060361	82/04/28 82/10/01 82/04/28 82/09/28 82/09/30	F01A 50-237 F01A 70-1100 50-280	Q S
8210060046 8210060047 8210060068 8210060077 8210060081	8210060024 8210060034 8210010008 8210010008 8210060076	82/09/17 82/09/27 82/06/28 82/06/28 82/09/23	50-247 50-29 FOIA FOIA 50-334	e a R	8210040380 8210040381 8210040384 8210040384 8210040390	8210060377 8210010008 8210060379 8210060377 8210060385	82/07/30 82/06/28 82/07/21 82/07/30 82/07/27	50-263 FDIA 50-373 50-263 50-317	р 0. Р 5
8210040082 8210040083 8210040084 8210040085 8210040096	8210010008 8210040074 8210010008 8210040080 8210040088	82/06/28 82/09/24 82/06/28 82/09/30 82/09/28	50-296 50-277 FOIA 50-293 50-334	8 8 P R	8210060373 8210060374 8210060378 8210060400 8210060405	8210060387 8210060385 8210060361 8210060376 8210060375	82/09/22 82/09/27 82/09/30 82/09/24 82/09/27	50-315 50-317 50-280 50-247 50-254	9 8 8 8 8
8210060100 8210060104 8210060119 8210060124 8210060127	8210010008 8210040079 8210040117 8210040109 8210040079	82/04/28 82/09/17 82/09/30 82/09/14 82/09/17	FOIA 50-317 50-361 50-362 50-317	о Р О О	8210040411 8210040412 8210040415 8210040422 8210040424	8210060406 8210060409 8210060406 8210060414 8210060420	82/09/20 82/09/30 82/09/30	FOIA 50-259 FOIA 50-259 CONTRACT	8 S
8210060131 8210060141 8210060147 8210060148 8210060157	8210060126 8210060133 8210060138 8210060145 8210060155	82/09/15 82/09/17 82/09/30 82/09/15 82/09/24	50-228 50-275 70-398 50-247 50-508	0 0 F	8210040427 8210040429 8210040430 8210040432 8210040433	8210010008 8210040424 8210010008 8210010008 8210060431	82/06/28 82/09/29 82/06/28 82/06/28 82/09/23	FOIA FOIA 50-336 50-334 50-272	ទ ទ F
8210060163 8210060173 8210060173 8210060180 8210060203	8210060155 8210060171 8210060171 8210060201	82/09/24 82/09/30 82/09/29 82/09/30 82/09/29	50-508 50-293 50-309 50-293 50-416	0 0 р 0 Б	8210040447 8210040449 8210040451 8210040452 8210040453	8210060442 8210010000 8210060442 8210010008 8210060442	82/08/24 82/06/28 82/08/24 82/06/28 82/08/24	50-537 F01A 50-537 F01A S0-537	D A A
8210060206 8210060208 8210060212 8210060214 8210060215	8210060174 8210060207 8210060207 8210060174 8210060211	82/09/30 82/09/29 82/10/01 82/09/30 82/09/17	50-443 50-220 50-25! 50-443 50-412	0 8 8 0	8210060455 8210060458 8210060460 8210070005 8210070006	8210060442 8210060442 8210010008 8210070003 8210070003	82/08/24 82/08/24 82/06/28 82/09/17 82/09/17	50-537 50-537 50-320 50-346 50-346	A D S F F
8210060216 8210060221 8210060226 8210060227 8210060230	8210060213 8210060219 8210060225 8210060228	82/10/01 82/07/30 82/07/30 82/07/30	50-255 50-327 50-416 70-7 50-289	8 \$ 8 F	8210070008 8210070014 8210070018 8210070021 8210070030	8210010008 8210070013 8210070013 8210070017 8210070007	82/06/28 82/07/29 82/07/29 82/07/20 82/08/10	FOIA 50-155 50-155 CONTRACT 50-244	P P
8210040238 8210040241 8210040243 8210040247 8210040248	8210060237 8210060239 8210060240 8210060245 8210060246	82/09/24 82/09/30 82/09/29 82/10/01 82/09/23	50-336 50-155 50-317 50-528 50-366	P P G A B	8210070032 8210070035 8210070037 8210070038 8210070039	8210070028 8210070028 8210070029 8210070007 8210070029	82/09/14 82/09/14 82/07/16 82/08/10 82/07/16	50-289 50-289 50-537 50-244 50-537	G D G A
6210060252 6210060254 6210060256 6210060257 6210060259	8210040251 8210040253 8210040253 8210040255 8210040255	82/09/20 82/10/04 82/10/04 82/10/01 82/10/01	50-373 50-315 50-315 TOPREP TOPREP	8 Q	8210070043 8210070044 8210070045 8210070047 8210070048	0210070029 8210070040 0210070042 8210070029 8210070040	82/07/16 82/09/17 82/09/10 82/07/16 82/09/17	50-537 50-416 50-373 50-537 50~416	D F H D F
					8210070050 8210070051 8210070053 8210070055 8210070056	8210070029 8210070042 8210070029 8210070042 8210070029	82/07/16 82/07/10 82/07/16 82/07/10 82/07/16	50-537 50-373 50-537 50-373 50-537	D H D M
					8210070058 8210070059 8210070060 8210070061 8210070064	8210070029 8210070054 8210070054 8210070042 8210070029	82/07/16 82/07/18 82/07/15 82/07/10 82/07/16	50-537 50-309 50-309 50-373 50-537	р Р Н В
					8210070066 8210070067 8210070068 8210070070 8210070071	8210070042 8210070029 8210070007 8210070029 8210070029	82/07/10 82/07/16 82/08/10 82/07/16 82/07/16	50-373 50-537 50-244 50-537 50-537	H P A A
					8210070073 8210070076 8210070080 8210070083 8210070084	8210070007 8210070007 8210070007 8210070007 8210070007	82/08/10 82/08/10 82/08/10 82/08/10 82/07/14	50-244 50-244 50-244 50-244 50-537	የ የ የ የ
					8210070086 8210070087 8210070089 8210070090 8210070091	8210070029 8210070007 8210070029 8210070007 8210070085	82/07/16 82/08/10 82/07/16 82/08/10 82/10/04	50-537 50-244 50-537 50-244 50-29	A P A P

ACCESSION	NUMBER				ACCESS1	ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISBUED	SUBJECT	
8210070093 8210070094 8210070095 8210070098 8210070099	8210070029 8210070085 8210070029 8210070029 8210070085	82/07/16 82/10/04 82/07/16 82/07/16 82/10/04	50-537 50-29 50-537 50-537 50-29	A P A P	8210070269 8210070270 8210070273 8210070273 8210070275	8210070029 8210070268 8210070029 8210070268 8210070029	82/07/16 82/09/22 82/07/16 82/09/22 82/07/16	50-537 50-219 50-337 50-219 50-537	F Q A Q
8210070101 8210070103 8210070112 8210070117 8210070118	8210070029 8210070029 8210070109 8210070106 8210070029	82/07/16 82/07/16 82/09/29 82/09/20 82/07/16	50-537 50-537 50-445 50-317 50-537	D A F A	8210070280 8210070282 8210070283 8210070283 8210070284	8210070027 8210070027 8210070277 8210070027 8210070277	82/07/16 82/07/16 82/09/22 82/07/16 82/10/04	50-537 50-537 50-293 50-537 50-315	C A A A
8210070119 8210070121 8210070123 8210070125 8210070124	8210070029 8210070007 8210070029 8210070106 8210070029	82/07/16 82/08/10 82/07/16 82/07/16 82/07/16	50-537 50-244 50-537 50-317 50-537	0 0 0 0	8210070287 8210070291 8210070293 8210070294 8210070298	B210070278 B210070027 B210070027 B210070290 B210070029	82/10/04 82/07/16 82/07/16 82/10/04 82/07/16	50-312 50-537 50-537 50-312 50-537	G C A Q A
8210070128 8210070129 8210070130 8210070131 8210070134	8210070029 8210070127 8210070106 8210070029 8210070029	82/07/16 82/10/05 82/09/20 82/07/16 82/07/16	50-537 50-454 50-317 50-537 50-537	0 0 0 0	8210070301 8210070302 8210070304 8210070308 8210070310	8210070029 8210070299 8210070029 8210070296 8210070029	82/07/16 82/10/04 82/07/16 82/07/16 82/07/16	50-537 50-397 50-537 50-278 50-537	A Q A Q A
8210070135 8210070138 8210070139 8210070142 8210070144	8210070007 8210070029 8210070007 8210070029 8210070141	82/08/10 82/07/14 82/08/10 82/07/14 82/07/15	50-244 50-537 50-29 50-537 50-397	P C G C A	8210070312 8210070313 8210070314 8210070315 8210070316	8210070307 8210070029 8210070305 8210070029 8210070307	82/09/24 82/07/16 82/09/22 82/07/16 82/09/24	70-344 50-537 50-272 50-537 70-344	D 5 D
8210070146 8210070148 8210070151 8210070154 8210070156	8210070029 920070029 9200700158 920070029 821070029	82/07/16 82/07/16 82/07/16 82/07/16 82/08/13	50-537 50-537 50-537 50-537 CONTRAC	C F A F	821007031B 8210070323 8210070323 8210070323 8210070330	8210070029 8210070017 8210070029 8210070029 8210070317	82/07/16 82/09/22 82/07/16 82/07/16 82/09/22	50-537 50-277 50-537 50-537 50-277	D D D
8210070157 6210070161 8210070163 8210070165 8210070166	8210070029 8210070029 8210070029 8210070007 8210070029	82/07/14 82/10/04 82/07/16 82/08/10 82/07/14	50-537 50-508 50-537 50-244 50-537	A G A P D	8210070331 8210070332 8210070333 8210070335 8210070342	8210070319 8210070029 8210070324 8210070029 8210070337	62/10/04 62/07/16 62/10/05 62/07/16 62/07/22	50-312 50-537 50-285 80-537 50-220	G D G D
8210070170 8210070172 8210070174 8210070179 8210070181	8210070029 8210070007 8210070029 8210070029 8210070178	82/07/16 82/08/10 82/07/16 82/07/16 82/09/24	50-537 50-249 50-537 50-537 50-219	C G C A S	8210070345 9210070346 8210070347 821007035 821007035	8210070341 8210070340 8210070029 8210070337 8210070348	82/09/24 82/09/29 82/07/16 82/09/22 82/10/04	50-219 50-293 50-537 50-220 50-438	9 8 0 4
8210070182 8210070185 8210070184 8210070187 8210070188	8210070029 8210070007 8210070029 8210070007 8210070177	82/07/14 82/08/10 82/07/14 82/08/10 82/09/29	50-537 50-266 50-537 50-266 50-277	A P D P O	8210070354 8210070358 8210070359 8210070364 8210070364	8210070352 8210070348 8210070351 8210070348 8210070361	62/10/05 62/10/04 62/09/22 62/10/04 62/09/27	50-245 50-438 50-311 50-438 50-247	Q А В А
8210070190 8210070191 8210070193 8210070195 8210070196	8210070029 8210070007 8210070189 8210070029 8210070007	82/07/16 82/08/10 82/07/16 82/07/16 82/08/10	50-537 50-266 50-522 50-537 FOIA	D P C C	8210070367 8210070369 8210070378 8210070377 8210070378	8210070362 8210070364 8210070368 8210070371 8210070357	82/10/04 82/09/22 82/09/22 82/09/22 82/09/20	50-333 50-445 50-272 50-311 50-309	0 0 5 8
6210070198 6210070200 8210070202 8210070205 8210070206	8210070007 8210070029 8210070029 8210070007 8210070029	B2/08/10 B2/07/14 B2/07/16 B2/08/10 B2/07/16	FOIA 50-537 50-537 50-246 50-537	С В Р С	6210070385 9210070397 9210070386 8210070393 6210070394	8210070363 8210070378 8210070380 8210070376 8210070383	92/08/13 82/10/04 82/09/22 82/09/24 82/09/13	40-6422 50-460 50-272 50-271 40-6622	G 8 Q
8210070207 8210070208 8210070216 8210070217 8210070218	8210070029 8210070007 8210070214 8210070007 8210070007	82/07/16 82/08/10 82/09/23 82/08/10 82/08/10	50-537 50-266 50-286 50-266 50-266	D Р О Р	8210070400 8210070410 8210070413 8210070418 8210070421	8210070392 8210070407 8210070409 8210070411 8210070411	82/09/22 82/08/18 82/08/18 82/09/10 82/09/10	50~443 71~9150 71~9150 FOIA FOIA	a
8210070222 8210070223 8210070225 8210070228 8210070231	8210070029 8210070029 8210070029 8210070007 8210070221	82/07/16 82/07/16 82/07/16 82/08/10 82/09/22	50-537 50-537 50-537 50-246 50-311	A D A G	8210070423 8210070426 8210070428 8210070431 8210070434	8210070417 8210070411 8210070411 8210070411 8210070411	82/09/29 82/09/10 82/09/10 82/09/10 82/09/10	FOIA FOIA FOIA FOIA	
8210070235 8210070240 8210070241 8210070247 8210070248	8210070007 8210070239 8210070238 8210070245 8210070246	82/08/10 82/09/22 82/09/27 82/09/29 82/09/22	FOIA 70-33 50-219 50-293 50-311	S	6210070436 8210070441 8210070445 8210070447 821007044	8210070411 8210070411 8210070411 8210070411 8210070411	82/09/10 82/09/10 82/09/10 82/09/10 82/09/10	FDIA FOIA FOIA FDIA FOIA	
8210070251 8210070252 8210070253 8210070256 8210070256	8210070029 8210070249 8210070029 8210070029 8210070254	82/07/16 82/09/22 82/07/16 82/07/16 82/09/22	50-537 50-311 50-537 50-537 50-311	A A A B	8210070451 8210070454 8210070458 8210070459 8210070454	8210070411 8210070411 8210070411 8210070456 8210070411	B2/09/10 B2/09/10 B2/09/10 B2/09/17 B2/09/10	FOIA FOIA FOIA CONTRACT FOIA	
8210070259 8210070260 8210070262 8210070264 8210070266	8210070029 8210070029 8210070029 8210070029 8210070029	82/07/16 82/07/16 82/07/16 82/07/16 82/07/16	50-537 50-537 50-537 50-537 50-537	ACCFA	8210070465 8210070467 8210070468 8210070471 8210070473	8210070029 8210070411 8210070411 8210070411 8210070411	82/07/16 82/07/10 82/07/10 82/07/10 82/07/10	50-537 FOIA FOIA FOIA FOIA	D

## TO PRINCIPAL DOCUMENTS

ACCESSION					ACCESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE DAUED	SUBJECT CATEGOR	·	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1980ED	SUBJECT CATEGORY	
6210070475 6210070478 6210070480 6210070482 9210070484	8210070411 8210070411 8210070411 8210070411 8210070411	82/09/10 82/09/10 82/09/10 82/09/10 82/09/10	FOIA FOIA FOIA FOIA FOIA		8210080214 8210080215 8210080216 8210080217 8210080228	8210080212 8210080015 8210080015 8210080015 8210080227	82/10/04 82/07/12 82/07/12 82/07/12 82/10/04	FOIA FOIA FOIA	a a
8210070485 8210070486 8210070488 8210070489 8210080002	8210070411 8210070411 8210070411 8210070411 8210080001	82/09/10 82/09/10 82/09/10 82/09/10 82/09/14	FOIA FOIA FOIA FOIA 50~237	þ	8210080230 8210080232 8210080237 8210080240 8210080250	8210080221 8210080225 8210080225 8210080234 8210080248	82/09/29 82/08/25 82/08/25 82/09/28 82/10/06	71-91 <i>6</i> 7 71-91 <i>6</i> 7 50-366	5 9 0
8210080005 8210080022 8210080030 8210080030	8210080029 8210080029 8210080029	82/09/10 62/09/21 82/09/22 82/09/22	XPORTLIC CONTRACT CONTRACT 50-295 50-295	F F	8210080253 8210080254 8210080257 8210080258 8210080259	6210080249 6210080248 6210080252 8210080254 6210080248	82/10/05 82/10/06 82/10/01 82/09/27 82/10/06	50~395 50-250 50-267	0 0 5 0 0
8210080032 8210080034 8210080035 8210080038 8210080040	8210080020 8210080033 8210080036 8210080037	82/09/16 82/09/14 82/09/09 82/08/13 82/09/08	FOIA FOIA XPORTLIC FOIA XPORTLIC		8210080284 8210080281 8210080288 8210080288	8210080240 8210080277 8210080282 8210080285 8210080284	82/09/30 82/10/04 82/10/04 82/10/04 82/10/05	50-416 50-416 50-346	***
8210080042 8210080044 8210080047 8210080051 8210080054	8210080037 8210080036 8210080036 8210080015 8210080015	82/07/12 82/08/13 82/08/13 82/08/13	XPORTLIC 50-269 50-287 50-289 FOIA	P P O	8210080297 8210080298 8210080299 8210080311 8210080320	8210080294 8210080295 8210080293 8210080302 8210080319	82/06/22 82/10/05 82/10/05 82/10/05 82/09/09	10PREP 50-416 70-2789 70-754 XPORTL2C	S
9210090055 8210080057 8210080064 8210080079 8210080080	8210080053 8210080015 8210080015 8210080063 8210080078	82/09/23 82/07/12 82/07/12 82/09/29 82/10/05	50-537 FOIA 50-317 50-219 50-275	D P P P	8210080323 8210080331 8210120018 8210120021 8210120023	8210080321 8210080327 8210120015 8210120015 8210120015	82/09/15 82/09/16 82/08/20 82/08/20 82/08/20	XPORTLIC XPORTLIC FOIA FOIA FOIA	
8210080085 8210080096 8210080100 8210080100 8210080101	8210080015 8210080015 8210080015 8210080095 8210080015	82/07/12 82/07/12 82/07/12 82/09/28 82/07/12	50-244 50-289 50-289 50-397 FOJA	ਬ P P K	8210120027 8210120030 8210120050 8210120053 8210120055	8210120015 8210120015 8210120047 8210120049 8210120015	82/08/20 82/08/20 82/10/04 82/09/23 82/08/20	FOIA FOIA 50-346 REVIEW CR FOIA	P <b>??</b>
8210080102 8210080106 8210080112 8210080114 8210080118	8210080078 8210080015 8210080015 8210080015 8210080015	82/09/30 82/07/12 82/07/12 82/07/12 82/07/12	50-29 FOIA 50-313 50-334 50-259	ዎ G G	8210120057 8210120062 8210120066 8210120068 8210120073	8210120015 8210120015 8210120015 8210120015 8210120058	82/08/20 82/08/20 82/08/20 82/08/20 82/09/24	FOIA FOIA FOIA FOIA 50-382	Q.
8210080125 8210080125 8210080127 8210080128 8210080132	8210080015 8210080015 8210080120 8210080015 8210080127	82/07/12 82/07/12 82/10/04 82/07/12 82/09/22	50-324 50-302 50-416 50-346 50-315	Q Q B Q F	8210120075 8210120112 8210120123 8210120132 8210120139	8210120015 8210120103 8210120103 8210120103 8210120134	82/08/20 82/07/12 82/07/12 82/07/12 82/09/27	50-400	Q Q F
0940000	j	82/07/12 82/09/22 82/07/12 82/07/12	50-333 50-315 50-247 50-220 50-219	Q F Q Q Q	8210120140 8210120143 8210120150 8210120151 8210120161	8210120103 8210120103 8210120146 8210120103 8210120103	82/07/12 82/07/12 82/10/01 82/07/12 82/07/12	50-537 71-6347	A A P
			10-255 10-293 10-387 10-312	g g p g	8210120164 8210120166 8210120170 8210120174 8210120176	8210120155 6210120158 6210120103 6210120169 6210120103	80/12/18 82/09/30 82/07/12 82/10/01 82/07/12	50-293 71-9001 FOIA 71-9034 FOIA	5
					8210120181 8210120188 8210120192 8210120196	8210120103 8210120103 8210120180 8210120103 8210120194	82/07/12 82/07/12 82/10/01 82/07/12 82/10/06	FOIA 50-3 71-6703 FOIA 50-508	P
					8210120202 8210120225 8210120233 8210120243 8210120247	8210120103 8210120215 8210120222 8210120240 8210120241	82/07/12 82/10/01 82/09/15 82/10/04 82/10/06	0A999 50~333	P R Q
					8210120250 8210120252 8210120281 8210120283 8210120285	8210120248 8210120246 8210120276 8210120278 8210120280	82/10/04 82/10/01 82/10/05 82/10/01 82/10/06	50-395 50-313 50-329 50-275 0A999	P
					8210120286 8210120289 8210120293 8210120299 8210120300	8210120278 8210120284 8210120280 8210120291 8210120296	82/10/01 82/09/27 82/10/06 82/10/08 82/10/04	50-275 50-327 GA999 50-259 50-213	P 0 P
					8210120304 8210120305 8210120306 8210120306 8210120312	8210120301 8210120297 8210120291 8210120301 8210120311	92/10/05 92/10/04 92/10/08 92/10/05 92/09/15	0A777 50-280 50-239 GA777 GA777	P O

ACCESSIO	N NUMBER				N NUMBER			
ENCLOSURE	PRINCIPAL DDCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSVED	SUBJEC CATEGO	
8210120315 8210120314 8210120317 8210120319 8210120329	8210120301 8210120291 8210120311 8210120311 8210120325	82/10/05 82/10/08 82/09/15 82/09/15 82/09/20	QA999 50-259 G QA999 QA999 Waste Mgt	8210130173 8210130176 8210130177 8210130201 8210130208	8210130189 8210130192 8210130195 8210130197 8210130204	62/10/08 82/10/01 62/10/01 82/09/28 62/10/04	50-271 50-254 50-244 50-249 50-280	R 8 8 8 8 8
8210120330 8210120331 8210120335 8210120336 8210120340	8210120321 8210120326 8209280426 8210120334 8210120339	82/09/15 82/10/06 82/09/20 82/09/24 82/10/01	CONTRACT REVIEW GRP GEN TEC IS 71-9010 71-9037	8210130210 8210130213 8210130214 8210130215 8210130216	8210130204 8210130204 8210130212 8210130200 8210130204	82/09/30 82/10/04 82/09/30 82/10/07 82/10/04	50-289 50-280 50-313 50-373 50-260	e S R S
8210120342 8210120350 8210120352 8210120353 8210120357	8210120338 8210120347 8210120349 B210120351 8210120354	82/09/22 82/09/29 82/09/24 82/08/30 82/09/28	CONTRACT CONTRACT 71-9964 WASTE MOT CONTRACT	8210130222 8210130223 8210130225 8210130227 8210130232	8210 130221 8210 130220 8210 130219 8210 130219 8210 130228	82/09/21 82/09/30 82/10/01 82/09/29 82/10/01	50-544 50-364 50-29 50-311 50-336	0 8 8 8
8210120362 8210120364 8210120366 8210120384 8210120386	8210120361 8210120363 8210120365 8210120381 8210120379	82/10/05 82/09/20 82/09/16 82/09/13 82/08/20	CONTRACT CONTRACT CONTRACT 71-5908 WASTE MOT	8210130235 8210130234 8210130244 8210130250 8210130253	8210130230 8210130234 8210130242 8210130249 8210130251	82/07/30 82/07/30 82/10/08 82/10/07 82/07/30	50~29 50~373 50~261 50~537 50~254	8 R A 8
8210120399 8210120401 8210120419 8210120422 8210120423	8210120392 8210120391 8210120411 8210120417 8210120416	82/09/24 82/09/30 82/09/28 82/09/27 82/10/08	50-331 F CONTRACT 27-39 CONTRACT 50-389 M	8210130254 8210130258 8210130263 8210130266 8210130267	8210130252 8210130256 8210130262 8210130264 8210130264	82/10/07 82/05/28 82/10/07 82/10/07 82/10/07	50-309 50-321 50-349 50-329 50-329	Р К К К
8210120425 8210120432 8210120440 8210120458 8210120471	8210120414 8210120427 8210120436 8210120454 8210120467	82/09/30 82/09/29 82/09/27 82/09/22 82/09/24	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	8210130274 8210130285 8210130286 8210130287 8210130276	8210130269 8210130278 8210130293 8210130257 8210130291	82/09/27 82/09/30 82/10/07 82/10/06 82/10/06	50-341 50-341 50-309 50-389 50-277	8 8 P E G
8210120480 8210120487 8210120488 8210120492 8210120496	8210120475 8210120475 8210120483 8210120475 8210120470	82/07/30 82/07/30 82/07/29 82/07/30 82/07/27	50-62 P 50-62 P CONTRACT 50-62 P CONTRACT	8210130297 8210130306 8210130309 8210130315 8210130319	8210130294 8210130302 8210130303 8210130311 8210130310	82/10/07 82/09/29 82/10/06 82/10/07 82/10/01	50-358 50-54 70-135 50-537 50-302	A P A S
8210120508 8210120517 8210120541 8210120550 8210120551	8210120497 8210120510 8210120534 8210120540 8210120546	82/09/10 82/09/30 82/09/30 82/09/27 82/09/24	CONTRACT CONTRACT CONTRACT CONTRACT 50-254 F	8210130328 8210130337 8210130342 8210130345 8210130349	8210130324 8210130335 8210130338 8210130340 8210130344	82/09/28 82/10/07 82/09/29 82/09/29 82/10/04	50-254 50-247 50-317 50-311 50-267	8 9 8 8
8210120556 8210120560 8210120565 8210120590 8210120604	8210120549 8210120557 8210120557 8210120584 8210120591	82/09/30 82/09/17 82/09/17 82/09/15 82/09/10	CONTRACT 50-315 P 50-315 P 50-298 P 40-8745	8210130350 8210130358 8210130361 8210130362 8210130366	8210130347 8210130351 8210130352 8210130353 8210130354	82/10/06 82/07/27 82/10/01 82/07/30 82/07/28	50-220 50-311 50-387 50-29 50-346	8 8 9 8
8210120613 8210120624 8210120636 8210120640 8210120642	8210120407 8210120419 8210120427 8210120427 8210120427	82/09/27 82/09/20 82/09/23 82/09/23 82/09/23	CONTRACT 40~8781 50~341 A 50~341 A 50~341 A	8210130369 8210130371 8210130374 8210130368 8210130369	8210130360 8210130363 8210130368 8210130382 8210130377	82/10/07 82/10/01 82/09/27 82/09/30 62/10/01	50-309 50-387 50-341 50-313 50-387	P 5 0 5 5
6210120645 6210120647 6210130005 6210130007 6210130014	8210120643 8210120643 8210130004 8210130004 8210130008	82/09/24 82/09/24 82/09/23 82/09/23 82/09/22	50-261 F 50-261 F 50-329 F 50-329 F CONTRACT	8210130370 8210130378 8210130403 8210130408 8210130410	8210130386 8210130373 8210130400 8210130400 8210130404	82/10/01 82/10/01 82/09/24 82/09/24 82/09/29	50-254 50-331 50-409 50-409 50-346	R = 0 0 S
8210130029 8210130038 8210130043 8210130054 8210130061	8210130024 8210130024 8210130024 8210130052 8210130058	82/09/20 82/09/20 82/09/20 82/09/23 82/09/28	50-416 P 50-416 P 50-416 P CONTRACT CONTRACT	8210130414 8210130416 8210130419 8210130423 8210130423	8210130406 8210130400 8210130411 8210130413 8210130415	82/07/28 82/07/24 82/07/28 82/07/27 82/10/06	50-366 50-409 50-247 50-254 50-460	8 9 8 9
8210130074 8210130080 8210130087 8210130103 8210130104	8210130071 8210130078 8210130075 8210130099 8210130101	82/09/28 82/09/17 82/09/28 82/10/06 82/09/28	CONTRACT XPORTLIC 50-289 T 50-317 Q 50-395 T	8210130426 8210130431 8210130432 8210130438 8210130449	8210130420 8210130427 8210130415 8210130429 8210130441	82/09/30 82/09/21 82/10/06 82/10/07 82/10/05	50-22 50-280 50-460 50-259 XPORTLIC	R G G S
8210130112 8210130114 8210130128 8210130192 8210130137	8210130105 8210130105 8210130124 8210130129 8210130133	82/09/28 82/09/28 82/09/30 82/10/07 82/10/01	50-338 F 50-338 F 50-346 S 50-321 R 50-331 8	8230130452 8210130457 8210130459 8210130462 8210130465	6210130442 8210130448 8210130451 8210130456 8210130461	82/10/05 82/10/04 82/10/05 82/10/06 82/09/30	50-327 50-155 50-461 50-335 50-317	6 9 8
8210130145 8210130156 8210130162 8210130163 8210130169	821013013B 8210130146 8210130157 8210130160 8210130165	82/10/08 82/09/30 82/10/07 82/09/30 82/10/07	50-255 R 50-255 S 50-296 S 50-184 R 50-259 S	8210130471 8210130473 8210130478 8210130479 8210130483	8210130448 8210130466 8210130469 8210130472 8210130477	82/10/06 82/09/30 82/10/01 82/09/30 82/10/04	50-155 50-254 50-341 50-293 50-325	8 8 8 0
8210130170 8210130174 8210130180 8210130184 8210130185	8210130164 8210130172 8210130177 8210130181 8210130183	82/09/29 82/10/07 82/10/01 82/10/06 82/09/28	50-311 B 50-259 S 50-369 S 50-461 G 50-366 S	8210130485 8210130486 8210130493 8210130497 8210130504	8210130469 8210130417 8210130469 8210130489 8210130496	82/10/01 82/10/05 82/10/01 82/10/04 82/09/29	50-361 50-528 50-361 50-325 70-1100	8 0 8 8

# TO PRINCIPAL DOCUMENTS

ACCESSION	NUMBER				ACCESSIO	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	Y	ENCLOSURE	PRINGIPAL DOCUMENT	DAYE 188UED	GUBJECT CATEGOR	
8210130505 8210130507 8210130500 8210130511 8210130517	8210130494 8210130500 8210130499 8210130501 8210130509	82/10/08 82/10/04 82/09/30 82/09/29 82/09/30	50-329 50-280 50-361 50-254 50-331	T 8 8 8 P	8210150123 8210150128 8210150128 8210150133 8210150133	8210150116 8210150120 8210150100 8210150126 8210150130	82/09/24 82/10/05 82/09/24 82/10/12 82/09/14	50-349 50-213 50-324 50-352 70-824	G S G A
8210130522 8210130523 8210130526 8210130529 8210130530	8210130513 8210130514 8210130515 8210130514 8210130520	82/09/24 82/09/16 82/09/29 82/09/16 82/10/01	50-313 50-483 50-289 50-483 50-302	8 9 8 9	8210150140 8210150142 8210150143 8210150152 8210150155	8210150127 8210150135 8210150131 8210150146 8210150148	82/09/29 81/07/07 82/09/23 81/03/27 82/09/29	50-272 50-220 50-267 50-255 50-272	55688
8210130531 8210130533 8210130535 8210130549 8210130550	8210130517 8210130510 8210130527 8210130541 8210130539	82/10/01 82/10/06 82/10/08 82/09/28 82/09/29	50-29 50-282 50-364 50-366 PR	8 8 8 8	8210160158 8210150157 8210160144 8210150170 8210150176	8210150150 8210150151 8210150149 8210150162 8210150163	82/10/11 82/10/08 82/09/21 82/09/24 82/10/12	50-266 50-275 50-438 50-324 50-528	R G O A
8210130555 8210130557 8210130558 8210130559 8210130562	8210130484 8210130547 8210130543 8210130556 8210130552	82/10/05 82/08/04 82/09/30 82/10/06 82/10/04	50-483 50-461 50-317 50-247 50-335	0 0 5 0 5	8210150178 8210150179 8210150189 8210150189 8210150182	8210150148 8210150154 8210150174 8210150171 8210150173	62/10/12 62/10/01 81/08/24 82/09/23 62/10/08	50-322 50-277 50-263 50-438 TOPREP	7 8 9
8210130566 8210130569 8210130573 8210130577 8210130578	8210130563 8210130565 8210130571 8210130571 8210130568	82/10/05 82/10/05 82/10/07 82/10/07 82/09/30	50-306 50-259 50-341 50-341 50-317	9 P P B	8210150188 8210150189 8210150174 8210150175 8210150201	8210150168 8210150171 8210150187 8210150171 8210150185	82/10/12 82/09/23 82/09/23 82/09/23	50-322 50-438 50-338 50-438 50-334	T Q: Q: Q: B:
6210130577 6210130582 8210130584 8210130590 6210130592	8210130572 8210130571 8210130583 8210130585 8210130587	82/10/05 82/10/07 82/10/06 82/10/01 82/09/02	50-328 50-361 50-320 50-331 CONTRACT	8 P P 8	8210150204 6210150206 8210150207 8210150208 8210150219	8210150197 8210150168 8210150171 8210150199 8210150215	82/09/14 82/10/12 82/09/23 82/09/27 82/09/17	70-143 50-322 50-438 50-334 70-1201	T G S
8210150003 8210150011 8210150012 8210150014 8210150017	8210150001 8210150005 8210150004 8210150009 8210150001	82/09/28 82/09/24 82/08/13 82/09/30 82/09/28	50-293 50-416 50-369 50-324 50-293	Q Q Q	8210150223 8210150226 8210150230 8210150231 8210150232	8210150168 8210150214 8210150209 8210150225 8210150221	82/10/12 82/09/27 82/10/04 82/10/05 82/10/01	50-322 50-317 50-390 50-327 50-289	T G G G
8210150018 8210150019 8210150020 8210150021 8210150023	8210150015 8210150005 8210150004 8210150014 8210150008	82/10/08 82/09/24 82/08/13 82/09/24 82/09/30	50-334 50-416 50-369 50-369 50-324	0 0 0 0	8210180235 8210150237 8210150239 8210150240 8210150241	8210150214 8210150225 8210150229 8210150168 8210150209	82/09/27 82/10/05 82/09/17 82/10/12 82/10/04	50-317 50-327 70-27 50-322 50-390	0 0 T 0
8210150024 8210150025 8210150027 8210150028 8210150032	8210150005 8210150006 8210150005 8210150005 8210150005	82/09/24 82/08/13 82/09/24 82/09/24 82/09/24	50-416 50-369 50-416 50-416 50-416	G G G	8210150245 8210150250 8210150251 8210150255 8210150256	8210 (50225 8210 (50168 8210 (50209 8210 (50249 8210 (50225	82/10/05 82/10/12 82/10/04 82/10/08 82/10/05	50-327 50-322 50-390 50-282 50-327	Q T Q Q
8210150034 8210150038 8210150039 8210150040 8210150045	8210150008 8210150036 8210150035 8210150008 8210150036	82/09/30 82/10/05 81/02/20 82/09/30 82/10/05	50-324 50-324 50-335 50-324 50-324	9 8 9	8210150257 8210150258 8210150260 8210150263 8210150265	8210150168 8210150246 8210150209 8210150253 8210150168	82/10/12 82/09/27 82/10/04 82/09/17 82/10/12	50-322 50-271 50-370 50-249 50-322	T 0 0 1
8210150046 8210150049 8210150049 8210150052 8210150059	8210150041 8210150036 8210150044 8210150036 8210150055	81/03/25 82/10/05 81/10/08 82/10/05 82/09/30	50-324 50-324 50-237 50-324 50-322	8 8 0	8210150268 8210150267 8210150272 8210150274 8210150278	8210150209 8210150262 8210150168 8210150246 8210150209	82/10/04 82/09/27 82/10/12 82/09/27 82/10/04	50-390 50-389 50-322 50-271 50-390	0 T 0
9210150062 9210150063 9210150065 9210150066 9210150067	8210150053 8210150008 8210150057 8210150058 8210150064	82/07/22 82/07/30 82/07/27 82/07/27 82/07/27	50-370 50-324 50-311 50-272 70-1113	0 8 8	8210150281 8210150283 8210150289 8210150289 8210150290	821015016B 8210150271 8210150207 8210150280 821015016B	82/10/12 82/10/07 82/10/04 81/06/08 82/10/12	50-322 50-333 50-390 50-320 50-322	T G G S T
8210150074 8210150075 8210150078 8210150082 8210150083	0210150072 0210150071 8210150072 0210150072 0210150076	82/10/04 82/09/29 82/10/04 82/10/04 82/10/05	50-348 50-272 50-348 50-348 50-289	Q 5 0 0	8210150272 8210130275 8220150276 6210150303 8210150303	8210150282 8210150288 8210150279 8210150279 8210150209	82/10/06 82/10/05 82/10/12 82/09/27 82/10/04	50-277 50-324 50-322 50-277 50-390	P Q Q Q
8210150084 8210150084 8210150089 8210150091 8210150093	8210150079 8210150072 8210150080 8210150076 8210150088	81/02/04 82/10/04 81/02/09 82/10/05 82/09/30	50-249 50-348 50-311 50-289 50-311	8 9 8	8210150307 8210150308 8210150313 8210150313 8210150315	8210150300 8210150291 8210150279 8210150306 8210150304	82/10/12 81/02/27 82/10/12 82/10/08 82/09/10	50-155 50-324 50-322 50-470 50-390	0 8 0 8 0
9210150101 9210150102 9210150103 9210150104 9210150112	8210150074 8210150077 8210150076 8210150100 8210150078	82/10/12 81/10/13 82/09/15 82/09/24 82/10/01	50-413 50-249 50-424 50-324 50-219	8 0 8	8210150316 8210150319 8210150332 8210150324 8210150326	8210150312 8210150306 8210150099 8210150279 8210150322	82/10/05 82/10/08 82/07/30 82/10/12 82/10/11	50-334 50-470 50-311 50-322 50-341	P E S O
8210150113 8210150114 8210150118 8210150120 8210150121	8210150100 8210150108 8210150109 8210150100 8210150111	82/09/24 82/09/24 82/09/29 82/09/24 82/09/29	50-324 50-324 50-311 50-324 50-272	9 9 9 8	8210150330 8210150331 8210150333 8210150334 8210150335	8210 150322 8210 150323 8210 150327 8210 150318 8210 150322	82/10/11 82/09/16 82/10/06 82/09/20 82/10/11	50-341 50-390 50-321 50-518 50-341	9 9 9

ACCESSION					ACCESSI	ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1950ED	SUBJECT CATEODR		ENGLOSURE	PRINCIPAL DOCUMENT	DATE 198UED	SUBJECT CATEGOR	
8210150337 8210150337 8210150343 8210150344 8210150346	8210   50279 8210   50311 8210   50322 8210   50338 8210   50322	82/10/12 82/09/30 82/10/11 82/10/11	50-322 50-311 50-341 50-344 50-341	0 5 0 4	8210180073 8210180075 8210180076 8210180078 8210180079	8210180070 8210180028 8210180070 8210180028 8210180070	82/10/06 82/08/20 82/10/06 82/08/20 82/10/06	50-206 FDIA 50-206 FDIA 50-206	P P
8210150350 8210150351 6210150353 6210150353 8210150355	8210150328 8210150279 8210150322 8210150347 8210150349	82/09/23 82/10/12 82/10/11 82/10/04 82/10/07	CONTRACT 50-322 50-341 50-382 50-390	G G A	921019090 821019083 821019083 821019085 821019087	8210180028 8210180028 8210180074 8210180028 8210180082	82/08/20 82/08/20 82/10/07 82/08/20 82/10/07	FOIA FOIA 50-244 FOIA 50-244	P P
8210150358 8210150365 8210150368 8210150371 8210150373	8210150345 8210150279 8210150356 8210150361 8210150362	82/09/22 82/10/12 82/10/08 82/10/07 82/10/15	50-335 50-322 50-277 70-143 50-424	Q Q R	82101800B7 8210180090 8210180091 8210180092 8210180094	8210180082 8210180088 8210180088 8210180028	82/06/20 82/10/07 82/09/12 82/08/20 82/10/07	FOIA 50~244 50~286 FOIA 50~244	P R
8210150376 8210150377 8210150380 8210150386 8210150390	8210150361 8210150364 8210150361 8210150385 8210150381	82/10/07 82/10/11 82/10/07 82/09/28 81/08/24	70-143 50-263 70-143 50-263 50-282	P (1) (5)	9210180076 9210180100 9210180100 931018010138	8210180028 8210180028 8210180097 8210180028 8210180028	62/08/20 62/08/20 62/10/01 82/08/20	FOIA FOIA 50-10 FOIA FOIA	R
6210150393 6210150401 6210150402 6210150406 6210150408	8210150279 8210150396 8210150279 8210150299 8210150403	82/10/06 82/09/17 82/09/20 82/10/12 82/10/12	50-322 50-261 50-322 50-259 70-143	G G G	8210180107 8210180108 8210180109 8210180111 8210180113	8210180103 8210180028 8210180104 8210180028 8210180028	82/10/14 82/08/20 82/10/14 82/08/20 82/08/20	70-143 FOIA 50-416 FOIA FOIA	R
8210150410 6210150411 6210150413 6210150422 8210150427	8210150279 8210150405 8210150407 8210150279 8210150434	82/10/12 82/10/06 82/10/11 82/10/12	50-322 50-255 50-250 50-322 50-315	Ç R P G P	8210180115 8210180114 8210180114 8210180121 8210180123	8510180150 8510180058 8510180058 8510180058	92/08/20 92/08/20 92/08/20 82/08/20 92/10/05	FOIA FOIA FOIA FOIA 50-316	8
8210150457 8210150477 8210150475 8210150500 8210150502	8210150449 8210150473 8210150487 8210150364 8210150497	82/10/11 82/09/22 82/09/30 82/10/11 82/09/28	50-35B 70-143 50-254 50-243 50-409	0 P 0	8210180125 8210180127 8210180137 8210180130 8210180132	8210180028 8210180120 8210180028 8210180028	82/08/20 82/08/20 82/10/05 82/08/20 82/08/20	FOIA FOIA 50-316 FOIA FOIA	8
8210150504 8210150509 8210150512 8210150517 8210150521	8210150364 8210150364 8210150499 8210150513 8210150513	82/10/11 82/10/13 82/10/08 82/10/08	50-263 50-263 50-528 GA999 GA999	P P G	8210180133 8210180136 8210180137 8210180137 8210180140	8210180124 8210180028 8210180131 8210180028 8210180028	82/09/22 82/08/20 82/10/04 82/08/20 82/08/20	50-317 FOIA 50-346 FOIA FOIA	8
8210150522 8210150526 8210150527 8210150528 8210150530	8210150518 8210150513 8210150279 8210150519 8210150523	82/10/07 82/10/08 82/10/12 82/10/04 82/09/28	50-369 04999 50-322 50-287 50-10	F G P G	9210180145 8210180146 8210180150 8220180152 8210180153	6210180028 6210180142 6210180028 6210180028 6210160149	82/08/20 82/10/14 82/08/20 82/08/20 82/10/08	FOIA 50-454 FOIA FOIA 50-244	o P
8210150535 8210150536 8210150538 8210150540 8210150543	8210150519 8210150532 8210150523 8210150532 8210150539	82/10/06 82/10/08 82/09/28 82/10/08 82/10/01	50-287 GA999 50-10 GA999 50-10	P G Q	6210180157 6210180159 6210180159 6210180161 6210180162	8210180028 8210180149 8210180028 8210180149 8210180154	82/10/08 82/10/08 82/10/08 82/10/08	FOIA 50-244 FOIA 50-244 50-275	P P
5210150544 6210150604 9210150607 6210150613 6210150616	8210150532 8210150594 8210150605 8210150607 8210150594	82/10/08 82/09/30 82/09/01 82/08/31 82/09/30	GA999 50-315 70-1739 40-2259 50-315	F F	8210180143 8210180144 8210180146 8210180171 8210180173	8210180154 8210180028 8210180028 8210180028 8210180028	82/10/13 82/08/20 82/08/20 82/08/20 82/08/20	50-359 FOIA FOIA FOIA FOIA	A
6210150643 6210150648 6210180007 6210180008 6210180026	8210150621 8210150621 8210180004 8210180005 8210180025	82/09/30 82/09/30 82/10/12 82/10/12 82/09/23	50-244 50-244 50-348 50-445 50-346	F G K P	8210180175 8210180178 8210180178 8210180191 8210180194	8210180157 8210180028 8210180028 8210180186 8210180028	82/10/07 82/08/20 82/08/20 82/10/05 82/08/20	50-304 FQIA FOIA 50-255 FOIA	5
8210180030 8210180032 8210180034 8210180036 8210180038	8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA		8210180197 8210180197 8210180200 8210180201 8210180208	8210 180028 8210 180194 8210 180028 8210 180195 8210 180204	82/08/20 82/10/12 82/08/20 82/09/20 82/09/20	FOIA 50-10 FOIA 50-312 50-352	P P C
6210180040 6210180041 6210180042 8210180043 8210180046	8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA		8210180213 8210180215 8210180225 8210180222	8210180028 8210180028 8210180028 8210180028 8210180223	82/08/20 82/08/20 82/08/20 82/08/20 82/09/27	FOIA FOIA FOIA FOIA 50-352	ø
8210180049 8210180051 8210180054 8210180057 8210180058	8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA FOIA		8210180229 8210180234 6210180239 8210180248	8210180028	82/08/20 82/08/20 82/08/20 82/08/20 82/09/23	F01A F01A 50-244 F01A 50-528	P A
8210180060 8210180061 8210180064 8210180066 8210180072	8210180055 8210180028 8210180028 8210180028 8210180028	82/10/08 82/08/20 82/08/20 82/08/20 82/08/20	50-269 FOIA FOIA FOIA FOIA	P	8210180251 8210180265 8210180265 8210180265	8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA	

ACCESSIDA				ACCESSION			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	PATE ISSUED	SUBJECT CATEGORY
6210160270 6210160275 6210160277 6210160262 6210160264	8210180028 8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA FOIA	8210180427 8210180428 8210180429 8210180430 8210180431	8210180028 8210180028 8210180028 8210180028	62/08/20 82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA
8210180287 8210180270 8210180275 8210180278 8210180301	8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA FOIA	8210180432 8210180433 8210180434 6210180435 6210180436	8210180028 8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA
8210180304 8210180307 8210180310 8210180312 8210180315	8210180028 8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA FOIA	8210190002 8210190004 8210190010 8210190016 8210190017	8210170001 8210170003 8210170005 8210170013 8210170013	82/09/29 82/09/30 82/09/23 82/09/29 82/09/29	CONTRACT CONTRACT CONTRACT 50-321 F 50-321 F
8210180318 8210180319 8210180324 8210180326 8210180328	8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20 82/08/20	FOIA FOIA FOIA FOIA FOIA	8210190024 8210190025 8210190026 8210190029 8210190037	8210170020 8210170018 8210170020 8210170022 8210170030	82/10/01 82/09/30 82/10/01 82/10/05 82/09/28	50-344 F CONTRACT 50-344 F 50-271 S CONTRACT
8210180332 8210180333 8210180335 8210180337 8210180338	8210180327 8210180028 8210180028 8210180028 8210180329	82/09/28 82/08/20 82/08/20 82/08/20 82/09/30	CONTRACT FOIA FOIA CONTRACT	8210190040 8210190046 8210190051 8210190058 8210190063	8210190036 8210190042 8210190042 8210190030 8210190037	82/10/01 82/10/01 82/10/05 82/10/05	50-315 F 50-321 F 50-321 F 50-373 E CONTRACT
8210180340 8210180341 8210180343 8210180344 8210180344	8210180028 8210180028 8210180028 8210180028	92/08/20 92/08/20 92/08/20 92/08/20 92/08/20	FOIA FOIA FOIA FOIA FOIA	8210190073 8210190077 8210190087 8210190095 8210190103	8210190066 8210190069 8210190076 8210190092 8210190097	82/10/01 82/10/07 82/09/24 82/09/30 82/09/29	50-348 F 50-333 S CONTRACT REVIEW GRP 50-369 F
8210180347 8210180348 8210180349 8210180351 8210180352	8210180028 8210180329 8210180028 8210180028 8210180028	82/08/20 82/09/30 82/08/20 82/08/20 82/08/20	FOIA CONTRACT FOIA FOIA FOIA	8210190105 8210190108 8210190115 8210190121 8210190124	8210190102 8210190097 8210190112 8210190112 8210190112	82/09/30 82/09/29 82/10/06 82/10/06 82/10/06	CONTRACT 50-369 F FDIA FOIA FOIA
8210180353 8210180354 8210180358 8210180359 8210180360	8210180028 8210180028 8210180028 8210180354 8210180028	92/08/20 92/08/20 92/08/20 92/08/20 92/08/20	F01A F01A F01A 40-8786 F01A	8210190141 8210190152 8210190154 8210190156 8210190161	8210190132 8210190144 8210190145 8210190147 8210190145	82/09/23 82/09/30 82/09/30 82/09/30	CONTRACT FOIA 50-269 P CONTRACT 50-269 P
8210180362 8210180363 8210180366 8210180367 8210180370	8210180357 8210180028 8210180028 8210180028 8210180028	82/08/20 82/08/20 82/08/20 82/08/20	CONTRACT FOIA FOIA FOIA FOIA	8210190166 8210190167 8210190169 8210190173 8210190177	8210190150 8210190162 8210190145 8210190150 8210190172	82/09/28 82/09/30 82/09/29 82/09/28 82/09/21	50~387 F CONTRACT 50~269 P 50~307 F CONTRACT
8210180371 8210180372 8210180373 8210180374 8210180374	8210180365 8210180028 8210180028 8210180028	82/09/29 82/08/20 82/08/20 82/08/20	CONTRACT FOIA FOIA FOIA	8210190182 8210190185 8210190186 8210190191 8210190194	8210190179 8210190180 8210190178 8210190189 8210190178	82/09/21 82/09/29 82/09/30 82/09/30	CONTRACT 50-320 F 50-250 F FOIA 50-250 F
				8210190198 8210190204 8210190209 8210190218 8210190223	8210280402 8210170177 8210170177 8210170210 8210170217	82/09/30 82/09/15 82/09/15 82/09/30 82/09/30	FOIA 50-440 F 50-440 F CONTRACT CONTRACT
				8210190231 8210190237 8210190244 8210190256 8210190261	8210190228 8210190235 8210190240 8210190246 8210190254	82/10/14 82/10/01 82/10/11 82/09/03 82/10/07	50-312 Q 50-293 B 50-261 B 40-299 50-346 B
				8210190270 8210190277 8210190282 8210190283 8210190287	8210190264 8210190266 8210190274 8210190278 8210190266	82/10/12 82/10/12 82/10/04 82/10/13 82/10/12	50-338 8 50-315 8 50-334 8 50-312 R 50-315 8
				8210190293 8210190296 8210190317 8210190323 8210190328	8210190289 8210190290 8210190309 8210190309 8210190309	82/10/12 82/10/06 82/10/08 82/10/08 82/10/08	50-243 B 50-317 S 50-341 S 50-341 B 50-341 S
				8210190337 8210190339 8210190342 8210190346 8210190349	8210170329 8210170230 8210170340 8210170344 8210170347	82/10/12 82/09/30 82/10/12 82/10/04 82/09/22	50-330 B CONTRACT 50-315 B 50-373 B 50-265 Q
				8210190355 8210190356 8210190359 8210190361 8210190362	8210190353 8210190353 8210190358 8210190360 8210190360	82/10/11 82/10/11 82/10/11 82/10/05 82/10/05	50-305 Ø 50-305 Ø 60-346 Ø 50-331 Ø 50-331 Ø

ACCESSION	! NUMBER					ON NUMBER			
CHOLOCURE	PRINCIPAL	DATE	SUBJECT		ENCLOSURE	PRINCIPAL DOCUMENT	DATE I SSUED	SUDJEC CATEGO	
ENCLOSURE 8210190368	9210190366	(SSUED 	CATEGO  50-397		8210190675	6210190669	82/10/04	50-266	ā
8210170372 8210170374	6510190369	82/10/14	QA <i>999</i>	œ 	8210190676 6210190685	8210190665 8210190676	82/10/01 82/10/01	50-397 50-315	G R
8210190386	8210190371 8210190378	82/10/12 82/10/14	50-335 50-327	f	8210190687 8210190690	8210190677 8210190686	82/10/08 62/10/15	50-302 50-29	₽ P
8210190389	B2101903B0	02/10/13	50~315	s	8210170474	8210190692	82/10/04	50-373	Q
B210190398 B210190404	8210190375 8210190380	82/10/12 82/10/13	50-219 50-315	0 5	8210190700	8210190658 8203050387	82/10/04 82/02/16	50-254 50-317	Š
8210190412 8210190415	8210190403 8210190380	82/10/06 82/10/13	50-249 50-315	s	6210190702 6210190702	8210190701	82/10/04	50~267	P
8210190419	8210190413	82/09/28	50-478	Q	8210190707	8210190699	82/10/04	50~255	•
8210190420 8210190424	8210190411 8210190417	82/10/15 82/10/13	50-333 50-416	Q 8	8210190714 8210190715	8203050387 821019 <i>0</i> 689	82/02/14 82/10/05	50-317 50-295	8
8210190427 8210190428	8210190421 8210190411	82/09/29 82/10/15	50~255 50~333	ā	8210190720 8210190723	8210190709 8210190722	82/10/14 82/10/12	50-261 50~348	PR
6210190429	B210190422	82/10/12	50-282	P	8210190733	8210190731	82/10/06	50-344	a
8210190435	8210190411	82/10/15	50-333	q	8210190734 8210190735	8210190728 8210190727	82/10/12 82/10/08	50-284 50-314	B.
8210190437 8210190439	B210190431 B210190432	82/09/30 82/10/07	50-382 50-282	a	8210190743 8210190744	8210190731 8210190737	82/10/05 82/10/07	50-344 50-373	ē
8210190444 8210190449	8210190352 8210190421	82/10/12 82/09/29	50-375 50-255	P Q	8210190745	8210190726	82/10/08	50~306	s
8210190452	8210190431	02/09/30	50-382	G G	8210190746	8210190736	82/10/12	50-285	R
8210190454 8210190455	8210190448 8210190450	82/10/11 82/10/13	50-409 50-361	8	9210170750 9210170751	8210190739 8210190742	82/10/06 82/10/15	50-329 50-369	GI FR
8210190457 8210190466	8210190352 8210190019	82/10/12 82/10/06	50~395 50~322	P	8210170757 8210190759	8210190749 8210190748	82/10/07 82/10/15	50-315 50-324	8
			<del></del>	Α .	8210190760	8210190753	82/10/12	50-254	F
8210190468 8210190471	8210190462 8210190458	02/09/29 02/10/05	50-373 50-249	9	8210190761 8210190762	8210190725 8210190754	92/10/01 92/10/08	GA799 50-324	8
8210190476 8210190481	0210190472 0210190462	02/10/06 02/09/29	50-334 50-373	0 B	8210190766 8210190771	8210190756 8210190763	82/09/27 82/09/27	9A999 50-440	g
8210190493	8210170483	82/10/08	50-295	S	8210190773	8210190767	92/10/12	50~364	R
8210190494 8210190500	8210190487 8210190492	82/09/29 82/10/15	50-373 50-395	S P	8210190776	8210190772	82/10/01	50-445 50-254	Q.
8210170501 8210170503	8210190478 8210190498	82/10/05 82/09/29	50-361 50-373	9	8210190785 8210190787	8210190763	82/10/12 82/09/27	50-440	Ö.
8210170506	6210190490	02/10/04	50-204	8	6210190803	8210190797	82/10/12	50-317	G
821019050 <b>8</b> 8210190511	8210190505 8210190504	82/10/12 82/10/05	50-395 50-366	P S	8210190620 8210200004	8210190816 8210200001	82/09/29 82/10/15	50-445 70-143	Œ
8210190514	8210170507	02/09/29	50-373	8	8210200007 8210200013	8210200002 8210200007	82/09/29 82/10/15	50-373 50-400	5
8210190515 8210190516	0210190507 8210190497	82/10/05 82/09/28	50-272 50-313	G P	8210200014	8210200010	82/10/10	116-04	R
8210190525	8210190522	82/09/29	50~373	S	9210200021 9210200024	8210200009 8210200018	82/10/15 82/02/03	50-400 50-333	ē R
6210190926 6210190933	8210190517 8210190530	82/10/07 82/10/12	50-313 State Pr	8 0g	6210200035	8210200026	82/10/13 82/10/15	50-443 50-333	ë
8210190539 8210190543	8210190531 8210190537	82/09/22 82/10/08	50-265 50-267	G 8	6210200039 8210200042	8210200026 8210200026	82/10/13	50-443	ò
6210190552	8210190544	82/10/15	50~269	R	8210200049	8210200043	82/10/06	50-280	P
8210190556 8210190558	6210190549 6210190545	82/10/01 82/10/06	50-344 50-368	Q.	8210200049 8210200063	8210200024 8210200044	82/10/13 82/10/13	50-443 50-277	P
8210190567 8210190569	8210190561 8210190562	82/10/13 82/09/28	50~416 50-397	8	8210200048 8210200083	8210200046 8210200074	82/10/15 82/10/12	50-277 50-322	P
		92/10/08	50-373	s	8210200086	8210200084	82/10/15	50-400	G
8210190573 8210190577	8210190536 8210190570	82/10/13	50-320	P	8210200989 8210200090	8210200074 8210200085	82/10/12 82/10/10	50-322 50-272	Q R
8210190578 8210190579	8210190572 8210190568	82/10/08 82/09/30	50~315 50~295	s G	8210200096 9210200106	8210200093 8210200104	82/10/13 82/08/18	50-331 70-820	R
8210170582	8210190576	82/10/04	50-397	E	8210210010	821021000A	82/10/07		
8210190586 8210190588	8210190576 8210190572	82/10/04 82/10/08	50-397 50-315	E 8	8210210018 8210210038	8210210015 8210210036	82/10/12 82/08/30		
8210190591 8210190598	8210190580 8210190594	82/10/07 82/09/28	50-244 50-312	Q P	8210210044	8210210033	85/10/0		
8210190599	8210190548	82/09/30	50-295	0	8210210048				
8210190601 8210190602	B2101905B9 B210190595	82/09/29 82/10/05	50~373 50~366	G 8	8210210053 8210210055				
E090610128	8210190594 8210190596	82/09/28 82/09/22	50-312 50-482	ē a	82102103 82102103				
8210190608 8210190612	8210190605	82/09/30	50-312	ä	8210210055				
8210170414	8210190609	82/10/08	50~348	8	8210210072 821021008				
8210190415 8210190416	8210190404 8210190580	82/10/11 82/10/07	50-255 50-244	8	821021008 821021008				
8210190624 8210190626	8210190613 8210190617	82/10/07 82/10/05	50-295 50-295	G G	821021009				
8210170628	8210190420	92/10/11	50~255	8	621021011				
8210170636 8210170637	8210190432 8210190580	82/10/01 82/10/07	50-27 50-244	Q	85105101 85105101				
8210170647	8210190580 8210190639	82/10/07 82/10/11	50-244 50-255	Ģ B	85105101; 85105101;				
8210170647				_	821021011				
8210190654 8210190664	8210190638 8210190643	82/10/13 82/10/13	50-409 50-331	G G	85105101, 85105101,				
8210190667 8210190668	8210190455 8210190463	82/10/12 82/09/27	50-267 50-213	R	82102(01; 82102(01)				
8210190674	8210190666	82/10/11	50-325	6	GE10#1014				

ACCESSION NUMBER	1			ACCESSION	NUMBER			
ENCLOSURE DOCU	IENT ISSUED	SUBJECT CATEODRY	_	ENCLOSURE	PRINCIPAL DOCUMENT	DATE DAVED	SUBJECT CATEGORY	Y
8210210161 821021 8210210162 821021 8210210178 821021 8210210179 821021 8210210176 821021	0147 82/09/29 0144 92/10/05 0174 82/09/20 0173 82/10/20	CONTRACT 50-320	a a a	8210220092 8210220097 8210220100 8210220108 8210220116	8210220066 8210220095 8210220095 8210220103 8210220112	82/10/01 82/10/14 82/10/14 82/10/13 82/10/15	40-8111	555
8210210197	0185 82/09/15 0194 82/10/15 0201 82/10/06	50-271 50-13 50-244	9 9 0 8	8210220125 8210220128 8210220132 8210220136 8210220137	8210220122 8210220123 8210220127 8210220130 8210220127	82/10/14 82/09/28 82/10/12 82/10/14 82/10/12	50-498 40-1142 50-400 50-298 50-400	G G G
8210210223 821021 8210210236 821021 8210210238 821021 8210210240 821021 8210210248 821021	0231 82/10/06 0221 82/10/04 0232 82/10/19	50-271 50-537	g q q q	8210220141 8210220145 8210220147 8210220150 8210220157	8210220127 8210220127 8210220139 8210220131 8210220153	82/10/12 82/10/12 82/10/04 82/10/18 82/10/15	50-400 50-400 50-324 50-416 50-29	0 0 0 8 0
8210210261 821021 8210210264 821021 8210210273 821021 8210210277 821021 8210210301 821021	0255 82/10/04 0285 82/10/11 0292 82/09/29	50~220 50~387 50~287	0 9 9 9 9	8210220159 8210220162 8210220163 8210220165 8210220171	8210220155 8210220158 8210220160 8210220161 8210220161	82/09/29 82/10/08 82/10/04 82/09/27 82/09/27	50-424 50-416 50-400 40-2259 40-2259	0 8 0
8210210306 821021 8210210307 821021 8210210316 821021 8210210321 821021 8210210337 821021	0300 82/10/07 0313 82/10/07 0313 82/10/07	50-247 50-309 50-309	A G G G B	8210220172 8210220173 8210220174 8210220179 8210220183	8210220168 8210220169 8210250398 8210220177 8210220180	82/10/08 82/10/04 82/09/23 82/10/14 82/06/28	70-371 50-324 50-447 70-371 50-438	0 A 0
8210210342 821021 8210210347 821021 8210210358 921021 8210210366 821021 8210210368 821021	0344 82/10/18 0351 82/10/15 0351 82/10/15	50-440 50-440	9 9 9 9	0210220187 0210220188 0210220189 0210220191 0210220194	8210220182 8210220185 8210220181 8210220181	82/10/12 82/10/13 82/06/28 82/10/08 82/10/15	50-219 TOPREP 50-438 50-414 50-277	Cr Gr S R
6210210397 821021 6210210400 821021 8210210403 821021 6210210410 821021 8210210411 821021	0391 82/10/18 0395 82/09/30 0395 82/09/30	50-358 50-305 50-305	G G P P P	8210220213 8210220201 82102202011 8210220211	8210220176 8210220175 8210220204 8210220204 8210220204	92/10/07 92/10/15 82/10/15 92/10/15 92/10/15	50-416 50-245 50-424 50-424 50-424	8 0 0
8210210430 821021 8210210434 821021 8210210436 821021 8210210444 821021 8210210446 821021	0428 82/10/15 0433 82/10/11 0438 82/09/28	50-289 50-387 CONTRACT	8 T 8 8	8210220218 8210220222 8210220232 8210220234 8210220241	8210220204 8210220217 8210220227 8210220227 8210220237	82/10/15 82/10/07 82/10/04 82/10/07 82/10/20	50-424 50-321 50-348 50-338 50-498	0 5 0 8 A
8210210448 82102 8210210451 82102 8210210457 82102 8210210469 82102 8210210470 82102	0435 82/10/06 0328 82/10/15 0464 82/10/06	50-317 50-272	Q R Q P	8210220244 8210220293 8210220262 8210220264 8210220267	8210220259 8210220259 8210220260 8210220260	82/10/18 82/10/18 82/10/08 82/10/13 82/10/06	50-528 50-482 50-416 70-687 50-261	A B S
8210210473 82102 8210210477 82102 8210210505 82102 8210210512 82102 8210210525 82102	0464 82/10/06 10502 82/07/29 10508 82/10/05	50-272 Contract	Р a T	8210220271 8210220274 8210220276 8210220279 8210220281	8210220237 8210220269 8210220268 8210220268 8210220270	82/10/15 82/10/18 82/10/20 82/10/20 82/10/05	50-436 50-414 50-537 50-537 50-313	00000
8210210534 82102 8210210543 82102 8210210546 82102 8210210550 82102 8210210551 82102	10539 82/06/21 10544 82/09/23 10548 82/09/20	50-346	F F	8210220282 8210220283 8210220284 8210220287 8210220288	8210220278 8210220268 8210220280 8210220277 8210220268	82/10/18 82/10/20 82/10/15 82/10/14 82/10/20	50-416 50-537 50-335 50-321 50-537	8000
6210210552 82102 8210210553 82102 8210210555 82102 8210210556 82102 8210210559 82102	10548 82/09/20 10545 82/09/30 10548 82/09/20	50-346 50-29 50-346	P P P P	8210220291 8210220291 8210220292 8210220295 8210220297	8210220284 8210220280 8210220277 8210220248 8210220280	82/10/18 82/10/15 82/10/14 82/10/20 82/10/15	50-416 50-335 50-321 50-537 50-335	8 0 0
8210210570 82102 8210210581 82102 8210210594 82102 8210220007 82102 8210220017 82102	10576 92/09/30 10584 82/09/30 20006 82/10/19	CONTRACT 50-278	p የ	8210220298 8210220299 8210220303 8210220304 8210220307	8210220270 8210220277 8210220280 8210220276 8210220277	82/10/15 82/10/14 82/10/15 82/10/08 82/10/14	50-366 50-321 50-335 50-250 50-321	P Q Q Q
8210220028 82102 8210220048 82102 8210220056 82102	20020 82/09/30 20025 82/09/29 20047 82/09/17 20052 82/10/15 20053 82/10/08	70-1257 NUREO 50-302	P S S	8210220310 8210220317 8210220317 8210220320 8210220323	8210220294 8210220294 8210220312 8210220308 8210220315	82/10/08 82/10/08 82/10/14 82/10/15 82/09/30	50-250 50-250 50-140 70-1113 50-370	Q G G
8210220067 82102 8210220070 82102	20058 82/10/08 20060 82/10/14 20065 82/10/11 20066 82/10/01 20066 82/10/01	50-328 50-336 50-416 40-8111 40-8111	8 6 8	8210220325 8210220327 8210220329 8210220330 8210220337	8210220312 8210220318 8210220312 8210220312	82/10/14 82/10/15 82/10/08 82/10/14 82/09/29	50-140 50-349 50-250 50-140 50-370	0 8 9 9
8210220085 82102 8210220086 82102	20046 82/10/01	40-8111	8	8210220341 8210220344 8210220352 8210220354 8210220357	8210220312 8210220340 8210220344 8210220331 8210220351	82/10/14 82/10/15 82/10/13 82/10/04 82/10/20	50-160 50-395 50-244 50-280 50-367	0 0 0 0

ACCESSIO)	NUMBER					ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 15SUED	SUBJEC CATEOD	₹Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEGOR	RY
8210220360 8210220369 8210220374 8210220385 8210220388	8210220344 8210220363 8210220367 8210220378 8210220384	82/10/13 82/10/20 82/10/13 82/10/15 82/09/28	50-244 50-275 50-352 50-318 50-321	G H G P 8	6210250184 8210250184 8210250198 8210250201 8210250201	6210250181 6210250192 6210250195 6210250197 6210250208	82/10/04 82/10/01 82/09/23 82/10/08 82/08/30	TOPREP 50-133 50-341 50-275 50-338	R F R F
8210220378 8210220401 8210220405 8210220406 8210220408	8210220392 8210220396 8210220387 8210220387	82/10/08 82/10/12 82/10/12 82/10/08	50-280 50-259 50-440 50-438 50-280	5 0 0 6	8210250218 8210250227 8210250231 8210250232 82102502532	8210250214 8210250222 8210250226 8210250224 8210250248	82/10/15 82/10/18 82/10/14 82/10/06 82/10/20	50-361 50-361 50-346 50-461 50-463	8 0 8
8210220413 8210220417 8210220418 8210220421 8210220422	8210220392 8210220407 8210220411 8210220415 8210220387	82/10/08 82/10/05 82/10/12 82/10/07 82/10/12	50-280 0A999 50-271 50-339 50-438	8 0 8	8210250261 8210250262 8210250264 8210250273 8210250273	8210250251 8210250258 8210250254 8210250254	82/10/11 82/10/13 82/10/19 82/10/15 82/10/19	50~331 50~266 50~387 50~361 50~387	8868
8210220427 8210220431 8210220431 8210220432 8210220435	8210220420 8210220420 8210220428 8210220387 8210220424	92/10/12 92/10/12 92/10/18 92/10/12 92/10/07	70~1113 70~1113 50~414 50~438 50~281	9 0 5	6210250278 6210250279 6210250296 6210250297 6210250298	8210250269 8210250270 8210250283 8210250286 8210250272	82/10/12 82/10/12 82/10/14 82/10/07 82/10/13	50-237 50-346 50-237 50-346 50-368	8 8 8
8210220437 8210220442 8210220443 8210220446 8210220448	8210220420 8210220420 8210220438 8210220387 8210220439	82/10/12 82/10/12 82/10/15 82/10/12 82/10/19	70-1113 70-1113 50-395 50-438 50-170	S Q	8210250300 8210250314 8210250327 8210250332 8210250333	8210250267 8210250304 8210250323 8210250323 8210250323	82/10/11 82/09/22 82/10/18 82/10/21 82/10/18	50-331 50-249 50-135 50-289 50-155	888
8210220450 8210220461 8210220462 8210220466 8210220471	8210220441 8210220454 8210220458 8210220459 8210220457	82/10/07 82/10/04 82/10/08 82/10/18 82/09/29	50-339 50-338 50-416 50-390 50-413	8 9 9	8210250337 8210250339 8210250342 8210250343 8210250348	8210250323 8210250330 8210250334 8210250334 8210250328	82/10/18 82/10/19 82/10/07 82/10/15 82/09/22	50-185 50-375 50-331 50-244 50-249	P 0 8 8
8210220474 8210220476 8210220480 8210220482 8210220485	8210220469 8210220464 8210220469 8210220469 8210220469	92/10/18 92/09/27 92/10/18 92/10/18 92/10/18	50-327 40-6622 50-327 50-327 50-327	Q Q Q	8210250350 8210280352 8210280361 8210290372 8210250373	8210250334 8210250344 8210250351 8210250363 8210250367	82/10/07 82/10/15 82/10/08 82/10/20 82/10/17	50-331 50-266 50-528 50-213 50-387	0 9 0 0
8210220492 8210220494 8210220496 8210220499 8210220500	8210220489 8210220489 8210220489 8210220495 8210220495	82/10/18 82/10/18 82/10/18 82/10/18 82/10/18	50-324 50-324 50-324 50-261 50-261	0 0 0	8210250375 8210230374 8210250377 8210250380 8210250385	8210250351 8210250364 8210250367 8210250367 8210250381	82/10/08 82/10/15 82/10/14 82/10/19 82/10/14	50-528 50-282 50-387 50-387 50-387	9 8 8 8
8210220501 8210220503 8210220504 8210250008 8210250021	8210220495 8210220489 8210220495 8210250006 6210250019	82/10/18 82/10/18 82/10/18 82/08/27 82/07/30	50-261 50-324 50-261 40-8681 40-299	0 0	8210250387 8210250387 8210250370 8210250372 8210250373	8210250384 8210250382 8210250384 8210250148 8210250340	92/10/12 92/10/06 92/10/15 92/10/06 82/10/04	50-331 50-311 50-312 50-275 50-315	8888
8210250033 8210250050 8210250051 8210250056 8210250057	8210250030 8210250048 8210250048 8210250054 8210250053	82/09/30 82/09/21 82/09/21 82/08/27 82/10/06	NUREG 50-335 50-335 40-8402 50-311	р Р	8210250394 8210250395 8210260010 8210260011 8210860012	8210250340 8210250340 8210250008 8210250009 8210250008	82/10/04 82/10/04 82/10/05 82/08/30 82/10/05	50-315 50-315 50-302 70-2968 50-302	P F F
8210250059 8210250041 8210250070 8210250074 8210250075	8210250058 8210250060 8210250067 8210250067 8210250072	92/10/19 82/10/21 82/10/15 92/10/15 82/10/07	50-322 70-143 50-260 50-260 50-341	e P P G	6210240014 9210240016 9210240049 9210240049 9210240080	8210260013 8210260017 8210260038 8210260038 8210260079	82/08/30 82/08/31 82/07/02 82/07/02 82/08/18	40-6422 40-8681 70-820 70-820 40-3453	
8210250077 8210250078 8210250080 8210250093 8210250095	8210250067 8210250067 8210250072 8210250084 8210250088	82/10/15 82/10/15 82/10/07 82/10/11 82/10/15	50-260 50-260 50-341 50-344 50-318	P 0 6 8	8210260091 8210260099 8210260119 8210260119 8210260119	8210260086 8210260096 8210190764 8210260116 8210260115	82/06/09 82/08/26 82/10/07 82/10/18 82/10/19	HASTE MG 40-8781 50-397 50-250 50-373	A S S
8210250097 8210250101 8210250109 8210250113 8210250116	8210250092 8210250094 8210250105 8210250110 8210250105	82/10/12 82/10/15 82/10/07 82/10/12 82/10/07	50-219 50-259 50-373 50-70 50-373	P 9 9 9	8210260123 8210260125 8210260127 8210260129 8210260131	8210240124 8210240122 8210240122 8210240120	82/10/15 82/10/08 82/10/05 82/10/08 82/10/05	50-368 50-334 86777 50-334 86777	s F
8210250126 8210250128 8210250140 8210250141 8210250147	6210250114 6210250121 6210250197 6210250195 6210250145	65\10\15 85\10\18 85\10\18 85\10\18	50-254 QA999 50-361 GA999 50-247	6 8	8210260136 8210260141 8210260166 8210260167 8210260167	8210240133 8210240134 8210240159 8210240153 8210240145	82/10/21 82/10/22 82/10/11 82/10/11	50-338 50-322 50-395 50-334 50-29	P Q P 9 8
0210250153 0210250160 0210250161 0210250163 0210250169	B21025014B B210250154 B210250157 B210250152 B210250152	82/10/07 82/10/13 82/10/15 82/10/15 82/10/18	50-254 50-317 50-368 50-373 50-254	8 8 8 8 8	8210260175 8210260180 8210260183 8210260184 8210260185	8210260170 8210260178 8210260176 8210260177 8210260182	82/10/19 82/10/19 82/10/18 82/10/21 82/10/15	50-333 50-313 50-255 50-220 50-219	99 G
8210250171 8210250175 8210250177 8210250178 8210250183	8210250147 8210250164 8210250155 8210250173 8210250177	62/10/08	50-275 50-344 50-254 50-362 50-282	P 9 9 8	6210260187 8210260191 8210260195 8210260196 8210260200	8210260188	82/10/13 82/10/15 82/10/20 82/10/20 82/10/16	50-219 50-219 50-329 50-328 50-309	9 0 8

ACCESSION	NUMBER				ACCESSION			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8210260208 8210260221 8210260222 8210260223 8210260223	8210260179 8210260210 8210260212 8210260219 8210260203	82/10/18 92/10/18 92/10/20 92/10/19 92/10/14	50-307 50-373 50-257 50-304 50-324	9 8 8 8 8 8 8	8210240530 8210240538 8210240542 8210240547 8210240548	8210260525 8210260535 8210260526 8210260535 8210260543	82/09/28 82/09/24 82/10/06 82/09/24 82/09/01	CONTRACT 50-320 P 50-10 P 50-320 P 40-8027
8210260230 8210260234 8210260238 8210260238 8210260239	8210260224 8210260224 8210260225 8210260227 8210260232	82/10/12 82/10/22 82/10/18 82/10/18	50-72 50-72 50-320 50-373 50-322	R R Q B T	8210260552 8210260558 8210260540 8210260541 8210260569	8210260535 8210260494 8210260557 8210260559 8210260568	82/09/24 82/10/12 82/09/03 82/09/28 82/08/30	50-320 P 0A999 40-B102 CONTRACT 70-143
8210260240 8210260242 8210260246 8210260247 8210260254	8210260237 8210260232 8210260232 8210260231 8210260233	82/10/12 82/10/12 82/10/12 82/10/01 82/10/20	CONTRACT 50-322 50-322 50-387 50-295	T T Q S	8210260575 8210260579 8210260582 8210270009 8210270020	8210260572 8210260572 8210260581 8210270008 8210270015	82/10/0B 82/10/0B 82/09/16 82/10/12 82/10/22	50-440 F 50-440 F 50-201 0 50-309 0 50-537 0
8210260287 8210260263 8210260268 8210260266 8210260270	8210260241 8210260260 8210260245 8210260256 8210260241	82/10/01 82/10/18 82/10/22 82/10/18 82/10/01	50-387 50-305 50-327 50-325 50-387	d 6 8	6210270023 6210270033 8210270035 6210270041 6210270051	8210270015 8210270027 8210270015 8210270015 821027004a	82/10/22 82/10/12 82/10/22 82/10/23	50-537 G CCNTRACT 50-537 G 50-537 G 50-447 A
8210260280 8210260284 8210260287 8210260273 8210260297	8210260278 8210260282 8210260281 8210260290 8210260275	82/09/24 82/09/29 82/10/19 82/10/19 82/10/19	CONTRACT CONTRACT 50-337 50-338 50-373		8210270052 8210270056 8210270060 8210270064 8210270068	8210270015 8210270015 8210270015 8210270015 8210270015	82/10/22 82/10/22 82/10/22	50-537 0 50-537 0 50-537 6 50-537 0 50-537 0
8210260301 8210260310 8210260313 8210260314	8210260298 8210260307 8210260309 8210260311 8210260315	82/10/22 82/10/22 82/10/18 82/10/18	50-298 50-454 50-302 50-373 50-155	Q G B G	8210270049 8210270070 8210270079 8210270081 8210270085	8210270015 8210270047 8210270074 8210270077 8210270074	82/10/22 82/09/03 82/09/07 82/09/14 82/09/07	50-537 <i>0</i> 70-687 71-6639 40-2061 71-6639
8210260318 8210260321 8210260325 8210260336 8210260337	8210260317 8210260317 8210260323 8210260331	82/10/14 82/10/19 82/10/21 82/10/21 82/10/21	50-324 50-373 50-324 50-369 50-440	8 9 P 0	8210270088 8210270095 8210270096 8210270113 8210270118	8210270077 8210270090 8210270083 8210270104 8210270104	82/07/14 82/10/25 82/10/25 82/10/15 82/10/15	40-2061 50-289
8210240338 8210240345 8210240351 8210240352 8210240353	8210260334 8210260341 8210260340 8210260341 8210260347	82/10/21 82/10/22 82/09/17 82/10/22 82/10/19	50-333 40-8610 TOPREP 40-8610 50-260	G , , , , , , , , , , , , , , , , , , ,	8210270129 8210270139 8210270142 8210270144 8210270152	8210270124 8210270132 8210270136 8210270132 8210270149	82/10/25 82/10/08 82/10/07 82/10/08 82/10/05	50-584 A 50-369 F 50-272 P 50-369 F XPORTLIC
8210260354 8210260360 8210260369 8210260367 8210260377	8210260350 8210260346 8210260344 8210260357 8210260370	82/10/20 82/10/19 82/10/18 82/10/15 82/09/17	50-387 50-339 50-325 50-335 50-302	P 8 8 9	8210270149 8210270177 8210270182 8210270183 8210270183	8210270164 8210270165 8210270179 8210270180 8210270184	82/09/29 81/05/26 82/09/14 82/08/25 82/10/22	TOPREP 50-309 9 40-8577 40-8502 50-275 P
8210260377 8210260382 8210260384 8210260385 6210260386	8210260366 8210260372 8210260360 8210260366 8210260378	82/10/22 82/10/18 82/10/22 82/10/22	50-387 50-341 50-454 50-387 50-333	P Q P 8	8210270193 8210270197 8210270203 8210270208 8210270215	8210270190 8210270195 8210270199 8210270204 8210270212	82/10/20 82/07/02 82/07/28 82/10/26 81/12/07	50-382 K 40-8102 CONTRACT 50-338 P 50-280 B
8210260391 8210260392 8210260404 8210260407 8210260410	8210260376 8210260380 8210260397 8210260381 8210260405	82/10/22 82/10/22 82/10/21 82/10/19 82/10/22	50-335 50-454 50-537 50-259 50-324	Q Q Q B P	8210270220 8210270221 8210270223 8210270224 8210270227	8210270212 8210270207 8210270207 8210270212 8210270222	81/12/07 82/09/29 82/09/29 81/12/07 82/08/27	50-200 8 CONTRACT CONTRACT 50-290 8 40-8632
8210260411 8210260424 8210260435 8210260441 8210260446	8210260399 6210260416 8210260416 6210260432 8210260417	82/10/19 82/10/21 82/10/21 82/10/17 82/10/19	50-295 50-361 50-361 50-336 50-260	8 P P S S	8210270230 8210270239 8210270240 8210270241 8210270247	8210270224 8210270227 8210270234 8210270237 8210270242	82/07/28 82/07/24 82/10/22 81/05/15 82/07/24	CONTRACT 57-302 G 50-275 R 50-318 8 40-8027
8210260463 8210260465 8210260470 8210260477 8210260479	8210260453 8210260457 8210260453 8210260472 8210240476	82/10/18 82/10/20 82/10/18 82/10/21	50-348 50-309 50-348 50-206 50-244	9 9 8 P P	8210270248 8210270249 8210270254 8210270257 8210270259	8210270244 8210270245 8210270251 8210270252 8210270256	81/06/05 81/05/18 81/12/15 81/05/22 82/10/08	50-317 S 50-213 S 50-249 S 50-317 S 50-266 F
				8 A P 8 8	8210270260 8210270261 8210270268 8210270269 8210270271	8210270258 8210270256 8210270267 8210270266 8210270267	82/10/12 82/10/08 82/10/22 81/05/20 82/10/22	50-338 P 50-246 F 50-334 P 50-317 S 50-334 P
	De10260376	82/10/22	\$0~335	E P R G	8210270273 8210270275 8210270278 8210270280 8210270288	8210270272 8210270274 8210270276 8210270279 8210270270	81/06/01 81/05/20 81/05/22 81/05/01 82/10/19	50-317 8 50-317 8 50-317 8 50-317 8 50-155 P
8210260511 8210260515 8210260520 8210260521 8210260524	8210260508 8210260376 8210260516 9210260518 8210260518	82/10/22 82/10/22 82/09/28 82/09/16 82/09/16	50-241 50-335 CONTRACT 50-272 50-272	F	8210270297 8210270302 8210270303 8210270304 8210270317	8210270294 8210270294 8210270294 8210270301 8210270314	82/10/15 82/10/15 82/10/15 82/10/15 82/09/29	50-266 P 50-246 P 50-266 P ORG 50-312 P

ACCESSIO	NUMBER					ON NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 18SUED	SUBJECT CATECORY
8210270320 8210270325 8210270332 8210270355 8210270360	8210270314 8210270319 8210270327 8210270352 8210270352	82/09/29 82/10/13 82/10/14 82/10/18 82/10/18	50-312 50-346 50-382 50-272 50-272	P P M P P	8210280200 8210280201 8210280205 8210280205 8210280212	8210280194 8210280196 8210280196 8210280203 8210280211	81/04/03 82/10/25 82/10/25 81/04/14 82/10/22	50-318 S 50-277 P 50-277 P 50-317 S 50-275 R
8210270366 8210270376 8210270382 8210270386 8210270387	8210270352 8210270373 8210270372 8210270372 8210270372	82/10/18 82/09/15 82/10/13 82/10/13 82/10/13	50-272 40-8824 50-346 50-346 50-346	P P P	8210280219 8210280228 8210280229 8210280232 8210280235	8210280215 8210280223 8210280223 8210280223	82/10/19 82/10/13 82/10/13 82/10/13 82/09/30	50-387 B 50-305 Q 50-305 Q 50-305 Q TOARTNOO
8210270395 8210270402 8210270407 8210270413 8210270419	8210270393 8210270399 8210270403 8210270411 8210270416	82/10/12 82/09/13 82/10/20 82/09/30 82/09/30	CONTRACT CONTRACT CONTRACT 50-387 CONTRACT	x	8210280244 8210280248 8210260255 8210280267	8210280241 8210280241 8210280249 8210280263 8210280275	92/10/12 82/10/12 81/04/23 81/04/16 82/10/22	50-397 0 50-397 G 50-317 S 50-317 B 50-324 F
8210270427 8210270428 8210270429 8210270430 8210270432	8210270423 8210270425 8210270423 8210270426 8210270426	82/09/23 82/09/30 82/09/23 82/10/08 82/10/08		F F	9210280284 8210280293 8210280297 9210280298 8210280301	8210280277 8210280271 8210280286 8210280273 8210280276	81/04/03 82/10/22 82/10/22 82/10/21 81/04/14	50-318 S 50-250 F 50-460 Q 50-264 P 50-317 S
8210270436 8210270437 8210270438 8210270439 8210270452	B210270434 B210270423 B210270423 B210270435 B210270448	82/10/12 82/09/23 82/09/23 82/09/03 82/09/27	70-1151 70-1510 70-1510 40-8681 XPORTLIC		92102803103 82102803103 82102803103 9210280319	8210280287 8210280277 8210280305 8210280311 8210280310	82/10/14 82/10/05 81/04/10 82/10/01 82/10/05	50-275 Q CONTRACT 50-317 B 71-9057 CONTRACT
8210280017 8210280019 8210280020 8210280021 8210280024	8210280016 8210280013 8210280016 8210280013 8210280013	82/10/12 82/09/17 82/10/12 82/09/17 82/09/17	F01A 50-349 50-324	F P P	8510580335 8510580331 8510580339 8510580351	8210280013 8210280322 8210280324 8210280327 8210280318	82/09/17 82/10/01 82/10/14 82/10/05 81/05/12	FOIA 71-6346 50-275 0 CONTRACT 50-317 8
9210280027 9210280031 9210280036 9210280037 9210280041	8210280013 8210280013 8210280033 8210280033 8210280033	82/09/17 82/09/17 82/10/08 82/10/08 82/10/08	50~336 50-322 50-322	P P F F	8210280393 8210280397 8210280341 8210280342 8210280345	8210280329 8210280334 8210280336 8210280338 6210280343	82/10/01 82/09/17 81/04/17 82/09/17 82/09/21	71-6745 71-6677 50-318 S 71-6678 71-6115
8210280042 8210280047 8210280048 8210280049 8210280051	8210280013 8210280013 8210280045 8210280046 8210280045	82/09/17 82/09/17 82/10/08 82/09/10 82/10/08	50-324 50-409 40-8745	P P F	8210280351 6210280354 8210280359 6210280344 8210280342	8210280348 8210280354 8210280357 8210280361 8210280368	82/10/26 82/10/05 82/09/16 82/10/12 82/10/13	REVIEW ORP CONTRACT 71-9098 50-254 F 50-528 Q
8210280053 8210280055 8210280059 8210280061 8210280063	8210280045 8210280045 8210280056 8210280058 8210280058	82/10/08 82/10/08 82/10/04 82/10/08 82/10/08	50-409 XPORTLIC 50-255	F F F	8210280374 8210280375 8210280380 8210280383 8210280383	8210280370 8210280361 8210280378 8210280378 8210280386	82/10/07 82/10/12 82/10/12 82/10/12 82/10/15	CONTRACT 50-254 F 50-315 F 50-315 F CONTRACT
8210280048 8210280074 8210280078 8210280082 8210280084	8210280066 8210280071 8210280075 8210280013 8210280080	82/10/19 82/10/20 82/10/19 82/09/17 82/10/19	50~213 50~346 50~261	5 5 6	8210280405 8210280408 8210280413 8210280417 6210280421	8210280402 8210280397 8210280399 8210280415 8210280415	82/09/30 82/10/12 82/10/12 82/10/14 82/10/14	FOIA 50-315 F 50-315 F 70-2957 70-2957
8210280095 8210280100 8210280103 8210280110 8210280112	8210280013 8210280013 8210280074 8210280013 8210280108	82/09/17 82/09/17 82/10/15 82/09/17 82/10/12	50-324 50-250 50-29 FOIA 50-313	P P P	8210280424 8210280425 8210280427 8210280430 8210280430	8210280417 8210280423 8210280419 8210280428 8210280428	82/10/12 82/10/15 82/10/12 82/10/18 82/10/18	50-295 F 50-305 F 50-295 F 50-247 P 50-247 P
8210280114 8210280120 8210280125 8210280124 8210280128	8210280108 8210280117 8210280122 8210280117 8210280123	82/10/12 82/10/12 82/10/22 82/10/12 82/10/15	50-313 50-295 50-373 50-295 50-311	F 0 F 8	8210260445 8210260447 8210260453 8210270003 8210270004	B210280442 B210280442 B210280452 B206270053 B206270053	82/10/12 82/10/12 82/09/21 82/10/04 82/10/04	50-295 F 50-295 F 70-364 COMMISSION COMMISSION
8210280131 8210280138 8210280141 8210280143 8210280145	8210280129 8210280136 8210280134 8210280136 8210280142	82/10/20 82/10/12 82/10/20 82/10/12 82/10/06	50-273 50-271 50-318 50-271 50-267	8 F 9 G	8210270027 8210270032 821027004 8210270041 8210270043	8210270023 8210270023 8210270023 8210270038 8210270023	82/09/03 82/09/03 82/09/03 82/10/12 82/09/03	FOIA FOIA 50-142 F 50-285 P 50-142 F
8210280149 8210280150 8210280154 8210280154 8210280159	8210280142 8210280144 8210280148 8210280152 8210280148	82/10/06 82/10/20 82/10/12 82/10/15 82/10/12	50-267 50-293 50-3 50-311 50-3	0 5 6 6	8210290048 8210290051 821029055 8210290055 8210290057	8210290023 8210290023 8210290023 8210290050 8210290054	82/09/03 82/09/03 82/09/03 82/10/23 82/10/13	50-142 G 50-142 F FOIA 50-416 B 50-259 S
8210280165 8210280168 8210280171 8210280174 8210280174	8210280158 8210280164 8210280164 8210280170 8210280170	82/10/25 82/10/13 82/10/13 82/10/13	50-348 50-282 50-282 50-461 50-461	P 0 0	8210270058 8210270060 8210270065 8210270065 8210270066	8210 290023 8210 290047 8210 290023 8210 290023 8210 290062	82/09/03 82/10/08 82/09/03 82/09/03 82/10/13	FOIA 50-10 F FOIA FOIA 50-259 8
8210280184 8210280184 8210280190 8210280195 8210280198	8210280180 8210280183 8210280185 8210280191 8210280194	82/10/25 82/10/21 82/10/22 81/04/08 82/10/25	40-7580 50-223 50-460 50-318 50-277	R Q B P	8210270047 8210270047 8210270047 8210270072 8210270072	8210270023 8210270063 8210270042 8210270068 8210270047	82/09/03 79/08/14 82/10/04 82/10/15 82/10/08	FOIA 50-341 A 50-338 P 50-289 Q 50-10 F

ACCESS1	ON NUMBER					ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE SESUED	SUBJEC CATEGO	ŶΥ	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	PΥ
8210290076		82/10/22	50-261	5	9210270286	8210290284	82/10/21	50-375	5
8210290080		92/10/19	50-364	s	8210290290	8210270278	85/10/24	50-358	a
8210290081	8210290073	82/10/25	50-416	8	6210290292	8210290289	82/10/19	50-364	S
8210290087		82/10/15	50-270	8	8210290301	8210290300	82/10/08	50-184	O
8210290086	8210290047	82/10/08	50-10	F	8210290304	8510540300	82/10/08	50-184	a
8210290089		82/10/15	50-322	g	8210270313	621029030B	85/10/18	50-287	s
8210290090		B2/10/15	FOIA		6210290314	8210270310	82/10/04	50-272	8
8210290093		82/10/15	50-322	Q	8210270320 8210270321	8210270316 8210270317	82/10/26	50~206	v
8210290094		82/10/14	50-328	5	8210270321	8210290319	82/09/24	50-259	8
8210270097	9210290079	85/10/55	50-324	S			02/07/24	50-275	R
8210290106		82/10/14	50-321	8	8210290329	8210290326	02/10/14	50-321	S
8210290107		82/10/08	50~220	a	8210290331 8210290332	8210290325 8210290311	82/10/15	50-325	S
8210270113		82/10/01	50-324	P	8210290332	8210290311	82/10/25 82/10/12	50-416	8
8210290126		82/10/04	50-387	P	621029033B	8210290325	82/10/12	50-321	8
8210290130	8210290115	82/10/04	50-387	P			027 10721	50-395	S
8210270131	8210270104	82/10/18	CONTRACT	Г	8210270339	8210290333	82/10/22	50-261	5
8210290132		82/10/15	50~322	a	8210270342	6210290336	82/10/15	50-324	9
8210290135		82/10/23	50-416	8	8210290344	8210290341	82/10/12	50~322	G
8210270136		82/10/04	50~387	p	8210290345	8210290340	85\10\53	50-416	S
821029 <b>01</b> 37	8210270127	82/10/26	50-409	G.	8210290347	8210290337	82/10/13	50-338	8
8210290143		82/09/21	50-313	P	8210270351	8210290348	82/10/25	50-416	s
8210290144		82/10/19	TOPREP		5210290352	B210290346	82/10/13	50-325	9
9210290146		85/09/21	50-313	P	8210290356	8210290350	85/10/07	50~322	G
8210290148		82/09/21	50-313	P	8210290359	8210270347	82/10/21	50-321	S
8210290157	8210290147	82/10/08	50-29	G	8210270341	8210270353	85/10/07	50-272	S
8210290163		82/10/27	50~329	Q.	8210270364	B210290357	82/10/07	50-366	8
8210290173		82/10/14	50-244	œ	8210290365	B210290355	82/10/14	50-249	8
8210290175		82/10/22	50-206	P	8210290371	8210290368	82/10/15	50-259	S
8210290180		82/10/22	50-206	P	6210290372	8210290367	62/10/13	XPORTL 10	
8210270183	8210290169	82/10/22	50-206	P	8210290375	8210290373	62/10/12	50-321	s
6210270194	8210290189	82/10/15	50-213	Q.	8210290380	8210290377	02/10/26	50~329	G-
8210290199	8210270170	82/10/15	50-249	B	8210270381	8210290374	82/10/12	50-366	8
8210290207		82/10/08	50~387	a	8210290382	8210290378	82/10/20	50-346	P
8210290209		82/10/14	50-366	8	8210270385	8210290378	82/10/20	50-346	P
8210290210	8210290208	02/10/08	50-352	q	8210290387	0210290370	82/10/20	50-346	Р
8210290217	8210290212	82/10/25	50-244	G	8210290392	8210290383	82/10/12	70-2944	
8210270218		82/10/06	50-272	ន	8210270398	6210290396	82/09/28	CONTRACT	•
8210270222		82/10/18	50-275	s	8210290416	8210270414	82/10/04	50-338	P
8210290229	8210290228	82/09/23	50-329	Α	8210290417	8210290413	82/10/07	50-344	Q.
8210290232	8210270231	82/10/14	50-296	5	8210290418	6210270414	82/10/04	50-338	P
8210290241	8210270238	82/10/14	70-33		8210290421	8210270414	82/10/04	50-338	Þ
8210290246	8210290243	82/10/21	50-324	8	8210270422	8210270420	85/10/08	CONTRACT	
8210290270		82/10/22	50-280	8	8210290428	8210290412	82/09/23	50-317	P
6210270272		82/10/14	50-321	8	6210290431	0210290426	82/10/04	50-266	Þ
8210290276	8210290264	82/10/22	50-280	8	8210290436	0210270426	82/10/04	50-266	ħ
B210290279	8210290277	82/10/14	50-327	8	8210290439	8210290412	82/09/23	50-317	P
0210290280		82/10/13	50-293	G .	8210290441	8210270426	82/10/04	50~266	P
9210290281	9210290278	82/10/26	50-356	Q.	8210270444	8210290412	85/09/23	50-317	P
8210290282		82/10/22	50~260	8	8210290451	8210290449	82/09/22	50-275	0
8210290285	8210290278	02/10/26	50-358	a	9210290454	8210290449	82/09/22	50~275	Q

#### APPENDIX A

#### **DEFINITIONS OF DOCKET 50 CATEGORIES**

#### A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating hoense. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are

- 1. Application for construction permit
- 2. General Information submitted with construction permit application.
- 3 Amendments and changes to items 1 and 2
- 4. NRC questions, requests for additional information, and applicant responses
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6 Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9 Construction Permit, amendments, and correspondence relating to the construction permit.
- 10 Scheduling of license application submission or review.
- 11 Environmental review information
- 12. Application for operating license
- 13. General Information submitted with operating license application
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility, not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

#### B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

#### C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

### D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- Transmittal and acknowledgement letters.
- Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.

- 1. Satety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

#### F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

#### G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1 Change of address notifications
- 2 Changes in structure of organization.
- 3. Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8 Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

#### I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

#### J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- <sup>2</sup> Other correspondence regarding indemnity and insurance matters.

#### K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

#### L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit

- 1. Limited Work Authorizations (LWA) and amendments.
- 2 Correspondence pertaining to work performed under LWAs.

#### M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
- 2 Correspondence where the primary topic of discussion is antitrust matters
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N

#### N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

### O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews
- 2 Correspondence from ACRS
- 3 Announcement of ACRS meetings
- 4 Transmittal and acknowledgement letters
- 5. ACRS reports.
- 6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7 Minutes at ACRS Subcommittee Meetings.

#### P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

------ to itypio i aliu Z

- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

### Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1 Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN s).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

#### R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature

- 1 Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets

5. Correspondence or other documents relating to the above listed items.

#### S. REPORTABLE OCCURRENCES, PNOs, PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER s) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences)
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports
- 4 Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNO s) and Preliminary Notification of Safeguards Events (PN s)
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1-7.

#### T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

## U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

- 1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches
- 2. Preparatory and backup documents for item 1.
- Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters

#### V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1 Operator licenses or administrative information bearing on licensing of operators.
- 2 NRC examination results.
- 3 Power plant examination summary sheet.

#### W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4 Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

# X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

#### APPENDIX B

### DEFINITIONS OF NONDOCKETED CATEGORIES

# 10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record, record of votes of Commissioners on items under consideration at meetings

### ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

# COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

 Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE. For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

### CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or 1FB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any.

#### DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

#### FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year—numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

# GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.

- 3. Meeting notifications and minutes.
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

# I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

# MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

# NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
  - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
  - b. They present the results of Commission licensing and policy decisions.
  - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development, and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are

- Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility, e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

#### PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- Federal Register notices stating the terms or substance of the proposed rule or a specification
  of the subject and issues involved.
- 2. Text of the Proposed Rule (PR),
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- Requests from the nuclear industry, organizations and other parties for written interpretations
  of the PR,

#### PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- o. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission teview of staff recommendations, see the 10CFR category.

# PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects (1) commercial nuclear power plants for which NRC has full licensing responsibilities, and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

I. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
  - 1. Application submitted by the utility.
  - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
  - 3. Applicant's Quality Assurance Manual.
  - 4. Early site review information.
  - 5. Backup technical documents submitted in support of the application.
  - 6. Early site visits.
- B. Utility PSAR and Amendments
  - 1. PSARs submitted by the utility.
  - 2. Amendments and changes to the PSAR.
  - 3. Transmittal letters.
  - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
  - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
  - 1. Submittals and related material pertaining to the antitrust review.

- 1 Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

#### Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

## PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include.

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations of the existence of defects which could create a substantial safety hazard.
- Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

## QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling e 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR by utilities for specific facilities. Documents in this category include:

ection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspecover the design, fabrication, construction and testing of structural systems and

ns.

3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

## REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are.

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

# RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
  - a. model documentation reports
  - b. code documentation reports
  - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examit
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by cont
- 8. Letter, monthly, quarterly, interim or annual status or projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with to and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting pleted research programs.

NOTE: For final reports of research conducted by contracto

# REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of N groups provide a broad base of technical expertise to aid mana

projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- 2. Summary numutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

## RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

#### SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

#### STATE PROG — State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

of haison and cooperative activities regarding such functions as licensing and siting. It includes.

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State haison officers, regarding
  - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
  - b technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations, i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4 Agreement State Licensing Statistics Reports

NOTE For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

#### TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

#### WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

in the waste isolation Pilot Plan (WIPP) for burial of defense wastes.

4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

# XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses,
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

NRC FORM 335 US NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET	1 REPORT NUMBER (Assisted by DDC) NUREG-0540 Vol. 4, No. 10
4 TITLE AND SUBTITLE (Add Volume No il appropriate)	2 (Leave biank)
	<b>}</b>
Title List of Documents Made Publicly Available October 1-31, 1982	3 RECIPIENT S ACCESSION NO
7 AUTHOR(S)	5 DATE REPORT COMPLETED
	MONTH YEAR
9 PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include ZIE	Codel DATE REPORT ISSUED
Division of Technical Information and Document (	Control MONTH YEAR
UTTice of Administration	January 1905
U.S. Nuclear Regulatory Commission	6 (Leave blank)
Washington, DC 20555	8 (Leave blank)
2 SPONSORING ORGANIZATION NAME AND MAILING ADDRESS finclude Zip	Code) 10 PROJECT TASK/WORK UNIT NO
Same as 9, above.	
	11 FIN NO
3 TYPE OF REPORT PE	RIOD COVERED linclusive dates!
Monthly	, and days need in warms and
Thoriting .	
5. SUPPLEMENTARY NOTES	14 (Leave olank)
This document is a monthly publication containing received and generated by the U.S. NRC. This informaterial associated with civilian nuclear power pactive materials, and (2) nondocketed material repertinent to its role as a regulatory agency. The Personal Author Index, Corporate Source Index, Reference to Principal Documents Index.	ormation includes (1) docketed plants and other uses of radio- eceived and generated by NRC he following indexes are included:
KEY WORDS AND DOCUMENT ANALYSIS 17a	DESCRIPTORS
D IDENTIFIERS OPEN ENDED TERMS	
	19 SECURITY CLASS (This report)   21 NO OF PAGES
AVAILABILITY STATEMENT	Unclassified
	20 SECURITY CLASS (This name) 22 BRICE

u-limited